Title List of Documents Made Publicly Available

October 1-31, 1982

Office of Administration U.S. Nuclear Regulatory Commission



Available from

NRC/GPO Sales Program

Superintendent of Documents Government Printing Office Washington, D. C. 20402

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program Washington, D. C. 20555

Title List of Documents Made Publicly Available

October 1-31, 1982

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	xvii
Docketed Items	
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	7
Domestic Licensing of Special Nuclear Material — Docket 70	328
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71	335
Nondocketed Items	
10 CFR — Commission Meeting Records	339
ACRS — Advisory Committee on Reactor Safeguards	339
COMMISSION — NRC Commissioners	340
CONTRACT — NRC Contracts and Modifications	340
FOIA — Freedom of Information Act Requests and Releases	347
GEN TECH IS — Generic Technical Issues	364
I&E Inspection and Enforcement	365
MISC — Public Document Room Miscellaneous	366
NUREG — NUREG Reports and Related Correspondence	366
ORG — Correspondence with Other Organizations	370
PR — Proposed Rule	371
PRM — Petition for Rulemaking	374
PROJ — Projects - Predocket Licensing	374
PT 21 — Noncompliance Reports and Related Correspondence	374
QA999 — Quality Assurance Inspections	374
REGGD — Regulatory Guides	376
RES — Research and Technical Assistance Reports	377
REVIEW GROUP - NRC Research Review Groups	378
SECY — Position Papers Before the Commission	379
STATE PROG — State Programs	379
TOPREP — Vendor Reports and Related Correspondence	380
WASTE MGT — Nuclear Waste Management	383
XPORTLIC — Export and Import Licenses	384
Personal Author Index	389
Corporate Source Index	419
Report Number Index	449
Cross Reference of Enclosures to Principal Documents	451
Appendix A — Definitions of Docket 50 Categories	A-l
Appendix R — Definitions of Nondocketed Categories	B-1

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

P Operating license stage documents & correspondence

2 3
8203090028 Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research. Ctr. by 820408. Proprietary repts will be provided to NRC by 820510.

4 MILLS, L.M. 5 Tennessee Valley Authority. 6 82/03/04 7 VASSALLO, D B. Operating Reactors Branch 2. 8 1p. 1216:254. 24XFiche: 50-259, 82/03/04, 8203090028.

- NRC/PDR Document category (see Appendix A)
- 2. NRC Accession Number (year, month, day, and sequence number of item).
- 3. Description of information contained in the document.
- 4. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source.
- 6. Date of document described.
- 7. Recipient of document and NRC or corporate affiliation.
- 8. Pages in this document.
- 9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files
- This three-digit portion of this entry is the number of the frame on which this document starts.
- 11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
- 12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues

1&E - Inspection and Enforcement

MISC - Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG - Correspondence with Other Organizations

PR - Proposed Rule

PRM — Petition for Rulemaking

PROJ — Projects—Predocket Licensing

PT21 — Noncompliance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD - Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP - NRC Research Review Groups

RM — Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP — Vendor Reports and Related Correspondence


WASH — Regulatory Publications—Pre-NUREG Series

WASTE MGT - Nuclear Waste Management

XPORTLIC - Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



- 1. Nondocketed category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 6. Corporate, agency or other nonindividual source.
- 7. Contract or financial (FIN) number (if any). If the document has a sceondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- 9 Date of document described.
- 10. NRC organizational recipient.
- 11. Pages in document.
- 12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13. Price for which NRC sells the document.

- 14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files
- 15 This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES.

1 The address for NRC is.

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C 20555

To place orders, send check or money order, payable to the Superintendent of Documents GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2 The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order

3. The address for the PDR is:

1717 H Street, N W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Rad	lwaste Disposal Sites — Docket 27		40-8452	Bear Creek Uranium Co., Casper, WY	4
27-010	Beatty, NV, U.S. Ecology, Inc.	1	40-8502	Wyoming Mineral Corp., Lakewood, CO	5
27-039	Sheffield, IL, U.S. Ecology, Inc.	I	40-8577	Air Force, Dept. of, Vandenberg AFB, CA	5
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	40-8602	Silver King Mines, Inc., Casper, WY	5
27-048	Richland, WA, U.S. Ecology, Inc.	1	40-8610	Stepan Chemical Co., Maywood, NJ	5
Domestic Licer	nsing of Source Material — Docket 40		40-8632	Army, Dept. of, Chambersburg, PA	5
40-0017	Dow Chemical Co., Midland, MI	1	40-8681	Energy Fuels Nuclear, Inc., Denver, CO	5
40-0299	Union Carbide Corp., Grand Junction, CO	I	40-8697	Rocky Mountain Energy Co., Denver, CO	6
40-1162	Western Nuclear Corp., Jeffrey City, WY	2	40-8698	Piateau Resources, Ltd.,	
40-1202	NL Industries, Inc., Niagara Falls, NY	2		Grand Junction, CO	6
40-1341	Tennessee Valley Authority,		40-8714	Cleveland-Cliffs Iron Co., Cleveland, OH	6
	Chattanooga, TN	2	40-8728	Teton Exploration Drilling Co., Inc., Casper, WY	6
40-2061	Kerr-McGee Chemical Corp., Oklahoma City, OK	2	40-8743	Conoco, Inc., Denver, CO	6
40-2259	Pathfinder Mines Corp., Riverton, WY	2	40-8745	Ogle Petroleum, Inc., Casper, WY	6
40-3392	Allied Chemical Corp., Morristown, NJ	2	40-8768	Kerr-McGee Nuclear Corp.,	,
40-3453	Atlas Mineral, Inc., Denver, CO	2	40 0EET	Oklahoma City, OK	6
40-6622	Pathfinder Mines Corp.,		40-8771	Melapai Resources Co., Phoenix, AZ	6
	Shirley Basin, WY	3	40-8781	Teton Exploration Drilling Co., Inc., Casper, WY	6
40-6659	Getty Oil Co. — Petrotomics Co., Shirley Basin, WY	3	40-8786	Uranium Resources, Inc., Richardson, TX	7
40-7580	Fansteel, Inc., North Chicago, IL	3	40-8793	Conoco, Inc., Denver, CO	7
40-8027	Kerr-McGee Nuclear Corp., Oklahoma City, OK	3	40-8820	Amax Environmental Services, Inc., Golden, CO	7
40-8084	Rio Algom Corp., Moab, UT	4	40-8824	Target Research, Inc., Wharton, NJ	7
40-8102	Exxon Co. USA, Houston, TX	4	Domestic Licer Docket 50	ising of Production and Utilization Facilities	
40-8111	Kennecott Copper Corp., Salt Lake City, UT	4	50-3	Indian Delay Station - I had t	
40-8153	Lebanon Steel Foundry, Lebanon, PA	4		Indian Point Station, Unit i	7
40-8355	Amax Speciality Metals Corp.,		50-10	Dresden Nuclear Power Station, Unit 1	8
	Parkersburg, WV	4	50-13	Babcock & Wilcox Co. Critical Facility	9
40-8380	Rocky Mountain Energy Co., Broomfield, CO	4	50-20	Massachusetts Institute of Technology Research Reacter	9

Docket	Name	Page	Docket	Name	Page
50-22	Westinghouse Test Reactor	9	50-247	Indian Point Station, Unit 2	36
50-27	Washington State Univ. Research Reactor	9	50-249	Dresden Nuclear Power Station, Unit 3	41
50-29	Yankee-Rowe Nuclear Power Station	9	50-250	Turkey Point Plant, Unit 3	43
50-54	Union Carbide Research Reactor	12	50-251	Turkey Point Plant, Unit 4	45
50-57	State Univ. of New York Research Reactor	12	50-254	Quad-Cities Station, Unit I	47
50-62	Univ. of Virginia Research Reactor	12	50-255	Palisades Nuclear Plant	49
50-70	General Electric Test Reactor	12	50-259	Browns Ferry Nuclear Power Station, Unit 1	51
50-72	Univ. of Utah Research Reactor	13	50-260	Browns Ferry Nuclear Power Station, Unit 2	54
50-83	Univ. of Florida Training Reactor	13	50-261	H, B. Robinson Plant, Unit 2	56
50-133	Humboldt Bay Power Plant, Unit 3	13	50-263	Monticelio Nuclear Generating Plant	58
50-142	UCLA Training Rector	13	50-264	Dow Chemical Co.	60
50-148	Univ. of Kansas Research Reactor	14	50-265	Quad-Cities Station, Unit 2	60
50-151	Univ. of Illinois Research Reactor	14	50-266	Point Beach Nuclear Plant, Unit 1	62
50-155	Big Rock Point Nuclear Plant	14	50-267	Fort St. Vrain Nuclear Generating Station	66
50-160	Georgia Institute of Technology Research Reactor	17	50-269	Oconee Nuclear Station, Unit 1	67
50-170	National Naval Medical Center	17	50-270	Oconee Nuclear Station, Unit 2	69
50-182	Purdue Univ. Research Reactor	18	50-271	Vermont Yankee Nuclear Power Station	71
50-184	National Bureau of Standards Reactor	18	50-272	Salem Nuclear Generating Station, Unit 1	73
50-186	Univ. of Missouri Research Reactor	18	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	76
50-188	Kansas State Univ. Research Reactor	18	50-277	Peach Bottom Atomic Power Station, Unit 2	79
50-192	Univ. of Texas Research Reactor	18	50-278	Peach Bottom Atomic Power Station, Unit 3	81
50-199	Manhattan College Research Reactor	18	50-280	Surry Power Station, Unit 1	82
50-201	West Valley Reprocessing Plant	18	50-281	Surry Power Station, Unit 2	85
50-206	San Onofre Nuclear Station, Unit 1	19	50-282	Prairie Island Nuclear Station, Unit 1	87
50-208	Columbia Univ. Research Reactor	22	50-285	Fort Calhoun Station, Unit 1	89
50-213	Haddam Neck Plant	22	50-286	Indian Point Station, Unit 3	90
50-219	Oyster Creek Nuclear Power Plant	23	50-287	Oconee Nuclear Station, Unit 3	93
50-220	Nine Mile Point Nuclear Station, Unit 1	26	50-289	Three Mile Island Nuclear Station, Unit 1	96
50-223	Univ. of Lowell Research Reactor	28	50-293	Pilgrim Nuclear Power Station, Unit 1	101
50-228	Aerotest Radiography & Research Reactor	28	50-295	Zion Nuclear Power Station, Unit 1	102
50-237	Dresden Nuclear Power Station, Unit 2	28	50-296	Browns Ferry Nuclear Power Station, Unit 3	106
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	30	50-298	Cooper Nuclear Station	107
50-245	Millstone Nuclear Power Station, Unit 1	34	50-301	Point Beach Nuclear Plant, Unit 2	108

D	ocket	Name	Page	Docket	Name	Page
	50-302	Crystal River Nuclear Plant, Unit 3	111	50-352	Limerick Generating Station, Unit 1	199
	50-304	Zion Nuclear Power Station, Unit 2	113	50-353	Limerick Generating Station, Unit 2	201
	50-305	Kewaunee Nuclear Power Plant	116	50-354	Hope Creek Nuclear Station, Unit 1	203
	50-306	Prairie Island Nuclear Station, Unit 2	118	50-355	Hope Creek Nuclear Station, Unit 2	204
	50-309	Maine Yankee Atomic Power Plant	119	50-358	William H. Zimmer Nuclear Station, Unit !	204
	50-311	Salem Nuclear Generating Station, Unit 2	122	50-361	San Onofre Nuclear Station, Unit 2	206
	50-312	Rancho Seco Nuclear Generating Station	126	50-362	San Onofre Nuclear Station, Unit 3	209
	50-313	Arkansas Nuclear One, Unit 1	129	50-363	Forked River Nuclear Station, Unit 1	210
	50-315	Donald C Cook Nuclear Power Plant, Unit 1	131	50-364	Joseph M. Farley Nuclear Plant, Unit 2	210
	50-316	Donald C. Cook Nuclear Power Plant, Unit 2	134	50-366	Edwin 1. Hatch Nuclear Plant, Unit 2	213
	50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	137	50-367	Bailly Generating Station	215
	50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	141	50-368	Arkansas Nuclear One, Unit 2	216
	50-320	Three Mile Island Nuclear Station, Unit 2	144	50-369	William B. McGuire Nuclear Station, Unit 1	218
	50-321	Edwin I. Hatch Nuclear Plant, Unit I	146	50-370	William B. McGuire Nuclear Station, Unit 2	221
	50-322	Shoreham Nuclear Power Station	148	50-373	LaSalle County Station, Unit 1	222
	50-323	Diablo Canyon Nuclear Power Plant, Unit 2	152	50-374	LaSalle County Station, Unit 2	226
	50-324	Brunswick Steam Electric Plant, Unit 2	154	50-382	Waterford Generating Station, Unit 3	228
	50-325	Brunswick Steam Electric Plant, Unit 1	159	50-387	Susquehanna Steam Electric Station, Unit 1	230
	50-327	Sequoyah Nuclear Plant, Unit 1	164	50-388	Susquehanna Steam Electric Station, Unit 2	234
	50-328	Sequoyah Nuclear Plant, Unit 2	166	50-389	St. Lucie Plant, Unit 2	235
	50-329	Midland Plant, Unit l	168	50-390	Watts Bar Nuclear Plant, Unit 1	238
	50-330	Midland Plant, Unit 2	172	50-391	Watts Bar Nuclear Plant, Unit 2	241
	50-331	Duane Arnold Energy Center	176	50-395	Virgil C. Summer Nuclear Station, Unit 1	244
	50-333	James A. Fitzpatrick Nuclear Power Plant	178	50-397	WPPSS Nuclear Project, Unit 2	246
	50-334	Beaver Valley Power Station, Unit 1	180	50-400	Shearon Harris Nuclear Power Plant, Unit I	248
	50-335	St. Lucie Plant, Unit 1	182	50-401	Shearon Harris Nuclear Power Plant, Unit 2	251
	50-336	Millstone Nuclear Power Station, Unit 2	184	50-402	Shearon Harris Nuclear Power Plant, Unit 3	254
	50-338	North Anna Power Station, Unit 1	186	50-403	Shearon Harris Nuclear Power Plant, Unit 4	254
	50-339	North Anna Power Station, Unit 2	189	50-404	North Anna Power Station, Unit 3	254
	50-341	Enrico Fermi Atomic Power Plant, Unit 2	192	50-405	North Anna Power Station, Unit 4	254
	50-344	Trojan Nuclear Plant	194	50-409	La Crosse Boiling Water Reactor	255
	50-346	Davis-Besse Nuclear Power Station, Unit 1	195	50-410	Nine Mile Point Nuclear Station, Unit 2	257
	50-348	Joseph M. Farley Nuclear Plant, Unit 1	197	50-412	Beaver Valley Power Station, Unit 2	258

Docket	Name	Page	Docket	Name	Page
50-413	Catawba Nuclear Station, Unit 2	258	STN-50-485	Sterling Power Nuclear Project, Unit 1	303
50-414	Catawba Nuclear Station, Unit 2	261	STN-50-488	Perkins Nuclear Station, Unit 1	303
50-416	Grand Gulf Nuclear Station, Unit 1	263	STN-50-489	Perkins Nuclear Station, Unit 2	303
50-417	Grand Gulf Nuclear Station, Unit 2	267	STN-50-490	Perkins Nuclear Station, Unit 3	304
50-423	Millstone Nuclear Power Station, Unit 3	269	STN-50-491	Cherokee Nuclear Station, Unit 1	304
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	269	STN-50-492	Cherokee Nuclear Station, Unit 2	304
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	270	STN-50-493	Cherokee Nuclear Station, Unit 3	304
50-434	Surry Power Station, Unit 3	271	STN-50-498	South Texas Project, Unit 1	304
50-435	Surry Power Station, Unit 4	271	STN-50-499	South Texas Project, Unit 2	305
STN-50-437	Floating Nuclear Plant	271	STN-50-508	WPPSS Nuclear Project, Unit 3	306
50-438	Bellefonte Nuclear Plant, Unit i	271	STN-50-509	WPPSS Nuclear Project, Unit 5	307
50-439	Bellefonte Nuclear Plant, Unit 2	274	50-513	WPPSS Nuclear Project, Unit 4	307
50-440	Perry Nuclear Power Plant, Unit 1	276	50-514	Pebble Springs Nuclear Plant, Unit 1	307
50-441	Perry Nuclear Power Plant, Unit 2	280	50-515	Pebble Springs Nuclear Plant, Unit 2	307
50-443	Seabrook Nuclear Station, Unit 1	284	STN-50-518	Hartsviile Nuclear Plant, Unit 1	307
50-444	Seabrook Nuclear Station, Unit 2	286	STN-50-519	Hartsville Nuclear Plant, Unit 2	308
50-445	Comanche Peak Steam Electric Station, Unit 1	287	STN-50-520	Hartsville Nuclear Plant, Unit 3	308
50-446	Comanche Peak Steam Electric Station,	289	STN-50-521	Hartsviile Nuclear Plant, Unit 4	309
30-440	Unit 2	209	50-522	Skagit Nuclear Power Project, Unit 1	309
STN-50-447	GESSAR-238	290	50-523	Skagit Nuclear Power Project, Unit 2	310
STN-50-454	Byron Station, Unit 1	291	STN-50-528	Palo Verde Nuclear Station, Unit 1	311
STN-50-455	Byron Station, Unit 2	293	STN-50-529	Palo Verde Nuclear Station, Unit 2	314
STN-50-456	Braidwood Station, Unit 1	295	STN-50-530	Palo Verde Nuclear Station, Unit 3	316
STN-50-457	Braidwood Station, Unit 2	296	50-537	Clinch River Breeder Reactor	318
50-458	River Bend Station, Unit 1	297	STN-50-546	Marble Hill Nuclear Station, Unit 1	325
50-459	River Bend Station, Unit 2	298	STN-50-547	Marble Hill Nuclear Station, Unit 2	326
50-460	WPPSS Nuclear Project, Unit 1	298	STN-50-553	Phipps Bend Nuclear Station, Unit 1	326
50-461	Clinton Power Station, Unit 1	299	STN-50-554	Phipps Bend Nuclear Station, Unit 2	326
50-462	Clinton Power Station, Unit 2	301	STN-50-556	Black Fox Station, Unit 1	327
50-466	Allens Creek Nuclear Station, Unit 1	301	STN-50-557	Black Fox Station, Unit 2	327
STN-50-470	CESSAR System 80	301	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	327
		301	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	327
		302	STN-50-584	Gibbsar, Gibbs & Hill	328

Docket	Name	Page	Docket	Name	Page
Domestic Lice	nsing of Special Nuclear Material — Docket 70		70-2748	Scioto Memorial Hospital, Portsmouth, OH	334
70-0007	ICN Pharmaceuticals, Inc.,	***	70-2789	Missouri, Univ. of, Columbia, MO	334
	Irvine, CA	328	70-2792	Lower Bucks Hospital, Bristol, PA	334
70-0025	Rockwell International Corp., Canoga Park, CA	328	70-2873	Puerto Rico, Univ. of, Mayaguez, PR	334
70-0027	Babcock & Wilcox Co., Lynchburg, VA	328	70-2942	Harper-Grace Hospitals, Detroit, MI	334
70-0033	Texas Instruments, Inc., Attleboro, MA	328	70-2944	Duke Power Co., Charlotte, NC	334
70-0036	Combustion Engineering, Inc., Windsor, CT	329	70-2946	Louisiana Power & Light Co., New Orleans, LA	334
70-0135	Babcock & Wilcox Co., Apollo, PA	329	70-2949	Arizona Public Service Co., Phoenix, AZ	334
70-0143	Nuclear Fuel Services, Inc., Erwin, TN	329	70-2955	Edlow International Co., Washington, DC	334
70-0223	California, Univ. of, Los Angeles, CA	330	70-2957	Florida Power & Light Co., Miami, FL	334
70-0278	Dow Chemical Co., Midland, MI	330	70-2968	Cleveland Electric Illuminating Co.,	30.
70-0364	Babcock & Wilcox Co., Apollo, PA	330	10 2700	Cleveland, OH	335
70-0371	UNC Naval Products, Inc., Uncasville, CT	330	Packaging of R	adloactive Material for Transport and Transport	stion
70-0398	Commerce, Dept. of, Washington, DC	331		e Material Under Certain Conditions - Docket	
70-0416	Colorado State Univ., Ft. Collins, CO	331	71-0030	General Atomic Co.	335
70-0633	Pan American World Airways, Inc., Patrick AFB, FL	331	71-0481	Monroe X-Ray Co., Inc.	335
70-0687	Union Carbide Corp., Tuxedo, NY	331	71-5908	Model: DOT-6M Type B, Babcock & Wilcox Co.	335
70-0753	Wheaton College, Wheaton, IL	331	71-5926	Modei: GE-100, General Electric Co.	335
70-0754	General Electric Co., Pleasanton, CA	331	71-5939	Model: GE-1500, General Electric Co.	335
70-0820	United Nuclear Corp.,		71-6115	Model: R1010-0032, Energy, Dept. of	335
#A 0004	Wood River Junction, RI	331	71-6346	Model: FSV-1, General Atomic Co.	335
70-0824	Babcock & Wilcox Co., Lynchburg, VA	332	71-6347	Model: FSV-3, General Atomic Co.	335
70-1100 70-1113	Combustion Engineering, Inc., Windsor, CT General Electric Co., Wilmington, NC	332 332	71-6574	Model: HN-200, Hittman Nuclear & Development Corp.	
70-1143	Westinghouse Electric Corp., Pittsburgh, PA	332	71-6601	Model: CNS 8-120, Chem-Nuclear Systems,	
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	333		lnc.	333
70-1201	Babcock & Wilcox Co., Lynchburg, VA	333	71-6639	Model: MH-1A, Army, Dept. of	335
70-1257	Exxon Nuclear Co., Inc., Richland, WA	333	71-6677	Model: LP-12, Energy, Dept. of	335
70-1510	Nuclear Assurance Corp., Atlanta, GA	333	71-6678	Model: LP-50, Energy, Dept. of	336
70-1621	Duquesne Light Co., Pittsburgh, PA	333	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	336
70-1739	Tri-State Motor Transit Co., Joplin, MO	334	71-6703	Model: RG-1, General Atomic Co.	336
70-2116	Lawrence General Hospital, Lawrence, MA	334	71-6745	Model: FSV-2, General Atomic Co.	336
70-2650	St. John's Mercy Medical Center,		71-9001	Model: IF-300, General Electric Co.	336
	St. Louis, MO	334	71-9010	Model: NLI-1/2, NL Industries, Inc.	336

Docket	Name	Page	Docket	Name	Page
71-9034	Model. TRIGA-1, General Atomic Co	336	71-9091	Model: 30A & 30B, Gulf Nuclear Co.	337
71-9037	Model TRIGA-2, General Atomic Co.	336	71-9094	Model: CNS 14-195-H, Chem-Nuclear Systems, Inc.	137
71-9044	Model. GE-1600, General Electric Co	336		Systems, inc.	
71-9057	Model: FPD-100, General Atomic Co	336	71-9096	Model: CNS 21-300, Chem-Nuclear Systems, Inc.	337
71-9079	Model. HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	336	71-9098	Model: UCC-20WC-2 & 2A, Union Carbide Corp.	337
71-9080	Model: 9080, Hittman Nuclear & Development Corp.	336	71-9111	Model: CNS6-80-2, Chem-Nuclear Systems, Inc.	117
71-9081	Model. CNS-1600, Chem-Nuclear Systems, Inc.	336	71-9150	Model: PAT-2, Energy, Dept. of	117
	the.	330	71-9151	Model: HN-100, Series 3, Hittman Nuclear	
71-9086	Model: HN-100, Series 1, Hittman Nuclear & Development Corp.	336		& Development Corp.	317
#4 mos -			71-9167	Model: Type B, Amersham Corp.	117
71-9089	Model HN-100S, Hittman Nuclear & Development Corp.	337	71.0074	Maria and an analysis and an a	111
	ж Бетеюринені Согр.	337	71-9964	Model: LP-12-1, Energy, Dept. of	137

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Dockei	Page
Low Level Radwaste Disposal Sites - Docket 2	27				
Barnwell, SC, Chem-Nuclear Systems, Inc.	27-047	1	Melapai Resources Co., Phoenix, AZ	40-8771	6
Beatty, NV, U.S. Ecology, Inc.	27-010	1	NL Industries, Inc., Niagara Falls, NY	40-1202	2
Richland, WA, U.S. Ecology, Inc.	27-048	1	Ogle Petroleum, Inc., Casper, WY	40-8745	6
Sheffield, IL, U.S. Ecology, Inc.	27-039	1	Pathfinder Mines Corp., Riverton, WY	40-2259	2
Domestic Licensing of Source Material - Dock	cet 40		Pathfinder Mines Corp., Shirley Basin, WY	40-6622	3
Air Force, Dept. of, Vandenberg AFB, CA	40-8577	5	Plateau Resources, Ltd., Grand Junction, CO	40-8698	6
Allied Chemical Corp., Morristown, NJ	40-3392	2	Rio Algom Corp., Moab, UT	40-8084	4
Amax Environmental Services, Inc., Golden, C	O 40-8820	7	Rocky Mountain Energy Co., Broomfield, CO	40-8380	4
Amax Speciality Metals Corp.,	10 00 5		Rocky Mountain Energy Co., Denver, CO	40-8697	6
Parkersburg, WV	40-8355	4	Silver King Mines, Inc., Casper, WY	40-8602	5
Army, Dept. of, Chambersburg, PA	40-8632	5	Stepan Chemical Co., Maywood, NJ	40-8610	5
Atlas Mineral, Inc., Denver, CO	40-3453	2	Target Research, Inc., Wharton, NJ	40-8824	7
Bear Creek Uranium Co., Casper, WY	40-8452	4	Tennessee Valley Authority, Chattanooga, TN	40-1341	2
Cleveland-Cliffs Iron Co., Cleveland, OH	40-8714	6	Teton Exploration Drilling Co., Inc.,		_
Conoco, Inc., Denver, CO	40-8743	6	Casper, WY	40-8728	6
Conoco, Inc., Denver, CO	40-8793	7	Teton Exploration Drilling Co., Inc.,	40 0301	6
Dow Chemical Co., Midland, MI	40-0017	1	Casper, WY	40-8781	-
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	5	Union Carbide Corp., Grand Junction, CO	40-0299	1
Exxon Co. USA, Houston, TX	40-8102	4	Uranium Resources, Inc., Richardson, TX	40-8786	7
Fansteel, Inc., North Chicago, 1L	40-7580	3	Western Nuclear Corp., Jeffrey City, WY	40-1162	2
	40-1380	3	Wyoming Mineral Corp., Lakewood, CO	40-8502	5
Getty Oil Co. — Petrotomics Co., Shirley Basin, WY	40-6659	3	Domestic Licensing of Production and Utilizati	on Facilities —	
Kennecott Copper Corp., Salt Lake City, UT	40-8111	4	Docket 50		
Kerr-McGee Chemical Corp.,			Acrotest Radiography & Research Reactor	50-228	28
Oklahoma City, OK	40-2061	2	Allens Creek Nuclear Station, Unit 1	50-466	301
Kerr-McGee Nuclear Corp., Oklahoma City, O	K 40-8027	3	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	269
Kerr-McGee Nuclear Corp., Oklahoma City, O	K 40-8768	6	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	270
Lebanon Steel Foundry, Lebanon, PA	40-8153	4	Arkansas Nuclear One, Unit 1	50-313	129

Name	Docket	Page	Name	Docket	Page
Arkansas Nuclear One, Unit 2	50-368	216	Comanche Peak Steam Electric Station, Unit 1	50-445	287
Babcock & Wilcox Co. Critical Facility	50-13	9	Comanche Peak Steam Electric Station, Unit 2	50- 446	289
Bailly Generating Station	50-367	215	Cooper Nuclear Station	50-298	107
Beaver Valley Power Station, Unit 1	50-334	180	Crystal River Nuclear Plant, Unit 3	50-302	111
Beaver Valley Power Station, Unit 2	50-412	258	Davis-Besse Nuclear Power Station, Unit 1	50-346	195
Bellefonte Nuclear Plant, Unit 1	50-438	271	Diablo Canyon Nuclear Power Plant, Unit I	50-275	76
Bellefonte Nuclear Plant, Unit 2	50-439	274	Diablo Canyon Nuclear Power Plant, Unit 2	50-323	152
Big Rock Point Nuclear Plant	50-155	14	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	131
Black Fox Station, Unit 1	STN-50-556	327	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	134
Black Fox Station, Unit 2	STN-50-557	327	Dow Chemical Co.	50-264	60
Braidwood Station, Unit I	STN-50-456	295	Dresden Nuclear Power Station, Unit I	50-10	8
Braidwood Station, Unit 2	STN-50-457	296	Dresden Nuclear Power Station, Unit 2	50-237	28
Browns Ferry Nuclear Power Station, Unit 1	50-259	51	Dresden Nuclear Power Station, Unit 3	50-249	41
Browns Ferry Nuclear Power Station, Unit 2	50-260	54	Duane Arnold Energy Center	50-331	176
Browns Ferry Nuclear Power Station, Unit 3	50-296	106	Edwin I. Hatch Nuclear Plant, Unit I	50-321	146
Brunswick Steam Electric Plant, Unit 1	50-325	159	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	213
Brunswick Steam Electric Plant, Unit 2	50-324	154	Enrico Fermi Atomic Power Plant, Unit 2	50-341	192
Byron Station, Unit I	STN-50-454	291	Floating Nuclear Plant	STN-50-437	271
Byron Station, Unit 2	STN-50-455	293	Forked River Nuclear Station, Unit 1	50-363	210
Callaway Plant, Unit 1	STN-50-483	302	Fort Calhoun Station, Unit 1	50-285	89
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	137	Fort St. Vrain Nuclear Generating Station	50-267	66
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	141	General Electric Test Reactor	5 0 -70	12
Catawba Nuclear Station, Unit 1	50-413	258	Georgia Institute of Technology Research		
Catawba Nuclear Station, Unit 2	50-414	261	Reactor	50-160	17
stem 80	STN-50-470	ากเ	GESSAR-238	STN-50-447	290
			Gibbsar, Gibbs & Hill	STN-50-584	328
			Grand Gulf Nuclear Station, Unit I	50-416	263
			Grand Gulf Nuclear Station, Unit 2	50-417	267
			H. B. Robinson Plant, Unit 2	50-261	56
			Haddam Neck Plant	50-213	22
			Hartsville Nuclear Plant, Unit 1	STN-50-518	307
			Hartsville Nuclear Plant, Unit 2	STN-50-519	308

Name	Docket	Page	Name	Docket	Page
Hartsville Nuclear Plant, Unit 3	STN-50-520	308	Nine Mile Point Nuclear Station, Unit 1	50-220	26
Hartsville Nuclear Plant, Unit 4	STN-50-521	309	Nine Mile Point Nuclear Station, Unit 2	50-410	257
Hope Creek Nuclear Station, Unit 1	50-354	203	North Anna Power Station, Unit 1	50-338	186
•	50-355	204	North Anna Power Station, Unit 2	50-339	189
Hope Creek Nuclear Station, Unit 2	50-133	13	North Anna Power Station, Unit 3	50-404	254
Humboldt Bay Power Plant, Unit 3		7	North Anna Power Station, Unit 4	50-405	254
Indian Point Station, Unit 1	50-37		Oconee Nuclear Station, Unit 1	50-269	67
Indian Point Station, Unit 2	50-247	36	Oconee Nuclear Station, Unit 2	50-270	69
Indian Point Station, Unit 3	50-286	90	Oconee Nuclear Station, Unit 3	50-287	93
James A. Fitzpatrick Nuclear Power Plant	50-333	178		50-219	23
Joseph M. Farley Nuclear Plant, Unit 1	50-348	197	Oyster Creek Nuclear Power Plant	50-255	49
Joseph M. Farley Nuclear Plant, Unit 2	50-364	210	Palisades Nuclear Plant		311
Kansas State Univ. Research Reactor	50-188	18	Palo Verde Nuclear Station, Unit 1	STN-50-528	
Kewaunee Nuclear Power Plant	50-305	116	Palo Verde Nuclear Station, Unit 2	STN-50-529	314
La Crosse Boiling Water Reactor	50-409	255	Palo Verde Nuclear Station, Unit 3	STN-50-530	316
LaSalle County Station, Unit 1	50-373	222	Peach Bottom Atomic Power Station, Unit 2	50-277	79
LaSalle County Station, Unit 2	50-374	226	Peach Bottom Atomic Power Station, Unit 3	50-278	18
Limerick Generating Station, Unit i	50-352	199	Pebble Springs Nuclear Plant, Unit 1	50-514	307
Limerick Generating Station, Unit 2	50-353	201	Pebble Springs Nuclear Plant, Unit 2	50-515	307
Maine Yankee Atomic Power Plant	50-309	119	Perkins Nuclear Station, Unit 1	STN-50-488	303
Manhattan College Research Reactor	50-199	18	Perkins Nuclear Station, Unit 2	STN-50-489	303
Marble Hill Nuclear Station, Unit 1	STN-50-546	325	Perkins Nuclear Station, Unit 3	STN-50-490	304
Marble Hill Nuclear Station, Unit 2	STN-50-547	326	Perry Nuclear Power Plant, Unit 1	50-440	276
Massachusetts Institute of Technology	£0.20	0	Perry Nuclear Power Plant, Unit 2	50-441	280
Research Reactor	50-20		Phipps Bend Nuclear Station, Unit 1	STN-50-553	326
Midland Plant, Unit 1	50-329 50-330	168	Phipps Bend Nuclear Station, Unit 2	STN-50-554	326
Midland Plant, Unit 2		172	Pilgrim Nuclear Power Station, Unit 1	50-293	101
Milistone Nuclear Power Station, Unit 1	50-245	34	Point Beach Nuclear Plant, Unit 1	50-266	62
Millstone Nuclear Power Station, Unit 2	50-336	184	Point Beach Nuclear Plant, Unit 2	50-301	108
Millstone Nuclear Power Station, Unit 3	50-423	269	Prairie Island Nuclear Station, Unit 1	50-282	87
Monticello Nuclear Generating Plant	50-263	58		50-306	118
National Bureau of Standards Reactor	50-184		Prairie Island Nuclear Station, Unit 2		
National Naval Medical Center	50-170	17	Purdue Univ. Research Reactor	50-182	18

Vame	Docket	Page	Name	Docket	Page
Quad-Cities Station, Unit I	50-254	47	Susquehanna Steam Electric Station, Unit 1	50-387	230
Quad-Cities Station, Unit 2	50-265	60	Susquehanna Steam Electric Station, Unit 2	50-388	234
Rancho Seco Nuclear Generating Station	50-312	126	Three Mile Island Nuclear Station, Unit 1	50-289	96
River Bend Station, Unit 1	50-458	297	Three Mile Island Nuclear Station, Unit 2	50-320	144
River Bend Station, Unit 2	50-459	298	Trojan Nuclear Plant	50-344	194
Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	30	Turkey Point Plant, Unit 3	50-250	43
Salem Nuclear Generating Station, Unit 1	50-272	73	Turkey Point Plant, Unit 4	50-251	45
Salem Nuclear Generating Station, Unit 2	50-311	122	UCLA Training Reactor	50-142	13
an Onofre Nuclear Station, Unit 1	50-206	19	Union Carbide Research Reactor	50-54	12
San Onofre Nuclear Station, Unit 2	50-361	206	Univ. of Florida Training Reactor	50-83	13
San Onofre Nuclear Station, Unit 3	50-362	209	Univ. of Illinois Research Reactor	50-151	14
Seabrook Nuclear Station, Unit 1	50-443	284	Univ. of Kansas Research Reactor	50-148	14
eabrook Nuclear Station, Unit 2	50-444	286	Univ. of Lowell Research Reactor	50-223	28
equoyah Nuclear Plant, Unit I	50-327	164	Univ. of Missouri Research Reactor	50-186	18
equoyah Nuclear Plant, Unit 2	50-328	166	Univ. of Texas Research Reactor	50-192	18
hearon Harris Nuclear Power Plant, Unit 1	50-400	248	Univ. of Utah Research Reactor	50-72	13
hearon Harris Nuclear Power Plant, Unit 2	50-401	251	Univ. of Virginia Research Reactor	50-62	12
hearon Harris Nuclear Power Plant, Unit 3	50-402	254	Vermont Yankee Nuclear Power Station	50-271	71
Shearon Harris Nuclear Power Plant, Unit 4	50-403	254	Virgil C. Summer Nuclear Station, Unit 1	50-395	244
Shoreham Nuclear Power Station	50-322	148	Washington State Univ. Research Reactor	50-27	9
Skagit Nuclear Power Project, Unit 1	50-522	309	Waterford Generating Station, Unit 3	50-382	228
Skagit Nuclear Power Project, Unit 2	50-523	310	Watts Bar Nuclear Plant, Unit 1	50-390	238
South Texas Project, Unit 1	STN-50-498	304	Watts Bar Nuclear Plant, Unit 2	50-391	241
South Texas Project, Unit 2	STN-50-499	305	West Valley Reprocessing Plant	50-201	18
Plant, Unit 1	50-335	182	Westinghouse Test Reactor	50-22	9
Init 2	50-389	235	William B. McGuire Nuclear Station, Unit 1	50-369	218
	F3 (1)	12	William B. McGuire Nuclear Station, Unit 2	50-370	221
		303	William H. Zimmer Nuclear Station, Unit 1	50-358	204
		82	Wolf Creek Generating Station	STN-50-482	301

Name	Docket	Page	Name	Docket	Page
WPPSS Nuclear Project, Unit 4	50-513	307	Louisiana Power & Light Co., New Orleans, LA	70-2946	334
WPPSS Nuclear Project, Unit 5	STN-50-509	307	Lower Bucks Hospital, Bristol, PA	70-2792	334
Yankee-Rowe Nuclear Power Station	50-29	9	Missouri, Univ. of, Columbia, MO	70-2789	334
Yellow Creek Nuclear Plant, Unit 1	STN-50-566	327	Nuclear Assurance Corp., Atlanta, GA	70-1510	333
Yellow Creek Nuclear Plant, Unit 2	STN-50-567	327	Nuclear Fuel Services, Inc., Erwin, TN	70-0143	329
Zion Nuclear Power Station, Unit 1	50-295	102	Pan American World Airways, Inc., Patrick AFB, FL	70-0633	331
Zion Nuclear Power Station, Unit 2	50-304	113	Puerto Rico, Univ. of, Mayaguez, PR	70-2873	334
Domestic Licensing of Special Nuclear Material — Docket 70			Rockwell International Corp., Canoga Park, C.		328
Arizona Public Service Co., Phoenix, AZ	70-2949	334	Scioto Memorial Hospital, Portsmouth, OH	70-2748	334
Babcock & Wilcox Co., Apollo, PA	70-0135	329	St. John's Mercy Medical Center, St. Louis, MC		334
Babcock & Wilcox Co., Apollo, PA	70-0364	330	Texas Instruments, Inc., Attleboro, MA	70-0033	328
Babcock & Wilcox Co., Lynchburg, VA	70-0027	328	Tri-State Motor Transit Co., Joplin, MO	70-1739	334
Babcock & Wilcox Co., Lynchburg, VA	70-0824	332	UNC Naval Products, Inc., Uncasville, CT	70-0371	330
Babcock & Wilcox Co., Lynchburg, VA	70-1201	333	Union Carbide Corp., Tuxedo, NY	70-0687	331
California, Univ. of, Los Angeles, CA	70-0223	330	United Nuclear Corp., Wood River Junction, R		331
Cleveland Electric Illuminating Co., Cleveland, OH	70-2968	335	Westinghouse Electric Corp., Pittsburgh, PA	70-1143	332
Colorado State Univ., Ft. Collins, CO	70-0416		Westinghouse Electric Corp., Pittsburgh, PA	70-1151	333
Combustion Engineering, Inc., Windsor, CT	70-0036		Wheaton College, Wheaton, IL	70-0753	331
Combustion Engineering, Inc., Windsor, CT	70-1100		Packaging of Radioactive Material for Transpo-		
Commerce, Dept. of, Washington, DC	70-0398	331	of Radioactive Material Under Certain Condi		
Dow Chemical Co., Midland, MI	70-0278		General Atomic Co.	71-0030	335
Duke Power Co., Charlotte, NC	70-2944		Model: 30A & 30B, Gulf Nuclear Co.	71-9091	337
Duquesne Light Co., Pittsburgh, PA	70-1621	333	Model: 9080, Hittman Nuclear & Development Corp.	71-9080	336
Edlow International Co., Washington, DC	70-1021		Model: CNS 14-195-H, Chem-Nuclear Systems		
Exxon Nuclear Co., Inc., Richland, WA	70-1257		Inc.	71-9094	337
			Model: CNS 21-300, Chem-Nuclear Systems, Inc.	71-9096	337
Florida Power & Light Co., Miami, FL	70-2957		Model: CNS 8-120, Chem-Nuclear Systems, Inc	. 71-6601	335
General Electric Co., Pleasanton, CA	70-0754		Model: CNS-1600, Chem-Nuclear Systems, Inc		336
General Electric Co., Wilmington, NC	70-1113		Model: CNS6-80-2, Chem-Nuclear Systems,		
Harper-Grace Hospitals, Detroit, MI	70-2942		Inc.	71-9111	337
ICN Pharmaceuticals, Inc., Irvine, CA	70-0007		Model: DOT-6M Type B, Babcock & Wilco Co.		335
Lawrence General Hospital, Lawrence, MA	70-2116	334	C-0-	71-5908	333

Name	Docket	Page	Name	Docket	Page
Model: FPD-100, General Atomic Co.	71-9057	336	Model: LP-12, Energy, Dept. of	71-6677	335
Model: FSV-1, General Atomic Co.	71-6346	335	Model: LP-12-1, Energy, Dept. of	71-9964	337
Model: FSV-2, General Atomic Co.	71-6745	336	Model: LP-50, Energy, Dept. of	71-6678	336
Model: FSV-3, General Atomic Co.	71-6347	335	Model: MH-1A, Army, Dept. of	71-6639	335
Model: GE-100, General Electric Co.	71-5926	335	Model: NFS-4, Nuclear Fuel Services, Inc.	71-6698	336
Model: GE-1500, General Electric Co.	71-5939	335	Model: NLI-1/2, NL Industries, Inc.	71-9010	336
Model GE-1600, General Electric Co.	71-9044	336	Model: PAT-2, Energy, Dept. of	71-9150	337
Model: HN-100, Series 1, Hittman Nuclear Development Corp.	& 71-9086	336	Model: R1010-0032, Energy, Dept. of	71-6115	335
Model: HN-100, Series 2, 2A, Hittman Nuclea & Development Corp.	ır 71-9079	336	Model: RG-1, General Atomic Co.	71-6703	336
Model. HN-100, Series 3, Hittman Nuclear &			Model: TRIGA-1, General Atomic Co.	71-9034	336
Development Corp.	71-9151	337	Model: TRIGA-2, General Atomic Co.	71-9037	336
Model: HN-100S, Hittman Nuclear & Development Corp.	71-9089	337	Model: Type B, Amersham Corp.	71-9167	337
Model: HN-200, Hittman Nuclear & Development Corp.	71-6574	335	Model: UCC-20WC-2 & 2A, Union Carbide Corp.	71-9098	337
Model: 1F-300, General Electric Co.	71-9001	336	Monroe: X-Ray Co., Inc.	71-0481	333

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES DICKET 27-010 BEATTY, NV. U S ECOLOGY, INC.

219260304 PND-V-B2 044 on 821012 shipment of low level radwaste received from GE Vallecttos Nuclear Ctr containing box w/hole in side Administrative penalty of \$1500 levied Permit suspended indefinitely
PMCMAS.R D Region 5, Orfice of Director 82/10/19 ip 15901 264

DOCKET 27-039 SHEFFIELD. IL. U.S. ECOLOGY, INC

- 8210120320 Summary of 820908 steering committee meeting w/IDNS, State of IL USGS & US Ecology to discuss results of Phase II portion or tritium migration study & to determine need for Phase II investigations Exhibits encl
 SIEFKEN, D.L. Low Level Waste Licensing Branch 82/09/20
 HANKINS, E.F. Low Level Waste Licensing Branch 6pp 15689 236
- 6210120411 Notification of contract execution.Mod 5 to "Sheffield Trench Cap Study " Contractor Univ of IL FLEENDR.G M Technical Assistance Contracts Dranch FIN 8-4945-2 82/09/28 DAVIS.J. SIEFKEN.D Office of Nuclear Material Safety & Safeguards.Director 1p 15691 167
- --8210120419 Mod 5 revising task repts delivery schedule.increasing estimated cost.revising voucher submittal & substituting updated Manual Chapter 3202, to "Sheffield Trench Cap Study "PORTER.F W [llinnis. Univ of Urbana-Champaigp HAQAN.T FDivision of Contracts FIN B-6969-2 62/09/28 4pp 15691 166
- 62(0090095 Joint motion to continue proceedings until 830201 to provide add time for settlement negotiations Certificate of S.c enct
 LESSY,R P Hearing Branch 3 WETTERHAIN,M J US Ecology,
 Inc (Formerly Nuclear Engineering) 82/10/01 Atomic Gafety and Licensing Board Panel 3pp 15604 236
- 8210080075 Order granting NRC & applicant joint motion to continue proceedings until 830201
 COODHOPE,A C Alouic Safety and Licensing Doard Panel 82/10/06
 Office of the Executive Legal Director 1p 15643 267

DOCKET 27-047 BARNWELL, SC. CHEM-NUCLEAR SYSTEMS, INC.

- R2[0]20135 Consents to transfer of Licenses 46-13536-01 & 46-19524-01 rom Chem-Nuclear Bys.inc to WMI Holdings.inc All existing obligations & responsibilities under current license will be applicable to & binding upon subsidiary DAVIS.J Q Office of Nuclear Material Safety & Safeguards.Director 82/09/07 HUIZENGA.P Haste Management. Inc 2pp 15492-147
- E210120144 Confirms 820910 arrangements for J Davis 820921 site visit prior to attending 820923-24 meetings in Atlanta, GA PANGBURA, GC Low Level Waste Licensing Branch 82/09/13 PURVIS, J Chem-Nuclear Systems, Inc. ip 15692 170
- 8210120465 Trip rept of 820701-02 visit to Columbia, BC to attend State of SC hearings on qualifications of Haste Mgt. Inc to conduct radioactive matls operations under licenses currently held by Chem-Nuclear, Inc PANOBURN, O C Low Level Haste Licensing Branch 82/07/17 HAWKINS. Ef Low Level Haste Licensing Branch 4pp 15671 306

DOCKET 27-048 RICHLAND, WA, U.S. ECOLOGY, INC.

5210130130 PNO-V-82-040 on 821004 notified that shipment of low level radwaste received on 820927 from Smith Kline & French Labs was in violation of BOT regulations 490FR173 393(d) & 172 403(b) Vendor license suspended effective 820928 THEMASIR D Region 5. Office of Director 82/10/05 [p 15673 039]

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0017 DOW CHEMICAL CO , MIDLAND, MI

- 8210180028 Responds to FOIA request for seven categories of documents re Dow Chemical Co & incineration of low level radwastr Request for fee waiver granted Forwards listed documents FELTON.J M Division of Rules and Records 82/08/20 MILSON.A K Affiliation Unknown 2pp 15748 002 24% Fiche 50-264.82/08/20, 8210180029
- --B210180239 Application for renewal of Hat1/Byproduct Licenses 21-00265-06,21-00265-02,21-00265-04,21-00265-07,BNM-1293, STD-527 & R-10B authorizing any byproduct mat1 between Atomic Numbers 3 & B3,tiltium.Po-210 & Am-241 HOYLE-H R Dow Chemical Co 73/08/25 2pp 15748 115 24X Fiche 50-264,82/08/20,8210180028
- DOCKET 40-0299 UNION CARBIDE CORP , GRAND JUNCTION, CO
- 8210250017 Forwards "Investigation of Elevated Radioactivity Measurements Around Union Carbide Corp Inactive Tailings Area in Gas Hills.HY." per License Amend 10 WONG.T Union Carbide Corp 82/0//30 PETTENCILL.H Uranium Recovery Licensing Branch ip 19808 260
- --8210250021 "Investigation of E)evated Radioactivity Measurements Around Valon Carbide Carp Inactive Tailings Area in Oas Hills, HY " * Union Carbide Carp 82/07/30 10pp 15808 261
- 8210190246 Forwards "Spaintual ALARA Rept, Jan-June 1982," per Licouse Condition 17 WONG. T. Union Carbide Corp. 82/09/03 LYONS, P.J. Uranium Recovery Licensing Branch tp. 15759 001
- --8210190256 "Semiannual ALARA Rept. Jan-June 1982 " One gyersize map encl Aperture card is available in PDR 4 Union Carbide Corp 82/09/03 531pp 15759 003
- 8210130607 Requests written declaration of intent or interest in two listed tallings situations resulting in pollution & contamination of groundwaters of State of WY FRANCIS.E. Wyoming, State of 62/09/07 LINEHAN.J. Uranium Recovery Licensing Granch. 3pp. 13692-335
- 8210220491 Forwards revised lower limits of detection for Ra-226 & Th-230 in water LYONS, P J Union Carbide Corp 82/09/22 PETTENOILL, H Division of Fuel Cycle & Material Safety 2pp 13786 321
- 8210210530 Requests detailed breakdown of revised reclamation cost estimate in order to complete evaluation of 820804 submittel Info should be provided by 821030 PETTENGILL.H J Uranium Recovery Licensing Branch 82/09/30 LYONS,F Union Carbide Corp 2pp 15782 323

- DOCKET 40-1162 WESTERN NUCLEAR CORP , JEFFREY CETY, HY
- 82/0220123 Forwards IE Insp Rept 40-1162/82-02 on 820901 No noncompliance noted EROWLO D Division of Vendor & Technical Programs 82/09/28 WELLER, T Hestern Nuclear, Inc (subs of Phelps Dodge Corp) 2pp 15778 141
- --B21022012B IE Jnsp Rept 40-1162/82-02 on B20901 No noncompliance noted Major areas snspected V mill waste mgt activities ENDPENNIN M . CAIN.C L . EVERETT.R J Division of Vendor & Technical Programs B2/09/21 App 15778 143
- 8210220475 Submits review of Split Rock Hill 820630 annual technical evaluation of performance of tailings embankment Embankment performed as sipected No further action necessary GARCIA.P. J. Uranium Recovery Licensing Branch 82/10/05 Uranium Recovery Licensing Branch 2pp 15786-323
- DUCKET 40-1202 NL INDUSTRIES, INC . HIAGARA FALLS, NY
- 0210010418 Forwards IE Insp Rept 40-1202/02-01 Inquiry conducted to determine whether formerly licensed site meets current criteria for release for ubrestricted use kINNEMAN, J D. Division of Engineering & Technical Programs 82/09/23 JACOSS, J L. NL Industries, Inc. 2pp. 15570-217
- --8210010428 IE Insp Rept 40-1202/82-01 on B20595-0702 Inquiry conducted to determine whether formerly licensed site meets current criteria for priesse for unrestricted use Site meets criteria undansen, J H, KINNEMAN, J H Region 1, Office of Director 62/08/02 3pp 15570 219
- --8210010434 Forwards "Summary of Radiological Survey of NL Industries Mingrare Falls Plank," final rept JACOBS.J L NL Industries: Inc 62/05/24 JOHANSEN, J Region f. Office of Director 2pp 18570 222
- --8210010440 "Summary of Radiological Survey of NL Industries Niagera Falts Plant:" final rept LEIGH,D W NL Industries, Inc. 79/05/31 129pp 15570 224
- DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANDOGA, IN
- 8210050422 FINAL ENVIRONMENTAL STATEMENT RELATED TO THE DECOMMISSIONING OF EDGEMONT URANIUM MILL Decist No 40-1941 (Tennessee Valley Authority)

 Office of Nuclear Material Bafety & Safequards Director Nurse0-0846 82/06/30 320pp Available at NRC \$9.00 15623 074
- DOCKET 40-2061 KERR-HOGEE CHEHICAL CORP . DKLAHOMA CITY, OK
- 8210270077 Forwards fee for 820806 application to amend License STA-583 to allow dismantling of Bldgs 2.10.11 & 21 SMELLEY.N J Kerr-McGee Corp 82/09/14 WEISS.D License Fee Management Branch 1p 15836 214
- --B21027008B Application for amend to License STA-583 to allow dismantling of Bidgs 2.10.11 & 21
 SMELLEY, W J Kerr-Higges Corp B2/08/06 NIXON, W A Uranjum Fuel Licensing Branch 2pp 15836 216
- --8210270091 Requests payment of amend fee needed to process EQ0806 application for amend to License STA-583 to allow dismantling of Bidgs 2, 10, 11 & 21 HEISS, D. License Fee Management Branch 82/09/01 SHELLEY, W. J. Kerr-HcGee Corp. 1p 15836 215
- BRIO120187 Order designating NMSS Deputy Director to act as presiding officer to conduct hearing on Amend 5 Certificate of Svc enc]
 DAVIS-J O Diffice of Nuclear Material Safety & Safeguards, Director 82/10/05 Office of Nuclear Material Safety & Safeguards, Director 2pp 13651 235
- 8210150463 Requests info on hearing to be held per Commission 820806 Order CLI-82-21 Response should define rules for procedure, discovery & subpoense & should establish schedule SPELMAN.H.J. Harold J. Spelman & Associates 82/10/12 HOYLE.J.C. Office of the Secretary of the Commission 10 15703 inch.

- 82(0280434 Responds to 920706 ltr commenting on DES se decommissioning of Kerr-McGee Rare Earths facility Final statement will recognize site as alternative storage/disposal site for other residues in West Chicago. IL CUNNINGHAMAR E Division of Fuel Cycle & Material Safety \$\text{\$B1/10/15}\$ CAMILLER C Environmental Protection Agency \$\text{\$Qp}\$ \$\frac{1560}{45}\$ \$\text{\$Q45}\$
- 8210250315 Response to Kerr-McGee 820923 request for consolidation of License Amend & w/License Amend 5 for hearing purposes City does not object 5vc list enci SPELMAIN J West Chicago, IL SPELMAN, H J Harald J Spelman & Associates 82/10/22 Commissioners 3pp 15790 221
- DOCKET 40-2259 PATHFINDER MINES CORP , RIVERTON, WY
- 8210270054 Trip rept of 820826 site visit to templete annual inter FRANCIS.E , KEARNEY.B Pathfinder Mines Corp 82/08/26 Pathfinder Mines Corp 2pp 15836 [1]
- 8210150607 Forwards "Quarterly Effluent Monitoring Rept.Apr Jono 1992." per License Conditions 51 & 54 NUCEHICE L Pathfinder Mines Corp 82/08/31 SCARAND, R A Uranium Recovery Licensing Branch 1p 157(5 320
- --8210150613 "Quarterly Efficent Monitoring Rept. Apri-June 1982" " History oversite map encl Aperture card is available in PBR * Pathfinder Mines Corp 82/08/31 13pp 15715 321
- 8210130607 Requests written declaration of intent or interest in two listed tailings situations resulting in pollution & contamination of groundwaters of State of My FRANCIS.E Hyoming State of 82/09/07 LINCHAN. J Uranium Recovery Licensing Branch 3pp 15692 335
- 8210120514 Advises that equipment cost analysis tailings pend reclamation bend analysis & reclamation bend summary consistent w/approved reclamation plan for Pathfinder Lucky Mc Mill tailings pend SOLLENSERGER, D. PETTCNOILL, H. J. Uranium Recovery Licensing Biochem 82/09/20 Uranium Recovery Licensing Branch 3pp 15672 072
- 6210220161 Forwards 1E Insp Rept 40-2259/62-01 on 620727-29 % notice of violation BRCWN,0 D Division of Vendor & Technical Programs 62/09/27 NUGENT,EL Pathfinder Mines Corp 2pp 15770 038
- ~-8210220165 Natice of violation from insp on 820727-29 * Division of Vendor & Technical Programs 82/09/27 fp 15778 060
- --8210220171 IE Insp Rept 40:2259/82-01 on 020727-29 Noncompliance duted failure of personnel to shower or monitor for contamination prior to leaving mill restricted area MHITTEM JE, DROWN, RC or EVERETTR J Division of Vendor & Technical Programs 82/09/17 lipp 15778 064
- DECKET 40-3392 ALLIED CHEMICAL CORP , MORRISTONN, NJ
- \$210150600 Informs that drawings in 920701 application for renowal of License SUB-526 are not proprietary CIPOLLAA J Allied Chemical Copp 82709717 PAGE.R O Uranium Fuel Licensing Branch ip 15716-336
- DOCKET 40-3453 ATLAS MINERAL, INC . DENVER, CO
- 8210260079 Forwards second quarter 1982 quarterly rept re sampling & analysis results of environ monitoring program per License Canditions 42,43 & 47
 EDWARDS, D.L. Atlas Minerals 82/08/18 BCARAND, R A Uranium Recovery Licensing Branch 2pp 15810 257
- --8210260080 Second quarter 1982 sampling analysis results of environ manitoring program • Atlas Minerals 82/08/18 70pp 15810 289
- 8210150596 Responds to MRC 820728 ltr requesting proposed site for relocation of background station used to monitor environ air quality Tables re wind direction chemical concentration & resident exposure enci.

 BLUBAUOH,R E Atlas Minerals governo ---

- 8210210021 Reviews first quarter 1982 environ monitoring data & dose calculations for nearest receptor required by License Condition 47 Compliance w/40CFR190 stds will be determined when new site becomes operational UARCIA.P J PETTENGILL.H J Uranium Recovery Licensing Branch 82/09/20 Uranium Recovery Licensing Branch 4pp 15782 215
- 8210210521 Issues Amend 10 to License SUA-917 in response to 811204 request & revised by 820428 itr Amend adds Condition 54 delineating line of authority between radiation safety coordinator & onsite individual SMITALR D Uranium Recovery Licensing Branch 82/09/30 Atlas Minerals 2pp 15782 311
- 8210210525 Recommends issuance of Amend 10 to License SUA-917 in response to 811204 request 2 revised by 820428 ltr Amend adds Condition 54 delineating line of authority between radiation safety officer 2 onsite individual GARCIA-P J PETTEMBILL-H J Uranium Recovery Licensing Branch 82/07/30 Uranium Recovery Licensing Branch 52/07/30 Uranium Recovery Licensing Branch
- DOCKET 40-6622 PATHFINDER MINES CORP . SHIRLEY BASIN, WY
- 8710250028 Forwards State of WY 820721 request for info re tailings seepage & 820727 response RUSSELL JE Pathfinder Mines Corp 82/07/29 PETTENGILL,H NRC No Detailed Affiliation Given 5pp 15798 343
- 82(0150601 Forwards one oversise revised topographic map per Liconse Condition 41 Aperture card is available in PDR SMITH, J.C. Pathfinder Mines Corp. 82/08/06. Uranium Recovery Licensing Branch 1p. 15715-335
- BCI0180415 Forwards "Subsurface Migration Update & Answers to NRC Questions" MURDOCY E S Pathfinder Mines Corp 82/08/06 SDLLENBERGER, D Uranium Recovery Licensing Branch ip 15747 220
- -- #210183420 "Subsurface Migration Update & Answers to NRC Questions "
 Eight oversize drawings enc? Aperture cards are available in
 PDR
 (JRDDCK, E S , SMITH, J C Pathfinder Mines Corp 82/03/31 /4pp
 15747 221
- B_z 10070383 Forwards IE Insp Rept 40-6622/82-02 on 620713-16 & notice or violation 3RCVII.0 D Division of Vendor & Technical Programs 82/08/13 RUSSELL.JE Pathfinder Mines Corp 2pp 15633-318
- -0210070305 Notice of violation from insp on 020713-16

 Division of Vendor's Technical Programs 82/08/13 2pp 15-33 320
- --82i0070394 IE Insp Rept 40-6622/82-02 on 820713-16 Noncompliance noted on 820715.audible alarm setpoint on survey instrument adjusted to level exceeding acceptable limit CAIN.C.L. MURRAY.B. EVERETT.R.J. Division of Vendor & Technicai Programs 82/08/10 9pp 15633 322
- 82:0260013 Forwards revised environ QA program.per Amend 7 to License SWITH.J C Pathfinder Mines Corp 82/08/30 Uranium Recovery Licensing Branch 1p 15814 160
- --8210260014 Revised environ QA program
 Pathfinder Mines Corp 82/08/31 92pp 15814 161
- 8210290177 Forwards stability review for Number 5 embankment per Condition 42 of Amend 8 to License SUA-442 Rept gives strong evidence that Number 5 embankment functioning according to design features RUSSELL, J E Pathfinder Mines Corp 82/09/14 SOLLENBERO Uranium Recovery Licensing Branch 11pp 15876 233
- 6210120644 Advises that preliminary review of application for renewal of License SUA-442 complete General content acceptable but addi info will be needed Current license valid during period of review of renewal application PETTROBLEL U Uranium Recovery Licensing Branch 62/09/20 RITCHIE,M I Pathfinder Mines Corp ip 15684 233
- 8210220464 Ack receipt of 820903 ltr informing NRC of steps taken to correct violations noted in IE insprept GROWN 0 Region 4. Office of Director 82/09/27 RUBBELL, J E Pathfinder Mines Corp ip 15779 130

- --8210220476 Responds to NRC 820813 itr re violations noted in IE insprept Corrective actions high audible alarm setpoint reset Monthly surface contamination survey procedures improved RUSSELL, JE Pathfinder Mines Corp 82/09/03 BROWN, 0 D Region 4, Orfice of Director 2pp 15779 131
- DOCKET 40-6659 GETTY DIL CO PETROTOMICS CD , SHIRLEY BASIN, WY
- 8210220510 Forwards correspondence to & from State of MY re unauthorized disposal of radwaste in U mill tailings disposal facilities PFAFF,S J Getty Oil Co (Petrotomics) 82/08/26 PETTENGILL.H J Uranium Recovery Licensing Branch 4pp 15786 119
- 8210210254 Forwards marked-up ltr from Getty Gil Co to State of WY indicating that requested info re wells & piezometers is on file at NRC Expresses desire for interagency cooperation ACKERMAN. W C Wyoming, State of 82/09/14 SMITH, D Division of Waste Management 4pp 15774 320
- 8210120628 Advises that remedial actions proposed by licensee in response to 8iiii3 IE Miil Appraisal Rept 40-6657/81-01 sufficient to correct weaknesses No licensing action will be required JONES, 2 , GARCIA, P J Uranium Recovery Licensing Branch 82/09/20 Uranium Recovery Licensing Branch 2pp 15672 269
- 6210210527 Reviews environ monitoring data & 40GFR190 dose calculations for Petrotomics Mill.in response to B20604 itr NRC Loneurs Wiresults submitted by licensee
 JONES, S Z , PETTENGILL, H J Uranium Recovery Licensing Branch 62/09/30 Uranium Recovery Licensing Branch 5pp 15782 31B
- DOCKET 40-7580 FANSTEEL, INC , NORTH CHICAGO, IL
- 8210280180 Ack receipt of 820908 itr informing NRC of steps taken to correct violations nated in NRC 820813 itr & notice of violation Addi info requested within 10 days BROWN, 0 D Division of Vendor & Technical Programs 82/10/25 PIERRET, J A Fanstee| Metals (subs of Fansteel, Inc.) (p. 15892-019
- --8210280184 Responds to NRC 820813] tr & notice of violation Corrective actions portable radiation detection instruments calibragainst two refs & logged in lab log book PIERRET, J A Fansteel Metals (subs of Fansteel inc.) 82/09/00 BROWN, 0 D Division of Vendor & Technical Programs 1p 15837 020
- DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- B210260543 Forwards application for amend to License 8UB-1010 to construct & operate sludge calcining plant for purpose of converting raffinate sludge to readily disposable form SHELLEY, H J Kerr-McGee Corp B2/09/01 PAGE, R G Uranium Fuel Licensing Branch 3pp 15831 091
- --B2iO260548 Application for amend to License SUB-iOiO to construct & operate sludge calcining pient for purpose of converting raffinate sludgo to readily disposable form Oversize drawings encl Aperture cards available in FDR # Kerr-McGee Corp 82/09/01 133pp 15831 094
- 8210260565 Forwards OX State Dept of Health, Industrial Waste Mgt Div B20824 itr transmitting draft permit for use of deep disposal well for permanent disposal of treated raffinate, in ref to application for amend to License SUB-1010 8HELLEY, W J Kerr-McOee Corp 82/08/22 PAOE, R O Uranium Fuel Licensing Branch 6pp 15814 349
- 8210260576 Forwards initial comments on DK State Dept of Health draft permit for use of deep disposal well & replacement Page I to permit correcting nitrogen limit Page should be inserted into 820826 Version SHELLEY, W.J. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.) 82/08/31 PAGE, R. & Uranium Fuel Licensing Branch. 3pp. 13814-361
- 82:02204B7 Responds to 820824 itr outlining addit requirements for injection well permit Requests option to operate well at pressures equal to pump capacity of 400 psi Const methods & map of proposed monitoring location enci SHELLEY.W J Kerr-McGe-Nuclear Corp 82/09/17 HENSCH.D A Offichama, State of 7pp 15786-325

- 8210270242 Forwards application for renewal of License SUB-1010 Renewal fee encl SHELLEY, W. J. Kerr-McGee Corp. 82/09/24 PAGE, R. Q. Uranium Fuel Licensing Branch Jop. 15849 175
- --B210270247 Application for renewal of License SUB-1010 to refine U from yellowcake to convert U to pure U herafluoride Tharty-five oversize drawings encl Aperture cards available in PDR SHELLEY, N J Kerr-McGee Corp B2/09/24 328pp 15849 178

DOCKET 40-8084 RID ALGOM CORP . MOAB. UT

82/02/0515 Reviews two const repts for 15-ft embankment raise in Rio Algom Corp lower tailings dam performed by Dames & Moore & Region 4 No further action required by licenses MODLSEY.R T . PETTENGILL.H J Uranium Recovery Licensing Branch 82/09/30 Uranium Recovery Licensing Branch 4pp 15782 307

DOCKET 40-8102 EXXON CO USA, HOUSTON, TX

- 8210270195 Forwards "Environ Monitoring Data for Second Guarter, 1982, "
 pursuant to License Condition 36, including close evaluation
 at nearest residence & results of environ monitoring
 program
 YARNICK.T P Eiron Nuclear Co . Inc (subs of Exxon Corp.)
 82/09/02 PETIENGILL.H J Uranium Recovery Licensing Branch ip
 15833 349
- --8210270197 "Environ Homstoring Data for Second Guarter, 1782 "
 * Erron Nuclear Co : Inc (subs of Erron Corp) 82/09/02
 14pp 15835 350
- 8210260597 Forwards summary of airborne emissions of principal radionuclides & "Semiannual ALARA Rept. Jan-June 1982," pursuant to License Conditions 14 & 35 No liquid effluents discharged to unrestricted areas YARNICKLT Exxon Nuclear Co. Inc. (subs. of Exxon Corp.) 82/09703 Uranium Recovery Licensing Dranch. 3pp. 15830-260
- --8210260560 "Semiannual ALARA Rept. Jan-June 1982 "

 * Exten Nuclear Co., Inc. (subs. of Exten Corp.) 82/09/03
 75pp 18830 265
- 82(0120529 Advises that Erron general emergency action plans, submitted w/820526 ltr. are acceptable Condition if to License SUA-1139 should be amended as listed JONES 2 / PETTENDILL.H J Uranium Recovery Licensing Branch 82/09/23 Uranium Recovery Licensing Branch 2pp 15672 204
- B210120598 Natifies of issuance of Amend 3 to License SUA-1139, revising License Condition 25 re emergency preparedness SKITH-R D Uranium Recovery Licensing Branch B2/09/23 Exxonorp p 15672 350
- 8210150432 Advises that no additees for review of application for Amend 2 to License SUA-1139 required MILLER: NO License Fee Management Branch 82/10/07 GILCHRIST. J E Exon Corp. ip. 15715-359
- BOCKET 40-8111 KENNECOTT COPPER CORP , SALT LAKE CITY, UT
- 8210220066 Advises that NRC closed out license files when license expired in 1976 w/o closeout survey Facility meets NRC criteria for unrestricted use CARRICO, J B Licensing Management Branch 82/10/01 FOLSOM, B Kenneset Cons

- --8210220080 Source Matt License SUA-1106 for Kennecott Copper Corp authorizing possession of 2,000 kg U MALARD, J C Atomic Energy Commission 71/12/15 ip 15786 258
- --8210220086 Application for amend to License SVA-1106 licensing plant for storage only of refined product SPEDDEN,H R Kennecatt Copper Corp 73/11/12 MALARO,J C Atomic Energy Commission 2pp 15786 259
- --82(0220089 Certificate of disposition of matts matt disposed in compliance w/10CFR20

 4 Office of Nuclear Material Safety & Safeguards Director 76/12/17 ip 15766 260
- --8210220092 Confirms recent telcoms re unrestricted use of facility Radiation surveys to be performed & results sent to NRC CARRICOLU D Licensing Hanagement Branch 82/04/01 FOLSOM, D Kennecott Copper Corp 15pp 15788 281

DOCKET 40-8153 LEBARON STEEL FOUNDRY, LEBANON, PA

- 8210270370 Application for renewal of Source Matl License 8U8-1146authorizing possession of 56 kg U-235.enriched to less than O 4X, for use in area radiation sys ARNOLD M L Lebamon Steel Foundry 82/09/23 5pp 15835 001
- DOCKET 40-8355 AMAX SPECIALITY METALS CORP . PARKERSOURG. WV
- 8205240003 Forwards EIA of proposed site stabilization at AMAX, Inc NI/QN, W A Uranium Fuel Licensing Branch 82/05/05 KERRIGAN, J AMAX, Inc 1p 15612 022
- --8205240010 Negative declaration re storage of contaminated soil un license PAOE:R G Uranium Fuel Licensing Branch 82/05/03 App 15612 023
- --8205240006 ElA supporting proposed site stabilization

 * Office of Nuclear Material Safety & Safeguards, Director
 82/04/30 90pp 15612 025
- DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO . BROOMFIELD. CO
- B2101B0398 Forwards "Groundwater Restoration Rept for Rocky Mountain Energy-Halliburton-Mono Power Nine Mile Lake R&D in Situ U Project " MEUIAANN, M R Rocky Mountain Energy Co 82/08/30 NEUMANN, M R Uranium Recovery Licensing Branch ACKERMAN, H , GARLAND, B Wyomi State of 2pp 15747 001
- --B210180405 "Oroundwater Restoration Rept for Rocky Mountain Energy Halliburton-Hono Pouer Nine Mile Late R&D In Situ U Project "One oversize map encl Aperture card is available in PDR e Rocky Mountain Energy Co 82/06/21 216pp 15747 004

DOCKET 40-8452 BEAR CREEK URANIUM CD , CASPER, WY

- 8210150644 Forwards gradation results for Zone III sandstone in tailings disposal area in response to 820806 ltr Gradation tests for Zone IV claystone also submitted MEDLOCK, R. L. Bear Creet Uranium Co. 82/08/20 BCARANO, R. A. FETTENGILLIH J. Uranium Recovery Licensing Branch 13pp 15715 292
- 8210260084 Forwards Self-Bond BCU397-01 to Permit 399 for Bear Creek U Co BRYAN,V J Hyoming, State of 82/08/20 FLORY,C Uranium Recavi Licensing Branch 4pp 15814 149
- 8210280446 Forwards self-bond indemnity agreement to Permit 379 for Bear Creek U Mill between State of MY Dept of Environ Quality & Union Pacific Corp Vendor agreed to indemnify any Hability incurred by Bear Creek BRYAN, V. J. Wyoming: State of 82/08/30 FLORY, C. Uranium Recove Licensing Branch 5pp 15858 350
- 8210120634 Reviews first quarter 1982 environ monitoring data & dose calculations for Bear Creek U Hill License Conditions 19,49 & 54 estisfied.

 FLORY.C.A , PETTENGILL, H J Uranium Recovery Licensing Branch 82/09/20. Uranium Recovery Licensing Branch 5pp 15672 273

1

DOCKET 40-8502 HYDMING MINERAL CORP . LAKEHOOD, CO

- E.,10270180 Forwards "Trigdray Mine Site, Bemiannual Activity & Monitoring Rept. Jan-June. 1982"
 COMOY. B W Hyoming Mineral Corp 82/08/25 Region 4. (
 Director 2pp 15835-332 Region 4. Office of
- --8210270183 "Irigaray Mine Site, Semiannual Activity & Monitoring Rept, Jan-June, 1982 # Hyoming Mineral Corp 82/08/25 14pp 15835 334
- 8210040338 Discusses amnonia-nitrate relationships applied to groundwater restoration at MY Mineral Corp Inigaray U Solution Mining Project in FES & responses to comments on DES LOGSDON,M J. LINEHAN, J. Uransum Recovery Licensing Branch B2/09/07 Uransum Recovery Licensing Branch 3pp 15597 182
- DECKET 40-8577 AIR FORCE, DEPT OF, VANDENBERG AFB, CA
- 02:10270179 Forwards application for amend to License SUB-1289, reflecting changes in Western Space & Missile Ctr radiation protection committee & use of TLD instead of film badges BOLLINGER.L J Air Force. Dept of, Radioisotope Committee Division of Fuel Cycle & Material Safety 4pp 15835 023
- --82(0270192 Application for amend to License SUB-1289, reflecting changes in Western Space * Missile Ctr radiation protection committee Personnel resumes encl
 HEINT.E.L. Air Force.Dept of, Radioisotope Committee 82/09/14
 32pp 19835 027
- DUCKET 40-8602 SILVER KING MINES, INC , CASPER, MY
- 5210250054 Forwards "Preoperational Radiological Environ Monitoring Rept. Jan-June 1982" WOLFF.C E Silver King Haming, Inc. 82/08/27 SCARANG,R A Uranium Recovery Licensing Branch 3pp. 15808 014
- ~-8210250056 "Preoperational Radiological Environ Monitoring Rept. Jan-June, 1782" # Silver King Mining, Inc. 82/08/27 109pp 15808 019
- 821027004G Forwards three warranty deeds per 82081O telcon All deeds to be assigned to Silver King Mine.Inc. as trustee For TVA Deeds Fulfill land ownership requirements WDLFF.C E Silver King Mining. Inc. 82/08/20 PANTELL.S Division of Fuel Cycle & Material Safety 16pp 15836 086
- DUCKET 40-8610 STEPAN CHEMICAL CO . MAYWOOD, NJ
- 8210260341 Forwards QA Program Insp Rept 99770001/82-13 on 820923 No mancompliance noted KJNNEMAN, JD Region 1. Office of Dyrector, 82/10/22 FIGRE, R A Maywood, NJ FIGRE, R A Fiore & Jaskot 2pp 15803 033
- --8210260345 GA Program Insp Rept 99970001/82-13 on 820923 No בישנטטיטיט מא rrogram insp Rept אין אין אין 1001/82-13 on B20923 No nonconpliance noted Major areas inspected measurement of radiation levels & gathering of sediment samples in & along Coles Brook. Maywood. NJ JUHANEEN J. KINNEMANJ D. Region 1. Office of Director B2/10/21 6pp 15803 035
- -- 8210260352 Requests info on whether proposed stream clearance project would create hazard re radioactive contamination in vicinity of brook Exetches encl or or ox statenes ent FIGRE,R A Maywood, NJ FIGRE,R A Fibre & Jaskot 8; KINNEMAN,J D Region 1, Office of Director COSOLITO,F Jersey, State of 4pp 15803 041
- DOCKET 40-8632 ARMY, DEPT OF, CHAMBERSBURG, PA
- 8210270222 Forwards application to amend License SUC-1380 to allow Division of Fuel Cycle & Material

- --8210270227 Application for amend to License 5VC-1380 to allow 2102/022/ Application for amend to License SUC-1380 to Allow staballow to be used interchangeably w/depleted U when referring to U alloys
 SHITH.LE Army.Dept of, Headquarters Materiel Development & Readiness Command 82/08/20 Division of Fuel Cycle & Material Safety 2pp 15836-044
- DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC , DENVER, CO
- 8210220516 Submits questions re Amend 8. Condition 18 to License ElQ22016 Submits questions re Amend Bicondition 19 to License SUA-1358 Rewording of composition of internal audit committee suggested to allow for reorganization DAKER,C E Energy Fuels Nuclear, Inc 82/08/20 Olllen,D Uranium Recovery Licensing Branch 2pp 15786 086
- 8210250034 Application for amend to License SUA-1358, revising representation on internal audit committee & recipient of semiannual ALARA audits DAKER, C E Energy Fuels Nuclear, Inc. 82/08/20 GILLEN, D. Uranium Recovery Licensing Branch 2pp 15808 347
- 8210250006 Forwards "Effluent & Monitoring Rept.Apr-June 1982" BAKER: CE Energy Fuel's Nuclear, Inc 82/08/27 GILLEN.D Uranium Recovery Licensing Branch 1p 15808 135
- --8210250008 "Effluent & Monstoring Rept.Apr-June 1982 "
 * Energy Fuels Nuclear, Inc 82/08/27 45pp 158 1580A 136
- 8210260017 Forwards "Semiannual ALARA Audit Rept for Energy Fuels Nuclear, Inc White Mesa U Mill, Blanding, UT " BAKER.C E Energy Fuels Nuclear, Inc 82/08/31 VINCELETTE, M D Energy Fuels Nuclear, Inc 1p 15814 305
- --8210260018 "Semiannual ALARA Audit Rept for Energy Fuels Nuclear Inc White Mesa U Milli Dianding UT " * Energy Fuels Nuclear Inc 82/08/31 11pp 15814 306
- B2(026022 Application for amend to License SUA-1358, authorizing discharge of tailings into Cell 3 prior to completion of const of Cell 4 safety dike Progressive const of safety dike will contain vol of potential spill DAKER.C E Energy Fuels Nuclear. Inc. 82/09/02 GILLEN.D Uranium Recovery Licensing Branch 3pp 15814 318
- 8210270209 Advises that schedule for initiation of const on Cell 3 safety dike at White Mesa will be delayed 1 wk beyond date set forth in 820408 ltr Completion of safety dike may be delayed until Spring 1933
 DAKER.C E Energy Fuels Nuclear, Inc 82/09/03 GILLEN,D Uranium
 Recovery Licensing Branch ip 13834 034
- 8210270435 Forwards "Tailings Cover Design Revision" In response to NRC 620812 request for info re application for amend to License 8UA-1358 Proposed reduction in thickness of tailings reclamation cover adequate DAKER.C E Energy Fuels Nuclear. Inc 82/09/03 GILLEN.D Uran Recovery Licensing Branch | p | 15833 CO1 82/09/03 GILLEN, D Uranium
- --8210270439 "Tailings Cover Design Revision "
 * D'Appolonia Consulting Engineers, Inc. 82/08/28 55pp
- 8210040363 Notlification of 820913 meeting w/Energy Fuels Nuclear in Silver Epring: MD to discuss White Mesa facility reclamation plan: associated costs & proposed surety arrangements CILLEN.D M Uranium Recovery Licensing Branch 82/09/09 LINEHAN.J J. PETTENBILL: H J. FLENING: T.E. NRC No Detailed Affiliation Given 2pp 15597 191
- 6210120641 Recommends no action be taken on licensee request for hearing on license amend to require suresty for decommissioning & reclamation Issue may be mooted by licensee submittel of revised reclamation plan LINEHAN.J Uranium Recovery Licensing Branch 82/09/17 KLUGSIK.J F Office of the Central Counsel Ip 15672 278
- 8210210532 Issues Amend 15 to License SUA-1358, in response to 820902 request Amend adds Item 9 to License Condition 26 allowing licenses to forego const of Cell 3 safety dike SMITHAR D Uranium Recovery Licensing Branch 82/09/30 Energy Fuels Nuclear, Inc. Ip 15782 325 Energy
- --8210210534 Recommends issuance of Amend 15 to License SUA-1358, in response to 820902 request Amend adds Itam g to License Condition 26 allowing licensee to forego const of Cell 3 greety dike
 GILLEN,D M Uranlum Recovery Licansing Branch 82/10/04
 Uranium Recovery Licensing Branch 2pp 15782 326.

DOCKET 40-8697 ROCKY HOUNTAIN ENERGY CO , DENVER, CO

- 82(028045) Advises that differences identified in two lab finding for potassium values due to different lab procedures or lab capabilities Differences in pH values due to NML reporting field values
 SCHHITIDIEL.P Hyoming, State of 82/04/27 Hyoming, State of 4pp 15858 345
- 82:0250043 Forwards corrected rept for radionuclide contentrations in Pattern 2 injection & production wells from 820401 stabilization samples for, "Reno Creek Pattern 2 Restoration Rept Addendum " Recoky Mountain Energy Co 62/09/09 KALMAN.K Uranium Recovery Licensing Branch 2pp 15798 348
- 8210040344 Discusses review of Rocky Mountain Energy 1982 second quarterly rept for Reno Creek Bits No followup actions necessary KALMANIX L. LINEHANJ J. Uranium Recovery Licensing Branch 82/09/10 Uranium Recovery Licensing Branch 2009 15597 185
- DOCKET 40-8698 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO
- 3210260019 Confirms 820820 conversation re temporary suspension of production at Shootaring Canyon U processing facility Velloucate in sys presently being recovered Plant will resume milling & mining by late 1984 CERDEMAN.F H Plateau Resources, Ltd 82/08/24 FLEMING.T NRC No Detailed Affiliation Given ip 15814 317
- MCKET 40-8714 CLEVELAND-CLIFFS IRON CO . CLEVELAND, DH
- 3210220515 Notifies that Cleveland Cliffs surface discharge operation monitoring program complies w/requirements of NPDE9 Permit WY-0000783 No further action required PDHLE.JA . LINEHAN.JJ Uranium Recovery Licensing Branch 92/06/03 Uranium Recovery Licensing Branch ip 15786-088
- 3210220036 Advises that License SUA-1352 Amended to rovise License Condition 10 re authorized use of expanded ion exchange resin SCARANO,R A Uranium Recovery Licensing Branch B2/08/30 LQUDERBACK,T E Cleveland-Cliffs Iron Co 2pp 15784 281.
- HOCKET 40-8728 TETON EXPLORATION DRILLING CO , INC , CASPER, WY
- 1210280412 Forwards State of MY Dept of Environ Quality, Land Quality Div 820519 itr accepting groundwater stabilization in N zone equifer advising of plugging of zone wells APPELAR R Taton Exploration Drilling Co . Inc 82/08/23 ROSS, FM NRC No Detailed Affiliation Oliven 3pp 15859 336
- 1210120494 Advises that proposed in-plant radiation safety program acceptable w/listed exceptions, Conditions 25 & 30 of License SUA-1373 should be revised as stated SULLENDERGER, D., PETTENOILL, H.J. Uranium Recovery Licensing Branch 82/09/16 RDBS, F. H. Uranium Recovery Licensing Branch 6pp 18679 AM

- 8210260577 Objects to conditions on commencement of mining in Unit 2 Collection of baseline water quality data in Unit 3 prior to mining unnecessary to insure environ protection of groundwater CATCHPOLE.0 J Ogis Petroleum, Inc. 82/09/02 FRANCIS.E Hyoming, State of 2pp 15830 139
- 8210120591 Requests that second aquirer pump test be performed prior to ifcensing injection of liviviant into Mining Unit 2 are zone to evaluate confining nature of lower claystone layer Pravious test inadequate LINEHAN, J J Uranium Recovery Licensing Branch 82/09/10 Ogle Petroleum, Inc. (p. 15672-351
- --8210120604 Responds to request to analyze Hims Unit 2 pump test & associated data Use of ratio method to determine vertical hydraulic conductivity of lower aquitard invalid HILLIAMS.R E Williams-Robinette & Associates, Inc. 82/09/10 Williams-Robinette & Associates, Inc. 89p 15672 352
- 8210280046 Forwards im-plant radon concentrations table for first half of 1982, per NRC request SAUNDERS, O A Ugle Petroleum, inc 82/09/10 SMITH, D Uranium Recovery Licensing Branch Ip 15863 004
- --8210280049 "Radon Oas Concentration in uCi/mi." Jan-June 1982 4 Ogle Petroleum, Inc. 82/09/10 ip 15863-005
- DDCKET 49-8769 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, DK
- 8210040365 Discusses review of Kerr-McOes G-Sand Project quarterly rept for Jan-Mar 1982 To date no serious events identified which necessitate change of operations or shutdown MESTBROOK.K B . LINEMAN J J Uranium Recovery Licensing Branch 62/09/07 Uranium Recovery Licensing Branch 4pp 15597 193
- DOCKET 40-8771 MELAPAT RESOURCES CO . PHOENIX. AZ
- 62(0120536 Advises that me violation found during NRC 820406-07 preoperational safety insp FLEMIKO, T.E. MARTIN, D.E. Uranium Recovery Licensing Branch 82/09/22 Uranium Recovery Licensing Branch 1p 15672 216
- DOCKET 40-8781 TETON EXPLORATION DRILLING CD . INC , CASPER, WY
- 8210270066 Expresses appreciation for opportunity to review & comment on DES for Teton Exploration Drilling Project Document adequate re compatibility wilocal & regional comprehensive planning MATUSCHECK, R J Housing & Urban Development, Dept of 82/08/02 SCARANO, R A Uranium Recovery Licensing Branch ip 15026-127
- 8210230032 Comments on application process to date Use of environ rept for NRC purposes similar to State of WY format will save considerable preparation time APPEL, R United Nuclear Corp 82/08/23 SCARAND, R A Uranium Recovery Licensing Branch 2pp 15808 345
- 8210240096 Forwards state agency comments on project DES Encl analyses support issuance of combined source & hyproduct matl licenses subj to specific licensing conditions of other local state & federal state & regulations HERBCHLERIE Myoming State of 82708/26 SCARANO.R A Uranium Recovery Licensing Branch 9pp 15810 330
- --8210260099 Comments on DES Sentence that mobile fire units are maintained by Converse County Rural Fire Control Assoc should be added to Page 3-20 LUNDELL B.E. Hyoning, State of 82/07/19 Uranium Recovery Licensing Branch 1p 15810 339
- 8210120419 Forwards safety evaluation supporting issuance of License SUA-1403 for commercial in situ leach U mine & recovery plant MOCLGEY, R. T. , PETTENGILL, H. J. Uranium Recovery Licensing Branch 82/09/20 Uranium Recovery Licensing Branch 1p. 13672 238
- --8210120624 Safety evaluation supporting issuance of License SUA-1403 for commercial in situ leach U mine & recovery plant. HOOLBEY, R T , PETTENDILLH J Uranium Recovery Licensing Branch 82/09/20 22pp. 15672-239

- DUCKEY 40-8786 URANIUM RESOURCES. INC , RICHARDSON, TX
- §210180356 Forwards response to NRC 820723 ltr re malfunctioning flow meters, radiological environ monitoring & as-built pond specs One oversize map enc? Aperture card is available in PDR
- PELIZZA, M.S. Uranium Resources, Inc. 82/08/12 LINEHAN, J.J. Uranium Recovery Licunsing Branch .3pp. 15747-352
- --P2IO180359 'Pond Soil Analysis "

 * Affiliation Uninown 82/02/22 2pp 15747 357
- 8210250013 "North Platte Project Guarterly Rept. 820415-0715 "

 * Uranium Resources, Inc. 82/08/23 68pp 15808 183
- 8210120479 Approves licensee restoration of R&D wellfield using combination groundwater sweep & reinjection of reverse osmosis treated water Hells will be restored to propor levels at end of restoration WESTBROBK.P B , LINEHAN, J J Uranium Recovery Licensing Branch 82/07/17 Uranium Recovery Licensing Branch 2pp 156/2 05
- DOCKET 40-8793 CONDCO. INC . DENVER. CO
- 8210040348 Biscusses CONOCO. Inc request for withdrawal of Ruby Ranch In Situ U Project application Option of withdrawing and letton practed
 - application granted
 YDUNG.Y A. LINEHAN.J J Uranium Recovery Licensing Branch
 82/09/10 Uranium Recovery Licensing Branch 4pp 15597 187
- DUCKET 40-8820 AMAX ENVIRONMENTAL SERVICES, INC., GOLDEN, CO.
- G210250035 Advises that radioactive contaminated soil removed from adjacent property owned by Chiyoda Steel Corp Authorization by Chiyoda to enter property & remove soil encl KEPPLER.P AMAX. Inc. G2/08/31 NIXON,W NRC No Detailed Arfiliation Given 3pp 15808 349
- DUCKET 40-8924 TARGET RESEARCH, INC., WHARTON, NJ
- 8210270373 Forwards application for source matilitiense, authorizing possession of 6,000 kg U alloy, enriched to 97 8% U-23B, for use in assembling armor-piercing projectiles

 DAKUM, K E Target Research, Inc. 82/09/15

 Cycle & Material Safety ip 15835 820
- --8210270376 Application for license to possess 6,000 kg depleted U aftou, enriched to 99 8% U-238, for use in assembling armor-piercing projectiles GUADAGNO.V Target Research, Inc. 82/09/14 17pp 15835 221
- DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES
- DOCKET 50-3 INDIAN POINT STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8210280148 Releases public version of revised emergency plan implementing procedures FELTON.J H Division of Rules and Records 82/10/12 Document Management Branch 1p 15862 271 24X Fiche 50-003.82/10/12, 8210280148
- --8210280154 Forwards public version of revisions to Emergency Plan Implementing Procedures IP-1020 re airborne radioiodine determination & IP-1046 re util personnel responsibilities during Unit 3 emergencies
 O'TOOLE.J D Consolidated Edison Co of New York 82/10/01
 HAYNES.R C Region 1. Office of Director 3pp 15862 272 24X
 Fache 50-003,82/10/12,8210280148
- --8210280159 Public version of revisions to Emergency Plan Implementing Procedures IP-1020 re airborne radioiodine determination & IP-1046 re util personnel responsibilities during Unit 3 emergencies

 * Consolidated Edison Co of New York 82/09/01 16pp 15862 275 24X Fiche 50-003, 82/10/12/8210280148

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180077 Forwards comments on PRA study dealing w/seismic hazard Validity of conclusions rest on quality of primary data bases & assumptions in both studies Repts are not valid risk assessments due to data base limitations POMEROY.P W Rondout Associates POMEROY.P W ACRS Advisory Committee on Reactor Safeguards 82/08/24 OKRENT, D ACRS Advisory Committee on Reactor Safeguards 7pp 15876 001 24% Fiche 50-003.82/08/24,8207180077
- P Operating license stage documents & correspondence
- BC09080466 Forwards response to 800820 request for status rept re Zion/Indian Point task action pian Responsibilities are in area of severe accident mitigation features & not in interim operational actions portion
 MEYERJ F Reactor Systems Brench 80/08/25 NOVAK, T M Assistant Director for Operating Reactors 2pp 03484 009 24x
 Fiche 50-003, 80/08/25, 8009080466
- B010210036 Discusses SEP Branch review of sys environ qualification of safety-related electrical equipment for il SEP plants MCKENNALE M Systematic Evaluation Program Branch B0/09/30 LAINAB, 0 C Division of Licensing 2pp 03647 289 24X Fiche 50-003, 80/09/30, 8010210036
- 8210120103 Add1 response to FOIA request for nine categories of records generated by present NRC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents
 FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A
 Critical Mass Energy Project 3pp 15690 117 24X
 Fiche 50-000, 82/07/12, 8210120103
- --8210120188 Notifies that facility will be decommmissioned by util rether than make ECCS mods to meet NRC criteria Util proposed research funding cannot be provided Recommends approval of proposed itr to util ZECH.9 NRC No Detailed Affiliation Civen 81/11/95 ROBERTS.T M Commissioners 1p 15690 140 24x Fiche 50-000,82/07/12.8210120103
- 8210010401 Forwards application to amend Licenses DPR-26 & DPR-5, changing Tech Specs re facility organization & Unit 2 Tech Specs 3 6 & 4 for containment isolation valves 3 12 & 4 12 in pipe lines Class J. II & III fees enc! D'TOOLE. J D Consolidated Edison Co of New York 82/08/31 VARGA. B A Operating Reactors Branch 1 3pp 15572 211 24X Fiche 50-003, 82/08/31, 8210010401
- --8210010407 Application to amend Licenses DPR-26 & DPR-5, revising Tech Spec Figures 3 2 & 6 2-2 re facility organization for Units 1 & 2, respectively D'TOOLE.J D Consolidated Edison Co of New York 82/08/31 2pp 15572 214 24X Fiche 30-003,82/08/31,8210010401
- --8210010414 Proposed revisions to Tech Spec Figures 3 2 & 6 2-2, reflecting change in organizational structure to include position of operations superintendent Safety assessment enci
 * Consolidated Edison Co of New York 82/08/31 4pp 15572 216 24% Fiche 50-003,82/08/31,8210010401
- --8210010425 Application to amend License DPR-26, revising Tech Specs 3 6 & 4 to establish requirements for action required when containment isolation valves are inoperable & reflect changes to isolation valve provisions 0/TOOLE, J D Consolidated Edison Co of New York 82/08/31 2pp 15572 222 24X Fiche 50-003.82/08/31.8210010401
- --8210010438 Proposed revisions to Tach Specs 3 & & 4 4.establishing specific requirements for action during inoperability of containment isolation valves & reflecting changes & additions to isolation valve provisions Safety assessment encl * Consolidated Edison Co of New York 82/08/31 20pp 15572 224 24% Fiche 50-003.82/08/31.8210010401
- --B210010443 Application to amend License DPR-26, revising Tech Spec Sections 3 12 & 4 12 to deffiect editorial change safety-related pipe lines & to effict editorial change O/TOCLE.J D Consolidated Edison Co of New York 82/08/31. 2pp 13572 244 24X Fiche 50-003,82/08/31,8210010401
- --8210010449 Proposed revisions to Tech Spec Sections 3 12 & 4 12, reflecting redesigned support sys for safety-related pips lines & to effect editorial change Bafety assessment encl. * Consolidated Edison Co of New York 82/08/31 18pp 15572 246 24X Fichs 50-003.82/08/31.8210010401

- à inspection reports. IE Bulletins & correspondence
- G208199231 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged 1-125 inplant Seeds " Svc list encl COBP.L I Division of Fuel Facilities. Haterials & Safeguards E2/10/06 Cansolidated Edison Co of New York & App 15761 250 24
- 82LB190238 IE Builetin B2-03, "Stress Corrosion Cracking in Thick-Wall.Large-Dianeter. Stainless Steel Recirculation Bys Paping at DMR Plants " Sve list enci DEYGUND.R C Director's Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 123pp 15810 125 24% Fische 50-000.82/10/14.8208170238
- DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8209290125 Releases public version of revised generating station energency plan corporate command ctr emergency plan tepiementing procedure FFLION.J M Division of Rules and Records 82/09/16 Document Management Branch ip 15564 122 24X Fiche 50-000.82/09/16. 8209270175
- --B209290189 Forwards public version of Revision 4 to generating station energency plan corporate command ctr Emergency Plan Inplementang Procedure EOF-3, "Environ/Emergency Coordinator" Receipt form encl PAJONSKI, J E Commonwealth Edison Co B2/09/01 DENTON, H R NRC No Detailed Affiliation Olven ip 15564 123 24X Fichs 50-000, B2/09/16, B209290125
- 8210130376 Advises that installation of offsite dose calculation sys program fully operational tracking model to operational A-model will be delayed until 821231 to complete prima computer installation SMARTZ.E D Commonwealth Edison Co 82/10/06 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15682 098 24X Fiche 50-000, 82/10/06-0210130376
- S210290047 Releases public version of revisions to Quad Cities, Zion & Dresden emergency plan anneres & revised generating statum emergency plan to telephone directory FELTOH, J M Division of Rules and Records 82/10/08 Document Management Branch ip 15877 313 24% Fiche 50-000,82/10/08, 82/10290047
- --8210290060 Forwards public version of Revision 3 to Quad Cities & Zion emergency plan annexes. Revision 2 to Dresden emergency plan annex in Revision 0 to Buron swergency plan annex in revised generating station emergency plan telephone directory HODRE, R D Commonwealth Edison Co B2/07/30 DENTON, H R NRC -- No Detailed Affiliation Given 5pp 15877 314 24X Fishe 50-000, 82/10/08, B210290047
- --B210290077 Public version of Revision 3 to Quad Cities & Zion emergency plan annexes. Revision 2 to Drasden emergency plan annex & Revision 0 to Byron amergency plan annex & Commonwealth Edison Co B2/06/30 102pp 15877 319 24X Fiche 50-000.82/10/08.8210290047
- --821029008B Public version of revised generating station emergency plan telephone directory GALLED P Commonwealth Edison Co 82/08/12 43pp 15878 218 24X Fiche 50-000,82/10/08.82(0290047
- 8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs TRANH.TR Commonwealth Edison Co. 82/10/14 DENTON.HR Office of Nuclear Reactor Regulation, Director 9pp 15776-287 24X Fiche 50-000,82/10/14.8210220358
- B210250170 Advises that plans & preparedness for offsite protection near facility adequate & will be applied in event of radiological emergency IL State & local plans approved subject verification of adequacy of alerting & notification system (THOMABLA) Federal Emergency Hanagement Agency 82/10/14 DIRCKS.W J Office of the Executive Director for Operations ip 15789:285 24% Fiche 50-010.82/10/14.8210250170

- P Operating license stage documents & correspondence
- 92/0260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" gQLDEN, J C Commonwealth Edison Co 82/10/06 CASE, E 0 Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000, 82/10/06, 9210260526
- --B210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual"
 - Commonwealth Edison Co. 82/09/30 83pp 15805 139 24x Fishe 50-000, 82/10/06, 8210260526
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820909 ltr Staff encouraged to develop & implement means to incorporate pasitive attributes of Phase III in licensee/NRC interface RACICH, RM SEP Dumers Group KACICH, RM Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/07 EIEENHUT, D G Division of Licensing 7pp 19682 179 24X Fiche 50-000, 82/10/07, 82/10/30326
- 8210180196 Forwards "Final Status Rept in Preparation for Chemical Cleaning of Dresden 1." Sept 1982
 RAUSCH.T J Commonwealth Edison Co 82/10/12 EISENHUT.D Q
 Division of Licensing 1p 15749 135 24X Fiche 50-010.82/10/12.8210180196
- --8210180197 "Final Status Rept in Preparation for Chamical Cleaning Dresden i." Sept 1981 Aperture cards available in PRR * Dow Chemical Co DNS-D1-034 81/09/30 582pp 15749 134 24X Fiche 50-010.82/10/12.8210180196
- O Inspection reports, 1E Bulletins & correspondence
- 8210060329 Forwards 1E Insp Repts 50-010/82-02.50-237/82-03 & 50-249/82-03 on 820119-0218 No noncompliance noted LITTLE, N 5 Division of Engineering & Technical Programs REED. C Commonwealth Edison Co 2pp 15615 331 24X Fiche 50-010.82/09/22.8210060329
- --8210060335 IE Insp Repts 50-010/82-02,50-237/82-03 & 50-249/82-03 o 82019-0218 No noncompliance noted Major areas inspected open & unresolved items & items of noncompliance reintegrated leak rate test REIMANN,F W Region 3, Office of Director JACKIH, I N Division of Engineering & Technical Programs 82/09/21 7pp 15615 37.2 24X Fichs 50-010,82/09/22,8210060329
- 8210150523 Forwards IE Insp Repts 50-010/82-13.50-237/82-17 & 50-249/82-18 on 820708-0809 & notice of violation STREETER, J F Division of Project & Resident Programs 82/09/28 REED. C. Commonwealth Edison Co. 2pp 15713 099 24X Fiche 50-010.82/09/28.8210150523
- --8210150530 Notice of violation from insp on 820708-0809 STREETER.J F Division of Project & Resident Programs 82/09/20 19 15713 101 24X Fiche 50-010.82/09/28.8210150523
- 8210150539 Forwards 1E Insp Repts 50-010/82-15, 50-237/82-19 & 50-249/82-20 on 820830-0903 No noncompliance noted PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/10/01 REED, C Commonwealth Edison Co 2pp 15714 175 24X Fiche 50-010.82/10/01.8210150539
- --B210130543 IE Insp Repts 50-010/82-15, 50-237/82-19 & 30-249/82-20 mg
 820830-0903 & 09 No noncompliance noted Major areas
 inspected confirmatory measurements programs GC program for
 analytical measurements & environ monitoring program
 BCRUMACHER, M.C., NICHOLSON, N.A., JANUEKA, A.G. Division of
 Emergency Preparedness & Operational Support
 82/09/30 7pp
 15714 177 24% Fiche 50-010, 82/10/01, 8210150539
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COSBL 1 Division of Fuel Facilities, Materials & Safaguards 82/10/06 Cansolidated Edison Co of New York 66pp 157.61 250 24X Fichs 50-000, 82/10/06, 8208190233

- 8208190238 IE Builetin 82-03. "Stress Corresion Cracking in Thick-Wall-Large-Diameter. Stainless Steel. Recirculation Sys
 Piping at BNR Plants " Svc list encl
 DEYGUNG.R C Director's Office. Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 123pp 15810 125 24X Fichs 50-000, 82/10/14, 8208190238
- R Periodic operating reports & related correspondence
- 8210180097 Forwards monthly operating repts for Sept 1982 SCOTT-D J Commonwealth Edison Co 82/10/01 Director's Office, Office of Inspection and Enforcement ip 15718 001 24X Fiche 50-010:82/10/01:8210180097
- --8210180100 Monthly operating repts for Sept 1982 SCHROEDER, B. A. Commonwealth Edison Co. 82/10/01 15718 002 24X Fiche 50-010, 82/10/01.8210180097
- DOCKET 50-13 BABCOCK & WILCOX CO CRITICAL FACILITY

 F Security, medical, energency & fire protection plans
- 8210210194 Forwards iE Safeguards Insp Repts 50-013/82-03 & 70-0824/82-10 on 820930-1001 No noncompliance noted GIBSON, A F Division of Engineering & Technical Programs 82/10/15 ENGELDER, T C Babcock & Wilcos Co 2pp 15765 304 24X Fichs 50-013,821/01/15,8210210194
- --8210210206 IE Safeguards Insp Repts 50-013/82-03 & 70-0824/82-i0 on 820930-1001 No noncompliance noted Major areas inspected physical protection of low enriched SMM Details withheld (ref iOCFR2 790)
 GOODE.R · MCGUIRE.D R Division of Engineering & Technical Programs 82/i0/15 ip 19765-306 24X Fichs 50-013,82/10/15,8210210194
- P Operating license stage documents & correspondence
- B210040214 Betails evaluation of discrepancy between electronically simulated reactor & channel periods revealed in calibr test performed on Log-N-2 channel No unsafe condition existed & no Tech Spec violation occurred OLSEN.A F Consolidation Coal Co 82/09/27 Standardization & Special Projects Branch 3pp 15583 i20 24X Fiche 50-013, 62/09/27, 8210040214
- Q Inspection reports. IE Bulletins & correspondence
- 8210210194 Forwards IE Safeguards Insp Repts 50-013/82-03 & 70-0824/82-10 on 820930-1001 No noncompliance noted.
 GIBSON, A F Division of Engineering & Technical Programs 82/10/15 ENGELDER, T C Babcock & Wilcox Co 2pp 15765 304 24X Fiche 50-013, 82/10/15, 8210210194
- --8210210206 IE Safeguards Insp Repts 50-013/82-03 & 70-0824/02-10 on 820930-1001 No noncompliance noted Major areas inspected physical protection of low enriched SNM Details withheld (ref 100FR2 790)

 QUODE,R . MCGUIRE,D R Division of Engineering & Technical Programs 82/10/15 ip 15765 306 24X Fichs 50-013,82/10/15,8210210194
- DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR

 F Security, medical, emergency & fire protection plans
- 8210190334 Forwards Revision 27 to SAR for MIT research reactor, aefecting physical security plan SAR withheld (ref 100FR2 790)
 CLARK-L Massachusetts Institute of Technology 82/10/13
 TEDESCO: R L Assistant Director for Licensing ip 15742 125 24X
 FICHE 50-020, 82/10/13, 8210190334
- DOCKET 50-22 WESTINGHOUSE TEST REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- B2:01:30420 Forwards "Annual Insp of Retired Westinghouse Testing Reactor per License IR-2 for 1982 " NARDIA J Westinghouse Electric Corp B2/09/30 Stendardization & Special Projects Branch ip 15680 264 24X Fiche 50-022
- --8210130426 "Annual Insp of Ratired Westinghouse Testing Reactor per License TR-2 for 1982" # Westinghouse Electric Corp 82/09/16 3pp 15680, 265, 24X Fiche 50-022, 82/09/30, 8210130420

- R Periodic operating reports & related correspondence
- 8210130420 Forwards "Annual Insp of Retired Westinghouse Testing Reactor per License TR-2 for 1982 " NARDI.A J Westinghouse Electric Corp 82/09/30 Standardization & Special Projects Branch ip 15680 264 24X Fiche 50-022,82/09/30.8210130420
- --8210130426 "Annual Insp of Retired Westinghouse Testing Reactor per License TR-2 for 1982 " + Westinghouse Electric Corp 82/09/16 3pp 15680 265 24X Fiche 50-022,82/09/30/8210130420
- DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR

 G Inspection reports, IE Bulletins & correspondence
- 82i0i90632 Forwards IE Insp Rept 50-027/82-02 on 8207i4-16 & 08i0 No noncompilance noted BOOK,H E Division of Radiological Safety & Safeguards Program 82/10/01 WILBON,W E Washington, Univ of 2pp 15740 025 24X Fiche 50-027,82/10/01,82i0i90632
- --8210190636 IE insp Rept 50-027/82-02 on 820714-16 & 0810 No noncompliance noted Major areas inspected radiation control program, including posting & labeling.personnel monitoring, instrument calibr & effluent monitoring GARCIA;E M , WENSLAMSKI,F A , BOOK, H E Division of Radiological Bafety & Safequards Program 82/09/30 &pp 15740 027 24X Fiche 50-027,82/10/01.8210190632
- DOCKET 50-29 YANKEE-ROHE NUCLEAR POHER STATION

 F Security, medical, emergency & fire protection plans
- B210060034 Forwards IE Safeguards Insp Rept 90-027/82-09 on 820802-05 No noncompliance noted HARTIN.T Division of Engineering & Technical Programs 82/09/27 HEIDER, L H Yankee Abomic Electric Co 2pp 15615 051 24X Fiche 50-027, 82/09/27/8210060034
- --8210060049 IE Safeguards Insp Rept 50-029/82-09 on 820802-05 No noncompliance noted Major areas inspected testing & maint records, physical barriers in protected & vital areas & security sys power supply Details withheld (ref 10CFR79 2() DUNLAP, J.M., SMITH, O.C., CODY, A.T. Division of Engineering & Technical Programs 82/09/23 pp. 15615-053 24X Fiche 50-029,82/09/27.8210060034
- 8210060306 Ack receipt of 820827 ltr informing NRC of steps taken to implement recommendations nated in IE Emergency Preparedness Appraisal Rept 50-029/81-20
 9HITH, 0 H Division of Emergency Preparedness & Operational Support 62/09/27 HEIDER, L H Yanke Atomic Electric Co ip 15619 230 24/ Fiche 50-029/82/09/27,8210060306
- --8210060310 Responds to NRC 820630 itr re findings noted in IE Emergancy Preparedness Appraisal Rept 50-027/81-20 Corrective actions chemistry personnel placed on redio pager sys to afford earlier notification & response HEIDER, L. H. Yankee Atomic Electric Co. 82/08/27 HAYNES, R. C. Region i, Office of Director. 62pp. 15619-231 24X Fiche 50-029,82/09/29.8210060304
- 8210210345 Forwards Amend 73 to License DPR-3 & notice of issuance Amend incorporates guard training & qualification plan, in response to licensee \$10610 & 1208 applications CRUTCHFIELD D Operating Reactors Dranch 5 82/09/30 KAY, J A Yankee Atomic Electric Co 3pp 15782 352. 24X Fiche: 50-029, 82/09/30, 8210210345
- --8210210352 Amend 73 to License DPR-3, requiring implementation of guard training & qualification pian within 60 days & qualification of all security personnel within 2 yrs CRUTCHFIELD, D Operating Reactors Branch 5 82/09/30, 5pp 15782-355 24X Fiche 50-029,82/09/30,8210210545
- --82i02i0355 Notice of issuance of Amend 73 to License DPR-3 CRUTCHFIELD, D Operating Reactors Branch 5 82/09/30 2pp. 15782 358 24X Fiche 50-029,82/09/30.8210210545
- 8210220133 Ack receipt of 820927 itr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-027/82-08.

 8TAROSTECKIR. Division of Project & Resident Programs HEIDER.L H Yankee Atomic Electric Co ip 15778,090, 24X Fiche 50-027,82/10/15,8210220153

--8210220157 Responds to MRC 820901 ltr re violations noted in IE Bafeguards (map Rept 50-029/82-08 Corrective actions withheld (ref 100FR2 790) HEIDER, L H Yankee Atomic Electric Co 82/09/27 HAYNES, R C Region 1, Office of Director 2pp 15778 091 24X Fiche 50-029,82/10/15.8210220153

Operating license stage documents & correspondence

10040397 Requests processing of listed documents re BEP Topic 11-04 E. "Dam Integrity" SHITH: H Operating Reactors Branch 5 82/09/17 Division of Technical Information & Document Control 2pp 15597 226 24X Fiche 50-029, 82/09/17, 8210040399

i0040132 Forwards safety evaluation & tethnical evaluation repts of licensee response to proposed design mods to degraded grid voltage Schadule for response requested within 30 days CRUTCHFIELD. D Operating Reactors Branch 5 82/09/27 KAY. J A Vankee Atomic Electric Co 2pp (5583 095 24% Fichs 50-029, 82/09/27, 82/0040132

- 8210040139 Bafety evaluation re degraded grid voltage protection for Class IE sys Design acceptable subj to resolution of listed items # Operating Reactors Branch 5 82/09/27 7gp 15583 097 24% Fiche 50-029,82/09/27,8210040132
- -B209200475 "Proposed Design Mods & Tech Spec Changes on Grid Voltage Degradation for Yankee Rome Nuclear Power Station." tachnical evaluation rept SELAN.J C Lawrence Livermore Laboratory FIN A-0250 UCID-19147 82/07/30 NRC - No Detailed Affiliation Olven 13pp 15583 104 24% Fiche 50-029.82/09/27.8210040132
- 210120207 Forwards safety evaluation of SEP Topic III-4 C reinternally generated missiles Generation of internal missiles within facility will not prevent safe shutdown CARUSO.R Operating Reactors Branch 5 82/09/29 KAY, J A Yankee Atomic Electric Co 28pp. 15652 155 24X Fiche 50-029,82/09/29,8210120207
- 12100B0098 Proposed Change 178 to License DPR-3,adding & deleting containment isolation valves specifying equipment parameters, adding new equipment & recategorizing valves to accommodate mod implementation during refueling gutage HEIDER-L H Yankee Atomic Electric Co 82/09/30 Office of Nuclear Reactor Regulation, Director 9pp 15640 244 24k Fiche 50-029, 82/09/30, 8210080098
- --8210080102 Proposed Tech Spec pages, adding & deleting containment isolation valves, specifying equipment parameters, adding new equipment & recategoritating valves to accommodate mod implementation during refueling outage * Yantee Atomic Electric Co 92/09/30 22pp. 15640 253 24X Fiche 50-029, 82/09/30, 8210080098
- 8210120245 Forwards safety evaluation & technical evaluation repts of SEP Topics 11-3, A, 11-3 B, 11-3 B i & II-3 C re hydrologic considerations Facility does not meet NRC criteria Deviations will be resolved in integrated safety assessment, CARUSO, R Operating Reactors Branch 5 E2/09/30 RAY, J, A, Yantan Atomic Electric Co. 3ipp 15651 OD1 24% Fiche 50-029, 82/09/30, 82/0120245
- --B208100269 "Hydrological Considerations (SEP.11-3 A.B.B 1.C.III-3 B)," technical evaluation rept SHERRER.J Franklin Institut#/Franklin Research Center. NRC-03-79-11B TER-C5257-426 B2/08/06 BTALEY,0 NRC No Netailed Affiliation Given Bipp. 15651:032 24X 129,82/09/30,8210120245

- ~-8210210552 Amend 73 to License DPR-3, requiring implementation of guard training & qualification plan within 60 days & qualification of all security personnel within 2 yrs CRUTCHFIELD.D Operating Reactors Branch 5 B2/09/30 5pp 13782 355 24% Fiche 50-029, 82/09/30,8210210545
- --B210210555 Notice of issuance of Amend 73 to License DPR-3 CRUTCHFIELD.D Operating Reactors Branch 5 82/09/30 2pp 15782 358 24X Fiche 50-029,82/09/30.8210210545
- B210070169 Forwards topic difference summary for SEP Topic III-6, "Seismic Design Considerations" & updated difference summaries for Topics V-10 B.V-11 B.VII-3 & IX-3 re RMR sys & sys required for safe shutdown CARUSO.R Operating Reactors Branch 5 B2/10/01 KAY.J A Yankee Atomic Electric Co 7pp 15627 001 24X Fiche 50-029.B2/10/01, B210070169
- 8210070085 Forwards drart safety evaluations of SEP Topics III-6 reseisaic design considerations & SEP III-11 recomponent integrity Licensee proposal re dedicated hot shutdown sysuall be evaluated during integrated assessment of factiity CARUSO, R. Operating Reactors Branch 5 82/10/04 KAY, J. A. Yankee Atomic Electric Co. 20pp. 15628-331 24X Fiche 50-029.82/10/04, 8210070085
- --8210070094 "SEP, Review of Seismic Re-evaluation Program of Yankee Nuclear Power Station" a NRC - No Datailed Affiliation Given 82/09/30 83pp 15629 018 24X Fiche 50-029.82/10/04.8210070085
- --8210070099 "Technical Evaluation of Yankse Rows Power Station Grissic Design." Aug 1982 BRIDGES, T.L., BUSCH, S.L., THUMPSUN, T.R. EQ&Q, inc. FIN A-6426 EQG-EA-6017 82/08/31 CHENG, T. Division of Licensing 250pp 15629 100 24X Fiche 50-029, 82/10/04,8210070085
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in Individual topic definitions appended to 820707 ltr Staff encouraged to develop & Implement means to incorporate positive attributes of Phase III in licensee/NRC Interface KACICH:R H SEP Owners Oroup KACICH:R H Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/07 CISENIUT.D O Division of Licensing 7pp 15682 179 24X Fiche 50-000,82/10/07.8210130326
- 8210130401 Concurs w/content of systematic assessment of licensee performance board recommendations.per NRC B20903 its Licensee action on primary vent stack monitor failures should be clarified to show thorough evaluation of LERs KAY. J Yankee Atomic Electric Co B2/10/08 STAROSTECKI.R Division of Project & Resident Programs 2pp 15682 070 24X Fiche 50-029.82/10/08.8210130401
- 82:0150363 Responds to Generic Ltr B2-12 re plant working hours flant policy re working hours should not be incorporated into Tech Specs due to loss of fiexibility KAY. JA Yankee Atomic Electric Co 82/10/08 EISENHUT, D Q Division of Licensing 2pp 15704 305 24X Fiche 50-027, 82/10/00, 82/1050363
- 8210180187 Clarifies 820804 request for add1 info re NUREG-0737.

 Item I1 B 3, "Post-Accident Sampling Sys " Guidance on meeting NUREG-0737 criteria discussed CRUTCHFIELD, D Operating Reactors Branch 5 82/10/08 KAY, J A Yantee Atomic Electric Co 3pp 15719, 130 24X
 Fiche 50-029, 62/10/08, 8210180187
- 8210210123 Forwards evaluation of SEP Topic 111-3 A. "Effects of High Mater Level on Structures," based on 820318 BAR Turbine & svc bidgs:screenwall & pumphouse unprotected from postulated flood condition CARUSO:R Operating Reactors Branch S 82/10/13 KAY. J A Yankee Atomic Electric Co. 7pp 13766 027 24X Fiche 50-027.82/10/13.8210210123
- B2101906B6 Application to amend License DPR-3, replacing 40 fuel assemblies to refuel for Core XVI operation & inserting cycle dependent parameters in Tech Spect HEIDER, L. H. Yenkee Atomic Electric Co. 92/10/15. Office of Nuclear Reactor Regulation. Director 2pp 1873B 165 24X Fiche 50-027, 82/10/15, 8210170686
- --8210190490 Proposed Yach Spac mod insarting cycla depandent parameter > Yankoe Atomic Electric Co 82/10/15 25pp, 15738 167 24% Fiche 50-029,82/10/15,8210190686,

- 8210C80094 Application to amend App A of License DPR-3.consisting of Proposed Change 179.allowing increase in plant operating elevibility while maintaining sufficient RMR flow to ensure reactor vessel water temp does not exceed 140 F in Mode 6 HEIDER, L H Yankee Atomic Electric Co 92/10/15 Office of Nuclear Reactor Regulation, Director 2pp 15837 185 24X Fiche 50-029,82/10/15,8210280074
- --8210280103 Proposed Tech Spec Change 179, allowing increase in plant operating flexibility while maintaining sufficient RHR flow to ensure reactor vessel water temp does not exceed 140 F in Mode 6

 * Yankee Atomic Electric Co 82/10/15 4pp 15837 187 24X Fiche 50-027, 82/10/15, 8210280074
- O Inspection reports. IE Bulletins & correspondence
- 8210070097 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udeii FOIA Request 81-313 Forwards documents listed in App B FELTON, J H Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007
- --B210070139 Forwards tabulated data on steam generator insp & maint at racilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Dranch B2/04/01 VARGA.S Operating Reactors Branch 1 CLARK.R Operating Reactors Branch 1 CLARK.R Operating Reactors Branch 3 STOLZ.J Operating Reactors Branch 4 Spp 13645 131 24% Fische 50-000.82/08/10.8210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PMRs, per 750320 & 21 requests Details of insps; including defect indications: tube plugging criteria & tubes plugged unil not be provided except for Point Deach i GOLLERIX R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R D Division of Technical Review (NRR-1975 only) 5pp 15645 194 24X Fishe 50-000, 82/08/10, 8210070007
- 8210060034 Forwards IE Safeguards Insp Rept 50-029/82-09 on 820802-05 No noncompliance noted MARTIN, T T Division of Engineering & Technical Programs 62/09/27 HEIDER, L H Yankee Atomic Electric Co 2pp 15615-051 24X Fiche 50-029, 82/09/27, 8210060034
- --8210060049 IE Safeguards insp Rept 50-029/82-09 on 820802-05 No noncompliance noted Major areas inspected testing 5 maint records physical barriers in protocted & vistal areas & security sys power supply Details withheld (ref 10CFR73 21) DNNLAP.J M. SMITH.O C. GDBY.A T Division of Engineering & Technical Programs 82/09/23 ip 15615 053 24X Fiche 50-029.82/09/27.8210060034
- 8210060306 Ack receipt of 820827 itr informing NRC of steps taken to implement recommendations noted in IE Emergency Preparedness Appraisal Rept 50-029/81-20 SMIH.0 H Division of Emergency Preparedness & Operational Support 82/09/29 HEIDER,L H Yankee Atomic Electric Co ip 15619 230 24/ Fiche 50-029.82/09/29.8210060306
- --8210060310 Responds to NRC 820630 ltr re findings noted in IE Emergency Preparedness Appraisal Rept 50-029/81-20 Corrective actions chemistry gersonnel placed on radio pager sys to afford earlier notification & response HEIDER.L H Yankee Atomic Electric Co 82/08/27 HAYNEB, R C Region 1. Office of Director 62pp 19619 231 24X Fichs 50-029.82/09/29.8210060306
- 8210120272 Forwards avaluation of util response to SEP Topic III-3 C, "Inservice Insp of Water Control Structures" Present insp program does not conform w/Reg Ouide 1 127 & should be modified to incorporate NRC recommendations CARUSDIR Operating Reactors Branch 5 82/10/04 KAY, J A Yankee Atomic Electric Ca 10pp 15651 190 24X Fiche 50-029,82/10/04. 8210120272
- --8207190431 "Hydrological Considerations, Inservice Insp of Hater Control Structures (SEP III-3 C), Yankee Rowe Nuclear Power Station, "technical evaluation rept SCHERRER, J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-03257-544 82/07/15 8TALEY, 0 NRC No Detailed Affiliation Given 279p 15651 200 24x Fiche 50-029,82/10/04,8210120272
- 8208190203 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB. I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Cunsolidated Edison Co of New York 66pp 15761 250 24X Fichs 50-000.82/10/06.0203190233

- 8210130401 Concurs w/content of systematic assessment of licensee performance board recommendations.per NRC 820703 itr Licensee action on primary vent stack monitor failures should be ciarified to show thorough evaluation of LERs KAY. J Yankee Atomic Electric Co 82/10/08 8TAROSTECKI.R Division of Project & Resident Programs 2pp 15682 070 24X Fiche 50-029.82/10/08.8210130401
- 8210290147 Forwards IE Insp Rept S0-029/82-10 on 820802-0930 No noncompliance noted STARDSTECKI,R Division of Project & Resident Programs 82/10/08 HEIDER,L H Yankee Atomic Electric Co 2pp 15854 214 24X Fiche 50-029,82/10/08.8210290147
- --8210290157 IE Insp Rept 50-029/82-10 on 820802-0903 No noncompilance noted Major areas inspected review of plant operation, plant maint observation, plant events. LERs. I Icensee plant info rept. perlodic & special repts & preparation for refueling COLLINS. 8 J. CALLO.R M Division of Project & Resident Programs 82/10/07 16pp 15954 218 24X Fiche 50-029, 82/10/08.8210290147
- 8208190238 IE Builetin 82-03. "Stress Corrosion Cracking in Thick-Wall. Large-Diamster. Stainless Steel. Recirculation Sys Piping at BWR Plants " Svc list enci DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 8210220153 Ack receipt of 820927 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-027/02-08

 STAROBTECKI.R Division of Project & Resident Pragrams 82/10/15
 HEIDER.L H Yankee Atomic Electric Co ip 15778 090 24X
 Fiche 50-029, 82/10/15.8210220153
- --8210220157 Responds to NRC 820901 ltr re violations noted in IE Safeguards Insp Rept 50-029/82-08 Corrective actions withheid (ref 10CFR2 790) HEIDER, L. H. Yankee Atomic Electric Co. 82/09/27 HAYNES, R. C. Region 1, Office of Director 2pp 15778 091 24X Fiche 50-029, 82/10/15,8210220153
- 8 Reportable occurrences. LERs & related correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 003 24X Fiche 50-000.82/06/28.8210010008
- --8109280175 Requests addl info re loss of offsite power event on 810914. SANDS, S. P. Director's Office 81/09/18 CARUSO, R. Operating Reactors Branch 5 ip 15730 250 24X Fiche 50-000, 82/06/28, 8210010008
- --B210010161 Discusses potential problem re sequoyah reactor pressure notzle, supplementing 800222 memo Underclad cracks found by use of ultrasonic equipment Addl items of recent origin discussed Related info encl DENTON. HR Office of Nuclear Reactor Regulation, Director 80/02/28 AMERINE, Commissioners 9pp 15727 178 24X Fiche 50-000, 62/06/28, 8210010008
- 8210130230 Forwards LER 82-025/03L-0 AUTIO.H. A Yankse Atomic Electric Co 82/09/30 MAYNES,R C Region 1. Office of Director 1p 15675 269 24X Fiche 50-029.82/09/30.8210130230
- --8210130235 LER 82-028/03L-0 on 820831.gas leak developed in weld joining safety valve drain line to valve body on waste gas datay 2 drum safety valve Cause not stated Leaking weld isolated ground out & reweided RICE, DA Yankse Atomic Electric Co 82/09/30 Region 1, Office of Director ip 15675 270 24X Fiche 50-029, 82/09/30, 8210130230
- 8210130218 Forwards LER 82-027/03L-0 AUTIO.H A Yanker Atomic Electric Co 82/10/01 HAYNEB,R C Region 1. Office of Director 1p 15675 235 24X Fiche 50-027,82/10/01.8210130218
- --8210130225 LER 82-027/03L-0 on 820902; while in Mode i, sustitiary builgr room sprinkler sys isolated to stop & repair gasket leak Caused by insufficient gasket contact w/vaive*F8-V-739 Casket replaced.

 MAY.E L. Yankse Atomic Electric Co. 82/10/01 Region 1, Office of Director ip 15675 236, 24X Fiche 50-029,82/10/01. 8210130218

- 3210130519 Forwards LER 82-026/03L-0 AUTIO.H A Yante Atonic Elsctric Co 82/10/01 HAYNEB,R C Region 1. Office of Director 1p 15682 361 24X Fiche 50-027, 82/10/01, 82/0130519
- -8210133531 LER 82-026/03L-O on 820702, while performing surveillance of low main coolent flow sys train A. boop 3, phase C relay failed to drop out when de-energised Caused by abnormal amount of friction between plunger & upper bushing FRENCH.L D. Vanter Atomic Electric Co. 82/10/01 Region 1. Office of Director 1p. 15682 362 24% Fiche 50-027,82/10/01, 8210130517
- 12:02:60:109 LER B2-032/011 on B2:1006.positive indication observed during shipping of second cycle fusi assembly B-578 Analysis shows assembly caused slight increese in reactor coolant activity during Core 15 operation AUTIO. H A Yantee Atonic Electric Co B2/10/07 HAYNES.R C Region 1. Office of Director ip 15799 116 24X Fiche 50-029.82/10/07.82(02:60109
- 210290267 Part 21 deficiency rept re-potential galling problem between size & bonnet of I 25-inch & larger A105 carbon stesi & A182-F22 valves supplied Feb 1981-Aug 1982 Valves should be serviced & stem & Are bonnet replaced ISABELLE.L D Convai. Inc 82/10/11 HAYNES.R & Region I, Office of Director 17pp 15954 202 24X Fiche 50-000.82/10/11.
- 210260106 RO 50-29/82-33 on 821009.main contant pump 1 vent isolation valve usid discovered slightly moist Weld will be repaired during current refueling outage AUTIO, HAY Yantee Atomic Electric Co 62/10/12 HAYNES.R C Region 1. Office of Director ip 15799 119 24X Fiche 50-029.82/10/12.8210260106
- '10260169 Forwards LER 82-029/03L-0 AUFIO.H A Yantee Atomic Electric Co 82/10/13 HAYNES,R C Region 1. Office of Director 1p 15799 001 24X Fichs 50-029.82/10/13.8210260165
- 8210260169 LER 62-029/03L-0 on 820913.during refueling outage in Mode 5 while performing calibr of steam generator marrow-range level trip system to 3 found less then Tech Speciant Ceused by setpoint Grift FRENCH.L D Yantes Atomic Electric Co 82/10/13 Region 1. Office of Director 1p 15797 002 24X Fiche 50-029.82/10/13. 8210260165
- 10260428 LER B2-035/01T on B21013, reactor protection sys permissive 2/stables B/S 420 & B/S 423 found cellbr out of tolerance 2aused by surveillance procedure inadequacy Bistables ecalibr 30410.H A Yankee Atomic Electric Co 82/10/13 HAYNES,R C 1egion 1. Office of Director. 1p 15806 273 24X 1che 50-029, B2/10/13, B210260428
- 0280085 LER 82-032 has been cenceled JUTIO,H A Yantee Atomic Electric Co 82/10/20 HAYNES,R C legion 1, Office of Director 1p 15837 183 24X 1ch 50-029, 82/10/20,8210280085

KET 50-54 UNION CARBIDE RESEARCH REACTOR

Operating license stage documents & correspondence

- 0:30302 Forwards figures inadvertently omatted from 800323 ppilotion for renewal of License R-81 & addition henges to Tech Bees
 OTH:N H Union Carbide Corp 82/09/29 BERNARD.H tanderdization & Special Projects Branch 13pp 15678 318 24X ich 50-054, 82/09/29, 8210120302
- 210130306 Proposed Tech Spec changes re fueled experiments to staffing, supplementing 800523 application to renew Licente R-Bi

 e Union Carbide Corp 82/09/29 5pp 15678 333 24X Fiche: 50-054.82/09/29 8210130302
- KEY 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR Security, medical, emergency & fire protection plans
- 0010277 Forwards Revision 4 to security plan Revision withheld ref 10CFR2.790) ENRYLL.0 New York, State Univ of, Buffain 82/09/17 THOMAS, C tandardistation & Special Projects Branch. 1p 13573 121 24X 1che:50-057:82/09/17.8210010277

- DOCKET 50-42 UNIV OF VIRGINIA RESEARCH REACTOR
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8210050377 SAFETY EVALUATION REPORT RELATED TO THE RENEWAL OF THE OPERATING LICENSE FOR THE UNIVERSITY OF VIROINIA OPEN-POOL RESEARCH REACTOR Docket No 50-062

 4 Division of Licensing NAREG-0928 92/09/30 77pp Available at NRC \$5 00 15826 030 24% Fich 50-062,82/09/30,8210050377
- P Operating license stage documents & correspondence
- 8210060086 informs of minor mods made to ECCS piping Flexibls piping installed on tank side of remote coupling to provide necessary movement for coupling alignment Repair will have no adverse effect on ability of ECCS to perform BRENIZER.J S Virginia. Univ of 82/09/27 Standardization & Special Projects Branch 6pp 15615 038 24X Fiche 50-062, 82/09/27.8210060086
- B2100B0237 Forwards licensee B20929 itr to ORNL requesting shipment of DDE-owned MTR type reactor fuel using MFIR spent fuel shipping caek
 BERNECHE,P E Virginia, Univ of B2/09/30 CARTER,R E
 Standardizetion & Special Projects Branch 3pp 15638 078 .24X
 Fiche 50-062,82/09/30.8210080237
- 8210120475 Forwards Amend 15 to Licenee R-66.EIA & notice of isswance/ nagative dscleration Amend renews OL for 20 yrs THOMAS.C O Standardijation & Special Projects Branch 82/09/30 BRENIZER.J S Virginia-Univ of 2pp 15672
- --8210120480 Amend 15 to License R-66 renewing OL for 20 yrs
 THOMAS.C D Standardization & Special Projects Branch 82/09/30
 34pp 15672 007 24% Fiche 50-062 82/09/30 8210120475
- --8210120487 EIA supporting Amend i5 to License R-66
 * Stendardization & Special Projects Branch 82/09/30 3pp
 15672 042 24X Fiche 50-062.82/09/30.8210120475
- --8210120492 Notice of renewal of facility OL & negative declaration re Amend 15 to License R-66 THOMAS: C O Standardization & Special Projects Branch 82/09/30 2pp 15672 049 24X Fiche 50-062.82/09/30,8210120475
- 8210180014 Submits daily highlight for 820930 NRR issued 20-yr renewal of License R-66 CARTER: R E Standardization & Special Projects Branch 62/10/DI CASE.E . CARTER: J Office of Nuclear Reactor Regulation, Director EISENHUT. D Division of Licensing ip 15717 352 24X Fiche 30-062: 82/10/01.8210180014
- OOCKET 50-70 GENERAL ELECTRIC TEST REACTOR
 G Adjudicatory correspondence
- 8210200097 Notics of ASLB reconstitution of Frye, chairman & H Foreman & GA Linenberger, members COTTER: 8 P Atomic Safety and Licensing Board Panel B2/10/14 2pp 15753 196 24X Fiche 50-070, 82/10/14, 8210200087
- 8210220343 Memorendum & order directing OE to file rept on intention is submit applications to renew OL & SMM license, within 15 days of svc of order FRYE.J H Atomic Bafety and Licensing Board Panel 82/10/21 Osneral Electric Co 3pp 13776 265 24X Fiche 30-070,82/10/21,82102-2047
- P Operating license stage documents & correspondence
- 8210250110 Application to amend License TR-1, requesting additect Epec changes reflecting removal of irradiated SNM by eliminating tests re reactor bldg integrity GUNNINAMA, 0 E. General Electric Co. 82/10/12 TEDESCO, R. L. Assistant Director for Licensing 2pp 15787 028 24X Fiche 50-070, 82/10/12, 8210250110
- --8210250113 Proposed Tach Spac changes reflecting removal of irradiate SMM by eliminating tests re reactor bldg integrity 4 Ceneral Elsetric Co. 82/10/12 2pp. 15787 030 24% Fiche 50-070,82/10/12,8210250110

- DOCKET 50-72 UNIV OF UTAH RESEARCH REACTOR
- A Periodic operating reports & related correspondence
- 8210260224 Ack receipt of 820924 ltr forwarding revised annual operating rept for 1981 SEIDLE: W C Division of Resident. Reactor Project & Engineering Programs 82/10/22 JACOBS, H R Utah. Univ of ip 15799 156 244 Fiche 50-072,82/10/22,8210260224
- ~~8210260230 Forwards revised "Annual Operating Rept.1981"

 JACOBS.H R Utah. Uni. of 82/D9/24 MADSEN.G L Region 4.

 Office of Director ip 15799 157 24X Fiche 50~072,82/10/22.
 8210260224
- --8210260234 Revised "Annual Operating Rept. 1981" SANDOUIST. G M Utah. Univ of 82/07/24 2pp 15799 158 24% Fiche 50-072, 82/10/22, 8210260224

DOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR

- G Enspection reports, IE Bulletins & correspondence
- 8210010120 Forwards 1E Insp Rept 50-083/82-02 on 820811-13 No noncompliance noted VERRELLID H Division of Project & Resident Programs 82/08/31 JACOBS.A M Florida. Univ of, Gainesville 2pp 15566 032 24X Fiche 90-083.82708/31.8210010120
- --0210010122 IE Insp Rept 50-083/82-02 on 820811-13 No noncompliance noted Major areas inspected radiation protection PEERY.W W . BARR.K P Division of Engineering & Technical Programs 62/08/30 3pp 15564 034 24X Fiche 50-083,82/08/31, 8210010120

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

- F Security, medical, emergency & fire protection plans
- 6210010198 Forwards safeguards info re changes implemented in security plan info withheld (ref 100FR73 21)
 CRANE.P A Parific Oak & Electric Co 82/07/23 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ip 15568 077 24X
 Fiche 50-133.82/07/23.8210010199
- G Adjudicatory correspondence
- 8210060189 Order extending time until 821012 for Commission to act to review Director's Decision DD-82-7 CHILKS J Office of the Secretary of the Commission 82/10/04 Commissioners in 15513 228 24x Fiche 50-133,82/10/04,8210040189
- 82:0)50193 Advises that Commission declined review of Director's Decision DD-82-7 Time for Commission to act expired Decision became final agency action on 82/1012 CHILKS J Office of the Secretary of the Commission 82/10/13 GUENTHER.R Affiliation Unknown ip 15707 259 24X Fishe 50-133, 82/10/13, 82/10/5193
- P Operating license stage documents & correspondence
- 8210240359 Responds to Generic Ltr 82-12, "Policy on Factors Causing Fatigue of Operating Personnel at Nuclear Reactors "Existing procedures comply w/policy statement CRANE.P A Pacific Cas & Electric Co 82/10/21 MIRAQLIA,F J Licensing Branch 3 ip 15804 258 24% Fiche 50-133,82/10/21.
- Q Inspectson reports: IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 implant Seeds " Syc list encl CODB.L I Division of Fuel Facilities, Materials & Safequards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000, 82/10/06, 8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Dismeter, Stainless Steel, Recirculation Sys
 Piping at BWR Plants " Syc list encl
 DEYGUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche 30-000, 82/10/14, 8208190238

- R Periodic operating reports & related correspondence
- 8210250192 Forwards third quarterly status rept re plant operational status & util activities.per 820216 order Study re future disposition of plant uill be completed within & months of issuance of NRC final reactor safety policy statement OHLBACH.R., CRANE.P.A., LOCKE.R.F. Pacific Oas & Electric Co 82/10/01 LAZQ.R.M. SCHINK.D.R. LINENBERGER.O. Atomic Safety and Licensing Board Panel 2pp 15787 336 24X Fiche 50-133,82/10/01,8210200192
- --8210250196 Third quarterly status rept for facility Certificate of Svc encl LOCKERF Pacific Gas & Electric Co 82/10/01 4pp 15787 338 24% Fiche 50~133.82/10/01.8210250192

DOCKET 50-142 UCLA TRAINING REACTOR

- F Security, medical, emergency & fire protection plans
- 8210270023 Partial response to FOIA request for documents re UCLA Lab & research reactors Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/03 HIRSCH, D government Accountability Project 2pp 15864 195 24X Fiche 50-142,82/09/03,8210270023
- ~-8210270036 Requests that licensee submit new physical security plan to comply w/new regulations to 10CFR50:70 & 73 by 740107 SKOVHOLT.D J Atomic Energy Commission. Directorate of Licensing 73/1/30 HICKS, T E California. State of 1p 15864 257 24x Fiche 50~142,82/09/03.8210270023
- ---B210290043 Forwards add1 info re physical security plan Info withheld (ref 10CFR2 790) ASHBAUGH, C E California, Univ of, Los Angeles 74/11/27 GOLLER, K R Atomic Energy Commission, Directorate of Licensing 1p 15844 260 24X Fiche 50-142,82/09/03,8210270023
- --B210290051 Forwards SNM inventory info for nonpower reactor facilities
 Info withheld (ref 10CFR2 790) Authorization to retain
 inventory requested
 ABHGAUGH.C E California. Univ of, Los Angoles 76/01/30
 GOLLER.K R Division of Operating Reactors 2pp 15864 263 24X
 Fiche 50-142,82/09/03.8210290023
- --8101200322 Notifies that since reactor operating & SNM storage sites are contiguous. Pacility must implement interim Category I physical security requirements Compliance plan required by 810131
 MILLER.J R Standardization & Special Projects Branch 81/01/12
 MEOBT. W F California. Univ of, Los Angeles 1p 15865 093
 24% Fiche 50-142.82/09/03.8210270023

O Adjudicatory correspondence

- B210080077 Response supporting Committee to Bridge the Oap B20720 motion for summary dismissal of NRC & util B20701 & 03 motions for summary disposition. ABLB statements on use of summary disposition flagrantly disregarded by NRC & util BHRLEY, BJ Banta Monica, CA B2/10/06 Abomic Safety and Licensing Board Panel App 15640 193 24X Fiche 50-142,82/10/06,8210090077
- 8210120261 Response opposing Committee to Bridge the Gap 820920 motion to dismiss NRC & applicant 820901 summary disposition motions Extension until 821113 should be granted to allow Committee response W/Certificate of Svc MODDHEAD.C P Hearing Branch 1 82/10/08 Atomic 8afety and Licensing Board Panel 26pp 15652 184 24X Fiche 50-142,82/10/08, 8210120261
- 8210150454 Response opposing Committee to Bridge the Qap 820720 motion to dismiss NRC & util motions for summary disposition Commission rules preclude dismissal of summary disposition motions filed per schedule W/Certificate of Svc CORMIER WH California, Univ of, Los Angeles, 82/10/08 Atomic Bafety and Licensing Baard Panel 19pp 15703 132 24X Fiche 50-142,82/10/08,8210150456
- 8210230076 Forwards UCLA 821008 ltr to NRC smending Feb 1780 license renswal application Changes include reducing licensed limit on permissible inventory of fuel to less than 500 g enriched U-235 CORMIER, W H California, Univ. of, Los Angeles. 82/10/15 FRYE, J H , PARIB, O H , LUEBKE, E A Atomic Safety and Licensing Board Panel | 11pp | 15789 352 | 24x Fiche 50-142,82/10/15,8210230076

8210250223 Hemorandom & order denying Committee to Bridge the Gap (CBG) 820920 motion to summarily dismiss NRC & util autions for summary disposition or alternative relief UCLA-NRC & CBG must furnish lists of citations of mati fact LUEBKE.E A. PARIS, O H. FRYE.J H. Atomic Safety and Licensing Board Panel 82/10/22 Committee to Bridge the Gap. 12pp. 15789-314 24X Fiche 50-142-82/10/22,8210250223

P Operating license stage documents & correspondence

- 8210130115 Requests amend to application for 10CFR70 license to reflect reduced inventory of unitradiated U-235 reactor fuel THOMAS.C O Standardization & Special Projects Branch 82/09/27 (#808T.W F California Univ of Los Angeles ip 15696 082 24% Fiche 50-142.82/09/27.8210130115
- 8210200081 Application for amend to Feb 1980 renewal application for License R-7i, replacing pages re reduction of permissible inventory of reactor fuel & altering purpose & function of cafety high level radiation monitor WEOST.N F California, Univ of, Los Angeles 82/10/08 THOMAS.C O Standardization & Special Projects Branch 10pp 15783 198 24% Fiche 50-142,82/10/08.8210200081
- B210250076 Forwards UCLA B21008 ltr to NRC amending Feb 1980 license renewal application Changes include reducing licensed limit on permissible inventory of fuel to less than 500 g enriched U-235 CORMIER.H H California, Univ of, Los Angeles 82/10/15 FRYE.J H. PARIS:O H. LUEBKE.Z A Atomic Safety and Licensing Board Panel lipp 15789 352 24X Fiche 50-142.82/10/15.8210250076

Q Inspection reports: IE Bulletins & correspondence

- 8210270023 Partial response to FOIA request for documents re UCLA Lab & research reactors Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/09/03 HIRSCH.D Government Accountability Project 2pp 15864 195 24X Fiche 50-142.82/09/03.8210270023
- --8210290048 Discusses ansp of activities authorized under License R-71 & SNN-974 on 790520 No noncompliance noted Major areas inspected control of SNM & selective esams of procedures & personnel interviews
 ENDELKEN.R H. Region 5. Sam Francisco. Office of the Director 75/06/10 BROWN.R V California. Univ of Los Angeles 1p 15864 262 24X Fiche 50-142,82/09/03.8210290023

DOCKET 50-148 UNIV OF KANSAS RESEARCH REACTOR

H General correspondence

- 820829090 FOIA request for six documents to Univ of KS research reactor
 ROBINSON B Affiliation Unknown 82/09/07 FELTON, J M Division of Rules and Records 2pp 15436 210 24X Fiche 50-148,82/09/07,8208290990
- 8208290097 FDIA request for documents re Univ of KS research reactor BARNES.C Affiliation Unknown 82/09/07 Docketing & Services Brench ip. 15889 119 24% Fiche 50-148,82/09/07.8208290097
- 8210060437 Responds to FOIA request for six documents re Univ of KS research reactor Request referred to PDR for processing FELTON.J M Division of Rules and Records 82/09/13 ROBINSON, 8 Affillation Unknown 1p 15636 212 24X Fiche 50-i48,82/09/13,8210060437
- 82102803B9 Responds to FDIA request for listed documents re Univ of KB rasearch reactor Request referred to PDR for processing FELTON. JH Division of Rules and Records 82/09/14 BARNES.C Affiliation Unknown 1p 15859 120 24X Fiche 50-148,82/09/14,82102803B9

DOCKET 50-151 UNIV OF ILLINOIS RESEARCH REACTOR

A Reportable occurrences. LERs & related correspondence

8210130476 RD From 820103-0505 reactor operated under reactor operator u/expired license. Caused by oversight Unicensed operator in charge of operation for approx 50-h.Individual filing application for license BECK. 0.P. Illinois, Univ. of, Urbana-Champeign 82/09/29 Division of Licensing 2pp 15682-161 24X Fiche 50-151.82/09/29, 82/0130476

- DOCKET 50-158 DIG ROCK POINT NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- 8210060222 Forwards addl fire protection info re associated circuits, alternate safe shubdown design & emergency condenser caustic attack in response to NRC 820430 ltr & NRC questions raised during 820908-09 site meeting concerning 10CFR50 App R VANDEMALLE.D J Consumers Power Co 82/09/28 CRUTCHFIELD.D Uperating Reactors Branch 5 57pp 15620 062 24X Fiche 50-155, 82/09/28, 8210060222
- 8210080279 Confirms commitment to incorporate responses to iE Inap Rept 50-155/81-17 into emergency plan implementing procedures & requests approval to use general ofc control ctr as temporary emergency operations facility yANDEHALLE.D J Consumers Power Co 82/10/01 KEPPLER.J Q Region J. Office of Director 5pp 15638 203 24X Fiche 50-155.62/10/01.
- 8210200029 Forwards emergency preparedness pamphlet for use in 5-mile emergency planning zone in Charlevoix County & part of Emnet County Pamphlet incorporates revisions & mods set forth in ASLB 820806 partial initial decision GALLO.J I sham Lincoln & Beale GALLO.J Consumers Power Co 82/10/14 GLOCKIP B. PARIS.O H. SHON.F.J. Atomic Gafety and Licensing Board Panel 30pp 15756 149 24% Fiche 50-155.82/10/#4.
- 8210250371 Provides addl info on proposed shift technical advisor position based on review of plant administrative procedures & site amergency plan & implementing procedures Min shift provides necessary protection in event of amergency BORDING.T C Consumers Power Ca 82/10/19 CRUTCHFIELD.O Operating Reactors Branch 5 2pp 15790 186 24x Fiche 50-135,82/10/19.8210250371

G Adjudicatory correspondence

- 8210010408 Motion for extension of time until \$21011 to file petition for reconsideration %/or motion for clarification re emergency planning portions of ASLO \$820914 decision Certificate of Svc encl GALLO.J Consumers Power Co GALLO.J Isham, Lincoln & Deale \$2/09/28 Atomic Safety and Licensing Board Panel Spp 15572 176 24X Fiche 50~135.82/09/28.8210010408
- 8210010446 Forwards util 820916 ftr to NRC re future scheduling matters in spent fuel pool mod proceeding Related correspondence GALLO, J lsham, Lincoln & Beale GALLO, J Consumers Power Cp 82/09/29 BLOCK, P B . PARIS D H . SHON, F J Atomic Safety and Licensing Board Panel 4pp 15572 292 24% Fiche 50-155,82/09/29,8210010446
- B2100400Bi Forwards proposed findings of fact & conclusions of law on O'Neill Contention II E 3 re criticality
 GDDARD, R J Hearing Branch 3 82/10/01 BLOCH, P B , SHON, F J ,
 PARIB.D H Atomic Safety and Licensing Board Panel 1p 15504 212
 24X Fiche 50-155,82/10/01,8210040081
- --B210040089 Proposed findings of fact & conclusions of law on O'Neil) Contention II E-3 re criticality GODDARD R J Hearing Byanch 3 82/10/01 10pp 15584 213 24x Fiche 50-155,82/10/01,8210040081
- 6210050232 Proposed initial decision on criticality contention Certificate of Svc encl CALLO.J. THORNYON.P Consumers Power Co. OALLO.J. Isham. Lincoln & Beale 82/10/01 28pp 15610 353 24X Fiche 50-155, 82/10/01. 8210050232
- 8210050356 Proposed findings of fact & conclusions of law on criticality contention Certificate of Svc encl
 QALLO, J. THORNTON, P. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale 82/10/01 17pp 19609 025 24X Fiche 50-155,82/10/01,8210050356
- 8210060204 Motion to establish hearing dates during wk of 821115-19 to littlgate Christa-Maria Contentions 2.9(1).9(6), 9(8) & 9(9) & 0'Neill Contentions II A.II D & II E-4 Early resolution of issues serves interests of parties W/Certificate of Syc OALLO, J Consumers Power Co OALLO, J Calio, J 82/10/01 Atomic Safety and Licensing Board Panel Spp 15614 162 24X Fiche 50-155, 82/10/01, 8210060204
- 8210060192 Order deferring briefing of Christa-Maria exceptions to AELB 820915 third partial initial decision & tolding time for filing exceptions to future partial initial decisions until svc of last decision Piecemeal review unproductive TOMPKINB.B A Atomic Bafety and Licensing Appeal Panel 82/10/04 Opp 15613,290 24X Fiche 50-155,82/10/04,8210060192

- 8210130448 Forwards reply to intervenor proposed findings of fact & conclusions of law on O'Neill Contention II-C re cask drop issue
 - 18848 GPELAND, V G Isham, Lincoln & Beale COPELAND, V G Consumers Power Co 82/10/06 BLOCH,P B , PARIS, D H , SHCN,F J Atomic Syfety and Licensing Board Panel 1p 15682 118 24X Fiche 50-155 82/10/06.8210130448
- --8210130457 Reply to intervenor proposed findings of fact & conclusions of law on O'Neill Contention II-C recask from issue GALLO, J. COPELAND, V. G. Consumers Power Co. GALLO, J. Isham, Lincoln & Deale 82/10/07 9pp. 15682 119 24X Fiche 50-155,82/10/06,8210130448
- -8210130471 inffidavit of TC Bordine re util commitments to upgrade visual acusty requirement for crane operators to comply w/stds of ANSI 830 2-1976, "Goverhead & Cantrys Crens" to cross-ref maint procedures Certificate of Svc enci 80RDINE.T C Consumers Power Co 82/10/05 4pp 15682 128 24X Fiche 50-155, 82/10/06. 820130448
- 9210150300 Hotion for extension of time until B21203 for util to demonstrate that deficiencies are remedied are not serious or are being remedied Util has diligently pursued steps to address deficiencies GALLO, J. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale 92/10/12 Atomic Safety and Licensing Board Panel 5pp 15707 273 24% Fichs 50-155,82/10/12,8210150300
- --B210150307 Affidavit of RW Sinderman re util actions in response to ASLB 820914 initial decision Addition required to assemble 2 document info in manner consistent W/ASLB request Certificate of Svc encl SINDERMAN R W Consumers Power Co 82/10/11 14pp 15707 278 24X Fiche 50-155.82/10/12.8210150300
- b210150341 Responses opposing licensee motion to fragment hearing intervenors would be denied right to be represented by counsel, noney would be wasted & fragmentation would violate intent of ASLAB order Certificate of Svc encl
 SEMMEL, the Christa-Maila SEMMEL, H Antioch Coilege of Law
 82/10/12 Atomic bafety and Licensing Board Fanel 6pp
 15706 002 24x Fichs 50-155.82/10/12.8210150341
- 8210150470 Reply to Christa-Maria B20927 proposed findings of fact & conclusions of law on 0'Meill Contention IIE-3 recriticality Contention w/o merit & should be dismissed Certificate of Svc encl GALLO, J. THORNTON, P. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale 62/10/12 topp 15703 053 24% Fiche 50-155, 62/10/12. 8210150470
- 8210180206 Metion for clarification &/or petition for reconsideration of portion of ASLB 820914 partial initial decision re legal requirement of NUREG-0554 Term "relocation requirement" unclear Celtificate of Syc encl CALLO. J Consumers Power Co CALLO. J Isham, Lincoln & Beale 82/10/12 Atomic Safety and Licensing Board Fanel App 15718 128 24X Fichs 50-155.82/10/12.8210180206
- 8210180242 Motion for extension of time until 821012 to file motion for clarification 2/or petition for reconsideration of ASLB 820914 partial initial decision Holiday to honor Columbus Day not considered in schedule GALLO. J. Isham, Lincoln & Beale 82/10/12 Atomic Safety and Licensing Board Panel 2pp 15718 059 24X Fichs 50-155,82/10/12,8210180242
- 8210150167 Hemorializes 821008 telcon w/ASLB re NRC position on util 821001 metion to establish hearing dates NRC agrees to splitting hearing into two phases but dates pose unalterable conflict w/another hearing for ASLB chairman & NRC counsel COUDARDLR J Hearing Branch 3 82/10/13 BLOCH, P B, SHON, F J, PARIB, O H Atomic Safety and Licensing Board Panel 2pp 15707 180 24x Fiche S0-155,82/10/13,8210150167
- 8210150469 Forwards 0 Zech 821012 trip rept of 820928 site visit, sugmarting events & conversations ROBERTS.T H Commissioners 82/10/13 SEMMEL.H Antioch College of Law SEMMEL.H Christa-Marta 3pp 15703 060 24X Fiche 50-155
- 8210200029 Forwards emergency preparedness pamphlet for use in 8-mile emergency planning ione in Charlevolx County & part of Emmet County Pamphlet incorporates revisions & mods set forth in ASLD 820806 partial initial decision CALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Cn 82/10/14 BLOCH, P B. PARIS, O H. SHON, F J Atomic Safety and Licensing Board Pamel 30pp 15756 149 24X Fiche 50-155,82/10/14,82000029

- 8210210349 Memorandum & order denying util 821001 motion to establish hearing dates & 821012 motion for clarification Hearing on issues delayed by applicant deferred Clarification motion not ripe for adjudication BLOCH, P B . PARIS, O H . SHON, F J Atomic Bafety and Licensing Board Panel 82/10/19 Consumers Power Co 3pp 15764 201 24X Fiche 50-155, 82/10/19, 8210210349
- 8210210381 Opposition to licensee motion to continue plant operations w/o compliance w/ASLB order on emergency planning Continued operation u/o adequate planning poses threat to lives & health of citizens W/Certificate of Svc SEMMEL.H . WIKTOR:D Christa-Maria SEMMEL.H . Antioch College of Law 82/10/21 About Safety and Licensing Board Panel App 13745 193 24% Fiche S0-155,82/10/21,8210210381
- 8210220338 Memorandum & order granting util 821012 motion for extension of time until 821203 to comply w/ASL8 821014 order to demonstrate compliance w/Commission emergency planning requirements
 BLOCH, P.B., PARIS, O.H., SHON, F.J. Atomic Safety and Licensing Board
 Panel 82/10/21 Carolina Power & Light Co. 3pp 19776 008
 24X Fiche 50-155,82/10/21,8210220338
- 8210250301 Advises that Region 3 will notify util to delete erroneous language in emergency preparedness pamphlet re respiratory protection measures Mods would not contrevene ASLB order CODDARD, R. J. Hearing Branch 3 82/10/22 BLOCH, P. B., PARIS, G. H., SHON, F. J. Atomic Safety and Licensing Board Panel 2pp 15790 21/3 24X Fiche 50-155.82/10/22,8210250301
- B210270271 Confirms U21026 telcon Intervenor has not decided whether to file 10CFR2 206 petition to suspend or revoke license because of emergency planning concerns

 BACHMANN,R Q Hearing Branch I B2/10/28 SEMMEL.H Antioch
 Coilege of Law Ip 15854 072 24X Fiche 50~155.82/10/28,
 B210270271
- J . Insurance & indemnity information
- 8210050100 Bubmits responses to 820712 questions concerning additionsurance coverage re 820622 request for exemption BACON.J L Consumers Power Co 82/08/10 BALTZMAN.J Office of State Programs, Director Opp 15603 278 24X Fiche 50-155.82/08/10.8210050100
- P Operating license stage documents & correspondence
- 8210280013 Responds to FOIA request for all internal non-public documents, nemos, evaluation repts & other mati dealing w/ nuclear plant operations forwards documents listed in App A FELTON, J M Division of Rules and Records 82/09/17 MCINNIS, D News & Observer 5pp 15850 065 24% Fiche 50-000.82/09/17, 8210280013
- --8208310034 Forwards draft info notice re deficiencies in air filtration & ventilation sys Notice based on radioactive resin release at Filgrim I & on four related events at other plants involving deficiencies in maint & testing of filter sys MATTBON.R J Division of Bystems Integration (post 81:005) 82/08/05 JORDAN.E L Division of Engineering & Quality Assurance Spp 19841 024 24X Fiche 50-000.82/09/17.8210280017

- --8210070018 Draft "Offsite Dose Calculation Manual," Palisades Plant & Consumers Power Co 82/09/24 55pp 13628 276 24% Fiche 50-000,82/09/29,8210070013
- 8210050425 Forwards "Evaluation of High Energy Pips Break Inside Containment for Sig Rock Point Nuclear Plant," in response to SEP Topic III-5 3 VANDEMALLE.D J Consumers Power Co 82/09/30 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15607 042 24X Fiche 50-155, 82/09/30, 8210050425
- --8210050427 "Evaluation of High Energy Pipe Break Inside Containment for Big Rock Point Nuclear Plant " GEBER W V. MASER: I R. RICCARDELLA, F. NUTECH (Nuclear Technology, Inc.) CPC-01-110 ROD BI/10/23 79pp 15507 044 24X Fiche 50-155,82/09/30,8210050425
- 8210050152 Comments on NRC draft safety evaluation of SEP Topic V-5.

 "RCPB teakage Detection." per 820319 request Info missing from Tables I t 2 of 820319 submittal encl Detection sysmest intent of current licensing criteria VANDEWALLE, D J Consumers Power Co 82/09/30 CRUTCHFIELD, D Operating Reactors Branch 5 9pp 15614 047 24X Fichs 30-155, 82/09/30, 8210050152
- 8210060237 Forwards response to NRC request for add1 into on SEP Topic 111-2, "Wind & Tornado Loadings " App C supersedes 820803 submitted Drawing showing cross-section of south end of control room wall can be retrieved from NMS VANDEMALLE.D J Consumers Power Co 82/09/30 CRUTCHFIELD.D Operating Reactors Branch 5 12pp 15619 327 24X Fiche 50-155.82/09/30.8210060239
- --8210060241 "Specs for Designing.Furnishing & Erecting Reinforced Concrete Chinney "

 4 Dechtel Corp. 3159 C-21 61/03/17 12pp 15619 339 24X Fitche 50-155, 82/09/30. 8210060239
- 821025009; Forwards draft safety evaluation & technical evaluation rept. "Design Codes, Design Criteria & Load Combinations (SEP 111-7 B), Big Rock Point" Util requested to respond to factual correctness of SER in 30 days CRUTCHFIELD, D. Operating Reactors Branch 5 B2/09/30 VANDEMALLE, D J Consumers Power Co. 11pp 15788 001 24X Fiche 50-155, B2/09/30, 8210250091
- --8209160459 "Dusign Codes, Design Criteria & Loading Combinations (SEP III-7 B), Big Rock Point: "technical evaluation rept STILHELL.T Frantiin Institute/Frantiin Research Center NRC-03-79-118 TER-C5257-317 B2/09/13 PERSINKO, D NRC No Detailed Affiliation Given 216pp 15788 012 24X Fiche 50-155,82/09/30.8210250091
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820909 ltr Staff encouraged to develop 2 implement means to incorporate positive attributes of Phase III in licensee/NRC interface KACICH.R H SEP Owners Group KACICH.R H Northeast Nuclear Energy Co (sube of Northeast Utilities) 82/10/07 EIBENNUT.D C Division of Licensing 7pp 15682 179 24% Fiche 50-000.82/10/07, 8210130326
- 8210150505 Advises of Franklin Research Ctr 820430 technical evaluation rept, "Containment Leskage Rate Tacking-(A 04)." Exemptions for instrument pressure lines should be granted to significant segredation of penetration scals observed BURDINE, T C Carolina Power & Light Co 82/10/12 CRUTCHFIELD, D Operating Research Sp. 2pp 15714 210 24x Fichs 50-153, 82/10/12, 8210150505
- 8210190459 Forwards current status of program to evaluate adequacy of overload & short-circuit protection for electrical circuits that pass through reactor containment per SEP Topic VIII-4 "Electrical Penetrations of Reactor Containment."

 TONER, K. A. Consumers Power Co. 82/10/12. CRUTCHFIELD.D. Operating Reactors Branch 5. 21pp. 15740 268 24X Fiche 50-000.82/10/12. 82/10/20459
- 8210200041 Forwards safety evaluation of SEP Topic IX-5, "Ventilation Sys " Evaluation will be basic input to integrated safety assessment Also forwards "Review of Design & Operation of Ventilation Sys for SEP Plants," technical availation rept GRUTCHFIELD.D Operating Reactors Branch 5 NRC-03-79-118 B2/10/12 VANDEMALE, DJ Consumers Power Co 9pp 15755; 358 24% Firth 50-155, 82/10/12, 8210200041.
- --B208180082 "Review of Design & Operation of Ventilation Sys for SEP Plants:" final technical evaluation rept HERRION.R.C. Franklin Institute/Franklin Research Center NRC-03-79-119, TER-C5257-414 B2/08/13 BROWN.S NRC No Detailed Affiliation Given, 21pp 15756 003 24X Fich; 50-159, 82/10/12, 8210200061

 $(1-\frac{1}{10},\frac{1}{10$

e 1,

- 8210150469 Forwards 0 Zech 821012 trip rept of 820928 site visit, summar(sing events & conversations ROBERTS, T M Commissioners 82/10/13 SEMMEL, H Antioch College of Law SEMMEL, H Christa-Maria 3pp 15703 060 24X Fiche 50-155, 82/10/13, 8210150469
- 8210150503 Comments on 820812 final safety evaluation of SEP Topics V+11 A. "Requirements for Isolation of High & Low Pressure Sys" & V-11 B. "RHR Interlock Requirements " Core spray sys designed to perform function safely TDNER.K A Consumers Power Co 82/10/13 CRUTCHFIELD.D Operating Reactors Branch 5 4pp 15713 145 24X Fiche 50-155,82/10/1J,8210150533
- 8210250213 Forwards evaluation of SEP Topic III-4 C, "Internally Openerated Missiles," 5 related SER Facility meets acceptance criteria for topic Info will be basic input to integrated sarety assessment CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/14 VANDEMALLE, D. J. Consumers Power Co. 25pp. 15/88.247 24X Fishe 50-155.82/10/14.8210250213
- B250220368 Forwards safety evaluation of MARCG-0737. Item 11 € 4 .2. "Containment Isolation Dependability " Facility meets guidance Item resolved CRUTCHFIELD.D Operating Reactors Branch 5 02/10/18 VANDEHALLE.D Consumers Power Co 5pp 15/79 187 24X Fiche 50-155. 82/10/18.8210220368
- 0210250323 Forwards Amend 54 to License DPR-6, safety evaluation & notice of issuance & availability Amend approves Tech Opec changes re NUREQ-0737; Item [[Fi(3]]] on leak testing intervals CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/18 VANDEHALLE, D. J. Consumers Power Co. 1p (5790-010) 24X Fiche 50-155, 82/10/18, 8210250323
- --82i0250327 Amend 94 to License DPR-6, changing foch Specs re containment high radiation monitor requirement by TMI Action Item II F t(3) on leak testing intervals CRUICHFIELD, D Operating Reactors Branch 5 82/10/18 10pp 15790 011 24X Fiche 50-155,82/10/18,82(0250323
- --9210250333 Safety evaluation supporting Amend 94 to License DPR-6 • Office of Nuclear Reactor Regulation, Director 82/10/10 Jep 15790 021 24% Fiche 50-155.82/10/18.8210230323
- --8210250337 Notice of issuance & availability of Amend 54 to License PRF-4 CRUTCHFIELD: D Operating Reactors Branch 5 82/10/18 2pp 19790 024 24X Fichs 50-155, 82/10/18, 8210250323
- 8210220117 Forwards GE turbine hydraulic control lever Diagram 2127316-A (ALTO), requested by fower Sys Branch during 821013 conference call per SEP Topic III-4 B. "Turbine Missiles" TDNER.K A Consumers Power Co 82/10/19 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 15778 147 24% Fiche 50-155,82/10/19,8210220117
- 8210270270 Forwards draft safety evaluation of SEP Topics III-6. "Seismic Design Considerations" & III-11. "Component Integrity " Licensee analyses of structures.burged piping & reactor coolant loop piping insdequate CRUTCHFIELD.D Operating Reactors Branch 5 82/10/19 VANDEMALLE.D Consumers Power Co 36pp 15852 048 24% Fische 50-155.82/10/19.8210270270
- --8208110271 Forwards geotechnical review of seismic safety margin study in response to verbal request during 820524 meeting Range of soil shear module values used in parametric study by licensee adequately envelope expected values

 LEAR. 9 Hydrologic & Geotechnical Engineering Branch 82/07/30 RUSECLLW T Systematic Evaluation Program Branch 10pp 15852 108 24X Fiche 50-155, 82/10/19,8210270270
- --8205250010 Forwards "Seismic Review of Big Rock Point Nuclear Power Plant Containment Shell Structure.as Part of SEP "
 LO, T Lawrence Livermore Laboratory FIN A-0436 82/05/20 RUSSEL, 4 T & Systematic Evaluatian Program Branch 1p 15852 118 24X Fiche 50-155, 82/10/19,8210270270
- --8203250020 "Beismic Review of Big Rock Point Nuclear Power Plant, Containment Shell Structure, as Part of SEP " LIAM.C Y EG&O, Inc FIN A-0436 SRO-307 B2/04/30 NRC - No Detailed Affiliation Given 28pp 15852 119 24X Fiche 50-153, 82/10/19, 8210270270
- --8210270288 "Seismic Design," informal technical evaluation rept CALL.V B.: THOMPSON,Y R EQ&O, Inc FIN A-6426 EQG-EA-6051 82/09/30 HERRINO,K Division of Licensing S2pp 15852 146 24X Fiche 50-155,82/10/19.8210270270

- ©210250310 Forwards safety evaluation of SEP Topic XV-19, "LOCA nicidents Resulting From Spectrum of Postulated Piping Breaks Within RCPD (Radiological) "Facility meets acceptance criteria CRUICHFIELD D Operating Reactors Branch 5 82/10/20 VA.DEMALLE, D J Consumers Power Co 10pp 15790 053 24X Fiche 30-155, 82/10/20 82/0250310
- p210270269 Advises that NUREG-0737, Items II K 3 IB & II K 3 45 ro automatic depressorization sys, inapplicable to facility Therefore items resolved CRUTCHFIELD.D Operating Reactors Branch 5 82/10/20 VANDEMALLE.D Consumers Power Co 4pp 15827 045 24X Fiche 50-155, 82/10/20, 8210270265
- 🕝 Inspection reports, 1E Bulletins & correspondence
- \$210050336 Ack receipt of B20917 ltr informing NRC of steps taken to correct moncompliance noted in IE lnsp Rept 50-155/B2-12 SPESBARD, R L Division of Project & Resident Programs 82/09/24 DEMITT, R B Consumers Power Co Ip 15610 098 24X Fiche 50-155, B2/09/24, 8210050336
- --0210050342 Responds to NRC 820817 ltr te noncompliance noted in IF Insp Rept 50-155/82-12 Corrective actions unauthorized activity terminated on 820417 following review by operations superintendent VANDEMALLE. D.J. Consumers Power Co. 82/09/17 KEPPLER, J. O. Region 3. Office of Director 2pp 15610 679 244 Fiche 90-155, 82/09/24, 8210050336
- E3210080279 Confirms commitment to incorporate responses to LE Insp Rept 50-155/81-17 into emergency plan implementing procedures & requests approval to use general ofc control ctr as temporary emergency operations facility VANDCHALLE.D J Consumers Power Co 82/10/01 KEPPLER.J C Region J. Office of Director 5pp 15638 203 24X Fiche 50-155.82/10/01, 8210080279
- ER 208190233 IE Info Notice 80-35, Suppl 1, "Lraking & Disiodged 1-125 Implant Seeds " Svc Iist encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 244 Fiche 50-000.82/10/06.8208190233
- 3≥10220233 Forwards evaluation of SEP Topic III-3 C. "Inservice Insp of Mater Control Structures" Insp program needs mod to conform W/Reg Quide 1 127 CRUTCH*IELD.D Operating Reactors Branch 5 82/10/12 VAIDEMALLC.D J Consumers Power Co Bpp 15775 104 24X Fiche 30-155.82/10/12.8210220233
 - -6206300189 "Hydrological Considerations Inservice Insp of Water Control Structures, (SEP. 11-3A, B, B), C, [[1-3B], " technica] evaluation rept SCHERRER, J Franklin Institute/Franklin Research Center NRC-03 79-118 TER-05257-542 62/06/23 STALEY, O NRC No Octailed Affiliation Given 15pp 15775 112 24X Fiche 50-155, 82/10/12, 82/022023
- 203190238 IE Dulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter: Stainless Steel-Restroulation Sys Paping at BMR Plants" Svc list encl
 DEYOUND.R C Director's Office. Office of Inspection and Envorcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24x Fishe 50-000.02/10/14.8203190238
- 210260220 Advises that spiked air particulate filter being forwarded to util for analysis per 820427 discussion Util results will be compared w/NRC analysis, in effort to close out open Item in IE insp Rept 50-155/82-07

 PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/10/20 HOFFMAN, D P Consumers Power Co ip 1 5804 247 24% Fiche 50-155/82/10/20,8210240220
- E1 O260315 Ack receipt of 821015 Itr informing NRC of steps taken to Correct violations noted in IE Insp. Rept 50-155/82-09
 MADRELIUB.C E Division of Project & Resident Programs B2/10/22
 DEWITTER B Consumers Power Co 1p 15799 328 24X
 Fische 50-155, 82/10/22, 8210260315
- E210260316 Responds to NRC 820917 ltr re violations noted in IE Insp Rept 50-155/82-09 Corrective actions training procedures & requirements revised & will be clarified by 830101 VANDEWALLE, D. J. Consumers Power Co. 82/10/15 KEPPLER, J. G. Region 3, Office of Director 6pp 15799-329 24X Fiche 50-135,82/10/22,8210260315

- 5 Reportable occurrences, LERs & related correspondence
- 8210080251 PNO-111-82-097 on 820914.A5LB issued order delineating deficiencies in state offsite emergency preparedness Util given 1 month to demonstrate deficiencies remedied PAGLIARO.J. AXELSON.W. PAPERIELLO.C Region 3. Office of Director 82/09/20 ip 15638 lib 24% Fiche 50-155.82/09/20.8210080251
- T Hearing transcripts on non-antitrust matters
- 8210290360 Forwards signed original transcript of L Reiter deposition taken on 820917 W/o enc1

 BACHMANNIR 0 Hearing Branch 1 82/10/28 GALLO, J [sham: Lincoln & Beate GALLO, J Consumers Power Co ip 19853 089 24X

 Fiche 50-155: 82/10/28.8210270360
- DOCKET 50-160 GEORGIA INST. OF TECH RESEARCH REACTOR

 O Inspection reports, 1E Bulletins & correspondence
- 8210220312 Ack receipt of 821004 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-160/82-02 VERRELLI, D.M. Division of Project & Resident Programs 82/10/14 CARLSON, N.O. Georgia Institute of Technology ip 15776 ti7 24x Fiche 50-160, 82/10/14.8210220312
- --8210220319 Responds to NRC 820908 ltr re violations noted in IC Insp Rept 50-160/82-02 Corrective actions personnel counseled RUSSELL.J U Georgia Institute of Technology 82/10/04 VERRELUI.D M Division of Project & Residont Programs 3pp 15776 il8 24% Fiche 50-160, 82/10/14,8210220312
- --8210220325 Forwards 1E 18sp Rept 50-160/82-02 on 820825-26 & notice of violation VERRELLI.D M Division of Project & Resident Programs 82/09/08 DAVIS, M V Georgia Institute of Technology 2pp 15776 121 24) Fiche 50-160, 82/10/14,8210220312
- --8210220330 Notice of violation from insp on 820825-26 = Division of Project & Resident Programs 02/09708 ip 19774 123 24x Fiche 50-160.02/10/14.0210220312
- --B210220341 IE Insp Rept 50-160/82-09 on B20825-26 Noncompliance noted on B20513 irradiated mat1 removed from biological shield penetration H-12 w/o health physics supervision PEER', W W , BARR, K. Division of Project & Resident Programs B2/09/07 Ap 19776 124 24X Fiche 50-160.82/10/14.8210220312

DUCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

- G Adjudicatory correspondence
- 8210050273 Order scheduling 821015 prehearing conference in Bethesda.MD re remaining outstanding issues Proposed schedules should be presented HOYT.N F Atomic Bafaty and Licensing Board Panel 82/10/01 2pp 15607 191 24X Fichs 50-170.82/10/01.8210050273
- 8210150317 Second supplemental response to first set of interrogatories Certificate of SVc encl Related correspondence
 MACKLIN.L Citizens for Nuclear Reactor Safety, Inc MACKLIN.L Institute for Public Representation 82/10/08 47pp 13701 270 24X Fiche 30-170, 82/10/08, 8210150317
- 8210150395 Provides info re counsel for Citizens for Nuclear Reactor Safety Entousle to continue as counsel L Macklin & Inst for Public Representation will withdraw as counsel effective 821219.

 MAGKLIN.L Institute for Public Representation MACKLIN,L Citizens for Nuclear Reactor Safety, Inc. 82/10/08 HQYT,H Atomic Safety and Licensing Board Panel 2pp 15704 032 24X Fiche 30-170,82/10/08. B210150395
- 8210220439 Forwards motion for encl protective order to protect against public disclosure or misuse of I Stillman address & telephone number MACKLIN.L. Institute for Public Representation MACKLIN.L. Citiens for Nuclear Reactor Safety, Inc 82/10/19 HOYT.H Atomic Safety and Licensing Board Panel ip 15778 239 24% Fiche 50-170.82/10/19,8210220439.
- --8210220448 Motion for protective order to protect against public disclosure or misuse of I Stillman address & telephone number Proposed protective order & Certificate of Svc encl MACKLIN.L.W S. Citizens for Nuclear Reactor Safety, Inc MACKLIN.L.W,S. Institute for Public Representation 82/10/19. Atomic Bafety and Licensing Board Panel 5pp 15778 240 24X Fiche 50-170.82/10/19.8210220439

9210250235 Order granting Citizens for Nuclear Reactor Safety 821019 motion for protective order to protect against public disclosure ar misuse of 1 Stillman address & telephone number HOYT, HF Atomic Safety and Licensing Board Panel 82/10/21 Citizens for Nuclear Reactor Safety, inc 1p 15788 357 24% Fiche 30-170, 82/10/21, 8210250235

B210280220 Provides dates when Citizens for Nuclear Reactor Safety would be available for plant tour MACKLIN,L Institute for Public Representation MACKLIN,L Citizens for Nuclear Reactor Safety.inc B2/10/21 H0YT,H Atomic Safety and Licensing Board Panel 2pp 15837 087 24% Fiche 30-170.82/10/21.02210280220

8210260429 First supplementary answers to interrogatories Certificate of Svc enci RICKARD,D C Armed Forces Radiobiological Research Institute 82/10/22 Citizens for Nuclear Reactor Safety, Inc 12pp 15806 038 24x Fichs 50-170,82/10/22,8210260425

H General correspondence

S210150200 Notice of change of address
ENTHISLE,E B Citizens for Nuclear Reactor Safety, Inc
ENTHISLE,E B Entwisle.E B 82/10/08 1p 15701 362 24X
Fiche 30-170,82/10/08.8210150200

T Hearing transcripts on non-ant(trust matters

6210170238 Transcript of 821015 prehearing conference re license remewals in Bethesda MD Pp 652-738

* Atomic Safety and Licensing Board Panel 82/10/15 87pp 15742 230 24% Fiche 50-170.82/10/15,8210170238

DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

9210050540 Forwards Amend 6 to License R-87 & safety evaluation Amend changes Tech Specs re drop times of shim safety rods & time intervals between meetings or surveillance action THOMASIC O Standarditation & Special Projects Branch 82/09/13 STANSBERRY.E R Purdue Univ 2pp 15637 204 24X Fiche 50-182, 82/09/13,8210050540

--B210030543 Amend & to License R-B7, changing Tech Spec limits on drup times of shim safety rods & changing certain surveillance intervals THOMAS.C D Standardization & Special Projects Branch B2/09/13 11pp 15637 206 24X Fiche S0-182,82/09/13.8210050540

--8210050548 Safety evaluation supporting Amend 6 to License R-87

• Office of Nuclear Reactor Regulation, Director 82/09/13 Spp
15537 217 24X Fiche 50-182.82/09/13.8210050540

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

G Inspection reports: IE Bulletins & correspondence

8210270300 Forwards 1E insp Rept 50-184/82-02 on 820708-10 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/10/08 CARTER.R 8 Commerce.Dept.of. National Bureau of Standards 2pp 15855 036 24X Fiche 50-184.82/10/08.8210270300

--8210270301 Notice of violation from insp on 820708-10 * Division of Project & Resident Programs 82/10/08, 1p \$5855 038. 24% Fiche, 50-184, 82/10/08, 8210290300

--8210290304 IE insp Rept 50-184/82-02 on 820908-10 Noncompliance noted failure to instruct worker in precautions, procedures, purposes & functions of protective devices used to minimize personal exposure to radiuactive matl & radiation KINNEY,W W : KEIMIQ.R R Division of Project & Resident Programs 82/09/28 7pp 15855-039 24X Fiche 50-184,82/10/08,8210290300

R Pariodic operating reports & related correspondence

8210130160 Forwards "Operations Rept 33, Jan-June 1982,"
CARTER: R S Commerce: Dept of, National Bureau of Standards
82/09/30 THOMAS: C D Standardization & Special Projects Branch
1p 15673 066 24X Fiche 50-184,82/09/30,8210130160.

--B210130163 "Operations Rept 33, Jan-June 1982 "
CARTER.R 8 Commerce, Dept of, National Bureau of Standards
82/09/30 5pp. 15673 067 24X Fiche 50-184,82/09/30,8210130160

DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR

- O Inspection reports, IE Bulletins & correspondence
- 8210050359 Forwards 1E insp Rept 50-186/82-01 on 820816-17 & notice of violation
 MILLER, J R Division of Engineering & Technical Programs 82/09/45
 ALGER, D M Missouri, Univ of, Columbia 2pp 15609 001 2:4X
 Fiche 50-186, 82/09/15, 8210050359
- --8210050365 Notice of violation from insp on G20B16-17 MILLER, J.R. Division of Engineering & Technical Programs G2/09/15 2pp 15609 003 24% Fiche 50-186, G2/09/15, G210040 159

--8210050380 JE insp Rept 50-186/82-01 on 820816-17 Noncompliance noted failure to parform surveys to yost radiation & radioactive matis area & storage of radwaste at unauthorized offsite facility LOVENDALE, P C, ORANT, W B, OREGER, L R Division of Engineering & Technical Programs 82/09/14 8pp 15609 005 24X Fichs 50-186,82/09/15,8210050359

DOCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR

R Periodic operating reports & related correspondence

8210190365 Submits list of facility procedure changes, tests & experiments for Oct 1981-Sept 1982, per 10CFR50 59(b)
FAUR E Kansas State Univ 82/10/11 MILLER, J R Standardirats on & Special Projects Branch 2pp 15/40 316 24X
F(che 50-188,82/10/11,8210190365

DOCKET 50-192 UNIV OF TEXAS RESEARCH REACTOR

- P Operating license stage documents & correspondence
- 8210050174 Forwards description of mods to be made to reactor instrumentation % control sys Changes will modernize function or reliability of current console functions Phase i.Parts A & B of changes completed BAVER.T L Texas, Univ of 82/07/30 RUNNICUIT Region 4, Uffile of Director 14pp 15504 124 24X Fiche 50-192,82/07/30,820.0080178

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

P Operating license stage documents & correspondence

6210050341 Requests guidance on procedure for renewal of 10-yr titemae R-94 which expires on 630930
KANER B Manhattan College 82/09/28 BERNARD, H Standardiration & Special Projects Branch 1p 15610 120 24X
Fichs 50-199,82/09/28,8210050341

8210260506 Responds to 820728 request for guidance in preparing application to renew license NRC evaluations of recent applications end W/o end!

THOMAS/C O Standardization & Special Projects Branch #2/10/14 KANE.R 8 Manhattan College 2pp 15830 156 24X

Fiche 90-179,82/10/14,8210260506

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

Q Adjuditatory correspondence

8210260581 Forwards NFS & NY State Energy R&D Authority B20916 Juint Itr notifying of B20916 settlement date Settlement satisfies all three conditions of Paragraph 8 A of License CSF-1 for termination of NFS authority & responsibility under license EDOAR. O L Morgan, Lewis & Bockius EDOAR, O L Nuclear Fuel Services, inc (subs of Qetty Oll Co) 82/09/16 CUNNINGHAM, R L Division of Fuel Cycle & Material Sefety 1p 15830 143 244 Fiche. 30-201, 82/09/16, 8210260581

--82102605B2 Notifies of 820916 settlement date Settlement satisfies all three conditions of Peragraph B A of License CSF-1 for termination of NFS authority & responsibility under license. JACK: A New York, State of. Energy Research & Development Administration DEUSTER: R W Nuclear Fuel Services, Inc. (subsof Cetty 01: C) 82/09/16 CUNNINOHAM: R E Division of Fuel Cycle & Material Safety, ip 15830 144 24X Fiche 50-201:82/09/16:8210260581

- 8210070183 informs that time for Commission to review ALAB-679 expired Commission declined review Decision became final agency action on 821001 CHILK S.J. Office of the Secretary of the Commission 82/10/05 Office of the Esecutive Legal Director 1p 15634 261 24% Fichs 50-201.82/10/05.8210070183
- Operating license stage documents & correspondence
- 3210210041 DEDMORPHIC PROCESSES AND EVOLUTION OF BUTTERMILK VALLEY AND SELECTED TRIBUTARIES, MEST VALLEY, NEW YORK BOOTHROYD, J. C., TIMSON, B.S., DUNNE, L. A. New York, State of FIN B-6350 MUREO/CR-2862 B2/07/31 Division of Health, Sitting & Environment 117pp 15785 255 24X Ficho 50-201.82/07/31, 8210210041
- 3210260381 Forwards NFS & NY State Energy R&D Authority 820916 joint itr notifying of 820916 settlement date Settlement satisfies all three conditions of Peragraph 8 A of License CSF-1 for termination of NFS authority & responsibility under license EDGAR.G L Morgan. Leuis & Bockius EDGAR.G L Nuclear Fuel Services. Inc (subs of Cetty Dil Co) 82/09/16 CUNNINGHAM.R E Division of Fuel Cycle & Material Safety ip 15830 143 24X Fiche 50-201.82/09/16.8210260581
- -8210260582 Notifies of 820916 settlement date Settlement satisfies all three conditions of Paragraph 8 A of License CSF-1 for termination of NFS authority & responsibility under license JACK, R A New York, State of, Energy Research & Development Administration DEUSTER.R W Nuclear Fuel Services, Inc. (subs of Cetty Dii Co.) 82/09/16 CUNNINGHAM.R E Division of Fuel Cycle & Material Safety 1p. 15830-144 24X Fiche 50-201,82/09/16,8210260581
- P10180414 Notification of contract execution. Mod 4 to "West Valley Haste Burial" Contractor State Univ of NY. Albany JACOBS. A Research Contracts Branch FIN B-6350 82/09/26 BATSON. H. MICHOLSON. J. Office of Nuclear Regulatory Research, Director 1p 15745 275 24% Fishe 50-201.82/09/26.8210180414
- -8210180419 Mod 4, extending period of performance to 831231 to "West Valley Haste Durial" MAURER.R J New York, State of GUSTAVE.R P Division of Contracts FIN 8-6350 82/09/24 12pp 19745 276 24X Fiche 50-201.82/09/26.8210180414
- OCKET 50-206 SAN ONDERS NUCLEAR STATION, UNIT 1

 Security, medical, emergency & fire protection plans
- 210080210 Ack receipt of 820710 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50~206/82-21
 BIEHOP, I W Division of Resident, Reactor Project & Engineering Programs 82/10/04 FD0ARTY, DJ Bouthern Callfornia Edison Co ip 15640 080 24X Fiche 50-206,82/10/04,8210080210
- -8210080211 Responds to NRC 820812 ltr re violations noted in IE Insp Rept 50-206/82-21 Corrective actions nonfire retordant wood, oily rags & combustible debris removed from areas & amend to include emergency light impairment prepared FODARTY,D J Southern California Edison Co 82/09/10 ENGELKEN.R H Region 5, Office of Director 5pp 15640 081 24X Fithe 50-206,82/10/04.8210080210
- 210190525 Forwards Revision 7 to physical security plan Revision withheld (ref 10CFR73 21)
 BASKIM, K P Southern California Edison Co 82/10/15 EIBENHUT, D G Office of Nuclear Reactor Regulation, Director 1p 15740 035 24X Fiche 50-206,82/10/15,8210170625

Operating license stage documents & correspondence

- PiQIBBO013 Responds to FD1A request for all internal, non-public documents, menos, evaluation repts & other mati dealing w/ nuclear plant operations forwards documents listed in App A FELTON, J H Division of Rules and Records 82/09/17 MCINNIS, D News & Observer 5pp 15860 045 24X Fiche 50-000, 82/09/17, 8210280013
- 8210280082 "Desimetry Placement for Steam Generator Workers" WARNOCK, R Institute of Nuclear Power Operations 82/01/31 13pp 15860 310 24X Fiche 50-000,82/09/17,8210280013
- 1005030D Forwards draft evaluation of SEP Topic III-7 B, "Design Codes, Design Criteria & Load Combinations " Response to factual correctness of EER & proposed schedule for resolution of open items requested within 30 days PAULEUN.H Operating Reactors Branch 5 82/09/21 DIETCH.R Bouthern California Edison Ca lipp 15402 OOI 24X Fiche 50-206, 62/09/21.8210050300

- --B208170083 "Design Codes, Design Criteria & Loading Combinations (SEP, III-78), "technical evaluation rept STILNELL.T C Franklin Institute/Franklin Research Center NRC-03-79-118 TER-05257-318 B2/08/13 PERSINKO.D NRC No Detailed Affiliation Given 222pp 19602 012 24X Fiche 30-206, 82/09/21, 8210050300
- --0207300222 Draft "SEP Structural Review of San Dnofre Unit 1 Containment Structure Under Combined Loads" LOIT Lawrence Livermore Laboratory FIN A-0436 UCID-19141 DRFI 82/09/31 45pp 15602 234 24X Fiche 50-206.82/09/21, 8210050300
- B210060003 Requests submittal of fees for 820625 application for Amend 62 to License DPR-62.permitting delay in safety injection sys hydraulic value testing MILLER: N C License Fee Management Branch 82/09/23 DIETCH: R Southern California Edison Co Ip 13636 266 24X Fiche 50-206.82/09/23.8210060003
- 8210040062 Forwards safety evaluation rept & technical evaluation remain steem line break w/continued resolvanter addition Analysis acceptable CRUTCHFIELD. D Operating Reactors Branch 5 82/09/27 DIETCH.R Southern California Edison Co 2pp 15584 178 24% Fiche 30-206.82/09/27.8210040062
- ~-8210040064 Safety evaluation re main steam line break w/continued feedwater addition Licensee commitment acceptable w/installation of auxiliary feedwater motor driven pump w/pump runout protection # Office of Nuclear Reactor Regulation, Director 82/09/27 7pg 15584 180 24% Fiche 50-206.82/09/27,0210040062
- --8206030064 "PWR Main Steam Line Break W/Continued Feedwater Addition." technical evaluation rept VQ88URY:FW Franklin Institute/Franklin Research Center NRC-03-81-130 TER-05506-151 82/05/28 HEARN,P NRC No Detailed Affiltation Olven 25pp 15584 187 24X Fiche 50-206,82/09/27.8210040062
- 8210040193 Advises that util proposed masonry wall test program acceptable, subj to satisfactory resolution of concerns delineated in enci evaluation AddI info requested no later than 30 days prior to groposed restart date PAULSGN. H. Operating Reactors Branch 5 82/09/29 DIETCH. R. Southern Callfornia Edison Co. 4pp 15592 341 24x Fichs 50-206.82/09/29.8210040153
- 8210040177 Forwards "Seismic Evaluation of Reinforced Concrete Masonry Walls: Ban Onofre Unit 1," Vol 5 Fuel Storage Bldg Soli Backfill Condition Evaluation, per SEP Topic III-6 No addimods required to fuel storage bldg BASKIN.K P Bouthern Callfornia Edison Co B2/09/30 CRUTCHFIELD.D Operating Reactors Branch 5 1p 15582 045 24X Fiche 50-206.82/09/30.8210040177
- --8210040178 "Seismic Evaluation of Reinforced Concrete Masonry Walls, San Onofre Unit 1," Vol 5 Fuel Storage Bidg Soil Backfill Condition Evaluation * Computech Engineering Services, Inc. R843-02 V05 82/09/30 1898p 15582 046 24X Fiche 50-206.82/09/30.8210040177
- 8210130276 Forwards abstract of paper on experience gained in evaluating effects of high energy into breaks at facility Paper will be presented at ASME Pressure Vessel & Piping Div & Analysis Committee 4th Natl Congress

 BASKIN.K P Southern California Edison Co 82/10/04 CHEN, P NRC
 Na Detailed Affiliation Given 2pp 15678 165 24X

 Fichs 30-206.82/10/04.8210130274
- 8210260249 Provides addl info supporting 820923 position that no fees are required for Amend 62 issued 820825 Survelllance program previously submitted w/Amend 57 for which appropriate fees applied BASKIN.K P Southern Cellfornia Edison Co 82/10/04 MiLLER.W & License Fee Hanagement Branch 1p 15799: 352 24X Fiche 30-206.82/10/04.82102260249
- B210070082 Discusses use of radwaste solidification sys Unit 2 license condition does not prevent util from using Chem-Nuclear Bys, Inc process to solidify wet solid radwaste produced at Unit 1 Basette evaluation will be performed BASKIN.X P Bouthern California Edison Co 82/10/05 CRU(CHFIELD, D Operating Reactors Branch 3 2pp 13628 162, 24X Fithe 50-206, 82/10/05, 8210070082
- 8210080073 Informs that crane operating maint & insp procedures implemented on 821001 per 820703 ltr. insuring compliance w/NUREO-0612 Cost & implementation schedule of Items 1-3 to be completed by 821215 due to vendor delays KRIEOER,R W Southern California Edison Co 82/10/05 CRUTCHFIELD,D Operating Reactors Branch 5 ip 15640 236 24% Fiche 30-206,82/10/05,8210080073

- 821013008B Responds to 820825 ltr requesting info re SEP Topics [[]-2 & [][-4 A. "Hind & Tormado" be withheld Request cannot be approved until appropriate affidavit submitted CRUTCHFIELD. O Operating Reactors Branch 5 82/10/05 DIETCH.R Bouthern Callfornia Edison Co 2pp 15673 124 24X Fiche 50-206. 82/10/05.821013008B
- 8210180070 Forwards Amend 64 to License BPR-13, safety evaluation & notice of isacance & availability Amend revises App A Tech Specs & bases to reflect revised time intervals for entering various subcritical modes CRUTCHFIELD D Operating Reactors Dranch 5 82/10/06 DIETCH.R Southern Callyfornia Edison Co 3pp 15719 351 24X Fiche 50-206.82/10/06,8210180070
- --8210189073 Amend &4 to License DPR-13, revising App A Tech Specs & bases to reflect revised time intervals for entering various subcritical operational modes when limiting condition cannot be satisfied CRUTCHFIELD, D. Operating Reactors Branch \$ 82/10/06 7pp 13719 354 24X Fiche 50-20&, 82/10/06 8210180070
- --8210180076 Safety evaluation supporting Amend 64 to License DPR-13 * Office of Nuclear Reactor Regulation, Director 82/10/06 Jpp 13719 361 24X Fiche 50-206.82/10/06.8210180070
- --B210180079 Notice of issuance & availability of Amend 64 to License DPR-13 CRUTCHFIELD, D. Operating Reactors Brench 5 82/10/06 2pp 15720 QO1 24% Fiche 50-206.82/10/06/82/0180070
- 9210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820909 its Staff ancouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface MACICH.R M SEP Owners Group 82/10/07 EISENHUT.D 0 Division of Licensing 7pp 13482 177 24X Fiche 50-000,82/10/07,8210130326
- 8210190065 Clarifies NRC 920630 request for add1 info re TMI Item II B 3. "Post-Accident Sampling Sys" CRUTCHFIELD D Operating Reactors Branch 5 82/10/07 DIETCH,R Southern California Edison Co 3pp 15720 007 24X Fiche 50-206,82/10/07.8210180065
- E2:0240214 Advises that final evaluation to determine applicability of EPRI program test results for power operated relief valves, safety valves & block valves, per TMI Item iI D I, will be sent by 82:130 Delay due to need for add1 analyses RRIEGER.R W Southern California Edison Co 82/10/08 CRUTCHFIELD.D Operating Reactors Branch 5 ip 15804 265 24X Fiche 50-206, 82/10/08, 82:10240214
- 8210150144 Submits updated schedules re NUREC-0737. Items 11 E 1 2, "Auxiliary Feedwater Initiation & Flow Indication." I A 1 3 1, "Limit Overtime." II D 1, "Performance Testing of PMR Relief & Safety Valves" & III D 3 4 8ASKIN.X P Southern California Edison Co 62/10/12 CAUTCHFIELD.D Operating Reactors Branch 5 2pp 15697 272 24X Fiche 50-206.82/10/12,8210150144
- 8210200023 Forwards draft evaluation of SEP Topic III-4 C. "internally Cenerated Missles " Facility adequately protected from internally generated missles PAULSON.H Operating Reactors Branch 5 82/10/12 DIETCH.R Southern California Edison Co. 33pp. 19757-230 24X Fiche 50-206.82/10/12,8210200023
- B21015029B Notification of B21021 meeting w/util at plant site to discuss soil parameters re-seismic re-evaluation per SEP Topics III—6 & II-4 1
 PAULSON.W A Operating Reactors Branch 5 82/10/13 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15706 132 24X
 Fische 50-206.82/10/13,8210150278
- 821019067: Bummary of 82100: meeting w/util in Bethesda.MD re scope of seismic remevaluation program Addl info re vent stack, electrical equipment & instrument supports required PAULSON.W A Operating Reactors Branch 5 82/10/13 Operating Reactors Branch 5 5pp 15737 248 24X Fiche 50-206, 82/10/13, 8210190671
- 82(02&0449 Advises that safety-grade replacements for commercial grade anmeter & transducer have been received & will be installed prior to return to power from current outage Ungrades complete nacessary compliance w/NUREO-0737, ltmm II E 1 2 BASKIN,K P Southern California Edison Co 82/10/14 CAUTCHIELD, D Deprating Reactors Branch 5 1p. 15806 154, 24X Fiche-50-206, 82/10/14,82102&0448

- 6210260272 Requests additime to complete proposed Tech Specs recontainment leakage testing, reflecting App J of 10CFR50, as requested in NRC 820803 ltr Proposed Tech Specs expected to be submitted by 821130 KRIEGER, R W Bouthern California Edison Co 82/10/15 CRUTCHFIELD. D Operating Reactors Branch 5 ip 15801 351 24k Fiche 50-206.82/10/15.8210260272
- B210260229 Forwards request for additinfo to assist in NRC review of SEP Topic II-4 F. "Settlement of Foundations & Buried Equipment" Revised SAR incorporating appropriate revisions re soil conditions should be submitted CRUTCHFIELD.D Operating Reactors Branch 5 82/10/18 DIETCH.R Southern California Edison Co 9pp 15799 139 24X Fiche 50-206.82/10/18.8210260229
- 8210260450 Forwards "Status of Category A Unresolved Safety lesues at San Onefre Nuclear Generating Station Unit 1" Rept provides description of each issue & discussion of NRC generic bases for continued operation & sate specific considerations HEDFORD, N O Southern California Edison Co 82/10/20 CRUICHFIELD. D Operating Reactors Granch 5 40pp £5806 [55], 14x Fiche 50-206, 82/10/20, 8210260450
- 8210260472 Forwards supplemental info rept re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants" Rept contains commitments requiring changes to crane operating procedures to be implemented by 830115

 BASKIN, K. P. Sauthern California Edison Co. 82/10/21

 CRUTCHFIELD, D. Operating Reactors Brench 5 1p 15807 230 P4x Fiche 50-206, 82/10/21.8210260472
- --8210260477 "Control of Heavy Loads San Onofre Nuclear Generaling Station Unit 1." supplemental info rept 4 Southern California Edison Co 82/10/31 22pp 15607 21i 24x Fiche 50-206.82/10/21,8910260472
- B210290169 Forwards Amend 65 to License DPR-13.safety evaluation & notice of Issuance & availability Amend Incorporates NURGO-0737. Item If E i I. "Auxiliary Feedwater Pumps & Valves" into Tech Specs CRUTCHFIELD. D. Operating Reactors Branch 5 B2/10/22 DIETCH. R Southern California Edison Co. 3pp 15854 189 24X Fiche 50-206.82/10/22.8210290169
- --8210290175 Amend 45 to License DPR-13, incorporating NUREC-0737, ltrm II E ! 1. "Auxiliary Feedwater Pumps & Valves" into Tech Specs CRUICHFICLD: D. Operating Reactors Branch 5 82/10/22 5pp 18854 192 24X Fiche 50-206, 82/10/22, 8210290169
- --8210290180 Safety evaluation supporting Amend 65 to Licenso DPR L'3 « Office of Nuclear Reactor Regulation. Director 82/10/22 15pp 15854 197 24X Fiche 50-206.82/10/22,8210290169
- --8210290183 Notice of issuance & availability of Amend 65 to litente PR-13 CRUTCHFELD.D Operating Reactors Branch 5 82/19/22 2pp 15854 212 24X Fiche 50-206,82/10/22,8210290169
- O Inspection reports: 1E Bulletins & correspondence
- 821001000B Responds to FOIA request for 19 categories of documents renuclear reactor events 5 safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UBELL.R A Critical Mass Energy Project 15pp 15727 QOS 24X Fiche 50-000:82/06/28.821001000B
- 0210070007 Responds to FOIA request for eight categories of records restand generators & steam turbines App A documents provided in R Udell FOIA Request BI-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Hinthrog, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VAROA.S Operating Reactors Branch 1 CLARK.R Operating Reactors Branch 3 STOLZ.J Operating Reactors Branch 4 Spp 15645 131 24X Fiche 50-000, 82/08/10, 8210070007

- -8210070172 Forwards info re steam generator integrity & insps at all operating PMRs, per 750320 & 21 requests Details of insps, including defect indications, tube plugging criteria & tubes plugged uill not be provided except for Point Deach (GDLLER & R. Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R. Division of Technical Review (NRR-1975 only) 5pp (5645-196 24% Fiche 50-000-82/08/10,8210070007
- 210060264 Forwards 1E Insp Rept 50-206/B2-24 on B20802-31 No noncompliance noted BISHOP, T & Division or Resident, Reactor Project & Engineering Programs 82/09/17 PAPAY, L T Southern California Edison Co .pp 15619 309 244 Fiche 50-206.82/09/17,8210060264
- -8210060269 IE insp Rept 50-206/82-24 on 820802-31 No noncompliance noted Major areas inspected plant operations during long-term shutdown, annual review of plant operations, monthly maint & surveillance activities & LER followup MILER L. KIRSCH.DF Division of Resident, Reactor Project & Engineering Programs 82/09/16 App 15619 311 247 Fiche 50-206.82/09/17.8210060264
- TIOO60294 Forwards 1E Insp Rept 50-206/82-25 on 820830-0903 No noticempliance noted BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82/09/21 PAPAY.L T Southern California Edison Co 2pp 15619 223 24x Fithe 50-206,82/09/21,8210060294
- 8210050299 IE Insp Rept 50-206/82-25 on 820830-0903 No noncompliance noted Major areas inspected const activities associated w/seismic upgrading of safety-related structures & supports MAGNER, W. J. ZMETZIG. G. B. Division of Resident. Reactor Project & Engineering Programs 82/09/17. Spp. 15619 225 24X Fiche 50-206.82/09/21.8210060294
- *10170232 Ark receipt of payment of civil penalties imposed on 820811 Proposed corrective action will be examined in future inspace (and KELRAD. J. A. Enforcement Staff 82/09/22 PAPAY. L. T. Southurn faltsorns Edison Co. 2pp. 15758-175 24X Fiche 50-206.82/09/22, 8210190232
- 10010042 Confirms 821021 mgt meeting in Rosemead.CA to discuss tystemafic assessment of licensee performance Anticipated meeting attendees & agenda enci
 CNEMB.J L Division of Resident, Reactor Project & Engineering Programs 82/09/27 PAPAY.L T Southern California Edison Co
 Rep 155a5 317 24x Fiche 50-206/82/09/27,8210010042
- (O250302 Forwards info per Item 3 of 1E Builetin 82-02, "Degradation or Threaded Fasteners in RCPB of PNR Plants " Repts required by Item 4 will be submitted within 70 days of outage completion

 MAYNED. J G Bouthern California Edison Co 82/10/01 ENGELKEN,R H Region 5, Orfice of Director 5pp 15790 200 24X Fichs 50-206,82/10/01,8210250302
- 'IOABD210 Ack receipt of 820710 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-206/82-21 BISMCP.T W Division of Resident, Reactor Project & Engineering Programs 82/10/04 FOGARTY,D J Southern California Edison Colp 15440 080 24% Fiche 50-206.82/10/04,8210080210
- G210080211 Responds to NRC 820812 ltr re violations noted in lk Insp Rept 50-202/82-21 Corrective actions nonfire retardant wood, oily rage & combustible debris removed from areas & amend to include emergency light impairment prepared FOGARTY D J Southern California Edison Co 82/09/10 FNGELKUN,R H Region 5. Office of Director 5pp 15640 OB1 24X Fiche 50-206,82/10/04-8210080210
- 10080212 Ack receipt of 820907 ltr informing NRC of staps taken to correct violations noted in IE Insp. Rept 50-206/82-23
 BISHGP.T II Division of Resident. Reactor Project & Engineering Programs 82/10/04 PAPVL T Southern California Edison Co lp 15438 086 244 Fiche 50-206.82/10/04.8210080212
- 8210080214 Responds to NRC 920812 ltr re violations noted in 1E Insp. Rept 50-206/82-23 Corrective actions station procedure amended to include instructions on drawing reactor coolant samples from all locations & double valve verification PAPAY.L T Southern California Edison Co 82/09/07 ENGELKEN.R H Region 5. Diffice of Director 3pp 15438 08/ 24X Fiche 50-206.82/10/04.8210080212
- OB190233 IE Info Notice BO-35, Suppl 1, "Leaking & Dislodged I-125
 Implant Beeds " Svc list enc!
 COBB. L 1 Division of Fuel Facilities, Materials & Safeguards
 82/10/06 Consolidated Edison Co of New York 66pp 19761 250
 24X Fiche 50-000,82/10/06,8208190233

- 8208:90238 IE Builletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210080124 Recommends that 810717 event reignition of gaseous waste decay tank should be considered for inclusion in NRC third quarterly AD rept to Congress for 1981 Details of event encl
 CRNSTEIN, H L Director's Office 81/08/06 MICHELSON, C
 Director's Office Jpp 15663 285 24X Fiche 50-206,81/08/06, 8210080124
- \$21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents
 listed in App A
 FELTON.U #: Division of Rules and Records 82/06/28 UDELL,R A
 Critical Mass Energy Project [5pp 15727 005 24X
 Fiche 50~000,82/06/28,8210010008
- --8108130268 Forwards details re 810717 ignition of gaseous waste decay tank at facility Event should be included in Commission third quarterly AO rept to Congress for 1981
 GRMSTEIN.H L Director's Office 81/08/06 MICHELSON.C
 Director's Office 3pp 15730 103 24X Fiche 50-000,82/06/28,8210010008
- --8111300367 Operating Reactor Event Memorandum 81-32 on 810903, control room operator manually tripped reactor after transient from 88% power initiation by steam generator flow & lavel oscillator Caused by regulated power supply failure EISENHUIT. O B Division of Licensing 81/10/31 VOLLMER, R H Division of Engineering HANAUER, S H Division of Human Factors Safety MAITSON, R J Division of Safety Technology 7pp 15731 059 24% Fiche 50-000, 82/06/28,8210010008
- --B201150180 Forwards draft FR notice re 810903 AO on failure of high pressure safety injection sys
 DIRCKS,W J Office of the Executive Director for Operations
 81/12/08 CHilk,S J Office of the Secretary of the Commission
- 8210010260 PND-V-82-038A on 820922, one truckload of trace contaminated sewage dumped at Los Angeles County sewage treatment facility Contamination found in rinse truck Truck returned to licensee for decontamination Addi samples will be taken YUHAS.0. MENGLAMSKI.F. Region 5. Office of Director 82/09/24 ip 15574 055 24X Fiche 50-204.82/09/24.8210010260
- 6210190490 Forwards revised LER 81-025/01X-2 Detailed event analysis encl
 RAY, H B Southern California Edison Co 62/10/06 ENGELKEN.R. H
 Region 5, Office of Director 2pp 15735 335 24X
 Fiche 50-206, 82/10/06, 82(0190490
- --B210170506 Revised LER B1-025/01X-2 on B11025, while conducting to' shutdown valve testing, ball valve CV-534 did not close automatically on isolation signal Caused by failed relay closing circuit of each valve Relays replaced RAY.H B Southern California Edison Co B2/10/06 Re Office of Director ip 15735 337 24X Fiche 50-206.82 B210170470
- 8210250280 RD 82-025 on 821012 & 13, fire watch patrol posted lubrication of i reservoir area but not at post Time period exceeded 1-h interval by 30 minutes Caused by personnel misunderstanding RAY, H D Southern California Edison Co 82/10/14 ENGELK Region 5, Office of Director 2pp 15791 096 24X Fiche 50-206.82/10/14, 8210250280
- 8210280066 Forwards LER 82-023/03L-0 Detailed event analysis RAY,H B Southern California Edison Co 82/10/19 ENGELK Region 5, Office of Director 2pp 15837 249 24X Fiche 50-206: 82/10/19, 8210280066
- ~-8210280068 LER 82-023/03L-0 on 820919, fire water crossije d during new const activities Caused by incorrect const digging process West fire water pump returned to svc ßack fire suppression hoses rigged RAY,H B. Southern California Edison Co 82/10/19 Re Office of Director ip 15837 251 24X Fiche 50-206.82 8210280066

V Operator Examinations

- 8210290316 Forwards "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 1 & II B 4 for Ban Onofre Nuclear Generating Station. Unit 1." technical evaluation rept Training programs acceptable CRUTCHFIELD. D Operating Reactors Branch 5 82/10/26 DIETCH.R Southern California Edison Co 3pp 15854 101 24X Fithe 50-206.82/10/26.8210290316
- --B210290320 "Improvements in Training & Requalification Programs as Regulted by THI Action Ikems I A 2 1 & II B 4 for San Onofre Nuclear Deherating Station, Unit 1." technical evaluation rept

 = Stience Applications, Inc NRC-03-82-094 SAI-186-029-17 82/08/17 NRC NO Detailed Affiliation Olven 15pp 15854 104 24X Fichs 50-206,82/10/26.8210290316

DOCKET 50-208 COLUMBIA UNIV RESEARCH REACTOR

- P Operating incense stage documents & correspondence
- 8210270307 Advises that reactor has never been fueled or operated Fuel not on campus No plans to activate reactor in near future Requests variance to 10CFR50.App E requirements until anticipated reactor startup MELKONIAN.E Columbia Univ 82/10/12 DENTON.H R Office of Nuclear Reactor Regulation. Director ip 15853 166 24X Fiche 50-208.82/10/12.8210270309

DOCKET 50-213 HADDAM NECK PLANT

- P Operating license stage documents & correspondence
- 8209300326 Forwards "Geological & Seismological Biudies, Haddam Neck Nuclear Station, Part I Responses to 1979 NRC Info Request" & "Part II Responses to 1981 NRC Info Request." in response to 5EP Topics 11-4 & II-4 B COUNSIL.N O Connecticut Vankee Atomic Power Co 82/09/22, CRUTCHIFIELD, D Operating Reactors Brench 5 2pp 13557-179 24X Fiche 50-213, 82/09/22,8209300324
- --8209300332 "Geologica] & Seammological Studies Haddam Neck Nuclear Station Part 1 Responses to 1979 NRC Info Request " Twelve oversize figures encl Aperture cards are available in PDR * Nestern Geophysical, 82/09/30 194pp 15557 181 24X Fiche 50-213,82/09/22,8209300326
- --8209300336 "Geological & Seismological Studies:Haddam Neck Nuclear Station:Part II Responses to 1931 NRC info Request " Nine oversize figures enci Aperture cards are available in PDR # Western Geophysical 82/09/30 117pp 15558 014 24X Fiche 50-213,82/09/22.8209300326
- 8210010207 Forwards "Haddam Neck Plant Procedure AOP 3 2-22-C RCB Venting of Moncondensible Cases" & "Milistone Nuclear Power Station RCB Venting Procedure OP 2378," in response to THI Action Plan I tam II B i. "RCB High Point Vents" COUNSIL.H O. Connecticut Yankse Atomic Power Co COUNBIL.H O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.H O. Northeast Utilities 82/09/22 CRUTCHFIELD.D Operating Reactors Branch 3 CLARK, A Operating Reactors Branch 3 3pp 15568 048 24X Fiche 50-000.82/09/22.6210010207
- --8210010210 Revision 2 to "Haddam Neck Plant Procedure AOP 3 2-22-C RCB Vanting of Noncondensible Gases"

 * Connecticut Yankee Atomic Power Co, 82/08/26, 11pp 15568 031 24X Fiche 50-000 82/09/22,8210010207
- --8210010214 Revision 2 to "Millstone Nuclear Power Station Unit 2 Plant Procedure DP 2398 RCS Venting Procedure " SCACE.6 E Northeast Nuclear Energy Co (subs of Northeast Utilities) B2/08/20 Ilpp 15586-062 24X Fiche 50-000.82/09/22.8210010207
- 8210010312 Requests that processing of B20812 license amend application be postponed Revised application changing radiological efficient Tech Spacs will be docketed on or about 821115 for both facilities.

 COUNSIL W O Connecticut Yankee Atomic Pawer Co COUNBIL, W O. Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL-W O Northeast Utilities alongwish advanced to Counsil-W O Northeast Utilities alongwish Counsil-W O Northeast Utilities alongwish Reactors Branch 3 CRUTCHFIELD-D, Operating Reactors Branch 5 3pp 15574 047. 24X Fiche 50-000, 82/09/22, 8210010312

- 8210190663 Responds to open items re SEP Topic III-4 "Seismic Design Considerations," per 820622-23 meetings to discuss status of seismic re~evaluation program COUNSIL-4 O Connecticut Yankee Atomic Power Cs 82/09/27 CRUYCHFIELD, D Operating Reactors Branch 5 5pp 15738 213 247 Fiche 50-213, 82/09/27,8210190663
- --8210190668 "Mechanical & Electrical Equipment Seismic Re-Evaluation Program Haddam Neck Nuclear Generating Station." Interim rept 4 Stevenson & Associates 810152 | 82/06/30 224pp 15738 218 24X Fiche 30-213,82/09/27,8210190663
- 8210070010 Forwards summary of SEP topics for which facility does not meet current licensing acceptance ritteria CRUTCHFIELD.D Operating Reactors Branch 5 82/09/30 COUNSIL,H.G. Connecticut Yantee Atomic Power Co. 45pp 15628 082 24X Fiche 50-213.82/09/30.8910070010
- 8210130331 Discusses revision of administrative procedures to incorporate revised working hour guidelines & provisions for authorizing deviations per 820208 & 0615 requests. THI Item I A 1 3. "Bhift Hanning" & Generic Ltr 82-12 COUNSIL, W 0. COMPETIAL P. Northeast Notlear Energy Co. (subs. of Northeast Utilities). COUNSIL, W 0. Consecticut Yankee Atomic Power Co. 82/10/01 EISCHMIT, D. 6. Division of Licensing. 3pp. 15679-127. 24X Fiche 50-000.82/10/01.8210130331
- 8210070404 Advises that review indicates requirements of NUREO-0337 Items II E 4 2 5 & II E 4 2 7 re containment isolation dependability have been met CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/04 COUNSIL, N. Connecticut Vantee Atomic Power Co. 3pp. 13633-314 24X Fiche 50-213, 92/10/04.8210070404
- 8210120296 Forwards "Haddam Neck Plant Seismic Design," technical evaluation rept
 CRUTCHFIELD.D Operating Reactors Branch 5 FIN A-6426 82/10/C4
 CDUNSIL.W 9 Connecticut Yankee Atomic Power Co 44pp 15654 201
 24X Fiche 50~213.82/10/04.8210120296
- --B210120300 "Haddam Nock Plant Selamic Design," technical evaluation rept
 BRIDGES,T L., BUSCH,S L., MORTON,D K. E080, Inc. FIN A-6424
 E00-EA-6016 D2/00/31 CHENG,T Division of Licensing 203pp
 15654-293 24X Fiche 50-213, 82/10/04, 8210120296
- 8210130205 Forwards safety evaluation of NUREG-0737.TML Action lies 11 E 1 2, "Auxiliary Feedwater Sys Automatic Initiation & Figu Indication (F-16.F-17).Haddam Neck Plant." technical evaluation rept CRUTCHFIELD.D Operating Reactors Branch 5 82/10/05 COUNSHI.W G Connecticut Yankee Atomic Power Co 6pp 15675 271 24X Fiche 30-213.82/10/05.0210130205
- --B20B19017B "Auxiliary Feedwater Automatic Initiation & Figw Indicate:
 Haddam Neck Plant," technical evaluation rept
 KANCHER.J E. FCRIMER.K Franklin Institute/Franklin Research
 Center NRC-03-79-11B TER-03297-294 B2/0B/17 KCNDALL,R.
 WIGDOR,M NRC No Detailed Affiliation Given 16pp 15675 2/s
 24X Fiche 50-213,82/10/05.8210130205
- 8210130326 Comments on proposed scape of Phase III of SEP as reflect+1 in individual topic definitions appended to 820907 its Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in ilcensee/NRC interface KACICH-R M SEP Duners Group 82/10/07 EISENHUT, D 0 Division of Licensing 7pp 15682 179 24% Fiche 50~000,82/10/07,8210130326
- 8210210226 Forwards safety evaluation of licensee safety assessment of SEP Topic III-5 A. "Effects of Pipe Break on Structures, System Components Inside Containment "Methodology & acceptance criteria appropriate to resolve issues in safety evaluation CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/12 CQUNGIL, W.C. Connecticut Yankee Atomic Power Co. 10pp 15766-321 24X Fiche 50-213, 82/10/12.8210210226
- 8210270200 Forwards summary of NRC positions on 26 unresolved safety issues, consisting of excerpts from NRC publications 5 repts to Congress & assessment of generic applicability Adequate basis exists to warrant continued plant operation COUNGIL.44 0 DPEKALJF Connecticut Yankee Atumic Power Co COUNGIL.44 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/13 CRUTCHFIELD.D Dparating Reactors Branth 3 48pp 15824 354, 24X Fiche 50~000,82/10/13,8210270200
- 8210250363 Forwards *SEP Topic VII-1 A, Isolation of Reactor Protection Sys From Nonsafety Bys for Haddam Nack Plant, * final technical avaivation.
 CRUSTRIFIELD, D Operating Reactors Branch 5 FIN A-6425 92/10/20 COUNSIL. N O Connecticut Yankse Atomic Power Co 2pp 15790 151 24X Fiche 50-213,82/10/20.8210250363

- 82:10250372 "SEP Topic VII-1 A, Isolation of Reactor Protection Sys From Nonsafety Sys for Haddam Neck Plant," final technical evaluation
 MORKEH, D. J., UDY, A. C. EGSO, Inc. FIN A-6425 EGG-EA-6033 B2/07/30 23pp 15770 153 24x Fiche 50-213, B2/10/20, B210250363
- G. Inspection reports. 1E Bulletins & correspondence
- SCIGO70007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udeil FOIA Request 81-313 Forwards documents listed in App B FELICN.J M Division of Rules and Records 82/08/10 LCNO, D J Winthrap, Stimson, Putham & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007
 - E210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees [PPDLITO, T. Operating Reactors Assessment Branch 82/04/01 VARGA.S. Operating Reactors Branch i 5pp 15645 i31 24X Fiche 50-000,82/08/10.8210070007
 - 82100701'2 Forwards info re steam generator integrity & inspectating PURs, per 750320 & 21 requests Details of inspectations including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach i GDLLER, K. R. Division or Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R. Division of Technical Review (NRR-1975 only) 5pp 15445 196 24X Fiche 50-000,82/08/10.8210070007
- 5210010332 Ack receipt of B20513 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-213/82-03 Violation until be rescined due to misunderstanding retermination dates of contractor employees MARTIN. I T Division of Engineering & Technical Programs 82/09/23 CGU/85LLN G Connecticut Yankee Atomic Power Co 2pp 15569 144 24x Fiche 50-213,82/09/23.8210010332
- SI 10050374 Ack receipt of B20628 evaluation of SEP lopic III-3 C, Inservice Insp of Water Control Structures "No comments Forwarded CDU:SIL W C Connecticut Yankee Atomic Power Co 82/09/24 (RUTCHFICLD, D Operating Reactors Branch 5 tp 15408 274 24X Fiche 50-217.822/09/24.8210050374
- 32:0150699 Forwards request for add1 info to complete review of B01104 response to IE Bulletin GO-11. "Masonry Wall Design" Response expected within 60 days of ltr receipt (LARK.R A Operating Reactors Branch 3 02/09/28 COUNSIL, W Q (onnecticut Yankes Atomic Power Co COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 13pp 15716 100 24X F1che 50-000, 82/07/28, 8210150699
- 62.08190233 IC Info Notice 80-35. Suppl 1, "Leaking & Disladged 1-12b Implant Seeds" Bev list enc! (OBD.L I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York 66pp 15761 250 24x Fiche 50-000, B2/10/06. 920819/0233
- 5-208190238 IE Oulletin 82-03, "Stress Corrosion Cracking In Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- 5210290189 Forwards IC Insp Rept 50-213/B2-17 on 820823-0928 No noncompliance noted STAROSTECKI: R Division of Project & Resident Programs 82/10/15, CQUNSIL: N O Connecticut Yankee Atomic Power Co 2pp 15853 313 24x Fiche 50-213,82/10/15.8210290189
- --8210270194 IE Insp Rept 50-213/82-17 on 820823-0926 No noncompliance noted Major areas inspected facility tours.log & record review surveillance & containment ent; REBELOWSKI, T. ELSASSER, T. C. Division of Project & Resident Programs 82/10/14 7pp 15853 315 24X Fiche 50-213,82/10/15,8210290189
- S Reportable occurrences. LERs & related correspondence
- 9210270245 Forwards LER 81-005/03L-0 GRAVES:R H Cunnetticut Yankee Atomic Power Co 81/05/18 ORIER, B Region 1. Philadelphia Office of the Director (81/03/01) ip 15822 341 24x Fiche 50-213,81/05/18,8210270245

- --B210270249 LER B1-005/03L-0 on B10424, unattended welding cables found running through access in fire barrier, possibly preventing closure Caused by contractor failing to Inspect fire barriers & failing to provide connectors in cables TEST, R Z Connecticut Yankse Atomic Power Co B1/05/18 Region 1, Philadelphia, Office of the Director (B1/03/01) 2pp 15822 342 24X Fiche 50-213, B1/05/18, B210270245
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON,J M Division of Rules and Records 82/04/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000:82/04/28.8210010008
- --BiiiiBOCOI Recommends comprehensive assessment of plant operating conditions to determine specific predetermined time related sequences of occurrence to emergency buses SRP should be revised re design features
 ABHE.F Director's Office Bi/10/16 HICHELGON.C Director's Office 4pp 15731 049 24X Fiche 50-000.02/06/28.821001000B
- 8210150122 Forwards LER 82-006/03L-0 CRAVES.R H Connecticut Vankee Atomic Pawer Co 82/10/05 HAYNES.R C Region 1, Office of Director 1p 15721 277 24X Fiche 50-213,82/10/05,8210150122
- --82i0150128 LER 82-006/03L-0 on 820919, emergency dc battery bank II, celi 42, found leaking electrolyte through seam crack lnsp revealed ii more batterles w/cracks in same location Caused by cell plate expansion against jar & battery age QUINN, II D Connectleut Yankee Atomic Power Co 82/10/05 Region 1. Office of Director 2pp 15721 278 24X Fiche 50-213, 92/10/05, 8210150122
- 9210280071 Forwards LER 82-007/03L-0 GRAVES.R H Connecticut Yankee Atomic Power Co 82/10/20 HAYKES.R C Region i. Office of Director ip 15837 247 24X Fiche 50-213.82/10/20.8210280071
- --8210280074 LER 82-007/03L-0 on 820927, operator received rad drive slave cycler failure/rod stop alarm-rendering all bank B subgroups inoperable Caused by master cycler relay hanging up due to poor relay contact hercury wetted contacts rewet QUINN:H D Connectleut Yankee Atomic Power Ca 82/10/20 Region 1, 0ffice of Director 1p. 15837 248 24X Fiche 50-213,62/10/20,8210280071
- DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

 F Security, medical, emergency & fire protection plans
- 8210220182 Ack receipt of 820812 ltr informing NRC of actions taken to improve emergency preparedness program per IE Emergency Preparedness Appraisal Rept 50-219/82-01 ALLAN, J M Region 1 Office of Director. 82/10/12 FIEDLER.P II General Public Utilities QPU Service Corp 2pp 15776 328 24X Fiche 50-219.82/10/12.8210220182
- --8210220187 Responds to IE Emergency Preparedness Appraisal Rept 50-219/82-01 Corrective actions training program developed, amergency control ctr moved away from control room & ventilation sys upgraded FIEDLER.P B. General Public Utilities ~ OPU Bervice Corp 82/08/12 8MTH,0 H Division of Emergency Preparedness 9pp 15776.330. 24X Fiche 50-219.82/10/12.8210220182
- 6210250383 Forwards Revision 13 to physical security plan Revision withheld LAGOART.H U general Public Utilities GPU Bervice Corp. 82/10/19 Dffice of Nuclean Reactor Regulation. Director IP, 15790-136-24X Fiche 50-219.
- H General correspondence
- 8207180051 FOIA request for seven categories of info re nuclear matl transported by M Roh in Apr 1980 to Beatty, NV & General Public Utils submissions from 800101 per Price Anderson Act VAN BYCC, C Tomar, Parks, Bellger, Simonoff & Addurian, 82/08/24 FELTON, J M. Division of Rules and Records. 2pp 15760 196 24X Fiche 50-219, 82/08/24, 8207180051
- 8210190163 Partial response to FOIA request for seven categories of info re nuclear mat! transported by M Roh in Apr 1980 to Beatty.NV & General Public Utile submissions since 800101 per Price-Anderson Act re facility Forwards App A documents FELTON, J M Division of Rules and Records. 92/09/15, VAN BYOC, C Tomar, Parks. 8210er. Simonoff & Adourien 2pp 15760, 198 24X Fichs 50-219, 82/09/15, 8210190163

P Operating license stage documents & correspondence

- 8210010063 Informs that Erron Test Rept XN-NF-78-12, "Spray Cooling Heat Transfer Test Results, Phase-II Facility & Test Data ENC Gis BHR Fuel," buil be withheld per 10CFR2 790, in response to 820806 request CRUTCHFIELD. D. Operating Reactors Branch 5 82/07/23 FIEDLER, P. B. General Public Utilities OPU Service Corp. 3pp. 15567 167 24X Fische 50-219, 82/09/22,8210010063
- 8210010077 Forwards Mark I containment long-term program, plant-unique analysis repts for suppression chamber & vent sys & torus attached piping Safety relief valve piping analyses will be completed & forwarded by 821215

 FIEDLER.P B General Public Utilities GPU Service Corp 82/09/24
 CRNICKHIELD.D Operating Reactors Branch 5 2pp 15566 093 24X
 Fiche 50-219,82/09/24,8210010077
- --8210010081 "Oyster Creek Nuclear Generating Station Herk 1 Containment Long-Term Program.Plant-Unique Analysis Rept.Suppression Chamber & Vent Sys" * MPR Associates, Inc. MPR-733 82/08/31 300pp 15566-055 24X Fiche 30-219.92/09/24.8210010077
- --8210010035 "Myster Creek Nuclear Generating Station Mark I Containment Long-Term Program, Plant-Viique Analysis Rept. Torus Attached Piping " 4 MPR Associates, Inc. MPR-734 82/08/31 137pp 15366 357 24X Fliche 50-219,82/09/24,8210010077
- 6210040261 Forwards notice of consideration of issuance of amend to provisional QL, DPR-16,re increase in spent fuel storage capacity to 2,600 assemblies CRUTCHFIELD, D. Openating Reactors Branch 5 62/09/28 FIEDLER,P. G. General Public Utilities QPU Service Corp. 2pp. 15595-003 24X Fiche 50-219,62/09/28,82:0040261
- --B210040265 Notice of consideration of issuance of amend to provisional OL-0PR-16-re (increase in spent fuel storage capacity to 2.400 assamblies CRUTCHFIELD, D Operating Reactors Branch 5 82/09/28 4pp 15595 005 24X Fithe 50-219, 82/09/28.8210040261
- 8210080053 Forwards INPO "Evaluation of Dyster Creek Nuclear Generating Station," per Moseley 910506 request & Stello 910626 memo FMITH 6 H Dylsion of Emergency Preparedness & Operational Support 92/09/29 TAYLOR.O H Division of Reactor Programs 1p 15443 037 24% Fiche 50-219, 82/09/29, 8210080063
- --B2100BD079 "Evaluation of Oyster Creek Nuclear Generating Station "
 ** Institute of Nuclear Power Operations B1/12/31 33pp
 15643 038 24% Fiche 50-219,82/09/29,8210080063
- 8210270345 INTEGRATED PLANT SAFETY ASSESSMENT, SYSTEMATIC EVALUATION PROGRAM Obster Creek Nuclear Generating Station Docket 50-219 (CPU Nuclear Corporation And Jersey Central Power And Light Company)

 **Division of Licensing NUREO-0822 DRFT 62/09/30 537pp 15850 146 24X Fiche 50-219, 82/09/30, 8210270345
- 8210130326 Comments on proposed scope of Phase 111 of SEP as reflected in indivadual topic definitions appended to 820909 for Staff encouraged to develop t implement means to incorporate positive attributes of Phase III in Ricensee/NRC interface KACICH, R M SEP Owners Group 82/10/07 EISENHUT, D C Division of Licenseing 7pp 13682 179 24% Fiche 50-000,82/10/07,8210130326

- 82:0190502 Advises that company no longer performing analyses for LearNuclear supplied fuel under irradiation in plant Util made
 separate arrangements Util vitilizing or planning to utilize
 fuel for operating conditions outside analyzed conditions
 OHSEEV.G F Erron Nuclear Co. Inc. (subs. of Erron Corp.)
 82:100/13 RUBENSTEIN.L S. Assistant Director for Core & Plant
 Systems. 1p. [5740-198-24X Fiche 50-217.82/10/13.6210190502]
- 8210200060 Forwards corrected FR notice of consideration of amoud to License DPR-16 respent fuel storage capacity published 821008 reflecting 821108 as deadline for requesting hearing CRUTCHFIELD D Operating Reactors Branch 5 82/10/13 HIFC.DIM.P & General Public Utilities OPU Service Corp 4pp 15737 206 248 Fiche 50-219, 82/10/13.8210200060
- 8210260182 Forwards Amond 63 to License DPR-16, safety evaluation a notice of issuance & availability Amond authorizes addition of control rod drive scram discharge vol high level & rod block to Tech Specs
 CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/15 FIEDILM, P. B. General Public Utilities GPU Service Corp. 2pp. 15803, 130 (4)
 Fiche 50-219, 82/10/15, 8210260182
- --8210260185 Amend 63 to Liceuse DPR-16, authorizing addition of contrat rod drive scram discharge vol high level & scram trip bypus v rod block to Tech Specs CRUICHTIELD, D. Operating Reactors Branch 5 82/10/15 (*pp 15803 292 244 Fiche 50-217, 82/10/15, 8210260182
- --8210260187 Safety evaluation supporting Amend 63 to License 19th 16.

 Office of Nuclear Reactor Regulation, Director 62/10/15 15803 241 24X Ficho 50-219.02/10/15, 8210260182
- --8202010167 "Technical Evaluation Rept for BWR Scram Discharge Vol Long-Term Mods Oyster Cieck Nuclear Generating Station " HUCHA,E Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-58 82/01/27 ECCLESTON, K NRC Na Detailed Affiliation Given 5ppp 15803 243 24X Fiche 50-219, 82/10/15, 8210260162
- --8210260191 Notice of issuance & availability of Amend 63 to ((center) PR-16
 CRUTCHFIELD, D. Operating Reactors Branch 5 80/10/15 Ppp
 15803-298 24X Fiche 50-219.02/10/15.8210260182
- 8210210280 Submits add1 comments on SEP Phase II During final stages of SEP.NRC properly & effectively assessed safety intent of SRPs & evaluated ments of alternative proposals CLARK.P R General Public Utilities GPU Service Corp. #2/10/iii CRUICHFIELD, D Derating Reactors Branch 5 2pp 15/65 148 244 Fiche 50-219.82/10/i8.8210210280
- 9210250136 Forwards info re reactor protection sys power supply.in response to 820702 request for addl info Periodic functional testing will be performed on assemblies by removing motor generator set from distribution bus FIEDLER,P B General Public Utilities GPU Service Corp 02/10/16 CRUYCHFIELD, D Operating Reactors Branch 3 2pp 19707-005 24x Fiche 50-219,82/10/10,8210250136
- 8210250189 Requests approval of Tech Spec Change Request RB re adequals of station electric distribution sys voltages & degraded grid protection for Class IE power sys. in response to 011016 itrs Voltage regulators provide no safety function FIEDLER.PB General Public Utilities OPU Service Corp 82/30/18 CRUCHFIELD.D Operating Reactors Branch 5 2pp 19700 286 244 Fiche 50-217, 82/10/18, 8210250189
- 8210290254 Submits corrections to discrepancies identified in util 821008 ltr re control room habitability One oversize drawing enci Aperture card is available in PDR FIEDLER, PB Deneral Public Utilities QPU Service Corp 82/10/19 EISENUIT.D O Division of Licensing 2pp 18853 112 24X Fiche 50-219,82/10/19:8210270254
- 8210270202 Advises of review of deviations to stated positions contained in NUREO-0737. Item If F 1 3. "Containment High Range Radiation Monitor" Monitors expected to be installed during Cycle II refueling outage CRUTCHFIELD.D Operating Reactors Branch 5 82/10/20 FIEDLER, P 8 General Public Utilities GPU Service Corp 2pp 15823 094 242 Fiche 50-219, 82/10/20,8210270202
- 8210250284 Notification of 821103 meeting w/util in Bethesda.HD to discuss core spray sparger effectiveness in steam environ at facility LOMBARDO.J J. Operating Reactors Branch 5. 82/10/21 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 15791 175 24K Fiche 50-219.82/10/21.8210250284

- 8210270004 Advises that response to NUREO-0737. Item II K 3 25, "Effect of Loss of AC Power on Pump Seals," acceptable, based on endorsement of BRR owners group position Mods to seal cooling for recirculation pumps not required CRUTCHFIELD. D. Operating Reactors Branch 3 82/10/22 FIEDLER, P B General Public Utilities GPU Service Corp 7pp 15815 353 24X Fiche 50-2:9.82/10/22,8210270004
- Q Inspection reports, IE Bulletins & correspondence
- U2:10080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events 5 safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/07/12 UDELL,R A Unitical Mass Energy Project 9pp 15665 027 24X Fiche 50-000, 82/07/12:8210080015
- --8210080140 Systematic assessment of licensee performance notes re facility evaluation for Aug 1979--Uul 1980 * NRC - No Detaited Affiliation Given 80/07/3t 7pp 19688 008 24% Fiche 50-000.82/07/12:8210080015
- 8210070269 Forwards 1E Insp Rept 50-219/82-20 on 820803-0907 & notice or violation STAROSTECKI.R Division of Project & Resident Programs 82/09/22 FIEOLER.P 8 General Public Utilities GPU Service Corp 2pp 15634 148 24X Fiche 50-219,82/09/22,8210070268
- -92(007027D Notice of violation from insp on 820803-0907 ** Division of Project & Resident Programs 82/09/22 1 19534 150 24× Fiche 50-219, 82/09/22 8210070268
- --8210070275 iE insp Rept 50-219/82-20 on 820803-0907 Noncompliance noted failure to follow equipment control procedures & prepare procedures consistent w/10CFR20 for work involving personnel radiation exposure COWGILL.C. THOMAS.J. TRIPP.L E Division of Project & Resident Programs 82/09/17 10pp 15634 151 24X Fiche 50-219,82/09/22,8210070260
- 5210070341 Forwards IE Insp Rept 50-219/62-19 on 620802-06 No noncompilance noted MARTIN.T T Division of Engineering & Technical Programs 82/09/24 FIEBLER.P B General Public Utilities - GPU Service Corp 2pp 15634 092 24X Fiche 50-219.82/09/24.8210070341
- -82100/0345 IE Insp Rept 50-219/82-19 on 820802-06 No noncompliance noted Major areas inspected licensee action on previous insp fundings, radiation protection instrument calibr & training, pasting, labeling, ALARA program & radwaste program WRAY, J.R., RONE, C.A., GREENMAN, C.O. Division of Engineering & Technical Programs 82/09/23 84pp 15634-094 24X Fiche 50-219.82/09/24.8210070341
- 920B190233 IE info Notice 80-35, Suppl 1, "Leaking & Distodged 1-125 Implant Seeds " Svc list encl CDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000.82/10/06.8208190233
- G210250285 Requests relief from insp of listed welds using volumetric & surface exam methods Results of review of inservice insp program requirements & justification for relief in inspecting 10 dissimilar metal welds encl FIEDLER.P B General Public Utilities ~ GPU Service Corp 82/10/08 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 15791 172 24X Fiche 50-219.82/10/08,8210250285
- 8210190375 Ack receipt of 820831 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Rept 30-219/80-17 MARTIM: T Division of Engineering & Technical Programs 82/10/12 FIEDLER.P B General Public Utilities of OPU Service Corp 2pp 15741 017 24X Fiche 50-219.82/10/12.8210190375
- --B210190378 Responds to NRC 820416 itr reviolations noted in IE Insp Rept 50-219/80-17 Corrective actions GA audit insp program of health physics activities implemented & training & definitions of radiation protection steff improved FIEDLER.P B Congral Public Utilities - GPU Service Corp B2/09/31 SMITH O H Division of Emergency Preparedness & Operational Support 15pp 15741 019 24X Fiche 50-219,82/10/12, B210190375
- 5210220182 Ack receipt of 820812 ltr informing NRC of actions taken to improve emergency preparedness program per IE Emergency Preparedness Appraisal Rupt 50-219/82-01
 ALLAN, J M Region J. Office of Director 82/10/12 FIEDLER.P D General Public Utilities GPU Service Corp 2pp 15776 328 24X Fiche 50-219, 82/10/21,8210220182

- --8210220187 Responds to IE Emergency Preparedness Appraisal Rept 50-219/82-01 Corrective actions training program developed, emergency control ctr moved away from control room & ventilation sys upgraded FIEDLER,P B General Public Utilities - QPU Service Corp 82/08/12 SMISH.G H Division of Emergency Preparedness 9pp 15776 330 24X Fiche 50-219.82/10/12.8210220182
- 8203190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list enci DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8200190238
- S Reportable occurrences, LERs & related correspondence
- 82:10070438 Forwards angineering evaluation rept on 810827 shutdown cooling sys HX failure Failures diagnosd as fatigue failures due to flow induced vibration Event not considered AO Repairs to be complete by 81:012
 LANIN.O Director's Office 81/10/15 Director's Office 7pp 18637 337 24X Fichs 50-219,81/10/15:8210070438
- 921001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- --Bii0230085 Forwards engineering evaluation rept on shutdown conling syn HX failures which occurred in late Aug 1981 Failures diagnosed as fatigue failures due to flow induced vibration Recommends event not be considered AO LANIK, 0 F NRC No Detailed Affiliation Given 81/10/15 NRC No Detailed Affiliation Given 81/10/15 NRC No Detailed Affiliation Given 7pp 15731 0/12 24X Fiche 50-000,82/06/20.82100100008
- 8210130167 Ro on 820814 normal shutdown initiated to invostigate higher than normal differential pressure readings in emergency svc water sys Caused by debris blockage consisting of live & dead animal matter Organisms removed & tubes cleaned FIEDLER.P B Oeneral Public Utilities OPU Service Corp 82/07/22 HAYNES.R C Region i. Office of Director App 15673 047 24X Fiche 50-217.82/07/22.8210130167
- 8210070178 Forwards LER 82-049/03L-O Detailed event analysis encl FIEDLER.P B Oeneral Public Utilities - GPU Bervice Corp 82/09/24 HAYNES.R C Region 1. Office of Director 3pp 15634 298 24X Fiche 50-219.82/09/24.8210070178
- --8210070181 LER 82-049/03L-0 on 820825, soven hydraulic snubbors failed functional testing after being replaced by certified functional spare; Two snubbers had improper mati seals Caused by seal degradation £/or worn poppet valves CHARTERINA, J. General Public Utilities GPU Service Corp 62/09/24 Region J. Office of Director ip 15634 301 24X Fiche 50-219,82/09/24,8210070178
- 8210070238 Forwards LER 82-048/03L-0 Detailed event analysis sncl FIEDLER.P B Quarral Public Utilities - GPU Service Corp 82/09/27 HAYNES.R C Region 1. Office of Director 3pp 15637 151 24X Fiche 50-219:82/09/27.8210070238
- --8210070241 LER 82-048/03L-0 on 820826, reactor water level instrumentation for one channel in each of several safety sys rondered inoperable as result of loss of ref column head RIGGLE, E I Ceneral Public Utilities OPU Service Corp 82/07/27 Region i. Office of Director ip 15637 154 24X Fiche 50-219, 82/07/27, 8210070238
- 8210130397 RO on 820829, reactor startup conducted w/inoperable rod worth minimizer Minimizer failed due to defective clock drive modula in slot 40 of CPN unit, damaging several components Ali damaged components replaced FIEDLER.P B General Public Utilities CPU Barvice Corp GR/09/28 MAYNESR C Region I. Office of Director 2pp 19679 010 24% Fiche 50-219, 82/09/28,8210130357
- 8210060376 PNO-1-82-063 on 821001, anonymous phone caller notified licensee that bomb was set to go off in plant No bomb discovered in protected area COMOILL.C., TRIPP, MCAME Region 1. Office of Director, 62/10/01 ip 15619 055 24K Fiche 50-219, 82/10/01, 8210060376
- 8210150078 Forwards LER 82-050/03L-0 Detailed event analysis encl FIEDLER.P B General Public Utilities - QPU Service Corp 82/10/01 HAYNES.R C Region i Office of Director 3pp 15701 178 24X Fiche 50-219, 82/10/01,82101500

- --8210150112 LER B2-050/03L-0 on 620828, reactor vessel pressurized in sicess of 110 paig offication water temp greater than 212 F Caused by inadequate Procedure 802 4 Ool Test procedure will be reviewed to redefine temp/pressure requirements SANTELLA: A Cemeral Public Utilities OPU Service Corp 82/10/01 Region 1. Office of Director (p. 15701 181 24X Fiche 50-219, 82/10/01.8210150098
- DOCKET 50-220 NINE HILE POINT NUCLEAR STATION, UNIT 1
 F. Security, medical, exergency & fire protection plans
- 8210010275 Forwards "Systematic Assessment of Licenser Performance (SALP). Nine Hile Point Nuclear Station Unit 1." for May 1981 Apr 1982. vell 820728 ltr re performance improvements & NRC 820530 request List of SALP 620708 meeting attenders encl HAYNES. R C Region 1. Office of Director 82/09/28 RHODE. O K Niagara Mahauk Power Corp 4pp 15568 327 24% Fiche 50-220. 82/09/28, 8210010275
- --8210010280 "Systematic Assessment of Licenses Performance. Nine Mile Point Nuclear Station Unit 1." for May 1981-Apr 1982 # Region 1. Office of Director 82/06/22 27pp 18569 331 24x Fiche 50-220,82/09/28.8210010275
- 5210060202 Ack receipt of 620324 ltr informing NRC of steps taken to improve items identified in Apps A.B.&.C of IE Emergency Preparedness Appraisal Rept 50-220/81-18 SHITH.G.H. Division of Emergency Preparedness & Operational Support 82/09/29 RNOSE.O.K. Niagara Nobawa Power Corp. 2pp. 15614-018 24X Fiche 50-220-82/09/29.82109/29.82100
- --8210060203 Responds to NRC 820222 ltr transmitting IE Emergency Preparedness Appraisal Rept 50-220/61-16 Descriptions of assessment/actions to be taken for improving items identified in Apps A.O. & C of rept encl LEMPGES.T E Niagara Mohawi Power Corp 82/03/24 HAYNES.R C Region f. Office of Director 22pp 15614 020 24% Fiche 50-220,82/09/29.8210060202
- 8210040276 Forwards review of safe shutdown analysis in response to 820426 request for additinfor re 100FR50.App R. Sections 111 Q t. III L DC sys 125-volt analysis for breater fuse coordination to be completed by 821231 MANGAN.C V Nisgara Mahawk Power Corp 82/10/01 VASSALLO, D B Operating Reactors Branch 2 lp 15976 001 24x Fiche 50-220.82/10/01.8210040276
- 8210050083 Forwards "Dispersion Model Description for Kine Hile Point/ James A Fitzpatrick Nuclear Stations," upgraded meteorological sys description per Thi Action Item III A 2 BAYKE, J P Power Authority of the State of New York 82/10/01 VASSALLO, D B Greating Reactors Branch 2 2pp 15604 255 24X Fichs 50-333,82/10/01,8210050083

- P Operating license stage documents & correspondence
- 82(0050014 Approves recirculation sys piping removal lnfo required prior to safe-end replacement VASSALLO, D 8 Operating Reactors Branch 2 82/09/02 015F, D 1 Niagara Mohawk Power Corp 3pp 15624 058 24X Fichs 50-220, 82/09/02, 8210050014
- 8210120632 Advises that 800421 request for title change of vice-president ribsed out since util advised change no longer required VASSALLO, D.B. Operating Reactors Branch 2 62/09/17 DISC. D.P. Miagara Mohau): Power Corp. 2pp. 15672 271 24X Fiche 50-220. B2/09/17. B210120632
- 8210010033 Submits info re removal & replacement of reactor recirculation sys piping.per 820922 request Combined man rem exposure estimates bounded by original estimate of 2.906 man rem MANGAN.C V Niagara Mohawk Power Corp 82/09/27 EISENHUT, D C Division of Licensing 2pp 15565-170 24X Fiche 50-220.02/09/27.
- 8210040117 Forwards fee for Tech Spec changes re-containment isolation dependability (n compliance w/requirements of NURCO-073/ & reactor recirculation safe-end replacements program Fee submittal in response to NRC 820825 tr MANOAN.C V Niagara Mohawk Power Corp 82/07/27 DigCt, R license Fee Management Branch 2pp 15981 189 24% Fiche 50-220, N2/07/.*/, 8210040117
- 8210040182 Forwards "Nine Mile Point Unit 1 Station Power Distribution Sys (Class IE) Load Study & Freld Test." in response to NIC 810202 request Required motor rewinding & cable replacement will be performed during next scheduled refueling outage LEMPOES, T E Niagara Hohawk Power Corp 82/09/27 VASGALID, B Operating Reactors Branch 2 3pp 15582 206 24X Fiche 50~220,82/09/27.8210040182
- --8210040183 "Mine Mile Paint Unit 1 Station Power Distribution "Un (Class IE) Load Study & Field Test " BLASIAK.L J., RIBEIROJ J. LAIRD.R C Niagera Hohauk Power (urp B1/12/10 96pp 15582 210 24X Fiche 50 220.82/09/2/.8/21(8)46(18)2
- 8210010275 Forwards "Systematic Assessment of Licensee Performance (SALP). Name Hile Point Nuclear Station Unit 1: " for May 1781 Apr 1982. util 820728 itr re performance improvements & NRC 820630 request List of SALP 820708 meeting attendees oncl HAYRES.R C Region 1, Office of Director 82/09728 RHRNLU. UK Niagara Mohawk Power Corp 4pp 15568 327 24X Fiche 50-220,82/09728,8210010275
- ~~8210010280 "Systematic Assessment of Licenses Performance, Nine Hile Point Nuclear Station Unit 1." for May 1781-Apr 1782 * Region 1. Office of Director 82/06/22 27pp 15568 J/N 24 Fiche 50-220,62/09/28,8210010275
- --9210010287 Responds to radiological controls section of 82062% systematic assessment of licenses performance rept Commitments for performance improvements provided LEMPOES.T E Niagora Mohauk Power Corp 82/07/28 STAROS II-UNI.F Division of Project & Resident Programs 4pp 15568 358 24% Fiche 50-220,82/09/28 8210010275
- --8210010294 Informs of 920709 meeting at site to discuss NRC 820841 systematic assessment of licensee performance Discussion of efforts re radiological control activities should be prepared STAROSTECKI, R Division of Project & Resident Programs 82/04/30 LEMPORES, T E Ningara Mohauk Power Corp 2pp 15568-362 24X Fiche 50-220,82/09/28-8210010275
- 8210050260 Forwards 42 oversize drawings showing connection of alternate shutdown sys to normal shutdown sys in response to NRC 820426 Ity Aperture cands are available in PDR MANOANIC V Niggera Mohawk Power Corp 82/09/30 VASSALLO, D & Operating Reactors Branch 2 ip 15603 001 24X Fiche 50-220.82/09/30.8210050260
- B210050354 Notifies that Proposed mods to automatic depressurisation sys logic will not be submitted until 821203 Delay needed to consider effects of lasted analyses MANGAN.C V Niagara Mohawk Power Corp 82/09/30 EISENNUT.D 0 Division of Licensing ip 15601 348 24x Fiche 50-220,82/09/30 8210050354
- 8210030111 Forwards one oversize revised schedule for recirculation sys repairs at facility. Aperture card is available in PDR MANGAN.C V Niegara Mohaut Power Corp 82/10/01 VASSALLO.D D Operating Reactors Branch 2 ip 15603 002 24X Ficher 50-220.82/10/01.8210050111

- 8210130107 Submits addi info to 820927 itr re analysis criteria for recirculation sys piping replacement Reanalysis criteria provides same mangin as original criteria High energy line break would not affect engineered safeguard sys MAKOAN C V Niagara Mohawk Power Corp 82/10/05 EISENHUT, D C Dévision of Licensing 3pp 15673 101 24% Fiche 50-220,82/10/05, 62102007 8210130107
- 8210280144 informs that review of technical evaluation rept.
 "Comparison of Plant & Model Radiological Effluent Tech
 Specs & Plant Offsite Dose Calculation Manual Nine Mile
 Point Nuclear Station Unit 1." will be completed by 821130
 LEMPOES.T & Niagara Mohauk Power Corp 82/10/25 VASSAL
 Operating Reactors Branch 2 1p 15837 135 24X
 Fiche 50-220.82/10/25.8210280144 VASSALLO, D B
- Q Inspection reports, IE Builetins & correspondence
- 6210080015 Addi response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) 82/07/12 UDELL,R A

FELTON, J. H. Division of Rules and Records 82/ Critical Mass Energy Project 9pp 15645 027 Fiche 50-000, 82/07/12, 8210080015

- --B210080139 Systematic assessment of licenses performance notes re facility evaluation for Feb 1980-Oct 1981 > NRC No Detailed Affiliation Given 81/01/31 Spp 15668 003 24% Fiche 50-000.82/07/12.8210080015
- 1210070337 Forwards IE Insp Rept 50-220/82-14 on 820801-31 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/09/22 RHODE, 0 K Niagara Mohawk Power Corp 2pp 15634 073 Fiche 50-220, 82/09/22, 8210070337
- -8210070342 Notice of violation from insp on 820801-31 * Region i, Office of Director 82/09/22 lp 19634 075 24X Fiche 50-220, 82/09/22, 8210070337
- -8210070350 IE Insp Rept 50-220/82-14 on 820801-31 Noncompliance noted
- 210010157 Ack receipt of 820818 ltr informing NRC of steps taken to currect violations noted in IE Insp Rept 50-220/82-10
 MARTIN, T T Division of Engineering & Technical Programs 82/09/6
 RHODE O K, Niagara Mohawk Power Corp ip 15567 254 24X
 Fiche 50-220,82/09/24.8210010157 89/09/94
- -8210010165 Responds to NRC 820719 itr re violations noted in IE Insp Rept 50-220/82-10 Corrective actions safety evaluation & procedures for reactor vessel rectroulation nozzle safe-end replacement reviewed by site operations review committee LEMPGES T E Niagara Mohawk Power Corp 82/08/18 MARTIN, T T Division of Engineering & Technical Programs 3pp 19567 255, 24X Fiche: 90-220, 82/09/24, 82:0010157
- '10010275 Forwards "Bystematic Assessment of Licensee Parformance (SALP), Nine Mile Point Nuclear Station Unit 1," for May 1981 (SALP), Nine Hile Foint Nuclear Station Unit 1: "or may 1991 "App 1992 util 820728 itr re performance improvements & NRC 820630 request List of SALP 820708 meeting attendess entl HAYMES.R.C. Region i, Office of Director 82/09/28 RHODE.O K Niagara Mohauk Power Corp. 4pp 19548 327 24X Fiche 50-220, 82/09/28.8210010275
- 8210D10280 "Bystematic Assessment of Licensee Performance, Nine Mile Point Nuclear Station Unit 1." for May 1981-Apr 1982 * Region 1. Office of Birector 82/06/22 27pp 15568 331 2: Fiche 50-220.82/09/28,8210010275 15568 331 24X
- 9210010287 Responds to radiological controls section of 820622 systematic assessment of Illensee performance rept Commitments for performance improvements provided LEMPGES-TE Niegara Hohauk Power Corp 82/07/28 BTAROSTE Division of Project & Resident Programs 4pp 15568 338 Fiche 50-220,82/09/28,8210010275 BTAROSTECKI, R
- 22:0010274 Informs of 820708 meeting at site to discuse NRC 820623 systematic assessment of licenses performance Discussion of efforts re-radiological control activities should be prepared
 BTARGSTECKI,R Division of Project & Resident Programs 82/06/3
 LEMPGES.T E Niagara Mohauk Power Corp. 2pp 15568 362 24X
 Fighe 50-220,82/09/28,8210010275 82/06/30

- 8210060202 Ack receipt of 820324 ltr informing NRC of steps taken to improve items identified in Apps A.B.& C of IE Emergency Preparedness Appraisal Rept 50-220/BI-18 SMITH, OH Division of Emergency Preparedness & Operational Support 62/09/29 RHODE, O K Nisgara Mohawk Power Corp 2pp 15614 018 24X Fiche 50-220, 62/09/29, 6210060202
- --8210060208 Responds to NRC 820222 itr transmitting IE Emergency 2:1006020B Respands to NAC 820222 IT transmitting 18 Emer Preparedness Appraisal Rept 50-220/81-18 Descriptions of assessment/actions to be taken for improving items identified in App A.B & C of rept enci LEMPGES.T E Niagara Mohawk Power Corp 82/03/24 HAV Region 1. Office of Director 22pp 15614 020 24X Fichs 50-220, 82/09/29, 8210060202 HAYNES R C
- 8208190233 IE Info Notice 80-35. Suppl 1, "Leaking & Dislodged I-12b Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolsdated Edison Co of New York 66pp 15761 200 82/10/06 Consolidated Edison Co of New York 66pp 24x Fiche 50-000.82/10/06.8208190233
- 8210210255 Forwads IE Insp Rept 50-220/82-16 on 820824-27 No nuncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/10/06 RHODE, 0 K Niagara Mobauk Power Corp 2pp 15766 237 24X Fiche 50-220/82/10/06/8210210255
- --8210210264 IE Insp Rept 50-220/82-16 on 820824-27 No noncompliance elociozo4 le insp xept 30-220/22-to on ucoez-2/ no noncompisance noted Major areas inspected inservice insp program & activities associated w/recirculation sys mod.including walder training/qualification & weld procedures GRAY.E H. MCDREARTY,R A. DURR.J P. Region I. Office of Director 82/09/14
 6pp 15766 239 24X Fiche 50-220,82/10/06,8210210255
- 8210290103 Forwards IE Bafeguards Insp Rept 50-220/82-18 on 820915-16 No noncompliance noted

 MARTIN.T T Division of Engineering & Technical Programs 82/10/08

 SUNSER, J J Niagara Mohawk Power Corp 2pp 15853 257 24X

 Fiche 50-220, 82/10/08, 8210270103
- --8210290107 IE Safeguards Insp Rept 50-220/82-18 on 820915-14 No noncompliance noted Major areas inspected organization & operation shipping & receiving storage & internal control physical inventory & records & repts COHEN, I , MOLTNER, E , GODY, A T Division of Engineering & Technical Programs 82/10/07 &pp 15850 259 24X Etch. 50-220, 82/10/84, 82/10/80103 Fich: 50-220, 82/10/08, 8210290103
- 820819023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-208190438 IE Bulletin 82-03, "Stress Carrosion Cracking in Thick Mail, Large-Diameter, Stanless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enfarcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 8210260177 Ack receipt of 820915 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-220/82-06
 MARTIN.T T Division of Engineering & Technical Programs 82/10/6
 RHDDE, O K Niagara Mohawk Power Corp 1p 15799 042 24X
 Fiche 50-220.82/10/21,8210260177 82710/21
- --8210240184 Responds to NRC 820819 itr re violations noted in iE Insp Rept 50-220/82-06 Corrective actions personnel surveyed, nasel smears taken meeting held w/personnel & disciplinary action taken
 LEMGES.T E Niagara Mohawk Power Corp 82/09/15 MARTIN.T T
 Division of Engineering & Technical Programs 2pp 15799 043
 24x Fiche 50-220,82/10/21.8210260177
- A Periodic operating reports & related correspondence
- 82:0130347 Forwards monthly operating rept for Sept 1982 LEMPGER T E Niagara Mohawk Power Corp 82/10/06 Director's Office, Office of Inspection and Enforcement 1p 15679 134 24K Fiche 50-220.82/10/06.8210130347
- ---8210130350 Monthly operating rept for Sept 1982 ROMAN,T W Niagara Mohawk Power Corp. 82/10/05 App 15679 135 24% Fiche 50-220,82/10/06,8210130347
- 8 Reportable occurrences, LERs & related correspondence
- 82:0150135 Forwards LER 81-019/03L-0 BARTLETT, J Niagara Mohawk Power Corp 81/07/07 GRIER, 8 H Region 1, Philadelphia, Oeffice of the Director (81/03/01) 1p 15697 085 24X Fiche 30-220, 81/07/07, 82:0150135

- --8210150142 LER BL-019/03L-O on 810607. while performing local leak rate testing. I-inch Fisher isolation valve 39-11 of emergency condenser steam line drain sys failed to seat Gausad by worn seating & packing malls Valve repacked NE(LD). J Riagara Hohawk Power Corp 81/07/06 Region i. Philadelphia. Office of the Director (81/03/01) ip 15697 086 24X Fishes 50-220, 81/07/07.82(0150135)
- 8210050284 Forwards LER 82-012/04L-0 LEMPCES,TE Niggara Hohawk Power Corp 82/09/24 HAYNES,R C Region 1. Office of Director 1p 15621 071 24X Fiche 50-220,82/09/24,8210060284
- -8210050271 LER 82-012/04L-0 on 820831. Jower limit of detection sensitivity not met for several radionuclides in analysis of fish samples Tech Spec parameter too narrow for wetfdry weight units conversion Tech Spec revision underway PATROW, N. Nagara Mohaux Power Corp. 82/09/24 Region L. Ottice of Director. Ip. 15621-072 24X Fishe 50-220, 82/09/24, 8210050284
- 8210010007 PNO-1-82-031C on 820924.eight ultrasonic indications found in emergency condenser sys piping & four in shudown cooling sys piping Evaluation revealed indications due to piping geometry & not reportable x1816R.H. BRUNNER.E Region i. Office of Director 82/09/27 by 13565-162 24X Fische 50-220.82/09/27.8210010007
- 8210280121 LER 82-001 has been canceled COLLINS.H Niagara Mohawk Power Corp 82/10/19 Region 1, Office of Director Ip 15837 022 24X Fiche 50-220,82/10/19,8210280121
- DOCKET 50-223 UNIV OF LOWELL RESEARCH REACTOR
- A Periodic operating reports & related correspondence
- G210280183 Forwards monthly operating for June 1982 HALLACE,T Lowell. Univ of 82/10/21 Director's Office. Office of Inspection and Enforcement ip 15037 Oli 24X Fiche 50-223.82/10/21.8210280183
- --8210280186 Monthly operating mept for June 1982

 Lowell. Univ of 82/10/21 7pp 15837 012 24X
 Fiche 50-223,82/10/21,8210280183
- DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR
 F Security, medical, emergency & fire protection plans
- 8210060126 Forwards IE Insp Rept 50-228/82-02 on 820830 & 0902 No noncompliance noted 300K.N E Division of Raddiningical Safety & Gafeguards Program 82/09/15 NEWACKECK.R Acrotest Operations 4pp 15614 320 24X Fiche 50-228.82/09/15.8210060126
- --8210060131 IE losp Rept 50-228/82-02 on 820830-0902 No noncompliance noted Major areas inspected radiation protection program, energency planning program & environ monitoring program CILLIS.H., MEMSLAMSKI,F.A., BOOK,H.E. Division of Radiological Safety & Bafeguards Program 82/09/14 App 15614 324 24X Fiche 50-228,82/09/15,8210060126

- --B209290189 Forwards public version of Revision 4 to generating statics emergency plan corporate command ctr Emergency Plan Inplementing Procedure EGF-3, "Environ/Emergency Coordinator " Receipt form encl PAUDMERI, J E Commonwealth Edison Co. 82/09/01 DENTON, H. R. P.P.C. No. Betailed Affillation Given ip 15544 123 24X Fiche 50-000, 82/09/16, 8209290125
- --8209290225 Public version of Revision 4 to generating station emergency plan corporate command ctr emergency plan implementing Procedure EGF-3, "Environ/Emergency Coordinator"

 PAJONSKI, J E., LITERSKI, L A., FLESSNER, S. A. Communumalth Edison Co. 82/08/31 Jipp 15564 124 24X Fiche 30-000,82/09/16, 8209290125
- 8210010009 Forwards info to suppl 820701 request for exemption from Ajj R per 820917 telcon Request applies to Sections III 0 2 a b 1II 0 3 b re installation of fire suppression sys RAUSCH, T J Commonwealth Edison Co 82/09/23 EISENHUT, D Q Division of Licensing Bpp 15565 152 24X Fiche 50-000.02/09/23, 82(0010009
- 9210130376 Advises that installation of offsite dose calculation sysprogram fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation
 SWARTZ.E D Commonwealth Edison Co 82/10/06 DENTON, H R Uffice of Nuclear Reactor Regulation, Director 2pp 15682 098 24X
 Fiche 30-000682/10/06.8210130376
- 8210290047 Releases public version of revisions to Quad Cities, Zion by Desiden emergency plan annexes & revised generating station emergency plan telephone directory FELTON. J. H. Division of Rules and Records 82/10/08 Document Hanagement Branch 1p 15877 313 24X Fiche 50-000, B2/10/08. B210270047
- --B210270060 Forwards public version of Revision 3 to Quad Cities & Iiii emergency plam annexes. Revision 2 to Dresden emergency plam annexes. Revision 2 to Byron emergency plan annex & revised generating station emergency plan telephone directory MODRE.R D Commonwealth Edison Co 82/07/30 DENTON, H R NRC No Detailed Affillation Given Spp 15877 314 24X Fiche 50-000, 82/10/08, 8210290047
- --8210290077 Public version of Revision 3 to Guad Cities & Zion emergency plan annexes Revision 2 to Dresden emergency plan annex & Revision O to Byron emergency plan annex • Commonwealth Edison Co 82/06/30 102pp 15877 319 24X Fichs 50-000, 82/10/08, 8210290047
- --8210290088 Public version of revised generating station emergency plantslephone directory
 GALLE D P Commonwealth Edison Co 82/08/12 43pp 15878 218
 24X Fiche 50-000.82/10/08.8210290047
- 821022038 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment, Training coordinator assigned in Apr 1782 to improve health physics training programs

 TRANT, T.R. Commonwealth Edison Co. 82/10/14 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 9pp 19776-287 24X Ficha 50-000-82/10/14.8210220358
- 8210230170 Advises that plans & preparedness for offsite protection near facility adequate & will be applied in event of radiological emergency IL State & local plans approved subj to verification of adequacy of alerting & notification sys THOMAS.L M Federal Emergency Management Agency 82/10/14 DIRCKS W J Gffice of the Executive Obsector for Operations 19 13788 265 24X Fiche 50-010,82/10/14.8210250170
- O Adjudicatory correspondence
- 8210010257 Decision ALAB-695 affirming LBP-81-37 & LBP-82-65, sanctioning mod to OL for Unit 3 to permit installation of five high density spent fuel storage racks & authorizing issuence of amends to OLs, respectively TQHPKINS, B A Atomic Safety and Licensing Appeal Panel 82/09/29 2pp 15574 056 24X Fiche 50-237.82/09/29.8210010257
- P Operating license stage documents & correspondence
- 8210080001 Advises that board notification issued on 820903 re use of auxiliary overhead crane rather than main overhead crane to move spent fuel pool racks should have been assued w/Number BN-82-92
 MIRACLIANF. Assistant Director for Safety Assessment 62/09/14
 Atomic Safety and Licensing Board Fanel 4pp 15668 341 24%
 Fiche 30-237.62/09/14.8210080001

DOCKETED ITEMS

- --8210080002 Board Notification 82-92 informs of util failure to carry out fuel pool rack removal & installation in manner described in testimony at hearings Auxiliary overhead crane used instead of redundant main overhead crane IPPOLITO. TA Assistant Director for Safety Assessment 82/09/03 Atomic Safety and Licensing Board Panel 2pp 15668 345 24X Fiche 50-237,82/09/14,8210080001
- --8209210383 Recommends board notification re util use of auxiliary crane instead of main redundant crane to install fuel racks, as described in testimony before ASLB Licensee has committed to follow testimony in completing remaining work IPPOLITO, T.A. Assistant Director for Safety Assessment 82/09/03 EISENHUT, D.O. Division of Licensing 2pp 15668 349 24X Fiche 50-237,02/09/14.8210080001
- 6210050307 Forwards final safety evaluation of SEP Topic VI-4, 'Containment Isolation Sys' Evaluation will be basic input to integated safety assessment Differences from current criteria listed O CONNOR, P Operating Reactors Branch 5 B2/09/24 DELQEORGE, L Commonwealth Edison Co 28pp 15608 184 24X Fiche 50-237, B2/09/24, B2/0050309
- 8210120105 Requests delay of implementation due dates re NUREO-0737, Items II B 2. "Plant Shielding," II B 3. "Post-Accident Sampling" & II F I I. "Noble Gas Effluent Monitor" SWARTZ.E D. Commonwealth Edison Co. 82/10/04 EISENHUT, D 0 BIVISION of Licensing Spp. 15651 237 24X Fiche 50-000,82/10/04,8210120105
- \$210190464 Informs that mods to SRP Section B 3 2 re SEP Topic VIII-3 B on dc power sys bus voltage monitoring & annunciation initiated Mods will provide battery voltage indication in control room & will replace process computer RAUSCHIT J Commonwealth Edyson Co 82/10/05 O'CONNOR, P Operating Reactors Branch S ip 15740 298 24Y Fiche 50-237, 82/10/05, 8210190464
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" COLDEN J C Commonwealth Edison Co 82/10/06 CASE,E 9 Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000,82/10/06
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculatio Manual" - Commonwealth Edison Co 82/09/30 83pp 15805 139 24X Fiche 50-000, 82/10/06, 8210260526
- 8210130326 Comments on proposed scape of Phase III of SEP as reflected in individual topic definitions appended to 820709 itr Staff encouraged to develop b implement means to incorporate positive attributes of Phase III in licensee/NRC interface KACICH.R M SEP Owners Group 82/10/07 EISENHUT.D G Division of Licensing 7pp 15492 179 24% Fiche 50-000, 82/10/07, 8210130326
- J210180057 Provides addi guidance & Clarification re 820806 request for addi info per NUREG-0737. Item II 8 3. "Post-Accident Sampling Sys " Detailed reliability analysis not required to satisfy NRC concerns CRUTCHFIELD, D Operating Reactors Branch 5 82/10/08 DELOEDROF, L Commonwealth Edison Co 3pp 15720 004 24X Fiche 50-000, 82/10/08, 8210180059
- *210190565 Responds to SEP Topic III-4 B, "Turbine Missiles " Visual & fiber optic exams revealed water cutting in line w/keyways on hub wheels RAUSCH.T J Commonwealth Edison Co 82/10/08 D'CONNOR.P Operating Reactors Branch 5 2pp 15736 135 24X Fiche 50-237.82/10/08.8210190565
- 210190480 Forwards safety evaluation of licensee 820414 & Odii responses to NUREO-0737. Item II E 4 2. "Purge/Vent Valve Isolation Dependability " Responses acceptable Topic review completed CRUICHFIELD, D. Operating Reactors Branch 5 82/10/13 DELGEORGE, L. Commonwealth Edison Co. 5pp. 15738 192 24x Fiche 50-237, 82/10/13. 8210190680
- 210190445 Forwards supplemental response to Generic Ltr B2-05 re implementation status of NURGG-0737. Items II B 3,1I F 1 2. II F 1 3, II F 1 5 & II F 1 6,111 response to B21006 request SMARTZ, E D Commonwealth Edison Co 82/10/14 EISENHUT, D D Division of Licensing 5pp 15741 202 24X Fiche 50-000,82/10/14,8210190445
- 210220335 Forwards info re NUREO-0737. Item II D 1, "Performance Testing of BWR Safety/Relief Valves," per 820727 request Info adequately demonstrates applicability of results of BWR owners group generic test rept NEDE-24988-P to facility SWARTZ.E D Commonwealth Edison Co 82/10/15 EISENHUT, D Q Division of Licensing 17pp 15776 011 24X Fiche 50-237.82/10/15, 8210220335

- 82:0250203 Forwards preliminary draft of integrated plant safety assessment rept.Chapter 4. "Integrated Assessment Summary "
 Encl draft includes commitments submitted in response to NRC 820715 ltr & assessment meetings CRUTCHFIELD.D Operating Reactors Branch 5 82/10/15 DELOECRGE.L Commonwealth Edison Co 60pp 15789 204 24X Fiche 50-237,82/10/15,8210250203
- 8210250155 Forwards corrections to proposed Tech Spec Pages 1 2/2 2-1: 1, 9/4 3-5, supporting review of future reloads & revised Figure 3 5 i. Sheet i. providing extended MAPLHOR vs. exposure curves for berrier lead test assembly fuel RAUSCH.T J. Commonwealth Edison Co. 82/10/18 DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director 2pp 15768 233 24X Fache 50-000, 82/10/18, 8210250155
- --8210250177 Errata & Addenda Sheet 8, replacing Page 4-10 to "LUCA Analysis Rept for Dresden Units 2 & 3 & Guad Cities ! & 2 Nuclear Pouer Stations " * General Electric Co NEDD-24146A ERR 08 82/09/30 3pp 15788 239 24X Fichs 50-000, 82/10/18, 8210250155
- 8210250069 Provides additinfore reactor water cleanup room area temp monitors Temp elements cause no automatic plant response beyond control room alarms
 RAUSCH, T. J. Commonwealth Edison Co. 82/10/19 £15ENHUT, D. Q. Division of Licensing 2pp 15787 081 24X Fiche 50-000, 82/10/19, 8210250069
- 8210260485 Provides add1 info re actuation of relief valve PRV 2-1201-80 on reactor water cleanup sys Existing configuration adequate to handle transient w/o either reactor screm or reactor water cleanup overpressurization RAUSCH.T J Commonwealth Edison Co 82/10/19 0'CONNOR,P Operating Reactors Branch 5 2pp 15807 257 24X Fiche 50-237.82/10/19.8210260485
- 8210260296 Forwards safety evaluation of BWR owners group generic response to NUREO-0737. Item II K 3 25. "Effect of Loss of AC Power on Pump Seals " No mods to seal cooling for recirculation pumps required Item resolved CRUTCHFIELD.D Operating Reactors Branch 5 82/10/21 DELGEGRGE, L Commonwealth Edison Co 7pp 15803 018 24X Fiche 50-237. 82/10/21.8210260296
- O Inspection reports, IE Bullstins & correspondence
- 02:0040329 Forwards IE Insp Repts 50-010/82-02.50-237/92-03 & 50-249/82-03 on 820:19-02:8 No noncompliance noted LITTLE,W 9 Division of Engineering & Yechnical Programs 82/09/22 REED.C Commonwealth Edison Co 2pp 154:5 33: 24X Fiche 50-010,82/09/22.82:0040329
- --8210060335 IE Insp Repts 50-010/82-02.50-237/82-03 & 50-249/82-03 un 820119-0218 No noncomptiance noted Major areas inspected open & unresolved items & items of noncompliance reintegrated leak rato test REIMANN.F W Region 3, Office of Director JACKIW,I N Division of Engineering & Technical Programs 82/09/21 7pp 15615 333 24X Fichs 50-010.82/09/22.8210060329
- 8210150523 Forwards IE Insp Repts 50-010/82-13,50-237/82-17 50-249/82-18 on 820708-0809 & notice of violation STREETER, J F Division of Project & Resident Programs REED: C Commonwealth Edison Co 2pp 15713 099 PAY Fiche 50-010,62/09/28,8210150523
- --B210150838 IE Insp Repts 50-010/82-13,50-237/82-17 & B20708-0809 Noncompliance noted failure to issue & air pressure test procedure TONOUE, T M. JORDAN, M J., WALKER, R D. Division of Resident Programs 82/09/28 8pp 15713 102 24 Fiche 50-010,82/09/28,8210150523
- 8210060339 Ack receipt of 820910 itr informing NRC of a correct violations noted in IE Insp Repts 50-237/81-550-249/81-32, 50-254/81-23, 50-265/81-23, 50-275/81-31 & 50-304/81-29 SPESSARD, R L Division of Project & Resident Program REED, C Commonwealth Edison Co ip 15618 334 24 Fiche, 50-000, 82/10/01/8210060359.
- --82i0060367 Responds to NRC 820712 ltr re violations n Repts 50-237/81-39,50-249/81-32,50-254/81-23,50-265 50-295/81-31 & 50-304/81-29. Corrective actions trai mgt priorities re plant availability will be conduc REED, C Commonwealth Edison Co 82/09/10 KEPPLE 3, Office of Director 13pp. 15618,355 24% Fiche,50-000,82/10/01,8210060359.

- 8210080178 Forwards listing of piping sys which fail to meet FSAR requirements, per IRC 800818 confirmatory action ltr iE Bulletin 79-14 operability evaluation updates until not be provided for Bresden & Guad Cities Final update by Dec 1982 RAUSCH. T J Commonwealth Edison Co 82/10/01 KEPPLER. J G Regio 3, Defice of Director App 15440 L59 24X Fiche 50-000.82/10/01, pp.0000138
- 8210150539 Forwards IE insp Repts 50-010/82-15.50-237/82-19 & 2003037 Forwards II in graphs Sovetone 18 10 237/16277 A
 50-249/08-20 on 820800-0903 No noncompliance noted
 PAPERIELLO, C J Division of Emergency Preparedness & Operational
 Bupport B2/10/01 REED, C Commonwealth Edison Co 2pp
 15714 175 24X Fiche 50-010, B2/10/01, 8210150539
- --B210150543 IE lnsp Repts 50-010/B2-15,50-237/B2-19 & 50-249/B2-20 on 820B30-0903 & 07 No noncompliance noted Major areas inspected confirmatory measurements program GC program for analytical measurements & environ monitoring program SCHUMACHER: M.C. NICHOLEON, N.A. JANUSKA, A.G. Division of Energency Preparedness & Operational Support 82/09/30 7pp 15714 177 24X Fiche 50-010.82/10/01.8210150539
- 8210060266 Confirms 821103 enforcement conference at Region 3 off re 0A aspects associated w/procurement, installation & use of non-qualified valve guides in electramagnetic relief valves at facilities
 SPESSARD.R L Division of Project & Resident Programs 82/10/04 REED, C Commonwealth Edison Co ip 15640 181 Fichs 50-000, 82/10/04, 821 0080 190
- 8210080170 Confirms 821103 enforcement conference at Region 3 ofc re GA aspects associated m/procurement, installation & use of non-qualified valve guides in electromagnetic relief valves at facilities

 SPESGARD.R L Division of Project & Resident Programs 82/10/04

 REEO.C Commonwealth Edison Co 1p 15640 181 24X

 Fichs 50-000, 82/10/04, 8210080190
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leating & Dislodged i-125 Implant Seeds " Syc list enci
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-WIGHTHERS IN METERS OF THE STREET CONTROL OF THE CHARLES STEED, PROTECTION OF THE CHARLES STEED, PROTECTION OF THE PROTECTION OF THE CONTROL OF THE CONTROL
- R Periodic operating reports & related correspondence
- 8210180097 Forwards monthly operating repts for Sept 1982 SCOTT.D J. Commonwealth Edison Co. 82/10/01 Director's Office of Inspection and Enforcement Ip. 15718 001 24X Fiche 50-010.82/10/01.8210180097 Director's Office,
- --8210180100 Monthly operating repts for Sept 1982 BCHROEDER, B. A. Commonwealth Edison Co. 82/10/01 15718 002 24X Fiche 50-010,82/10/01,8210180097 2200
- S Reportable occurrences. LERs & related correspondence
- 8210150044 Forwards LER 81-059/031-0 SCIDTL D J Commonwealth Edison Co 81/10/08 XEPPLER, J Q Res S. Chicago, Office of the Director (81/03/01) 1p 15701 126 Fiche. 50-237, 81/10/08, 8210150044 Region 26 24X
- --B210130049 LER 81-039/03L-0 an 810910, while conducting insp on pump 2A.CCSW outboard bearing found burned out Caused by lack of lubricetion in sealed bearing Bearing replaced ZIRMAS, X R Communealth Edison Co 81/10/08 Region 3. Chicago, Office of the Director (81/03/01/2pp 15701/127 24) Fiche 50-237.81/10/08.8210130044. 2pp 15701 127 24X
- 8210080915 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Deruments in App B completely withheld (ref FOLA Exemption 5]
 FELTON. J. H Division of Rules and Records. 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15645 027 24X
 Fisha 50-000.82/07/12.8210080015
- --8210080197 NRC operations ctr usage chart re events at facilities * NRC No Datalied Affiliation Glven 82/07/12. 1p i3668-221 24X Fiche 50-000.82/07/12.8210080015

- 8210040188 Forwards LER 92-040/03L-0 SCOTT, D.J. Commonwealth Edison Co. 82/09/15 KEPPLER, J.O. Regist 3. Office of Director Lp. 15583 164 24% Fiche 50-237,82/09/15, Region 821004018B
- --9210040189 LER 82-040/03L-O on 820830. valve Z-1601-33A exhibited binding during movement while performing torus-drywell vacuum breaker operability test (DOS 1600-91 Cause not determined Repairs to be made during next outage
 WEE, D T Commonwealth Edison Co 82/09/15 Region 7, Office et
 Director 2pp 15583 165 24X Fiche 50-237,82/09/15,82(0040188
- 8210050227 Forwards LER 82-038/03L-0 SCOTT.D J Commonwealth Edison Co 82/09/22 KEPPLER, J Q Region 3. Office of Director 1p 15611 026 24% Fiche 50-237,82/09/22, 8210050227
- --8210050233 LER 82-038/03L-0 on 820829, during MSIV timing jurveillants valves 2-203-(C & 2-203-10 had closed times of 2 25-s & 2 67-s, respectively Caused by timing mechanism drift Valves
 - adjusted
 RMEE.S Commonwealth Edison Co 82/09/22 Region 3. Office o
 D(rector 2pp 15611 027 24% Fiche 50-237, 82/09/22, 8210050227 Region 3. Office of
- 8210040198 PNO-III-82-101 on 820824, plant tripped due to broken cooling water line to generator hydrogen cooling sys spraying water onto current transformer Line repaired & transformer replaced
- replaced TONGUE, T., WALKER, R. & STREETER, J. Region 3. Office of Director 82/09/27 ig 15883 147 24% Fiche 50-237.82/09/27.8210040[40 82/09/27
- 8210250268 Forwards LER 62-042/03L-0 SCOTT.D J Commonwealth Editon Co 82/10/12 KEPPLER.J G Region 3, Office of Director ip 15791 145 24X Fiche 50-237,02/10/12, Region 8210250268
- --8210250278 LER 82-042/03L-0 on 820930, control rod drive N-\$0 overtrad 21022027B LEN 82-092703.—Don 82073D, control rod drive N-10 overta.

 **alarm annunciated & rod position indication lost Caused by
 uncoupled inner filter Drive recoupled at greater than 207
 power Drive will be overhauled during next refueling outage
 **HOLLAND, P Commonwealth Edison Co 82/10/12 Region 3. Uffice
 of Director 20p 15791 146 24% Fiche 50-237, 82/10/12. 8210250268
- 8210250283 Forwards LER 82-042/01T-0 SCOTT.D J Commonwealth Edison Co 82/10/14 KEPPLER, J G Reg. 3. Office of Director ip 15791 102 24X Fiche 50-237,82/10/1 8210250283
- --8210250296 LER 82-042/01T-O on 821002, sightglass isolation & vent valves reported open w/no indication of excess makeup Calculations indicate leakage was in excess of Tech Spec Caused by operator error Valves closed HOLLAND, P. Commonwealth Edison Co. 82/10/14 Region 3 of Director 3pp (5791 103 24X Fiche 50-237,82/10/14, 221/10/2022 Region 3. Office 8210250283
- DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1 F Security, medical, emergency & fire protection plans
- 8210150621 Releases public version of revision to emergency plan implementing procedures FELTON.J H Division of Rules and Records 62/09/30 Docum Management Branch 1p 15717 064 24X Fiche 50-244,82/09/30, 8210150621
- --8210130443 Forwards public varsion of revision to emergency plan implementing procedures, including Procedure SC-411 re NY State warning point test & Procedure SC-410 re insp of emergency equipment
 MAIER, J E Hochester Cas & Electric Corp 82/09/23
 CRUTCHFIELD, D Operating Reactors Branch 5 1p 15717 065 243 Fiche 50-244, 82/09/30, 8210150421
- --8210159648 Public version of revision to emergency plan implementing procedures, including Procedure 80-411 re NY State warning point phone test & Procedure 80-410 re insp of emergency soulament BODINE, J C . SPECTER, 6 M 7, SPECTER, 6 M. Rochester Gas & Electric Corp. 48pp. 15717 064 24X Fiche 50-244, 82/09/30, 821015068 82/09/20
- 8210190580 Ack receipt of 820224 ltr informing NRC of steps taken is correct violations noted in IE Insp Rept 50-244/81-22 ALLANJ H Region i. Office of Director 82/10/07 HAIER. J E Rochester Gas & Electric Corp ip 15739 307 24X Fiche 50-244, 82/10/07, 8210190580

- --B210190591 Responds to NRC Bil215 ltr re violations noted in 1E Insp Rept 50-244/Bi-22 Corrective actions emergency plan training program will be realigned by B20115 to be consistent w/ functional area requirements MAIER. J E Rochester Gas & Electric Corp B2/02/24 HAYNES. R C Region 1. Office of Director 4pp 15739 308 24X Fiche 50-244.82/10/07.8210190580
- --8210190418 Responds to NRC 811215 ltr re violations noted in 1E Insp Rept 50-244/81-22 Corrective actions clarified required action, eliminated existing ambiguities; inconsistencies & errors for emergency functions HAIFR. J E Rochester Gas & Electric Corp 82/04/19 HAYNES. R C Region 1. Office of Director 2pp 15739 312 24X Fiche 30-244,82/10/07.8210190580
- --82:019063/ Responds to NRC 820520 ltr re violations noted in IE Insp Rept 50-244/81-22 Corrective actions committee established to evaluate & inventory supplies Rept will be submitted by 82:1231 MAIER, J E Rochester Oas & Electric Corp 82/06/30 SMITH.G H Division of Emergency Preparedness & Operational Support 22pp 15739 314 244 Fiche 50-244,82/10/07.8210190380
- ~-8210190647 Responds to NRC 811215 itr reviolations noted in IE Insp Rept 50-244/81-22 Corrective actions revision of Emergency Plan 8C-i completed prior to startup after 1982 refueling shutdown MAIER, J E Rochestor Gas & Electric Corp 82/10/07 HAYNES, R C, Region I, Office of Director 1p 15739 336 24X Fiche 50-244,82/10/07,8210190580
- 6210290212 Ack receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-15 STAROSTECKI, R Division of Project & Resident Programs 62/10/25 MAIER, J E Rochester Gas & Electric Corp in 15853 279 24% Fiche 50-244-82/10/25.8210290212
- --8210290217 Responds to NRC 820914 itr re violations noted in 1E Insp Ropt 50-244/82-15 Corrective actions situation reviewed & determined to be isolated case Further action unnecessary MAIER.J C Rochester Gas & Electric Corp 82/10/15 BRUNNER,E J Region 1. Office of Director 2pp 15853 280 24X Fiche 50-244,82/10/25,8210290212

a Adjudicatory correspondence

- 8210280060 Updates 820730 status rept on NRC issuances Final integrated plant safety assessment rept to be issued on 821029 Conversion safety evaluation rept & update to FEB to be issued in Nov YOUNG: If A Hearing Branch 4 82/10/26 OROSSMAN, H, LUEBKE, E A, COLE, R F Atomic Safety and Licensing Board Panel ip 15837 262 24X Fiche 50-244,82/10/26,8210280060
- Ū Advisory Committee on Reactor Safaguards reports & correspondence
- 8208290018 Summarizes 268th ACRS meeting on 820812-14 in Washington, DC re full power OLs for Grand Oulf I & Watts Dar I & II, systematic evaluation & integrated reliability assessment or Ginna & control room habitability SHEMYON, P ACRS Advisory Committee on Reactor Safeguards 82/08/06 PALLADINO, N J Commissioners 3pp 15647 233 24X Fiche 50-000: 82/08/26, 8200270018
- 8210180074 Forwards 820917 response to ACRS comments & recommendations per facility SEP review CRUTCHFIELD, D Operating Reactors Branch 5 82/10/07 MAIER, J E Rochester Gas & Electric Corp 2pp 15719 347 24X Fiche 50-244,82/10/07.8210180074
- --8210180083 Responds to ACRS 82081B comments & recommendations refactlity SEP review Draft NUREO-0821 will be revised to reflect agreements

 DENTON, H R Office of Nuclear Reactor Regulation, Director 82/09/17 SHEWMON, P S ACRS Advisory Committee on Reactor Safeguards 2pp 15719 349 24X Fiche 50-244,82/10/07, 8210180074
- P Operating license stage documents & correspondence
- B210010008 Responds to FOIA request for 19 catagories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000, 82/06/28, 8210010008

- --8003310179 Forwards NRC evaluation of use of four mixed oxide fuel assemblies for Cycle 10 Use of assemblies is acceptable ω/nα changes For future cycles NRC wift require increase in nuclear uncertainty ne total peaking factor CHECK, P S Reactor Safety Branch 80/03/11 ZIEMANN.D L Operating Reactors Branch 2 (Pre 800428) 8pp 19727 036 24X Fichs 50-000, 82/06/28, 8210010008
- 8210120103 Addl respons» to FOIA request for nine categories of records generated by present NRC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents FELTON. J M Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 3pp 18690 117 24% Fiche 50-000.82/07/12,8210120103
- --B210120151 Agrees w/point raised in 820201 mamo re NRC incident response program Points raised by staff will be addressed in rept on lessons learned at incident response ctr from facility event
 PALLADINO, N J Commissioners 82/02/16 RDERTS, T M Commissioners 19 15690 13B 24X Fiche 80-000,82/07/12, 8210120103
- 8210070007 Responds to FDIA request for eight categories of records rosteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-333 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007
- ---8202170310 Forwards background summary of operating experience w/
 steam generators prior to 820125 tube rupture
 JOHNSTON, W V Assistant Director for Materials & Qualifications
 Engineering 82/01/29 LAINAS-G C Assistant Director for Bafety
 Assessment 5pp 15645 104 24X Fiche, 50-000, 82/08/10.
 8210070007
- --6202240397 Submits daily highlight re 920203 insp of steam generator () to determine location of 620125 ruptured tube event Eddy current tests performed on tube near periphery on hot leg side & four adjacent tubes
 LYONS, J E Operating Reactors Branch 5 62/02/03 DENTON, H ,
 CARTER, J , EISENHUT, D NRC No Detailed Affiliation Olven ip 15645 089 24X Fiche 50-000, 62/08/10.8210070007
- --8203020267 Submits daily highlights for 820210 meeting w/util re requirements for restart Prior to restart.util should finish fiber optic insp of secondary side of 8 steam generator & obtain designer opinion on effects of plugging LYONS, J E Operating Reactors Branch 5 82/02/11 DENTON.H R . CARTER, J . EISENHUT, D . NRC Na Detailed Affiliation Given ip 15645 072 24X Fichs. 50-000.82/08/10.8210070007
- ---8203040502 Submits daily highlight re television insp of B steam generator revealing missing, partially missing & damage tubes & presence of foreign objects Mesting WARC planned LYONS, J E. Operating Reactors Branch 5 B2/02/19 DENTON, H . CARTER, J . EJSENHUT, D NRC No Detailed Affiliation Given. ij 15443 096 24X Fiche 50-000,82/08/10,8210070007
- --8203100573 Submits daily highlights he insplot ruptured tube using fiber optics Five-inch kite shaped rupture caused by stress corrosion linked to differential expansion between tube k tube wrapper wedge Tube being plugged LYONS, J.E. Operating Reactors Branch 5 82/02/08 DENTON, H. GARTER, J. FISENHUIT. D. NRC No Detailed Affiliation Given 1p 15645 091 24X Fiche 50-000,82/08/10,8210070007
- --8203110334 Submits highlights re fiber optic investigation of secondary side of B steam generator revealing damage to previously plugged tubes freliminary indications show one tube severed investigation of peripheral area continuing.

 LYONS, J E Operating Reactors Branch 5 B2/02/12 DENTON.H . CARTER, J . EISENNUT.D NRC No Datalled Affiliation Given ip. 15645 094 24% Fiche 50-000, B2/08/10, B210070007
- --8203110337 Submits daily highlights re insp of periphery of B steam generator had leg Insp results indicate approx 7-10 previously plugged tubes in peripheral area severly damaged TV insp planned for A & B generators.

 LYDNS, J E Operating Reactors Branch 5, 82/02/16 DENION, H, CARTER, J. EIEENHUT, D NRC No Detailed Affiliation Given 2pp 13645 075 24% Fithe 50-000, 82/08/10,8210070007
- --8203110403 Forwards response to JD Dumela chairman of Pollution Control Board State of IL questions in 820127 ltr JOHNSTON, M. V. Assistant Director for Materials & Qualifications Engineering 82/02/22. LAINAS. G. Assistant Director for Safety Assessment. 2pp. 15648 124 24X Piche. 50-000, 82/08/10. 8210070007.

- --8206070250 Forwards Operating Reactors Assessment Branch input for Ginna restart safety evaluation rept. Section 5.re steam generator insp program. Failure analysis & repairs 1PPOLITO. I.A. Operating Reactors Assessment Branch 82/05/18 CRUTCHFIELD.D Operating Reactors Branch 5 45pp 15645 138 24X Fiche 50-000.92/08/10.6210070007
- --8206290655 Forwards Hechanical Engineering Branch input to restart SER Sections 4 5 through 4 8.5 1.5 2.5 4.6 1 & 6 2.per 820423 request XNIOHT.J P Assistant Director for Components & Structures Engineering 82706/15 LAINAS.0 C Assistant Director for Safety Assessment 13pp 15645 183 24X Fiche 50-000.82/08/10.
- --8210070030 Util handout from 820210 meeting w/NRC re 820125 steam generator tube rupture at facility * Rochester Gas & Electric Corp 82/02/10 17pp 15645 072 24X Fiche 50-000, 82/08/10.8210070007
- --B210070068 Submits daily highlight re 820210 meeting w/util concerning requirements to be met prior to restart of facility No sufficient basis presented at this time to permit plant to return to operation LYONS.JE Operating Reactors Branch 5 82/02/11 DENTON.H. CARTER.J. EISENNUT.D NRC No Detailed Affiliation Given 1p 15445 093 24X Fiche 50-000.82/08/10.8210070007
- --82i0070073 Submits daily highlight re util 820219 press conference presenting update on recovery activities at facility Masting w/NRC scheduled for 820302 LYONS.JE Operating Reactors Branch 5 82/02/22 DENTON.H., CARTER.J. EISENHUT.D NRC No Detailed Affiliation Given [p 15645 097 24X Fiche 50-000,82/08/10.8210070007
- ---B210070074 Submits daily highlight re B20301 meeting w/util & B20302 meeting w/Westinghouse in Betheda: ND to discuss recovery activities at facility & generic steam generator tube degradation: respectively tyONB.J E Operating Reactors Branch 5 82/02/26 DENTON.H; CARTER.J; EISENHUT.D NRC NO Detailed Affiliation Given ip 15445 078 24X Fiche 50-000, B2/08/10.8210070007
- --B2100700B0 Submits doily highlight re B20301 meeting w/util re proposed recovery program for facility NRC concurred w/proposal to remove small number of steam generator tube sections for metallurgical exam
 LYONS-JE Operating Reactors Branch 5 B2/03/04 DENTON.H,
 CRRYER,J, EISENHUT,D NRC No Detailed Affiliation Given ip
 15445 099 24X Fiche 50-000,82/09/10.8210070007
- --B210070083 Bubmits daily highlight re util completion of cutting 3-inch hole in stram generator B on 82030B Burst tube & tubes 844054.R43054 & R43056 removed for metallurgical eram Meeting tentatively scheduled for 820322 LYONS-J.E Operating Reactors Branch 5 B2/03/10 DENION.H. CARTER.J. EISENNUT.D NRC NO Detailed Affiliation Given 1p 15645 100 24X Fiche 50-000.82/08/10.8210070007
- --8210070087 Bubmits daily highlight re 820323 meeting w/util to the stinghouse concerning status of proposed repair activities Twenty-four tubes removed from steam generator Beforeign object found in Hedge Area 4
 LYONS-JE Derating Reactors Branch 5
 82/04/05 DENTON.H.
 CARTER-J. EIBENHUT.D NRC No Detailed Affiliation Given 2pp 13545 101
 24X Fiche 50-000, 82/08/10.8210070007
- --B210070090 Submits daily highlight re restart of facility Plant expected to be ready for operations above 5% power upon completion of startup physics testing on 820325 DENTON.H , CARTER.J . EISCHUT.D NRC No Detailed Affiliation Given ip 15645 103 24% Fiche 50-000.82/09/10.8210070007
- --8210070121 Forwards preliminary estimate of leak rate vs time during Ginna 820125 steam generator tube rupture event & plot showing important parameters & status of sys IPPOLITIO.TA Operating Reactors Assessment Branch 82/02/05 RDE.J. NRC No Detailed Affiliation Given 3pp 15645 121 24% Fiche 50-000,82/08/10.8210070007
- --B210070135 Bevil rept input re Ginna 820125 steam generator tubo rupture event NRC 15th monthly status rept to Congress re THI-1 restart enc!

 * NRC No Detailed Affiliation Given 82/03/11 3pp 15545 128. 24X Fiche 50-000, 82/08/10.8210070007
- --8210070165 Beyil rept input re removal of selected tube samples through two access ports drilled in side of steam generator to obtain metallurgical date for evaluation of steam generator B tube failure mechanism

 # NRC No Detailed Affiliation Given 82/04/0B 2pp 15645 136 24% Fiche 50-000, 82/08/10,8210070007

- B210010444 Responds to NRC 020902 request for review of NUREO-0737, ltem 11 B 3, "Post-Accident Sampling "Criterion will be adequately addressed by 030213 MAIER.JE Rochester Oas & Electric Corp 82/09/23 CRUTCHFIELD.D Operating Reactors Branch S ip 15570 174 24X Fiche 50-244, B2/09/23. B210010444
- 8210010397 Forwards application to amend App A of License BPR-18 & proposed Tech Specs to permit reorganization of plant staff MAIER. J E Rochester Gas & Electric Corp 82/09/28 DENTON, H G Office of Nuclear Reactor Regulation, Director 1p 15574 144 24x Fiche 50-244.82/09/28.8210010357
- --8210010365 Application to amend App A of License DPR-18, changing lech Specs to germit reorganisation of plant staff MAIER. J E Rochester Gas & Electric Corp 82/09/28 2pp 13974 145 24% Fiche 50-244.82/09/28.8210010357
- --8210010369 Proposed Tech Spec changes to permit reorganization of plant staff

 * Rochester Gas & Electric Corp 82/09/28 11pp 15574 147 24% Fiche 50-244,82/09/28,8210010357
- 82:0040281 Forwards application to amend License DPR-19, revising containment isolation boundary requirements MAIER. J E Rochester Gas & Electric Corp 82/09/28 DENTON. H II Office of Nuclear Reactor Regulation. Director 1p 15587 167 24K Fiche 50-244.82/09/28.8210040281
- --8210040284 Application to amend License DPR-18, revising containment isolation boundary table MAIER, JE Rochester Gas & Electric Corp 82/09/28 4pp 15587 170 24X Fiche 50-244,82/09/28,8210040281
- --8210040288 Proposed change to Tech Spec Page 3 4-6 re containment isolation boundary table Safety evaluation enc1
 * Rochester Qas & Electric Corp 82/09/28 3pp 15587 i74 24k Fiche 50-244,82/09/28.821004028
- B210050214 Notifies that except for occasional transient species.co
 federally listed or proposed threatened or endangered
 species exist in project impact area. in response to B20702
 request Federal list of endangered species enci
 HAMILYDN, P Interior. Dept of. Fish & Wildlife Service B2/07/20
 CRUTCHFIELD. D Operating Reactors Branch 5 Jpp 15611 297 24X
 Fiche 50-244.82/09/28.8210050214
- B210050059 Approves B00220 request for withholding info re use of mixed oride fuel assemblies for Cycle iQ from public disclosure (ref 10CFR2 790)
 CRUTCHFIELD,D Operating Reactors Branch 5 82/09/29
 WIESEMANN,R A Westinghouse Electric Corp 3pp 15603 171 24x
 Fiche 50-244,82/09/29,8210050059
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820709 ltr Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface MACICH's H SEP Duners Group 82/10/07 EISENHUT.D 0 Division of Licensing 7pp 15682 179 24X Fiche 50-000.82/10/07.8210130326
- 8210180074 Forwards 820717 response to ACRB comments & recommendations per facility SEP review CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/07 MAIER. J E. Rochester Oas & Electric Corp. 2pp. 15717 347 24X Fiche 50-244,82/10/07,8210180074
- --8210180083 Responds to ACRS 820818 comments & recommendations re facility SEP review Draft NUREO-0821 will be revised to reflect agreements DENTON, H R Office of Nuclear Reactor Regulation, Director 82/09/17 SHEWMON, PS ACRS ~ Advisory Committee on Reactor 8afeguards 2pp 15719 347 24X Fiche 50-244,82/10/07, 8210180074
- 8210180082 Forwards Amend 54 to License DPR-18, safety evaluation & notice of issuance & availability Amend approves provisions updating containment isolation valve in Table 3 4-1, to reflect plant sys mod CRUTCHFIELD.D Operating Reactors Branch 5 82/10/07 MAIER, J E Rochester Oas & Electric Corp. 2pp. 15719 294 24% Fiche 50-244, 82/10/07, 8210180082
- --8210180087 Amend 54 to License DPR-18.approving provisions updating containment isolation valve in Table 3 6-1.to reflect plant sys mod CRUTCHFIELD.D Derating Reactors Branch 5 62/10/07 1p 19719 296 24X Fichs.50-244.82/10/07.8210180082
- --8210180090 Sefety evaluation supporting Amend 54 to License BPR-18 + Office of Nuclear Reactor Regulation, Director 82/10/07 Dep 15719-300 24X Fiche 50-244,82/10/07,8210180082

- 8210180112 Forwards 821004 FR notice announcing ACRS Subcummittee on Extreme External Phenomena 821021 & 22 meetings in Santa Monica. CA to discuss flooding to seismic hazards CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/07 MAIER, J.C. Rochester Oas & Electric Corp. 3pp. 15719 322 24X Fiche 50-244, 82/10/07, 8210180112
- 8210180149 Forwards Amend 55 to License DPR-18, safety evaluation & notice of issuance & availability Amend incorporates new License Condition 2 C(10) to confirm that nert steam generator insp will be performed during refueling outage CRUTCHFIELD. D. Dperating Reactors Branch 5 82/10/08 MAIER. J E Rochester Cas & Electric Carp. 2pp 15717 105 24X Fiche 50-244.82/10/08.8210180147
- --9210180153 Amend 53 to License DPR-18, incorporating new License Condition 2 C(10) to confirm that next steam generator inspirivolving eddy current & visual insps & water lancing will be performed during refueling outage CRUTCHFIELD, D Operating Reactors Branch 5 82/10/08 2pp 15719 107 24% Fiche 50-244,62/10/08.6210180149
- --821018015B Safety evaluation supporting Amend 55 to License DPR-18
 4 Office of Nuclear Reactor Regulation, Director 82/10/08 3p
 15717 107 24X Fiche 50-244,82/10/08.8210180147
- --8210180161 Notice of issuance & availability of Amend 55 to License DRR-18 GRUTCHFIELD,D Operating Reactors Branch 5 82/10/08 2pp 15719 112 24X Fiche 50-244,82/10/08,8210180149
- 8210180181 Clarifies 820902 request for add1 info re NUREO-0737. Item II B 3, "Post-Accident Sampling Sys " Clarification section of 820902 ltr provides staff guidelines.not requirements on meeting NUREO-0737 criteria CRUTCHFIELD.D Deprating Reactors Branch 5 82/10/08 MAIER.J E Rochester Gas & Electric Corp 3pp 15719 145 24X Fiche 50-244.82/10/08.8210180181
- B210220105 Advises that review of util 810904 response to NUREG-0737, Item III D 3 4, "Control Room Habitability," completed Issue satisfactorily resolved except for single failure criterion of Intake & exhaust ductwork CRUTCHFIELD D Operating Reactors Branch 5 82/10/18 MAIER, J E Rochester Gas & Electric Corp 2pp 15775 100 24X Fiche 50-244, 82/10/18, 8210220105
- --8209140027 Informs that info submitted by licensee in response to NUREO-0737. Item III D 3 4. "Control Room Habitability" acceptable MURPHY: D W Battelle Hemorial Institute, Pacific Northwest Laboratory FIN 8-2323 82/03/23 HULMAN, L Q Accident Evaluation Branch 2pp 15775 102 24X Fiche 50-244,82/10/18,8210220105
- B210250275 Forwards status rept re unresolved safety issues, per NRC B20617 request Info includes description of problem based on NRC documentation MAIER, J E Rochester Gas & Electric Corp B2/10/19 CRUTCHFIELD, D Operating Reactors Branch 5 47pp 15791 049 24% Fiche 50-244, 82/10/19, 8210250275
- O Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FDIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON. J M Division of Rules and Records 82/08/10 LONG. D J Winthrop, 8timson. Putnam & Roberts 9pp 15445 063 24X Fiche 50-000. 82/08/10.8210070007
- --8210070038 Submits daily highlight to May 1981 insp of ruptured tube in Oinca steam generator Failed tube located in wedge area of steam generator
 LYUNB, J E Operating Reactors Branch 5 82/02/04 DENTON, H,
 CARTER, J. EIBENHUT, D NRC No Detailed Affiliation Given ip
 15648 090 24X Fiche 50-000, 82/08/10, 8210070007
- --8210070137 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensess IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VAROA.B Operating Reactors Branch 1 5pp 15645 131 24X Fichs 50-000,82/08/10,8210070007

- --8210070172 Forwards info re steam generator integrity & insps at all operating PURs.per 750320 & 21 requests Details of insps. including defect indications tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 GOLLER.K R Division of Reactor Licensing (RRR-1975 only) 75/03/24 HACCARY.R R Division of Perthical Review (NRR-1975 only) 5pp 15645 196 24X Fishe 50-000.62/08/10.6210070007
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Svc list enc! CDBL I Division of Fuel Familities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15/61 250 24X Fichs 50-000.82/10/06 H208197023
- 6210130439 Discusses results of eddy current fiber optics,video & visual insps Burst in Inactive tube in B-steam generator inlet probably caused by reduction in uall due to wear & pressurization from primary side through leaking plug MAIER. J E Rochester Gas & Electric Corp 82/10/06 CRUTCHFIFLD. D Openating Reactors Branch 5 3pp 15682 010 24x Fiche 50-244.82/10/06.8210130439
- 8210210201 Forwards IE Insp Rept 50-244/82-16 on 820830 0903 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/10/06 MATER.J E Rochester Gas & Electric Corp &p 15/66 345 24X Fiche 50-244
- --8210210213 IE Insp Rept 50-244/B2-16 on 820830 0703 No noncompliance noted Major areas inspected followup on previously identified insp findings, administrative controls for design changes & mod & mod & design program BLUMBERGN , BISSETT-P , CAPHTON B L Division of Project & Resident Programs 82/10/05 9pp 15766 147 24x Fiche 50-244,82/10/06.8210210201
- 8210190580 Ack receipt of 820224 ltr informing NRL of steps taken to correct violations noted in IC Insp Rept 90-244/81-22 ALLAN-J M Region I. Office of Director 82/10/07 MA(FR.J E Rochester 0a* & Electric Coip ip 15739 307 24x Fiche 50-244,82/10/07.8210190580
- --8210190591 Responds to NRC 811215 itr re violations noted in It Insp Rept 50-244/81-22 Corrective actions emergency plan training program will be realigned by 820115 to be consistent w/ functional area requirements MATER.JE Rochester Oas & Electric Corp 82/02/24 MAYNE's, R C Region 1. Office of Director 4pp 15739 700 24y Fiche 50-244.82/10/07.8210190580
- --8210190618 Responds to NRC 811215 ltr re violations noted in IL lisp Rept 50-244/81-22 Corrective actions clarified required action, eliminated existing ambiguities, incunsistencies & errors for emergency functions
 MAIER.J E Rochesfer Gas & Electric Corp 8/2/04/19 HAYRES. 8 (Rejion 1. Office of Director 2pp 157.39 312 24% Fiche 50-244,82/10/07,8210170580
- --8210190637 Responds to NRC 820520 itr re violations noted in II insp Rept 50-244/81-22 Corrective actions committee established to evaluate & inventory supplies Rept will be submitted by 821231 MAIER, J.E. Rochester Qas & Electric Corp. 82/06/30 SMITH, G.H. Division of Emergency Preparedness & Operational Support 22pp 15739-314 24% Fichs 50-244,82/10/07/8210190580
- --8210190447 Responds to NRC 811215 itr re violations noted in IE Insp Rept 50-244/81-22 Corrective actions revision of Emergency Plan 8C-1 completed prior to startup after 1982 refueling shutdown MAIER, J E Rochester Oas & Electric Corp 82/10/07 NAYNES, R C Region 1, Office of Director 1p 15737 334 24X Fiche 50-244,82/10/07.8210190580
- 8210180149 Forwards Amend 55 to License DPR-18. safety evaluation & notice of issuance & availability Amend incorporates new License Condition 2 C(10) to confirm that next steam generator insp will be performed during refueing outage CRUTCHFIELD.D Operating Reactors Branch 5 82/10/08 MAIER, J & Rochester Oas & Electric Corp. 2pp 15719 105 24X Fichs 50-244, 82/10/08, 82:0180149
- --8210180153 Amend 55 to License DPR-18, incorporating new License Condition 2 C(10) to confirm that next steam generator insprinvolving eddy current & visual insps & water lancing will be performed during refueling outage CRUTCHFIELD, D Derating Reactors Branch 5 82/10/08 2pp 15719 107 24X Fiche 50-244,82/10/08,0210180149
- --8210180158 Safety evaluation supporting Amend 55 to License DPR-18 • Office of Nuclear Reactor Regulation, Director 82/10/08 3pp 15719 109 24X Fichs 50-244.82/10/08.8210180149

- -8210180161 Notice of Issuance & availability of Amend 55 to License PRF-18 CRUICHFIELD. D Operating Reactors Branch 5 82/10/08 2pp 15719 112 24% Fiche 50-244,82/10/08,8210180149
- 8210220344 Act receipt of 820915 & 1005 (trs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-14
 STARDSTECKI.R Division of Project & Resident Programs 82/10/13
 HAIER.J E Rochester Cas & Electric Corp 1p 15777 355 24X
 Fiche 50-244, 82/10/13.8210220344
- --8210220352 Responds to NRC B20Bi6 ltr reviolations noted in IE Insp Rept 50-244/B2-14 Corrective actions all four 480-volt safeguard buses tested & dreft test procedure issued to offsite engineering dept for review MAIER. J E. Rochester Gas I. Electric Corp. 82/09/15 BRUNNER. E. J Region 1. Office of Director 2pp. 15777 356 24X Fiche 50-244,82/10/13.8210220344
- --8210220360 Responds to NRC 820816 ltr re violations noted in IE insp Rept 50-244/82-14 Corrective actions all four 480-volt safeguards buses tested & draft test procedure issued to off-site engineering dept for review MATER.J E Rochester Gas & Electric Corp 82/10/05 DRUNNER, E J Region I. Office of Director 2pp 13777 358 24X Fiche 50-244, 82/10/13.8210220344
- 8208190238 IE Suffetin 82-03, "Stress Corrosion Cracking in Thick-Waff, Large-Diameter, Stainless Steef, Rectrculation Sys Piping at BWR Plants" Svc isst encl
 DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 248 Fiche 50-000, 82/10/14 8208190238
- 8210290171 Forwards IE Insp Rept 50-244/82-18 on 820901-0930 No noncompliance noted STAROSTECKI.R Division of Project & Resident Programs 62/10/14 MAIER.JE Rochester Ges & Electric Corp 2pp 15853 276 24X Fiche 50-244.62/10/14.8210270171
- --8210290173 IE Insp Rept 50-244/82-18 on 820901-0930 No noncompliance noted Hajor areas inspected plant operations, surveillance testing. LERs, licensed 'nonlicensed employee training programs & followup or THE lessons learned implementation ZIMMERMAN, R.P. BAUNACK, W.H. KISIER, H.B. Division of Project & Resident Frograms 82/10/13 11pp 15853 298 24X Fiche 50-244, 82/10/14, 821029017E
- 8210270212 Act receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-65 STAROSTECKIR Division of Project & Resident Programs 82/10/25 MAIER, J E Rochester Oas & Electric Corp 1p 15853 279 24X Fiche 50-244, 82/10/25, 8210290212
- --8210290217 Responds to MRC 820914 ltr re violations noted in IE Insp Rept 50-244/82-15 Corrective actions situation reviewed 5 determined to be isolated case Further action unnecessary MAIER. J E Rochester Gas & Electric Corp 82/10/15 BRUNNER.E J Region 1. Office of Director 2pp 15853 280 24X Fiche 50-244/82/10/25.8210290212

- 8210190703 LER 82-022/017 on 821001 one tube of A steam generator [n]+1 found w/crevice intergranujar attack indication above piugging limit B steam generator iniet had 28 tubes above plugging limit b 2 w/stress corrosson Rept follows SKOW B A Rochester Gas & Electric Corp 82/10/04 HAYNES, R C Region 1, Office of Director [p 15736 154 24X Fiche 50-244, 82/10/04,8210190703
- 8210250334 Forwards LER 82-022/01T-0
 MAIER.J E Rochester Oas & Electric Corp 82/10/15 NAYNEG.R C
 Region 1, Office of Director ip 15790 001 24X
 Fiche 50-244, 82/10/15, 8210250334
- --82i0250343 LER 82-022/0iT-0 on 82i001.eddy current exam of steam generator A iniet indicated one tube w/crevice intergranular attack indication above plugging criteria & 32 tubes on steam generator 8 w/indications All 33 tubes plugged BDDINE.J C Rochester Gas & Electric Corp 82/i0/15 Region I Office of Director 2pp 65790 002 24X Fiche 50-244.82/10/15.8210250314
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8210040120 Discusses util compliance w/SEP Topic VIII-3 B. "DC Power Sys Dus Voitage Monitoring & Annunciation "Sufficient monitoring equipment provided in control room or locally to alert operators of dc sys trouble No mode needed COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 82/09/23 CRUTCHFIELD. D Operating Reactors Branch 5 3pp 153G1 204 24x Fiche 50-245, 82/09/23, 82/0040120
- 8210210192 Forwards IE Insp Repts 50-245/82-17 & 50-334/82-19 on 820808-0925 No nuncompliance noted STAROSIECKI, R Division of Project & Resident Programs 82/10/0/COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 15766 041 24X Fiche 50-245,82/10/07,8210210102
- --6210210176 IE Insp Repts 50-245/62-17 & 50-336/62-19 on 620001-0725 & noncompliance noted Major areas inspected plant & refueling operations, equipment alignments & readiness, radiation protection & physical security SKEDLOSKY.J T. LIPINSKI.D R. ELABSER.T C. Division of Project & Resident Programs 82/10/05 (Spp. 15766-043 24% Fiche 50-245,62/10/07,82/0210182
- P Operating license stage documents & correspondence
- 6210010312 Requests that processing of 820812 license amend application be postponed Revised application changing radiological efficient Tech Specs will be docketed on or about 621i15 for both facilities

 CDURGIL.W O Connecticut Yankee Atomic Power Co COUNSIL.W Q

 Northeast Nuclear Energy Co (subs of Northeast Utilities)

 CDUNSIL.W O Northeast Utilities 82/09/22 CLARK.R A Operating Reactors Branch 3 CRUCHFIELD. Deprating Reactors Branch 5

 3pp 15574 047 24X Fiche 50-000.82/09/22.82(0010312
- 821005011B Forwards summary of differences for SEP topics & description of intended actions Schedule provided for topics requiring add1 info Topics will be addressed in detail in topics specific correspondence COUNBIL. W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL. W O Northeast Utilities 82/09/22. CRUICHFIELD. D Operating Reactors Branch 5 48pp 15404 182 Jac Fiche 50-245,82/09/22.8210050118
- B210010320 Summary of 820915 meeting w/util in Bethesda.MD rs post-LQLA combustible gas control evaluation fuel/clad gap lodina release vs water radiolysis rates Calculational methodology presented in util 820805 submittal acceptable SHEA.JJ Operating Reactors Branch 5 82/09/23 Operating Reactors Branch 5 6pp 15874 040 24% Fiche 50-245,82/09/23.8210010320
- 82i0030i77 Comments on NRC evaluation of SEP Topic VIII-2, "Emerganty Unsite Power Sys" Protective trips of gas turbine interlacks should be bypassed under accident conditions unless bypassing trip would result in machine destruction COUNBIL. W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL. W O Northeast Utilities 82/09/27 CRUICHFIELD. D Operating Reactors Branch 5 4pp 15603 350 24x Fichs 30-245,82/09/27,8210050177
- 8210040233 Informs that SEP Topic V-6, "Reactor Vessel Integrity." meets current criteria Evaluation will be basic input to integrated safety essessment for facility. SHEALJ Operating Reactors Branch 5 82/09/29 COUNSIL. W O Northeast Outlear Energy Co (subs of Northeast Utilities) 259 15581 360 24X Ficbs, 50-245, 82/09/29, 8210040233.

- 8210040273 Informs that licensee response to Item (a) of NRC 820628 ltr re SEF Topic III-5 B. 'Pipe Break Outside Containment," acceptable NRC draft evaluation factually correct & considered final NRC evaluation of topic SHEA. J. Operating Reactors Branch 5 82/09/27 COUNSIL. W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 15587 135 24X Fishe 50-245.82/09/29.8210040293
- 8210060048 Comments on NRC evaluation of SEP Topic III-4 B, "Turbine Missiles" Current insp & testing schedules adequate to provide assurance that turbine missiles not safety concern COUNSIL-W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL-W G Northeast Utilities 82/09/29 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 15614 332 24X Fiche 50-245,82/09/29,8210060048
- 8210000094 Responds to open items identified in 820630 safety evaluations for 6EP Topics III-6. "Seismic Design Considerations" & III-11. "Component Integrity " Corrections & status of IE Bulletin 79-14 program made encl COUNSIL.N G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.N G Northeast Utilities 82/09/29 (RUICHFIELD.D Operating Reactors Branch 5 9pp 15615 013 24X Fiche 50-245,82/09/29,8210060094
- 82;0290405 Responds to request for estimate of amount of indine released to coolant following LDCA Total care inventory of indine.both stable & radioactive isotopes.approx 10 kg. w/variation depending on fuel burnup HULMAN.L G Accident Evaluation Branch 82/09/29 CRUTCHFIELD.D Operating Reactors Branch 3 3pp 15863 307 24X Fiche 50-245.82/09/29.8210290405
- F2101503B2 Advises that gas turbine generator bldg can adequately resist design basis tormado loadings.per SEP Topic III-2 rewind & tormado loadings Fechnical evaluation rept & final SER encl SHEA.J Operating Reactors Branch 5 B2/09/30 CDUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 9pp 15710 244 24X Fiche 50-245.82/09/30.8210150382
- --8206230020 'Wind & Tornado Loadings." technical evaluation rept BARRETT.D J., AGARNAL.R Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C527-403 82/06/21 PERSINKO.D IRC - No Detailed Affiliation Given 120pp 15710 294 24X Fiche 50-245,82/09/30.8210150382
- 8210130331 Discusses revision of administrative procedures to incorporate revised working hour guidelines & provisions for authorizing deviations per 820208 & 0615 requests, TMI

 Ifem I A 1 3. "Shift Manning" & Generic Ltr 82-12

 COUNSIL W 6. CAONETTA J P. Northeast Nuclear Enorgy Co. (subs. of Northeast Utilities). COUNSIL W 9. Connecticut Yanies Atomic Power Co. 82/10/01. EISEMUT.D 6. Division of Licensing. 3pp. 15679-127. 24X Fiche 50-000.82/10/01.8210130331
- 5210130073 Forwards request for addl info (e containment purge & vent operability (B-24) necessary to complete review CRUTCHFICED.D Operating Reactors Branch 5 82/10/05 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 15673 115 24X Fiche 50-245,82/10/05.8210130073
- B210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820909 lit Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface KACICH.R M SEP Owners Oroup 82/10/07 EISENHUIT.D @ Division of Licensing 7pp 15682 179 24X Fichs 50-000.82/10/07.8210130326
- 8210220486 Forwards final evaluation of SEP Topic VI-4, "Containment (solation Stys" Daviations from review guidelines listed Implementation of administrative controls on values recommended SHEA.J Operating Reactors Branch 5 B2/10/08 COUNSIL:W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 34pp 15779 036 24X Fiche 50-245,82/10/08.8210220486
- 8210270200 Forwards summary of NRC positions on 26 unresolved safety issues, consisting of excerpts from NRC publications & repts to Congress & assessment of generic applicability Adequate basis exists to warrent continued plant operation COUNSIL. H O . OPEKA. J F Connecticut Vankee Atomic Power Co (COUNSIL. H O Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/13 CRUICHFIELD. D Operating Reactors Branch 5 4Gpp 15824 334 24% Fiche 50-000.82/10/13.8210270200
- 8210240194 Discusses util review of rod control carcuitry No credible single failure could cause inadvertent movement of more than one control rod at time info should resolve concerns re SEP Topic IV-2, "React(vity Control Bys "
 COUNSIL.H O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.H O Northeast Utilities 82/10/14
 CRUICHFIELD.D Operating Reactors Branch 5 2pp 15797 019 24X Fachs 50-245, 82/10/14 8210260194

- 8210260414 Provides addl info re 2-phase degraded grid undervoltage protection scheme for Class IE power sys.in response to 820623 request Mods usil be deferred until 1984 refueling outage Next rept will be submitted during Jul 1983 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O . OPERAL F Northeast Utilities 82/10/14 CRUTCHFIELD D Operating Reactors Branch 5 6pp 19806 144 24X Fiche 50-245,82/10/14.8210260414
- 8210230124 Forwards draft integrated plant safety assessment rept Draft provided for SEP Subcommittee 821026-27 moeting CRUTCHF[ELD, D. Operating Reactors Branch 5 82/10/15 COUNSIL.W O Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 79pp 15787 164 24X Fiche 50-245,82/10/15.8210250124
- 8210260517 Forwards proprietary "STR Bundle Submittal.Millstone-1 Segmented Test Rod Bundle.Suppl 6." as app to 821015 Reload B license amend submittal Rept withheld (ref lOCFR2 790) COUNSIL.W 0. OPENALJF Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 0 Northeast Utilities 82/10/15 CRUICHFIELD, D Operating Reactors Branch 5 3pp 15805 228 24x Fische 50-245,82/10/15,8210240519
- 8210260459 Forwards corrections to draft evaluation of SEP Topic III-1. "Classification of Structures, Components & Sys." in response to 820505 request COUNSIL. W G. BISHOP, R W Northeast Nucleer Energy Co (subs of Northeast Utilities) COUNSIL, W G. Northeast Utilities 82/10/19 CRUTCHFIELD, D Operating Reactors Branch 5 13pp 15806 210 24X Fichs 50-245, 82/10/19, 8210260459
- 8210250217 Advises that SEP Topic VI-6 "Containment Leak Testing," considered complete to conduct integrated assessment Multi-plant Item A-4 review will be conducted independent of SEP SHEA. J Operating Reactors Branch 5 82/10/22 COUNCIL, H G Northeast Nuclear Energy Co (subs of Northeast Utilities) ip 15768 344 24% Fiche 50-245, 82/10/22, 8210830219
- Q Inspection reports, IE Bulletins & correspondence
- 8210060233 Advises that masonry wall mods will be complete by Nov 1982 & const will be completed by June 1983, per IE Bulletin 80-11
 COUNSIL.W C Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W C Northeast Utilities #22/09/24
 HAYNESR C Region 1. Office of Director 2pp 15620 009 24X
 Fichs 50-245, 82/09/24, 8210060233
- 8210150699 Forwards request for add1 info to complete review of 801104 response to IE Bulletin 80-11. "Masonry Hall Design "
 Response expected within 60 days of ltr receipt CLARK,R A Operating Reactors Branch 3 82/09/28 COUNBIL, H 0 Connecticut Yankee Atomic Power Co CDUNSIL. W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 13pp 15716 100 24X Fichs 50-000.82/09/28.8210150699
- 821006004B Comments on NRC evaluation of SEP Topic 111-4 B, "Turbing Missiles" Current insp & testing schedules adequate to provide assurance that turbing missiles not safety concern CQUNBIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) CQUNBIL.W O Northeast Utilities 82/09/29 CRUICHFIELD, D Operating Reactors Branch 5 2pp 15614 332 24X Fiche 50-245,82/09/29.8210040048
- 8210070352 Ack receipt of 820714 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/82-10 & 50-336/82-14 MARTIN.T Division of Engineering & Technical Programs 82/10/05 COUNSILW O Northeast Nuclear Energy Co (subs of Northeast Utilities) ip 13634 051 24X Fiche 50-245,82/10/05,8210070352
- --8210070355 Responds to NRC 820813 itr reviolations noted in IL Insp. Repts 50-245/82-10 & 50-336/82-14 Corrective actions controlled documents updated & Unit 1 control room drawing deficiencies corrected COUNSIL.H Q Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.H Q Northeast Utilities 82/09/14 MARTIN.T T Division of Engineering & Technical Programs 3pp 13540 032 24% Fiche, 50-245, 82/10/05,8210070352
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dielooged I-125 Implant Seeds " Svc list encl COBB.L 1 Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co. of New York 6Aps 15761 250 24/
- 8210210182 Forwards IE Insp Repts 50-245/82-17 & 50-336/82-19 on 820808-0925 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 82/10/07 COUNSIL-N Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 15766 041. 24X Fiche 50-245,82/10/07,8210210182

- --8210210196 IE Insp Repts 50-245/82-17 & \$0-336/82-19 on 820808-0925 No noncompliance noted Hajor areas inspected plant & refueling operations, equipment alignments & readiness, radiation protection & physical security SHEDLOSXY, J T , LIPINSKI, D R , ELASSER, T C Division of Project & Resident Programs 82/10/05 | Topp 15766-043 24X Fichs 50-245,82/10/07,8210210182
- 8208190238 IE Bulietin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys-Piping at 8WR Plants " Svc list encl DEYQUND.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000, 82/10/14, 8208190238
- 8210220479 Nots fication of 821027 meeting w/util in Bethesda.HD to discuss spray sparger crack indications detected during visual insplusing underwater television squipment SHEA.J J Operating Reactors Branch 5 82/10/21 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 15779 075 24X Fiche 50-245.82/10/21.8210220479
- S Reportable occurrences, LERs & related correspondence
- B21001000B Resgands to FOIA request for 19 categories of documents renuclear reactor events & safety groblems Forwards documents issted in App A FELTON.J M Division of Rules and Records B2/06/28 UDECL.R A Critical Mass Energy Project 15pp 15727-005 24X Fiche 50-000.82/06/28.8210010008
- --8103190719 Operating Reactor Event Memo BL-29 ne cracking in several ASME Code Class (& Class 2 piping sys Affected sys are isolation condenser shutdown cooling cleanup & LPC1 subsystem Defective sections are under repair EISEMHUT.D O Division of Licensing 81/03/05 VOLLMER, & Division of Eisensing 81/03/05 VOLLMER, & Fiche 50-000,82/06/28,8210010008
- 8210080015 Addi response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents 1/354d in App A Documents in App B completely withheld (ref FDIA Exemption 5) FELTON.J M Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000.82/07/12.8210080015
- --8206070106 Operating Reactor Event Memo 82-01 re 810910 reactor scram w/water hammer event Study of Unresolved Safety Issue A-1 shows no other water hammer events in BMR isolation condensers
 EISENHUT D & Division of Licensing 82/05/25 VOLLHER R H Division of Engineering MATTSON R J Division of Systems Integration (post 811005) HANAUER S H Division of Safety Technology 7pp 15665 150 24X Fiche 50-000.82/07/12.
- 8210070360 LER 82-018/OFP on 820925, while performing remate visual image of core apray spargers, crack indication identified on one core apray sparger to junction box welds, Addl info will be provided in 14-day followop rept MROCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA,E J Northeast Director 19 15634 059 247 Fiche 50-245, 82/09/27, 8210070360
- 8210070304 LER 82-019/01P on 820928; three safety relief valves failed to open at required setpoint pressure during bench test Cause under investigation Three remaining safety relief valves will be removed & bench tested.

 MROCZKA:E J Martheast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA:E J Northeast Utilities 82/09/29
 HAYNEB:R C Region 1: Office of Director 1p 15634 245 24X Fiche 50-245, 82/09/29, 8210070304
- 8210070250 Telecopy message of LER 82-020/01P on 820930.1TT Orinnell snubbers failed loctup & bleed rate requirements Snubbers with be made operable or replaced prior to reactor startup MROCZKA.E J Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA.E J Northeast Utilities 82/10/01 MROCZKA.E J Northeast Utilities 82/10/01 MRYMES.R C Region 1. Office of Director 19 15634 287 24X Ficher 50-245, 82/10/01,8210070250
- 8210210425 Forwards LER 62-018/01T-0 Datailed event analysis encl MRGCZKA: E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MRGCZKA: E.J. Northeast Utilities 82/10/12 HAYNES: R.C. Region in Offica of Director. 2pp | 5763 087, 24X Fiche 50-245, 82/10/12, 8210210425

- --B210210430 LER 82-018/01T-0 on 820925, crack indication identified on one core spray sparger to junction but weld Caused by high weld residual stresses Stress correction cracking may have initiated indication Sparger hold clamp will be installed THULL.T S Northeast Utilities 82/10/12 Republic 10/12/8910210425 Director Ip 15763 069 24X Fiche 50-245,82/10/12/89310210425
- 8210220103 Forwards LER 82-021/03L-0 Detailed event analysis encl MRQCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MRQCZKA.E J Northeast Utilities 82/10/13 HAYNES.R C Region 1, Office of Director 2pp 15770 169 .4k Fiche 50-245, 82/10/13, 8210220103
- --8210220108 LER 82-021/03L-0 on 820913, diesel generator tripped durioperational readiness demonstration test Caused by broken ring type wire lug at current transformer secondary connection due to flexing during installation THULL.TS Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/13 Region 1. Office of Director (p 15778 171 24X Fiche 50-245,82/10/13,8210220103
- 8210220112 Forwards LER 82-020/01T-0 Detailed event analysis encl MRGCZKA,E J . MRGCZKA,E J . Northeast Nuclear Energy Co. Isub. of Northeast Utsitites . 82/10/15 . HAYNES.R C . Region 1, fiffice of Director . Opp. 15778
- --B210220116 LER B2-020/01T-0 on B20930, four ITT Orinnell shubbers fails to fall within recommended range Fuither analysis showed that only one snubber failed design acceptance range (assed by oil leakage through cracked reservoir THULL, T & Northwast Nuclear Energy Co (subs of Northwast Utilities) B2/10/15 Region 1, Office of Director 1p 15778 167 24% Fische 50-245,82/10/15,8210220112
- 6210220195 Forwards LER 82-019/01T-O Detailed event analysis enti-MRGCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MRGCZKA,E J Northeast Utilities 82/10/15 HAYNES,R C Region 1, Office of Director 2pp 15//7 2/0 .4 Fiche 50-245, 82/10/15,8210220195
- --0210220201 LER 82-019/01T-0 on 820920, five safety relief valves failing to open at required setpoint Cause being investigated by UP. Two valves will be replaced or rebuilt Other three will be reworked & retested.

 THULL, T S Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/15 Region 1. Office of Director 19 15777 272 24X Fiche 50-245, 82/10/15,8210220195
- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
- F Becurity, medical, emergency & fire protection plans
- 8210060145 Forwards "Testing & Repair of Siren Portion of Alers I. Notification Sys for Indian Point Nuclear Power Generaling Plant." per discussion at 820708 status meeting KECLY.J J Power Authority of the State of New York 182/97/1. DAYIDDF, D New York State of 1p 15614 275 24x Fiche 50-247, 82/07/15,8210060145
- -B210060148 "Testing & Repair of Siren Portion of Alert & Notificatings for Indian Point Nuclear Power Generaling Plans "

 Power Authority of the State of New York 82/07/14 Upp 15614 296 24% Fiche 50-247,82/07/15,8210060145
- 8210280148 Releases public version of revised emergency plan implementing procedures FELTON, JM Division of Rules and Records 82/10/(2 Bocument Management Branch ip 15862 271 24X Fiche 50-00-J. 62/16/12
- --8210280154 Forwards public version of revisions to Emergency Plan
 Implementing Procedures IP-1020 re airborne radioiodine
 determination & IP-1046 re util personnel responsibilities
 during Unit 3 emergencies
 0/TOOLE.J D Consolidated Edison Co of New York 82/10/01
 HAYNES.R C Region i. Office of Director 3pp 158/2 2/J 24;
 Fiche 50-003,62/10/12.8210280148
- --82i0280159 Public version of revisions to Emergency Plan Implementa-Procedures IP-1020 re airborne radiocodine determination & IP-1046 re util personnel responsibilities during Unit 3 emergencies < Consolidated Edison Co of New York 82/09/01 | Japp 15862 275 | 24X Fiche 50-003,82/10/12,8210280148

- B2[0200019 Advises that serious deficiencies in emergency preparednoss will not be corrected since State of NY & FEMA not addressing concerns of local officials by involvement in current changes HOLT. J Public Interest Research Group, New York POSNER.P Parents Concerned About Indian Point FLEISHER.Z S West Branch Conservation Association 82/10/15 PALLADINO,N J , AHEARNE.J F , GILINSKY V Commissioners Spp 15795 083 24% Fische 50-247.82/10/19,8210200019
- Adjudicatory correspondence
- ELOAZ3078B Ack receipt of 800416 memo w/insp repts verifying intelim actions required of facilities in 8002[1] confirmatory orders Requests verification that Item F 2 in orders is met Item E 5 in W Gammill 8003[7] memo should be F 5 NGVAK. T M Assistant Director for Operating Reactors 80/06/13 BRYAN, S E Division of Reactor Operations Inspections ip 02765 285 24X Fiche 50-247,80/06/03.800623078B
- P2.10050235 Declines invitation to appear before Subcommittee on Energy Conservation & Power Subcommittee investigation is intrusion into engoing regulatory proceeding & threatens independence of Commission MORGAN, C Morgan Associates MORGAN, C Power Authority of the State of Neu York 02/09/30 OTTINGER, R L House of Rep , Energy & Commerce 10pp 15619 360 24X Fiche 50-247, 82/09/30, 9210060235
- GILO040108 Order CLI-82-28, requesting ASL8 reconstituted by CLI-82-24 to estimate when recommendations called for by CLI-81-29 can be provided CHILK, S. J. Office of the Secretary of the Commission 82/10/01 Atomic Safety and Licensing Board Panel ip 15580 350 24X Fiche 50-247, 82/10/01, 8210040108
- 5210050254 Memorandum & order restating contentions & establishing procedures based on Commission guidance GLEASCH.JP. PARTS.O.H. SHON.FJ. Atomic Safety and Licensing Board Panel 82/10/01 42pp 15609 211 24X Fiche 50-247. 622/10/01.8210050254
- R210130335 Motion for ASLB to direct NRC to reschedule B21013 meeting w'utils ? Sandia in Albuquerque.NM to either New York,NY or Washington.DC Intervenor mable to attend meeting in NM WEISS.E.R. Union of Concerned Scientists WEISS.E.R. Public Interest Research Group, New York 82/10/07 Atomic Safety and Licensing Board Panel 3pp 15682 050 24% Fiche 50-247,82/10/07,8210130335
- --0210130337 Motion for Commission to direct that all future meetings on issues be held in NY or Washington, DC & that intervenors be given notice concurrently w/other parties WEISS, ER Union of Concerned Scientists WEISS, ER Public Interest Research Group, New York 82/10/07 Commissioners 2pp 15682 053 24X fiche 50-247.82/10/07.8210130335
- G210180203 Reply to ASLB 821001 memorandum & order Plant should be totally reinspected w/appropriate tests of piping, electrical 3 control sys conducted List of parties should be shortened to active participants Certificate of Svc encl FLEISHER: X S West Branch Conservation Association 82/10/11 4pp 15718 124 24X Fiche 50-247.82/10/11,8210180203
- 3210130072 Order denying UCS/NY PIRG B21007 motion to direct NRC to reschedule B21013 meeting in Albuquerque,NM to NY or Washington,DC Only Commission has jurisdiction over NRC partermance of administrative responsibilities PARIS. D H. SHON,F J. GLEASON, J P. Atomic Bafety and Licensing Board Panet B2/10/12 Union of Concerned Scientists 3pp 15701 194 24X Fiche 50-247,82/10/12,8210150072
- B2[0]50141 Grder scheduling B2]103-04 prohearing conference in White Plains,NY re oral argument on responses to ASLB B2]001 memorandum 2 order restating contentions GLEASON, JP Atomic Safety and Licensing Board Panel B2/10/12 2pp 15678 306 24% Fiche 50-247,82/10/12,82]0150141
- 8210180138 Motion in response to ASLB 821001 order requesting clarification & importance of term "discussion" & extension of time to determine position re issue of consolidation Certificate of Svc encl KAPLAN.C New York.NY 82/10/13 Atomic Bafety and Licensing Board Panel 7pp 15719 123 24X Fiche 50-247.82/10/13.8210180138
- 8210200069 Felegraphic order granting licensee request for extension of time to file responses to 821001 order All party responses due 821019 GLEASON, J.P. Atomic Safety and Licensing Board Panel 82/10/14 Pouer Authority of the State of New York 1p 15757 280 24X Fiche 50-247, 82/10/14, 8210200069

- 8210200019 Advises that serious deficiencies in emergency preparedness until not be corrected since State of NY & FEMA not addressing concerns of local officials by involvement in current changes HOLT, J. Public Interest Research Group, New York POSNER, P. Parents Concerned About Indian Point FLEISHER, Z. S. West Branch Conservation Association 82/10/15 PALLADINO, N. J. AHEARNE, J. F. OILINSKY, V. Commissioners 5pp 15755-083 24X Fiche 50-247, B2/10/15, 8210200019
- 8210220389 Submittal of comments on ASLB 821001 memorandum & order & motion for ASLB to issue reformulated contentions on Commission Questions 3 & 4 by 821115 & to restore Contention 6 2 Certificate of Svc enci TOSCANI.K Parents Concerned About Indian Point 82/10/15 Atomic Safety and Licensing Board Panel 2pp 15777 307 24X Fiche 50-247,82/10/15,8210220389
- 6210210390 Requests destruction of West Branch Conservation Assor 821011 reply to 821001 memorandum & order & substitution of enci version
 FLEISHER, Z B West Branch Conservation Association 62/10/18
 NRC No Detailed Affiliation Given 1p 15764 099 24X
 Fiche 90-247.82/10/18.8210210390
- --8210210397 Response to 821001 memorandum & order Certificate of Svc encl FLEISHER.Z B West Branch Conservation Association 82/10/13 4pp 15764 100 24X Fiche 50-247.82/10/18.8210210390
- 8210200059 Response to ASLB 821001 order ASLB should narrow language or ASLB Question 1 1 % adopt proposed schedule for continuation of proceeding Certificate of Svc enci MOJRE, J, MCOURREN, H J Hearing Branch 1 62/10/19 9pp 15757 290 24X Fiche 50-247,82/10/19,8210200059
- 8210220375 Request for mod of ABLB 821001 order to permit Rock1 and County to continue presentation of witnesses re Commission Questions 3 & 4 prior to taking evidence on Questions 1,2,5,6,7 THORSEN.E D Rockland County, NY 82/10/19 Atomic Safety and Licensing Board Panel 2pp 15779 187 24X Fiche 50-247,82/10/19.8210220375
- 8210220410 Joint response of intervenors to ASLB 821001 order Meaning of "discussion" of probability should be clarified & ASLB should immediately reformulate contentions on Guestions 3 & 4 Certificate of Svc enci HEIBS.E R. Union of Concerned Scientists WEISS.E R. Harmon & Weiss 82/10/19 Atomic Bafety and Licensing Board Panel 12pp 15778 313 24X Fiche 50-247,82/10/19.8210220410
- 82102500B1 Proposed hearing schedule Certificate of Svc encl BRANDENBURG. B Consolidated Edison Co of New York HORGAN, C Power Authority of the State of New York MORGAN, C Morgan Associates 82/10/19 9pp 15787 049 24X Fiche 50-247.82/10/19, 82102500B1
- 8210250216 Response to ASLB 821001 order reformulating contentions Opposes admission of new Contention 1 1.Contentions 2-1(a)-(d).2 2(a) & 2 2(b) & ASLB Question 2 2 1 Notice of appearance & Certificate of Svc encl MOROAN. C Power Authority of the State of New York MOROAN. C Morgan Associates 82/10/19 Atomic Safety and Licensing Board Panel 35pp 15789 166 24X Fiche 50-247.82/10/19,8210250216
- 8210250245 Notice of appearance in proceeding BAUM, B L. Fower Authority of the State of New York DAUM, B L Morgan Associates 82/10/19 ip [5791 152 24X Fiche 50-247.82/10/19,8210250265
- 8210250287 Motion for order reversing ASLB 821001 memorandum & order re taking of testimony on Questions 3 & 4 & establishing schedule for presentation of testimony upon expiration of 120-day clock Certificate of Svc encl VETERE, L A Westchester County, NY 82/10/19 Atomic Safety and Licensing Board Panel 7pp 15791 165 24X Fiche 50-247, 82/10/19, 8210250287
- 8210230324 Memorandum re ASLB 921001 order reformulating contentions
 Objects to new Contention 1 1.Bases 1a & 1b.Contentions
 2 1(a),2 1(b),2 1(c),2 1(d),2 2(a) & 2 2(b) Certificate of
 Svc enc1
 DRANDENBURO. B Commonwealth Edison Co 82/10/19 Atomic Safety
 and Licensing Board Panel 49ap 15790 243 24X
 Fiche 30-247,82/10/19,8210250324
- 8210250099 Motion for leave to file memorendum in response to ASLD B21001 order i day late Methanical difficulties encountered w/word processing equipment Certificate of Eve encl BRANDENBURG. B Consolidated Edison Co of New York 82/80/20 Commissioners 6pp 15787 062 24X Fiche 50-247.82/10/20. 8210230099.

- 6210280242 Requests Commission issue order directing all meetings between NRC 2 licenses be held in Washington. DC or NY, that intervenors receive notice of meetings concurrently w/utils 2 that intervenors be provided w/minutes of 821013 meeting WEISS.E R Harmon & Neiss WEISS.E R Union of Concernd Scientists 82/10/25 PALLADINO, N J . AMERNG, J . 01LINGMY, V Commissioners 2pp 15937 058 24X Fiche 50-247.82/10/25, 821038042
- 8210260230 Advises that NRC does not intend to respond to intervenor motions filed in response to ASLB 821001 order until after 821103-04 prehearing conference MODRE.J E Hearing Branch I 92/10/27 OLEASON.J P , SHON.F J . PARIS.D H Atomic Safety and Licensing Board Panel 1p 15837 082 24X Fishe 50-247.82/10/27,8210260230
- 8210280353 Response opposing UCS/NY PIRG B21012 motion to direct NRC to reschedule all future meetings on hearing issues in NY or Washington DC NRC should be permitted flexibility to determine most appropriate location W/Certificate of Svc MCGURREN. H J Hearing Branch 1 92/10/27 Commissioners 9pp 15839 048 24% Fiche 50~247, 82/10/27, 8210280353
- 8210290271 Advises that literaces plan to address all matters raised in responses/motions re ASLB 821001 memorandum & order at 821103-04 prehearing conference BRANDENBURG, B. Consolidated Edison Co. of New York MOROAN, C. Power Authority of the State of New York MORGAN, C. Morgan Associates 82/10/27 GLEASON, J. P., SHON, F. J., PARIS, D. H. Atomic Safety and Licensing Board Panel 2pp. 15853-012 P4X Fiche 50-247, 82/10/27, 8210290271

H General correspondence

- 8210250272 Requests substitution of SL Baum u/TR Frey on official syclist for proceeding Related correspondence COLARVLLIP F Power Authority of the State of New York 82/10/19 STUCKY.8 W Docketing & Services Branch 19 15791 190 24X Fiche 50-247,82/10/19, 82/10250272
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 8207180077 Forwards comments on PRA study dealing w/seismic hazard Validity of conclusions rest on quality of primary data bases & assumptions in both studies Repts are not valid risk assessments due to data base limitations POMEROY.P W Rondout Associates POMEROY.P W ACRE Advisory Committee on Reactor Safeguards 82/08/24 DKRENT, D ACRE Advisory Committee on Reactor Safeguards 7pp 15876 001 24X Fiche 50-003 82/08/24.8207180077

- 8007310117 Forwards request for addlinfo required to complete tranks, Research Ctr evaluation of adequacy of steam generator & reactor coolant pump supports Request should be sent to licensee HICHMAN.K R Operating Reactors Assessment Branch B0/07/14 VARGA, S.A. Operating Reactors Branch I 7pp 03056 268 24% Fiche 50-247,80/07/14,8007310117
- 8008050220 Requests LB Marsh be permitted to continue reviewing overpressure protection sys & associated Tech Specs NOVAK.T Assistant Director for Operating Reactors ERNST.M L Assistant Director for Technology Review 03078 175 24X Fiche 50-247.80/07/30.8008050220
- B008130744 Summary of 800617 meeting w/utils in Dethesda.MD recontainment structural response to core mait accident sequences
 MEYER.J F Power Systems Branch 80/07/31 Power Systems Brance
 3pp 03266 243 24% Fiche 50-247.80/07/31.8008130744
- B009100104 Approves Tech Specs revision proposal re insplof hydraulit fluid of shubbers supplied by common reservoir & ercessive fluid loss due to external tubing leakage

 DARRETTLL H Operating Reactors Assessment Branch 60/06/05 VARCALS A Operating Reactors Branch (Pre 600420) 1p

 03546 074 24x Fiche 50-247,60/08/05,6009100104
- 6009210627 Forwards request for addlinfo re spent fuel pool retarting Info needed to complete review of util Application for literase amend RUBENSTEINLS Assistant Director for Core & Containment (water) 80/08/08 NOVAK.T M Assistant Director for Operating Reacture 3pp 03382 306 24% Fiche 30 247.80/08/08.8008210627
- 6007100100 Forwards recommendations on staff task action plan to be sent to licensees for review 8 response
 BARRETT.L H Operating Reactors Assessment Branch (80/06/08/VARCA, S A Operating Reactors Branch (Pre 800428) (Rep
- 6009030334 Forwards Reactor Fuel Section questions re LOPAR fuel an core previously containing HIPAR fuel Questions should be rorusarded to licensee RUBENSTEIN.L S. Assistant Director for Core & Containment Hyelman B0/08/18 NOVAK.T M. Assistant Director for Operating Reactors 3pp. 03462 022 24X Fiche 50-247.80/08/18.8009030734
- 8009080466 Forwards response to 800820 request for status rept to Zion/Indian Point task action plan Responsibilities are in area of severe accident mitigation features & not in interim operational actions portion
 MEYER.J F. Reactor Systems Branch 80/08/25 NOVAK, F. M. Assistant Piche 50-003, 80708/25, 8009080466
 Fiche 50-003, 80708/25, 8009080466

- 2010240644 Forwards safety evaluation re electrical override of manual actuation features for containment ventilation isolation to other ESF sys OLSHRIGERIJA Operating Reactors Assessment Branch 80/10/06 VARQA, S.A. Operating Reactors Branch 1. 3pp. 03661 092 24X Fiche 50-247, 80/10/06, 8010240644
- 8/10270312 Advises that Frankinn Research Ctr was notified to proceed by final evaluation of fracture toughness of stram generator. It reactor coolant pump supports Due to util BOOB2D request for delay, appropriate conservative assumptions will be made OLSHINSKI J A Diperating Reactors Assessment Branch NRC-03-79-j18 BO/10/06 VARGAS A Operating Reactors Branch 1 2pp 03661 208 24x Fichs 50-247.80/10/06.8010270312
- POLITICOBA Requests Instrumentation & Control Sys Branch evaluation of ulil responses to questions ie incore instrumentation tubes at facilities Info will aid branch evaluation mitigation reatures re backfitting or severe mitigation features SPEIS.T P Ryactor Systems Branch 80/10/09 SATTERFIELD.R Instrumentation & Control Systems Branch | p 02227 001 24X Fiche 50-247 80/10/09 8011110084
- E010280098 Forwards NRC questions % util answers re backfitting of severe accident mitigation features Evaluation needed in two uts
 SPEIS.T P Reactor Systems Branch B0/10/17 SCHAUER,F P
 Structural Engineering Branch ip 65767 184 24X
 Fiche 50-247.80/10/17.8010280098
- HQ11200025 Forwards Power Sys Branch evaluation of differences between Indian Point 2 b 3.in response to technical assistance request Requests meeting whiteensee prior to formal response to evaluation CHECH P S Assistant Director for Plant Systems B0/10/21 FOVAN. T Assistant Director for Operating Reactors 21pp 03743 111 24X Fiche 50-247,80/10/21.8011200025
- HOLI 210284 Forwards draft safety evaluation of licensee response to last Action Plan Iten II E 1 2 Automatic initiation logic, instrumentation by associated circuitry & automatic feedwater flow indication channels meet safety-grade requirements SATTERFIELD. A Instrumentation b Control Systems Branch 80/10/22 VARGA. S Operating Reactors Branch 1 8pp 03744 123 24X Fiche 50~247, 80/10/22.8011210284
- 9101050528 Forwards questionnaire to be completed by each near-term UL.

 / each listeneed plant by 801107 Objective is to assess best
 collective judgment re extent of problems recently
 experienced at facility
 URRDAN.E L Office of Inspection / Enforcement, Office of the
 Directol 80/10/28 BRUNNER.E J Region i, Philadelphia, Reactor
 Uperations Nuclear Support Branch LEWIS.R C Region 2. Atlanta,
 Reactor Operations Nuclear Support Branch HEISHMAN.R F Region 3,
 Chicago, Reactor Operations Nuclear Support Branch 2pp 94581 186
 244 Fiche 50-24/.80/10/26.8101050528
- 60:1070227 Requests all operating reactor project managers to conduct telephone survey w/licensees to determine if plants are suscoptible to svc water leaks Results of survey requested by 80:103:

 DLSHAHL H Decrating Reactors Branch i 80/10/29 Operating Reactors Branch i 1p 03715 124 24X Fiche 50-247,80/10/29,
- Bill120679 Forwards response to request for determination of licensing basis for reactor pressure vessel & containment fan cooler sys re FSAR requirements & current NRC criteria Licensee must perform thermal 2 stress analysis of vessel LAINAS.G C Assistant Director for Safety Assessment BO/10/29 EIESNHUT, D Q Division of Licensing App 03719 357 24X Fiche 50-247.BO/10/29.BO/11/20679
- 8011100165 Submits revision of relative concentration for short-term release foilowing an accident Facilities exclusion radius found to be 520 maters resulting in relative concentration equal to 0.00051 sec/cu meter in southwest direction HOUSTON.R W Accident Evaluation Branch 80/10/30 VARGA, 8 A Operating Reactors Dranch 1 ip 65768 021 24X Fiche 50-247,80/10/30,8011100165
- B207050085 F0IA request for eight categories of records re steam generators & steam turbines LONO, D J Winthrop, Bitmeon, Putnam & Roberts 82/07/i3 Office of Administration 3pp 15645 060 24X Fiche 50-247,82/07/i3,8207050085
- 6210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON. J M Division of Rules and Records 82/08/10 LONO, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fische 50-000,62/08/10,6210070007

- 8210010401 Forwards application to amend Licenses DPR-26 & DPR-5, changing Tech Specs re facility organization & Unit 2 Tech Specs 3 6 & 4 4 re containment isolation valves 3 12 & 4 12 in pipe lines Class I. Ii & !ii fees encl O'TOLE. J D Consolidated Edison Co of New York 82/08/31 VAROA. S A Denating Reactors Branch I 3pp 15572 211 24X Fiche 50-003, 82/08/31, 82/10010401
- --8210010409 Application to amend Licenses DPR-26 & DPR-5, revising Tech Spec Figures 3 2 & 6 2-2 re facility organization for Units 1 & 2, respectively 0/TOGLE, J D Consolidated Edison Co of New York 82/08/31 2pp 15572 214 24X Fithe 50-003,82/08/31,8210010401
- --82i0010414 Proposed revisions to Tech Spec Figures 3 2 % 6 2-2.
 refiseting change in organizational structure to include
 position of operations superintendent Safety assessment
 encl
 * Consolidated Edison Co of New York 82/08/31 App
 15572 216 24% Fiche 50-003.82/08/31.82i0010401
- --8210010425 Application to amend License DPR-26, revising Tech Specs 3 6 & 4 4 to establish requirements for action required when containment isolation valves are inoperable & reflect changes to isolation valve provisions 0'TOOLE, J D Consolidated Edison Co of New York 82/08/31 2pp 15572 222 24% Fiche 50-003.82/08/31,8210010401
- --82100i0438 Proposed revisions to Tech Specs 3 6 & 4 4,establishing specific requirements for action during inoperability of containment isolation vaives b reflecting changes & additions to isolation vaive provisions Safety assessment enci * Consolidated Edison Co of New York 82/08/31 20pp 15572 224 24% Fiche 50-003.82/08/31.8210010401
- --B210010443 Application to amend License DPR-26, revising Tecb Spec Sections 3 12 & 4 12 to defficet editorial change safety-related pipe lines & to efficet editorial change O'TOOLE, J D Consolidated Edison Co of New York 82/08/31 2pp 15572 244 24% Fiche 50-003,82/08/31,8210010401
- --8210010449 Proposed revisions to Tech Spec Sections 3 12 & 4 12, reflecting redesigned support sys for safety-related pipe lines & to effect editorial change Safety assessment encl * Consolidated Edison Co of New York 82/08/31 1Spp i5572 246 24X Fiche 50-003 82/08/31 8210010401
- 8210080049 Notification of 820929-30 meeting w/utl1 & Franklin Research Ctr in Buchanan.NY to discuss contractor review of util radiological effluent Tech Specs THOMA.J O Operating Reactors Branch 1 82/09/23 VARGA.S A Operating Reactors Branch 1 2pp 66367 336 24X Fiche 30-247.82/09/23.8210080049
- 8210130602 informs that review of 810731 response to Generic Ltr 81-01, "Qualifications for Insp.Exam & Testing & Audit Personnel," complete Commitments & exceptions to Revision 1 to Reg Quide 1 38 Reg Guide 1 146 acceptable VARGA.S A Operating Reactors Branch 1 82/09/27 0'700LE, J D Consolidated Edison Co of New York 2pp 15672 347 24X Fiche 50-247.82/09/27,8210130602
- 8210130455 Forwards responses to items 1,3,4 & 8 of NRC 820315 request for additinfo re control of heavy loads (NUREO-0612) Info addressing Items 2,5,6 & 7 will be submitted by 830131 O'TDOLE,J D Consolidated Edison Co of New York 83/09/30 VAROA,S A Operating Reactors Branch 1 7pp 15682 019 24X Fiche 50-247,82/09/30,8210130455
- 8210120253 Forwards initial comments on Sandis Natl Labs 820825 preliminary draft ltr rept on review & evaluation of probabilistic safety study, addressing wind, seismic, fire, pressurized thermal shock & fan cooler issues of the study of the state of the state of New York BAYNE, J.P. Power Authority of the State of New York B2/10/06 VARGA, S.A. Operating Reactors Branch 1 62pp 13652 215 24X Ficha 50-247, 82/10/06, 82/01/0253
- 62:0190693 Advises that results of 820920 evc water systest prove that Indian Point probabilistic safety study reflect actual plant configuration Remaining plant improvements in 820305 itr.escept ATMS mod.to be complete by return to sec O'TOOLE.J D Consolidated Edison Co of New York 62/10/08 VAROA,6 A Operating Reactors Branch i 2pp 15798 141 24X Fiche 50-247, 82/10/08, 8210190493
- 8210210032 Forwards request for add1 info to complete review of TMI Item II K 3 25, "Power to Pump Seals " Areas of conformance or deviation from stated position should be identified & info re design & operation of cooling sys provided VAROA.S A Operating Reactors Branch I 82/10/15 0/TOOLE, J D Consolidated Edison Co of New York 3pp 15774 360 24X Fiche 50-247,82/10/15,8210210032

- 8210280242 Requests Commission issue order directing all meetings between NRC & licensee be held in Washington OC or NY, that intervenors receive notice of meetings concurrently w/vutils bethat intervenors be provided w/minutes of 821013 meeting WEISS.E R Harmon & Weiss. WEISS.E R Union of Concerned Scientists 82/10/25 PALLADINO, N J . AMEARNE, J . GLINNSKY V Commissioners 2pp 15837 058 24X Fiche 50-247,82/10/25,8210280242
- 8210280230 Advises that NRC does not intend to respond to intervenor motions filed in response to ABLB 821001 order until after 821103-04 prehearing conference MOORE J E Hearing Branch I 82/10/27 QLEASON J P. SHON, F J. PARISO H Atomic Safety and Licenzing Board Panel ip 13837 082 24X Fiche 50-247,82/10/27.8210280230
- 8210280353 Response opposing UCB/NY PIRG 821012 motion to direct NRC to Plosedous and future meetings on hearing issues in NY or Washington, DC NRC should be permitted flexibility to deternine most appropriate location W/Certificate of Syc MCGURREN, H J Hearing Branch | 82/10/27 Commission; 15837-048 24X Fiche 50-247.82/10/27.82(0280353
- 8210290271 Advises that licensees plan to address all matters raised in responses/motions re ASLB 821001 memorandum & order at 82103-04 prehearing conference BRANDENBURG, B. Consolidated Edison Co. of New York MORGAN, C. Pouer Authority of the State of New York MORGAN, C. Morgan Associates B2/10/27 GLEASCH, J.P., SHON, F.J., PARIS, D.H. Atomic Safety and Licensing Board Panel 2pp 15853-012 24X Fiche 50-247, B2/10/27, B210290271

H Ceneral correspondence

;

 $t \in \{ \cdot \}$

- 8210250272 Requests substitution of SL Baum w/TR Frey on official syclist for proceeding Related correspondence COLARULLIPF Morgan Associates COLARULLIPF Power Authority of the State of New York 82/10/19 STUCKYS W Bocketing & Services Branch ip 15791 190 24X Fiche 50-247,82/10/19, 821073-0772
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180077 Forwards comments on PRA study dealing w/selsmic hazard Validity of conclusions rest on quality of primary data bases & assumptions in both studies Repts are not valid risk assessments due to data base limitations POMEROY, PW ACRS - Advisory Committee on Reactor Safeguards 82/08/24 OMRENT, D ACRS - Advisory Committee on Reactor Safeguards 7pp 15876 001 24% Fiche 50~003,82/08/24.8207180077

P Operating license stage documents & correspondence

- 8006240851 Discusses postulated fuel handling accident inside containment, based on licenses 770&15 accident analysis analysis includis worst single failure during accident Satety evaluation & containment purge sys Tech Specs encl BARRETTLL Operating Reactors Assessment Branch 80/06/06 VAROA, S. Operating Reactors Branch 1 3pp 02767 167 2 Fiche 50-247.80/06/06/06/0806940851
- 8007010458 Operating Reactor Event Hemo 80-7 re nearly simultaneous traps of Units 2 & 3 Event was of negligible safety significance & trips were unrelated & coincidental EISENHUT.D G Division of Licensing 60/06/13 VOLLHER,R H Division of Engineering MATEGN,R J Division of Safety Technology HARAUER,B H Division of Human Factors Bafety 2pp 02815 145 24X Fiche 50-247.80/06/13.8007010658
- 6007070448 Operating Reactor Event Mimo 80-8 reliass of offsite power Effects of thunderstorm resulted in total loss of offsite power Emergincy diesel generators functioned properly EISENHUT, D.O. Division of Licensing 80/06/13, VOLLMER, R.H. Division of Engineering 8055.D.F. Division of Systems Integration (pre 811005) HANAVER.S.S. Division of Human Factors Safety Bpg 02881 349, 24% Fiche 50-247,80/06/13,8007070448
- 8007150303 Notifies that review will be conducted of Offshore Power Bys short-term risk studies using various resources, in response to 800405 request Evaluation will be submitted by 800922 MATTEGN.R J Division of Bafety Technology. 80/07/02. EISENHUT, 0 Q Division of Licensing 2pp 02752 301 24X Fiche 50-247, 80/07/02, 8007150303
- 8007280312 Summary of 800625 masting w/util re implications of Class 9 accidents on liquid pathways at facility.

 CODELL, R Hydrologic & Geotschnical Engineering Branch 60/07/08 LEAR Q, Hydrologic & Geotschnical Engineering Branch 5pp.

 03016-253. 24X Ficks 30-247,80/07/08,8007280312

- 8087310117 Forwards request for add1 info required to complete Frankly, Research Ctr evaluation of adequacy of steam generator & reactor coolant pump supports Request should be sent to Licensee NICHMAN, R Operating Reactors Assessment Branch 80/07/ VARGA, S A Operating Reactors Branch 1 7pp 03056 268 Fiche 50-247, 80/07/14, 8007310117 80/07/14
- BCOBOSO220 Requests LB Marsh be permitted to continue reviewing overpressure protection sys & associated Tech Specs NOVAK. I Assistant Director for Operating Reactors BO/0//3() ERNSTIM L Assistant Director for Technology Review IP 030/8 175 24X Fiche 50-247.BO/0//30,8008050220
- 8008130744 Summary of 800617 meeting w/utils in Bethesda.MD recontainment structural response to core melt accident Sequences
 MEYER.JF Power Systems Branch 80/07/31 Power S
 Jpp 03266 243 24% Fiche 50-247.80/07/31,8008130744 Power Systems Orac s
- 8009100104 Approves Tech Specs revision proposal re insp of hydraulic fluid of snubbers supplied by common reservoir & excessive fluid loss due to external tubing leakage BARREITIL H Operating Reactors Assessment Branch 80/08/Uh VARGAS A Operating Reactors Granch 1 (Pre 800428) ip 03516 074 24X Fiche 50-247,80/08/05.8009100104
- 8008210627 Forwards request for add1 info to spont fuel pout sereching.

 Info needed to complete review of util application for RUDENSTEIN. L. ticense amend RUBENSTEIN.L S. Assistant Director for Core & Containment Systems 80/08/08 NOVAK,T M. Assistant Director for Operating Reacture 3pp. 03382 306 24X Fichs 50-247,80/08/08/800821062/
- 8009030334 Forwards Reactor Fuel Bection questions re tilPAR firel in core previously containing RIPAR fuel Questions should be forwarded to licenses
 RUGENSTEIN, L. S. Assistant Director for Core & Containment Lyster, B0/09/18 NQVAR, T.M. Assistant Director for Operating Resistant 3pp 03462 022 247 Fiche 50-247, B0/09/18, 8009030314
- 8007080466 Forwards response to 800820 request for status rept re-Zion/Indian Point task action plan Responsibilities ari in area of severe accident mitigation features & not in interior operational actions portion MEYERJ F Reactor Systems Branch 80/08/25 NINVAK, F N Assa Director Por Operating Reactors 2pp 03484 009 24X Fiche 50-003, 80/08/25, 8009080466 NEWARLT H ASSESS
- 8010150103 Discusses union representative allogation re hardwas, to security guard personnel Add) info necessary prior to MHK investigation of allegations MARD.N J Office of Inspection & Enforcement, Office of the Director 80/08/29 Office of Inspection & Enforcement, infect the Director 2pp 03630 268 24X Fichs 50-247, RO/OH/2B, pointention
- 8007250234 Submits description of work being done on analysis of releases from facilities Simple 1-D multicompartment thermal hydraulic code being written to analyse variety of FVUS designs Related data enci Reactor Systems Branch 80/09/10 BPLID P Reactor Systems Branch 4pp 03589 257 24% Fiche 30 24/ MO.13 8009250234
- B010220234 Responds to B00917 request re control room review FRC in its detailsf five addl items to near-term OL requirements Item III D 3 4 requires analysis of control room habitability by B10101 MOUSTON R W Accident Evaluation Branch B0/09/23 VARGA & A Operating Reactors Branch i p 03540 001 24X Fiche 50-247,80/09/25.B010220234
- B010210783 Forwards recommendations for meeting auxiliary fastwall min flow requirements Licenses must demonstrate decay heat removal for 10 minutes w/o operator action or reset control valve throttled position CHECK, P.S. Assistant Director for Plant Bystems 80/07/29 NOVAK, T.M. Assistant Director for Operating Reactors 225 03647 104 24% Fiche 50-247,80/07/28,8010210783
- 8010240329 Discusses human factors control room design anspt seek Old 2022 Discusses Auman factors control room Sesign inset as on 800219-22 & 800310-11 Corrective actions procedures to implementation schedule provided. Con Ed & PASNY conled read design repts found incomplete MODRE, V.A. Division of Human Factors Safety. 80/09/29 CLSHINSKI. J. Division of Licensing Spp. 03659 357 Pay Fichs: 50-247, 80/09/27, 8010240327.

- 2010240644 Forwards safety evaluation re electrical override of manual actuation features for containment ventilation isolation & niher ESF sys
 ULSMINSKI.J A Operating Reactors Assessment Branch 80/10/06
 - ULEMINSKI, JA Operating Reactors Assessment Branch 80/10/06 VARGA S A Operating Reactors Branch 1 3pp 03661 092 247 Fiche 30-247, 80/10/06, 8010240644
- 0010270312 Advises that Franklin Research Ctr was notified to proceed wifting evaluation of fracture toughness of steam generator. The reactor coolant gump supports Due to util 800828 request for delay, appropriate conservative assumptions will be made OLSMITSP1. J A Operating Reactors Assessment Branch NRC-03-79-118 80/10/04 NRG-03 A Operating Reactors Operators Deanch 1 2pp 03col 208 24X Fiche 50-247,80/10/06,8010270312
- 3011110034 Requests Instrumentation & Control Sys Branch evaluation of util responses to questions to incore instrumentation tubes at facilities info will aid branch evaluation mitigation reatures re backfitting of severe mitigation features SPEIS 1 P Reactor Systems Branch 80/10/09 SATTERFIELD, R Instrumentation & Control Systems Branch ip 02227 001 24X Fiche 50-247, 80/10/09, 80(1110084
- Olocecope Forwards NRC questions & util answers re backfitting of severe accident mitigation features Evaluation needed in two luts SFEIS.TP Reactor Systems Branch 80/10/17 SCHAUER.FP Structural Engineering Branch 1p 65767 184 24X Fiche 50-247.80/10/17.8010280098
- JOI1200025 Forwards Power Sys Branch evaluation of differences between Indian Point 2 & 3, in response to technical assistance request Requests meeting w/licensee prior to formal response to evaluation
 CHECK.P S Assistant Director for Plant Systems 80/10/21
 ACLAY.T Assistant Director for Operating Reactors 21pp
 03743 111 24X Fishe 50-247-80/10/21-8011200025
- IOI1210284 Forwards draft safety evaluation of licensee response to lask Action Plan Iten II E 12 Automatic institution logic, instrumentation in associated circuitry & automatic feedwater riow indication channels meet safety-grade requirements SANTERFIELD. In Instrumentation & Control Systems Branch 80/10/22 VARGA. S Operating Reactors Branch 1 8pp 03744 123 24X Fiche 50-247.80/10/22.8011210284
- OliO70227 Requests all operating reactor project managers to conduct telephone survey wellicensees to determine if plants are susceptible to svc water leafs Results of survey requested by 801031
 OLSHAML L M Gporating Reactors Branch 1 80/10/29 Operating Reactors Branch 1 1p 03715 124 24X Fiche 50-247,80/10/29,
- Oli120677 Forwards response to request for determination of licensing basis for reactor pressure vessel & containment fan cooler sys re FSAR requirements & current NRC criteria Licensee must perform thermal & stress analysis of vessel LAINAS. G C Assistant Director for Safety Assessment 80/10/27 EISENHUT, D Q Division of Licensing 6pp 03719 357 24X Fiche SQ-247.80/10/29.8011120679
- Oli100165 Bubmits revision of relative concentration for short-term release following an accident Facilities exclusion radius round to be 520 meters resulting in relative concentration equal to 0 00051 sec/cu meter in southwest direction HGUSTON.R W Accident Evaluation Branch 80/10/30 VAROA.S A Operating Reactors Branch 1 p 65768 021 24X Ficha 50-247.80/10/30.801:100165
- 207050085 FOIA request for eight categories of records re steam generators & steam turbines LONG, D. J. Winthrop, Etimson, Putnam & Roberts 82/07/13 Office of Administration 3pp 15645 060 24X Fiche 50-247,62/07/13,8207050085
- 210070007 Responds to FOIA request for eight categories of records re stam generators & steam turbines App A documents provided in R Vdeli FOIA Request Bi-313 Forwards documents listed in App B FELTON. J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10.8210070007

- 82(00)0401 Forwards application to amend Licenses DPR-26 & DPR-5, changing Tech Specs re facility organization & Unit 2
 Tech Specs 3 6 & 4 4 re containment isolation valves 3 12 & 4 12 in pipe lines Class I.II & III fees encl
 G'TOOLE.J D Consolidated Edison Co of New York 82/08/31
 WARGA.S A Operating Reactors Branch 1 3pp 15572 211 24X
 Fiche 50-003,82/08/31,8210010401
- --B210010409 Application to amend Licenses DPR-26 & DPR-5, revising Ta Spec Figures 3 2 & 6 2-2 re facility organization for Units 1 & 2, respectively O'TOOLE, J D Consolidated Edison Co of New York 82/08/31 2p 15572 214 24X Fiche 50-003.82/08/31.821001040:
- --8210010414 Proposed revisions to Tech Spec Figures 3 2 & A 2-2, reflecting change in organizational structure to include position of operations superintendent Safety assessment enc!

 * Consolidated Edison Co of New York 82/08/31 App 15572 216 244 Fiche 50-003,82/08/31,8210010401
- --8210010425 Application to amend License DPR-26, revising Tech Specs 3 & & 4 & to establish requirements for action required when containment isolation valves are inoperable & reflect changes to isolation valve provisions G*TOOLE, J D Consolidated Edison Co of New York 82/08/31 2p 15572 222 24% Fiche 50-003, 82/08/31, 8210010401
- --821001043B Proposed revisions to Tech Specs 3 & & 4 4.establishing specific requirements for action during inoperability of containment isolation valves & reflecting changes & additions to isolation valve previsions Safety assessment encl * Consolidated Edison Co of New York 82/08/31 20pp 15572 224 24X Fiche 50-003.82/08/31.8210010401
- --8210010443 Application to amend License DPR-26, revising Tech Spec Sections 3 12 & 4 12 to defflect editorial change safety-related pipe lines & to efflect editorial change O'TOOLE.J D Consolidated Edison Co of New York 82/08/31 2; 15572 244 24% Fiche 50-003.82/08/31.821001040;
- --B210010449 Proposed revisions to Tech Spec Sections 3 12 & 4 12, reflecting redesigned support sys for safety-related pipe lines & to effect editorial change Safety assessment encl P Consolidated Edison Co of New York 82/08/31 18pp 15572 246 24x Fiche 50-003,82/08/31,821001040;
- 8210080049 Notification of 820927-30 meeting w/util & Franklin Resear Ctr in Buchanan,NY to discuss contractor review of util radiological effluent Tech Specs THOMA.J D Operating Reactors Branch I 82/09/23 VAROA.8 A Operating Reactors Branch I 2pp 66367 336 24X Fiche 50-247,82/09/23,8210080049
- 8210130602 Informs that review of 810731 response to Generic Ltr 81-4 "Qualifications for Insp.Exam & Testing & Audit Personnel," complete Commitments & exceptions to Revision 1 to Reg Guide 1 58 & Reg Guide 1 146 acceptable VARQA-B A Operating Reactors Branch i 82/09/27 B'TODLE, J D Consolidated Edison Co of New York 2pp 15692 347 24X Fiche 50-247.8210130602
- 8210130455 Forwards responses to Items 1.3.4 & 8 of NRC 820315 requestor add1 info re control of heavy loads (NUREG-0&12) Info addressing Items 2.5.6 & 7 will be submitted by 830131 O'TOOLE.J D Consolidated Edison Co of New York 83/09/30 VAROA.S A Operating Reactors Branch i 7pp 18682 019 24X Fiche 50-247.82/09/30.8210130455
- 82(0120253 Forwards initial comments on Sandia Natl Labs 820825 preliminary draft itr rept on review & evaluation of probabilistic safety study, addressing wind, seismic, fire, pressurized thermal shock & fan cooler issues O'TOOLE, J. D. Consolidated Edison Co. of New York BAYNE, J. P. Por Authority of the State of New York B2/10/06 VARGA B. Operat Reactors Branch 1 62pp. 15652 215 24X Fichs 50-247, B2/10/06, B2/10/20253
- 8210190693 Advises that results of 820920 svc water sys test prove t Indian Point probabilistic safety study reflect actual plant configuration Remaining plant improvements in 820305 itrescept ATMS mode to be complete by return to svc O'TOOLE, J D Consolidated Edison Co of New York 62/10/08 VAROA, S A Operating Reactors Branch i 2pp 15738 141. 24% Fiche 50-247.62/10/08.8210190693
- 8210210032 Forwards request for add1 info to complete raviaw of TMI Item II K 3.25, "Power to Pump Beals " Areas of conformance or deviation from stated position should be identified & info re design & operation of cooling sys provided VARCA: S A Operating Reactors Branch I 82/10/15 D'TOOLE, J D Consolidated Edison Co of New York 3pp 13774 360 24% Fiche 50-247, 82/10/15, 8210210032

- 8210280428 Forwards safety evaluation of adequacy of station electric distribution sys voltages based on util 820707 ltm Sys voltages adequate Review closed VARQA: S. A. Operating Reactors Branch 1 82/10/18 0'TDDLE. J.D. Consolidated Edison Co. of New York 2pp 15860 017 24X Fiche 50 247, 82/10/18, 8210280428
- --8210280430 Safety evaluation supporting adequary of station electric distribution sys voltages

 4 Office of Nuclear Reactor Regulation, Director 15960-021 24% Fische 90-247-02/10/16,9210280428
- ~-8210280402 "Adequacy of Station Electric Distribution bys Voltages.
 Indian Point Nuclear Station, Unit 2 "
 UDY.A C. HEBER, D. A. 6020, Inc. FIN A-6429 EQQ-EA-5007 R01
 62/07/30 PREVATTE.R L. Division of Systems Integration (past
 811005) 1499 15860 028 247 Fiche 50-247,82/10/18.8210280428
- 8210250332 Notsfies of changes in estimated schedule of completion for TMT (tems 11 f 1, "Noble Cas Monitoring." I1 B 3, "Post-Accident Sampling," & 111 D '1 + Control Room Habitability "Inds will be completed by end of refueling C100LE. J D Consolidated Edison Co of New York 82/10/19 WARGA. B A Operating Reactors Brench 1 2pp 15802-357 24% Fische 50-247,82/10/19.8210240332
- a inspection reports. If Mullotins & correspondence
- 0210080015 Add1 response to FOIA request for 19 categories of information reactor evolts & safety problems Forwards documents insted in App A Documents in App B completely withheld (ref FOIA Exception 5) FELTON J (1 Division of Rules and Records 92/07/12 UDELL.R A Critical Mass Energy Project 9p 19665 027 24X Fithe 50-000, 82/07/12, 8210080015
- ---B2100B0137 Equation assessment of licensee performance notes refacility evaluation for 1980

 * NRC No Betalled Affiliation Given 60/12/31 7pp
 19867 358 24X Fiche 50-900, 82/07/12,82100B0015
- 0210070097 Responds to FOIA request for eight categories of records resteam generators & stoom turbines App A documents provided in A Udell FOIA Request 91-313 Forwards documents listed in App B
 FELTON, J M Division of Rules and Records 82/08/10 LONO, D J
 Winthrop, Stimson, Putnam & Roberts 9pp 19645 063 24X
 Fiche 50-000, 62/08/10, 62/00/0007
- --8010070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensess IPPOLITO. T. Operating Reactors Assessment Branch 82/04/01 VARBA.S. Operating Reactors Branch 1 5pp 19645 131 24X Fiche 50-000, 82/08/10, 8010070007
- --B210070172 Forwards info re steam generator integrity & insps at all operating PNRs, per 750370 & 21 requests Details of insps. including defect indications tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 GOLLER.K.R. Division of Heactor Litemeing (NRR-1975 only) 75/03/24 MACCARY.R.R. Division of Technical Roview (NRR-1975 only) 5pp 15645 196 24X Fiche 50-000, 82/08/10, 8210070007
- 8210200078 Forwards stoam generator exam program for 1982 refueling/ maint outage O'TODLE.J D Commonwealth Edison Co 92/09/18 VARQA, 8 A Licensing Branch 1, 21pp 15759 179 24X Fiche 50~247.82/08/18, 8210200078
- --B210060041 Notice of violation from insp on B20801-31 * Division of Project & Resident Programs B2/07/17 ip 15615 Q56 24% Fiche 50-247,82/09/17,8210060024

d

- --B210050046 IR Imap Rept 50-247/B2-18 on B20801-31 Noncompliance noted failure to maintain containment integrity for isolation valves

 REBELOWSKI, T., KOLTAY, P., KIBTER, H. Division of Project & Resident Programs. B2/09/16 15pp 15615 057 R4X Fiche 50-247, 82/09/17, 8210050024
- 8208170233 IE Info Notice 80-35. Buppl 1. "Leaking & Dislodged I-125 Implant Beeds " Bvc list encl COBB.L I Division of Fuel Facilities. Heterials & Bafeguards 82710706 consolidated Edison Co of New York 66pp 13761 250 24X Fishe 50-000.82710706.8208170233

- 8210130556 Ack receipt of 820915 ltr informing NRC of steps taten to correct violations noted in 1E Insp Rept 50-247/82-14 STAROSTECKI.R Division of Project 2 Resident Programs 0/TODLE, J D Consolidated Edison Co of New York 1p 15483 304 24X Fiche 50-247, 82/10/06, 8210130556
- --8210130559 Forwards response to NRC 820816 ltr re violations ented at IE lnsp Rept 50-247/82-14 Corrective actions post-major tests/insp per CGL-51 will be ensured All post-maint activities after 82103 will be verified 0/TGLELJ Consolidated Edison to of New York 82/09/15 STARDSTECKI, R Division of Project & Resident Programs ip 15483 305 24% Firhs 50-247,82/10/04,8210130556
- 8210210300 Forwards IE Insp Rept 50-247/82-19 on 820901-00 No honcompliance noted STARQSTECKI, R Division of Project & Resident Programs 82/10/07 O'TOLEC, D Consolidated Edison Co of New York 2pp 1576; 248 24X Fiche 50-247,82/10/07,8210210300
- --8210210307 IE insp Rept 50-247/82-19 on 820901-30 No noncompliance noted Major areas inspected licensee mpt changes operational sefety verification, plant tours, operability of ESF, safety sys challenges & LER followups
 REBELOWERI, T., FOLEY, T., KISTER, H. Division of Project & Resident Programs 82/10/06 17pp 15764 250 24% Fiche 50-247,82/10/07 8210210300
- 8208190238 IE Autletin 82-03, "Stress Corrosion Cracking on Molt-Mall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list enci DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14.8208190238
- S Reportable occurrences, LERs & related correspondence
- 621001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 Until R A Critical Mass
- --8011120679 Forwards response to request for determination of licens basis for reactor pressure vessel & containment fan rooler sys re FSAR requirements & corrent NRC criteria Licensee must perform thermal & stress analysis of vessel LAINAS.G C Assistant Director for Safety Assessment 80/LG/29 EISENBUT.D G Division of Licensing App 15728 045 24x Fichs 50-000.82/06/28.8210010008
- --8011240024 Forwards Containment Sys Branch discussion paper compar facility event w/current licensing criteria RUBENSTEIN, L. Assistant Director for Core & Containment Systems 80/11/07 LAINAS.0 Assistant Director for Safety Assessment App 15728 051 24X Fiche 50-000.82/06/28.8210010008
- --810109029A Describes sequence of events leading to containment flo at Unit 2 Unit 3 should be aliqued to return to gower operation pending long-term actions IE Info Notice 80-37 re containment cooler leaks & press release encl WODUS.H W Office of Inspection & Enforcement, Office of the Director 80/11/13 JURDAN, E. L. Office of Inspection & Enforcement, Office of the Director App 19728 039 24x Fiche 50-000,82/06/28.8210010008
- --Bi03090387 Informs that Safety Program Evaluation Branch does not develop requirements for non-RCS leakage detection Branch syaluates proposed requirement adequacy in terms of cost-benefit analysis & possible adverse consequences MURLEY. T E Division of Safety Technology 81/02/27 EIEENHUT, D 0 Division of Licensing 2pp 15728 033 24% Fichs 50-000,82/04/28,8210010008
- B210080015 Add1 response to FOIA request for 19 categories of infonuclear reactor events & safety problems. Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON.J M. Division of Rules and Records B2/07/12 UDELL.R A Critical Mass Energy Project 9pp 15645 027 24%
 Fiche 50-000.82/07/12,8210080015
- --8205030617 Forwards "Engineering Evaluation of Indian Point Unit Flooding Event of 801017" Flooding Event of 801017 But Ballotton of Birector's Office 82/04/22 MICHELSON C Director's Office ip 18665 239 24X Fiche 50-000, 82/07/12, 8210080015
- --8205030619 "Engineering Evaluation of Indian Point Unit 2 Flood; Event of 801017 " LANNING, W D. Director's Office 82/04/30 25pp 15665 240 Fiche 50-000,82/07/12,8210080015.

- 82100A0396 Forwards LER 82-036/03L-0 O'TOOLE.J D Consolidated Edison Co of New York 82/09/24 HAYMESR C Region 1. Orfice of Director ip 15615 326 24X Fiche 50-247,82/09/24.8210060396
- -- #210060400 LER 82-036/03L-0 on 820825, temporary change procedure authorized to permit simultaneous operation under load of two diesel generators during surveillance test-potentially reducing degree of redundancy Test procedure PTM-21 changed SMLTH.H C Consolidated Edison Co of New York 82/09/24 Region I, Office of Director 2pp 15615 327 24% Fiche 50-247,82/09/24,8210060396
- 6210070361 Forwards LER 82-034/03L-0 0'TQCLE.J D Consolidated Edison Co of New York 82/07/27 HAYMES.R C Region 1. Office of Director ip 15634 060 24X Fiche 50-247, 82/07/27, 8210070361
- --8210070346 LER 82-034/03L-0 on 820828, during normal operation, charging pump 22 developed leak & was declared inoperable Caused by defective gastet on cylinder head 4 Gasket replaced & pump returned to svc # Consolidated Edison Co of New York 82/09/27 Region I. Office of Director 1p 15634 061 24x Fiche 50-247, 82/09/27, 8210070746
- 6210040141 Forwards LER B2-032/01T-0 G'TDOLE-J D Consolidated Edison Co of New York 82/09/28 HAYNES.R C Region 1. Office of Director 1p 15583 088 24X Fiche 50-247, 62/09/28, 8210040141
- --8210040145 LER 82-032/01T-0 on 820817.bloudown outer isolation valve FCV 1215A failed closed due to failure of solenoid valve SOV 1315A caused by open circuit in pilot solenoid valve SQV 1315A coll Coll replaced FITZPATRICK.8 Consolidated Edison Co of New York 82/08/31 Region i, Office of Director 3pp 15583 089 24X Fiche 50-247.82/09/28.8210040141
- 8210130411 Forwards LER 82-035/03L-0 O'TOOLE.J D Consolidated Edison Co of New York 82/07/28 HAYNES.R C Region 1. Orfice of Director ip 15680 241 24X Fiche 50-247, 82/09/28, 8210130411
- --B210330419 LER 82-035/03L-0 on 820829, nuclear power range instrumentation channel N4! became inoperative due to failure of power supply unit Gause of unit failure not stated Defective high voltage power supply removed NADIPURAM.P Consolidated Edison Co of New York 82/09/28 Reg1901 1. Diffice of Director ip 15680 242 24X Fiche 30-247.82/09/28.8210130411
- 8210290267 Part 21 deficiency rept re potential galling problem between stem & bonnet of 1 25-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1981-Aug 1982 Valves should be serviced & stem &/or bonnet replaced ISABELLE.L D Convai, Inc 82/10/11 HAYNES,R C Region 1, Office of Director 17pp 15854 232 24X Fiche 30-000,82/10/11, 8210290267
- 82:10250145 Forwards LER 82-039/03L-0 O'TOCLE.J D Consolidated Edison Co of New York 82/10/12 HAYNES.R C Region i, Office of Director ip 15787 354 24) Fiche 50-247, 82/10/12:8210250145
- ~-8210250149 t.ER 82-039/03L-0 on 820910, chemical sampling indicated in 15% concentration of boric acid in storage tank 22 Boric acid transfer pump also out of svc for maint Cause not stated Contents diluted HIMPICHS, O Consolidated Edison Co of New York 82/10/12 Region 1. Office of Director in 15787 355 24% Ficha 50-247.82/10/12.8210250145
- T Hearing transcripts on non-antitrust matters
- 8210060232 Testimony of JD O'Toole before US House of Representatives Subcommittee on Energy & Conservation of Committee on Energy & Conmerce re role of public participation in NRC proceedings M/Certificate of Bvc Related correspondence O'TOOLE, JD Consolidated Edison Co of New York 82/10/01 2ipp 15621 204 24X Fiche 30-247,82/10/01,8210060232

- DOCKET SO-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8209290125 Releases public version of revised generating station emergency pion corporate command ctr emergency plan implementing procedure FELTON.J.M Division of Rules and Records 82/09/16 Document Management Branch ip 15564 122 24X Fiche 50-000,82/09/16,8009290125
- ---B209290189 Forwards public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EDF-3, "Environ/Emergency Coordinator " Receipt form encl PAJOHSKI, J E Commonwealth Edison Co 82/09/01 DENTON, H R NRC No Detailed Affiliation Given Ip 13564 123 24X Fiche 50-000, 82/09/16, 8209290125
- --B200290225 Public version of Revision 4 to generating station emergency plan corporate command ctr emergency plan implementing Procedure EOF-G. "Environ/Emergency Coordinator "PAJONSKI.J E. LITERSKI.L A. FLESSNER: S. A. Commonwealth Edison Co. 82/08/31 lipp 15564 124 24X Fiche 90-000.82/09/16, 820920125
- 8210010007 Forwards info to suppl B20701 request for exemption from App R per B20917 telcon Request applies to Sections III 0 2 a & 1II 0 3 b re installation of fire suppression sys RAUSCH: TJ Commonwealth Edison Co 82/09/23 EISENRUT, D Q Division of Licensing 8pp 15565 152 24X Fiche 50-000,82/09/23, 8210010009
- 8210130376 Advises that installation of offsite dose calculation syspogram fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation
 SWARTZ.E D Commonwealth Edison Co 82/10/06 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 15682 098 24X Fiche 50-000, 82/10/06, 8210130376
- 8210270047 Releases public version of revisions to Quad Cities, Zlon & Dresden emergency glan annexes & revised generating station emergency plan telephone directory FELTON. J M Division of Rules and Records 82/10/08 Document Management Branch 1p 15877 3:3 24X Fiche 50-000,82/10/08. 8210270047
- --8210290060 Forwards public version of Revision 3 to Quad Cities & Zion emergency plan annexes. Revision 2 to Dresden emergency plan annex. Revision 0 to Buron emergency plan annex & revised generating station emergency plan telephone directory MODRER D Commonwealth Edison Co 82/07/30 DENTON, H R NRC No Detailed Affiliation Given 5pp 15877 314 24X Fiche 50-000, 82/10/08, 8210290047
- --8210290077 Public version of Revision 3 to Quad Cities & Zion emergency plan annexes, Revision 2 to Dresden emergency plan annex & Revision 0 to Byron emergency plan annex * Commonwealth Edison Co 82/06/30 102pp 15877 319 24X Fiche 50-000, 82/10/08.8210290047
- --8210270088 Public version of revised generating station emergency plan telephone directory QALLE,DP Commonwealth Edison Co. 82/08/12 43pp 15878,218 24X Fichs 30-000,82710/08,8210290047
- 8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs.

 TRAMM.T R Commonwealth Edison Co 82/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 15776 287 24X Fiche 50-000, 82/10/14, 8210220358
- 8210250170 Advises that plans & preparedness for offsite protection near facility adequate & will be applied in event of radiological emergency IL State & local plans approved sub; to verification of adequacy of alerting & notification sys THOMAS.L M Federal Emergency Hanagement Agency 82/10/14 DIRCKS, W J Diffice of the Executive Director for Operations ip 15788:285 24X Fiche \$0-010.82/10/14.8210250170.
- Q Adjudicatory correspondence
- 8210010257 Decision ALAB-695 affirming LBP-81-37 & LBP-82-65, sanctioning mod to OL for Unit 3 to permit installation of flyw high density spant fuel storage racks & authorizing issuence of amends to OLs, respectively.

 TOMPKINS.B A A Atomic Sefety and Licensing Appeal Panel 82/09/29.

 2p 15574.056 24% Fiche:50-237,82/09/29,8210010257

- P Operating license etage documents & correspondence
- 6210000001 Advises that board notification issued on 820703 re use of auxiliary overhead crame rather than main overhead crame to move spent fuel pool racks should have been assued w/Number 811-82-92
 MIRAGLIA: F. Assistant Director for Safety Assessment 62/09/14
 Atomic Safety and Licensing Board Fanel 4pp 15668 341 24X
 Fiche 50-237.82/09/14.8210080001
- --8210080002 Board Notification 82-92 informs of util failure to tarry out fuel pool rack removal & installation in manner described in testimony at hearings Austiliary overhead crans used instead of redundant main overhead crans IPPOLITO.T A Assistant Director for 8afaty Assessment 82/09/03 Atomic Safety and Licensing Board Panel 2pp 15668 345 24X Fiche 50-237.82/09/14.8210080001
- --B2092103B3 Recommends board notification resulting use of auxiliary crane instead of main radundant crane to install fuel racks as discribed in testimony before ASLB Licenses has committed to follow testimony in completing remaining work.

 IPPOLITO, The Assistant Director for Bafety Assessment B2/09/03 EISCHNUT.D O Division of Licensing 2pp 1566B 349 24X Fiche 50-237.82/09/14.8210380801
- 6210120105 Requests delay of implementation due dates no NUREO-0737, items II B 2. "Plant Shielding." II B J. "Post-Accident Sampling" & II F I 1. "Noble 0a. Effluent Monitor" SHARTZ.E D. Commonwealth Edison Co. 82/10/04 EISENHUT, D 0 Division of Licensing Spp. 15651 237 24% Fichs 50-000, 82/10/04, 6210120105
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" GQLDEN-J C Commonwealth Edison Co 82/10/06 CASE,E 9 Office of Nuctear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000-82/10/06
- --0210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Namual"

 Commonwealth Edison Co 02/09/30 83pp 15805 139 24X Fiche 50-000.02/10/06.8210260584
- 8210180059 Provides add1 guldance & clarification re 820806 request for add1 info per NUREO-0737. Item If B 3, "Post-Accident Sampling Sys " Detailed reliability analysis not required to satisfy NRC concerns CRUTCHFIELD D Operating Reactors Branch 5 82/10/08 DELGEORGE, L Commonwealth Edison Co Spp 15720 004 24X Fiche 50-000, 82/10/08, 8210 180059.
- 8210190680 Forwards safety evaluation of licensee 820414 & Obil responses to NUREO-0737. Item II E 4 2. "Purga/Vent Valve Isolation Dependability" Responses acceptable Topic review completed CRUTCHFIELD.D Operating Reactors Branch 5 82/10/13 DELOCORDE.L Commonwealth Edison Co Spp 15738:192 24X Fiche S0-237. 82/10/13.921019048D
- 8210190445 Forwards supplemental response to Generic Ltr 82-05 re implementation status of NUREG-0737, Items II B 3,11 F 1 2, II F 1 5 & II F 1 6, In response to 821005 request SHARTZ, E D Commonwealth Edison Co 82/10/14, EISENHUT, D Q Division of Licensing 5pp 15741 202, 24X Fichs 50-000, 82/10/14, 8210190445
- 8210220335 Forwards into re NUREQ-0737, Item II D : "Performance Testing of BMR 8afety/Relief Velves," per 620727 request.
 Into adequately damonstrates applicability of results of BMR owners group generic test rep NEDE-24988-P to facility EMARTZ.E D Commonwealth Edison Co. 82/10/13 EISENHUT, D O. Division of Licensing 17pp 15776 GII 24% Fiche 50-237,82/10/15,8210220335
- 8210250155 Forwards corrections to proposed Tech Spsc Pages i, 2/2, 2-1 & 3 3/4 3-5, supporting review of future reloads & revised Figure 3 5 i, Sheet i, providing estended MAPLHOR vs exposure curves for barrier leed test assembly fuel RAUSCH: T J Commonwealth Edison Co 82/10/18 DENTON: H R Defice of Nuclear Reactor Regulation. Director 2pp 15788, 233 24X Fichs: 50-000, 82/10/18, 8210250155
- --8210250177 Errate & Addenda Sheet S, registing Page 4-10 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Guad Cities 1 & 2 Nuclear Pager Stations"

 " General Electric Co NEDO-24146A ERR OB, 82/09/30 3pp, 15788-239, 24% Ficha.50-000,82/10/18:8210250155

- 8210250069 Provides addi info re reactor water cleanup room area ter; monitors Temp elements cause no automatic plant response beyond control room alarms RAUSCH T J Commonwealth Edison Co 82/10/19 EISENHUT, D O Division of Licensing 2pp 15787 081 24X Fiche 50-000, 82/10/19 2210250069
- B210260296 Forwards safety evaluation of BMR owners group generic response to NUREO-0737. Item II K 3 25. "Effect of Loss of AC Power on Pump Seals " No mods to seal cooling for restreulation pumps required Item resolved CRUTCHFIELD. D Operating Reactors Branch 5 82/10/21 DC 0F40P2F. Commonwealth Edison Co 7pp 15803 018 24X Fiche 50-2,17. B2/10/21, B210260296
- O Inspection reports. IE Dulletine & correspondence
- --8210060335 IE Insp Hopts 50-010/82-02,50-237/82-03 & 50 249/82 ft. 820119-0218 No noncompliance noted Hajot areas inspected open & unresolved items & items of noncompliance reintegrated leaf rate test REIHANN,F W. Region 3, Office of Director JACKIM-1 N. Dieter. of Engineering & Technical Programs 82/09/21 Jpp 15655 30: 24X Fichs 50-010,02/09/22,8210060329
- 8210130523 Forwards IE Insp Repts 50-010/82-13.50-237/82 1/ t. 50-249/82-18 on 820708-0809 & notice of violation STREETER. J F Division of Project % Resident Programs (he/09/13 REED, C Commonwealth Edison Co 2pp 15713 099 24x Fiche 50-010,82/09/28,8210150523
- --B210150530 Notice of violation from insp on B20708-0009 STREETER J F Division of Project & Resident Programs (02/67), Ip 15713 101 24% Fiche 50-010.82/09/28.8210190529
- --B2[015053B IE Insp Repts 50-010/82-13,50-237/82-17 \$ 50 249/()... LB 82070B-0809 Noncompliance noted fallure to issue & perform air pressure test procedure TONQUE,T M , JORDAN,M J , WALKER,R D Division of Project & Resident Programs 82/09/28 Bpp 15713 102 J4X F(che 50-010,82/09/28,8210150529
- 82j00.60359 Ack receipt of 820910 itr Informing NRC of steps telent correct violations nated in IE Inep Repts 50-237/81*[9.50-249781-32,50-249781-32,50-254781-23.50-258581-23.50-295/8]*11 & 50-304/81-29 SPESBARD.R L Division of Project & Resident Programs (JJ/IC**) REED.C Commonwealth Edison Co ip 15418-354 24x Fiche 50-004,82/10/01.8210060339
- ~-8210060367 Responds to NRC 820712 ltr re visiations unted in IE:
 Repts 50-237/81-39, 50-249/81-32, 50-294/81-23, 50-286/811 2;
 50-295/81-31 & 50-304/81-29 Corrective actions training Farmot priorities re plant availability will be conducted
 REED, C. Commonwealth Edison Co. 82/07/10 KERPIER, J. Q. 48,
 3, Office of Director 13pp 15618 355 24X
 Fiche 50-000, 82/10/01, 8210960359
- 8210080178 Forwards listing of piping sys which fell to mest bear requirements; per NRC 800818 confirmatory action lit if Bulistin 79-14 operability evaluation updates will not be provided for Dresdan & Guad Cities Final update by Bet 1452 RAUSCH, T J Commonwealth Edison Co 82/10/0; Kiffilk & Q 3, Office of Director 6pp 15640 159 24X Fichs 50 Offic 52×18210080178
- 8210150539 Forwards IE Insp Repts 50-010/82-15.50-237/82-19 to-249/82-20 on 820830-0903 No noncompliance noted PAPERIELLO, C J Division of Emergency Proparedness to Greenith Support 82/10/01, REED, C. Commonwealth Edison Co Pja 15714,175 24X Fichs 50-010,82/10/01,8210150539
- --8210150543 IE Insp Repts 50-010/82-15, 50-237/82-19 4 50 %27/2; 820830-0903 & 09 No noncompliance noted Hajor area; inspected confirmatory measurements program GC prayram analytical measurements is environ monitoring program GCHUMACHER, M.C., NICHOLSON, N.A., JANUSKA, A.O. Division of Emergency Preparedness & Operational Support 82/09/200 15714-177. 24X Fichs 50-010, 82/10/01, 8210150539
- 8210080190 Confirms 821103 enforcement conference at Region De aspects associated e/procurement, installation & use of non-quelified valve guides in electromagnatic relief velves at facilities.

 SPESSARDIRL. Division of Project & Resident Programs REED, C. Commanuealth Edison Co. ip 15540:181, 24g Fiche, 50-000, 82/10/04, 8210080190

- 8208190233 IE info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000:62/10/06.9208190233
- 8208190238 to Bulletin 82-03. "Stress Corrosion Cracking in Thick-Mall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Svc list encl DEYOUND.R C Director's Office. Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- R Periodic operating reports & related correspondence
- EC10180097 Forwards monthly operating repts for Sept 1982 SCOTT.D J Commonwealth Edison Co 82/10/01 Director's Office. Office of Inspection and Enforcement 1p 19718 001 24X Fiche 50-010.82/10/01.8210180097
- ~-8210180100 Monthly operating repts for Sept 1982 SCHRUEDER. II A Commonwealth Edison Co 82/10/01 22pp 13718 002 24X Fichs 50-010, 82/10/01,8210180097
- S Reportable occurrences. LERs & related correspondence
- ©210150097 Forwards LER 81-026/03L-0 SCDTI,D J Commonwealth Edison Co 81/10/13 KEPPLER, J O Regio 3, Chicago, Office of the Director (81/03/01) ip 15701 182 24 Fiche 50-249, 81/10/13, 8210150097
- --8210i50102 LER 81-026/03L-0 on B10915, while shutting down, rod P-10 showed wrong position on rod worth minimizer Caused by several diode failures on two digital output printed circuit boards Boards removed, repaired & tested satisfactorily SCHROEDER, B. Commonwealth Edison Co. 81/09/27 Region 3, Chicago, Office of the Director (81/03/01) 2pp. 15701 183 24X Fiche 50-249, 81/10/13, 8210150097
- E210270251 Forwards LER 81-040/017-0 ECOTT.D J Commonwealth Edison Co 81/12/15 KEPPLER, J Q Region 3. Chicago. Office of the Director (81/03/01) 1p 15829 233 24X Fiche 50-249, 61/12/15,8210270251
- ---B210270254 LER BI-040/01T-0 on B11201.whom Rx pressure decreased to 32 psig.rud N-9 notched from position 02 to 04 & then to position 06 Cause unknown Hork requost issued to check single notch control switch during next refueiing outage SCHROEDER, B A Commonwealth Edison Co B1/12/07 Region 3, Chicago. Office of the Director (B1/03/01) 3pp 15829 234 24X Fiche 50-249,81/12/15,8210270291
- 8210040126 Forwards LER 82-035/03L-0 SCOTT.D J Commonwealth Edison Co 82/09/16 KEPPLER.J Q Region J. Office of Director ip 15581 207 24X Fiche 50-249.82/09/16, 8210040126
- --8210040129 LER 82-035/03L-0 on 820905, during testing of control rod drive II-4 for overtravel, overtravel alarm came up & position indication lost, indicating uncoupling of control blade from drive Probably caused by inner filter becoming detached WHALEIR Commonwealth Edison Co 82/09/16 Region 3, Dffice of Director 2pp 15381 208 24X Fiche 50-249,82/09/16,8210940626
- B210250306 Forwards updated LER 82-029/01X-1 SCOTT, D J Commonwealth Edison Co 82/09/22 KEPPLER, J O Region 3. Office of Director 1p 15791 038 24X Fiche, 50-249, 82/09/22, 8210250306
- --8210250316 Updated LER 82-027/01X-1 on 820712, magnetrol switches 820 & 82D did not trip when tested for proper tripping upon water loading Cause not known Visual Inspiravism & weekly testing revealed no abhornalities Vendor review encl.

 WHALEN, R Commonwealth Edison Co 82/09/22, Region 3, Office of Director 3pp 19791 039 24X Fiche 50-249, 82/09/22, 8210250304
- 8210250328 Forwards updated LER 82-023/01X-1 SCOTT, D J Commonwealth Edison Co 82/09/22 KEPPLER, J O Regio 3. Office of Director is 15790 082 24X Fichs 50-249,82/09/22, 8210250328
- --B210250348 Updated LER 82-023/01X-1 on B20510, no low power range monitor input to rod block monitor (RBM) noted during DDP 700-E3 Caused by shorted steering diodes on several RBM cards Defective diodes replaced MOROAN, W Commanwealth Edison Co 82/09/22 Region 3, Office of Director, 2pp 15790 083 24X Fiche 50-249,82/09/22,8210250328

- 8210130197 Forwards LER 82-034/03L-0 SCOTT.D J Commonwealth Edison Co 82/09/28 KEPPLER.J Q Region J. Office of Director 1p 15474 117 24X Fiche 50-249,82/09/28, 8210130197
- --9210130201 LER 82-034/03L-O on 820701, investigation revealed that substandard electromatic relief velve main valve disc guide sizeve utilized on ERV 3-203-3C Caused by personnel error in ordering sizeve Gleeve will be replaced holl.AND. P Commonwealth Edison Co 82/09/28 Region 3, Office of Director 2pp 15674 LEB 24X Fiche 50-249.82/09/28, 820130197
- 8210190458 Forwards LER 82-036/03L-0 SCOTT.D J Commonwealth Edison Co 82/10/05 KEPPLER.J Q Region 3. Office of Director 1p 15735 319 24X Fiche 50-249.82/10/05, 6210190458
- --8210190471 LER 82-036/03L-0 on 820912, during startup #t 45% power, annunciator 903-5-N-4 Indicated turbine pressure operator load rejection & turbine stop valve scrams bypassed on one subchannel of Channel A half scram circuitry TURNQUESTL Commonwealth Edison Co 82/10/05 Region 3, Office of Director 2pp 15735 320 24% Fiche 50-249,82/10/05,8210190458
- 8210190403 Forwards LER 82-037/03L-0 SCOTT, D J Commonwealth Edison Co 82/10/06 REPPLER, J Q Region 3. Office of Director 1p 15740 356 24% Fichs 50-249, 82/10/06, 8210190403
- --8210190412 LER 82-037/03L-0 on 820922, transient in-core probe ball valve 3E would not reclose Caused by lose of tension in high tension spring in drive mechanism Valve closed & spring retensioned MOROAN W Commonwealth Edison Co 82/10/06 Region 3, Office of Director 2pp 15740 357 24X Fiche 50-249,82/10/06,8210190403

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

- F Security, medical, emergency & fire protection plans
- 8209170062 Forwards Revision 6 to physical security plan Revision withheld (ref 10CFR73 21)
 UHR10.R.E Florida Power & Light Co 82/09/08 EISENHUT, D G
 Division of Licensing 2pp 14910 069 24% Fiche 50-250,82/09/08,8209170062
- 6210190178 Reteases public version of emergency plan implementing procedure FELTON, J M Division of Rules and Records 82/09/30, Document Management Branch ip 15758 062 24X Fiche 50-250,82/09/30,8210190178
- --8210190184 Forwards public version of Emergency Plan implementing Procedures 20104. "Emergency Roster," 20101, "Duties of Emergency Coordinator," 20107, "Fire/Explosion Emergencies" & 20127 "Duties of Assembly Ares Bupervisor" UNRIGHE Florida Power & Light Co. 82/09/24 O'REILLY, J P. Repion 2. Office of Director 1p. 15759.063. 24X Fichs 50-250,82/09/30,8210190178
- --BR10190194 Public version of Emergency Plan Implementing Procedures 20101, "Duties of Emergency Coordinator." 20104, "Emergency Roster." 20107, "Fire/Explosion Emergencies" & 20127, "Duties of Assembly Area Supervisor" * Fiorida Power & Light Co 82/09/16 Supp 15759:064 24X Fiche 50-250, 82/09/30, 8210190178
- S210190440 Extends invitation to observe S21019 demonstration of emergency response sys at Technology for Energy Corp. Knoxville, TN UHRIO,R E Fiorida Power & Light Co. S2/10/12 EISENHUT, D. Q. Division of Licensing ip 15741:186. 24X Ficha 30-000.82/10/12, 8210190440
- 8210230244 Forwards revisions to physical security plan. Revisions withhold (ref 10GFR73 21)
 KAMER, D. 8 Tennessee Valley Authority 82/10/19 DENTON, H R
 Office of Nuclear Reactor Regulation, Director. 1p 15788, 345, 24x
 Fichs 50-250, 82/10/19, 8210250244
- 8210280291 Forwards Revision 1 to 10CFR 30 App R fire protection review Revision corrects typographical errors in 820701 submittal UHRIO:R E. Florida Power & Light Co 82/10/22 EISENHUT:D. O Division of Licensing. 1p 13838:080. 24% Fichs:50~250:82/10/22, 8210280291.

ן י

- ------

11

- --8210280293 Revision 1 to 10CFR50 App R fire protection revieu 4 Florida Power & Light Co 62/10/22 63pp 15838 CB1 24X Fiche 50-250,82/10/22.8210280291
- P Operating license stage documents & correspondence
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents Eisted in App B FELTON J H FELTON, J. H. Division of Rules and Records 82/08/10 LGNG, D. J. Winthrop, Stimson, Putnam & Roberts 9pp 15445 C63 24X Fiche 50-000, 82/08/10, 8210070007
- 8210120521 Summary of exit interview following 820713-15 audit of pressurized thermal shock in-plant training programs & operating proceduras
 GROTENHUIS.H Operating Reactors Branch 1 82/09/15 Operating Reactors Branch 1 5pp 15672 261 24X Fiche 50-250,82/09/15.
- 8210280013 Responds to FOIA request for all internal non-public documents nemos, evaluation repts & other mati dealing w/ nuclear plant operations Forwards documents listed in App A FELTON J H Division of Rules and Records 82/09/17 MCINN15.D Nams & Observer 5pp 15860 065 24X Fiche 50-000.82/09/17. 8210260013
- --8208310034 Forwards draft info notice re deficiencies in air filtration & ventilation sys Notice based on radioactive resin release at Pilgrim 1 & on four related events at other plants involving deficiencies in maint & testing of filter sys MATTBON R J Division of Systems Integration (post 8):005) 82/08/05 JURDAN E L Division of Engineering & Quality Assurance. 3pp 15861.024 24X Fiche 50-000.82/09/17.8210280013
- --8210280100 Notifies that on 820224.C Alderson advised that rept sent re possible willful violation of reporting requirements & falsification of QA & guard qualification records at facilities
 REGNER, M E Office of Inspector & Auditor 82/03/01 Office Inspector & Auditor 1p 15861 037 24% Fichs 50-000,82/09/17, 8210280013
- 8210050589 Requests submittal of fees for 82060A request for Tech Spec cloudloop requests submittal of feet for Excount request for tech a changes are depraded grid voitage & 820810 request for approval of mode to turbine runback sys
 BIOOS, R M License Fee Hanagement Branch 82/09/23 UHRIO, R.E. Florida Power & Light Co. 1p. 13626 270 24x Fiche 30-250, 82/09/23, 8210050589
- 8210010292 Forwards response to NRC 820219 ltr requesting addl info re anviron qualification of THI action items contained in NUREO-0737 NUREO-0737 UHRÎQ.R.E. Florida Power & Light Co. 82/09/24 VAR Operațing Reactors Branch | 56pp 15573 125 24X Fiche: 50-250.82/09/24.8210010292 VARGA, S. A.
- 8210060281 Forwards revised schedule for providing final response recentrol of heavy loads on Ouideline 4 (special lifting devices) & Ouideline 7 (crane design) Only manufacturers can obtain requested info URRIO, R E Florida Power & Light Co. B2/09/QO, VAROA, B A, Operating Reactors Branch 1. 2pp. 15621.162. 24X Fichs: 50-250.82/09/QO, 8210060281.
- 8210150407 Revised application for Amenda 87 & 81 to Licenses DPR-91 & DPR-41, respectively, correcting typographical errors re DHR UHRIG.R.E Florida Pawer & Light Co 82/10/11 EIBENHUT, D.G.
 Division of Licensing ip. 15704: QSS. 24X Fiche: 50-250, 82/10/11, E210150407.
- --- BRIGISDAIR Corrected pages to Tech Specs re DNR systeplacing pages in 901230 submittal. * Florida Power & Light Co 82/10/11, Rpp. 15704.026 24X Fiche: 80-280: 82/10/11, 9210150407.
- E210150439 Advises that review of current status of nuclear power plant staff working hours per Generic Ltr ER-22 indicates requirements adequately enforced by incorporation in administrative procedures Amend to Tach Specs unnecessary. UKRIO,R.E. Florida Fower & Light Co. 82/10/12, EIGENHUT, D.Q. Division of Licensing. ip. 18705-004. Z4X Fiche. 50-250, 82/10/12, 8210150439.
- BRIO190559 Forwards payment of proposed license amend fee re-redundancy in RHR sys. UHRIO.R.E Florida Fower & Light Co. 82/10/12. MILLER, W. C. License Fee Management Branch. 2pp. 15735:014. 24X Ficha: 30-250, 92/10/12, 9210190557.

- B210270253 Forwards util B21012 itr containing payment of license 271; far re redundancy in RHR sys requested in NRC B20816 itr UHRIO.R E Florida Power & Light Co 82/10/21 D1005;R M Licers, Fee Management Branch 1p 15828 279 24X Fiche 50-250.82/10/21. 8210270253
- Q Inspection reports. IE Bulletins & correspondence
- 8210070007 Responds to FDIA request for eight categories of records ;; steam generators & steam turbines App A documents provided in R_Udell FDIA Request 81-313 Forwards documents iisted in App B FELTON, J M Division of Ruiss and Records 82/08/10 Winthrop, Stimson, Putham & Roberts 9pp 15645 063 Fiche 50-000, 82/08/10,8210070007 LONG, D. J.
- --8210070137 Forwards tabulated data on steam generator insp & maint or facilities Data should be provided to licensers
 [PPOLITOIT Operating Reactors Assessment Branch 82/04/01 VARRA, S Operating Reactors Branch 1 Spp 15645 131 24X Fichs 50-000, 82/08/10, 8210070007
- --B210070172 Forwards info re steam generator integrity & inspi at all 2100/01/2 Forwards into re stand generator integrity & inspi at a operating PURs.per 750320 & 21 requests Datalis of inspanincivoding defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 QULLER, K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY,R R Division of Technical Review (NRR-1975 only) 5pp 15645 196 24X Fiche 50-000,82/08/10,8210070007
- B210010316 Ack receipt of 820825 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-24 & 50-251/82-24 DANCE.H C Division of Project & Rusident Programs 02/09/13
 UHRIO.R E Florida Power & Light Co ip 15568 224 24%
 Fichs 50-250, 82/09/13.8210010316
- --8210D10321 Responds to NRC 820726 litr re violations noted in it I*s, Repts 50-250/82-24 & 50-251/82-24 Corrective actions plant manager discussed need for increased control of activities affecting fire barrier penetrations w/const personnel UHRIG, R E Florida Power & Light Co 82/08/25 0'REILLY, J P Region 2. Office of Director 3pp 19568 225 24% Fichs 50-250.82/09/13.8210010316
- --8210010329 Forwards IE Insp Repts 50-250/82-24 & 50-251/82 24 on 820526-0625 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/07/26 UHRIO.R E. Florida Power & Light Co 2pp 15568 228 24 k Fiche 50-250.82/09/13.8210010316
- --8210010338 Notice of violation from insp on 820326-0625 LEWIS.R C Division of Project & Resident Programs C 2pp 15568 230 24X Fiche, 50-250, 82/07/13, 8210010316 02/07/25
- --8210010346 IE Insp Repts 50-250/82-24 & 50-251/82-24 on 820528 0521 Noncompliance noted inadequate corrective action allowed recurrence of reportable condition re failure to adhere to radiation work permit VOOT-LOWELL.R., JULIAN.C Division of Project & Resident Program B2/07/26 App 1556B.232 24X Fiche 50-250.82/07/13.82100101.
- 8208190233 IE Info Notice 80~35. Suppl 1. "Leaking & Dislodged 1-121 Implant Seeds" Syc list enci COBB.C. I. Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co. of New York 66pp 15761 20 82/10/06 Consolidated Edison Co of New York 66pp 15761 2:3 24X Fiche. 50-000, 82/10/06, 8208190233
- 8210220296 Ack receipt of 820927 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-80 & 50-251/82-88
- ---8210220304 Responds to NRC 820826 Itr rs violations noted in 16 I/H
 Repts 00-250/82-28 & 50-251/82-28 Corrective actions access
 log setablished to control access to high radiation areas
 Alarm says installed on Unit 3 RRR pit access gate
 UHRIGAR.E. Florida Power & Light Co 82/09/27 O'REILLY. J &
 Repion 2. Office of Director 2pp. 15776-094. 24X
 Fiche. 50-250,82/10/08,8210220276
- --8210220310 Forwards IE Insp Repts 50-250/82-28 & 50-251/62-28 em 820624-0725 & notice of violation.

 LEWISER, G. Division of Project & Resident Programs 82/08/24 UHRIOR E Floride Fours & Light Co. 2pp 15778-098 24x Fichs: 50-250.82/10/08/8210220294
- --8210220317 Notice of violation from insp on 820624-0725 * Division of Project & Resident Programs. 82/08/26 ip 15776:098. 24% Fiche:50-250,82/10/08,8210220296

- --8210220327 1E Insp Repts 50-250/82-28 & 50-251/82-28 on 820626-0725
 Noncompliance noted on 820701, ground level gates to Unit 4
 RHR pit stairmags.surveyed at dose rates exceeding 1,000,
 found open & unattended
 VGGT-LOBELL, R. JULIAN, C Division of Project & Resident Programs
 82/08/24 Spp 15776 099 24% Fitche 50-250,82/10/08,8210220296
- 8210190351 Advises that util review of current nuclear plant steff working hours indicates that overtime restrictions meet intent of revised NRC policy Requirements incorporated in administrative procedures & need not be added to Tech Specs UHRIO.R E Florida Power & Light Co 82/10/12 EISENHUT.D O Division of Licensing 1p 15742 ill 24X Fiche 50-250,82/10/12.8210190351
- 9208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall. Large-Diameter: Stainless Steel: Recirculation Sys Piping at BUR Plants "Svc list encl DEYOUND: R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp. 15810 125 24X Fiche 50-000.82/10/14.8208190238
- S Reportable occurrences. LERs & related correspondence
- 8210080104 Forwards "Engineering Evaluation of Feedwater Translant & Sys Pips Breat at Turkey Point Unit 3 on 801119," in response to request re Congressman DB Fascell 810129 ltr MICHELBON.C Director's Office 81/03/02 REHM.T A Office of the Executive Director for Operations 1p 15670 001 24X Fiche 50-250.81/03/02/28210080104
- 0210090252 Forwards LER 02-012/01T-0 WILLIAMS,J W Florida Power & Light Co 82/10/01 O'REILLY,J P Region 2, Office of Director 1p 15638 112 24X Fiche: 50-250, 02/10/01, 0210000252
- --8210080257 LER 82-012/017-0 on 820917, insp revealed that electrical penetration did not mest double barrier criteria of 10CFR50 & testability requirements of App J Caused by failure to properly document plant changes Plant change implemented PACE, P L Florida Power & Light Co 82/10/01 Region 2, Office of Director 3pp 15638 113 24X Fiche 50-250,82/10/01.
- 8210260116 Forward» LER 82-013/03L-0 WILLIAMS,JW Florida Power & Light Co 82/10/18 O'REILLY,JP Region 2. Office of Director 1p 15799 105. 24X Fiche 50-230, 82/10/18, 8210260116
- --8210260117 LER 82-013/03L-0 on 820917, steam turbine pressure control valve CV-3707 did not close completely, resulting in poor pressure & causing safety relief valve to trip auxiliary feedwater pump C Caused by foreign matter under valve seat PACE.P.L. Florida Power & Light Co 82/10/18 Region 2. Office of Director 3pp 15799 106 24X Fiche.50-250.82/10/18, 821024014.

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

- F Security, medical, emergency & fire protection plans
- 8209170062 Farwards Revision 6 to physical security plan Revision withheld (ref 10CFR73 21)

 URRIO. R E Florida Fower 5 Light Co 82/09/08. EIBENHUT, D 0

 Division of Licensing 2pp 14910.069 24X Fiche 50-250, 82/09/08, 8209170062
- 8210190178 Releases public version of emergency plan implementing procedure FELTON, J M Division of Rules and Records, 82/09/30. Document Management Branch ip 15758 062 24X Fiche, 50-250, 82/09/30, 8210190178
- --8210190186 Forwards public version of Emergency Pian Implementing Procedures 20104, "Emergency Roster," 20101, "Duties of Emergency Coordinator," 20107, "Fire/Explosion Emergenciee" & 20127 "Duties of Assembly Area Supervisor" UHRTO,R E Florida Power & Light Co 82/09/24 O'REILLY, J P. Region 2, Office of Director ip 15758 069 24X Fiche. 50-250.82/09/30,8210190178.
- --8210190194 Public version of Emergency Flan Implementing Procedures 20101, "Duties of Emergency Coordinator," 20104, "Emergency Roster," 20107, "Fire-Explosion Emergencies" & 20127, "Duties of Assembly Area Supervisor"

 # Florida Power & Light Co 82/09/16 50pp 13758-064 24X Fiche 50-250, 82/09/30,8210190178

- 8210190440 Extends invitation to observe 821019 demonstration of emergency response sys at Technology for Energy Corp.Knoxville.TN
 UHRIG.R E Florida Power & Light Co 82/10/12 EISENHUT, D 0
 Division of Licensing 1p 15741 186 24X Fiche 50-000,82/10/12,8210190440
- 8210280291 Forwards Revision 1 to 10CFR50 App R fire protection review Revision corrects typographical errors in 820701 submittal UHR10.R E Flarida Power & Light 6: 827/10/22 EISENHUT.D 0 Division of Licensing 1p 15838 080 24X Fiche 50-250,82/10/22, R210280291
- --8210280293 Revisian 1 to 10CFR50 App R fire protection review * Florida Power & Light Co 82/10/22 63pp (5838 081 24X Fiche 50-250, 82/10/22, 8210280291
- P Operating license stage documents & correspondence
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request BI-313 Forwards documents listed in App B FELTON.J H Division of Rules and Records B2/0B/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 1945 043 24X Fiche 50-000, 82/08/10, 8210070007
- 8210280013 Responds to FOIA request for all internal non-public documents memos, evaluation repts & other mat1 dealing w/ nuclear plant operations Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/09/17 MCINNIS. D News & Observer 5pp 15860 065 24% Fiche 50-000, 82/09/17. 8210280013
- --B210280100 Notifies that on B20224.C Alderson advised that regt sent re possible willful violation of reporting requirements & falsification of GA & guard quelification records at facilities
 RESHER, H E Office of Inspector & Auditor 82/03/01 Office of Inspector & Auditor 82/03/01 Office of Inspector & Auditor 19 15861 039 24X Fiche 50-000,82/09/17, 8210280013
- 8210030589 Requests submitted of fees for 820606 request for Tech Spec changes re degraded grid voltage & 820810 request for approval of mode to turbine runback sys

 D1008.R M License Fee Management Branch 82/09/23 UHRIO.R E
 Florida Power & Light Co 1p 15626 290 24X Fiche 50-250. 82/09/23, 8210030589
- B210010292 Farwards response to NRC B20219 1tr requesting add1 info re environ qualification of TMT action (tems contained in NURCO-0737 UHRIO,R.E Florida Power & Light Co B2/09/24 VARGA, S A Operating Reactors Branch 1 56pp 15573 125 24X Fiche 50-250.82/09/24,8210010292
- 8210040281 Forwards revised schedule for providing final response re control of heavy loads on Guideline 4 (special lifting devices) & Guideline 7 (crane design) Only manufacturers can obtain requested info UHRIO,R E Florida Power & Light Co 82/09/30 VARGA, & A Operating Reactors Branch 1 2pp 15621 162 24X Fiche 50-250, 82/09/30, 8210060281
- B210150407 Revised application for Amends 87 & 81 to Licenses DPR-31 & DPR-41.respectively.correcting typographical errors re DPR sys
 UHRIO.R E Florida Power & Light Co 82/10/11 EISENHUT.D 9
 Division of Licensing lp 15704 025 24X Fiche 50-250.82/10/11.
 B210150407
- --8210150413 Corrected pages to Tech Specs re DHR sys.reglacing pages in 801230 submittal * Fioride Pawer & Light Co 82/10/11 2pp 15704 026 24X Fiche 50-250,82/10/11.8210150407.
- 8210150439 Advises that review of current status of nuclear power plant staff working hours per Generic Ltr 82-22 indicates requirements adaquately enforced by incorporation in administrative procedures Amend to Tech Bpecs unnecessary UHR10.R E Florida Power & Light Co. 82/10/12 EISENHUT.D 0 Division of Licensing. 1p 15705 004 24X Fiche 50-250.82/10/12, 8210150439
- 8210190559 Forwards payment of proposed license amend fee re redundancy in RHR sys. UHRIG:R E. Florida Power & Light Co 82/10/12 MILLER,# C License Fee Management Branch 2pp 15735 014 24X Fiche.50-250,82/10/12,8210190559

- 8210220090 Advises that procedures/plans submitted for Unit 3 for steam generator repair project apply to Unit 4 & need not be resubmitted UHRIGAR E Florida Power & Light Co 82/50/15 EISENHUT.D G Division of Licensing ip 15778 183 24% Fiche 50-251,82/10/15, R210220090
- 8210270253 Forwards util 821012 ltr containing payment of license amend fee re redundancy in RHR sys requested in NRC 820816 ltr UHRIG.R E Florida Fower & Light Co 82/10/21 DIGGS.R H License Fee Hanagement Branch ip 15828 278 24X Fiche 50-250,82/10/21, 8210270253
- G Inspection reports. IE Bulletins & correspondence
- 82:0070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 83-313 Forwards documents listed in App B FELTON, J H Division of Rules and Records 82/08/10 LONO, D J Hintbrop, Stimson, Putnam & Roberts 9pp 19649 063 24X Fiche 50-000.82/08/10,8210070007
- --8210070137 Forwards tabulared data on steam generator insp & maint at facilities Data should be provided to licensess [PPOLITO.T Operating Reactors Assessment Branch 82/04/01 VAROA.S Operating Reactors Branch 1 5pp 15645 131 24X Fichs SO-000.82/09/10.8210070007
- --8210070172 Forwards info to steam generator integrity & insps at all operating PMRs, per 750020 & 21 requests Details of insps, including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach | GOLLER, K.R. Division of Reactor Licensing (MRR-1975 only) 75/03/24 MACCARY, R.R. Division of Jechnical Review (MRR-1975 only) 5pp 15645 196 24X Fiche 50-000,82/08/10,8210070007
- 8210010316 Ack receipt of 820825 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-24 & 50-251/82-24 DANCE.H C Davision of Project & Resident Programs 82/09/13 UHRIG.R E Florida Power & Light Co lp 15568 224 24X Fiche 30-250.82/09/13.8210010316
- --8210010321 Responds to NRC 820726 ltr reviolations noted in 18 Insp Repts 50-250/82-24 & 50-251/82-24 Corrective actions plant manager discussed need for increased control of activitles affecting fire barrier penetrations w/const personnel UHRIO.R & Florida Power & Light Co 82/08/25 O'REILLY, J P Region 2. Office of Director 3pp 15568 225 24X Fiche 50-250,82/09/13,8210010316
- --B210010029 Forwards IE Insp Repts 50-250/82-24 & 50-251/82-24 on B20526-0625 & notice of viplation LEMIS.R C Division of Project & Resident Programs 82/07/26 UNRIG.R E Fiorida Power & Light Co 2pp 15568 228 24X Fiche 50-250, 82/07/13, 82/00/0316
- --B2:001033B Notice of violation from insp on 820324-0525 LEMIS.R C Division of Project & Resident Programs 82/07/26 2pp 15568 230 24% Fiche 50-250.82/09/13:8210010316
- --B210010346 IE lnsp Repts 50-250/B2-24 t 50-251/B2-24 on 820926-0625 Noncompliance noted inadequate corrective action allowed recurrence of reportable condition re failure to adhere to radiation work permit VOOT-LOWELL, R. JULIAN.C Division of Project & Resident Programs 82/07/26 App 15568 232 24X Fiche 50-250,82/09/13.8210010314
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Syc list encl COSB.L ! Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06.8208190233
- 8210220276 Ack receipt of 820727 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-250/82-80 & 50-251/82-20
 LEVIS.R C Division of Project & Resident Programs 82/10/08 UHR10.R E Florida Power & Light Co ip 15776 093 24X Fiche 50-250.82/10/08.8210220276
- --B210220304 Responds to NRC 820826 ltr re violations noted in IE Insp Repts 50-250/82-28 & 50-251/82-28 Corrective actions access log established to control access to high redistion areas Alarm sys installed on Unit 3 RHR pit access gate UMRIG.R E Florida Fover & Light Co 82/09/27 0'REILLY, J P. Region 2. Office of Director 2pp 15776 094 24X Fiche 50-250.82/10/08.8210220296

- --8210220310 Forwards IE Insp Repts 50-250/82-28 & 50-251/82-28 on 820626-0725 & notice of violation LEMB.R C Division of Project & Resident Programs 82/08/26 URRIG.R E Floride Power & Light Co 2pp 15776-096 24X Fichs 50-250.82/10/08.8210220296
- --8210220317 Notice of violation from lnsp on 820626-0725 * Division of Project & Resident Programs 82/08/26 lp 15776 098 24X Fiche 50-250, 82/10/08,8210220294
- --8210220327 IE Insp Repts 50-250/82-28 & 50-251/82-28 on 820626-0725
 Noncompliance noted on 820701.ground level gates to Unit 4
 RHR pit stalrways. surveyed at dose rates exceeding 1,000.
 found open & unattended
 VMOY-LOMPLL, R. JULIAN. C Division of Project & Resident Programs
 82/08/24 59p 15776 099 24X Fichs 50-250.82/10/08.8210220296
- 8210190351 Advises that util review of current nuclear plant staff working hours indicates that overtime restrictions meet intent of revised NRC policy Requirements incorporated in administrative procedures & need not be added to Tech Specs URRIO, R E Florida Power & Light Co 82/10/12 EISENKUT.D 0 Division of Licensing ip 15742 111 24% Ficher 50-250,82/10/12.
- 9208190238 IE Dulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter; Staintess Steel, Recircolation Sys Piping at BMR Plents " Svc list encl DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Cansolidated Edison Co of New York 1(5pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- S Reportable occurrences, LERs & related correspondence
- 8209210425 Responds to FOIA request for eight categories of LERs Forwards documents listed in App A FELTON.J H Division of Rules and Records 82/08/20 ARROLD.J Hiami Herald 3pp 14946 262 24X Fiche 50-000,82/08/20,
- --B209210527 Forwards draft FR notice re AD pressure transients during shutdown at nuclear power plant for approval pIRCKS.W J Office of the Executive Director for Operations B2/07/29 CHIK.S J Office of the Secretary of the Commission 11pp 14946 353 24X Fiche 50-000.82/08/20.8209210425
- 6210270083 Add1 response to FOIA request for eight categories of LEMs Forwards documents listed in App A App B documents withheld (ref FOIA Exemption 5) FELTON, J H Division of Rules and Records B2/09/20 ARNOLD, J Hiami Herald App 15836 221 24X Fiche 50-251.62/09/20, B2102700B3
- --8210270096 Concurs w/draft Commission paper proposing facility law temp overpressure event as AO DENTON, H.R. Office of Nuclear Reactor Regulation. Director BI/06/16 MICHELSON.C Director's Office 2pp 15836 270 24x Fich
- --B206240119 Requests approval of AO determination re pressure transie while unit shutdown in preparation for startup DIRCKB, W J Office of the Executive Director for Operations SECY-B2-255 82/06/17 10pp 15836 272 24X Fiche 50-251,82/09/20,8210270083
- 8210060209 Forwards LER 82-013/03L-0 HILLIAMB, J W Fiorada Power & Light Ca 82/10/01 O'REILLY, J P Region 2. Office of Director 1p 15614 043. 24X Fich: 50-251:82/10/01.8210060209
- 8210190376 PND-II-82-107 on 821010, unit shut down for scheduled refueling & maint for 6 months, All three steam generators will be replaced Licensee plans news release.
 LANDIS, K. D., UULIAN, C. A. Region 2, Office of Director 82/10/12 15 15740:315 24X Fiche 50-251,82/10/12,8210190376

- DOCKET 50-254 GUAD-CITIES STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8-109290125 Releases public version of revised generating station energency plan corporate command ctr emergency plan implementing procedure FELTQN, J H Division of Rules and Records 82/09/16 Document Hanagement Branch ip 15564 122 24X Fiche 50-000,82/09/16,8200300158
- --8209290189 Forwards public version of Revision 4 to generating station are regency plan corporate command ctr Emergency Plan Inplementing Procedure EOF-3, "Environ/Emergency Coordinator" Receipt form enci PAJOHOKI, J & Commonwealth Edison Co 82/09/01 DENTON, H R NRC No Detailed Affiliation Given ip 15564 123 24X Fiche 50-000,82/09/16,8209290125
- --8209290225 Public version of Revision 4 to generating station energency plan corporate command ctr emergency plan Inplementing Procedure EDF-3, "Environ/Emergency Coordinator "PAJOHSKI, J E Commonwealth Edison Co 82/08/31 11pp 15544 124 24X Fiche 50-000,82/09/16,8209290125
- 82:100:10009 Forwards info to suppl 820701 request for exemption from App R per 820917 telcon Request applies to Sections III 9 2 a 5 III 6 3 b re installation of fire suppression sys RAUSCH, T J Commonwealth Edison Co 82/097/23 EISENHUT, D 9 Division of Licensing 8pp 15565 152 24X Fiche 50-000,82/09/23,82:100:10009
- G210120546 Releases public version of revised cover sheet to facility procedures
 FELTON.J M 3):vision of Rules and Records 82/09/24 Document Hanagement Branch 1p 15672 219 24X Fiche 50-254,82/09/24.
 82:0120546
- --0210120551 Forwards public version of revision cover sheet to facility procedures Completion of enc] checklist requested MALIVIANAMIS,N Commonwealth Edison Co 82/09/15 DENTON,H R Office of Nuclear Reactor Regulation, Director App 15472 220 24X Fiche 50-254,82/09/24,8210120546
- 8210150487 Forwards IE Insp Repts 50-254/82-i4 & 50-265/82-i6 on 820823-22 & 0903 & 09 No noncompliance noted MEPPLER.J G Region 3, Office of Director 82/09/30 REED, C Commonwealth Edison Co 3pp 15721 289 24X Fiche 50-294.82/09/30, 8210159487
- --B2I0180495 IE Insp Repts 50-254/82-14 & 50-265/82-16 on B20823-25 & 0903 & 09 No noncompliance noted Hajor areas inspected emergency preparedness exercise & Ilionsee actions on previously identified emergency preparedness items PHILLIPS.N P. SHITH.N J. AXELSON.W L. Division of Emergency Preparedness & Operational Support B2/09/29 15pp 15721 292 24X Fiche 50-254.82/09/30.8210180487
- 8210130376 Advises that installation of offsite dose calculation sysphogram fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation

 5WARTZ.E D Commonwealth Edison Co 82/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15682 098 24X

 Fichs 50-000.82/10/06.8210130376
- 8210270047 Releases public version of revisions to Quad Cities.Zion & Dreaden emergency plan annexes & revised generating station emergency plan telephone directory FELTON:J H Division of Rules and Records 82/10/08 Document Management Branch ip 15877 313 24X Fiche 50-000.82/10/08, 8210270047
- --82i0290060 Forwards public version of Revision 3 to Quad Cities & Zipn emergency plan annexes.Revision 2 to Dresden emergency plan annex. Revision 0 to Buron emergency plan annex & revised generating station emergency plan telephone directory MODRE.R D Commonwealth Edison Co 82/07/30 DENTON.H R NRC No Detailed Affiliation Given 5pp 15877 314 24X Fiche 50-000.82/10/08.8210270047
- --B2t0250077 Public version of Revision 3 to Guad Cities & Zion amergency plan annexes. Revision 2 to Dresden emergency plan annex & Revision 0 to Byron emergency plan annex « Commonwealth Edison Co B2/06/30 325pp 15877 319 24X Fiche 50-000, 82/10/08.8210290047.
- -- B2102900BB Public version of revised generating station emergency plan telephone directory GALLE.O.P. Commonwealth Edison Co. 82/08/12 43pp 19878 218 24X Fiche 50-000.82/10/08,8210290047

- 8210190753 Forwards 820722 itr re late submittals of exercise scenarios & failure to adhere to FEMA Ouidance Memo 17 If FEMA does not observe exercise, offsite authorities will not participate HIND. J A Division of Emergency Preparedness & Operational Support 82/10/12 REED. C Communumenth Edison Co 2pp 15736 247 24X Fiche 50-254.82/10/12,8210190753
- --8210190760 Discusses concerns reliate submittals of emergency exercise scenarios & failure to adhere to FEMA Guidance Memo 17
 Future exercise not meeting intent of advance notification guidance should be postponed or canceled
 BREHENY.P J Federal Emergency Management Agency 82/09/22
 KEPPLER.J G Region 3. Office of Director ip 15736 249 24X
 Fiche 50-254,82/10/12,8210190753
- 8210280361 Releases public version of revised emergency plan implementing procedures FELTON. JM Division of Rules and Records 82/10/12 Document Management Branch 1p 15059 204 24X Fiche 50-254, 82/10/12, 8210280361
- --B210280364 Forwards public version of revised emergency plan implementing procedures including Procedures GEP 200-0 re emergency conditions GEP 200-11 re emergency action levels & GEP 330-3 re SFING control terminal operation KDVACK.T 8 , GERNER.L F Commonwealth Edison Co 82/09/23 DENTON.H R NRC No Detailed Affiliation Given 2pp 15859 205 24X Fiche 50-254.82/10/12.8210280361
- --8210280375 Public version of revised emergency plan implementing procedures, including Procedures GEP 200-0 re emergency conditions, GEP 200-T1 re emergency action levels & GEP 330-3 re SPIN9 control terminal operation a Commonwealth Edison Co. 82/09/23 2ipp 15859 207 24X Fiche 50-254,82/10/12-821028036
- 8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs RAMM.T R Commonwealth Edison Co 82/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 15776 287 24X Fiche 50-000, 82/10/14, 8210220358
- 8210250309 Responds to 820917 telcon request for info re fire protection safe shutdown rept Items 2 & 3 are preliminary results, subj to revision following engineering review RAUSCH.T J Commonwealth Edison Co 82/10/18 EISENHUT.D 0 Division of Licensing App 15790 215 24% Fiche 50-254,82/10/18,8210250309
- P Operating license stage documents & correspondence
- 8210050142 Requests that charcoal adsorber F64-DY#2 be counted within 2 wks of receipt decay corrected to 790317 lavels & returned Liquid beta analyses results received in NRC 820917 ltr will be incorporated in rept addendum PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/09/28 KALIVIANAKIS, N Commonwealth Edison Co 1p. 15605 167 24% Fichs 50-254.82/09/28, R210050142
- 8210120105 Requests delay of implementation due dates re NUREG-0737, Items II B 2. "Plant Shielding." II B 3. "Post-Accident Sampling" & II F 1 i. "Noble Qas Effluent Honitor "SHARTZ,E D Commonwealth Edison Co 82/10/04 EISENHUT,D Q Division of Licensing 5pp 15651 237 24X Fiche 50-000,B2/10/04, 8210120105
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual." ODLDEM, J. C. Commonwealth Edison Co. 82/10/06 CASE, E. G. Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche: 50-000, 82/10/06, 8210260526
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dase Calculation Hanual" + Commonwealth Edison Co 82/09/30 83pp i5805:139 24X Fiche 50-000,82/10/06.8210260526
- 8210180059 Provides add1 guidance & ciarification re 820806 request for add1 info per NUREG-0737, Item II B 3, "Post-Accident Bampling Bys " Detailed reliability analysis not required to satisfy NRC concerns CRUTCHFIELD.D Operating Reactors Branch-5 82/10/08 DELGEORGE, L Commonwealth Edison Co 3pp 15720 004 24X Fiche: 50-000, 82/10/08, 8210 180059

- 8210190780 Forwards "OE SHR Extended Load Line Limit Analysis for Quad Cities Nuclear Power Station Unit 1, Cycle 7 & Unit 2, Cycle 6" RAUSCH, T J Commonwealth Edison Co 82/10/12 EISENHUT, D 0 Division of Licensing 1p 15736 206 24X Fiche 50-254,82/10/12,0010180780
- --8210190785 "GE BWR Extended Load Line Limit Analysis for Ovad Cities Nuclear Power Station, Unit 1. Cycle 7 & Unit 2. Cycle 6 " 4 General Electric Co NEDD-22192 82/07/31 31pp 15736 207 24X Fiche 50-234, 82/10/12.8210190780
- 8210190445 Forwards supplemental response to Generic Ltr B2-05 re implementation status of NUREQ-0737, Items 11 B 3,11 F 1 2, 11 F 1 5 & 11 F 1 4, in response to B21004 request SHARTZ.E D Commonwealth Edison Co B2/10/14 EISENHUT.D G Division of Licensing 5pp 15741 202 24X Fishe 90-000, 92/10/14, 8210190445
- 8210250114 Application for amend to License DPR-29, changing safety relief actuating setpoint of Target Rock valve to 1.135 psig 5 changing setpoint of two electromatic relief valves to 1.115 psig RAUSCH.T J Commonwealth Edison Co 82/10/18 DENTON, K R Office of Nuclear Reactor Regulation, Director 3pp 19787 032 24X Fichs 30-254, 82/10/18, 8210250114
- --8210250126 Proposed changes to Tech Specs changing safety relief actuating setpoint of Target Rock valve to 1,135 psig & setpoint of two electromatic relief valves to 1,115 psig * Commonwealth Edison Co 82/10/18 3pp 15787 035 24X Fiche 50-254,82/10/18,8210250114
- 8210250155 Forwards corrections to proposed Tech Spec Pages 1 2/2 2-1 & 3 3/4 3-5, supporting review of future reloads & revised Figure 3 5 1. Sheet 1, providing extended MAPLHOR vs exposure curves for barrier lead test assembly fuel RAUSCH. T J Commonwealth Edison Co 82/10/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15788 233 24X Fiche 50-000, 82/10/18, 8210250155
- --8210250169 Revised proposed Tech Spec Pages 1 2/2 2-1 & 3 3/4 3-5, supporting review of future releads & revised Figure 3 5 1, Sheet i,providing steended MAPLHGR vs exposure curves for barrier lead test assembly fuel Supersedes 820819 version * Comeonwealth Edison Co 82/10/18 4pp 15788 235 24X Fichs 50-000,82/10/18,8210250155
- --8210250177 Errata & Addenda Sheet B. replacing Page 4-10 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations"

 > General Electric Co NEDO-24146A ERR 08 82/09/30 3pp 15788 239 24X Fiche 50-000, 82/10/18,8210250155.
- 8210250069 Provides add1 info re reactor water cleanup room area temp monitors Temp elements cause no automatic plant response beyond control room alarma RAUSCH.T J Commonwealth Edison Co 82/10/19 EISENHUT.D O Division of Licensing 2pp 15787 081 24X Fiche 50-000,82/10/19,82102280069
- Q Inspection reports. IE Bulletins & correspondence

1.

11 1

- 8210150487 Forwards IE Insp Repts 50-254/82-14 & 50-265/82-16 on 820823-25 & 0903 & 09. No noncompliance noted KEPPLER, J Q Region 3. Office of Director 82/09/30 REED, C Commonwealth Edison Co 3pp 15721 289 24X Fiche 50-254, 82/09/30, 8210150487
- --6210150495 IE Insp Repts 50-294/82-14 k 50-265/82-16 on 820823-25 k 0903 k 09 No noncompliance noted Major areas inspected emergency preparedness exercise k licensee actions on previously identified emergency preparedness items PHILLIPB M P . SHITH M J . AKELSON W L Division of Emergency Preparedness & Operational Support 82/09/29 15pp 15721 292 24X Fiche 50-254,82/09/30,8210150487
- 8210060359 Ack receipt of 820910 ltr informing NRC of steps taken to correct violations noted in iE Insp Repts 50-237/81-39, 50-2497/81-32, 50-254/81-23, 50-265/81-23, 50-2697/81-31 & 50-304/81-29 SPEESARD, R L Division of Project & Resident Programs, REED, C. Commonwealth Edison Co 1p, 15618 354 24X Fiche: 50-000, 82/10/01, 8210060399
- --8210060367 Responds to NRC 820712 ltr reviolations noted in IE Insp. Repts 50-237/81-39, 50-249/81-32, 50-254/81-33, 50-2565/81-23, 50-299/61-31 & 50-394/81-29, Corrective actions training for mgt priorities re plant availability will be conducted REED. C. Commonwealth Edison Co. 82/09/10 KEPPLER, J. 0 Region 3, Office of Director 13pp 15618, 355 24X Fiche 50-000, 82/10/01, 8210060359.

- 8210080178 Forwards listing of piping sys which fail to meet FBAR requirements, per NRC 800B18 confirmatory action ltr IE Bulistin 79-14 operability evaluation updates will not be provided for Dresden & Quad Cities Final update by Dec 1902 RAUSCH.T J Commonwealth Edison Co 82/10/01 KEPPLER.J Q Regir J. Office of Director Opp 15640 157 24X Fiche 80-000,82/10/01.8210080178
- 8210080190 Confirms B21103 enforcement conference at Region 3 ofters aspects associated w/procurement.installation & use of non-qualified valve guides in electromagnetic relief valves at facilities
 SPESSARD, R L. Division of Project & Resident Programs 82/10/04 REED. C. Commonwealth Edison Co. 1p. 15640-181 24x
 Fichs 50-000.82/10/04,8210080190
- 820B190233 IE Info Notice 80-35. Suppl 1, "Leaking & Dislodged 1 (2) Implant Seeds " Svc list enc! COBB.L I Division of Fuel Facilities. Materials & Safeguarda 82/10/06 Consolidated Edison Co of New York 66pp 15761 2"J 24X Fiche 50-000.82/10/06.8208190233
- B208190238 IE Builletin 62-03. "Stress Corrosion Cracking in Thick Wall, Large-Diameter, Stainless Steel, Recirculation 8ys Fiping at 84R Plants "Svc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement 92/10/14 Consolidated Edison Co of New Yor) 115pp 15810 128 24X Fiche 50-000, 82/10/14, 8208190238
- R Periodic operating reports & related correspondence
- 8210130386 Forwards monthly operating repts for Bept 1982 RALIVIANAKIS,N Commonwealth Edison Co 82/10/01 Director s Defice: Defice of Inspection and Enforcement 1p 15680 139 20 Fiche 50-234, 82/10/01,0210130386
- --8210130390 Monthly operating repts for Sept 1982 BUSS.R D Commonwealth Edison Co 82/10/04 13pp 13600 (14) 24% Fische 50-254, 82/10/01, 8210130386
- S Reportable occurrences, LERs & related correspondence
- 8011060561 Discusses facility 770103 loss of air event & effect on scram capability Conservative analysis of data indicates short operator response time Immediate scram on loss of control rod driveline air header should be required LANIK. © Director's Office 80/10/20 HICHELERUN. © Director's Office 80/10/20 HICHELERUN. © Director's Office 80/10/20 HICHELERUN.
- -8011060565 Forwards senior resident inspector 800829 memb re effect of facility 770103 loss of air event & its effect on scram capability KEPPLER.J O Region 3. Chicago, Office of the Director 90/u7/2 MICHELSON.C Director's Office ip 15692 271 24X Fiche 50-254,80/10/20.8011060561
- --B01106056B Discusses facility 770103 loss of air ovent & effect as scram capability Event indicates that scram discharge vol. aithough filled to approx 59% capacity, was capable of accepting vol of water to shut down reactor safely CHRISSOTIMOS, N Region 3, Chicago, Office of the Director B0/08/29 SPEEBSARD, R L Region 3, Chicago, Reactor Operations Nuclear Support Branch 2pp 15692 272 24% Fiche 50-254,80/10/20,8011060561
- 8210060395 Forwards LER 82-026/03L-0
 KALIVIANAKIS, N Commonwealth Edison Co 82/09/27 KFPFilR, J
 Region 3. Office of Director ip 15616 017 24X
 Fiche 50-254,82/09/27,8210060395
- --B210060405 LER B2-026/03L-0 on B20906, flange seal gastet leat valt found exceeding 30 BCFH & possibly exceeding Tach Spec limit of 36 72 BCFH for double-gastet seals Caused by seal gastet deterioration Gastet to be repaired/replaced MENDENHALL, E E Commonwealth Edison Co 82/09/27 Region 3. Office of Director ip 15616 018 24X Fiche 50-254,82/09/27. B210060395.
- 8210130324 Forwards LER 82-027/01T-0
 KALIVIANAKIS.N Commonwealth Edison Co 82/09/28 KEPPLER, J
 Region 3. Office of Director 1p 15678 292 24X
 Fiche 50-254.82/09/28.8210130324
- --8210130328 LER 82-029/017-0 on 820916, two small cracks found in heat affected some of welds 128-F9 & F10 of reactor water cleanup sys piping Caused by stress corrosion Piping to be replaced w/stainless steel pipe & fittings prior to startup WILQUE,D Commonwealth Edison Co 82/09/28 Region 3- Offset of Director, 4pp 13678 293, 24X Fiche 50-254.82/09/20, 8210130324.

DOCKETED ITEMS

- E210130413 Forwards LER 82-027/03L-0

 VALIVIANAKIS.N Commonwealth Edison Co 82/09/29 KEPPLER, J
 Region 3. Office of Director 1p 15680 243 24X

 fiche 50-254.82/09/29.8210130413
- --B210130423 LER 82-027/03L-0 on B20902 electromagnetic relief valve main valve guides & piston rings inadvertently ordered as nonsafety-related Caused by inadequate implementation of procurement requirements frocedures revised TIETZ. G Commonwealth Edison Co B2/09/28 Region 3, Office of Director ip 15680 244 24X Fiche 50-254.82/09/29,8210130413
- 8210130501 Forwards LER 82-025/03L-0

 KALIVIANAKIGAN Commonwealth Edison Co 82/09/29 KEPPLER, J
 Region 3. Office of Director 1p 15682 189 24X

 fithe 50-254.82/09/29.8210130501
- --0210130511 LER 82-025/03L-0 on 020707.1/2A standby gas treatment train heater found tripped during Procedure QDP 020-1 Caused by conservative switch setting due to inadequate setpoint differences Heater trip reset LIHOU.H Commonwealth Edison Co 02/09/27 Region 3. Office of Director 3pp 15602 190 24x Fiche 50-254.02/09/29.0210130501
- S2L0130251 Forwards LER 92-031/03L-0 KALIVIANAKIS, W. Commonwealth Edison Co. 82/09/30 KEPPLER, J. Region 3. Office of Director ip 15678 094 24X Fiche 90-254, 82/09/30, 8210130251
- --0210130253 LER 02-031/03L-0 on 820905.RCIC sys taken out of svc to uncouple turbine from pump Caused by need to perform scheduled turbine overspeed surveyilance test LHMUV.H Commonwealth Edison Co. 82/09/30 Region 3, Office of Director ip 15678-095 24X Fiche 50-254.82/09/30,8210130251
- 3210130466 Forwards LER 82-032/03L-0 PALIVIANAKIS.N Commonwealth Edison Co 82/09/30 KEPPLER, J Region 3. Office of Director ip [5602 136 24X Fithe 50-254.82/09/30.8210130466
- -8210130473 LER 82-032/03L-0 on B20905.tHPCI removed from svc w/o actuation of electromatic relief valves Caused by need to perform scheduled turbing overspeed surveillance test HPCI sys will be tested operable upon return to power LHCU.H Commonwealth Edison to B2/09/30 Region 3, Office of Director Ip 15682 137 24X Fiche 50-254,82/09/30.6210130466
- P210130192 Forwards LER 82-030/03L-0

 KALIVIANAKIS.N. Commonwealth Edison Co. B2/10/01 KEPPLER, J @

 Region 3. Office of Director (p. 15674 100 24X

 Fiche 50-254.82/10/01.8210130192
 - 8210130176 LER 82-030/03L-0 on 820705, while testing RHR svc water pump 1-1001-650, packing found burned Caused by excessive tightening in packing to limit leakage Mods installed to protect bearings from seal leakage SCHNITZMEYER. J Commonwealth Edison Co 82/07/05 Region 3, Office of Director 3pp 15674 101 24X Fichs 50-254,82/10/01,6210130192
- 210190658 Forwards LER 92-020/03L-0 MALIVIANAKIE: N. Communeatth Edison Co. 82/10/04 KEPPLER, J Q Rogion 3. Office of Director 1p. 15737 267 24X Fiche 30-254.82/10/04.8210190658
- -8210190700 LER 82-020/03L-0 on 820920 & 21.RCJC area high temp isolation 015-28.3 switches 1-1360-14A.1-1360-178 & 1-1360-16C. would not trip Cause not specifically determined Failed switches returned to manufacturer for analysis PREUSS.M Commonwealth Edison Co 82/10/04 Region 3, Office of Director 3pp 15737 268 24% Fiche 50-254.82/10/04.82/10/9058
- 210250148 Forwards supplemental LER 82-022/03L-1
 KALIVIANAKIS, N. Commonwealth Edison Co. 82/10/07 KEPPLER, J. G. Region S. Office of Director ip 15787 360 24X
 Fishe 50-254, 82/10/07, 8210250148
- -8210250153 Supplemental LER 82-022/03L-1 on 820816, maint outage for 1/28 diesel fire pump exceeded 7-day limit Cause not stated Diesel pump wear rangs replaced LHOU.H Commonwealth Edison Co 82/10/07 Region 3, Office of Director ip 15787 361 24X Fiche 50-254,82/10/07,8210250148
- 210260467 PND-III-82-112 util notified that high density fuel storage racks installed do not meet design criteria for spacing due to bouing condition Handfacturer resanalyzed seismic response of racks & concluded bowed distance acceptable GROBE. J. WALKER, R. STREETER, J. Replon 3. Office of Director 82/10/18, 191806 237 24X Fiche 50-254, 82/10/18, 8210260467

- DOCKET 50-255 PALISADES MUCLEAR PLANT

 F Security, medical, emergency & fire protection plans
- 8210050302 Updates status & schedule for responses to NUREG-0737. Items I D 2. "Plant Safety Parameter Display Console" & III A 2. "Improving Licenses Emergency Preparedness Long-Term "JOHANGON: B D Consumers Power Co 82/09/30 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15602 359 24% Fiche 30-285. 82/09/30. 8210050302
- 8210280058 Releases public version of revised emergency plan FELTON, J M Division of Rules and Rocards 02/10/08 Document Management Branch Ip 15862 (24 24X Fiche 50-255, 82/10/08, 8210280058
- --8210280061 Forwards public version of Revision I to emergency plan * Consumers Power Cp 82/09/24 NRC - No Detailed Affiliation Qiven 2pp 15862 125 24X Fiche 50-255.82/10/08.8210280058
- --8210280063 Public version or Revision 1 to emergency plan RANY, J. Consumers Power Co. 82/09/14 105pp 15862 127 24X Fiche 50-255, 82/10/08, 8210280058
- 8210280107 Submits response to NRC questions re util 820701 fire protection submittal JGHNSDN,8 D Consumers Power Co 82/10/25 CRUTCHFIELD,D Operating Reactors Branch 5 3pp 15837 191 24X Fiche 50-255,82/10/25,8210280107

G Adjudicatory correspondence

- 8210190480 Requests assistance in representing Great Lates Energy Alliance in steam generator replacement proceeding Author deeply involved in Midland proceeding SIRCLAIR.M Great Lakes Energy Alliance B2/10/04 GARDE. @ O
- 8210080082 Motion for indefinite continuance of proceeding Need for steam generator replacement alleviated due to better than expected corrosion performance of steam generator tubes. Future rate of corrosion unpredictable U/Certificate of Svc STEPTOE, P. P. Consumers Power Co. STEPTOE, P.P. Isham, Lincoln & Beale 82/10/05. Atomic Bafety and Licensing Roard Panel App. 15640 205 24% Fiche 50-259, 82/10/05.8210080082
- 9210080099 Notice of appearance in proceeding STEPTOE.P.P. Consumers Power Co. STEPTOE.P.P. Isham, Lincoln & Beale 82/10/05 ip 15440 275 24x Fichs 50-256,82/10/05, 8210080099
- B2102700B7 Response to applicant B21005 motion for indefinite continuance NRC does not object to motion Certificate of Byc encl
 BARTH.C A Hearing Branch 1 82/10/25 Atomic Gafety and Licensing Board Panel 2pp 13822 338 24X Fiche 50-255.82/10/25, 8210270087
- P Operating license stage documents & correspondence
- 8210120033 Ack receipt of 820830 application proposing Tech Spec changes re EBF filtration sys Application provides supplemental info to 750306 pre-fee application to add) fee required Refund of 820803 application fee authorized MILLER, W O License Fee Management Branch 82/09/23 VANDEMALLE, D J Consumers Power Co. 1p 15689-202 24X Fiche 50-205,82/09/23,8210120033
- 8210050072 Discusses 820208 finel assessment rept for 8EP Topic IX-4, "Boron Addition Bys " Check valves 3408,3409 & 3410 should be added to Tech Spec Table 4 3 i Response requested within 45 days CRUTCHFIELD, D. Operating Reactors Branch 5 82/07/27 VANDEWALLE, D J Consumers Pawer Co 2pp 15403 186 24K Fiche 50-255,82/09/29,8210050072
- 8210070013 Forwards draft "Offsite Dose Calculation Manual" for facilities VANDEWALLE, D. J. Consumers Power Co. 82/09/27 CRUTCHFIELD, D. Operating Reactors Branch 9 ip. 19628 222 24X Fiche 50-000, 82/09/29, 8210070013
- --8210070018 Draft "Offsite Dose Calculation Manual," Falisades Plant Consumers Power Co 82/09/24 55pp 15628 276 24X Fiche. 50-000, 82/09/29, 8210070013

- 8210030265 Confirms that auxiliary feedwater ays mod provides for pumps P-8A 2 P-8C to be loaded on emergency diesal generators upon loss of offsite power JOHNSON-B D Consumers Power Co 82/09/30 CRUTCHFIELD, D Operating Reactors Branch 3 lp 18610 283 24X Fiche 50-255, 62/09/30, 8210050265
- 8210050302 Updates status & schedule for responses to NUREQ-07:37, Items I D 2. "Plant Safety Parameter Display Console" & III A 2. "Improving Licenses Emergency Preparedness Long-Term " JOHNSON.B D Consumers Pawer Co 62:707:30 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 15602 359 24X Fishe 50-255, 82/097:30, 8210050302
- 8210120078 Submits info re failure of control rod to fully insert during testing in hot shutdown condition Locking paw & pin, piston guido tute, rack assumbly & brvel garn housing replaced All defective uncoupling tools removed from svc UOHNSGIR, B D Consumers Pawer Co 82/10/06 CRUTCHFIELD, D Operating Reactors Branch 5 App 15551 246 24X Fiche 30-255, 82/10/06, 8210120078
- 8210120323 Formards suppl to safety evaluation of EEP Topics 11-3 A. II-3 S & II-3 C reanalyzing design basis surge level for facility Unresolved differences now considered acceptably resolved & topic reviews complete MAMBACH.T V Operating Reactors Branch 5 82/10/07 VANDEMALLE, D J Consumers Power Co. 5pp 15653 033 24X Fiche 50-235, E2/10/07, 8210120323
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820909 itr Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface KACICHAR M SEP Owners Group 82/10/07 EISENHUT.D 0 Division of Licensing 7pp 15682 179 24% Fiche 50-000, 82/10/07,8210130326
- 8210190110 Provides addl guidance re purpose of NRC 820630 request for addl info concerning NUREQ-0737. Item II. 0 3 re post-accident sampling sys CRUICHFIELD. D Operating Reactors Branch 5 82/10/07 VANDEWALLE. D J Consumers Power Co 3pp 15719 319 24X Fiche: 50~255, 82/10/07, 8210180110
- 0210130334 Forwards evaluations of open items identified in NRC 020212 ltr rs SEP Topic 11I-7 B, "Dasign Codes.Design Criteria & Load Combinations." per util 620817 commitment Code change will not affect safety margin of plant structures VANDENALLE.D J Consumers Power Co 82/10/08 CRUTCHFIELD.D Operating Reacture Branch 5 12pp 15679 i40 24% Fiche 50-235.82/10/08.0210130334
- 8210170459 Forwards current status of program to evaluate adequacy of overload & short-circuit protection for electrical circuits that pass through reactor containment per BEP Topic VIII-4 "Electrical Penetrations of Reactor Containment"

 TONER. N. A. Consumers Power Co. 82/10/12 CRUTCHFIELD, D. Operating Reactors Branch 5 21pp 19740 268 24X Fichs 50-000, 82/10/12, 82/10/70459
- 8210190935 Forwards summary of actions taken to address specific 820412 draft NUREO-0820 concerns re-eccentric loads & valve functionability in small bore piping Summary of plans to perform addi analysis on control valve CV-3003 encitons Rr. A. Consumers Power Co. 82/10/13 CRUICHFIELD, D. Operating Reactors Branch 5 Sipp 15751 255 Q4X Fichs 50-255,82/10/13,8210190535
- 8210190546 Summarises status of util commitment re 8EP Topic IX-3,
 "Station Svc & Cooling Mater Eys " Analysis verifying that
 component cooling water tamp limits are not exceeded under
 postulated conditions will be submitted by 82115
 TONER.K A Consumers Power Co 82/10/15 CRUTCKFIELD.D Operating
 Reactors Branch 5 2pp. 15751.361. 24X Piche 50-255,82/10/15,
 8210190546
- B210220186 Provides add1 info re control room toxic chamical analysis & self-contained breathing apparatus in response to NUREO-0737, Item III.D 3 4 on contol room habitability.per 820720 request JOHNSON, B D. Consumers Power Co 82/10/19, CRUTCHFIELD, D. Operating Reactors Branch 5, 9pp. 19777.284, 24% Fiche 50-255, 82/10/19, 8210220186
- 8210240179 Responds to 820817 request for removal of administrative limit on auxiliary feedwater flow rate to ateam generator. Limits discussed in NRC 801001 immediate action it no longer appropriate New flow rates should be established. KEFFLER: U.O. Region G. Office of Director. 82/10/20, JCHNSON, B D Consumers Power Co. 1p. 15799:036 24X Fichs: 50-255, 82/10/20, 8210230179.

- 8210280276 informs of new commitment dates for NUREC-0737. Items if F 1 1,11 F 1 2,11 F 1 3,11 F 1 4 & 11 B 3 UPHNSON. I D Consumers Power Co 82/10/25 CRUTCHFIELD. D Operating Reactors Branch 5 3pp 15837 304 24X Fiche 50-255,82/10/25,82(0280276
- O Inspection reports. IE Bulletins & carrespondence
- B2100B0015 Add1 response to FQIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FQIA Exemption 5) FELTON.J M Division of Rules and Records B2/07/12 UQELL,R A Critical Mass Energy Project 9pp 15465 027 24X Fiche 50-040.82/07/12,82100B0015
- --E210080144 Systematic assessment of I(censee performance notes re facility evaluation for 790901-800901 # NRC - No Detailed Affiliation Given 80/09/01 10pp 11688 015 24% Fithe 50-000.82/07/12.8210080015
- 8210070007 Responds to FOIA request for eight categories of records ; a steam generators & steam turbines App A documents provided in R Udell FOIA Request Bi-313 Forwards documents listed in App B FELTON.J M Division of Rules and Records B2/09/10 LONO.D J Hinthrop, Etimson, Putnem & Roberts 9pp 15649 063 24X Fiche 80-000-82/08/10.8210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PWRs.per 750320 & 21 requests Details of insps. including defect indications.tube plugging criteria & tubes glugged will not be provided except for Point Beach i OCLLER.K R Division of Reactor Licensing (NRR-1975 analy) 75/03/24 MACCARY.R R Division of Fechnical Review (NRR-1975 analy) 5pp 19645 196 24X Fiche 50-000.82/09/10.8210070007
- 82:0190421 Forwards IE Insp Rept 50-255/82-20 during Aug 1982 & notice of violation STREETER, J F Division of Project & Resident Programs 82/09/29 DEWITT. R B Consumers Power Co 2pp 19741 034 24X Fiche 50-255,82/09/29,8210190421
- --8210190427 Notice of violation from insp during Aug 1982 STREETER.J F Division of Project & Resident Programs Ip 19741 003 24X Fiche 50-255.82/09/29.8210190421
- ~-8210190449 IE Insp Rept 50-255/82-20 during Aug 1792 Moncompliance noted on 820931 BBA Sequences Test Procedure T-157 revised during implementation & new steps involving bypass of sefety functions performed w/o permission of shift supervisor JORGENSEN, B. L., HELLER, J. K., REYEG, L. A. Division of Project & Resident Programs 62/07/29 7pp 15741 037 24X Fiche 50-255/82/09/29, 821019042i
- 8210190699 Forwards IE Mgt Meeting Rept 50-255/82-21 on 820908 No mancompliance noted KEPPLER.J O Region 3. Office of Director 82/10/04 DENITT.R 8 Consumers Power Go 2pp 15737 276. 24X Ficha 50-255.82/10/04. 8210190699
- --8210190707 IE Mgt Meeting Rept 50-255/82-21 on 820909 No honcomply noted Major areas discussed current status of util program for meeting requirements of 810309 confirmatory order regulatory improvement program
 JDROENSEN, B. L., SPESSARD, R. L. Division of Project & Regident Programs 82/10/01 3pp 15737 278 24X Fiche 50-255,82/10/, 8210190699.
- B208170233 IE info Notice 80-35, Suppl i. "Leaking & Dislodged [-12: Implant Beeds." Syc list encl.
 COSB,L. I Division of Fuel Facilities, Materials & Bafeguards
 B2/10/05 Consolidated Edison Co of New York 56pp 13761 2
 24X Fiche 50-000.82/10/06.8208190233
- 8208190238 IS Sulletin 82-03, "Stress Corrosion Cracking in Thict-Wall, Large-Dlamster, Stainless Steel, Recirculation Sys Piping at BWR Plents," Svc list encl DEYQUNO, R C Director's Office of Inspection and Enforcement, 82/10/14, Consolidated Edison Co of New Yer 115pp 15810:123, 24% Fiche, 50-000, 82/10/14, 8208190238
- 8210260176 Ack receipt of supplemental 820727 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/82-07
 NORELIUS, C.E. Division of Engineering & Technical Propress, 82/10/18, DEWITT, R.S. Consumers Power Co. ip. 15797 643 24 Ficher 50-255, 82/10/18, 8210260176.

- --8210260183 Supple response to NRC 820412 ltr re violations noted in IE insp Rept 50-295/82-07 Corrective actions NBS-traceable hydrometer received & compared w/hydrometers used for squre(illance Calibr results enci JOHNBON, B D Consumers Power Co 82/09/29 KEPPLER, J O Region 3. Office of Director 2pp 15799 046 24X Fiche 50-255, 82/10/18, 8210260176
- Periodic operating reports & related correspondence
- P210130138 Forwards monthly operating rept for Sept 1982

 KENNEDY.D II Consumers Power Co 82/10/08 NRC No Detailed

 Affiliation Given Ip 15673 090 24X Fiche 50-255,82/10/08.
- -8210130145 Monthly operating rept for Gept 1982 PETERSON, D. A., VANDENBERG, D. Consumers Power Co 15673 091 24X Fiche 50-255, 82/10/08,8210130138 82/10/04 499
- Reportable occurrences. IFRe & related correspondence
- 1210150146 Forwards LER 81-011/03L-0 HDFFMAN, D.P. Consumers Power Co. 81/03/27 KEPPLER, J.Q. Region 3, Chicago. Dffice of the Director (81/03/01) ip 15697 083 24X Fiche 50-255,81/03/27,8210150146
- -8210150152 LER 81-011/03L-0 on 810304, diesei generator i-i overspeed & low air pressure alarms actuated & would not reset after 16 cylinder leak test Caused by broken micro-switch due to high impact resulting from improper use of trip lever = Consumers Power Co 81/03/27 Region 3, Chicago, Office of the Director (81/03/01) ip 15697 084 24X Fiche 50-255,81/03/27,8210150146
- 210070415 Discusses abnormal wear encountered on ALOYCO swing check valves installed in low pressure safety injection sus IE should issue info notice to inform licensees of problem MICHELSON. C. Director's Office 81/12/23 DEYOUND, R.C. Director's Office. Office of Inspection and Enforcement 5pp 15637-327 24X Fiche 50-255.81/12/23.8210070415
- 210010008 Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents
 listed in App A
 FELTON, J M Division of Rules and Records 82/06/28 UDELL, R, A
 Critical Mass Energy Project 15pp 15727 005 24X
 Fiche 50-000,82/06/28,8210010008
- -8201200453 Recommends issuance of info notice to inform licensess of problems w/ALOVCO swing check valves as encountered at facility Abnormal wear reported in LER 81-037 MICHELSON, C Director's Office 81/12/23 DEYOUNG, R C Director's Office 0ffice 81/12/23 DEYOUNG, R C Director's Office 081/081010008 15702 076 24% Fiche 50-000, 82/06/28.8210010008
- 210050213 Forwards LER 82-026/03L-0 JQHNSON.8 D Consumers Power Co 82/09/29 KEPPLER.J O Region 3, Office of Director 1p 15615 097 24X Fiche 30-235.82/09/29, 8210050213
- -8210050214 LER 82-026/03L-0 on 820901. determined that four fire doors elucabels LER 82-026/031-O on 920901 determined that four fire domined by Pratective Matis Co not documented to confirm testing & approval by mationally recognized lab Caused by vandor failure to obtain certification following mods \$2,007.29 Region 3, Office of Director \$10 15615 098 24X Fiche 50-255.82/09/29,8210040213
- 210130146 Forwards LER 82-027/03L-0

 JOHNEGN, B D Consumers Power Co 82/09/30 KEPPLER, J O Region 3,

 Office of Director 1p 156/3 084 24X Fichs, 50-255, 82/09/30.
- -8210130156 LER 82-027/03L-0 on 820901, procedural inadequacies discovered which could cause reduction in dagree of redundancy in containment cooling sys Procedures revised to require fans to be declared inoperable if stopped * Consumers Power Co 82/09/30 Region 3, Office of Director ip 15673 085 24X Fiche 50-255,82/09/30,8210130146
- 210180186 Forwards LER 82-031/03L-0 JOHNSON B D Consumers Power Co. 82/10/06 KEPPLER, J O Regi Office of Director ip 15718 177 24X Fiche 50-235, 82/10/06, 8210180184
- -8210180191 LER 82-031/03L-0 on 820909, i-1 diesel generator water jackst heater found inoperable Caused by corrosion of heater element. Heater replaced w/similar type element Mod developed to replace heater element

 # Consumers Power Co 92/10/06 Region 3, Office of Director
 1p 13718 178 24X Fich = 50-255, 82/10/06, 8210180186

- 8210170604 Forwards LER 82-028/03L-0
 8210170604 Forwards LER 82-028/03L-0
 82/10/11 KEPPLER: J Q Region 3. 8210190404
- --8210190615 LER 82-028/03L-0 on 820915.borac acid heat trace circuit 401 (gravity feed line to charging pumps) failed Rudundant channel remained operable Caused by failed heater element Heater element replaced # Consumers Power Co 82/10/11 Region 3, Office of Director ip 19739 358 24x Fiche 50-255,62/10/11,6210190604
- 8210190620 Forwards LER 82-027/03L-0 JOHKSON, B D Consumers Power Co 82/10/11 KEPPLER, J O Repi Office of Director 19 15737 219 24X Fiche 50-255, 82/10/11.
- --8210190628 LER 82-029/03L-O on 820916.T-82B (safety injection tank B) level reached Tech Spec limit of 198 inches three times in 24-h period Caused by misor leakage past loop theck valve & fill & drain valve Fill & drain cycled to stop leakage * Consumers Power Co 82/10/11 Region 3. Office of Director ip 15737 220 24X Fich 50-255.82/10/11.8210190420
- 8210190639 Forwards LER 82-030/03L-0 JOHNSON, B D Consumers Power Co. 82/10/11 KEPPLER, J O Region 3, Office of Director 1p 15740 044 24% Fiche 50-255, 82/10/11.
- --8210190649 LER 82-030/03L-0 on 820927, boric acid heat trace circuit 432 failed Redundant channel remained sperable Caused by blown fuse in controller Circuitry tested & fuse replaced W Consumers Power Co B2/10/11 Region 3. Office of D 1p 15740 045 24X Fiche 50-255.82/10/11.8210170637 Office of Director
- DOCKET SO-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8209170101 Forwards minor revisions to proposed physical security plan Revisions withheld (ref 10CFR73 21) MLLEs.L M Tennesses Valley Authority 82/08/31 DEN3ON, H R Office of Nuclear Reactor Regulation, Director, 2pp 14910 081 24X Fiche 50-259,82/08/31,8209170101
- 8210210034 STATION BLACKOUT AT BROWNS FERRY UNIT ONE-10DINE AND NOBLE CAS DISTRIBUTION AND RELEASE WICKNER, R P. KEBER, C F., LORENZ, R A Cak Ridge National Laboratory FIN B-0452 NURSCO(R-2182 VOZ 82/09/30 Division of Accident Evaluation 261pp. 18773,001 24% Fiche 50-259,82/09/30, Evaluation 8210210034
- 8210250236 Forwards sacurity plan table of contents Table of contents withheld (ref 10CFR73 21)

 withheld (ref 10CFR73 21)

 KARMER D 8 Tempesse Valley Authority 82/10/19 DENTON, H, R

 Office of Nuclear Reactor Regulation: Director 1p 15788 362 Fiche, 50-259, 82/10/19, 8210250234
- O Adjudicatory correspondence
- 8210120271 Response to ASLAD 820920 order to provide any supplemental info re questions posed to util Authorization is for 5-yr storage of low lavel radwasta, w/o limit on use of modules for Interim use on backup basis 2/10/08 Epp 15652 071 24X Fichs. 50-259, 82/10/08 E20102091.
- --8210120299 Affidavit of P Loysen re application for storage of low level radwasts No restriction requested or contemplated limiting use of modules only to interim use on backup basis LOYSEN, P Advanced Fuel & Spent Fuel Licensing Branch 82/10/08 23pp 15652,079 24X Fiche, 50-259,82/10/08,8210120291.
- --B210120308 Affidavit of JR McOrath Timely request for renewal of facility license filed for Beatly, NV low level radwaste disposal facility NV State Board of Health voted not to renew facility license.

 MCGRATH. J. R Assistant Director for State Agreements Programs 82/10/08 2pp 15652.102 24X Fiche. 50-259, 82/10/08, 8210120291
- --B210120316 Affidavit of SN Balomon Southeast Interstate Low Layel
 Radwaste Mgt Compact agreed to close Barnwell, SC facility
 on 921231 & open new site on 911231. Cartificate of Svc encl.
 SALONON.S.N Assistant Director for State Agreements Programs,
 82/10/08 4pp. 15652 104 24X Fiche: 50-259, 82/10/08, 8210120291

- 8210250063 Telecopy message of motion for ASLAB to grant 30-day extension to respond to ASLB B20920 order Time necessary to explore settlement possibilities of all matters in controversy PYLE.R B Pyle, R B 82/10/20 Docketing & Services Branch lp 15787 061 24X Fiche 50-259,82/10/20,8210250063
- 8210260429 Motion for extension of time until 821121 to respond to 820720 order Time necessary to explore possibilities of settlement Certificate of Svc encl PYLE.R B Pyle, R B 82/10/20 Atomic Safety and Licensing Appeal Panel 2pp 15806 036 24X Fiche 50-259,82/10/20,8210260429
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8208170297 Chapter 2 to Browns Ferry updated FSAR. "Bite "
 * Tennesser Valley Authority 82/08/12 346pp 14852 202 24%
 Fiche 50-259, 82/08/12,8208170297
- P Operating license stage documents & correspondence
- 8210050268 Application to amend License DFR-33, revising Cycle 5 may critical power ratio values Error discovered in active fuel length used in original Cycle 5 analysis Approval requested by 821119
 MILLS L M Tennessee Valley Authority 82/09/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15611 231 24X Fiche 50-259, 82/09/21, 8210050268
- --8210050271 Proposed Tech Specs re max tritical power ratio * Tennessee Valleg Authority 62/09/21 3pp 15611 233 24% Fiche 50-259,82/09/21,8210050268
- 8210060301 Application to amend License DPR-33, updating curve of pressure vs temp to extend applicability through 5 0 effective full power yrs Approval of change requested by 821126 MILLS.L.H. Tempessee Valley Authority 82/09/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15619 29J 24X Fichs 50-259,82/09/23,8210060301
- --B210060304 Proposed Tech Bpac Figure 3 &-1, updating curve of pressure vs temp to extend applicability through 5 0 effective full power yrs * Tennessee Valley Authority B2/09/23 3pp 15619 295 24X Fishe 50-259, B2/09/23, 9210060301
- 8210070255 Forwards response to NRC request for add1 info on NUREO-0612, "Control of Heavy Loads of Nuclear Power Plants "
 HILLS.L M Tennessee Valley Authority 82/09/28 VASSALLO.D B Operating Reactors Branch 2 56pp 15635 243 24X Fiche 30-259, 82/09/28, 8210070255
- G2108021B Forwards add1 info in response to NRC 82080B request re NUREO-0737: Item [] N 3 24. "Adequacy of Space Cooling for HPCI & RCIC."

 MILLS,L M Tennessee Valley Authority 82/10/04 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 1563B:091 24X Fiche: 50-259, 82/10/04, 82(008021B
- 8210130142 Forwards description of final mods & changes to BMR scram sys & short-term interim commitments for Unit 2 Mods will be implemented for Unit 2 before startup from Reload 4 outage & subsequent Units 1 & 3 outages HILLS, L M Tennessee Valley Authority 82/10/06 DENTON, H, R Office of Nuclear Reactor Regulation, Director 4pp 15673 086, 24X Fiche 50-259,82/10/06,8210130142
- 8210230096 Forwards revision to 821006 implementing procedures HILLS.L M Tennesses Valley Authority. 62/10/15 DENTON, H R Office of Nuclear Reactor Regulation, Director. 1p 13793:058 24% Fiche: 50-259, 82/10/15, 8210250096
- --8210250101 Revised implementing procedures.

 * Tennessee Valley Authority 82/10/15 16pp 15793.059 24X
 Fiche 50-259,82/10/15,8210250096
- Q. Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems. Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5).
 FELTON J H Division of Rules and Records 82/07/12, UDELL R A Critical Mass Energy Project 9pp, 15665 027 24X Fiche 30-000 82/07/12, 8210080015

- --8210080118 Systematic assessment of licensee performance notes refacility evaluation for Apr 1979-Mar 1980

 * NRC No Detailed Affiliation Queen 80/03/31 App 15667 315 24X Fiche 50-000, 82/07/12, 8210080015
- 8210150105 Notifies that corrective actions re IE Insp Repts 50-237/81-13, 50-260/81-13 & 50-276/81-13 delayed Procedure BPM NBOE3 re exam of CSSO items to be revised by 820915 DOMER, J A Tennessee Valley Authority 82/07/13 O'RE(LLY, J P Region 2, Office of Director ip 15701 159 24X Fiche 50-239, 82/07/13,8210150105
- 8210220151 Provides supplemental response to NRC ltr re violations noted in IE Insp Repts 50-259/82-10.50-260/82-10 % 50-256/82-10 Div of procedures Manual N82A3 will not be revised until 821001 due to scope of effort involved MILLS.L M Tennesses Valley Authority 82/08/18 0'RE(LLY, J P Repion 2. Office of Director ip 15778 106 24X Fiche 50-259.82/08/18.8210220151
- B210010035 Confirms B2090B site meeting to discuss recent violations re-radwaste shipments Agenda encl
 D'REILLY, J.P. Region 2, Office of Director B2/09/03 PARRIGHE 5
 Tennessee Valley Authority 2pp 15565 166 24X
 Fiche 50-259, 82/09/03,8210010035
- 8210010430 Forwards IE Insp Repts 50-259/82-25.50-260/82-25 & 50-296/02-25 on 820810-11 No noncompliance noted VERRELLI.D M Division of Project D Resident Programs G2/09/07 PARRIES.H G Tennessee Valley Authority 2pp 15570 211 24x Fiche 50-259.82/09/03.8210010430
- --0210010432 IE Insp Repts 50-259/82-25,50-260/82-25 & 50-296/82-25 to 020810-11 No noncompliance noted Hajor areas inspected reactor secondary containment integrity problem & MBIV testing BRODKS, E X . JAPE. F Division of Engineering & Technical Prograss 02/00/27 4pp 15570 213 24X Ficha 50-259,82/09/03,821001643
- 8210150399 Forwards IE Insp Repts 50-259/82-28.50-260/82-28 & 50-296/82-28 on 820830-0903 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 62/09/20 PARRIS, H O Tennesses Valley Authority 2pp 15704 029 24X Fiche 50-259, 82/09/20, 8210150399
- --8210150406 IE Insp Repts 50-259/82-28,50-260/82-28 & 50-246/82-28 cn 820830-0903 No noncompliance noted Hajar areas inspected inservice inspected inservice inspected program & inservice testing program review QIRARD, E H , BLAKE, J Division of Engineering & Technical Programs 82/09/16 4pp 15704 031 24X Fiche 50-259,82/09/20 8210150399
- 8210010097 Appraves revised commitment dates for Item 25 of App L to IE Insp Repts 30-259/81-19.50-260/81-19 & 50-294/81-19 & Item C 2 of App A to IE Insp Repts 50-259/82-12.50-260/82-12 & 50-276/82-12 & Item C 2 of App A to IE Insp Repts 50-259/82-12.50-260/82-12 & Item C 2 of App A to IE Insp Repts 50-259/82-12.50-260/82-12 & Item C 2 of App A to IE Insp Repts 50-259/82-12.50-260/82-12 & Item C 2 of App A to IE Insp Repts 50-259/82-12.50-259
- --B210010104 Requests extension to respond to App C. Item 25 in IE Insp. Repts 80-25 9/81-19, 50-260/81-19 & 50-296/81-19 & Item C 2 in IE Insp. Repts 50-259/82-12, 50-260/82-12 & 50-296/82-12 Responses will be submitted by 830101 & 821101. respectively MILLS., M. Tennessee Valley Authority 82/09/01 0'REILLY. J. P. Repion 2: Office of Director ip 15565 002 24% Fiche 50-259, 82/09/22. 8210010097
- 0210010326 Forwards summary of 820708 enforcement meeting w/util to discuss corrective actions re leakage during sipment of low level waste & util plans for improving employee training O'RETLLY, J P Region 2, Office of Director 82/09/22 PARRIS, H & Tennessee Valley Authority 4pp 15569 188 24X Fiche: 50-259, 82/09/22,8210010326
- 8210010270 Ack receipt of supplemental 820701 itr informing NRC of steps taken to correct Violation B noted in IE Insp Repts 30-257/61-26, 30-260/82-26 & 50-276/81-26 LEWIB.R C Division of Project & Resident Programs 82/09/24 PARRIS.H G Tennesses Valley Authority 1p 15573 183 24X Fiche. 30-259, 82/09/24,8210010290
- --B210010304 Forwards revised response to NRC 811028 itr re Visistics]
 noted in IE Insp Repts 50-259/82-26, 50-260/82-26 &
 50-296/82-26 Corrective actions R factor returned to within
 limits & revision to Tech 8pec approved
 MILLS,L.M Tennessee Valley Authority 82/09/01 D'REJLLY. J F
 Repion 2, Office of Director 3pp 15573-184 24X
 Fiche 50-259,82/09/24,8210010290

i

- 8210220370 Forwards IE Insp Repts 50-259/82-29, 50-260/82-29 & 50-296/82-29 on 820906-10 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/09/30 PARRIS.H G Tennessee Valley Authority 2pp 15779 220 24X Fiche 50-259, 82/09/30,8210220390
- --8210220401 IE Insp Repts 50-259/82-29, 50-260/82-29 & 50-296/82-29 on 820906-10 No noncompliance noted Major areas inspected Unit 2 refueling & maint outage & procedural compliance of health physics-related practices by workers COLLINS.T R. BARR.K P Division of Engineering & Technical Programs 82/09/27 5pp 15779 222 24X Fiche 50-259,82/09/30,8210220390
- 6210080219 Forwards revised request for relief from inservice Insp 7 re inaccessible welds in piping penetrations & under rigid pipe restraints Best effort visual exam will be performed during sys hydrostatic pressure test
 MILLS.L M Tennessee Valley Authority 82/10/04 DENTON.H R
 Effice of Nuclear Reactor Regulation, Director 3pp 15638 083
 244 Fiche 50-259.82/10/04.8210080219
- B20B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl CODB.L I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000, B2/10/06 B208190233
- 8210150218 Forwards update of present work & schedule for implementation of insps required under IE Builetins 79-02 & 79-14 Phase II evaluation will not be completed until 84080:
 MILLS.L M Tennessee Valley Authority 82/10/07 0'REILLY, J P Region 2. Office of Director 2pp 15705 276 24X
 Fiche 50-259.82/10/07.8210150218
- 8208190238 IE Builetin 82-03. "Stress Corrosion Cracking in Thick-Mall. Large-Diameter: Stainless Steel. Recirculation Sys Piping at BNR Plants " Svc list enc) DEYDUNG. R C Director's Office. Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000.82/10/14.8208190238
- 5 Reportable occurrences. LERs & related correspondence
- 6210120129 Advises of need for in-depth evaluation of potential for unacceptable interaction between control rod drive sys & nonessential control air sys Margin of safety inherent in licensed design basis should be promptly restored MICHELSON, C Director's Office BO/OB/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 15692 150 24X Fiche 50-296,80/08/18,8210120129
- G209300170 Forwards LER 82-071/01T-0 GREEN.H J Tennessee Valley Authority B2/09/24 O'REILLY, J P Region 2. Office of Director 1p 15553 281 24X Fiche 50-259.82/09/24.8209300170
- --8209300175 LER 82-071/01T-0 on 820909, HPC1 condensate storage tank iou level switches LS-73-56A & LS-73-56D failed to operate Caused by dirty & corroded level switches activating plates Plate points cleaned tRBY. B J Tennessee Vailey Authority 82/09/24 Region 2, Office of Director 2pp 15553 282 24X Fiche 50-259, 82/09/24, 8209300170
- 8210060409 Forwards LER 82-067/03L-0 GREEN-H J Tennessee Valley Authority 82/09/30 D'REILLY, J P Region 2, Office of Director [p 18618 319 24X Fiche 50-239, 82/09/30, 8210060409
- --8210060412 LER 82-067/03L-0 on 820901.during normal operation, while performing fire protection surveillance insp, heat detection ione 6 for spreader room A common to Units 1 & 2 found inoperable Caused by loose fire protection panel relay MURPMY. D E Tennessee Valley Authority 82/09/30 Region 2, Office of Director 2pp 15615 320 24X Fiche 50-259,82/09/30,8210060409
- 5210060414 Forwards LER 62-06B/03L-0 GREEN.H J Tennessee Valley Authority 62/09/30 O'REILLY, J P Region 2. Office of Director ip 15615 004 24X Fichs 50-259.82/09/30.8210060414
- --8210060422 LER 82-068/03L-0 on 820702, while performing primary containment isolation valve leak rate test. A hydrogen analyzer became inoperable Caused by failed hydrogen sample inlet pump power relay contacts
 CARTER: 8 D Tennessee Valley Authority 82/09/30 Region 2, Office of Director 2pp 15615 005 24X Fiche 50-259, 82/09/30, 8210060414

- 8210130565 Forwards LER 82-069/03L-0 GREEN H J Tennessee Valley Authority 82/10/05 O'REILLY, J P Region 2. Office of Director 1p 15683 110 24X Fiche 50-257.82/10/05.8310130565
- --8210130567 LER 82-069/03L-0 on 820907, during startup testing, rod sequence control sys found inoperable Caused by failure of QE sequence generator card Model 19389480AA Card replaced & testing satisfactorily completed IRBY. B J Tennessee Vailey Authority 82/10/05 Region 2. Office of Director 2pp 15683 111 24X Fiche 50-259,82/10/05.8210/30545
- 82:0130165 Forwards LER 82-072/03L-0 QREEN.H J Tennesses Valley Authority 82/10/07 O'REILLY, J P Region 2. Defice of Director 1p 15673 054 24X Fiche 50-259, 82/10/07, 8210130165
- --8210130169 LER 82-072/03L-0 on B20908, during startup, rod worth minimizer (RMM) applied rod blocks when rod 30-51 selected Caused by listing two rods twice in RMM sequence due to typing error RMM sequence corrected & returned to svc NAVE, E Tennessee Valley Authority 82/10/07 Region 2, OPFice of Director 2pp 15673 055 24X Fiche 50-259, 82/10/07, 8210130145
- 8210130172 Forwards LER 82-075/017-0 OREEN.H J Tennessee Valley Authority 82/10/07 O'REILLY, J P Region 2, Office of Director 1p 15673 046 24X Fiche 50-259, 82/10/07.8210130172
 - -8210130176 LER 82-075/01T-0 on 820924 four degraded voltage relays, three timers & one loss-of-voltage relay found to be outside allowable Tech Spec setpoint range Caused by setpoint drift Relays recalibr & returned to svc CHRISTOPHER, W Tennessee Vailey Authority 82/10/07 Region 2, Office of Director 2pp 15673 047 24X Fiche 50-259,82/10/07.8210130172
- 8210130429 Forwards LER 82-070/03L-0 GREEN H J Tennessee Valley Authority 82/10/07 G'REILLY, J P Region 2. Office of Director 1p 15681 160 24X Fiche 50-259, 82/10/07, 8210130429
- --8210130438 LER 82-070/03L-0 on 820908, while calibr reactor protection sys high-water level switches on scram discharge tank level switch LS-88-45E operated at 27 gallons, combary to Tech Specs Caused by calibr drift on level switch SL-305-E1-X IRBV, D J Tennessee Valley Authority 82/10/07 Region 2, Office of Director 3pp 1568(161 24X Fiche 50-289, 82/10/07, 8210130429
- 8210220053 Forwards LER 82-073/03L-0 OREEM H J Tennessee Valiey Authority 82/10/08 O'REILLY, J P Region 2. Office of Director 1p 15778 204 24X Fiche 50-257,82/10/08,8210220053
- --8210220057 LER 82-073/03L-0 on 820910.while performing maint on diesel generator A.fuel oil flowed out discharge filter drain valve when transfer pumps supplied oil to day tank Caused by personnel error Responsible person reinstructed PORTER.M R Tennessee Vailay Authority 82/10/08 Region 2. Office of Director Ip 15778 205 24X Fiche 50-257,82/10/08,8210220053
- 8210270054 Forwards followup LER 82-023/03X-2 OREEN H J Tennesse Valley Authority 82/10/13 O'REILLY, J P Region 2. Office of Director 1p 15854 050 24X Fiche 50-257, 82/10/13, 8210270054
- --B210290057 Followup LER B2-023/03X-2 on 820327, recordiation pump 1A tripped due to spurious generator starter relay operation Caused by Hi-temp relay trip Relay reset in 20 minutes & pump returned to avo No recurrence control planned CMRISTOPHER, W. Tennessee Valley Authority 82/10/13 Region 2, Office of Director 3pp 13854 051 24% Fiche 50-259,82/10/13. 8210290054
- 8210290062 Forwards updated LER 82-042/03X-1 OREEN H J Tennessee Valley Authority 82/10/13 O'REILLY, J P Region 2, Office of Director 1p 15853 339 24X Fiche 50-259, 82/10/13, 8210290062
- --B210290066 Updated LER B2-042/03X-i on B20biB, quarterly Surveillance Insp 3 2 B for testing of HPCI & RCiC vacuum reilef valves not performed per ABME Section XI Caused by personnel error Foreman missplaced performance reminder CAMPBELL.O. Tennessee Valley Authority B2/10/13 Region 2, Dffice of Director 2pp 15853 340 24X Fiche 50-259,82/10/13,8210290062

- 9210290317 Forwards updated LER 82-031/03X-2 GREEN H J Tennessee Valley Authority 82/10/13 O'REILLY, J P Region 2. Office of Director 1p 15853 080 24X Fiche 50-259, 82/10/13.8210290317
- --821027032: Updated LER 82-031/03X-2 on 820510 hydrogen analyzer B inoperable due to failure of hydrogen sample inlet pump Caused by failure of Allen Bradley relay Hodel 700-N400A1 contacts Relay investigation results expected 830215 CARTER: S Tennessee Valley Authority 82/10/13 Region 2. Office of Director 2pp 15853 CB1 24X Fiche 50-299.82/10/13, 8210290317
- 8210290368 Forwards LER 82-077/03L-0 QREEN-H J Tennessee Valley Authority 82/10/15 G'REILLY.JP Region 2. Office of Director 1p 15853 083 24X Fiche 50-257, 82/10/15,8210270368
- --8210290371 LER 92-077/03L-0 on 920918, control rod 38-39 declared inoperable due to fuse failure alarms & high-water level alarms indicating Caused by control rod drive hydraulic control unit accumulator level switch being grounded MURPHY.D E Tennessee Valley Authority 82/10/15 Region 2, Office of Director 2pp 15853 084 24% Fiche 50-259, 82/10/15.
- 8210260381 Forwards LER 82-076/03L-0 GREEN, H J Fennesse Valley Authority 82/10/19 O'REILLY, J P Region 2. Office of Director 1p 15803 359 24X Fiche 50-259, 82/10/19, 8210260381
- --8210260407 LER 82-076/03L-0 on 820925, turbine bldg roof vant monitor CAM 1-90-251 became inoperable Caused by failure of pump drive motor model 6K562C due to end of natural life Drive motor replaced, THERPE, A Tennessee Valley Authority 82/10/19 Region 2, Office of Director 20 15803 360 24X Fiche 50-259, 82/10/19,
- --8210260222 Updated LER 82-067/03x-1 on 820901.heat detection zone 6 for spreader from A & preaction sprinkler automatic initiation circuit found inoperable Gaused by Jose fire protection panel relay Relay repositioned & clipped in place MURPHY. D E Tennessee Valley Authority 82/10/20 Region 2, Office of Director 2pp 15799 154 24X Fiche 50-259, 82/10/20. 8210260212
- T Hearing transcripts on non-antitrust matters
- 82:0070133 Testimony of JW Hotton answering ASLAB questions on low level radwaste mgt options Availability of adequate space to dispose of low level wastes in next 5 yrs uncertain Certificate of Syc enci HUTTON, J W Tennesse Valley Authority 82/10/01 12pp. 15627 031 24X Fiche 50-259,82/10/01,8210070133
- DOCKET 50-260 DROWNS FERRY NUCLEAR POWER STATION, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8209170101 Forwards minor revisions to proposed physical security plan Revisions withheld (ref 10CFR73 21) MILLS.L M Tennessee Valley Authority 82/08/31 DENTON.H R Office of Nuclear Reactor Regulation, Director, 2pp 14910 OBI 24X Ficher 50-259,82/08/31,8209170101.
- 8210250236 Forwards security plan table of contents Table of contents withheld (ref 10CFR73 21)

 KAMMER.D 8 Tennessee Valley Authority 82/10/19 DENTON, H R

 Office of Nuclear Reactor Regulation, Director 1p 15/38 362 24X

 Fiche 50-259,82/10/19,8210250236
- 8210230244 Forwards revisions to physical security plan Revisions withheld (ref 10CFR73, 21)
 RAMER, D. B. Tennesse Valley Authority 82/10/17 DENTON, H. R. Office of Nuclser Reactor Regulation, Director 1p. 15788 345 24X
 Fiche. 50-250, 82/10/17, 8210250244

G Adjudicatory correspondence

- 8210120291 Response to ASLAB 820920 order to provide any supplemental info re questions posed to usil Authorization is for 5-yr storage of low level radwaste.w/o limit on use of modules for interin use on backup basis
 RAWSDN:R J Hearing Branch 4 82/10/08 Bpp 15652 071 24x
 Fiche 50-259.82/10/08.8210120291
- --8210120299 Affidavit of P Loysen re application for storage of low level radwasts No restriction requested or contemplated limiting use of modules only to interim use on backup basis LOYSEN.P Advanced Fuel 2 Spent Fuel Licensing Branch 82/10/68 23pp 13652 079 24% Fiche 50-259,82/10/08.8210120291
- ~-B210120308 Affidavit of JR McGrath Timely request for renewal of facility iscense faled for Beatly.NV low level radwaste disposal facility NV State Board of Health voted not to renew facility license MCGRATH, JR Assistant Director for State Agreements Programs 82/10/08 2pp 19652 102 24X Fiche 50-259.82/10/08.8210120241
- --8210120316 Affidavit of SN Salomon Southeast Interstate Low Level Radwaste Hot Compact agreed to close Barnwell. SC facility on 921231 & open new site on 911231 Certificate of Svc encl SALOHON. S N Assistant Director for State Agreements Programs 82/10/08 4pp 15852 104 24X Fiche 50-259.82/10/09,04101202/1
- 82(0250063 Telecopy message of motion for ASLAB to grant 30-day extension to respond to ASLB 820920 order Time necessary to explore settlement possibilities of all matters in controversy PYLE.R B Pyle, R B 82/10/20 Docketing & Services Branch 1:15787 061 24X Fiche 50-259,82/10/20,8210250063
- 8210260429 Motion for extension of time until B21121 to respond to 820920 order Time necessary to explore possibilities of settlement Certificate of Svc encl PMER B Pyle. R B 82/10/20 Atomic Safety and Licensing Appeal Panel 2pp 15806 036 24% Fiche 50-259,82/10/20. B210260429
- P Operating license stage documents & correspondence
- 8210070255 Forwards response to NRC request for addl info on NUREO-0612, "Control of Heavy Loads of Nuclear Power Plants"
 MILLS,L M Tennessee Valley Authority 82/09/28 VABSALU,D & Operating Reactors Branch 2 50pp 15635 243 24X Fiche 50-259,82/09/28.8210070255
- 8210080218 Forwards add1 info in response to NRC 820808 request re NVREO-0737. Item II K 3 24. "Adequacy of Space Cooling for HPCI & RCIC" MILLS.L M Tennessee Valley Authority 82/10/04 DENION.H H Diffice of Nuclear Reactor Regulation. Director 2pp 15630 091 24X Fiche 50-259, 82/10/04,8210080218
- 82(0)30142 Forwards description of final mods & changes to BHR stras sys & short-term interim commitments for Unit 2 Mods will be implemented for Unit 2 before startup from Reload 4 outage & subsequent Units 1 & 3 outages MILLS.L. H. Ternessee Valley Authority 82/10/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp 15673 086 24% Fiche 50-259, 82/10/06, 8210130142
- 8210250067 Application to amend License DPR-52 to accommodate Reload & Cycle 5 operation & outage-related mods Approval by 830112 requested to avoid impacting refueling & startup MILLS,L.M Tennessee Valley Authority 82/10/15 DENTON:H R Office of Nuclear Reactor Regulation, Director 2pp 15792 145 24% Fiche 50-260,82/10/15.8210250067
- --8210250070 Proposed Tech Spec changes, accommodating Reload 4.Cycle 5 operation & outage-related mods
 ** Tennesse Valley Authority 82/10/15 82pp 15792 147 24x
 Fiche: 50-260, 82/10/15, 8210250067
- --8210230074 "Supplemental Reload Licensing Submittal for Browns Felta Nuclear Plant: Cycle 5. Unit 2. Reload 4 " HLF, C. L., ZARBIS, M. A., CHARNLEY, J. S. General Electric Co Y1003501A40 82/07/31 36pp 15792 230 24X Fiche 50-260, 82/10/15, 8210250067
- --8210250077 Errata & Addenda Sheet 4 to NEDD-24088-1, "LOCA Analysis for Browns Farry Nuclear Plant Unit 2" " General Electric Co NEDD-24088-1 NO4 ERR 82/07/31 Bpp 15772.255. 24% Fichs 50-260,82/10/15,8210250067

- --2210250078 Errata & Addenda Sheet 5 to NEDD-24088-1. "LOCA Analysis for Brouns Ferry Nuclear Plant Unit 2"
 a General Electric Co NEDD-24088-1 NO5 ERR 82/08/31 2pp 15792 263 24% Fiche 50-260, 82/10/15,8210250067
- F210250096 Forwards revision to 821006 implementing procedures hILLS.L M Tennessee Valley Authority 82/10/15 DENTON,H R Uffice of Nuclear Reactor Regulation, Director 1p 15793 058 24X Fiche 50-259, 82/10/15,8210250096
- -8210250301 Revised implementing procedures a Tennessee Valley Authority 82/10/15 1App 15793 059 24X Fichs 50-259 82/10/15 8210250094
- n inspection reports. IE Builetins & correspondence
- Ralo080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events 2 safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELION, J M Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000.82/07/12.8210080015
- -8210080118 Systematic assessment of licensee performance notes refacility evaluation for Apr 1979-Mar 1980

 RRC No Detailed Affiliation Given 80/03/31 App 15667 315 24X Fiche 50-000, 82/07/12-8210080015
- 5210150105 Notifies that corrective actions re IE Insp Repts 50-259/01-13 50-260/01-13 50-259/01-13 delayed Procedure pPM MB0G3 re earm of C556 items to be revised by 820915 DCCER.J A Tennessee Valley Authority 82/07/13 O'REILLY, J P Region 2. Dfrice of Director 1p 15701 159 24X Fiche 50-259.82/07/13.8210150105
- E210220151 Provides supplemental response to NRC ltr re violations noted in IE lnsp Repts 50-259/82-10.50-260/82-10 & 50-275/82-10 Div of procedures Manual NB2AD will not be revised until 821001 due to scope of effort involved MILLS.L M Tennessee Valley Authority 82/08/18 0'REILLY, J P Region 2 Office of Disctor 1p 15778 106 24x Fiche 50-259.82/08/18.8210220151
- 6:10010035 Confirms 820908 site meeting to discuss recent violations re radwaste shipments Agenda encl B'REILLY JP Region 2, Office of Director B2/09/03 PARRIS.H G Tennessee Valley Authority 2pp 13565 166 24X Fiche 50-259.82/09/03.8210010035
- #210010430 Forwards IE Insp Repts 50-259/82-25,50-260/82-25 & 50-296/82-25 on 820810-11 No noncompliance nated VERRELLI.D M Division of Project & Resident Programs 82/09/03 PARRES.H 6 Tennessee Valley Authority 2pp 15570 211 24X Fiche 50-259,62/09/03,8210010430
- -8210010432 IE Insp Repts 50-259/82-25, 50-260/82-25 & 50-296/82-25 on 820910-11 No noncompliance noted Major areas inspected reactor secondary containment integrity problem & MSIV testing BRCOKS.E H. JAPE,F Division of Engineering & Technical Programs 82/08/27 4pp 15570 213 24% Fiche 50-259,82/09/03,8210010430
- H210150399 Forwards IE Insp Repts 50-259/B2-28,50-260/B2-28 & 50-296/B2-28 on B20830-0903 No noncompliance noted VERRELLE, D M Division of Project & Resident Programs 82/09/20 PARRIS, H G Tennessee Valley Authority 2pp 15704 029 24X Fiche 50-259,82/09/20,8210150399
- --8210150405 lE insp Repts 50-259/82-28,50-260/82-28 & 50-276/82-28 on 820830-0903 No noncompliance noted Major areas inspected inservice insp program & inservice testing program review QIRARD,E H, BLAKE,J Division of Enginoering & Technical Programs 82/09/16 4pp 15704 031 24X Fiche 50-259,82/09/20, 6210150399
- 6210010077 Approves revised commitment dates for Item 25 of App C to IE Insp Repts 50-259/81-19.50-260/81-19 & 50-296/81-19 & 1tem C 2 of App A to IE Insp Repts 50-259/82-12.50-260/62-12 & 50-296/82-12
 LEWIG.R C Division of Project & Resident Programs 82/09/22 PARRIES.H G Tennessee Valley Authority 1p 15565 001 24X Fiche 50-259.82/09/22.8210010097
- --8210010104 Requests extension to respond to App C. Item 25 in IE Insp Repts 50-239/81-19.50-260/81-19 & 50-296/81-19 & Item C 2 in IE Insp Repts 50-259/82-12.50-260/82-12 & 50-296/82-12 Responses will be submitted by 830101 & 821101.respectively HILLS.L M Tennessee Valley Authority 82/09/01 0'REILLY, J P Regison 2. Office of Director 1p 15565 002 24X Fiche 50-259.82/09/22, 8210010097

- S210010326 Forwards summary of B20908 enforcement meeting w/util to discuss corrective actions re leakage during shipment of low level waste & util plans for improving employes training O'REILLY.JP Region 2. Office of Director 82/09/22 PARRIS.H G Tennesses Valley Authority 4pp 15969 188 24X Fiche 50-259.82/09/22.8210010326
- 8210010270 Ack receipt of supplemental 820701 itr informing NRC of steps taken to correct Violation B moted in IE Insp Repts 50-257/61-26, 50-260/82-26 & 50-296/61-26
 LENIS.R C Division of Project & Resident Programs 82/09/24
 PARRIS.H G Tennessee Valley Authority 1p 15573 183 24X
 Fichs 50-259, 82/09/24, 8210010270
- --B210010304 Forwards revised response to NRC 811028 ltr re Violation B noted in IE Insp Repts 50-259/82-26.50-260/82-26 & 50-296/82-26 Corrective actions R factor returned to within limits & revision to Tech Spec approved MILLS.L M Tennessee Vailey Authority B2/09/01 D'REILLY.J P Region 2. Office of Director 3pp 15573 184 24X Fiche 50-259,82/09/24.8210010270
- 8210220390 Forwards IE Insp Repts 50-259/82-29,50-240/82-29 & S0-296/82-29 on 820906-10 No noncompliance noted VERRELLI,D H Division of Project & Resident Programs 82/09/30 PARRIS,H O Tennessee Valley Authority 2pp 15779 220 24X Fiche 50-259,82/09/30,8210220390
- --B210220401 IE Insp Repts 50-259/62-29, 50-260/82-29 & 50-296/82-29 on B20906-10 No noncompliance noted Major areas inspected Unit 2 refueling & maint outage & procedural compliance of halth physics-related practices by workers COLLINS, T R . BARR.K P Division of Engineering & Technical Programs B2/09/27 5pp 15779 222 24% Fiche 50-259, 82/09/30, 8210220390
- 8210080219 Forwards revised request for relief from Inservice Insp / re inaccessible welds in piping penetrations & under rigid pipe restraints Best effort visual exam will be performed during sys hydrostatic pressure test
 MILLS.L. M Tennessee Valley Authority 62/10/04 DENTON.H R
 Office of Nuclear Reactor Regulation, Director 3pp 15638 063
 24X Fiche 50-259,82/10/04,8210080219
- 8208170233 IE lnfo Notice 80-35, Buppl 1, "Leaking & Dislodged I-125 loplant Seeds " Svc list encl COBD.L I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 260 24X Fiche 50-000,82/10/06,8208190233
- 8210150218 Forwards update of present work & schedule for implementation of imaps required under IE Bulletins 79-02 & 79-14 Phase II evaluation will not be completed until 840801 MILLS.L.M Tennessee Valley Authority 82/10/07 O'REILLY, J P Region 2, Office of Director 2pp 15705 276 24X Fiche 50-259, 82/10/07.8210190218
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Rectrculation Sys Piping at BMR Plants "Svc list encl. DEYQUNO.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000. 82/10/14.8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210120127 Advises of need for in-depth evaluation of potential for unacceptable interaction between control rod drive sys & nanessential control air sys Margin of safety inherent in licensed design basis should be promptly restored MICHELSON. C Director's Office 80/08/18 DENION. H R Office of Nuclear Reactor Regulation. Director 3pp 15692 150 24X Fiche 50-296, 80/08/18.8210120127
- 8210070490 Discusses 810406 deliberate pump trip Control switches manipulated for two trains of circulating water sys resulting in pump trip FBI & util investigations failed to find culprit Event listed in safeguerds watch list LAMNINO, H D. Director's Office 81/06/24 Director's Office. Ip 15644 338 24K Fiche: 50-260,81/06/24,8210070490
- B21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Korwards documents listed in App A, FELTON.J. H Division of Rules and Records. B2/06/28 UDELL.R. A Critical Mass Energy Project 15pp 15727.005 24X Fiche-50-000, B2/06/28, B21001000B

- --BI07160079 Informs that manipulation of control switches for two trains of circulating water sus resulted in tripping of two circulating water pumps located in intellecture FDI investigated & found no evidence of who operated switches LANNING.W D Diroctor's Office BI/06/24 Director's Office 1p 15729 250 24X Fiche 50-000.82/06/28.8210010008
- 8210260349 Forwards LER 82-0P9/03L-0 QREEM H J Tennesse Vailey Authority 82/10/19 O'RE(LLY, J P Region 2, Office of Director 1p 15802 347 24X Fiche 50-260.82/10/19,8210260349
- --8210260353 LER 82-027/03L-0 on 820721.pinhole feat discovered in 3-inch fire protection line supplying water to cable-tray fixed water spread says Caused by through-wall pitting corresson attack Ultrasonic testing to be done by 803201 KECKEISEN.T Tennessee Valley Authority 82/10/19 Region 2: Office of Director 2pp 15802 348 24X Fithe 50-260.82/10/19.821020049
- 8210260417 Forwards LER 82-028/03L-0 GREEN H J Tennessee Valley Authority 82/10/19 G'REILLY, J P Region 2. Office of Director 1p 15806 150 24x Fiche 50-260-82/10/19,8210260417
- ~-8210260446 LER 82-028/03L-0 on 820921, during refueling, turbine to reactor bidg doors 237 & 238 opened simultaneously, breaking secondary containment Caused by Folger Adams interlock sys faiture due to loose door latch screws
 TAYLOR, D. Tennessee Valley Authority 82/10/17 Region 2.
 Office of Director 2pp 15806 151 24X Fiche 50-260,82/10/17,8210260417
- T Hearing transcripts on non-antitrust matters
- 8210070133 Testimony of JW Hutton answering ASLAN questions on low level radwate mgt aptions Availability of adequate space to dispose of low level wastes in next 5 yrs uncertain Certificate of Svc encl HUTTOR. J W Tennessee Valley Authority 82/10/01 12pp 15627 031 24% Fiche 50-259.82/10/01.0210070133
- DOCKET 50-241 H B ROBINSON PLANT, UNIT 2
- F Security, medical, emergency & fire protection plans
- B210250202 Forwards scenario for 821014 small-scale emorgency preparedness exercise
 ZIMMERNANAS R Carolina Power & Light Co B2/09/02 BTOHR, J P
 Division of Emergency Preparedness & Operational Support 5pp
 15788 272 24X Fiche 50-261, B2/09/02. B210250202
- 8210150396 Forwards IE Insp Rept 50-261/82-29 on 820816-19 No noncompliance noted LEWIS.R C Division of Project & Resident Programs 82/09/17 JOKES.J A Carolina Power & Light Co 2pp 15704 035 24X Fiche 30-261, 82/09/17, 8210150396
- --8210150401 IE Imap Rept 90-261/82-29 on 820816-19 No noncompliance noted Major areas inspected reducingical emergency preparedness CLINE, W.E., JENKINS, G.R. Division of Emargency Preparedness & Operational Bupport 82/09716 15pp 15704 037 24X Fiche 50-261, 82/09/17, 8210150396

- --8210060354 "Radiation Shielding Analysis for HB Robinson [schnics] Support Ctr/Emergency Operating Facility " BRODE.R W. NATHAN.S.J. SCHMIDT.E.R. NUS Corp. NUS-4154 82/06/30 54pp 15419 134 24X Fiche 50-261.82/10/04.82100.00.451
- H General correspondence
- 8210010028 Requests NRC direct all official correspondence to EH. Utl:, util vice-president due to 820930 retirement of JA Jones
 JONES J A Carolina Power & Light Co 82/09/27 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 15565 314 24
 Fiche 50-000, 82/09/27, 8210010028
- 8210130323 Requests changes to distribution list for NUREO-0020. "Licensed Operating Reactors - Status Summary Rept "
 21MMERMAN, S.R. Carolina Power & Light Co. 82/10/11 BETBE.M.P.
 ADP Systems Development Branch 2pp 15683 361 24X
 Fiche 50-000.82/10/81.8210130323
- P Operating license stage documents & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of into re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (rof FOIA Examption 5) FELTON, J H Division of Rules and Records 62/07/12 UNELL, R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000, 82/07/12, 8210080015
- --8104220145 Provides results of discussion w/licensee to apparent problem u/proper sealing of containment purge valves Licensee estimated that excessive leakage condition occurred at frequency of one time for every five valve cycles DANCE.H C Region 2, Atlanta, Office of the Director 71/10,27 JRRAN.E L Division of Reactor Operations inspections 2pp 15648 145 24X Fiche 50-000,87/07/12.0210080015
- 8210070007 Responds to FDIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed on App B FELTON, J K Division of Rules and Records 82/08/10 (QWA, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 2/4X Fiche 50-000, 82/08/10/8210070007
- 8207180044 FOIA request for all internal non-public documents, usage, evaluation repts & other mati dealing winuclear plant operations
 MCINNIS.B News & Observer 82/08/17 Office of Administrations
 15 15860 064 24X Fiche 50-000.82/08/17, 8207180044
- 8210280013 Responds to FOIA request for all internal non-public documents, memos, evaluation repts & other mat1 dealing w/ nuclear plant operations Forwards documents listed in App A FELTON, J & Division of Rules and Records 82/09/17 HCRMIH D News & Observer 5pg 15860 065 24X Fiche 50-000.82/09/17, B310280013
- --7908130654 Recommends licensee be requested to submit solid waster process control program & offsite dose calculation manual to aid in timely review of radiological effluent Tech Specs Forwards guidelines
 COLLINS.J T Effluent Treatment Systems Branch 79706/21
 SCHWENCER.A Operating Reactors Branch 1 (Pre 791030) 10pp 15860 092 24% Fiche 50-000,82/09/17.8210280013
 - 107010140 Marked-up memo re B10323 angineering evaluation rept bh
 810127 RCB leak Event & recommendations will be taken into
 consideration for further evaluation info has been
 transmitted to utils
 DENTON.H R Office of Nuclear Reactor Regulation, Director
 B1706/15 MICHELEON.C Director's Office 2pp 15868-229 gr
 Fiche 80-000,82/09/17.8210280013
 - | 108270422 Notifies that util 801201 request for license agent gas spent fuel pool storage expansion is acceptable Safety evaluation to EIA input encl KREQER, W E Assistant Director for Radiation Protection 81/07/23 NDVAK.T Assistant Director for Operating Reactors Opp 15860 240 24X Fichs 50-000, 82/09/17, 8210280013
 - 3112020852 Forwards input to safety evaluation & EIA of proposed 5.5 fuel pool storage capacity expansion Evaluation & appraisal based on info provided in 801201 ltr Proposed mod acceptable HOUSTON.R H. Accident Evaluation Branch. 81/11/17. VAROA.S Operating Reactors Branch i 3pp 15860 246 24% Fiche.50-000.82/09/17.8210280013

- --8201200658 Forwards technical evaluation of deviation in licensee B10303 response to requirements of NURCO-0737 Item II F I-1 Yechnical evaluation should be forwarded to licensee for justification of deviations

 MREGER, W.E. Assistant Director for Radiation Protection B1/12/15 NOVAK.T W. Assistant Director for Operating Reactors 2pp 15860 265 24% Fiche 50-000.82/09/17.8210280013
- --8201200662 "Add) Accident Monitoring Instrumentation," technical evaluation of response to Attachment 1 of Item II F 1 of NUREC-0737 Two major deviations from requirements unacceptable HUCHTON,R L Eixon Nuclear Co. Inc (subs of Exion Corp.) 81/11/02 8pp 15860 267 24% Fiche 50-000.82/09/17.8210280013
- 8203220514 Forwards safety evaluation % EIA supporting util 820128 request to allow use of circulating water pump discharge flow as backup source for dilution in calculating radioactive liquid effluent release when pump out of syc HOUSTON.R W Assistant Director for Radiation Protection 82/02/26 NOVAK,T M Assistant Director for Operating Reactors 7pp 15861 017 24X Fiche 50-000.82/09/17.8210280013
- --G205050480 Forwards audit of procedures & training for pressuriled thermal shock Control room emergency procedures remain unlighted toward core cooling & do not go far enough in addressing pressurized thermal shock issue MAZETIS, G R NRC No Detailed Affiliation Given 82/04/15 THOMPSON, H L Division of Human Factors Safety 38pp 15861 049 24% Fiche 50-000,82/09/17,8210280013
 - 0209150106 Provides requested add1 info re 820730 power aperated relief valve block valve failure Maint errors made during previous activities 11sted

 BROWN, E. J. LANNING W. D. Reactor Operations Analysis Branch
 62/08/25 SEYFRIT, K. V. Reactor Operations Analysis Branch 3pp
 15961 344 24X Fiche 50-000, 82/09/17, 8210280013
- --0210200042 Responds to encl E Urley 701227 request for extension to submit draft effluent Tech Specs Request Unacceptable Util reason for extension not valid Draft Tech Specs must be submitted by 790215
 COLLINS. J T Effluent Treatment Systems Branch 79/01/08
 SCHWENCER. A Operating Reactors Branch 1 (Pre 791030) 1p 15860 087 24X Fiche 50-000, 82/07/17.0210280013
- --8210280082 "Dosimetry Placement for Steam Generator Workers " MARNOCK, R Institute of Nuclear Power Operations 82/01/31 13pp 15860 310 24% Fiche 50-000.82/09/17.8210280013
- 8210010054 Ack receipt of 820823 ftr requesting temporary relief from cornitments re-training of shift technical advisors Program approved & request for wanded to NRR for evaluation O'REILLY, JP Region 2. Office of Director 82/09/20 JONES, J A Carolisa Power & Light Co 1p 15565 322 24X

 Ficho 50-000, 82/09/20, 8210010051
- 6210290197 Requests add1 info documenting how each criterion of fUREO-0737, Item II B 3, "Post-Accident Sampling Bys" has been satisfied, in order to conduct post-implementation review Scheduler requested uithin 20 days VAROA-S A Licensing Branch | 82/09/24 JONES J A Carolina Power & Light Co | 10pp | 15876 247 24X Fiche 50-261,82/09/24,8210290197
- 82:10050007 Advises that response to 820318 request for add1 info re INDEG-0737. Item II B 1. "RCS Vents." will be submitted 6 months before end of first refueling scheduled to begin in Dec 1983
 EURY, L I? Carolina Power & Light Co 82/10/01 VAROA, 8 A Operating Reactors Branch 1 1p 15605 192 24%
 Fiche 50-261, 82/10/01, 8210050009
- 82:0060D13 Application to amend License DPR-23 consisting of revision to Tech Space providing three auxiliary feedwater pumps operable prior to exceeding RCS temp of 350 F EURY.L W Carolina Power & Light Co 82/10/01 VARGA.S A Operating Reactors Branch 1 2pp 15615 074 24X Fiche 50-261.82/10/01.8210060013
- --B210060016 Proposed revision to Tech Apecs providing three auxiliary feedwater pumps operable prior to exceeding RCS temp of 350 F & Carolina Power & Light Co 82/10/01 5pp 15615 076 24X Fiche 50-261,82/10/01,8210060013
- 8210150264 Forwards add1 info re plant-specific homogeneous number densities for matls & fluid in reactor vessel core region, per 820917 request for info re pressurized thermal shock ZIMMERMAN.S R Carolina Power & Light Co 82/10/07 VAROA.S A Operating Reactors Branch 1 7pp 15703 254 24X Fiche 50-261.82/10/07.8210150264

- 8210150198 Responds to 820707 request for rept documenting pressurizer power operated relief valve & pressurizer safety valve failures per NUREG-0737. Item II K 3 3 No failures or challenges identified from 810401 to present ZIMMERHAN.8 R Carolina Power & Light Co 82/10/08 VARGA.8 A Operating Reactors Branch 1 2pp 15707 271 24X Fiche 30-261.82/10/08.8210150198
- 8210190709 Forwards "Supplemental Info for Degraded Grid Voltage
 Analysis.CP & L. HB Robinson Nuclear Generating Station
 Unit 2 " in response to 810131 request re adequacy of
 electrical distribution sys voltage
 EURY.L W Carolina Power & Light Co 82/10/14 VARGA.S A
 Operating Reactors Branch 1 3pp 15737 287 24X
 Fichs 50-261.82/10/14.8210190709
- --8210190720 "Supplemental Info for Degraded Orid Voltage Analysis, CP&L, HB Rotinson Nuclear Generating Station Unit 2 " NARAYANI, I V, FIELDS, W W, CASEY, B J Ebasco Services, Inc (subs of Enserth Carp.) 82/09/30 209pp 15737 290 24X Fiche 50-261,82/10/14,8210190709
- 8210260475 Application to amend License DPR-23.revising Tech Epecs to clarify in-place testing criteria used on safety-related HCPA filter sys & compliance w/more recent ANSI std EURY.L W Carolina Power & Light Co 82/10/22 VARGA, S A Operating Reactors Branch 1 2pp 15806 228 24X Fiche 50-261.82/10/22,8210260475
- --8210260482 Proposed Tech Spec changes clarifying in-place testing criteria used on safety-related HEPA filter sys & compliance w/more recent ANSI std & Carolina Power & Light Co 82/10/22 2pp 15806 230 24% Fiche 50-261,82/10/22 8210260475
- 8210260508 Application for amend to License DPR-23, revising Tech Spec to clarify limiting conditions of operation for pressurizer code safety valves EURY.L W Carolina Power & Light Co 82/10/22 VARGA.S A Operating Reactors Branch 1 2pp 15805 133 24X Fiche 50-261.82210/22,8210260508
- --8210240511 Proposed Tech Spec 3 1 1 3 re pressurizer code safety valves

 * Carolina Power & Light Co 82/10/22 ip 15805 135 24X Fiche 50-241, 62/10/22, 6210240508
- 8210290358 Requests extension until 821215 for submittal of schedule re TMI Item II I 3, "Post-Accident Sampling Sys" NRC 820924 request for add info significantly expanded scope of work ZIMMERMAN.8 R Carolina Power & Light Co 82/10/26 VARGA.8 A Operating Reactors Branch 1 lp 15853 047 24X Fiche 50-261.82/10/26.8210290358
- O Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON.J M Division of Rules and Records 82/08/10 LONG.D.J Winthrop, Stimson, Putnam & Roberts 9pp 19449 063 24X Fiche 50-000.82/08/10.8210070007
- --B210070137 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees
 IPPOLITO.T Operating Reactors Assessment Branch 82/04/01
 VAROA:S Operating Reactors Branch 1. 5pp 15645 131 24X
 Fiche 50-000,82/08/10.8210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PWRs.per 750320 & 21 requests Details of insps. including defect indications tube plugging criteria & tubes plugged will not be provided except for Point Beach i ODLLER.K R Division of Reactor Licensing (NRR-1975 anty) 73503/24 MACCARY.R R Division of Technical Review (NRR-1975 only) 5pp 15645 196 24% Fiche 50-000.82/08/10.8210070007
- 8210010173 Forwards IE Insp Rept 50-261/82-30 on 820810-12 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 62/09/08 JONES:J A Carolina Power & Light Go 2pp 15568 132 24X Fiche 50-261,82/09/08,8210010173
- --B210010176 IE Insp Rept 50-261/B2-30 on B20B10-12 No noncompliance noted Major areas inspected post-refueling startup tests & closeout of earlier anforcement item BURNETT:P T , JAPE;F Division of Engineering & Technical Programs B2/09/02 6pp 1556B-134 24X Fiche 50-261; B2/09/0B; B210010173

- 6210150396 Forwards IE Insp Rept 50-261/82-29 on 620816-19 No noncompliance noted LEWIS.R C Division of Project & Resident Programs 62/09/1 JONES.J A Carolina Power & Light Co 2pp 15704 035 24X Fiche 50-261.82/09/17.8210150396
- --8210150401 JE Insp Rept 50-261/82-29 on 820816-19 No noncompliance noted Major areas inspected radiological emergency preparedness CLINC.N E. JENKINS.O R Division of Emergency Preparedness & Operational Support 82/09/16 15pp 15704-037 24X Fiche 50-261.82/09/17.8210150396
- 8210150493 Requests addi info re util response to IE Bulletin 80-11.
 "Masonry Wall Design " Info required by 821122 to complete
 review
 VAROA.S A Operating Reactors Branch 1 82/10/04 JUNES, J A
 Carolina Power & Light Co 4pp 15717 271 24X
 Fichs 30-261.82/10/04.8210150493
- B20B190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl CDBb.L I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York & 6pp 15761 250 24X Fiche 50-000, B2/10/06, B208190233
- 820B19023B IE Bullotin 82-03. "Stress Corrosion Cracking in Thick-Wall-Large-Diameter. Stainless Steel. Recirculation Sys Piping at EMR Plants " Svc list encl BEYDUNG. R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consultated Edison Co of New York 115pp. 15810 125 24X Fiche 50-000.62/10/14.820819023B
- 8210220495 Ack receipt of 821008 itr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-261/82-27 LEWIS.R C Division of Project & Resident Programs 82/10/18 UTLEY.E E Carolina Power & Light Co 1p 15779 009 24X Fische 50-261.82/10/18.8210220495
- --B210220499 Responds to NRC 820908 ltr re violations noted in IE Insp Rept 50-261/82-27 Corrective actions changes to plant operating manual included in permanent change book & operations revisions status list updated tuice weekly STARKEY.R B Carolina Power & Light Co 82/10/08 O'REILLY, J P Region 2. Office of Director 4pp 15779 010 24X Fitche 50-261,82/10/18.8210220495
- ~~8210220500 Forwards IE Insp Rept 50-261/82-27 on 820711-0810 & notice of violation
 LEWIS, R C Division of Project & Resident Programs 82/09/08
 JONES, J A Carolina Power & Light Co 2pp 15779 014 24X
 Fiche 50-261,82/10/18,8210220495

- 8210190240 Forwards updated LER 80-027/01T-1 STARKEY, R B Carolina Power & Light Co 82/10/11 O'REILLY, J P Region 2. Office of Director (p 15742 196 24X F(che 50-26), 82/10/11, 8210190240
- --8210190244 Updated LER 80-027/01T-1 on 801122. relay RT-9 in reactor protection train A failed to re-energize during periodic test of reactor protection logic Caused by shortning of lead using connection to coll wires Relay replaced COX.HT Carolina Power & Light Co 82/10/11 Region 2. Offic of Director 4pp 15742 197 24X Fiche 50-261.82/10/11, 8210190240
- 8210290074 Forwards updated LER 81-031/017-1 STARKEY.R B Carolina Power & Light Co 82/10/22 O'REILLY.J P Region 2, Office of Director 1p 15854 028 24X Fiche 50-261.82/10/22.8210290074
- --8210270078 Updated LER 81-031/01T-1 on 811201.during hot shutdown, pressurizer PORV block valve operators did not fully shut block valves Caused by improper maint Valves closed nanually COX.H T Carolina Power & Light Co 82/10/22 Region 2. Offing Firector 3pp 15854 027 24X Fiche 50-261.82/10/22. 8210290074
- 8210290333 Forwards LER 82-013/03L-0 STARKEY,R B Carolina Power & Light Co 82/10/22 O'REILLY,J P Region 2, Office of Director 1p 15853 103 24X Fiche 50-261,82/10/22.8210290333
- --8210270337 LER 82-013/03L-0 on 820723, svc water pump A failed to restart following periodic test Caused by failed control power fuses Fisses replaced & pump started & retested COX.H T Carolina Power & Light Co 92/10/22 Region 2, Offic of Director 2pp 15853 104 24X Fiche 50-261.82/10/22.8210270333
- DOCKET 50-269 MONTICELLO NUCLEAR GENERATING PLANT
- F Security, medical, emergency & fire protection plans
- 8210150385 Forwards LE Insp Rept 50-269/82-09 on 820703-0828 Na noncompliance noted STREETER: J F Division of Project & Resident Programs 62/09/28 LARBON, C E Northern States Power Co 2pp 15703 272 24X Fiche 50-263, 82709/28, 82101505085
- ---8210150386 IE Insp Rept 50-263/82-09 on 820703-0828 No noncompliance noted Major areas inspected LER followup, operational safety verification, fire protection/prevention, security personnel qualifications, operator overtime & onsite review committee RRGMN, C H . HADISON, A L . WALKER, R D Division of Project & Resident Programs 82/09/28 5pp 15703 274 24X Fiche 50-263,82/09/28,8210150385

- --8210010046 Proposed Tech Specs re surveillance, reactor protection constoring sys, jet pump surveillance, organization & steam line area temp switch deviation

 Northern States Power Co 82/09/24 60pp 15365 183 24X Fiche 50-263, 82/09/24 8210010036
- 9210050377 Forwards application for amend to License DPR-22.App A Amend changes Pages 207 % 209 to remove 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant MUSDLF. D. Northern States Power Co. 82/09/30 ... Office of Nuclear Reactor Regulation. Director 1p. 15615-340. 24X Fiche 50-263.82/09/30.8210060377
- --8210060380 Application for amend to License DPR-22, App A Amend changes Pages 207 & 209 to remove 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant MUSQLF.D Northern States Power Co 82/09/30 4pp 15615 341 24X Fiche 50-283,82/09/30.8210060377
- --8210060386 Proposed Tech Specs 3/4 10. removing 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant 4 Northern States Power Co 82/09/30 2pp 15615 345 24X Fiche 50-263.82/09/30.8210060377
- 8210130261 Submits add! info re application For single loop operation license amend.in response to NAC 820720 request MAPLHCR reduction factors reviewed by GE & found applicable to Cycle 10 MUSOLF.D Northern States Power Co 82/10/05 Office of Nuclea Reactor Regulation, Director ip 15676 014 24X Fiche 50-263,82/10/05,8210130261
- GE10130260 Discusses implementation of NRC guidelines for working hours, provided in Generic Ltr B2-12 Revised guidelines have been implemented, w/eiceptions of 72-h per wk limitation & relief from control board duties MUSQLF, D. Northern States Power Co. B2/10/07 Office of Nuclear Regulation, Director 2pp 15676-012 24% Fische 50-000, 62/10/07, 6210130260
- 22:0150364 Forwards response to request for info in Sections 2 2 % 2 3 of Generic Ltr 81-07 re overhead handling sys Revised 9 month submittal, "Control of Heavy Loads" % review of special lifting devices also encl MUSDLF.D Northern States Power Co 82/10/11 Office of Nuclear Reactor Regulation. Director 16p 15715 102 24X Fiche 50-263.82/10/11.8210150364
- --B210150377 "Evaluation of Conformance w/NUREO-0612 for Drywell/Reactor Vestel Head & Dryer/Separator Sling Lifting Devices "
 SMITH.S K . VOCEL T N NUTECH (Nuclear Technology, Inc.)
 46P-77-008 62/09/29 14pp 15715 118 24X
 Fiche 50-263,82/10/11.8210150364
- --8210150500 "Design Spec for Reactor Vessol Head Lifting Device "
 FISCHER.L. VDGEL.T N . SMITH.J K NUTECH (Nuclear Technology,
 Inc.) NSP-77-001 ROO 82/09/24 9pp 15715 132 24X
 Fiche 50-263,82/10/11.8210150364
- --8210150504 "Evaluation of Selected Special Lifting Devices for Compliance W/NUREG-0612"
 SMITH.J K., VOSEL.T N. NUTECH (Nuclear Technology, Inc.)
 NSP-77-007 R00 B2/09/24 12pp 15715 141 24X
 Fiche 50-263,82/10/11.8210150364
- --8210150509 "Design Spec for Dryer & Steam Separator Sing Lifting Device "
 FISHER, L. VOCEL, T. N. SMITH, J. K. NUTECH (Nuclear Technology, Inc.) NSP-77-003 ROO B2/09/24
 Fiche 50-263.82/10/11.8210150364
- 6210190479 Informs that control room & technical support ctr habitability sys mod.per NUREO-0737. Item Ii D 3 4 will be delayed until 830515 due to need for design work untimely mati delivery & low productivity Revised schedule encl MUSOLF. D Northern States Power Co 82/10/13 Office of Nuclear Reactor Regulation, Director 3pp 15740 243 24X Fiche 50-263. 82/10/13. 8210190479
- 8210250320 Confirmatory action ltr relections util will undertake as result of 821014 meeting at Region 3 ofc relectack indications found on welds on recirculation sys piping KEPPLER. J G Region 3. Office of Director 82/10/19 LARBON. C E Northern States Power Co. 2pp 15790 224 24X Fiche 50-263. 82/10/19. 8210250320

- 8210240209 Forwards check to camplete fee payment for Addendum 1 to 801010 license amend request MUSCLFID Northern States Power Co 82/10/22 DIGOS,R M License Fee Management Branch 1p 15799 152 24X Fiche 50-263,82/10/22,8210240209
- Q inspection reports. IE Builetins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project 9pp 15645 027 24X Fiche 50-000.82/07/12.8210080015
- -8i05280476 Requests that regions confirm licenses submittal of rept for satisfactory implementation of Item 4 of IE Builetin 79-26. Revision I JORDAN.E L Division of Resident & Regional Reactor Inspection 8i/05/18 GRIER.B H Region 1. Philadelphia. Office of the Director (8i/03/01) O'RELLLY.J P Region 2. Atlanta. Office of the Director (8i/03/01) KEPPLER.J G Region 3. Chicago. Office of the Director (8i/03/01) Ip 15668 I30 24X Ficho 50-000,82/07/12,8210080015
- 82101503B5 Forwards IE Insp Rept 50-263/82-09 on 820703-0828 No noncompliance noted STREETER, JF Division of Project & Resident Programs 82/09/28 LARSDN. C E Northern States Power Co 2pp 15703 272 24X Fiche 50-263-82709/28
- --8210150386 IE Insp Rept 50-263/82-07 on 820703-0828 No noncompliance noted Major areas inspected LER followup, operational safety verification, fire protection/prevention, security personnel qualifications, operator overtime & onsite review committee BROWN, C H , MADISON, A L , WALKER, R D Division of Project & Resident Programs 82/09/28 5pp 15703 274 24X Fiche 50-263,82/09/28,8210150385
- 8210130166 Confirms plans for 821014 meeting in Olen Eilyn, IL to discuss proposed corrective action for cracks in welds on endcap of recirculation Loop A SPESSARD, R L Division of Project & Resident Programs 62/10/05 LARSUN.C E Northern States Power Co ip 15673 053 24% Fiche 50-263, 82/10/05.8210130166
- 8208190233 IE Info Notice 80-35, Suppl 1: "Leaking & Disiodged I-125 Implant Seeds" Svc list encl CUBD: L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761.280 24
- 8208190238 iE Bulletin 82-03, "Stress Corrusion Cracking in Thick-Waii, Large-Diameter, Stainiess Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYQUMO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Ca of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14.8208190238
- 8210230320 Confirmatory action ltr reactions util will undertake as result of 821014 meeting at Region 3 ofc re crack indications found on welds on recirculation sys piping KEPPLER.J O. Region 3. Office of Director 82/10/19 LARSON.C E Northern States Power Co 2pp 15790 224 24X Fiche 50-263.82/10/19.8210230320
- 8 Reportable occurrences, LERs & related correspondence
- 8210150174 Forwards LER 81-020/03L-0 MAYER.L O Northern States Power Ca 81/08/24 KEPPLER, J O. Region 3, Chicago Office of the Director (81/03/01) 1p 18707 193 24X Fichs 50-263.81/08/24.8210150174
- --8210150180 LER 81-020/03L-0 on 810724,main steam leak revealed in drain line to condenser Gaused by piping leaking immediately downstream of 45 degree elbow due to erosion & impingement resulting from steam & water flow from restricting orifice.
 TOBIN.F A Northern States Power Co 81/08/24 Region 3, Chicago, Office of the Director (81/03/01) ip 15707 174 24X Fiche 50-243,81/08/24,8210150174.
- 8210050182 PNO-III-82-103 on B20928, radiographs of recirculation loop cap A revealed four cracks extending from weld root into adjacent heat-affected zone No through-well cracking evident Repair procedures under evaluation WALKER, JORDAN, M Region 3, Office of Director 82/09/28 lp. 15603 344 24X Fiche 50-263, 82/09/26, 8210050182

- 8210150396 Forwards IE Insp Rept 50-261/82-29 on 620816-19 No noncompliance noted LEUIS.R C. Division of Project & Resident Programs 62/09/17 JONES.J A Carolina Power & Light Co 2pp 15704 035 24X Fight 50-261.82/09/17.8210150396
- --6210150401 IE insp Rept 50-261/82-29 on 620816-19 No noncompliance noted Major areas inspected radiological entreency preparedness CLINE.W E . JENNING.D R Division of Energincy Preparedness & Operational Support 82/09/16 19pp 19704 037 24% Fiche 50-261, 62/09/17, 8210150396
- 3210150493 Requests add1 info re util response to IE Bulletin GD-11.
 "Matenry Wall Design " Info required by 821122 to complete
 revisu
 VARCA: S A Decrating Reactors Branch 1 62/10/04 JQMES. J A
 Carolina Power & Light Co 4pp 15717 271 24X
 Fiche 50-261.82/10/04.8210150493
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Distodged I-125 Implant Seeds " Bvc list enc! C097.L 1 Division of Fuel Factitizes. Naterials & Rafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corresion Cracking in Thack-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Gwc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 62/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- B210220495 Ack recript of 821008 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/02-27 LEMIE-R C Division of Project & Resident Programs 82/10/18 UTLEV.E E Caroline Power & Light Co ip 15779 009 24X Fiche 50-261.821/07/18.8210220495
- --8210220499 Responds to NRC 82090B ltr re violations noted in IE Insp Rept 50-261/82-27 Corrective actions changes to plant operating namual included in permanent change book & operations revisions status list updated twice weekly STARKEY,R B Carolina Power & Light Co 82/10/08 D'RESCLY, J P Region 2. Office of Director App 15779 010 24X Fithe 50-261,82/10/18.8210220495
- --82102205GO Ferwards IE Insp Rept 50-261/82-27 on 820711-0810 & notice of violation LEMIS,R C Division of Project & Resident Programs 82/09/08 JONES,J A Caroline Power & Light Co 2pp 15779 014 24X Fiche, 50-261,62/10/18,8210220495
- --B210220501 Notice of violation from insp on 820711-0910 4 Division of Project & Resident Programs 82/09/08 2pp 15779-016 24X Fisha 50-261-82/10/18-8210220493
- --8210220504 IE Insp Rept 50-261/82-27 on 820711-0810 Noncompliance noted adequate review procedures not implemented for Maint Procedure HPI-10 for safety-related instrument valve itaugs.

 KRISE, 8, BURGER, C Division of Project & Resident Programs B2/09/02 IESP. 13779 018 24% Fiche 50-261.82/10/18.8210220495
- R Pariodic operating raports & related correspondence
- 8210130242 Forwards monthly operating rept for Bept 1982 STARKEY, R B Carolina Power & Light Co 82/10/08 DEYOUNG, R C Ulyactor's Uffice, Office of Inspection and Enforcement 19 15678 096 24% Fiche 50-R61.82/10/08.8210130242
- --8210130244 Honthly operating rept for Sept 1982 NORRIS.H.R. Carelina Power & Light Co. 82/10/05 3pp 15678 097. 24% Fichs: 50-261.82/10/08.8210130242
- & Reportable occurrences. LERs & related correspondence
- 8210220265 Forwards LER 82-012/03L-O.
 STARKEV.R. B Carolina Power & Light Co B2/10/06 D'REHLLY.J.P
 Ragion 2. Office of birector. ip. 15775 202 24X
 Fichs \$0-251,62/10/05.821022025
- --B210220267 LER 82-012/031-0. on 820706, at 74% power, letdown relief valve CVC-203 lifted & would not reseat Caused by eater hanner due to operator error in realignment of charging pump from restriculation to normal operation. Operator counseled, COX.H. T. Carolina Power & Light Co 82/10/06 Region 2, Office of Director 3pp 15776 203 24% Fiche 50-261,82/10/06, 8210220765.

- 0210190240 Forwards updated LER 80-027/017-1 STARKEY,R B Carolina Power & Light Co 82/10/11 U FEJLL' Region 2, Office of Director 1p 15742 196 "4x Fiche 50-261, 82/10/11, 8210190240
- --B210170244 Updated LER B0-027/017-1 on B0112d, relay HT V 30 "In protection train A failed to re-energize during periodic test of reactor protection logic Caused by shorting of Iril time connection to coil wires Relay replaced COX.H T Carolina Power & Light Co B2/10/11 Pagics 2 of Director App 15742 197 24X Fiche 50 Mil. 12/16/11 8210170240
- 8210290074 Forwards updated LER 81-031/01T-1 STARKEY.R B Carolina Power & Light Co (12/10/22 1) 141111 | Region 2. Office of Director 1p 15854 (12) 241 | Fiche 50-261, 82/10/22, 8210290074
- --0210290078 Updated LER 81-031/01T-1 on 811203 during hot it pressurizer PORV black valve operators did not fully and block valves Caused by improper maint Valves (loss) manually COX-H T Carolina Power & Light Co U2/10/22 heater 2 of Director 3pp 15854 029 24X Fiche 30 John 12/30/23 pp 27/22/20074
- 82:0290333 Forwards LER 82-013/03L-0 STARKEY,R 8 Cardina Power & Light Co 80/10/--/ 1/ first Region 2: Office of Director 1p 1585) 101 241 Fiche 30-261.8210/22.8210290333
- --B210270337 LER 82-013/03L-0 on 820923, svt water pine A failtrestart following periodic test Caused by failed cartest power fuses rupelaced & pump started & retexted COX.H T Carolina Power & Light Co Hd/10/dd Raji.-a of Director 2pp 15853 104 24X Fiche 30 additions & 8210270333
- DOCKET 50-260 MONTICELLO NUCLEAR GENERATINO PLANS
- F Security, medical, emergency & fire protection plant
- B210150385 Farwards IE Insp Rept 50-263/82-09 on B20A transformation noted STREETER, J.F. Division of Project & Resident Programs for LARSON C.E. Korthern States Power Co. 2pp 15/0121. 30 Fichs 50-263, 82/09/28, 8210150385
- -- E210150386 IE Insp Rept 50-243/82-09 on H20/01 (finite, -, -) noted Mayor areas inspected LER followup, operative a lata', varification fire protection/provention set unity pers, in qualifications, operator overtime & onsite several confidence (ROSM), C. H., MADISON, A. L., MALKER, R. D. Division of Fre, 14 Resident Programs 82/09/28 5pp 15/01 4/4 .44 Fiche 50-243, 82/09/28, 8210130395
- 8210240178 Requests that R Walter be added to link 1 (3). 'I to provide for unexcorted access to vital to proteins are KEPPLER, J O Region 3. Office of Director (0.410). In the Northern States Power Co. ip 15799 160 241 line (1.50) 62/10/20. 8210240178
- P Operating license stage documents & correspondents
- 8210040005 Responds to 820825 ltr re-spent fuel ruisin in the notification requirements of shipments of predease feel fuel contained in 10CFR73 37 MENCZER. H B Region 31 Office of Director flavoris 2(#1 Minnesota, Etate of 2pp 15577 262 24x highe: _sp E 8210040005
- 8210010060 Forwards andified info to 820707 susplement 4-75 s E01008 license amend request MUEDLF.D. Northern States Power Co 82/04/23 4748, p. p. 448 Reactor Regulation, Director 13pp 15567 154 mas Fiche 50-263.82/07/23.8210010060
- --8210010041 Proposed amend to License DPR-J2. changing 18-1 Section and strong areas of surveillance, reactor protection manistring bit. In purp surveillance, organization & steam line area tray suitch deviation (USDLF, D. Northern States Power Co. 82/09/24 12s) 12 24% Fiche 50-263, 82/09/24. 8210010036

- ~-8210010044 Proposed Tech Specs re surveillance reactor protection monitoring sys, jet pump surveillance organization & steam line area temp switch deviation

 # Northern States Power Co 82/09/24 40pp 15565 183 24X
 Fiche 50-263,82/09/24,8210010036
- 8210060377 Forwards application for amend to License DPR-22.App A Amend changes Pages 207 & 209 to remove 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant MUSOLF. D Northern States Power Co 82/07/30 Office of Nuclear Reactor Regulation. Director ip 15615 340 24X Fiche 50-243.82/09/30.0210060377
- --82100603HD Application for amend to License DPR-22. App A Amend changes Pages 207 & 209 to remove 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblaces exist in quadrant MUSOLF. D. Northern States Power Co. 82/09/30 4pp 15615-341 24X Fiche 50-263, 82/09/30, 8210060377
- --8210050386 Proposed Tech Specs 3/4 10.removing 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant + Northern States Power Co. 82/09/30 2pp 15615-345 24X Fiche 50-263,82/09/30,8210050377
- 8210)30261 Submits add1 info re application for single loop operation license amend, in response to NRC 820920 request MAPLHOR reduction factors reviewed by GE & found applicable to Cycle 10 MUSDLF, D. Northern States Power Co. 82/10/05 Diffice of Nuclear Reactor Regulation, Director ip 15676-014 24X Fiche 50-263.82/10/05.8210130261
- 9210130260 Discusses implementation of NRC guidelines for working hours, provided in Generic Ltr 82-12 Revised guidelines have been implemented, w/exceptions of 72-h per wk limitation & relief from control board duties MUSQLF. D. Northern States Power Co. 82/10/07 Office of Nuclear Reactor Regulation. Director 2pp. 15676-012 24% Fishe 50-000, 82/10/07, 8210130260
- 82:0150364 Forwards response to request for info in Sections 2 2 % 2 3 of General Ltr 81-07 re overhoad handling sys Revised 9 month submittal, "Control of Heavy Loads" & review of special lifting devices also encl MUSULF.D Northern States Power Co 82/10/11 Office of Nuclear Reactor Regulation, Director 16p 15715 102 24X Fishe 30-263, 82/10/11.8210150364
- -8210150377 "Evaluation of Conformance w/NUREG-0612 for Drywell/Reactor Vessel Head & Dryer/Separator Sling Lifting Devices " SHITHS K . VOCEL T N KUTECH (Nuclear Technology, Inc.) NSP-77-008 82/09/29 14pp 15715 11B 24X Fiche 50-263.82/10/ii-8210150364
- --0210150500 "Design Spec for Reactor Vessel Head Lifting Device " FISCHER. L. , VODEL, T. N. , SMITH, J. K. NUTECH (Nuclear Technology, Inc.) NSP-77-001 R00 82/09/24 9pp 15715 132 24X Fiche 50-263,82/10/11/8210150364
- --8210150504 "Evaluation of Selected Special Lifting Devices for Compliance W/NUREG-0612"
 SMITH, J K. VOGELT N NUTECH (Nuclear Technology, Inc.)
 NGP-77-007 R00 82/09/24 12pp 15715 141 24X
 Fiche 50-263.82/10/11.8210150364
- --8210150509 "Design Spec for Dryer & Steam Separator Sling Lifting Device" FISHER, L., VOOEL, T. N., SMITH, J. K. NUTECH (Nuclear Technology, Inc.) NSP-77-003 ROO 82/09/24 9pp 15715 153 24X Fiche 50~263,82/10/11,8210150364
- S210190479 Informs that control room & technical support ctr habitability sysmodiper NVREG-0737. Item II D 3 4 will be delayed until 830515 due to need for design work untimely mati delivery & low productivity Revised schedule encl MUSQLF.D. Northern States Power Co. 82/10/13. Office of Nuclear Reactor Regulation, Director Spp. 15740-263. 24X Fiche 50-263. 82/10/13, 8210190479
- 8210250320 Confirmatory action ltr relactions Util will undertake as result of 821014 meeting at Region 3 ofc relactions from on welds on recinculation syspaping KEPPLER. J.O. Region 3. Office of Director 82/10/19 LARSON.C.E. Northern States Power Co. 2pp 15790 224 24X Fiche 50-243. 82/10/19. 8210250320.

- 8210260209 Forwards check to complete fee payment for Addendum 1 to 801010 lacense amend request MUSDLF.D Northern States Fower Co 82/10/22 DIGOS,R M License Fee Management Branch 1p 15799 152 24X Fiche 50-263,82/10/22, 8210260209
- Q Inspection reports. IE Bulletins & correspondence
- B210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON. J M Division of Rules and Records B2/07/12 UDELL,R A Critical Mass Energy Project 9pp 15665 027 24X
 Fithe 50-000. 82/07/12, B210080015
- -8105280476 Requests that regions confirm licensee submittal of rept for satisfactory implementation of Item 4 of IE Bulletin 79-26. Revision i JGRDAN.E.L. Division of Resident & Regional Reactor inspection 81/05/18 ORIER.B H Region I. Philadelphia. Office of the Director (81/03/01) O'REILLYJ P Region 2. Atlanta, Office of the Director (81/03/01) MEPPLER.J G Region 3. Chicago. Office of the Director (81/03/01) ip 15668 130 24% Fiche 50-000.82/07/12.8210080015
- 8210150385 Forwards IE Insp Rept 50-263/82-09 on 820703-0828 No noncompliance noted STRECTER, J. F. Division of Project & Resident Programs 82/09/28 LARSON, C. E. Northern States Power Co. 2pp 15703 272 24X Fiche 50-263
- --8210150386 IE Insp Rept 50-263/82-07 on 820703-0828 No noncompliance noted Major areas inspected LER foliousproperational safety verification, fire protection/prevention, security personnel qualifications, operator overtime & onsite review committee BROWN.C H , MADISON.A L , WALKER.R D Division of Project & Resident Programs 82/09/28 5pp 15703 274 24X Fichs 50-263,82/09/28,8210150385
- 8210130166 Confirms plans for 821014 meeting in Olen Eliyn, IL to discuss proposed corrective action for cracks in welds on endcap of recirculation Loop A SPESSARD, R L Division of Project & Resident Programs 82/10/05 LARSON, C E Northern States Power Co 1p 15673 053 24X Fiche 50-263, 82/10/05.8210130166
- 8208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06.8208170233
- 820Bi9023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Walk.Large-Diameter.Stainless Steel.Recirculation 89;
 Plping at NWR Plants "Svc list encl
 DEYOUND, R C Director's Office, Office of Inspection and
 Enforcement B2/10/14 Consolidated Edison Co of New York
 115pp 15810,125 24X Fichs 50-000.82/10/14,820819023B
- 8210250320 Confirmatory action ltr relactions util will undertake as result of 821014 meeting at Region 3 ofc relactions found on welds on recirculation sys piping KEPPLER. J O Region 3. Office of Director 82/10/19 LARSON. C E Northern States Power Ca 2pp 15790 224 24X Fiche 50-263,82/10/19.8210250320
- 8 Reportable occurrences, LERs & related correspondence
- 8210150174 Forwards LER 81-020/03L-0 MAYERL D Northern States Power Co 81/08/24 KEPPLER, J G, Region 3, Chicago, Office of the Director (81/03/01) 1p 15707 193 24X Fiche 50-263.81/08/24.8210150174
- --8210150180 LER B1-020/03L-O on 810724, main steam leak revealed in drain line to condenser Caused by piping leaking immediately downstream of 45 degree elbow due to erosion & impingement resulting from steam & water flow from restricting origines TOBIN:P A Northern States Power Co 81/08/24 Region 3, Chicago. Office of the Director (81/03/01) 1p (5707 194. 24X Fiche 50-263,81/08/24,8210150174
- 8210030182 PNO-III-82-103 on 820928, rediographs of recirculation loop cap A revealed four cracks extending from welf root into adjacent heat-affected zone. No through-wall cracking evident Repair procedures under evaluation WALKER, R., JORDAN, M. Region 3, Office of Director 82/09/28 ip. 15603 344 24X Fiche 50-263, 82/09/28, 82/050182.

- 210080117 RQ on 820928, crack indication in end cap of A recirculation riser confirmed by radiography Indications initially detected by ultrasonic etam during normal inservice insp Ramedial measures under investigation SHAMLA-N A Northern States Power Co 82/09/28 KEPPLER-J G Region 3. Office of Director ip 15540 204 24X Fiche 50-263, 82/09/28, 8210080117
- 210060258 Forwards LER 82-008/03L-0 MUSOLF.D Northern States Power Co 82/09/29 Region 3. Office of Director 1p 15621 067 24% Fiche 50-263.82/09/29.8210060258
- -8210060260 LER 82-008/03i-0 on 820830.RCIC barameter condenser cooling water supply valve failed Caused by severed stem dus to Rotork motor operator torque switch misadjustment Valve stem replaced HOUCHGUSKI.A V Northern States Power Co 82/09/29 Region 3. Office of Director ip 15621 968 24X Fichs 50-263.82/09/29, 8210060258
- 210190289 Forwards LER 62-016/017-0 MUSDLF.D Northern States Power Cq 62/10/12 Region 3. Office of Director 1p. 15742 175 24X Fichs 50-263,82/10/12.8210190289
- -8210190293 LER 82-016/01T-O on 820928, three indications in 22-inch diameter reactor recirculation sys riser manifold and cap confirmed as rejectable Caused by interpranular stress corrusion cracking End cap to be replaced HAKMER, S Northern States Power Co 82/10/12 Region 3, Office of Director ip 15742 176 24X Fiche 50-263,62/10/12, 8210190289

OCKET 50-264 DON CHEMICAL CO

' Insurance & indemnity information

2:004023f Forwards Endorsements 47 & 48 to NELIA Policy NF-160
Endorsement 47 amends description of Pacility to include
Lartin Lab
COALWELL-T N Dow Chamical Co 82/09/29 SALTZMAN. J D Antitrust
E-Connomic analysis Branch (Utility Finance) 3pp 15586 111 24X
Fiche 50-264,82/09/29,8210040231

Operating license stage documents & correspondence

- 210180028 Responds to FDIA request for seven categories of documente re Dou Chemical Co & incineration of low level radwasts Request for fee waiver granted Forwards listed documents FECTON-J H Division of Rules and Records 82/09/20 WILSON, A K. Affiliation Unknown 2pp 15748 002 24X Fiche 50-264,82/08/20,8210180028
- -8210180237 Application for renewal of Mati/Byproduct Licenses 21-00265-06,21-00265-02,21-00265-04,21-00265-07,5NM-1253, 518-927 & R-108 authorlying any byproduct matl between Atomic Numbers 3 & B3, tritium Po-210 & Am-241 HOYLE: H R Dow Chemical Co 73/06/25 2pp 15748 L15 24X F1che-50-264,82/08/20,8210180028

Reportable occurrences. LERs & related correspondence

210290202 RD on 821006, maifunction of Eberline AMS-3 continuous air monitor pump caused pump to be inogerable for approx i-h. No loss of significant signals indicated Pump repaired Changes to procedures or equipment under review RAMPY, L. H., KNOLL, F. J. Daw Chemical Co. 82/10/20 MILLER, J. R. Standerdiration & Epecial Projects Branch 1p. 15853-354 24X Fiche 50-264, 82/10/20.8210290202

DCKET 50-265 QUAD-CITIES STATION. UNIT 2

Security, medical, emergency & firs protection plans

- 209270125 Releases public version of revised generating station emergency plan corporate command ctr emergency plan implementing procedure FELTON-J M. Division of Rules and Records 82/09/16. Document Management Branch 1p. 15564:122 24X Fiche 50-000,82/09/16,8209270125
- -8209290189 Forwards public version of Revision 4 to generating station smargancy plan corporate command ctr Emergency Plan Implementing Procedure EOF-3. "Environ/Emergency Coordinator." Receipt form enci PAJOMSKI, J E Commonwealth Edison Co 82/09/01 DENTON, H R NRC No Detailed Affiliation Given Ip 15564-123. 24X Fiche: 50-000,82/09/16,8209290125

- ---8207270225 Public version of Revision 4 to generating station emergency plan corporate command ctr emergency plan inplementing Procedure EOF-3, "Environ/Emergency Coordinator"

 PAUDUSKIJ E Commonwealth Edison Co 82/08/31 11pp 15564 124 24% Fiche 50-000, 82/07/16.8207270125
- 8210010009 Forwards info to suppl 820701 request for exemption Irca #1 R per 820917 telcon Request applies to Sections III 0 2 a & III 0 3 b re installation of fire suppression sys RAUBCH.T J Commonwealth Edison Co 62/09/23 EISENBUT, P. 0 Division of Licensing 8pp 15545 152 24X Fiche 50-000.62/09/3 REPORTION OF SECOND ON SECOND OF SECOND ON SECOND OF SECOND ON SEC
- 6210120546 Releases public version of revised cover shoet to facilite procedures
 FELTON.J H Division of Rules and Records 82/09/24 Dacument Management Branch ip 15672 219 24X Fiche 50-254, D2/09/24 8210120546
- --8210120551 Forwards public version of revision cover sheet to facil's procedures Completion of encl checklist requested KALIVIANAKIS.N Commonwealth Edison Co. 82/09/15 DENIGN.H H. Office of Nuclear Reactor Regulation. Director Spp. 196/18 229 24X Fiche 50-254.82/09/24.8210120546
- 8210150487 Forwards IE Insp Repts 50-254/82-14 & 50-265/82 16 on 820823-25 & 0903 & 09 No noncompliance noted KEPPLER.J G Region 3. Office of Director 82/09/30 R[{0 Commonwealth Edison Co 3pp 15721 289 24X Fichs 50 294.83/67/3 9210150487
- --8210150495 IE Insp Repts 50-254/82-14 & 50-265/82-16 on (\$20021 a) \$
 0903 & 09 No noncompliance noted Major areas inspected
 emergency preparedness exercise & incensee actions on
 previously identified emergency preparedness items
 PHILLIPS N P Division of Emergency Preparedness & (\$perational
 Bupport B2/09/29 (5pp 1572) 292 24% Fiche 50 294.82/09F5
 8210150487
- 8210130376 Advises that installation of offsite dose calculation Mysprogram Fully operations tracking model & operational A model will be delayed until 821231 to complete prima computer installation SMARTS, E D Commonwealth Edison Co 82/10/06 DEMIGN, II 8 (1864) of Nuclear Reactor Regulation, Director 2pp 15602 099 348 Fiche 50-000, 82/10/06, 82/0130376
- 8210270047 Releases public version of revisions to Qued Cittes. Jun 1
 Dresden emergency plan annuases & revised generating
 station emergency plan telephone directory
 FELTON. J M Division of Rules and Records 82/10/00 Document
 Management Branch is 15877 313 24X Fiche 50-000, 62/10/00
 8210270047
- --8210290060 Forwards public version of Revision 3 to Quad ('tips t].

 emergency plan ennexes.Revision 2 to Dresden emergency plan
 annex.Revision 0 to Byron emergency plan annex & revised
 generating station emergency plan telephone directory
 MODRE:R D Commonwealth Edison Co 82/07/30 DENION, H R MR:
 No Detailed Affiliation Given Spp 15877 314 24X
 Fichs 50-000.82/10/08.8210290047
- --8210290077 Public version of Revision 3 to Gued Cities & Jish emergency plan annexes. Revision 2 to Dresden emergency plan annex & Revision 0 to Byron emergency plan annex * Commonwealth Edison Co 82/06/30 325pp 15877 314 248 Fiche 50-000, 82/10/08 8210290047
- --8210290088 Public version of revised generating station energants; talephone directory GALE, DP Commonwealth Edison Co 82/08/12 43pp 150/B 288 24X Fichs 50-000,82/10/08/8210290047
- 8210190753 Forwards 820922 itr relate submittals of exercise scenarios & failure to adhere to FEMA Quidance Mamo 17 if FEMA does not observe exercise, offsite authorities will not participate
 HND, J, A Division of Emergency Preparedness & Operational Busiest 82/10/12 REED, C Commonwealth Edison Co 2pp 13736 947 241 Fiche 50-254 82/10/12, 8210190753
- ----B210190760 Discusses concerns relate submittels of emergency field, scenarios & failure to athere to FEMA Guidance Memo 17 Foture exercise not maseling intent of advance notification guidance should be postponed or canceled BREHEMY.P. J. Federal Emergency Nanagement Agency 82/09/22 KEPPLER.J G. Region 3. Office of Director ip 15736 249 241 Fiche 50-254,82/10/12,8210190753.

- 8210280361 Releases public version of revised emergency plan implementing procedures FELTON.J H Division of Rules and Records 82/10/12 Document Management Branch ip 15859 204 24X Fiche 50-254,82/10/12,8210280361
- --B210280364 Forwards public version of revised emergency plan implementing procedures including Procedures QEP 200-0 re emergency conditions, QEP 200-11 re emergency action levels & QEP 330-3 re Splink control terminal operation KQVACK, T S . QERNER.L F Commonwealth Edison Co 82/09/23 DENFON,H R NRC No Detailed Affiliation Given 2pp 15859 205 24X Fiche 50-254,82/10/12,8210280361
- --8210280375 Public version of revised emergency plan implementing procedures, including Procedures QEP 200-0 re emergency conditions, OEP 200-17 re emergency action levels & OEP 330-3 re SPINO control terminal operation communication between Communication of SPINO control terminal operation at Communication Co. 82/09/23 21pp 15859 207 24X Fiche 50-254, 82/10/12, 8210280361
- 8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs

 IRAMH.TR Commonwealth Edison Co 82/10/14 DENTON, HR Office of Nuclear Reactor Regulation, Director 9pp 15776 287 24X Fiche 50-000.82/10/14.8210220358
- 82:0250309 Responds to 820917 telcon request for info re fire protection safe shutdown rept Items 2 & 3 are preliminary results, subj to revision following engineering review RAUBCH.T J Commonwealth Edison Co 82/10/18 EISENHUT, D G D3V1510n of Licensing App 15790 215 24X Fiche 50-254,82/10/18,8210250309
- P Operating license stage documents & correspondence
- G210050142 Requests that charcoal adsorber £64-DYH2 be counted within 2 Uks of receipt decay corrected to 790319 levels & returned Liquid beta analyses results received in NRC B20917 itr will be incorporated in rept addendum PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 82/09/28 KALIVIANAKIS, N. Commonwealth Edison Co. ip 15605 167 24% Fiche 50-254, B2/09/28, B210050142
- 82:0120105 Requests delay of implementation dur dates re NUREO-0/37. Items 11 B 2, "Plant Shielding," II B 3, "Post-Accident Sampling" & II F 11. "Noble Qas Effluent Honitor" SHARTZ.E D Commonwealth Edison Co 82/10/04 EISENHUT, D Q Division of Licensing Spp 15651 237 24% Fiche 50-000,82/10/04,82:0120105
- 5210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" GDLDEN.J C Commonwealth Edison Co 82/10/06 CASE,E 0 Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fische 50-000, 82/10/06
- --B210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Hanual" Commonwealth Edison Co 82/09/30 83pp 15805 i39 24X Fiche 50-000,82/10/06.8210260526
- 6210180059 Provides addi guidance & clarification re 820806 request for add1 info per NUREG-0737. Item II B 3. "Post-Accident Sampling Sys " Detailed reliability analysis not required to satisfy NRC concerns CRUICHFIELD, D Operating Reactors Branch 5 82/10/08 DELOEDRGE, L Commonwealth Edison Co 3pp 24X Fiche 50-000. 82/10/08, 8210180059
- G210190780 Forwards "GE BWR Extended Load Line Limit Analysis for Guad Cities Nuclear Power Station Unit 1.Cycle 7 & Unit 2.Cycle 6 '
 RAUSCH.T J Commonwealth Edison Co 82/10/12 EISENHUT, D G
 Division of Licensing ip 15736
- --8210190785 "OE BWR Extended Load Line Limit Analysis for Quad Cities Nuclear Power Station, Unit 1. Cycle 7 & Unit 2, Cycle 6." * General Electric Co NEDO-22192 82/07/31 31pp. 15736-207 24% Fiche 50-284,82/10/12.8210190780
- 8210190445 Forwards supplemental response to Generic Ltr 82-05 re implementation status of NUREO-0737, Items II B 3, II F i 2, II F i 3, II F i 5 & II F i 6, in response to 821004 request SHARTZ, E D Commonwealth Edison Co 82/10/14 EISENHUT, D O Division of Licensing 5pp 24X Fiche 50-000, 82/10/14, 8210190445

- B210230155 Forwards corrections to proposed Tech Spec Pages 1 2/2 2-1 & 3 3/4 3-5, supporting review of future reloads & revised Figure 3 5 in Sheet i, providing extended MAPLHOR vs exposure curves for barrier lead test assembly fue! RAUSCH.T J Commonwealth Edison Co 82/10/18 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 15788 233 24% Fiche 50-000, 82/10/18, 8210250155
- --8210250177 Errata & Addenda Sheet B.replacing Page 4-10 to "LCCA Analysis Rept for Dresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations" 4 General Electric Co NEDD-24146A ERR 08 82/09/30 3pp 15768 239 24X Fichs 50-000,82/10/18,8210250155
- 9210250069 Provides addi info re reactor water cleanup room area temp monitors Temp elements cause no automatic plant response beyond control room alarms
 RAUSCH, T. J. Commonwealth Edison Co. 82/10/19 EISENHUT, D. C. Division of Licensing 2pp 15787 081 24% Fiche 50-000, 82/10/19, 8210250049
- Q inspection reports, IE Bulletins & correspondence
- 8210150487 Forwards 1E Insp Repts 50-254/82-14 % 50-265/82-16 on 820823-25 % 0703 % 09 No noncompliance noted KEPPLER, J G Region 3. Office of Director 82/09/30 REED, C Commonwealth Edison Co 3pp 15721 289 24% Fiche 50-254.82/09/30, 8210150487
- --8210150495 IE Insp Repts 50-254/82-14 & 50-265/82-16 on 820823-25 & 0903 & 09 No noncompliance noted Major areas inspected emergency preparedness exercise & licensee actions on previously identified emergency preparedness items PHILLIPS:M P , SMITH:M J , AKELSON,W L Division of Emergency Preparedness & Operational Support 82/09/29 15pp. 15721 292. 24X Fiche 50-254,82/09/30,8210150487
- B210060359 Ack receipt of 820710 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 PRESARD, R L Division of Project & Resident Programs B2/10/01, REED, C Commonwealth Edison Co 1p 15618 394 24X Fiche 50-000, 82/10/01, 8210060359
- --8210040347 Responds to NRC 820712 ltr re violations noted in IE Insp Repts 50-237781-39, 50-249/81-32, 50-284/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 Corrective actions training for mgt priorities re plant availability will be conducted REED. C. Commonwealth Edison Co. 82/09/10 KEPPLER, J. O. Region 3. Office of Director 13pp 15418 355 24X Fiche 50-000, 82/10/01, 8210040339
- 8210080178 Forwards listing of piping sys which fail to meet F8AR requirements, par NRC 800818 confirmatory action ltr IE Bulletin 79-14 operability evaluation updates will not be provided for Dresden & Quad Cities Final update by Dec 1982 RAUBCH, T J. Commonwealth Edison Co 82/10/01 KEPPLER, J & Regio 3, Office of Director 6pp 15640 159 24X Fiche 50-000,82/10/01,8210080178
- 8210060266 Confirms 821103 enforcement conference at Region 3 ofc re QA aspects associated w/grocurement.installation & use of non-qualified valve guides in electramagnatic rellef valves at facilities

 8PESBARD.R L Division of Project & Resident Programs, 82/10/04

 REED.C Commonwealth Edison Co ip 15640:181 24X

 Fiche 50-000.82/10/04.8210080:90
- 8208170233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBs.L ! Division of Fuel Facilities, Materiale & Safeguards, 82/10/06 Consoitdated Edison Co of New York 66pp 18761.250 24X Fiche 50-000.82/10/06.8208190233
- B20Bi9023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation SysPiping at BWR Plants " Svc list encl
 DEYOUND.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York
- R Periodic operating reports & related correspondence
- 8210130386 Forwards monthly operating repts for Bept 1982, KALIVIANAKIS, N Commonwealth Edison Co 82/10/01. Director's Office, Office, of Inspection and Enforcement 19, 15680-339 24X Fiche, 50-254, 82/10/01.8210130386.
- --B210130390 Monthly operating repts for Sept 1982 BUSS.R.D Commonwealth Edison Co 82/10/04 13pp 15680 341. 24X Fiche.50-254,82/10/01.8210130386

S Reportable occurrences. LERs & related correspondence

B210260467 PNO-III-82-II2 util notified that high density fuel storage racks installed do not meet design criteria for spacing due to bouing condition Hanufacturer reanalyzed seismic response of racks & concluded bowed distance acceptable GROBE, J. WALMER, R. STREETER, J. Region 3, Office of Director B2/10/18 pp 15806 207 20% Fiche 30-234/82/10/18 8210260467

DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT I

F Security, medical, emergency & fire protection plans

8210040119 Discusses revision of plant emergency response procedures specifying necessary precautions required before post-accident re-entry into auxiliary bidg or facads, in response to 820914 request for info re NUREO-0737, Item II B 2 FAY, C H Wisconsin Electric Power Co 82/09/24 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 2pp 15581 201 24X Fiche 50-266, 82/09/24, 8210040119

B210050272 Forwards add1 info requested in NRC 920916 telcon to support util 820630 App R exemption request Eight oversize drawings encl Aperture cards are available in PDR FAY.C W Hisconsin Electric Power Co B2/09/29 DENTON, H R Office of Nuclear Reactor Regulation. Director CLARK.R A Operating Reactors Branch 3 13pp 15606 047 24X Fiche 50-266.82/09/29.8210050272

8210050054 Forwards add1 info re proposed mods for emergancy support ctr FAY.C W Wisconsun Electric Power Co. 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 16pp 15603 328 24X Fiche 50-266,82/09/30,82

8210270254 Releases public version of revised emergency plan implementing procedures
FELTON J H Division of Rules and Records B2/10/08 Document Management Branch ip 15834 001 24X Fiche 50-266, 82/10/08. 8210270254

--B210270259 Forwards public version of revised emergency plan implementing procedures including Procedures EPIP [] reinitial classification, EPIP 1 3 re estimation of source term & EPIP 1 4 re radiological dose evaluation FAV.C M Hisconsin Electric Pewer Co 82/09/10 DENTON.H R Office of Nuclear Reactor Regulation, Director CLARK,R A Operating Reactors Branch 3 4pp 15834 002 24X Fiche 50-264, B2/10/08.B210270256

--8210270261 Public version of revised emergency plan implementing procedures including Procedures EPIP i 1 re initial classification EPIP i 3 re estimation of source term & EPIP i 4 re radialogical dose evaluation

* Wisconsin Electric Power Co 82/09/10 244pp 15834 006 24X Fiche 50-286,82/10/08.8210270256

6210130471 Forwards add1 info re 620630 requests for exemption from 10CFR50 App R concerning Fire Area 9, control room & vertical cable trays in response to 821001 & 06 telcons w/NRC W/16 oversite drawings Apprivar cards in PDR FAY, C W Hisconsin Electric Power Co 62/10/11 DENTON, H. R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 12pp 15734 350 24X Fiche: 50-266, 82/10/11, 8210150471

O Adjudicatory correspondence

B210040125 Amend to HI Environ Decade B20810 petition to intervene including affidavits requesting HI Environ Decade to intervene on affiant behalf Certificate of Syc enci ANDERSON, P Wisconsin's Environmental Decade 82/09/28 Commissioners 5pp 15581 196 24X Fiche, 50-266, 82/09/28, 8210040125

B210050251 Memorandum & order granting summary disposition of all WI Environ Decade issues arrept issue of demonstration of adequacy of eddy current testing to detect cracking BLOCH.P B · KLINE.J R · PAXTON.H C. Atomic Safety and Licensing Board Panel. B2/10/01. Wisconsin's Environmental Decade. 19pp 13610 306. 24K Fiche 50-266.82/10/01/8210050251

B210050275 Decision ALAB-696 affirming ASLB B11105 order permitting plant to return to syc after refueling outage during which licenses planned to repair degraded steam generator by sleeving TOMPKINS, B.A. Atomic Bafety and Licensing Appeal Panel 82/10/01, 34pp 15611: 197. 24X Fiche: 50-266,82/10/01,8210050275.

8210120267 Forwards documentation re steam generator replacement application filed prior to 820819 establishment of ASLB Documentation consists of steam generator repair repts & correspondence between incenses & Commission M/O encl RIDOWAY, D.A. Shaw, Pittman, Potts & Trowbridge RIDOWAY, D.A. Wisconsin Electric Power Co. 82/10/07 KLINE, J.R., PAXTON, R.C. Atomic Safety and Licensing Board Panel 3pp 15652 327 24x Fiche 50-266,82/10/07.8210120267

8210200027 Notice of 821117-20 evidentiary hearing in Two Rivers, Hi to adequacy of inservice nondestructive testing of sleeves proposed to be used to repair corroded steam generator tubes Prehearing conference to be held after hearing ULOCH, P. B. Atomic Safety and Licensing Board Panel 62/10/15 | 15756-325 24X Fichs 50-266,82/10/15,8210200027

8210200055 Response to WI Environ Decade 820928 amend to petition to intervene Decade established standing but affiant P Anderson must demonstrate authority to act on behalf of Decade Certificate of Svc enci
BACHMANN, R O , MCGURREN, H J Hearing Branch 1 82/10/18 Attags Safety and Licensing Board Panel 4pp 15753 006 24% Fiche 50-266.82/10/18.8210200055

G210250120 Notice of appearance in proceeding Certificate of Buc enri ANDERSON,P Wisconsin's Environmental Decade 82/10/20 dpp 15787 116 24X Fiche 50-266:82/10/20.8210250120

82(0220242 Notice of rejocation of 821117-20 hearing from Two flivers be to Milwaukee, WI Limited appearance statements will be taken at original location on 821117
8LOCH.P B Atomic Safety and Licensing Board Panel 82/10/21 I; 15775 351 24X Fiche 50-266,82/10/21,8210220242

8210260404 Ack receipt of B21018 ltr requesting documents Util will cooperate but is not required to respond since nonparties not entitled to discovery CHURCHILL.B W Shaw Pittman. Potts & Trowbridge B2/10/22 ANDERSON.P Wisconsin's Environmental Decade 3pp 15803 319 las Fiche 50-266.82/10/22.8310260406

8210280253 Advises that util requested to send FSAR Chapter 14 "Safrig Analyses" to WI Environ Decade, in ref to 821018 telcon 8vc list enci Related correspondence CHURCHILL, 8 W Shaw, Pittman, Potts & Trowbridge CHURCHILL, 8 W Wisconsin Electric Power Co 82/10/25 ANDERSON, P Wisconsin 6's Environmental Decade 2pp 15839 027 24X Fichs 50-266.82/10/23 8210280253

K Utility Final Safety Analysis Report (FSAR) & amends

8207290257 Chapter 4 to Point Beach updated FSAR. "RC8 "

• Wisconsin Electric Power Co 82/07/21 102pp 14821 074 24:
Fiche 50-266.82/07/21.8207290257

8207290279 Chapter 1: to Point Reach updated FSAR, "Waste Disposal & Radiation Protection Sys "

* Wisconsin Electric Power Co 82/07/21 126pp 14823 371 241 , Fiche 50-266, 82/07/21, 9207290279

P Operating license stage documents & correspondence

B210210009 Recommends review of design of interconection between redundant safety-related electrical load groups Design should be modified to assure full compliance w/Reg Quids 1 6 MICHELBON.C Director's Office 80/08/27, DENTON, If R Director's Office, 2pp 15782 209 24% Fiche 50-266.80/08/27, D20210009

621001000B Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON.J H Division of Rules and Records 82/06/20 UDELL.R A Critical Hass Energy Project 15pp 15727 005 24X Fiche 50-000, 82/06/28, 8210010008

--B002i40204 Forwards avaluation of proposed Tech Specs change to ejerfacility at 2250 or 2000 psia Proposed changes are acceptable Myd enci CHECK.P S. Reactor Gafety Branch 79/12/26 BCHWENCER.A Operating Reactors Branch 1 (Pre B00428) 6pp 15727.030 241 Fiche 50-000.82/06/29.8210010008

8210070007 Responds to FOIA request for eight categories of recording steam generators & steam turbines. App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON. J. H. Division of Rules and Records 82/08/10 LOW. D J Winthrop. Stimson. Putnam & Roberts 9pp 15645 043 R4X Fiche 50-000, 82/08/10, 8210070007

- --7812200285 Summarires steam generator tube leak on 780920 & insp Leak rate reached 560 gpd at 5 00 AM, caused by two tubes w/cracks located w/in thickness of tube sheet & one tube w/leaky plug General cause plant conversion to AVT MOGNAM. V S Engineering Branch (Pre 791030) 78/12/12 ORIMES. B X Assistant Director for Engineers & Projects (Pre 790623) 2pp 1545 244 24X Fiche 50-000.82/08/10.8210070007
- --7909280105 Discusses steam generator tube leak & inservice insp Steam generator caused by deep crevice cracking of three tubes within tube sheet Not leg tube tests indicated 52 tubes w/deep crevice cracking in excess of 50% plugging limit MODNAH, V S Engineering Branch (Pre 791030) 79/08/17 EISENHUTL D G Division of Operating Reactors 3pp 15645 254 24X Fiche 50-000,82/08/10.8210070007
- --8004300616 Requests that util provide BNL w/tube samples for examination Forwards list of tubes (GCNAN) V S Engineering Branch 80/04/14 SCHWENCER, A Operating Reactors Branch (Pre 800428) 2pp 15645 266 24X Fiche 50-000,82/08/10,8210070007
- -8009040493 Forwards safety evaluation of Aug 1980 steam generator insp Concludes generators may be operated safely per 791130 & 800103 orders PAHLICKIS S Materials Engineering Branch 60/08/08 CLARK.R A Operating Reactors Branch 2 ip 15645 309 24X Fiche 50-000,82/08/10.8210070007
- --2009040497 Safety evaluation supporting operation of steam generators per 791130 & 800103 orders * Materials Engineering Branch 80/08/08 7pp 15645 310 24X Ficha 50-000.82/08/10.8210070807
- --Bli0290050 Advises that technical reviewers providing input for BER nust be available to testify at Bil029-31 hearings Schedule & agenda info encl CLARK-R A Departing Reactors Branch 3 B1/10/20 MURPHY.E , PEHEMIAS.J , MD.T NRC -- No Detailed Affiliation Oven 3pp 15645 271 24X Fiche 50-000, 82/08/10.8210070007
 - 8110300460 Requests evaluation by 811023 of util 810702 application for license amend to permit steam generator tube sleaving Info to be presented at ASLB 811029-30 hearing COLBURN, TO Operating Reactors Branch 3 81/10/19 BALLARD, R L Environmental Engineering Branch ip 15645 270 24X Fichs 50-000, 82/08/10.8210070007
- --+111090062 Forwards safety evaluation for proposed steam generator sleeving demonstration covering radiation protection & ALARA aspects KREGER.41 E. Assistant Director for Radiation Protection 81/10/22 NOVAK.TA. Assistant Director for Operating Reactors 4pp. 15645-276. 24X Fiche S0-000.82/08/10.8210070007
- --Biii24007: Submits review of util request to demonstrate tube sleeving program Activities of proposed demonstration will not result in any significant environ impact BALLARD.R L Environmental Engineering Branch Bi/10/23 CLARK.R A Operating Reactors Branch 3 ip 15645 280 24X Fiche 50-000, B2/08/10.6210070007
- --8202120129 Discusses environ review of application for steam generator tube sleeving program Environ impact insignificant BALLARD.R L Division of Engineering 82/01/25 CLARK.R A Operating Reactors Branch 3 ip 15645 282 24X Fiche 50-000.82/08/10.8210070007
- --8210070185 Responds to 750320 question concerning licensing action re Pacility steam generator tube rupture incident M/o enci preliminary results of tube inspiperformed by licensee, Tech Specs & related info GULLER.K R Division of Reactor Licensing (NRR-1975 only) /5/03/31 GALLO,J Hearings Division ip 15445 201 24X Fiche 50-000.82/08/10,8210070007
- --8210070187 Informs of incorrect info contained in third paragraph of Encl 2 to 750331 memo re facility steam generator tube rupture incident Corrected paragraph submitted QCLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/04/09 QALLO, J Hearings Division 2pp 15645-202 24X Fichs 3D-000,82/08/10,8210070007
- --8210070191 Requests technical assistance re 750226 steam generator tube leakage incident Review of enci info & current regulatory requirements re steam generator tube integrity requested by 750530 W/o encis

 LEAR. Ø Division of Reactor Licensing (NRR-1975 only) 75/04/18 SCHROEDER.F Division of Technical Review (NRR-1975 only) 3pp 15645 204 24X Fiche 50-000, 82/08/10, 8210070007

- --B210070205 Bubmits summary of findings & comments re facility steam generator tube leak incident & insp results contained in Annual Operating Rept 1974 Recommends that licensee be requested to submit insp program for next scheduled insp BHAO.L. C. Engineering Branch (Pre 791030) 77/07/25 EISENHUT.D 0 Division of Operating Reactors 2pp 15445 235 24X Fiche 50-000,82/08/10.8210070007
- ~-8210070208 Forwards request for add1 info re 780524 steam generator tube leak.per LER 78-010/017-0 LER does not clearly indicate evaluation of exact location

 ★ Engineering Branch (Pre 791030) 78/07/13 SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 3pp 15645 241 24X Fiche 50-000, 82/08/10.8210070007
- ~~B210070217 Expresses appreciation for 791130 effort to perform essential licensing work on steam generator matter EIBENHUT.D 0 Division of Operating Reactors 79/12/03 TRAMMELL.C M Operating Reactors Branch 1 (Pre 800428) ip 15645 257 24X Fiche 50-000, 82/08/10, 8210070007
- --8210070218 Forwards A Schwencer & CM Trammell statements re 791116 LER 79-017, per 791228 request SCHMENCER: A Operating Reactors Branch 1 (Fre 800428) 79/12/31 EISENHUT, D 0 Division of Operating Reactors 6pp 15645 258 24X Fiche 50-000.82/08/10.8210070007
- 82:0040414 Forwards Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends revise inservice insp Tech Bpecs CLARK, R A Operating Reactors Branch 3 82/08/31 FAY.C W Wisconsin Electric Power Co Spp 15597 134 24X Fiche 50-266, 82/08/31.8210040414
- --B210040420 Amends &3 & 68 to Licenses DFR-24 & DFR-27, respectively, revising language of Tech Speca re inservice insp requirements of safety class components to conform U/10CFR50 55
 CLARK.R A Operating Reactors Branch 3 82/08/01 14pp 15597 139 244 Fiche 30-266.82/08/31.8210040414
- --820421057; "Point Beach Nurlear Plant Units 1 & 2 Inservice Insp Program Tachnical Evaluation Rept" * Science Applications, Inc. NRC-03-82-074 SAI-186-028-22 82704715 NRC - No Detailed Affiliation Given 20pp 15597 159 24X Fiche 50-266, 82/08/31,8210040414
- --B210040427 Notice of issuance % availability of Amends 63 % 68 to Licenses DPR-24 % DPR-27.respectively CLARK,R A Operating Reactors Branch 3 82/08/31 3pp 13597 179 24% Fiche 50-266, 82/08/31, B210040414
- 8210050005 Advises that error analysis of reactor vessel water level instrumentation sys requested in NRC 820617 ltr will be available by 93015 FAY:C M. Hisconsin Electric Power Co 82/09/29 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK:R A Operating Reactors Branch 3 lp 15605 208 24% Fiche 50-266:82/09/29,8210050005
- 82:0050055 Forwards info requested in NRC 820430 itr re implementation of TMI Item 11 8 2. "Post-Accident Sampling Bys " Addirequirements re backup power sources for lab are beyond scope of original NUREO-0737 implementation schedule BURSTEIN, 8 Wisconsin Electric Power Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, P A Operating Reactors Branch 3 21pp 15603 307 24% Fiche 50-266,82/09/30,8210050055
- 82:0050222 Application to smend Licenses DPR-24 & DPR-27, revising spent fuel pool poison surveillance specimen location & clarifying conditions for operating power-operated relief velves FAY.C W Hisconsin Electric Power Co 82/09/30 DENTON.H.R Office of Nuclear Reactor Regulation, Director, 3pp 15609,056, 24X Fiche, 50-266,82/09/30,8210050222
- --8210050231 Proposed Tech Baces revising spent fuel pool poison surveillance specimen location & clarifying condition for operating power-operated relief valves # Wisconsin Electric Power Co. 82/09/30 3pp, 15609-059 24X Fiche 50-266,82/09/30.8210050822

- 8210270426 Forwards Amends 64 & 69 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends modify operation & surveillance testing requirements of containment purge supply & exhaust valves COLBURN, T O Derating Reactors Branch 3 82/10/04 PAY. C Wisconsin Electric Power Co 4pp 15863 143 24X Fiche 50-266, 82/10/04, 8210270426
- --8210270431 Amends 64 & 69 to Licenses DPR-24 & DPR-27 respectively, and if ying operation & surveillance testing requirements of containment purge supply & exhaust isolation valves & terminology of Tech Spec 15 4 4 on testing CLARK-R A Deparating Reactors Branch 3 82/10/04 12pp 15863 154 24X Fiche 50-266.82/10/04,8210270426
- --8210270436 Safety evaluation supporting Amends &4 & &7 to Licenses BPR-24 & BPR-27, respectively « Office of Nuclear Reactor Regulation. Director 82/10/04 Sp 18863 146 24% Fiche 50-266.82/10/04.8210290426 82/10/04 5pp
- --B210290441 Notice of issuance & availability of Amende 64 & 69 to Licensee DPR-24 & DPR-27, respectively CLARK.B A Operating Reactors Branch 3 82/10/04 2pp 15863 151 24X Fiche 50-246.82/10/04.8210290426
- 8210120267 Forwards documentation reletan generator replacement application filed prior to 820819 establishment of ASLB Documentation consists of steam generator repair repts & correspondence between licensee & Commission W/o enci RIDONAY.D A Shaw, Pittman, Potts & Troubridge. RIDONAY.D A Misconsin Electric Power Co. 82/10/07 KLING.J R , PAXTON.H C Atomic Safety and Licensing Board Fanel 3pp 19652 327 24X Fiche 50-266, 82/10/07.8210120267
- 8210150430 Advises that refueling shutdown at end of Cycle 10 planned to begin 821022 Startup of Cycle 11 expected to occur in early Dec 1782 Cycle 11 reload core designed to operate under current nominal design parameters & Tech Specs FAY.C W Hisconsin Electric Power Co 82/10/11 DENTON.H R Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3 2pp 15704 019 24X Fichs 50-266,82/10/11,8210150430
- 8210190284 Advises of mod to RCB gas vent sys to prevent operation of power operated valves during normal plant operation.per 821012 telcon Physical restraining device fitted on or over valve operator ewitch FAY.C W Wisconsin F valve operator euiton
 FAY.C W Histonisin Electric Power Co 82/10/15
 Office of Nuclear Reactor Regulation, Director Cl
 Operating Reactors Branch 3 1p 15742 177 24X
 Fiche 50-266, 82/10/15, 8210170284 DENTON H R
- 8210190519 Forwards responses to request for add1 info on Tech Spec Change Request 85 re operation when add1 steam generator tube plugging causes primary sys flow to drop below thermal design flow value

 FAY.C H Hisconsin Electric Power Co 82/10/15 DENTON.H R

 Office of Nuclear Reactor Regulation, Director CLARK.R A

 Operating Reactors Branch 3 5pp 15751 238 24x

 Fiche 50-266, 82/10/15, 8210170519
- 5210270294 Forwards Amends 65 & 70 to Licensee DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amend allows relaxation of monthly turbine stop & governor valve test during end of cycle operation COLBURN. T O. Operating Reactors Branch 3 82/10/15 FAY.C Wisconsin Electric Fower Co 3pp 15836 316 24% ,8210270274

a Licenses DPR-24 & DPR-27, respectively. nthly turbing stop & governor valve operation,
Branch 3 82/10/15 7gp
/10/15,8210270274

* ** *> Licensee

10/15, 200

Tech

. 0

- --B210260479 Proposed Tech Spec changes incorporating revisions re administrative control of high radiation areas # Wisconsin Electric Power Co 62/10/19 ip 15806 235 24 Fiche 50-266.82/10/19.8210260476
- 8210280295 Application to amend Licenses DPR-24 & DPR-27, changing Tell ZIUGEULZYD APPLICATION TO AMENO LICENSEE DYN-24 & DYN-27, chai Specs re requirements for periodic leakage rate testing of containment airlock doors Class I & II amend fees encl FAY, C W Wisconsin Electric Power Co 82/10/21 DENTON. Office of Nuclear Reactor Regulation, Director 3pp 158 24X Fiche 50-266.82/10/21.8210280295 DENTON-H R
- ~-8210280298 Tech Spec Change Request 82, changing requirements for periodic leakage mate testing of containment air lock doors # Hisconsin Electric Power Co #82/10/21 4pp 15837 275 24t Fich > 50-786.82/10/21.8210280275
- 8210290294 Provides results of confirmatory analysis demonstrating that unacceptable redicactive release from containment would not take place as results of small break LOCA in which operator action required Radioactive release negligible FAY.C H Hisconsin Electric Pawer Co 82/10/22 CLARK.R A Operating Reactors Branch 3 ip 15853 135 24X Fiche 50-266.82/10/22.8210270274
- O Inspection reports, IE Builetins & correspondence
- 8107270156 Forwards add1 info in response to 1E Bulletin 80-11 re masonry walls Thirteen repts & 109 oversize drawings and Aperture carde are available in PDR FAY.C W Wisconein Electric Power Co Bi/07/17 DENTON.H R Office of Nuclear Reactor Regulation, Director CLARK,R Degrating Reactors Dranch 3 19pp Available at NTIS 09151 026 24% Fiche 50-266.81/07/17.8107270156
- ~~8107270161 "Modal Contribution to Dynamic Analysis Resulte "

 * Computer h Engineering Services, Inc. R553 02 81/07/31 115jg
 09151 045 24% Fiche 50-266.81/07/17.8107270156
- --- 8107270166 "Cyclic Loading Tests of Masonry Single Piers, Vol 1 Hay to Width Ratio of 2 " HIDALGO.P A. MAYES.R L. MCNIVEN.H D California, Univ of. Berkeley UCB/EERC-78/27 VOI 78/11/30 14:pp Available NTIB 07151 158 24X Fiche 50-266/81/07/17.8107270156 Available at
- --8107270169 "Cyclic Loading Tests of Masonry Single Piers, Vol 2 Heigh 10/2/0169 Togric Loserny rest of the Midth Ratio of 1 "
 CHEN, S. J. HIDALGO, P. A. NAYES, R. L. California, Univ. of,
 Berkeley UCB/ERC-78/28 VOZ 78/12/31 188pp 09151 298 241
 Fiche 50-266,81/07/17,8107270156
- --B107270174 "Cyclic Loading Tests of Masonry Single Piers. Vol J Fely (07270174 "Cyclic Loading 1955 or Hamaing Single Financial to Width Ratio of 0 5 "

 HIDALGO, F A : MAYES, R L : MCNIVEN, H D California, Univ of Berkeley UGB/EERC-99/12 VOJ 79/05/21 154pp Available NTIS 09152 124 24X Fiche 50-266.81/07/17.8107270156 Available at
- --8107270178 "Shaking Table Study of Single-Story Masonry Houses, Vol 1 Test Structures 1 & 2 " OULKAN, P. MAYEB, R. L., CLOUGH, R. W. California, Univ. of Berleiq UCB/EERC-79/23 VOI 79/09/30 275pp Available at NTIS 09152.277 24X Ficher 50-266.81/07/17.8107270156
- --8107270182 "Shaking Table Study of Bingle-Story Masonry Houses: Vol 2-Test Structures 3 & 4 " OULKAN, P. MAYES, R. L. CLOUGH, R. W. California, Univ. of Berialds UCB/EERC-79/24 VO2 79/09/30 300pp 09[53 i84 24X Fiche 50-266,81/07/17,8107270156
- --8107270185 "Bhaking Table Study of Bingle-Story Maconry Houses, Vol 3-Summary, Conclusions & Recommendations " CLOUGH, R. H. MAYES, R. L., OULKAN, P. California, Univ. of, Berlele, UCD/CERC-79/25 VQ3 79/09/30 110pp Available at NTIS 09154 078 24X Fiche 50-266, 81/07/17, 8107270156
- --Bi0727018B "Cyclic Shear Teets of Hasonry Piers, Vol 1 ~ Test Relvits' MAYES.R.L + OMATE.Y , CLOUGH.R W California, Univ of, Berteleg EERC 76-8 76/05/31 105pp 09154 182 24X Fiche. 30-264. 81/07/17. 8107270155
- --BiO727019: "Cyclic Shear Tests of Masonry Piers, Vol 2 Analysis of Test Results MAYEG, R L , OMATE, Y , CLOUGH, R W California, Univ of, Bertilia EERC 76-16 76/06/30, 78pp 09154 288 24X Fiche: 50-266, 81/07/17, 8107270156
- --8107270194 "Strength of Timber Roof Connections Subjected to Cyclic LO72/0174 "Strength by Find A California, Univ of, Beriela UCB/EERC-78/17, 78/09/30 171pp 09155 005 24X Fichar 50-266,81/07/17,8107270156

- --B107270196 'Literature Survey Transverse Strength of Hasonry Wolls " DKATE, Y. HA/ES,R L. CHEN,S J California, Univ of, Berkeley UCB/EERC-77/07 77/03/31 149pp 09155 140 24X Fiche 50-286.B1/07/17.B107270156
- --Bi07270198 'Literature Survey Compressive.Tensile.Bond & Shear Strength of Masonry "
 MAYES R L. CLOUGH.R W California. Univ of, Berkeley EERC
 /5-15 79/06/30 212pp 09155 286 24X Fiche 50-266.81/07/17,
- --8107270197 "State-of-the-Art in Seismic Shear Strength of Masonry Evaluation & Review ' MAYES.R L. CLOUGH.R W Lalifornia. Univ of, Berkeley ECRC 75-21 75/10/31 147ep 09156 135 24X Fiche 50-266.81/07/17, 6107270156
- ©210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udeil FOIA Request B1-313 Forwards documents listed in App B FELTON. J M Division of Rules and Records B2/0B/10 LONG, D J Winthrop. Winson. Putnam & Roberts 9pp 15645 063 24X Fiche 50-000.82/08/10.8210070007
- --7812200285 Surmarites steam generator tube leak on 780720 & insp Leak rafe reached 560 gpd at 5 00 AM caused by two tubes w/cracks located w/in thickness of tube sheet & one tube w/leaky plug General cause plant conversion to AVT AUDNAN, V S Engineering Branch (Pre 791030) 78/12/12 GRIMES, B K Assistant Director for Engineers & Projects (Pre 790525) 2pp 15645 244 24X Fiche 50-000.82/08/10.8210070007
- --7909280105 Discusses steam generator tube leak & inservice insp Steam generator caused by deep crevice cracking of three tubes within tube sheet Hot leg tube tests indicated 52 tubes w/ deep crevice cracking in excess of 50% plugging limit ADDNANLY S Engineering Branch (Pre 791030) 79/09/17 tisENHUT, D O Division of Operating Reactors 3pp 15645 254 24% Fiche 50-000-82/09/10-8210070007
- -8210070137 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licenses
 IPPOLITO. F. Operating Reactors Assessment Branch 82/04/01
 VANGALS Operating Reactors Branch 1 5pp 15445 131 24X
 Fiche 50-000,82/08/10.8210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PNRs, per 750320 & 21 requests Details of insps, ancluding defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach I COLLER K R Division of Reactor Liconsing (NRR-1975 only) 75/03/24 MACCARY, R Division of Technical Review (NRR-1975 only) 5pp 15615 196 24X Fichu 50-000,82/08/10,8210070007
- --B210070205 Bubmits summary of findings & comments ie facility steam generator tube leak incident & insp results contained in Annual Operating Rept 1976 Recommends that licensed be requested to submit insp program for next scheduled insp EHADL C Engineering Branch (Pre 791030) 77/07/25 EISENHUT, D G Division of Operating Reactors 2pp 15645 235 24X Fiche 50-000.82/08/10.8210070007
- --8210070228 Forwards evaluation of 800226 proposed steam generator insp & tube pulling program Recommends that program be revised to reflect listed comments NOUNAN.V S Engineering Branch 82/08/10 SCHWENCER.A Operating Reactors Branch 1 (Pre 800428) 2pp 15645 268 24X Ficha 50-000.82/08/10.8210070007
- G210040414 Forwards Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of Issuance & availability Amends revise inservice insp Tech Specs CLARK.R A Operating Reactors Branch 3 82/08/31 FAY, C W Nisconsin Electric Power Co Spp 15597 134 24X Fithe 50-266, 82/08/31, 8210040414
- --8210040420 Amends 63 b 68 to Licenses DPR-24 & DPR-27, respectively, revising language of Tech Specs re inservice inspectively, requirements of safety class components to conform W/10CFR50 55
 CLARK,R A Operating Reactors Branch 3 82/08/31 16pp 15597 139 24X Fiche 50-266, 82/08/31, 8210040414
- --8210040425 Safety evaluation supporting Amends 63 & 68 to Licenses DPR-24 t DPR-27, respectively * Office of Nuclear Reactor Regulation, Director 82/08/31 App 15597, 155 24% Fiche 50-266, B2/08/31, B210040414

- --8206210571 "Point Beach Nuclear Plant Units 1 & 2 Inservice Insp Program Technical Evaluation Rept" ★ Science Applications, Inc NRC-03-82-096 SAI-186-028-22 82/06/15 NRC - No Detailed Affiliation Given 20pp 15597 189 24X Fiche 50-266,82/08/31,8210040414
- ~-8210040427 Notice of issuance & availability of Amends 43 & 68 to Licenses DPR-24 & DPR-27.inspectively CLARKIR A Operating Reactors Drauch 3 82/08/31 3pp 15597 179 24X Fiche 50-246.82/08/31.8210040414
- 8210050186 Forwards IE Insp Repts 50-266/82-12 & 50-301/82-12 on 820503-04 & 0615 & notice of violation KEPPLER, J O Region 3, Office of Director 82/07/15 BURSTEIN, 6 Wisconsin Electric Power Co 3pp 15611 115 24X Fiche 50-266.82/07/15.8210050186
- ~-8210050174 Notice of violation from insp on 820503-04 & 0415 KEPPLER, J G Region 3, Office of Director 82/09/15 3pp 15611 118 24X Fiche 50-266,82/09/15,8210050186
- --B210050205 IE Insp Repts 50-246/82-12 & 50-301-82-12 on 820503-04 & Odi5 Noncompliance noted failure to control access to high radiation areas & failure to follow approved procedures LOVENDALE.P C : HAGVE, R L : GREGER, L R Region 3, Office of Director 82/07/13 8pp 15611 121 24X Fiche 50-246,82/09/15,8210050186
- 8210070033 Notifies that fees for 820820 application requesting relief from certain inservice inspirequirements not remitted w/application Class III fee category appropriate D1008.R H License Fee Managament Branch 82/09/23 FAY.C W Wisconsin Electric Power Co ip 15645 346 24X Fiche 50-266.82/09/23.82100/0033
- B210050256 Requests relief from ASME Section XI, inservice insprequirements re frequency of reactor vessel interior examp FAY.C W Hisconsin Electric Power Ca 82/07/27 DENYGN.H R Office of Nuclear Reactor Regulation. Director CLARK, R A Operating Reactors Branch 3 4pp 15610 286 24X Fichs 50-266.82/09/29.8210050256
- 8210190669 Forwards IE lnsp Repts 50-266/82-20 % 50-301/82-20 on 820714-16 No noncompilance noted LITTLE.W 8 Division of Engineering & Technical Programs 82/10/04 BURSTEIN.8 Wisconsin Electric Power Co 2pp 15738 152 24X Fichs 50-266 82/10/04.8210190669
- --8210190675 IE Insp Repts 50-266/82-20 & 50-301/82-20 on 820914-16
 No noncompliance noted Major areas inspected survaillance
 & calibr procedures & performance history
 HABSE, H A , PEBCHEL, J M , HAWKING, F C Division of Engineering &
 Technical Programs 82/09/29 4pp 13738 154 24X
 Fiche 50-266, 82/10/04, 8210190669
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Olslodged I-125 Implant Seeds " Syc 11st encl COUD, L 1 Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000, 82/10/06, 8208190233
- 8210180067 Forwards Class III for re 820820 request for exemptions from certain inservice insp requirements Util considers imposition of 10CFR170 22 fees inappropriate as request does not involve license amend FAY, C W Hisconsin Electric Power Co 82/10/11, DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 ip 15720.003 24X Fiche 50-266, 82/10/11, 8210180067
- 8208190238 IE Builetin 82-03, "Stress Corrosion Cracking In Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants." Syc 1ist enci DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125. 24X Fiche 50-000.82/10/14.8208190238
- R Periodic operating reports & related correspondence
- 8210150150 Forwards monthly operating repts for 8apt 1982 FAY,C W Misconsin Electric Power Co 82/10/11 Office of Nuclear Reactor Regulation, Director ip 15697 074 24X Fiche,50~266.82/10/11.8210150150
- --8210150158 Monthly operating repts for Bept 1982, FAY.C W Wisconsin Electric Power Co 82/10/04 8pp 15697.075 24X Fiche 50-266.82/10/11.8210150150.

- S Reportable occurrences, LERs & related correspondence
- 921025025B Forwards LEA 82-015/03L-0 FAY.C.W Misconsin Electric Power Co 62/10/13 KEPPLER.J G Region 3. Office of Director ip 15791 148 24X Fiche 50-266, 82/10/13,821025025B
- --82(0250262 LER 82-015/03L-0 on 820914.fluid level an gas stripper noted decreasing abnormally after stripper returned to svc following maint Caused by high stress low cycle fallure of lap joint flange stub piece Lap joint flange replaced FAY.C W Wisconsin Electric Power Ca 82/10/13 Region 3, Office of Director 3pp 15791 149 24X Ficha 50-266.82/10/13.
- 8210250344 Forwards LER 82-016/01T-0 FAY.C H Hisconsin Electric Power Co 82/10/15 KEPPLER.J 0 Region 3. Dffice of Director ip 15790 332 24X Fiche 50-266.82/10/15.8210250344
- --8210250352 LER 82-016/01T-0 on 821002.containment isolation velve 10V-3200C in suction line of radioactive gas & particulate monitoring sys failed to close Caused by failure of 3-way solenoid valve to cycle Valve closed & repaired FAY.C W Hisconsin Electric Power Co 82/10/15 Region 3, Office of Director 4pp 15790 333 24X Fiche 50-266.82/10/15, 82/0250344
- T Hearing transcripts on non-antitrust matters
- 8210080052 Transcript of 821006 telephone conference to discuss rescheduling of hearing in Washington.DC Pp 1:342-1:352 a Atomic Safety and Licensing Board Panel 82/10/06 i2pp 15643 284 24X Fiche 50-266.82/10/06.8210080052
- DOCKET 50-267 FORT BT VRAIN NUCLEAR GENERATING STATION
 F Security, medical, emergency & fire protection plans
- 8209150434 Releases public version of updated radiological emergency response plan. FELTON.J.H Division of Rules and Records 82/08/25 Document Management Branch ip 14890 193 24X Fiche 50-267.82/08/25, 8209150434
- --B209130440 Forwards public version of updated radiological emergency response plan, per B20315 request Encl revision is almost complete rewrite except for visitors ctr & RERP-FIELD procedures W/o encl WAREMBOURG, D Public Service Co of Colorada, 62/08/10 ROHRER, D Director's Office, Office of Inspection and Enforcement in 14890 194 24% Fiche 50-267,82/08/25,8209150434
- 8210250083 Commits to revising security plan & Implementing Procedure APH 0-4 to provide for background investigation of outside contractor personnel at facility Screening program will be implemented within 60 days
 LEE, 0 R Public Service Co. of Colorado 82/08/25 COLLINB, J T Region 4, Defice of Director. 3pp 15787 083 24X Fiche 50-267, 82/08/25, 8210250083
- 8210210D73 Releases public version of radiological emergency response plan implementing procedures. FELTDN.J.H Division of Rules and Records 92/09/29 Document Management Brench ip 15774 [26 24X Fiche 50-267,82/09/29,8210210073
- --B2102100Bi Forwards public version of radiological emergency response plan implementing procedures, including inplant/oneite ure & field monitoring

- 8210220404 Ack receipt of 820819 response to App A Items of [E Emergency Preparedness Appraisal Rept 50-267/82-01 Add1 info needed to complete evaluation of response MADSEN.G L Division of Resident, Reactor Project & Engineering Programs 82/10/19 LEE, OR Public Bervice Co of Colorado Cy, 15779 160 24% Fiche 50-267, 82/10/19, 82/10220404
- P Operating license stage documents & correspondence
- 9210040114 Forwards Info documenting Satisfaction of each criterion of NUREO-0737. Item II B 3 mp post-accident sampling system (RNL investigation of source terms remains only open item HAREMBOURO Public Gervice Co of Colorado 82/09/27 CIARK.R A Operating Reactors Branch 3 40pp 15581 146 24X Fichs 30-267.82/09/27,8210040114
- 8210080256 Forwards "Radiochemical Analysis of First Plateout Prope from Fort St Vrain High-Temp Gas-Cooled Reactor" WAREHBOURO, D. W. Public Service Co. of Colorado 82/09/2/ WUJNYCZ, O. NRC - No. Detailed Affiliation O
- --8210080258 "Radiochemical Analysis of First Plateout Probe from Fort St Vrain High-Temp Oas-Cooled Reactor" BURNETTE, R D QA Technologies, Inc./General Atomic Co OA-Al6/84 82/06/30 128pp 15649 281 24X Fiche 50-267,82/09/27. 8210080256
- 8210060273 Forwards suppl to EE-11-0002, Revision 2, "Addi Gurveillanta Requirements for PCRV Penetrations & Closures," & suppl to EE-22-0002, Revision 1, "Inservice Insp & Testing Program Addl Surveillance Requirements for Steam Generator "

 8REY, H L Public Service Co of Colorado 82/09/30 CLARK. R A dperating Reactors Branch 3 2pp 15621 180 24%

 Fiche 50-267, 82/09/30, 8210060273
- --0210060202 Suppl to EE-ii-0002 Revision 2, "Fort St Vrain Addl Surveillance Requirements for PCRV Penetrations & Closures " * Public Service Co of Colorado 82/09/28 12pp 15621 182 24% Fiche 50-267, 82/09/30,8210060273
- --9210060286 Suppl to EE-22-0002, Revision 1. "Fort St Vrain Inservice Insp & Testing Program Addi Surveillance Requirements for Steam Generator"

 * Public Service Co of Colorado 82/09/28 7pp 15621 144 24% Fiche 50-267, 82/09/30.8210060273
- 82:0190701 Forwards "Fort St Vrain Accident Reanalysis Code (AFCA 3)
 Verification Following Region Outlet Temp Redistribution."
 per Bi0210 meeting commitment Code accurately predicts
 transient behavior in temp redistribution configuration.
 BREY.H L Public Service Co of Colorado 82/10/06 NOVAM, I H
 Assistant Director for Operating Reactors ip 15736 155 241
 Fiche 50-267, 82/10/06,8210190701
- --B210190706 "Fort St Vrain Accident Reanalysis Code (RECA 3) Verification Following Region Outlet Temp Redistribution " * Public Service Co of Colorado 82/10/06 42pp 15/J6 8% 24% Fiche 30-267,82/10/06/8210190701
- 62:0270:04 Forwards 82:012 application to amond License DPR-34. severity surveillance requirements LEE.D R Public Bervice Co of Colorado 82/10/15 CLARK. A Assistant Director for Operating Reactors 2pp 15827 050 24% Fiche 90-267, 82/10/15, 82:0270:104
- --8210270113 Application to amend License OPR-34, changing Tech Epoca ve inservice imap & testing program surveillance requirements LEE, O R Public Service Co of Colorado 82/10/12 9ep 18827 052 24X Fiche 50-267, 82/10/15, 8210270104
- ---B210270118 Proposed Tech Specs changes involving reserve shutdown Eps surveillance, primary coolant sys surveillance requirements, tendon corrustion & anchor assemblies implementation schedule & SAR enci * Public Service Co of Colorado. B2/10/15 54pp | 1502/ 061 24X Fiche 50-267, 82/10/15.8210270104
- Q. Inspection reports: IE Bulletine & correspondence
- 82:0050226 Forwards IE Insp Rept 50-267/82-20 on 820801-31 Ne noncompliance noted MADBEN. 0 L Division of Resident, Reactor Project & Engineering Programs 82/09/16 LEE, 0 R Public Service Co of Colorede Per 15608-309. 24X Fiche 50-267.82/09/16,8210050226

- -8210050239 IE Insp Rept 50-267/82-20 on 820801-31 No noncompliance noted Major areas inspected surveillance, maint, operational safety verification, previous insp findings, plant operations & procedures & repts DICKERSON M W. PLUMLEE, C.L. WESTERMAN, T.F. Division of Resident Reactor Project & Engineering Programs 82/09/10 13pp 15608 311 24X Fiche 50-267, 82/09/16, 8210050226
- 8210060273 Forwards suppl to EE-11-0002, Revision 2. "Add1 Surveillance Requirements for PCRV Penetrations & Closures," & suppl to EE-22-0002, Revision 1. "Inservice Insp & Testing Program Add1 Surveillance Requirements for Steam Generator"

 8REV.H t. Public Service Co of Colorado 82/09/30 CLARK, R A Operating Reactors Branch 3 2pp 15621 180 24X

 Fiche 50-267, 82/09/30, 8210060273
- --B210060282 Suppl to EE-i1-0002, Revision 2, "Fort St Vrain Addl Surveillance Requirements for PCRV Penetrations & Closures " 4 Public Service Co of Colorado 82/09/28 12pp 15621 182 24X Fiche 50-267.82/09/30,8210060273
- --8210060286 Suppl to EE-22-0002, Revision 1, "Fort St Vrain Inservice Insp & Testing Program Addl Surveiliance Requirements for Steam Cenerator"

 † Public Service Co of Colorado 82/09/28 7pp 15621 194 24% Fiche 50-267, 82/09/30, 8210060273
- 620B190233 IE Info Notice B0-35, Suppl J. "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fsche 50-000.82/10/06.82081970233
- #210280142 Forwards IE Insp Rept 50-267/82-19 on #20809-13 & 0830-0903 & motice of violation #ADSEN.C L Division of Resident, Reactor Project & Engineering Programs #62/10/06 LEE, D.R. Public Service Co of Colorado 2pp 15837 227 24X Fiche 50-267,82/10/06.6210280142
- --8210280145 Notice of violation from insp on 820809-13 & 0830-0903 + Division of Resident. Reactor Project & Engineering Programs 82/10/06 lp 15837 229 24X Fiche 50-267, 822/10/06, 8210280142
- --0210280149 IE Insp Rept 50-267/82-17 on 820809-13 & 0830-0903 Noncompliance noted failure to maintain test records of safety-related design changes REDAND, R T. MESTERMAN, T F Division of Resident, Reactor Project & Engineering Programs 82/09/29 9pp 15837 230 24X Fiche 50-267,82/10/06.8210280142
- 8208190238 IE Builetín 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainiess Steel, Recirculation Sys Piping at BUR Plants " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 8210270104 Forwards B21012 application to amend License DPR-34, revising surveillance requirements
 LEE.O R Public Service Co of Coloredo 82/10/15 CLARK, R
 Assistant Director for Operating Reactors 2pp 15827 050 24X
 Fiche 50-267. 82/10/15. 8210270104
- --B210270113 Application to amend License DPR-34, changing Tech Specs re inservice insp & testing program surveillance requirements LEE.O R Public Service Co of Colorado B2/10/12 9pp 15827 052 24% Fiche 50-227, 82/10/15,8210270104.
- --B210270118 Proposed Tech Specs changes involving reserve shutdown aga surveillance, primary coolant sys surveillance requirements, tendon corrosion & anchor assemblies Implementation schedule & SAR encl 4 Public Service Co of Colorado 82/10/15 54pp 15827 G61 24X Fiche 50-267.82/10/15.8210270104
- 8210220404 Ack receipt of 820B19 response to App A items of IE Emergency Preparedness Appraisal Rept 50-267/82-01. Add1 info needed to complete evaluation of response MADSEN. C I. Division of Resident: Reactor Project & Engineering Programs 82/10/19 LEE, D R Public Service Co of Colorado 2pp 63779 160 24% Fiche 50-267.82/10/19.B210220404
- R Periodic operating reports & related correspondence
- B210130344 Forwards monthly operating rept for Sept 1982
 WAREMBOURG, D. Public Service Co. of Colorado 82/10/06
 Director's Office Office of Inspection and Enforcement, 1p
 15682 030 24X Fichs 50-267, 82/10/06, 8210130344

- --8210130349 Monthly operating rept for Sept 1982 MCBRIDE:L M Public Service Co of Colorado 82/10/06 Spp 15482 031 24X Fiche 50-267, 82/10/04, 8210130344
- 82:0190655 Forwards monthly operating rept for Sept 1982
 WAREMBOURG, D. Public Service Co. of Colorado. B2/10/12
 QAMMILL, W.P. Assistant Director for Operating Reactors. 2pp 15739, 0B1 24X Fiche 50-267, B2/10/12, B2:0190655
- --8210190467 Monthly operating rept for Bept 1982 Narrative summary encl MCBRIDE: L M Public Service Co of Colorado 82/10/06 9pp 15739 083 24X Fiche 50-247, 82/10/12.8210190455
- S Reportable occurrences. LERs & related correspondence
- 8210050331 Forwards LER 82-035/03L-0 Detailed event analysis encl HAREMBOURG, D Fublic Service Co of Colorado 82/09/23 COLLINS, J T Region 4. Office of Director 4pp 19402 394 24X Fiche 50-267, 82/09/23, 8210050331
- --8210050337 LER 82-035/03L-0 on 820827, engine 18 of standby generator set 1A rendered inoperable Caused by indicator lamp &/or lamp socket short circuiting causing 15 amp fuse to blow in angine 18,125-volt dc cranking circuit FULLER, C Public Service Co of Colorado 82/07/23 Region 4, Office of Director 1p 15602 358 24X Fiche 50-267,82/07/23, 8210050331
- 82:0390537 Forwards LER 82-036/03L-0 Detailed event analysis encl HAREMBOURG, D Public Service Co of Colorado 82/10/08 COLLINS. J Y Region 4. Office of Director 3pp 15751 323 24X Fiche 50-267, 82/10/08.8210190537
- --B210190543 LER B2-036/03L-0 on B2090B, one of two bearing water makeup pumps removed from svc Caused by need to rebuild mechanical seal due to normal wear Seal rebuilt FULLER.C Public Service Co of Colorado B2/10/0B Region 4. Office of Director ip 19751 326 24X Fiche 50-267.B2/10/0B, B210190537
- 8210190547 PND-1V-82-037 on 821013 indication of increasing reactor bldg activity & decreasing regeneration train pressure occurred Caused by gaseous radioactivity leaking from flanged line in A purification train WESTERMAN.T F. MADSEN.O L. Region 4. Office of Director 82/10/13 ip 15751 360 24X Fiche 50-267.82/10/13.8210190547
- DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8210010352 Forwards revision to safeguards contingency plan Revision withheld (ref 10CFR73 21)
 TUCKER,H B Dute Power Co 82/09/17 DENTON,H R Office of Nuclear Reactor Regulation, Director Ip 15574 139 24X
 Fiche 50-269,82/09/17,8210010352
- 8210260527 Agrees w/determination to locate fire hose stations outside affected fire areas Change from earlier commitment acceptable
 BTGLZ.J F Operating Reactors Branch 4 82/09/23 TUCKER.H B
 Duke Power Co 2pp 15830 189 24X Fiche 50-269.82/09/23.
 B210260527
- 8210040232 Application to amend Licenses DPR-98, DPR-47 & DPR-55 Amend requests delation of Tech Spec 6 4 2 re site emergency drill & definition of time within which redundant component test must be performed prior to performing maint per Tech Spec TUCKER, H. B. Duke Power Co. 82/09/27 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 15586 104 24X Fiche 50-269, 82/09/27, 8210040232
- --8210040245 Proposed revision to Tech Spec Pages 3 3-4 & 6,4-1 re site amergency drill & time period within which redundant component test must be performed prior to performing maint 4 Duke Power Ca. 82/09/27 4pp. 15586 107 24X Fiche 50-269.82/09/27.8210040232
- P Operating license stage documents & correspondance
- 8205130256 Forwards task force on pressurized thermal shock audit of Robinson plant re adequacy of in-plant training programs to operating procedures NRC will conduct similar audit at Brunswick plant.

 NOVAN.T M Assistant Director for Operating Reactors. 82/04/23, PARKER, W D Duke Power Co. 2pp 13089 038 24X Fiche. 50-249, 82/04/23, 8205130256

- 8210080036 Responds to FOIA request for documents re pins designed to conditions Forwards documents listed on App A
 FELTDN.J M Division of Rules and Records 82/08/13 EDDLEMAN.W
 Public Interest Research Oroup in North Carolina 2pp 15649 240
 24X Fiche 50-269,82/08/13,8210080036
- --8210080044 Notification of Bl1009 meeting w/util in Bethesda.MD to discuss broken thermal shield bolts in Unit i HAONER.P C Operating Reactors Branch 4 8i/10/05 BTOL2.J F Operating Reactors Branch 4 2pp 15669 268 24X Fiche 50-000.82/08/13.8210080036
- ---8208250417 Discusses broken core barrel assembly thermal shield boits at Ocones i & applicability to other B&W plants Insp of Ocones 3 & other B&W plants w/thermai shield bolts made of same matls recommended GLSHINSKI, J A Division AGENINSKIJA Division of Engineering & Technical Programs B2/03/29 EIBENHUT.D 9 Division of Licensing App 15669 285 24X Fiche 50-000, 82/08/13,6210880036
- 8210040107 Advises that util response to MRC 820218 ltr will be provided by 82/00B Ruceipt of into from crans vendor & axtraordinary analytical work have delayed response TUCKER; H B Dute Power Co 82/09/24 DENTON; H R Defice of Nuclear Reactor Regulation, Director STOL7. J F Operating Reactors Branch 4 Jp 15581 024 24% Fiche 50-269.82/09/24,8210040107
- 8210040232 Application to amend Licenses DPR-38, DPR-47 & DPR-55 Amend requests deletion of Tech Spac 6 4 2 resite emergency drill & definition of time within which redundant component test must be performed prior to performing maint per Tech Spac TUCKER, II D Dute Power Co 82/09/27 DENTON, HR Dffice of Nuclear Reactor Regulation. Director 870L7, JF Operating Reactors Branch 4 3pp 15586 104 24% Fiche 50-269,82/09/27,9210040232
- --8210040245 Proposed revision to Tech Spec Pages 3 3-6 & 4-1 re site emergency drill & time period within which redundant component test must be performed prior to performing maint * Duke Power Co 82/09/27 4pp i5586.107 24X Fiche 50-269.82/09/27.8210040232
- 8210190145 Forwards Amends 113,113 & 110 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to allow full power operation of Unit 3 during Fuel Cycle 7
 WAGNER, P C Operating Reactors Branch 4 82/09/29 TUCKER, H D
 Dute Power Co 2pp 15757 341 24X Fiche 50-269, 82/09/29. Duke Power Co 8210190145
- --B210190154 Amends 113,113 & 110 to Licenses DPR-38, DPR-47 & DPR-95, respectively, revising Tech Specs to allow full power operation of Unit 3 during Fuel Cycle 7 STOL7.J F Operating Reactors Branch 4. 82/09/29 31pp 15757 343 24X Fiche 50-269, 82/09/29, 8210190145
- --8210190161 Safety evaluation supporting Amends (13, (13 & (10 to Licenses DPR-30, DPR-47 & DPR-53, DPR-52tively # 0ffice of Nuclear Reactor Regulation, Director 82/09/29 82/09/29 App 24X Fiche 50-269.82/09/29.8210190145
- --8210170169 Notice of issuance & availability of Amends 113.113 & 110 to Licenses DPR-36.DPR-47 & DPR-55.respectively BTOL7.JF Operating Reactors Branch 4 82/09/29 2pp 18758 018 24X Fiche 50-269,82/09/29,8210190145
- 3210180323 Responds to 820913 ltr re reactor bidg purge sys Position given in 810707 & 17 ttrs remains unchanged Schedule For submitting info indicating purge sys meets operability requirements requested LAINAS, 0 C Assistant Director for Operating Reactors B2/09/30 Co 3pp 15745 334. 24% 10180323

ongoing NRC research program W NSSS plant Declines

> Office of Division of /07,8210130157

re adequacu of

Office of trating Reactors 8210180055

- -- 8210180060 Forwards partial response to Franklin Research Ctr draft technical evaluation rept re control of heavy loads, per
 - technical evaluation repute to SUIDOB DENTON, H R Diffice of TUCKER, H B Duke Power Co 82/10/08 DENTON, H R Diffice of Nuclear Reactor Regulation Director STOLZ, J F Operating Reactors Branch 4 Spp 15720 011 24X Fiche 50-269, 82/30/03
- B2:02:0:31 Responds to NRC 820908 itr transmitting technical evaluator rept on emergency feedwater sys Sys may not meet all current criteria for seismic qualification but will remain functionally operable during OBE
 TUCKER, H B Duke Power Co B2/10/13 DENYON, H R Office of
 Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactor
 Branch 4 App 15766-356 24% Fiche 50-249, B2/10/13, B210210131
- 8210210407 Application to amend OLs, revising Tech Spec 3 1 allowing full gower operation of Unit 1 for interim period until appropriate safety valve ring settings can be implemented Nuclear Reactor Regulation, Director STOLZ, J F Operating Restit.

 Branch 4 Bpg 15764 038 24X Fiche 50-269,82/10/14,8210210497
- --8210210411 Proposed revision to Tech Spec 3 i allowing full power operation of Unit 1 for interim period until appropriate safety valve ring setting can be implemented 4 Dute Power Co 82/10/14 p 15764 048 24% Fiche 50-269, 82/10/14,8210210407
- Q Inspection reports. IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records in steam generators & steam turbines App A documents provided in R_Udell FOIA Request 81-313 Forwards documents listed in FELTON, J M Division of Rules and Records 82/08/10 [ONG.D J Winthrep, Stimson, Putnam & Roberts 9pp 15445 063 24x Fiche 50-000, 82/08/10,8210070007
- --8210070172 Forwards info re steam generator integrity & imaps at all operating PWRs.per 750320 & 21 requests Details of imaps. including defect indications, tube plugging criteria t tubes plugged with not be provided except for Point Boach t GOLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R Division of Technical Review (NRR-1975 only) 5pp 15645 196 24X Fiche 50-000.82/08/10.821007000/
- 8210150369 Forwards results of investigation of Item 7s of IC Insp. Repte 50-269/82-21.50-270/82-21 & 50-287/82-21 Deadtime values for gamma spectroscopy analyses of waste gas silver reditte certridges will cause only insignificant errors TUCKER. H B Duke Power Co 62/08/17 D/REILLY, J P Region 2 Diffice of Director 2pp 15704 269 24X Fiche 50-264, 63/08/17 8210150347.
- 8210010117 Forwards IE Insp Repts 50-269/82-33.50-270/02-33 t 50-287/82-33 on B20817-20 No noncompliance noted DANCE, H C Division of Project & Resident Programs E2/09/02 TUCKER, H D Duke Pawer Co 2pp 15566 019 24X Fiche 50-269, 82/09/02, 8210010117
- --B210010124 IE Insp Repts 50-269/82-33.50-270/82-33 & 50-207/82-33 on 820817-20 No noncompliance noted Major areas inspected action on previous enforcement matters.auxiliary feedwater header repair & inservice insp procedures
 CROMLEV.B R., BLAKE, J Division of Engineering & Technical
 Programs 82/09/01 8pp 15564 021 24X Fiche 50-269.82/09/12
 8210010117
- 6210010198 Forwards | E Insp Repts 50-269/62-30, 50-270/82-30 & 90-287/82-30 on 820716-0810 No noncompliance noted DANCE, H C Division of Project & Recident Programs 82/09/02 TUCKER, H D Duke Power Co 2pp 15367 258 24X Fichs 50-267, 82/09/02,8210010158
- --8210030166 IE Insp Repts 50-269/82-30, 50-270/82-30 & 50-207/82-30 p 820716-0810 No noncompliance noted Major areas inspected operations, surveillance testing, maint, NUREO-0737 mods & Programs 82/09/02 13pp 15567 260 24X Fiche 50-269.82703
- 8210010458 Ack receipt of 820805 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-249/82-23, 30-270/82-23 & 50-287/82-23 LEWIS.R C Division of Project & Resident Programs 82/09/17 TUCKER.H.B Duke Power Co 1p. 15570 182 24X Fiche, 50-249, 82/09/17, 8210010458

- --8210010463 Responds to NRC 820712 itr re violations noted in 1E Insp Rept: 50-269/82-23.50-270/82-23 & 50-287/82-23 Corrective actions personnel counseled to valve 21P-14 cut out & properly reinstalled TUCKER.H.B. Dute Power Co. 82/08/05 D'REILLY, J.P. Region 2, Office of Director 4pp 15570 183 24X Fiche 50-269.82/09/17, 8210010458
- --8210010468 Forwards 1E Insp Repts 50-269/82-23.50-270/82-23 & 50-287/82-23 on 820510-0610 > notice of violation LEMIS,R C Division of Project & Resident Programs 82/07/12 PARKER,N O Duke Power Co 2pp 15570 187 24X Fiche 50-269,82/09/17.8210010458
- --B210010471 Notice of violation from insp on B20510-0610 • Division of Project & Resident Programs B2/07/12 2p 15570 189 24X Fiche 50-269,82/09/17,8210010458
- --8210010474 IE Insp Repts 50-269/82-23.50-270/82-23 & 50-287/82-23 on B20510-0610 Noncompliance noted Failure to follow procedures resulting in plant trip & inadequate procedure resulting in improper reassembly of safety-related valve ORDERS.W. FALCONER.D. BRYANT.J C Division of Project & Resident Programs 82/07/09 12pp 15570 191 24% Fiche 50-269.82/09/17, 8210010458
- 63210150253 Forwards 16 Insp Repts 50-269/82-32, 50-270/82-32 & 50-287/82-32 on 820817-18 No noncompliance noted DANCE.N C Division of Project 7, Resident Programs 82/09/17 TUCKER.N B Duke Power Ca 2pp 15703 267 24X Fiche 50-269, 82/09/17.8210150253
- --B210150263 1E Insp Repts 50-267/82-32,50-270/82-32 & 50-287/82-32 on 820817-18 No noncompliance noted Major areas Inspected lab GC & review of radiochemistry procedures & records EVANS.C D . MONTOUMERY, D M Division of Emergency Preparedness & Operational Support 82/09/15 3pp 15703 269 24X Fiche 50-269, 82/09/17, 8210150253
- 8210150531 Forwards 1E Insp Repts 50-269/82-35, 50-270/82-35 & 50-287/82-35 on 820908-10 No noncompilance noted DANCE H C Division of Project & Resident Programs 82/09/23 TUCKER H B Duke Power Co 2pp 15698 312 24X Fiche 50-267, 82/09/23, 8210150131
- --8210150143 IE Insp Repts 50-269/82-35.50-270/82-35 & 50-287/82-35 on 82090B-10 No noncompliance nuted Hajor areas inspected RCS leakage calculations
 BURNETT, P T , JAPE.F Division of Engineering & Technical Programs 82/09/21 4pp 15698 314 24X fiche 50-269.82/09/23, 8210150131
- 공화10130290 Requests relief from inservice insp requirements
 (hydrostatic) of Section XI of ASME Boller & Pressure Vessei
 Code
 TUCKER.H B Duke Power Co 82/10/04 DENTON,H R Office of
 Nuclear Reactor Regulation, Director STOLZ-J F Operating Reactors
 Branch 4 20pp 15678 243 24X Fiche 50-269,82/10/04,8210130290
- ### 208170233 1E Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-i25 Implant Seeds " Svc list encl COBUL I Division of Fuel Facilities, Materials & Safequards ### 22/10/06 Consolidated Edison Co of New York ### 65/24X Fiche 50-000.82/10/06,8208190233
- B210220426 Forwards Revision 5 to response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts"

 TUCKER.H B Dute Power Co 82/10/08 O'REILLY, J P Region 2, Office of Director 24pp 15778 273 24X Fiche 50-269,82/10/08, 82/10220426
- B210150285 EN-82-021A on 821012, order imposing civil monetary penalty issued to incensee Action based on feiture to follow procedures affecting safe operation of facility BARBER.G. AXELRAD.J Director's Office. Office of Inspection and Enforcement 62/10/12 ip 15701 319 24X Fiche 50-269.82/10/12.6210150285
- B208190238 IE Builetin 82-03. "Stress Corrosion Cracking in Thick-Walls-Large-Diameter Stainless Steel, Recirculation Sys Paping at BWR Plants "Syc list encl DEYOUNG, R C Director's Office Office of Inspection and Enforcement B2/10/14 Consolidated Edison Go of New York. 115pp 15810 i25 24X Fiche 50-000.82/10/14,8208190238
- 2. Periodic operating reports & related correspondence
- ⇒≥10i90544 Forwards monthly operating repts for Gept 1982 TWCKER.H B Duke Power Co 82/i0/15 Director's Office, Office of Inspection and Enforcement ip i5751 343 24X Fiche 90-269, 82/10/15.8210190544

- --8210190552 Monthly operating repts for Sept 1982 REAVIS.J A Duke Power Co 822/10/15 16pp 15751 344 24x Fiche 50-269,82/10/15/82101905544
- S Reportable accurrences. LERs & related correspondence
- 8210150079 Forwards LER 81-001/03L-0 Detailed event analysis anci PARKER,W O Duke Power Co Bi/02/04 O'REILLV,J P Region 2, Atlanta, Office of the Director (Bi/03/01) 3pp 15697 063 24) Fiche 50-269.Bi/02/04.B210150079
- --8210i50084 LER 8i-00i/03L-0 on 8i0i08, turbine trip from 90% full power occurred Caused by ioss of excitation on generator field resulting from mismatch during personnel attempt to raise voit amperes reactive on Units i & 2

 JONES, J. L. Duke Power Co. Bi/02/04 Region 2, Atlanta, Office of the Director (8i/03/01) 1p 15697 066 24%

 Fiche 50-269,81/02/04,8210150079
- 82:00:0008 Responds to FOJA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass En
- --8210040374 Forwards LER 80-20/03L & RO 269/80-9 re failure to open auxiliary feedwater valve & failure of fire detection sys, respectively Addi attention may be warranted BENDER. M ACRE Advisory Committee on Reactor Bafeguards 80/05/23 FRALEY. R F. ACRE Advisory Committee on Reactor Bafeguards 1p 15727 272 24X Fiche 50-000, 82/06/28, 8210010008
- 8210190653 PNO-II-82-111 on 821014. Unit 2 shut down after determining that pressurizer code safety valve design flow could not be fully maintained if called upon Beven-day outage required to change valves Esemption requested for Unit 1 IONATONIS. A. DANCE. H. C. Region 2. Office of Director 62/10/14 2pp 15740 036 24% Fiche 50-269. 82/10/14.8210190653
- 8210290395 Forwards LER 82-014/03L-0 Detailed event analysis encl TUCKER.H B Duke Power Co 82/10/14 O'REILLY.J P Region 2. Office of Director. 3pp 15853 043 24X Fiche 50-267.82/10/14. 8210290355
- --8210290365 LER 82-014/03L-0 between 820816-0920, reactor bidg cooling unit fan 1A tripped on low speed thermai overloads seven times Cause unknown Fan under surveillance Fan motor may be replaced if cause of trips cannot be determined PETTY, J C Duke Power Co 82/10/14 Region 2, Office of Director 1p 15853 046 24X Fiche 50-269,82/10/14.8210290355
- 8210290190 Forwards LER 82-015/03L-0 Detailed event analysis encl TVCKER, H D Duke Power Co 82/10/15 O'REILLY, J P Region 2. Office of Director 3pp 15853 287 24X Fiche, 50-269, 82/10/15, 8210290190
- --8210290197 LER 82-013/03L-0 on 820917, reactor protection sys tr1p
 pushbutton declared technically inoperable Caused by
 procedure deficiency which did not include required test,
 Necessary procedures changed
 PETTY, J C Duke Power Co 82/10/15 Region 2, Office of
 Director 1p 15853 290 24X Fiche 30-269,82/10/15,8210290190
- DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210010008 Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J.M Division of Rules and Records 82/06/28 UDELL.R.A. Critical Mass Energy Project 15pp 13727 005 24X Fiche 50-000, 82/06/28, 8210010008
- --B204290048 Recommends prompt attention be given to problem of reactor coolent pump closure stud corrosion detected at facilities.
 Response by 820415 requested
 EISENHUT, D O Division of Licensing B2/03/24 HANAUER, S H
 Division of Systems Integration (post 811005) 3pp. 15745 270
 24% Fiche: 50-000, 82/06/28, 8210010008
- F Security, medical, emergency & fire protection plans
- 8210010332 Forwards revision to safeguards contingency plan Revision withheld (ref 10CFR73 21).

 TUCKER, H. B. Duke Power Co. 82/09/17. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 15574 139 24X Ficher 50-269, 82/09/17, 8210010332.

- 8210260529 Agrees w/determination to locate fire hose stations outside affected fire areas Change from werlier commitment TUCKER H R
 - acceptable STOLZ.J F Operating Reactors Branch 4 82/09/23 TUCKER. Duke Fower Co 2pp 15830 189 24% Fiche 50-269.82/09/23.
- 8210040232 Application to amend Licenses DPR-38.DPR-47 & DPR-55 Amend 210040232 Application to amend Litenses by R-36-UPR-9' & UPR-9 requests deletion of Tech Epec 4 4 2 te site emergency drill & definition of time within which redundant component test must be performed prior to performing maint per Tech Spec TUCKER-H B Dute Power Ca 82/09/27 DENTOM: H A Defice Nuclear Reactor Regulation. Director 3pp 15886:104 24X Fiche 50-249.82/09/27-8210040232
- --8210040245 Proposed revision to Tech Spec Pages 3 3-6 & 6 4-1 re site emergency drill & time period within which redundant component test must be gerformed prior to performing maint 4 Duse Power Co 82/09/27 4pp 15586 107. 24% Fiche 50-269, 82/09/27, 8210040232

P Operating license stage documents & correspondence

- 8210080036 Responds to FOIA request for documents re pins designed to held neutron shielding pads in place under accident conditions Forwards documents listed on App A FELTON. Jh Division of Rules and Records 82/09/13 EDDLEMAN, W Public Interest Research Group in North Carolina 2pp 15669 240 24X Fich: 50-267, 82/08/13, 8210080036
- 8210040107 Advises that util response to NRC 820218 ltr will be provided by 821008 Receipt of info from crane vendor & extraordinary analytical work have delayed response TUCKER.H B Doke Power Co 82/09/24 DENFON.H R Office of Nuclear Reactor Regulation, Director STOLZ.J.F Operating Reactors Branch 4 1p 15581 024 24X Fichs 50-269.82/09/24,8210040107
- 82(0040R32 Application to amend Litenses DPR-35 DPR-47 & DPR-85 Amend requests deletion of Tech Spec 6 4 2 re-site emergency drill & definition of time within which redundant component test worthiston or time bitain which resumbant temporate tests must be performed prior to performing maint per Tech Spec
 TUCKER: H B Duke Power Go 82/09/27 DENTON, H R Office of
 Nuclear Reactor Regulation, Director SIOL 2. J F Operating React
 Branch 4 3pp 13586 104 24% Fiche. 50-269: 62/09/27. 8210040232
- --8210040245 Proposed revision to Tech Sper Pages 3 3-6 & 64-1 re sith emergency drill & time period within which redundant component test must be performed prior to performing maint a Duke Power Co 82/09/27 4pp 15586 107 24X Fiche 50-269,82/09/27,8210040232
- 8210190145 Forwards Amends 113,113 & 110 to Licenses DPR-3B.DPR-47 & DPR-55 respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to allow full power operation of Unit 3 during Fuel Cycle 7
 WAGNER.P C Operating Reactors Branch 4 82/09/27 TUCKER.H B
 Dute Power Co. 2pp 15757 341 R4X Fiche: 50-269, 82/09/29, Duke Power Co. 2pp 8210170145
- --9210190154 Amends 113.113 & 110 to Licenses DPR-38, DPR-47 & DPR-59, respectively, revising Tech Space to allow full power operation of Unit 3 during Fuel Cycle 7 BTOL7.J F. Operating Reactors Branch 4 82/09/29 3ipp 15757:343 24X Fiche 50-269.82/09/29.8210190145
- --8210190161 Bafety evaluation supporting Amenda 113,113 & 110 to Licenses DPR-3B,DPR-47 & DPR-55, respectively.

 **OPfice of Nuclear Reactor Regulation, Director B2/09/29 15758 012 24% Fiche 50-269, B2/09/29, B210190145. B2/09/29 608
- --B210190169 Notice of issuance & availability of Amends 113,113 & 110 to Licenses DPR-3B,DPR-47 & DPR-3B, respectively SYOUX, J F Gparating Reactors Branch 4 82/09/29 2pp 18758 018 24X Fiche: 50-269,82/09/29,8210190145
- 8210180323 Responds to 820913 itr re reactor bldg purge sys Position given in 810707 & 17 ltre remains unchanged Bchedule for submitting info indicating purge sys meets operability requirements requested LAINAS. O.C. Assistant Director for Operating Reactors. 82/09/30. TUCKER, H. B. Dute Pouer Co. Opp. 15745:034 24% Fichs 50-269, 82/09/30,8210190323
- 8210180055 Responds to NRC 820608 request for addl info re adequacy of 2101B0035 Responds to NNC 82060B request for add1 info re asequacy of station plectric distribution sys voltages. Requested info expected by 82/022.
 TUCKER, H B. Duke Power Co. 82/10/08. DENTON:H R. Office of Nuclear Reactor Regulation, Director. BTOLZ, J F. Operating Reactors Branch 4. 1p. 15720.010. 24X Fiche 50-269,82/10/08,8210180055.

- --8210180060 Forwards partial response to Franklin Research Ctr draft technical evaluation rept re control of heavy loads, per technical evaluation rept retuntrol or newly localiner.
 NURCO-0612
 TUCKER, H B Duke Power Co 82/10/08 DENTON, H R Defice of
 Nuclear Reactor Regulation, Director STOLZ, J F Operating
 Reactors Branch 4 Spp 15720 011 24X Fiche 30-269,82/10/02
- 8210210131 Responds to NRC 82090B itr transmitting technical evaluationary feedwater sys Sys may not meet all current criteria for seismic qualification, but will remain functionally operable during OBE TUCKER, H B Duke Power Co 82/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director SIGLZ, J F Dearsting Reactor Branch 4 4pp 15766 J56 24% Fiche 50-269, 82/10/13, 8210210131
- 8210210407 Application to amend Distrevising Tech Spec 3 I allowing full power operation of Unit 1 for interim period until appropriate safety valve ring settings can be implemented TUCKER. B Dute Power Co 82/10/14 DENTON. H R Office of Nuclear Reactor Regulation, Director STOLZ. J F Operating Reacts; Branch 4 Bpp 15764 038 24% Fiche 50-269,82/10/14,8210210407
- --82102104ti Proposed revision to Tech Spec 3 I allowing full power operation of Unit 1 for interim period until appropriate safety valve ring setting can be implemented a Duke Power Co 62/10/14 tp 15764 048 24X Fiche 50-269, 82/10/14, 8210210407
- Q Inspection reports, IE Bulletins & correspondence
- 8210070097 Responds to FOIA request for eight categories of recorders steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed (n App B FELTON, J M FÉLTON, J M Division of Rules and Records 82/08/10 LONO, D J Winthrop, Stimson, Putham & Roberts 9pp 15645-063 24X Fiche 80-000: 82/08/10, 8210070007
- --8210070172 Forwards info re steam generator integrity & imsps at all operating PMRs.per 750320 & 21 requests Details of incos. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach & GOLLER.K R Division of Reactur Licensing (NRR-1975 only) 75/03/24 MACCARY.R R Division of Technical Review (NRR-1975 only) Spp. 15845 196 24X Fiche 50-000,82/08/10,826070007
- 8210150369 Forwards results of investigation of Item 7a of IE Inty-Repts 50-269/82-21.50-270/82-21 & 50-267/82-21 Deadtime values for gamma spectroscopy analyses of waste gas silver require cartridges will cause only insignificant errors TUCKER, H B Dute Power Co 82/08/17 O'REILLY J P Region 2. Office of Director 2pp 13704 269 24X Fishe 50-269.02/08/17.
- 8210010117 Forwards 1E Insp Repts 50-249/82-33, 50-270/82-33 t 50-287/82-33 on 820817-20 No noncompliance noted DANGE.H.C Division of Project t Resident Programs 82/09, TUCKER,H B Duke Power Ca 2pp 15566 019 24x Fiche 50-269, 82/09/02, 8210010117 82/07/02
- --8210010124 IE Insp Repts 50-269/82-33,50-270/82-33 % 50-287/82-33 Aldublica it Insp Repts 50-267/02-33, 50-270/02-33 1 50-287/02-33 on 820817-20 No noncompliance noted Major areas inspected action on previous enforcement matters, auxiliary feedwater cardine repair & inservice insp procedures CROMLEY, B R , BLAKE, J J Division of Engineering & Technical Programs 82/09/01 Spp 15566 021 24% Fiche 50-269.82/09/28210010117
- 8210010158 Forwards IE Insp Repts 50-269/82-30, 50-270/82-30 t 50-287/82-30 on 820716-0810 No honcompliance noted DANCE, M. C Division of Project t Resident Programs E2/09, TUCKER, H. B Duke Power Co 2pp 15567 258 24% Fiche 50-269, 82/09/02, 8210010158 82/09/02
- ---8210010166 IE Insp Repts 50-269/82-30.50-270/82-30 & 50-287/82-30: 820716-0810 No noncompliance noted Major areas inspected operations, surveillance testing maint NUREG-0737 mods & orders, H., FALCONER, D., BRYANT, J.C. Division of Project & Reibt Programs. 82/09/02 13pp 15567 260. 24X Fiche 30-269.83/01 8210010158.
- 6210010458 Ack receipt of 620805 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/62-23, 50-270/62-23 & 50-287/62-23 EEKIG.R.C. Division of Project & Resident Programs 62/09/17. TUCKER, H B Dute Power Co ip 15570,182, 24X Fiche: 50-269, 82/09/17, 8210010458

DOCKETED ITEMS

- --8210010453 Responds to NRC 820712 ltr re violations noted in IE Insp Repts 50-269/82-23,50-270/82-23 & 50-207/82-23 Corrective actions personnel counseled & valve 24P-14 cut out & properly reinstabled TUCKER, H B Dute Pawer Co 82/08/05 O'REILLY, J P Region 2, Office of Director 4pp 15570 183 24X Fiche 50-269,62/09/17, 8210010458
- --B210010468 Forwards IE insp Repts 50-269/82-23,50-270/82-23 & 50-287/82-23 on B20510-0610 & notice of violation LENIS.R C Division or Project & Resident Programs B2/07/12 PARKER.N O Dute Power Co 2pp 15570 187 24X Fiche 50-269,82/09/17.8210010458
- --8210010471 Natice of violation from insp on 820910-0610 * Division of Project & Resident Programs 82/07/12 2p. 15570 189 24% Fiche 50-264, 82/09/17.8210010459
- --B210010474 IE Insp Repts 50-269/82-23.50-270/82-23 & 50-287/82-23 on 820510-0610 Noncompliance noted failure to follow procedures resulting in plant trip & inadequate procedure resulting in temproper reassembly of safety-related valve DRDERS, W. FALCONER. D. BRYANT, J. C. Division of Project & Resident Programs 82/07/09 12pp 15570 191 24X Fiche 50-269, 82/09/17, 8210010458
- 6210150253 Forwards IE Insp Repts 50-269/82-32,50-270/82-32 & 50-287/82-32 on 820817-18 No noncompliance noted DANCE H C Division of Project & Resident Programs 82/09/17 fucker, H B Dake Power Co 2pp 15703 267 24X Fische 50-269, 82/09/17,8210150253
- --0210150263 1E Insp Repts 50-269/82-32,50-270/82-32 & 50-287/82-32 on 020817-18 No noncompliance noted Major areas inspected lab QC & revieu of radiochemistry procedures & records EVAUS.C D , MONTOUMFRY.D II Division of Emergency Preparedness & Operational Support 82/09/15 3pp 15703 269 24X Fiche 50-269,82/09/17.8210150253
- 6210150131 Forwards IE insp Repts 50-269/82-35,50-270/82-35 & 50-287/82-35 on 820908-10 No noncompliance noted DANCE. H C Division of Project & Resident Programs 82/09/23 TUCKER. H B Dake Power Co 2pp 15698 312 24X Fiche 50-269, 82/09/23,8210150131
- 0210130290 Requests relief from inservice insp requirements (hydrostatic) of Section XI of ASME Boiler & Pressure Vessel Code TUCKER.H B Duke Power Co 82/10/04 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ.JF Operating Reactors Branch 4 20pp 15678 243 24X Fiche 50-269,82/10/04,8210130290
- B20B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Syc list encl COBB.L ! Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York 64pp 15761 250 244 Fiche 50-000. B2/10/06, B208190233
- 8210220426 Forwards Revision 5 to response to IE Bulletin 79-02. "Pipe Support Dase Plate Designs Using Concrete Expansion Anchor Bolts" TUCKER, H B Duke Power Co 82/10/08 O'REILLY, J P Region 2, Office of Director 24pp 15778 273 24X Fiche 50-269, 82/10/08,
- 620B17023B IE Builstin 82-03, "Btress Corrosion Cracking in Thick-Hall:Large-Diamster, Stainless Steel: Recirculation Bys Piping at DUR Plants "Sve list enci DEYDUNG: R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York, 115pp 15810 125 24X Fichs 50-000: 82/10/14: 820819023B
- R Periodic operating reports & related correspondence
- 8210190544 Forwards monthly operating repts for Bept 1982 TUCKER, H B Duke Power Co 82/10/15 Director's Office, Office of Inspection and Enforcement ip 15751 343 24X Fiche 50-269, 82/10/15,8210190544
- --8210190552 Monthly operating repts for Sept 1982 REAVIS-J A Duke Power Co 82/10/15 16pp 15751 344 24X Fiche 50-269, 82/10/15, 82101905044

- 8 Reportable occurrences. LERs & related correspondence
- 8210190653 PNO-II-82-111 on 821014. Unit 2 shut down after determining that pressurizer code safety valve design flow could not be fully maintained if called upon Seven-day outage required to change valves Exemption requested for Unit 1 IGNATONIS. A. DANCE. H. C. Region 2. Office of Director 62/10/14 2pp 15740 036 24% Fiche 50-267.82/10/14.8210190653
- 8210170695 RO on 821014. Unit 2 core relief valves declared inoperable due to analysis prompted by BEM safety concern Unit 3 valves were offsite undergoing ring adjustment Immediate shutdown of Unit 2 commenced

 Duke Power Co. 82/10/14 Region 2, Office of Director ip 15736 200 24% Fiche 50-270.82/10/14.8210170645
- 8210290083 Forwards LER 82-012/03L-0 Detailed event analysis enci TUCKER.H B Duke Power Co 82/10/15 O'REILLY,J P Region 2, Office of Director 2pp 15854 047 24X Fiche 50-270,82/10/15, 8210270083
- --B2102700B7 LER 82-012/03L-0 on 820714, turbine driven emergency feedwater pump declared inoperable when trip/thruttle valvo 2MS-74 discovered tripped in closed position Cause not known Valve resut Video alarm will be repaired PETTY, J C Duke Power Co 82/10/15 Region 2, Office of Director ip 15854 049 24X Fiche 50-270, 82/10/15,8210270080
- DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

 F Security, modical, emergency & fire protection plans
- 8210120346 Informs that Revision 6 to physical security plan acceptable Encl to 820720 itr transmitting revision withheld (ref 10CFR73 21) VASSALLO.D B Operating Reactors Branch 2 82/09/22 SINCLAIR. J B Vermont Yankee Nuclear Power Corp 2pp 15691 101 24X Fiche 50-271.82/09/22.8210120346
- 6210210221 Forwards IE Safeguards Insp Ropt 50-271/82-15 on 820728-30 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs B2/10/04 SINCLAIR. U. Permont Yankee Nuclear Power Corp 2pp 15766 331 24
- --B210210238 IE Safeguards Insp Rept 50-271/82-15 on 820728-30 No noncompilance noted Major areas inspected facility organization, measurement & controls, shipping & receiving storage & internal control & physical inventory DELLA RATTA, A. WOLTNER, E.F. GODY, A.T. Division of Engineering & Technical Programs B2/07/30 7pp 15766-333 24X Fichs 50-271, 82/10/04, 821021021
- B210270426 Releases public version of revised emergency plan FELTON, J M Division of Rules and Records 62/10/08 Document Management Branch 1p 15833 054 24X Fiche 50-271,82/10/08, B210270425
- --B210270430 Forwards public version of Revision 4 to emerge MARKT.D.I Vermont Vankee Nuclear Power Corp., MARKT.D. Atomic Electric Co. 82/09/90. Office of Nuclear Reac Regulation. Director 2pp 15833 055 24X Fiche 50-27 8210270426
- --8210270432 Public version of Revision 4 to emergency plan MURPHY, W F Vermont Yankee Nuclear Power Corp 82/09/28 15833 097 24X Fiche 50-271,82/10/08,8210270426
- 8210180190 Forwards edd1 info requested in 820812 telcon re pr atternate shutdown sys Encl info addresses separate routing of cables for valves FCV 2-17 & FCV 2-18 & RHR valves V10-17 & V10-18 MARSOLAIB.L D Vermont Yankee Nuclear Power Corp 82/10/11 VASSALLO.D B Operating Reactors Branch 2 2pp 15719 118 Fichs 90-271.82/10/12,8210180190
- 6210220411 Ack receipt of 820908 itr informing NRC of steps to carrect violations noted in 1E Insp Rept 50-271/82-05.
 ALLAN J. H. Region 1, Office of Director 82/10/12 MURPH)
 Vermont Yankse Nuclear Fouer Corp. 1p. 15780 228 24%
 Fiche 50-271, 82/10/12, 8210220411
- --8210220418 Responds to NRC B20722 itr re violations noted in Rept 50-271/82-05 Corrective actions study performed to determine how intent of augmentation goals of NUREO-0554 could be achieved after declaration of emergency.

 MURPHY, W P Vermont Yankee Nuclear Power Corp. 82/09/08 SMITH, 0 H Division of Emergency Preparedness & Operation Support. 29pp 15780 229 24X Fichs 50-271,82/10/12,821

- 8210280134 Releases public version of emergency plan ltrs of agreement FELTON, J N Division of Rules and Records 82/10/12 Document Management Branch 1p 15842 248 24X Fiche 50-271.82/10/12.8210280134
- --B210280438 Forwards public version of errata to Change 4 to emergency plan App E. consisting of ltrs of agreement between licensee & States of V.F.M. D. N.U.A. U.S. Air Force & various local hosps & businesses Receipt form enc!
 HARKE.D. Vermant Yankee Nuclear Power Curp MARKE.D. Yankee Atomic Electric Co. 82/10/05. Office of Nuclear Reactor Regulation. Director 1p. 15862 249. 24X Fiche 50-271.82/10/12, 8210280136.
- -- B210280143 Public version of errats to Change 4 to emergency plan App E. consisting of Itrs of agreement between licensee & States of VT. (A& & NH. (NDAA. US Air Force & various local hosps & businesses e Vermont Vankee (Nuclear Power Corp. & Yankee Atomic Electric Co. B2/10/05 Pipp. 158/2 250 24X Fiche 50-271.82/10/12.
- P Operating license stage documents & correspondence
- 8210210185 Forwards safety evaluation of methods used for analysis of physics & thermal-hydraulic performance VASSALLO.D B Operating Reactors Branch 2 82/09/15 SINCLAIR, J B Vermont Yankes Nuclear Power Corp 2pg 15774 270 24X Fiche 50-271-82/09/15,8210210185
- --B210210200 Safety evaluation supporting reload analysis methods based on review of technical repts submitted by util re analysis of physics & thermal-hydraulic performance BROOKS, H. H911, Y. ROGNEY, V. Office of Nuclear Reactor Regulation. Director 82/09/15 27pp 15774 272 24% Fiche 50-271.82/09/15.8210210185
- 8210210101 Forwards Amend 72 to License DPR-28, safety evaluation & notice of issuance & availability Amend incorporates revised core thermal hydraulic limiting conditions of operation during Fuel Cycle 9
 RODREY.V L Deprating Reactors Branch 2. 82/09/16 SINCLAIR, J B Venenot Yankee Nuclear Power Corp 2pp 15774 301 24X Fiche 50-271, 62/09/16, 62102/0101
- --B210210112 Amend 72 to License DFR-28, changing Tech Specs to incorporate revised core thermal hydraulic limiting conditions during Funl Cycle 9
 VASSALLO.D B Operating Reactors Branch 2 62/09/16 App. 15774 303 24X Fiche 50-271.82/09/16.8210210101
- --0210210121 Safety evaluation supporting Amend 72 to License DPR-28 * Office of Nuclear Reactor Regulation, Director 62/09/16 App 15774 307 24X Fishe 50-271,82/09/16,8210210101
- --8210210127 Notice of issuance & availability of Amend 72 to Lirense DPR-28 VASSALLO, D 8 Operating Reactors Branch 2 82/09/16 2pp 15774 311 24X Ficher 50-271, 82/07/16,8210210101
- 8210040113 Comments on systematic assessment of licenses performance rept.discussed at 820708 meeting Rept fair appraisal of activities for rept period MRPHY, N P Vermont Vankes Nuclear Power Corp 82/07/28 STAROSTECKI, R Division of Project & Resident Programs 2pp 15581 144. 24x Fichs 50-271,82/09/28.8210040113
- 9210120343 Requests listing of submittals re inservice testing program within 30 days
 vASBALLO, D B Operating Reactors Branch 2. 82/09/28 SINCLAIR, J B
 Vermont Yanker Nuclear Power Corp 2pp 15693 039 24X
 Fichs 50-271, 82/09/28, 8210120343
- 8210150447 Informs that revision to administrative section of Tech Specs re shift manning requirements & working hour guidelines not appropriate Suitable controls already imposed twill be subj to insp & enforcement by Region 1 MURPHY. W P Vermont Yankee Nuclear Power Corp 82/10/12 EISENHUT, D O Division of Licensing 1p. 15705 028 24X Fiche 50-271, 52/10/12, 8210150447
- B210270356 Advises that util response to NUREO-0578 also setisfies NUREO-0737. Item II E 4 1. "Bedicated Hydrogen Penetrations " Item resolved.
 VABBALLO, D B Operating Reactors Branch R 62/10/14 BINCLAIR, J B Varnont Yankee Nuclear Power Corp is 15834 359 24X Fithe. 50-271. 92/10/14, 8210270356.

- Q Inspection reports. IE Bulletins & correspondence
- B21005044B Forwards request for addt info based on review of 800/07 & 1110 responses to IE Builetin 80-11 re masonry wall design VASSALLO, D B Operating Reactors Branch 2 82/08/30 SINCLAIR, J & Vermont Yankee Nuclear Power Corp Spp 15612 357 24X Fiche 50-271, 82/08/30, 8210050448
- 8210070376 Forwards IE 10sp Rept 50-271/82-16 on 820802-30 No noncompliance noted STARDSTECKI, R Division of Project & Resident Programs 82/09/28 SINCLAIR. J B Verment Yankee Nuclear Power Corp 2pp 15633 3±0 244 Fiche 50-271, 82/09/24, 8210070376
- --8210070393 IE Insp Rept 50-271/82-16 on 820802-30 No noncompliance noted Najor areas inspected previous insp findings.plant operations.physical security.operational surveillance, maint activities & safeguard sys operability RAYMOND.W J. OALLO.R H Division of Project & Resident Programs 82/09/22 16pp 19634 001 24X Fishe 50-2/1.82/09/24.621007027c
- B210010135 Advisos that all future correspondence from Region 1 (1) be addressed to MP Kurphy Change will assure direct communication to senior licensee mgt re NRC insp findings, enforcement actions or requests HAYNES.R C Region 1. Office of Director B2/09/27 MURPHY. IF P Vermont Yankee Nuclear Power Corp 3pp 19567 237 24X Fiche 50-2/1. 82/09/27. 8210010136
- 921015024& Forwards IE insp Rept 50-271/87-14 on 820704-30 & notice of violation
 STAROSTECKI,R Division of Project & Resident Programs 62/09/22
 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 2pp 15704 334
 24X Fiche 50-271.82/09/27.8210150246
- --8210150258 Notice of violation from insp on 820706 30
 # Division of Project & Resident Programs 82/09/27 lp
 15704 336 24% Firhe 30-271.82/09/27.8210150246
- --BRIO150274 IE Insp Rept 50-271/B2-14 on BRO706-30 Noncompliance noted failure to post hot spot radiation area per plant Administrative Procedure 0503 & Tech Beece RAYMOND. W J . COLLING. B J . GALLO. R M Division of Project & Resident Programs 02/07/21 20pp 19704 337 24x Fiche 50-271.82/07/27.8210150246
- 8210040113 Comments on systematic assessment of licenses performance rept. discussed at 820908 meeting Rept fair appraisal of activities for rept period MURPHY. W P Vermont Yankee Nuclear Power Corp 82/09/20 STAROSTECKI, R Division of Project & Resident Programs 2pp 15581 144 24% Fiche 50-271,82/09/28,8210010113
- 8210210221 Forwards IE Safeguards Insp Rept 50-271/8P-15 on 8207.8-3. No noncompliance noted MARTIN.T Y Division of Engineering & Technical Programs 82/10. SINOLAIR, J B Vermont Yankes Nuclear Power Corp 2pp 15765 31 24X Fiche 50-271.82/10/04.8210210221
- --8210210238 IE Bafeguards Insp Rept 50-271/B2-15 on 870778-10 No noncompliance noted Major areas Inspected facility organization, measurement & controls, whipping & receiving storage & internal control & physical inventory DELLA RATTA. A. WOLTNER: E F. ODDY, A T. Division of Engineering Technical Programs & 82/09/30 Ppp 15766-333 24X Fiche. \$0-271,82/10/04,8210210221
- 8208190203 lE Info Notice 80-33, Suppl 1, "Leaking & Dislodged 3-121 implant Seeds " Syc list entl COBB-L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & Sapp 15761 2' 24% Fiche 50-000,62/10/06,6208190233.
- 8210150267 EN-82-033 on or about 821015, notice of violation to heter civil penalty will be issued Action based on violation refailure of station personnel to promptly recognize changes in actus of safety-related equipment CRAIG. J. AKELRAD, J. Region i. Office of Director 82/10/12 1 15703 244 24% Fiche 30-271, 82/10/12, 8210190267
- 8210220411 Ack receipt of 820708 ltr informing NRC of steps talen; correct violations noted in IE Insp Rept 50-271/82-05 ALLAN.J N Region I. Office of Director 82/10/12 MURPHY, W p Vermont Yankse Nuclear Power Corp ip 18780 228 24X Fiche 50-271.82/10/12.8210220411

- -8210220418 Responds to NRC 820722 itr re violations noted in IE Insp Rept 50-271/82-05 Corrective actions study performed to determine now intent of augmentation goals of NUREO-0654 could be achieved after declaration of emergency MURPHY, M P Vermont Yankee Nuclear Power Corp 82/09/08 SMITH.O H Division or Emergency Preparedness % Operational Support 29pp 15780 229 24% Fiche 50-271,82/10/12,8210220411
- 6208190238 IE Bulletin 82-03. "Stress Corrosion Crecking in Thick-Mallitarge-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants " Svc list enci DEYGUNO.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidate Edison Co of New York 115pp (5810-125 24x Fiche 50-000.82/10/14.8208190238
- R Periodic operating reports & related correspondence
- 5310130189 Forwards monthly operating rept for Sept 1982 HURPHY, W.P. Vermont Yonkee Nuclear Power Corp. 82/10/08 Management Information Branch 1p 15674 107 24X Fiche 50-271, 82/10/08, 8210130189
- --8210130193 Monthly operating rept for Bept 1982 BURGER, F J Vermont Yantoe Nuclear Power Corp 82/10/08 6pp 15674 108 24X Fiche 50-271,82/10/08,8210130189
- S Reportable occurrences, LERs & related correspondence
- 62:0190022 Forwards LER 62-020/03L-0
 PELLETIER, J P Vermont Yanker Nuclear Power Corp 82/10/05
 HAVNES, R C Region 1, Office of Director 1p 15742 139 24X
 Fiche 50-27L 62/10/05, 8210190022
- --8210190029 LER 82-020/03L-0 on 820702, indication on RHR 89B blinked on & off at 2.700 gpm flow rate indication lost when valve shut Caused by loose wiring on valve limit switch resulting in loss of position indication Connection tightened PELLETIER J P Vermont Yankee Nuclear Power Corp 82/10/05 Region 1. Office of Director 3pp 15742 140 24X Fiche 50-271.82/10/05,8210190022
- B210210204 Forwards LER 82-021/03L-0
 PELLETIER, J P Vermont Yankee Nuclear Power Corp B2/10/12
 HAYNES, R C Region 1, Office of Director 1p 15766 343 24X
 Fische 50-271, 82/10/12.8210210204
- --8210210214 LER 82-021/03L-0 on 820914, while performing pump operability surve; llence on RCIC sys.RCIC tutbine tripped on overspeed Caused by failure of electric governor module Module replaced Bad transistor found in tach generator PELLETIER. J. P. Vermont Yankee Nuclea: Power Corp. 82/10/12 Region 1. Office of Director ip 15766-344 244 Fiche 50-271.82/10/12.8210210204
- DOCKET 50-272 GALEM NUCLEAR GENERATING STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8210250245 Forwards 1982 FEMA/NRC observed exercise scenario for B21013 erercise Revisions reflect changes agreed upon during 820420 neeting w/NRC & FEMA ZUPMCD.J M Public Bervice Electric & Gas Co of New Jersey 82/09/16 HAYNEBJR C Region 1, Office of Director 148pp 15789 002 24X Fiche 50-272.82/09/16.8210250245
- 6210240518 Forwards exemption from requirements of 10CFR50 48 re fire protection of safe shutdown capability VARGA: 8 A Operating Reactors Branch I 82/09/14 UDERITZ: R A Public Service Electric 8 0as Co of New Jersey 3pp 15830 168 24X Fiche 50-272.82/09/16.8210240518
- --8210260521 Exemption from requirements of 10CFR50 48 re fire protection of safe shutdown capability
 EISENHUT.D 0 Division of Licensing 82/09/16 Public Service
 Electric & Cas Co of New Jarey App 15830 171 24X
 Fiche 50-272,82/09/16.8210260518
- --8210240524 Safety evaluation supporting licensee request for exemption from requirements of 10CFR50 48 re fire protection of safe shutdown capability # Office of Nuclear Reactor Regulation, Director 82/09/16 3pp 15830 175 24X Fiche 50-272.82/09/16.8210240518
- 8210040431 Forwards exemption from requirements of Bection IV F 1 of App E to 10CFR50, to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820729; granting 820709 request VAROA.S A Operating Reactors Branch 1 82/09/23 UDERITZ, R A Public Service Electric & Cas Co of New Jersey 3pp 15536 227 244 Fichs. 50-272, 82/09/23. 8210060431

- --8210060433 Exemption from requirements of Section IV F 1 of App E to 10CFR30 to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820929 Evaluation encl EISENHUT. D 0 Division of Licensing 82/09/23 Public Service Electric & Oas Co of New Jersey 5pp 15636 230 24X Fiche 50-272.82/09/23.8210060431
- P Operating license stage documents & correspondence
- 8210050485 Forwards documentation of satisfactory completion of requirements contained in 790921 ltr re TMI Action Item II E 1 i concerning auxiliary feedwater sys VAROA.6 A Operating Reactors Branch I 82/09/20 UDERITZ.R A Public Service Electric & Oas Co of New Jersey 3pp 15626 277 24X Fiche 50-272.82/09/20.8210050485
- --8210050490 "Suppl to Safety Evaluation Rept for Salem Units 1 & 2 Implementation of Recommendations for Auxiliary Feedwater Sys "

 ** Office of Nuclear Reactor Regulation, Director 82/09/20 3pp 15626 280 24% Fiche 50-272.82/09/20.8210050485
- G210130403 Advises that installed monitoring sys required by TMI Action Items II F 1 4.II F 1 5 & II F 1 6 acceptable & items considered closed VAROA.B A Operating Reactors Branch 1 B2/09/28 UDERITZ, R A Public Service Electric & Qas Co of New Jersey 2pp 15692 349 24X Fiche 50-272.82/09/28.8210130603
- 8210190047 Informs that util rod exchange methodology not approved because of calculational content of roactvity measurement New submittal or return to boron dilution method requested VAROA.8 A Operating Reactors Branch 1 82/09/29 UDERITZ.R A Public Bervice Electric & Qas Co of New Jersey 3pp 15761 04f 24X Fiche 50-272.62/09/29,8210190047
- 8210190507 Application for amend to Licenses DPR-70 & DPR-75, revising core limits, fractional thermal power factor limit, performance of RCB water inventory balance & boron concentration & contained voi limits LIDEN, E A Public Service Electric & Gas Co of New Jersey B2/10/05 VARCA, S A Operating Reactors Branch i 2pp 15863 124 24X Fiche 50-272, 82/10/05, 82/10/90507
- --8210190515 Proposed Tech Spece supporting application to amend Licenses DPR-70 & DPR-75, revising core limits, fractional power factor limit, performance of RCB water inventory balance & boron concentration & contained vol limits

 * Public Service Electric & Oas Co of New Jersey 82/10/05
 17pp 15863 126 24% Fichs 50-272,82/10/05.8210190507
- 8210270136 Licenso Chango Requests 82-17-20-21 & 22 to Licenses DFR-70 & DFR-75 Changes involve inservice insp of snubbers steam generator insp ports, containment ventilation valve insp & surveillance functional testing
 LINDEN.E A Public Service Electric & Gas Co of New Jersey
 82/10/07 VAROA: 8 A Operating Reactors Branch | 3pp | 15827 026
 24X Fichs 50-272.82/10/07.8210270136
- --8210270142 Proposed Tech Spec changes re inservice insp of snubbers, installation of steam generator insp ports, pressure drop test & reactor trip instrumentation # Public Service Electric & Gas Co of New Jersey 82/10/07 8pp 15827 029 24X Fiche 50-272,82/10/07,8210270136
- 8210160009 Advise, that design changes satisfying concerns expressed in 620917 request for addl info re reactor protection sys/EGF actuation sys initiated Tech Specs will be modified to address setpoint changes
 LIDEN.E A Public Service Electric & Gas Co of New Jersey, 62/10/08, VARQA.E A Operating Reactors Branch I ip 15720 024 24% Fiche 50-272,62/10/08,62101600009
- 6210220275 Informs that review & plans re Cycle 5 reload core is expected to achievs burnup of 11500 MMD/MTU Startup physics testing will include control rod drive tests & droptims & critical boyon concentration grassuraments
 LIDEN, E. A. 'Public Service Electric & Gas Co. of New Jersey
 62/10/14 VAROA. B. Operating Reactors Branch i 4pp. 15778 191
 24X Fiche 50-272, 62/10/14, 6210220275
- 8210270332 Forwards Amends 48 & 13 to Licenses DFR-70 & DFR-75, respectively, safety evaluation & notice of issuance & availability Amend revises process & effluent monitors to agree wirxisting plant conditions ROSB.W J Operating Reactors Branch 1 82/10/18 UDERITZ.R A Public Service Electric & Cas Co of New Jersey 2pp 15834 318. 24X Fichs 50-272.82/10/18.8210270352

- --8210270355 Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively, revising process & effluent monitors to agree w/esisting plant conditions VAROA, 5 A Depending Reactors Branch 1 82/10/18 14pp 15834 320 24X Fiche 50-272,82/10/18,8210270352
- --B210270360 Safety evaluation supporting Amends 48 & 13 to Licenses DPR-70 & CPR-75, respectively. • Office of Nuclear Reactor Regulation, Director 15834 334 24% Fiche 50-272.82/10/18.8210270352
- --8210270366 Notice of issuance & availability of Amends 48 & 13 to Licenses DPR-70 & DPR-75.respectively VARGA.S A Operating Reactors Branch 1. 82/10/18 2pp 15834 340 24X Fiche 50-272,82/10/18.8210270352
- O Inspection reports, EE Bulletsns & correspondence
- 8210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15565 027 24X Fiche 50-000.82/07/12.8210080015
- --8210080150 Sqstematic assessment of litensee performance notes re facility evaluation for Sept 1979-Aug 1980 4 NRC - No Detailed Affiliation Given 80/08/31 8pp 13568 043 24X Fiche 50-000,82/07/12,8210080015
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON. J H Division of Rutes and Records 82/08/10 LONG. D J Winthrop. Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 80-000.82/08/10.8210070007
- --8210070837 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees
 IPPOLITO.T Operating Reactors Assessment Branch 82/04/01
 VAROA:S Operating Reactors Branch 8, 5pp 13645 131 24X
 Fiche 50-000, 82/08/10, 8210070007
- 8210120328 Responds to violations noted in IE Insp Repts 50-272/82-17 b 50-311/82-17 on 820707-0803 Corrective actions administrative procedure will be revised so future temporary design changes are removed on timely basis UDERITIZ. A public Service Electric & Oas Co of New Jersey 82/09/28 HAYNSS,R C Region 1, Office of Director STAROSTECKI.R Division of Project & Resident Programs 5pp 15652 125. 24X Fiche 50-272.82/09/28.8120120328
- 8210210146 Forwards IC lnsp Rept 50-272/82-23 on 820831 & 0901-03 No noncompliance noted MARTIN-T T Division of Engineering & Technical Programs. 82/10/05 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 2pp 13746 092 24x Fiche 50-272.82/10/05.82/02/20146
- --8210210162 IE Insp Rept 50-272/82-23 on 820831 & 0901-03 No noncompliance noted Major areas inspected inservice testing surveillance program for pumps & vaives & containment penetration leakage testing surveillance REKITO.4 A , RETTENMAUSEN.L Division of Engineering & Technical Programs 82/09/29 5pp 15746 094 24X Fiche 50-272,82/10/05,8210210146
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Syc list enc! COBB.t I Division of Fuel Facilities, Materials & Safeguerds 62/10/06 Consolidated Edison Co of New York 64pp. 15761 250 24X Fiche: 50-000, 82/10/06, 8208190233
- 8210210435 Forwards IE Insp Repts 50-272/82-20 & 50-311/82-20 on 820816-20 No noncompliance noted MARTIN-T T Division of Engineering & Technical Programs. 82/10/04 UDERITZ:R A Public Service Electric & Gas Co. of New Jersey. 2pp 15763.036 24% Fiche 50-272.82/10/06.8210210435
- --8210210451 IE Insp Repts 50-272/82-20 & 50-311/82-20 on 820816-20 No noncompliance noted. Major areas inspected; qualification & training, radiological surveys, rediation exposure permits, posting, licensee audits & exposure control HOSEY. C. H. ROWE, C. A. PREEMMAN. E. Q. Division of Engineering & Technical Programs 8 2709/20. Spp 15763:038, 24% Fiche 50-272, 82/10/06, 8210210435.

- 8210210464 Forwards IE (nsp. Repts 50-272/82-25 & 50-311/82-24 an 820901-27 & notice of violation 81AROSTECKI.R Division of Project & Resident Programs 62/10 A UDERITY.R A public Service Electric & Oas Co. of New Jersey 2, 13763 018 24X Fiche 50-272,827/10/06.8210210464
- --8210210469 Notice of violation from insp on 820901-27 * Region 1. Office of Director 82/10/06 1p 15763 020 : Fiche 50-272,82/10/06.8210210464
- --8210210477 IE Insp Repts 50-272/82-25 & 50-311/82-24 on 820%1-2*
 Noncompliance noted trip breakers closed w/o two operable source range instruments in svc & failure to submit 30-day LER
 NORRHOLM, L J , SUMMERS, R , TRIPP, t E Division of Project & Resident Programs 82/10/04 15pp 15763 021 24%
 Fiche 50-272.82/10/06.8210210464
- 8210270136 License Change Requests 82-17-20-21 & 22 to License F67 & DPR-75 Changes involve inservice insploy solublers steam generator insployts conditainment ventilation valve insploys surveillance functional testing LINDEN E A Public Bervice Electric & Gas Co. of New Jersey 62/10/07 VAROA, S A Operating Reactors Branch i 3pp. 15927 C 24X Fiche 50-272-82/10/07.8210270136
- --8210270142 Proposed Tech Spec changes re inservace insp of small installation of steam generator insp ports.pressure drop test & reactop trip instrumentation a Public Service Electric & Oas Co of New Jersey 92/10/63 8pp 15827 029 24% Fiche 50-272, 82/10/07.8210270136
- 8208190238 IE Builetin 82-03, "Stress Corresson Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants " Svc list encl DEYGUNO.R C Director's Office, Office of Inspection and Endorcement 82/10/14 Consolidated Edison Co of New York #15pp 15810 129 24% Fiche 50-000.82/10/14.8208190238
- 8210280221 EN-82-034 on 821027 notice of violation & proposed imposition of civil penalty in amount of \$40,000 issued reinadequate vital physical area barrier ROSANO, R. AXELRAD, J. Director's Office, Office of Inspirition by Enforcement 82/10/22 ip 15837 089 24X Fiche 50-272,82/0.2 8240260221

6.

60

62

621

- R Periodic operating reports & related correspondence
- 0210200085 Forwards monthly operating rept for Sept 1982
 MIDURA.H J Public Service Electric & Gas Co of New Jersey
 02/10/10 Director's Office of Inspection and Enforcer1p 19757 201 24X Fiche 50-272,82/10/10,8210200085
- --8210200090 Monthly operating rept for Sopt 1982
 MILLER, L K Public Service Electric & Oas Co of New Jersey
 62/10/10 14pp 15757 202 24% Fiche 50-272, 88/10/10.821000.2
- S Reportable occurrences: LERs & related correspondence
- 8210120369 Discusses consistent failure of solenoid valves in conteniment fan coil unit syc water flow control valves Licensee investigation determined that overheated valves caused sticking Valves replaced CHIRAMALIM Director's Office 80/09/12 Director's Office L 15690 190 24X Fiche 50-272,80/09/12,8210120369
- B21001000B Responds to FOIA request for 19 categories of documents ranuclear reactor events & safety problems Forwards documents listed in App A
 FELTON, J.M. Division of Rules and Records 82/06/20 UDELLR & Critical Mass Energy Project 15pp 15727 005 24X
 Fiche 50-000, 82/06/28, 8210010008
- ---3202120236 Notifies that imadvertent isolation of containment for coolers sys due to radiation alarms is not likely LER re syr water isolation valves found closed to containment fan coil units does not merit further consideration LANNING, W Director's Office 82/01/21. HICHELSON, C Director Office 82/01/21. HICHELSON, C Director Office 82/01/21.
- 8210080015 Add1 response to FOIA request for 19 categories of infar nuclear reactor events & safety problems Forwards documents listed in App A Documents in App 8 completely withheld (ref FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 82/07/12, UDELL.PA Critical Mass Energy Project 9pp 15665 027 24X
 Fiche 50-000, 82/07/12,8210080015

- 8210610181 Forwards LER 82-069/03L-0 Detailed event analysis encl HICUPA: H J Public Service Electric & Gas Co of New Jersey 82/09/16 HAYNES: R C Region 1. Office of Director 3pp 15367 302 24x Fiche 50-272,82/09/16.8210010181
- --8210010172 LER 82-069/03L-0 on 820831, svc water leak discovered on charging pump 12 lube oil coaler outlet piping & pump declared imoperable Caused by erosion of piping by silt-laden svc water Pips replaced INSLLER, R Public Service Electric & Cas Co of New Jersey 82/09/16 Region 1, Office of Director 1p 15567 305 24X Fische 50-272,82/09/16,8210010181
- 8210010383 Forwards LER 82-068/03L-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Gas Co of New Jersey 82/09/16 HAYNES: R C Region 1. Office of Director 3pp 15589 193 24% Fiche 50-272.82/09/16:8210010383
- --8210010390 LER 82-068/03L-0 on 820827,100-ft slevation containment air lock declared inoperable after excessive leakage discovered gast inner door seals Caused by closing door w/excessive force Seal replaced installation of snubbers proposed HELLER.R Public Service Electric & Gas Co of New Jersey 82/09/16 Region 1, Office of Director 1p 15569 196 24X Fiche 50-272.62/09/16.8210010383
- B210070305 Forwards LER 82-073/03L-0 Detailed event analysis encl MIDURA.H J Public Service Electric & Gas Co of New Jersey B2/09/22 HAYMES,R C Region 1. Office of Director 3pp 15634 107 24X Fiche 50-272, 82/09/22, 8210070305
- --8210070314 LER 82-073/03L-0 on 820906, calculation showed that quadrant power tilt ratio for bottom detector N42 exceeded max allowable (smit Caused by failed milliamp detector switch in current meter assembly Assembly replaced & channel tested FRAHM.R Public Service Electric & Gas Co of New Jersey 82/09/22 Region 1. Defice of Birector 1p 15634 110 24% Fiche 50-272,82/09/32,82/0070305
- I210070368 Forwards LER 82-074/04L-0 Detailed event analysis encl MIDURA.N J Public Service Electric & Gas Co of New Jersey B2/09/22 HAYNES.R C Region 1. Office of Director 3pp 13634 031 24x Fiche 50-272,82/09/22,8210070368
- -8210070375 LER 82-074/04C-0 on 820903, indication of unplanned release through plant vent received Three individuals contaminated during attempts to locate source Caused by door hitting against drain valve ICV332, causing valve to loosen & open HELLER.R Public Service Electric & Gas Co of New Jersey 82/09/22 Region I. Office of Director ip 15634 034 24X Fiche 50-272, 82/09/22, 8210070368
- 210070380 Forwards LER 82-071/04L-0 Detailed event analysis encl HIDURALH J Public Service Electric & Oas Co of New Jersey 82/09/22 HAYNES.R C Region 1. Office of Director 3pp 13633 336 24X fiche 50-278.82/09/22.8210070380
- -B210070393 LER B2-071/04L-0 on 920827.control operator discovered increasing level on plant vent radioactivity monitor & assued significant event notifications for unplanned releases Caused by primary coolant leakage from RCB filter FRAMM.R Public Service Electric & Qas Co of New Jersey 62/09/22 Region 1. Defice of Director ip 15633 339 24X Fiche 50-272,82/09/23,8210070380
- 210150058 Forwards LER 02-066/03X-1 Detailed event analysis encl MIDURA, H J Public Service Electric & Oas Co of New Jersey 82/09/29 HAYNES, R C Region 1. Office of Director 3pp 15698 276 24X Fiche 50-272, 02/09/29, 8210150058
- -8210130066 LER 62-046/03/-1 on 820825,100 ft elevation containment air lock outer door discovered not properly sealed Caused by seal damage due to personnel closing door w/excessive force Seal replaced & door tested satisfactorily HELLER.R Public Service Ejectric & Gas Co of New Jersey 82/09/27 Region i. Office of Director ip 15698 279 24X Fiche 50-272,82/09/27,8210150058
- P10150D71 Forwards LER 82-044/03X-1 Detailed event analysis encl MIDURA.H J Public Service Electric & Oas Co of New Jersey 82/09/29 HANYES.R C Region 1. Office of Director 3pp 15701 243 24X Fiche 50-278,82/09/29,8210150071
- 8210150075 LER 82-044/03Y-1 on 820623, during routine operation, vital ventilation control ctr 10 tripped, rendering control room emergency air conditioning fan 12 inoperable. Caused by setpoint driff & breaker iCi6Y trip Breaker replaced HELLER, R Public Service Electric & Oas Co of New Jersey 62/09/29 Region i. Office of Director ip 15701 246 24X Fiche 50-272, 82/09/29, 8210150071

- 8210150111 Forwards LER 81-019/03X-1 Detailed event analysis encl MIDURA.H J Public Service Electric & Qas Co of New Jersey 82/09/27 HAYNES.R C Region 1. Office of Director 3pp 15697 070 24X Fiche 50-272.82/09/29.8210150111
- -8210150121 LER 81-019/03X-1 on 810221, fire alarm annunciation on Panel 1RP5 for waste gas compressor observed but no audible alarm heard Caused by failure of amplifier to discriminate sysnaise from announcement function Amplifier adjusted HELLER, R Public Service Electric & Gas Co of New Jersey 82/09/29 Region 1. Office af Director ip 15697 073 24X Fiche 50-272,82/09/29.8210150111
- B210150127 Forwards LER B2-067/03L-0 Detailed event analysis encl MIBURALH J Public Service Electric & Oas Co of New Jersey B2/09/29 HAYNES.R C Region 1, Office of Director 3pp, 15698 324 24X Fiche 90-272.82/09/29.8210150127
- --8210150140 LER 82-047/03L-0 on 820712, no indication of eye water flow to containment fan coal unit f1 noted while coal unit f4 inoperable Caused by terminal screw on eye water flow transmitter breaking off Screw replaced FRAMM.R Public Service Electric & Oas Co of New Jersey 82/07/27 Region 1. Defice of Director Ip 15698 327 24% Fiche 50-272,82/09/27,8210150127
- 8210150148 Forwards LER 82-051/03X-1 Detailed event analysis enci MIDURA: H J Public Service Electric & Oas 10 of New Jersey 82/09/29 HAYNEB: R C Region 1: Office of Director Jpp 15497 288 24X Fiche 50-272:82/09/29:8210150148
- --B210190155 LER 82-051/03X-1 on 820728, following reactor trip, level in auxiliary feed storage tank dropped below Tech Spec min Caused by binding of valve 1DR6 Valve manually cycled & tank level restored to normal Valve returned to remote mode HELLER, R Public Service Electric & Oas Co of New Jersey 82/07/27 Region 1. Office of Director ip 15697 291 24X Fiche 50-272,82/09/27,8210150148
- B210210134 Forwards LER B2-070/03L-0 Detailed event analysis encl MIDURA:H J Public Bervice Electric & Gas Co of New Jersey B2/10/04 HAYNEB:R C Region i. Office of Director 3pp 15764 120 24% Fiche 50-272,82/10/04:8210210134
- --8210210144 LER 82-070/03L-0 on 820912 & 14, pressursizer pressurs controller shifted to manual mode w/decreasing pressure Caused by intermittent problem in pressure controller or manual-auto station Manual-auto station replaced FRAHM.R. Public Service Electric & Gas Co of New Jersey 82/10/06 Region 1, Office of Director ip. 15746 123 24X Fiche. 50-272, 82/10/06, 8210210134
- 8210270216 Forwards corrected LER 82-016/04L-0 Detailed event analysis encl
 MIDURA, H J Public Service Electric & Cas Co of New Jersey
 82/16/06 HAYNES, R C Region 1, Office of Director. Spp
 15853-250 24X Fiche 50-272,82/10/06,8210270216
- --B210290218 Corrected LER B2-014/04L-0 on B20326, during gaseous release from waste gas sus, containment/plant vent monitors iRila. iRI2A & iRI28 incorrectly aligned Caused by operator failure to properly perform operating instruction. FRAHMIR Public Service Electric & Gas Co of New Jersey B2/04/13 Region 1 Office of Director ip. 15853 253 2AX Fiche 50-272,82/10/06.8210270216
- 8210290310 Forwards corrected LER 82-050/04L-0 Detailed event analysis encl
 MIDURA, H J Public Service Electric & Oas Co of New Jersey
 82/10/06 HAYNES, R C Region 1, Office of Director 3pp,
 13853-090 24X Fiche 50-272,82/10/06,8210290310.
- --8210290314 Corrected LER 82-050/04L-0 on 820710. Atlantic loggerhead tuntle found impinged on circulating water sys intake trash bars Caused by inability of turtle to actively avoid approach velocities to intake due to weakened state FRAHM.R Public Bervice Electric & Gas Co. of New Jersey. 82/08/06 Region 1. Office of Director 1p. 15853.093. 24X Fiche 50-272.82/10/06.8210270310
- 8210290353 Forwards corrected LER 82-045/04L-0 Detailed event analysis encl MIDURA, H J Public Service Electric & Cas Co of New Jersey. 82/10/06. MAYNES, R C Region 1, Office of Director Spp 15853 014 24X Fiche 50-272,82/10/06,8210290353
- --B210290361 LER B2-045/04L-0 on S20710; waste monitor tank contents sample discarded before composite samples assembled Caused by technician inadvertently pouring out sample. Personnel counseled te procedures Simulated sample made, FRAHM.R. Public Sarvice Electric & Oas Co. of New Jersey B2/07/28 Region 1 Office of Director, ip. 15853 017, 24X Fiche 50-272,82/10/06.8210290353

- DOCKET 50-275 DIABLO CANYON NUCLEAR POHER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 821001000B Responds to FOIA request for 19 cetagories of documents renuclear reactor avents & safety problems. Forwards documents listed in App A FELTON, J H Division of Rules and Records 82/06/28 UDELL, R A Critical Mass Emergy Project 15pp 15727 005. 24X Fichs 50-000. 82/06/28. 921001000B
- --BOOBO90265 Discusses addl required info to better define potential for cracking in reactor vessel nottles NOONAN, V B Assistant Director for Materials & Qualifications Engineering B0/05/05 TEDEBCO.R L Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000, 82/06/28, 8210010008
- F Security, medical, emergency & fire protection plans
- 9210010406 Forwards application for amend to License DPR-76, revising security plan (CRARE, P. A. Pacific Gas & Electric Go. 82/09/17 DENTON, H. R. Diffice of Nuclear Reactor Regulation, Director ip. 15572.207, 24X Fichs. 50-275, 82/09/17, 8210010406.
- --B210010413 Application to amend License DPR-76, revising security plan Bafeguards into deleted. MAKKATIB.O A. CRANE, P. A. Pacific Oas & Electric Co. B2/09/17 3pp 15578: 208. 24X Fichs 50-275, 82/09/17,8210010406.
- BRIO210033 Releases public version of revised emergency plan implementing procedures.
 FELTON J.H. Division of Rules and Records 82/10/01 Document Management Branch Ip. 15782:091 24X Fiche: 50-275, 82/10/01, 8210210033.
- --BR10210044 Forwards public version of ravised emergency plan implementing procedures; including Procedure EP M-3 rechioring release; EP M-5 re Taunani warning & EP M-8 recombainment amergency personnel habeh.

 CRANG.P.A. Pacific Oas & Electric Co. B2/09/23, ENORLKEN,R H Region b, Office of Director. 30, 18782:092, 24X Fiche. 50-R75,82/10/01,9210210033
- --B210210048 Public version of revised emergency plan implementing procedures, including Procedure EP H-3 re chlorine release, EP H-5 re Tsunami warning & EP H-8 re containment emergency personnel hatch.

 Pecific Gas & Blactric Co. 82/09/13, 84pp. 15782:095, 24X Fiche: 50-275, 82/10/01, 8210210033,
- 8210150389 Suppl to 820719 application for emend to License DPR-76 re security plan Engl withheld (ref 10CFR73,21), CRANE.P.A. Pacific Cas & Electric Co. 92/10/12. DENTON, H.R., MIRAGIA Offices of Nuclear Reactor Regulation, Director, 2pp, 18703:279. 24x Fiche:80-276.82/10/12.8210150389.

Q. Adjudicatory correspondence

- 9210270449 Responds to 820512 petition requesting action under IOCFRE.206. For reasons stated in enclosed Director's Desision; petition denied. DKNTON-H.R. Office of Nuclear Reactor Regulation, Director. 82/09/22, REYNOLDS.J. Center for Law in the Fublic Interest. Spp. 188631164, 828 Fichs: 80-870,82/09/22:8810290449.
- --BRIGHTOATS Director's Decision DD-82-10 denying Ctr for Law in Public Interest 880518 petition requesting NRC lasve order to util to suemit again to DL to cover OA & QC issues, DENTON. H.R. Office of Nuclear Rescor Regulation, Director, 82/09/28, 7pp, 158431171. 24X Fichel 50-275, 82/09/28, 8210890449.
- ### BRIGHTOA54 Notice of issuance of Director's Decision DD-BR-10 under 100FRH. HOS denying patition by Ctr for Law in Public Interest request to require will to submit amend to CL to sover GA & do issues. DENTIN, H.R. Office of Nuclear Asactor Regulation, Director, BR/09/HR, dpp. 15863:178. 24X Fiche: 80-278, 88/09/HR, 8810890449.
- BRIGO40102 Order extending time until BRIGO5 for Commission to act to review ALAB-681, OHILM-81, Office of the Secretary of the Commission. 82/09/00. Commissioners. Ip, 19581:025. 84X Fishe: 50-975, 82/09/30, 8810040108.

- 8210050218 Reply to applicant & NRC 820924 briefs re status of prappeals from authorization of low power operation No adequate factual basis exists to support ASLD dismissal of Joint Intervenor OA contention as moot W/Certificate of Bvc REYNOLOS, J R Joint Intervenors-Diablo Canyon REYNOLOS, J R Center for Law in the Public Interest 82/09/30 Atomic Safand Licensing Appeal Panel 8pp 15611 237 24% Fiche 50-275, 82/09/30, 8210050218
- 8210060220 Reply brief to other party briefs re mootness of low s contentions Emergency planning issues & certain other issues moot Certificate of Svc encl LOCKE, R F Pacific Oas & Electric Co 82/09/30 Atomic Saf and Licensing Appeal Penel App 15620 190 24x Fishe 30-275, 82/09/30, 8210060220
- 8210040097 Reply to Governor Brown & Joint Intervenors 820924 fill in response to ASLB 820902 ander on moothess of low power issues Emergency planning issues & some low power contentions mooted Certificate of Syc encl JONES, B W. Hearing Branch | 82/10/01 Atomic Safety and Licensing Appeal Penel 9pp | 15981 026 24% Fiche 50-275.82, 8210040097
- 8210050180 Reply brief to util & NRC 820724 briefs re moothess si power issues, per AGLB 820702 order Issues not moot Controversy still exists & issue is of practical significance Certificate of Svc encl BROWN, H H California, State of BROWN, H H Kirkpatrick, Los Hill, Christopher & Phillips 82/10/01 Atomic Gafety and Licensing Appeal Panel Spp 15603 245 24% Fiche 50-275, 82,8210050180
- 8210060186 Request for leave to withdraw certain exceptions to AS B20831 initial decision ASLB 820927 clarification of & local jurisdiction acquiescence to preconditions re SUPs render acceptions unnecessary Certificate of Byc encl HAGELL, D F Hearing Branch 1 82/10/04 Atomic Safety and Licensing Appeal Panel 5pp 15613 193 24X Fiche 50-275, 82, 8210060186
- 8210070145 Order extending time until 821008 for Commission to at review ALAR-681 CHILK, B. J. Office of the Secretary of the Commission 82/10/6 Commissioners. Ip 15627 076 24X Fiche 50-279,82/10/05,821070448
- 8210130272 Forwards Ban Luis Obispo County Board of Supervisors faction approving Ban Luis Obispo County nuclear power plant emergency response plan & State of CA Benate Bill 1473 amending govt code. Certificate of Svc encl CRANE.P.A Pacific Oas & Electric Co. B2/10/06 BUCK.Jii. JOHNBON.W.R. MOORE! B Atomic Befety and Licensing Appal Pidpp. 15678.284, 24X Fiche 50-275.82/10/06.8210130272
- 8210120332 Order CLI-82-30 directing all natl security classifies be expunged from ALAD-653 & underlying record info not essential to ABLAB opinion & expunction would not prejudice any party or public CHICK-B. J. Office of the Secretary of the Commission B2/10/22p. 18452:108. 24X Fiche 50-275,82/10/08,8210120332
- 8210130327 Order extending time until 821026 for Commission to at review ALAD-681. CHIEK, 8.J. Office of the Secretary of the Commission. 82/10/10 Commissioners. 1p. 15678:282. 24X Fiche: 50-275.82/10/08.8210130327.
- 8210210422 Order extending time until 821105 for Commission to at review NRR Director 820922 denial of Joint Intervenors 10CFR2. 206 request. CHILK, B. J. Office of the Secretary of the Commission 82/10/: Commissioners. 1p. 18769:083 24X Fiche: 50-275.82/10/18.
- 8210280245 Memorandum in response to util 820924 motion for clarification of ABLB 820831 initial decision. Decision supports conclusion of law on adequacy of offsite emerging planning. WDLF, J.F. Atomic Bafety and Licensing Board Panel 82/10/2& 18837:005, 24X Fichs. 50-275, 82/10/2& 8210280245.

H. General correspondence

9210220363 Advises that 921010 ltr requesting util recalculate at safety syst at plants will be sent to all parties of LINSKY, V. Commissioners. 92/10/20. BOHULKE, B. Affiliation Unknown. 1p. 18779; 201, 24X Fiche: 80-275,82/10/20.921022031:

- --8210220369 Urgss util be forced to recalculate entire seismic safety sys at plant SCHULHE.S Affiliation Unknown 82/10/10 OILINGKY,V Commissioners 1p 15779 202 24X Fiche 50-275,82/10/20,8210220363
- P Operating lizense stage documents & correspondence
- 6210080350 Informs that procedure including proposed "Statement re Potential of Apparent Conflicts of Interest," meets requirements for independence Requests procedure be included in program mgt plans for Phase I & Phase II
 DENITOR, HR Office of Nuclear Reactor Regulation, Director 82/09/08 COOPER, HE Teledyne Engineering Services Ip 13663 316 24X Fiche 50-275,82/09/08,8210080330
- 6210010406 Forwards application for amend to License DPR-76.revising security plan
 CRANE, P A Pacific Gas & Electric Co 82/09/17 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ip 15572 207 24%
 Fiche 50-275, 82/09/17.8210010406
- --B210010413 Application to amend License DPR-76, revising security plan Safeguards info deleted MARKEATIS. Q A. CRANE.P A. Pacific Gas & Electric Co. 82/09/17 Jpp. 15572 208 24X Fiche 50-275, 82/09/17, 8210010406
- 8210040429 Informs of decision to partially refund fees remitted w/ 800821 application to extend latest CP completion dates MILLER.W O License Fee Management Dranch 82/09/21 FURDUSH, M H Pacific Oas & Electric Co 1p 15997 262 24X Fiche 50-275, 82/09/21, 8210040429
- \$210130056 Responds to \$20727 request for status rept on design verification program & briefing on proposed Phase II of program Info discussing background & current status enci DIRCKS,W J Office of the Executive Director for Operations 82/09/24 PALLADIND.W J, GILINSKY,V, AHEARNE, JF Commissioners 28pp 15692 284 24X Fiche 50-275,82/09/24,8210130056
- 8210010149 Provides guidance to assure independence of Teledyne Engineering Svcs while recognizing need for communication between Teledyne & util DENION.H R Office of Nuclear Reactor Regulation, Director 82/09/29 COOPER.H E Teledyne Engineering Services Spp 15567 244 24X Fichs 50-275.82/09/29.8210010149
- 6210080191 Forwards Revision 2 to Procedure DCNPP-IDVP-PP-005,
 "Potential or Apparent Conflicts of Interest of
 Individuals " Words "engineering mgt" inadvertently omitted
 in Section 2 0 during retuping of Revision 1
 COOPER.W E Teledyne Engineering Services 62/09/29 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
 Region 5, Office of Director MANEATIS, Q A Pacific Qas & Electric
 Co 1p 15640 182 24X Fiche 50-275, 82/09/29, 8210080191
- --82:0080193 Revision 2 to DCNPP-IDVP-PP-005, "Potential or Apparent Conflicts of Interest of Individuals"

 COOPER.W E Teledyne Engineering Services 82/07/29 Spp
 15640 183 24x Fiche 50-275,82/07/27,8210080191
- 8210050122 Forwards info addressing Sections 2 1.2 2.2 3 & 2 4 of Generic Ltr 81-07 re NUREO-0612. "Control of Heavy Loads"
 Section 2 (updates B10924 submittal Submittal addressing remaining required analyses expected by end of Feb 1783
 CRANE.P A Pacific Oas & Electric Co 82/09/30 MIRAQLIA.F J
 Licensing Branch 3 176pp 15605 212 24X Fiche 50-275,82/09/30,8210050122
- 82:0050144 Responds to Generic Ltr 82-12 re plant staff working hours
 Util administrative procedures address revised working
 hours
 CRANE,P A Pacific Gas & Electric Co 82/10/01 MIRAQLIA,F J
 Licensing Branch 3 lp 15605 161 24% Fichs 50-275,82/10/01,
 02:0050144
- B210120278 Forwards "Design Verification-Phase I," final rept & "Blume Internal Reviews (BIR) Independent Internal Reviews of Work Done by LRS/Plume Enganeers on Diablo Canyon Nuclear Power Plant "
 CRANE.P A Pacific Oas & Electric Co 82/10/01 EISENHUT, D, O Division of Licensing 2pp 15653 243 24X Fiche 50-275, 82/10/01, 8210120278
- --9210120283 "Design Verification Phase 1.Final Rept "
 4 Pacific Gas & Electric Co T1002745 R03 82/10/01 233pp
 15553 245 24X Fiche 50-275, 82/10/01.8210120278

- --8210120285 "Blume Internal Review Independent Internal Review of Work Done by URS/Blume Engineers on Diablo Canyon Nuclear Power Plant: "final rept + URB Carp URB/JAB 8216 82/09/30 80pp 15654 117 24X Fiche 50-275,82/10/01.8210120278
- B210080272 Notifies that program procedure for communication from & to independent design verification program will be revised to conform w/guidelines provided in 820929 ftr CGOPER.W E Teledyne Energy Systems 82/10/02 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15638 124 24X Fiche 50-275,82/10/02,8210080272
- 8210080078 Forwards interim technical rept "Independent Design Verification Program Verification Program for PG&E Carrective Action," Revision O DENISON.E Robert L Cloud Associates, inc 82/10/05 DENITON,H R Office of Nuclear Reactor Regulation, Director ENGELKEN.R H Region 5, Office of Director MNRATIS,0 E Pacific Gas & Electric Co 1p 15440 277 24% Fiche 50-275,82/10/05,8210080078
- --B2100B00B0 "Independent Design Verification Program Verification Program for POKE Corrective Action," Revision O DENISON.E Robert L Cloud Associetes, Inc. P 105-4-839-00B ROD B2/10/05 6ipp 15640 278 24% Fiche 50-275,82/10/05.82100B007B
- 8210250167 Forwards "Diablo Canyon Nuclear Power Flant Independent Design Verification Program Program Plan Revieton 1, Adjunct Program for Evaluation of Const QA"

 COUPER, W E Teledyne Engineering Services 82/10/05 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS, OA Pacific Ges & Electric Co 2pp 15787 120 24% Fiche 50-275,82/10/05,8210290167
- --8210250171 "Diabio Canyon Nuclear Power Plant independent Design Verification Program Program Plan. Revision 1. Adjunct Program for Evaluation of Const GA " * Teledyne Engineering Services 82/10/01 12pp 15787 122 24X Fiche 50-279.82/10/05.8210250167
- 8210250168 Forwards RH Engalken 820915 memo re RF Reedy, Inc exit meeting concerning GA audits for consideration in evaluation of GA program EISENHUT. D 0 Division of Licensing 62/10/06 COOPER, W E Teledyne Engineering Services. 2pp 15808 009 24X Fiche 50-275,82/10/06,8210250168
- ---B210250372 Summary of 820910 meeting w/util & RF Reedy, Inc re GA audit of in-house design ENGELKEN,R H Region 5, Office of Director 82/09/18 DENTON.H R Office of Nuclear Reactor Regulation, Director 5pp 15808-011 24X Fiche 50-275,82/10/06,8210250168
- B210250240 Forwards independent design verification program comments on Phase I final rept Rept should contain detailed descriptions of scope; criteria; methodology & models for ell structures; sys & components CODPER, HE Teledyna Engineering Services 82/10/07 DENTON, HR Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIB, O A. Pacific Oas & Electric Co 16pp is789 150 24X Fiche 50-279, B2/10/07, B210250240
- 821080123 Notifies of 821007 meeting w/util in Ban Francisco.CA to discuss status of Pheess I & II.instrument test rig for verification of corrective action & NRC 820819 itr re fuel load.

 * Teledyne Energy Systems 82/10/08 Teledyne Energy Systems ip 15440 129 24X Fiche 50-275,82/10/08,8210080123
- 8210270446 Steff requirements mamo re 821007 effirmation/discussion & vote on extension of const completion dates for WPRES, purging of classified met in ALAB-553 & emergency preparedness & risks associated w/fuel loading, CHILK.B J Office of the Secretary of the Commission. 82/10/08 Office of the Secretary of the Commission. 82/10/08 Fiche: 50-000, 82/10/08,8210270446
- 8210190470 Fravides info re ownership of Bechtel Power Corp FRIEND, H B Bechtel Corp 82/10/11 MIRAGLIA, F J Licensing Brench 3 1p 15740 181 24X Fiche 50-275,82/10/11.8210190470.
- 8210270351 Advises that Bechtel Power Corp is entity responsible for work on project Ownership held by officers of Dechtel Oroup, Inc FRIEND, H B Pacific Gas & Electric Co FRIEND, H, B, Bechtel Corp 82/10/11 HIRAOLIAF, J, Licensing Brench 3 ip 15834-338, 24X Fiche 50-275, 82/10/11, 8210270351
- 8210150389 Supp) to 820719 application for amend to License DPR-76 re security plan Encl withheid (ref 10CFR73 21) CRANE.P.A Pacific Oss & Electric Co 82/10/12 DENTON.H R , MIRAOLIA Office of Nuclear Reactor Regulation, Director, 2pp. 15703 279 24% Fiche 50-275,82/10/12,8210150389

- 8210230291 Clarifies 821007 statement of required systatuctures & components for plant operating modes for independent design verification program CHOPER.W E Teledyne Engineering Services 82/10/12 EISENHUT.D O Division of Licensing 4pp 15790 191 24X Fiche 50-275.82/10/12.82(0250291
- 8210290097 Requests explanation of process & chronology of events in which Teledyne discussed count QA review of plant w/util. Bechtel & SkM info required to determine presence of conflict of interest Heating requested BROWN. H H Kirkpatrack, Lockhart, Mill, Christopher & Phillips BROWN. H H California, State of 82/10/12 COOPER. W E Teledyne Engineering Services 2pp 15853 361 24% Fiche 50-275.82/10/12. \$210270097
- 8210270214 Provides NRC recommendation re Phase II of independent design verfication program Phase II program plan & requirement that Phase II review/evaluations be completed prior to fuel load/low power decision approved DIRCKS.W J. Office of the Executive Director for Operations SECV-82-414 82/10/13 61pp 15976 261 24X Fiche 50-275, 82/10/13,8210290214
- 8210190583 Advises that two former Eachtel employees will be retained on independent design verification program Individuals do not violate procedure on conflict of interest & will not verify work participated in as Beachtel employee COOPER, H E. Teledyne Engineering Services 82/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 3, Office of Director MANEATIE, OA Pacific Oas & Electric Co. 3pp 15791 184 24X Fiche 30-275,62/10/14,8210190583
- 8210190584 Provides preliminary response to 820701 request for review of seven points re validity of ENL results & generic implications in final rept concerning analysis of facility COOPER.W E Teledyne Engineering Services 82/10/15 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 15791 187 24X Fichs 50-275.82/10/15.6210190584
- 8210220371 Forwards add1 sections for Phase I final rept re design verification program per commitment made in 820820 ltr. Ravision 4 to outline Phase I final rept & revision to sections previously submitted CRANE.P A Pacific Oas & Electric Co 82/10/15 £18EN;UT.D Q Division of Licensing 10ipp 19779 238 24% Fiche, 50-275, 82/10/15, 82/10-20371
- 8210250210 Identifies concerns resulting from review of URB/Blumb containment annulus structure model evaluation Concerns resulted in issuance of EOI Files 2006 & 5007 HRAY.R Teledune Engineering Services 82/10/19 MANEATIS, Q A Pacific Qas & Electric Q 4pp 15789 292, 24X Ficher 50-275, 82/10/15, 8210250210
- 8210250318 Comments on Region 5 820915 memo re Phase II of Independent design verification program.psr 821006 request Change in Phase II not indicated COPPER. II not indicated COPPER. II E Teledyne Engineering Services 62/10/15 EISCNHUT. D O Division of Licensing 5p2 15790 048 24X Fiche 50-275, 82/10/15, 8210250318.
- 8210280272 Notifies of planned B21101 meeting w/plant personnel to discuss audit logistic planning for activities performed tince 820820 REGDV.R F. R F Reedy, Inc 82/10/15 COOPER, W E Teledyne Engineering Services 3pp 15837 292 24X Fiche 50-275, 82/10/15, 8210280272

- G Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of receffin steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Ruies and Records 82/00/10 (RM D J Hinthrop, Stimson, Putnam & Roberts 9pp 15645 063 24% Fichs 50-000, 82/08/10, 8210070007
- --8210070139 Forwards tabulated data on steam generator lines & raill; facilities Data should be provided to licensees. IPPOLITO.T Operating Reactors Assessment Branch 82/05/01 VAROA.S Operating Reactors Branch 1 5pp 19645 131 246 Fiche 50-000,82/08/10.8210070007
- 82100&0133 Forwards IE Insp Repts 50-275/82-26 & 50-323/82-13 an 820726-30.0816-20 & 0830-0901 No noncompliance nated 815MOP. T W Division of Resident, Reactor Project & Engineering Programs 82/09/17 CRAME.P A Pacific Cas & Electric Co 518 15614 307. 24X Fichs 50-275.82/09/17.8210060133
- --8210060141 IE Insp Repts 50-275/82-26 & 50-323/82-13 on BWJ28-2 OB16-20 & OB30-0701 No noncompliance noted Major areas inspected site tour & mod to piping & sistrical rateway supports resulting from revised annulus seismic spectra EURDDIN JF , ZMETZIO. 9 B Division of Resident, Beactor Progris Engineering Programs BZ/09/17 9pp 15614 311 24% Fichs 50-275,82/09/17,8210060133
- 8208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-13)
 Implant Seeds " Svc list end
 CUBB.L I Division of Fuel Facilities, Materials & Gafequarde
 62/10/06 Consolidated Edison Co of New York 66pp 13161 2V
 24X Fache 50-000,82/10/04,8208190233
- 8208190238 IE Dulietin 82-03, "Stress Corrosion Cracking in Inter-Hall-Large-Diameter. Stainless Steel. Recirculation flys Piping at BUR Plants "Sve list encl BEYOUNO.R C Director's Diffice. Diffice of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 30-000.82/10/14.82081902.80
- 8210280287 Forwards IE Insp Rept 50-275/82-29 on 820827-1003 has noncompliance noted BISHOP.T W Division of Resident, Reactor Project & Ingineeri-2 Programs 82/10/14 GRANE.P A Pacific Oas & Electric Co 6/15839 010 24X Fiche 50-275/82/10/14/8210280287
- --8210280303 IE Insp Rept 50-275/82-29 on 820829-1002 No northeplia moted Major areas inspected plant operations, surveillance testing, physical security, maint & TMI task action plan items
 CARLEON, J D , MENDONCA, M M , KIRBCH, D F Division of Resident Reactor Project & Engineering Programs 82/10/13 5pp 15939 014 24% Fichs 50-275, 82/10/14,8210280287
- 8210280324 Forwards IE Insp Repts 50-275/82-30 & 50 (121/112-11 ex 820914-16 No moncompliance noted BIGNOP.T W Division of Resident, Reactor Project & Ingineerery Programs 82/10/14 GRANELP A Pacific Oas & Electric Ca 731
- --BR10280330 IE Insp Repts 50-275/82-30 & 50-323/82-14 on fighth the concompliance noted Major areas inspected implementation of independent verification program; including independent entitle concompliance qualifications of personnel & implementation of GA grogres MORRILL.P.J., ECKMARDT.J.H., BICHOP.T.H. Division of Resident Reactor Project & Engineering Programs 82/10/01 App 15839.021. 24% Fiche 50-273, 82/10/14.8210280324
- ? Periodic operating reports & related correspondence
- --8210270322 "Diable Canyon Nuclear Power Plant Independent Diriga 1 Verification Program," semimonthly rept for Sept 1902

 Teledyne Engineering Services. 82/09/24 49p 15634 121 , 24% Fiche: 50-276.82/09/24.8210270319.
- 9210150151 Forwards "Semimonthly Rept 23, Diablo Canyon Virification Program." 820921-1004 CRANE,P A Pacific Oss & Electric Co 82/10/08 DENTON, M & Office of Nuclear Reactor Regulation, Director ENGELKEN, N + Region 5, Office of Director 1p. 15697 294, 24% Fiche: 50-275, 82/10/08, 8210150151

- --8210150159 "Semimonthly Rept 23. Diable Canyon Verlfication Program," 820921-1004 HIGH.J 8 Pacific Gas & Electric Co 82/10/08 51pp 15497 295 20% Fiche 50-275.82/10/08.82/0150151
- 8210230197 Forwards "Independent Design Verification Program." semimonthly rept for Oct 1982 COMPER. B Teledyne Engineering Services 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS. O A Pacific Oas & Electric Co 3pp 15789 264 24X Fiche 50-275.82/10/08,8210250197
- --8210250201 "Independent Design Verification Program," semimonthly rept for Oct 1982 • Teledyne Engineering Services 8 24x Fiche 50-275,82/10/08,8210250197 82/10/08 29pp 15789 267
- 8210250221 Advises that RL Cloud Associates, Inc has not issued open ten repts during prior reporting period

 DENISON.E Robert L Cloud Associates, Inc. 82/10/08 DENTON.H R

 Office of Nuclear Reactor Regulation, Director ENGELKEN.R H

 Region D. Office of Director HANEATIS,G A Pacific Gas & Electric

 Co. lp. 15788 348 24X Fiche 50-275,82/10/08,8210250221
- 8210250247 Submits Semimonthly Progress Rept 20 for 820902-1008 No open item repts issued, but two open item repts identified individuals completed acceptable statements re potential or apparent conflicts of interest REEDY, R.F. R.F. Reedy, Inc. 82/10/08 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN, R.H. Region 5. Office of Director MANEATIS, O.A. Pacific Gas & Electric Co. 15788
- 8210250308 Forwards Oct 1982 semimonthly rept.consisting of Open Item
- 8210280157 Forwards program managers 3rd Friday Oct 1982 rept re independent design verification program REEDY.R F R F Reedy Inc 82/10/15 COOPER.W E Teledyne Engineering Services App 15807 215 24% Fiche 50-275.82/10/15, B210280157
- 0210270236 Forwards "Diablo Canyon Verlfication Program," Semimonthly Rept 24 for 821005-18 per Commission Order CLI-81-30 CRANE.P A Pacific Gas & Electric Co 82/10/22 DENTON.H.R Office of Nuclear Reactor Regulation, Director ENGELKEN,R H Region 5, Office of Director ip 15828 222 24X Fiche 50-275.82/10/22.8210270236
- --8210270240 "Diable Canyon Verification Program," Semimonthly Rept 24 for 821005~18 * Pacific Cas & Electric Co 82/10/22 52pp 15828 223 24X Fiche 50-275,82/10/22,8210270236
- 8210280211 Forwards "Diablo Canyon Nuclear Power Plant Independent Design Verification Program," semimonthly status rept for Oct 1982 Oct 1982 CODPER: G E Teledyne Engineering Services 82/10/22 DENTON, H.R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5. Office of Director MANEATIS, O A Pacific Oas & Electric Co 2pp 15833 001 24X Fiche 50-275,82/10/22,8210280211
- ---8210280212 "Diablo Canyon Nuclear Power Plant Independent Design Varification Program" semimonthly status rept for Oct 1982 1702 * Teledyne Englneering Services \$2/10/22 76ep 15838.003 24% Fiche 50-275.82/10/22.8210280211
- S Reportable occurrences, LERs & related correspondence
- 8210250055 PND-V-82-043 on 821016 unusual event declared when grass fire started in 500 kV switchyard On 821017, three 500 kV circuits tripped resulting in loss of all offsite power Second unusual event declared STERNDERO
- 8210290219 Forwards LER 82-009/01T-0 Region 5. 9fflee of Director 10 15853 226. 24X Fiche 50-275, 82/10/18, 8210270219

- --8210290222 LER 82-009/01T-0 on 821007, testing on auxiliary saltwater sys revealed sys susceptible to water hammer effects during anticipated operational transients Caused by water column separation be recombination at piping slope change KAEFER: W B Pacific Oas & Electric Co 82/10/19 Region 5, Office of Director 2pp 15853 227 24X Fiche 50-275,82/10/16, 223-22302018 Office of Director 8210290219
- T Hearing transcripts on non-antitrust matters
- 8210290370 Unofficial transcript of 821020 public discussion of Phase II reverlfication program in Washington.DC Pp 1-113 Supporting documentation enci.

 Commissioners 82/10/20 144pp 15865-095 24X Fiche 50-275, 82/10/20, 8210270370
- 8210220416 Forwards transcript of Commission 821020 meeting to eluggodle Forwards transcript of Commission URIDED meeting to receive NRC briefing on proposed scope of Phase II of independent design verification program & 821019 meeting w/ util & participants re program & SECY-BE-414 W/d encl
 CHILK.8 J Office of the Secretary of the Commission 82/10/21
 Office of the Executive Legal Director 1p 15779 211 24X
 Fichs 30-275.82/10/21.8210220416
- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2 J Insurance & indamnity information
- 8210060276 Forwards Endorsement 99 to NELIA Policy NF-140 & Endorsement BRADLEY.E J Philadelphia Electric Co 82/09/30. SALTZMAN, J Assistant Director for State & Licensee Relations 3pp. 15619 206 24/ Fiche 50-277,82/07/30,8210060296
- P Operating license stage documents & correspondence
- 9210280013 Responds to FOIA request for all internal, non-public documents memos, evaluation repts & other matl dealing w/
 nuclear plant aperations Forwards documents listed in App A
 FELTON, J M Division of Rules and Records 82/09/17 MCINNI.
 News & Observer 5pp 15860 065 24X Fiche 30-000,82/09/17. MCINNIS. D B210280013
- -- 8208310034 Forwards draft info motice re deficiencies in air filtration 208310034 Forwards draft info notice redeficiencies in air filtrati
 & ventization sys. Notice based on radioactive resin release
 at Pilgrim 1 & on four related events at other plants
 involving deficiencies in maint & testing of filter sys.
 MATTSON.R J Division of Systems Integration (post 811005).
 82/09/05 UDRDAN.E. L Division of Engineering & Quelity
 Assurance 5pp 15861-024 24X Fiche. 30-000, 82/09/17,8210280013
- 8210050320 Forwards "Thermal Happing Rept 82-3 for 820818 for Thermal Monitoring Requirements." per App 8 to ET8
 MILLERY:N B Philadelphia Electric Co 82/09/28 IPPOLITG, T. A Operating Reactors Branch 3 ip 15601:358 24X
 Fiche 50-277, 82/09/28, 8210050320
- --8210050321 "Thermal Mapping Rept 82-3 for 820818 for Thermal Monitoring Requirements ** Philadelphia Electric Co 82/09/28 4pp 15401 359 24X Fichs 50-277,82/09/28,8210050320
- 82:0150282 Forwards "Rept of Plant Startup Following Fifth Refueling Outage," Feb 1982 ALDEN.H M. Philadelphia Electric Co 82/10/06. HAYNES,R C Regi 1. Office of Director lp. 15705:266 24X Fiche 50-277.82/10/06.
- --8210150272 "Rept of Plant Startup Following Fifth Refueling Outage," 820219 02V417 ULRICH, H T Philadelphia Electric Co. 82/02/28 7pp. 15705 267. 24X Fiche; 50-277, 82/10/04, 8210150282.
- 8210260329 Submits info re potential problem w/ventilation systassociated w/battery & emergency switchgear rooms, solution to problem & schedule for completion of necessary mods Modswill be completed by 821231 COONEY, M J. Philadelphia Electric Co 82/10/14 HAYNES, R (Region I, Office of Director 3pp. 13803, 205 24X Fiche: 50-277, 82/10/14, 8210260329 HAYNES, R C.
- 8210200046 Forwards application to amend Licenses DPR-44 & DPR-56 to reflect mods required to meet criteria of NUREC-0&61,App A;
 "Mark I Containment Long-Term Program."
 BRADLEY,E J Philadelphia Electric Co. 82/10/13 DENTON,H. R.
 Office of Nuclear Reactor Regulation, Director. 1p. 15756:135. 24X
 Fiche: 50-277, 82/10/15, 8210200046

ءِ ا ه

1 1

ļ,

1

ų.

- --8210200063 Application to amand Licenses DPR-44 & DPR-36 to reflect mode required to meet criteria of NURCO-0661. App A. "Mark I Containment Lang-Term Program" Afficavit & Certificate of Sve encl BAUER. E G . DRADLEY, E J Philadelphia Electric Co 82/10/15 70s 15756 136 24X Fishe 50-277. 82/10/15.8210200046
- --8210200068 Proposed Tech Spec pages, reflecting mods required to mest criteria of NUREO-0561. App A. "Hark I Containment Long-Term Program"

 4 Philadelphia Electric Co 82/10/15 App 15756 143 24X Fiche 50-277. 82/10/15.
- 8210210297 Submits additinfo re util 811229 response to NUREG-0803. "Safety Concerns Associated W/Pips Breaks in BWR Scram Sys." in response to NRC 820824 request DALTROFF. S L. Philadelphia Electric Co. 82/10/15 STOLZ. J F Operating Reactors Branch 4 10pp 15764 267 24X Fiche 50-277.82/10/15.8210210257
- 8210210330 Proposes 830131 as date for responding to NUREQ-0737, Etem 11 B 3, "Post-Accident Sampling Sys " DALTROFF, S L Philadelphia Electric Co 82/10/15 STOLZ, J F Operating Reactors Granch 4 2pp 15765 063 24X Fiche 50-277, 82/10/15, 8210210330
- 8210280196 Forwards response to draft technical evaluation rept recontrol of heavy loads Addi info requested in 820405 telcon onci

 DALTROFF.8 L Philadelphia Electric Co 82/10/25 STOLZ.J F Operating Reactors Branch 4 45pp 15839. 136 24X Fiche 30-277.82/10/25.8210280196
- --B210280193 "Structural Analysis of Peach Bottom Units 2 & 3 Reactor Pressure Vessel Head Brog. Shroud Head Assembly Brog & Stram Bryer Assembly Brog Conditions "HERRERA,M L. MOK.9 General Electric Co 82-32 82/08/31 39p
- --B210280201 "Lifting Devices & Lifting Points Stress Analysis for Reactor Pressure Vessel Head Strongback Stoom Dryer/
 Separator Sling & Syc Platform to Comply W/NUREG-0612 for Peach Bottom Units 2 & 3 "
 KONG.Y H General Electric Co NSE-50-0582 82/05/31 3ipp 15839 219 24X Fiche 50-277, B2/10/25,8210280196
- --B210280204 "Lifting Devices & Lifting Points Stress Analysis for Fuel Paol Oate Lifting Points. Hydraulic Tensioner Lifting Device & Lifting Points & Reactor Pressure Vessel Insulation Removal Lifting Device & Insulation Lifting Points " SZUMBKI, T J Philadelphia Electric Co NSEQ-72-0762 82/07/31 27pp 15839 250 24X Fichs 50-277.82/10/R5.8210280196
- O Inspection reports: IE Builetins & correspondence
- 8210070317 Forwards IE Insp Repts 50-277/82-20 & 50-278/82-19 on 820816-20 & notice of violation MARTIN T Division of Engineering & Technical Programs 82/09/22 DALFROFF, 8 L. Philadelphia Electric Co 2pp 15634, 135 24% Fiche 50-277, 62/09/22, 8210070317
- --8210070322 Notice of violation from insp on B20916-20.

 * Division of Engineering & Technical Programs B2/09/14 ip 15634 137 24% Fiche, 50-277, 82/09/22, 8210070317
- --8210070330 IE Insp Repts 50-277/82-20 & 50-278/82-19 on 820816-20 Nancoapliance noted no notification given for abnormal degradation in primary containment, evidenced by unacceptable local leak rate test results for nine isolation valves PULLANI.8 V , BETTENHAUSEN L Division of Engineering & Technical Programs 82/09/14 7pp 15634 138 24X Fiche.50-277,82/09/22,8210070317.
- 8210150299 Forwards IE Insp Repts 50-277/82-19 k 50-278/82-18 on 820807-0915 No noncompliance noted STAROSTECKIR Division of Project & Resident Programs, 82/09/27, DALTROFF, S L. Philadelphia Electric Co 2pp 15707 234 24X Fiche-50-277, 82/09/27, 8210150299
- --8210150302 IE Insp Repts 50-277/82-19 & 50-278/82-18 on 620807-0915. No noncompliance noted Major areas inspected operational safety-radiation protection, physical security, control room activities & IE bulletin followup.

 BLOUGH, A.R., MCCANE, E.C. Division of Project & Resident Programs, 82/09/20 19pp. 15707 236 24% Fiche 50-277, 82/09/27, 8210150299.
- 8210070177 Forwards inservice insprept completed during 820220-0702 refueling outage, Insprequirements met satisfactorily. COUNEY. If J. Philadelphia Electric Co. 82/09/29 HAYNEB, R. C. Region I. Office of Director. 1p. 15635-278. 24X Fiche. 50-277, 82/09/29, 8210070177.

- --8210070188 Inservice insp rept completed during 820220-0702 refusing subage a Philadelphia Electric Co 82/09/20 96pp 15635 299 248 Fiche 50-277, 82/09/29, 8210070177
- 6210150069 Submits final response to IE Dulistin Si-Oi. "Gurveilla-e of Mechanical Snubbers " Pacific Scientific Co manufectures 49 mechanical snubbers utilized at facility List of model numbers and DALTROFF.S L. Philadelphia Electric Co 82/10/04 HAYNES.R C Region 1. Office of Director 2pp 15701 241 24x Fishe 50-277. 82/10/04.8210150069
- 8208190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged 1-323 Implant Beeds " Svc list enci COBD.L I Division of Fuel Facilities. Materiais & Ga/equarde 82/10/06 Consuidated Edison Co of New York 66pp 13761 25. 24x Fiche 50-000.82/10/06.8208190233
- E210130291 Ack receipt of 820929 ltr informing NRC of step; talent; correct violations noted in IE Insp Repts 50-277/82-14 & 50-278/82-14 BTAROSTECKI.R Division of Project & Resident Programs 92/10/66 DALTROFF, S L. Philadelphia Electric Co. ip 15678 347 24x Fichs 50-277.82/10/06.8210130291
- --8210130276 Responds to NRC 820901 itr re violations noted in It Iru Ropts 50-277/82-14 & 50-278/82-14 Corrective actions defective inciting machanism replaced & personnel instructed to be more forceful when checking locked doors DALTROFF.S L Philadelphia Electric Co 82/09/29 BTARM316-14 Division of Project & Resident Programs 2pp (5678 348 241 Fiche 50-277,82/10/06,8210130291
- 820819023B IE Buitetin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter: Stainless Steel. Recirculation Ggi Piping at BWR Plants "Svc list encl DEYOUNO: R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 113pp 15810 123 24X Fiche 50-000.82/10/14.8200190238
- R Pariodic operating reports & related correspondence
- 8210150336 Forwards Thermal Happing Rept 82-4 for 820909 for thereal monitoring requirements, per App 8 to ETB WILLSEY, N B Philadelphia Electric Co 82/10/08 JPPC0 110, T A Operating Reactors Branch 3 ip 15704 277 24X Fiche 50-277, 82/10/08, 8210150356
- --B21015036B Thermal Mapping Rept 82-4 for 820909 + Philadelphia Electric Co 82/10/08 4pp 15704 278 241 Fiche 50-277,82/10/08,8210150356
- 8210220170 Forwards monthly operating ropts for Bopt 1982 GOONEY, H J Philadelphia Electric Co 82/10/15 Director's Office. Office of Inspection and Enforcement 1p 15777 273 24: Fiche 50-277, 82/10/15,8210220170
- ~-8210220194 Monthly operating repts for Sept 1982 ALDEN.W M Philadelphia Electric Co 82/10/15 10pp 15/97 2/4 24X Fiche 50-277/82/10/15/8210220190
- 8 Reportable occurrences, LERs & related correspondence
- E210060074 Forwards LER 82-027/017-0 Detailed event analysis and COONEV.M J Philadelphia Electric Co E2/09/24 HAYNES.R C Region i. Office of Director Opp 15615 047 24X Piche. 50-277. E2/09/24.8210060074
- ---B210060083 LER 82-027/01T-0.on 820910.svc air valve to container? found open Caused by personnel failure to make entry in locked valve log book when valves opened Valve closed & locked CQUNEY.M.J Philadelphia Electric Co. 82/09/24 Region I: Uffice of Director Ip. 15615 050 24X Fiche, 80-277, 82/09/24 8210060074
- 8210060353 LER 82-025/03L-0 on 820827, while performing surveillars test: C RHR pump room C cooling fan would not start in automatic Caused by corroded contacts on C fan switch DPS 0400-16 Switch rewired & calibr COONEY, H J Philadelphia Electric Co 82/09/24 HAYNES, R C Region 1, Office of Director in 15615 194, 24X Fiche 30-277, 82/09/24, 8210060353.

- 8210050047 LER 82-028/03L-0 on 820908.LIS-2-3-73B.reactor Lo-Lo-Lo containment spray interlock discovered out of calibr Caused by setpoint drift of Rosemont Model i151 trip unit Device recalibe GOUNEY, M J Philadelphia Electric Co 82/09/27 HAYNES, R C Region i. Office of Director 1p 15615 088 24X Fiche 30-277, 82/09/27, 82/0060047
- 8210060177 LER B2-026/03L-0 on B20B31,RMR pump 2A failed to start during test on FR-2-10-143 Caused by uncharged breaker closing spring due to faulty closing latch monitoring switch in charging motor circuitry Buitch replaced COCNEY.M J Philadelphia Electric Co 82/09/30 Region 1, Uffice of Director 1p 15615 099 24X Fiche 50-277,82/09/30,8210060177
- 8210150400 LER 82-031/03L-0 on 820831, smoke detector 814 in emergency Forther Section 103 - 10
- 6210150154 Forwards LER 82-030/01T-0 Detailed event analysis submitted COONEY.H J Philadelphia Electric Co 82/10/01 HAYNES.R C Region L Office of Director 3pp 15707 311 24X Fiche 50-277, 82/10/01.8210150154
- --9210150179 LER 82-030/01T-0 on 820517. w/both units at power, small quantity of slightly contaminated water released from recombiner bldg into stoin drain sys Caused by spurious action of Grinnell Model B fire suppression valve COONEY. H J Philadelphia Electric Co 82/10/01 Region 1, Office of Director ip 15707 314 24X Fiche 50-277,82/10/01, 0210150154
- 6210260112 LER 62-029/03L-0 on 620915.during power, supervisory alarm occurred indicating fire sys problems Investigation revealed heat detectors in startup switchgear bldg Inoperable Caused by disconnected circuit breaker due to stripped scree COUNEY.M J Philadelphia Electric Co 82/10/14 HAYNES.R (Region I. Office of Director lp 15805 247 24X Fiche 50-277.82/10/14.8210260112 HAYNES, R C
- 8210270366 PNO-I-82-06B on 821024 primary sys relief valve began cycling during startup after maint shutdown causing sys swell which resulted in feed pump trip on high reactor water level followed by low lovel scram HPGI manually initiated MCCABE.E C . KEIMIQ Region 1, Office of Director 82/10/25 ISB53 034 24X Fiche 50-277.82/10/25.8210290366
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3
- J Insurance & indemnity information
- 0210060296 Forwards Enforsement 99 to NELIA Policy NF-140 & Enforsement cloud 270 Forwards Endorsement 99 to NELIA Policy NF-53 to MAELU Policy NF-67 BRABLEY.E J Philadelphia Electric Co 82/09/30 Assistant Director for State & License Relations 24% Fiche 50-277, 82/09/30,8210060296 SALTZMAN, J 3pp 15619 204
- P Operating license stage documents & correspondence
- 8207090201 Forwards application to amend License DPR~56, changing Tech Spaces to reflect changes to ODYN computer code & including Revision 1 to "Supplemental Reload Licensing Submittal for Peach Bottom Unit 3.Reload 4 "
 BRADLEY.E J Philadelphia Electric Co 82/07/06. DENTON.H R
 DF#1Ce of Nuclear Reactor Regulation. Director ip 13788,113. 24x
 Fiche 50-278.82/07/06.8207090201
- --8207090208 Application for amend to License DPR-54, changing Tech Bpscs to reflect changes in analyses resulting from corrections to DALTROFF, 6 Philadelphia Electric Co 82/07/06 6pp 13788.115, 24X Fiche 50-278,82/07/06,8207090201
- --8207090215 Tech Spec Tables 3 5 K 2 & 3 5 K 3 & Figures 3 5 K 1 & 3 5 % 2 supporting application for amend to License DPR-56 Philadelphia Electric Co. 82/07/06 App 13788 120 Fiche 50-278, 82/07/06, 8207090201
- --8207090224 Revision 1 to "Supplemental Reload Licensing Submittal for Peach Bottom Atomic Power Station Unit 3, Reload 4 "
 LEASER, J D , ENGEL, R E Ceneral Electric Co Y1003J01A20 R01.
 82/06/30 41pp 13788-124 24X Fiche 50-278, 82/07/06, 8207090201.
- 8210050320 Forwards "Thermal Mapping Rept B2-3 for 820818 for Thermal Monitoring Requirements," per App 8 to ETB WILLSEY,W B Philadelphia Electric Co 82/09/28 IPPOLITO, T. A Operating Reactors Branch 3 ip, 15601,358 24X Ficha 50-277.82/09/28.8210050320

- --8210050321 "Thermal Mapping Rept 82-3 for 820818 for Thermal Monitoring Requirements "
 * Philadelphia Electric Co 82/09/28 4pp 15601 359 24x
 Fiche 50-277,82/09/28,8210050320
- 6210240329 Submits info re-potential problem w/ventilation sys-associated w/battery & emergency switchgear rooms, solution to problem & schedule for completion of necessary mods Mods-will be completed by 821231 COUNEY, M J Philadelphia Electric Co 92/10/14 HAYNES, R (Region 1, Office of Director 3pp 15803 205 24% Fiche 50-277, 82/10/14, 8210240329
- 8210200046 Forwards application to amend Licenses DPR-44 & DPR-56 to reflect mods required to meet criteria of NUREO-0661, App A. "Mark I Containment Long-Term Fragram" BRADLEY.E J Philadelphia Electric Co 82/10/15 DENTON, H R Office of Nuclear Reactor Regulation, Director lp 15756 135 ; Fichs 50~277, 82/10/15, 8210200046
- --8210200063 Application to amend Licenses DPR-44 & DPR-56 to reflect mods required to meet criteria of NUREQ-0661.App A. "Hark I Containment Long-Term Program " Affidavit & Certificate of Svc encl SVC enc.

 BAUER: E 0 . BRADLEY.E J Philadelphia Electric Co B:

 7pp 19756.136 24X Fiche 50-277.82/10/15.8210200046 82/10/15
- ~-B210200068 Proposed Tech Spec pages, reflecting mods required to meet criteria of NUREO-O661, App A, "Mark I Containment Long-Term Program" * Philadelphia Electric Co 82, Fich: 50-277,82/10/15,8210200046 82/10/15 6pp 15756 143 24X
- 8210210297 Submits addi info re utll 811229 response to NUREQ-0803. "Safety Concerns Associated W/Pipe Breaks in BMR Scram 8ys." in response to NRC 820824 request DALTROFF, 8 L Philadelphia Electric Co 82/10/15 8TOLZ. J. F Operating Reactors Branch 4 10pp 15764 267 24X Fiche 80-277. 82/10/15. 8210210297
- B210210330 Proposes B30131 as date for responding to NUREQ-0737. Item II B 3. "Post-Accident Sempling Bys "
 DALTROFF, B L Philadelphia Electric Co 82/10/15 STOLZ, J F Operating Reactors Branch 4 2pp 15765 063 24% Fiche 50-277, 82/10/15, 8210210330
- 8210220006 Forwards application to amend License DPR-36 requesting Tech Spec change to extend insp interval applicable to two inaccessible hydraulic snubbers BRADLEY, E.J. Philadelphia Electric Co. 82/10/19 DENTON H.R. ERROLLT.E J Philadelphia Electric Co 82/10/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 15778 219 24x Fiche 50-278, 82/10/19, 8210220006
- --8210220007 Application to amend License DPR-56, changing Tech Specs to extend inspiritual applicable to two inaccessible hydraulic snubbers Certificate of Bvc enci BAUER, E 0 , BRADLEY, E J Philadelphia Electric Co Ba Gap 15778 220 24X Flohe 30-278,82/10/14,82/0220006
- 9210280196 Forwards response to draft technical evaluation rept recontrol of heavy loads Addl info requested in 820405 telcon enci DALTROFF,8 L Philadelphia Electric Co B2/10/25 STOLZ:J F Operating Reactors Branch 4 45pp. 15639 134 24X Fiche 50-277: B2/10/25: B210280194
- --8210280178 "Btructural Analysis of Peach Bottom Units 2 & 3 Reactor Pressure Vessel Head Drop. Shroud Head Assembly Drop & Steam Dryer Assembly Drop Conditions " HERRERA,M L. MCN.O General Electric Co. 82-32 82/08/31 38pp 15837, 181 24X Fiche: 50-277,82/10/25.8210280176,
- --- 8210280201 "Lifting Devices & Lifting Points Stress Analysis for elocated intering between a Litting Paints Stress Analysis for Reactor Pressure Vessel Head Strongback.8team Duyer/ Beparator Sling & Svc Platform to Comply W/NUREQ-0612 for Peach Bottom Units 2 & 3 " KONO.Y.H. Oemral Electric Co NSE-50-0882 82/05/31. 3ipp 15839 219 24X Fiche 50-277,82/10/25,8210280196
- --8210280204 "Lifting Devices & Lifting Points Stress Analysis for Fuel Pool Oate Lifting Points, Hydraulic Tensioner Lifting Device & Lifting Points & Reactor Pressure Vessel Insulation Removal Lifting Device & Insulation Lifting Points " SZUMBKI.T J. Philadelphia Electric Co., NBEO-72-0782, 82/07/31 27pg 15839, 250 24X Fichs: 50-277, 82/10/25, 8210280196.

@ Inspection reports, IE Builetins & correspondence

- 8210070317 Forwards IE Insp Repts 50-277/82-20 & 50-278/82-19 on 820816-20 & notice of violation MARTIN,T T Division of Engineering & Technical Programs 82/09/22 DALTROFF.S L Philadelphia Electric Co 2pp 15634 135 24X Fiche 50-277, 82/09/22, 8210070317
- --B210070330 IE Insp Repte 50-277/B2-20 & 50-278/B2-19 on 620816-20 Noncomplience noted no notification given for abnormal degradation in primery containment, evidenced by unacceptable local leak rate test results for nine lealation valves PULLANI.S V , BETTENHAUSEN.L Division of Engineering & Technical Programs. 82/09/14 7pp. 15634.138 24X Fiche-50-277,82/09/22,8210070317
- 8210070296 Forwards JE Insp Rept 50-278/81-28 on 811013-15 MARTIN.T T Division of Engineering & Technical Programs 82/09/24 DALTROFF,S L Philadelphia Electric Co 2pp 15634-218 24X Fiche 50-278,82/09/24,8210070296
- --B210070308 IE Inep Rept 50-278/81-28 on 811013-15 Noncomplience noted failure to follow redistion protection procedure & promptly notify NRC in accordance w/10CFR50-72 NIMITZ. R L , GREENMAN. E Q. Division of Engineering & Technical Programs. B2/07/26 18pp 15634-220 24X Fiche 50-278, 82/09/24, 8210070296
- 6210150299 Forwards IE Imap Repts 50-277/82-19 & 50-278/82-18 on 820807-0915 No noncompliance mated STAROBTECKI.R. Division of Project & Resident Programs 82/09/27. DALTROFF, B L Philadelphia Electric Co 2pp 19707 234 24X Fiche: 50-277, 82/09/27. 8210150299
- --8210150302 IE Insp Repts 50-277/82-19 & 50-278/82-18 on 820807-0913 No noncompliance noted Major areas inspected operational safety, radiation protection, physical security, control room activities & IE bulletin followup BLOUGH. A R. , MCCANE. E C. Division of Project & Resident Programs 82/09/20 19pp 15707 236 24% Fiche 50-277, 92/09/27, 8210150399
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Disiodged I-125 Implant Beeds," Svc list enci. CDBB-L 1 Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche-50-000,82/10/06,8208190233
- 8210130271 Act receipt of 820927 itr informing NRC of steps taken to correct violations noted in IE insp Repts 50-277/82-14 & 50-276/82-14.

 STAROSTECKI:R Division of Project & Resident Programs B2/10/06, DALTROFF:S L Philadelphia Ejectric Co. 1p. 15578 347 Fiche: 50-277. 82/10/26, 8240130291
- --8210130296 Responds to NRC 820901 ltr re violations noted in IE Insp. Rapts 50-277/82-14 & 50-278/82-14 Corrective actions defective locking mechanism replaced & personnel instructed to be more forceful when checking locked dones, DALTROFFIS L. Philedelphia Electric Co. 82/09/29, STAROSTECKI.R. Division of Project & Resident Programs, 2pp. 19678 348 24X Fiche 50-277, 82/10/06, 8210130291.
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Crecking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation SysPiping at BMR Plants " Syc list encl.

 DEYOUND, R. C Director's Office, Office of Inspaction and Enforcement. 82/10/14 Consolidated Edison Co. of New York 115pp 15810-125 24X Fiche, 50-000, 82/10/14, 8208190238
- 8210220006 Forwards application to amend License DPR-55, requesting Tech Spec change to extend inep interval applicable to two inaccessible hydraulic anothers. BRADLEY, E. J. Philadelphia Electric Co 82/t0/19 DENTON, H R. Office of Nuclear Reactor Regulation, Director ip, 15778:219, 24x Fiche, 50-278, 82/10/19, 8210220006.
- --821022007 Application to amend License DPR-56, changing Tech Space to artend insp interval applicable to two ineccessible hydraulic snubbars. Certificate of Buc encl.

 BAUER. E. 0: BRADLEY. E. J Philadelphia Electric Co. 82/10/19. 6pp. 15778: 220. 24K Fiche. 50-278, 82/10/19, 8210220006.
- R Periodic operating reports & related correspondence
- 8210150356 Forwards Thermal Happing Rept 82-4 for 820709 for thermal monitoring requirements, per App B to EYB HILLSEY.W B. Philadelphia Electric Co 82/10/08, IPPOLITO, T A Operating Reactors Sranch 3. ip 19704:277. 24% Fiche. 50-277, 82/10/08, 8210150356.

- --8210150368 Thermal Mapping Rept 82-4 for 820909 + Philadelphia Electric Co 82/10/08 4pp 15704 278 26 Fiche 50-277,82/10/08:8210150356
- 8210220190 Forwards monthly operating repts for Bept 1902 CDONEY:M J Philadelphia Electric Co 82/10/15 Directs*'s Office. Office of Inspection and Enforcement ip 15777 273 P Fichs 50-277, 82/10/15, 8210220190
- --8210220194 Monthly operating repts for Sept 1982 ALDEN.W Philediphia Electric Co 82/10/13 10pp 117777 24X Fichs 50-277.82/10/15.8210220190
- 8 Reportable occurrences, LERs & related correspondence
- 8210070474 Discusses 810225 manuel scram of reactor after irad."

 RMR relay logic A signal initiated simultaneous closure
 of both recirculation pump discharge veives All battery
 ground tracing ehould be done w/ohmeter w/o fuses
 AGHE.F Director'e Office 81/04/17 Director's Office 21
 15644 351 24X Fiche 50-278.81/04/17.8210070474
- 821001000B Responds to FOIA request for 19 categories of doller'" nuclear reactor events & safety problems Forwards documents listed in App A
 FELTON.J M Division of Rules and Records 62/06/20 UDELL\$4
 Critical Mass Energy Project 15pp 15727 003 24x
 Fichs 30-000.82/06/28.821001000B
- --B210050023 Discusses 810225 simultaneous closure of recirrulal discharge valves Event occurred while station personnel arrelatementing to remove ground associated w/A div of 123-veit dc subsystem

 ASHE, F Director's Office B1/04/17 Director's Office 2
 15727 039 24X Fiche 50-000, 82/06/28,8210010000
- 8210060017 LER 82-015/09L-0.on 820822.drywell pressure retorfir his failed downscale Caused by blown fuse Fuse replaced & sys operation verified COUNEY-IT J Philadelphia Electric Co 82/09/21 KMYNES # (Region 1, Office of Director ip 15615 08/ 24x Fiche, 30-278, 82/09/21, 8210060017
- 8210130226 LER 82-017/03L-0 on 820702, during heavy reinsteraction observed that vent eteck flow recorder indicated downcals on both channels Gaused by pilot tubes filling whete during severe storm indication returned when stora subsides COONEY.M. J. Philadelphia Electric Co. 82/10/01 MAYNEG.8 C. Region 1. Defice of Director ip 15679 009 24% Fiche: 50-278.82/10/01.8210130226
- DOCKET 50-280 BURRY POWER STATION, UNIT I
- F Security, medical, emergency & fire protection plans
- 8210010156 Ack receipt of 820820 responses re smergenty preparely deficiency items per 820406 confirmation of action lts Corrective action & plans will be examined during subsequent insps LEMES, R. C. Division of Project & Resident Programs 67/67/15 LEMBURO, R H Virginie Electric & Power Co 1p 18585 325 & Fiche 50-280, 82/07/10, 8210010156
- 8210010125 Forwards revised security training & qualification prices withheld.
 LEABBURDOR H Virginia Electric & Power Co 02/09/17 CATA:
 Office of Nuclear Reactor Regulation, Director, VANOA.S A
 Operating Reactors Branch 1 ip 15366 013 24X
 Fiche: 30-000, 82/09/17, 82(0010125
- 8210050074 Bubmits correction to 820628 Revision 3 to respects NUREO-0737. Item I.D.2. "Sefety Perameter Display Bys" Correction should be included in schedular exception: pertaining to emergency response capabilities LEABBURG. R. H. Virginia Electric & Power Go. 82/09/29 DO'N Office of Nuclear Reactor Regulation, Director. E186MAT.Ps Division of Licensing ip. 15403:185 24X Fiche 50-000-83 >-8210050074.
- 8210210030 Releasee public version of changes to emergancy plan implementing procedure FELTON.J M Division of Rules and Records. 82/09/29 Section Management Brench 1p. 15774-109. 24X Fiche.50-280.82/09/29 9210210030.

- --B210210053 Forwards public version of Change 1 to Emergency Plan Implementing Procedure EPJP-4 11. "Followup Offsite Release Assessment." Change 2 to emergency plan re NVREG-0654 cross-ref & Change 3 modifying Table 5 i

 DEWANDEL, E. P. Virginia Electric & Power Co. B2/09/17 NRC
 Detailed Affjlation Given 1p i5774 i10 24X
 Fische 50-280, 82/09/29, 8210210050 NRC - No
- --8210210035 Public version of Change 1 to Emergency Plan Implementing Procedure EPIP-4 11. "Followup Offsite Release Assessment" Virginia Electric & Power Co 82/09/17 2pp 15774 111 24X Fiche 30-280.82/09/29.8210210050
- --8210210058 Public version of Changes 2 & 3 to emergency plan re NUREC-0654 cross-ref & Table 5 1, "Min Shift Manning Requirements," respectively Virginia Electric & Power Co 82/09/17 10pp 15774 113 24X Fiche 50-280, 82/09/29, 8210210050
- Operating license stage documents & correspondence
- 3210280013 Responds to FOIA request for all internal, non-public documents, mamos, evaluation repts & other mat1 dealing w/
 nuclear plant operations Forwards documents listed in App A,
 FELTOR, J M Division of Rules and Records 82/09/17 MCINNIS, D
 News & Observer Spp 15860 045 24X Fiche 50-000, 82/09/17. 6210280013
- --8208310034 Forwards draft info notice re deficiencies in air filtration & ventilation sys Nobice based on radioactive resin release at Pilgrim 1 & on four related events at other plants involving deficiencies in maint & testing of filter sys MATTEON:R J Division of Bystems Integration (post 81005) 82/080/05 JORDAN:E L Division of Engineering & Quality Assurance 5pp 15861 024 24X Fiche 50-000:82/09/17.8210280013
- 12:01:20265 Informs of implementation status of NUREO-0737, Item II B 2, 'Plant Shielding' per NRC 820517 request All required work completed
- LEASBURG. R H Virginia Electric & Power Co 82/10/01 Office of Nuclear Reactor Regulation, Director EIGENHUT, D Q Division of Licensing 2pp 15451 230 24% Fiche 50-000, 82/10/01, 8210120245
- 1210120297 Forwards errata to Togical Rept VEP-FRD-33, "VEPCO Reactor Core Thermal-Hydraulic Analysis Using COBRA IIIc/MIT Computer Code "
- LEASBURD, R H Virginia Electric & Power Co 82/10/04 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D 0 Division of Licensing 2pp 15452 330 24X Fiche 50-000.82/10/04, 8210120277
- -8210120305 Errata to "VEPCO Reactor Core Thermal Hydraulic Analysis Using COBRA-Ific/HIT Computer Code "

 * Virginia Electric & Power Co VEP-FRD-33 ERR 82/10/04 lp 13652 332 24X Fiche 50-000,82/10/04.8210120277
- 2:01:201:10 Forwards payment of requisite technical review fees for intervice imap & testing program
 LEASBUROR H Virginia Electric & Power Co 82/10/05 DENTON, H R
 Office of Nuclear Reactor Regulation, Director VARGA, B, A
 Operating Reactors Branch i ip 15651 250 24X
 Fiche 50-280, 82/10/05,8210120110
- 210120238 Forwards payment of requisite technical review fees for reflect requests from requirements of ABPE Section XI LEASBURGOR H Virginia Electric & Pawer Co. 82/10/05 DENTON, H R Office of Nuclear Reactor Regulation. Director VARGA, S A Operating Reactors Branch i p 15652 210 24X Fiche 50-280, 82/10/05, 82/10/20258
- 210200093 Application for amend to Licenses DPR-32 & DPR-37 consisting of proposed changes to Tech Specs modifying reporting & notification requirements
 LEASBURGOR H Virginia Electric & Power Co 82/10/06 DENTON, H R
 Office of Nuclear Reactor Regulation, Director VAROA, 8 A
 Operating Reactors Branch 1, 3pp 15757:225 24X
 Fiche 50-280, 82/10/06, 8210200043
- -8210200048 Proposed changes to Tech Specs modifying reporting & notification requirements

 • Virginia Electric & Power Co 82/10/06 2pp 15757 228 24X
 Fiche 50-280, 82/10/06, 8210200043
- 210270298 Ack receipt of 820915 application requesting relief from cartain post-repair test requirements of ABME code Class [II fas requested since review involves consideration of single safety issue
 Dl005.R H License Fee Management Branch 82/10/15
 Virginia Electric & Power Co lp 15836-329 24X
 Fiche 50-280, 82/10/15, 8210270298 82/10/15 LEASBURG, R H,

- 8210220170 Forwards corrected drawing re 1 1/2-inch drain valve f-MS-74 Valve incorrectly labeled f-MS-208 in 820915 itr LEASBURG.R H Virginia Electric & Fower Co. 82/10/18 DENTON.H R Office of Nuclear Reactor Regulation. Director VARGA.S A Operating Reactors Branch 1. 2pp 19778 043 24X Fiche 50-280, 82/10/18,8210220170
- 8210220178 Comments on evaluation of significant dynamic loads in determining capacity of slings used per NUREG-0512 Rating can be safely expressed in terms of max static load LEASBURG. R H Virginia Electric & Power Co 82/10/18 DENTON, H R Defice of Nuclear Reactor Regulation. Director EIESNHUT, D G. Division of Licensing 2pp 15777 293. 24X Fiche 50-000, 82/10/18, proceedings. 6210220178
- 8210280266 Informs that containment purge valve qualification program for 36-inch containment purge valves completed To ensure prevention of radioactive release, new automatic isolation valve will be installed LEASBURG.R H Virginia Electric & Hower Co 82/10/25 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA.B A Operating Reactors Branch i 2pp 15837 316 24X Fiche 50-280, 82/10/25,8210280266
- 8210280130 Informs that review of new fuel container lifting rig completed Rig does not comply w/Paragraph 3 2 1 1 of ANSI Ni4 6-1978 Proposed design mod for conformance being reviewed & will be implemented by 840322 LEASBURG, R H Virginia Electric & Power Co 82/10/28 DENTON, H R Office of Nuclear Reactor Regulation. Director EISENHUT, D Q Division of Licensing ip 15837 163 24X Fiche 80-280, 82/10/28, 8210280130 Division of Licensing ip 8210280130
- O Imepection reports. IE Bulletins & correspondence
- 8210080015 Add1 response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) Ficher 50-000, 82/07/12, 8210080015.
- --8210080154 Systematic assessment of licensee performance notes re facility evaluation for May 1979-Apr 1980 * NRC No Detailed Affiliation Given 80/04/30 6pp, 15668-051 24% Fiche-50-000, 82/07/12,8210080015
- 8208260424 Ack receipt of util 820607 ltr & payment of civil penalty Based on review of incidente-no basis for remission or mitigation of penalty identified LIEBERMAN.J Enforcement Staff 82/07/27 LEASBURG.R H Virgini Electric & Power Go 3pp 15574 313 24X Fiche 50-280,82/07/29, 8208260424
- --8206160306 Responds to NRC 820510 ltr re violations noted in IE Inap Rept 50-280/82-58 Corrective actions prestartup checklist will be performed by instrument supervisor & all employees counseled re procedural compliance
 LEASBURD, R H Virginia Electric & Power Co 82/06/09
 DEYOUNG, R. C pirector's Office, Office of Inspection and Enforcement App 15574 316 24X Fiche 50-280.82/07/29, 8208260326032
- --821001023B Forwards IE Insp Repts 50-280/82-04 & 50-281/82-04 on 820125-0226. Enforcement action sent separately on 820510 O'REILLY.U.F Region 2. Office of Director. 82/05/13 LEABBURG.R. H. Virginia Electric & Power Co. 2pp 15574, 320. Fiche 50-280, 82/07/29, 8208260424. 15574,320. 24X
- --B210010245 IE Insp Repts 50-280/82-04 & 50-281/82-04 on 820125-0226 Noncompliance noted failure to maintain operability of steam flow instrumentation & to foliou GA manual & procedures for documenting inoperable steam flow instrumentation.

 BURKE, D. J. DAVIB, M. J. DANCE, H. C. Division of Project & Resident Programs. 82/04/08. Ppp. 15574.322 24X Fiche 50-280,82/07/29,8208260424.
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines. App A documents provided in R_Udell FOIA Request 81-313 Forwards documents lieted in App B FELTON: J H FELTON, J H Division of Rules and Records. 82/08/10. Winthrop, Stimson, Putnam & Roberts 9pp. 15645.063 Fiche.50-000,82/08/10,8210070007. LONG, D J
- --B210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensess IPPOLITO, T. Operating Reactors Assessment Branch. B2/04/01. VAROA.B Operating Reactors Branch 1 5pp. 15645 131 24X Fiche: 50-000, 82/08/10, 8210070007.

- --8210070172 Forwards info re steam generator integrity & insps at all operating PHRs.per 750320 & 21 requests Details of insps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 GOLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R Division of Technical Review (NRR-1975 only) 5pp 15645 176 24X Fiche 50-000.82/08/10,8210070007
- B210010156 Ack receipt of B20B20 responses re emergency preparedness deficiency Items per B20406 confirmation of action itr Corrective action & plans will be examined during subsequent inaps LEMIS.R C Division of Project & Resident Programs B2/09/10 LEMSBURO.R H Virginia Electric & Power Co ip 15565 325 RAX Fiche 50-260, 82/09/10. 6210010156
- B210130427 Forwards "Inservice insp Program Interval 2,821222-921222 "Relief requested from ASME Code:Section XI testing & Inspraguirements
 LEASURO, R H Virginia Electric & Power Co 82/09/21 DENTON, H R
 Office of Nuclear Resctor Regulation, Director EISENHUT, D 0
 Division of Licensing ip 15679 152 24X Fiche 50-280,82/09/21,
- --9210130431 "Inservice Insp Program Interval 2,821222-921222"

 * Virginia Electric & Power Co 82/09/21 432pp 15679 153
 24X Fich#: 50-280,82/09/21,8210130427
- 8210220331 Forwards IE Insp Repts 50-280/82-25 & 50-281/82-25 on 820830-0903 No noncompliance noted DANCE, H C Division of Project & Revident Programs 82/10/04 LEASBURD, R H Virginia Electric & Power Co 2pp 15776 275. 24X Fiche 50-280, 82/10/04, 8210220331
- ~-8210220356 IE Insp Repts 50-280/82-25 & 50-281/82-25 on 820830-0903 No noncompliance noted Major areas inspected followup on previous enforcement matters & unresolved items & followup on unplanned release of paseous radioactivity HOSEY.C M. BARR.K P Division of Engineering & Technical Programs 92/09/30 10pp 15776 277 24X Fiche: 50-280,82/10/04,8210220331.
- 8210120110 Forwards payment of requisite technical review fees for inservice insp & testing program LEASBURG, R H Virginia Electric & Power Co 82/10/05 DENTON: H R Office of Nuclear Reactor Regulation. Director VARGA: S A Operating Reactors Branch 1 p 15651 250 24X Fiche 50-280,82/10/05.8210120110
- 920B190233 IE Info Notice 80-35. Suppl 1, "Leaking & Dislodged 1-129 Impiant Seeds " Svc list encl.

 CD88.L.1 Division of Fuel Factifities: Materials & Safeguards S2/10/06 Consolidated Edison Co of New York 66pp. 15761 250 24X Fiche 50-000.82/10/06.8208190233
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter-Stainless Steel-Recirculation Sys Piping at BNR Plants " Svc list encl DEYOUNG.R C Director's Office- Diffice of Inspection and Enforcement. 82/10/14 Consolidated Edison Co of New Yort, 115pp. 15810 125. 24X Fiche 30-000-82/10/14-8288190238
- 8. Reportable occurrences. LERs & related correspondence
- 8210150095 LER 81-022/03L-0 on 810703, low flow alarm observed for process vent syx Caused by process blower motors out of syx due to valve 1-CM-21 leaking through to vent piping during attempt to drain mixed bed damineralizer IA for resin fill Witson, J L Virginie Electric & Power Co. 81/07/31 Region 2, ector 2pp 15701 192 24X Fiche 50-280,81/07/31.

- 8210150139 LER 81-029/03L-0 on 810808, while at 1007 power, individual rod position indicator for rod F 12 indicated erratically & 12 steps less than bank demand position Caused by poor electrical connection between coil & signal module HILBON, J L Virginia Electric & Power Co 81/08/28 Region | Philadelphia. Office of the Director (81/03/01) 2pp \$55698 309 24X Fiche 50-280-81/08/28,8210150139
- 8210270212 Forwards LERs 81-069/03L.81-073/03L-0 & 81-072/03L-0 HILSON.J L Virginia Electric & Power Ca 81/12/07 0'RETLLY, J Regian 2, Atlanta, Office of the Director (81/03/01) 1p 15827 042 24X Fichs 30-280.81/12/07.8210270212
- --8210270215 LER BI-069/03L-0 on Billi5, discovered loss of flow the BM-0H-101 & 102 process vent monitors Caused by radiation monitor sample pump circuit breaker tripping Cause not determined Breaker reset & pump started WILSOM, J. L. Virginia Electric & Pawer Co. 81/12/07 Region Atlanta. Office of the Director (Bi/03/01) 3pp. 15827 043 Fiche 50-280.81/12/07,8210270212
- --8210270220 LER 81-072/03L-0 on 811108, motor operated va)ve 28692 to open when operated from control room during testing Cause undetermined Valve opened normally when tested later WILSON, J. Virginia Electric & Power Co. 81/12/07 Regim Atlanta, 0.616ce of the Director (81/03/01) 2pp 15827 046; Fiche 50-280, 81/12/07, 8210270212
- --9210270224 LER Bi-073/03L-0 on Biii0B, isolation valve to recircul. spray RX A failed to close Cause undetermined Valve operated normally later Limit switch & torque sattings eramined & found satisfactory
 WILBON, J. L. Virginia Electric & Power Co. 81/12/07 Region Atlanta, Office of the Director (81/03/01) 2pp. 15027-049, Fiche 30-280, Bi/12/07, 8210270212
- 8210050103 Forwards LER 82-086/03L-0 HILGON, J L. Virginia Electric & Power Co. 82/07/24 O'REILLY. Region 2, Office of Director ip 15603 292 24X Fiche 50-280,82/07/24.8210050103
- --8210050109 LER 82-084/03L-0 on 820827, radiation monitor RM-LU-I; indicated 9 084 CPM w/o annunciation of alarm Caused by defective push button to setpoint drift Push button replaced a monitor recalibr HILSON, J. L. Virginia Electric & Power Co. 82/09/24 Region Office of Director 2pp. 15603-293 24X Fiche 50-280, 82/09, 82/0050103
- B210050071 Forwards LER 82-083/03L-0 & updated LER 82-084/01X-1 HILBON, J L Virginia Electric & Power Co 82/09/27 Cl'AFILL:, Region 2, Office of Director 1p. 15603 175 24X Fiche 50-280, 82/09/27, 8210050071
- --8210050074 LER 82-083/03L-0 on 820831, performance of PT-27E red that amp reading for heat tracing panel 9, circuit 20, was below acceptance criteria Caused by excessive heat Heat tracing replaced & tested HILSON, J.L. Virginia Electric & Power Co. 82/09/27 Reput Office of Director 2pp 15603 176 24X Fiche 50-260, 82/69/8210050071
- --8210050078 Updated LER 82-084/01X-1 on 820808, vanting of A charge pump resulted in max instantaneous release rate being exceeded Caused by failure to change radiation monitor setpoint alarms to reflect new vent sys flow rates WILBON-J L. Virginia Electric & Power Co. 82/09/27 Rejis Office of Director 3pp 15603 178 24X Fiche 50-200,82/09-8210050071
- 82100500B) Forwards LERs 82-093/03L-0.82-054/03L-0.8 B2-092/03L-0. WILBON, J. Urginia Electric & Power Co. 82/09/27 Q'REILLY. Region 2. Office of Director ip 15604 244, 24X Fichs.50-280.82/09/27,8210050081.
- --8210050086 LER 82-073/03L-0 on 820704, at 100% power, air bant if emergency diesel generator 1 found w/insufficient air pressure to start generator Caused by failure to reset local low air pressure Bottles filled to 200 psi WILSON, J L Virginia Electric & Power Co 02/07/27 Rigst Office of Director 2pp 15604 245, 24% Fiche, 30-280, 82/07-8210050081
- --8210050091 LER 82-054/03L-O on 820905, unattended portable pue; i' to clean weterbox C swung around & flooded svc water pit conteining svc water Valve MOV-SM-2028 grounded in open position Caused by operator error MOV-SM-2028 fried WILSON-J L. Virginia Electric & Power Co 82/09/27 Registrate of Director 3pp 15504 247 24x Fiche 50-280,82704 8210055081.

DOCKETED ITEMS

- --8210050092 LER 82-092/03L-0 on 820905, at full power, RPI F-8 observed fluctuating up to 15 steps Caused by exposure of containment side electrical penetration to excessive moisture & faulty signal Steam leak repaired WILSON, J L. Virginia Electric & Power Co. 82/09/27 Region 2, Office of Director 2pp. 15604-250. 24X Fiche 50-280, 82/09/27, 82100500B1
- 8210060361 Forwards LERs 82-087/03L-0 & 82-057/03L-0
 HILSON, J L. Virginia Electric & Power Co 82/09/30 G'REILLY, J P
 Region 2, Office of Director 1p 15619 006 24X
 Fichs 50-280, 82/09/30, 8210060361
- --B210060372 LER G2-087/03L-0 on B20901 & 20, pump 1-SW-P-10A experienced loss of suction power & on B20901.14 & 20, pump 1-SW-P-10A experienced similar loss of suction Cause due to insufficient NPSH Svc water replaced Svc water pumps vented WILSON, J L Virginia Electric & Power Co 82/09/30 Region 2, Office of Director 3pp 15619 007 24X Fiche 50-280,82/09/30, 62/0060361
- --8210060398 LER 82-057/03L-0 on 820701.13.18 & 20.pump 2-8W-P-10A experienced loss of suction pressure & on 820913 & 14.pump 2-8W-P-10B experienced similar loss of suction Caused by insufficient NPSH Buc water reduced 8uc water pump vented WILSON, J L Virginia Electric & Power Co 82/09/30 Region 2. Gffice of Director 3pp 15619 010 24X Fiche 50-280.82/09/30.
- 8210130204 Forwards LERs 82-055/03L-0.82-094/03L-0 & 82-095/03L-0 HILSON, J L. Virginia Electric & Power Co. 82/10/04 O'REILLY, J P Region 2, Office of Director | p. 15675 258 24X Fiche 50-280, 82/10/04, 8210130204
- --8210130208 LER 82-055/03L-0 on 820906, charging pump auxiliary oil pump A tripped leading to tripping of replacement pump/motor Auxiliary pump failure caused by open winding in motor Replacement tripping caused by undersized thermal overloads UILSON, J L Virginia Electric & Power Co 82/10/04 Region 2, Office of Director 2pp 15675 259 24X Fiche 50-280,82/10/04,821030204
- --B210130213 LER B2-096/03L-0 on 820916. Wunit at 99% power, PT-27C reveated that amp readings for beat tracing Panel 9.cfrcuit 19. was below acceptance criteria Caused by excessive heat Defective heat tracing replaced & tested WILSDM. J L. Virginia Electric & Power Co. 82/10/04 Region 2, Office of Director 2pp. 15675-261 24X Fithe 50-280.82/10/04, 8210130204
- --8210130216 LER 82-095/03L-0 on 820911.w/unit at full power, steam generator C level indication LI-1-495 drifted high Caused by body-bonnet leak on transmitter ref leg root valve Repairs unil be performed during next outage WILSON, J. L. Virginia Electric & Power Co 82/10/04 Region R. Office of Director 2pp 15675 263 24% Fiche 50-280,82/10/04,8210130204
- 9210130500 Forwards LER 92-091/03L-0 WILEDN, J. L. Virginia Electric & Power Co. 82/10/04 O'REILLY, J.P. Region 2. Office of Director lp. 15682 186 24X Fiche 50-280, 82/10/04, 8210130500
- --8210130507 LER 82-091/03L-0 on 820905, water & sediment found in lube oil of charging pump 1-CH-P-1A Caused by leak in one tube of lube oil cooler Gooler replaced, oil changed & pump returned to svc WILSON, J.L. Virginia Electric & Power Co. 82/10/07 Region 2, Office of Director 2pp 15682 187 24X Fiche 50-280,82/10/04, 6210130500
- 8210220392 Forwards updated LER 80-019/03X-1 & LERs 82-058/03L-0 & 82-099/03L-0 WILSON, J L Virginia Electric & Power Co 82/10/08 O'REILLY, J P Region 2, Office of Director 1p 15779 212 24X Fichs 50-280. 82/10/08, 8210220392
- --8210220398 Updated LER B0-019/03X-1 on 800304, error discovered in vol of contaminated drain tanks for increasing tankage Caused by stroneous labeling Vols relabeled & other tanks evaluated for use in liquid waste release calculations WILSDN.J L. Virginia Electric & Power Co. 82/10/08 Region 2, Office of Director. 3pp. 15779 213 24X Fiche 50-280, 82/10/08, 82/10/20392
- --8210220408 LER 82-058/03L-0 on 820915, safety injection accumulator C round w/reduced boron concentration of 1, 924 ppm Caused by leakage through check valve 2-85-144 during sensitized pipe flush Flush stopped Valve to be reworked during outage WILEON, J L Virginia Electric & Power Co 82/10/08 Region 2, Office of Director 2pp 15779 216 24X Fiche 50-280, 82/10/08, 8210220392

- --82102204]3 LER 82-099/03L-0 on 820920, radiation monitors RJ-0M-101 & 102, V0-103 & 104 & RM-LM-108 lost power for 10 minutes Caused by blown supply fuse due to inadvertent shorting of control relay to ground fuse replaced WILSON, J L Virginia Electric & Power Co 82/10/08 Region 2, Office of Director 2pp 15779 218 24X Fiche 50-280, 82/10/08, 8210220392
- 8210290267 Part 21 deficiency rept to potential galling problem between stem & bonnet of 1 25-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1981-Aug 1982 Valves should be serviced & stem &/or bonnet replaced ISABELLE, L D Conval, Inc 82/10/11 HAYNES, R C Region 1, Office of Director 17pp 15854 232 24% Fiche 50-000,82/10/11, 6210290267
- 8210220095 Forwards LERs 82-098/03L-0 & 82-053/03L-0
 HILBON, J. L. Virginia Electric & Power Co. 82/10/14 G'REILLY, J. P. Region 2. Office of Director ip. 15778 177 24X
 Fiche 50-280, 82/10/14, 8210220095
- --B210220097 LER 82-098/03L-0 on 820919. Liquid waste monitor RM-LW-10B alarm setpoint exceeded Tech Specs limit during performance of PT-26 I Caused by defective log rate board. Defective parts replaced & meter calibr WILSON. J L Virginia Electric & Power Co 82/10/14 Region 2, Office of Director 2pp 15778 178 24x Fiche 50-280. 82/10/14, 8210220095
- --B210220100 LER 82-053/03L-0 on 820914.pump 2-8H-P-10A lost suction pressure Caused by insufficient NPBH due to throttled svc water to air conditioning chillers Pump vented to restore NPBH WILSON, J L Virginia Electric & Power Co. B2/10/14 Region 2, Uffice of Director 3pp 15778 180 24% Fiche 50-280,82/10/14, B210220095
- 8210290264 Forwards LERs 82-100/03L-0.82-102/03L-0. & 82-103/03L-0. WILSON, J. L. Virginia Electric & Power Co. 82/10/22 0'REILLY, J. P. Region 2. Office of Director lp. 15853 128 24X Fichs 50-280.82/10/22.8210290264
- --8210290270 LER 82-100/03L-0 on 820922, pump 1-SWP-108 became airbound during use of air to clear sensing lines to water strainers in delta P gauges Caused by injecting air into syc water lines upstream of pump Personnel reinstructed WILSON, J L Virginia Electric & Power Co 82/10/22 Region 2, Office of Director 2pp 15853 129, 24X Fiche 50-280,82/10/22,8210290264
- --8210290276 LER 82-102/03L-0 on 820923, discovered pin attaching snubber 1-8HP-H68-35B to main steam line partially out & snubber cocked Caused undetermined Snubber straightened & pins properly installed HILSON, J L Virginia Electric & Power Co 82/10/22 Region 2, Office of Director 2pp 15853 131 24X Fiche 50-280,82/10/22.
- --8210270282 LER 82-103/03L-0 on 820927.amp readings for heat tracing panel 2 circuit 24D found below acceptance level Cause unknown Defective heat tracing replaced & design change initiated WILBON.J L Virginia Electric & Power Co 82/10/22 Region 2, Office of Director 2pp 15853.133 24X Fiche: 50-280.82/10/22, 8210290244.
- DOCKET 50-201 OURRY POWER STATION, UNIT 2

 F Security, medical, smergency & fire protection plans
- 6210010156 Ack receipt of 620820 responses to emergency preparedness deficiency items per 620406 confirmation of action itr Corrective action k plans will be examined during subsequent insps.

 LEMIS, R. C. Division of Project & Resident Programs 62/07/10 LEASBURG, R. H. Virginia Electric & Power Co. ip 15565-325 24X Fiche 50-280, 82/07/10, 8210010156
- 6210010125 Forwards revised security training & qualification plans Plans withheld LEASBURG,R.H. Virginia Electric & Power Co. 82/09/17. DENTON,H R Office of Nuclear Reactor Regulation. Director VARGA,B A Operating Reactors Branch i pp. 15566: 013 24X Fiche 50-000.82/09/17.8210010125
- 8210050076 Submits correction to 820628 Revision 3 to response to NUREO-0737. Item I.D 2, "Safety Parameter Display Bys." Correction should be included in schedular exceptions pertaining to emergency response capabilities

 LEASBURG, R H. Virginia Electric & Power Co. 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation. Director, ESBENHUT, D 0 Division of Licensing ip 13603 185 24% Fiche 50-000.82/09/29, 8210050076

- 8210210050 Releases public version of changes to emergency plan implementing procedure FRLTDN, J. H. Bivision of Rules and Records 82/09/29 Bocument Management Branch ip 15774 109 24X Fiche 50-280.82/09/29, 82102100550
- --3210210033 Forwards public version of Change i to Emergency Plan Implamenting Procedure EPIP-4 it. "Followup Offsite Release Assessment," Change 2 to swergency plan re NUREQ-0454 cross=tef & Change 3 modifying Table 5 i DEMANDEL E P Virginia Electric & Power Co 82/09/17 NRC No Detailed Affiliation Given ip 15774 110 24x Ficha 50-280,82/09/29,8210210050
- --8210210055 Public version of Change I to Emergency Plan Implementing Procedure EPIP-4 11, "Followup Offsite Release Assessment"

 Virginia Electric & Power Co. 82/09/17 2pp 15774 111 24X Fiche 50-280,82/09/29,8210210050
- --82i02i0058 Public version of Changes 2 & 3 to emergency plan re NUREO-0654 cross-ref & Table 5 I, "Min Shift Manning Requirements." respectively 4 Virginia Ejectric & Power Co 82/09/17 iOpp i5774.113 24X Fiche, 50-280, 82/09/29, 82i02i0050
- P Operating license stage documents & correspondence
- 8210120265 Informs of implementation status of NUREO-0737.1tem II 0 2: "Plant Shtelding" per NRC 820517 request All required work completed
 LEASBURG, R H Virginia Electric & Power Co 82/10/01 BENTON, R R
 Office of Nucleer Reactor Regulation, Director EISENHUT. D Q
 Division of Licensing 2pp 15651 230 24X Fichs 50-000,82/10/01,8210120245
- 9210120297 Forwards errets to Topical Rept VEP-FRD-33, "VEPCO Reactor Core Thermal-Hydraulic Analysis Using COBRA lilic/HIT Computer Code "
 LEABBURG: H Virginia Electric & Power Co 92/10/04 DENTON, H R
 Office of Nuclear Reactor Regulation, Director EISENHUT, D 0
 Division of Licensing 2pp 19552 330 24% Fiche 30-000,82/10/04,
 9210120297
- --8210120305 Errata to "VEPCO Reactor Core Thermal Hydraulic Analysis Using COBRA-IIIc/MIT Computer Code " * Virginia Electric & Power Co VEP-FRD-33 ERR 82/10/04 Ip i3852 332 24% Fiche 30-000.82/10/04.8210120297
- 8210200043 Application for amend to Licenses DPR-32 & DPR-37 consisting of proposed changes to Tech Specs modifying reporting & notification requirements.

 LEASBURG, R. H. Virginia Electric & Power Co. 82/10/06 DENTON, H. R. OPfice of Nuclear Reactor Repulation, Director VARCA, S. A. Operating Reactors Branch i 3pp. 15757 225 24X Fiche 50-280, 82/10/06, 8210200043
- 8210220178 Comments on avaluation of significant dynamic loads in determining capacity of tilings used per NUREO-0512 Reting can be safely expressed in terms of max static load LEA88URO.R H. Virginia Electric & Power Co. 82/10/18 DENTON.H R. Office of Nuclear Reactor Regulation, Director E38ENHUT, D. O. Division of Licensing. 2pp. 15777, 293. 24X Fiche 50-000, 82/10/18, 8210220178
- 8210280266 Informs that containment purge valve qualification program for 36-inch containment purge valves completed To ensura prevention of radioactive release new automatic isolation valve will be instailed.

 LEASSURG, R. K. Virginia Electric & Power Co 82/10/25, DENTON, H. R. Office of Nuclear Reactor Regulation: Director. VARGA, 8 A Operating Reactors Branch 1 2pp 15837, 316, 24X Fiche 50-280, 82/10/25, 8210280266
- 8210280130 Informs that review of new fuel container lifting rig completed. Rig does not comply w/Paragraph 3.2 i 1 of ANSI NI4 6-1978 Proposed design mod for conformance being reviewed & will be implemented by 840322 LEASBURO.R.H. Virginia Electric & Power Co 82/10/29 DENYON, H.R. Office of Nuclear Reactor Regulation. Director. RISENHUT.D 0 Division of Licensing 10. 13837-163. 24K Fichs. 50-280.82/10/28, 8210280130

- Q Inspection reports, IE Builetins & correspondence
- 8210080015 Addi response to FOIA request for 19 categories of islam nucleet reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 82/07/12 UDELL # 2 Critical Mass Energy Project 9pp 15643 027 24%
 Fiche 50~000.82/07/12.8210080015
- ~-B2100B0154 Bystematic assessment of incenses performance noise refectifity evaluation for hay 1979-Apr 1980

 * NRC No Detailed Affiliation Given 80/04/30 hpp
 15648 051 24X Fiche 50-000, 82/07/12/8210080015
- B20B260424 Ack receipt of util B20609 ltr & payment of civil perily Based on review of incidents, no basis for remission or nitigation of penalty identified LIEBERMAN. J. Enforcement Staff B2/07/29 LEASEURO, A. N. 1977. Electric & Power Co. Spp. 15574 313 24X Fiche 30 280.02/07/29 G20B260424
- --B206160306 Responds to NRC B20510 itr re violations noted in 11',
 Rept 50-280/82-88 Corrective actions prestartup checklish
 will be performed by instrument supervisor & all employees
 counseled re procedural compliance
 LEABBURG, R H Virginia Electric & Power Co B2/05/09
 DEYOUNG, R C Director's Office. Office of Inspection and
 Enforcement 4pp 13574 316 24X Fiche 80-280.82/07/23
- --8210010238 Forwards IE Insp Repts 50-280/82-04 & 50 481/82 (4 r 820125-0226 Enforcement action sent separately on 830510 O'REILLY, J P Region 2, Office of Director 82/05/17 LEASBURG, R H Virginia Electric & Power Co 250 15574 32 Fichs 50-280,82/07/27.8208260424
- --8210010245 tE insp Repts 50-280/82-04 & 50-281/82 04 on \$2-125 -Noncompliance noted failure to maintain operability of signs
 flow instrumentation & to follow GA menual & procedures for
 documenting inoperable steam flow instrumentation
 BURKE, D J DAVIS, M J DANCE, H C Division of Projets & Rep.
 Programs 82/04/08 9pp 15574 322 24% Fichs 50-aim \$2.11
- 8210070007 Responds to FOIA request for eight categorism of raceinstant generators & steam turbines App A documents prostagg in R Udell FOIA Request 81-313 Forwards documents listed an App B FELTON, J.M. Division of Rules and Records 82/00/10 11-3 \$. Hinthrop. Stimson. Putnam & Roberts 9pp 13643 069 241 Ficher 50-000. 82/08/10.8210070007
- --8210070139 Forwards tabulated data on steam generator trap & a. factlittes Data should be provided to licenses.

 IPPOLITORY Operating Reactors Assessment Branch 62/05 the VAROA.8 Operating Reactors Dranch i Dop 15645 131 341 Fishe 50-000.82/08/10.8210070007
- --B210070172 Forwards info re steam generator integrity & garage operating PMRs:per 750320 & 21 requests Datalis of image including defect indications, tube plugging triteria & Lates plugged will not be provided except for Point Basin ; QOLLER.K.R. Division of Reactor Licensing these terms of the Point Basin ; 75/03/24 MACCARY.R R Division of Technical Review (ARCARY. only). Spp. 13645-176 24X Fiche SO-000.02/08:10 Baticaly.
- B2:00:0156 Ack receipt of 820820 responses is emergenty pressing deficiency items per 820406 confirmation of action like Corrective action is plans will be examined during subsequent insps.

 LEMIS, R.C. Division of Project & Resident Progress & \$7.23.1.2 LEMISON.R.H. Virginia Electric & Power Co. 19 15:25 2.2 Fichs. 50-288, 82/09/10:8210010156
- 8210220331 Forwards IE Insp Repts 50-280/82-25 k 60 18:181 25 27 820830-0903 No noncompliance nated DANCE, M. C. Division of Project & Resident Program 62:11 t LEABBURG: R H Virginia Electric & Power Co 2pp 13772 2% Fiche 30-280, 82/10/04, 8210220331
- --B2102203056 IE Insp Repts 50-280/B2-20 & 50-281/82 23 on the nancompliance noted Major areas (nepected follows an previous enforcement matters & unresolved (teas & Fallows on unplanned release of gaseous radioactivity HOSEY/C N : BARR/K P Division of Engineering & Tacastial Programs 82/09/30 iOpp 18776 277 24K Ficas \$2 200.5

- DB190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COSB.& I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York 66pp 15761 250 24x Fiche S0-000,82/10/06,8208190233
- OB190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Hall.Large-Diameter.Stainless Steel Recirculation Sys Piping at INKR Plants " Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15910 125 24% Fiche 50-000.82/10/14/8208170238

Reportable occurrences. LERs & related correspondence

- 10150359 LER 81-042/03L-0 on 810719.containment spray chemical addition tank (CAY) level found below Tech Specs Caused by Jeaking valve HOV-CS-202B Valve scheduled for repair during mext outage Tank level restored WILSON. J. L. Virginia Electric & Power Co. 81/09/17 Region & Atlanta. Office of the Director (81/03/01) 2pp 15704 315 24 Fache 50-281.81/08/17.8210150359
- ·10270212 Forwards LERs 81-069/03L,81-073/09L-0 & 81-072/03L-0 WILSON J L Virginia Electric & Power Co 81/12/07 O'REILLY, J P Region 2, Atlanta, Office of the Director (81/03/01) 1p 15827 042 24% Fiche 50-280,81/12/07,8210270212
- 9210270220 LER Bi-072/03L-0 on 811108, motor operated valve 28693 failed to open when operated from control room during tasting Cause undetermined Valve opened normally when tested later WILSON, J. L. Virginia Electric & Power Co. 81/12/07 Region 2, Atlanta. Office of the Director (81/03/01) 2pp 15827 046 24X Fiche 50-280.81/12/07.8210270212
- E210270224 LER 81-073/03L-0 on Bill08, isolation valve to recirculation spray HX A failed to close Cause Undetermined Valve operated normally later Limit switch & torque settings examined & found satisfactory
 HILSON.J L Virginia Electric & Power Co 81/12/07 Region 2,
 Atlanta. Diffice of the Director (81/03/01) 2pp 15827 048 24X
 Fische 50-280.81/12/07.8210270212
- :50080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents 1 isted in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTOW.J H. Division of Rules and Records B2/07/12 UDELL.R A
- Fig. 6 50-000, 82/07/12, 8210080015
- -8204120487 Discusses problems w/water in fuel oil tank Case does not have generic implications
 TREMAN,N K. Director's Office 82/04/06 MICHELSON,C,
 Director's Office 5pp 15665 036 24X Fiche 50-000,82/07/12,
 8210080015
- -8205180693 Forwards engineering evaluation of 820118 loss of reserve station see transformer B TREHANN K Director's Office 82/05/10 MIGHELSON.C Director's Office 2pp 18666 089 24X Fiche 50-000,82/07/12,8210080018
- ≥10050081 Forwards LERs 82-093/03L-0.82-054/03L-0 & 82-092/03L-0 ₩3L5DN.J L Virginia Electric & Power Co 82/09/27 0'REILLY.J.P Region 2. Office of Director ip 15604 244. 24X Fiche 50-280.82/09/27.8210050081
- ~8210050091 LER 82-054/03L-0 on 820905, unattended portable pump in use to clean waterbox C swung around & flooded svc water pit containing svc water Valve MOV-8M-202B grounded in open position Ceused by operator error MOV-8M-202B dried WILSON.JL Virginia Electric & Power Co 82/09/27 Region 2, Office of Director 3pp 15604 247 24X Fiche 50-280, 82/09/27, 8210050081
- Q10060361 Forwards LERs 82-087/03L-0 & 82-057/03L-0
 WELSON, J L. Virginia Electric & Power Co 82/09/30 0'REILLY, J P.
 Region 2. Office of Director 1p 15619:006 24X
 Fiche 50-280,82/09/30,8210060361
- -8210060398 LER 82-057/03L-0 on 820901,13,18 % 20, pump 2-8M-P-10A experienced loss of suction pressure % on 820913 % 14, pump 2-5M-P-108 experienced similar loss of suction Caused by insufficient NPBH Buc water reduced Syc water pump vented. WiLSOM-J L Virginia Electric & Power Co 82/09/30 Region 2. Office of Director 3pp 15419 010, 24X Fiche 50-280,82/09/30,82109/09/30,

- 8210130204 Forwards LER: 82-055/03L-0.82-096/03L-0 & 82-095/03L-0 WILEON, J L Virginia Electric & Power Co 82/10/04 8'REILLY, J P Region 2. Office of Director ip 15675 258 24X Fiche 50-280.82/10/04.8210130204
- --8210130208 LER 82-055/03L-0 on 820906, charging pump auxiliary oil pump A tripped leading to tripping of replacement pump/motor Auxiliary pump failure caused by open winding in motor Replacement tripping caused by undersized themal overloads WILSON, J L Virginia Electric & Power Co 82/10/04 Region 2, Office of Director 2pp. 156/5:259 24X Fiche 50-280, 82/10/04, 8210130204.
- B210220424 Forwards LER 82-056/03L-0.
 WILSON.J L Virginia Electric & Power Co 82/10/07 O'REILLY, J P
 Region 2, Office of Director ip. 15778: 270 24X
 Fiche 50-281.82/10/07, 8210220424
- --B210220435 LER 82-056/03L-0 on B20907.pressure in nitrogen bottle supplying emergency air to PCV-MB-202A & B discovered below limit Caused by leaking nitrogen bottle connection Replacement bottle correctly installed. WILSON, J L Virginia Electric & Power Co 82/10/07 Region 2. Office of Director. 2pp 15778 271 24X Fiche: 50-281,82/10/07.821020424
- 8210220392 Forwards updated LER 80-019/03X-1 & LERs 82-058/03L-0 & BZ-099/03L-0 WILSON, J. L. V(rginia Electric & Power Co. 82/10/08 O'REILLY, J. P. Region 2, Office of Director. ip. 15779 212 24X Fiche 50-280, 82/10/08, 8210220392
- --8210220408 LER 82-058/03L-0 on 820915, saPety injection accumulator C found w/reduced boron concentration of 1,924 ppm. Caused by laskage through check valve 2-81-144 during sensitized pipe flush Flush stopped Valve to be reworked during outage WILSON, J L Virginia Electric & Fower Co 82/10/08 Region 2, Office of Director 2pp 15779 214 24X Fiche 50-280,82/10/08, Region 2000,000,000 Region 2000,000 Region 2000
- 8210270247 Part 21 deficiency rept re potential galling problem between stem & bonnet of i 25-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1781-Aug 1782 Valves should be serviced & stem A/or bonnet replaced ISABELLE, L.D. Conval, Inc. 82/10/11 HAYNES,R.C. Region 1. 0ffice of Director 17pp 15854 232 24X Fiche, 50-000, 82/10/11. 8210270267
- 8210220095 Forwards LERs 82-098/03L-0 & 82-053/03L-0 UILBON.J.L Virginia Electric & Power Co 82/10/14, D'REILLY.J P Region 2: Office of Director. 15 15778:177. 24X Fiche 50-280.82/10/14,8210220095
- --B210220100 LER 82-053/03L-0: on B20914, pump 2-8W-P-10A lost section pressure Caused by insufficient NP8H due to throttied svc water to air conditioning chillers, Pump vented to rectore NP8H WILSON.J.L. Virginia Electric & Power Co. 82/10/14 Region 2, Office of Director 3pp, 15778:180 24% Fiche 50-280,82/10/14, 8210220095
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8210250200 Forwards scenario cutline for 821014 emergency plan evaluation exercise, per NRC 820112 guidance 1tr. WARD, E C Northern States Power Co 82/09/01 Region 3, Office of Director 2pp 15788 277. 24% Fiche, 50-282, 82/09/01, 8210250200
- 8210040345 Forwards IE Insp Repts 50-282/82-15 & 50-306/82-15 on 820824-25 No noncompliance nated PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 82/09/10 LARSON.C.E. Northern States Fower Co 2pp. 15393 336 24% Fiche: 50-282, 82/09/10, 8210040345
- --8210040354 IE, Insp Repts 50-282/82-15 & 50-306/82-15 on 820824-25 No moncompilance noted Major areas inspected previous deficiencies in prompt notification/unarning sys.
 PATTERSON.J.P. AXELSON.H.L. Division of Emergency Preparedness & Operational Support 82/09/09. 4pp. 15593.358, 24X Fiche. 50-282, 82/09/10.8210040345
- 8210080184 Forwards revised Page 4 reflecting NRC guidance on activation of public alert & notification system 821014 emergancy plan exercise MARDLE C. Northern States Power Co. 82/09/28 AXELSON, W.L. Region G. 021009158

- 8210120559 Notification of 821001 meeting u/licensee. BNL & Engineering, Planning & Mgt. Inc. in Bethesda. MD to discuss requests for exemption from 10CFR50. App R requirements re-fire protection
 DIIANNI.D C Operating Reactors Branch 3 B2/09/26
 Operating Reactors Branch 3 2pp 15672 346 24X
 Fiche 50-282, 92/09/28, 9210120589 82/09/28 CLARK, R A
- 3210260374 Ack receipt of FEMA 820526 itr re evaluation of offsite emergency preparedness for facility exercise & associated final exercise evaluations Offsite emergency preparedness deficiencies should be addressed by util
 HIND.J A Division of Emergency Preparedness & Operational Support
 82/10/21 GILBERTS.D E Northern States Power Co 2pp 15804 CO1
 24X Fichs 50-282,82/10/21,8210260374
- 3210270262 Forwards info clarifying 820630 rept. "Fire Protection Bafe Shutdown Analysis in Compliance W/10CFR50, App R. Section III G & Substantive Basis for Exemption Requests," per HUSOLF, D Northern States Power Co B2/10/22
 Reactor Regulation, Director 132pp 15829 049 821001 meeting w/NRC Office of Nuclear 15829 049 24X Reactor Regulation, Director 1: Fichs 50-282, 82/10/22, 8210270262

Operating license stage documents & correspondence

- 3210040123 Submits supplemental info re util 820614 request for amend to Licenses DPR-42 & DPR-60 "LOCA ECCS Limiting Break & Exposure Sensitivity Analysis for ENC XN-1 & XN-2 Reloads at Prairie Island I "applies to both Units 1 & 2 MUSCLE-D Northern States Power Co 82/09/24 Office of Nuclear Reactor Regulation, Director ip 15581 203 24X Matica of Nuclear Fiche 30-282, 82/09/24, 8210040123
- 8210050319 Forwards response to Core Performance Branch 820816 concerns re-methods of monitoring core power distributions for Cycle 7 operation MUSCLF, D Northe Northern States Power Co 82/09/29 Office of Nuclear Reactor Regulation, Director 13pp 15610 248 24X Fiche 80-262, 82/09/29, 8210050319
- 82:0130260 Discusses implementation of NRC guidelines for working hours, provided in Generic Ltr 82-12 Revised guidelines have been implemented, w/exceptions of 72-h per we limitation & relief from control board duties MUSDLF, D Northern States Power Co B2/10/07 Of Reactor Regulation, Director 2pp 15676 012 24X Fiche 50-000, 82/10/07, 6210130260
- 8210190422 Forwards "Analysis of Capsuls P From Northern States Power Co Prairie Island Unit i Reactor Vessel Radiation Surveillance Program" MUSCRF, D Northern States Power Co. 82/10/12 (Reactor Regulation, Director, 1p 15741 044 24X Fiche 50-282,82/10/12,8210190422 Office of Nuclear
- --B210190429 "Analysis of Capsule P From Northern States Power Co Prairie Island Unit i Reactor Vessel Radiation Surveillance Program " YANICHKO, B E , TRAN.K C , KAISER.H T Westinghouse Electric Corp HGAP-10102 82/05/31 EBpp 15741 045 24X Fiche 50-282, 82/10/12,8210190422
- 8210260154 Advises that mods required by NUREO-0737. Item III D 3 4. "Control Room Mabitability," will not be completed until 830315 due to delays in receipt of matl & sampling #USDLF.D Northern States Power Co 82/10/22 G Reactor Regulation, Director Spp 15799.012 24X Fiche: 50-282, 82/10/22, 8210260154 Office of Nuclear

G Inspection reports: IE Bulletins & correspondence

- 6210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R_Udell FOIA Request 61-313 Forwards documents listed in App B FELTON: J. H FELTON.J.M Division of Rules and Records. 82/08/10 LONG, D J Wintarop, Stimeon, Putnam & Roberts, 9pp 15645,063 24X Ficher 50-000, 82/08/10,8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities. Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VAROA:8 Operating Reactors Branch 1 5pp. 15645:131 24X Fiche:50-000.82/08/10,8210070007

- --B210070172 Forwards info re steam generator integrity 4 inips at all 1 operating PKRs, per 750320 & 21 requests Details of image. (including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach I OCLLER.K R Division of Roactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R R Division of Fechnical Review (RRR-1975 only) 5pp 15645 196 24X Fiche 50-000.82/08/10.0210070007
- 9210040345 Forwards IE Insp Repts 50-282/82-15 & 50-306/82-15 on 820824-25 Nu noncompliance noted
 PAPERIELLO, C J Division of Emergency Preparedness & Operations
 Support 82/09/10 LARSON, C E Noithern States Power Co 73,8
 15593-356 24% Fiche 50-282,82/09/10.8210040345
- --8210040354 IE Insp Repts 50-282/82-15 & 50-306/82-15 on Na0024-15 & 210040334 It has kepts 30-282/06-13 a 0-300/82-35 an M2024-35 w noncompliance noted Major areas inspected previous deficiencies in prompt notification/warning sys PATTERSON, J.P., AXELSON, W.L. Division of Emergency Preparedress; Operational Support 82/09/09 4pp 15593 358 24X Fiche 50-282,82/09/10,8210040345
- 820B190233 iE Info Notice 80-35. Suppl 1. "Leaking & Dislodged 1-13 Implant Seeds " Svc list enc! CDBB.L I Division of Fuel Facilities, Materials & Bafaguards 82/10/06 Consolidated Edison Co of New York & Spp. 15761;" 24X Fiche 50-000.82/10/04.8208190233
- 8210190432 Ack receipt of 820919 litr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/82-11 & 50-304/82-11 50-306/82-11 SPESSARD,R L Division of Project & Resident Programs 182/ LARSON.C E Northern States Power Co ip 15741 182 24X Fiche 50-282,82/10/07,8210190432 102710701
- --8210190439 Responds to NRC 820817 itr re-vaciations noted in It II-4 Repts 50-282/82-11 & 50-306/82-11 Corrective actions startup program changed to normalize flux difference channels LARSON, C E Chambers
 LARSUN,C E Northern States Power Co 82/09/15 SIRIFIER
 Division of Project & Resident Programs 2pp 15741 183
 Fiche 50-282,82/10/07/8210190432 STREETER J F 741 183 24E
- 8210150249 Ack receipt of 820928 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/82-13 & 50-306/82-19 STREETER, J F Division of Project & Resident Programs #82/10/63 LARSON, C E Northern States Fower Co ip 15/04 361 28 Fiche 50-282, 82/10/08, 9210150249
- --8210150255 Responds to NRC 820702 ltr re violations noted in [E t]
 Repts 50-282/82-13 & 50-306/82-13 Corrective actions dissel
 generator test procedures will be revised by 821201 &
 investigative rept will be discussed w/operators
 LARGON.C E Northern States Power Co 82/07/28 hTRLEM4.) F
 Division of Project & Resident Programs 2pp. 19/04 362 443
 Fiche 50-282,82/10/08.8210150249
- 8210280144 Forwards IE Insp Repts 50-282/82-16 & 50-305/82 16 bm B20901-17 & notice of violation
 BTREETER, J F Division of Project & Resident Programs D2/(C/I)
 LARSON, C E Northern States Power Co 2pp 1503/ 199 248
 Fiche, 50-282, 82/10/13, 9210280164
- --8210280168 Notice of violation from insp on 820901-17 STREETER, J F Division of Project & Resident Programs 82/12.3 ip 15837 201 24X Fiche 50-282.82/10/13,8210280164
- --8210280171 IE Insp Repts 50-282/82-16 & 50-306/82-16 on 82091-1F Noncompliance noted failure to post no smoking sign in safety-related equipment areas & operators found smoking DURY, N. E. REYESL. Division of Project & Resident Programs 82/10/12 6pp 15837 202 24X Fiche 50-282,82/10/17.830026 1
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thisth-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BUR Plants "Sve list ench DEYGUNO, R C. Director's Office, Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co of New Yers 115pp 15810,125 24X Fiche 50-000.82/10/14.8200190238
- S Reportable occurrences, LERs & related correspondence
- 8210150381 Forwards LER 81-011/01T-0 MAYER.L G Northern States Power Ca 81/08/24 MEPP Region 3. Chicago, Office of the Director (81/03/01) 15704:065 24% Fiche 50-282,81/08/24,8210150381 KEPPLER, J Q l.s

- --8210130390 LER 81-011/01T-0 on 810812.D2 diesel generator tripped & locked out during operability test Caused by generator operating in unfamiliar mode & var & watt meters being confused by operator HUMSTAD.A A Northern States Power Co 81/08/24 Region 3, Chicago, Office of the Director (81/03/01) 2pp 15704 066 24X Fiche 30-282,81/08/24,8210150381
- E210130510 Forwards LER 82-016/03L-0 MUCOLF.D Northern States Power Co 82/10/06 Region 3, Office of Director 1p 15682 256 24X Fiche 50-282,82/10/06,8210130510
- --82(0130533 LER 82-016/03L-0 on 820906, spike occurred in RCS activity up to 1 38 uCi/g dose equivalent I-131 Caused by reactor trip 2 subsequent washout of fission product from existing fuel defects Region 9 fuel will be removed HUNSTAD.A A Northern States Power Co 82/10/06 Region 3, Office of Director App 15682 257 24X Fiche 50~282,82/10/06, 8210130510
- 8210250179 Forwards LER 82-019/03L-0 MUSOLF, D. Northern States Power Co. 82/10/15 Region 3, Office of Director 1p. 15788 296 24% Fiche 50-282,82/10/15,8210250179
- --8210250183 LER 82-019/03L-0 on 820917.diesel cooling water pump 22 did not start on demand during lesting Start attempt 7 minutes later successful Cause unknown In 5 days of testing, failure could not be reproduced HURBTAD, A A Northern States Power Co 82/10/15 Region 3. Office of Director lp 15788 297 24% Fiche 50-282,82/10/15,8210250179
- B210250364 Forwards LER 82-018/03L-0 MUSDLF. D. Northern States Power Co. 82/10/15 Region 3, Office of Director 1p. 15790 177 24X Fiche 50-282,82/10/15,8210250364
- --8210250376 LER 82-018/03L-0 on 820915, discovered that two ventilation flow tests not performed as scheduled Caused by personnel error Tests rescheduled HUMSTAD.A A Northern States Power Co 82/10/15 Region 3, Office of Director 1p 15790 178 24X Fiche 50-282,82/10/15. 82:10250364

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

- A Application/construction stage documents & correspondence
- E21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 62/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- --820427004B Recommends prompt attention be given to problem of reactor coolant pump closure stud corrosion detected at facilities Response by 820415 requested EISENHUTT.D Q Division of Licensing 82/03/24 HANAUER.B. H Division of Systems Integration (post Bil005) 3pp 15745 270 24% Fiche 50-000.82/06/28.8210010008
- F Security, medical, emergency & fire protection plans
- 8209170051 Forwards site security plan Revision 11 Revision withheld (ref 10CFR73 21)
 JONES.W C Omaha Public Power District 82/08/27 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 1p 14910 097 2:
 Fische 50-283
- 62:10220110 Notifies of emergency preparedness appraisal team 82:1108 site visit to close out Apps A & II items identified in IE Emergency Preparedness Appraisal Rept 50-285/82-27 on 61:207-16

 SEIDLE: W C Division of Resident, Reactor Project & Engineering Programs 82:10/17 JONES,W C Omaha Public Power District 1:13778 168 24X Fiche 50-285.82:10/19-0210220110
- H General correspondence
- 8210060244 Requests that author be deleted from mailing list Further mailings should be sent to Metropolitan Planning Agency KIRBHEN, A H Kirshen, A H 82/09/30 TOURIGNY, E NRC No Detailed Affiliation Given is 15619 320 24X Fiche 50-285,82/09/30,8210060244

- P Operating license stage documents & correspondence
- G210010008 Responds to FOIA request for 17 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 62/06/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000, 82/06/28,8210010008
- --8004100193 Forwards evaluation of facility for Cycle & operation All Tech Spec changes & safety analyses required for 1500 MH Approved CHECK.P 8 Reactor Safety Branch 60/03/16 REID.R W Operating Reactors Branch 4 (Pre 800428) 34pp 15727 Q44 24X Fiche 50-000.82/06/28.8210010008
- 8210080015 Addi response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X
 Fiche 50-000.82/07/12,8210080015
- --8105040512 Discusses actions proposed as result of borse acid corresson damage of stud bolts & piping at PWR plants IE proposal & schedule for actions will be discussed at 810409 meeting in Bethesda. MD SNIEZEK, J H. Division of Resident & Regional Reactor Inspection 81/04/02 EIGENHUT, D 0 Division of Licensing ARLOTTO & A Division of Engineering Standards 3pp 15668 127 24X Fiche 50-000, 82/07/12-8210080015
- 8210050247 Forwards post-accident Sampling sys Status update & revised completion schedule per NUREG-0737. Item II 8 3 Reasons for delay of TMI action plan mod discussed JONES.W C Omaha Public Power District 82/09/30 CLARK.R A Operating Reactors Branch 3 3pp 15610 330 24X Fiche 80-285.82/09/30.8210050247
- 8210050176 Advises of delay in receipt of motor curves from vendor per 820521 commitment to provide justification re adequacy of electrical distribution sys voltages Curves & evaluation scheduled for submittal by 821201

 JONES, W. C. Omaha Public Power District 82/10/01 CLARK, R. A. Operating Reactors Branch 3 ip 15614 009 24X Fiche 50-285, 82/10/01, 8210050196
- 8210270038 Forwards PNL final rept on 820608-10 audit of procedures & training addressing pressurized thermal shock issue Max & min subcooling margin curve.NDT & saturation curves should be available on single plot in control room CLARK-R A Operating Reactors Branch 3 82/10/12 JGNES.W C Omaha Public Power District 3pp 15877 278 24X Fiche 50-285, 82/10/12.8210290038
- --8210270041 "Audit of Fort Calhoun Procedures & Training that Address Pressurized Thermal Shock Issue," final rept CLARK.R O. AMES, K. RANKIR.H U. Battelle Memorial Institutu. Pacific Northwest Laboratory 82/06/30 28pp 15877 281 24x Fiche 50-285.82/10/12.8210270038
- 8210000000 As form that that amonaged achedule for fulfilling NUREO-

- --8210190349 IE Insp Rept 50-285/82-17 on 820830-0903 No noncompliance noted Major areas inspected housekesping/cleanliness, onsite review committee & calibr MURPHY.M E , FLIPPO.T.A , MUNNIGUTT.D M Division of Resident. Reactor Project & Engineering Programs 82/09/20 Opp 15742 114 24% Fiche 50-285,82/09/22,8210190347
- 821019053i Forwards IE Insp Rept 50-285/82-16 on 820801-3i No noncompliance noted SEIDLE:W C Division of Resident, Reactor Project & Engineering Propras 82/09/22 JONES:W C Gmaha Public Power District 2pp 15751 306 24X Fiche 50-285.82/09/22.8210190531
- --B210190539 IE Insp Rupt 50-285/82-16 on B20801-31 No noncompliance noted Hajor areas inspected operational safety verifications surveillance testing meint, preparation for refueling & LER fullows YANDELL.1. A. HUNNICUTT.D H Division of Resident, Reactor Project & Engineering Programs 82/09/17 6pp 15751 308 24X Fiche 80-285,82/09/22,8210190531
- 3210070326 Ack receipt of 820629 ltr supplementing 811012 & 0904 ltrs informing NRC of steps taken to correct violations noted in IE insp Rept 50-285/Bi-16
 SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs 82/10/05 JONES.W C Omaha Public Pager District Ip 15634 085 24% Fiche 50-285.82/10/05/8210070326
- --B210070333 Responds to NRC B10B05 ltr re violations noted in IE Inap Rept 50-285/81-16 Corrective actions all OA records will be entered into record mgt sys by 831231 Info updates 810904 & 1012 responses

 JONES, W.C. Omaha Public Power District 82/06/29 GEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs 2pp 15634 086 24X Fiche 50-285, 82/10/05, 8210070326
- 1208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged i-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06.8208190233
- 1208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys
 Piping at BNR Plants " Syc list encl
 DEYDUNG.R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consultdated Edison Co. of New York
 115pp 15810 125 24X Fiche 50-000,82/10/14,8208170238,
- 1210220110 Notifies of emergency preparedness appraisal team 821108 site visit to close out Apps A & B items identified in IE Emergency Preparedness Appraisal Rept 50-265/82-27 on 811207-16
 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/10/19 JOMES, W C Omaha Public Power District 19 15778 168 24% Fiche 50-285, 82/10/19, 8210820110

Periodic operating reports & related correspondence

- 210190736 Forwards monthly operating rept for Sept 1982 JONES W C Omaha Public Power District. 82/10/12 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 13736 262 24X Fiche, 50-285,82/10/12,8210190736
- -9210190746 Monthly operating rept for 8ept 1982 SHORT, R. W Omeka Public Power District 82/10/12 7sp 15736, 263 24X Fiche 50-285, 82/10/12, 9210190736

Reportable occurrences, LERs & related correspondence

- 210040186 Forwards LER 82-018/01T-0
 JONES N C Omaha Public Power District, 82/09/20 SEIDLE N C Region 4, Office of Director. 1p 15581 352 24X
 Fiche 50-285,82/09/20,8210040186
- -9210040187 LER B2-018/01T-0 on 820917, review of electro-pneumatic (E/P) valve positioners revealed absence of analysis or test qualification data for Honeywell Model 67400-023 positioners Centrol circuit, solenoid valves to be modified MEMAFFEY.R F. Omaha Public Power District 82/09/17 Region 4, 8210040186.
- 210130570 Forwards LER 92-017/03L-0
 JONES H C Omaha Public Power District 82/09/29 SEIDLE-W C
 Division of Resident, Reactor Project & Engineering Programs. ip.
 15679:109 24% Fiche:50-285,82/09/29,8210130570.

- 82(005030) Forwards LER 82-017/03L-0 Detailed event analysis subbite.

 JONES W C Down Public Power District 82/10/01 CLARK, R A
 Operating Reactors Branch 3 to 15610 261 24x
 Fiche 50-283, 82/10/01.8210050301
- --8210050303 LER 62-017/03L-0 on B20830, control room operator noticely valve position indication for inboard containment isolation valves, HCV-0208 to 8210 Caused by Valcor Engineering Cosolenoid valves containing failed solenoid coils CORE, MR Omaha Public Power District B2/09/29 Region 4 Office of Director 4pp 15410 262 24% Fiche 50-285, D2/10/C1 B210050301

V Operator Examinations

8210200077 Advises that util proposed schedule for fulfilling NUMEC-0737. Item I A 1 3, "Shift Hamming Requirements." has been delayed due to NRC not having graded exams for two icolor reactor operator trainees New completion date is 830101 JONES. W C Omaha Public Power District 82/10/15 CLARK. A A Operating Reactors Branch 3 2pp 15755 354 24X Fichs 50-285. 82/10/15.8210200077

DOCKET 50-284 INDIAN POINT STATION, UNIT 3

F Security, medical, emergency & fire protection plans

- B210060091 Submits request for mods to emergency notification eye. In to upcoming relocation of emergency facilities BRCNS. J C Power Authority of the State of New York B2/09/13 SHITH. G H Division of Emergency Preparedness & Operational Sept. 2pp 15614 359 24X Fiche 50-286.82/09/13.8210060091
- 82i0060145 Forwards "Testing & Repair of Siren Portion of Alert & Notification Gys for Indian Point Nuclear Power Generating Plant," per discussion at 820708 status meeting KELLY, J J Pawer Authority of the State of New York 6,2/07/15 DAVIDDF, D New York State of 1p 15614 275 24X Fiche 50-247, 82/09/15,8210060145
- --8210060148 "Testing & Regair of Siren Portion of Alert & Molificat Sys for Indian Point Nuclear Power Generating Plant " + Power Authority of the State of New York 92/09/14 Gpe 15614 296 24% Fiche 50-247.82/09/15.8210060145
- B210130047 Notification of B20924 meeting w/util in Bethewda.HD to discuss App R review THOMA,J O Operating Reactors Branch 1 B2/09/20 VARGA.S A Operating Reactors Branch 1 2pp 15696 282 24X Fiche 30-286, B2/09/20.B210130047
- 8210130604 Forwards Auxiliary Bys Dranch input to agenda for 926724 meeting in Bethesda.MD to discuss App R & probabilistic rist assessment
 - VAROA, B.A. Operating Reactors Branch 1 82/09/21 Linctain L. Power Authority of the State of New York 8pp 15692 351 24s Fiche 50-286, 82/09/21, 8210130604
- 8210040204 Ack receipt of 820902 itr describing status of activities underway to correct significant deficiencies identified by FEMA, in response to NRG 820803 itr BMITH, 0 H Division of Emergency Preparedness & Operational E.pr. 92/09/27 BRONB, J C Power Authority of the State of New Yerlip 15583 134. 24X Fiche 50-286, 82/09/27, 8210040206
- --B210040213 Forwards description of activities planned or unigrue, correct deficiencies listed in FEMA 820730 interia findings re adequacy of radiological emergency response preparadies; of state & local govts, per NRC 820803 request BAYNE, J. P. Fower Authority of the State of New York 82/69/27 HAYNESAR C. Region 1, Office of Director 11pp 13583 135 2 Fiche 50-286, 82/09/27, 8210040R06
- 8210050079 Informs that installation of CRT terminal in emergency operations facility & video surveillance sys per TMI Action Item III.A i 2 will be completed by end of current refueling outage BAYNE, J. P. Power Authority of the State of New York 62/09/50 VARQA, 8. A. Operating Reactors Branch i 2pp 15604 274 24s Fiche 80-286, 82/09/30, 8210050079.
- 8210190738 Forwards schedule for providing info requested in NSC 62. Itr re App R
 BAYNELJ P Power Authority of the State of New York 62/10/12
 VARQA.8.A Operating Reactors Branch 1 4pp 15736 258 281
 Fiche 50-286, 82/10/12

DOCKETED ITEMS

8210200019 Advises that serious deficiencies in emergency preparedness will not be corrected since State of NY & FEMA not addressing concerns of local officials by involvement in current changes
HDLT.J Public Interest Research Group, New York KESSLER.J Rockland Citiens for Safe Energy SCHEINER,C A Westchester Peoples Action Coalition Inc 82/10/15 PALLADINO.N J , ROGERTS.T M , ASSELSTINE.J K Commissioners Spp 15755 083 24X Fiche 50-247.82/10/15.8210200019

G Adjudicatory correspondence

- 8C0623078B Ack receipt of 800416 memo w/insp repts verifying interim actions required of facilities in 800211 confirmatory orders Requests verification that Item F 2 in orders is met Item E 5 in W Commill 800317 memo should be F 5 NOVAK.T M Assistant Director for Operating Reactors 80/06/13 RPYAH.S E Division of Reactor Operations Inspections 1p 02765 285 24% Fiche 50-247.80/06/03.8006230788
- 8210060235 Declines invitation to appear before Subcommittee on Energy Conservation & Power Subcommittee investigation is intrusion into ongoing regulatory proceeding & threatens independence of Commission MDRGAN.C Morgan Associates MDRGAN.C Power Authority of the State of Neu York 82/09/30 OTTINGER.R L House of Rep., Energy & Commerce 10pp 15619 360 24% Fiche 50-247.82/09/30.8210060235
- 8210040108 Order CLI-92-28, requesting ASLB reconstituted by CLI-92-24 to estimate when recommendations called for by CLI-81-23 can be provided CHILK.S J Office of the Secretary of the Commission 82/10/01 Atomic Safety and Licensing Board Panel 1p 15580 350 24X Fichs 50-247,82/10/01.8210040108
- 8210050254 Memorandum & order restating contentions & establishing procedures based on Commission guidance GLEASOR, JP. PARISIO H. SHON, FJ. Atomic Safety and Licensing Board Penel B2/10/01 42pp 15609 211 24X Fiche 50-247, 82/10/01.8210050254
- 6210130335 Motion for ABLB to direct NRC to reschedule 821013 mosting woutlis & Sandia in Albuquerque.NM to either New York, NY or Washington. BC Intervenor unable to attend meeting in NM WEISS.ER Union of Concerned Scientists WEISS,ER Public Interest Research Group, New York 82/10/07 Atomic Safety and Licensing Board Panel 3pp 15682 080 24X Fiche 50-247, 82/10/07, 82:0130335
- --8210130337 Notion for Commission to direct that all future meetings on issues be held in NY or Washington, DC & that intervenors be given notice concurrently w/other parties NEISS.E R Union of Concerned Scientists HEISS.E R Public Interest Research Group, New York B2/10/07 Commissioners 2pp 15682 053 24X Firbs 50-247, 82/10/07,8210130335
- G210180203 Reply to ASL8 821001 memorandum to order Plant should be totally reinspected w/appropriate tests of piping, electrical & control sys conducted ist of parties should be shortened to active participants Certificate of Svc encl FLEISHER. Z S Hest Branch Conservation Association 82/10/11 4pp 15718 124 24X Fiche 50-247, 82/10/11.8210180203
- G210150092 Order denying UCS/NY PIRO B21007 motion to direct NRC to reschedule B21013 meeting in Albuquerqua, NM to NY or Hashington, DC Only Commission has jurisdiction over NRC performance of administrative responsibilities PARIS, O H . SHON, F J . GLEASON, J P Atomic Safety and Licensing Board Panel B2/10/12 Union of Concerned Scientists 3pp 13701 194 24X Fiche 50-247, 82/10/12, 8210150092
- G210150141 Order scheduling B21103-04 prehearing conference in White Plains.NY re oral argument on responses to ASLB 821001 memorandum & order restating contentions GLEASON.J P Atomic Safety and Licensing Board Panel 82/10/12 2pp 15698 306 24X Fiche 50-247.62/10/12.8210150141
- G210180138 Motion in response to ASLB 821001 order, requesting clarification & importance of term "discussion" & extension of time to determine position re issue of consolidation Certifficate of Eve encl MAPLAN. © New York. NY 82/10/13 Atomic Safety and Licensing Board Fanel 7pp 15719 123 24X Fiche 50-247.82/10/13.8210180138
- 8210200069 Telegraphic order granting licenses request for extension of time to file responses to 821001 order All party responses due 821019
 GLEASON.J P Atomic Safety and Licensing Board Panel 82/10/14
 Power Authority of the State of New York ip 15757 280 24X
 Fiche 50-247, 82/10/14, 8210200069

- 8210200019 Advises that serious deficiencies in emergency preparedness will not be corrected since State of NY & FEMA not addressing concerns of local officials by involvement in current changes HOLT.J Public Interest Research Group, New York POENER.P Parents Concerned About Indian Point FLEIGHER.Z S Host Branch Conservation Association 82/10/15 PALLADING,N J , AHEARNE.J F , GILINGKY.V Commissioners 5pp 15755 083 24X Fiche 50-247,82/10/15,8210200019
- 8210220389 Submittal of comments on ASLB 821001 memorandum & order & motion for ASLB to issue reformulated contentions on Commission Questions 3 & 4 by 821115 & to restore Contention 6 2 Certificate of Svc encl TOSCANI, K Parents Concerned About Indian Point 82/10/15 Atomic Safety and Licensing Board Panel 2pp 15777 307 24X Fiche 50-247, 82/10/15, 8210220389
- 8210210390 Requests destruction of Wost Branch Conservation Assot 821011 reply to 821001 memorandum & order & substitution of encl version FLEISHER, Z.S. West Branch Conservation Association 82/10/18 NRC - No Detailed Affiliation Given ip 15764 099 24X Fiche 50-247, 82/10/18, 8210210390
- --8210210377 Response to 821001 memorandum & order Certificate of Svc enci FLE1SHER.Z S Hest Branch Conservation Association 82/10/13 4pp 15744 100 24X Fiche 50-247. 82/10/18.8210210390
- 8210200059 Response to ASLO 821001 order ASLO should narrow language of ASLB Question 1 1 % adopt proposed schedule for continuation of proceeding Certificate of 8vc enci MODRE, J. MCGURREN, H. J. Hearing Branch 1 82/10/19 9pp 15757 290 24% Fiche 50-247,82/10/19.8210200059
- B210220375 Request for mod of ASLB 821001 order to permit Rockland County to continue presentation of witnesses re Commission Questions 3 & 4 prior to taking evidence on Questions 1,2,5,6 & 7
 THORSEN,E O Rockland County, NY 82/10/19 Atomic Safety and Licensing Board Panel 2pp 15779 187 24X Fiche 50-247,82/10/19,8210220375
- 8210220410 Joint response of intervenors to ASLB 821001 order Meaning of "discussion" of probability should be clarified & ASLB should immediately reformulate contentions on Questions 3 & 4 Certificate of Svc enci (MEISS.E R Union of Concerned Scientists WEISS.E R Harmon & Weiss 82/10/19 Atonic Safety and Licensing Board Panel. IRpp 15778 313 24% Fiche 50-247.62/10/19.8210220410
- B210250081 Proposed hearing schedule Certificate of Svc encl
 BRANDENBURG. B Concolidated Edison Co of New York MORGAN, C
 Power Authority of the State of New York MORGAN, C
 Associates B2/10/19 9pp 13787 049 24X Fiche 50-247.82/10/19,
- 8210250216 Response to ASLB 821001 order reformulating contentions
 Opposes admission of new Contention t 1.Contentions 2-1(a)(d), 2 (a) & 2 2(b) & ASLB Question 2 2 1 Notice of
 appearance & Certificate of Svc encl
 MCRGAN, C Power Authority of the State of New York MCRGAN, C
 Morgan Associates 82/10/17 Atomic Safety and Licensing Board
 Panel 35pp 15789 166 24x Fiche 50-247.82/10/17.8210250216
- 8210250265 Notice of appearance in proceeding BAUM B L Power Authority of the State of New York HAUM B L Morgan Associates 82/10/19 ip 15791 152 24X Fiche 50-247, 82/10/19, 8210250265
- 8210250287 Motion for order reversing ASLB 821001 memorandum & order re taking of testimony on Questions 3 & 4 & establishing schedule for presentation of testimony upon expiration of 120-day clock Certificate of Svc encl VETERE.L A Westchester County.NY 82/10/19 Atomic 8efety and Licensing Board Panel 7pp 15791 165 24X Fiche 50-247.82/10/19, 8210250287
- B210290324 Memorandum re ASLB 821001 order reformulating contentions Objects to new Contention 1 1. Bases La & 1b. Contentions 2 1(a).2 1(b).2.1(c).2 1(d).2 2(a) & 2 2(b). Certificate of Svc encl
 BRANDENBURG. B Commonwealth Edison Co 82/10/19 Atomic Sefety and Licensing Board Panel 49pp. 15790 243 24K Fiche 50-247.82/10/19.8210280324.
- B210250099 Motion for leave to file memorandum in response to ASLB 821001 order 1 day late Mechanical difficulties encountered w/word processing equipment Certificate of Syc encl BRANDENBURG. B Consolidated Edison Co of New York. 82/10/20. Commissioners App 15787 062 24X Fiche 50-247.82/10/20, 8210250099

- 8210280242 Requests Commission issue order directing all meetings between NRC & licensee be held in Hashington, DC or NV. that intervenors receive notice of meetings concurrently w/utils that intervenors be provided w/minutes of 821013 meeting HEISS, ER Harmon & Heiss HEISS, ER Union of Concerned Scientists 82/10/25 PALLADINO, N J. AHEARNEJ, GILINSKY, V Commissioners 2pp 15837-058 24X Fiche 50-247, 82/10/25, 8210260242
- 8210280230 Advises that NRC does not intend to respond to intervenor motions filed in response to ASLB 821001 order until after E21103-04 prehearing conference MOORE.JE Hearing Branch I B2/10/27, GLEASON.JP, SHON.FJ, PARIS,D H Atomic Safety and Licensing Board Panel ip 15837 082 24X Fiche 50-247,82/10/27,8210280230
- 8210280353 Response opposing UCS/NY PIRO 821012 motion to direct NRC to reschedule all future meetings on bearing issues in NY or Hashington, DC NRC should be permitted flexibility to determine most appropriate location W/Certificate of Svc MCOURREN.H U Hearing Branch 1 B2/10/27 Commissioners 7pp 15839 048 24X Fichs 50-247.82/10/27.8210280353
- B210290271 Advises that licensess plan to address all matters raised in responses/motions re ASLB B21001 memorandum & order at B2103-04 prehearing conference SRRANDENBURG. B Consolidated Edison Co of New York MDRGAN, C Power Authority of the State of New York MDRGAN, C Horgan Associates B2/10/27 GLEASON, J P , SHON, F J , PARIS, O H Atomic Safety and Licensing Board Panel 2pp 15853 012 24% Fiche 50-247, 82/10/27, 9210290271

H General correspondence

- 8210190713 Informs that SS Zulio & RA Burns authorized to sign util ltrs to NRC BAYHEJ P Power Authority of the State of New York 62/10/13 Office of Nuclear Reactor Regulation, Director 2pp 15738 209 24X Fiche 50-000,82/10/13,8210190713
- 8210250272 Requests substitution of SL Baum w/TR Frey on official svc list for proceeding Related correspondence COLARULLI.P F Morgan Associates COLARULLI.P F Power Authority of the State of New York 82/10/19 STUCKY.S W Docketing & Services Branch 19 15791 190 24X Fichs 50-247.82/10/19, 82(0250272)
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180077 Forwards comments on PRA study dealing w/stismic hazard Validity of conclusions rest on quality of primary data bases & assumptions in both studies Repts are not valid risk assessments due to data base limitations
 POMEROY, P W Rondout Associates 82/08/24 OKRENT, D ACRS Advisory Committee on Reactor Safeguards 7pp 15876 001 24X Fiche 30-286, 82/08/24, 8207180077
- P Operating license stage documents & correspondence
- 8007010558 Operating Reactor Event Hemo 80-7 re nearly simultaneous trips of Unite 2 & 3 Event was of negligible safety significance & trips were unrelated & coincidental EISERHUT, D O Division of Licensing 80/06/13 VOLLMER, R H Division of Engineering MATTGONR J Division of Safety Technology. HANAVER, S H Division of Human Factors Safety 2pp 02815 145 24X Fiche 50-247,80/06/13,8007010658
- B0072B03i2 Summary of 800625 meeting w/util re implications of Class 9 accidents on liquid pathways at facility CODELL-R Hydrologic & Geotechnical Engineering Branch. 80/07/08 LEAR, 0 Hydrologic & Geotechnical Engineering Branch 5pp 03016 253. 24% Fiche 50-247.80/07/08.8007280312
- 8008050220 Requests LB Marsh be permitted to continue reviewing overpressure protection sys & associated Tech Specs NDVAK, T Assistant Director for Operating Reactors B0/07/30, ERNBT.H L Assistant Director for Technology Review IP 03078.175. 24X Fiche, 50-247, 80/07/30, 8008050220,
- 9008130744 Summary of 800617 meeting w/utils in Bethesde, MD re containment structural response to core melt accident sequences MEYER, J. F. Power Systems Branch 80/07/31 Power Systems Branch 3pp 03266-243 24X Fiche 30-247, 80/07/31, 8008130744
- 8009100100 Forwards recommandations on staff task action plan to be sent to licensees for review & response.

 BARRETTL M. Operating Reactors Assessment Branch 80/08/08 VARGA.S. A Operating Reactors Branch (Pre 800428) 8pp 03516 066 24x Ficher 50-247, 80/08/08, 8009100100.

- 8009080466 Forwards response to 800820 request for status rept re-Zion/Indian Point task action plan Responsibilities are in area of severe accident mitigation features & not in interia operational actions portion MEYER, J.F. Reactor Systems Branch 80/08/25 NOVAK, T.M. Aniis*s' Director for Operating Reactors 2pp 03484 009 24X Fiche 50-003.80/08/25.8009080466
- 8010150103 Discusses union representative allegation re harespech if security guard personnel Addi info necessary prior to MRC investigation of allegations HARP. H. Office of Inspection & Enforcement, Office of the Director 80/08/28 Office of Inspection & Enforcement, Office the Director 2pp 03630 268 24X Fiche 50-247, 80/08/29, 80/10150103
- 6009250234 Submits description of work being done on analysis of releases from facilities Simple 1-D multicompertment thereal hydraulic code being unitten to analyse variety of FVCB designs Related data enci FENSIERMACHER Reactor Systems Branch 80/09/10 GFE18,7 P Reactor Systems Branch 4pp 03589 257 24% Fiche 50 247.82/7.8009250234
- 8010220234 Responds to 800917 request re control room review ARC 62'16r detailed five add1 items to near-form QL requirements
 16em [II D 3 4 requires analysis of control room
 habitability by 810101
 HOUSTON-R W Accident Evaluation Branch 80/09/25 VARQA, 8 A
 Operating Reactors Branch 1 ip 03560 001 24X
 Fichs 90-247,80/09/25,8010220234
- 6010210783 Forwards recommendations for meeting auxiliary featurals, min flow requirements Licensee must demonstrate decay heat removal for 10 minutes w/o operator action or reset control valve throttled position
 CHECK, P.S. Assistant Director for Plant Systems 60/07/20 NOVAK, T.H. Assistant Director for Operating Reactors 25p 03647 104 24% Fiche 50-247,60/09/28,6010210783
- EOILI10084 Requests Instrumentation & Control Sys Branch evaluation util responses to questions re incore instrumentation tues at facilities Info will aid branch evaluation mitigation features re backfitting of severe mitigation features SPEIS: T P Reactor Systems Branch GO/10/09 BATTERFIFED R Instrumentation & Control Systems Branch 1p 02927 001 243 Fiche 50-247, 80/10/09, 8011110084
- 806028009B Forwards NRC questions & util answers re backfitting of savere accident mitigation features Evaluation needed in two uts SPEIS, T.P. Reactor Systems Branch 80/10/17 8CHAULR, F.P. Structural Engineering Branch 1p 65747 184 24X Fiche 50-247, 80/10/17, 801028009B
- 8011200025 Forwards Power Sys Branch evaluation of differences Ester Indian Point 2 & 3, in response to technical assistance request Requests meeting w/licensee prior to formal response to evaluation
 CHECK-P B Assistant Director for Plant Systems B0/10/21
 NDVAK, T Assistant Director for Operating Reactors Ripp
 03749 111 24X Fichs 50-247.80/10/21,8011200025
- 8210070007 Responds to FOIA request for eight categories of recert; steam generators & steam turbines App A documents provided in R Udell FOIA Request 61-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 10 2 J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 241 Fiche 50-000,82/08/10,8210070007
- 8210050452 Requests comments on draft Sandia "Ltr Rept on Review b Evaluation of Indian Point Probabilistic Safety Study" by 821001 Meeting to discuss comments will be held approx 821013 W/o enc! VAROA: 8 A Operating Reactors Branch I 82/07/15 SINCLAIS La Power Authority of the State of New York 2pp 13626 248 248 Fiche 50-286, 82/09/15, 8210050452
- 8210040400 Notification of 820921 meeting w/util in Setheria. HD to discuss proposed repair program for steam generator shall THOMA, U Deprating Reactors Stranch 1 82/09/16 VARGA & A Operating Reactors Stranch 1 15597 228 24X Fiche: 80-286.82/09/16.8210040400
- 8210050534 Requests reply to 800923 request for add1 info *4 GA program VARSA.S A Operating Reactors Branch 1 B2/09/21 SIMCLAIR to Power Authority of the State of New York 2pp 15626 359 241 Fiche 50-286, 82/09/21.8210050534

- B210290203 Requests results of evaluations, analyses & detailed description of any ongoing or planned insp & plans & schedule for repair to steam generator Results requested within 30 days of receipt of itr EISENRUT.D 0 Division of Licensing 82/09/24 SINCLAIR.L W Power Authority of the State of New York 3pp 15876 244 24X Fiche 50-286.82/09/24,8210290203
- G2:0130063 Summary of 820921 meeting w/util.Westinghouse.C-E & BMI reproblems u/steam generator tubes Util proposed to sleeve degraded tubes & plug remaining tubes Viewgraphs enci
 ThOMA.J D Operating Reactors Branch 1 82/09/28 Operating Reactors Branch 1 82/09/28 Pricke 50-286,82/09/28,8210130063
- 621CO60181 Forwards responses to 820315 request for addl info. Items i. 2-3 & 8 re control of heavy loads, per 820421 commitment Responses to Items 5.6 & 7 & supplemental response to Item 2 will be provided by 821130 8474E. J P Power Authority of the State of New York 62/09/30 VARGA-S A Operating Reactors Branch 1 9pp 15614 111 24X Fiche 50-286.62/09/30.8210060181
- 6210120253 Forwards initial comments on Sandia Nati Labs 820825 preliminary draft itr rept on review & evaluation of probabilistic safety study, addressing wind, seismic, fire, pressurized thermal shock & fan cooler issues
 0 TOCLE, J D Consolidated Edison Co of New York DAYNE, J P Power Authority of the State of New York 82/10/06 VARGA, S A Operating Reactors Branch i 62pp 15652 215 24X Fiche 50-247,82/10/06,
- S210150031 Forwards addi payment required for 820604 application to amend Tech Specs re mgt organization structure.per NRC B20714 itr Addi payment made under protest pending final determination of legality of fee schedule BANNE.JP Power Authority of the State of New York 82/10/08 MILLER.WO License Fee Management Branch Spp 15701 265 24X Fache 50-000.82/10/08.8210150031
- 0210190728 Forwards info re NUREO-0737. Item II B 3. "Post-Actident Sampling Sys." per NRC 820630 ltr BANAME. J P Power Authority of the State of New York 82/10/12 VARCA-S A Operating Reactors Branch 1 2pp 15736 272 24X Fiche 50-286. 82/10/12. 8210190728
- --8210190734 "Response to 820630 NRC Info Request Concerning Post-Accadent Sampling "

 * Power Authority of the State of New York 82/10/31 24pp 15736 274 24% Fiche 50-286, 82/10/12,8210190728
- E210120455 Forwards request for additinfore TMI Item II K 3 25.

 Power to Purp Seals "Areas of conformance & deviation from stated position should be identified & infore design & operation of affected cooling sys provided VARGA, 5 A Operating Reactors Branch 1 82/10/15 SINCLAIR, L. W Power Authority of the State of New York 3pp 15786 211 24X Fiche 50-286, 82/10/15, 8210220455
- E210210459 Forwards application to amend License DPR-64 & proposed Teth Spec changes re steam generator surveillance requirements

 BAYNE.J P Power Authority of the State of New York B2/10/18
 VARCA.S A Operating Reactors Dranch 1 2pp 15762 236 24X Fiche 50-286. 82/10/18.8210210459
- ---B210210470 Application to amend License DPR-64 changing Tech Specs re steam generator surveillance requirements BAYNEJ P Power Authority of the State of New York 82/10/18 2pp 15762 238 24% Fiche 50-286.82/10/18,8210210459
- --8210210473 Proposed Tech Spec changes re steam generator surveillance requirements
 4 Power Authority of the State of New York 82/10/18 16pp 15762 240 24% Fiche 50-286, 82/10/18,8210210459
- 9210280070 Forwards response to NRC 820924 request for info re girth weld repair program with the State of New York 82/10/25 EISENHUT.D Q Division of Licensing Sipp 15845 095 24X Fiche 50-226, 82/10/25, 8210280070
- @ Inspection reports, IE Builatins & correspondance
- 8210070097 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 LONG, D. J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fache 50-000, 82/08/10, 8210070007

- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VARGA.8 Operating Reactors Branch 1 5pp 15645 131 24X Fiche 50-000,82/08/10.8210070007
- 8210070214 Forwards IE Insp Rept 50-286/82-16 on 820816-0915 No nancompliance noted STARDSTECKI,R Division of Project & Resident Projects 82/09/23, BRONS, J C Power Authority of the State of New York 2pp 15634 246 24x Fiche 50-286.82/09/23.8210070214
- ~-82(0070216 IE lasp Rept 50-286/82-16 on 820816-0915 No noncompliance noted Major areas inspected plant operations, plant tour, surveillance, maint, purging & venting of containment, test & measurement acquipment program
 FOLEY, T. KENNY, T. J. KISTER, H. Division of Project & Resident Programs 82/09/22 10pp 15634 248 24% Fiche 50-286.82/09/23, 8210070214
- 8210270203 Requests results of evaluations analyses & detailed description of any ongoing or planned insp & plans & schedule for repair to steam generator Results requested within 30 days of receipt of ltr.
 EISENHUT.D 9 Division of Licensing 82/09/24 SINCLAIR.L W Power Authority of the State of New York. 3pp 15876 244 24X Fiche 50-286.82/09/24.8210290203
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Beeds" Sec list encl COBE, L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 13761 250 24X Fiche 50-000, 82/10/06, 8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYDUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- R Periodic operating reports & related correspondence
- 8210180088 Forwards monthly operating rept for Sept 1982 BRONS.J C Power Authority of the State of New York 82/07/12 Management Information Branch ip 15719 340 24X Fiche.50-286.82/09/12.8210180088
- --8210180071 Monthly operating mept for Sept 1982
 AUTERING.L Power Authority of the State of New York 82/10/01
 App. 15719 341 24X Fiche 50-286.82/09/12,8210180088
- 8 Reportable occurrences, LERs & related correspondence
- 8210270267 Part 21 deficiency rept re potential galling problem between stem & bennet of 1 25-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1781-Aug 1782 Valves should be serviced & stem &/or bennet replaced ISABELLE.L.D. Conval. Inc 82/10/11 HAYNES.R C Region 1. Office of Director 179p. 15854 232 24% Fichs 50-000,82/10/11. 8210290267.
- T Hearing transcripts on non-antitrust matters
- 8210040232 Testimony of JD D'Toole before US House of Representatives Subcommittes on Energy & Conservation of Committee on Energy & Conservation of Committee on Energy & Commerce re role of public participation in NRC proceedings H/Certificate of Svc Related correspondence.

 D'TOOLE, J D Consolidated Edison Co of New York 82/10/01 Ripp 15621.204 24X Fiche 80-247.82/10/01.8210060232
- DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

 F Security, medical, amergency & fire protection plans
- 8210010352 Forwards revision to safeguards contingency plan Revision withheld (ref 10CFR73 21)
 TUCKER,H 8 Duke Power Co 82/09/17, DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 15574.139 24X
 Fiche \$0-269,82/09/17,8210010352
- 8210260327 Agrees w/determination to locate fire hose stations outside affected fire areas Change from earlier commitment ecceptable STOLZ.J F Operating Reactors Branch 4 82/09/23 TUCKER, H. B Duke Power Co 2pp 15830.189. 24X Fiche 50-269, 82/09/23, 8210260529

- 8210040232 Application to amend Licenses DPR-39.DPR-47 & DPR-55 Amend requests deletion of Tech Spec 6 4 2 re site emergency drill & definition of time within which redundent component test must be performed prior to performing maint per Tech Spec TUCKER.H B Duke Power Co 82/09/27 DENYGN.H R Defice of Nuclear Reactor Regulation. Director 3pp 15586-104 24X Fiche 50-269.62/09/27,8210040232
- --8210040245 Proposed revision to Tech Spac Pages 3 3-6 & 6 4-1 re site emergency drill & time period within which redundant component test must be performed prior to performing maint a Duke Power Co 82/09/27 4pp 15586 107 24X Fiche 50-269,82/09/27,8210040232

P Operating license stage documents & correspondence

- B2100B0D36 Responds to FQIA request for documents re pins designed to hold neutron shielding pads in place under accident conditions Forwards documents listed on App A FELTON. J M Divisson of Rules and Records 82/08/13 EDDLEMAN. W Public Interest Research Group in North Carolina 2pp 15669 240 244 Fichs 50-237.82/08/13.82/080036
- --B2IGOBDOA7 Discusses work items to be accomplished after 820423 shutdown for extended refusing outage Lower thermal shield bolts will be replaced w/Inconel X-750 studs & nut assembly Unit 3 scheduled to return to operation on 820715 WAGNER, P.C. Deperating Reactors Branch 4 82/06/15 DENTON, H.R., CARTER, J. EISENHUT, D.G. NRC No Detailed Affiliation Given ip 15567 283 24X Fiche 50-000,82/08/13,8210080036
- B210040107 Advises that util response to NRC B20218 itr will be provided by B21008. Receipt of info from crane vendor & extraordinary analytical work have delayed response TUCKER, H B. Duke Power Co B2/09/24 DENTON, H R Office of Nuclear Reactor Regulation. Director STOLZ, J F Operating Reactors Branch 4 1p 15581 024 24X Fiche 50-269,82/09/24,8210040107
- 8210040232 Application to amend Licenses DPR-38.DPR-47 & DPR-95 Amend requests deletion of Tech Spec & 4 2 resite emergency drill & definition of time within which redundant component test must be performed prior to performing maint per Tech Spec TUCKER.H B Dute Power Co 82/09/27 DENTON.H R Office of Nuclear Reactor Regulation, Director STULZ.JF Operating Reactors Branch 4 3pp. 15586-104 24X Fisha 50-269.82/09/27.8210040232
- --8210040245 Proposed revision to Yech Spec Pages 3 3-6 & 6 4-1 re site emergency drill & time period within which redundant component test must be performed prior to performing maint. a Duke Pauer Co 82/09/27 4pp 15586 107 24X Fishe 50-269,82/09/27,8210040232
- 8210190145 Forwards Amends 113,113 & 110 to Licenses DPR-3B,DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Spics to allow full power operation of Unit 3 during Fuel Cycle 7 HAGNER,P C Operating Reactors Branch 4 82/09/29 TUCKER,H B Dute Power Co. 2pp 15757 341. 24X Fiche 50-269,82/09/29. 8210190145
- --8210190154 Amends 113.113 & 110 to Licenses DFR-38.DFR-47 & DPR-55. respectively, revising Tech Specs to allow full power aperation of Unit 3 during Fuel Cycle 7 STOLZ, J F Operating Reactors Branch 4 82/09/29 3ipp 15757 343 24% Fiche: 50-269.82/09/29.8210190145
- --8210190161 Bafety evaluation supporting Amends 113.ii3 & 110 to Licenses DPR-36.DPR-47 & DPR-55.respectively + Dffice of Nuclear Reactor Regulation, Director 15758 Olz. 24X Fiche 30-269,82/09/27.8210190145
- --8210190169 Notice of issuance & availability of Amends 113,113 & 110 to Licenses DPR-38, DPR-47 & DPR-55, respectively STOLZ, J F. Operating Reactors Branch 4 82/09/29, 2pp 13738 OIE. 24X Fiche. 50-269, 82/09/29, 8210190145.
- 8210210292 Advises that review of info on mods to emergency feedwater sys & repairs mede to once-through steam generators complete. Plant may resume operation w/listed conditions LAINAB. O C Assistant Director for Operating Reactors 82/09/29. TUCKER. H. B Duke Power Co 3pp 15774: 347. 24X Fiche. 30-287. 82/09/29. 8210210292
- --8210210299 Safety evaluation supporting steam generator repair & energency feedwater sys mods # 04fice of Nuclear Reactor Regulation, Director. 82/09/29. 7pp. 15774:350. 24X Fiche: 50-287:82/09/29,8210210292.

8210180323 Responds to 820913 itr re reactor bldg purge sús Poblitic given in 810707 % i7 ltrs remains unchanged Schedule for submitting info indicating purge sus meets operability requirements requested LAINAS.C C Assistant Director for Operating Reactors 82/09/X TUCKER.H B Dute Power Co 3pp 15745 334 24X Fiche 50-269.82/09/30.8210180323

i

- 8210150519 Discusses NRR actions taken under Task Interface Agrass' 82-20 for steam generator auxiliary feedwater header damage Licensee authorized to resume power operation at Ocones 3
 EISENHUT, D.O. Division of Licensing 82/10/06 DLSHIMMI, J. Division of Engineering & Technical Programs 1p 15717 251 2'. Fiche 50-000, 82/10/06, 82:0150519
- --B21015052B Forwards safety evaluation relonce-through steam general repair & emergency feedwater sys mod Licensee authorized to resume power operation LAINAS, G.C. Assistant Director for Operating Reactors 02/452 TUCKER, H.B. Duke Power Co. 2pp. 15717-262-24X Fiche 50-000, 82/10/06.8210150519
- --8210150535 Sefety evaluation supporting resumption of power opins'following once-through steam generator repair & emergency
 feeduator sys mods
 WAGNER, P.C., HAPIZ, A., RIDOELY, J. Assistant Director for Opins,
 Reactors 82/09/29 7pp 15717 264 24X Fiche 50-000.82/11 a
 8210150519
- 8210130502 Advises that flow demonstration & water hammer tests.jer NRC 820929 Itriconfirm that modified auxiliary feedwater sys satisfactory Bys supplies required amount of feedwater w/no evidence of water hammer phenomenon TUCKER.H B Dute Power Co 82/10/07 DENTON.H R (Iffice of Nuclear Reactor Regulation, Director STGLZ, J.F. Operating Rist. Branch 4 ip 15482 252 24% Fiche 50-287,82/10/07,D21013057)
- 8210180055 Responds to NRC 820608 request for add1 info re alequate station electric distribution sys voltages Requested info expected by 821022
 TUCKER, H B Duke Power Co 82/10/08 DENTON-IR (Iffice of Nuclear Reactor Regulation, Director SDLZ-JF Operating Pet Pranch 4 1p 15720 010 24% Fiche 50-269.82/10/08.0210100555
- --8210180060 Forwards partial response to Franklin Research Cit 4's technical evaluation rept re control of heavy loads.per NURSG-0612 TUCKER, H B Duke Power Co 92/10/08 DENTON, H R Cifics if Nuclear Reactor Regulation, Director BIOLZ. J F Operating Reactors Branch 4 Spp 15720 011 24X Fiche 50-269, BJ/10 / 6 8210180055
- 8210210131 Responds to NRC 820908 ltr transmitting technical s.el. rept on emergency feedwater sys Sys may not mest all current criteria for seismic qualification; but will remain functionally operable during OBE TUCKER.H B Duke Power Co B2/10/13 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.JF Operators Fig. Branch 4 App 15766 356 24% Fiche 50-249,82/10/13.021021612
- 8210210407 Application to amend DLs.revising Tech Spec 3 i alles.g full power operation of Unit 1 for interim period until appropriate safety valve ring settings can be implemented TUCKER.H B. Duke Power Co. 82/10/14 DENTON.H R. Office of Nuclear Reactor Regulation, Director STOLZ.J F. Operator Stol. Storm Branch 4 8pp 15764-038 24X Fiche 50-269.82/10/14.821021081
- --8210210411 Proposed revision to Tech Spec 3 1 allowing full posts operation of Unit 1 for interim period until appropriate safety valve ring setting can be implemented 4 Duke Power Co. 82/10/14 ip 15764 048 24% Fiche: 50-269, 82/10/14, 8210210407
- O Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of Factories steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B.

 FELTON. J M Division of Rules and Records. 82/08/50 tCR2.0 J Winthrop, Stimson, Putnam & Roberts 9pp 15645 Q63 241 Fiche: 50-000. 82/08/10.8210070007
- --B210070172 Forwards info re steam generator integrity & IRSPS SEL operating PWRs.per 750320 & 21 requests Details of IRSE. including defect indications, tube plugging criteria & tybes plugged will not be provided except for Point Beach 1 OOLLER.K.R. Division of Reactor Licensing (NRR-1975 enly) 75/03/24, MACCARY.R. Division of Technical Review (RRR-1875 only) 5pp. 13645 196, 24X Fiche 50-000,82/98/10.92/037257

- O150369 Forwards results of investigation of Item 7a of IE Inspiepts 50-269/82-21.50-270/82-21 & 50-287/82-21 Deaptime alues for gamma spectroscopy analyses of waste gas silver colite cartridges will cause only insignificant errors UCMER.H B Dute Power Co 82/08/17 O'REILLY, J P Region 2. IEffice of Director 2pp 15704 269 24% Fiche 50-269,82/08/17, 12/10150369
- Octol17 Forwards IE Insp Repts 50-269/82-33.50-270/82-33 & iD-287/82-33 on 820817-20 No noncompliance noted ARICE. H C Division of Project & Resident Programs 82/09/02 UCKER.H I Duke Power Co 2pp 15556 019 24X sche 50-269, 82/09/02.8210010117
- '210010124 IE Insp Repts 50-269/82-33.50-270/82-33 & 50-287/82-33 on 820817-20 No noncompliance noted Major areas inspected action on previous enforcement matters, auxiliary feedwater header repair & inservice insp procedures CROWLEY. B R , BLAKE, J J Division of Engineering & Technical Programs 82/09/01 8pp 15566 021 24X Fiche 50-269,82/09/02,8210010117
- OOIO158 Forwards 1E Insp Repts 50-264/82-30, 50-270/82-30 & 00-287/82-30 on B20716-0810 No noncompliance noted 'ANCE: H C Division of Project & Resident Programs 82/09/02 UCUER: H B Dute Power Co 2pp 15567 258 24X iche 50-269, 82/09/02, 8210010158
- *210010166 IE Insp Ropts 50-269/82-30.50-270/82-30 & 50-287/82-30 on 620716-0810 No noncompliance noted Major areas inspected operations, surveillance testing, maint, NUREO-0737 mods & refueling activities GRIDERS.W. FALCONER.D. BRYANT.J C Division of Project & Resident Programs 82/09/02 13pp 15567 260 24X Fiche 50-269, 82/09/02, 8210010158
- 3210010463 Responds to NRC 820712 ltr re violations noted in IE Insp Repts 50-269/82-23.50-270/82-23 & 50-287/82-23 Corrective actions personnel counseled & valve 2HP-14 cut out & properly reinstalled IUCKER.H B Duke Power Co 82/08/05 O'REILLY, J P Region 2, Office of Director 4pp 15570 183 24% Fiche 50-269.82/09/17.6210010438
- 3210010468 Forwards IE Insp Repts 50-269/82-23.50-270/82-23 k 50-287/82-23 an 820510-0610 k notice of violation LEWIS.R C Division of Project & Resident Programs 82/07/12 PARKER.N D Duke Power Co 2pp 15570 187 24X Fiche 50-269.82/09/17.8210010458
- B210010474 IE Insp Repts 50-269/82-23,50-270/82-23 & 50-287/82-23 on 820510-0610 Noncompliance noted failure to follow procedures resulting in plant trip t inadequate procedure resulting in improper reassembly of safety-related valve GRBERS.W., FALCONER.D., BRYANT.J.C. Division of Project & Resident Programs 82/07/09 12pp 15570 191 24X Fiche 50-269,82/09/17,8210010438
- 10150253 Forwards IE Insp Repts 50-269/82-32,50-270/82-32 & 50-287/82-32 on 820817-18 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/09/17 TUCKER, IB Duke Power Co 2pp 15703 267 24X Fiche 50-269,82/09/17,8210150253
- 8210150263 IE Insp Repts 50-269/82-32,50-270/82-32 & 50-287/82-32 on 820817-19 No noncompliance noted Major areas inspected lab QC & review of radiochemistry procedures & records EVANS.C D. MONTOOMERY,D M. Division of Emergency Preparadness & Operational Bupport 82/09/15 Spp. 15703 269 24X Fache 50-269,82/09/17,8210150253
- 10150131 Forwards IE Insp Repts 50-269/B2-35, 50-270/B2-35 & 50-287/B2-35 on 820908-10 No noncompliance noted DANGE, H C Division of Project & Resident Programs 82/09/23 TUCKER, H B Duke Power Co, 2pp 15698 312, 24X Fiche 50-269, 82/09/23, 8210150131
- 8210150143 IE Insp Repts 50-267/82-35,50-270/82-35 & 50-287/82-35 on 820908-10 No noncompliance noted Major areas inspected RCS leakage calculations BURNETT, F T., JAPE, F Division of Engineering & Technical Programs 82/09/21 App 15698:314 24X Fiche 50-269,82/09/23,8210350131

- 8210130290 Requests relief from inservice insp requirements (hydrostatic) of Saction XI of ASME Boiler & Pressure Vessel Code TUCKER.H B Duke Power Co 82/10/04 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,JF Operating Reactors Branch 4 20pp 18678 243 24% Fiche 50-269.82/10/04,8210130290
- 8208190233 IE Info Notice 80-35. Suppl i. "Leaking & Dislodged I-125 Implant Seeds " Svc list ancl. CDBL I Division of Fuel Facilities. Meterials & Safeguards B2/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06.8208190233.
- 8210220426 Forwards Revision 5 to response to IE Bullstin 79-02. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts"
 TUCKER: HB Duke Power Ca 82/10/08 O'REILLY, J P Region 2, Office of Director 24pp 15778 273 24X Fiche 50-269,82/10/08. 821020426
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation SysPiping at BMR Plants " Svc 15st encl
 DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche 50-000, 82/10/14, 820819023
- R Pariadic operating reports & related correspondence
- 8210190544 Forwards monthly operating repts for Bept 1982 TUCKER.H B Duke Power Co 82/10/15 Director's Office of Inspection and Enforcement ip 15751 343 24X Fiche 50-269: 82/10/18, 8210190544
- --B210190552 Manthly operating reptm for Bept 1982 REAVIS,J.A. Duke Power Co. 82/10/15 16pp 15751 344 24X Fiche 50-249, 82/10/15,8210190544.
- 8 Reportable occurrences. LERs & related correspondence
- 8210120114 Advises of immediate need for imposing specific requirements re operational restrictions for Class IE 120-voltac vital instrument buses in operating plants MICHELSON.C Director's Office 80/07/15 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 15489 165 24X Fiche 50-000.80/07/15,8210120114
- 8210010008 Responds to FDIA request for 19 categories of documents renuclear reactor system & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL, R. A Critical Hass Energy Project 15pp 15727 005 24X Fiche 50-000 82/06/28.8210010008
- 8210190447 PNO-II-82-108 on BRI010, increasing steam generator tube leakage indicated in 3A steam generator Reactor placed in hot shutdown. No abnormal radioactive releases identified IGNATONISA. BRYANT, J. C. Region 2, Office of Director 82/10/12 ip 15740:169 24X Fiche 50-287.82/10/12,8210390447
- 8210190653 PNO-II-82-111 on 821014, Unit 2 shut down after determining that pressurizer code safety valve design flow could not be fully maintained if called upon Beven-day outage required to change valves Exemption requested for Unit 1 IONATONIS, A Region 2, Office of Director 82/10/14 2pp 24X Fichs. 30-287: 82/10/14, 8210190653.
- 8210190695 RO on B21014. Unit 2 core relief velves declared inoperable due to analysis prompted by B&W safety concern. Unit 3 valves were offsite undergoing ring adjustment Immediate shutdown of Unit 2 commenced.

 Duke Power Co. B2/10/14. Region 2. Office of Director. ip. 15736 200 24X Fiche: 50-270, 82/10/14, B210190695.
- 8210290308 Forwards LER 82-010/01T-0 Detailed event enalysis enci-TUCKER H B Duke Power Co 82/10/18 0'REILLY, J.P Region 2, Office of Director. 3pp 18853 018 24X Fiche. 50-287, 62/10/18, 8210270308
- --8210270313 LER 82-010/01T-0 on 821004, discovered that weetly boron waste storage tank boron sample not taken as scheduled, contrary to Tech Spec 4, 1 3 Caused by personnel not having access to posted schedule board Board replaced.
 PETTY, J C. Duke Power Co. 82/10/18, Region 2, Office of Director, ip. 15853 021 24X Fiche 50-287,82/10/18,8210270308

- DOCKET 50-289 THREE BILE ISLAND NUCLEAR STATION, UNIT i
- B210050491 Forwards exemption from annual emergency plan exercise requirements of 100FR50.App E re level of govt participation STOLZ.J F Operating Reactors Branch 4 82/09/14 HUKILL.H D General Public Utilities ~ CFU Service Corp. 7pp 15626 291 24 Fiche 50~289.82/09/14.8210050491
- --B210050495 Exemption from annual emergency plan requirements re level of govt participation in exercises EISENHUT.D O Division of Licensing B2/09/14 General Public Utilities OPU Service Corp 4pp 15424 298 24X Fiche 50-289.82/09/14.8210050491
- 8210060228 Forwards revisions to fire hazards analysis rept & App R
 Section III 0 re-safe shutdown evaluation
 HUKILL.H D General Public Utilities CPU Service Corp 62/10/0
 EISENHUT.D 0 Division of Licensing 2pp 15620 013. 24X
 Fiche 50-289.62/10/01.8210060228
- --8210060230 Revisions to Pire hazards analysis rept & App R Section III O re safe shutdom evaluation
 Ogneral Public Utilities OPU Service Corp 82/10/01 32pp 15620 015 24X Fiche 50-289,82/10/01.8210060228
- 82i013024B Advises of deiry farm located approx i i miles east of TMI yielding fose commitment greater than six of seven present milk sampling stations Results of land census to be included in 830501 annual radiological environ operating rept HUKILL-H D Oeneral Public Utilities OPU Service Corp 82/10/04 HAYNES-R C Region 1. Office of Director 1p 15576 008 24X Fichs 50-289, 82/10/04, 8210130248
- 8210150202 Clarifies position re Action 4 of IE Bulletin 79-21, "Temp Effects on Level Heasurements" Inclusion of tables, curves or correction factors in emergency procedures will unnecessarily complicate procedures, HUXILL.H D General Public Utilities QPU Service Corp 82/10/04 IMAYNES.R C Region I, Diffice of Director 2pp 15701 334 24X Fiche 50-289, 82/10/04.8210150202
- 8210130161 Responds to ASLAB 811204 partial initial decision re alert & notification sys Sizen sys for offsite alerting adequate, panding determination of compliance w/NWR60-0654 & FEMA REP-1.

 KRIKH,R W Federal Emergency Henagement Agency 82/10/06 GRIMES,B Division of Emergency Preparedness 5pp 19673 061, 24X Fiche 50-287, 82/10/06. 8210130161
- 82(0130320 Bubmits updated status rept on offsite emergency planning issues at facility Emergency preparedness brockures distributed Biren sys testing satisfactorily completed Communications drill held on querterly basis KRIMM, R W Federal Emergency Management Agency 82/10/06 CRIMES B K Division of Emergency Preparedness 2pp 15678.158 24X Fiche 50-289,82/10/06,82(0130320

G Adjudicatory correspondence

- 8210070028 Board Notification 82-93 forwards RJ Mattson 820830 memo to DD Eisenhut notifying of results of Semiscale test on feed & bleed capability LAINAS.O.C Assistant Director for Operating Reactors 82/09/14 Atomic Safety and Licensing Appeal Panel 4pp 15645:317 24X Fiche 30-269.82/09/14.8210070028
- --9210070032 Requests all PNR licensing boards be informed of results of Semiscale feed & bised test. Unespected uncovery of core simulator occurred MATTSON-R. J. Division of Systems Integration (post 811005). 62/09/30 RISENNUT, D.J Division of Licensing 3pp. 15645:321 24X Fiche: 50-289, 82/09/14, 8210070028
- --8210070035 Recommends that board notification on Semiscale feed & blood experiments not be issued BASSETT.0 E Division of Accident Evaluation 82/08/23 SPEIG.T.P. Assistant Director for Reactor Safety 22pp 15645-324 24% Fiche: 50-209, 82/09/14.8210070020.
- 8210010427 Hemorendum & order granting licensee request to refer Ammodt 820903 motion to respen evidentiary record to ASLAB ASLAB lacks jurisfiction over subjunctor SMITH, I.H. Atomic Gafety and Licensing Buerd Panel 82/09/29 Metropolitan Edison Co. 8pp. 15369:355. 24X Fiche 50-289,82/09/29,82/000427.

- 8210050176 Brief in support of exceptions to ASLB 810827 t 830⁷²⁷ partial initial decisions re mgt issues & reopened proceedings BRADFORD.L., DDROSHOW.J Three Mile Island Alert 82/09/30 Atomic Safety and Licensing Appeal Panel 93pp 15604-025 Fiche 50-289. 82/09/30.6210050176
- G210030192 Brief on exceptions to AGLB 810827 & 820727 partial initial decisions on mgf issues training & integrity Certificate of 8vc encl AAMDDT: M M Aemodts, The 82/09/30 Atomic Safety and Licent-1 Appeal Panel 36pp 15609 256 24X Fiche 50-289,82/09/30,8210030192
- B210050237 Advises that TMI Alert unable to present full discussion as some issues in brief due to severe time constraints.

 BRADFORD.t. Three Mile Island Alert 82/09/30 EDLEG, Q J Atts. C Safety and Licensing Appeal Panel BUCK, J H , KOHL, C Alemis Sefer, and Licensing Board Panel 19 15609 051 24X

 Fichs, 50-289, 82/09/30, 82/0050237
- 8210060210 Brief supporting UCS brief on exceptions to ASIB 820/27 partial initial decision ASLB cannot continue to rely on operator judgment understanding & integrity to compensate for lack of reliable equipment Certificate of Svc ancl UCISS.E R Metropolitan Edition Co WEIGS.E R Narmon & Weiss 82/09/30 Atomic Safety and Licensing Appeal Panel 3699 15614 121 24X Fiche 50-289, 82/09/30, 8210060210
- 8210060218 Brief in support of exceptions to ASLB 820727 partial initial decision on reopened proceeding on operator cheating Certificate of Svc encl ADLER R H Pennsylvania, State of 82/09/30 Atomic Gafety **4 Licensing Appeal Panel 45pp i5614 243 24X Fiche 50-269. B2/09/30, B210060218
- 8210070194 Forwards THI training program essessement representing recent view of program & covering hearing topics GPU has made significant progress Recommendation for changes made M/o rept Bvc list encl
 BLAKE.E.L. Shaw. Pittman. Potts & Trowbridge BLAKE.I. I.
 Hetropolitan Edison Co B2/10/05 EDLES, G J , BUCK.J H , FG.E.C & Atomic Gafety and Licensing Appeal Panel 4pp 19534 2/4 2/4 Fiche 50-289, 82/10/05.8210070194
- 8210070143 Order scheduling 821107 hearings in Harrisburg.PA (codis) will hear partise re ASLB G11214 & 820727 partial initial decisione & will hold public meeting on restart CHIELK.8 J Office of the Secretary of the Commission (1/10/03) 3pp 15627 077 24X Fiche 50-289,82/10/06.8210070144
- 8210080074 Forwards licensee first annual progress rept on invitable; of exact replica simulator Bid package delayed from Apr to Sept. 1782 Installation expected in 1785 Svc list encl BLAKE, E.L. Shaw Pittman, Potts & Troubridge BLAKE, E.L. Shaw Pittman, Potts & Troubridge BLAKE, t. Matropolitan Edison Co. 82/10/06 EDLES, G.J., BUCK, Ji., KO: E.C. Atomic Safety and Licensing Appeal Panel 7pp 13640 27/ 241 Fiche 50-289, 82/10/06,8210080074
- 8210120274 Responds to 820914 Board Notification BN-02-93 re tests on feed & bleed & motion that AGLAB direct RRC to provide pertinent documentation UCB Exceptions 9-11,14,10-19 & 107 should be sustained W/Certificate of Evc POLLARD, R, D , WEISS, E Wison of Concerned Ecientists Willife, F Harmon & Weiss 62/10/07 Atomic Safety and ticensing Appeal Panel 17pp 13652 297 24X Fiche 50-289,82/10/07,0280120226
- 8210130278 Advises that Itr-designated Individual O resigned referice 821015 Individual O was NRC licensed control room operator whose performance on tests & exams was issue in reopened phase of proceeding Svc list encl
 BLAKE, E. Shaw, Pittman, Potts & Trowbridge BLAKE, E. |
 Netropolitan Edison Co 82/10/07, EDLEB, O J. BUCK, J H. KC.-4, [4
 Atomic Bafety and Licensing Appeal Panel Spp 15578 162 2cs
- 8210120256 Forwards Commission 821006 order scheduling 821107 hear-with Harrisburg, PA, in response to 811216 request BICKHIT, L. Office of the General Counsel 82/10/08 1011 hill Stland Public Interest Resource Center ip, 15652 211 ger Fiche 50-289, 82/10/08,8210120256
- 8210120314 Forwards Commission 821006 order advising of 821109 Past to meeting in Harrisburg.PA BICKWIT.L. Office of the General Counsel 82/10/00 MiffICM_JE Dauphin County, PA Ip 15651 251 24X Fiche.50~289.82/10/08. 8210120014.
- 8210130288 Requests to make limited appearance statement of Computer 821109 meeting in Harrisburg: PA re lifting of immediate effectiveness orders HOFFMAN; J C Friends & Family of TMI. 82/10/08 CHILK: 3 CMJ. of the Secretary of the Commission ip 15678 305 241 Fiche: 50-287, 82/10/08, 8210130288

- 8210210359 Motion to file brief supporting exceptions to ASLB 810807 & 820727 partial initial decisions out of time on 821002 Circumstances beyond intervenor control necessitate extension Certificate of Syc encl AAMODT.H M Asmodts. The 82/10/09 Atomic Bafety and Licensing Appeal Panel 4pp 15763 342 24X Fiche 50-289,82/10/09,6210210359.
- 8210180160 Advises that ltr-designated Individuals 0 & VV will not respond to UCS.Commonwealth of PA.TMI Alert & Aamodts brisfs supporting exceptions THI Alert Exceptions 23 & 24 & Aamodt Exception 133 waived VOIOT.H H Leposuf, Lamb, Leiby & MacRae 82/10/13 EDLES.O J. BUCK.J H. KOHL.C N Atomic Safety and Licensing Appeal Panel J 15719 169 24% Fiche 50-289.82/10/13.8210180160
- 8210180180 Memorandum & Order CL1-82-31 directing IE to determine whether civil penalty proceeding should be instituted against licensee for acts uncovered in hearing & Ofc of Investigations to investigate alleged metl false statement CHILK.5 J Office of the Secretary of the Commission 82/10/14 10pp 15717 135 24% Fiche 50-287.82/10/14.8210180180
- 6210200033 Advises that licensee will file one consolidated brief, on 621104 in response to Commonwealth of PA.TMI Alert, UCB & Aamodt briefs supporting appellant exceptions re mgt issues. Svc list encl
 BLAKE.E L. Shaw. Pittman. Potts & Troubridge BLAKE.E L. Metropolitan Edison Co 82/10/14 EDLEB.O J. BUCK.J H., KOHL.C N Atomic Safety and Licensing Appeal Panel 4pp 15757 304 24X Fiche 50-289,82/10/14,8210200033
- 8210200004 Order directing NRC to respond to UCS 821007 motion, characterized as response to Board Notification BN-82-93, that NRC provide all documents re semiscale test on feed & bized capability
 SHOEMAKER, C., J. Atomic Safety and Licensing Appeal Panel 82/10/15
 Office of the Executive Legal Director 3pp 15753,208 24X
 Fiche 50-209,82/10/15,8210200006
- 9210200011 Order extending time until 821022 for Commission to act to review ALAB-465 CHILK-8 J Office of the Secretary of the Commission 82/10/15 Commissioners ip 15753 211 24X Fiche 50-289, 82/10/15, 8210200011.
- 8210210378 Advises that author will represent Commonwealth of PA at 821109 oral presentations before Commission, Byr list encl ADLER, R W Pennsylvania, State of 82/10/18 CHILK, B J Office of the Secretary of the Commission, 3pp 15763 147 24X Fiche, 50-289, 82/10/18, 8210210378
- E210260400 Advises that ND Aamodt will represent Aamodt family at 821509 oral presentations in Harrisburg, PA
 AAMODI, M M Aamodts, The 82/10/19 CHILK, 8 J. Office of the Secretary of the Commission ip 15803, 103 24X
 Fiche 50-259, 82/10/19, 8210260400
- 8210210374 Notifies that licensee will appear at 821109 public hearing to make presentation & respond to questions re restart Licensee expects to reserve portion of time for rebuttal of other presentations Svc list encl
 TROWDRIDGE.0 F Shaw, Pittman, Potts & Trowbridge TROWBRIDGE.0 F Hetropolitan Edison Co. 82/10/20, PALLADINO, N J . OILINSKY, V . AHEARNE.J F. Commissioners App. 15762 014 24X
 Fiche 50-289,82/10/20.8210210374
- B210210493 Order establishing arrangements for 821109 meetings in Harrisburg:PA re restart CHILK:B J Office of the Secretary of the Commission. 82/10/20. 3pp 15762.259 24X Fiche:50-289,82/10/20,8210210493.
- 8210220445 Advises that JH Cutching. JR Goldberg & JR Gray will represent NRC at oral argument on whether to lift immediately effective shutdown orders in view of ASLB 820727 & 81:214 partial initial decisions.

 ORAY. J. R. Hearing Branch 4, 82/10/20 CHILK, 8 J Office of the Secretary of the Commission 1p. 15778 338 24X Fiche: 50-289, 82/10/20, 8210220445.
- 8210220455 Advises that author will represent UCB at 821109 oral argument Certificate of Svc encl HEISS.E R Hammon & Weiss. HEISS.E.R Union of Concerned Scientists. 82/10/20 PALLADINO, N. J., AHEARNE, J., GILINGKY, V. Commissioners 4pp 15779:121 24X Fichs: 50-289, 82/10/20, 82/10/20445.
- 8210250325 Forwards Commissioners TM Roberts & V Oilinsky corrected separate views on Order CLI-82-31
 8TUCKY:S W. Docksting & Bervices Branch. 82/10/21 Office of the Executive Legal Director. 1p. 13790.077. 24X Fiche 50-289, 82/10/21,8210250325

- --8210250332 Corrected separate visus of Commissioners TM Roberts & V 011insky on Order CLI-82-31 ROBERT8.T K , 01LINSKY.V Commissioners 82/10/21 4pp 15790 078 24% Fiche 50-289, 82/10/21, 8210250325
- 8210260433 Decision ALAB-698 affirming ASLB decision not to require predistribution of permanent record dosimeters & modifying decision on emergency support director SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel 82/10/22 67pp 15805 328 24% Fiche 50-287,82/10/22,8210260433
- 8210260449 Decision ALAB-697 affirming ASLB decisions on emergency planning w/condition that Commonwealth of PA agricultural info brochure be given to farmers in 10-mile plume exposure emergency planning ione SHOEHAKER.C J Atomic Safety and Licensing Appeal Panel 82/10/22 50pp 15807.054 24% Fiche 50-289.82/10/22.8210260449
- 8210260468 Order CLI-82-32 edvising that ASLAB should not be concerned about current status of compliance w/restart requirements Proceeding should determine necessary actions to protect public & progress of long-term items CHILK, S. J. Office of the Secretary of the Commission 62/10/22 Atomic Safety and Licensing Appeal Panel 4pp 15806 224 24% Fiche 50-289, 82/10/22, 8210260468
- B210270090 Response to ASLAB B21015 order UCS requests for relief in B21007 response to Board Notification BN-82-93 should be denied All documents NRC considers relevant & matl re Semiscale tests served on UCS RAWSON, R J Hearing Branch 4 B2/10/25 10pp 15815 302 24X Fiche 50-289, 82/10/25, 8210270090
- --B210270095 Affidavit of BW Sheron & WL Jensen re Semiscale S-SR-2 results Test results do not raise significant safety issue, do not exhibit any new phenomena & can be adequately predicted by existing computer codes W/Certificate of Svc SHERON.8 W , JENSEN, W L Reactor Systems Branch B2/10/25 43pp 18815 311 24X Piche 50-289,82/10/25,8210270090
- 82i0280250 Confirms 82i025 telcon in which Docketing & Svc Granch agreed to add name to svc list, as counsel for ltr-designated Individuals D & VV Related correspondence MCGRIDE, M F. LeBoeuf, Lamb, Leiby & MacRae 82/10/25 Docketing & Services Branch ip 15837 050 24X Fiche 50-289,82/10/25, 22(020036)
- 8210280360 Reply opposing UCB 821007 response to Board Notification 82-93 re Semiscale tests of feed & bleed & motion that ABLB direct NRC to provide documentation Feed & bleed capacity not essential to operation W/Certificate of Byc BAXTER: TA Metropolitan Edison Co BAXTER: TA Shaw, Pittman, Potts & Troubridge. 82/10/25 Atomic Safety and Licensing Noard Panel 9pp 15845 146 24X Fiche. 50-289, 82/10/25, 8210280360
- 82i0280265 Order allocating time for presentation of oral arguments on immediate effectiveness of ASLB 820727 & 81i214 partial initial decisions Issues to be discussed in detail listed CHILK, BJ Office of the Secretary of the Commission 82/10/27 2pp. 15837.312 24X Fiche 50-289;82/10/27,82i0380265

1 .

- 1

- 6210070440 Responds to 820825 itr transmitting constituent JB Hurst 820810 inquiry re restart Changes made as result of reopened proceedings will satisfy conterns DIRCHS.W J Office of the Elecutive Director for Operations 82/09/16 SPECTER.A Senate 4pp 15649 224 24X Fiche \$0-289,82/09/16,8210070440
- --8208010016 Requests response to constituent JR Hurst 820810 inquiries re restart proceedings SPECTER.A Sanate 82/09/25 NRC No Detailed Affiliation Given 6pp 15649 228 24X Fichs 50-289, 62/09/16, 8210070440
- 8210210501 Responds to constituent J Doroshou 820820 ltr re ASLD partial initial decision on cheating TMI Alert filed exceptions to decision & presented views on restart to Commission DIRCKS.W J Office of the Erecute Director for Operations 82/09/27 SPECTER.A Senate 9pp 15782 266 24X Fishe 50-289, 82/09/29, 8210210506
- 8210250015 Responds to constituent J Doroshou 820820 ltr re ASLB 820727 partial initial decision Commission is now deciding restart issues DIRCKS, M J Office of the Elecutive Director for Operations 82/09/29 PROXMIRE, M Senate 7pp 15808 128 24X Fiche 50-289, 82/09/29, 8210250015
- 8210280236 Opines that questions re operator exam cheating must be thoroughly investigated BRADFORD. L. Three Hile Island Alert 82/10/25 PALLADINO.N. J. OILINSKY.V. AHEARNE.J.F. Commissioners 2pp 15837-062 24X Fiche 50-289.82/10/25.8210280236

J Insurance & indemnity information

- R210150147 Forwards Endorsements 53 & 54 to MAELU Policy MF-73 & Endorsements 61 & 62 to NELIA Policy NF-220 GERETY. H F General Public Utilities GPU Bervice Corp 82/10/07 SALTZMAND Antitrust & Economic analysis Branch (Utility Finance) 5pp 1567/359 24X Fiche 50-289.82/10/07.8210150147
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8210090015 Addl response to FOTA request for 17 categories of info ro nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOTA Exemption 5) FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24% Fiche 50-000.82/07/12,9210080015
- --B2100B0051 Forwards General Public Utils 820407 News Release 45-82 discussing suspected cause of RM-1 steam generator tube degradation problem & proposed repairs Repairs estimated to be completed by Uct 1982 MAURIR ACRE Advisory Committee on Reactor Safeguards 62/04/20 MCELLER, D.W. ACRE Advisory Committee on Reactor Safeguards 82100B0015
- #210270410 Summary of ACRS Subtommittee on Metal Components #20607 meeting in Palo Alto.CA te status of Steam Generator owners group program & Thi-; steem generator problems & mods

 * ACRS Advisory Committee on Reactor Safeguards #2/09/11

 ACRS Advisory Committee on Reactor Safeguards #2/09/12

 244 Fiche 50-289,82/08/11,8210270410

12 at an income to be appropriately

license stage documents & correspondence

k safety evaluation re moderad to inadvertent
'oss of
mentation power
MICHELSON,C Director's
B1/9704.B210080024

ories of documents re-

12/06/28 UDELL.R.A

ng re reactor water lavel tr to util equirements for

ICHELBON. C Director's 1,82/06/28,8210010008

- --BiggiBO478 Forwards safety evaluation re mod to correct inagviring opening of atmospheric dump valves on DMR plants during less of instrument control sys non-nuclear instrumentation pages of the pag
- 8210080015 Addl response to FOIA request for 19 categories of irfs of nuclear reactor events & safety problems Forwards documents its App B completely withheld tree FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 82/07/12 UTite.R&Critical Mass Energy Project 9pp 15665-027 24X
 Fiche 50-000.82/07/12.8210080015
- --B20420043B Forwards std order for DDE work "Evaluation of THI-IF'.
 Cenerator Corrosion"
 VOLLMER, H. Division of Engineering. FIN D-2506 D2x34ff3
 FREMLING. O Energy. Dept of 2pp 15465,137 24x
 Fiche 50-000,82/07/12/8210080015
- --8204200442 Btd order for DDE work: "Evaluation of THI 1 Squar & Fr. Corrosion: " issued to DNML VOLLMER.R H Division of Engineering FIN 0:2506 2 83/Af: \$ 1p 13665 138 24% Fiche 50-000.82/07/12:8210000010
- --BD04290237 Discusses info available re unit steam generators Trip repts, status updates & notebooks of info on tube fabrication, identification & operating history encl W/d encl NGUAK-T H Assistant Director for Licensing 82/04/05 EISENHUT, D.O. Division of Licensing 2pp 15669-321 248 Fiche 50-000.82/07/12/8210080015
- --8205280533 Recommends formal review of facility steam gameratar corrosion problem. Detailed discussion of rationals for request and JOHNSTON, W V Assistant Director for Materials & Qualification Engineering 82/05/19 NOVAK, T Assistant Director for Case, Reactors 5pp 15665'146 24X Fichs. 50-000, 82/07/12, 82:656...
- --B206140329 Discusses facility steam generator tube review Meeting licenses to discuss details of procedures to be followed proposed NRC will develop complimentary independent program intended to verify repair process.

 NOVAK, T.M. Assistant Director for Operating Reactors D2/64.4
 EISENHUT, D.O. Division of Licensing 2pp 13665-157 241
 Fichs 50-000, B2/07/12, B2100B0015.
- --B206270666 Defines Div of Engineering reaponabilities & jaterin assure efficient & high quality review of licensee proposal for repairing THI atsem generator tubes.

 VOLLMER, R H Division of Engineering 82/06/14 ANSENSUM AT Assistant Director for Haterials & Qualifications ingineering KNIOHT. J P Assistant Director for Components & Birutiuse Engineering, 2pp 15666.152. 24X Fichs 50-000.82/07/18 B210080015.
- --8210080091 Forwards and order for DDE work, "Evaluation as tal-jp Generator:" issued to BNML Period of performance estantial to 821015 W/no addition to NRC VOLLHER, R. H. Division of Engineering, FIN 8-2505 \$2,724/4 FREMLING, A 0 Energy Dept. of. ip. 15666 150 34% Ficher 50-000, 82/07/12, 8210080015
- --8210080096 8td order for DDE work "Evaluation of TR1 1 % to a Congretor," issued to BNML.

 VOLLMER, R. H. Division of Engineering. FIN 8-2506 7 M2 24.1 ip 15666.101. 24K Fiche: 50-000.82/07/12.8210680015
- 8210030506 Recommends approval of deferral of implementation fettle MUREO-0737: Items II B 3: II F 1, 4: II F 1.5 & II F 1 d while 830331 or before restart. Approval of Item II B 2 2 thous 6s withheld until review completion.

 DIRCKS: W J. Office of the Executive Director for Operations 82/09/16 7pp 15624 033. 24X Fiche 50-289:88/09/16. Ext. Ret. ~ 4
- --8210050528 Informs that Commission will be briefed an ART recommendations re restart certification in late Sept 1990 prior to Commission decision on effectiveness of ARE initial decision.

 DIRCKB, W. J. Office of the Executive Director for Ogentalized 82/08/13, PALLADING, W. J. Commissioners, ip 15624 3-1 24 Fiches 50-289, 82/09/16,8210050506
- --B210050536 Informs that package or facility restart is restar is commission for approval of change in NUREQ-0737 fals: [8] become precipitation problem affects conformance w/regulations/deferral amounts to exemption BCINTOL Office of the Executive Legal Director \$2750.24 EIGENHUT, D. 0. Division of Licensing App. 15624 043 3aj Fiche: 50-289,82/09/16.8210050506

- --8207050040 Requests NUREO-0737 requirement deferrals be addressed as outlined in Commission 810325 order Paper discusses staff plans for certifying completion of restart requirements on ESCY-82-250 & describes approach to be taken on NUREO-0737 PALLADINO.N J Commissioners 82/07/27 DIRCKS.W J Office of the Executive Director for Decretions in Available at NRC nrc 15624 048 24X Fithe 50-289.82/09/16.8210050506
- G210210503 Provides Commission W/status of implementation of NUREO-0737 requirements on TMI-1 Recommends deferral of implementation dates for NUREO-0737. Items II B 3.II F 1 4.II F 1 5 & II F 1 6 until 63033i or before restart DRCKS.W J Office of the Executive Director for Operations SECV-82-384 82/09/16 14pp 15782 283 24X Fiche 50-289, 62/09/16.8210210503
- 9210050113 Forwards outline of Phase i ventilation separation program to meet short-term intent of ASLB 811214 order Program completed & sys turned over to plant operations Further details discussed in restart rept.Suppl 1.Part 2
 HUMILL.H D General Public Utilities ~ GPU Service Corp 82/09/29
 STOLZJ F Operating Reactors Branch 4 4pp 15603 257 24X
 Fische 50-289.82/09/29.8210050113
- 6210050196 Forwards table listing 96 emergency feedwater sys/instrument air valves as suppl to 820914 ltr Valves structurally & operationally adequate during SSE stresses & normal loads HUKILL.H D General Public Utilities GPU Service Corp 82/09/29 STOL2.J F Operating Reactors Branch 4 2pp 15609 292 24X Fiche 50-289.82/09/29.8210050196
- 8210070372 Advises that util has contracted w/Electronic Associates, Inc for basic principles trainer Contracted date of delivery is Dec 1982 HUKILL.H D General Public Utilities - OPU Service Corp 82/09/29 STCLZ.J F Operating Reactors Branch 4 Ip 15633 317 24X Fishe 50-289, 82/09/29, 8210070372
- 8210120043 Nots fication of 821013-14 meeting w/PNL, ORNL, Franklin Research Ctr. OH State & util in Bethesda MD to review status of steam generator recovery program JACOBS,R H Operating Reactors Branch 4 82/09/29 870LZ, J F Operating Reactors Branch 4 2pp 15689 205 24X Fiche 50-289, 82/09/29, 8210120043
- 6210130206 Forwards application to amend License DPR-50 consisting of Fech Spec Change Request iiB.deleting App B Tech Specs HUKILL.H D General Public Utilities - GPU Service Corp 82/09/30 STGLZ.J F Operating Reactors Branch 4 Ip 15674 127 24X Fiche 30-299.82/09/30.8210130206
- --8210130210 Application to amend License DPR-50 consisting of Tech Spec Charge Request 118, deleting App D Tech Specs Justification enci HUMILL, H D General Public Utilities - GPU Service Corp 62/09/30 3pp 15674 128 24X Fiche 50-289, 82/09/30, 8210130206
- 8210060342 Forwards "Assessment of Selected THI-1 Training Progrems,"
 Vol 1 Rept concludes that util has made significant progress
 in past 3 yrs to expand THI training capability & to improve
 quality of training programs
 ARNOLD, R C General Public Utilities GPU Service Corp 82/10/01,
 DENION, H R Office of Nuclear Resector Regulation, Director 1p
 19618 020 24X Fiche 50-289,82/10/01,8210060342
- --8210060348 "Assessment of Selected TH1-1 Training Programs," Vol 1 w Data Design Laboratories 82/09/10 301pp 15618 021 24X Fishe 50-289,82/10/01.8210060342
- 821008D043 Forwards status rept re procurement & installation of replica simulator.per 820827 mgt piping & instrumentation diagrams Second status rept will be provided in Oct 1783 HUXILL.H D General Public Utilities GPU Service Corp 82/10/04 STOL2.J F Operating Reactors Branch 4 3pp 15443 281 24X Ficha 50-289, 82/10/04,8210080043
- G21008030B Forwards first status rept re procurement & installation of replica simulator for TMI-liper requirements of Paragraph 583 (3) of 810827 mgt PID Next status rept will be provided in Oct 1983 HUMILL.H D General Public Utilities OPU Service Corp 82/10/04, STOL2.J F. Operating Reactors Branch 4 3pp 15638-044 24X Fiche 50-289, 82/10/04,8210080308
- 8210130248 Advises of dairy farm located approx i.i miles east of THI yielding dose commitment greater than six of seven present milk sampling stations Results of land census to be included in 830501 annual radiological environ operating rept HUXILL.H D General Public Utilities GPU Service Corp 82/10/04, HAYNES.R C Region 1, Office of Director ip 15676 008 24X Fichs 50-289, 82/10/04,8210130248

- 8210130548 Forwards Revision i to "TMI-1 Steam Generator Repair Safety Evaluation," submitted on 820820 as suppl to LER 81-13 Revisions of not affect previous conclusions Revision withheld (ref 10CFR2 790) HUKILL,H D General Public Utilities 9PU Service Corp. 82/10/05 EISENNUT.D Q Division of Licensing ip 15684 195 24X Fiche 50-289, 82/10/05,8210130548
- B210290162 Notification of date change for B21018-19 meetings w/util & consultants in BetheadarMD to discuss results of steam generator repair qualification programmeddy current testing program & RCB cleaning JACOBS:R H Operating Reactors Branch 4 82/10/05. BTOLZ, J F Operating Reactors Branch 4 92/10/05. BTOLZ, J F Fiche 50-289, 82/10/05, 8210270162
- 8210270342 Clarifies request for add1 info re TMI Item II B 3. "Post-Accident Sampling Sys"
 STOLZ, J F Operating Reactors Branch 4. 82/10/07 HUKILL, H D
 Ceneral Public Utilities GPU Service Corp Spp 15851 347. 24X
 Fiche 50-269, 82/10/07, 8210270342
- 8210220249 Staff requirements memo re 821006 briefing on status of certification of licensee compliance w/restart requirements CHILK: 9 J Office of the Secretary of the Commission 82/10/12 Office of the Secretary of the Commission 1p 15786 210 24% Fiche 50~269.82/10/12.8210220249
- 8210250092 Forwards operational GA plan for facilities FIEDLER.P B General Public Utilities - GPU Service Corp 82/10/12 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 15792 265 24X Fiche 50-000.82/10/12.8210250092
- --8210250097 Operational GA plan for facilities KAYANAS.N C , LONO,R L , HUKILL.H D Oeneral Public Utilities -GPU Bervice Corp 1000-PLN-7200 01 R00 82/09/01 150pp 15792 267 24% Fiche 50-000, 82/10/12.8210250092
- 8210270015 Forwards documents to be placed in PDR. Documents respond to NRDC & Sierra Club 820917 third request for production of documents & Sierra Club 27th set of interrogatories.
 SHEENEY,M F Office of the Executive Legal Director 82/10/22 SCOTT.8 Document Management Branch 4pp. 15818 092 24X Fiche 50-000. 82/10/22.0270015
- --8210270020 "Greater Commitment Needed to Solve Continuing Problems At THI." rept to Congress

 * General Accounting Office, EMD-81-106 81/08/26 122pp
 13818-076 24X Fiche-80-000,82/10/22-8210270015
- B210290204 Forwards summary status rept for items needing NRC certification prior to restart, per 770807 order & notice of hearing. Date of equivalent timing for verification will be provided in future status summaries

 ARNOLD, R C General Public Utilities -- GPU Service Corp 82/10/25
 DENTON, H R Office of Nuclear Reactor Regulation. Director 3pg 15853 293 24X Fichs 50-289, 82/10/25,8210270204
- Q Inspection reports. IE Bulietins & correspondence
- 82:0080015 Add1 response to FOIA request for 19 categories of info re

- --8210150232 IE Insp Rept 50-289/82-13 on 920802-05,31 & 0901-03
 No noncompliance noted Major areas inspected actions on previous insp findings, reactor bidg flood level limitations, plant shielding design review & restart mode-implementation HAVERMAHP.D. EAPEN.P., FABANO.A. Division of Project & Resident Programs 82/10/01 20pp 15705-214 24X Fiche 50-289,82/10/01, 8210150221
- 6210150202 Clarifies position re Action 4 of IE Bulletin 77-21, "Temp Effects on Level Measurements" Inclusion of tables, turves or correction factors in smergency procedures will unnecessarily complicate procedures HUKILLIH D Oeneral Public Utilities QPU Bervice Corp #2/10/04 HAYNES.R.C Region 1, Office of Director 2pp 15701 334, 24% Fichs 50-289, 82/10/04.8210150202
- 8210150076 Notifies that 820929 1E Insp Rept 50-289/82-14 was submitted w/erroneous loss Rept Number 82-12 STAROSTECKI.R Division of Project & Resident Programs 82/10/05 HUKILL.H D Openral Public Utilities GPU Service Corp 18696 339 24% Fiche, 50-289, 82/10/05, 8210150076
- --8210150083 Forwards IE Insp Rept 50-289/82-14 on 820807-0907 No noncompliance noted. STAROSTECKI.R Bivision of Project & Resident Programs 82/09/29 HUKILL.H D. General Public Utilities - GPU Service Corp 2pp 18696 340 24X Fiche:50-289,82/10/05.8210150076
- ~-8210150091 IE insp Rept 50-289/82-14 on 820807-0907 No noncompliance noted Hajor areas inspected plant operation, including steam generator repairs & restart mods
 CONTE.R. YOUNG.F. FASAND.A Division of Project & Resident Programs 82/09/21 opp 15696 342 24X Fichs 50-289.82/10/05, 8210150076
- B210210052 Forwards IE Insp Rept 50-269/82-16 on B20907-10 No noncompliance noted MARTIN-T T Division of Engineering & Technical Programs B2/10/05 HUKLLL-K D General Public Utilities - QPU Service Corp 15762 018 24% Fiche:50-289,B2/10/05;8210210052
- --8210210056 IE Insp Rept 50-289/82-16 on 820907-10 No noncompliance noted Major areas inspected licenses action re TMI Item I C 7 on feedback of operating experience k Item I C 6 on verification of teeting k maint activities MEYER.0 W : CAPHTON.D.L Division of Engineering & Technical Programs 82/09/29 App 15762 020 24X Fiche: 50-289,82/10/05,8210210032
- 8208190233 IE Info Notice 80-35. Suppl 1, "Leaking & Dislodged 1-125 Implant Beeds," Svc list encl. COBS.L f Division of Fuel Facilities, Materials & Bafeguards 92/10/06 Consolidated Edison Co of New York 66pp 15761, 250. 244 Fichs 50-000.82/10/06.8208190233
- 9209170239 IE Bulletin 92-03, "Btrass Corrosion Crecking in Thick-Walls Large-Diameter, Stainless Bteel, Recirculation Sys Piping at BWR Plants "Syt list end! DEYOUNG, R C Director's Office of Inspection and Enforcament B2710714. Consolidated Edison Co of New York. 113pp 15810.125 24% Fichs 50-000, 8270714, 8208190239
- 821029006B Forwards IE Insp Rept 50-289/82-18 on 820920-24 No noncompliance noted.

 MARTIN: T T. Division of Engineering & Technical Programs. 82/10/15

 #UNILL: H D. General Public Utilities QPU Service Corp 15853, 342. 24% Fiche 50-289, 82/10/15, 821029006B
- --8210290072 IE Insp Rept 50-287/82-18 on 820920-24 No noncompliance noted Major areas (napacted licenses action on previous insp items, procedures & representative records & interviews Upersonnel RHAUS.E. NAPUDA, Q. CAPHTON, D.L. Bivision of Engineering & Technical Programs 82/10/08 10pp 15853 344 24% Fiche 50-289,82/10/15,8210290068

R Periodic operating reports & related correspondence

82:0070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines. App A documents provided in R Udall FOIA Request 81-313. Forwards documents listed in App B FELTON, J M. Bivision of Rules and Records 82/08/10, LONG, D J, Hinthrop, Stimson, Putnam & Roberts. 9pp 15645:063 24X Fichs: 50-000, 82/08/10, 8210070007

- --8210070135 Sevil rept input re Ginna 820125 steam generator till rupture event NRC 16th monthly status rept to Congress re TMC-1 restart encl 4 NRC - No Detelled Affiliation Given 82/03/11 3pp 15645 128 24K Fiche 50-000,82/08/10,8210070007
- 8210260499 Forwards Revision 1 to "Efficient & Waste Disposal Semiannual Rept. Jan-June 1982" Revision reflects change in Fe-55 batch mode for second quarter HUKILL.H D Oeneral Public Utilities GPU Service Corp 62/19 HAYKES R C Region I. Office of Director is 18804-136 24; Fiche 50-289, 82/10/15, 8210260499
- --B210260505 Revision i to "Effluent & Waste Disposal Semiannus) t_{r.}
 Jan-June 1782 "

 * General Public Utilities GPU Service Corp B2/10/15 []
 15804 137 24X Fiche \$0-289,82/10/15.8210226049
- 5 Reportable occurrences, LERs & related correspondence
- B210010008 Responds to FDIA request for 19 categories of documents nuclear reactor events & safety problems Forwards documents listed in App 4.

 FELTON, J H Division of Rules and Records 82/06/20 UMELLA, Chifical Mass Energy Project 15pp 15727 005 24X

 Fiche 50-000.82/06/28.8210010008
- --BlifiBOOO! Recommends comprehensive assessment of plant operations to determine specific predetermined time related sequences of occurrence to emergency buses ERP should be revised re design features

 ASH6.F Director's Office. B1/10/16 MICHELSON, C Direct. Office 4pg 15731 04? 24X Fiche 50-000.82/06/20.82/04/20.
- 8210130515 Forwards LER 82-013/03L-0 HUKILL-H D General Public Utilities - GPU Service Corp 82.5 HAYMES R C Rejon 1, 0fetce of Director ip 15682 278 24 Fiche 50-289, 82/09/29,8210130315
- --8210130526 LER 82-013/03L-0 on 820830, plant effluent radiative (RM-L-7) had no sample flow Caused by open breaker on sample pump BR-F-4 Breaker closed Operator surveillance program continued to ensure proper flow STEPHENSON, C J. General Public Utilities OPU Bervice Cosp. 82/09/29 Region 1, Office of Director 2pp 13202 277 Fiche, 50-289, 82/09/29, 8210130315
- B210070245 PND-TM1-B2-020 on B21005, game poacher apprehended of property & turned over to state police & Oame Commission No vital areas threatened Becurity increased Licanses will issue press release
 HIEBE, J. BELLAMY, R. Region 1, Office of Director B2/10/6, 15644 306 24% Fiche 50-289, 82/10/06,8210070265
- B210260483 PNO-1-82-047 on 821022, kinetic expansion conductifications of tubes in B once-through steam generator Espansion involves controlled defonation within tube Bone media attention espected CONTE: R. KELMIO, R. BTARDETECKI, R. Region 1. Diffice of Dise 82/10/22 pp. 15806-232 24X Fiche 50-289, 82/10/22, 821026
- T Hearing trenscripts on non-antitrust matters
- 8210130075 Porwards Commission determination statement withhelf transcript of 820910 restert proceeding CHILK'S J Office of the Secretary of the Commission. E2301 Public Document Branch 1p 15696 250. 24X Fiche 50-268.86
- ~-8210130087 Commission determination withholding transcript commission 820910 discussion of contested issues in restriction of the Commission BP CHILK, B J Office of the Secretary of the Commission BP is 15676: 251 24% Fiche 50-289, 82/09/28, 8210136075
- 8210270168 Transcript of 821006 public meeting or status of A certification on licenses compliance w/rastart requirement on THI-1 in Washington.DC.Pp 1-34 Commissioners 82/10/06 34pp 15835 276 24x Fiche. 50-289, 82/10/06, 8210270188,
- 821021042B Forwards transcript of Commission 821014 masting? vessel water level indicator program Comments should be submitted by 821101 CHILKI B J. Office of the Secretary of the Commission 621 Office of the Executive Legal Director. Ip. 15762 272 2 Fiche. 50-289. 82/10/15.8210210428

DOCKETED ITEMS

- E210210434 Transcript of 82i014 public meeting in Washington, Dc Pp I-91 Viewgraphs re request for NRC approval of recommendations for implementation of NUREG-0737, Item 1I F 2 encl Commissioners 82/10/14 91pp 15762 273 24X Fiche 50-269,82/10/15 8210210428
- 1 TIND WHITE SO-293 PILGRIM NUCLEAR POWER STATION, UNIT 1
- P Operating license stage documents & correspondence
- E_ICOSCO15 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & sarety problems Forwards documents insted in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON. J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15565 027 24X Fiche 50-000 82/07/12.8210080015
 - 2203290028 Forwards "Engineering Evaluation of Sait Svc Mater Sys Finw Blockage at Pilgrim Nuclear Power Station by Blue Mussels (Mythius Edilus) "Further recommendations re sys fouling by aquatic organisms not needed MMBROLE V Birector's Office 82/03/18 MICHELSON, C Director's Office 2pp 15666-073 24% Fiche 50-000,82/07/12,8210080015
- --8203290031 Engineering Evaluation or Sait Syc Water Sys Flow Blockage at Pilgrim Nuclear Power Station by Blue Mussels (Mytifus Editus) "
 IMBRO. E (**) Director's Office 82/03/31 14pp 15666 075 24X
 Fiche 50-000.82/07/12.8210880015
- --8205130:114 Advises that engineering evaluation of saltwater sys flow blockage by blue mussels indicates surveillance requirements in Tech Specs are not sufficient to demonstrate sys operability "11CHELSON.C Director's Office 82/05/06 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 15666-070 24X Fiche 50-000,82/07/12.8210080015
- PairOb00BO Application for Proposed Change 82-11 to License DPR-35, changing Tech Specs 3.7 D.1 & 3.7 D.2 to permit operation in A between reactor modes when isolation valve is inoperable
 MARRIGITON W.D. Boston Edison Co. 82/09/30 VASBALLO, D.B. Uperabing Reactors Branch 2. 2pp. 15415-044 24X
 Fiche 50-273.82/09/30.8210060080
- --0210060085 Proposed changes to Tech Specs 3 7 D 1 & 3 7 D 2 allowing aperation in 4 between reactor mode when isolation valve is imagerable 8 satisfying conditions for primary containment integrity

 Biston Edison Co 82/09/30 ip 15615 046 24X
 Fiche 50-293.82/09/30.8210060080
- 6210150444 Requests extension to submit Mark I containment program plant-unique analysis Delay due to need for extensive QA verification not previously identified by Teledyne Corp MORISI.A V Boston Edison Co 82/10/03 VASSALLO, D 0 Operating Reactors Branch 2 Ip 15705 005 24X Fiche 50-293,82/10/08,8210150444
- 6210220015 Concurs w/LLL evaluation of util 820617 submittal redegraded protection for Class IE power sys Mods, procedures, operating restrictions & voltage schedules will ensure that Class IE equipment will not be exposed to degraded voltage vASSALLO.D B Operating Reactors Branch 2 82/10/08 MDRISI, A V Spaton Edison Co 2pp 15786 226 24X Fiche 50-293,82/10/08,82:0220015
- --B2t0220017 Safety evaluation supporting licensee conclusion that addition protection not required for unit auxiliary transformer power source to Class IE buses
 PREVATTE.R Operating Reactors Branch 2 82/10/08 4pp
 15786 228 24X Fiche 50-293, 82/10/08, 8210220015
- --B209133461 "Technical Evaluation Rept (Revision i) on Proposed Design Mods 5 Tech Spec Changes on Orid Voltage Degradation for Pilgrim Nurlpar Power Station, Unit 1"

 SELAN-J C Lawrence Livernore Laboratory FIN A-0250 UCID-18689 R01 B2/08/20 NRC No Detailed Affiliation given 13pp 13786 232 24% Fiche 50-293, 82/10/08.8210220015
- 8210250085 Forwards filing fee for 820930 proposed Tech Spec Change 82-11 MCRIS[, A V Boston Edison Co 82/10/15 VASSALLO,D B Operating Reactor's Branch 2 lp 15787 075 24% Fiche 50-293,82/10/15, 8210250085

- O Inspection reports. IE Bulletins & correspondence
- 8204160212 Responds to MRC 820118 natice of violation & proposed imposition of civil penalties Corrective actions containment atmospheric control sys made fully operable on 810605 & procedure re performance of analyses being reviewed STASZESKY, FM Boston Edison Co. 82/03/19 DEYGUNG, R C. Director's Office. Office of Inspection and Enforcement lipp 15611 275 24X Fichs 50-293, 82/03/19.8204160212
- --8204160222 Forwards performance improvement program in response to NRC 820118 order modifying license, effective immediately Program debails 18 to 24-month period that will result in demonstrated effective regulatory performance HARRINGTON H D Boston Edison Co 82/03/18 HAYNES, R C Region 1, Office of Director 3pp 15611 284 24X Fiche 50-293, 82/03/19.8204160212
- --8204160225 "Performance Improvement Plan"

 * Boston Edison Co 82/03/08 [6pp 15611 267 24X Fiche 50-293, 82/03/19, 8204160212
- 8210080015 Add1 response to FQIA request for 17 categories of info re nuclear reactor events & safety problems Forwards documents issted in App A Documents in App B completely withheld (ref FQIA Exemption 5)
 FELTON, J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24%
 Fiche 50-000, 82/07/12, 8210080015
- --8210080145 Systematic assessment of licensee performance notes re facility evaluation for Aug-Dec 1980 4 NRC - No Detailed Affiliation Oiven 80/12/31 10pp 15668-025 24% Fiche 50-000, 82/07/12,8210030015
- 8210070277 Forwards IE Insp Rept 50-293/82-23 on 820817-20 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/09/22 HARRINGTON.W D Boston Edison Co 2pp 15634 162 24X Fiche 50-293,82/09/22,8210070277
- --8210070283 IE Insp Rept 50-293/82-23 on 820817-20 No noncompliance noted Major areas inspected licensee action on previous insp finding, followup on IE Gulletin 81-01.surveillance of mechanical snubbers & Cycle & post-refueling startup tests PETRONE.C D. BETTENHAUSEN.L Region 1. Office of Director 82/09/09 7pp 15634 164 24X Fiche 50-293/82/09/22,8210070277
- 6210010372 Confirms licensee actions taken in response to Revision I of performance improvement program discussed during 920824 mgt meeting Summary of areas needing clarification or corrections encl HAYNES,R C Region i. Office of Director 82/07/27 HARRINOTON,W D Boston Edison Co 3pp 15573 087 24X Fiche 50-293, 82/09/27, 8210010372
- R210150001 Forwards IE Insp Rept 50-293/82-22 on 820802-0906 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 82/09/28 MARRINOTUN, W P Boston Edison Co 2pp 15696 285 24X Fiche 50-293,82/09/28,8210150001
- --8210150003 Notice of violation from insp on 820802-0706 * Division of Project & Resident Programs 82/07/28 2pp 15676 287 24X Fiche 50-273,82/07/28,8210150001
- --8210150017 IE insp Rept 50-293/82-22 on 820802-0906 Noncompliance noted failure to notify NRC within 1-h of reactor scram & to perform leak rate test required by limiting conditions for operation for inoperable alarm sys JOHNSON, J. EICHENHOLZ, H., ELSABBER, T. Division of Project & Resident Programs 62/09/22 20pp 15696 287 24X Fiche 50-293,82/09/28,8210150001
- 8210050166 Forwards response to request for further info re IE Bulletin 80-11 "Masonry Wall Design " Issues discussed include shear stress for safety-related shear walls, block pullouts, use of Branson formula, masonry wall cracks & allowable tension MORISI.A V Boston Edison Co 82/09/29 VASSALLO, D B Operating Reactors Branch 2 8pp 15605 114. 24% Fiche 50-293, 82/09/29, 8210050166
- 8210060150 Ack receipt of 820806 & 27 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/82-12 STAROSTECKI,R Division of Project & Resident Programs, 82/09/30 HARRINOTON M D. Boston Edison Co ip 15615 081 24X Fiche 50-293,82/09/30,8210060150

- --8210060164 Responds to NRC 820707 ltr re-violations noted in IE Insp. Rept 50-293/82-12 Corrective actions draft training plan written, interin administrative controls re-Tech Specs implemented & operator requalification program revised HARRINGTON, 40 Diston Edison Co. 82/08/27 STARGSTECKI.R Division of Project & Resident Programs 2pp i5615-082 24X Fiche 50-293,82/09/30.8210060150
- --82(0050180 Responds to NRC 820707 ltm re violations noted in IE lusp Rept 50-293/82-12 Corrective actions add1 operator training implemented & reactor water level divergence issue incorporated into operator requalification program HARRINGTON, H D Boston Edison Co 82/08/06 STAROSTECKI, R Division of Project & Resident Programs App 15615 084 24% Fiche 50-293,82/09/30.8210060150
- 821022052i Notification of 821005 meeting w/wti) in King of Prussia.PA to discuss licensee response to NRC order EL6ASER.T Division of Project & Resident Programs 82/09/20 DIRCKS.W J Office of the Executive Director for Operations DEYOUNG.R C Director's Office. Office of Inspection and Enforcement MURRAY.JP Office of the Executive Legal Director ip 15786 076 24X Fiche 50-273.82/09/30.8210220321
- 8208190233 IE Info Notice 80-35, Suppl i. "Leaking & Dislodged 1-125 Implant Seeds " Svc list end! COBB.L | Division of Fuel Facilities. Materials & Gafeguards 82/10/05 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.68/10/06.8208170233
- 8210190721 Completes response to 1E Bulletin 30-06, "ESF Reset Controls " Review of actions taken in compliance w/bulletin revealed deficiencies in Temporary Procedure 81-6A re valve testing New best procedures developed MCRIBI.A V Boston Edison Co 82/10/07 HAYNES,R C Region 1, Office of Director 2pp 15736 310 24X Fishe 50-293,82/10/07,82/10/90721
- 8210290275 Parwards IE Insp Rept 50-293/82-25 on 820914-17 No noncompliance noted MARTIN: T T Division of Engineering & Technical Programs 82/10/13 HARRINOTON N D Boston Edison Co 2pp 15854 059 24X Fiche 50-293, 82/10/13, 8210290275
- --8210290280 1E Insp Rept 50-293/82-25 on 820914-17 No honocompliance noted Hajor areas inspected inservice insp program & drewing control, licenses actson on previous insp findings & licenses response to IE builetins
 KCBRCARTY.R A . BURR.J P Division of Engineering & Technical Programs 82/10/05 App 15854 Odi 24x Fiche 50-293,82/10/13,8210290275
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Lerge-Diameter. Stainless Steel, Recirculation Sys Piging at BMR Plants" Svc list enci DEYOUNG.R C Director's Office. Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 19810 125 24% Fichs 50-000. 82/10/14.8208190238
- 8 Reportable occurrences, LERs & related correspondence
- 8210:20155 Informs of adequacy of Graft IE info notice, "Potential Failure of BHR Bactup Manual Scram Capability" injtiated by NRR, IE & GE subsequent to 800829 LER 80-039/017-0 CHIRAMALM Director's Office 80/12/18 Director's Office lp 15692.179 24X Fiche 50-293,80/12/18,8210120155
- --8210120164 Forwards draft IE info notice: "Potential Failure of DWR Backup Manuai Scram Capability." per 801208 meeting agreement LAINAS, G C Assistant Director for Safety Assessment 80/12/15 JCRDAN.E.L Division of Resident & Regional Reactor Inspection 4pp 15692 160 24% Fiche 50-293, 80/12/18, 8210120155
- 8210040100 Forwards LER 82-037/03L-0 MATHIS, C J Boston Edivon Co 82/09/22 HAYNES, R C Region 1, Office of Director 1p 15580 354 24x Fiche 50-293, 82/09/22, 8210040100
- --8210040105 LER 82-037/03L-0 pn 820823, three monthly functional surveillances performed in slight excess of allowable 25% tolerance Caused by personnal surveysight Serior level compilance review implemented Proposed test aids planned. HHITNEY, 0 0. Boston Edison Co. 82/09/22 Region 1, Office of Director 2pp 15380:355 24% Fichs. 50-273, 82/09/22, 6210040100
- 8210060023 Forwards LER 82-034/03L-0
 MATHIB.C J. Boston Editon Co., 82/09/24 MAYNES, R C Region I
 Diffice of Director 19 156/5 072 24X Fiche 30-293,82/09/24,

- --8210060030 LER 82-034/031-0 on 820826 both HPCI area smale detector sign taken out of six for corrective maint Maint required due to relative from steam leak condensing inside detector, causing false smoke indication betectors replaced 2 located LHITMEY.O G Doston Edison Co. 82/09/24 Region 1, 0ffile cd Director ip 15615 0/3 24X Fiche 50-293,82/09/24.82100/nim
- --B210070247 LER 82-036/03L 0 on 820903.during 75% power.main steak Li. flow indicator B went to 0 % three other steam flows increased Cause suspected to be valve stem separation flow poppet Yalve repair plan will be implemented after outage Wilf TMEY. 6 G Baston Edison Co 82/09/29 Region L. Office to Director ip 15637 143 24% Fiche 50-293.82/09/29.82000 Mc.4*
- 8210070340 Forwards LER 82-035/03L-0

 HATHIS.C J Boston Edison Co 82/07/29 HAYNES.R C Regium 3

 Office of Director 1p 15634 066 24% Fiche 50-291 8.709/2/.
- --0210070346 LER 02-035/03L-0 np 020030, during HPC1 surveillant (bit gland seal condenser gasket failed Caused by overpressure of gasket during startup Oasket mett changed to rubber bounds asbestos Unit tested & returned to sve thITNEY, 0 0 Soston Edison Co. 02/09/29 (Region), (Fig. e. p. Director ip 15634 067 24% Fiche 50-293, 02/09/29 (Refur).)
- 8210130472 Forwards updated LER 82-003/79X-1
 MATHIS: C J Boston Edison Co 82/09/30 HAYNES: R C Region 1.
 Diffice of Director Ip 19682 132 P4X Fiche 50 -00 1. (8//09/33)
 03/04/30472
- --8210130479 Updated LER 82-002/99X-1 on 820901.util organisation revised Tech Specs being reviewed for submitted to MAL Updated reorganization chart encl HAITNEY,0 0 Goston Edison Co. 82/09/20 Region J. 8881c. 1 Director Spp 15682 133 24X Fiche 50-293.82/09/30 82801 MARS.
- 8210190235 Forwards updated LER 82-0.14/03X-1 HATHIB,C J Boston Edison Co 82/10/01 HAYNES,R C Region 1 Dffice of Director 1p 15737 239 24K Fiche 50-491.11/10/01 E210190235
- --B210170237 Updated LER 82-034/034-1 on 8208Pb. buth HP(1 area e-y), defector sys made inoperable Caused by need for corrective maint due to false smoke indication resulting from condensation inside detectors Detectors removed & replaced wittney, 6 G Boston Edison Co 82/10/01 Region 1, 01ft.ce 14 Director 19 15/37 240 24% Ficho 50-273.82/10/01.8/101.
- E210280129 Forwards LER 82-039/03L-0

 HATHIS.C J Boston Edison Co 82/10/20 HAYNES, R C 8999en CO 06fice of Director 1p 15837 117 24x Ficho 50-291 (82/10/2-78210280129
- --8210280131 LER 82-039/03L-0 on 820720, timing tests of thres react water cleanup isolation valves 1201-2.-5 & -80 not completed within allowed time Caused by operational constraints requiring testing at reduced power WHITMEY, 0 O Boston Edison Co 82/10/20 Region 3. (() 11:15 & Director 2pp 15837 118 24X Fiche 50-293, 6()/10/20, 6()()(2):24
- 9210280146 Forwards LER 82-040/03L-0 MATH/8.C J Boston Edison Co 82/10/20 HAYNES.R C Papies I Office of Director ip 15837 225 24% Fiche 50-293.82/10/a* 9210280146
- --8210280150 LER 82-040/03L-0 on 820920, found reactor protection is initiation function of turbine stop valve completed; day late Caused by decision to defer test due to MBIV D into isolation Tracking sys implemented to prevent recurrents MHITMEY, 0 Q Boston Edison Ca 82/10/20 Region; Office Director 1p 15837 226 24% Fiche 50-293, 82/10/20.6200204
- DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8209290125 Releases public version of revised generating status emergency plan corporate command ctr emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/09/16 Dissert Hangement Branch, ip 15564 122 24X Fiche 50-000.82/09/11 E209290125

- --8209270187 Forwards public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EOF-3. "Environ/Emergency Coordinator " Receipt form enci PAJDMEKIJ E Commonwealth Edison Co 82/07/01 DENTON,H R NRC No Detailed Affiliation Quen 1p 15844 123 24% Fiche 50-000,82/09/16.8209270125
- --8209270225 Public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EDF-3. "Environ/Emergency Coordinator"

 PAJOHSKIJ E Commonwealth Edison Co. 82/08/3i iipp 15544 124 24X Fiche 50-000, 82/09/16.8209270125
- E210080029 Releases public version of revision to emergency plan implementing procedure FELTON. J M Division of Rules and Records 82/09/22 Document Management Branch 1p 15669 307 24X Fiche 50-295,82/09/22,8210080029
- --8210080030 Forwards public version of Revision 3 to Emergency Plan Implementing Procedure EPIP 550-3, "Radiological Supplies for Medical Emergencies" Receipt form encl PLIML, G. Commonwealth Edison Co. 82/09/07 DENTON, H.R. NRC No Detailed Affiliation Given ip 15669 308 24X Fiche 50-275,82/09/22,8210080029
- B210050207 Forwards revised exemption requests from provisions of 10CFR50.App R.Section iii 0.2 re post-fire shutdown capability.per 820917 telcon
 LENTINE.F 0 Commonwealth Edison Co 82/10/01 DENTON.H R Office of Nuclear Reactor Regulation. Director 30pp 156/11-086 24X Fiche 50-295.82/10/01.8210050207
- 82:0130376 Advises that installation of offsite dose calculation sysprogram fully operational tracking model & operational A-model will be delayed until 82:231 to complete prime computer installation SMARTZ-E D Commonwealth Edison Co 82/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15682 098, 24X Fiche 50-000, 82/10/06, 8210130376
- 9210290047 Releases public version of revisions to Quad Cities, Zion & Bresden emergency plan annexes & revised generating station emergency plan telephone directory FELTON.J M Division of Rules and Records 82/10/08 Document Management Branch ip 15977 313 24% Fiche 50-000, 82/10/08, 82/10290047
- --8210270060 Forwards public version of Revision 3 to Quad Cities & Zinn emergency plan annexes, Revision 2 to Dresden emergency plan annexes, Revision 0 to Byron emergency plan annex & revised generating station emergency plan telephone directory HOURE, R D Commonwealth Edison Co 82/07/30 DENTON, H R NRC No Detailed Affiliation Given 5pp 15977 314 24X Fiche 50-000,82/10/08.8210290047
- ---8210290077 Public version of Revision 3 to Quad Cities & Zion emergency plan annexes, Revision 2 to Dresden emergency plan annex & Revision 0 to Byron emergency plan annex & Commonwealth Edison Co 82/06/30 325pp 15877 319. 24X Fiche 50-000,82/10/08,8210290047
- --8210290088 Public version of revised generating station emergency plan telephone directory GALLE.D P Commonwealth Edison Co 82/08/12 43pp 15878 218 24X Fiche 30-000, 82/10/08,8210290047
- B210280117 Releases public version of revised emergency pian implementing procedure. PELTON.J H Division of Rules and Records 82/10/12 Document Management Branch ip 18862 241 24X Fiche 50~275, 82/10/12, 8210280117
- --8210280120 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 150-1, "Btores Director" Receipt form enci. PLIML 0 Commonwealth Edison Co 82/09/17. DENTON, H, NRC - No Detailed Affiliation Given ip 15862 242 24X Fiche 50-275,82/10/12,821028017
- --8210280126 Public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 150-1, "Btores Director," Procedure change request form encl Commonwealth Edison Co 82/09/16 5pp 15862 243 24X Fichs. 50-275, 82/10/12, 8210280117

- 8210280419 Releases public version of revised emergency plan implementing procedure FELTION, J H Division of Rules and Records 82/10/12 Document Management Branch 1p 15860 001 24X Fiche 50-295,82/10/12.8210280419
- --8210280424 Forwards public version of Revision 5 to Emergency Plan Implementing Procedure 110-i, "Station Director "Procedure change request & receipt forms encl PLIML,0 Commonwealth Edison Co 82/09/17 DENTON,H R NRC — No Detailed Affiliation Olven 2pp 19860 002 24X Fiche 50-295,82/10/12,8210280419
- --8210280427 Public varsion of Revision 5 to Emergency Plan Implementing Procedure 110-t, "Station Director" Revised index encl * Commonwealth Edison Co 82/09/16 Spp 15860 004. 24X Fiche 50-295, 82/10/12, 8210280419
- B210280442 Releases public version of revised emergency plan implementing procedure FELTON. J M Division of Rules and Records B2/10/12 Document Management Branch ip 15859 OO: 24X Fiche 50-275,82/10/12,8210280442
- --8210280445 Forwards public version of Revision 4 to Emergency Plan Implementing Procedure EPIP 530-2, "Environ Emergency Wit & Emergency Operations Facility Radiological Equipment" Receipt form encl
 PLTML,0 Commonwealth Edison Co 82/09/10 DENTON,H R NRC No Detailed Affiliation Qiven ip 15859 002 24X
 Ficha 50-295,82/10/12,9210280442
- --8210280447 Public version of Revision 4 to Emergency Plan Implementing Procedure EPIP 550-2, "Environ Emergency Kit & Emergency Operations Facility Radiological Equipment "Procedure change request form encl & Commonwealth Edison Co 82/09/09 App 15859 003 24X Fichs 50-295,82/10/12,8210280442
- B21022033B Provides info re organization & performance of depts responsible for radiation protection activities, per B20702 commitment Training coordinator assigned in Apr 1782 to improve health physics training programs
 TRAMM.T R Commonwealth Edison Co 82/10/14 DENTON.H R Dffice of Nuclear Reactor Regulation, Director 7pp 15776 287, 24% Fiche 50-000, 82/10/14,821022035B
- 92102B0405 Notification of 82102B-29 meetings w/util & INL in Bethesda, MD to discuss & resolve questions on proposed exemption to App R WIOQINTON, D Operating Reactors Branch i 92/10/22, VARQA, B. A. Operating Reactors Branch i. 2pp i5859, 327 24X Fiche 50-295, 82/10/22, 82102B0405
- H General correspondence
- 8210210235 Comments on facility operation NRC should deny util permission to use high burnup nuclear fuel Evidence supporting continued operation of facility should be provided to public GUIGO: C Pollution & Environmental Problems, Inc 82/10/11, Director's Office, Office of Inspection and Enforcement 5pp 13746 259. 24X Fiche 50-295,82/10/11,8210210235
- J Insurance & indemnity information
- B210060283 Forwards Endorsements 60 % 51 to NELIA Policy NF-201 & MAELU Policy MF-64, respectively OSTER.J Commonwealth Edison Co 82/10/01 BALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp 15621,072, 24X Fiche 50-293, B2/10/01, B210060283
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8210270408 Comments on probabilistic risk assessment per 811221 matl. General methods & principles employed in analysis of possible earthquake shaking & site appear to apply modern state of art techniques.

 TRIFUNAC: M D Bouthern California, Univ. of, TRIFUNAC: M.D. ACRE Advisory Committee on Reactor Safeguards 82/02/23 GRIESMEYER: J M. ACRS Advisory Committee on Reactor Safeguards 3pp. 15832:353. 24X Fiche. 50-295, 82/02/23. 8210270408
- P Operating license stage documents & correspondence
- G007150303 Notifies that review will be conducted of Offshore Power Sys short-term risk studies using various resources, in response to B00605 request Evaluation will be submitted by B00922 MATTSON.R.J. Division of Safety Technology B0/07/02 EISENHUT, D.O. Division of Licensing 2pp 02952:301, 24X Fiche 30-247, B0/07/02.8007130303

- 800B130744 Summary of 800517 meeting w/utils in Bethesda. MD recontainment structural response to core delt accident
 - sequences
 MEMERJF Power Bystems Branch 80/07/31 Power Bystems Branch
 3pp 03286 243 24% Fichs 30-247-80/07/31-8008130744
- 8007100100 Forwards recommendations on staff task action plan to be sent to licensess for review & response.

 BARRETT, L. H. Operating Reactors Assessment Branch 60/08/08

 VAROA-8 A. Operating Reactors Panch (Pra 800423) 8pp

 03516-046-24X Fichs 50-247.80/08/08.6009100100
- 8009250234 Eubmits description of work being done on analysis of velsass from facilities. Bimpls I-D multicompartment thermal hydraulic cods being written to analysis variety of FVCE designs Related data entl FENSIERHACHER Reactor Systems Branch 80/09/10 SPE15, T P Reactor Systems Branch 4pp 03589 257 24X Fiche 50-247,80/09/10,8009250234
- SO10220234 Responds to B00917 request rs control room revise NRC 800507 itr detailed five addl items to near-term OL requirements Itam iII O 3 4 requires analysis of control room habitability by B10101 HOWSTON.R W Accident Evaluation Branch 80/09/25 VARCA.B A Gerating Reactors Granch I Ip 03560 001 24X Fich: 50-247.80/09/25.8010220234
- 80(02)0036 Discusses SEP Branch revisu of sys anviron qualification of safety-related electrical equipment for II SEP plants MCKENNA: E M Systematic Evaluation Program Branch 80/09/30 LAINAB, O C Division of Llcensing 2pp 03647 289 24X Fiths. 50-003, 80/09/30. 8010210036
- BOJIII00B4 Requests Instrumentation & Control Sys Branch evaluation of util responses to questions as incore instrumentation tubss at facilities Info will aid branch evaluation mitigation features re backfitting of severe mitigation features SPEIS.TP Reactor Systems Branch BO/10/09 BATTERFIELD.R Instrumentation & Control Systems Branch ip 02227 00: 24X Fichs SO-247.80/10/09.80111100B4
- 80:0280078 Forwards NRC questions & util answers ra backfitting of severa accident mitigation features Evaluation naeded in two wis SPEIR.T P Reactor Systems Brench 80/10/17 SCHAVER,F P Structural Engineering Branch ip 65767 184 24X Fiche 50-247.80/10/17.8010/200078
- 8210070007 Responds to FOIA request for eight categories of records restand generators & steam turbinss App A documents provided in R Udeil FOIA Request 81-313 Forwards documents listed in App B FELTON. J M. Division of Rules and Records 82/08/10 LONG, B J Winthrop, Stimson, Putnam & Roberts 9pp 15645-063 24X Ficha 50-000, 82/08/10, 8210070007
- --8203110403 Forwards response to JD Dunsle, chairman of Poliution Control Board, State of IL. questions in 820127 ltm JOHNSTON, H V Assistant Director for Materials & Qualifications Engineering 82/02/22 LAINMS Q Assistant Director for Safety Assessment 2pp 15445, 126 24X Fiths 50-000, 82/08/10, 821070007
- 8209160503 Buppls 820831 ltr re 820908 meeting at Region 3 ofc Recent operation of Unit 2 w/too Inoperable auxiliary feedwater pumps Added to assanda KEPPLER.J G. Region 3. Office of Director. 82/09/03 REED.C Commonwealth Editon Co ip 14904:087 24X Fiche 50-295,82/09/03, 8209160503
- 8210040218 Requests reaffirmation of technical basis for operation at 100% power Bignificant financial penalties incurred due to operation in overly conservative manner.

 STIEDE.H. L. Commonwealth Edison Co. 82/09/27 DEYOUNO, R.C. Director's Office, Defice of Inspection and Enforcement App 15583 115. 24% Fiche 50-295,82/09/27,8210040218
- 8210050270 Forwards single Class III amend fam for proposed change to License DPR-39 LENTING-F.C. Commonwealth Edison Co 82/09/27. DENTON R Office of Nuclear Reactor Regulation. Director ip 15409:188. 24X Fichs 50-295, 82/09/27,8210050270.

- 6210120105 Requests delay of implementation due dates to NOREO 17," Items II B 2. "Plant Shielding." II B 3. "Post-Accident Sampling" & II F i i. "Noble Ges Effluent Montagr " SHARTZ-E D Commonwealth Edison Co 82/10/04 EIGENHUT, D Q Division of Licensing 5pp 15651 237 24X Fiche 50-000.62/11, 8210120105
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offils Dote Calculation Manual" Office Calculation Manual Office Calculation Co. 82/10/06 CASS.E. 9 Off. Nuclear Reactor Regulation, Director 2pp 15805 137 242 Ficha 30-000, 82/10/06.8210260526
- --8210260542 Revision 3 of Chapter 9 of "Offsite Doss Calculation" Manual " Commonwealth Edison Co 82/09/30 83pp 15805 139 20 Fiche 50-000,82/10/04,8210260526
- 8210220399 Suppls 820414 response to Franklin Resparch Ctr GliC.11.
 technical evaluation rept re control of heavy loads
 (NUREO-0612), per 820824 & 25 telcons
 LENTINE, F G Commonwealth Edison Co 82/10/12 DENION H R
 of Nut
- 8210190443 Forwards add1 info re NUREO-0737. Item II D 3. *Post-Accident Sampling Sys." in response to NRC 820722 Itr Util currantiy pursuing possibility of developing procedura to estimate core damage via Westinghouse owners group SHARTZE D Commonwealth Edison Co 82/10/13 FGFNMMID De Bivision of Licensing 15pp 19741 187 24X Fiche 50-373.62...
- 8210270344 Notification of 821115-16 meetings w/util in Qlen tils-to discuss basss for current inservice testing proposed examption, including alternatives to required inspecting WigoINTON-D Operating Reactors Branch 1 82/10/22 VASOLS Operating Reactors Branch 1 2pp 15851 354 24X Ficha 50-295,82/10/22,8210270344
- Q inspection reports, IE Builetins & correspondence
- --8210050107 Notics of violation from insp on 820300-31.0107 (3.6.7) KEPPLER, J. O. Region 3. Office of Director 82/07/09 3jg 15605.024 24X Fiche 50-295.82/07/09.8210050103
- --82:00501:2 IE Insp Rept 50-295/82-09 on 820300-31.0407 (0 % 2) Noncompliance noted individual received whols body reflater does in access of three ram & failure to adsquately survey & evaluata radiation invels beneath reactor vessel MILLER.D E , ORECER.L R Division of Enginsering & Technica. Programs. 82/06/11 14pp 15605 027 24X Fiche 50-295 %: 8210050105
- 82:0070007 Responds to FOIA request for eight categories of FELLP' team generators & steam turbines App A documents provided in R Udali FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records. 82/08/10 LCA + Winthrop, Stimson, Putnam & Roberts 7pp 15/45 C63 241 Fichs 50-000, 82/08/10.8210070007.

8

8,

8:

- --B210070139 Forwards tabulated data on steam generator inspiles facilities, Data should be provided to licensees IPPOLITO, T. Operating Reactors Assessment Branch. B2/04'C) VAROA.S. Operating Reactors Branch 1 Spp. 15645 13: 28 Fichs. 50-000.82/08/10.8210070007.
- --B210070172 Forwards info ra steam generator integrity & initia's operating PHRs.per 750320 & 21 requests Details of initia's including defect indications, tube plugging criteria & twise plugged will not be provided except for Point Deach & OULLER.K R. Division of Reactor Licensing (NRR-1975 only) 75703/24 HACCARY.R R. Division of Technical Review (NRR-17001) 5pp 15645-176. 24X Fichs 30-000,82/08/10.9710023
- 8210190569 Forwards IE Enforcement Conference & Insp Repls 30-7837 & 50-304/82-17 on 820717-0909 & notice of violation SPESSARD, R L. Division of Project & Resident Programs E2/24/2 REED. C. Commonusalth & Gison Co. 2pp. 15736 112 24X Fiche 50-295, 82/09/30, 8210190568.
- --8210190579 Notics of violation from insp on 820717-0831 a Division of Project & Resident Programs. 82/09/30 15736:113 24X Fiche: 50-295, 82/09/30, 8210190368

- -8210170597 IE Enforcement Conference & Insp. Repts 50-295/82-19 & 50-304/82-17 on 820717-0909 Noncompliance noted failure to follow 800227 confirmatory order requiring expeditious shutdown whenever auxiliary feedwater mys inoperable MATERS. J. R. SCHNEIDER. C. D. REVES. L. Region 3. Office of Director 82/09/22 9pp 15736 114 24X Fiche 50-295,82/09/30,8210190568
- B210060359 Ack receipt of B20910 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29

 SPESSAYD, R L Division of Project & Resident Programs 82/10/01 REED. C Commonwealth Edison Co 1p 15618 354 24X Fishe 50-000, 82/10/01,8210060359
- --8210060367 Responds to NRC 820712 ltr re violations noted in IE Insp Repts 30-237/81-39,50-249/81-32,30-254/81-23,50-245/81-23, 50-295/81-31 & 50-304/81-29 Corrective actions training for mpt priorities re plant availability will be conducted REED.C Commonwealth Edison Co 82/09/10 KEPPLER, J O Region 3. Office of Director 13pp 15618 355 24X Fiche 50-000,82/10/01.8210060359
- *210080178 Forwards listing of piping sys which fail to meet F8AR requirements, per NRC 800818 confirmatory action ltr IE Bulletin 79~14 operability evaluation updates will not be provided for Dresden & Quad Citles Final update by Dec 1982 RAUSCH.T J Commonwealth Edison Co 82/10/01 KEPPLER.J O Region 3. Defice of Director 6pp 15440 159 24X Fiche 50-000,82/10/01,8210080178
- 210190637 Forwards 1E Insp Rept 50-295/82-21 on 820908-10 No moncompliance noted LITTLE-W S Division of Engineering & Technical Programs 82/10/05 REED.C Commonwealth Edison Co 2pp 15739 094 24X Fiche 50-295,82/10/05.8210190617
- -8210190626 IE Insp Rept 50-295/B2-21 on 820908-10 No noncompliance noted Major areas inspected Cycle 7 control rod drop time tests, control rod drive & position indication checks & reactor thermocoupie/resistance temp device cross-calibr ROSINSON, D L. JACKIW I N Region 3. Office of Director 82/10/01 4pp 15739 096 24X Fiche 50-295,82/10/05,8210190617
- 208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Disladged I-125 Emplant Seeds " Svc list enci
 COBB.L I Division of Fuel Facilities, Materials & Safeguards
 82/10/06 Consolidated Edison Co of New York 66pp 15761-230
 24x Fiche 50-000,82/10/06.8208190233
- *10190613 Ack recuipt of 820910 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/82-14 & 50-304/82-13 Interpretation of Tech Spec 1 o D unacceptable SPESSARD, R L Division of Project & Resident Programs 82/10/07 REED. C Commonwealth Edison Co ip 15739 361 24X Fiche 50-295.82/10/07,8210190613
- B210170624 Responds to NRC B20813 ltr re-violations noted in IE Insp. Repts 50-275/82-14 & 50-304/82-13 Disputes NRC classification of B20625 reactor trip Trip inadvertent Interpretation of Tech Spec 1 0 D encl STIEDE.W L. Commonwealth Edison Co. 82/09/10 KEPPLER.J 9 Region 3, Office of Director. 4pp. 13740 001 24% Fichs 50-275.62/10/07/8210190613
- Q8190238 IE Belietin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Dismeter, Stainless Steel, Recirculation Bys
 Piping at DWR Plants " Svc list encl
 DEYQUNO.R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24% Fiche 50-000, 82/10/14-8208190238
- 10270344 Notification of 82(115-16 meetings w/util in Olen Ellyn, IL to discuss bases for current inservice testing proposed exemption, including alternatives to required insps. AIGOINTEN, D. Operating Reactors Branch 1, 82/10/22, VAROA, S. A. Dperating Reactors Branch 1, 2pp. 13851:354 24X Fisher 50-295,82/10/22,8210270344
- Periodic operating reports & related correspondence
- LO150405 Forwards monthly operating repts for Sept 1982
 FRAESER.K L Commonwealth Edison Co 82/10/04 Director's
 Dffice. Office of Inspection and Enforcement 1p 15704 003 24:
 Tiche 50-275. B2/10/06, 8210150405.
- 3210150411 Monthly operating repts for Sept 1982 AUSTIN:0 Commonwealth Ediaon Co 82/10/06 11pp. 15704'004 24X Fiche 50-293:82/10/06:8210150405.

- 8 Reportable occurrences, LERs & related correspondence
- 8210120182 Discusses findings re numerous failures of containment isolation valvae All failures resulted from inoperable ASCO Series 8320 solenoid valves, usually due to oil in air supply Valves undergoing qualification LANNING, W D Director's Office 80/08/22 Director's Office 2pp 15692 216 24X Fiche 50-295,80/08/22,8210120182
- 8210070429 Discusses 810115 salenoid valve failure Failure of valve to thift attributed to impurities in oil settling on valve surface Valves replaced No further action recommended ASHE.F Director's Office 81/11/10 MICHELEON.C Director's Office 4pp 13644 317 24% Fiche 30-275,81/11/10.8210070429
- B210070422 Recommends IE issue info notice to inform licenses of possible inadequate surveillance for proper tuning of output capacitance for certain inverters Recommendation based on B10505 & 28 sola output transformer shorts HELTEMES, C. J. Director's Office. B1/12/10 JOHDAN.E. L. Division of Resident & Regional Reactor Inspection. 4pp 15444 285 24X Fiche 50-295,81/12/10,8210070422
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents iteted in App A FELTON, J M Division of Rules and Records. 82/06/28 UDELL.R.A Critical Mass Energy Project 15pp 15727 005 24% Fiche 50-000, 82/06/28,8210010008
- --Bi11270314 Discusses LER 81-002/03X-1. dtd 810430, re inoperable eclenoid valves. Cause found to be impurities in internal machanisms Valves replaced w/Kesne valves & solenoids w/higher strength coll Findings to be incorporated in instrument air study ASHE, F Director's Office, Bi/11/10 MICHELSON, C Director's Office 3pp 15731 109 24X Fiche 50-000, 82/06/28, 8210010008
- 8210080088 PND-III-82-106 on 820930. while operating at full power, one of two main feedwater pumps failed Reactor control rod drive sys failed to insert rods automatically Caused by faulty circuit board Circuit board replaced REYES. L. STREEYER. J. SPESBARD. R. Region 3. Office of Director 82/10/01 p 15640 222 24% Fiche 50-295.82/10/01.8210080088
- 8210190689 Forwards LER 82-027/03L-0 ORAESSER, K. Commonwealth Edison Co 82/10/05 KEPPLER, J 0 Region 3. Office of Director 1p 15738 143 24X Fiche 50-295, 82/10/05, 8210190689
- --8210190715 LER 82-027/03L-0 on 820905, 1C containment spray diesel driven pump found completely void of engine Jacket Maker. Caused by leak in Jacket Maker heater due to corresion Heater replaced Mylpe plug New heaters ordered SHIM, K. Commenusalth Edison Co. 82/10/05. Region 3, Office of Director ip 15738 144 24X Fiche 50-295,82/10/05,8210190689
- 8210190483 Forwarde LER 82-028/03L-0 GRAESSER, K. L. Commonwelth Edison Co. 82/10/08 KEPPLER, J Q Region 3, Office of Director ip 15740 266 24X Fiche 50-293, 82/10/08,8210170483.
- --8210190493 LER 82-028/03L-0 on 820910, during surveillance at 100% power, RHR miniflow control valve switch iFIC-510A failed & would not close miniflow valve at 1000 gpm as designed Gaussed by switch out of tolerance Mod initiated BINOGELIAB L Commonwealth Edison Co 82/10/08 Region 3, Office of Director ip 15740 267 24% Fiche.50-295,82/10/08,8210190483
- 8210260399 Forwards LER 82-030/03L-0 ORAEGSER: K L Commonwealth Edison Co 82/10/19, KEPPLER, J Q Region 3, Office of Director. 1p 15803 327 24K Fiche 50-295, 82/10/19,8210260399.
- --B21026041\$ LER B2-030/03L-0 on B20919. charging flow found 30 gpm less than letdown flow Increased demand on charging flow control valve did not increase flow rate Caused by fatigue Rotating element replaced Investigation ongoing BINOGELIB.L. Commonwealth Edison Co B2/10/19 Region 3, Office of Director 3pp 15803-328. 24X Fiche 50-275, 62/10/19, 8210260399
- 8210260233 Forwards LER 82-029/03L-0 ORAEBER, K L. Commonwealth Edison Co. B2/10/20 KEPPLER. J. 0 Region 3, Office of Director Ip. 15803:029 24x Fiche: 50-295,82/10/20,8210260233

- --B2iO260254 LER B2-029/03L-0 on B20920.logic relay NC4iH-XA associated w/power range XIOX reactor trip for train A malfunctioned nonconservatively Caused by plunger pin shifting to one side & binding against relay housing RCHDE.J E Commonwealth Edison Co B2/10/20 Region 3, Defice of Director 1p 15903 030 24X Fichs 50-295.82/10/20. 8210260233
- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3 F Security, medical, emergency & fire protection plans
- B207170101 Forwards minor revisions to proposed physical security plan Revisions withheld (ref 10GFR73 21) HILLB:L M Tennessee Valley Authority 62/09/31 DENTON:H R Office of Nurlear Reactor Regulation: Director 2pp 14910 081 24X Fiche 50-259.92/08/31.8209170101
- 8210290236 Forwards security plan table of contents Table of contents withheld (ref 10CFR73 21)

 KARKER,D S Tennessee Valley Authority 82/10/19 DENTON,H R Office of Nuclear Resoulation, Director 1p 15788 362 24 Fichs 50-259,82/10/19.8210250236
- 8210250244 Forwards revisions to physical security plan Revisions withheld (ref 100FR73 21)

 KANKER D S Tennesse Valley Authority 82/10/19 DENTON. H R
 Office of Nuclear Reactor Regulation. Director (p 15788 345
 Fiche 50-250

G Adjudicatory correspondence

- 8210120291 Response to ASLAB 820920 order to provide any supplemental info re questions posed to util Authorization is for 5-yr storage of low level radwaste, w/o limit on use of modules for interim use on backup basis RAMSON, R J Hearing Branch 4 82/10/08 8pp 15452 071 24x Fiche 50-259, 82/10/08, 8210120291
- --8210120299 Affidavit of P Loysen re application for storage of low level raduaste No restriction requested or contemplated limiting use of modules only to interim use on backup basis LOYSEN P Advanced Fuel & Spent Fuel Litemaing Branch 82/10/08 R3pp 15652 079 24X Fishe 50-259.62/10/08.8210120291
- --8210120300 Affidavit of JR McGrath Timely request for renewal of facility license fited for Beatly,NV low level raduaste disposal facility NV State Board of Health voted not to renew facility license MCCRATH, J R Assistant Director for State Agreements Programs 82/10/08 2pp 13652 102. 24X Fiche 50-259,82/10/08,8210120291
- --8210120316 Affidavit of SN Balomon Southeast Interstate Low Level Raddaske Hgt Compact agreed to close Barnuell, 80 facility on 921231 a open new site on 911231, Certificate of Syc encl. SALDHON, 8 N Assistant Director for State Agreements Programs B2/10/08 4pp 15452 104. 24X Fiche. 50-259, 82/10/08, 8210120291
- 8210250063 Telecopy message of motion for ASLAB to grant 30-day extension to respond to ASLB 820920 order. Time necessary to explore settlement possibilities of all matters in Controversy
 PYLE:R B Pyle: R B. 82/10/20 Docketing & Services Branch
 15787-061 24% Fiche 50-259.82/10/20.8210250063.
- 8210260427 Motion for extension of time until 821121 to respond to B20720 order Time necessary to explore possibilities of settlement Certificate of Svc encl
 PVLER B Pyle, R. B 82/10/20. Atomic Safety and Licensing Appeal Panel 2pp 15806 036 24% Fiche 50-259,82/10/20,8210260429

P Operating license stage documents & correspondence

- 8210070255 Forwards response to NRC request for addl info on NUREO-0612, "Control of Heavy Loads of Nuclear Power MILLS.L.H. Tennesses Valley Authority. 82/09/28 t Operating Reactors Branch 2 36pp. 13633 243 24X Fiche 50-239,82/09/28,8210070235 VASBALLO, D B
- 8210080218 Forwards addit info in response to NRC 820808 request re NUREO-0737, Item II KAS.24, "Adequacy of Space Cooling for HPLI & Note: "
 HTLLG.L.H. Tennessee Valley Authority 82/10/04 DENTON, H. R.
 Office of Nuclear Reactor Regulation Director, 2pp. 15538-091.
 24X Fiche: 50-259,82/10/04,8210080218.

- 8210130142 Forwards description of final mods & changes to BHM scrax sys & short-term interim commitments for Unit 2 Hods will be implemented for Unit 2 before startup from Reload 4 outage & subsequent Units is 3 outages
 MILLS.L M Tennessee Valing Authority 82/10/06 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 4pp 15673 085
 24% Fiche 50-259.82/10/06.8210130142
- 8210250076 Forwards revision to 821006 implementing procedures MILLS/L M Tennessee Vailey Authority 82/10/15 DENTON II R Office of Nuclear Reactor Regulation, Director ip 15793 058 15793 058 -Fiche 50-259, 82/10/15, 8210250096
- ~~8210250101 Revised implementing procedures # Tennessee Valley Authority 82/10/15 16pp 15793 059 24: Fiche: 50-259, 92/10/15, 8210250096
- O Inspection reports. IE Builetins & correspondence
- 8210080015 Addi response to FOIA request for 19 categories of information of the response of t FOIA Exemption 5)
 FECTON-J M Division of Rules and Records 6:
 Critical Mass Energy Project 9pp 15665 027
 Fiche 50-000.82/07/12.8210080015 82/07/12 UDELL.S A 27 24%
- --82:0080118 Systematic assessment of licensee performance notes ry facility evaluation for Apr 1979-Mar 1980 NRC No Betailed Affiliation Given 80/03/31 App 15667 313 24X Fiche 50 000.82/07/12:82:10880015
- 8210190105 Notifies that corrective actions re IE Insp Repts 50-259/81-13, 50-260/81-13 & 50-296/81-13 doiayed Procedure DPM N80E3 re exam of C580 (tems to be revised by 820915 DOMER, J A Tennessee Valley Authority 82/07/13 O'RESLL Region 2, Office of Director ip 1570(159 24X Fiche 50-259, 82/07/13, 8210150(05 O'REILLY, J.P.
- 8210220151 Provides supplemental response to NRC Itr re violations noted in IE Insp Repts 50-259/82-10, 50-240/82-10 & 50-296/82-10 Div of procedures Manual N82/3 will not be revised until 821001 due to scope of effort involved MICLB/L H Tennessee Vailey Authority 82/08/18 G'REILLY, JP Region 2, Office of Director ip 15778 106 24X Fiche: 50-257, 82/08/18, 8210220151
- 8210010035 Confirms 820708 site meeting to discuss recent violations re radwaste shipments Agenda encl G'REILLY.J.P. Region 2: Office of Director 82/09/03 PARRIS.H.C Tennesses Valley Authority 2pp 15565 166 24X Fiche 50-259, 82/09/03: 8210010035
- 6210010430 Farwards IE Insp Repts 50-259/82-25, 50-260/82-25 & 50-276/82-25 on 820810-11 No nancompliance noted VERRELLI, D M Division of Project & Resident Programs 62/09/0 PARRELS H O Tennessee Valley Authority 2pp 15570 211 24K Fiche 50-259, 82/09/03, 8210010430 82/09/0
- --82:00:0432 IE Insp Repts 50-259/82-25,50-260/82-25 & 50-296/82-2 8208:0-11 No noncompliance noted Major areas inspected reactor secondary containment integrity problem & MSIV testino BROOKE H JAPE F. . JAPE, F. Division of Engineering & Technical Proj. 4pp 15570 213 24X Fiche 50-259,82/07/03,82(00) 82/09/27
- 8210150399 Forwards IE Insp Repts 50-259/82-28.50-260/82-28 & 30-296/82-28 on 920830-0903 No noncompliance noted VERRELLI, DM Division of Project & Resident Programs 82/09/2 PARRIS, H O Tennessee Veliey Authority 2pp 15704 029 24X Fiche: 50-259, 82/09/20, 8210150399
- --8210190404 IE insp Repts 50-259/82-28,50-260/82-28 & 50-295/82-26 820830-0903 No noncompliance noted Major areas inspected or one of the state of the stat
- 8210010097 Approves revised commitment dates for Item 25 of App Ct IE Insp Repts 50-299/81-19.50-260/81-19 & 50-296/81-19 & Item C.2 of App A to IE Insp Repts 50-259/82-12.50-260/82-12 & 50-276/82-12. LEWIG.R C. Division of Project & Resident Programs 82/09/22 PARRIS, H O. Tennessee Valley Authority, 1p 15545 COL 24x Fiche: 50-259, 82/09/22, 82:0010097

J

- --8210010104 Requests extension to respond to App C. Item 25 in IE Insp Repts 50-259/81-19.50-260/81-19.50-296/81-19. t Item C. 2 in IE Insp Repts 50-259/82-12.50-260/82-12. 50-296/82-12. Responses will be submitted by 630101 & 821101. respectively MILLS.L. M. Tennessee Valley Authority 82/09/01 0'REILLY, J. P. Regsan 2. Office of Director 1p 15565 002 24% Fischs 50-259.82/09/22.8210010097
- F210010326 Forwards summary of 820908 enforcement meeting w/util to discuss corrective actions re leakage during shipment of low level uaste & util plans for improving employee training OfREILLY. J.P. Region 2. Office of Director 82/09/22 PARRIS. H. O. Tennessee Valley Authority 4pp 15567 188 24X Fiche 30-259.82/09/22, 8210010326
- P10010270 Act receipt of supplemental 820901 ltr informing NRC of steps taken to correct Violation B noted in IE Insp Repts 50-259/81-26. 50-260/82-26 & 50-299/81-26. ELGHIS.R C Division of Project & Resident Programs 82/09/24 PARRISIN G Tennessee Valley Authority 1p 15573 183 24X Fiche 30-259.82/09/24.82100102290
- -8210010304 Forwards revised response to NRC 811028 ltr re Violation B noted in IE Insp Repts 50-259/82-26, 50-260/82-26 & 50-296/82-26 Corrective actions R factor returned to within limits & revision to Tech Spec approved MILLS-L K Tennessee Valley Authority 82/09/01 D'REILLY, J P Region 2, Office of Director 3pp 15573 184 24X Fiche 50-259, 82/09/24,8210010290
- 110220390 Forwards IE Insp Repts 50-259/82-29,50-260/82-29 & 50-296/82-29 on 820904-10 No noncompliance noted VERRELLI.D H Division of Project & Resident Programs 82/09/30 PARRIS.N G Fennessee Valley Authority 2pp 15779 220 24X Fiche 50-259,82/09/30,8210220390
- B210220401 IE Insp Repts 50-259/82-29.50-260/82-29 & 50-276/82-29 on B20906-10 No nancompliance noted Major areas inspected Unit 2 refueling & maint outage & procedural compliance of health physics-related practices by workers COLLINS.TR., BARR.KP Division of Engineering & Technical Programs 82/09/27 5pp 15779 222 24X Fiche 50-259.82/09/30, B210220390
- 10080217 Forwards revised request for relief from Inservice Insp 7 restractes the welds in piping penetrations & under rigid pipe restraints Best effort visual exam will be performed during sys hydrostatic pressure test 4ILLS/L M Tennesses Valley Authority 82/10/04 DENTON, H. R 3ffice of Nuclear Reactor Regulation. Director 3pp 15638 083 24% Fiche 50-259,82/10/04.8210080219
- #8190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 rplant Seeds " Svc list encl
 USB.L l Division of Fuel Facilities, Materials & Safequards "2/10/06 Consolidated Edison Co of New York 66pp 15761 250 4% Fiche 50-000,82/10/06,8208190233
- O150218 Forwards update of present work & schedule for mplementation of insparequired under IE Bulletins 79-02 & 9-34 Phase II evaluation will not be completed until 40801
 ILLS.L M Tennessee Valley Authority 82/10/07 O'REILLY, J Pagion 2: Office of Director 2pp 15705 276 24X sche 50-259.82/10/07.8210150218
- 3190238 IE Bullatin 82-03, "Stress Corrosion Cracking in Thick-
- all-Large-Diameter Stainless Steel Recirculation Syseping at BWR Plants "Sycilst encl EYOUNG.R C Director's Office, Office of Inspection and offorcement 82/10/14 Consolidated Edison Co of New York 15pp 15810 125 24% Fiche 50-000.82/10/14.8208190238

reportable occurrences. LERs & related correspondence

- 120129 Advises of need for in-depth evaluation of potential for acceptable interaction between control rod drive sys & nessential control air sys Mergin of safety inherent in censed design basis should be promptly restored CHELSOU.C Director's Office 80/08/18 DENTON, H. R Office of clear Reactor Regulation, Director Spp 15692, 150 24X che. \$0-296.80/08/18,8210120129
- O1000B Responds to FOIA request for 19 categories of documents reclear reactor events & safety problems. Forwards documents sted in App A LTON. J M Division of Rules and Records. 82/06/28 UDELL.R. A itical Mass Energy Project 15pp 15727 005 24x cha 50-000/82/06/28,8210010008.

- --8112210338 Forwards description of events & resulting action re high circulating current associated w/inverter output due to lack of circuit tuning IE circular or info notice should be issued to address issue
 HELTEMES.C J Director's Office 81/12/10 JORDAN.E L
 Director's Office 4pp 15731 361. 24X Fiche 50-000,82/06/28,8210010008
- --B2100600B2 "Bummary of Ofc of Analysis & Evaluation of Operational Data Analysis & Evaluation of Browns Ferry Unit 3 Partial Failure to Scram Event of 80042B"

 LANIK, 0 Director's Office 81/11/30 22pp 19731 263 24X Fiche 50-000, 82/04/28, 8210010008
- 8210080015 Addi response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J N DIVision of Rules and Records 82/07/12 USELL, R A Critical Mass Energy Project 9pp 15645 027 24X Fiche 50-000,82/07/12,8210080015
- --8210080197 NRC operations ctr usage chart re events at facilities « NRC - No Detailed Affiliation Given 82/07/12 ip 15668 221 24X Fiche 50-000, 92/07/12, 8210080015
- 8210060265 Forwards LER 82-042/03L-0 OREGN.H J Tennesses Valley Authority 82/09/28 O'REILLY, J P Region 2, Office of Director. 19 15621 O.4 24X Fichs 50-296.82/09/28.8210060265
- --8210060270 LER 82-042/03L-O on 820831, diesel generator 3C right bank air starters falled to develop min rpm Caused by loose bolts on right bank air start valve 853-3 Bolts tightened PORTER,M.R. Tennessee Valley Authority. 82/09/28 Region 2. Office of Director 2pp 15621 077 24X Fiche 50-296,82/09/28, 8210060265
- 8210130157 Forwards LER 82-043/03L-0 OREEN.H J Tennessee Valley Authority 82/10/07 O'REILLY, J P Region 2, Office of Director 1p. 15673 077. 24X Fiche 50-296.82/10/07.8210130187
- --8210130162 LER 82-043/03L-0 on 820909,480-volt reactor motor operated valve board 3DN motor-generator set removed from svc when generator/fiywheel ball bearing became noisy Caused by Jack of adequate lubricant film on bearing Bearing replaced AARON.J.A. Tennessee Valley Authority 82/10/07 Region 2, Office of Director 2pp 15673 078 24X Fiche 50-296.82/10/07, 8210130157
- 8210270231 Forwards updated LER 82-037/01X-1 GREEN.H J Tennessee Valley Authority 82/10/14 O'REILLY, J.P. Region 2, Office of Director ip 15853 231 24X Fiche: 50-296. 82/10/14.8210290231
- --8210270232 Updated LER 82-037/01X-1 on 620824, during instrumentation calibr for core standby cooling sys suppression chamber, calibr valve on level switch LS-73-57A found open rendering switches inoperable Gaused by open valve Valve closed IRBV-8 J Tennessee Valley Authority B2/10/13 Region 2, Office of Director 2pp 15853.232 24X Fiche 50-296,62/10/14, 221029023
- T Hearing transcripts on non-antitrust matters
- 8210070133 Testimony of JW Hutton answering ASLAB questions on low level radwaste mgt options Availability of adequate space to dispose of low level wastes in next 5 yrs uncertain Centificate of Svc encl HUTTON, JW Tennessee Valley Authority 82/10/01, 12pp 15627 031 24X Fiche 50-259,82/10/01,8210070133
- DOCKET 50-298 COOPER NUCLEAR STATION

 F Security, medical, emergency & fire protection plans
- 8210010058 Forwards rept of change to safeguards plan, Revision O. Rept withheld (ref 10CFR2, 790 & 10CFR3, 21). PILANT, J. M. Nebraska Public Power District. 82/09/13, VASSALLO, D.B. Operating Reactors Branch 2 fp 15567
- 8210130318 Forwards changes to Revision 1 to safeguards plan, Changes withheld (ref 10CFR2 790 & 10CFR73 21)
 PILANT, J.M. Nabraska Public Power District 82/10/04, VASSALD, D. B. Operating Reactors Branch 2 2pp 15678 160 24X
 Fiche 50-298, 82/10/04, 8210130318

- 8210180320 Forwards OE proprietary unique analysis repts for facility Repts withheld (ref 10CFR2 790) SIECEL.B. Operating Reactors Branch 2 82/10/04 BUBRAMONIAN.N Franklin Institute/Franklin Research Center ip 15746.018 24X Fiche 50-298,82/10/04,8210180320
- 8210260217 Forwards response to NRC 820809 ltr forwarding notice of violation & proposed imposition of civil penalty & order modifying license Magnitude of enforcement action not warranted JONES.C R Nebraska Public Power District 82/10/07 DEYOUNG.R C Director's Office, Office of Inspection and Enforcement, 84pp 13804 081, 24X Fiche 50-298,82/10/07,8210260217.
- 8210220254 Submits update to B20416 response to Generic Ltr 82-05, confirming operability & installation of post-TMI requirement per NUREO-0737, Item II F i re accident monitoring instrumentation noble ges & iodine particulate PILANT. J H Nebreska Public Power District 82/10/18 EISENHUT, D & Division of Licensing ip 15774 228 24X Fiche 50-278, 82/10/18, 8210220254
- 8210240278 Forwards IE Befeguards Insp Rept 50-278/82-28 on 920800-0901. Notice of violation withheld (ref 100FR73 21). MADSEN. O.L. Division of Resident, Reactor Project & Engineering Programs, 82/10/22 PLANT, J N. Nebresia Public Power District, 2pp 15801-358 24X Fiche, 50-278, 82/10/22, 82/0740298
- --8210260301 lE 8afaguards Rept 50-298/82-28 on 820830-0901 Noncompliance noted, details withheld (ref 10CFR73 21)
 CALDHELL, R A . KELLY, J A F. Region 4, Office of Director 82/10/14 lp, 15801.360 24X Fiche 50-298.82/10/22.8210260298

P Operating license stage documents & correspondence

- 8210120584 Forwards order modifying 810113 order.stending completion date for installation of plant mods needed to comply w/ NVREO-0661.app A to start of feel Cyls 9.

 VASBALLO.D.B. Operating Reactors Branch 2 62/09/15, PILANT, J H. Natraska Fubiic Power District, 2pp. 15684:209 24X Fiche:50-298.82/09/15.8210120584.
- --82(0120590 Order modifying 810110 order,extending completion date for installation of plant mode needed to comply w/NUREO-0661.

 App A to start of Fuel Cycle 9, EIBENNUT.D.O. Division of Licensing. 82/09/15. Nebreska Public Power District. Spp. 15684:211. 24X Fiche: 50-298,82/09/15. R210120584.
- 8210270308 informs that integration of NUASO-0737, item II. M. 3. 27
 "Common Ref Level" & Item 1.D. i. "Control Room Design
 Revieu." per ubil 820930 commitment will aliminate operator
 confusion resulting from changing water level.
 VAESALLO, D. B. Operating Reactors Branch 2. 82/10/12, PILANT, J. M.
 Nebratak Public Power District. 2pp. 15836: 337. 24X
 Ficha: 50-298.82/10/12.8210270308.
- 8210220264 Submits update to 820416 response to Generic Ltr B2-05, confirming operability & installation of poet-TMI requirement per NUREG-0737, Item II.F. I reaccident moniforing instrumentation, meble get k loding particulate. PILANT.J. M. Nebraska Public Power District. 82/10/18. ISSENNY.J. D. Division of Licensing. Ip. 19774: 228. 24% Fiche: 50-278, 82/10/18, 821020084.
- 9210260328 Forwards revisions to 920329 Relief Requests RP-02 & RP-04 Fe inservice insp/testing requirements for pumps & valves. PILANTIJ.M. Rebrests Public Fauer District, 92/10/19, VASSALLO.D.B. Operating Reactors Sranch S. 4pp, 18799;044, Q4X Fiche: 50-278;82/10/19,8210240328.
- BRIO270323 Submits justification for continued plant operation re GE dc motor controllers, Fallure of OE controllers due to harsh environ will not affect sate shutdown. Controllers will papeads satisfactorily after expanse to redistion does, PILANTS. M. Nabraeta Public Rever District. 82/10/22, VASSALIO, D.S. Operating Restors Branch 2. 1p. 16883:066, 24% Fiche: 80-278, 82/10/22, 8210270323.

d. Inspection reports: IE Bulletins & correspondence

9208190233 IK Into Notice 80-35, Suppl 1; "Lasking & Dialogged I-125 Implant Seeds," Svc list and, COSB, L. I. Division of Fuel Facilities, Haterials & Safaguards, S2/10/26. Contolidated Edison Co. of New York, 64pp. 18761:250. E4X Fishe:50-000,52/10/04,8208190232.

- 8210260217 Forwards response to NRC 820809 ltr forwarding notics of violation & proposed imposition of civil penalty & order modifying license Magnitude of enforcement action not warranted JONES.C R Nebraska Public Power District 82/10/07 novembers.
- WATTARTES UNIONES CR Nebraska Public Power District 82/10/07 DEYDUMD, P.C Director's Office. Office of Inspection and Enforcement Sipp 15804 081 24% Fichs 50-278,82/10/07,8210240217
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys-Piping et BWR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 62/10/14, 8208190238
- 8210220130 Ack receipt of 820710 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-278/82-14 MADSEN O L Division of Resident, Reactor Project & Engineering Programs 82/10/14 PLANT J M Nebraska Public Power District ip 13778 118 24x Fiche 50-298.82/10/14.8210220130
- -8210220136 Responds to NRC 820813 ltr re violations noted in IE 1 a Rept 50-298/82-16 Corrective actions entry ways into affected area posted locked or observable to radiographs: Disciplinary action taken re Procedure 7 4 4.Revision 12 PILANT.J M Nebraste Public Power District 82/09/10 MADSEN.G L Division of Resident, Reactor Project & Engineering Programs 3pp 15778 119 24% Fiche 50-298,82/10/14,8210721%
- 8210260328 Forwards revisions to 820329 Relist Requests RP-02 £ 67 and inservice insp/testing requirements for pumps & valves PLLANT.J M Nebrasks Public Fower District 82/10/19 VASSALLO, D B Operating Reactors Branch 2 4pp 15799 344 To Fiche: 50-278, 82/10/19, 8210260328
- 8210260278 Forwards IE Safeguards Insp Rept 50-278/82-28 on 820830-0761 Notice of violetion withheld (ref 10CFR73 21) MADSEN.O L Division of Resident: Reactor Project & Engineering Programs 82/10/22 PILANT.UN Nobraska Public Power District 2pp 15801 358 24% Fiche 50-278.82/10/22.8210260278
- --8210260301 IE Bafeguards Rept 50-298/82-28 on 820830-0901 Nantry noted details withheld (ref 100FR73 21) CALDMELLAR A., KELLY, J A F Region 4, Office of Director 82/10/14 lp, 15801 360 24X Fiche 50-298, 82/10/22, 82102
- 8. Reportable occurrences, LERs & related correspondence
- 8210010008 Responds to FDIA request for 19 categories of documental nuclear reactor events & sefety problems Forwards documental listed in App A FELTON, J H DAV(sion of Rules and Records 82/06/28 UDELL, & Critical Hass Energy Project, 15pp 15727, 005 24X Fiche: 30-000, 82/06/28, 8210010008.
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2 F. Gecurity, medical, emergency & fire protection plans
- 8210040119 Discusses revision of plant emergency response providing apacifying necessary precautions required before post-accident rementry into auxiliary bldg or facade in response to 820914 request for info re NUREO-0737. Item II B. 2. FAY.C.W. Hisconsin Electric Power Co. 82/09/24 DENTON-H R Office of Nuclear Reactor Regulation. Director. CLARA, R A Operating Reactors Branch 3. 2pp 15581.201. 24X Fiche: 50-266: 82/09/24, 8210040119
- 8210050272 Forwards edd1 info requested in NRC B20916 teleen to support util 820630 App R exemption request. Eight oversite drewings encl. Aperture cerds are available in FDR, FAY.C. W. Hisconsin Electric Fower Co. 82/09/29, DENYON H R Diffice of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 13pp, 15606-047, 24X Fiche: 80-266, 82/09/29, 8210050272.
- 8210080054 Forwards add1 into re proposed mods for emerganty state ctr.
 FAY: C H. Hisconsin Electric Power Co 82/09/30. DENTOWHER Office of Nuclear Reactor Regulation. Director. 16pp 13:03 22 R4X Ficha: 50-266, 82/09/30, 8210050084.
- 8210270256 Releases public version of revised emergency plan implementing procedures. FELTON.J.M. Division of Rules and Records. 82/10/08. Securing Management Branch. 1p. 15894.001. 24X Fiche: 50-266,62/10X1-8210270256.

- --B210270259 Forwards public version of revised emergency plan implementing procedures including Procedures EPIP 1 1 re anitial classification. EPIP 1 3 re estimation of source term L EPIP 1 4 re radiological dose evaluation FAV.C W Histonian Electric Power Co 82/09/10 DENTON.H R Office of Nuclear Reactor Regulation Director CLARK.R A Operating Reactors Branch 3 4pp 15834 002 24X Fiche 50-264,82/10/08.8210270256
- B210150471 Forwards addl info re 820630 requests for exemption from 1CCFR59 App R concerning Fire Area 9.control room & vertical cable trays, in response to 821001 & 06 telcons w/Azc W/16 aversize drawings Aperture cards in PDR FAY.C H Hisconsin Electric Power Co 82/10/11 DENTON, H R Diffice of Nuclear Regulation. Director CLARK, R A Operating Reactors Branch 3 12pp 15734 350 24X Fiche 50-266, 82/10/11, 8210150471

G Adjudicatory correspondence

- 9210050251 Memorandum % order granting summary disposition of all WI Environ Decade issues except issue of demonstration of adequacy of eddy current testing to detect cracking BLOCH, P B . KLINE, J R . PAXTON, H C . Atomic Safety and Licensing Board Panel 82/10/01 Wisconsin's Environmental Decade 19pp 156/10 306 24X Fiche 50-266,82/10/01.8210050251
- 8210200027 Natice of 821117-20 evidentiary hearing in Two Rivers, WI re adequacy of inservice nondestructive testing of slaeves proposed to be used to repair corroded steam generator tubes Prehearing conference to be held after hearing BLOCH.P B Atomic Safety and Licensing Board Panel 82/10/15 ip 15756 325 24X Fiche 50-266, 82/10/15, 8210200027
- 8210220242 Notice of relocation of 821117-20 hearing from Two Rivers, WI to Milwavkee, WI Limited appearance statements will be taken at original location on 821117
 BLOCK PB Atomic Safety and Licensing Board Panel 82/10/21 ip 15775 351 24X Fiche 50-266.82/10/21.8210220242
- P Operating license stage documents & correspondence
- B210210009 Recommends review of design of Interconection between red undant safety-related electrical load groups Design should be modified to assure full compliance w/Reg Gulde
 1 A
 MICHELBON.C Director's Office 80/08/27 DENTON, H R Director's Office 20/08/27 DENTON, H R DIRECTOR DENTON DEN
- SQ1001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, JM Division of Rules and Records 82/08/10 LONG, D J Glinthrop, Stimson, Futnam & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007
- ~-Bit0290050 Advises that technical reviewers providing input for SER must be available to testify at 8i1027-31 hearings Schedule & agenda info enci
 CLARK; A Operating Reactors Branch 3 81/10/20 MURPHY, E. NEHEMIAS, J. HO, T. NRC No Detailed Affiliation Olven 3pp 15645 271 24% Fishs 30-000, 82/08/10.8210070007.

- 8210040414 Forwards Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends revise inservice insp Tech Specs CLARK, R A Operating Reactors Branch 3 82/08/31 FAV.C W Misconsin Electric Power Co 5pp 15597 134 24X Fiche 50-266, 82/08/31.8210040414
- --8210040420 Amends 63 & 68 to Licenses DFR-24 & DFR-27, respectively, revising language of Tech Specs re inservice inspectively. Tequirements of safety class components to conform WIDCFRSO 35 CLARK, R A Operating Reactors Branch 3 82/08/31 16pp 1597 137 24X Fichs 50-266, 82/08/31,8210040414
- --8210040425 Safety evaluation supporting Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively * Office of Nuclear Reactor Regulation, Director 82/08/31 4pp 15597 155 24X Fiche 50-266,82/08/31,8210040414
- --8210040427 Notice of issuance & availability of Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively CLARK.R A Operating Reactors Branch 3 82/08/31 3pp 15597 179 24X Fiche 50-266, 82/08/31,8210040414
- 8210030005 Advises that error analysis of reactor vessel water level instrumentation sys requested in NRC 820619 ltr will be available by 83015
 FAY.C W Hisconsin Electric Power Co 82/09/29 DENYON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 ip 15605 208 24%
 Fiche 50-266, 82/09/29, 8210050005
- 8210050055 Forwards info requested in NRC 820630 ltr re implementation of TMI Item II B 2. "Post-Accident Sampling Sys " Adding equipments re backup power sources for lab are beyond scope of original NUREO-0737 implementation schedule BURSTEIN, S. Misconsin Electric Power Co. 82/09/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director CLARK, P.A. Operating Reactors Branch 3. 21pp. 15003-307. 24X Fiche 50-266, 82/09/30, 8210050055
- 8210050222 Application to amend Licenses DPR-24 & DPR-27, revising spent fuel pool poison surveillance specimen location & clarifying conditions for operating power-operated relief valves FAY.C W Misconsin Electric Power Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director, 3pp 15609 056 24% Fiche 50-266,82/09/30,8210050222
- --82i005023i Proposed Tech Specs revising spent fuel pool poison surveillance specimen location & clarifying condition for operating power-operated relief valves # Wisconsin Electric Power Co 82/09/30 3pp 15609 059 24% Fiche 50-266,82/09/30,8210050222
- 8210270426 Forwards Amends 64 & 67 to Licenses DPR-24 & DPR-27, respectively, safaty evaluation & notice of issuance & availability Amends modify operation & surveillance testing requirements of containment purge supply & exhaust valves COLBURN.TO Operating Reactors Branch 3 82/10/04 FAY.C Wilsconsin Electric Power Co. 4pp 15863 143 24% Fiche 50-266, 82/10/04, 8210270426
- --B21027043: Amends 64 & 67 to Licenses DFR-24 & DFR-27, respectively, modifying operation & surveillance testing requirements of containment purge supply & exhaust isolation valves & terminology of Tech Spec 15 4.4 on testing.

 CLARK, R A Deprating Reactors Branch 3 82/10/04 12pp
 15863.154 24% Fiche 50-266.82/10/04.8210270426
- ---8210270426 Safety evaluation supporting Amends 64 & 69 to Licenses DPR-24 & DPR-27, respectively 4 Office of Nuclear Reactor Regulation, Director 82/10/04 5pp 15863 146 24X Fiche 50-266, 82/10/04/8210270426
- --821029044; Notice of issuance & availability of Amenés 64 & 69 to Licenses DPR-24 & DPR-27. respectively CLARK, R A Operating Reactors Branch 3 82/10/04 2pp. 15863 151 24% Fiche 50-266, 82/10/04.8210290426
- 8210190284 Advises of mod to RCB gas vent sus to prevent operation of power operated valves during normal plant operation; per 821012 telcon Physical restraining device fitted on or over valve operator switch FAY.C W Hisconsin Electric Power Co 82/10/15 DENTON.H.R Office of Nuclear Reactor Regulation; Director CLARK.R.A Operating Reactors Branch 3 ip 15742:177 24X Fiche 50-246.82/10/15.8210190284

- 8210270294 Forwards Amends 65 & 70 to Cicenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amend allows rejaration of monthly turbine stop & governor valve tests during end of cycle operation COLBURN T O Operating Reactors Branch 3 82/10/15 FAY, C W Misconsin Electrac Power Co 3pp 15836 316 24% Fiche 50-266,82/10/15,8210270294
- --B210270297 Amends 65 & 70 to Licenses DPR-24 & DPR-27, respectively, allowing relaxation of monthly turbine stop & governor valve tests during end of cycle operation CLARK, R A Operating Reactors Branch 3 82/10/15 7pp 15836 319 24X Fiche 50-266, 82/10/15,8210270294
- --8210270302 Safety evaluation supporting Amends 65 % 70 to Licenses DPR-24 & DPR-27, respectively
 4 Office of Nuclear Reactor Regulation, Director 82/10/15 2pp 1533 325 24% Fitch 50-266/92/10/15/8210270294
- --8210270303 Notice of issuance & availability of Amends 65 & 70 to Licenses DPR-24 & DPR-27, respectively CLARK, R A Operating Reactors Branch 3 82/10/15 2pp 19835 327 24X Fich: 50-266, 82/10/15,8210270274
- B210260476 Application to amend Licenses DFR-24 & DFR-27, revising Tech Spec re administrative control of high radiation areas FAY, C H Hisconsin Electric Power Co 82/10/19 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 15806 833 24X Fiche 50-266, B2/10/19, B210260476
- --8210R60477 Proposed Tech Spec changes incorporating revisions re administrative control of high radiation areas • Misconsin Electric Power Co 82/10/19 ip 15804 235 24x Fich 50-266,82/10/19,8210260476
- G210280295 Application to amend Licenses DPR-24 & DPR-27, changing Tech Specs re requirements for periodic leakage rate testing of containment atrlock doors Class I & II amend fees encl FAY.C W. Wisconsin Electric Power Co. 82/10/21 DENTON.H R Office of Nuclear Reactor Regulation. Director Spp. 15837 272 24X Ficher 50-266,82/10/21,8210280295
- ~-8210280298 Tech Spec Change Request 82, changing requirements for periodic leakage rate testing of containment air lock doors + Hisconsin Electric Fouer Co 82/10/21 4pp i5807 275 24X Fiche 50-266, 82/10/21, B210280295
- B210290294 Provides results of confirmatory analysis demonstrating that unacceptable radioactive release from containment uould not take place as result of smell break LOCA in which operator action required Radioactive release negligible FAY.C H. Hisconsin Electric Fower Co 82/10/22 CLARK, R A Operating Raactors Branch 3 ip 15653 135 24% Ficha 50-266,82/10/22,8210290294
- O Inspection reports, IE Bulletins & correspondence
- 8i07270156 Forwards add1 info in response to IE Bulletin 60-il remasonry walls Thirteen repts & 109 oversite drawings encl Aperture cards are available in PDR FAYs.W Hisconsin Electric Power Co. 81/07/17. DENTON.H R Office of Nuclear Reactor Regulation. Director. CLARK, R Operating Reactors Spanch G. 19pp. Available at NTIS 09151,026 24X Fichs 50-266,81/07/17.8107270156
- --8107270161 "Model Contribution to Dynamic Analysis Results"

 * Computer Engineering Services Inc R553 02, 81/07/31 115pp
 09151-045 24K Fiche 50-266.81/07/17.8107270156
- --8107270166 "Cyclic Loading Tests of Masonry Bingle Piers, Vol 1 Height to Width Ratio of 2 " HIDALOG, PA, HAYEB, R.L., MCNIVEN, H D California, Univ of, Berkeley UCB/EERC-78/27 Vol 78/11/30 Idipp Available at NTIS 09151-158 24X Fiche 50-266.81/07/17.8107270156
- --8107270169 "Cyclic Loading Tests of Hesonry Bingle Piers, Vol 2 Height to Width Ratio of 1."

 CKEN,B J. HIDALGO,P A. HAYEB,R L California, Univ of, Berteley. USP/EERC-78/28 VO2 78/12/31. 188pp 09:51 298 24x Fiche. 50-266.81/07/17.8107270356
- --8107270174 "Cyclic Loading Tests of Hesonry Bingle Plers, vol 3 Height to Width Ratio of 0.5."
 HIDALCO.P A , MAYES.R L , MCNIVEN.H D California, Univ of, Berieley UCB/EERC-79/12 V03 79/05/31. 154pp Available at NTIB 0915R 124. 24X Ficher 50-266,81/07/17,8107270136.

- --BIO7270182 "Shating Table Study of Single-Story Masonry Houses, Vol 2-Test Structures 3 & 4 " GULKAN, P. MAYES, R. L. CLCUUGH, R. H. Cailfornia, Univ. of, Berbele, UCB/EERC-79/24 VO2 79/09/30 300pp 09153 184 24x Fishe 50-266, 81/07/17, 8107270156
- "-Bi07270185 "Shaking Table Study of Single-Story Masonry Housesivil]
 Summary, Conclusions & Recommendations "
 CLOUGH.R M., MAYES.R L., GULKAKIP California, Univ. of, Bertaly,
 UCB/CERC-79/28 VO3 79/09/20 ilopp Available at RTIE
 09134 078 24X Fiche 50-266, 81/07/17.8107270156
- --810727018B "Cyclic Shear Tests of Masonry Piers, Vol 1 Test Regults":

 MAYES, R L , CMATE, Y , CLQUOH, R W California, Univ of, Berssleg
 EERC 76-8 76/05/31 105pp 09154 182 24X
 Fiche 50-266.81/07/17.8107270156
- --B107270191 "Cyclic Shear Tests of Masonry Piers, Vol 2 Analytis of Test Resolts " MAYES, R L. GMATE, Y. CLGUOH, R W. California, Univ. of, Qeriple, EERC 76-16 76/06/30 78pp 09154 288 24X Fiche 50-266, 81/07/17, 8107270156
- --Bi07270194 "Strength of Timber Roof Connections Subjected to Cyclic Loads "

 OULKAN.P., MAYES.R.L., CLOUGH.R.W. California, Univ. of, Barasa, UCB/EERC-78/17 78/09/30 171pp 09195 005 24X Fiche 50~266.81/07/17.8107270156
- --8107270196 "Literature Survey Transverse Etrength of Matoniy Well," DMATE,Y . MAYES,R L . CHEN,S J Callfornia, Univ of, Deradis, . UCG/EERC-77/07 77/03/21 149p 09155 140 24x
 Fiche 50-266,81/07/17.8107270156
- --8107270198 "Literature Survey Compressive Tensile Bond & Bhear Simon of Masonry "
 MAYES R L . CLOUGH R H California Univ of Bertaley EERC 75-15 75/06/30 212pp 09155 286 24X Fiche 50-266,81/07/| B107270136
- --8107270197 "State-of-the-Art in Ssismic Shear Strength of Heat-s, Evaluation & Review "
 MAYES.R L., CLOUGH.R H Cailfornia, Univ of, Bartelsy Efs.
 75-21 75/10/31 147pp 09156 135 24X Fiche 50-266.81/074/18107270156
- 82:0070007 Responds to FDIA request for eight tategories of reresting steam generators & steam turbines App A documents provided in R Vdell FGIA Request 81-313 Forwards documents listed in App 8.

 FELTON.J M Division of Rules and Records 82/08/10 LCM9.D J Hinthrop. Stimson. Putnam & Roberts 9pp 15645 060 24K Fiche 50-000.82/08/10.8210070007
- --8210070139 Forwards tabulated data on steam generator into be approximated to licensees

 FPOLITO.T Operating Reactors Assessment Branch 82/04/01

 VAROA-B Operating Reactors Branch 1. 5pp 15645 131 241

 Fiche 50-000,82/08/10,8210070007
- --8210070172 Forwards info re steam generator integrity t inspects operating PMRs, per 750320 & 21 requests Details of inigs, including defect indications, tube plugging criteria & tubes plugged with not be provided except for Point Beach i OOLLER.K R Division of Reactor Licensing (MRR-1975 only) 75/03/24, MACCARY, R Division of Technical Review (MR-18) only) 5pp 15445 196 24X Fiche 50-000,82/08/10,8210070007
- 8210040414 Forwards Amends 63 & 68 to Licenses DPR-24 & DPR-27. respectively, safety evaluation & notice of issuance & availability Amends revise inservice insp Tech Spect CLARK, R A Deprating Reactors Branch 3, 82/09/31 FAY, Wisconsin Electric Power Co 5pp 15597 134 24X Ficher 50-266, 82/08/31,8210040414
- --8210040420 Amends 63 & 68 to Licenses DPR-24 & DPR-27.respectively revising language of Tech Specs re inservice inspectively requirements of safety class components to conform L/10CFRS0.55
 CLARK. R. A. Operating Reactors Branch 3 82/08/31 16/7
 13597 139 24X Fichs 50-266/82/08/31/8210040414
- --8210040425 Bafety evaluation supporting Amends 63 & 68 to titteen DPR-24 & DPR-27, respectively. * Office of Nuclear Reactor Regulation, Director 82/08/31 & 15597-155. 24X Fichs 50-266-82/08/31.8210040414

- --P206210571 "Point Beach Nuclear Plant Units 1 & 2 Inservice Insp Program Technical Evaluation Rept" * Science Applications, Inc NRC-03-82-096 SA1-186-028-22 82/04/15 NRC - No Dotailed Affiliation Given 20pp 15597 159 24X Fiche 50-266,82/08/31,8210040414
- --P210040427 Notice of issuance & availability of Amends 63 & 68 to Licenses DPR-24 & DPR-27.respectively CLARY.R A Openating Reactors Branch 3 82/08/31 3pp 24X Fiche 50-26,82/08/31,8210040414
- 8210050186 Forwards IE Insp Repts 50-266/82-12 & 50-301/82-12 on 820503-04 & 0615 & notice of violation FPPLER.J 0 Region 3. Office of Director 82/09/15 BURSTEIN, 8 Wisconsin Electric Power Co 3pp 15611 115 24X Fiche 50-266, 82/09/15, 8210050186
- --9210050194 Notice of violation from insp on 820503-04 & 0615 PEPPLER, J G Region 3, Office of Director 82/09/15 3pp 15611 118 24X Fiche 50-266, 82/09/15, 8210050186
- --8210050205 lE lnsp Ropts 50-266/B2-12 & 50-301-82-12 on B20503-04 & Obi5 Noncompliance noted failure to control access to high radiation areas & failure to follow approved procedures LOVENDALE,P C . HADUE,R L . GREGER,L R Region 3, Office of Director 82/07/13 Spp 15611 121 24X Fiche 50-266,82/07/15, P210050186
- 8210050256 Requests relief from ASME Section XI, inservice insprequirements re frequency of reactor vessel interior exam FAY, C IS disconsin Electric Power Co 82/09/29 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 4pp 15610 286 24X Fichs 50-266, 82/09/29, 8210050256
- 8210190669 Forwards IE Insp Repts 50-266/82-20 & 50-301/82-20 on 820914-16 No noncompliance noted LIFTLE.N S Division of Engineering & Technical Programs 82/10/04 BURSTEIN.S Wisconsin Electric Power Co 2pp 15738 152 24X Fiche 50-266.82/10/04.8210190669
- --8210190675 IE Insp Repts 50-266/82-20 & 50-301/82-20 on 820914-16 No noncompliance noted Major areas inspected surveillance & calibr procedures & performance history HASSF.R A , PEGCHEL.J M , HAWKINS.F C Division of Engineering & Technical Programs 62/09/29 App 15738 154 24X Fichs 50-266.82/10/04.8210190669
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.t. 1 Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 23
- 9209170239 IE Bulletin 92-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation Sys Piping at UNR Plants " Svc list encl DEYDUNO.R C Director's Office Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co. of New York 115pp 15810 125 24X Fiche 50-000.82/10/14,8208190238
- A Periodic operating reports & related correspondence
- E210150150 Forwards monthly operating repts for Sept 1982 FAV.C N Misconsin Electric Power Co B2/10/11 Office of fluctear Reactor Regulation, Director ip 15697 074 24X Fiche 50-226.82/10/11.8210150150
- --8210150158 Monthly operating repts for Sept 1982 FAY: C W Hisconsin Electric Power Co 82/10/04 8pp 15697 075 24X Fiche 30-266/82/10/11/8210150150
- Reportable occurrences, LERs & related correspondence
- B2101203B0 Advises that operator action necessary to protect B&W plants from excessive feedwater translents B&W plants do not employ high steam generator level turbine or reactor trips to protect against translents CRESMELL.J S Director's Office. BO/09/12 HICHELSON, C. Director's Office 34pp 15689 284 24X Fiche 50-327, 80/09/12, B2101203B0
- 3210040325 Forwards updated LER 82-005/017-0 FAY.C W Hisconsin Electric Power Co 82/09/28, KEPPLER, J Q. Region 3, Office af Director 1p 15616 022 24X Fiche 50-301,82/09/28,8210040325

- --8210060333 Updated LER 82-005/017-1 on 820727, discovered 2 of 3 level Instruments on C borlo acid storage tank powered from common source Gause not determined due to poor early maint of documents Wirlng corrected FAY, C W Wisconsin Electric Power Co 82/09/28 Region 3, Office of Director 5pp 15616.023 24X Fiche 50-301, 82/09/28, 8210060325
- T Hearing transcripts on non-antitrust matters
- 8210080052 Transcript of 821006 telephone conference to discuss rescheduling of hearing in Mashington.DC Pp 1.342-1.352 * Atomic Safety and Licensing Board Panel 82/10/06 12pp 15643 284 24X Fiche 50-266.82/10/06.8210080052
- DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8210270227 Forwards IE Bafequards Insp Rept 50-302/82-17 on 820706-09 & notice of violation. Notice of violation & rept details withheld (ref 10cfR73_21)

 LEWIS.R C Division of Project & Resident Programs 82/07/26

 HANCOCK.J A Florido Power Corp 2pp. 15823.007 24X

 Fiche 30-302,02/07/26,8210270227
- --0210270239 IE Safeguards Insp Rept 50-302/82-17 on 820706-09 Noncompilance noted failure to initiate adequate compensatory measures Details withheld (wef 100FR73 21) PERNY, C. MCOVIRE, D. R. Division of Engineering & Technical Programs 82/07/22. 19 15823 009. 24% Fiche.50-302,82/07/26,8210270229
- B210260370 Ack receipt of 820825 ltr Informing NRC of steps taken to correct violations noted in IE Safeguards Imap Rept 50-302/82-17 Encl containing safeguards info withheld (ref 10CFR73 21)
 LEWIS.R C Division of Project & Resident Programs 82/09/17 HANCOCK.J A Florida Power Corp 2pp. 15804 255 24X
 Flche 50-302,82/09/17.8210260370
- --8210260377 Forwards response to NRC 820726 ltr re violations noted in IE Safeguards Insp Rept 50-302/82-17. Details withheld (ref 10CFR73 21 & 10CFR2 770)

 BAYNARD, P. Y. Florida Power Corp 82/08/29 O'REILLY, J. P. Region 2, Office of Director ip. 15804 257 24% Fiche 50-302,82/09/17,8210260370
- 8210010379 Ack receipt of 820907 ltr informing NRC of steps taken to correct swargency planning deficiencies noted in IE Insp. Rept 50-302/82-08 LEHIS:R C Division of Project & Resident Programs B2/09/20. HANCOCK, J A Florida Power Corp Ip. 15573-053 24X Fiche 30-302, 82/09/20. 8210010379.
- 8210010044 Ack receipt of 820701 ltr Informing NRC of steps taken to correct emergency preparedness deficiency noted in IE
 Emergency Preparedness Appraisal Rept 50-302/81-14
 LEWIS.R C Division of Project & Resident Programs 82/09/22.
 HANCOCK.J A. Florida Power Corp ip 19565-320 24X
 Fithe 80-302, 82/09/22, 8210010044
- --8210010049 Responds to NRC 810911 ltr re emergency preparedness deficiency noted in IE Emergency Preparedness Appraisal Rept 50-302/81-14. Corrective actions new meteorological tower to be built west of plant.

 MRDIG.D C. Florida Power Corp. 82/09/01 CFREILLY, J.F Region 2. Office of Director ip 19569 321. 24X Fiche. 90-302, 82/09/22, 8210010044
- 8210260008 Releases public version of revised radiological amergency response plan
 FELTON-J.M. Division of Rules and Records. 82/10/05, Document Management Branch. 1p. 15811.001. 24X Flche 50-302,82/10/05, 8210260008.
- --8210260010 Forwards public version of Revision 1 to radiological emergency response plan, in response to NRC 820408 ltr 8AVNARD, P Y. Florida Fower Corp. 82/09/28. Q'REILLY, J. P. Region 2. Office of Director ip 15811 002. 24X Fiche: 50-302.82/10/05, 8210260008
- --8210260012 Public version of Revision 1 to radiological emergency response plan.
 4 Florida Power Corp. 82/08/27, 388pp. 15811 003 24X Ficha: 50-302.82/10/05,8210260008

- 8210260309 Ack receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-302/82-17 -302/82-17 50-302/42-17

 LEMJS.R C Division of Project & Resident Programs B

 HANCOCK.J A Florida Pover Corp ip 15802 361 24X

 Fiche 50-302, 82/10/22, 8210260309 82/10/22
- ~-8210260310 Responds to NRC 820917 ltr re violations noted in IE Safeguards Insp Rept 50-302/82-17 Corrective actions withheld (ref 10CFR2 790 & 10CFR73 21) BAYNARD.P Y Florida Power Corp 82/10/15 D/REILLY,J P Region 2, Office of Director ip 15802 362 24X Fichs 50-302,82/10/22,8210260309
- P Operating license stage documents & correspondence
- 8210180010 Forwards request for add1 info re Unresolved Sefety Lasue 8-24 re operability of purge valves STOLZ, J F Operating Reactors Branch 4 82/09/20 HANCOCK, J A Floride Power Corp 7pp 15717 353 24X Fiche 50-302, 82/09/20, Florida Power Corp B2(0180010
- 8210180035 Advises that plant emergency feedwater automatic initiation te flow indication sys comply w/NRC long-term safety-grade requirements w/exception re control room indication of overriding automatic initiation capability STOLZ-J F Operating Reactors Branch 4 82/09/27 HANCOCK, J A Florida Power Corp 7pp 13746 260 24X Fiche 50-302,82/09/27, 031418005 82101B0035
- --8208190290 "Auxiliary Feedwats" Sys Automatic Initiation & Flow Indication, Crystal River Unit 3." technical evaluation rept KAUCHER, J E Franklin Institute/Franklin Research Center NRC-03-79-118 TER-05257-282 82/08/17 KENBALL, R NRC N Detailed Affiliation Given 16pp. 15746-267. 24X Fiche 50-302,82/09/27,8210180035 NRC - No
- 8210050198 Submits update to 801106 responses to interim reliability evaluation program study recommendations No further comments offered EAYNARD, P Y Fiorida Power Corp 82/09/29 BTDLZ. J F Operat Reactors Branch 4 5pp. 15614 010 24X Fiche 50-302, 82/09/29,
- 8210060263 Submits orimary test results re yearly goal for containment purging time, per TMI Action Item II E 4 2, based on data collected during 30-day test period which BaynaRD.P Y Floride Power Corp. 82/09/29 STDLI, J.F. Operating Reactors Branch 4 2pp [582] 063 24% Fiche 50-302,82/09/29, 6810060263
- 8210150216 Requests exemption from 10CFR50 44(c)(3)(iii) requiring reactor vessel head high point vent Alternative methods for vent performance provided in util 810130 submittal, in response to NUREG-0737, Item II B. It BAYNARD, P Y Florida Power Corp. 82/10/12. 8TOLZ, J F Operati Reactors Stanch 4 3pp. 15705:283 24X Fiche 50-302,82/10/12, 0210180014 Coerating 8210150216
- 8210190691 Provides add1 into re dose calculations for NUREG-0737, Item II B 2. " Design of Plant Shielding & Environ Qualifications of Equipment for Spaces/Equ Which May Be Used in Post-Accident Operations "

Y Florida Power Corp B: 'ranch 4, 2pp 15736 201 82/10/12 STOLZ, J F Operating 1 24% Fithe. 50-302, 82/10/12,

> term work schedule re NUREQ-0630. "lodels for LOCA Analysis," not is to incomplete short-term d w/MC approval of rept irp 82/10/14 LAINAS.O C, Assistant 1p. 15738-145 24X

> > ivisors licensed at senior : & NUREQ-0737. rent candidates

EISENHUT, D Q Division 302. 82/10/15.

itian

Operating /10/18

- 8210260436 Forwards revision to 820219 submitted re calculations & measurements of bus voitages used to demonstrate adequaty of electrical distribution sys BAYNAND.P Y Florids Power Corp 82/10/19 STOLZ.U F BAYNARD, P Y Florida Power Corp 82/10/19 STOLZ, J F Desait: Reactors Branch 4 45pp 15806 246 24% Fithe 50-302,82/10/19, 8210260436
- 82:0260422 Requests concurrence w/interim plan to maintain lines and for chemistry control in once-through steam generators in high energy line state during each startup until Refuel V Condition reported in LER 82-058 Amend fee will be sent BAYNARD, P Y Fiorida Power Corp 82/10/22 SYOLZ, UF Optral Reactors Brench 4 2pp 15806 312 24X Fiche 50-302,02/10/22 8210260422
- 8210260454 Updates status of safe-end task force action plan Task force activities expected to be concluded by 821231 Final rept & recommended implementation plans will be submitted by 8210260454
- 8210260497 Submits responses to Encl 1. Questions 1 & 2 in KRC 82.55 lite to Generic Item 8-24, "Operability of Purge Valves"

 Wiffive oversize drawings Aperture cards are available in PUK BAYNARD, P.Y. Florida Power Corp. 82/10/22 STOLT. J.F. 82914 Reactors Branch 4 3pp. 15805 244 24X Fiche 50-302,02/10/22 8210260497 Operat. 4
- Q Inspection reports: IE Bulletins & correspondence
- 8210080015 Addi response to FOIA request for 19 categories of lefs : nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld inge FDIA Elemption 5) FELTON. J M Division of Rules and Records 82/07/12 UDELL.# L Critical Mass Energy Project 7pp 18645 027 24% Fiche 50-000,82/07/12,8210080015
- --8210080125 Bystemetic assessment of licensee performance notes is facility evaluation for May 1979-Apr 1980

 * NRC - No Detailed Affiliation Given 80/04/30 7pp 15667 327 24% Fiche 30-000, 82/07/12, 8210080015
- 8210270229 Forwards IE Safeguards Insp Rept 30-302/82-17 on 023/427 & notice of violation Notice of violation & rept details withheld (ref 10CFR73 21) LEWIS-R C Division of Project & Resident Programs B2 HANCOCK, J A Florida Power Corp 2pp 15823 007 24x Fiche 50-302, 82/07/28, 8210270229 82/07/21
- --B210270239 IE Bafeguards Insp Rept 50~302/B2-17 on 020706 07 Noncompliance noted failure to initiate adequate compensatory measures Details withheld (ref 100FR73 21) PERNY. C. . MCGUIRE, D.R. Division of Engineering & Technical Programs 82/07/22 ip 15823 009 24X Fiche 50 302.07/1.a 8210270229
- 8210260370 Ack receipt of 820825 ltm informing NRC of steps tales to correct violations noted in IE Safeguards Insp Rept 50-302/82-17 Enci containing safeguards into withheld tref 10CFR73 21) HANCOCK, J A Florida Power Corp 2pp 15804 255 24x Fiche 50-302, 82/09/17, 8210260370. 02/09/11
- -8210250377 Forwards response to NRC 820726 ltr re violations c.tr E Safeguards Inep Rept 50-302/82-17 Details withheld (ref 100FR73 21 & 100FR2 790)

 100FR73 21 & 100FR2 790)

 21 Office of Director 1p 13804 257 24X Fiche 50-307.873
- 8210010379 Ack receipt of 820907 ltr informing NRC of sleps false correct emergency planning deficiencies noted in It lass Rept 30-302/82-08 HANCOCK.J.A Florida Power Corp ip. 15573 053. 241 Fiche 50-302, 82/09/20, 8210010379. 82764723
- 8210010044 Ack receipt of 820901 ltr informing NRC of steps talest correct emergency preparedness deficiency noted in 16 Emergency Preparedness Appraisal Rept 50-020/81-14 LEUIS, R. C. Division of Project & Resident Programs 82/04/22 HANCOCK, J. A. Florida Power Corp ip 15565:320 24x Fiche 50-302, 82/04/22 B210010044

- --E210010049 Responds to NRC Bi0911 ltr re emergency preparedness deficiency noted in IE Emergency Preparedness Appraisal Rept 50-302/81-44 Corrective actions new meteorological tower to be built west of plant MARDIS.D G Florida Power Corp B2/09/01 D'REILLY, J P Region 2. Diffice of Director ip 15569 321 24X Fiche 50-302,82/09/22,82(0010044
- 8208190233 IE Info Notice 80-35, Suppl t. "Leaking & Dislodged I-125 Implant Seeds" Svc list encl CO88.L I Division of Fuel Facilities, Materials & Safeguards. 82/10/06 Consolidated Edison Co of New York 66pp 15761 256
- 9208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at 6WR Plants "Svc list encl OEYGUNG.R C Orrector's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 '24X Fiche 50-000, 82/10/14:8208190238
- 8210260309 Ack receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-302/82-17

 LEMIS.R C Division of Project & Resident Programs 82/10/22.

 HANCOCK.J A Florida Power Corp ip 15802 361 24X

 Fiche 50-302. 82/10/22,8210260309
- --0210260310 Responds to NRC 820917 ltr re violations noted in IE Safeguards Insp Rept 50-302/82-17 Corrective actions withheld (ref 10CFR2 790 & 10CFR73 21) EAVNARD, P Y Florida Power Corp 82/10/15 0'REILLY, J P Region 2. Office of Director ip 19802 362 24X Fiche 50-302, 82/10/22, 8210260309
- S Reportable occurrences, LERs & related correspondence
- 8004020420 Discusses decay heat closed cycle cooling water pump motor being out of spec Gaused by inadequate lubrication Problem highlights volnerability of nuclear pawer plants to inadequate lubrication Specs & work order encl ORNSTEIN.H L Director's Office 80/03/20 MICHELSON, C Director's Office 4pp 15649 237 24% Fiche 50-302, 80/03/20, 8001020420
- 8210120380 Advises that operator action necessary to protect I&W plants from excessive feedwater transients B&W plants do not employ high steam generator level turbine or reactor trips to protect against transients
 CRESWELL, J & Director's Office 80/09/12 MICHELGON, C
 Director's Office 34pp 15689 286 24% Fiche 50-302,80/09/12, 82:0120380
- 8010230435 Forwards summary of 800930 transient, alligator clip event While at 100% power, instrument test leads fell causing feedwater runback & control rod insertion ORNSTEIN, H L Director's Office 80/10/08 MICHELSON, C Director's Office 3pp 15692 265 24% Fiche 50-302, 80/10/08, 8010230433
- 3012290818 Discusses conclusions of engineering evaluation of steem generator overfull translents at C-E & Hestinghouse plants LAUNING. H D Director's Office 80/10/29 MICHELSON, C Director's Office 3pp 15692 262 24X Fich
- 3210010000 Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents
 listed in App A
 FELTON: J M Division of Rules and Records 82/06/28 UDELL. R. A
 Critical Mass Energy Project 15pp 15727 003 24X
 Fiche 30-000, 82/06/28, 8210010008
- --8106150555 Informs that ESFAS relay failure reviewed to determine significant number of failures, safety consequences & qualifications of ESFAS relays Failure considered simple isolated event & does not warrant further action EAINAS, 0 C Assistant Director for Safety Assessment 81/05/05. EISENHUT, D 0 Division of Licensing 2pp 15730 137 24X Fiche 50-000,62/06/28,8210010008
- --BIOPOBO417 Concludes that no addl actions are required re engineered safeguards relay failures Various relays, including new Crydon relays, should be monitored as watch list items Failures after Sept 1981 outage should be reviewed CHIRAMAL, M Director's Office BI/08/28 MICHELSON, C Director's Office 2pp 13730 128 24% Fiche 50-000, 82/06/28, E210010D08

- --8210010161 Discusses potential problem re Sequoyah reactor pressure nozzle, supplementing 800222 memo Underclad cracks found by use of ultrasonic equipment Add1 stems of recent origin discussed Related info encl
 DENTON.H R Office of Nuclear Reactor Regulation, Director 80/02/28 AMEARNE.J., OILINSKY,V., KENNEDY,P. Commissioners 9pp 15727 178 24X Fichs 50-000, 82/04/28, 8210010008
- 8210130310 Forwards LER 52-045/03L-0

 HARCOCK, J A Florida Power Corp 62/10/01 D'REILLY, J P Region
 2. Office of Director 1p 19678 338 24x Fiche 50-302, 82/10/01,
 8210130310
- --B210130319 LER 82-045/03L-0 on 820704, emergency feedwater ultrasonic flow indicator FW-313-FI discovered insperable & train 8 arbitrarily declared insperable Caused by failed power supply. Power supply replaced & indicator repaired FORD, E W Florida Power Corp 82/10/01 Region 2, Office of Director 2pp 15678 339 24X F1che 50-302, 82/10/01, 8210130310
- 8210130520 Forwards LER 82-057/03L-0 HANCOCK, J A Florida Power Corp 82/10/01 D'REILLY, J P Region 2. Office of Director 1p 15682 352 24% Fiche 50-302, 82/10/01, 8210130520
- --B210130930 LER 82-057/03L-0 on B20527.containment isolation valve in svc water sys (SNV-49) not stroke time tested following maint Caused by personnel failure to include stroke time testing in work request Naint planners instructed FORD.E W Florida Power Corp. B2/10/01 Region 2. Office of Director 2pp 15682 353 24X Fiche 50-302.82/10/01.8210130320
- 8210190677 Farwards LER 92-058/01T-0 LUTKEHAUS,T C Florida Power Corp 82/10/08 O'REILLY,J F Region 2. Office of Director ip 15738 162 24% Fiche 50-302,82/10/08, 8210190677
- --8210190687 LER 82-098/01T-0 on 820924, valve lineups identified which allow once through steam generator drain lines to be used for bloudoum operations & also allows high energy fluid through lines Caused by inadequate review of 94% design WILSON.K R Florida Power Corp 82/10/08 Region 2. Office of Director 2pp 15738 163 24% Fiche 50-302,82/10/08,8210190677
- 8210190271 PNO-II-82-313 on 821014.rise in airborne radioactivity levels in reactor bidg detected Caused by leak in vicinity of reactor coolant drain tank Unit shut down & will be out of svc for about 3 wks to investigate & repair leak ROGGE, J.F., BROWNLEE, V.L. Rogion 2, Office of Director 82/10/15. 2p 15737 241 24% Fiche 50-302,82/10/15,8210190271
- 8210220052 Forwards LER 82-057/03L-0.

 HANCOCK.J A Florida Power Curp 82/10/15 O'REILLY.J P Region 2. Office of Director 1p 15778 207 24% Ficha: 50-302,82/10/15,8210220052
- --8210220086 LER 82-059/031-0 on 820715 valve DHV-111 on decay heatline B failed to control flow Caused by inoperable flow switch Switch replaced & calibr & DHV-111 functionally tested U/satisfactory results. HUGHES,P.O Florida Pour Corp 62/10/15 Region 2, Office of Director 2pp 15778: 208 24% Fiche: 50-302, 82/10/15, 8210220052
- 6210290186 RD 82-058 high energy lines exist in reactor bldg Study on restraining lines for sips whip completed Albarnatives under review Requests approved to maintain lines until Refuel 5
 BAYNARD, PY Florida Power Corp 82/10/22 STOLZ, J. F. Operating Reactors Branch 4 2pp 15853 209 24% Fiche 50-302, 82/10/22, 8210290186
- 8210290312 Informs that special rept supposedly encl in 821001 submitted LER 82-045 determined to be more useful as basis of Tech Spec change request to be submitted at later date. BAYNARD. P Y Florida Power Corp. 82/10/25, 0'REILLY, J P. Region 2, Office of Director ip 15853.158 24X Fiche 50-302,82/10/25,8210290312
- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8209290125 Releases gublic version of revised generating station emergency plan corporate command ctr emergency plan implementing procedure.
 FELTON, J M. Division of Rules and Records 82/09/16 Decument Management Branch 1p. 15564, 122 24X Fiche: 50-000, 82/09/16, 8209290125.

- --B209290189 Forwards public version of Revision 4 to generating station emergency plan corporate commend of Emergency Plan Implementing Procedure EGF-3, "Environ/Emergency Coordinator " Receipt form enci PAJOHSKI.J E Commonwealth Edison Co 82/09/01 DENTON, H R NRC No Detailed Affiliation Given 1p 15564.123 24X Fiche 50-000,82/09/16,8209290125
- --B209270225 Public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EOF-3, "Environ/Emergency Coordinator" PAJOWSKI. J E Commonwealth Edison Co B2/08/31 11pp 15544 124 24X Fiche 50-000, B2/09/16, B209270125
- G210080029 Releases public version of revision to emergency plan implementing procedure FELTON, JH Division of Rules and Records B2/09/22 Document Managament Branch ip 15669 307 24X Fichs 50-295,82/09/22.
- --B210080030 Forwards public version of Revision 3 to Emergency Plen Implementing Procedure EPIP 550-3. "Radiological Supplies for Medical Emergencies " Receipt form encl PLIML.0 Commonwealth Edison Co 82/09/07 DENTON, H R NRC ~ No Debailed Affiliation Given ip 15569-308 24X Fiche-50-295,82/09/22,82(0080029
- --8210080031 Public version of Revision 3 to Emergency Plan Implementing Procedure EPJP 850-3, "Redictogical Supplies for Hedical Emergencies "Procedure chengs request form encl. + Commonwealth Edison Co 82/07/03 Bpp 15669 309 24X Fiche 50-295,82/09/22,8210080029
- B210050207 Forwards revised exemption requests from provisions of iOCFR50, App R. Bection III. 0 2 rs post-fire shutdown capability, per 820917 tellcon LENTING. F G Commonwealth Editor Co B2/10/01 DENTUN, H R Office of Nuclear Reactor Regulation, Director. 30pp. 15611 086 24X Fiche 50-295. B2/10/01. B210050207.
- 8210130376 Advises that installation of offsite dose calculation sys program fully operational tracking model & operational A-model will be deleged until 821231 to complete prime computer installation
 SHART7.E D Commonwealth Edison Co 82/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 13682 078 24X
 Fiche 50-000.82/10/06.8210130376
- 8210290047 Releases public vertion of revisions to Guad Cities, Zion & Dresden emergency plan Annaies & revised generating station amergency plan telephone directory.
 FELTON, J. H. Division of Rules and Records B2/10/08 Document Management Branch ip. 15877 313 24X Fiche 50-000, 82/10/08, B210290047.
- --B210290060 Forwards public version of Revision 3 to Quad Cities & Zion smergency plan ennexes Revision 2 to Dreaden emergency plan ennex. Revision 0 to Byron emergency plan ennex & revised generating station emergency plan telephone directory MODRE.R D. Commonwealth Edison Co. 82/07/30. DENTON, H R NRC No Detailed Affiliation Given Spp. 15977 314 24X Fiche 50-000.82/10/08.8210290047
- ---B210370077 Public version of Revision 3 to Quad Cities \$ 710n emergency plan annexes. Revision 2 to Dresden swergency plan annex & Revision 0 to Byron emergency plan annex * Commonwealth Edison Co 82/06/30 325pp 15877,317 24X Fithe, 50-000,82/10/08,8210290047.

- 8210280419 Releases public version of revised emergency plan implementing procedure FELTON.J H Division of Rules and Records 82/10/12 botter hangement Branch 1p 15860 001 24X Fiche 50-295,62/10/12, 8210280419
- ~-8210280424 Forwards public version of Revision 5 to Emergancy Plan Implementing Procedure 110-1. "Station Director " Procedure chenge request & receipt forms enc! PLING. Gommonwealth Edison Co 82/09/17 DENTON-N R MRC 4; Detailed Affiliation Given 2pp 15860 002 24X
- --8210280427 Public version of Revision 5 to Emergency Plan Ispless**
 Procedure 110-1, "Station Director " Revised index and
 * Commonwealth Edison Co 82/09/16 5pp 15860 004 24x
 Fiche 50-295,82/10/12,18210280419
- 8210280442 Releases public version of revised emergency plan implementing procedure FELTON. J M Division of Rules and Records 82/10/12 Deciset Hanagement Branch. is 15859 001 24X Fiche 50-295,82/10/12, 2010/20422.
- --8210280445 Forwards public version of Revision 4 to Emergency Plar, implementing Procedure EPIP 550-2, "Environ Emergency Kit & Emergency Operations Faculity Reduciogical Equipment Receipt form enc.!

 PLIMI. 0 Commonwealth Edison Co. 82/09/10. DENTON: If R Not 1 Detailed Apriliation Given ip 15859 002 24X Fiche 50-295, 82/10/12, 8210280442
- ~-8210280447 Public version of Revision 4 to Emergency Plan Implementing Procedure EPIP 550-2. "Environ Emergency Kit & Emergency Operations Faculity Radiological Equipment" Procedure change request form encl # Commonwealth Edison Co 82/09/03 8pp 15057 003 24x Fiche 50-295,82/10/12.8210280442
- B210220358 Provides info re organization & performance of dapts responsible for rediction protection activities, per 920702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs.

 TRAMM.T.R Commonwealth Edison Co 82/10/14 DENTON:HR Director 9pp 15776 287 241 Fiche 50-000, 82/10/14, 8210220358
- 8210280405 Notification of 821028-29 meetings w/util & DNL in Faltick MD to discuss & resolve questions on proposed exemption to App R WIGOINTON, D Operating Reactors Branch 1 82/10/22 VARGA.9 a Operating Reactors Branch 1 2pp 15859 327 24X Fiche 50-295, 82/10/22 8210280405

H General correspondence

- 8210210235 Comments on facility operation NRC should deny util permission to use high burnup nuclear fuel Evidence supporting continued operation of facility should be provided to public GUIGO.C Pollution & Environmental Problems. Inc 82/10/15 Director's Office, Office of Inspection and Enforcement 5,9 15766.259 24X Fichs 50-295,82/10/11.8210210235
- O Advisory Committee on Reactor Bafeguards reports & corresponders
- 82:0270408 Comments on probabilistic risk assessment per fil??!

 math.General methods & principles employed in analysis of
 possible earthquaks shaking & site appear to apply modern
 state of art techniques.

 TRIFUNAC.M D Bouthern Californie, Univ of TRIFUNAC.K D AM
 Advisory Committee on Reactor Safeguerds 82/02/23 GRISMITT.

 ACRS Advisory Committee on Reactor Safeguards 3pp 15872/23
 24X Ficher 30-299,82/02/23,8210274048.
- P. Operating license stage documents & correspondence
- 8007150303 Notifies that review will be conducted of Offshers femiliator-term risk studies using various resources, in respense to 800605 request Evaluation will be submitted by 800922 MATTSON, R. J. Division of Bafety Technology 80007702 EIBENHUT, D. O. Division of Licensing. 2pp. 02952-301, 24% Fiche-50-247, 80/07/02, 8007150303.
- 8210070007 Responds to FDIA request for eight categories of exercise steam generators & steam turbines App A documents provided in R Udell FDIA Request Bi-313 Forwards documents listed in App B.

 FELTON: J M Division of Rules and Records 82/08/10 LOW Bd Winthrop, Stimson, Putnem & Roberts 9pp. 13645:063 2NI Fiche: 30-000, 82/08/10, 8210070007

- -8203110403 Forwards response to JD Dumele, chairman of Pollution Control Board, State of IL. questions in 820127 ltr JCHNISTON, H V Assistant Director for Materials & Qualifications Engineering 82/02/22 LAINAS. O Assistant Director for 8afety Assessment 2pp 15643 126 24X Fiche 50-000, 82/08/10, 821002007
- 209160503 Supple 820831 ltr re 820908 mesting at Region 3 ofc Recent operation of Unit 2 w/two inoperable auxiliary feedwater pumps added to agenda KEPPLER, J G Region 3. Office of Director 82/09/03 REED, C Cognonwealth Edison Co ip 14904 087 24X Fichs 50~295.82/09/03, 8209160503
- 210040218 Requests reaffirmation of technical basis for operation at 1002 power Significant financial penalties incurred dus to operation in overly conservative manner STIEDE. H. Commonwealth Edison Co. 82/09/27 DEYOUNG.R.C. Director's Office, Office of Inspection and Enforcement. 3pp. 15593 115 24X Fiche 50-295,82/09/27,8210040218
- 210080111 Forwards compistion status & revised scheduls for improvements mads to control room display since 1980 rapt, per 900229 confirmatory order LENTINE, F. Q. Commonwealth Edison Co. 82/10/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp 15640 022, 24X Fiche 50-295, 82/10/04, 8210080111
- 210120105 Requests delay of Implementation due dates re NUREO-0737, Items ti p 2. "Plant Shielding," iI B 3, "Post-Accident Sampling" & II F 1 1. "Noble Qas Effluent Monitor "SHARTZ.E P Commonwealth Edison Co 62/10/04 EISENHUT, D Q Division of Licensing Spp 15651 237 24% Fichs 50-000.82/10/04. 8210120105
- '10260526 Forwards Revision 3 of Chapter 9 of "Offsite Doss Calcutation Manual" GOLDEN, J C Commonwealth Edison Co 82/10/06 CASE,E 0 Offics of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000.82/10/06.8210260526
- 8210260542 Revision 3 of Chapter 9 of "Offsits Dose Caiculation Manual"
 - # Commonwealth Edison Co 82/09/30 83pp 15805 139 24% Fiche 50-000, 82/10/04, 8210260526
- 10220399 Suppls 820414 response to Franklin Research Ctr 811005 draft technical evaluation rspt re control of heavy loads (NUREO-0612), per 820824 & 25 telcons
 LENTINE, FO Commonwealth Edison Co 82/10/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 15777 329 24% Fiche 50-295, 82/10/12,8210220399
- 10190443 Forwards addi info re NUREO-0737, Item II D 3, "Post-Accident Sampling Sys:" in response to NRC 820722 ltr
 Util currently pursuing possibility of dsveloping procedurs
 to estimate core damags via Wistinghouse owners group
 SHARTZ.E D Commonwealth Edison Co 82/10/13 EISENHUT, 0 0
 Division of Licensing 15pp 15741 187 24X Fiche 50-295,82/10/13,8210/190443
- 10270344 Notification of 821115-16 mastings w/util in 01sn Ellyn,IL to discuss bases for current inservice testing proposed exemption,including alternatives to required insps HIGGINTON,D Operating Reactors Branch I 82/10/22 VAROA,S A Operating Reactors Branch 1 2pp 15851,354 24X Fichs 50-275,82/10/22.8210270344

Inspection reports, IE Bulletins & correspondence

- 10070007 Responds to FOIA request for eight catsgorlss of records re steam generators & steam turbinss. App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App 18
- App B FELTON, J H Division of Rules and Records 82/08/10. LONG, D. J. Finthrop. Stimson, Putnam & Roberts, 9pp. 15645, 063 24X Fiche 50-000. 82/08/10. 8210070007
- 3210070139 Forwards tabulated data on steam ganarator insp & maint at facilities Data should be provided to licensess IPPOLITO.T Operating Reactors Assessment Branch 92/04/01 VAROA.B Operating Reactors Branch 1 Spp 15645 131. 24X Fiche 50-000,82/08/10.8210070007.
- 3210070172 Forwards info re steam generator integrity & insps at all operating PMRs.per 750320 & 21 requests, Details of insps. including defect indications, tubs plugging criteria & tubes plugged will not be provided except for Point Beach i. GDLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R R Division of Technical Review (NRR-1975 only) 5pp 15645 194 24X Fichs 50-000,82/08/10.8210070007.

- 821019056B Forwards IE Enforcement Conference & Insp Repts 50-295/82-19 & 50-304/82-17 on 820717-0909 & notice of violation EPESSARD.R L Division of Project & Resident Programs REED.C Commonwealth Edison Co 2pp 15736 112 24X Fiche 50-295.82/09/30.8210190568
- --8210190579 Notice of violation from insp on 820717-0831 * Division of Project & Rssident Programs 92/09/30 lp. 15/36 li3 24X Fichs 50-295,82/09/30,8210190568
- --8210170597 iE Enforcement Conference & Insp Repts 50-295/82-17 & 50-304/82-17 on 820717-0707 Noncompliance noted failure to follow 800227 confirmatory order requiring expeditious shutdown whenever auxiliary feedwater sye inoperable MATERS.J R. SCHNEIDER.O O. REVEG.L Region 3. Office of Director 82/07/22 9pp 15736.114. 24% Fiche.50-295.82/09/30, 8210170568
- 8210060359 Ack rsceipt of 820910 1tr informing NRC of steps taken to correct violations noted in IE inep Repts 50-237/81-39, 50-249/81-32, 50-249/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 SPESBARD, R L Division of Project & Resident Programs, 82/10/01 REED, C Commonwealth Edison Co Ip 15618 354 24X Fichs, 50-000, 82/10/01, 8210060359
- --B210060367 Responds to NRC B20712 ltr re violations noted in IE Insp Rspts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 Corrective actions training for mgt priorities re plant availability will be conducted REED.C Commonwealth Edison Co B2/09/10. KEPPLER, J O Region 3, Offics of Director 13pp 15418 355 24X Fichs 50-000,82/10/01,8210060359
- 8210080178 Forwards listing of piping sys which fail to mast FBAR requirements, per NRC 800818 confirmatory action ltr.iE Buistin 79-14 operability svaluation updates will not be provided for Dresden & Qued Cities Final update by Dec 1982. RAUSCH.T.J. Commonwealth Edison Co. 82/10/01 KEPPLER.J 0. Region 3, Office of Director App 15640:157. 24X Fiche 50-000.82/10/01, 8210080178
- 8208190233 iE Info Natice 80-35, Suppl 1, "Leaking & Dislodged i-125 Implant Seeds " Swc list entl COBB.L.I. Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co. of New York 66pp 18761 250, 24X Fichs 50-000:82/10/06.8208190233
- 8210190619 Act receipt of 820910 ltr informing NRC of eteps taken to correct violations noted in iE Insp Repts 50-295/82-14 & 50-304/82-13 Interpretation of Tech Spec i 0, D unacceptable SPEBSARD, R L Division of Project & Resident Programs 62/10/07 REED, C Commonwealth Edison Co. ip 15739 361 24X Ficks 50-293, 82/10/07, 8210190613
- --8210170624 Responds to NRC 820813 ltr re violations noted in IE insp. Rspts 50-295/82-14 & 50-304/82-13, Disputes NRC classification of 820625 reactor trip. Trip inadvertent Interpretation of Tsch Spec 1 0 D sncl.

 8YIEDE, W.L. Commonwealth Edison Co. 82/09/10 KEPPLER, J. 0 Region 3, Office of Director. 4pp 15740, OOt. 24X Fichs 50-295, 82/10/07, 8210190613.
- 8208190238 IE Bujketin 82-03. "Stress Corrosion Cracking in Thick-Nall, Large-Diameter, Stainless Stesl, Recirculation Sys Piping at SWR Plants " Syc list sncl DEYOUND, R C. Director's Office, Office of Inspection and Enforcement 62/10/14 Consolidated Edison Co. of New York 115pp. 15810 125 24% Fiche 50-000, 82/10/14, 8208190238
- 8210270344 Notification of 821115-16 meetings w/util in Olsn Ellyn, IL to discuss bases for current inservice testing proposed samption; including alternatives to required insps. WIGGINTON, D. Operating Reactors Branch 1, 82/10/22, VARGA, B. A. Operating Reactors Branch 1, 82/10/22, VARGA, B. A. Fiche: 50-295, 82/10/22, 8210270344
- R Periodic operating raports & related correspondence
- 8210130405 Forwards monthly operating repts for Sept 1982, GRAEGSER:K. L. Commonwealth Edison Co. 82/10/06. Director's Office: Office of Inspection and Enforcement ip, 15704.003 24X Fichs: 30-275, 82/10/06, 8210130403
- --8210150411 Monthly operating repts for Bent 1982. AUSTIN.9 Commonwealth Edison Co. 82/10/06. 11pp. 15704:004. 24X Fiche.50-295.82/10/06.8210150405.

S Reportable occurrences, LERs & related correspondence

- 8210070422 Recommends IE issue info notice to inform licenses of possible inadequate surveillance for proper tuning of quiput capacitance for certain inverters Recommendation based on 810305 & 28 sais output transformer shorts HELTEKES.C J Director's Office 81/12/10 JORDAN.E L Division of Resident & Regional Reactor Inspection 4pp 15644 285 24X Fiche 50-295.81/12/10.8210070422
- B21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON,J M Division of Rules and Records. B2/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fichs 30-000. B2/06/28.8210010008
- --Bi:210538 Forwards description of events 2 resulting action to high circulating corrent associated w/inverter output due to lack of circulat tuning IE circular or info notice should be issued to addrass issue
 HELTEMES.C. J. Director's Office Bi/12/10, JORDAN.E.L.
 Director's Office 4pp 1573i 361 24X Fiche.50-000,82/06/28,8210010008
- --8203090669 Responds to request to evaluate Bil211 trip of two inservice auxiliary feedwater pumps from low suction Installation of time raday on starting circuitry of motor driven auxiliary feedwater pumps will aliminate problem ZUKOR.D Director's Office 82/02/24 NICHELSON, C Director's Office 3pp 15750 359 24% Fiche 50-000, 82/06/28, 8210010008
- --8210050075 Summary of 810513 operating reactor evants meeting LAINAB, 0 C Assistant Director for Safety Assessment 81/05/18 EISENNUT.D 0 Assistant Director for Licensing 6pp 15729 160 24% Fichs. 50-304.82/06/28.8210010008
- 92[0040116 Forwards LER 82-02]/03L-0 GRAEBSER, K. Commonwealth Editon Go 82/09/24 KEPPLER, J O Region 3. Office of Director 1p i558[i9] 24X Fiche 50-304, 82/09/24, 8210040116
- --B210040121 LER 82-021/03L-0 on 820827, during running of 2A turbing driven avriliary feedwater pump, flow observed on pump 2 discharge header Caused by improper procedure inplementation Procedure will be revised JOHNSON.0 Commonwealth Edison Co 82/09/24. Region 3, Office of Director 19 15381 192 24X Fiche 30-304,82/09/24, 8210040116
- 8210060262 Forwards LER 82-022/03L-0 GRAEGSER,K. L. Commonwealth Edition Co 82/09/30 KEPPLER,J Q Region 3, Office of Director 1p 15621 045 24X Fiche 50-304,82/09/30,8210060262
- --BR10060267 LER 82-022/03L-0 on 820903, contrinment spray distairdriven pump 2C failed to start during remote control room startup for mechanical meint Caused by sticty underspased switch in closed position due to impurities Switch suff-cleaned SHIM. K Commonwealth Edison Co 82/09/30 Region 3, Office of Director ip 13521 066 24% Fichs 50-304,82/09/30,8210060262
- 8210180167 Forwards LER 82-023/031-0. ORAESSER, K . Commonwealth Edison Co. 82/10/07 KEPPLER, J G Region 3, Office of Director ip 157(8 182 24x Fiche 30-304, 82/10/07, 8210180167
- --8210180175 LER 82-023/03L-0 on 920907.28 steam generator level channel 2L-549 did not track Causad by failure of transmitter (Fischer/Porter 130249588ABB9-NS). Transmitter replaced investigation ongoing CANTHELL-P E Commonwealth Edison Co 82/10/07 Region 3, Office of Director ip 15718 183 24X Ficha: 50-304, 82/10/07, 8210180167
- B210260219 Forwards LER 82-024/01T-0 RRAESSER, K. Commonwealth Edison Co 82/10/19, KEPPLER, J. Q Region 3, Office of Director, 10 15804:262, 24X Ficha. 50-304, 82/10/19, 8210260219
- --B210260223 LER 82-024/01T-0 on 82092B, while taking RCB solid, dilution occurred via incorrect makeup when containment integrity was not intent w/shutdown margin Causad by personnel error Operator reinstructed T'MIEMI.W D. Commonwealth Edizon Co. 82/10/19. Region 3, Gffice of Director. 299 15804:249, 24X Fiche, 30-304,82/10/19. 8210260219

- DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT
- F Security, medical, emergency & fire protection plans
- 8209170061 Forwards draft vital area definition rept for facility
 Div of Safaguards will review technical basis for rept
 during 820927-1001 site visit M/o enci
 VAROA.5 A Operating Reactors Branch 1 82/09/09 Olester.C w
 Hisconsin Public Servica Corp ip 14910 106 24x
 Fiche 50-305.62/09/08.6209170061
- 8210120505 Ack cooperation in planning Div of Safeguards 820027-12 regulatory effectiveness review Team until evaluate overell effectiveness of security program to determine if safeguards regulations yield acceptable leval of protection EISEMHUT.D O Division of Licensing 82/09/20 OLEGLER.C Williams in Public Service Corp 8pp 15672 076 24X Fichs 30-305, 82/09/20, 8210120505
- 8210080201 Forwards IE Safaty Evaluation Rept 50-305/82-17 (urlrgs, 1982 No noncompliance noted HIND, J A Division of Emergency Preparedness & Operational E.pp. 82/09/22 GIESLER, C W Hisconsin Public Service Corp 2pp 15640 090 24% Fiche 50-305,82/09/22,8210080201
- --8210080204 IE Safety Evaluation Rept 50-305/82-17 during Aug 162 No noncompliance noted Major areas inspected emergency plan dtd Nov 1981 PAGLIANG, J. A. AKELSON, H. L. Division of Emergency Preparational Support 82/09/20 32pp 15640 092 24x Fiche 50-305, 62/09/22, 6210080201
- 8210130300 Forwards Revision 3 to security force training bequalification manual Revision withhald (ref 10CFR2 790) 01EBLER.C W Wisconsin Public Service Corp 82/09/29 DEMICA. Office of Nuclear Reactor Regulation, Orector 2pp 15610 2.1 24X Fichs 50-305.82/09/29.8210130300
- 8210030102 Forwards IE Bafaguards Insp Rept 50-305/82-16 on 62082-2 & notice of violation Notice of violation withheld (ref 100FR73 21)

 MILLER, J. R. Division of Engineering & Technical Program 82 Procedure Corp. 2pp 15603 295 2 Fichs 50-305, 82/07/30, 8210050102
- --8210050110 IE Safeguards Insp Rept 50-305/82-14 on 62082 27
 Noncompliance noted failure to certify qualifications for security force numbers, Details withheld (raf 100F873 2):
 BELANOER, J. L. CREED, J. R. Region 3. Office of Director \$2 50, 15.003 297 24X Fiche 50-305,82/09/30.8210050102
- B210130581 Provides info re changes to facility fire protection commitments Revised and schedule submitted in Attachent 1 of util 820804 its should be considered most current & securate schedule OIEBLER.C W Wisconsin Public Barvice Corp 82/10/00 CANCA-Office of Nuclear Reactor Regulation. Oirector 2pp 15679 CM 24X Fichs 50-305.82/10/09.8210:30581
- --8210280425 One-time exemption from iOCFRSO App & requiring 40° penergency preparedness exercise Next exercise schedulif for 831101
 EISENHUT, D.Q. Division of Licensing 82/10/15 Wistentia Public Service Corp. 3pp. 15860-016, 24X Fiche 50-36582/:8210280423
- P Operating license stage documents & correspondence
- 8210010179 Application to amend License DPR-43, revising Tota State reorganization of nuclear dept GESLER.C. W. Misconsin Public Servica Corp. 82/09/27 DM.: Nuclear Reactor Regulation, Director. 2pp. 15567:287 241 Fiche, 80-305, 82/09/27, 8210010179.
- --8210010186 Proposed Tech Spece reflecting organisation Lauler, corporate nuclear engineering staff, clarifying frequency of meetings to line of authority for nuclear safety review to audit committee to showing functional responsibilities ** Wisconsin Public Service Corp. 82/09/27 13pp 15547 李 24% Fiche: 50-305,82/09/27,8210010179

- B210G60312 Advises that analyses of plant-specific safety & relief valve discharge plang per NUREO-0737. Item II D i require more time than proposed in B20712 itr Item resolution will be identified & implementation schedule provided by B21115 GIESLER.C W Hisconsin Public Service Corp 82/09/27 EISENRUT.D O Division of Licensing Ip 15619 189 24X Fiche 50-305, B2/09/27, B210060312
- E210130600 Informs that review of 81083(& 0915 responses to Generic Letter 81-01. "Qualifications for insp.Exam & Testing & Audit Personnel." completed Commitments & exceptions to Pevisson 1 to Reg Quides 1 58 & 1 146 acceptable VARGA. S A Operating Reactors Dranch 1 82/09/28 OIESLER. C W Hisconsin Public Service Corp 2pp 15692 345 24X Fiche 50-305, 82/09/28, 8210130600
- 6210210395 Forwards safety evaluation of Ceneric Issue B-24, "Containment Purging During Normal Plant Operation "
 tWREC-0737. Item II E 4 2 will be completed by purge & vent
 review Technical evaluation encl
 VARCA: S A Operating Reactors Branch 1 82/09/30 GIESLER, C W
 Hiscomsin Public Service Corp 9pp (5772 314 24X
 Fiche 50-305, 82/09/30, 82(0210395
- --8210210403 Safety evaluation of containment purging & venting during normal operation Request for addi info re dA program encl + NRC No Detailed Affiliation Olven 82/09/30 4pp 15772 323 24X Fiche 50-305, 82/09/30, 82/02/0375
- --8210210410 Safety evaluation of facility override of containment purge isolation Licensee should demonstrate that override condition automatically removed upon clearing initial signal or provide sys level annunciation 4 MRC No Detailed Affiliation Given 82/09/30 2pp 15772 327 24X Fichs 50-305, 82/09/30, 8210210375
- --8010070320 "Technical Evaluation of Electrical Instrumentation & Control Design Aspects of Override of Containment Purge Value Isolation & Other Engineered Safety Features for Kewaunee Puciear Power Plant "

 HACKEIT. D B EG&D, Inc EGO-(183-4168 80/09/30 NRC No Detailed Affiliation Olven 23pp 15772 329 24X Fichs 80-305,82/09/30.8210210395
- B210070108 Comments on ARC proposed generic requirements for steam generators Opposes requirements, favoring mgt control program courrently in effect Program should be at volition of util mgt & notice requirements
 OIESLER.C W Misconsin Public Service Corp 82/10/04
 IPPOLITO, TA Operating Reactors Assessment Branch App
 15628 070 24X Fichs 50-305,82/10/04,8210070108
- 8210170487 Forwards progress update on implementing NUREO-0737, Items II B 3.II B 4.II F 1 3.II F 1 6 & 1II D 3 4
 GIESLER, C H Wisconsin Public Service Corp 82/10/14
 EISENHUT, D G Division of Licensing 4pp 15735 331 24X
 Fache-50-305,82/10/14,8210170487
- O Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FDIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FEETON J M Division of Ruies and Records 82/08/i0 LDNO, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000,82/08/i0,82i0070007
- ~-B210070(39 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensess [PPOLIYO.T Operating Reactors Assessment Branch 82/04/01 VAROA.S Operating Reactors Branch 1 5pp 15645, (31 24X Fichs 50-000, 82/08/10, 82/0070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PKRs.per 750320 & 21 requests Deteils of insps. succluding defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach i OOLLEER.K R Division of Reactor Licensing (NRR-1975 only) 73/03/24 MACCARY.R Division of Technical Review (NRR-1975 only) 5pp 15645 196 24% Fiche 80-000.82/08/10.8210070007
- 8210080201 Forwards IE Bafety Evaluation Rept 50-305/82-17 during Aug 1982 No noncompliance noted HIND. J A Division of Emergency Preparedness & Operational Bupport 82/09/22 OIESLER, C W Misconsin Public Service Corp 2pp 25640 090. 24X Fichs 50-305,82/09/22,8210080201

- --82(0080204 IE Safety Evaluation Rept 50-305/82-17 during Aug 1982
 No noncompliance noted Major areas inspected emergency
 plan dtd Nov 1981.
 PAGLIARO, J A., AXELSON, W L. Division of Emergency Preparedness &
 Operational Support 82/09/20 32pp 15640:092 24X
 Fichs 50-305,82/09/22,8210080201
- 8210060328 Forwards util 820917 response to NRC 820715 questions re IE Bulietin 80-04. (nadvertently sent to Region 3 OIESLER: C W Wisconsin Public Service Gorp 82/09/29 VARQA: B A Operating Reactors Branch 1 ip 15619:028 24X Fiche, 50-305, 82/09/29, 8210060328
- 82(0050102 Forwards IE Safeguards Imap Rept 50-305/82-16 on 820823-27 & notice of violation Notice of violation withheld (ref 100FR73 21)
 MILLER, J.R. Division of Engineering & Technical Programs 82/09/30, 0IESLER, C.W. Wisconsin Public Service Corp. 2pp. (5603 275 24X Fichs 30-305,82/09/30,8210050102.
- --82(00501)0 IE Bafeguards Insp Rept 50-305/82-16 on 820823-27 Noncompliance noted failure to certify qualifications for security force members Details withheld (ref 100FR73 21) BELANDER.J L., CREED, J R. Region 3, 0ffice of Director 82/09/28 ip 15403 297 24% Fiche 50-305,82/09/30,8210050102
- 8210080174 Forwards confirmatory measurements program data addendum sheet for IE Insp Rept 50-305/82-08.closing out Open Item 50-305/82-08-01.
 PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 82/10/05 01ESLER, C. M. Wisconsin Public Service Corp ip 15640 157 24X Fiche 50-305,82/10/05,8210080174
- --B210080177 Addendum to IE insp Rept 50-305/82-08 consisting of confirmatory measurements program data sheat re 8r-89 & Sr-90 samples below comparison limits * Region 3, Office of Director 82/10/05 ip. 15440 158 24X Fiche 50-305,82/10/05.8210080174
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Disladged I-125 implant Seeds " Syc list encl COBB. L I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York 64pp. 15741 250 24X Fiche 50-000,82/10/06.8208190233.
- 8210190532 Confirms schedule for 821018 enforcement conference at Region 3 ofcs to discuss potential escalated enforcement actions re recent identification of capped containment pressure sensing lines

 KEPPLER. J Region 3. Defice of Director 82/10/13 MATHEMS.E.R Wisconsin Public Service Corp ip 15751 254 24X

 Fiche 50-305.82/10/13.8210190532
- B210280223 Forwards IE Insp Rept 50-305/B2-13 on B20701-0B31 & notices of violation & deviation STREETER.J F Division of Project & Resident Programs 02/10/13 0168LER.C W Wisconsin Public Service Corp 2pp. 15837 277 24X Fiche 50-305.82/10/13.B210280223
- --8210280226 Notice of violation from insp on 820701-0831 STREETER, J F Division of Project & Resident Programs. 82/10/13 1p 15839 281, 24X Fiche, 50-305, 82/10/13, 8210280223
- --8210280229 Notice of deviation from (nap on 820701-0831. STREETER, J. F. Division of Project & Resident Programs ip 15839 282 24X Fiche 50-305,82/10/13,8210280223.
- --8210280232 IE Insp Rept 50-305/82-13 on 820701-0831 Moncompliance noted failure to maintain control of combustible maths & to issue operations mano as of 820820 NCLSUN.R.L., REYES,L.A. Division of Project & Resident Programs 82/10/06 10pp. 15839.283 24X Fiche 50-305,82/10/13,8210280223
- B208190238 IE Bulletin 82-03, "Btress Corrosion Cracking in Thick-Wali, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYGUNO.R C Director's Office, Office of Inspection and Enforcement. B2/10/14 Consolidated Edison Co of New York 115pp 15810-125, 24% Fiche: 50-000, 82/10/14.8208190238
- 8210260161 Confirms schedule for 821022 enforcement conference w/util to discuss potential escalated enforcement action re recent identification of capped containment pressure sensing lines. SPESBARD.R L Division of Project & Resident Programs 82/10/15 MATHEMS.E.R. Wisconsin Public Service Corp. 1p 15799 007. 24X Fiche. 50-303.82/10/15.8210260161

8 Reportable occurrences, LERs & related correspondence

- B210120182 Discusses findings to numerous failures of containment isolation valves All failures resulted from inoperable ASCO Series 8320 solenoid valves, usually due to oil in air supply Valves undergoing qualification LANNINO, H D Director's Office 80/08/22 Director's Office 2pp 13692 216 24X Fiche 50-295.80/08/22.8210120182
- 8210040156 Forwards LER 82-028/03L-0 & updated 81-036/03X-1 GIEBLER: C W Hisconsin Public Service Corp 82/09/24 KEPPLER, J o Ragion J. Office of Diractor ip 15582 317 24X Fiche 50-305, 82/09/24, 8210040156
- --B210040159 LER B2-028/03L-0 on 920825, damper on Train A failed open causing rone special ventilation fan to start automatically Caused by bad coil on solenoid controlling enhaust filter inist damper Coil replaced BERNHOFT. B L Wisconsin Public Service Corp 82/09/24 Ragion 3, Dffice of Director ip 15582 318 24X Fiche 50-305, B2/09/24, B210040155
- --B210040162 Updated LER 81-036/03X-I: on Bili03, motor drive auxiliary feedwater lube oil pump continued to run when pump IA stopped Caused by excessive wear & missignment of switch linkage mechanism Worn parts replaced BELANT. J L. Hisconsin Public Service Corp 82/09/21 Region 3. Diffice of Director 2pp 15582 319 24X Fiche 50-305.82/09/24. 8210040156
- 8210190353 Forwards LERs 82-029/01X-1 & 82-031/03L-0 QIESLER.C W Wisconsin Public Service Corp 82/10/11 XEPPLER.J 0 Region 3. Office of Diractor. ip 15742 607 24X Fiche 30-305.82/10/11.8210190353
- --B210190355 LER 82-029/01X-1 on 820927 discovered that monthly testing requirements exceeded for containment radiation monitors R-11 & R-12 Caused by postponement of test due to backup radiation monitor baing out of svc & personnel oversight # Wisconsin Public Service Corp B2/10/11 Region 3. Office of Director. 2pp 15742 108 24X Fichs 50-305,82/10/11,8210190393
- --8210170356 LER 82-031/03L-0 on 820913 train ID of shiald bldg vant failed to switch to recirculation mode after drawing vacuum Recirculation damper failed to open due to broten hydraulic pump on electro-hydraulic damper actuator. Operator replaced BERNHOFT. 8 L Wisconsin Public Service Corp. 82/10/13 Region 3, Office of Director. 1p 15742 110 24X Fiche 50-305,82/10/11,8210190333
- 8210260260 Forwards LER 82-090/01T-0
 01ESLER, C.W Wisconsin Public Service Corp 82/10/18 KEPPLER, J 0
 Region 3, Office of Director 1p 15799 348 24X
 Fiche 50-305, 82/10/18, 8210260260
- --B210260263 LER B2-030/017-0 on 821004.sensing lines on all six containment pressure transmitters found capped off inside, randering transmitters imperable, Caused by refueling caps inadvertently placed on ends of sensing lines Caps removad. MARCHINI Wisconsin Public Sarvice Corp 82/10/18 Region 3 Office of Director 1p 15797 349. 24X Fiche 50-305,82/10/16,8210260260

V Operator Examinations

í.

8210050263 Describes implementation of senior reactor operator upgrada training to comply w/NUREO-0737, Itam J.A 2 i. "Senior Reactor Operator Qualifications "All potential candidates cannot be examined until Hay/June of 1983 OIESLERIC W. Wisconsin Public Service Corp. 82/09/29, DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director ... 3pg 15609; 193 24X Fiche: 50-305,82/09/29,8210050283

- --8210040354 iE Insp Repts 50-282/82-15 & 50-304/82-15 on 930324 its noncompisance noted Major areas inspected previous deficiancies in prompt notification/warning sys PATTERBON, J.P. Division of Emergency Preparadness & Optralicas' Bupport 82/09/09 App 15593 358 24X Fiche 50-202.02/07.8210040345
- 6210080184 Forwards revised Page 4 reflecting NRC guidance on activation of public elect to notification system 621014 energency plan exercise MARDLE C Northern States Power Co 82/09/28 AXFIGURY L Fs., 3. Office of Director 2pp 15640 175 24X Fichs 50 202 62/03 36210080184
- 8210120589 Notification of 821001 meeting w/licenses.BNL bfrgirpr., Planning & Mgst Inc in Betheeda.MD to discuss requests for examption from 10CFR50.App R requirements re fire protection
 DISANNI.D C Operating Reactors Branch 3 82/09/20 (LARS & a Operating Reactors Branch 3 22p 15672 346 24X Fiche 50-282,82/09/28,8210120589
- 8210260374 Ack receipt of FEMA 820526 itr re evaluation of affaite emergency preparedness for facility exercise & associated final exercise evaluations Offsite emergency preparedness deficiencies should be addressed by util
 HIND, J. A. Division of Emergency Preparedness & Operational Company of the State of the State of the State of the State of State
- 8210270262 Forwards info clarifying 820630 rept. "Fire Profittize is) Shutdown Analysis in Compilance WilderRSO. App R. Blection iII O & Bubstantive Basis for Exemption Requests." per 821001 meeting w/RRC MUSDLF.D Northern States Power Co 82/10/22 iiffiles = -, Raactor Regulation. Director 132pp 15829 049 24x Fiche 50-262, 82/10/22,8210270262

P Operating license stage documents & correspondence

- 82:0040123 Submits supplemental info re util 920414 request for the Licenses DPR-42 & DPR-60 "LOCA ECCS Limiting Break & Exposure Sensitivity Analysis for ENG XN-1 & XN-2 Release at Prairie Island I "applies to both Units 1 & 2 MOSOLF.D Northern States Power Co 82:007/24 Office of x , Reactor Regulation. Director 1p 1558: 203 24x Fiche 50-282.82/09/24.82:0040123
- 8210050319 Forwards response to Core Performanta Branch P; HB 4 12 to methods of monitoring core power distributions for Cycle 7 operation
 MUSIC.F.D. Northern States Power Co. 62/09/29 (liftics + > 1 3)
 Reactor Regulation. Director 13pp 15610 260 Jax
 Fiche 50-202. 82/09/29, 8210050319
- 8210130260 Discusses implementation of NRC guidalines for puricy hours, provided in Generic Ltr 82-12 Revised guidalines leve been implemented, w/exceptions of 72-h per will initiation a relief from control board duties MUSDLF.D Northern States Power Co. 82/10/07 (Iffice at the Grant Regulation, Director, 2pp. 15676 012 24x Fiche: 30-000, 82/10/07, 8210130260
- 8210260154 Advises that mods required by NUREQ-0737. Itself to "Control Room Habitability," will not be completed until 830315 due to delays in receipt of matl 4 sampling equipment.

 MUBOLF.D Northern States Power Co 82/10/22 Ufficest % e Reactor Regulation, Director 3pp. 18799 012 24x
 Fiche: 30-282, 82/10/22, 8210260184

O Inspection reports, IE Bulletins & correspondence

- B210070007 Responds to FDIA request for eight categories (#) s. # 11 steam generators & steam turbinas App A documents provines in R Udell FOIA Request 81-313 Forwards documents issues 14 App B FELTON, J. M Division of Rules and Records. B2/00/13 (CM 2 4 Minthrop, Stimson, Putham & Roberts 9pp. 15645 083 215 Fiche 50-000, 82/08/10,8210070007
- --8210070137 Forwards tabulated data on steam generater into Each facilities. Data should be provided to licensees IPPDLITG.T. Operating Reactors Assessment Branch \$7.57 & VAROA:S Operating Reactors Branch 1 5pp 15645 121 325 Fiche. 50-000, 82/08/10, 8210070007.

- --8210070172 Forwards info re steam generator integrity & insps at all operating PURs.per 750320 & 21 requests Details of insps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach 1. GOLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R R. Division of Technical Revisw (NRR-1975 only) 5pp 15645 196 24X Fiche 50-000.82/08/10.8210070007
- 8210040345 Forwards IE Insp Repts 50-282/82-15 & 50-306/82-19 on 820824-25 No nencompliance noted PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/09/10 LARSON, C E Northern States Power Co 2pp
- --8210040354 IE Insp Repts 50-282/82-15 & 50-306/82-15 on 820824-25 No noncompliance noted Major areas inspected previous deficiencis; in prompt hotification/warning age PATTERSON, J P . AXELSON, M L Division of Emergency Preparadness & Operational Support 82/09/09, 4pp 15593 358 24X Fiche 50-282,82/09/10,8210040345
- 82:0130563 Forwards "Inservice Insp-Exam Summary, Prairie Island Nuclear Generating Plant-Unit II.820601-0709 " HUSDLF, D Northern States Power Co 82/10/05 Office of Nuclear Reactor Regulation, Director ip 15683 118 24X Fiche-50-304,82/10/05,8210130563
- --8210130566 Inservice insp rept on 620601-0707 Rept summarizes exam results of belance-of-plant & eddy current exam of steam generator tubing ANDERSON. N T , BCHANEN. J F , DAHLHAN, L C Northern States Power Co. 82/09/15 180pp 15683 [19 24X Fiche 50-306, 62/10/05, 8210130563
- 6206190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 implent Seeds " Svc list encl COBD.t. I Division of Fuel Facilitiss, Materiels & Safeguards 622/10/06 Consolidated Edison Co of New York & Spp 15761 250 24X Fiche 50-000,82/10/06,6208190233
- 8210190432 Ack receipt of 820915 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/82-11 & 50-305/82-11 & 50-305/82-11 & Division of Project & Resident Programs 82/10/07 LARSON.C E Northern States Power Co ip. 15741 182 24X Fiche 50-282,82/10/07,8210190432
- --8210190439 Responds to NRC 820817 ltr rs violations noted in IE Insp Repts 50-282/82-11 & 50-306/82-11 Corrective actions startup program changed to normalize flux difference channels LARBUNNC E Northern States Power Co 82/09/15 BTREETER. J F Division of Project & Resident Programs 2pp 15741 183 24X Fichs 50-282,82/10/07,8210190432
- 8210150249 Ack receipt of 820928 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/82-i3 & 50-306/82-i3 Boraceter, J F Division of Project & Resident Programs 82/i0/08 LARSON.C. E Northern States Power Co. 1p 15704 361. 24X Fiche 50-282, 82/i0/08, 8210150249
- --8210150255 Respands to NRC 820902 itr rs violations noted in IE Insp. Repts 50-282/82-13 & 50-306/82-13 Corrective actions dissel generator test procedures will be revised by 821201 & investigative rept will be discussed w/operators LARSON.C E. Northern States Power Co. 82/09/28 STREETER, J. F. Davision of Project & Resident Programs 2pp. 15704, 362 24X Fiche. 50-282, 82/10/08.8210150249
- 8210280144 Forwards IE Insp Repts 30-282/82-16 & 50-304/82-16 on 820901-17 & motice of violation STREETER, J.F. Division of Project & Resident Programs 82/10/13 LARBON, C.E. Northern States Power Co 2pp 15837 179. 24X Fichs. 50-282, 82/10/13, 8210280164
- --8210280171 IE Insp Repts 50-282/82-16 & 50-304/82-16 on 820901-17.
 Noncompliance noted failure to post no smaking sign in safety-related equipment areas & operators found smoking.
 DUBRY, N E., REYEB.L Division of Project & Resident Programs 82/10/12. App. 15837-202 24X Fiche. 50-282, 82/10/13, 8210280164
- 8208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Wall, Large-Diameter Stainiess Stess, Recirculation 89s Piping at BMR Plants." Byo list encl DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co. of New York 115pp. 13810, 125, 24X Fiche 50-000, 82/10/14,8208190238.

- S Reportable occurrences. LERs & related torrespondence
- 8210190726 Forwards LER 82-017/03L-0 MUSDLF,D Northern States Power Co 82/10/08 Region 3, Office of Director 1p 15737-144 24X Fiche 50-306.82/10/08.8210190726
- ~-8210190745 LER B2-017/03L-0 on 820908, two undervoltage relays found to trip outside toierance band of 90 plus or minus 2% of nominal voltage Cause not stated Relays recalibly HUNBTAD.A A Northern States Power Co 82/10/08 Region 3, Office of Director 1p 15737 145 24% Fichs 50-306,82/10/08,82/10/9726
- DOCKET 50-309 HAINE VANKEE ATOMIC POWER PLANT F Security, medical, emergency & fire protection plans
- 8210070054 Forwards Amend 64 to License DPR-36 & notice of issuance & availabilisty Amend requires meint of safsgwards contingency & guard training & qualification plan
 HEITNER.K. L. Operating Reactors Branch 3 82/09/15 CARRITY.J H
 Mains Yankes Atomic Power Co. 4pp 15646 351 24X
 Fichs 50-309,82/09/15,8210070054
- ~-8210070059 Amend 64 to License DPR-36.including requirement to maintain Commission approved guard training & qualification plan CLARK, R A Operating Reactors Branch 3 82/09/15 2pp 15646 355 24X Fichet 50-309, 82/09/15.8210070034
- ~-8210070040 Notice of issuance & availability of Amend 64 to License DPR-36
 CLARK.R A Operating Reactors Branch 3 82/09/15 2pp 15646 357 24% Fiche 50~309,82/09/15,8210070054
- 8210050013 Reisases public version of Voi II of emergency plan FELTON.J M. Division of Ruiss and Records 82/09/16 Document Management Branch ip 15622 221 24X Fichs 50-309,82/09/16,8210050013.
- ~-8210050015 Forwards public vsrsion of Vol 11 of emergancy plan Receipt form enc1 # Mains Atomic Powsr Co 82/08/30 EISENMUT, D O MRC -No Detailed Affiliation Oivan. 2pp 15622 222 24X Fichs 50-309,82/09/16,8210030013
- ---8210050018 Public version of Vol II of smergency plan

 * Maine Yankss Atomic Power Co 82/07/12 21ipp 15622 224
 24% Fiche 50-309.82/09/16.8210050013
- 8210210136 Forwards 1E Insp Rept 50-309/82-12 on 820726-30 No noncompliance noted ALLAN, J M Region 1. Offics of Director 82/10/06 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 15766 107, 24x Fiche. 50-309, 82/10/06, 8210210136
- ~-8210210142 IE Insp Rspt 50-309/82-12 on 820726-30 No noncompliance noted Hajor areas inspected followup of emsrgency preparendsss items from 810908-15 appraisal MOUNABLE.J. CROCKER.H W Division of Emergency Preparednsss & Operational Support. 82/09/30, lipp. 15746 109 24X Fiche 50-309,82/10/06.8210210136
- 8210210313 Forwards IE Bafsguards Insp Rept 50-309/82-i1 on 820719-21 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 82/10/07 RANDAZZA.J B Mains Yankes Atomic Power Co 2pp 15764-227 24x Fiche: 50-309.82/10/07.8210210313
- --0210210316 Notice of violation from insp on 820717-21 ** Division of Enginsering & Tschnical Programs 82/10/07 ip 15764 229 24X Fiche: 50-309, 82/10/07, 8210210313
- --821021032i IE Bafeguards Insp Rapt 50-309/82-11 on 820719-21.
 Noncompliance noted failurs to establish 8NM control & accounting procedures to assure that sources & detactors received, controlled, inventoried & shipped properly.
 KUBHNER, H L., GODY, A. T. Division of Enginsering & Technical Programs 82/09/14 7pp. 15764.230. 24% Fiche:50-309.82/10/07, 8210210313
- B210130178 Ack receipt of B20527 ltr informing NRC of steps taken to correct violations noted in 1E Safeguards Insp Rept 50-309/81-02 Corrective actions withheld (ref 100FR73 21). MARTIN T.T Division of Engineering & Technical Progrems B2/10/08 RANDAZZA, J.B. Haine Yankee Atomic Power Co 2pp. 15473-020 24% Fiche. 50-309, 82/10/08, 8210130178.

1.0

Ή,

- 8210280097 Advises of recent changes to 820601 security plan, including moving portion of perimoter security fence & observation touer to provide addl area within protected area Changes do not decrease effectiveness of plan GARRITY, J. H. Maine Yankee Atomic Power Co. 82/10/21 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 15837-184 24X Ficha 50-309, 82/10/21, 8210280087
- G. Adjudicatory correspondence
- 8310050236 Response apposing NMC & util objections to Sensible HE Power 820830 addl specific contentions NRC & util stds sought to be imposed are unfairly & improperly restrictive of intervenor right to be heard MILLER.D S Sensible Maine Power MILLER.D S Miller.D S 82/09/30 Atomic Safety and Licensing Board Panel 13pp 15608 349 24X Fiche 50-309, 82/09/30, 6210050236
- B210060170 Response opposing NRC & util 820915 replies to State of ME 820830 addl contentions All contentions should be admitted Certificate of Svc encil ANRENS.P Maine, State of 82/09/30 Atomic Bafety and Cirensing Board Famel 24pp 15613 240 24x Fiche 50-309,82/09/30,8210060190
- 8310080049 Forwards 10CFR2 Subpart 8 per 820926 request GUTIERREZ, J M Hearing Branch 3 62/10/01 MILLER, 0 8 Hiller, 0 S 5pp 85643 030 24x Fichs 50-309,82/10/01,8210080049
- 8210130314 Answer opposing Sensible ME Power 820924 motion for clarification & mod of ASLD 820412 order on admissibility of contentions Filing is untimely & forbidden by regulations Certificate of Svc encl DIGNAN.T 0 . GAD.R K Haine Vankee Atomic Power Co DIGNAN,T Q Ropes & Gray 82/10/09 Atomic Safety and Licensing Board Panel 4pp 15678 151 24X Fiche 50-309,82/10/08,8210130314
- 62:0150134 Forwards ASLB 82:0915 partial initial decision in Bly Rock Point spent fuel pool amend proceeding Same procedure re E19 should be used in instant case GUTIERREZ, J M Hearing Branch 3 82:10/13 LAZO,R M HAND,C H , MORRISP A About Cafety and Licensing Board Panel 2pp 15697 346 24X Fiche 50-309,82/10/13.8210150134
- 8210200065 Reply apposing NRC & applicant apposition to Sentible ME Power matter for util disclosure Matter should not be characterized as premature discovery Info requested basic & essential to proceeding Certificate of Svc encl MILLER.D S Sensible Maine Power MILLER.D S Miller.D S 82/10/13 Atomic Sefety and Licensing Board Panel 5pp 19757 201 24X Fische 50-309.82/10/13.8210200065
- 9210150460 Response opposing Sensible HE Power 820924 motion for clarification & mod of ASLB 920412 order ruling on admissibility of Power proposed contentions Motion merely repeats arguments already rejected Certificate of Svc encl GUTIERREZ-JH Hearing Branch 3 82/10/14 Atomic Setsty and Licensing Deard Panel App 15703 106 24% Fichs 50-309,82/10/14, 8210150460
- 8210240457 Forwards Safe Power for ME.EG Carrett.J8 Green & J Jerabek request for issuance of show cause order to licenses MURRAY.P L Hurray, Plumb & Hurray MURRAY.P L Safe Power for Maint 82/10/20 Director's Office. Office of Inspection and Enforcement 1p. 15807 123 24X Fichs 50-309.82/10/20.8210260457
- --8210260465 Safe Power for HE,EQ Garrett, JB Green & J Jerabet request for issuance of show cause order to licensee Adequate financial backing must be shown to raise capital required to continue operations & to make capital investment HURRAY, PL Safe Power for Haine MURRAY, PL Murray, Plumb & Hurray 82/10/20 Director's Office, Office of Inspection and Enforcement 6pp 15807 124 24% Fiche 50-309, 82/10/20, 8210260457
- 8210280227 Comments on HRC B21013 ltr to ASLB re contentions Decision on merits in Bug Rock Point case does not affect admissibility of contentions in instant case AHRENS.P Mains. State of 82/10/20 LAZD.R M. HAND.C.H. NORRIS.P A Atomic Safety and Licsning Board Panel 3pp. 15837 083 24X Fiche 50-309, 82/10/20,8210280227
- 8210290303 First set of interrogatories & requests for documents
 Certificate of Eyc enci
 MILLER, D 8 Sansible Mains Power MILLER, D 8 Miller, D 6
 82/10/25 Maine Vanies Atomic Power Co Spp 13953 170 24X
 Fichs 50-309, 82/10/25, 8210290303

- H General correspondence
- 9210240202 Requests response to listed questions re assignment of personnel during shutdown & nature of work personnel will be conducting at plant BARROWS.J Maine Nuclear Referendum Committee B2/10/21 CLARK,R A Operating Reactors Dranch 3 lp 15804 270 241 Fichs 50-309,82/10/21,8210260202
- P Operating license stage documents & correspondence
- 8210040074 Advises that Items 1,2 & 3 of NRC Confirmatory Action Lit 82-01 have been satisfied per util 820202.22 & 0308 ltrs Approval for facility restart requested GARRITY.J H Kains Yankee Atomic Power Co 82/03/12 HAVNES.8t Region 1, Office of Director CLARK.R A Operating Reactors Er. 3 2pp 15581 L41 24X Fiche 50-309.82/03/12.8210040074
- 821001000B Responds to FOIA request for 19 categories of documents of nuclear reactor events & safety problems Forwards documents listed in App A
 FELTON.J M Division of Rules and Records 82/06/20 UCELL.R s
 Critical Mass Energy Project 15pp 15727 005 24X
 Fiche 30-000.82/06/28.8210010008
- --8204270048 Recommends prompt attention be given to problem of fish coolant pump closure stud corrosion detected at facilities Response by 820415 requestsd EISENHUT. D O Division of Licensing 82/03/24 HANAUER, 8 H. Division of Systems Integration (post 811005) 3pp 66035 2.1 24X Fiche 50-000.82/06/28.8210010008
- 8210040077 Advises that refueling water storage tank level setpoint for automatic recirculation actuation signal should not be changed in short term.psr 820727 itr
 OARRITY, J H Maine Yankee Atomic Power Co 82/07/28 HANKS.RI
 Region 1, Office of Director 2pp 15581 270 24X
 Fiche 50-309, 82/07/28, 8210040077
- 8210040217 Submits addl info to 820727 ltr rs refueling unter streat tank temp upper limit & water level lower limit Reanalysis of NPSH for ECCS performance included safeguards pumps. fluid sys & calculations of plping sys OARRITY, J H Hains Yankes Atomic Power Co 82/07/29 NAYNES IC Region 1. Offics of Director 2pp 15583:118 24X Fiche 50-309, 82/07/29, 8210040217
- 8209210514 Requests addl info re responses to NUREO-0737. Itsa
 III D 3 4. "Control Room Habitability " Response requested
 within 40 days of receipt of itr
 CLARK, R A Operating Reactors Branch 3 82/09/01 GARRITY, J *
 Haine Yankee Atomic Power Co 2pp 14947 201 24X
 Fiche 50-309, 82/09/01.8209210514
- --B209210523 Informs of acceptability of control room habitability as on licenses responses to NUREG-0737. Itsm III D 3 4 Conclusion based on present plant sys & presumes implementation of affective HVAC mode HURPHY.D W Battells Hemorial Instituts, Pacific Northwist Leboratory, FIN B-2323 B2/03/23 HULHAN.L O Accident Evaluation Branch 3pp 14947 203 24X Fichs 50-309,82/09/2; 8209210514.
- 8210050497 Forwards Amend 63 to License DPR-36. safety evaluation is notice of issuance & availability Amend changes Tech Specimeking limiting conditions for operation more restrictive increasing surveillance requirements for ventilation system. RELEGIN. C. C. Operating Reactors Branch 3 82/09/07 GARRITY. J. Haine Yankee Atomic Power Co. 3pp. 15626-304 24X Fiche: 50-309. 82/09/07.8210050497.
- --8210050503 Amend 63 to License DPR-36, changing Tech Specs to selflimiting conditions for operation more restrictive & increasing surveillance requirements for ventilation & filter sys. CLARK: A. Operating Reactors Branch 3 82/09/07 14;6 15626 307. 24% Fichs 50-309, 82/09/07,8210050497
- --8210050505 Bafety evaluation supporting Amend 63 to Litense DPE-#
 # Office of Nuclear Reactor Regulation, Director 82/07/67
 11pp 15626.321 24X Fichs.50-309.82/09/07.8210050497
- --8210050509 Notice of issuance & availability of Amend 63 to based DRR-36 CLARK.R A Operating Reactors Branch 3 82/09/07 2pp 15626:332. 24% Fichs.50-309.82/09/07.8210050497

- B210040413 Requests add1 info re 810403 proposed mod to Tech Specs concerning snubber surveillance Response requested within 30 days CLARKIR A Operating Reactors Branch 3 82/09/14 GARRITY, J H Maine Yantee Atomic Power Co 2pp 15597 235 24X Fiche 50-309, 82/09/14, 8210040413
- B210040423 Advises that util response to NUREO-0737. Item II X 3 3. "Reporting Relief & Bafety Valve Failures & Challenges," acceptable HEITMER: X L. Operating Reactors Branch 3 82/07/15 QARRITY, J H Maine Yankee Atomic Power Co. 2pp 15597 239 24X Fiche 50-307. 82/09/15. 8210040423
- E210070054 Forwards Amend 64 to License DPR-36 & notice of issuance & availability Amend requires maint of safeguards contingency & guard training & qualification plan
 HEITNER K L Operating Reactors Branch 3 82/09/15 GARRITY, J H
 Maine Yantee Atomic Power Co 4pp 15646 351 24X
 Fiche 50-309, 82/09/15, 8210070054
- --8210070059 Amend 64 to License DPR-36, including requirement to maintain Commission approved guard training & qualification plan CLARA-R A Operating Reactors Branch 3 82/09/15 29p. 15646 355 24X Fiche 50-309, 82/09/15, 8210070054
- --8210070060 Notice of issuance & availability of Amend 64 to License DPR-96 CLAMAR A Operating Reactors Branch 3 82/09/15 2pp 15646 357 24X Fiche 50-309, 82/09/15,8210070054
- 8210250267 Forwards audit rept re procedures & training on pressurised thermal shock containing specific recommendation for training program Requests summary of plans in response to recommendations within 45 days
 CLARK.R A Operating Reactors Branch 3 82/09/23 GARRITY , J H Maine Yankee Atomic Power Co 34pp 15807 341 24X
 Fishe 50-309,82/09/23,8210250267
- 8210060171 Application for amend to Tech Specs App A re Cycle 7 core performance analysis RANDAZZA, J B Maine Yankee Atomic Power Co 82/09/27 Office of Nuclear Reactor Regulation, Director 3pp 15614 068 24X Fiche 50-309, 82/09/29, 8210060171
- -8210050173 Proposed changes to Tech Specs re Cycle 7 core performance analysis 4 Mains Yankee Atomic Power Co 82/09/29 36pp 15514 071 24X Fiche 50-309,82/09/29,8210060171
- B210290160 Notification of changed location for B21013 meeting w/utils in Bethesda, ND to discuss Cycle 7 reload package HEITNER, K L Operating Reactors Branch 3 82/10/05 CLARK, R A Operating Reactors Branch 3 ip 15876 228 24x Fiche 50-309, 82/10/05, 8210290160
- BE10270165 Notification of B21013 meeting w/utils in Bethesda,MD to discuss Cycle 7 reload package fizITNER,K L Operating Reactors Branch 3 B2/10/05 CLARK,R A Operating Reactors Branch 3 2pp 15865 340 24X Fiche 50-309,82/10/05,8210270165
- 8210130252 Proposed Change 94 to License DPR-36.App A Mod renders RCB power-operated relief valves temporarily inoperable during hydrostatic testing when setpoint approached Approval requested prior to startup of Cycle 7

 RANDAZZA.J B Maine Yankee Atomic Power Co 82/10/07 CLARK.R A Operating Reactors Branch 3 3pp 15678 042 24X

 Fiche 50-309.82/10/07.8210130232
- --8210130254 Proposed Tech Spec Pages 3 3-1 through 3 3-3-rendering RCS power-operated relief valves temporarily inoperable during hydrostatic testing when setpoint approached # Haine Yankee Atomic Power Co 82/10/07 3pp 15678 045 24X F1che 30-309.82/10/07.8210130252
- 8210130283 Proposed Change 75 to License DPR-36, modifying Tech Specs to satisfy generic concerns re containment purge & vent sys & tests required to verify valve operability for on-line purge & leakage rate of isolation valves RANOAZZA. J.B. Maine Yankee Atomic Power Co. 82/10/07 CLARK.R.A. Operating Reactors Branch 3 Spp. 15678:297 24X Fiche-50-309, 82/10/07.8210130283
- --BR101302BB Proposed Tech Spec changes re containment purge & vent sys & tests required to verify valve operability for on-line purge & leatage rate of isolation valves
 + Maine Yankee Atomic Power Co 82/10/07 5pp 15678 300 24X Fiche 50-309,82/10/07,82/10/302B3

- 8210130360 Application to amend App A of License DPR-36.consisting of Proposed Change 92.modifying Tech Specs to restrict operations when reactor protective sys channels & ESF actuation sys sensors bypassed.

 RANDAZZA. J B Maine Yankee Atomic Power Co. 82/10/07 CLARK.R A Operating Reactors Branch 3 2pp 15679 117 24X Fiche 50-309.82/10/07.8210130360
- --8210130369 Proposed changes to Tech Spec 3 9, restricting operations when reactor protective sys channels & ESF actuation sys sensors bypassed * Maine Yankee Atomic Power Co 82/10/07 App. 15679 119 24X Fiche 50-309,82/10/07,8210130360
- 8210270008 Forwards Revision 2 to "Inservice Insp & Testing Program " GARRITY.J H Maine Vankee Atomic Power Co 82/10/12 CLARK.R A Operating Reactors Branch 3 ip 15822 134 24X Fiche 50-309, 82/10/12, 8210270008
- --8210270007 Revision 2 to "Inservice Insp & Testing Program " JONES.D L Maine Yankee Atomic Power Co 82/09/21 133pp 15822 135 24X Fiche 50-309,82/10/12,8210270008
- 8210220203 Forwards add1 info re "Environ Qualification of Safety-Related Electrical Equipment," Item A 1 MM G/a encl OARRITY, J H Maine Yankes Atomic Power Ca 82/10/18 CLARK, R A Operating Reactors Branch 3 3pp 15776:354 24X Fiche 50-309, 82/10/18,8210220203
- 8210250098 Clarifies NUREG-0737, Item II II 4 1, "Training for Mitigating Core Damage." per NRC 820914 request All replacement licensed operators & shift technical advisors receive training prior to assuming duties GARRITY. J H Maine Yankee Atomic Power Co 82/10/18 CLARK.R A Operating Reactors Branch 3 2pp 15787 109 24X Fiche 50-309, 82/10/18, 8210250098
- 8210220212 Informs that saturation monitor upgrading delayed due to equipment availability Rosemount resistance temp detectors (RTD) will be used in conjunction w/steam tables to provide adequate backup in case of loss of RTD indication OARRITY. J H Haine Yankee Atomic Power Co 82/10/19 CLARK.R A Operating Reactors Branch 3 2pp 15776-229 24X Fiche 50-309, 82/10/19,8210220212
- 8210260420 Advises that installation of isolation valves in letdown, steam generator blowdown & auxiliary steam lines will not be completed during 1982 refueling due to late equipment delivery. Installation to be completed by next outage OARRITY, J H Maine Yankee Atomic Power Co. 82/10/21 CLARK, R A Operating Reactors Branch 3 pp. 15806 314 24X Fiche 50-309, 82/10/21, 8210260420
- 8210280161 Advises that seismic design review re auxiliary feedwater sys seismic qualification will not be completed as committed to in util 810805 ltr but in accordance w/plan presented in util 820621 ltr.

 QARRITY, J H Maine Yankee Atomic Power Co 82/10/22 CLARK, R A Aperating Reactors Branch 3 ip 15837:209 24X Fiche 50-309,82/10/22,8210280161.
- Q Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight catagories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10. LONG, D. J Winthrop, Stimson, Putnam & Roberts. 9pp 15645 063 24X Fiche 50-000. 82/08/10, BZ10070007
- --9210070172 Forwards info re steam generator integrity & insps at all operating PWRs.per 750320 & 21 requests Details of insps. including defect indications, tube glugging criteria & tubes glugged will not be provided except for Point Beach (... OOLLER.K R Division of Reactor Licensing (NRR-1975 only) 73/03/24 MaCCARY.R Division of Technical Review (NRR-1975 only) 5pp. 13645.196 24X Fiche 50-000.82/08/10.8210070007.
- B210070357 Forwards IE Enforcement Conference Rept 50-309/82-14 on 820602 & 0714 No noncompliance noted Enforcement action pending & will be forwarded under separate cover.
 BTAROSTECKI.R Division of Project & Resident Programs 82/09/20 RANDAZZA.J B Haine Yankee Atomic Power Co 2pp 15634 062 24X Fiche. 50-309. 82/09/20, 8210070357.
- --8210070381 IE Enforcement Conference Rept 50-309/82-14 on 820602 & 0714. No noncompliance noted, Major areas discussed NRC concerns to design change control & event reporting weaknesses identified in IE Insp Rept 50-309/82-05. SHETLAND, P. OALLO.R. Division of Project & Resident Programs 82/09/09, 2pp. 15634 064. 24X Fiche. 50-309, 82/09/20, 8210070337

- 8210060302 Responds to 820708 request for add1 info re control alement assembly & fuel assembly fretting user inspe OARRITY, J H. Haine Yantez Atomic Power Co. 82/09/28 CLASK, R.A. Operating Reactors Branch 3 4pt 15419 202 24X Fiche, 50-309, 82/09/28, 8210080302
- 8210150398 Forwards response to NRC request for add1 info re IE Bullstin 80-11, "Masonry Wall Design " All required mods installed by 820301. Math error detected which requires strengthening of well will be accomplished et 1982 outage GARRITY, J H Maine Yankee Atomic Power Co 82/09/30 CLARK. R A Operating Reactors Branch 3 78pp 15703 286 24x Fiche 50-309, 82/09/30, 8210180398
- 620B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dielodged I-125 Implant Seeds " Svc liet enc! COBB.L I Division of Fuel Facilities, Meterials & Sefsguards 62/10/05 Consolidated Edison Co of New York & Sopp 15761 250 24X Fiche 50-000.82/10/06.8208190233
- 8210210135 Forwards 1E Ensp Rapt 50-309/82-12 on 820725-30 No noncompliance noted ALLAN, J H Region 1, Office of Director 82/10/05 RANDAZZA, J B Maine Vantes Atomic Power Co 2pp 15755 107 24X Fiche 50-309, 82/10/05,8210210135
- --B210210142 IE Insp Rept 50-309/82-12 on B20726-30 No noncompliance noted Hejor areas Inspected following of emergency praparendass items from B10908-13 appreciaal.

 HIDNAS.E J., CROCKER.H W. Division of Emergency Preparedness & Operational Europath B2/09/30 11pp 15766 109 24X

 Fiche 50-309.82/10/06.8210210136
- 8210210313 Forwards IE Safequerds Insp Rept \$0-309/82-11 on 820719-21 & notice of violation MARTIN.T T Division of Engineering & Technical Programs E2/10/07 RANDATZA:J B Helne Yantee Atomic Power Co 2pp 15764 227 24X Fiche 50-309,82/10/07.8210210313
- --8210210316 Notice of violation from insp on 820719-21 * Division of Engineering & Technical Programs 82/10/07 ip 15764 229 24% Fichs 50-309.82/10/07.8210210313.
- --8210210321 IE Befeguarde Insp Rept 50-309/82-11 on 820719-21
 Nancompliance noted failure to establish SNM control &
 accounting procedures to essure that sources & detectore
 racelvedicontrolled, inventoried & shipped property
 KUSHNER:M.L., ODDY, A.T. Division of Engineering & Technical
 Programe 82/09/14 7pp. 15764-230. 24X Fiche 50-309,82/10/07,
 8210210313
- 8210130178 Ack receipt of 820527 ltr informing NRC of stepe taken to correct violations noted in IE Safeguards Insp Rept 50-309/81-02 Corrective actions withheld (ref 100CR73 21). HARTIN, T.T. Division of Engineering & Technical Programs 82/10/08 RANDAZZA, J.B. Maine Vanies Atomic Power Co 2pp 15673 020 24X Fiche: 50-309, 82/10/08, 8210130178
- 821027000B Forwards Revision 2 to "Inservice Inep & Testing Program" GARRITY.J.H Mains Yankes Atomic Power Co 82/10/12 CLARK.R A. Operating Reactore Branch 3 1p 15822 134 24X Fichs 30-309, 82/10/12.821027000B.
- --8210270009 Revision 2 to "Inservice Insp & Teeting Program"
 JONES,D L Meine Yankes Atomic Power Co. 82/09/21, 133pp
 15822.135 24K Fiche.30-309,82/10/12,8210270008
- 8208190238 IR Bulletin 82-03, "Stress Corposion Cracking in Thick-Well, Large-Diameter, Stainiese Steel, Recirculation Sysfiping at BWR Piants." Syc list enci.
 DEYOUNG.R.C. Director's Office Office of Inspection and
 Enforcement. 82/10/14 Consolidated Edison Co of New York
 i15pp. 15810-125, 24X Fiche 50-000, 82/10/14,8208190238
- 8210260144 Forwards addi info re IE Bulistin 80-11. Two addl masonry usils identified in fuel bldg Gne wall located south of spent fuel pool k one wall adjecent to ventilation penthouse. Design adequacy will be re-evaluated.

 OARRITY.J.H. Maine Yankes Atomic Power Co 82/10/21. GLARK.R.A Operating Resctors Branch 3. 28p. 15799.089. 24x

 Fiche 50-309.62/10/21.8210260144
- S Reportable occurrences. LERs & related correspondence
- 8210270165 Forwards LER 81-005/03L-0 WOOD E C Haine Yankse Atonic Pewar Co 81/03/26 Region 1, Philladesphia, Office of the Director (81/03/01), 1p. 15822, 255 24X Ficher 50-209, 81/05/26, 8210270165

- --8210270177 LER Bi-005/03L-0 on 810509, one of three RAS actualish switches failed to close Caused by mati incompatibility Switch replaced w/improved model utilizing stainlsss sizel in place of 6 fress 4 Haine Yantee Atomic Power Co 81/05/26 Region 1, Philadelphia: Office of the Director (81/03/01) 1p 15022 356 24X Fiche 50-309,81/05/26.8210270165
- 8210290267 Part 21 deficiency rept re potential galling problem letter stem & bonnet of 1 25-inch & lerger A105 carbon steel & A182-F22 valves supplied Feb 1981-Aug 1982 Valves should be serviced & stem &/or bonnet replaced ISABELLE.t. D Conval. Inc 82/10/11 HAYNES.R C Region | . CH of Director 17pp 15854 232 24X Fiche 50-000.82/10/11. 8210290267
- 8210210015 Forwards LER 82-027/03L-0
 M00D.E C Maine Vankes Atomic Power Co 82/10/12 Region I. i
 Office of Director Ip 15766 021 24x Fiche 50-309,82/10/12,
 8210210015
- ---8210210019 LER 82-027/03L-0 on 920929, containment isolation illivite safety injection actuation signal steam generator bloudoun valve BD-T-02 failed to fully closs Caused by loose screel lodged between disk & seating surface Parts replaced NELSON,R H Mains Vankee Atomic Power Co 82/10/12 Requiril Office of Director ip 15766 022 24X Fiche 30-309,62/10/12 202020013
- B210260193 Forwards LER 82-026/03L-0 W00D,E C Maine Yenkee Atomic Power Co B2/10/18 Region 6, Office of Director 1p 15804 272 24X Fiche 50-309.02/10/18 B210260193
- --8210260200 LER 82-026/03L-0 on B20924 one steam generator safit; infailed to operate & two veives operated above Tech Bpgc 11mite during test Caused by Instrument drift Cause of instrument drift unknown NELSON.R H Hains Yenkes Atomic Power Co 62/10/10 Replan. Office of Director 2pp 15804 273 24X Fiche 50-30%,02/10.1 Replan.
- 8210260199 Forwards LER 82-028/03L-0 WOOD,E C Maine Vankee Atomic Power Co 82/10/18 Region t Office of Director 1p 15799 148 24X Flohe 50-309,02/10/16 8210260199
- --8210260208 LER 82-028/03L-0 on 820929, containment isolation sign, reset resulted in unexpected opening of control element drive mechanism cooler return velve Caused by open coil in Agretat EEF reset panel vaive suitch control relay NELSON.R H Maine Yenkee Atomic Power Co 82/10/18 Regim Office of Director 2pp 15797 149 24X Fiche 30-309.07/12 t 8210220199
- 8210260327 LER 82-029/017-0 scheduled eddy current tests of stead generator 2 tubes revealed emelt number of tubes esceeding tube plugging limit OARRITY. J. H. Maine Yenkee Atomic Power Co 82/10/18 Fig1:s Office of Director ip 15801.362 24X Fiche 50-309,62/16/18 8210260327.
- 8210290343 LER 82-029/017-1 eddy current tests on steam generales at tubes revealed 10 tubes exceeding tube plugging limit Causes by short radius bend tube degradation Condition also reported by eintier C-E plant
 OARRITY-J H Mains Yankes Atomic Power Co 82/10/19 Riginal Office of Director ip. 15853 028 24X Fiche. 50-309.82/10/19 8291020033
- DOCKET 50-311 BALEM NUCLEAR GENERATING STATION, UNIT 2

 F Security, medical, emergency & fire protection plane
- 8210250245 Forwards 1982 FEMA/NRC observed exercise scenario for Kexercise Revisions reflect changes agreed upon during 820425 meeting W/NRC & FEMA ZUPKO, J. H. Public Service Electric & Qas Co. of New Jerss 82/09/16. HAYNEB, R C. Region 1, Office of Director 1491 15789:002 24% Fichs 50-278, 82/09/16, 8210250245
- 8210260518 Forwards exemption from requirements of JOCFREG 48 of Protection of safe shutdown capability VAROA.S. A. Operating Reactors Branch 1. 82/09/16 UCERITAR Public Service Electric & Ges Co. of New Jarsey 3pp 15839 Hz 24X Fichs 50-272.82/09/16.8210260518.
- ---8210260521 Exemption from requirements of 10CFR50 48 re fire 1">
 of safe shutdown capability.
 EIGENHUT, D. O. Division of Licensing 82/09/14 Public Ference Company Company

- --B210260524 Safety evaluation supporting licenses request for exemption from requirements of 10CFR50 48 re fire protection of safe shutdown capability
 - ** Office of Nuclear Reactor Regulation, Director 82/09/16 3pp 15830 175 24X Fiche 50-272,82/09/16,8210260518
- 8210040431 Forwards exemption from requirements of Section IV F 1 of App E to 10CFR50, to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820739; granting 820709 request VARGA-S A Operating Reactors Dranch 1 82/09/23 UDERITZ, R A Public Service Electric & Qas Co of New Jersey 3pp 15636 227 24X Fiche 50-272,82/09/23,8210040431
- --8210060433 Exemption from requirements of Section IV F 1 of App E to 10CFRSO, to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820929 Evaluation enci EXESENHUT.D O Division of Licensing 82/09/23 Public Service Electric & Oas Co of New Jersey 5pp 15636 230 24% Fithe 50-272.82/09/23.8210060431

P Operating license stage documents & correspondence

- B2100x1000B Responds to FOIA request for 19 categories of documents runclear reactor events & safety problems Forwards documents listed in App A
 FELTON.J H Division of Rules and Records 82/06/28 UDELL.R A
 Critical Mass Energy Project 15pp 15727 005 24X
 Fiche 50-000.82/06/28.8210010008
- --8008050265 Discusses add1 required into to better define potential for cracking in reactor vessel noizles
 ADONAN, V S Assistant Director for Materials & Qualifications
 Engineering 80/05/05 TEDESCO.R L Assistant Director for
 Licensing 2pp 15727 176 24X Fiche 50-000,82/06/28,8210010008
- --8203310089 Forwards memo re equipment malfunctions during 820114 turbine load reduction operation Following review of final rept from licensee & Region 1, will complete evaluation of event for generic implications MICHELSDM.C Director's Office 82/03/13 JORDAN, E L Division of Engineering & Quality Assurance ip 15745 050 24% Fiche 30-000,82/06/28,8210010008
- --8203310074 Summary of 820204 meeting re evaluation of sequence of events of Salem 820114 load reduction transient, operators actions, lessons learned & future remedial actions to be taken
 TREMAN, N K Director's Office 82/02/22 MICHELBON, C
 Director's Office 2pp 15734 034 24X Fiche 30-000, 82/06/28, 82/0010008
- 8210050485 Forwards documentation of satisfactory completion of requirements contained in 790921 ltr re TMI Action Item If E i concerning auxiliary feedwater sys VARGA:S A Operating Reactors Branch i 82/09/20 UDERITZ.R A Public Sarvice Electric & Oas Co of New Jersey 3pp. 15626 277 24% Fiche 50-272,82/09/20,8210050485
- --82:0050490 "Suppl to Bafety Evaluation Rept for Salem Units 1 & 2 Implementation of Recommendations for Auxiliary Feedwater Eys"

 → Office of Nuclear Reactor Regulation, Director 82/09/20 3pp 15626 280 24X Fiche 50-272.82/09/20,8210030485
- B2:0130503 Advises that installed monitoring sys required by TMI Action
 I tems II F 1 4.II F 1 5 & II F 1 6 acceptable & items
 considered closed
 VAROA: S A Operating Reactors Branch I 82/09/28 UDERITZ.R A
 Public Service Electric & Oas Ca of New Jersey 2pp. 15672.349
 24X Fiche 30-272.82/09/28.8210130603
- 8210179047 Informs that util rod exchange methodology not approved because of calculational content of reactivity measurement New submittal or return to boron dilution method requested. VARQA: SA Operating Reactors Branch 1 82/09/29 UDERITZ, RA Public Service Electric & Oas Co of New Jersey 3pp 15761 041 24X Fiche 50-272,82/09/29.8210190047
- 8210190507 Application for amend to Licenses DFR-70 & DPR-75, ravising core limits, fractional thermal power factor limit, performance of RCB water inventory belance & boron concentration & contained vol limits.

 LIDEN.E A Public Service Electric & Oas Co of New Jersey 82/10/05 VARQA: B A Operating Reactors Branch 1 2pp 15863,124 24X Fichs 50-272,82/10/05,8210190507.

- ~-8210190515 Proposed Tech Space supporting application to amend Licensea DPR-70 & DPR-75, revising core limits, fractional power factor limit, performance of RCS water inventory balance & boron concentration & contained vol limits Public Service Electric & Oas Co of New Jersey 82/10/05 17p 15863 126 24X Fichs 50-272,82/10/05.8210190507
- 8210270136 License Change Requests 82-17-20-21 & 22 to Licenses DPR-70 & DPR-75 Changes involve inservice insp of snubbers, steam generator insp ports, containment ventilation valve insp & surveillance functional testing LINDEN.E A Public Service Electric & Gas Co of New Jersey 82/10/07 VAROA.S A Operating Reactors Branch 1 3pp 15837 026 24X Fiche 50-272,82/10/07,8210270136
- ~-8210270142 Progosed Tech Spec changes re inservice insp of snubbers, installation of steam generator insp ports, pressure drop test & reactor trip instrumentation
 # Public Service Electric & Gas Co of New Jersey 82/10/07
 8pp 15927 029 24X Fiche 50-272.82/10/07.8210270134
- 8210180009 Advises that design changes satisfying concerns expressed in 820917 request for add1 info re reactor protection sys/EBF actuation sys Initiated Tech Specs will be modified to address satpoint changes
 LIDENIE A Public Service Electric & Oas Co of New Jeresy 82/10/08 VAROA, 8 A Operating Reactors Branch 1 ip 18720 024 24X Fiche 50-272, 82/10/08, 82/10180009
- 8210270352 Forwards Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively, safety evaluation & notice of issuance & availability Amend revises process & effluent monitors to agree w/existing plant conditions
 ROSS: W J Operating Reactors Branch 1 82/10/18 UDER1TZ, R A Public Service Elactric & Oas Co. of New Jersey 2pp 15934-318
 24% Fiche. 50-272, 82/10/18, 8210270352
- --8210270359 Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively, revising process & effluent monitors to agree w/existing plant conditions URPA-45, respectively, plant conditions VAROA.5 A Operating Reactors Branch 1 82/10/18 14pp, 15834 320 24X Fiche 50-272, 82/10/16, 8210270352
- ~-8210270360 Safety evaluation supporting Amends 48 & 13 to Licenses BPR-70 & BPR-75, respectively ◆ Office of Nuclear Reactor Regulation, Director 82/10/18 &pp 15834 334 24X Fiche 50-272,82/10/18,8210270352
- --B210270346 Notice of issuance & availability of Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively VAROA: S A Operating Reactors Dranch 1 B2/10/18 2pp 15834 340 24% Fiche 50-272, 82/10/18,8210270352
- Q Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 17 categories of info re nuclear reactor events & safety problems. Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5).
 FELTONIJ M. Division of Rules and Records 82/07/12 UDECLIR A Critical Mass Energy Project 9pp 15665 027 24K Fiche 50-000, 82/07/12, 8210080015
- ---B210080150 Systematic assessment of licensee performance notes re facility evaluation for Sept 1979-Aug 1980 * NRC - No Detailed Affiliation Given 80/08/31 Spp 15648 043 24X Fiche-50-000, 82/07/12, 8210080015
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B.
 FELTON.J H Division of Rules and Records 82/08/10, LDNO, D J Winthrop, Stimson, Putnam & Roberts. 9pp 13645 063 24% Fiche 50-000, 82/08/10, 8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch. \$2/04/01. VAROA.B Operating Reactors Branch 1. 5pp. 15645,131. 24X Fiche 50-000,82/08/10,8210070007.
- 821012032B Responds to violations noted in IE Insp Repts 50-272/82-17 to 50-311/82-17 on 820707-0803. Corrective actions administrative procedure will be revised so future temporary design changes are removed on timely basis UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 82/09/28. HAYNES, R. C. Region i, Office of Director. 87ARDSTECKI, R. Division of Project & Resident Programs. 5pp 15452:125 24X Fichs. 50-272, 82/09/28, 821012032B

- 8210050302 Responds to 820708 request for addition or control element assembly & furl assembly fretting year insys
 OARRITY.5 H. Maine Yantse Atomic Power Co. 82/09/28 GLARK.R. A
 Operating Reactors Branch 3 490 15519 202 24X
 Fiche 50-309.82/09/28.8210050302
- 8210150399 Forwards response to NRC request for addd info re IE
 Bulletin 80-ii, "Masonry Hall Design " All required mods
 installed by 820301 Math error detected which requires
 strangthaning of wall will be accomplished at 1982 outage
 QARRITY, J H Maine Yankse Atonic Power Co 82/09/30 CLARK, R A
 Operating Reactors Branch 3 78pp 15703 886 24%
 Fiche 50-309. 82/09/30. 82/0150398
- 820Bi90233 IE Info Notice 80-35, Suppl i. "Leaking & Dislodged I-125 Explant Stads " Svc list encl COBBL I Division of Fuel Facalities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fisch 50-000:82/10/06:820Bi90233
- 8210210135 Foruards IE lnsp Rept 50-309/82-12 on 620726-30 No noncompliance noted ALLANJ H Region 1. Office of Director 82/10/06 RANDAZZA, J B Haine Yankee Atomic Faver Co 2pp 15765 107 24X Fiche 50-309, 82/10/06, 8210210136
- --8210210142 IE Insp Rept 50-307/82-12 on 820724-30 Ne noncompliance noted Major areas inspected followup of energency preparendess items from 810908-15 appreiral HOUNAGE J . CRUCKER. H W Division of Emergency Preparedness & Operational Support 82/09/30 11pp 15766 109 24% Fiche 50-309, 82/10/04, 8210210136
- B210210313 Forwards IE Bafeguards Insp Rept 50-309/82-11 on 820719-21 binobics of violation in Engineering & Technical Programs B2/10/07 RANDAZZA, J B Hains Yanter Atomic Power Co 2pp 15764 227 24% Fiche 50-309, 82/10/07
- --8210210316 Notice of violation from insp on 820719-21 • Division of Engineering & Technical Programs 62/10/07 ip 15764 229 24% Fiche 80-309, 82/10/07, 8210210313
- --8210210321 IE Sefeguards Insp Rept 50-209/82-11 on 820719-21
 Noncompliants moted failure to establish SNN control &
 eccounting procedures to essure that sources & detectors
 received controlled inventoried & shipped properly
 KUSHNER.H L , CODY.A T. Division of Engineering & Technical
 Programs 82/09/14. 7pp 15744.230, 24X Fiche:50-309.82/10/07,
 8210210313
- 8210130178 Atk receipt of 830527 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Right 50-309/81-02 Corrective actions withheld (ref 100FR73.21). HARTIN: T. Division of Engineering & Technical Programs 92/10/08 RANDAIZA: J B Mains Yankse Atomic Power Co 2pp 15673 020 24X Fichs: 50-309.82/10/08,8210130178
- 821027000B Forwards Revision 2 to "Inservice Insp & Yesting Program "
 CARRITY, J H Heine Yentee Atomic Power Co 82/10/12 CLARK: R A.
 Operating Reactors Branch 3 jp. 15822 134. 24X
 Fiche. 00-309: 82/10/12.0210270008
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diemeter, Stainlass Steel, Recirculation Sys Piping at BKR Plants " Syc list encl DEYOUND, S. C. Director's Office, Office of Inspection and Enforcement, 82/10/14 Concolidated Edison Co. of New York 115pp. 13810:125 84X Fichs 50-000,82/10/14,8208190238
- E210260144 Forwards add1 info re IE Bulletin 80-11 Two add1 masonry walls identified in fust bids One wall located south of spent fuel pool is one well adjacent to ventilation penthouse Design adequacy will be re-evaluated GARRITY. J. H. Haine Yantee Atomic Power Co. B2/10/21. CLARK. R. A. Operating Reactors Branch J. 2pp. 13799-089 24X Fiche. 50-309. 82/10/21. 8210260144.
- S Reportable occurrences, LERs & related correspondence
- B210270165 Forwards LER 81-003/031-0 UDOD, E.C. Maine Yankes Atomic Power Co. 81/05/26. Region i, philadelphia, Office of the birector (81/03/05) ip. 13822: 555. 24X Fichs. 50-309. 81/05/26. 8210270165

- --9210270177 LER 81-005/03L-0 on 810309, one of three RAS actualized switches failed to close Caused by mall incompatibility Switch replaced w/improved model utilizing stainless right in place of brass a Heine Yankee Atomic Power Co 81/05/26 Region 1. Philadelphia, Office of the Director (81/03/01) is 15022 3/2 24% Fishe 50-209, 81/05/26, 8210270165
- 8210290267 Part 21 deficiency rept re-potential gallang problem 164 stem & bonnet of i 25-inch & larger A105 carbon steel & A182-F22 vaives supplied Feb 1981-Aug 1932 Valves should be serviced & stem &/or bonnet replaced ENABELLE, L. D. Convel. Inc. B2/10/11 HAYNES, R. C. Region 1. Cr. of Director 179p 15854 232 24X Fiche 50-000.82/10/11. 8210290267
- E210210015 Forwards LER 82-027/03L-0
 NODO.E C Maine Yankee Atomic Power Co 82/10/12 Region 1.
 Office of Director ip 15766 021 24X Fich = 50-309,82/10/12
 8210210015
- --8210210018 LER 62-027/03L-0 on 920929 containment isolation eight safety injection actuation signal steam generator bloadcun valve BD-T-32 failed to fully close Caused by loose trew ludged between disk & seating surface Parts replaced NELSON.R H Maine Yankee Atomic Power Co 82/10/12 Republice of Director 1p 15766 022 24X Fiche 50-10% 02/16/12 6210210013
- 0210260193 Forwards LER 82~026/03L-0 1000/E C Maine Yankee Atomic Power Co 82/10/10 Region 2 Office of Director 1p 15804 272 24% Fiche 50~309,82/10/18 P210220193
- --B210260200 LER 82-026/03L-0 on 820924 one steam generator (afet). failed to operate & two valves operated above Tech Spec limits during test Caused by instrument drift cause of instrument drift unknown NELBON. R H Haine Yankee Atomic Power Co 02/10/10 Regn. Office of Director 2pp 15804 272 24% Fiche 38-30% 62/17 (8210260193
- 6210280199 Forwards LER 82-028/03L-0 (MODDLE C Mains Vankes Atomic Power Co 82/10/10 Region' Office of Director in 15799 148 24X Fiche 50 TOV. ID/10/12
- --8210260208 LER 82-028/03L-0 on 820727.containment isolation e.g. reset resulted in unexpected opening of control element drive mechanism coder return valve Caused by open coll in Agastat EBF reset panel velve switch control relay NELEGIB H Hains Vankee Atomic Power Co 92/10/10 Fet. Office of Director 2pp 15797.149 24x Fiche 50 307.62/1/1 8210260197
- 8210260327 LER 82-029/017-0 scheduled eddy current tests of size generator 2 tubes revealed small number of tubes esceeding tube plugging limit OARRITY. J. H. Haine Yankoe Atomic Power Co. 82/10/18 Feet Office of Director ip. 15801 362. 24X Fiche. 50-309 64/17/18 8210260327
- 8210290343 LER 82-029/017-1.eddy current tests on clean generally tutes revealed in tubes exceeding tube slugging limit Caulil by short radius bend tube degradation Condition also reported by similar C-E plant GARRITY.J.H. Hains Yankes Atomic Power Co. 82/10.19 Fig. Office of Director ip. 15853 028. 24% Fiche 50-309. F2/11 18210290343.
- DOCKET 50-311 SALEN NUCLEAR GENERATING STATION, UNIT 2 F Security: medical, emergency & fire protection plane
- 8210230245 Forwards 1982 FEMA/NRC observed exercise scenario for Axercise. Revisions reflect changes agreed upon during 826422 , asetting u/NRC & FEMA (UPKO, J. M. Public Bervice Electric & Oas Co. of New Jerses, 82/09/16. MAYNES, R. C. Region 1. Office of Director 14819 15789:002. 24X Fiche: 50-272, 82/09/16, 8210250245
- 8210260818 Forwards exemption from requirements of 106f850 & 1117 grotection of safe shutdown capability VARQA-8. A. Operating Reactors Branch 1. 82/09/16 USTF1111 Public Service Electric & Oas Co of New Jarssy 319 1202 & 24K Fiche: 50-272,82/09/16,8210260518
- --B210260321 Examption from requirements of 10CFR30 4B st 41/2 pm of 3afa thutdown capability RIBCHHUT. D O Division of Licensing. 82/09/16 Patics RIBCHHUT. D O Division of Licensing. 82/09/16 Patics RIBCHHUT. D OF New Jarrey 4pp. 15830 171 341 Fiche: 50-272, 82/09/16, 8210260518.

- --821026D524 Safety evaluation supporting licenses request for exemption from requirements of 10CFR50 48 re fire protection of safe * Office of Nuclear Reactor Regulation, Director 15830 i75 24% Fiche 50-272,82/09/16,8210260518 82/09/16 3pp
- 8210050431 Forwards exemption from requirements of Section 1V F 1 of App E to 10CFR50 to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820929, granting 820709 request VAROA.8 A Operating Reactors Branch 1 82/09/23 UDERITZ, R A Public Service Electric & Cas Co of New Jersey 3pp 15636 227 24X Fiche 50-272,82/09/23,8210060431
- --8210060433 Exemption from requirements of Section IV F 1 of App E to 10CFR50, to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820729 Evaluation encl
 EISENHUT.D 0 Division of Licensing 82/09/23 Public Service
 Electric & Oas Co of New Jersey 5pp 15636 230 24X
 Fiche 50-272,82/09/23,8210060431

P Operating license stage documents & correspondence

- 5210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents Issted in App A Fig. To. 30 M Division of Rules and Records 82/06/28 Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008 82/06/28 UDELL,R A
- --8908050265 Discusses addl required info to better define potential for cracking in reactor vessel horries
 NOONAR VS Assistant Director for Materials & Qualifications
 Engineering 80/05/05 TEDESCO.R L Assistant Director for
 Lacensing 2pp 15727 176 24X Fichs 50-000,82/06/28,8210010008
- --8203310089 Forwards memo re equipment maifunctions during 820114 ACCIONATION TO THE PROPERTY OF THE PROPERTY OF
- --8203310094 Summary of 820204 meeting re evaluation of sequence of events of Salem 820114 load reduction transient operators actions, lessons learned & future remedial actions to be TREMAN, N K Director's Office 82/02/22 MICHELSON, C Director's Office 2pp 15734 036 24% Fiche 50-000, 82/06/28, 8210010008
- 8210050485 Forwards documentation of satisfactory completion of requirements contained in 790921 itr re TMI Action Item II E 1 concerning auxiliary feedwater sys VARGA.8 A Operating Reactors Branch 1 82/09/20 UDERITZ.R A Public Service Electric & Coas Co of New Jersey 3pp 15626 277 244 Fiche.50-272:82/09/20.8210050485
- --8210050490 "Suppl to Safety Evaluation Rept for Salem Units 1 & 2 Implementation of Recommendations for Auxiliary Feedwater Sys "
 - nys -• Office of Nuclear Reactor Regulation, Director 82/09/20 3pp 15626 280 24X Fiche 50-272,82/09/20,8210050485
- 8210130603 Advises that installed monitoring sys required by TM1 Action Items II F i 4.11 F i 5 k II F i 6 acceptable k items considered closed
 - VARQA'S A Operating Reactors Branch 1 82/09/28 UDERITZ, R A Public Service Electric & Gas Co of New Jarsey 2pp. 15492:349 24% Fiche 50-272:82/09/28.8210130403
- B210190047 Informs that util rod exchange methodology not approved 210190047 Informs that util rod exchange methodology not approved because of calculational content of reactivity measurement New submittal or return to boron dilution method requested VARGA-S A Operating Reactors Branch 1 82/09/29 UDERITZ,R A Public Service Electric & Gas Co of New Jersey 3pp. 15761 04! 24X Fiche 50-272.82/09/29,8210190047. 3pp. 15761 041
- 8210190507 Application for amend to Licenses DPR-70 & DPR-75, revising core limits, fractional thermal power factor limit, performance of RCS water inventory balance & boron concentration & contained vol limits
 LIDEN.E A Public Service Electric & Gas Co of New Jersey 82/10/05 VAROA: S A Operating Reactors Branch 1 2pp. 15863.124, 24X Fiche 50-272,82/10/05,8210190507

- --8210190515 Proposed Tech Specs supporting application to amend Licenses DPR-70 & DPR-75 revising core limits fractional power factor limit parformance of RCS water inventory balance & boron concentration & contained vol limits * Public Service Electric & Oas Co of New Jersey. 82/10/05 17pp 15863 126 24% Fiche 50-272,82/10/05,8210170507
- 8210270136 License Change Requests 82-17-20-21 & 22 to Licenses BPR-70 & DPR-75. Changes involve Inservice insp of snubbers, steam generator insp ports, containment ventilation valve insp & surveillance functional testing LINDEN, E & Public Service Electric & Gas Co of New Jersey. 82/10/07 VAROA, E & Operating Reactors Branch 1 3pp 15827 026 24X Fichs 50-272,82/10/07,8210270136
- --B210270142 Proposed Tech Spec changes re inservice imap of snubbers, installation of steam generator insp ports, pressure drup test & reactor trip instrumentation a Public Service Ricctric & Oas Co of New Jersey 82/1 Bpp 15827 029 24X Fiche 50-272,82/10/07.8210270134
- 8210180009 Advises that design changes satisfying concerns expressed in 820917 request for addl info re reactor protection sys/ESF actuation sys initiated Tech Specs will be modified to address setpoint changes B2/10/08 VARQA,S A Operating Reactors Branch 1 lp 15720.024 24X Fiche 50-272.82/10/08.8210180009
- 8210270352 Forwards Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively, safety evaluation & notice of issuance & availability Amend revises process & effluent monitors to agree w/existing plant conditions.

 ROSB: W J Operating Reactors Branch | 62/10/18 UDERITZ:R A Public Service Electric & Gas Co. of New Jersey 2pp | 19834 318 24X Fiche 50-272,82/10/18.8210270352
- --8210270355 Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively, revising process & effluent manitors to agree w/existing Plant consistions
 VARQA.S A Operating Reactors Branch 1. 82/10/18 14pp
 15934 320 24X Fiche 50-272, 82/10/18, 8210270352
- --8210270360 Safety evaluation supporting Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively

 * Office of Nuclear Reactor Regulation, Director
 15834 334 24X Fiche 50-272,82/10/18,8210270352 82/10/18, App.
- --8210270366 Notice of issuance & availability of Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively VAROA, B A Operating Reactors Branch 1 82/10/18 2pp 15834 340 24% Fiche: 50-272, 82/10/18,8210270352
- Q Inspection reports, IE Bulletins & correspondence
- 8210080019 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents iisted in App A Documents in App B completely withheld (ref Exemption 5) FOLTON, J.M. Division of Rules and Records, 82/07/16 Critical Mass Energy Project 9pp 15665; 027 24X Fiche 50~000, 82/07/12, 8210080015 82/07/12 UDELL,R A
- --8210080180 Systematic assessment of licensee performance notes re facility evaluation for Sept 1979-Aug 1980 + NRC No Detailed Affiltation Given 80/08/01 Bpp 15668 043 24X Fiche:50-000,82/07/12.8210080015
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines. App A documents provided in R_Udel1 FOIA Request B1-313 Forwards documents listed in App B FELTON.J.H Division of Rules and Records. 82/08/10. LONG.D J. Winthrop. Stimson. Putnem & Roberts. 7pp. 15645 069 24X Fiche 50~000, 82/08/10, 8210070007
- -8210070139 Forwards tabulated data on steam generator insp & maint at PROLITO, T. Operating Reactors Assessment Branch 92/04 VAROA. B. Operating Reactors Assessment Branch 92/04 VAROA. B. Operating Reactors Branch 1 Spp 15645-131 Fiche 50-000, 82/08/10, 8210070007 82/04/01
- 3210120328 Responds to violations noted in IE Insp Repts 50-272/82-17 & 50-311/82-17 on 820707-0803 Corrective actions. administrative procedure will be revised to future temporary design changes are removed on timely basis.

 UDERITZ-R.A. Public Bervice Electric & Ges Co of New Jersey.
 92/09/28 HAYNES,R C Region 1, Office of Director STAROBIECKI,R Division of Project & Resident Programs. Spp 15652,125 24X Fichs 50-272,82/09/28,8210120328

14

1

1 4

1.

٠.

1

- 820B190233 IE Info Notice 80-35, Suppl 1. "Leating & Dislodged I-125 Implant Seeds " Syc fist encl COBB.t I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Constituted Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06.920B190233
- 8210210435 Forwards IE Insp Repts 50-272/82-20 & 50-311/82-20 on 820816-20 No noncompliance noted MARTIN.T T. Division of Engineering & Technical Programe 82/10/06 UDERITZ.R A Public Service Electric & Cas Co of New Jersey 2pp 15763 036 24X Fiche 50-272,82/10/06,8210210405
- --8210210451 IE Insp Repts 50-272/82-20 & 50-311/82-20 on 820816-20 No noncompliance noted Hajor areas inspected qualification & training, radiological surveys, radiation exposure permits, posting, licensee audits & exposure control HOSEY, C M. ROME, C A. GREENHAN, E Q Division of Engineering & Tachnical Programs 82/09/30 5pp 15763 03B 24X Fiche 50-272, 82/10/06, 8210210435
- 8210210464 Forwards IE Insp Repts 50-272/82-25 & 50-311/82-24 on 820901-27 & notice of violation STAROBIECKI, R Division of Project & Resident Programs. 82/10/06 UDERITZ, R A Public Service Ejectric & Gas Co of New Jersey 2pp 15763 018 24x Fiche 50-272,82/10/06,8210210464
- --8210210469 Notice of violation from insp on 820901-27
 ** Region i, Office of Director 82/10/06 ip 15743,020 24X
 Fiche 50-272,82/10/06,8210210464
- --B210210477 IE Insp Repts 50-272/B2-25 & 50-31i/B2-24 on B2090i-27 Noncompliance noted trip breaters closed w/o two operable source range instruments in svc & failure to submit 30-day LER NORRHOLH, L. J. SUMMERS, R. TRIPP, L. E. Division of Project & Resident Programs B2/10/04 i5pp 15763 G21 24X Piche 50-272,82/10/06,8210210464
- B2/02/0136 License Change Requests B2-17-20-21 & 22 to Licenses DPR-70 & DPR-75 Changes involve inservice insp of snubbers, steam generator insp ports, containment ventilation valve insp & surveillance functionel testing LINDEN, E.A. Public Bervice Electric & Gas Co. of New Jersey B2/10/07 VARGA, B.A. Deperating Reactors Branch (3pp. 15827-026-24X Fiche: 50-272, 82/10/07, 82/10270136
- --8210270142 Proposed Tech Bpec changes re inservice insp of snubbers, installation of steam generator insp ports, pressure drop test it reactor trip instrumentation a Public Service Electric & Qas Co of New Jersey 82/10/07 8pp 15827 029. 24X Fiche 50-272,82/10/07,8210270136
- 820B17023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Mall.Lerge-Diamater, Stainless Steel, Recirculation Sys Piping at BMR Plante " Svc list encl.
 DEYOUND: R C Director's Office, Office of Inspection and Enforcement. B2/10/14. Consolidated Edison Co of New York 115pp 15810-125 24X Ficher 50-000, 82/10/14, 820B17023B
- 8210280221 EN-82-034 on 821027 notice of violation & proposed imposition of civil penelty in amount of \$40,000 issued reinadequate vitel physical area berrier ROSAND.R., AXELRAD.J Director's Office. Office of inspection and Enforcement 82/10/22 ip 15837 087 24% Fiche 50-272,82/10/22, paragraphy.
- R Periodic operating reports & related correspondence
- 8210200010 Forwards monthly operating rept for Bept 1982 MIDURA: H J Public Bervice Electric & Qae Co. of New Jersey. ice. Office of Inspection and Enforcement. 30-311.82/10/10.8210200010

f New Jarsey. 2/10/10,8210200010

- 8210010008 Responds to f01A request for 19 categories of documents requested in the reactor events & safety problems Forwards documents listed in App A FELTON.) M Division of Rules and Records 82/06/28 UDELL.R & Critical Mass Energy Project 15pp 15727 005 24% Fiche 50-000, 82/06/28, 8210010008
- --82(0050124 Summary of 810610 operating reactor events meeting LAINAB.0 C Assistant Director for Safety Assessment 01/06/17 ; EISEMHUT.D O Division of Licensing 5pp i5729 217 241 Fiche 50-000, 82/06/28.8210010008
- 02:00:0045 Forwards LER 82-095/03L-0 Detailed event analysis sncl MIDURA:H J Public Service Electric & Oas Co of New Jersey 82/09/16 HAYNES:R C Region in Office of Director Jep 15565 137 24X Fichs 50-31i,82/09/16.82100:0045
- --8210010047 LER 82-095/03L-0 on 820831, surveiliance revealed that control placed in valve 21 MS46 of auxiliary feedwater systems iine 23 Caused by sheared off stud which attaches valve dist to hanger Engineering analysis conducted HELLER, R Public Service Electric & Gas Co of New Jersey 82/09/16 Region i, Office of Director 19 15565 140 241 Fiche 50-311,82/09/168210010045
- 8210010123 Forwards LER 82-092/017-0 Detailed event analysis snot MIDURA. H J. HELLER.R Public Service Electric & Ges Co. of New Jersey 82/09/16. HAYNES.R C Region 1, Office of Director Units 60 014 24x Fiche 50-311,82/09/16,8210010123
- --B210010128 LER B2-092/01T-D on B2090B, svc water leak distruser? es containment fan coil unit 21 Caused by erosion of motor cooling coils Motor cooler replaced & fan coil tested satisfactorily
 HELLER.R Public Service Electric & Cas Co of New Javety
 B2/09/16 Region 1. Office of Director ip 15566 010 241
 Fiche 50-311. B2/09/16.8210010123
- 8210010144 Forwards LER 82-096/03L-0 Detailed event analysis 4613 MIDURA, H J Public Service Electric & Oas Co of New Jerily 82/09/16 HAYNES, R C Region 1. Diffice of Director 3gs 15567 240 24X Fichs 50-311, 82/09/16, 8210010144
- --8210010150 LER 82-096/03L-0 on 820831, containment fan ceil unit 27 declared inoperable when operator received indication of lew sex water fiow Caused by sith buildup in cooling ceils flow control valve cycled & unit tested satisfactority HELLER.R Public Service Electric & Cas Co of New Jersey 82/09/16 Region in Office of Director ip 13367 243 Ear Fiche 50-311,82/09/16.8210010144.
- B210010227 Forwards LER 82-090/03L-0 Datailed event analysis and MIDURA.H.J Public Service Electric & Cas Co of New Jersey 82/09/16 HAYNES.R C Region 1, Office of Director 3pp 13574 018 24X Fiche 50-311,82/09/16.8210010237.
- --8210010239 LER 82-090/03L-0 on 820882.operator discovered 1915 (-) F 100-ft stevation containment air lock outer door Gaused by rubber seal pertially leaving retaining groove due to personnel closing door w/excessive force 8481 replaced HELLER.R Public Service Electric & Oas Co of New Jersty 82/09/16 Region 1, Office of Director 1p 15574 021 24 Fiche, 50-311, 82/09/16 8210010827
- 8210010344 Forwards LER 82-094/03L-0 Detailed event analysis set induka, H J. Public Service Electric & Oat Co of New Jeret, B2/09/16 HAYNES, R C. Region in Office of Director Set 1555-222. 24X Fiche 50-311,82/09/16,8210010344
- --8210010355 LER 82-094/03L-0 on 820825,2C vitel bus undervelter the failed to trip at required satpoint Causad by satpoint drift Channel declared operable & Action Statement 3.3 % Action 14 terminated HELLER, R Public Service Electric & Qas Co of New Jersi 82/09/16. Region in Office of Director 19. 15567 232 Feb Fiche: 50-311,82/09/16.8210010344
- B210010407 Forwards LER 82-088/03L-0 Detailed event analysis reli MIDURA.H.J Public Service Electric & Oas Co. of New Jarrey 82/09/16 HAYNES.R.C Region 1. Office of Director 3pp 15572-203. 24K Fichs 50-311.82/09/16.8210010407
- --8210010412 LER 82-088/03L-0 on 820824, containment fan cell weit 2d declared inoperable after low svc water flow observaf Causal by air regulator being out of adjustment. Air regulator adjusted & fan cell unit satisfactorily tested.

 HELLER, R Public Service Electric & Gas Co. of New Jersel 82/09/16 Region i, Office of Director ip 15572 204 24 Fiche. 50-311, 82/09/16. 8210010407

- 8210010419 Forwards LER 62-093/017-0 Detailed event analysis encl HIDURA.H J Public Service Electric & Gas Co of New Jersey 82/09/16 HAYNES.R C Region 1. Office of Director 4pp 13569 339 24x Fiche 50-311,82/09/16.8210010419
- --8230010423 LER 82-093/01T-0 on 820910, containment fan coll unit 21 declared inoperable when svc water leak discovered Caused by erosion of cooling coll Leaking coll blanked off Design change submitted to replace colls w/erosion resistant matl HELLER.R Public Service Electric & Cas Co of New Jersey 82/09/16. Region 1. Office of Director 1p 15569 342 24x Fachs 50-311,82/09/16.8210010419
- 0210010455 Forwards LER 02-102/03L-0 Detailed event analysis encl MIDURAH J Public Service Electric & Gas Co of New Jersey 82/09/16 HAYNES,R C Region 1. Office of Director 3pp 15570 001 24x Fiche 30-311,02/09/16.8210010455
- --B210010461 LER 82-102/03L-0 on B20823.130-ft elevation containment air lock declared inoperable after excessive leakage discovered past inner door seals Caused by closing door w/escessive force Seal replaced Installation of snubbers proposed HELLER, Public Service Electric & Gas Co of New Jersey B2/09/16 Region 1. Office of Director ip 15570 004 24x Fiche 50-311,82/09/16,8210010455
- 8210070221 Forwards LER 82-101/01T-0 Detailed event analysis encl MIDUSA.H J Public Service Electric & Gas Co of New Jersey 82/09/22 HAYNEB.R C Region 1, Office of Director App 15537 156 24X Fiche 50-311,82/09/22,8210070221
- --B210070231 LER 82-101/01T-0 on 820916, svc water leakage discovered in cooling coils of containment fan coil unit 21 Gaused by excessive erosion of cooling coils by silt Coils repaired New design coils will be installed during next refueling FRAMHR Public Service Electric & Qas Co of New Jersey B2/09/22 Region 1, Office of Director 1p 15637:160 24X Fische 50-311,82/09/22.8210070221
- 8210070246 Forwards LER 82-099/03L-0 Detailed event analysis encl MIDURA:H J Public Service Electric & Gas Co of New Jersey 82/09/22 HANNES,R C Region 1. Office of Director 3pp 15634 293 24x Fiche 50-311.82/09/22.8210070246
- --8210070248 LER E2-099/03L-0 on 820902, control room operator received indication of low syc water flow on containment fam coil 23 Caused by silt buildup in cooling coils 8vc water flow control isolation valve cycled MELLER.R Public Service Electric & Cas Co of New Jerszy 62/09/22 Region 1. Office of Director ip 19434 294 24x Fiche 50-311,82/09/22,8210070246
- 9210070249 Forwards LER 92-100/017-0 Detailed event analysis encl MIDURAH J Public Service Electric & Gas Co of New Jersey 92/09/22 HAYNES, R C Region 1, Office of Director 4pp 158-34 268 24x Fiche 50-311,62/09/22,8210070249
- --B210070252 LER 82-100/01T-0 on 820915, svc water leak of approx 0 3 gpm discovered on cooling coil of containment fan coil 22 Caused by excessive erasion of cooling coil by silt in svc water. Leaking coil repaired FRAHN.R Public Service Electric & Gas Co of New Jersey. 82/09/22 Region 1 Office of Director ip 15634 292 24X Fiche 50-311,82/09/22,8210070249
- 8210070254 Forwards LER 82-061/03X-1 Detailed event analysis and MIDURA:H J Public Service Electric & Gas Co of New Jarsey 82/09/22 HAYNES:R C Region 1. Office of Director 3pp 15634 283 24X Fiche 50-311.62/09/22.6210070254
- --821007025B LER 82-061/03/-1 on 820716.steam generator level channel II indication erratic Caused by leakage past packing on Root valve 218F28 Valve repacked & leakage stopped FRAMH.R Public Service Electric & Oas Co of New Jersey 82/09/22 Region i. Office of Director ip 15634,286 24X Fiche 50-311,82/09/22.8210070254
- 8210070351 Forwards LER 82-078/03L-0 Detailed event analysis encl MIDURAH J Public Service Electric & Qas Co. of New Jersey 02/07/22 HANNES, R C Region 1, Office of Director 2pp 15634 047 24X Fiche 50-311.62/09/22.8210070351
- --B210070359 LER 82-098/03L-0 on 820901.indication of low syc water flow received on containment fan coil unit 21 Caused by slit build-up in cooling coils 8vc water flow control valve cycled & coil unit tested satisfactorily HELLER.R Public Service Electric & Cas Co of New Jersey B2/09/22 Region 1. Office of Director ip 15634 050 24X Ficha 50-311,82/09/22.8210070351

- B210070371 Forwards LER 82-012/03X-1 Detailed event analysis encl HIBURA.H J Public Service Electric & Gas Co of New Jersey 82/09/22 HAYNES.R C Region 1. Office of Director 3pp 15433.027 24X Fiche 50-311,82/07/22,8210070371
- --8210070377 LER 82-012/03X-1 on 820209, steam generator level channel 2 displayed erratic behavior. Indicating Grift Apparently caused by intermittent ground on signal lead. Ground aliminated by lifting leads while troubleshooting problem FRAHM.R Public Service Electric & Gas Co of New Jersey 82/09/22 Region 1. Office of Director ip 15634 030 24% Fiche 50-311,82/09/22.8210070371
- 8210130164 Forwards LER 82-103/03L-0 Detailed event analysis encl MIDURA,H J Public Service Electric & Gas Co of New Jersey 82/09/27 HAYNES,R C Region i. Office of Director 3pp 15473 057 24X Fichs 50-311,82/09/29,8210130464
- --8210130170 LER 82-103/03L-0 on B20704, while running auxiliary alarm summary, control breaker elarm observed for containment spray pump 21 Gaused by opened 4 ky breaker HL contact Breaker racked out & pump declared operable FRAHM: R Public Service Electric & Gas Co of New Jersey 82/07/27 Region 1. Office of Director ip 15673-060 24X Fiche 50-311,82/09/29,8210130164
- 8210130219 Forwards LER 82-097/03L-O Detailed event analysis encl MIDURA, H J Public Service Electric & Cas Co of New Jersey 82/09/29 HAYNES, R C Region 1, Office of Director 3pp 15675 265 24X Fiche 50-311, 82/09/29, 8210130219
- --8210130227 LER 82-097/03L-0 on 820910.RCS water inventory not performed within specified time interval Caused by failure of surveillance to make allowance for routine unavoidable transients precluding inventory performance FRAMM.R Public Service Electric & Cas Co of New Jersey 82/09/29 Regaon 1. Office of Director 1p 15675 268 24X Fiche 50-311.82/09/29.8210130219
- 8210130340 Forwards LER 82-105/03L-0 Detailed event analysis encl MIDURA, H J Public Service Electric & Qas Co of New Jersey 82/09/29 HAYNES, R C Region 1, Office of Director 3pp. 15682 046 24X Fiche 50-311,62/09/29,6210130340.
- --8210130345 LER 82-105/03L-O on 820908, svc water flow to containment fan coil unit 22 found less than required by Tech Specs. Caused by silt deposited in cooling coils restricting eve water flow Pressure control valve cuted to flush out silt FRAHM.R Public Service Electric & Cas Co of New Jersey 82/09/29 Repion i. Office of Director ip 15682 049 24X Fiche-50-311,82/09/29.8210130340
- 8210130351 Forwards LER 82-107/01T-0 Detailed event analysis encl MIDURA, H J Public Service Electric & Cas Co of New Jersey 82/07/29 HAYNES, R. C Region 1. Office of Director 4pp 15680 315, 24X Fiche 50-311,82/07/29,8210130351
- --8210130358 LER 82-109/01T-0 on 820923 svc water leakage of approx 0 6 gpm discovered on containment fan cull unit 21 cooling cull Caused by erosion by silt in evc water Leaks repaired w/blanked flange & Beliona metal filler.
 FRAHM.R. Public Service Electric & Gas Co of New Jersey 82/09/29 Region 1 Office of Director 19 15680-319 24X Fiche 50-311, 82/09/29, 8210130351
- 8210150057 Forwards LER 82-086/03L-0 Detailed event analysis encl MIDURA,H J Public Service Electric & Oas Co of New Jersey. 82/09/29 HAYNES,R. C Region 1. Office of Director 3pp 15698 300 24x Fiche 50-311.82/09/29,8210150057
- --8210150065 LER 82-086/03L-0 on 820915, water observed dripping from oil level sightglass on svc water pump motor Caused by failed mator bearing oil cooler for due to accelerated erosion & corrosion Failed cooler repaired.

 FRAHMIR Public Service Electric & Oas Co. of New Jersey 82/07/27 Region 1, Office of Director ip. 15678,303. 24X Fiche 50-311,82/09/29,8210150057.
- 6210150109 Forwards LER 62-104/03L-0. Detailed event analysis encl MIDURA: H J. Public Service Electric & Oas Co of New Jersey. 62/09/29 HAYNES: R C Region i. Office of Director Spp. 15697 059 24X Fiche 50-311.62/09/29.8210150109
- --B210150118 LER B2-104/O3L-0 an B2090B, vital bus 2A would not transfer automatically from one 4 kV transformer to another. Caused by dirt in undervoltage relay Relay cleaned FRAHMIR. Public Service Electric & Oas Co of New Jersey B2/09/29. Region 1. Office of Director. Ip 18697 062 24K Fiche 50-311, 82/09/29, 8210150109

- 8210150088 Forwards LER 82-073/01T-0 MIDURA, H J Public Service Electric & Gas Co of New Jersey B2/09/30 HAYNES, R C Region 1, Office of Director ip 15701 198 24% Fiche 50-311,82/09/30.8210150088
- --8210150093 LER 82-073/01T-0 on 820813, during containment entry, 1 5 gpm svc water leak discovered on containment fan coil Unit 23 Caused by failed cooling coil due to erosion by salt particles Leak repaired w/8813ma metal filler FRAHM: R Public Service Electric & Oas Co of New Jersey 82/08/16 Region 1. Office of Director ip 15701 199 24X Fiche 50-311,82/09/30.8210150088
- 6210150097 Forwards corrected LER 82-075/01T-0 MIDURA,H J Public Service Electric & Gas Co of New Jersey 82/09/30 HAYNES,R C Region L Office of Director ip 15707 302 24x Fiche 50-31;82/09/30.8210150099
- --8210150320 Corrected LER 82-075/017-0 on 820814, 1 gpm syc water leak 210300220 Corrected LER B2-075/01T-0 on B20814.1 gpm svc water lea discovered on containment fan coil unit 22 Cause not determined. Unit required by blanking flanges in svc water piping to coil New design coils will be installed FRAMM.R Public Service Electric & Qas Co of New Jersey B2/08/18 Region 1. Office of Director Ip 15707-303 24X Fiche 50-311, 82/09/30.8210150099
- 8210150311 Forwards corrected LER 82-074/01T-0 HIDURA:H J Public Service Electric & Qas Co of New Jersey 82/09/30 MAYNES:R C Region 1, Office of Director 1p 15701.343 24X Fiche 50-311,82/09/30.8210150311
- --8210150337 Corrected LER 82-074/017-0 on 820813, control operator elolouday corrected LER H2-074/011-0 on B20BIG.control operation discovered increased leakage to containment sump Caused by coil failures due to silt particles in svc water Leek repaired by blanking flanges
 FRANKIR Public Service Electric & Oas Co of New Jersey
 82/08/18 Region i, Office of Director ip 15701:344
 Pichs 50-311,82/09/30,8210150311
- 8210070243 Telecopy measage of LER 82-331/01P on 821002, during routine power operation, we water leak discovered inside containment bldg on containment fan coil unit 23 Cause undetermined Rept will be submitted per LE Bullatin 80-24 MIDURA, H J Public Service Electric & Oas Co of New Jersey 82/10/04 HAYNES, R C Region 1, Office of Director 1p 15649 243 24% Fiche: 50-311,82/10/04,8210070243
- 8210080241 LER 82-113/01P on B21005, during routine operation, syc water leak discovered inside containment on fan coil 22 Cause unknown Investigation in progress Rept will be submitted per IE Bulletin 80-24 MIDURANH.J Public Bervice Electric & Gas Co of New Jersey 82/10/06 HAYNES, R C Region 1, Office of Director 1p 15638 077 24X Fiche-50-311,82/10/06,8210080241
- 8210080296 LER 82-112/01P on 821005, suc water discovered leating at rate of 1 gallon per minute inside containment bldg on den coil unit 21 Cause not stated Leak isolated investigation coli Unit 21 Cause not stated Lear inclated investigation continuing Detailed rapt forthtoming MIDURA:H J Public Bervice Electric & Oas Co of New Jersey B2/10/04 HAVNEB.R C. Region 1, Office of Director ip. 15438:295 24X Fiche 50-311,82/10/06.8210080276
- 8210250053 Forwards LER 82-106/03L-0 Detailed event analysis enci #IDURA:H J fublic Service Electric & Gas Co of New Jersey 82/10/04 HAVMESR C Region 1, Office of Director 3pp 13787.086 24X Fiche 30-31:82/10/06/8210250053
- --9210250057 LER 82-104/03L-0 on 820913. is broken links discovered on circulator travelling screen 21A Possibly caused by stress-induced cracking.Links replaced Design change request issued to consider stainless at links FRAMH.R. Public Service Electric & Oas Co of New Jersey, 82/10/06 Region 1, Office of Director. ip 15787.089 Fiche 50-311,82/10/06.8210250050.
- 8210250382 Forwards LER 82-108/03L-0 Detailed event analysis encl. MIDURA: H. J. Public Service Electric & Gas Co. of New Jersey 82/10/06. HAYNES: R. C. Region 1, Office of Director. App 15790.072. 24X Fiche: 50-311:82/10/06:8210250382
- --8210250389 LER 82-108/03L-0 on 820915 & 17.RPI 104 discovered reading preater than 12 steps lower than bank demand indication. Caused by combination of RPI module calibr drift & thange in actual rod position signal output.
 FRANH.R. Public Service Electric & Qas Co. of New Jersey 82/10/06 Region I. Office at Director, ip. 15790:076. R4X Fiche:50-311,82/10/06.8210250382

- 82:0190644 LER 82-119/019 on 82:1008.1 gpm svc water leat discovered to containment fan coil unit 21 Leak isolated Investigation in progress Betailed rept will be submitted per IE Bulistin progress Detailed rept will be boomstreed by the descript 80-24
 HIDDRA.H J Public Service Electric & Gas Co of New Jersip 82/10/12 HAYNES,R C Region 1, Office of Director Jp 15737 213 24X Fiche 50-311,82/10/12,8210190644
- 82(019065) LER 82-120/01P on 82(011,0 5 gpm two water leak discovered on containment fan coil unit 21 Leak isolated investigation in progress Detailed rept will be submitted per IE Bulletin MIDURA, H J
 - 80-24 MIBURA, H. J. Public Service Electric & Cas Co. of New Jersey 82/10/12 HAYNES, R. C. Region 1, Office of Director ip 15737 212 24X Fiche 50-311,82/10/12,8210170651
- 8210280123 Forwards LER 113/017-0 Detailed event analysis encl MIDURAL J Public Service Electric & Oas Co of New Jersey 82/10/15 HAYNEG,R C Region 1. Office of Director App 15837 158 24X Fiche 50-311,82/10/15,8210280123
- -8210280128 LER 82-113/01T-0 on 821005, small svc water leak distance on cooling coils of containment fan coil unit \$2 Caused by erosion of cooling coils by silt in svc water Coil repaired w/Bellona metal filler FRAHM.R Public Service Electric & Oas Co of New Jersey 82/10/15 Region 1, 0ffice of Director ip 15837 162 246 Fiche 50-311,82/10/15,8210280123
- 8210280152 Forwards LER 82-112/01T-0 Detailed event analysis and MIDURA: H J Public Service Electric & Gas Co of New Jersey 82/10/15 HAYNES, R C Region 1, Office of Director Jpp 15837 221 24% Fiche 30-311,82/10/15,8210280152
- --B2i0280156 LER 82-i12/01T-0 on 821005, svc water leak of 1 0 gpa frcs 5 flange in piping discovered on containment fan coil unit 21 Caused by removal of blank following Belzona repair Flange retorqued retorquea FRAHM,R Public Service Electric & Gas Co of New Jersey 82/10/15 Region 1, Office of Director 1p 15837 224 248 Fiche 50-311,82/10/15,8210280152
- 8210260335 LER 82-122/01P on 821018, svc water leak of approx 0 4 gys 21020033 LEM 82-122/01F on 821018.svc water leak of approx 0 discovered on containment fan coil unit 24 Leak isolated Detailed rapt to be submitted HIDURA.H J Public Service Electric & Gas Co of New Jersey 82/10/19 HAYNES.R C Region 1. Office of Dispector ip 15804 275 24% Fiche 50-311.82/10/19.8210240335
- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION F Security, medical, amergency & fire protection plans
- 8210010057 Provides clarification of 820920 telcon re TMI Action Itsa 21001005/ Provides citarification of 820920 teicon re IMI Act III A i Radiological surveys that cannot be performed by NRC-tuppited equipment will be performed by util staff MATTIMOE. J Bacramento Municipal Utility District 82/0 EISENHUT.D 0 Division of Licensing 2pp 19565 117 24 Fiche, 50-312, 82/09/22,8210010057 District 82/09/22 19565 117 24X
- B210270314 Forwards Amend 40 to License DPR-54 & notice of Issumice & availability Amend adds License Condition 2 C (10) reinglementation of IAEA safeguards SIGLZ, J F Operating Reactors Branch 4 82/09/29 MATT Sacramento Municipal Utility District 4pp 15836 341 Fiche-50-312,82/09/29,8210270314.
- --8210270317 Amend 40 to License DPR-54,adding License Condition 2 t. re implementation of IAEA safeguards STOLT.UF Operating Reactors Brench 4 82/09/27 5pp 19836.345. 24X Fiche 50-312,82/09/29,8210270314
- --8210270320 Notice of issuance & availability of Amend 40 to Litting DPR-54 STOLZ. J. F. Operating Reactors Branch 4 82/09/2 15836 350 24X Fiche: 50-312, 82/09/29, 8210270314. 82/09/29 200
- 8210190228 Forwards "Systematic Assessment of Licenses Performants St. Rancho Seco," for Jul 1981-Sept 1982 Performance analysis for listed functional areas requested by 821112
 STERNBERO, D. M. Division of Resident, Reactor Project & Enginterial Programs. 82/10/14 YOUNG: T. CANTER, H. D'BRIEN, J. Ragion 5. Office of Director 2pp 13742 201 24X Fiche 50-312,82/10/14.
- --8210190231 "Bystematic Assessment of Licensee Performance:SM0 Figure Beco," for Jul 1981-8apt 1962 "Region 5, Office of Director. 82/10/31. 24pp 15742 20 14 Fiche 50-312,82/10/14,8210190228

- S210250955 Forwards Amend 11 to security plan Amend withheld fref 100FR73 21)
 MATTIMOE.J J Secremento Municipal Utility District 82/10/15
 STGLZ-J F Operating Reactors Branch 4 1p 15787 048 24X
 Fiche 50-312, 82/10/15, 8210825005
- & Adjudicatory correspondence
- E210040073 Order directing NRC to provide results of NRC reviews of util revised reliability analysis of proposed mods to auriliary feedwater sys & Brooshaven rept on analysis by E21201
 TOMPKINS.B A Atomic Safety and Licensing Appeal Panel E2/09/30 2pp 15581 035 24% Fiche 50-312.82/09/30.8210040093
- E210190370 Motice of RL Black withdrawal of appearance & RP Lessy appearance in proceeding Certificate of Svc encl BLACK.R L . LESSY.R P Hearing Branch 3 82/10/15 4pp 15741 207 24X Fiche 50-312,82/10/15.8210190370
- P Operating license stage documents & correspondence
- 8210180195 Forwards safety evaluation supporting adequacy of station electrical distribution voltages, based on 820421 submittal Requests verification of test schedule within 45 days of ltrectipt STOLE.JF Operating Reactors Branch 4 82/09/20 MATTIMOE, J J Sacramento Nunicipal Utility District 3pp 15747 327 24X Fiche 50-312, 62/09/20. 6210180195
- --821018020) Safety evaluation supporting adequacy of station electric distribution sys voltages sub; to completion of proposed mods

 4 Operating Reactors Branch 4 82/09/20 7pp 15747 332 24X
 Fishe 50-312,82/09/20,8210180195
- --8206170006 "Technical Evaluation of Adequacy of Station Electric Distribution Sys Voltages for Rancho Eeco Nuclear Generating Station Unit 1." selected issues program WHITE.R L. Lawrence Livermore Laboratory FIN A-0250 UCID-19119 81/11/10 Assistant Director for Operating Reactors 14pp Available at NTIS \$5.00 15747 339 24X Fiche 50-312,82/09/20,8210160195
- E210190594 Application to amend License DPR-54, revising Tech Specs to allow for replacement of existing fuel storage racks w/high density poisoned storage racks MATTIMUE, J J Sacramento Municipal Utility District 82/09/28 Division of Licensing 2pp 15739 106 24X Fiche. 50-312.82/09/28, 8210190594
- --8210190598 Proposed Tech Specs allowing for replacement of existing fuel storage racks w/high density poisoned storage racks * Sacramento Municipal Utility District 82/09/28 ip. 15739 108 24X Fiche 50-312,82/09/28,8210190594
- --8210170503 "Licensing Rept for Spent Fuel Storage Capacity Expansion "

 ★ Sacramento Municipal Utility District 82/06/30 165pp
 15739 110 24X Fiche 50~312,82/09/28,8210170594
- 8210270314 Forwards Amend 40 to License DPR-54 & notice of issuance & availability Amend adds License Condition 2 C (10) resumpte to not 1AEA safeguards
 STOLZ.JF Operating Reactors Branch 4 82/09/29 MATTIMDE, J J Sacramento Municipal Utility District 4pp 15836 341 24X Fiche 50-312, 82/09/29, 6210270314
- --8210270317 Amend 40 to License DPR-54, adding License Condition 2 C (10) re implementation of IAEA safeguards
 STGLZ-JF Operating Reactors Branch 4 82/09/29 Spp.
 15836 348 24X Fiche 50-312, 82/09/29,8210270314
- --3210270320 Notice of issuance & availability of Amend 40 to License DPR-54
 SYCLZ.JF Operating Reactors Branch 4 82/09/29. 2pp 15886 350 24% Fichs 50-312,82/09/29,8210270314.
- B210050220 Forwards "Transient Assessment Rept for Rancho Seco Reactor Trip on B10807," per request HATTIMOE.J J Sacramento Municipal Utility District 82/09/30 HINOR.S Operating Reactors Branch 4 44pp. 15611 029 24X Fiche.50-312.82/09/30.8210050220

- 8210130175 Advises that diesel generator room supply & exhaust fans will be moved to Block 4 to resolve NRC concerns arising from sequencing auxiliary feedwater pump onto bus at 35-5 No diesel generator sequential loading test will be performed MATTIMOE. J. Bacramento Municipal Utility District 82/10/05 STOLZ. J.F. Operating Reactors Branch 4 Jpp. 15673-026 24X Fiche 50-312, 82/10/05.8210130175
- 8210150519 Discusses NRR actions taken under Task Interface Agreement 82-20 for steam generator outiliary feedwater header damage Licensee authorized to resume power operation at Occores 3
 EISENRUT, D.O. Division of Licensing 82/10/06 OLGHINGKI, J. Division of Engineering & Technical Programs ip 15717 261 24X Fiche 30-000, 82/10/06. B210150519
- 8210190331 Forwards add1 info requested 820712 re TMI Item II B 3, "Post-Accident Bampling Bys "
 MATTIMOE.J J Sacramento Municipal Utility District 82/10/13
 STOLZ.J F Operating Resettors Branch 4 19pp 18742 066 24X
 Fiche 50-312,82/10/13,8210190331
- 8210190228 Forwards "Systematic Assessment of Licensee Performance, SMUD Rancho Beco," for Jul 1791-Sept 1782 Parformance analyses for listed functional areas requested by 821112 STERNBERG, D M Division of Resident, Resctor Project & Engineering Programs 82/10/14 YOUNG, T. CANTER, H. D'GRIEN, J. Region 5, Office of Director 2pp 15742 201 24X Fichs 50-312,82/10/14, 8210190228
- --8210170231 "Systematic Assessment of Licensee Performance, SMUD Ranchu Seco," for Jul 1981-Sept 1982 * Region 5, Office of Director 82/10/31 24pp 15742 203 24X Fiche 50-312,82/10/14.8210170228
- 8210190381 Advises that NRC will provide results of reviews of reliability study of modified auxiliary feedwater sys by 821201 even though util intends to install sys in mid-1984, not Jan 1983, as anticipated BLACK, R L Hearing Branch 3 82/10/15 ROSENTHAL, A B, KOHL, C N, BUCK, J H Atomic 8sfety and Licensing Appeal Panel 2pp 13740 345 24% Fiche 50-312,82/10/15,8210190381
- 8210250074 Responds to B&W potential deficiency rept re effects of ring settings on Dresser safety valves Two Model 31759A Drasser valves operable per Tech Specs Short inlet pipe configuration expected to remain stable during B&W testing MATTIMGE.J.J. Sacramento Municipal Utility District 62/10/19. STOLZ.J.F. Operating Reactors Branch 4 2pp 15787 071 24X Fiche 50-312,82/10/19.8210250094
- 8210260331 Documents util position re safety valve operability. Valve performance cannot be quantitatively determined for given ring settings Preliminary B&W evaluation confirms util position pending more rigorous analysis per NWREO-0737 MATTIMOS. J. J. Sacramento Hunicipal Utility District 82/10/21 STOLZ. J F. Operating Reactors Branch 4 ip 15803 229 24% Fiche 50-312, 82/10/21.8210260231
- 8210280228 Commants on NRC safety evaluation of NUREO-0737, Itoms
 II E 1 2 1 & II E 1 2 R re auxiliary feedwater automatic
 initiation & flow indication, transmitted by 820907 ltr
 Safety grade flow instrumentation info due by Jan 1983
 NATTIMOE, J. J. Sacramento Municipal Utility District 82/10/22
 STOLZ, J. F. Operating Reactors Branch 4 2pp 15837:028 24X
 Fiche 50-312,82/10/22,8210280228.
- 8210280163 EN-82-020A notice of order imposing civil monetary penalty issued to util Proposed action was based on two items of noncompliance Both items resulted from failure to properly return safety-related equipment to svc CRAIO.J. AXELRAD.J. Director's Office. Office of Inspection and Enforcement 82/10/26 ip. 15837:208. 24X Fichs 50-312,82/10/26,8210280163
- Q Inspection reports, IE Bulletins & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & tafety problems. Forwards documents listed in App A. FELTON.J H. Division of Rules and Records 82/06/28 UDELL.R A Critical Hass Energy Project. 15pp. 15727 005. 24X Fiche 50-000.82/06/28.8210010008.
- --Biii191042 Comments on dreft IE circular re MSIV failures to close Problem W/control air for MSIV may be part of larger spectrum of problems for many valves MICHELSON,C Director's Office. Bi/10/01. JORDAN,E.1. Division of Resident & Regional Reactor Inspection 1p. 15730:335. 24X Fiche. 30-000. B2/05/29. B210010008.

- 8210080015 Add1 response to FGIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FGIA Exemption 5)
 FELTON, J H Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X
 Fichs 50-000, 82/07/12, 8210080015
- --B2100BD14B Systematic assessment of licensee performance notes re facility evaluation for 790415-800415 + NRC - No Detailed Affiliation Oliven 80/04/15 8pp 1564B 035 24X Fiche 50-000, 82/07/12, 8210080015
- 8210070007 Responds to FDIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udeli FDIA Request B1-313 Forwards documents listed in App B FELTON, J H Division of Rules and Records 62/08/10 LONO, D J Minthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PNRs, per 750320 & 21 requests Details of insps. including defact indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach i GOLLER, K. R. Division of Reactor Licensing (NRR-1975 only) 75703/24 MACCARY, R. R. Division of Technical Review (NRR-1975 only) 5pp 15645 696 24X Fiche 50-000, 82/08/10, 8210070007
- 8210040330 Forwards JE Insp Rept 50-312/82-35 on 820804-0914 No noncompliance noted STERNBERO, D H Division of Resident, Reactor Project & Engineering Programs 82/09/23 MATTIMOE. J. Secremento Municipal Utility District 2pp 15419 034 24X Fiche 50-312,82/09/23,8210040330
- --8210060336 IE Insp Rept 50-312/82-35 on 820804-0914 No noncompliance noted Major areas inspected operational safety verification, surveillance observations, mgt meeting & LER followup CANTER, H L . 0'BREN.J . YDUNO.T Division of Resident, Reactor Project & Engineering Programs 82/09/22 8pp 15619 038 24% Fichs 50-312,82/09/23,8210060330
- 8210190505 Forwards IE Insp Rept 50-312/82-33 on 820907-10 No moncompliance noted BODK.H C Division of Radiological Safety & Safeguards Program 82/09/30 MATTIMOE.J J Sacramento Municipal Utility District 2pp 15737 275 24X Fiche 50-312,82/09/30,8210190605
- --8210170612 IE Insp Rept 50-312/82-33 on 820707-10 No roncompliance noted Major areas inspected organization & staffing, transportation activities.plant tour & health physics appraisal followup of computer based multichannel analyser NORTH.H 8. WEMBLAWSKI.F A. BOOK.H E. Division of Radiological Safety & Saf
- 8210070278 Ack receipt of 820824 ltr Informing NRC of steps taken to correct violations noted in IE Insp.Rept 50-312/62-20
 8TERNSERO, D. Division of Resident, Reactor Project & Engineering Programs 82/10/04 MATTIME, J. Sacramento Municipal Utility District 1p 15634 171 24X Fiche 50-312.82/10/04,8210070278
- -- 8210070287 Responds to NRC 820729 ltr re violations noted in IE Insp. Rept 50-312/82-20 Corrective actions: 011son Shaker not maintained by Ceneration Engineering therefore E11 G-6 not applicable NCR-9-2671 dispositioned on 820527 HATTIMOE. J Barramento Municipal Utility District 82/08/24 ENGELKEN. R H. Region 5. Office of Director 2pp 15634 172 24X Fiche 50-312, 82/10/04, 8210070278
- 8210070290 Ack receipt of 820920 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-312/82-32 STERNBERO,D M Division of Resident, Reactor Project & Engineering Programs. 82/10/04 MATTIMED M Sacramento Municipal Utility District 1p 15534 180. 24% Fiche 50-312.82/10/04.8210070290
- ---8210070294 Responds to NRC 820901 itr re-violations noted in IE Insp. Rept 50-312/82-32 Corrective actions.ell QA Class I Tech Epecs on overail contract specs will include statement re-iOCFR21 regulations
 HATTIMOE, J. J. Sacramento Hunicipal Utility District 82/09/20.
 BTERNBERO, D. N. Division of Resident, Reactor Project & Engineering Programs 2pp 15634 [81 24x Fiche 50-312,82/10/04,8210070290]
- 8210070319 Ack receipt of 820909 ltr informing NRC of steps taken to correct violetions noted in IE Insp Rept 50-312/82-28 STERNBERG, D.M. Division of Resident, Reactor Project & Engineering Programs 82/10/04, MATT/M3E, J., Bacramento Municipal Utility District 1p. 13634'110. 24% Fiche 30-312,82/10/04,8210070319.

- --8210070331 Responds to NRC 820816 Itr re violations noted in it in Rept 50-312/82-28 Corrective actions QA manual revised to define commercial grade spare parts & receiving into performed on all Class I & commercial grade spare parts MATTIMOE. J Sacramento Municipal Utility District 82/09/u9 SIERNDERO. D M Division of Resident Reactor Project & Engineer Programs 2pp 15634 III 24X Fiche 50-312.82/10/04,821007031
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Syc list enci COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 46pp 15741 2-24
- 820B19023B IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Walli-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " 5vc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50~000, 82/10/14, 8208190238
- 8210190228 Forwards "Systematic Assessment of Licensee Perforance.S Rancho Seco." for Jul 1981-Sept 1982 Performance analyses for listed functional areas requested by B21112 STERNBERG.D M Division of Resident. Reactor Project & Engineering Programs 82/10/14 YOUNG.T., CANTER.H., O'BRIEN.J. Region 5 Office of Director 2pp 15742 201 24X Fiche 50-312.82/10/14. 8210190228
- --8210190231 "Systematic Assessment of Licensee Performance, SMJD Pr-Seco." for Jul 1981-Sept 1982 * Ragion 5, Office of Director 82/10/31 24pp 15742 203 Fiche 50-312, 82/10/14-8210190228
- R Periodic operating reports & related correspondence
- 6210190276 Forwards monthly operating rept for Sept 1902 RODRIGUEZ.R J Bacramento Municipal Utility District 82/10/13 Director's Office Office of Inspection and Enforcement is 15742 178 24% Fichs 50-312,82/10/13.8210190278
- --0210190289 Monthly operating rept for Sept 1982 CDLOMBB.R Bacramento Municipal Utility District 02/10/08 t 15742 179 24X Fiche 50-312.82/10/13.8210190278
- 5 Reportable occurrences, LERs & related correspondence
- 0210120114 Advises of immediate need for imposing specific requirements re operational restrictions for Class IE 120-volt ac vital instrument buses in operating plants HICHELSON, C Director's Office 80/07/15 DENTON, H R Offices Nuclear Reactor Regulation, Director 1p 15689 165 24x Fiche 30-000, 80/07/15, 8210120114
- BO12290118 Discusses conclusions of engineering avaluation of itse generator overfill transients at C-E & Westinghouse plants LANYINO, W D. Director's Office 80/10/29, MICHELSON, C Directs Office. 3pp 15672 262 24X Fiche 50-000, 80/10/29, 8012293119
- 8210070412 Discusses problems caused by entry of desiccant into instrument & control air lines Util should examine age & determine source & extent of contamination MIGHELSON, C Director's Office 81/09/15 DENTON, H R Offices Nuclear Reactor Regulation, Director STELLU, V Director's Office of Inspection and Enforcement 5pp 15637 301 24X Fiche. 50-312, 81/09/15, 8210070412.
- 8210010008 Responds to FOIA request for 19 categories of docusints: nuclear reactor events & safety problems Forwards documents listed in App A FELION, J M Division of Rules and Records 82/06/28 UDELL, R & Critical Mass Energy Project 15pp 15727 005 24% Fiche 50-000, 82/06/28, 8210010008
- --8109280036 immediate action memo re desiccant contemination of air lines.Recommends issuance of bulletin requiring all licenses experienced w/air sys contamination to furnish info MICHELSON,C Director's Office 81/09/15 DENYON, R 0/lice Nuclear Reactor Regulation, Director 2pp 15730 241 241 Fiche 80-312.82/06/28.8210010008
- --B201300388 Discusses loss of HPI lube oil cooling at facility be failure of monthly operability test of HPI to detect clogging of qualified lube oil coolers Test deficienty AFT be more critical than event Issue to be addressed by IE PELLET. J. Director's Office. B2/01/13, MICHELBON. C Director Office 3pp. 15732.254, 24X Fiche 50-000.82/06/28.821001000

- 62/10250386 Forwards LER 82-026/04T-0 Detailed event analysis submitted MATTIMDE, J Sacramento Municipal Utility District 82/10/15 ENGELYEU, R H Region 5, Office of Director 1p 15790 090 24X Fiche 50-312, 82/10/15, 8210250386
- --B210250390 LER 82-026/04T-0 on 821006, review of plant effluent records disclosed pH reading of 6 2 for less than 15 minutes on 820918 Caused by leaks at two elbows in acid line running room storage tank to turbine bldg Leaks repaired COLOMBD.R (F. Bacramento Municipal Utility District 82/10/14 Region 5, Office of Director 1p 15790 091 24X Fiche 50-312.82/10/15.8210250386
- 8210250139 PND-V-82-042 on 821016.RCS leakage of 1 15 gpm into reactor coolant drain sys through RCS loop drain valves discovered teatage stands at 0 47 gpm Media interest expected VQU.0.T. CANTER.H Region 5. Office of Director 82/10/18 ip 15787 117 24% Fiche 50-312.822/10/18.8210250138
- DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8210010175 Forwards IE Safeguards Insp Repts 50-313/82-25 & 50-348/82-22 on 820818-20 No noncompliance noted SEIDLE N C Division of Resident, Reactor Project & Engineering Programs 82/09/16 CAVANAUGH, M Arkansas Power & Light Co 2pp 15547 282 24X Ficho 50-313,82/09/16,8210010175
- --- 6210010178 IE Safeguards Insp Repts 50-313/62-25 & 50-368/82-22 on 820818-20 No noncompliance noted Major areas inspected security organization mgt.physical barriers & access control of packages Details withheld (ref 10CFR2 790) EVANUS.C A. KELLY.J AF Division of Vendor & Technical Programs 62/09/14 ip 15567 284 24% Fiche 50-313/62/09/16/6210010175
- 8210190497 Forwards IE Insp Repts 50-313/82-11 & 50-368/82-09 on 820318-20 No noncompliance noted EFIDLE:N C Division of Resident, Reactor Project & Engineering Programs 82/09/28 CAVANAUGH. W Arkansas Pawer & Light Co 2pp
- --8210190516 IE Insp Repts 50-313/82-11 & 50-368/82-09 on 820518-20 Nu noncompliance noted Major areas inspected licensee performance & capabilities during full-scale exercise of amergency plans & procedures
 ROMRER. D M. HUNNICUIT. D M. Division of Resident, Reactor Project & Engineering Programs 82/09/24 17pp 15735-346 24X Fiche 50-313.82/09/28.8210190497
- B210070395 Updates B11021 response to Generic Ltr B1-04, "Emergency Procedure & Training for Station Blackout Events " Seal return isolation is possible during blackout & is provided for in procedures

 MARSHALL JR Arkansas Power & Light Co 82/10/04 EISENHUT, D G
 Division of Licensing 2pp 15663 341 24X Fiche 50-313,82/10/04,8210070395
- 8210150073 Forwards add1 info re safe shutdown capability, in response to MRC 820703 request MARSHALL J R Arkansas Power & Light Co 82/10/05 CLARK, R. A Operating Reactors Branch 3 STOLT, J F Operating Reactors Branch 4 72pp 15496 349 24X Fiche 50-313,82/10/05,8210150073
- 8210280108 Releases public version of amend to emergency plan FELTON, J M Division of Rules and Records 82/10/12 Document Managament Branch 1p 15862 236 24X Fiche 50-313,82/10/12, 8210280108
- --8210280312 Forwards public version of Amend 6 to emergency plan MARSHALL, J. R. Arkansas Power & Light Co. 82/10/04 COLLINS, J. Region 4. Office of Director DENTON, H. R. Diffice of Nuclear Reactor Regulation, Director 1p. 15862-237 24X Fiche 50-313.82/10/12.8210280108
- ~-0210280114 Public version of Amend 6 to emergency plen * Arkenses Power & Light Co 02/09/20 3pp 15862.238 24X Fishe 50-013.82/10/12.8210280108
- 8210220377 Categorizes open items identified in IE Emergency
 Preparedness Repts 50-313/82-11 & 50-368/82-09 by need for
 Larnednate consideration & type of response acceptable
 Notification of expected response date due within 10 days
 SEIDLE: N C Division of Resident: Reactor Project & Engineering
 Programs 82/10/19 CAVANAUOH; N. Arkansas Power & Light Co 4p;
 15779 175 24X Fiche, 50-313,82/10/19,8210220377

- 8210260178 Ack receipt of 820927 ltr requesting add1 time to respond to violations noted in Emergency Preparedness Appraisal Repts 50-316/82-82 & 50-368/82-21 Response to App C due by 830501. SEIDLE, H C Division of Resident, Reactor Project & Engineering Programs 82/10/19 CAVANAUGH. H Arkansas Pewer & Light Co ip 15799 037. 24X Fiche 50-313,82/10/19,8210260178
- --B2102&0180 Responds to NRC B20&25 itr re App C to IE Emergency Preparedness Appraisal Repts 50-313/82-22 & 50-368/82-21 Deficiencies resolved in emergency plan amends & implementing procedure revisions CAVANAUGH.W Artansas Power & Light Co B2/09/29 CQLLING.J T Region 4. Office of Director 4pp 15797.038 24X Fiche 50-313.82/10/19.82102&0178
- P Operating license stage documents & correspondence
- 821001000B Responds to FOIA request for 17 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fichs 50-000.82706/28.8210010008
- --8106100203 Discusses evaluation of HPBI pump operability w/o svc water Operability of HPBI pumps w/o svc water not adequately justified based on info submitted by licensee IMBRO.E Director's Office 81/05/22 Director's Office 4pp 15729 185 24X Fiche 50-000.82/06/28.8210010008
- 8210190008 Responds to 820831 submittal re Tech Spec revision for snubber surveillance License amend application should be submitted to incorporate applicable portion of 801120 model Tech Specs within 60 days CLARK.R A Operating Reactors Brench 3 82/09/21 CAVANAUGH.W Arkansas Power & Light Co 2pp 15740.301 24X Fiche 50-3id.82/09/21,8210190008
- 8210290140 Forwards Amend 69 to License DPR-51, safety evaluation & notice of issuance & availability Amend revises Tech Bracs to require chlorine detection & protection capability for control room VISSING 0 B Operating Reactors Branch 4 82/09/21 CAVANAUCH, W Arkanses Power & Light Co 2pp 15876 209 24X Fiche 50-313, 82/09/21. 8210290140
- --B210290143 Amend 69 to License DPR-51, amending Tech Basecs to require chlorine detection & protection capability for control room STCLZ, J F Operating Reactors Branch 4 B2/09/21 Bpp. 15876:211 24% Fiche 50-313, 82/09/21,8210290140
- --8210290146 Bafety evaluation supporting Amend 69 to License DFR-51 * Office of Nuclear Reactor Regulation, Director 82/09/21 2pp 19876 219 24X Fiche 50-313,82/09/21,8210290140
- --B21029014B Notice of issuance & availability of Amend 69 to License DPR-51.
 STOLZ.J F Operating Reactors Branch 4 82/09/21 2pp 15876-221 24X Fiche 50-313,82/09/21,8210290140.
- 82:0040:09 Application for amend to License DPR-51, changing 820517 Tech Spec change request to allow higher steam line break instrumentation & control sys setpoint.
 CAVANAUOH, W Arkanses Power & Light Co 82/09/29 STOLZ, J F Operating Reactors Branch 4 2pp 15581 017, 24X Fiche. 50-313, 82/09/29, 82:0040109
- ---8210040111 Proposed revised Tech Spec S.4 2 re steam line break instrumentation & control sys • Arkansas Power & Light Co 82/09/29 5pp 15581:019. 84K Fiche: 50-313.82/09/29.8210040109.
- 8210150002 Forwards response to 820120 & 0301 requests for add1 info re RCB high point vents Credible missiles generated by fallure of RCB vent valves not postulated based on valve design. Leak detection provided for by monitoring pressure.

 MARBHALL.JR Arkansas Power & Light Co 82/10/04 BTOLZ, JF. Operating Reactors Branch 4 CLARK.R.A. Operating Reactors Branch 3 4pp. 15696 309 24X Fichs 50-313,82/10/04,8210150002.
- 82:01:50494 Submits info re status of waste gas mys & schedule for installation of redundant hydrogen/oxygen analyzers.
 Conceptual diagram of proposed upgraded waste gam mys redundant analyzer panel encl.
 MARSHALL.J R. Arkansas Fower & Light Co. 82/10/12 STOLZ.J F.
 Operating Reactors Branch 4 CLARK.R.A Operating Reactors Branch G. 4pp. 15714.184. 24X Fishe 50-313.82/10/12.8210150494.

- 8210220114 Formalize proposals made at 820729 meeting U/BiW owners group re NUREO-0737. Item II K 3 30. "Revised Small Break LOCA Methods to Show Compilance w/1007R30.App K "MARSHALL.J R Arkanas Power & Light Co 82/10/13 DENTON.H R Office of Nuclear Reactor Regulation. Director 15pp. 15778 149. 24X Fiche 50-313.82/10/13.8210220114
- 8210250206 Discusses operability of Dresser Hodel 31739A pressuritar safety in util & vendor documentation Ring settings should not cause valve chatter & mechnical damage Analytical models being developed for plant-specific data MARSHALL.JR Arkansas Power & Light Co 82/10/19 STOLZ.JF Operating Reactore Branch 4 2pp 13789 306 24X Fiche 50-313, 82/10/19, 8210250206
- 8210260192 Forwards add1 response to 820618 open items to emergency feedwater sye, per 820722 itt Functional test required every 18 months causes eddition of heavily oxygenated weter into once-through steam generator.

 MARSHALL, J. R. Arkansas Power & Light Co. 82/10/20. STGLZ, J.F. Dperating Reactore Branch 4. App. 15799-021. 24X. Fiche: 50-313, 82/10/20, 8210260192.

O Inspection reports, IE Bulletins & correspondence

- 62100B0015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety probleme Forwards documents ifsted in App A Documente in App B completely withheid (ref FGIA Exemption 5) FELTON.J H Division of Rules end Records B2/07/12 UDELL.R A Critical Mass Energy Project 9pp 15865 027 24X Fiche 50-000.82/07/12.8210080015
- --8210080112 Systematic desessment of liceness performance notes refacility evaluation for 790101-800819

 * NRC No Detailed Affiliation Given 80/08/19 8pp
 13667 291. 24X Fiche 50-000, 62/07/12.8210080015
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request Bi-313 Forwards documents listed in App 8 FELTON, J M Division of Rules and Records. 82/08/10 LONO, D J Hinthrop, Stimson, Putnam & Roberts 9pp i3645 043 24X Fiche 50-000,82/08/10,9210070007.
- --B210070172 Forwards info re eteam generator integrity & insps at all operating PWRs.per 750320 & 21 requests Details of insps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Deach 1 OCLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R R Division of Technical Review (NRR-1975 only). 5pp 13645:196 24% Fiche 50-000,82/08/10,8210070007.
- 8210010175 Forwards IE Safeguards Insp Repts 50-313/82-25 & 50-368/82-22 on 820818-20 No noncompliance noted SEIDLE, W C Division of Resident: Reactor Project & Engineering Programs 82/09/16 CAVANAUGH, W Arkensas Power & Light Co 2pp 13567 282 24% Fiche: 50-313,82/09/16,8210010175
- --8210010178 IE Safeguards Insp Repts 50-313/82-25 & 50-368/82-22 on 820818-20 No noncompilance noted Major areas inspected security organization mgt.physical berriere & access control of packages Details withheld (ref 10CFR2 790). EVANB.C A . KELLY, J A. F. Division of Vendor & Technical Progrems 82/09/14. ip 15367.284. 24X Fiche:50-313.82/09/16.8210010175.
- 8210190497 Forwards IE Insp Rapts 30-313/82-11 & 50-368/82-09 on 820518-20, No noncompliance noted SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs, 82/09/28 CAVANAUOH, W. Artaness Power & Light Co. 2pp 19735:344 24X Fichs 50-313,82/09/28,8210190497.
- --8210190516 IE Insp Repte 50-313/82-11 & 50-368/82-09 on 820518-20 No noncompliance noted Negor arese inepected: Ricensee performance & capabilities during full-scale exercise of emergency plans & procedures.

 ROMRER, D M , HUNNIGUTT, D M. Division of Resident, Reactor Project & Engineering Programs. 82/09/24. 17pp 15735-346 24% Fishe 50-313, 82/09/28, 8210190497.
- 8210120246 Act receipt of 820211 itr informing NRC of steps taten to correct violations noted in IE Imap Repts 50-313/81-30 & 50-368/81-29.

 BEIDLE: W C Division of Resident, Reactor Project & Engineering Programs, 92/10/01 CAVANAUGH: W Arkanses Power & Light Co 1p. 15652-110 244 Fiche. 50-313, 82/10/01, 8210120246.

- --82i0120252 Responde to NRC 820i04 ltr re violations noted in IE [*s; Repts 50-313/81-30 & 50-388/81-27 Corrective actions formal training sessions will be conducted w/appropriate station personnel to stress importance of individual responsibility MARSHALL, JR Ariansas Power & Light Co 82/02/11 MADSEH Q L Division of Resident, Reactor Project & Engineering Programs 7; 15652 iii 24X Fiche 50-313,82/10/01.8210120246
- 8210220270 Forwards iE Insp Repts 50-313/82-12 & 50-348/82-25 on 820524-27 No noncompliance noted SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/10/05 CAVANAUGH.W Arkansas Power & Light Co 2,, 15775 001 24X Fiche 50-313.82/10/05.8210220270
- --B21022028! IE Insp Repts 50-313/B2-12 & 50-364/B2-25 on E20324-27 k, moncompliance noted Major areas inspected radiochemistry program. including organization, staffing, training program. sample collection & sample treatment & analysis NICHOLAS. J B. HURRAV. B. Region 4. Office of Director B2/09/14 25pp 19775 003 24X Fiche 50-313.82/10/05.8210220270
- B208190233 IE Info Notice 80-35, Suppl i, "Leaking & Disloder f [2] Implent Seeds " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 2:) 24X Fiche 50-000,82/10/06,8208190233
- 6210120241 Ack receipt of 820715 itr informing NRC of etems taken to correct violations noted in IE Insp Repts 50-313/80-20 & 50-368/80-20 SEIDLE, #C Division of Resident, Reactor Project & Engineering Programs 82/10/06 CAVANAUGH, #W Arkansas Power & Light Co Ip 15652 113 24% Fishs 50-313.82/10/06/8210120241
- --8210120247 Provides status update on gaseous radidactive wasts signods in response to violations noted in IE Insp Repts
 50-313/80-20 & 50-368/80-20 High airborne activity incidents
 in auxiliary bidgs eignificantly reduced
 MARSHALLJ R Arksness Power & Light Co 82/07/15 GEDLE.WC
 Division of Resident, Reactor Project & Engineering Programs up
 15652 114 24% Fiche 50-313/82/10/06/8210120241
- 8208190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Mail.Large-Diameter. Stainless Steel. Recirculation Sys Piping et BUR Plante "Svc list encl DEYOUND.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Go of New York ilSpp. 15810 125. 24X Fiche 50-000, 82/10/14, 8208190230
- 8210220377 Catagorizas open items identified in IE Emargency Proparadness Rapts 50-313/82-11 & 50-358/82-07 by newf for immediate consideration & type of response acceptable Notification of expected response date due within 10 days SEIDLE:N C. Division of Resident. Reactor Project & Engineering Programs 82/10/17 CAVANAUOH,W Arkansae Power & Light Ce 5, 15779 175 24X Fiche 50-313,82/10/17.8210220377
- 8210260178 Act receipt of 820929 ltr requesting addl time to respect violations noted in Emergency Preparedness Appraisal Repts 50-313/82-22 & 50-368/82-21 Response to App C due by 830300 SEIDLE, H C. Division of Resident, Reactor Project & Engineering Programs 82/10/19 CAVANAUGH.H Arkamas Power & Light Ce : 13799:037 24X Fiche 50-313,82/10/19,8210260179
- --8210260180 Responds to NRC 820425 ltr re App C to 1E Emrishity
 Preparedness Appreieal Repte 50-313/62-22 & 50-348/62-21
 Deficiencies resolved in emergency plen amends &
 implementing procedure revisione
 CAVANAUGH, N. Arkaness Power & Light Ca 82/07/29 COLUMS J.
 Region 4: Office of Director 4pp 15799 038 24X
 Fiche: 50-313, 82/10/19, 8210260178
- 8 Reportable occurrences, LERs & related correspondence
- 8210120380 Advises that operator action necessary to protect 314 314 from excessive featuater transfents. SEW pients do not eapled high steam generator level turbine or reactor trips to protect against transients CREBWELL, J. S. Director'e Office 80/09/12 MICHELBON. C Director's Office 34pp 15689:286 24X Fiche 50-302.00/09/12 8210120380.
- 8012290118 Discussee conclusions of engineering evaluation of the generator overfill transferts at C-E & Hestinghouse plants LANNING, M D. Director's Office. 80/10/29 MICHESON & Stratts Office. 3pp. 15692.262 24% Fiche 50-000, 80/10/29, 80122018
- 8210070104 Speech entitled "Pressure Boundary Degradation Dui to Form Seal Failure at AR Nuclear One," presented at ninth meeting of Committee on Sefety of Nuclear Inetailations on 811103-04 in Peris. France.

 LANNINO, W. D. : BROWN.E J. Director's Office 81/11/03 91 15469:174. 24X Fichs 50-313.81/11/03.8210070104

- P21001000B Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- --B111040084 "Pressure Boundary Degradation Due to Pump Seal Failure of Arkansas Nuclear One " LARNING.W D , BRDWN,E J Director's Dffice B1/11/03 6pp 15731 079 24X Fiche 50-000, 82/06/28.0210010000
- --R203100549 Recommends explicit verification that seismic qualification for all protective devices used in control & protection circultry for dissel generator unite performed widevices in energized/de-energized & tripped/nontripped states NICHELBON.C Director's Dffice B2/02/24 VOLLMER.R H Division of Engineering MATTSON.R J Division of Systems Integration (post 8:1005) 2pp 15732 320 24% Fichs 50-000,82/04/28, R25010008
- 8210120145 "Abnormal Transient Operating Guideines as Applied to Apr 1981 Overfill Event at AR Nuclear One Unit 1" PELLETIJ L Reactor Operations Analysis Branch 82/08/3i i9pp 24X Fache 50-313.82/08/31.8230120145
- 6210130513 Forwards LER 82-025/03L-0
 MARSHALL-J R Arkansas Power & Light Co 82/09/26 SEIDLE, W C
 Division of Resident, Reactor Project & Engineering Programs 1;
 13682 23B 24X Fiche 50-313,82/09/26,8210130513
- --8210130522 LER 82-025/03L-O on 820828, electrical jumpers discovered across trip contacts or shutdown bupass high pressure trip bistables for A & D reactor protection sys channels Caused by personnel error Jumpers removed ROGERS,P Arkansas Power & Light Co 82/09/26 Region 4, Office of Director 2pp 15682 237 24X Fiche 50-313, 82/09/26, 8210130513
- 8210130212 forwards LER 82-027/03L-0 MARSHALL, JR Arkansas Power & Light Co 82/09/30 GEIDLE, W C Division of Resident, Reactor Project & Engineering Programs ip 15475 237 24x Fiche 50-313,82/09/30,8210130212
- --8210130214 LER 82-027/03L-0 on B207i4,RCS leak rate calculated at 3 4 gpm. in excess of Tech Spec Caused by low breatway torque valves, deteriorated gasket & eroded manuay cover Ali defective parts repaired or replaced ROGERS,P Artansas Power & Light Co 82/09/30 Region 4, Office of Birector 2pp 15675 238 24X Fiche 50-3i3,82/09/30,8210130212
- 8210130382 Forwards LER 82-026/03L-0 MARSMALL, JR Arkansas Power & Light Co 82/07/30 BEIDLE, W C Division of Resident, Reactor Project & Engineering Programs ip 15680 336 24X Fiche 50-313,82/07/30,8210130382
- --8210130388 LER 82-026/03L-0 on 820901, installed hose reei (HR-49) found not visually inspected per Tech Specs Caused by lack of communication, leading to omission of HR-49 from insperocedures HR-49 inspected & procedure revised ROCERS, P. Arkansas Power & Light Co. 82/09/30. Region 4, 04fice of Director 2pp. 15680-337 24X Fiche 50-313,82/09/30, 8210130382
- E210170517 Ferwards LER 82-028/03L-0 MARSHALL, JR Arkansas Power & Light Co 82/10/07 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 15751 244 24% Fiche 50-313,82/10/07,8210170517
- --B210190526 LER 82-028/03L-0 on 820909, diesel driven fire pump (P-48) failed to start when using B battery bank during surveillance Cause by normal end of svc life Batteries charged & later replaced ROGERS.P Arkansas Power & Light Co 82/10/07 Region 4. Dffice of Director 2pp 15751 245 24% Fiche 50-313,82/10/07, B210190517
- DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

 F. Security, medical, emergency & fire protection plans
- E2100403B7 Forwards IE Insp Repts 50-315/82-08 & 50-316/82-08 on B20412-16.0314 & Odio Deficiencies referred to Ofc of Investigation for review & investigation NORELIUS.C E Division of Engineering & Technical Programs. B2/07/22. DDLAN.J E Indiana & Michigan Electric Co 2pp 15615 350 24X Fiche 50-315,82/07/22.82100603B7

- --8210060393 IE Insp Repts 50-315/82-08 & 50-316/82-08 on 820412-16.0514 & 0610 Deficiencies noted inadequate fire protection of safe shutdown capablisity, inaccurate statements, inadequate procedure for alternate safe shutdown & inadequate lighting GROBE, J A , STONE, J C , HAUGHNEY, C J Division of Engineering & Technical Programs 82/09/17 27pp 15615 352 24% Fiche. 50-315,82/09/22.8210060387
- 8210080127 Releases public version of revised emergency plan procedures FELTON.J M Division of Ruies and Records 82/09/22 Document Management Branch ip 15663 293 24X Fiche 50-315,82/09/22, 8210080127
- --8210080132 Forwards public version of Revision 1 to Emergency Plan Procedures PMP 2081 EPP 012, "Offsite Radialogical Monitoring" & Revision 1 to PMP 2081 EPP 026, "Use of Stable Iodine for Thyroid Biocking During Radiation Emergency " # Indiana & Michigan Electric Co 82/09/13 NRC No Detailed Affiliation Oliven 1p 15663 294 24X Fiche 50-315,82/09/22,8210080129.
- --8210080136 Public version of Revision 1 to Emergency Plan Procedures PMP 2081 EPP 012, "Offsite Radiological Monitoring" & Revision i to PMP 2081 EPP 026, "Use of Stable iodine for Thyroid Biocking During Radiation Emergency " Index encl " indiana & Hichigan Electric Co B2/09/13 20pp 15663-295 24% Fiche 50-315,82/09/22,8210080129
- 8210010362 Forwards revision to modified amended security pian re key & fock control program Revision withheld (ref 10CFR73 21)
 HUNTER, R S Indiana & Hickigan Electric Co 82/09/27 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 2pp 15574, 158
 24% Fiche 50-935, 82/09/27. 82100103362
- 8210150594 Releases public version of revision to plant manager procedure/emergency plan procedure FELTON. J M Division of Rules and Records 82/09/30 Document Management Branch ip 15716:350 24K Fiche 50-315.82/09/30, 8210150594
- --8210150604 Forwards public version of Revision 3 to Plant Manager Procedure/Emergency Plan Procedure App A. "Telephone Numbers for Key Plant Personnei" # Indiana & Hichigan Electric Co 82/07/23 NRC - No Detailed Affiliation Given (p. 15716-351, 24X Fiche 50-315,82/07/30, 8210150504
- --8210150614 Public version of Revision 5 to Plant Manager Procedure/ Emergency Plan Procedure App A, "Telephone Numbers of Key Plant Personnel" * Indiana & Michigan Electric Co 82/09/23 2ipp i5716.352 24X Fiche 50-315.82/09/30:8210150594
- 8210190036 Releases public version of procedure temporary sheet to emergency plan procedure FELTON, J. M. Division of Ruies and Records 82/i0/01. Document Management Branch. ip 13761 034 24X Fiche 50-315,82/i0/01,820190036
- --8210190040 Public version of procedure temporary sheet to
 Emergency Plan Procedure PMP 2081 EPP 020. "Activation &
 Operation of Technical Support Ctr " Revised Index enci
 VINCE, S., 8 IMMS, R., CAMPBELL, D. Indiana & Michigam Electric Co
 82/09/17 2pp 15761 035. 24X Fiche 50-315,82/10/01,8210190036
- 8210190652 Forwards FEMA 820909 ltm.final evaluations of offsite emergency preparedness exercises conducted on 801009 & 820330 for 8tate of MI & Berrien County & 8tate of MI response. Recommendations for offsite preparedness requested HIND. J. A. Division of Emergency Preparedness & Operational Support 82/10/12. HERINO.R F American Electric Power Service Corp HERINO.R.F Indiana & Michigan Electric Co. 2pp 15707.147 24X Fiche 30-315, 82/10/12.8210190652
- 8210280378 Releases public version of revision to emergency plan procedure.
 FELTON.J. M. Division of Rules and Records 82/10/12 Document Management Branch 1p 15859 238 24% Fiche. 50-315, 82/10/12, 8210280378.
- --B2102B03B0 Forwards public version of Revision 3 to emergency plan procedure App 8 re hosp assistance plan w Indiana & Michigan Eiectric Co B2/10/01. NRG No Detailed Affiliation Given ip 15859 239. 24X Fithe. 50-315, 82/10/12, 82/102B0378
- --8210280383 Public version of Revision 3 to emergency plan procedure App B re hosp assistance plan. ** Indiana & Michigan Electric Co. 82/10/01. 17pp. 15859:241 24X Fiche: 50-315, 82/10/12, 8210280378.

- 6210280399 Releases public version of revised emergency plan procedures. FELTON.J M Division of Rules and Records. 82/10/12 Document Management Branch 1p 15859 261 24X Fiche 50-315,82/10/12, 8210280399.
- --B210280408 Forwards public version of revised emergency plan procedures, including Procedures PNP 2081 EPP 004 re protective action guides & protective actions & PHP 2081 EPP 009 to health physics procedures a Indiana & Michigan Electric Co B2/09/29, NRC No Detailed Affiliation Given ip 15859, 262 24X Fiche: 50-315, 82/10/12, cpt/2002393
- --B210280413 Public version of revised emergency plan procedures, including Procedure PMP 2081 EPP 004 Te protective action guides & protective actions & PMP 2081 EPP 009 Te health physics procedures Procedures index end a Indiana & Michigan Electric Co 82/09/29 57pp 15859;263 24X Fiche.50-315,82/10/12.8210280379

I Financial information

- \$210070279 Forwards Annual Financial Rapt for 1981 & projected cash flow for 1982 MERING R F Indiana & Michigan Electric Go. 82/10/04 DENTON: M R Office of Nuclear Reactor Regulation: Director 2pp 15634.185 24X Ficha 50-315.82/10/04.8210070279.
- --8210070286 "ID & Ml Electric Co-Annual Financial Rept 1981 "

 * American Electric Power Service Corp * Indiana & Hichigan
 Electric Co 82/10/04 32pp 15634 187 24X
 Fiche: 50-315, 82/10/04.8210070279
- J Insurance & indemnity information
- 82100403i3 Forwards Endorsement 54 to NELIA Policy NF-204 & Endorsement 44 to MAELU Policy MF-79 BUCKLES.J. Marsh & Kchennan, Inc., M & M. Nuclear Consultants, Inc DIV 82/09/27 SALTIMAN.J. Assistant Director for State & License Relations 3pp, 15586-168 24% Fiche 50-315.82/09/27,8210040313
- P Operating license stage documents & correspondence
- 821003033B Forwards Amends 59 & 42 to Licenses DPR-58 & DPR-74, respectively, tafety evaluation & notice of issuance & availability Amends revise Tech Bpecs to reflect installation or replacement of valves to inprove operation CILIMBERO, R & Operating Reactors Branch 1. B2/09/09. DOLANGUING and & Michigan Electric Co 2pp 13697-172 24X Fiche 50-315, 82/09/09, 8210030338
- --B210050541 Amends 57 & 42 to Licenses DPR-58 & DPR-74, respectively, revising Tech Specs to reflect installation or replacement of valves to promote improved operation VARGAS A. Operating Reactors Branch 1 82/09/07 26pp 15637 174 24X Fiche 50-315,82/09/09.8210050538
- --B210050544 Bafety evaluation supporting Amends 59 & 42 to Licenses DPN-58 & DPR-74: respectively * Office of Nuclear Reactor Regulation, Director 82/09/09, 2pp 18637, 200 24% Fishs: 50-315,82/09/09,8210050538
- --8210050546 Notica of issuence & availability of Amends 59 & 42 to Licenses DPR-58 & DPR-74, raspectively. GROTENHUIS, M. Dperating Reactors Branch 1 62/09/09 Rop. 15637-202. 24X Fithe 50-215, 82/09/09, 8210030538.
- 8210040415 Forwards Amends &: & 44 to Licenses DPR-58 & DPR-74, respectively, safaty evaluation & notice of issuance & : to reflect revisad PDC-II procedures

- ~-8210040419 Notice of issuance & availability of Amends 61 & 44 t. Licenses DPR-58 & DPR-74 respectively VAROA. S. A. Operating Reactors Branch i 92/09/15 pp 15597, 132 24X Fiche 50-315, 82/09/15, 8210040415
- 8210040428 Forwards request for add1 info re hydrogen control jesuis for ice condenser plants Response requested by 821015 VAROA,6 A Operating Reactors Brench | 82/09/16 DOLAM,J Indiana & Hichigan Ejectric Co 10pp 15597 252 24X Fiche 50-315,82/09/16,8210040428
- 8210120557 Forwards Amend 62 to License DPR-58 & notice of issuance & availability Amend extends until 821009.permissibly operation in Modes 2 & 3 w/one safety injection pump inaperable VAROA.8 A Operating Reactors Branch 1 82/09/17 DOLAN J indiana & Michigan Electric Co 3pp 15684 218 24X Fiche 50-315.82/09/17.8210120557
- --8210120360 Amend 62 to License DPR-58, extending until 825009 permissible operation in Modes 2 % 3 w/one safety injection pump inoperable VAROA, 6 A Operating Reactors Branch 1 82/09/17 App 15684 221 24X Fiche 50-315, 82/09/17, 8210120557
- --8210120565 Notice of issuance & availability of Amend 62 to Lice of DPR-58
 VAROALS A Operating Reactors Branch 1 82/09/17 2pp
 15684 225 24X Fiche 50-315,82/09/17.8210120557
- 8210040212 Discusses inconsistency in ECCS analysis Yech Spet val.e.?

 70 F used as temp for safety injection flow water determined nonconservative Refueing water storage tank temp raised to 80 F per Tech Spec requirement SMITH.W 0 Indiana & Michigan Electric Co 82/09/24 KEPPLER.J; Region 3. Office of Director ip 15583 123 24% Fiche. 50-315.82/09/24.8210040212
- 8210050138 Forwards documents as Phase I b of response to Section 21 of Encl 3 to DO Eisenhut 801222 ltr re control of heavy loads Westinghouse analysis of lifting arrangement for reactor vessel head & upper internals expected by 830315 HUNTER: R 8 Indiana & Michigan Electric Co 82/09/29 DEHTON of Office of Nuclear Reactor Regulation. Director 31pp 15006 027 24X Ficher 50-315,82/09/29,8210050138
- B210050159 Application for amend to Licenses DPR-SB & DPR-74.press: prech Spec changes for placement of new post-accident containment hydrogen mobitoring sys to satisfy NURGO-0737. Item IT F i.6 & to remove existing squipment from svc HUNIER.R S Indiana & Michigan Electric Co 92/09/29 DENFON AI Office of Nuclear Reactor Regulation. Director 2pp 15503 149 24% Fiche 50-015.82/09/29.8210050159
- --8210050160 Proposed Tech Spec 3/4,6 4 re combustible gas control # Indiana & Michigan Electric Co 82/09/29 3pp 15603 151 24X Fiche 50-315.82/09/29.8210050159
- 8210050349 Forwards add1 info re hydrogen mitigation & control it facilities Util continues to work w/TVA & Duke Power Co toward completion of executive summary rept on fice condenser hydrogan RED program HUNTER: R S Indiana & Michigan Electric Co 82/09/30 ENTON: 0ffice of Nuclear Rescriber Regulation, Director 126pp 15510:1% 24X Fiche 50-315,82/09/30.8210050349
- 8210080194 Comments on regulatory performance improvement preferance Comments can be dealt w/by revising program description to take full credit for mot review efforts Util views on comments will be discussed at meeting scheduled for 82:014 KEPPLER. J.O. Region 3. Office of Director 82:10/01 SUAN. J E American Electric Power Service Corp DOLAN. J E Indian & Firl & Electric Go. 2pp 13640 188 24X Piche 50-315.82/10/01.6210/63
- 8210060253 Discusses 820707 mgt meeting & forwards Systematic Assessment of Licensee Performence Repts 50-315/82-16 & 50-316/82-16 KEPPLER, J. O Region 3. Office of Director 82/10/04 DOLAN, J. E. American Electric Power Co. Inc. DOLAN, J. E. Indiana & Alchylli Power Co. 3pp. 13620, 178. 24X Fichs 50-315,82710/04.8210020713

- --8210060256 Responds to NRC B20625 Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 Tuelve previously trained operators hired & computerized radiation exposure maint sys & security access control sys installed MUNTER.R B Indiana & Michigan Electric Co 82/07/27 KEPPLER.J G Region 3 Office of Director 35pp 15620 208 24X Fische 50-315.82/10/04.8210060253
- 9210150491 Confirms 820922 telcon re masonry walls Addi info required within 45 days to complete review VARGA.8 A Operating Reactors Branch i 82/10/04 DOLAN.J Indiana & Hichigan Electric Co 3pp 15717 275 24X Fiche 50-315
- 8210250340 Forwards Amends &3 & 45 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & scallability Amend revises Tech Specs changing surveillance requirements for boron & safety injection sys CILIMERG.R L Operating Reactors Branch 1 82/10/04 DOLAN, J Indiana & Hichigan Electric Co 2pp 15807 259 24X Fachs 50-315, 82/10/04, 82/10250340
- --B210250393 Amends 63 & 45 to Licenses DPR-58 & DPR-74, respectively, changing Tech Spers re surveillance requirements for boron & safety injection sys & updating core flux VARGA, S A Operating Reactors Branch i B2/10/04 73pp 15807 261 24X Fiche 50-315, 82/10/04, 8210250340
- --B210250394 Safety evaluation supporting Amends 63 & 45 tp Licenses DPR-58 & DPR-74: respectively • Office of Nuclear Reactor Regulation. Director 82/10/04 5pp 15807 334 24X Fiche 50-315.82/10/04.8210250340
- --8210250395 Notice of issuance & availability of Amends 63 & 45 to Licenses DPR-58 & DPR-74, respectively VAROA. 5 A Operating Reactors Branch i 82/10/04 2pp 15907 339 24X Fiche 50-315, 82/10/04, 8210250340
- B210150434 Forwards safety evaluation re main steem line break w/continued feedwater addition & contractor technical evaluation rept W/O technical evaluation rept WARGA: A Derating Reactors Branch 1 82/10/05 DDLAN, J Indiana & Michigan Electric Co 2pp 15716 090 24X Fiche 50-315, 82/10/05, 8210150434
- --9210150437 Safety evaluation re main steam line break w/continued feeduater addition

 Operating Reactors Branch 1 82/10/05 7pp 15716 092 24X Fichs 50-315,82/10/05,8210150434
- 6210220478 Submits followup to 820907, 17 & 24 ltrs re emergency relief requests from Tech Spec 3 5 2 Repairs of north safety injection pump completed within alloted relief time granted by Amand 62 Amand fee encl HUMTER. R S Indiana & Michigan Electric Co 82/10/15 DENTON, H R Offste of Nuclear Reactor Regulation, Director 2pp 15779 001 24X Fiche 50-315, 62/10/15, 8210220478
- 8210250228 Forwards proprietary responses to five of 16 questions per NRC 820730 request for addi info re hydrogen control issues for ice condenser plants.particularly CLASIX computer program Responses withheld (ref 10CFR2 790) IRVATER.R B Indiana & Michigan Electric Co 82/10/15 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp. 15789 339 24X Fiche 50-315.82/10/15.82/0250228
- 8210220373 Advises that util will reload w/Westinghouse 15x15 optimized fuel assemblies during Cycle 8 scheduled for 830831 Meeting w/NRC requested on 82103 to clearly define 1 Icensing review schedule HUNTER: R 8 Indiana & Michigan Electric Co 82/10/18 DENTON; H R Office of Nuclear Reactor Regulation. Director 3pp 15777, 309 24X Fiche 30-315, 82/10/18,8210220393
- B2102&0081 Notification of B21103 meeting w/utils in Bethesda.MD to discuss use of Westinghouse optimized fuel assemblies in Cycle 8 operation
 H1001NT6N.D. Dperating Reactors Branch 1 82/10/21 VAROA, 8 A Operating Reactors Branch 1 3p 15814 321 24X Fiche 50-315, 82/10/21.8210260081.
- Q Inspection reports. IE Bulletins & correspondence
- B210070007 Responds to FDIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FDIA Request Bi-313 Forwards documents listed in App B FELTON, J. M Division of Rules and Records B2/08/10, LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645-063 24X Fiche. 50-000, 82/08/10, 8210070007

- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licenses:
 IPPOLITO,T Operating Reactors Assessment Branch 82/04/01
 VARQA-S Operating Reactors Branch 1 5pp 15645 131 24X
 Fiche 50-000,82/08/10,8210070007
- 8210060387 Forwards IE Insp Repts 50-315/82-08 & 50-316/82-08 on 820412-16:0314 & 06i0 Deficiencies referred to Ofc of Investigation for review & investigation for review & investigation NORELIUS.C E Division of Engineering & Technical Programs 82/09/22 DOLANJE Indian & Michigam Electric Co 2pp 13613 350 24% Fiche 50-315.82/09/22.8210060387
- --8210060393 iE insp Repts 50-315/82-08 & 80-316/82-08 on 820412-16.0514 & 0610 Deficiencies noted inadequate fire protection of safe sautdown capability, inaccurate statements, inadequate procedure for alternate safe shutdown & inadequate lighting ORDBE, J A. STONE, J C. HAUDHNEY, C. J. Division of Engineering & Technical Programs 82/09/17 27pp 15615 352 24X Fiche 50-315,82/09/22,8210060397
- B210050274 Ack receipt of B20914 ltr informing NRC of steps taken to correct violations noted in 1E insp Repts 50-315/82-12 & 30-316/82-12 STREETER, J F Division of Project & Resident Programs B2/09/24 DDLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co ip 15609 187 24X Fiche 50-315, 82/09/24, 8210050274
- --B210050276 Responds to NRC 820816 itr re violations noted in IE insp Repts 50-315/82-12 & 50-316/82-12 Corrective actions plant manager will issue memo to plant depts by 820930 re procedures for installation of new design changes HERINO, R F indiana & Michigan Electric Co 82/09/14 KEPPLER, J C Region 3, Office of Director 3pp 15609 188 24X Fichs 50-315, 82/09/24, 8210050274
- 8210060253 Discusses 820707 mgt meeting & forwards Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 KEPPLER.J @ Region 3. Office of Director 82/10/04 DOLAN.J E American Electric Power Co , Inc DDLAN.J E Indiana & Michigan Power Co 3pp 15620 198 24X Fiche 50-315.82/10/04,8210060253
- --8210060254 Bystematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 on 801001-820401 Major areas examined util regulatory performance * Region 3, Office of Director 82/06/30 7pp 15620 201 24x Fiche, 50-315, 82/10/04, 8210060253
- --B210060256 Responds to NRC 820625 Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 Twelve previously trained operators hired & computerized radiation exposure maint sys & security access control sys installed HUNTER, R & Indiana & Michigan Electric Co B2/07/27 KEPPLER, J G Region 3, Office of Oirector 35pp 15620 208 24X Fiche, 50-315, 82/10/04, 8210060253
- 8208190233 iE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,82/10/06.8208190233
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation 8ys Piping at BHR Plants "Syc list encl, DEYGUNO,R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125, 24X Fiche 50-000, 82/10/14,820819023B
- 8210150388 EN-81-047A on 821014, order imposing civil monetary penalty in amount of \$32,000 issued to licensee re-violations concerning fire protection program & containment integrity. One violation withdrawn & two modified CRAIG, J. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 82/10/14 ip 15721 307 24X Fiche 50-315,82/10/14,8210150388
- R Periodic operating reports & related correspondence
- 8210190676 Forwards Sr-89 & Sr-90 data not completed by contractor until after due date for submittal of semiannual radioactive effluent release rept for Jan-June 1982 HUNTER,R 8 Indiana & Michigan Electric Co: 82/10/01 KEPPLER,J G Region J. Office of Director 2pp 15738:197, 24X Fichs:50-315.82/10/01.8210190676
- --8210190685 "Effluent & Waste Disposal Semiannual Rept-1982, Oasedus Effluents-Elevated Release," Sr-89 & Sr-90 data omitted from original 820827 submittal # Indiana & Michigan Electric Co. 82/10/01, 10pp. 15738.199. 24X Fiche: 50-315, 82/10/01, 8210190676.

- 6 Reportable occurrences, LERs & related correspondence
- 8210080015 Add1 response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FDIA Elemption 5) FELTON.J H Division of Rules and Records 82/07/12 UDELL:R A Critical Mass Energy Project 7pp 15645-027 24X Fiche 30-000.82/07/12.8210080015
- --B2100B0197 NRC operations ctr usage chart re svents at #acilities a NRC - No Detailed Affiliation Olven B2/07/12 ip 15668 221 24X Fiche 50-000, B2/07/12, B2100B0015
- 8210040073 Forwards LER 82-076/03L-0 SMITH.W O Indiana & Michigan Electric Co 82/09/22 KEPPLER.J O Region 3. Office of Director 1p 1589 193 24X Fisha 30-315.82/09/22.8210040073
- --8210040075 LER 82-076/03L-0 on 920823; inverter for emergency diesel generator 4B falled lawing only centrifugal charging pump in ave w/o emergency power supply Couse not stated Charging pump shifted & inverter repaired DRAPER.D M Indiana & Michigan Electric Co 82/09/22 Region 3, Office of Director ip 15583 194 24K Fiche. 50-315, 82/09/22, 82/0040073
- 8210040199 Forwards LERs 82-077/01T-0 & 82-078/03L-0
 SMITH.W. 0 Indiana & Michigan Electric Co 82/09/24 KEPPLER.J G
 Region 3. Dffice of Director ip 15583 131 24X
 Fiche 50-315.82/09/24.8210040199
- --8210040203 LER B2-078/03L-0 on 920825, unplanned gas release detected by vent stack gaseous monitor R-25 resding Caused by water overflowing from liquid waste holdup tanks into room vents & vent sys

 KRAUSE, D Indiana & Michigan Electric Co 82/09/24 Region 3, Defice of Director 1p 15583 132 24X Fiche: 50-315, 82/09/24, 8210040197.
- --B210040205 LER 82-D77/01T-O on 820910 required surveillance testing following installation of design change on control room ventitation sys had not been performed Caused by unresolved status of design change sys issues

 BEILKAN, T P Indiana & Michigan Electric Co 82/09/24 Region 3. Office of Director ip 19582 133. 24X Fiche 50-315.82/09/24.
- 8210060300 Forwards LER 92-079/01T-0 BMITH, W 9. Indiana & Michigan Electric Co 82/09/29 KEPPLER, J Q Region 3. Office of Director. ip 15619 298, 24X Ficha 30-315.82/09/29.8210060300
- --B210060307 LER B2-079/01T-0 on 820915, during iou power physics testing program following end of Cycle & refueling unit entered Mode 2 w/overpower & evertemp detta-T bistable in nonconservative configuration Caused by unclear procedure FALMER.R. A. Indiana & Michigan Electric Co 82/09/29. Region 3, Office of Director App. 15619 299 24% Fiche: 50-315, 82/09/29.8210060300
- E210190749 Forwards LER 82-080/01T-0 SMITH.W 9 Indiana & Michigan Electric Co 82/10/07 KEPPLER.J. 0 Region 3. Office of Director ip. 15737.092, 24X Fiche 50-015.82/10/07.8210190749
- --B210190757 LER 82-080/01T-0 on 820923, discovered analysis for safety injection flow water temp used value of 70 F Value of 80 F vsed in containment spray water temp analysis. Action taken to maintain restorage water temp above 80 F BELLMAN, T P Indiana & Michigan Electric Co 82/10/07 Region 3, Office of Director. 4pp. 15737 093 24X Fiche: 50-315, 82/10/07, 82/10/9749
- 82:0190572 Ferwards LER: 82-08:/03L-0 & 82-082/03L-0 SMITH: W. G. Indiana & Michigan Electric Co. 82/10/08 KEPPLER: J. Q. Region 3: Office of Director 1p. 15735:099 24X Fiche: 50-315: 82/10/08: 8210190372.
- --B210190578 LER 82-081/03L-0 on 820908, during routine turbine bldg tour, operator discovered CD diesel room carbon dioxide (CO2) sysistelated w/no names on entry beard & no personnel in room. Caused by personnel arror Proper use of CO2 sys discussed, PALMER.R.A. Indians & Michigan Electric Co. 82/10/08. Region 3, Office of Director lp. (5736, 100, 24X Fiche, 50-315, 82/10/08, 8210190572.

- --8210190588 LER 82-082/03L-0 on 820908, low pressure carbon dissists, for AB diesel generator room discovered isolated w/no fire watch posted contrary to Tech Specs Responsible individual undetermined Personnel trained in fire door PIEHL, R H Indiana & Hichigan Electric Co 82/10/03 Report Office of Director ip 15736 101 24X Fiche 50-315,82/10/09 8210190572
- 8210190266 Forwards LER: 82-083/03L-0 & 82-085/03L-0 SMITH: 0 Indiana & Michigan Electric Co 82/10/12 KEPPLER. J E Ragion 3, Office of Director ip 15742 189 24X Fiche 50-315, 82/10/12, 8210190266
- --8210190277 LER 82-083/03L-0 on 820921, during hot standby fellewing refueiting, leak observed on isolation valve CB-422N Caused by failure of 2-inch Orinnell Grade M diaphrage Diaphrage replaced MIZNER, D G Indiana & Michigan Electric Co 82/10/12 Region 3, Office of Director ip 15742 190 24X Fiche, 50-315, 82/17:18210190266
- --8210190287 LER 82-085/03L-O on 820927, during hot standby following refuniting, steam generator 2 stop dump valve MRV-221 removed from svc Caused by need to correct seat leakage Valve disc, seat to stem replaced HIZNER, D 0 Indiana & Michigan Electric Co 82/10/12 Rep. 1 3, Office of Director 1p 15742 191 24X Fiche 50-215,82/11 2 8210190266
- 82:0190340 Forwards LER 82-084/04L-0 SHITM, W Q Indiana & Michigan Electric Co 82/10/12 KEPPLEP, J& Region 3. Office of Director 1p 15742 123 24X Fiche, 30-315, 82/10/12,8210190340
- --8210190342 LER 82-084/04L-0 on 820912, unplanned gas releast detectrielevated vent stack gaseous monitor Caused by leak on waste gas oxygen analyzer Leak repaired NURPHY.C E. Indiana & Michigan Electric Co 82/10/12 Regues 3, Office of Director ip 15742 124 24X Fiche 50-315.62/16.2 8210190340
- 8210190380 Forwards LERs 82-086/03L-0, 82-087/03L-0 & 82-088/03L-0 SHITH, H & Indiana & Michigan Electric Co 82/10/13 KEPPLCR.J& Region 3, Office of Director ip 15740 359 24X Fiche 50-315, 82/10/13, 8210190380
- --8210190389 LER 82-086/03L-0.on 820914 & 16. supply breater for heat trace circuits found tripped Cause unknown. Monitoring of panel will continue until cause can be determined PALMER.R. A Indiana & Michigan Electric Co 82/10/13 Regis 3. Office of Director ip 15740 360 24% Fiche. 50-3[5,82/L]. 8210190380
- --B210190404 LER 82-087/03L-0 on 820920, containment gaseous raffatis monitor channel (ER8-1305) failed high-forcing removal of containment air particulate monitor channel from svc Caused by defective I/O card Card replaced PALMER.R. A Indiana & Michigan Electric Co 82/10/13 Regla 3, Office of Director ip 15740.361. 24X Fiche 50-315.82/16.2 8210190380
- --8210190415 LER 82-088/03L-0 on 820916, safety velve 8v-1 for state generator 3 found leaking Cause not stated Seat leakage during plant heatup not uncommon Leakage stopped by sagging valve for short period of time HIZNER, D G. Indiana & Michigan Electric Co 82/10/13 Right 3, Diffice of Director. 1p 15740 362 24K Fiche 50-315.82/16.5 8210190380
- DDCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8210060387 Forwards IE Insp. Repts 50-315/82-08 & 50-316/82-08 and 820412-16:0514 & 0610 Deficiencies referred to Ofc of Investigation.

 NORELIUB, C. E. Division of Engineering & Technical Programs 82/07/22 DOLAN, J. E. Indiana & Hichigan Electric Co. 238 15615-350 24% Fiche. 50-315, 82/09/22, 8210060387
- --8210060393 IE Insp Repts 50-315/82-08 & 50-316/82-08 on 820412-162 & 0610. Deficiencies noted inadequate fire protection of safe shutfown capability; inaccurate statements: inadequate procedure for alternate safe shutdown & inadequate lighting GROBE, J.A.; CHANT.L.; EBERLY, R Division of Engineering & Technical Progrems, 82/09/17 27pp. 15615:352, 24% Fiche: 50-315, 82/09/22, 8210060387.

- 2:00G0127 Releases public version of revised emergency plan procedures FELTON. J H Division of Rules and Records 82/09/22 Document Hangement Branch 1p 15663 293 24X Fiche 50-315.82/09/22, 82100E0129
- B210080132 Forwards public version of Revision 1 to Emergency Plan procedures PMP 2081 EPP 012, "Offsite Radiological pholitoring" & Revision 1 to PMP 2081 EPP 026, "Use of Stable 1 adding for Thypoid Blocking During Radiation Emergency " Indiana & Michigan Electric Co B2/09/13 NRC No Detailed Affiliation Olven 1p 19863 274 24x Fichs 50-315,82/09/22, B2/10080127
- B210080136 Public version of Revision 1 to Emergency Plan Procedures PMP 2081 EPP 012. "Offsite Radiological Monitoring" & Revision 1 to PMP 2081 EPP 026. "Use of Stable Indine for Thyroid Blocking During Radiation Emergency "Index encl a Indiana & Michigan Electric Co 82/09/13 20pp 15663 295 24% Fiche 50-315.82/09/22.8210080129
- 10010352 Forwards revision to modified emended security plan re key & lock control progrem Revision withheld (ref 10CFR73 21)
 HUNTER:R S Indiana & Michigan Electric Co 82/09/27 DENTON, H R
 Office of Nuclear Resolvation, Director 2pp 15574 15B
 24x Fiche 50-315.82/09/27,8210010362
- 10150594 Releases public version of revision to plant manager procedure/emergency plan procedure
 FELTON-J M Division of Rules and Records 82/09/30 Document
 Management Branch ip 15716 350 24X Fiche 50-315.82/09/30,
 8210150594
- 3210150604 Forwards public version of Revision 3 to Plant Manager Procedure/Emergency Plant Procedure App A. "Telephone Numbers for Key Plant Personnel" # Indiana & Michigan Electric Co 82/09/23 NRC No Detailed Affiliation Given ip 15716 351 24X Fiche 50-315,82/09/30,8210150594
- 3210150616 Public version of Revision 5 to Plant Manager Procedure/ Emergency Plan Procedure App A. "Telephone Numbers of Key Plant Personnel" • Indiana & Michigan Electric Co 82/09/23 2ipp 15716 352 24X Fiche 50-315,82/09/30,8210150594
- 10190036 Releases public version of procedure temporary sheet to emergency plan procedure "ELTON: J M Division of Rules and Records 82/10/01 Document famagement Branch 1p 15761 034 24X Fiche 50-315,82/10/01, 3210190036
- 3210190040 Public version of procedure temporary sheet to Emergency Plan Procedure PMP 2081 EPP 020. "Activation & Operation of Technical Support Ctr " Revised index encl. VINCE, B, SIMMS, R. CAMPRELL, D. Indiana & Michigan Electric Co. B2/09/17. 2pp 13761 035 24X Fiche 50-315,82/10/01,8210190036
- O190552 Forwards FEMA 820909 1tr, final evaluations of offsite 'mergency preparedness exercises conducted on 801007 k 220330 for State of MI & Berrien County & State of MI exponse Recommendations for offsite preparedness requested (1ND. J A Division of Emergency Preparedness & Operational Support 12/10/12 HERINO, RF American Electric Power Service Corp (ERINO, RF Indian & Michigan Electric Co 2pp 15737:149. 24X 15che 50-315, 82/10/12,8210190652
- O280379 Releases public version of revision to emergency plan rocedure ELTON, J M Division of Rules and Records 82/10/12 Document Anagement Branch 1p 15859 238 24X Ficha 50-315, 82/10/12, 1210280378.
- #210280380 Forwards public version of Revision 3 to emergency plan
 Procedure App 8 re hosp assistance plan
 # Indiana & Michigan Electric Co 82/10/01 NRC No Detailed
 Affiliation Given ip 15859 239 24X Fiche 50-315,82/10/12,
 8210280378
- |210280383 Public version of Revision 3 to emergency plan procedura App 8 re hosp assistance plan # Indiana & Michigan Electric Co 82/10/01 17pp, 15859,241, 24x Fiche 50-315,82/10/12,8210280378
- ORBO399 Releases public version of revised emergency plan rocedures ELTON, J. M. Division of Rules and Records 82/10/12 Document ELTON, J. M. Division of Rules and Records 82/10/12 Document ELTON, J. M. Division of Rules and Records 82/10/12, ELOZBO399

- --8210280408 Forwards public version of revised emergency plan procedures, including Procedures PMP 2081 EPP 004 reprotective action guides & protective actions & PMP 2081 EPP 007 re health physics procedures Indiana & Michigan Electric Co 62/09/29 NRC No Detailed Affiliation Oliven 1p 15859 262 24X Fichs 50-315,82/10/12,82/10/12
- --8210280413 Public version of revised emergency plan procedures, including Procedure PMP 2081 EPP 004 re protective action guides & protective actions & PMP 2081 EPP 009 re health physics procedures Procedures index encl e Indiana & Michigan Electric Co 82/09/29 57pp 15859 263 24% Fiche 50-315.82/10/12.8210280399
- I Financial information
- B210070279 Forwards Annual Financial Rept for 1981 & projected cash flow for 1982 HERINO, R F Indiana & Michigan Electric Co 82/10/04 DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp 15634, 185. 24X Ficha 50-
- --8210070286 "ID & HI Electric Co. Annual Financial Rept 1981."

 American Electric Power Service Corp * Indiana & Michigan Electric Co 82/10/04 32pp. 15634 187 24X
 Fiche 50-315,82/10/04,8210070279
- J Insurance & Indomnity information
- 82100403:3 Forwards Endorsement 54 to NELIA Policy NF-206 & Endorsement 44 to MAELU Policy MF-79
 8UCKLES, J. Marsh & McLennan, Inc., M & M. Nuclear Consultants, Inc. Div. 62/09/27, SALTZMAN. J. Assistant Director for State & Licensee Relations 3pp 15386.168 24X Fiche.50-315,82/09/27,82100403:3.
- P Operating license stage documents & correspondence
- 8210050538 Forwards Amends 59 & 42 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to reflect installation or replacement of valves to improve operation CILIMBERO.R.L. Operating Reactors Branch 1. 82/09/09 DOLAN.J. Indiana & Michigan Electric Co. 2pp. 15637 172 24X Fiche 50-315.82/09/09.8210050538
- --82i0050541 Amends 59 & 42 to Licenses DPR-58 & DPR-74, respectively, revising Tech Bjecs to reflect installation or replacement of valves to promote improved operation VAROA,8 A Operating Reactors Branch I 82/07/09 26pp. 15637.174 24X Fiche 50-315,82/07/09,8210050538.
- --8210050544 Bafety evaluation supporting Amends 59 & 42 to Licenses DPR-58 & DPR-74, respectively.

 4 Office of Nuclear Reactor Regulation, Director 82/09/09. 2pp 15637:200 24X Fiche 50-315.82/09/09.8210050538
- --B210050546 Notice of issuance & availability of Amends 59 & 42 to Licenses DPR-58 & DPR-74:respectively GROTENHUIS, M. Operating Reactors Branch i 82/09/09 2pp. 15637 202. 24% Fiche 50-315, 82/09/09,8210050538.
- 8210040415 Forwards Amends 61 & 44 to Licenses DPR-38 & DPR-74, respectively, sefety evaluation & notice of issuance & availability. Amends revise Tech Specs to reflect revised LOCA analysis for Unit is Suppl 2 to PDC-II procedures, GILIMBERG,R L Operating Reactors Branch 1. 82/09/15. DOLAN.J. Indiana & Michigan Electric Co. 2pp 15597.098 24X Fiche: 50-315.82/09/15,8210040415
- --8210040417 Amends 61 & 44 to Licenses DPR-58 & DPR-74, respectively, revising Tech Specs to reflect revised LOCA analysis for Unit i & implementation of Buppl 2 to PDC-II power distribution control procedures for Units 1 & 2. VARGALS A. Operating Reactors Branch 1. 82/09/15. 29pp 15597.100. 24X Fiche.50-015.82/09/15,8210040415.
- ---B21004041B Bafety evaluation supporting Amends 61 & 44 to Licenses DPR-58 & DPR-74, respectively * Office of Nuclear Reactor Regulation, Directon, 82/09/15, Spp. 15597 129. 24X Fichs.50-S15.82/09/15.8210040415.
- --B210040417 Notice of issuance & availability of Amends 61 & 44 to Licenses DPR-58 & DPR-74: respectively. VARQA-8.A Operating Reactors Branch 1. 82/09/15. 2pp 15597: 132 24% Fichs: 50-315. 82/09/15,8210040415

- 8210040428 Forwards request for add1 info re hydrogen control issues for ite condenser plants Response requested by 821015 VARQALS A Operating Reactors Branch i. 82/09/16 BOLAN.J Indiana & Mitchigan Electric Co 10pp 15597
- 821005013B Forwards documents as Phase I b of response to Bection 2 i of Encl 3 to DO Elsenhut 801222 ltr re control of heavy loads Nestinghouse analysis of lifting arrangement for reactor vessel head & upper internals expected by 830315 HUNTER.R 8 Indiena & Michigan Electric Co. 82/09/29 DENTON.H R Office of Nuclear Reactor Regulation. Director. 31pp 15606 029 24x Fiche: 50-015, 82/09/29, 8210050138
- B210050159 Application for amend to Licenses DPR-58 & DPR-74.proposing Tach Spec changes for placament of new post-accident containment hydrogen monitoring sys to satisfy NUREG-0737. Item II F. 1 & & to remove existing equipment from svc MUNTER.R S Indiana & Michigan Electric Co 82/09/29 DENTON.H R. Office of Nuclear Reactor Regulation. Director 2pp 15605 149 24X Fiche 50-315.82/09/29,8210050159
- --8210050160 Proposed Tech Spec 3/4 6 4 re combustible gas control > Indiena & Michigan Electric Co 92/09/29 3pp 15605 151 24X Flche 50-315.82/09/29.8210050159
- B210120230 Forwards proprietary Suppl 1 to XN-NF-B2-37(P), "DC Cook Unit 2, Cycle 4 SAR, Thermal-Hydraulic Analysis," providing addit analysis of steady-state thermal margins during Cycle 4 operation Rept withheld (ref 10CFR2 790) CHANDLER, J C Exxon Nuclear Co, Inc (subs of Erxon Corp.) 82/09/29 EISENHUT, D O Division of Licensing 4pp 15656-079 24X Fiche 50-316,82/09/29,8210120230
- 8210050211 Second suppl to 820407 application for Cycle 4 reload & uprace license amend Further changes to App A Tech Specs necessary to allow Cycle 4 operation w/Erron Nuclear Cofurl at 3,411 MHt
 HUNTER,R B Indiana & Michigan Electric Co 82/09/30 DENTON.H R
 Office of Nuclear Reactor Regulation, Director lipp, 15411 246
 24% Fichs 50-316,82/09/30,8210050211.
- 8210050349 Forwards add1 info re hydrogen mitigation & control at facilities Util continues to work w/TVA & Duke Power Co toward completion of executive summary rept on ice condenser hydrogen R&D progrem HUNTER, R B Indiana & Hichigan Electric Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 126pp. 15410.126 24X Fiche 50-315.82/09/30.8210050349
- 8210080194 Comments on regulatory performance improvement program Comments can be dealt with revising program description to take full credit for mgt review afforts Util Yieus on comments will be discussed et meeting icheduled for 821014 XEPPLER, J.O. Region 3. Office of Director 82/10/01 DOLAN, J.E. American Electric Fower Service Corp. DOLAN, J.E. Indiane & Michigan Electric Co. 2pp 19640 188 24X Fiche: 50-315, 82/10/01, 8210080194
- 8210060253 Discusses B20707 mgt meeting & forwards Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16. KEPPLER, J. G. Ragion 3, Office of Director 82/10/04 DDLAN, J.E. American Electric Power Co., Inc. 3pp. 15620, 178 24X Fiche. 50-315, 82/10/04, 8210060253.
- --B210060254 Systematic Assessment of Licenser Performance Rapts 50-315/82-16 & 50-316/82-16 on 801001-820401. Hajor arees examined util regulatory performance ** Region 3. Office of Director. 82/06/30 7pp 15620.201. 24X Fiche: 50-315, 82/10/04, 8210060253
- --8210060256 Responds to NRC 820625 Systematic Assessment of Licensee Performance Repts 50-315/62-16 & 50-316/82-16. Twelve previously trained operators hired to computative radiation exposure maint sys & security access control sys installed HUNTER:R S Indiana & Michigan Electric Co. 82/07/27. KEPPLER:J G. Region 3. Office of Director. 35pp. 15620,208. 24X Fiche:50-315,62/10/04,8210060253
- 82:0150491 Confirms B20922 telcon re masonry walls. Addl info required within 45 days to complete review VARGA: 8 A. Operating Reactors Branch 1. B2/10/04. DOLAN. J Indiana & Michigan Electric Co. 3pp 15717:275. 24X Fiche: 50-315. 82/10/04, 8210130491.
- 8210230340 Forwards Amends 63 & 45 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability, Amend reviess Tech Specs changing surveillance requirements for boron & safety injection sys CTLIMBERO,R.L. Operating Reactors Branch 1, 82/10/04 DQLAN,J. Indiana & Michigan Electric Co. 2pp. 15807:259, 24X Fiche: 50-315, 82/10/04, 8210250340.

- --8210250393 Amends 63 & 45 to Licenses DPR-58 & DPR-74, respectively changing Tech Specs re surveillance requirements for boron & safety injection sys & updating core flux VAROA:6 A Operating Reactors Branch 1 62/10/04 73pp 15807 261 24X Fiche 50-315,82/10/04,8210250340
- --8210250394 Safety evaluation supporting Amends 63 & 45 to Licenses DPR-58 & DPR-74 respectively Office of Nuclear Reactor Regulation, Director 82/10/04 5pp 15807 334 24X Fiche 50-315.82/10/04.8210250340
- --8210250395 Notice of Issuance & availability of Amends 63 & 45 to Licenses DPR-58 & DPR-74 respectively VAROAr S A Operating Reactors Brench 1 82/10/04 2pp 15807 339 24X Fiche 50-315,82/10/04,8210250340
- BRIOISCAGA Forwards tafety evaluation re main steam line break w/continued feedwater addition & contractor technical evaluation rept W/o technical evaluation rept W/A technical evaluation rept VARQA. B A Operating Reactors Branch 1 B2/10/05 BOLAN, J Indiana & Michigen Electric Co 200 15716.090 24X Fiche, 50-315, 82/10/05, 8210150434
- --B210150437 Safety evaluation re main steam line break w/continus feedwater addition a Operating Reactors Branch 1 82/10/05 7pp 15716 092 2cc Fiche 30-315,82/10/05.8210150434
- 6210130123 Forwards proprietary "Users Manual for PTSPHR2-FURTRAN Program for Simulation of PIRR Plant Translents" & Suppl I to manual Affidavit supporting proprietary classification of documents enci Manuals withheld (ref 100FR2 790)

 OMBLEY, 0 F Exxon Nuclear Co. Inc (aubs of Exxon Corp.)

 82/10/08 THOMAS. CO Standardization & Special Projects Franc)

 App 15673 097 24X Fiche 50-316,82/10/08,8210130123
- 8210150033 Forwards Revision 1 to XN-NF-82-32(P), "Plant Transient Analysis for DC Cook Unit 2 Reactor at 3,425 MWt." including DNB analysis method changes to support Cycle 4 operation Revision withheld (ref 10CFR2 790) OMSLEY.0 F Exxon Nuclear Co., Inc. (subs of Exxon Corp.) 82/10/08 EISENHUT.0 P Division of Licensing 1p 15715 269 24X Fiche 50-316,82/10/08,8210150033
- 8210250228 Forwards proprietary responses to five of 16 questions per NRC 820730 request for addl info re hydrogen control issues for ice condenser plants, particularly CLABIX computer program Responses withheld (ref 100FR2, 790) HUNTER, R 8 Indiana & Michigan Electric Co 82/10/15 DENTO: N8 Office of Nuclear Reactor Regulation, Director 2pp 13787 337 24X Fiche 50-315, 82/10/15, 8210250228.
- O Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of receifs a steam generators & steem turbines App A documents provided in R Udeil FOIA Request 61-313 Forwards documents listed in App B.
 FELTON, J H Division of Rules and Records 82/08/10 L0x3,0 J Hinthrop, Stimson, Putnem & Roberts. 9pp 15445,063 24% Fiche: 80-000,82/08/10,8210070007
- --8210070139 Forwards tabulated data on steam generator insp k mark: facilities. Data should be provided to licenses: IPPOLITO. Y Operating Reactors Assessment Branch 82/04/01 VARQA: 8 Operating Reactors Branch 1 5pp 15645,131 2KK Fiche 50-000.82/09/10.8210070007
- 8210040387 Forwards IE Insp Repts 50-315/82-08 & 50-316/82-08 on B20412-16.0514 & Oxio Deficiencies referred to Dfc of investigation for review & investigation NORELIUS, C E. Division of Engineering & Technical Programs 82/09/22, DDLAN, J E. Indiana & Michigan Electric Co 2/9 15615.350 24K Fiche 50-315.82/09/22.8210040387
- --8210060393 IE Insp Repts 50-315/82-08 & 50-316/82-08 on 920412-112 & 0610 Deficiencies noted inadequate fire protection of 14ft shutdown capability, inaccurate statements, inadequate procedure for alternate safe shutdown & inadequate lighting GROBE, J.A., STONE, J.C., HAUGHNEY, C.J. Division of Engineering Technical Programs 82/09/17 27pp 15615-352 24% Fiche, 50-315, 82/09/22, 8210060387.
- 8210050274 Ack receipt of 820914 ltr informing NRC of steps latin to correct violations noted in 1E Insp Repts 50-315/82-12 & 50-316/82-12.

 8TREETER.JF Division of Project & Resident Programs 82/09/M DOLAN.JE , American Electric Power Bervice Corp DOLAN.JE Indiana & Michigan Electric Co ip. 15509:187, 24X Fiche:50-315,82/09/24,8210050274

- --E210030276 Responds to NRC 820816 ltr re violations noted in IE Insp Repts 50-315/82-12 & 50-316/82-12 Corrective actions plant canager will issue memo to plant depts by 820930 re procedures for installation of new design changes HERINO, R F Indiana & Michigan Electric Co 82/09/14 KEPPLER. J G Region 3, Office of Director 3pp 15607 188 24X Fiche 50-315,82/09/24,8210050274
- 8210050253 Discusses B20707 mgt meeting & forwards Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 EPPLER, J O Region 3, Office of Director 82/10/04 DOLAN, J E American Electric Power Co., Inc. DOLAN, J E Indiana & Michigan Power Co. 3pp. 15620 198 24X Fiche 50-315,82/10/04,8210060253
- --8210060254 Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 on 801001-820401 Major areas examined util regulatory performance.

 * Region 3, Office of Director 82/06/30 7pp 15620 201 24x Fiche 50-315,82/10/04,8210060253
- --B210060256 Responds to NRC 820625 Systematic Assessment of Licensee Furformance Repts 30-315/82-16 & 50-316/82-16 Twelve previously trained operators hired & computerized radiation exposure maint sys & security access control sys installed FOWNIER: R S Indiana & Michigan Electric Co B2/07/27 KEFPLER: J G Region 3. Office of Director 35pp 15620/208 24X Fiche 50-315,82/10/04,8210060253
- -208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 leglant Seeds " Svc list encl COBB.L [Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,02/10/06,8208190233
- 1208190238 1E Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall-Large-Diameter: Stainless Steel, Recirculation Sys Piping at BMP Pients "Svc iist enci
 DEYGUNO.R C Director's Office, Office of Inspection and Enforcement 82/30/14 (Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000, 82/10/14,8208190238
- 210150388 EN-81-047A on 82:014, order imposing civil monetary penalty in amount of \$52,000 issued to licenses re violations concerning fire protection program & containment integrity One violation withdrawn & two modified CRAIG.J: AXELRAD,J Director's Office Office of Inspection and Enforcement 82/10/14 ip 15721 307 24X Fiche 50-315,82/10/14, 92:10150388
- Periodic operating reports & related correspondence
- 210390676 Forwards Sr-89 & Sr-90 data not completed by contractor until after due date for submittal of semiannual radioactive efficient release rept for Jan-June 1782 HUXIER, R S Indiana & Michigan Electric Co 82/10/01 KEPPLER, J G Region 3. Office of Director 2pp 15738 197 24X Fiche 50-315, 82/10/01,8210170676
- -8210190685 "Effluent & Waste Disposal Semiannual Rept-1982, Gaseous Effluents-Elevated Release: " 8r-89 & Sr-90 data omitted from original 820827 submittal solution Indiana & Michigan Electric Co 82/10/01 10pp 15738 199 24X Fiche 50-315.82/10/01.8210190576
- Reportable occurrences. LERs & related correspondence
- 210040321 Forwards LERs 82-072/03L-0 & 82-078/03L-0 SMITH.H @ Indiana & Michigan Electric Co 82/09/22 KEPPLER.J @ Region 3. Office of Director ip 15586 171 24X Fiche 50-316.82/09/22.8210040321
- 8210040327 LER 82-072/03L-0, on 820824, reactor trip occurred as result of facilure in 120-voit ac vital bus Caused by burned out resistor (R1) & diode (D1) on oscillator board & associated fuse Dscillator board & fuse replaced PALMER: R A Indiana & Michigan Electric Co. 82/09/22 Region 3. Office of Director 1p. 15586 172 24X Fiche. 50-316, 82/09/22, 8210040321
- 8210040330 LER 82-075/03L-0 on B20824, following reactor trip, RCB dose equivalent & I-131 concentration exceeded 1.0 uCi/g eteady state limit. Caused by inadvertent removal from evc of chemical & vol control sys mixed bed demineralizer. PALMER.R A Indiana & Michigan Electric Co 82/09/22 Region 3, Office of Director App 15586 173 24X Fiche 50-316. 82/09/22.82 10040321
- '10040201 Forwards updated LER 82-064/03X-1 SMITH, H Q Indiana & Michigan Electric Co 82/09/23 KEPPLER, J. Q. Region G. Office of Director. 1p 15583-161 24X Ficha: 50-316, 82/09/23, 8210040201

- --8210040209 Updated LER 82-064/03X-1 on 620724. Loop 3 overtemp Delta-T trip setpoint found high Caused by setpoint drift New module installed calibr & verified operational Loop returned to svc PALMER, R. A. Indiana & Michigan Electric Co 82/09/23 Region 3. Office of Director 1p 15583 162 24X Fiche 50-316,62/09/23, 8210040201
- 8210060277 Forwards LER 82-076/03L-0 SMITH-N 0 Indiana & Michigam Electric Co 82/09/29 KEPPLER.J Q Region 3, Office of Director 1p 15621 168 24X Fiche 50-316.82/09/29.8210060277
- --B210060313 LER 82-076/03L-0 on 920915, discovered diesel room AB carbon dioxide sys isolated w/no personnel in room Cause not stated Bigns posted cautioning personnel to restore carbon dioxide sys when exiting Administrative action taken LAMP.H S Indiana & Hichigan Electric Co 82/09/29 Region 3, Uffice of Director 1p 15621 169 24X Ficha 50-316,82/09/29,
- 8210080189 PNO-11I-82-105 on 820930, facility shut down for 3 days to repair weld crack in 1-inch feedwater drain between containment penetration for steam generator I & last feedwater chack valve, REVES.L. STREETER.J. SPESSARD.R Region 3, Office of Director 82/10/01 ip. 15640,180 24X Fiche 50-316,82/10/01,8210080189
- 8210180120 Forwards LERs 82-077/03L-0 & 82-078/03L-0, SMITH W 0 Indiana & Michigan Electric Co 82/10/05 KEPPLER, J 0 Region 3, Office of Director 1p 15719 325 24X Fiche 50-316, 82/10/05, 8210180120
- --8210180123 LER 82-077/03L-0 on 820907.equalizing vaive on inner door of upper containment personnel airlock found leaking slightly during containment antry Cause unknown Valve actuating mechanism adjusted PIEHL, R H. Indiana & Michigan Electric Co 92/10/05. Region 3, Office of Director ip 19719-326 24X Ficha 50-316,82/10/05,82/0180120
- --B21018D127 LER 82-078/03L-0 on 820918 & 20.RCB dose equivalent I-131 concentration exceeded i 0 uCi/g steady-state limit Caused by RCS dose equivalent I-131 spiked to max of 1 76 uCi/g PALMER,R A Indiana & Michigan Electric Co 82/10/05 Region 3, Office of Director 6pp 19717 327 24X Fiche 50-316, 82/10/05,8210180120
- 8210190727 Forwards LER 82-080/03L-0 SMITH W 0 Indiana & Michigan Electric Co 82/10/08 KEPPLER, J Q Region 3. Office of Director 19 15736 298 24X Fiche 50-316, 82/10/08, 8210190727.
- --8210190735 LER 82-080/03L-0 on 820909, west component cooling water HX outlet valve CMD-420 removed from svc due to leak Caused by elastomer seat being pulled loosed from valve body Valves returned to manufacturer HINER, D 0 Indiana & Michigan Electric Ca 82/10/08 Region 3, Office of Director 2pp 15736-279 24X Fiche 50-316, 82/10/08,8210190727.
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8203050387 Forwards IE Insp Repts 50-317/82-02 & 50-318/82-02 on 820106-0202 & notice of violation STAROSTECKIR. Division of Project & Resident Programs 82/02/16 LUNDVALL, A.E. Baltimore Oas & Electric Go. 2pp. 12134 298. 24X Fiche: 50-317, 82/02/16, 8203050387
- --8210190714 IE Insp Repts 50-317/82-02 & 50-318/82-02 on 820106-0202 Noncompliance noted failure to adequately control special processes associated w/repair of saltwater piping & failure to properly neutralize regenerative waste ARCHITZEL.R.E., MCCAME, E.C. Division of Project & Resident Programs. 82/02/12, 11pp 15751 024 24% Fichs:50-317,82/02/16,8203050387
- 8210210544 Releases public version of revised emergency response plen implementing procedures.
 FELTON, J.M. Division of Rules and Records. 82/09/23 Document Management Branch. 1p 15782 330. 24X Fiche: 50-317:82/09/23. 8210210544.
- --8210210545 Forwards public version of revised emergency response plan implementing procedures, including Procedures EPIP 5.5 re exercises, test & drills & EPIP App D.2 re maps & charts * Baltimore, Oss & Electric Co 82/09/15. CLARK, R.A Operating Reactors Branch 3 ip 15782:331. 24X Fiche: 50-317.82/09/23. 8210210544

- --821021055i Public varsion of revised emargency response plan implementing procedures including Procedures EPIP 3 5 researcises, test & drills & EPIP App 8 2 re maps & charts List of affective pages encl 82/09/15 20pg 15782 332 24x Ficha 50-317, 82/09/23, 8210210544
- 8210120134 Forwards third suppl to 790914 fire protection safety evaluation, resolving Item 3 2 1, Fire Hazards Analysis "Ninety-day period to inform of installation schedule for rinety-day perios so inform or installation schedule fo source range flux monitoring instrumentation acceptable CLARKIR A Operating Reactors Branch 3 82/09/27 LU Baltimore Gae & Electric Co 1p 15492 197. 24X Fiche 50-317, 82/99/27, 8210120134 LUNDVALL A. E
- --8210120139 Safety evaluation canciluding that proposed fire protection design meets requirements of App R to IOCFR50, Items III G 3 & III L re safe shutdown in event of fire FIGRAVANTE, N. MARRISON, O., JAFES, D. Departing Reactors Branch I 82/09/27 9pp 15592 138 24X Fiche.50-317.82/09/27,8210120134
- 8210150423 Application for amend to Licenses DPR-53 & DPR-49 consisting of Revision 10 to security plan; allowing devitalization of vital areas during cold outages Plan withheid (see 100FR73 21) Ref 10078/3 217

 BighMAKER.N J Baltimore Gas & Electric Co 82/10/07, CLARK.R A Operating Reactors Branch 3 3pp. 15704,021 24X

 Fiche 50-317,82/10/07,8210150423
- 8210180005 Submits update of util progress in closing TMT Action Items I C J, JJ F 1 & JJI.A 1 2.

 LUNDVALL, A E Baitimore Gas & Electric Co 82/10/12 CLARK, R A. Operating Reactors Branch 3 3pp 15720 028 24X

 Fiche 50-317, 62/10/12, 62/10/60005
- P Operating license stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A PELTON, J H Division of Rules and Records 82/06/28 Critical Mass Energy Project 15pp. 19727:005 24K Fiche: 50-000, 82/06/28, 8280010008 82/05/28 UDELL,R A
- --B20427004B Recommends prompt attention be given to problem of reactor coolant pump closure stud corrosion detected at facilities Response by 820415 requested EIBENHUT.D Q. Division of Licensing. B2/03/24. HANAUER.S H Division of Bystems Integration (post Bi1005). 3pp 66035 222 24X Fiche 50-000, B2/06/28 B21001000B
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON. J M Division of Rules and Records 82/07/12 Critical Mass Energy Project. 9pp. 13665,027, 24X Fiche 50-000.82/07/12.8210080015 82/07/12, UDELL,R A
- --8210080064 Trip rept of 820207 visit to NRR in Bethesda, MD & 820208-10 riouscos+ Trip rept of \$2000/ visit to NMX in setteeds, ND & site visit re installation of 10-inch automatic isolation valve in main feedwater sys Epsc 6750-H-253 for nuclear carbon steel gate; globe & check valves & related info ancl. BEARDEN.R Q. E000. Inc. 82/03/22 47pp 15665:192, 241 Fiche: 50-000; 82/07/12; 8210080015

- --8210070117 Amends 75 & 56 to Licenses DPR-53 & DPR-69, respective ALOUVUILY Amends 73 % 30 to Licenses DPR-53 & DPR-59, respectors-ting typographical seriors re inservice insp & valve testing & ailowing start up of reactors w/inoperable but isolated power operated relief valves CLARK, R & Operating Reactors Branch 3 82/09/20 34pp 15645 009 24x Fiche 50-3i7,82/09/20,8210070106
- --BR10070125 Bafety evaluation supporting Amends 75 & 56 to Licent DPR-53 & DPR-69: respectively JAFFE, D H Office of Nuclear Reactor Regulation, Director B2/09/24 4pp 15645 043 24X Fiche 50-317.82/09/20.82800%
- --8210070130 Notice of issuance & availability of Amends 75 % 5& 1 Licenses DPR-53 & DPR-69, respectively CLARK, R A Operating Reactors Branch 3 82/09/20 2pp 1545 047. 24X Fiche 50-317, 82/09/20.8210070106
- 8210180124 Forwards proprietary & nonproprietary versions of "Risc of Eddy Current Testing on Ouide Tubes at Calvert Cliffs I After Cycle 5 "
 LUNDVALL, A E Baltimore Oas & Electric Co 82/09/22 CLARK, R Operating Reactors Branch 3 2pp 15719 097 24X
 Fiche 50-317, 82/09/22, 8210180124
- --8210180133 Nonproprietary version of "Results of Eddy Current Te on Ouide Tubes at Calvert Cliffs I After Cycle 5 "

 Combustion Engineering. Inc CEN-216(8) B2/08/3i 7ep 15719 097 24X Fiche 50-317.82/09/22.8210180128
- 821027041R Forwards Amends 77 & 58 to Licenses DPR-53 & DPR-69, tespectively, safety evaluation & notice of issuance & availability Amends revise Tech Spec Table 3 7-4 which lists anubbers that require periodic insp & testing
 JAFFE,D H Operating Reactors Branch 3 82/09/23 LUNDVALLIA
 Baltimore Cas & Electric Co 3pp 15863 273 24x
 Fiche 50-317,82/09/23,8210290412
- --8210270428 Amends 77 & 58 to Licenses DPR-58 & DPR-69, respective revising Tech Spec Table 3 7-4 which provides lists of safety-related hydraulic shock suppressors (snubbers) which require periodic insp & testing CLARK, R A Operating Reactors Dranch 3 82/09/23 26pp 15863:276 24X Fiche 50-317, 82/09/23,8210290412
- --8210270437 Bafety evaluation supporting Amends 77 & 58 to Literal DRR-53 & DRR-69, respectively 4 Office of Nuclear Reactor Regulation, Director 15863: 302 24X Fiche 50-317,82/09/23,8210290412
- --8210270444 Notice of issuance & availability of Amends 77 t 88 te Licenses DPR-58 & DPR-59.respectively CLARK.R A Operating Reactors Branch 3 82/09/23 2pp 15863:305. 24X Fiche 50-317.82/09/23.8210290412
- 8210130338 Application to amend Licenses DPR-53 & DPR-69, revising Tech Speck re pressurizer limiting condition for operation & associated surveillance requirements.

 LUNDVALL: A E Baltimore Oas & Electric Co 82/09/29 CLASK, R a Operating Reactors Dranch 3 3pp 15680 268 24X Fiche 50-317, 82/09/29, 8210130338.
- --8210130342 Proposed Tech Specs 3 4 4 4 4 4 re RCS pressyristr * Baltimare Oas & Electric Co 82/09/29, 44pp 15680 221 Fiches :50-317,82/09/29/,9210130338
- 8210180423 Application for amend to Licenses DPR-53 & DPR-69 tensists of Revision 10 to security plan, allowing devitalization of vital areas during cold outages. Flan withheld (ref 10CFR73, 21) 82/10/07. CLARKIR A
- 8210180005 Submits update of util progress in closing TMI Action list I C. 1, II. F 1 & III. A 1 2. LUNDVALL. A. E Baltimore Cas & Electric Co. B2/10/12 CLARKER A Operating Reactors Branch 3, 3pp 15720; 028 Fiche; 50-317, 82/10/12, 8210180005.
- 8210200108 Notification of 821025 meeting w/util in Bethesdard to discuss control of heavy loads. JAFFE, D H Operating Reactors Brench 3. 82/10/18 CLARKA A Operating Reactors Branch 3. 2pp 15767,304. 24X Fiche: 50-317,82/10/18,8210200108

- 1 Inspection reports, IE Bulletins & correspondence
- --P210190702 Natice of violation from insp on B20106-0202 STAROSTECKL: R Division of Project & Resident Programs B2/02/16 28P 15751 022 24X Fiche 50-317.82/02/16.8203050387
- --9210390714 IE Insp Repts 50-317/82-02 & 50-318/82-02 on 820106-0202
 Nancomptiance noted failure to adequately control special
 processes associated w/repair of saltwater piping & failure
 to properly neutralize regenerative waste
 ARCHITZEL, R E . KCCABE, E C Division of Project & Resident
 Programs 62/02/12 lipp 15751 024 24X Fiche 50-317,82/02/16.
 6203050387
- E210070007 Responds to F01A request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell F01A Request 81-313 Forwards documents listed in App B FELTON. J H Division of Rules and Records 82/08/10 L0No, D J Winthrop, Stimson, Putnam & Roberts 7pp i5645 063 24X Fiche 50-000.82/08/10,8210070007
- --8210070172 Forwards info re steam generator integrity & insps at ail operating PURs, per 750320 & 21 requests Details of insps, sincluding defect indications, tube plugging criteria & tubes plugged uill not be provided except for Point Beach ! GDLLER. K. R. Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R. Division of Tachnical Review (NRR-1975 only) 5pp 15645 196 24X Fiche 50-000, 82/08/10, 8210070007
- 6210060099 Forwards iE Insp Repts 50-317/82-06 & 50-318/82-06 on E20315-16 & notice of violation HARTINATT Division of Engineering & Technical Programs 82/09/17 LUNDVALL, & Baitimore Oas & Electric Co 2pp 19614 345 24X Fache 50-317,82/09/17,8210060099
- --B210060104 Notice of violation from insp on 820315-16

 © Division of Engineering & Technical Programs 82/09/17 2pp
 15614 347 24X Fiche 50-317,82/09/17,8210060099
- --8210060127 IE insp Repts 50-317/82-06 & 50-318/82-06 on 820315-16
 Noncompliance noted failure to establish adequate
 procedures, failure to foilow radiation protection procedures
 & failure to make necessary radiological surveys
 PLUMLEE, K E . OREENMAN, E Q Division of Engineering & Technical
 Programs 82/09/17 10pp 15614 349 24X Fiche 50-317,82/09/17,
 8210050097
- E21007010& Forwards Amends 75 & 56 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amends correct typographical errors reinsprvice ines & valve testing JAFFE.D H Operating Reactors Branch 3 82/09/20 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 15645 006 24% Fiche 50-317, 82/09/20, 8210070106
- --0210070117 Amends 75 & 56 to Licenses DPR-50 & DPR-69, respectively, correcting typographical errors re inservice insp & valve testing & allowing start up of reactors w/inoperable but isolated power operated relief valves
 CLARK, R A Operating Reactors Branch 3 82/09/20 34pp, 15645 009 24X Fiche 50-317,82/09/20,8210070106
- B210190124 Forwards proprietary & nonproprietary versions of "Results of Eddy Current Testing on Guide Tubes at Calvert Cliffs I After Cycle 5"
 LUMDYALL.A E. Baltimore Gas & Electric Co 82/09/22 CLARK.R A Operating Reactors Branch 3 2pp 15719 097. 24X Fiche 50-317.82/09/22,8210180124
- --B210180133 Nonproprietary version of "Results of Eddy Current Testing on Guide Tubes at Calvert Cliffs I After Cycle 5 "
 « Combustion Engineering, Inc. CEN-216(8) 82/08/31 7pp 15719 099 24X Fiche 50-317.82/09/22,0210180124.
- 8210150214 Forwards IE Insp Repts 50-317/82-23 & 50-318/82-19 on 820810-0914 & notice of violation STARDSTECKI.R Division of Project & Resident Programs 82/09/27 LUNDVALL.A E Battimore Gas & Electric Co 2pp 15705:234, 24X Fiche: 50-317, 82/09/27, 8210150214
- --G210[50226 Notice of violation from insp on 820810-0914 4 Division of Project & Resident Programs 82/09/27, 2pp 15705 236 24X Fiche 50-317.82/09/27.8210150214.

- --8210150235 IE Insp Repts S0-317/82-23 & 50-318/82-19 on 820810-0914 Noncompliance noted radiological event not declared nor appropriate response taken & procedures not properly implemented ARCHITZEL.R E. TRIMBLE.D C. MCCASE.E C. Division of Project & Resident Programs \$2/09/27 18pp. 15705 238 24X Fichs 50-317,82/09/27.8210150214
- 8210060240 Forwards notice of violation re IE Insp Repts 50-317/82-07 & 50-318/82-07 on 820413-0511 Violation A re operation w/hydrogen analyzers insperable needs no response Violation B re inadequate review requires full response STAROBIECKI.R. Division of Project & Resident Programs 82/07/29 LVNDVALLA E Baltimore Gas & Electric Co 3pp 15619 322 24X Fiche 50-317,82/09/29,8210060240
- --8210060243 Notice of violation from insp on 820413-0511 Noncompliance noted plant operated w/both hydrogen analyzers inoperable plant operating safety review committee performed inadequate review on 800924 & approved revision w/o correct criteria Region 1, Defice of Director 82/09/29 2pp 15619:325 24x Fiche 50-317,82/09/29,8210060240
- 9210070159 Requests approval for excluding reactor vessel closure studs at facilities.per IE Bulletin 82-02 & Reg Quide 1.65
 Boiting matl complies w/recommended matls
 LUNDVALL.A E Baltimore Qas & Electric Co 82/10/01 DEYDUNO.R C
 Diractor's Office. Office of Inspection and Enforcement 3pp
 15627 013 24x Fiche 50-317.82/10/01.8210070159
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Beeds." Syc list enci COBB.L i Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York. 64pp 15761 250 24X Fiche 50-000,82/10/06.8208190233
- 8210130099 Ack receipt of 820917 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/82-20 & 50-318/82-17 MARTIN.T T Division of Engineering & Technical Programs 82/10/06 LUNDVALL.A E Baitimore Oas & Electric Co 1p 15473 104 24X Fiche 50-317, 82/10/06.8210130099
- --8210130103 Responds to NRC 820819 ltr re violations noted in 1E Insp. Repts 50-317/82-20 & 50-318/82-17 Corrective actions: Operating Instruction AU Procedurs 2 & Instruction 302 revised LUNDVALLA E Baltimore Gas & Electric Co 82/09/17, MARTIN.T T. Division of Engineering & Technical Programs 4pp 15673 105 24X Fiche 50-317,82/10/06,8210130099
- 6210190797 Ack receipt of 920913 1tr informing NRC of steps taken to correct violations noted in iE Insp Repts 50-317/62-16 & 50-316/62-16. ETAROSTECKI.R Division of Project & Resident Programs 62/10/12 LUNDVALLA E Baltimore Gas & Electric Co. 1p 15736 314 24X Fiche 50-317, 82/10/12 8210190797
- --B210190803 Responds to NRC 820816 itr re violations noted in IE Insp Repts 50-317/82-18 & 50-318/82-14 Corrective actions Instruction-112 revised to ensure essential equipment will not be inadvertently removed from svc FTI-107 also revised LUNDVALLA E Baltimore Cas & Electric Co 82/09/15 STAROSTECKI, R Division of Project & Resident Programs 2ρρ 15736 315. 24X Fiche: 50-317.82/10/12,8210190797
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants," Sec list encl DEYOUND, R.C. Director's Office, Defice of Inspection and Enforcement. 82/10/14. Consolidated Edison Co of New York, 115pp 15810;125, 24X Piche, 50-000, 82/10/14, 8208190238.
- R Periodic operating reports & related correspondence
- 8210210328 Forwards monthly operating repts for Sept 1982 LDTITO,E M Baltimore Qas & Electric Co. 82/10/15. Director's Office, Office of Inspection and Enforcement ip. 15762 003. 24X Fiche 30-317, 82/10/15.8210210328
- --8210210457 Monthly operating repts for Sept 1982. LOTITO.E. Baltimore Gas & Electric Co. 82/10/15. 10pp. 15762.004. 24X Fiche: 50-317, 82/10/15, 8210210328.
- 8 Reportable occurrences, LERs & related correspondence
- 8210280305 Forwards LER 81~019/03L-0 RUSBELL:L.S. Baltimore Oas & Electric Co. 81/04/10 ORIER, B H, Region 1, Philadelphia. Office of the Director (81/03/01). 1p. 15838:361 24X Fichs.50~317,81/04/10,8210280305

- 8210280313 LER 81-019/03L-0 on 810311.experienced feilure of one containment hydrogen enalyzer (0-AE-6519) Caused by defective analyzer (0-iphi 81A-1A1E) zero adjustment potentioneter. Analyzer replaced LEMBERLICH, R L RIZZO, P O Baltimore Oas & Electric Co 81/04/10 Region 1, Philadelphis. Office of the Director (31/03/01) ip 15838 362 24X Fiche 50-317,81/04/10,8210280305
- 210280203 Forwards LER 81-023/03L-0
 RUSSELL.L B Baittmore Gas & Electric Co 81/04/16 CRIER, B H
 Region 1. Philadelphia. Office ad the Director (81/03/01) 19
 15837 290 24X Fichs 50-317.81/04/16.8210280203
- -8210280205 LER 81-023/03L-0 on 810317, ventilation exhaust damper in cabla spreading room did not what Coused by reversal of Units 1 & 2 control circuits Control & Indication circuits reworked HEIBEL, R B Baltimore Cas & Electric Co 81/04/16 Region 1, Philadelphia, Office of the Director [81/03/01) ip 15837 291 24% Fiche 50-317, 81/04/16, 8210280203
- 210280263 Forwards LER 81~021/03L-0 RUSSELL-L B Baltimore Cas & Electric Co. 81/04/16 ORIER, B H Region 1, Philadelphis Office of the Director (81/03/01) 1p 15837 307 24X Fiche: 50-317, 81/04/16, 8210280263
- -8210280267 LER 61-021/03L-0 on 810320.w/coolant charging pump 12 inoperable due to sticking discharge railef valve.pump 13 tekan out of svc for repair Caused by loss of nitragen pump 13 Valve rapaired & desurger charged MENDERLICH, R L . HUSEN/D E Baltimare Ces & Electric Co 81704/16 Region 1. Philadelphia. Office of the Director (81/03/01) 2pp. 15837 308 24X Fichs 50-317.61/04/16.
- 210280296 Forwards LER 81-020/03L-0 RUSSELL, L 8 Baltimore Cas & Electric Co 81/04/16 ORIER, S. H Region 1. Philadelphia, Office of the Director (81/03/01), Ip 18837 277 24X Fiche 50-317.8L/04/16.8210280296
- -8210280301 LER 81-020/03L-0 on 810320 containment normal sump drain, i-MOV-5463, exceeded max closing time of 13-s Caused by valve operator open limit switch out of adjustment Switch adjusted.

 DAVIS, S. K., RIZZO, P. O. Baltimore Cas & Electric Co. 81/04/16
 Region i, Philedelphia, Office of the Director (81/03/01). ip 15837 280 24% Fiche 30-317.81/04/16.8210280296
- 8210280249 Forwards LER 81-022/03L-0 RUSSELL.L. B Beltimore Oas & Electric Co 81/04/23 ORIER. B H Region 1, Philadelphia, Office of the Director (81/03/01). ip 19897. 051 24% Fiche. 50-317. 81/04/23. 8210280249
- --B210260255 LER B1-022/03L-O on B10324.ESF actuation sys degraded voltage relay found inoperable. Caused by bind in relay output contacts Contact lever straightened & spring tension increased to hold posttioned lever & Baltimore Gas & Electric Co. B1/04/23. Region i, Philadelphia, Office of the Director (81/03/01). 2pp. 15837-052 24X Fiche 50-317, 81/04/23, 8210280249
- 8210270279 Forward: LER 81-024/03L-0 RUSBELL,L.B Baltimore Gas & Electric Co. 81/05/01, GRIER.B.H Region 1. Philadeiphia. Office of the Director (81/03/01) 1p 15828,285. 24X Fiche:50-317.81/05/01,8210270279
- --B210270280 LER 81-024/03L-0 on 810404.during routine shutdown.MRIV 12 closing time exceeded Tech Spacs Caused by contamination of valve actuation sys hydraulic fluid resulting in aticking check valves Finer filters will be used.

 DAVIS, S.M. MRIR.P.J. Baltimore Gas & Electric Co. 81/05/01 Region i. Philadelphia. Office of the Director (81/03/01). ip 15828-286. 24X Fiche 50-317,81/05/01,8210270279
- 8210280318 Forwards updeted LER 81-021/03L-1 RUBSELL,L B Baltimore Cas & Electric Co 61/05/12. ORIER, B. H Region 1, Philadelphia, Office of the Director (81/03/01) 1p 18638; 398 24X Fiche: 50-317, 81/05/12, 8210280318
- --8210280332 Updated LER 81-021/03L-1:on 810320, discharge relief valve for coolant charging pump 12 lifted & stuck open during testing following mainto-rendering second pump inoperable. Caused by pump discharge desurger losing mitrogen precharge # Baltimore Gas & Electric Co. 81/05/12. Region 1. Philadelphis. Office of the Director (81/03/01). 2pp. 15838.357. 24X Fiche 50-917.81/05/12.8210280318
- 8210270266 Forwards LER 81-032/03L-0 RUBSELLL B. Baitimore Cas & Electric Co. 81/05/20. ORIER, B. H. Region I. Phaledelphia, Office of the Director (81/03/01) 1p. 13827:043. 24% Fiche: 50-317.81/05/20, 8210270266.

- --B210270249 LER B1-032/03L-0 on B10420, reactor protective sys charmal highpower thermal margin/low pressure & exial shape index trip units bypessed Caused by need to replace transmitter j-TT-112D which drifted high LAGIENBERJ S. RIZZO.0 Beltimore Cas & Electric Co. 81/05/2v. Region 1. Philadelphia. Office of the Director (B1/03/01) 1p. 15829 044 24X Fiche 50-317, 81/05/20, 8210270266
- 8210270274 Forwards LER 81-033/04T-0 RUSSELL.L B Baittmore Oat & Electric Co 81/05/20 QRIER, & H Region 1, Philedelphia, Office of the Director (81/03/01) ip 15823-001 24x Fiche 50-317,81/05/20,8210270274
- --8210270275 LER 81-033/04T-0 on 810506, during normal operation, cuts. operator discovered waste neutralizing Tenk 12 drain valve leating Caused by small amounts of particulate matter ladged between valve seat & wedge Valve flushed & closed w Baltimore Gas & Electric Co 81/05/20 Region I, Philadelphia, Office of the Director (81/03/01) 2pp 15823 CC: 24% Fiche 50-317,81/05/20,8210270274
- 8210270252 Forwards LER 81-030/03L-0 RUSEELL, L. B Baltimore Cas & Electric Co 81/05/22 GRIER B H Region 1, Philadelphia Office of the Director (81/03/01) ip 15827 231 24X Fiche 50-317,81/05/22,8210270252
- --8210270257 LER 81-030/03L-0 on 810424 reactor protection sys (hard containment pressure trip unit & ESF actuation sys channel ID containment pressure sensor placed out of svc to replace E/E convertor Isolator failure might be due to mod work e Baitimore Cas & Electric Co 81/05/22 Region 1, Philadelphia, Dffice of the Director (81/03/01) ip 15829 70 24% Fishe 50-317,81/05/22.8210270252
- 8210270276 Forwards LER 81-031/017-0 Detailed event enalysis and RUSSELL, L B Baltimore Oas & Electric Co 81/05/22 QRIER B H Region 1, Philadelphia, Office of the Director (81/03/01) 2;p 15828 282 24X Fiche 50-317,61/05/22.8210270276
- --B210270278 LER 81-031/017-0 on 810518.both euxiliary bldg (0-ft elevation firs hots stations isolated w/o water supply. Causad by instructional error & operator unfamiliarity w/isolation valves Personnel counseled.

 # Baitimore Oas & Electric Co 81/05/22 Region 1. Philadelphis. Office of the Director (81/03/01) ip [5828 & 24% Fichs 50-817.81/05/22.8210270276
- 8210270272 Forwards LER 81-031/03L-0 RUSSELL.L B Baltimore Oas & Electric Co 81/06/01 CREER, 2 H Region 1, Philadelphie, Office of the Director (81/03/01) 1, 15828-280 24X Fiche 30-017, 81/06/01, 8210270272
- ~-8210270273 LER 81-031/03L-0 on 810508 during attempt to gut estimated first all attempt to gut estimated first all attempts of the second first attempts of the seco
- 8210270244 Forwards LER 81-035/03L-0 Detailed event analysis end RUBBELL, L B Daltimore Oas & Electric Co Bi/Ob/O5 GRIER, 9 R Region 1. Philadelphie. Office of the Director (81/03/01) 2); 15822 344. 24X Fichs 50-317,81/06/05.8210270244
- --8210270248 LER 81-035/03L-0 on 810506; one cwll of 125-volt it venta chase battery 12 found below Tack Epec min Cause unknown Cell disconnected & will be replaced 4 Battimore Cas & Electric Co. 81/06/05 Region 1, Philadelphia, Office of the Director (81/03/01) 19 15922 541 24X Fiche: 50-317,81/06/05,8210270244.
- 8210080017 "Rept on Calvert Cliffs Unit ! Loss of Eve Hair on 80012 IMBRO, E. V Director's Office. 81/12/31 40pp 15669:007 (4) Fiche, 50-317, 81/12/31, 8210080017
- 8210040142 Forwards LER 82~051/09L-0 RUBSELL,L B Baltimore Oas & Electric Co. 82/07/24 EAYESELT Region 1. Office of Director 1p 15583 085, 24X Fichs. 50~317: 82/09/24 8210040142.
- --B210040144 LER B2-051/09L-0. on B20827.plant air header isolatinimi inside containment i-PA-1040. found open. Caused by valve being inadvertently left open while securing plant air to containment on B20822 Standing instruction issued LA01EMBKI. J B. Baltimore Qas & Electric Co B2/09/24 Ripp in Office of Director. 2pp 15583-086. 24% Fichs 50-317. B2/09/24, B210040142.

- ©210060395 Forwards LER 82-053/03X-1 & corrected Prompt Rept RO 82-53
 Repts appropriate for Unit 1 only
 FUSSELLL B Baltimore Oas & Electric Co 82/09/27 HAYNES, R C
 Region 1. Office of Director 1p 15615 347 24X
 Fiche 50-317. 82/09/27, 8210060385
- --8210050370 LER 82-053/03.-i on 820910.hydrogen analyser 0-AE-6519 adjusted out of callbr during initial training exercise, rendering unit inoperable Caused by erroneous adjustment atep in chemistry procedure Procedure revised BILLS.J M Baltimore Gas & Electric Co 82/09/27 Region 1, Office of Director ip 15615 348 24X Fiche 50-317,82/09/27,82/09/28,
- --8210060394 Corrected RO 82-53 on 620910, during Mode i operation, hydrogen analyzer unintentionally adjusted out of calibr, rendering unit inoperable instrument recalibr & returned to eve Rept applicable to Unit i only RUSSELL. B Baltimore Oas & Electric Co 82/09/13 HAYNES,R C Region 1. Office of Director ip 15615 349 24% Fiche 50-317.82/09/27.8210060385
- S210130461 Forwards LER 82-096/03L-0 RUSSELL, E Baltimore Qas & Electric Co B2/09/30 HAYNES, R C Region 1. Office of Director ip 15682 138 24X Fiche 50-317, 82/09/30, 8210130461
- --8210130465 LER 82-036/03L-0 on 820707, containment particulate & gaseous RMS sample pump tripped & would not restart Caused by fasione of shaft coupling due to excessive wear created by corrosion of pump vanes Coupling replaced LAGIENSKI, J S. LUDWIO, P. G. Baltimore Qas & Electric Co. 82/07/30 Region 1. Office of Director ip 15682 139 24X Fiche 50-317,82/09/30.8210130461
- 8210130543 Forwards updated LER 82-023/01X-1 RUSSELL:L B Baltimore Oas & Electric Co 82/09/30 HAYNES:R C Region i. Office of Director 1p 15682 279 24X Fich* 50-317.82/09/30.8210130543
- --8210130558 Updated LER 82-023/01X-1 on 820514.unplanned dilution of RCB in excess of 0.5% delta K/K experienced Caused by perforated six tubes in steam generator il & 1 tube in steam generator 12 Tube support plate rim cut HENDERLICK, R. L. JENNINGS.R T Baltimore Gas & Electric Co 82/09/30 Region 1. Office of Director App 15682 280 24X Fishe 50-317.82/09/30.8210130543
- 821013056B Forwards LER 82-054/03L-0 RUSSELL.L B Balthore Qas & Electric Co 82/09/30 HAYNES,R C Region 1. Office of Director ip 15679 114. 24X Fitch 50-317,82/09/30,8210130368
- -- G210130576 LER 82-054/03L-0 on 820831. [2 auxillary feedwater pump governor linkage vibrated loose, rendering pump inoperable Caused by loose nut connecting governor lever to connecting rod backed off pin causing pin to come out Pin reinserted JUNGE. M A. L-MEUREUX.R W Balthmore Cas & Electric Co 82/09/30 Region 1. Office of Director 1p 15679 115 24X Fiche 50-317,82/09/30,8210130568
- 8210190290 Forwards updated LER 80-041/01X-1 RUSSELL.L B Baltlmore Oas & Electric Co 82/10/06, HAYNES:R C Region 1. Office of Director ip 13742 172 24X Fichs 50-317,82/10/06.8210190290
- -- B210190296 Updated LER 80-041/01X-1 on 800821,5 mlnutes after svc, water head tanks went from normal operating level to full isophase bus duct cooling low flow alarm received Caused by air compressor failure due to cracked after cooler tubes DAVIS, 8 M. HUSEBY, D.E. Baltimore Gas & Electric Co. 82/10/05 Region 1. 0ffice of Director 2pp 15742 173 24X Fiche 50-317,82/10/06,8210190290
- B210190730 RO on B20B27, oyster samples showed detectable levels of concentration of Ag-liom Caused by natural tendency of cysters to concentrate environ silver Radioactive releases for first half of 1982 within allowable limits.
 FUHRKAN, G. R. Baltimore Oas & Electric Co 82/10/11 HAYNES, R C Region 1. Office of Director 2pp 15736 270 24X
 Fiche 50-317, 82/10/11, 8210190730

- --8210250160 LER 82-052/03L-0 on 820913 & 20. emergancy diesel generator li failed to achieve required rpm within 10-s Caused by loose connector on speed switch 0-88-4848 Connector tightened & lock-wired PAVIS:08 S. BASSOLF Baltimore Gas & Electric Co 82/10/13 Region 1, Office of Director 2pp 15788 231 24% Fiche 50-317:82/10/13.8210250154
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8210180039 Forwards fee for 820830 Class III license amend request for relief from inservice insp program requirements FABRIZIO.R F Baltimore Oas & Electric Co 82/10/13 MILLER, W O License Fee Management Branch ip 15720 020 24% Fichs 50-318, 82/10/13, 8210180039.
- F Security, medical, emergency & fire protection plans
- 6203050387 Forwards IE Insp Repts 50-317/62-02 & 50-318/62-02 on 620106-0202 & notice of violation.

 87AR0STECKI.R Division of Project & Resident Programs 82/02/16 LUNDVALL.A.E Baitimore Cas & Electric Co 2pp 12134 298. 24X Fiche 50-317, 82/02/16.8203050387
- --82i0190714 IE lnsp Repts 50-317/82-02 & 50-318/82-02 on 820104-0202 Noncompliance noted failure to adequately control special processes Associated w/repair of saltuater giping & failure to properly neutralize regenerative waste ARCHITZEL.R & Division of Project & Resident Programs 82/02/12 lipp 24% Fiche 50-317,82/02/16.8203050387
- 8210210544 Releases public version of revised emergency response plan implementing procedures FELTON, J M Division of Rules and Records 82/09/23 Document Management Branch 1p 15782 330 24X Fiche 50-317,82/09/23,8210210544
- --8210210546 Forwards public version of revised emergency response plan implementing procedures, including Procedures EPIP 5 5 researcises, test & drills & EPIP App B 2 re maps & charts # Baltimore Oas & Electric Co 82/09/15. CLARK,8 A Operating Reactors Branch 3 ip 18782 331 24X Fiche: SO-317,62/09/23,621020534
- --8210210551 Public version of revised emergency response plan implementing procedures including Procedures EPIP 5 5 reexercises test & drills & EPIP App B 2 re maps & charts List of effective pages encl.

 # Baltimore Cae & Electric Co 82/09/15 ROPP 15782 332 24x Fiche 50-317, 82/09/23, 8210210544
- 8210120134 Forwards third suppl to 790914 fire protection safety evaluation, resolving Item 3 2 1, "Fire Hazards Analysis "
 Ninety-day period to inform of installation schedule for source range flux monitoring instrumentation acceptable CLARK, R. A. Operating Reactors Branch 3 82/09/27 LUNDVALL, A. E Baltimore Oas & Electric Co ip 15692.157 24X
 Fiche 50-317, 82/09/27, 8210120134
- --8210120139 Bafety evaluation concluding that proposed fire protection design meets requirements of App R to 10CFR50, Items III O.3 & III.L reseafe shutdown in event of fire FIRAVANTE.M., HARRISON, O. JAFFE.D Querating Reactors Branch 1. 82/09/27 9pp 15692-159 24X Fiche 50-317,82/09/27,8210120134.
- 8210180423 Application for amend to Licenses DPR-53 & DPR-69 consisting of Revision 10 to security plan, allowing devitatization of vital areas during cold outages Plan withheld (ref 100FR73 21)

 BOHMAKER, N J Baltimore Gas & Electric Co. 82/10/07 CLARK, R. A. Operating Reactors Branch 3 3pp. 15704.021 24X Fiche 50-317, 82/10/07, 82/0150423.
- 8210180005 Submits update of util progress in closing TNI Action Items I C.1.II F 1 & III.A.1 2 LUNDVALLA E. Baltimors Cas & Electric Co 82/10/12. CLARK.R.A. Operating Reactors Branch 3 3pp 13720.028 24X Fiche.50-317,82/10/12,8210160005
- P Operating license stage documents & correspondence
- 9210010008 Responds to FDIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON J M Division of Rules and Records 82/06/28 UDELL.R.A. Critical Mass Energy Project 15pp. 15727 005. 24X Fiche: 50-000, 82/06/28, 8210010008

- --8204290048 Recommends prompt attention be given to problem of reactor coolant pump closure stud corrosion datected at facilities Response by 820415 requested EISENHUI.D Q Division of Licensing 82/03/24 HAMAUER.8 H Division of Systems Integration (post 811005) 3pp 66035 222 24X Fiche 50-000.82/06/28.8210010008
- 8210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld tref FOIA Exemption 5 | FELTON, J. H. Division of Rules and Hacards 82/07/12. UDELL, R A Critical Mass Energy Project 9pp 15665 027 24% Fiche 50-000, 82/07/12. 8210080015
- --B210080064 Trip rept of 820207 visit to NRR in Bethasda.MD & B20208-10 sits visit re installation of 10-inch automatic isolation valve in main feeduater sys Bpec 6750-K-253 for nuclear carbon steel geterglobe & check valves & related info entl BEARDEN.R 9 E0809. Inc 82/03/22 47pp 15665 192 24X Fiche-50-000.82/07/12.8210080015
- 8210070106 Forwards Amends 75 % 55 to Licensee DPR-53 & DPR-59, taspactively, safety evaluation & notite of issuance & availability Amends correct typographical errore reinservice insp & valva tasting JAFFE, D H Operating Reactors Branch 3 82/09/20 LUNDVALL.A E Baltimore Oas & Elactric Co 3pp 15645.006 24X Fiche: 50-317, 82/09/20, 8210070106
- --B210070117 Amends 75 & 56 to Licenese DPR-53 & DPR-69, raspectively, correcting typographical errors re inservice insp & valve tasting & allowing start up of reactors w/inaparable but isolated power operated relief valves CLARK.R A. Operating Reactors Branch 3 82/09/20 34pp 15645 009 24X Ficha 30-017.82/09/20.8210070106
- ~~8210070130 Notice of issuance & availability of Amends 75 & 56 to Licenses DPR-53 & DPR-69, respectively CLARK,R A Operating Reactors Branch 3 82/09/20 2pp 15645 047 24% Fichs 50-317, 82/09/20, 8210070106,
- 8210290412 Forwards Amends 77 & 58 to Licenses DPR-83 & DPR-49, respectively, safety evaluation & notice of issuance & availability, Amends ravise Tech Bpec Table 3 7-4 which lists snubbers that require periodic insp & tasting JAFFE, D H Operating Reactors Brench 3 82/09/23 LYNDVALL: A E Battimore Oas & Electric Co 3pp. 15863, 273 24x Fichs 50-317, 82/09/23, 8210290412
- --8210290428 Amands 77 & 58 to Licenses DPR-58 & DPR-69, respectively, revising Tech Spec Table 3 7-4 which provides lists of safety-related hydraulic shock suppressore (snubbers) which require periodic insp & tasting CLARK, R A Operating Reactors Branch 3, 82/09/23 26pp 19863:276 24X Piche, 50-317, 82/09/23,8210290412
- --8210270437 Safety avaluation supporting Amends 77 & 58 to Licanses DPR-53 & DPR-69, respectively • Offics of Nuclear Reactor Regulation, Director, 82/09/23 Spp 1586-302 24% Fiche 50-317.82/09/23.8210290412.
- --8210290444 Notice of issuance & availability of Amenda 77 & 58 to Licenses DPR-58 & DPR-69; respectively CLARK, R A. Operating Reactors Branch Q. 82/09/23 2pp 15863,305, 24X Fiche 50-317,82/09/23,8210270412
- 8210130338 Application to amend Licenses DPR-53 k DPR-69, revising Tech Space re pressurizer imiting condition for operation & associated surveillance requirements.

 LUNDVALLIA E. Beltimore Cas & Electric Co 62/09/29. CLARK.R.A Operating Reactors Branch 3, 3pp 15680 269, 24X

 Fiche: 50-917, 82/09/29, 8210130338
- --8210130342 Proposed Tech Space 3 4 4 4 4.4 to RCS pressurizor.

 * Beltimore Gas & Electric Co. 82/09/29. 44pp. 15550.271. 24x
 Fiche: 50-317,82/09/29.8210130338
- BZi0150423 Application for amend to Licenses DPR-53 & DPR-69 consisting of Revision to to security plan, allowing devitalization of vital areas during cold outages, Plan withheld (ref 100FR73, 21)
 BOWMAKER, N. J. Baltinore Gas & Electric Co., BZ/10/07, CLARK, R.A., Operating Reactors Branch 3 Spp. 15704:021 24X
 Fiche: 50-317: BZ/10/07: BZ/10/07.

- 82:0180005 Submits update of util progress in closing TMI Action Items I C i.II.F 1 & III A i 2 LUNDVALL.A E Baltimore Gas & Electric Co 82/i0/12 CLARK.R A Operating Reactors Dranch 3 3pp 15720 028 24X Fiche 50-3i7.82/10/i2.8210180005
- 82i0220378 Application to amend License DPR-69, changing 878 for operation of Cycle 5 at rated power of 2.700 MHt LUNDVALL.A E. Baltimore Gas & Electric Co 82/LO/i5 CLARK.R & Operating Reactore Branch 3 2pp 18760 017 24x Fiche 30-318.92/i0/15.82i0220378
- 821020010B Notification of 821025 meeting w/util in Bathasda, MD to discuss control of heavy loads JAFFE, D H Gperating Reactors Branch 3 82/10/18 CLARK, R A Cperating Reactors Branch 3 2pp 15767 304 24X Fichs 30-317, 82/10/18, 821020010B
- 8210260299 Forwards Cycle 5 reload amend fea LIPPOLD.W J Baltimore Ose & Electric Co 82/10/21 CLARK.R A Operating Reactors Branch 3 lp 15803 211 24X Fiche 30-318, 82/10/21.8210260299
- O Inspection reports, IE Bulletins & correspondence
- 8203050387 Forwards IE Insp Repts 50-317/82-02 & 50-318/82-02 en 820106-0202 & natice of violation STARBSTECKI.R Division of Project & Resident Programs 02/02/16 LUNDVALL, A E Daltimers Oas & Electric Co 2pp 12/34 298 241 Ficha. 50-317, 82/02/16, 8203050387
- --BR10190702 Notice of violation from Insp on 820106-0202 STAROBTECKI.R Division of Project & Resident Programs 87/02/16 2pp 15751 022 24X Fiche 50-317.82/02/16.8203050387
- --8210190714 IE insp Repts 50-317/82-02 & 50-318/82-02 on 920104-0X2
 Noncompliance noted failure to adequately control special
 processes associated w/repair of saltwater piping & failure
 to properly neutralize regenerative wasts
 ARCHITZEL.R E : MCCABE.E C Division of Project & Resident
 Programs 82/02/12 lipp i5751 024 24X Fiche 50-317.82/02/16
 8203050387
- 8210060099 Forwards IE Insp Repts 50-317/82-06 & 50-318/82-06 pn 820315-16 & notice of violation, MARTIN.T.T Division of Engineering & Technical Programs 82/04 LUNDVALL.A.E Baltimore Qas & Electric Co 2pp 15614 345 & Fiche, 50-317.82/09/17.8210060099
- --8210060104 Notice of violation from Insp on 820315-16 * Division of Engineering & Technical Programs 82/09/17 2, 15614 347 24% Fiche 50-317,82/09/17,8210060099
- --8210060127 IE Insp Repte 50-317/82-06 & 50-318/82-06 on 920315-16 Moncompliance noted failure to establish adequate procedures, failure to foilow radiation protection procedures & failure to make necessary radiological surveys PLUMLEE.K E., GREENNAN.E. O Division of Engineering & Technica Programs, 82/09/17 10pp 156/4 349 24X Fiche 50-317.82/03 8210060099
- 8210070106 Forwards Amends 75 & 56 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of lesuance & availability. Amende correct typographical errors reinservice insp & vaive testing.

 JAFFE, D. H. Operating Reactors Branch 3 82/09/20 LUNDVALLAF Baltimore Oas & Electric Co. 3pp. 10645 006 24X Fiche: 50-317.82/09/20.8210070106
- --B210070117 Amends 75 & 36 to Licenses DPR-53 & DPR-69, respectively correcting typographical errors re inservice insp & valve testing & allowing start up of reactors w/inoperable but isolated power operated relief valves CLARK, R A. Operating Reactors Branch 3 B2/09/20 15645:009. 24% Fiche. 50-317, 82/09/20.8210070106
- B2:0150214 Forwards IE Inep Repts 50-317/B2-23 & 50-318/B2-19 an B20B10-0914 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 62/08/27 LUNDVALL.A E. Baltimore Gas & Electric Co 2pp 15705 234 211 Fiche: 50-317, 62/09/27, 8210150214
- --8210150226 Notice of violation from insp on 820810-0914 * Division of Project & Resident Programs. 82/09/27, 29 15705-236 24% Fichs: 50-917, 82/09/27, 8210150214

- --8210150235 IE insp Repts 50-317/82-23 & 50-318/82-19 on 820810-0914 Moncompilance noted radiological event not declared nor appropriate response taken & procedures not properly implemented ARCHITZEL,R E, TRIMBLE,D C., MCCABE,E C Division of Project & Resident Programs 82/09/27 18pp 15705 238 24X Fiche 50-317,82/09/27,8210150214
- B2100A0240 Forwards notice of violation re IE Insp Repts 50-317/B2-07 t 50-318/B2-07 on B20413-0511 Violation A re operation whydrogen analyzers inoperable needs no response Violation B re shadequate review requires full response STARUSTECKI.R Division of Project & Resident Programs B2/09/29 LUMOWALL.A E Baitimore 0as & Electric Co 3pp 15619 322 24X Fichs 50-317.B2/09/29.821006020
- 8210070159 Requests approval for excluding reactor vessel closure studs at facilities,per 1E Builetin 82-02 & Reg Ouide 1 65
 Boiting math complies w/recommended maths
 Lu/IDVALL,A E Baitingue Gas & Electric Co 82/10/01 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 15627 013 24X Fiche 50-317,82/10/01,8210070159
- 8209190233 [E info Notice 80-35, Suppl 1, "Leaking & Disiodged 1-125 Trplant Seeds " Svc list encl COSB.L I Division of Fuel Factilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24x Fiche 50-000,82/10/06,8209190233
- 8210130099 Ack receipt of 820917 ltr informing NRC of steps taken to correct violations noted in 1E insp Repts 50-317/82-20 & 50-318/82-17 MARTIN.T T Division of Engineering & Technical Programs 82/10/06 LUNDVALL.A E Baltimore Oas & Electric Co 1p 19673 104 24X Fiche 50-317.82/10/06.8210130099
- --B210130103 Responds to NRC B20819 itr re violations noted in 1E Insp. Repts 50-317/82-20 & 50-318/82-17 Corrective actions. Operating instruction.AD Procedure 2 & Instruction 302 revised.

 LUIDVALL.A E Baltimore Qas & Electric Co 62/09/17 MARTIN.T T Division of Engineering & Technical Programs 4pp 15673 105 24x Fiche 50-317.82/10/06.8210130099
- G210190797 Ack receipt of B20915 itr informing NRC of steps taken to correct violations mated in IE Insp Repts 50-317/B2-18 & 50-318/B2-14 A STAROSTECKI.R Division of Project & Resident Programs B2/10/12 LUMDVALL.A E Daltimore Oas & Electric Co ip 15736-314. 24X Fiche 30-317.82/10/12.8210190797
- ---0210190B03 Responds to NRC 820B16 itr re violations noted in IE insp Repts 50-317/82-18 & 50-318/82-16 Corrective actions Instruction-112 rovised to ensure essential equipment will not be inadvertently removed from svc FTI-107 also revised. LUNDVALL.A E Baltimore Oas & Electric Co 82/09/15 GTAROSTECKI,R Division of Project & Resident Programs 2pp 15736 315 24X Fiche 50-317, 82/10/12.8210190797
- 62:018039 Forwards for for 820830 Class III license amend request for relief from inservice insp program requirements.
 FABRIZIO,R F Baitimore Gas & Electric Co 62/10/13 MILLER,W O License Fee Anagement Branch ip 15720 020 24X Fiche 50-318,82/10/13,8210180039
- 8)208190238 IE Builstin B2-03, "Stress Corrosion Cracking in Thick-Hail, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants "Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 128 24x Fiche 50-000.82/10/14,8208190238
- R Periodic operating reports & related correspondence
- 821021032B Farwards monthly operating repts for Sept 1982 LOTITO.E M Beltimors Gas & Electric Co 82/10/15 Director's Dffice. Office of Inspection and Enforcement 1p. 15762 003 24X Fiche 50-317, 82/10/15,821021032B
- --B210210457 Monthly operating repts for Bept 1982 L0T1TG.E Baltimore Gas & Electric Co. 82/10/15. 10pp 15762 004 24X Fiche 50-317, 82/10/15, 8210210328
- B. Reportable occurrences, LERs & related correspondence
- E210280194 Forwards LER 81-014/03L-0

 RUSSELL.L B Baltimore Cas & Electric Co 81/04/03 GRIER, B H.

 Region 1, Philadelphia, Office of the Director (81/03/01) ip.

 15837-030 24X Fiche 50-318.81/04/03.8210R80194

- --B210280200 LER 81-014/03L-0 on 810305,4-kV buses 21 & 24 ESF actuation sys degraded voltage relays found out of calibr Cause unknown Trip setpoints readjusted Relays will be tested at increased frequency DAVIS,5 M . R1ZZO,P 0 Baltimore Oas & Electric Co 81/04/03 Region 1. Philadeiphia. Office of the Director (81/03/01) 2pp 15837 031 24X Fichs 50-318,81/04/03,8210280194
- 8210280279 Forwards LER 81-013/03L-0 RUSSELL.L B Baltimore Cas & Electric Co B1/04/03 GRIER, B H Region 1, Philadelphia, Office of the Director (81/03/01) 1p 15837 044 24X Fiche 50-318,81/04/03,8210280279
- --8210280284 LER Bi-013/03L-0 on Bi0304, while installing instrumentation, temporary shunt opened, causing loss of power to low pressure safety injection jump 22 & momentary loss of shutdown cooling flow Caused by opened lead on one end of shunt HENDERLICH, R L RIZZO, P 0 Baitimore Oas & Electric Co Bi/04/03 Region I, Philadelphia, Office of the Dir.ctor (61/03/01) 2pp 15837 045 24X Fiche 50-318,81/04/03, 8210280279
- 8210280191 Forwards LER 81-012/03L-0 RUSSELL,L B Battimore Cas & Electric Co 81/04/08 QRIER, B H Region I, Philadeighia, Office of the Director (81/03/01) 1p 15837 064 24% Fiche 50-318.81/04/08.8210280191
- --8210280195 LER 91-012/03L-0 on 810309, while personnel were exiting containment bldg via normal personnel batch, both doors were open simultaneously Caused by broken cam follower in door operator Maint on clutches incorporated into procedures # Baitimore Gas & Electric Co 81/04/08 Region 1. Philadelphia, Office of the Director (81/03/01) 2pp 15837 065 24X Fiche 50-318,81/04/08,8210280191
- 8210280336 Forwards LER 81-015/03L-10 ROBSCLL,L B Baltimore Cas & Electric Co 81/04/17 ORIER, B H Region 1, Philadeiphia, Office of the Director (81/03/01) 1p 18838 324 24X Fiche 50-318,81/04/17,8210280336
- --8210280341 LER 81-015/03L-0 on 810319, results of routine sample of boric acid storage tank 21 revealed boric acid concentration greater than Tech Spec limit, reducing borated warer sources to one Cause undetermined # Baittmore Oas & Electric Co 81/04/17 Region 1, Philadelphia, Office of the Director (81/03/01) 2pp 15838 325 24X Fichs 50-318.81/04/17,8210280336
- B210270237 Forwards LER 81-022/03L-0 RUSBELL,L B Baltimore Cas & Electric Co 81/05/15 GRIER, B H Region 1, Phitadelphia, Office of the Director (81/03/01) 1p 15828 275 24X Fiche 50-318,81/05/15,8210270237
- --8210270241 LER 81-022/03L-0 on B10419, during power increase, containment gaseous & particulate radioactivity monitoring sys sample failed Caused by broken motor coupling Motor coupling replaced

 Battimore Qas & Electric Co 81/05/15 Region 1.
 Philadelphia, Office of the Director (81/03/01) 2pp 15828 276 24% Fiche 50-318,81/05/15,8210270237
- 8210040216 Forwards LER 82-042/03L-0 RUSBELL,L B Baitimore Gas & Electric Co 82/09/23 HAYNES,R C Region i, Office of Director ip 15586 132 24X Fiche. 80-318, 82/09/23, 8210040216
- --B210040226 LER B2-042/03L-0 on 820824, inner door on normal personnel hatch to containment would not shut completely Caused by broken cam follower to handwheel Inner door repaired Matls upgraded MENDERLICHLR L., WEIR.P J Baltimore Gas & Electric Co. B2/09/23 Region 1, Defice of Director 1p 15586 133 24X Fiche 50-318,82/09/23.8210040216
- 8210040066 Forwards LER 82-041/03L-0 RUSSELL,B Baltimore Gas & Electric Co 82/09/24 HAYNES,R C Region 1, Office of Director 1p 15581 235 24X Fiche: 50-318, 82/09/24, 8210040066
- --8210040069 LER 82-041/03t-0 on 820826, excessive leak rate discovered past containment personnel air lockout & door gasket. Caused by decrease in force holding door shut Door operating mechanism adjusted to increase pressure JUNGE, H. A. Baitimore Cas & Electric Co. 82/09/24 Region 1, Office of Director ip 15581,236, 24X Fiche, 30-318, 82/09/24, 8210040066.
- 8210040211 Forwards LER 82-040/03L-0 RUBSELL,L.B Battimore Cas & Electric Co 82/09/24 HAYNES,R C Region 1. Office of Director 1p 15587.177 24X Fichs.50-318.82/09/24,8210040211

- --8210040219 LER 82-040/03L-0 between 820825 t 26, pressuriter level deviated slightly from program level by more than 5% during normal startup operations Caused by loading of main turning generator. RCB temp suings of 10 degrees not uncommon JUNGE.HA . WEIR.FJ Baltimore Cas b Electric Co 62/09/24 Region 1, Office of Director. ip 15587 178 24X Fiche 50-318, 82/09/24, 8210040211
- 8210190730 RD: on 820827, ogster samples showed detectable levels of concentration of Ag-110m Caused by natural tendency of ogsters to concentrate environ silver Radioactive releases for first half of 1982 within allowable limits FUHRMAN, OR Baltimore Gas & Electric Co 82/10/11 HAYNES, R C Region 1, Office of Director 2pp 15736 270 24X Fiche 50-317, 82/10/11, 9210190730
- 8210250088 Forwards LER 82-044/03L-0 RUSSELL.t. B. Baltimore Gas & Electric Co 82/10/15 HAYNE8.R C Region 1. Office of Director 1p 15787 058 24X Fiche 50-318.82/10/15.9210250088
- --8210250075 LER 82-044/03L-0 on 820915, emergency diesel generator 21 tripped during testing Caused by common low jacket cooling water pressure switch isolation valve left closed following maint Valves opened PAVIS.0 8. BASSOL F Baltimore Oas & Electric Co 82/10/15 Region 1, Office of Director 2pp 15787 059 24X Fiche, 50-318, 82/10/15, 8210250088
- 8210280134 Forwards LER 82-045/03L-0 RUSGELL.L B Battimore Cas & Electric Co. 82/10/20 HAYNES,R C Region 1. Office of Director ip 15837 239 24X Fiche 30-316, 82/10/20, 8210280134.
- --8210280141 LER 82-044/03L-O on 820920, reactor protective sys channel C trip unit for high pressurizer gressure tripped due to failed low trip bistable power supply, Model DRA15-750/15-7508 Cause unknown Power supply replaced LA0IENSKI, J B. RAYNOR, J W Battimore Cas & Electric Co B2/10/20 Region i. Office of Director 1p 15837 240 24X Fiche 50-318,82/10/20,8210280134
- DOCKET 80-320 THREE NILE ISLAND NUCLEAR STATION, UNIT 2 F Security, medical, amergency & fire protection plans
- 8210050491 Forwards exemption from annual emergency plan exercise requirements of 100FR50, App E re level of govt participation 870LZ, J F Operating Reactors Branch 4 82/09/14 HUKILL, H B General Public Utilities OPU Service Corp. 7pp i5626 291 24 Fiche 30-289, 82/09/14,8210050491.
- --B210050495 Exemption from annual amergency plan requirements re level of govt participation in exercises EIGENHUT.D O. Division of Licensing B2/09/14. General Public Utilities QPU Service Corp app 15626 298 24X Fiche: 50-289, 82/09/14, 8210050491
- 8210190180 Notification of contract execution "TNI-2 Fire Protection Evaluation: "awarded to Rolf-Jensen & Associates, Inc. FLEENOR. C. Technical Assistance Contracts Branch FIN B-8632 82/09/29 VOLUMER.R H. NOLAN. F. Division of Engineering. Ip 13738:118 24X Fiche: 50-320, 82/09/29, 8210190180
- --8210190185 Contract. "TMI-2 Fire Protection Evaluation: " awarded to Rolf Jensen & Associates, Inc. MEBB. W A Rolf Jensen & Associates, Inc. MATTIA.M J. Technical Assistance Contracts Branch. FIN 2-8632 82/09/29. 8pp. 15738; 119. 24X Fiche. 50-320, 82/09/29, 8210190180

Q Adjudicatory correspondence

- 6210040021 Notice of withdrawal of appsarance in proceeding. LEWIS,8 H Hearing Brench 2 82/09/29. 2pp 15581:260. 24x Fiche 50-320,82/09/29,8210040021.
- B2i0150486 Motion to modify Tech Space formally to conform w/B20924 amend of NRR Director 800211 order-allowing separation of Fuel handling bldg air cleanup exhaust sys & auxiliary bldg air cleanup exhaust sys & auxiliary bldg air cleanup exhaust sys Tech Bpaces, M/Certificate of Svc. MILCOVE: N N Hearing Brench 2 82/10/14. Atomic Safety and Licensing Board Panel. 170p 15714 193 24X Fiche. 50-320, 82/10/14, 8210150486

- 8210210266 Response to NRC 821014 motion to conform proposed Tech S; attached to NRR 800211 order w/820924 amend to order Licensee does not oppose motion, assuming formal amend awaifs outcome of prospective hearing W/Certificate of Svc RIDONAY, D A Metropolitan Edison Co RIDONAY, D A Bhaw. Pittare Potts & Troubridge 82/10/18 Atomic Safety and Licensing Bear Panel 5pp. 15766 232 24X Fiche 50-320, 82/10/18 8210210286
- B210210173 Motion to extend period of time for Commission to review ALAB-692 Certificate of Svc encl TROWBRIDGE.0 F Metropolitan Edison Co TROWBRIDGE.0 F Shaw. Pittman. Potts & Troubridge B2/10/20 Commissioners 4pg 15766
- --8210210177 Request for extension to 821115 to file motion for reconsideration & mod of 820715 ALAB-672 Certificate of 5xc encl
 TROUBRIDGE, O F Hetropolitan Edison Co
 Pittnan, Potts & Troubridge 82/10/20
 Licensing Appeal Panel 5pp 15766 064
 Fiche 50-320, 82/10/20, 8210210173
- B210220313 Order granting util B20714 request for leave to file petition for reconsideration of portion of ALAB-492. sub; to Commission granting util B20714 request to extend period for sua sponte review TOMPXING.B A Atomic Safety and Licensing Appeal Panel 02/10/29 Hetropolitan Edison Co 2pp 15776 177 24X Fichs 50-320, B2/10/20.8210220313
- 8210270176 Memorandum & order granting NRC motion to conform propose.

 Tech Specs to NRR Director 820924 order amending 800211

 order, separating fuel handling bidg air cleaning exhaust sys
 & auxiliary bidg air cleanup exhaust sys Tech Bees

 WOLF, J F, PARIS, O H, SHON, F J Atomic Safety and Licensing Boar,
 Panel 82/10/25 Office of the Executive Legal Director 3pp
 15823 011 24X Fiche 50-020, 82/10/25, 8210270176
- 8210270170 Order extending time until 821112 for Commission to act to review ALAB-692 CHILK, S. J. Office of the Secretary of the Commission 82/10/24 Commissioners ip 15822 348 24X Fiche 50-320, 82/10/26, 82/10/270170
- J Insurance & indemnity information
- 8210150147 Forwards Endorsements 33 & 54 to MAELU Policy MF-73 & Endorsements 61 & 62 to NELIA Policy NF-220 ORRETY.H F General Public Utilities OPU Service Corp 82/10/u1 SALTZMAN.J Antitrust & Economic analysis Branch (Utility Finence) 3pp 13697 339 24% Fiche 30-289.82/10/07,8210150147
- P Operating license stage documents & correspondence
- 8210050466 Requests installation of speakerphone at TMI info ofc KERR, V S Telecommunications Branch 80/01/30 ACCARDO, V 3:11: Pennsylvenia ip 15625-236 24X Fiche 50-320-80/01/30.82105648
- 8210080061 Comments on info gleaned from preoperational testing light; entries of 770905-12 Installation of reactimeter in all plants prior to startup testing suggested Logbook entries enci DRNGTEIN, H L Director's Office 81/07/16 Director's Office 25pp 15667 326 24% Fiche 50-320.81/07/16.8210080061
- 8210120406 "Recently Evaluated Preoperational Test Precursor of IMP-4 Accident," for presentation at ANS 1982 Power Div Topical Meeting in Charleston, 8C, 820328-31 ORNOTEIN, H. L. Director's Office. 82/03/31 24pp. 15671
- 821001000B Responds to FOIA request for 19 categories of documents nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J K Division of Rules and Records 82/06/28 UDELL.R & Critical Mass Energy Project 15pp 15727.005. 24X FIChe 30-000, 82/06/28, 8210010008.
- 8210060473 Requests submittal of implementation schedules for completing removal of EPICOR-II prefilter & submarged demineralizer sys ion exchange wastes, for defueling reactor core & for removal of reactor coolant wastes DENTON. H. R. Office of Nuclear Reactor Regulation, Director 82/07/08 ARNOLD, R. C. General Public Utilities GPU Service (17) 3pp. 15536-220 24X Fiche 50-320,82/09/08,8210060473.
- 82:0050537 Speech entitied: "Regulatory Aspects of TMI Cleans; "LO,R, BELLAHY,R TMI Program Office, 82/09/20, 6pp. 15537 144 24X Fiche: 50-320, 82/09/20, 8210050537

- 8210260535 Forwards amend of order, safety evaluation & proposed Tech Specs Amend changes Tech Specs to allow for operations to prepare for recovery mode activities SI(OPER, B. J. THI Program Office 82/09/24 KANGA, B.K. General Public Utilities - GPU Service Corp. 2pp 15830 333 24X Fische 50-220, 82/09/24, 8210260535
- ~~ 2210260538 Amend of order changing Tech Specs to define which equipment would provide adequate ventilation capability for fuel handling & auxiliary bldps
 CASELE Q Office of Nuclear Reactor Regulation, Director 82/09/24 General Public Utilities OPU Service Corp 4pp 85830 335 24% Fiche 50-320,82/09/24,8210260535
- ~-B210260347 Safety evaluation supporting Tech Specs change defining equipment to provide adequate ventilation capability for fuel handling & auxiliary bldgs

 # Office of Nuclear Reactor Regulation, Director 82/09/24 5pp 15830 339 24X Fiche 50-320.82/09/24,8210260535
- ~~B210260552 Proposed Tech Spec changes re fuel handling auxiliary bldg air ventilation ileamup sys → Office of Nuclear Reactor Regulation, Director 82/09/24 3pp 15930 344 24X Fiche 50-320,82/09/24.8210260535
- 8210270328 Informs that proposal to conduct extended decontamination effort acceptable Procedures used to implement decontamination effort subj to approval Rationale for approval & discussion of evaluation encl SNYDER.8 J TMI Program Office 82/09/24 KANOA.8 K General Public Utilities GPV Bervice Corp 7pp i5834 351 24X Fiche 50-320.82/09/24.8210270328
- S210190052 Requests attendance at 820928 meeting to discuss actions to whitain actual RCS gas space info & future plans for establishing inert gas atmosphere in drained RCS portions which need not be vented BARRETT.L H TMI Program Office 82/09/27 KANGA, B K General Public Utilities GPU Service Corp 2pp 1576i 044 24X Fighe 50-320, 82/09/27, 8210190052
- 8230040200 Informs of newly established dairy farm yielding calculated dose or dose commitment greater than several farms currently monitored by land use census Farm added to radiological monitoring program KANGA.8 & General Public Utilities OPU Service Corp 82/09/28. SNYDER.8 J TMI Program Office ip 15583 163 24% Fiche 50-320. 82/09/28. 8210040200
- 823G070220 Advises of installation of pressure relief device for longterm storage of spent submerged demineralizer sys liner went hoses KANGA.3 K General Public Utilities - OPU Service Corp 82/10/04 BARRETT.L H TMI Program Office 2pp 15637 161 24X Fiche 50-320.82/10/04:8210070220
- B230070355 Notifies of planned operations which will cause containment waste water inventory to exceed 50,000 gallons, in response to NRC 820420 itr KANGA, BK Oeneral Public Utilities GPU Service Corp 82/10/04 BARREIT, L N THI Program Office ip 15634 035 24X Fiche 50-320, 82/10/04,8210070365
- B210:320583 Revision 1 to Recovery Operations Plan Change Request 1B. Revision will permit opening of both equipment hatch air took doors in order to allow excessive length tools & equipment to be transported into containment KANVAN 8 K General Public Utilities CPU Service Corp 82/10/06 HARRETTL H TMI Program Office 12pp 15679 063 24X Fiche 50-320, 82/10/06, 8210130583
- --B2101305B4 Tech Spec 4 6 i re primary containment integrity General Public Utilities - GPU Service Corp 82/10/06. 2pp 15879 075 24% Fiche 50-230. 82/10/06.B2101305B3
- B210830279 Provides info on schedules for removal of EPICOR II
 prefilters, submerged demineralizer sys ion exchange wastes &
 reactor coolent purification sys ion exchange wastes, per NRC
 B20908 ltr & util 82092i response Syc list encl
 ARNOLD.R C. Ceneral Public Utilities OPU Service Corp 82/10/08
 DENTON.H R Office of Nuriser Reactor Regulation, Director 5pp
 13682 174 24X Fiche 50-320,82/10/08,8210130279
- #210150043 Provides results of sempling program to determine RC8 hydrogen evolution in response to 820927 Itr Based on prefiminary evaluation combustible gas mixture will not occur in loop high points in foreseeable future KANGA: B K Deneral Public Utilities GPU Service Corp 82/10/08 BARRETT, L H THI Program Office 3pp 15701 129 24X piche: 50-320, 82/10/08, 8210150043

- 8210150085 Forwards polar crans functional description & response to Item 4 of 820401 itr re crans maint Cherklist of specific items for crans maint to be evaluated MANOA.B K General Public Utilities GPU Service Corp 82/10/12 BARRETT,L H THI Program Office. 27pp 15701 214 24% Fiche 50~320,82/10/12-821015085
- 8210190570 Forwards Revision 0 to "Safety Evaluation for Submerged Demineralizer Sys Liner Recombiner & Vacuum Outgassing Sys "
 Sys satisfactorily tested by Rockwell Hanford Operations KANGA, I K General Public Utilities GPU Service Corp 82/10/13 BARRETTL H TMI Program Office 2pp 15736 103 24X Fiche 50-320, 82/10/13, 8210190570
- --8210170577 Revision 0 to "Safety Evaluation for Submerged Deminaralizer Sys Liner Recombiner & Vacuum Outgassing Sys " « General Public Utilities - OPU Service Corp 82/10/31 7pp 15736 103 24X Fiche 50-320, 82/10/13,8210190570
- 8210200012 Advises of status of EPICOR prefilter liner inserting Analyses indicate that hydrogen generator rate can be adequately determined for nonairtight liners by concentration of hydrogen at initial sampling & leak rate KANOA-B K General Fublic Utilities GPU Service Corp 82/10/14 BARRETT, L H TMI Program Office 2pp 15752 328 24X Fiche 50-320, 82/10/14,8210200012
- O Inspection reports, IE Bulletins & correspondence
- 8210260225 Ack receipt of 820902 itr in response to violations noted in IE Insp Rept 50-320/82-06 Info not previously available to inspector during insp Recent investigation revealed new facts that could alter item of noncompliance STAROBTECKIR Division of Project & Resident Programs B2/09/28 KANOA-B K General Public Utilities CPU Service Corp. 2pp 15830 349 24% Fiche 50-320,82/09/28.8210240225
- --8210260236 Responds to NRC 820730 ltr re violations noted in IE Insp Rept 50-320/82-06 Apparent violation re broken lid holddown ring on drum happened during transport Util not responsible KANGALB K General Public Utilities - QPU Service Corp 82/09/02 HAYNEB,R C Region i, Office of Director 4pp 15830 351 24X Fiche 50-320,82/09/28,8210260225.
- B20B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Disladged I-128 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards B2/10/06 Consolidated Edison Co. of New York 66pp. 15761 230 24% Fiche 50-000, B2/10/06, B208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-WallrLarge-Diameter.Stainless Steel, Recirculation SysPiping at BWR Plants "Syc list encl DEYOUND.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York i15pp 15810 125 24X Fiche: 50-000, 82/10/14, 8208190238
- R. Periodic operating reports & related correspondence
- 82:0070063 Forwards TMI Program Ofc weekly status rept for wk of 820829-0903

 BARRETTI.H TMI Program Office. 82/09/03 DENTON,H R. Office of Nuclear Reactor Regulation, Director SNYDER,D.J TMI Program Office 8pp. 15649 186 24X Fiche: 50-320,82/09/03.8210070063
- 8210070190 Forwards THI Program Ofc weekly status rept for wk of 820904-11. BARRETIL H THI Program Office, 82/07/13 DENTON,H.R. Office of Nuclear Reactor Regulation, Director SNYDER,B.J THI Program Office opp. 15644-359, 24X Fiche.50-320,82/07/13,8210070150
- B210190327 Forwards TMI Program Ofc weekly status rept for wk of 820912-18.

 BARRETT, L. H TMI Program Office 82/09/20, DENTUN, H. R. Office of Nuclear Reactor Regulation, Director 7pp 15761:230 24% Fiche 50-320, 82/09/20, 8210190127
- 82:01900:2 Forwards TMI Program Ofc weekly status rept for wk of 82:09:9-25. BARRETT, L. H. TMI Program Office 82/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director 7pp. 15760:321 24X Fiche 50-320, 82/09/27, 82:0190012
- B2i0070226 Forwards results of program to detect radioactive water leakage to groundwater at facility. Data includes computer graphs of tritium concentrations, computer tables of samma scan date & first & second querter strontium results KANDA: B K. General Public Utilities QPU Bervice Gorp 82/10/04 BARRETT, L.H TMI Program Office 40pp. 15634:308 24% Fiche: 50-320, 82/10/06; 8210070226.

- S Reportable occurrences, LERs & related correspondence
- 8012290118 Discusses conclusions of engineering evaluation of steam generator gverfill transients at 6-E & Hestinghouse plants
 LANKING, W D Director's Office SO/10/29 MICHELSON, C Director's
 Office Spp 15692 262 24X Fichs 50-000, 60/10/29, 8012290118
- 8210150280 Forwards LER 81-013/01L-0 HOVEY.O K Matropolitan Edison Co 81/06/08 GRIER.B H Region 1. Philadelphia. Office of the Director (81/03/01) 1p 15701 340 24% Fichs 50-320.81/06/08.8210150280
- --B210150289 LER 81-013/01L-0 on 810509, incore thermocouple L11 exhibited erratic behavior Cause undetermined due to condition of incore anothermation Condition monitored to determine long-term effect on safety CHAPLIN.S D. Hetropolitan Edison Co. 81/06/05 Region 1, Philadelphia, Office of the Director (81/03/01) 2pp 15701.341 24% Fiche 50-320,81/06/08.8210150280
- 8210080024 Forwards chronology of 770905-12 events in which steam bubble formed during preoperational testing GRNSTEIN.H L Director's Office 81/07/08 MICHELSON.C Director's Office 9pp. 15669 294 24X Fiche 50-320.81/07/08, 8210080024.
- 6210010008 Responds to FDIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A PELTON. J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24% Fiche 50-000.82/06/28.8210010008
- --8210010161 Discusses patential problem re-sequeyah reactor pressure norrie, supplementing 800222 nemo Undercled Cracks found by use of ultrasonic equipment Addl items of recent origin discussed Related info encl DENTON, H R Office of Nuclear Reactor Regulation, Director 80/02/28 AREARNEJ Commissioners 9pg 15727 178 24X Fiche 50-000, 82/06/28,8210010008
- --B210040374 Forwards LER 80-20/03L & R0 249/80-9 re failure to open auxiliary feedwater valve & failure of fire detection sqs. respectively Add1 attention may be warranted BENDER, M. ACR8 Advisory Committee on Reactor Safeguards 80/05/23 FRALEY, R F ACR8 Advisory Committee on Reactor Safeguards 1p 19727 272 24X Fichs. 50-000, 82/06/28, 8210010008
- --B210050161 Forwards add1 info re events at facility during preoperational testing on 770905-12 Failure of condensate polishers caused resin to clog strainers from closed cooling water pumps
 ORNSTEIN. H. L. Director's Office 81/07/08 MICHELSON. C
 Director's Office 9pp. 15729 346 24% Fiche. 50-000. 62/06/28, 6210010008.
- --8210060460 "Recently Evaluated Preoperational Test Precursor of TM1-2 Accident," presented at ANS 1982 Power Div topical meeting on 820328-31 CRNSTEIN-H L Birector's Office 82/03/28, 24pp 15745 049 24X Fiche 50-000,82/06/28,8210010008.
- 8210070255 PNO-TMI-82-020 on B21005.game poacher apprehended on util property & turned over to state police & Qame Commission.No vital areas threatened Security increased Licensee will issue press release HIEEE. J. BELLAMY, R. Region 1, Office of Director 82/10/06 ip 15564 206 24% Fiche 50-289;82/10/06:8210070255.
- 8210280124 LER 82-008 has been canceled. COLLINS M General Public Utilities - QPU Service Corp. 82/10/19. Region 1, Office of Director. 1p 15837.021, 24X Fiche 30-320, 82/10/19.8210280124
- 8210280127 LER 82-002 has been canceled COLLINS.M General Public Utilities CPU Service Corp. 82/10/19. Region 1. Office of Director. 1p 15837-023 24K Ficae 50-320, 62/10/19, 8210280127.
- DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT & F Security, medical, emergency & fire protection plans
- 6210190013 Releases public version of revised emergency plan implementing procedurs FELTON-J. M Division of Rules and Records 82/09/29 Document Management Branch. 1p 15760.328. 24X Fiche: 50-321, 62/09/29, 8210190013.

- --8210190016 Forwards public version of Revision 4 to Exerging 6 Inplementing Procedure HNP-8026, "High Radiation Area Entrance Control" SORRELL.E C Georgia Power Co 82/09/23 Office of Nucls Reactor Regulation, Director ip 15760 329 24x Fiche 50-321,82/09/29,8210190013
- --8210170017 Public version of Revision 4 to Emergency Plan Repli Procedure HNP-8026. "High Radiation Area Entrance Control " # Oworgia Power Co 82/09/22 12pp 19760 330 24x Fiche 50-321:82/09/29.8210190013
- 8210190042 Releases public version of pages to emergency plan FELTON.J M Division of Rules and Recorde 82/10/01 Decu-Management Branch ip 15761 037 24X Fiche 50-321,82/10/01, 8210190042
- --8210170046 Forwards public version of Pages M-1 & M-2 to sarry plan EDRRELL-E C Georgia Power Co 82/07/22 Office of Nucls Reactor Regulation, Director 1p 15761 038 24X Fiche 50-321.82/10/01.8210170042
- --8210170051 Public version of Pages M-1 & M-2 to emergancy plan * Georgia Power Co 82/03/31 2pp 15761 039 24X Fichs 50-321.82/10/01.8210190042
- 8210080227 Forwards IE Safeguards Insp Repts 50-321/82-31 & 50-366/82-29 on 820920-23 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/10/06 KELLY: R J Georgia Power Co 2pp 13638 057 24X Fiche 50-321.82/10/06.8210080227
- --8210080228 IE Safeguards Insp Repts 50-321/82-31 & 50-366/82-29 820920-23 No noncompliance noted Hajor areas inspected physical barraers. lighting. assessment aids, detection aids, access control & vehicles Deteils withheld (ref 10CFR73 21) HOORE, D E . MCGUIRE, D R Division of Engineering & Technical Programs 82/10/05 ip 15638 059 24X Fiche 50-321,82/10 8210080227
- P Operating license stage documents & correspondence
- 8210120099 Lists LERs re HPCI & RCIC sys failures, not included in NUREO/CR-1205 on LERs related to pumps Probabilistic Analysis Branch should carrect classification deficiencies ORNSTEIN, H L Director's Office 80/07/10 BERNERO, R H Probabilistic Analysis Staff (Pre 801119) 2pp. 19689 170 2-Fiche 50-021, 80/07/10, 8210120099
- 8210050330 Forwards schedule for qualification testing of enaleg transmitter trip sys.in response to 801001 request QUCHALL T Georgia Power Co 82/09/28 EISENHUT.D C Office Nuclear Reactor Regulation, Director 3pp 15610 258 24X Fiche 50-321, 82/09/28, 8210050330
- 8210150327 Application to amend License DPR-57, consisting of inler change to Tech Spec re maint of secondary containment for period of upcoming refueling outage Proposed mod allows more efficient access to torus area by workers SECKMAN.J T. Georgia Power Co. 82/10/06 Dffice of Nuclear Reactor Regulation. Director 3pp 15701 323 24X Fiche: 50-321.82/10/06.8210150329
- --8210150333 Proposed temporary changes to Tech Spac re maint of secondary containment for period of upcoming refueling outage

 * Caprile Power Co. 82/10/04. 8pp 15701 376 24x
 Fich. 50-321, 82/10/04. 8210150329
- Q Inspection reports, IE Bulletins & correspondence
- 8210010113 Forwards IE Insp Repts 50-321/82-26 & 50-36/82-25 on 820809-13, No noncompliance noted DANGE, H C Division of Project & Resident Programs 82/09/07 KELLY-R J Georpia Power Co 2pp 15567 206 24X Fiche 50-321, 82/09/07, 8210010113
- --8210010118 IE Insp Repts 50-321/82-26 & 50-366/82-25 on 82%07:18 noncompliance noted Major areas inspected lab GC program chemistry & radiochemistry procedures, airborne efficant sampling & accountability & mobile lab.

 EVANS.C D. MONTOCHERY.D M Division of Emergency Preparational Support. 82/09/02 11pp 15567 208 24% Ficher 50-321,82/09/07.8210010113
- 8210010235 Forwards IE Insp Rept 30-321/82-27 on 820818-19 No noncompliance noted DANCE, H. C. Division of Project & Resident Programs 82/04/69 KELLY, R. J. Georgia Power Co. 2pp. 15574-022 24X Fiche: 50-321, 82/09/08, 8210010235.

ì

- --8210010240 IE insp Rept 50-321/82-27 on 820818-19 No noncompliance noted Major areas inspected followup of RU 50-321/82-60 re 820703 reactor trip JAPE.F. HERDTLA R Division of Engineering & Technical Programs 82/09/02 7pp 15574 024 24x Fiche 50-321,82/09/08,8210010235
- 92:00:10309 Forwards IE Insp Repts 50-32:1/82-28 & 50-366/82-26 on 820727-0827 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/10 EELLY, R J Georgia Power Co 2pp 15568 274 24X Fiche 50-32:
- --8210010327 IE Insp Repts 50-321/82-28 & 50-366/82-26 on 820727-0827 No nancompliance noted Major areas inspected Tech Spec corpliance, operation sepformence, overall plant operations, GA practices & station & corporate mgt practices GOCRS.R F , HOLMES-RAY, P , GROWNLEE, V L Division of Project & Fissident Programs 82/09/10 4pp 19568 276 24X Fiche 50-321,82/09/10,8210010309
- 8210010019 Ack receipt of 820907 itr informing NRC of etsps taken to correct violations noted in iE Insp Rept 90-321/82-19
 O'REILLY.J P Region 2. Diffice of Director 82/99/16 KELLY.R J Georgia Power Co ip 15565 300 24% Fiche 50-321/82/09/16.
 8210010019
- --8210010022 Responds to NRC 820806 itr re violations noted in IE insp Repts 50-321/82-19 & 50-366/82-19 Corrective actions procedures being revised to include tighter controls on changes to fusi movement data packages BECKHAM.J T Opergia Power Co 82/09/07 D'REILLY.J P Region 2. Office of Director 3pp 15565 301 24X Fiche 50-321, 62/09/16,8210010019
- --8210010025 Forwards iE insp Repts 50-321/82-19 & 50-366/82-19 on 820421-0925 & notice of violation 0'REILLY.J P Region 2. Office of Director 82/08/06 KELLY.R J Georgia Power Co 2pp 15565 304 24X Fichs 50-321.82/09/16.
- --8210010029 Notics of violation from insp on 820421-0525 4 Region 2, Office of Director 82/08/06 ip 15565,306 24X Fiche 50-321,82/09/16,8210010019
- --B210010031 iE insp Repts 50-321/B2-i9 & 50-366/B2-i9 on 820421-0529 Moncompilance nated fuel loaded into core w/o all control rods fully inserted RODERS-R F Division of Project & Resident Programs BROWNLEE, V L Region 2, Office of Director B2/07/29 7pp 15565 307 24% Fiche 50-321,62/09/16.6210010019
- 9210040047 Ack receipt of check in payment of civil psnaity proposed on B20713 Corrective measures described in 820812 & 0907 ltrs will be examined in future insp.

 AYELRAD. J.A. Director's Office, Office of inspection and Enforcement 82/09/23 KELLY, R.J. Qsorgia Powsr Co. 2pp. 15577 290 24X Fiche 50-321,82/09/23,8210040047
- 320B190233 IE Info Notics 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Bvc list enci GBBh.t. I Division of Fuel Facilities, Materials & Safsguards 62/10/06 Consolidated Edison Co of New York 66pp 15761:250 24x Fiche 50-000,82/10/06,8208190233
- \$210080227 Forwards IE Safsguards Insp Repts 50-321/82-31 & 50-366/82-29 on 820920-23 No moncompliancs noted, DARCE.H C Division of Project & Resident Programs 82/10/06 MELLY.R J Georgia Power Co 2pp 15638: 057 24X Fichs 50-321.82/10/06.8210080227
- -82\$1080228 IE Safeguards Insp Repts 50-321/82-31 & 50-366/82-29 on 620920-23 No noncompliance noted Hajor areas inspected physical barriers, lighting, assessment aids, descrion aids, access control & vah.class Details withheld (rsf 10CFR73 21), MODRE, D E , MCQUIRE, D R Division of Engineering & Tschnical Programs 82/10/05 ip 15638 059, 24X Fichs 50-321,82/10/06,6210080227
- 1208190238 IE Bulistin 82-03, "Stress Corrasion Cracking in Thick-Wall, Largs-Diamster, Stainless Steel, Recirculation Sys Piping at BWR Plants "Syc list encl pEYOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York. 1 (5pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- P240270277 Act receipt of 820927 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/82-24 & 50-366/82-22
 LEWIS.R C Division of Project & Resident Programs 82/10/14
 KELLY.R J Georgia Power Co ip. 15775 028. 24X
 Fichs 50-321,82/10/14,8210220277

- --8210220287 Responds to NRC 820823 itr rs violations noted in IE Insp Repts 50-321/82-24 & 50-366/82-22 Corrective actions written plan will be prepared to scheduls & integrate lacture series to meet addi training needs OUCWALT Carogia Power Co 82/09/27 O'REILLY, J. P. Region 2, Office of Director 4pp 15775 029 24X Fichs 50-321,82/10/14, 8210220277
- --8210220292 Forwards IE insp Rspts 50-321/82-24 & 50-366/82-22 on 820726-30 & notice of violation LEWIS,R C Division of Project & Resident Programs 82/08/23 XELLYR J Georgia Power Co 2pp 15775 033 24X Fichs 50-321,82/10/14.8210220277
- --8210220299 Notics of violation from insp on 820726-30 * Division of Project & Resident Programs 82/08/23 2pp 15775 035 24% Ficha 50-321,82/10/14.8210220277
- --B210220307 IE Insp Repts 30-321/82-24 & 50-366/82-22 on 820726-30
 Noncompliancs noted failurs to provide GA indoctrination &
 scheduled preplanned iscture series based on svaluation of
 annual licensed operator stans
 SKINNER.P H , JACKSON.L H , UPRIGHT.C M Division of Engineering &
 Technical Programs 62/06/19 8pp 15775 037 24X
 Fichs 50-321.82/10/14/8210220277
- R Periodic operating reports & related correspondence
- 8210130129 Forwards monthly operating rapts for Sept 1982 NIX.H C Georgia Power Co 82/10/07 Director's Office. Office of inspection and Enforcement 1p 15673 029 24X Fiche 50-321.82/10/07,8210130129
- --B210130132 Monthly operating repts for Espt 1982 SMITH J A Georgia Power Co B2/10/07. 9pp 15673 030 24X Fichs 50-321.82/10/07/8210130129
- S Reportable occurrences, LERs & related correspondence
- 821012017i Discusses 810406 discovery that undervoltage relays of second offsits source would not operate.preventing closure of all dissel generator breakers Licenses will be proposing design mod to correct problem of non-Class IE interlock CHIRAMAL.M Director's Office 81704/21. Director's Office 3pp. 15692;202 24X Fichs 50-321.81/04/21.8210120171.
- 8210010008 Responds to FDIA request for 19 categories of documents re nuclear reactor syents & safety problems Forwards documents listed in App A FELTON, J M Division of Ruiss and Records. 82/06/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000. 82/06/28. 8210010008
- --8103120107 Summary of 810107 operating reactor events meeting W/o encl agenda LAIMAS, O Division of Licensing, 81/01/19 EISENHUT, D Q Division of Licensing 3pp 15727 361, 24X Fichs 50-000, 82/06/28,8210010008
- --Bi04290i03 Discusses IE daily rept for 810406 re alternate offsite source interiock w/emergency diesel generators at Unit 1 Licenese will propose mod to correct non-Class iE interlock preventing automatic operation of safety sys CHIRAMAL, M Director's Office 81/04/21 Director's Office, 3pp. 15729 041 24X Fichs 50-000, 82/06/28, 8210010008
- --8210010083 Recommends ACRS action on recent LERs re HPCI failt auto start after MSIV failure & single cooling supply lins on RHR pump motors

 BOEHNERT, P ACRS Advisory Committee on Reactor Safeguard: 80/06/13 KERR, W ACRS Advisory Committee on Reactor Safeguards ip 15727 138 24X Fiche 50-000.82/06/28.821(
- 8210130256 Forwards LER 82-074/03L-0 NIX.H C Osorgia Power Co 82/07/28 O'REILLY, J. P Region Office of Director. ip 15678 048. 24X Fichs 50-321.82/07/1 8210130256
- --8210130258 LER 82-074/03L-0 on 820901. HPCI steam pressure con switches A, C & D actuated at less than 107 3 psig Caused by component failure due to estpoint drift Switches calibr & function tested TIPPS, 8, B Georgia Power Co 82/09/28 Region 2, Offic Director 2pp 15578 049 24X Fiche: 50-321, 82/09/28, 8210
- 8210220384 Forwards LER 82-071/03L-0. NIX.H C Georgia Pawer Co. 82/09/28. O'REILLY, J. P Region Office of Director ip 13779 167 24X Fiche: 50-321, 82/09/ 8210220384

- --8210220388 LER 82-071/03L-0 on 820831.primary containment atmosphere concentration 02 exceeded Tech Spec requirements Caused by personnel failure to secure standby gas treatment sys in time while venting drywell Personnel counseled TIPPS.S 8 Occopia Power Co 82/09/28 Region 2, Office of Director 2pp 13779 168 24X Fiche 50-321, 82/09/28, 8210220384
- 8210220219 Forwards LER 82-082/03L-0 NIA:H C Georgia Power Co 82/10/07 O'REILLY:J P Region 2: Office of Director 19 15776:242 24X Fiche: 50-321:82/10/07: 8210220219
- --8210220222 LER 82-082/03L-0 on 820911,LPCI A inverter tripped Unit placed in 7-day limiting condition for operation. Caused by failure of output filter tapacitor Six fuses & 2 output filter capacitors replaced inverter placed in svc on 820913 TIPPS.S B Georgia Power Co 82/10/07 Region 2. Office of Director ip 15776 243 24X Fiche 30-321,82/10/07,8210220219.
- 8210290327 Forwards updated LER 80-016/03X-1 NIX.H C Osorgia Power Co 82/10/12 0'REILLY, J # Region 2, Office of Director 1p 19853 108 24X Fiche 50-321, 82/10/12,
- --B210270334 Updated LER 80-016/03X-1 on 800129, investigation of IE Bulletin 79-27 revealed that breaker control power to swing diesel B motor control ctr fed by non-Class IE vital ac sys Caused by design error SWANER.H L Georgia Power Co S2/10/12 Region 2. Office of Director ip 15853 107 24X Fiche 50-321.82/10/12,8210290327
- 8210290373 Forwards updated LER 82-054/03X-1 NIX.H C Georgia Power Co 82/10/12 Region 2, Diffice of Director 1p 15859 022 24X Fiche 50-321,82/10/12,8210290373
- --8210290375 Updated LER 82-054/03X-1 on 620628.at 100% power.RHR syrwater pump C failed operability & flow requirements Caused by normal wear to impeller seal & casing wear rings Pump removed-rebuilt, installed & tested successfully TIPPS-5 B Georgia Power Co 82/10/12 Region 2, Office of Director 1p 15853 023 24X Fiche 50-321,82/10/12,8210290373
- 8210290096 Forwards LER 82-083/03L-0 NIX.H C. Georgia Power Co 82/10/14 O'REILLY, J P Region 2, Difice of Director 1p 15853 359, 24X Fiche 50-32i,82/10/14, pp.10200000
- --82(0270105 LER 82-083/03L-0, on 820715, 00 review disclosed installation of non-0 part in level switch on A loop core spray discharge line Caused by ineffective administrative procedures. Part ordered Required & functions not affected TIPPS, 8 B Georgia Power Co. 82/10/14 Region 2. Office of Director ip 15853 360 24% Fiche, 50-321, 82/10/14, 8210270096
- B210270262 Forwards LER B2-086/03L-0

 NIX, H C. Osorgia Power Co 82/10/14 O'REILLY, J P Region 2:
 Office of Director ip 15854 074 24X Fiche. 50-321, 82/10/14;
 02/1080362
- --8210270272 LER 82-086/03L-0 on 8209i7.attempt to place torus cooling in syc failed due to lack of syc water flow Caused by loose bolts in valve operator coupling allowing coupling spring pin to break Pin replaced & bolts tightened TIPPS.S B Georgia Power Co 82/10/14 Region 2. Office of Director 1p 15854.095 24X Fiche.50-321.82/10/14.821027026R
- 8210270326 Forwards LER 82-084/03L-0 NIX,H C Georgia Power Co. 82/10/14 O'REILLY.J P Region 2-Office of Director 1p. 15853 062 24% Fiche 50-324.62/10/14. 8210270326
- --8210270327 LER 82-084/03L-0 on 820716, channel B main steam line radiation monitoring instrument failed Cause unknown Spare instrument installad, calling to tested TIPPS, S.B. Georgia Power Co. 82/10/14 Region 2, Office of Director 1p 15853 063 24X Fiche 50-321,82/10/14,8210290326.
- 8210270347 Forwards LER 82-071/03L-0 NIX,H C Omorgia Power Co 82/10/21 D'REILLY, J.P. Region 2. Office of Director 1p 15853.026 24X Fiche 30-321.82/10/21. 8210270349.
- --B210290359 LER 82-091/03L-0 on 820928; spec release order change to iquid radwaste monitor instrument FT&C procedure lacted plant review board evaluation Caused by personnel error TIFPS 8 B 0 georgia Power Co 62/10/21 Region 2, Office of Director 1p 15853-027 24X Fichs 50-321.82/10/21,8210290349

- DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION
- A Application/construction stage documents & correspondence
- B21001000B Responds to FOIA request for 19 categories of docuserts in nuclear reactor events & safety problems Forwards documents listed in App A FELTON J M Division of Rules and Records 62/06/28 UDELL.R.A Critical Mass Energy Project 15pp 15727 005 24x Fichs 30-000-82/06/28.8210010008
- --BOOB050265 Discusses addl required info to better define potential creating in reactor vessel notices ;
 NOONAN, V B Assistant Director for Materials & Quelificates ;
 Engineering B0/05/05 TEDESCO.R L Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000.02/06/20.02100; E'
- B20B290099 FOIA request for documents re shipment of radicactive as a fig by OE at Wilmington, NC, transported by Tri-fleate Mater Transit which traveled through NY on or about 820725 & received at facility SHARISON, SS New York, State of 62/09/14 Office of Administration in 15758 242 24X Fiche 50-322,82/09/[4,]
- 8210050488 Forwards requests for add1 info re instrumentation L control.containment sys & environ qualification of safety-related electrical equipment Schedule for submitting required info requested within 7 days W/o encis SCHMENGER. A Licensing Branch 2 82/09/20 POLLOCK. N C Light Lighting Co 3pp 15626 286 24X Fiche 80-322,02/02/21.8210050488
- 8210190019 Responds to FOIA request for documents re shipsent ef radioactive matl mfg by GE at Milmington.NC & transported by Tri-State Motor Transit to facility on 820725 Forwards DOF/NRC Form 741 handwritten note FELTON.J M Division of Rules and Records 82/10/06 CHARISON New York, State of 1p 15758 243 24X Fiche 50-322.82/10.15
- --8210190464 "DOE & NRC Nuclear Matl Transaction Rept "
 # NRC No Detailed Affiliation Given * Energy, Dept of 82/09/09 38pp 15758 245 24X Fiche 50-322,62/10/06.621(16)
- 8210280240 Provides NRC responses to Judge Morris 820914 questis*s based on NRC 820629 response to earler ABLB info requists Questions involve Unresolved Safety Issues A-44, A-46, A 42 k A-24. THI Item 1 A l. 1 & Item 63 REPKA-D A Hearing Branch 3 82/10/06 BRENNER.L. CASPENTES HORRIS.P.A Atomic Safety and Licensing Board Panel 17s; 15845:177 24X Fiche 30-322, 82/10/06, 8210280240
- B210210510 Responds to B20831 request to delay installation of hist radiation signal for purge valves, (NUREO-0737.1tem II E 4 2(7)) until fuel load Justification insufficient Re-evaluation requested SCHWENCER: A Licensing Branch 2 82/10/13 POLLOCK.HG Ls-1 Island Lighting Co 2pp 15782 278 RAX Fiche 50-332.82f(0/1) 8210210510
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8210190385 Forwards NRC 821013 response to util justification for installation of high radiation closure signal for purge valves info relevant to SER Open Item II E 4 2 & Suffoli County Contention 23 H/o encl.

 REPKA-D A Hearing Branch 3 82/10/15 BRENNER.L. CAPPATIF.

 HORRISP A Atomic Safety and Licensing Board Fanel 239 13741 214. 24% Ficher 50-322,82/10/15,8210190385
- F Security, medical, emergency & fire protection plans
- 8210150055 Forwards IE Emergency Preparedness Appreheal fijt % & BZ-18 on 820820-0702. App A. significant emergency preparedness findings & App D improvement items BHITH.O.H Division of Emergency Preparedness & Operational Saw 82/09/30 POLLOCK.M.B. Long Island Lighting Co 1011 15% 24X Fiche 50-322.82/09/30.8210150055
- --B210150059 IE Emergancy Preparedness Appreisal Rept 50-322/87-Jet B20820-0902 Corrective actions required to complete emergency preparedness training program TERC.N. M. GROCKER, H. W. Division of Emergancy Preparties & Operational Support 82/09/30 40pp 15701 071 211 Fiche. 50-322, 82/09/30, 8210150055

- 8210280033 Releases public version of revised info for facility emergency pian FELTON. JH Division of Rules and Records 82/10/08 Document Management Branch ip 15857 145 24X Fiche 50-322,82/10/08, 82/10280033
- ~-8210280036 Forwards public version of revised info for facility emergency plan, including updated cross-ref list, revised plan pages & radiological emergency evacuation plan Revised plan pages will be included in next amend SMITHJU Long Island Lighting Co 82/09/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 19857 146 24X Fishe 50-322,82/10/08.8210280033
- -- E210280039 Forwards public version of revised info for facility exergency plan including updated cross-ref list, revised plan pages & radiological emergency evacuation plan Revised plan pages will be included in next amend SHITH.JL Long Island Lighting Co B2/09/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15857 148 24X Fiche 50-322,82/10/08,8210280033
- --8210280041 Public version of radiological emergency evacuation plan, consisting of updated cross-ref list, revised pages & offsite dose assessment methodology Thirteen oversite maps encl Aperture cards available in PDR MAGNUS.D Long Island Lighting Co MAGNUS.D KLD Associates, Inc 82/08/27 213pp 15857 i90 24X Fiche 50-322,82/10/08,8210280033
- ©210290125 Forwards IE Insp Rept 50-322/82-24 on 820907-10 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/10/15 POLLOCK.M 5 Long Island Lighting Co 2pp i5853 322 24X Fiche 50-322.82/10/15.8210290125
- G. Adjudicatory correspondence
- 8208290094 FOIA request for CRAC & CRAC 2 analyses for facilities CURRAN, D Harmon & Weiss 82/09/10 Office of Administration 1p 15626 239 24% Fiche 50-000,82/09/10,8208290094
- 8210200036 Stipulation of Suffolk County Contention 25/Shoreham Opponents Coalition Contention 19(a) represervice & inservice insp & reactor prossure vessel integrity Certificate of Svc encl
 BURDENIGK.B M Hearing Branch 3 IRHIN.D P Long Island Lighting Co. SHANJ.J T Shoreham Opponents Coalition 82/09/17 lipp 15755 345 24X Fiche 50-322,82/09/17.8210200036
- 8210040011 Forwards NRC 820903 ltr to util transmitting IE lnsp Rept 50-322/82-14 BORDENICK-B M Hearing Branch 3 82/09/27 DRENNER, L, CARPENTER, J L. HORRIS, P A Atomic Bafety and Licensing Board Panel 4pp 15581 328 24X Fiche 50-322, 82/09/27, 8210040011
- 82:00:0395 Supplemental status rept on Emergency Planning Contentions &C & 7A per ASLB 820907 supplemental prehearing conference order Certificate of 8v enci MCMURRAY.C M Buffolk County, NY MCMURRAY.C M Kirkpatrick, Lockbart, Hill, Christopher & Phillips 82/09/28 5pp. 13549 239 24x Fichs 50-322,82/09/28,8210010395
- 8210010356 Supplemental memorandum & order granting util motion to compel discovery on Suffolk County emergency planning documents Executive privilege does not apply to county emergency planning steering committee meeting minutes BRENNER.L Atomic Safety and Licensing Board Panel 82/09/27 Suffolk County, NY 4pp 15574.140, 24% Fiche 50-322,82/09/29, 8210010356
- B2\$0050582 Responds to FDIA request for CRAC & CRAC 2 analyses for facilities No analyses exist for Shoreham Nuclear Plant Analyses for CRBR furnished under FDIA 82-344
 FELTON.J M Division of Rules and Records 82/09/29 CURRAN.D Harmon & Welss 1p 15626 240 24X Fiche 50-000,82/09/29, 92:10050582
- B210040063 Forwards NRC 820916 ltr to util % util 820812 ltr to NRC re IE Insp Rept 50-322/82-13 BGRDENICK.B M Hearing Brench 3 B2/09/30 BRENNER,L, CARPENTER.J L, MORRIG.P A Atomic Safety and Licensing Board Panel 4pp 15581 237 24X Fiche 50-322,82/09/30,8210040063

- 8210050189 Notice of relevant & matl new info re type of accident involving internal flooding which may lead to higher probability than calculated in draft probabilistic risk assessment Certificate of Svc encl BROWN. H H Suffolk County. NY BROWN. H H Kirkpatrick. Lockhart. Hill. Christopher & Phillips 82/09/30 dpp 15603 301 24X Fiche 50-322.82/09/30.8210050189
- 8210050383 Motion to suppl sponsorship of Suffolk County testimany on Contentions 12-15 re compliance w/NRC OA/QC requirements. Add1 witnesses will bring relevant expertise to proceeding Certificate of Svc 2 prof qualification encl LANPHER.L C Suffolk County, NY LANPHER.L C Kirkpatrick, Lockhart Hill, Christopher & Phillips 82/09/30 Atomic Safety and Licensing Board Panel 16pp 15608 235 24x Fiche 50-322, 82/09/30,8210050383
- 8210050243 Forwards NRC 820913 ltr to util transmitting IE Mgt Meeting Rept 50-322/82-25 on 820826 BORDENICK,B M Haaring Branch 3 82/10/01 BRENNER,L, CARPENTER,JL, MORRIS,JL Atomic Safety and Licensing Soard Panel App 15611 178 24X Fiche 50-322,82/10/01.9210050243
- 8210060187 App B to ASLB 820907 supplemental prehearing conference order on Phase 1 re emergency planning, listing edmitted Phase 1 contentions

 a Atomic Safety and Licensing Board Panel 82/10/04 16pp 15613: 212 24X Fiche 50-3R2.82/10/04.8210060187
- B210280251 Forwards IE Emergency Preparedness Appreisal Rept 50-322/82-18 BLACK.R L Hearing Branch 3 82/10/04 BRENNER,L, CARPENTER,J L, MORRIS.P A Atomic Safety and Licensing Board Panel 2pp. 15838 206 24% Fiche 50-322.82/10/04.8210280751
- B210120307 Motion for further ASLB direction on conduct of QA cross-examination Steps listed to ensure fair & efficient litigation of QA issues Certificate of Svc enc!

 EARLEY, A F Long Island Lighting Co EARLEY, A F Hunton & Williams. 82/10/05 Atomic Befety and Licensing Board Panel. 60pp 15651 255 24X Fiche 50-322.82/10/05.8210120307
- 8210280234 Forwards IE Insp Rept 50-322/82-23 BORDENICK, B H Hearing Branch 3 82/10/06 BRENNER, L , CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel 4pp 15837 067 24% Fiche 50-322, B2/10/06, B210280234
- 8210280240 Provides NRC responses to Judge Morris 820914 questions based on NRC 820629 response to earlier ABLB info requests Questions involve Unresolved Bafety Issues A-44.A-46.A-42 & A-24.TMI Item 1 A 1 1 & Item 63
 REPKA: D A Hearing Branch 3 82/10/06 BRENNER, L , CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Penel 17pp. 15845:177 24X Fiche 50-322.82/10/06.8210280240.
- 8210150234 Notifies that North Shore Committee Against Nuclear & Thermal Pollution & util have resolved Committee Contentions EP 11(D)(F)(E) & EP 12(A) Committee will not file testimony on Contentions EP 11(A)(B)(C) but will cross-examine SHAPIRO.R Cammer & Shapiro SHAPIRO.R North Shore Committee Against Nuclear & Thermal Pollution 82/10/08. BRENNERs L. CARPENTER.J. L. MORRIS.P A Atomic Safety and Licensing Board Penel 1p 15706 060 24X Fichs 50-322,82/10/08.8210150234
- 8210280209 Forwards Region i 820927 ltr to util re IE Insp Repts 50-322/82-10 & 50-322/82-11 & util 820701 & 19 ltrs.
 BORDENICK, B H Hearing Branch 3 82/10/08 BRENNER, L . CARPENTER, J . ., MORRISP, A Atomic Safety and Licensing Board Panel 4pp 15837 091. 24X Fiche 50-322,82/10/08,8210280209
- 8210150117 Advises that NMSS recommended Suffolk County not pursue 820916 request re NRC initiation of discussions \(\omega F \) to explore \(\omega Y \) to make F81 fingerprint identification \(\omega Y \) available to util 80RDENICK, B H Hearing Branch 3 82/10/12 MILLER, M 8 Kirtpatrick, Lockhart, Hill, Christophen & Phillips, MILLER, H S. Suffolk County, NY, 2pp. 15698:016, 24X Fiche, 50-322, 82/10/12, 8210150117.
- 8210150279 Forwards written testimony on Phase I emergency planning Contentions EP 1(8),2(A),2(B),4.5(A),5(B),7(B),10(B),10(C),11(A),11(B),11(C),13 & 14 Stipulations will be sent as soon as received, M/o testimony CHRISTHAN,J,N Long Island Lighting Co. 82/10/12 BRENNER,L, CARPENTER,J,H, MORRIS,P A Atomic Safety and Licensing Board Panel 4pp. 15715:055, 24X Fiche: 50-322,82/10/12,8210150279
- --8210130296 Forwards proposed settlement agreements on Emergency Planning Contentions 1(A).3.5(C).7(A),8,9,10(A),11(D),11(E),11(F) & 12(A) MCCLESHEY,K.E. Hunton & Williams 82/10/12 BRENNER,L., HORRIS,P.A., CARPENTER,J H Atomic Sefety and Licensing Board Panel. ip 15715 059 24X Fiche 30-322.82/10/12.8210150279.

- --B210150309 Stipulation on Suffolk County Contention EP 1(A) re effect of weather on sirens Util documented that effects of extreme weather taken into consideration in design of sirens
 BLACK.R L Hearing Branch 3 MCCLESKEY.K E Long Island Lighting Co SHAPIRD.R North Shore Committee Against Nuclear & Thermal Pollution B2/10/12 App 15715 080 24X Fiche 50-322,82/10/12,8210150279
- --8210150324 Stipulation on Suffolk County Contention EP 3 re federal resources Plant emergency plan to be amended to respond to concerns BLACK, R L Hearing Branch 3 MCCLESKEY, K E Long Island Lighting Co SHAPIRO, R North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 4pp 15715 066 24X Fiche 50-322, 82/10/12, B210150279
- --B210150337 Stipulation on Suffect County Contention EP 5(C) remotification of response organization & emergency personnel Plant emergency plan to be amended as listed BLACK.R L. Hearing Branch 3 MCCLEEKEY.K E. Long Island Lighting Co. SHAPIRG.R North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 4pp 15715 070 24X Fiche 50-322.82/10/12, 8210130279.
- --8210150351 Btipulation on Suffolk County Contentions EP 7(A) & EP 8 reonsite response organization & emergency operations accility respectively Plant sengency plan to be amended as litted BLACK.R L Hearing Branch 3 MCGLESKEY.K E Long Island Lighting Co SHAPIRO,R North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 App 15715 074 24X Fiche 50-322.82/10/12, 82/20130279
- --S2L0150365 Btipulation on Suffolt County Contention EP 9 re radiological exposure Plant emergency plan to be amended as listed BLACK-R L Hearing Branch 3 MCCLESKEY.K E Long Island Lighting Co SHAPIRO, R. North Shore Committee Against Nuclear & Thermal Pollution B2/10/12 7pp 15715.078 24X Fiche. 50-322.82/10/12. B210150279
- --B210150393 Stipulation on Buffolk County Contention 10(A) re field monitoring team Fourth replacement field monitoring team will be available to replace or relieve other three teams BLACKLR L Hearing Branch 3. MCCLESKEY, K E Long Island Lighting Co SHAPIRO, R. North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 App. 13715.085, 24X Fiche: 30-322, 82/10/12, 82/10/29
- --8210150402 Stipulation on North Shore Committee Against Nuclear & Thermal Pollution Contention EP 11(8) re redundant power supplies Backup diesel generator power provided to radios used by util as backup communication
 BLACK,R L Hearing Branch 3 MCCLESKEY,K E Long Island Lighting Co. SHAPIRO,R North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 3pp 15715 088 24X Ficha 50-322,82/10/12,8210150279
- --B210150410 Btipulation on North Bhore Committs: Against Nuclear & Thermal Pollution Contention EP 11(E) re communications through baspers Util commits to training personnel reresponse to bespers if telaphone sys overloaded.

 BLACK.R.L. Hearing Branch 3 MCCLESKEY, K E Long Island Lighting Co BHAPIRO, R. North Shore Committee Against Nuclear & Thermal Pollution B2/10/12 3pp. 15715 091 24X Fiche 50-322,82/10/12,8210150279.
- --8210150422 Bigulation on North Shore Committee Against Nuclear k
 Thermal Pollution Contention EP 11(F) re communication
 through nati alert warning sys. Concerns re coverage & lead
 capacity resolved.
 BLACK, R. L. Hearing Sranch 3. MCCLESKEY, K. E. Long Island Lighting
 Co. SHAPIRO, R. North Shore Committee Against Nuclear & Thermal
 Pollution 82/10/12 2pp 13713 094 24X Fiche 50-322,82/10/12,
 8210150279.
- --8210150527 Stigulation on North Shore Committee Against Nuclear & Thermal Pollution Contention EP 12(A) repersonnel assignments re-communication notification Util cummits to provide seven communicators Certificate of Svc encl BLACK.R L. Hearing Brench 3. MCCLESKEY.K E. Long Island Lighting Co SHAPIRO.R. North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 App. 15715 094. 24X Fiche 50-322,82/10/12,8210150279.
- 8210200076 Notification of corrections to Suffolk County Exhibits 51 & 56 LANPHER, L C Suffolk County, NY. LANPHER, L C, Kirtpatrick, Lockhart, Hill, Christopher & Phillips, 82/10/12, 3pp , 15754:173 24X Fichs. 50-922,82/10/12,8210200076.

- --8210200083 Response opposing Requests i & 3 in util 821065 action for further ASLB direction on conduct of cross-examination Mitls designated for use are relevant Opposes predetermined deadline by which County cross-examination must be complete LANPHER.L C Suffolt County, NY LANPHER.L C Kirtpatrich. Lockhart, Hill: Christopher & Phillips 82/10/11 Atomic Safeig and Licensing Board Panel 45pp 15754 176 24X Fichs 50-322,82/10/12.8210200076
- --8210200089 Submittal of GA/GC info in Subparagraphs (a)-(c),Page 15 of util 821005 motion for further ASLB direction conduct of GA cross-examination Certificate of Svc encl LANPHER.L C Kirkpatrick. Lockhart. Hill. Christopher & Phillips 82/10/11 149pp 15734 221 24X Fiche 50-022,82/10/12.8210200076
- 8210200003 Response to Suffolk County 821002 motion to suppl GA witrew panel Request is out of time, is impermissible attempt to suppl County direct testimony & is different from earlier approved game! suppls Cartificate of Svc enc! ELLIG.T S Long Island Lighting Co ELLIG.T S Hunton & Halliss: 82/10/14 Atomic Safety and Licensing Board Panel 12pp 15754.348 24X Fiche 50-522,82/10/14,8210200003
- 8210180099 Notice of withdrawal of appearance in proceeding Certificate of Bvc encl
 8LACK, R L Hearing Branch 3 82/10/15 4pp 15719 305 24x
 Fiche.50-322,82/10/15,8210180099
- 8210190395 Forwards NRC 821013 response to util justification for late installation of high radiation closure signal for purpe valves info relevant to SER Open Item II E 4 2 & Suffolk County Contention 23 H/o enc!

 REPKA-D A Hearing Branch 3 82/10/15 BRENNER,L. CARPENTER,JL

 HORRIBS-P A Atomic Safety and Licensing Board Panel 2pp

 15741 214 24X Fiche 50-322.82/10/15.8210190385
- 8210250058 Forwards stipulation re Buffolk County Phase I Contantion EP & MCMURRAY, C M. Kirkpatrick, Lockhart, Hill, Christopher & Phillips MCMURRAY, C M. Suffolk County, NY 82/10/19 BRENNER, L., CARPENTER, J H., MORRIS, P.A. Atomic Bafety and Licensing Bearf Pare, Ip 15787 094 24X Fiche 50-322,82/10/19,8210250058
- --B210250059 Stipulation on Suffolk County Contention EP & retraining emergency personnel Mading River fire dept trained per util emergency plan Certificate of Bvc encl BORDENICK, B Hearing Branch 3 MCCLESKEY, K E Long Island Lighting Co SHAPIRO, R North Shore Committee Against Nucleur L Thermal Pollution 82/10/15 5pp 15787 095 24X Fiche 50-322, 82/10/19,8210250058
- 8210270283 Forwards Buffolk County Deputy Executive F Jones 821020 memo to Buffolk county legislators re brief slippage in date scheduled for completion of county radiological emergency response plan. Related correspondence HCMURRAY. C. M. Kirkpatrick, Lockhart, Hill, Christopher & Phillips MCMURRAY. C M. Buffolk County, NY 82/10/26 DRENNER, L., CARPENTER, J. H., MORRIGS P. A. Atomic Bafety and Licensing Board Payl 2pp 13854 067 24X Fiche 50-322,82/10/26,8210290283

H General correspondence

- 8210070034 Provides responses to constituent T Hayes 8206ii questims re fuel storage & transport
 DIRCKB.H J Office of the Executive Director for Operations
 82/09/17 CARNEY.H. House of Rep. 17pp 15645 347 24X
 Fiche 50-322
- 8210260409 Forwards Hiddls Country Central School Board 821004 resolution opposing plant opening until acceptable safety set can be met & acceptable evacuation plan developed AMAKO, V. Suffolk County, NY 82/10/07 NRC No Datailed Affiliation Given. 2pp. 15803.317 24X Fiche 50-322.82/10/07.8210260409.
- Q Inspection reports: IE Bulletins & correspondence
- 8210040238 Ack receipt of 820701 & 19 ltrs informing NRC of stass that to correct violations noted in IE insp Repts 50-922/82-10 & 50-922/82-11 & MARTIN.T.T. Division of Engineering & Technical Programs 82/8/8/19 POLLOCK, M B Long Island Lighting Co 2pp. 15589-078 24x Fiche 50-922, 82/09/27, 8210040258.
- Fighe 50-322, 82/09/27, 8210040258.

 --8210040274 Responds to NRC 820524 ltr re violations noted in [E list]
- --B21040274 Responds to NRC 820324 for re-violations noted in it.
 Rept 30-322/82-10. Corrective actions procedure for leaf rati
 test panel rotometer calibr revised. Severity Level V
 violation contested
 POLLOCK.M S Long Island Lighting Co 82/07/01. MARIENT T
 Division of Engineering & Technical Programs 3pp. 13587 089
 24X Fiche. 50-322, 82/09/27, 8210040258

DOCKETED ITEMS

- --82i0040361 Responds to NRC 820618 itr re-violations noted in IE Insp. Rept 50-322/82-ii Corrective actions scope & frequency of battery svc modified POLLOCK, MS Long Island Lighting Co 82/07/19 MARTIN, T T Davisson of Engineering & Technical Programs App 15589 085 24X Fishe 50-322,82/09/27,8210040258
- 62(0150055 Forwards IE Emergency Preparedness Appraise) Rept 50-322/ 62-18 on 620920-0902, App A. significant emergency preparedness findings & App D improvement items SMITH. O H Division of Emergency Preparedness & Operational Support 62/09/30 POLLOCK.H 8 Long Island Lighting Co 10pp. 15701 061 24% Fiche. 50-322, 82/09/30, 8210150055
- --5210150059 IE Emergency Preparedness Appraisal Rept 50-322/82-18 on 820820-0902 Corrective actions required to complete emergency preparedness training program TERC:NN . CROCKER,HW Division of Emergency Preparedness & Operational Support 82/09/30 40pp 15701 071 24X Fichs 50-322,82/09/30,8210150055
- 6210050243 Forwards NRC 620913 ltr to util transmitting IE Hgt Meeting Rept 50-322/82-25 on 820826 BURDENICK, BM Hearing Branch 3 82/i0/0i BRENNER, L. CARPENTER, J. L. Atomic Safety and Licensing Board Panei 4pp 15611 178 24% Fiche 50-322.82/10/0i,8210050243
- B208190233 iE Info Notice 80-35, Suppl 1, "Leaking & Disiodged I-125 Implant Seeds " Svc list enci
 C080. L I Division of Fuel Facilities, Materials & Safeguards
 B2/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06. 8208190203
- 2210290350 Forwards IE Insp Rept 50-322/82-22 on 820823-27. No moncompliance noted MARTIN,I T Division of Engineering & Technical Programs 82/10/06 FOLLOCK.N S Long Island Lighting Co 2pp 15853 067 24X Fiche 50-322,82/10/06,8210290350
- --BRI0290356 JE Insp Rept 50-322/82-22 on 820823-27 No noncompliance noted Hajor areas inspected preoperational test program status, including program implementation, procedure review. procedure verification, test witnessing & evaluation results NICHOLAS; H H , BETTENHAUSEN, L Division of Engineering & Technical Programs 82/10/05 9pp i5853 069 24X Fiche 50-322,82/10/06,8210290350
- 821029034: Forwards IE Insp Rept 50-322/82-2: on 820729 No nuncompliance noted MARTINATI Division of Engineering & Technical Programs 82/10/12 FOLLOCK: MS Long Island Lighting Co 2pp 15853 056 24X Fiche 50-322, 82/10/12, 821029034:
- --82:0290344 IE Insp Rept 50-322/82-2: on 820729 No noncompliance noted Major areas inspected health physics personnel training to qualification program HHITE,J R. OREENMAN.E G. Region i. Office of Director 82/10/08 4pp 15853 058 24% Fiche 50-322,82/10/12,8210270341
- 82Q8190239 IE Builetin B2-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter. Stainless Steel, Recirculation Sys
 Piping at BMR Plants "Syc iist encl
 DEYQUNO.R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York.
 11Spp 15810 125 24% Fiche 30-000.82/10/14,8208190238
- 821029084 Forwards IE Insp Rept 50-322/82-19 on 820719-0813 & notice of violation
 HARTIN T T Division of Engineering & Technical Programs 82/10/15.
 PBLOCK.M S Long Island Lighting Co 2pp 15854 032 24X
 Fiche 50-322,82/10/15,8210290084
- --8210290089 Notice of violation from insp on 820719-0813 * Division of Engineering & Technical Programs 82/10/15 ip. 15854 034 24X Fiche 50-322, 82/10/15, 8210290084
- --B210270093 IE Insp Rept 50-322/82-i9 on 8207i9-08i3 Noncompliance noted two radiographs did not have required penetrameters & proper dispositions
 KERCK.H W . HARRIB,R H , DIERR,J P. Region 1, Office of Director 82/09/i9 i0pp 19854 035 24K Fiche 50-322,82/10/15,8210290084
- B210290125 Forwards IE Insp Rept 50-322/82-24 on 820907-10 No moncompliance noted MARTIN.T. Division of Engineering & Technical Programs 82/10/15 POLLOCK, M 8 Long Island Lighting Co 2pp 15853, 322, 24X F1che.50-322, 82/10/15,8210290125

- --8210270132 IE Insp Rept 50-322/82-24 on 820907-10 No noncompliance noted Hajor areas inspected actions on previous inspected findings & fire protection/prevention program in areas of administrative controls & cable separation requirements RICHARDS.S A , PLISCO.L R , BETTENHAUSEN.L Region i, Office of Director 82/09/29 7pp 13853 324 24X Fiche 50-322,82/10/15,8210270125
- 8210260134 Ack receipt of 821007 itr informing NRC of steps taken to correct violations noted in IE insp Rept 50-322/82-15 STAROSTECKI.R Division of Project & Resident Programs PCLLOCK.H S Long Island Lighting to 2pp 15799 093 24X Fiche 50-322.82/10/20,8210260134
- --B210260141 Responds to NRC B20830 ltr re violations noted in IE Insp Rept 50-322/82-15 Corrective actions startup mgt meeting held 820917 to review documentation for all testing & PT 554 007 reviewd to incorporate exceptions POLLOCK, M B Long Island Lighting Co 82/10/07 STAROSYECKI, R Division of Project & Resident Programs 7pp. 15797.095 24X Fiche: 50-322,82/10/20,8210260134
- S Reportable occurrences, LERs & related correspondence
- 82:0070384 Deficiency rept re analogue controllers supplied by Bailey Controls Co Initially reported on 820827. Circuit will be completed prior to fuel lead.per E & DCR F-43213 & CCF M50/06 MILLIOAN.M H Long Island Lighting Co 82/09/28, GRIER, B. H Region 1, Office of Director 3pp. 15633 346 24% Fiche 50-322. 82/09/28, 8210070384
- 8210280285 Interim deficiency rept re Jacket water pump shaft failures on emergency standby diese; generators Initally reported on 820917 Design mods to jacket water pump shaft-impeller assembly underway Alterations to shaft expected MILLIOAN.M H Long Island Lighting Co 82/10/15 HAYNES,R. G RELIGIOUS IN 1. 07fice of Director 3pp. 15837 040. 24X Fiche 50-322,82/10/15,8210280285
- T Hearing transcripts on non-antitrust matters
- 8210150168 Testimony of WQ Schiffmacher & WF Renz re Phase I emergency planning Contention 1(8) on prompt notification sys.Prof qualifications encl. SCHIFFMACHER W, RENZ.W F Long Island Lighting Co. 82/10/12 21pp 15707 315. 24X Fiche 50-322,82/10/12,8210150168.
- --8210150178 Testimony of RE Linmemann & ML Miele re Phase I emergency planning Contention 2(A) on adequate medical sycs Prof qualifications & supporting documentation encl. LINNEMANN, R E, MIELE, M L Long Island Lighting Go LinneMANN, R E Radiation Management Corp. B2/10/12 32pp. 15707:336 24X Fiche 50-322,82/10/12,8210150168
- --8210150188 Testimony of NJ DiMescia & E Lieberman re Phase I emurgoncy planning Contention 2(8) on ground transportation to hosp Prof qualifications & supporting documentation enci One aperture card available in PDR DIMASCIO. N. J. LIEBERMAN. E. Long Island Lighting Co. LIEBERMAN. C. KLD Associates, Inc. 82/10/12, 43pp. 15708:004 24X Fiche 50-322,82/10/12,6210150168
- --8210150206 Testimony of B Aidikoff, HM Blauer, M Cordaro, E Lieberman & J Rivello re Phase I emergency planning Contention 4 on protective actions. Prof qualifications & supporting documentation encl Six aperture cards available in PDR AIDIKOFF, B, BLAUER, H K, CORDARO, M Long Island Lighting Co 82/10/12, 170pp. 15708, 051. 24X Fiche. 50-922, 82/10/12, 8210150168
- --8210150223 Testimony of MC Cordaro, RR Dynes, DS Mileti & J Rivello re Phase I emergency planning Contention 5(A) on role conflict Prof qualifications encl CORDARO, M. C. DYNES, R., MILETI, D. S. Long Island Lighting Go 82/10/12 78pp 15708 222, 24X Fiche, 50-322, 82/10/12, 8210150168
- --8210150240 Testimony of NJ DiMascio & E Lisberman re Phase I emergency planning Contention 5(8) on traffic congestion affecting onsite smergency workers & offsite util personnel reporting to site Prof qualifications & supporting documentation enci. DIMASCIO.N J., LIEBERMAN.E. Long Island Lighting Co LIEBERMAN.E. KLD Associates: Inc 82/10/12 34pp. 15708.299. 24X Fiche.50-322.82/10/12.8210150168
- --B210150250 Testimony of HM Blauer, M Corderd & J Rivello re Phase I seergency planning Contention 7(B) on ability to augment procedures within 30 minutes Prof qualifications & supporting documentation encl.
 BLAUER, H. H., CORDARO, M., RIVELLO, J. Long Island Lighting Co. 82/10/12 60pp. 1570B:333. 24X Fiche: 50-322,82/10/12,8210150168.

- --B210150257 Testimony of HN Blauer, HC Cordaro & JF Schmitt re Phase I smargency planning Contention 10(B) on real time monitors Prof qualifications & supporting documentation encl BLAUER, H M . CORDARO, M.C . SCHMITT, JF Long Island Lighting Co B2/10/12 2B9pp 15709 031 24X Fiche 50-322, B2/10/12, B210150168
- --B210150265 Testimony of JF Schmitt & JS Baron re Phase I emergency planning Contention 10(C) on accident assessment & menitoring Prof qualifications & supporting documentation and SCHMITT. J F . BARON. J S Long Island Lighting Co BARON. J S Bane & Hebster Engineering Corp 82/10/12 30pp 15709 321 24% Fiche 50-322,82/10/12,8210150168
- --B21015D272 Testimony of MF Ren: & P Friedman re Phase I emergency planning Contention i1(A), (B) & (C) on communications u/offsite response organizations Prof qualifications & supporting documentation encl RENZ.W F . FRIEDMANP Long Island Lighting Co 62/10/12 57pp 15709:351 24X Fiche 50-322,82/10/12,8210150168
- --8210150281 Testimony of JA Notaro & RL Poltrino re Phase I emergency planning Contention 13 on interim safety parameter display sys Prof qualifications & supporting documentation enci NOTARO, J A , POLTRINO.R.L. Long Island Lighting Co POLTRINO.R.L. Stone & Webster, Int. 82/10/12 63pp 15710 046 24X Fiche 50-322,82/10/12,8210150168
- --B21015D290 Testimony of JB Baron, MC Cordero, NJ DiMascio, JN Hamawi, LP Pocaiujka & JF Schnitt re Phase I emergency planning Contention 14 on accident & dose assessment models M/ Certificate of Svc Five aperture cards available in PDR BARON, J S , CORDARD, M C , DIMASCID, N J Long Island Lighting Co B2/10/12 117pp 15710 126 24% Fiche 50-322,82/10/12, 8210150168
- 8210150370 Transcript of 821012 hearing in Bethesda: MD Pp 11:309-11:484 Supporting documentation end: = Atomic Sefety and Licensing Board Panel 62/10/12 194pp 15704 069 24X Fiche 50-322:82/10/12.8210150370
- 8210260232 Testimony of AC Kanen, JR Johnson, S Cole & KT Erikson on Contentions EP 28 & 38 re traffic congestion issues. KANEN, A C . JOHNBON, J. H., COLE, B Suffolk County, NY 82/10/12 337pp. 15802 001 24X Fiche 50-322, 82/10/12, 8210260232
- --B210240239 Testimony of KT Erikson & B Coie on Contention EP 5A revale conflict FRIKEON, K T , COLE, B Buffolk County, NY, ERIKSON, K T Yelv Univ B2/10/12 95pp 19802 178 24X Fiche 50-322, 82/10/12, B210240232
- --B210260242 Testimony of QC Minor on Contentions EP 108 & EP 10C re radiation monitoring & EP 14 re dose assessment MINDR, QC Suffolk County, NY B2/10/12 13pp 15802.273. 24X Fiche 50-322,82/10/12:8210260232
- --8210260246 Testimony of FC Finleyson on Contention EP 14 re-accident assessment & dose assessment models.Certificate of Byc encl. FINLAYSON, F.C Buffolk County, NY 82/10/12 50pp 15802:286. 24% Fiche 50-322, 62/10/12.6210260232.
- 8210150166 Transcript of 821013 hearing in Bethesda, MD.Pp 11, 485i1, 669. * Atomic Safety and Licensing Board Panel 82/10/13, 188pp. 15698 025. 24% Fiche 50-322, 62/10/13, 8210150166
- 8210180037 Transcript of 821014 hearing in Bethesda, MD Pp 11,670it,882 Supporting documentation entl.

 A Atomic Sefety and Licensing Board Panel 82/10/14, 299pp 15720:327, 24X Fiche, 50-322, 82/10/14, 8210180037
- 8210190338 Transcript of 821015 hearing in Bethesda: MD Pp 11,883i2,021.

 Atomic Safety and Licensing Board Panel. 82/10/15 i38pp 15742,322 24X Fiche: 50-322,82/10/15-8210190338
- 8210290004 Transcript of 821027 hearing in Bethesda. MD Pp 12:022-12:194 * Atomic Safety and Licensing Board Panel. 82/10/27 174pp. 13856:331 24X Fichs. 50-322.82/10/27.8210290004.

- DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A
 - listed in App A FELTON, J M Division of Rules and Records 92/06/20 UDELL,R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000, 82/06/28,8210010008
- --8008050265 Discusses addl required info to better define potential ear cracking in reactor vessel nozzles NOCNAN, V S Assistant Director for Materials & Qualifications Engineering 80/05/05 TEDESCOR & Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000.82/06/28.821001005
- 8210040429 Informs of decision to partially refund fees rematted v/ 800821 application to extend latest CP completion dates MILLER.W O License Fee Management Branch 82/09/21 FURBUSH.M F Pacifit das & Electric Co ip. 15597 262 24X Fiche 50-275.82/09/21.8210040429
- 8210130054 Responds to 820727 request for status rept on design verification program & briefing on proposed Phase II of program Info discussing background & current status encl DIRCKS.N J Office of the Executive Director for Operations 82/09/24 PALLADINO.N J. OfLINSKY.V, AHEARNE.J F Commissioners 28pp 15692 284. 24X Fiche 50-275.82/09/24.8210130056
- 8210050144 Responds to Generic Ltr 82-12 re plant staff working Ecurs Util administrative procedures address revised working hours CRANE.P A Pacific Gas & Electric Co 82/10/01 MIRAQLIA.F J Licensing Branch 3 1p 15605 161 24X Fiche 50-275,82/10/01, 8210050144
- 821025016B Forwards RH Engelken 820915 memo re RF Reedy.Inc elit meeting concerning GA audits for consideration in evaluation of GA program ELBERHUT,D.O Division of Licensing 82/10/06 COOPER.W E Teledyne Engineering Services. 2pp 15808 009 24X Fiche 50-275, 92/10/06, 8210250168
- --8210250392 Summary of 820910 meeting w/util & RF Reedy, inc re &A acof in-house design
 ENGELKEN,R H Region 5, Office of Director 82/09/15
 DENTQN,H R Office of Nuclear Reactor Regulation, Director \$3;
 15808-011. 24X Fiche 50-275,82/10/06,8210250168
- 8210230240 Forwards independent design verification program commissions of scapes of the property should contain detailed descriptions of scapes of termial methodology & models for all structures, says & components of the property of the scapes of
- 8210080123 Notifies of 821007 meeting w/util in San Francisco.Ch to discuss status of Pheses I & II. instrument test rig far verification of corrective action & NRC 820819 ltr re fuel load.

 * Teledune Energy Systems 82/10/08 Teledune Energy System ip. 15640 127 24X Fiche 50-275.82/10/08.8210080123
- 8210290446 Staff requirements memo re 821007 affirmation/discussion vote on extension of const completion dates for HPP89, purging of classified math in ALAB-659 & emergency preparedness & risks associated wifuel loading CHILK.B.J. Office of the Secretary of the Commission 82/10/09 Office of the Secretary of the Commission 220 Fiche 50-000.82/10/08.8210290446.
- 8210190470 Provides into re ownership of Bachtal Power Corp FRIEND: H B Bachtal Corp. 82/10/11. MIRAGLIA: F. J. Licenia Branch 3. 1p 15740.181 24X Ficha 50-275.82/10/11.8210199470
- B210270351 Advises that Bechtel Power Corp is entity responsible for work on project Ownership held by officers of Bachtel Oroup. Inc FRIEND, H B Pacific Cas & Electric Co FRIEND, H B Bechtel Grip B2/LO/11 MIRAQLIA.F. J. Licensing Branch 3 ip. 15834-338 20 Fiche: 50-275, 82/10/11.8210270351
- 8210150389 Suppl to 820719 application for amend to License PR-3511 security plan Encl withheld (ref 10CFR73 21). CRANE, P A Pacific Gas & Electric CO 82/10/12. DENTON, R R, NIRAOLIA 04916ce of Nuclear Reactor Regulation, Director 239 15703; 279 24X Fiche 50-275, 82/10/12, 8210150389.

- 8210250291 Clarifies 821007 statement re required sys, structures & components for plant operating modes for independent design **Prefixation program COOPER.H E Teledyne Engineering Services 82/10/12 EISENHUT, D o Division of Licensing 4pp 13790 191 24X Fiche 50-275,82/10/12,8210250291.
- 5210290077 Requests explanation of process & chronology of events in which Teledyne discussed const QA review of plant w/util. Berthel & S&W Info required to determine presence of confilts of interest Meeting requested ERGHM. H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips ERGHM. H H California, State of 82/10/12 COOPER.W E Teledyne Engineering Services 2pp 15853 361 24% Fiche 50-275,82/10/12,8210290097
- 8210290214 Provides NRC recommendation re Phase II of independent design verfication program Phase II program plan & requirement that Phase II review/evaluations be completed prior to feel load/lou power decision approved DIRCKS:H J Office of the Executive Director for Operations SECV-882-414 82/10/13 61pp 15876 261 24X Fiche 50-275, B2/10/13,8210290214
- B210190593 Advises that two former Bechtel employees will be retained on independent design verification program Individuals do not violate procedure on conflict of interest & will not verify work participated in as Bechtel employee CODPER.WE Teledyne Engineering Services B2/10/14 DENTON.HR Office of Nuclear Reactor Regulation, Director ENGELKEN,RH Region 5. Office of Director MANEATIB.O A Pacific Oas & Electric Co Spp 15791 184 24% Fiche 50-275.82/10/14,8210190583
- 8210190584 Provides preliminary response to 820701 request for review of seven points re validity of BNL results & generic implications in final rept concerning analysis of facility COOPER.W E Teledyne Engineering Services 82/10/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 15791 187 24X Fiche 50-275,82/10/15,8210190584
- 8210250210 Identifies concerns resulting from review of URS/Blume containment annulus structure model evaluation Concerns resulted in issuance of EDI Files 3004 & 3007 WRAY, R Teledyne Engineering Bervices 88/10/15 MANEATIS, 0 A Pacific Gas & Electric Co 4pp 15788 292 24X Fichs 50-275, 82/10/15, 8210250210
- 6210250318 Comments on Region 5 820915 memo re Phase II of independent design verification program.per 821006 request Change in Phase II not indicated COPPER.W E Teledyne Engineering Services 82/10/15 EIGENHUT, D. O Division of Licensing 5pp. 15790 048 24X Fiche 50-275,82/10/15,8210250318
- F Security, medical, emergency & fire protection plans
- 6210210033 Releases public version of revised emergency plan implementing procedures
 FELTON-JH Division of Rules and Recorde 82/10/01 Document Hanagement Branch 1p 15782 091 24X Fiche 50-275,82/10/01, 8210210033
- --8210210044 Forwards public version of revised emergency plan implementing procedures, including Procedure EP M-3 rechloring release, EP M-5 re Tsunami warning & EP M-8 recantainment emergency personnel hatch CRAME.P A Pacific Gas & Electric Co 82/09/23 ENGELXEN, R H Region 5, Office of Director 3pp 15782 092 24X Fiche 50-275.82/10/01,8210210033
- -- 8210210049 Public version of revised emergency plan implementing procedures, including Procedure EP M-3 re chlorine release, EP M-5 re Tsunami warning & EP M-8 re containment amergency personnel hatch

 Pacific Oas & Electric Co 82/09/13 84pp, 15782 095, 24X
 Fiche 50-275,82/10/01,8210210033
- B210150389 Suppl to 820719 application for amend to License DPR-76 re security pian. Encl withheld (ref iOCFR73 21), GRANE, P.A. Pacific Gas & Electric Co. 82/10/12, DENTON, H.R. GRAFIce of Nuclear Reactor Regulation, Director, 2pp. 15703, 279 24x Fiche 50-275,82/10/12,8210/50389
- O Adjudicatory correspondence
- 9250290449 Responds to 820512 petition requesting action under 10CFR2 206 For reasons stated in enclosed Director's Decision-getition denied DENTON, HR Office of Nuclear Reactor Regulation, Director 82/09/22, REYNOLDS, J. Center for Law in the Public Interest 5pp, 15863:166 24X Fiche 80-275,82/09/22,8210290449

- --B210270451 Director's Decision DD-82-10 denying Ctr for Lew in Public Interest 820512 petition requesting NRC issue order to util to submit amend to OL to cover GA & GC issues DENTON, HR Office of Nuclear Reactor Regulation, Director 82/09/22 7pp 15863 171. 24X Fiche 50-275, 82/09/22, 8210270447
- --8210290454 Notice of issuance of Director's Decision DD-62-10 under iOCFR2 206 denying petition by Ctr for Law in Public Interest request to require util to submit amend to DL to cover GA & GC issues
 DENTON,H R Office of Nuclear Reactor Regulation, Director B2/09/22 3pp 10863 178 24X Fiche 50-275,82/09/22,8210270449
- 8210040102 Order extending time until 821005 for Commission to act to review ALAB-661 (CHILK 8 J Office of the Secretary of the Commission 82/09/30 Commissioners 1p 15581 025 24X Fiche 50-275,82/09/30,8210040102
- 821005021B Reply to applicant & NRC 820924 briefs re-status of pending appeals from authorization of low power operation No adequate factual basis exists to support ASLB diamissal of Joint Intervenor GA contention as moot M/Gertificate of Svc. REYNOLDS, J. R. Joint Intervenors-Diablo Canyon REYNOLDS, J. R. Center for Law in the Public Interest 82/09/30 Atomic Safety and Licensing Appeal Panel Bpp 15611 237 24X Fiche 50-275, 82/09/30,821005021B
- 8210060220 Reply brief to other party briefs re moutness of low power cantentions Emergency planning issues & certain other issues moot Certificate of Byc enci LOCKE. R F Pacific Gas & Electric Co 82/09/30 Atomic Bafety and Licensing Appeal Panel opp. 15620.190. 24X Fiche 50-275,82/09/30.8210060220.
- 8210040097 Reply to Oovernor Brown & Joint Intervenors 820924 filings in response to ABLB 820902 order on mootness of low power issues Emergancy planning issues & some low power contentions mooted Certificate of Svc encl JONES, BW Hearing Branch i 82/10/01 Atomic Safety and Licensing Appeal Panel 9pp 13591 026 24X Fiche: 50-275, 82/10/01, 8210040097
- 8210050180 Reply brief to util & NRC 820924 bris#s re mothess of low power issues, per ABLB 820902 order Issues not moot. Controversy still exists & issue is of practical significance Certificate of 8vc encl.

 BROWN, H. H. California: State of. BROWN, H. H. Kirkpatrick, Lockhart, Hiii Christopher & Phillips 82/10/01 Atomic 8afety and Licensing Appsal Panel 8pp 15603 345 24X Fiche: 50-275, 82/10/01, 8210050180
- 8210060186 Request for leave to withdraw certain exceptions to ASLB 820831 initial decision ASLB 820927 clarification of & local jurisdiction acquiescence to preconditions re BOPs render exceptions unnecessary Castificate of Svc encl HASEELL, D.F. Hearing Branch 1 82/10/04 Atomic Bafety and Licensing Appeal Panel 5pp. 15613 193 24X Fiche 50-275.82/10/04, 8210060186
- 8210070145 Order extending time until 821008 for Commission to act to review ALAB-661.

 CHILK, B. J. Office of the Secretary of the Commission 82/10/03 Commissioners ip. 15627 076 24X Fichs. 50-275,82/10/05,8210070145.
- 8210130272 Forwards San Luis Obispo County Board of Supervisors 820927 action approving San Luis Obispo County nuclear power plant emergency response plant 8 State of CA Senate Bill 1473 amending govt code. Certificate of Svc enci CRANC.P A Pacific Gas & Electric Co 82/10/04 BUCK.J.H., JOHNSON.W.R. HOORE.T.S Atomic Safety and Licensing Appeal Panel. 6pp 15678 284, 24X Fiche 30-275.82/10/06.8210130272
- 8210120332 Order CLI-82-30 directing all natl security classified info be expunded from ALAB-653 & underlying record. Info not essential to ASLAE opinion & expunction would not prejudice any party or public.
 CHILK.S.J. Office of the Secretary of the Commission 82/10/08 2pp. 13652-108. 24X Fiche 50-275,82/10/08,8210120332.
- 8210130327 Order extending time until 821026 for Commission to act to review ALAB-681 CHILK, B. J. Office of the Secretary of the Commission. 82/10/08. Commissioners 1p. 15678 282. 24X Fiche: 50-275,82/10/08,
- 8210210422 Order extending time until 821105 for Commission to act to review NRR Director 820922 deniel of Joint Intervenors 10CFR2. 206 request.

 CHILK, 8 J. Difice of the Secretary of the Commission 82/10/18.

 Commissioners. 1s. 15763.083 24K Fichs. 50-275.82/10/18.

- 1

1

1 - 1

| 1 ųί

i +

| | |

 $\mathbf{r}^{\mathbf{r}}$

8210290245 Hemorandum in response to util 820924 motion for clarification of ASLB 820831 initial decision Decision supports conclusion of law on adequacy of offsite energency planning. HOLF JF. Atomic Sefety and Licensing Scard Penel B2/10/24 2pp 15937 056 24X Fiche 50-275,82/10/26.8210280245

H Canaral correspondence

- B210220363 Advises that B21010 ltr requesting util recalculate saismic safety sys at plants will be sent to all perties OILINEXY,V Cosmissioners B2/10/20 SCHULKE.S. Affiliation Uninoun is 15779 201 24K Fichs 50-275.62/10/20.8210220363
- --8210220369 Urges util be forced to recalculate entire seismic safety RIVERUGOT Urges util be forced to recalculate entire seisaic sys at plant SCHULKE, S. Affiliation Unknown 82/10/10 OILINSKY, V Commissioners ip 15779 202 24X Fiche 50-275, 82/10/20, 8210220363,

O Inspection reports. IE Bulletins & correspondence

- B210060133 Forwards iE Insp Repts 50-275/82-26 & 50-323/82-13 on 820726-30,0816-20 & 0830-0901 No noncompliance noted BIBHOP.1 M Division of Resident, Rector Project & Engineering Programs 82/09/17 CRANE.P.A Pacific Gas & Electric Co 2pp 19614 307. 24% Ficha-50-275,82/09/17,8210060133
- --82i0060141 lE Insp Repts 50-275/82-26 & 50-323/82-13 on 820726-30, 0816-20 & 0830-0901 No noncompliance noted Major areas inspacted sate tour & mod to piping & electrical raceway supports resulting from revised annulus satiamic spactra BURDOIN.JF . ZWETZIO.O B Division of Resident, Reactor Project & Engineering Programs. 82/09/17 9pp 15614 311 24X Fichs 50-275,62/09/17,8210060133
- 6208190233 IE info Notice 80-39, Suppl i, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Meterials & Safeguards 82/10/06. Consolidated Edison Co of New York 66pp 15761 250 24X Fiche-50-000.82/10/06,8208190233
- 6208190238 IE Bulletin 82-03, "Stress Corrosion Crecking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at DWR Plants "Svc list encl DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14, Consolidated Edison Co of New York 115pp 15810 125, 24x Fiche, 50-000, 82/10/14, 8208190238
- 6210280324 Forwards IE Insp Repts 50-275/82-30 & 50-323/82-14 on SIOCHUSE PATUARES IL INSP RAPES SO-2/3/2-30 & SO-22/3/2-14 on SIOCHICP.T W Division of Resident Reactor Project & Engineering Programs 82/10/14 CRANE.P A Pacific Oas & Electric Co 2pp 15837 019 24x Fiche 50-278, 82/10/14, 8210280324
- --8210280330 IE Insp Repts 50-275/82-30 & 50-323/82-14 on 820914-14 No noncompliance noted Major areas inspected.implementation of independent verification program including independence qualifications of personnel & implementation of GA program HORRILL.P. J., ECKHARDT.J. H., BISHOP, T. H. Division of Resident, Reactor Project & Engineering Programs. 82/10/08 6pp 15839 021. 24X Fiche: 50-275, 82/10/14, 8210280324

R. Periodic operating reports & related correspondence

82i0250247 Bubmite Semimonthly Progress Rept 20 for 820902-i008. No open item repts issued, but two open item repts identified Individuals completed ecceptable statements repotential or apparent conflicts of interest REEDY.R F R.F Reedy. Inc 82/10/08 DENTON.H R. Office of Nuclear Reactor Regulation. Director. ENGELKEN.R H Region 5, Office of Director MANEATIS, 9 A. Pecific Gas & Electric Co. 2pp. 15788 342. 24X Fiche 50-275,82/10/08,82(0250247.

8 Reportable occurrences, LERs & related correspondence

8210250055 PNO-V-82-043 on B21016.unusual event declared when grass fire started in 300 kV switchyard On B21017.three 500 kV circuits tripped:resulting in loss of all offsite power. Second unusual event declared.
STERNBERO.D.M. Region 5. Office of Director. 82/10/16. ip. 15787:100. 24% Fiche: 30-275,82/10/16,8210250035.

T Hearing transcripts on non-antitrust matters

8210290370 Unofficial transcript of 821020 public discussion of Phase II revarification program in Hashington, DC, Pp 1-113 Supporting documentation encl. # Commitationsep. 82/10/20, 144pa, 13865 095, 24X Fiche: 50-275, 82/10/20, 8210290370.

- 8210220416 Forwards transcript of Commission 821020 meeting to recalve NRC brieflag on proposed scope of Phase II of independent design verification program & 821019 meeting w/ util & perticipants re-program & 82CY-62-414 W/n encl CHILK-6 J Office of the Secretary of the Commission 82/10/21 Office of the Executive Legal Director 1p 15779 21; 24X Fiche 50-275, 82/10/21,8210220416
- DOCKET 50-324 BRUNSHICK STEAM ELECTRIC PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- 8209140148 Forwards "Fire Protection of Cable Spreading Room," evaluating quantity of translant combustibles necessary to cause ignition of most limiting cable Info supple 810304 exemption request
 HOMELP W Caroline Power & Light Co 62/09/08 DENTON, H R of Nuclear Reactor Regulation, Director 2pp 14782 001 24x
 Ficha 50-324, 82/09/08, 8209140148
- --8209140153 "Fire Protection of Cable Spreading Room" 4 Caroline Power & Light Co 82/08/31 6ip 147 Fiche 50-324,82/09/06,8209140148 14782 004 24E
- 8210060316 Forwards revised Sactions 5 & 6 to "Safe-Shutdown Capability Assessment & Proposed Hods "
 ZIMHERMAN.S R Ceroline Power & Light Co 82/10/01 DEMICN.HR
 Office of Nuclear Reactor Regulation, Director 1p 15616 033 &c
 Fiche 30-324,82/10/01,8210060316
- --8210060323 Revised Sections 5 & 6 to "Gafe-Shutdown Capability Assessment & Proposed Mods" * Carolina Power & Light Co 82/10/01 706pp 15616 034 24 Fiche 50-324, 82/10/01, 8210060316
- 8210130295 Forwards responses to BNWL & NRC Questions 1-6 re util 210130249 Forwards responses to BNML & NRC Questions 1-6 re util 820804 radiation shielding study for proposed emergency operations facility/technical support ctr Written concurrence requested by 821025
 ZIMMERNAN S R Caroline Power & Light Ca 82/10/11 VASSALLOD & Operating Reactors Branch 2 3pp 15678 240 24X
 Fichs 50-324.82/10/11.8210130295
- 8210220489 Ack receipt of 821006 ltr informing NRC of steps tales to correct violations noted in iE Insp Repts 50-324/82-30 & 50-325/82-30
 VERRELLI.D M Division of Project & Resident Progress
 UTLEY, E E Carolina Power & Light Go 1p 15777 057
 24x
 Fichs 50-324, 82/10/16, 8210220489
- --B210220492 Responds to NRC 620907 ltr re violations noted in II in Repts 50-324/62-30 & 50-325/82-30 Corrective actions technician counseled re compliance w/Maint instruction MI-10-2J Fire Protection Procedure FP-14 will be revised DIETZ, C R Ceroline Power & Light Co 62/10/06 O'REJLLY.JP Region 2. Office of Diractor 2pp. 15779 088 24X Fiche 50-324, 62/10/16, 8210220469
- --8210220496 Notice of violation from insp on 820715-0815 * Division of Project & Resident Programs 82/115779:092 24X Fiche: 50-324, 82/10/18, 8210220489
- --8210220503 IE Insp Repts 50-324/82-30 & 50-325/82-30 un 020315-083 (
 Nancomplience noted on 820805, safety-releted equipment Heist Instruction MI 10-2J incorrectly performed & Fire Protection Procedure FF-14 Step III A improperly implemented on 820718 MYERBID 0 , GARNER.L.W., CHABEJ Dlyision of Project & Reifing Programs 82/09/03, 9pp, 15779 093 24X Fiche 50-324,82/10/18 6210220489
- 8210280275 Forwards corrected pages to rept submitted in conjucties #US209275 crowards corrected pages to rept submitted in conjuting wy/820905 cable spread room examption request & Pages

 A.3-7-A 3-10 inedvartently omitted.

 ZIMMERMAN, B Carolina Power & Light Co 82/10/22 DENIGN, B R

 Office of Nuclear Reactor Regulation, Director 1p 15837 295 & Fichs. 50-324, 82/10/22, 8210280275
- --8210280278 Corrected & add1 pages to "Fire Protection of Calls Byreading Room." * Caroline Power & Light Co 82/10/22 Bpp 15837 298 20 Fiche: 50-324, 82/10/22, 8210280275

H General correspondence

8210010028 Requests NRC direct all official correspondence to EE Ulle, util vice-president, due to 820930 retirement of JA Jones JONES, J A Caroline Power & Light Co 82/09/27 DENTON: H R. Office of Nuclear Resctor Regulation, Director, ip. 15385 314 M Fiche: 50-000, 82/09/27, 8210010028

- 8210130323 Requests changes to distribution list for NUREG-0020, 'Licensed Operating Reactors - Status Summary Rept " ZIHMERMAN, S R Caroline Power & Light Co 82/10/11 BESSE, M R ADP Systems Development Branch 2pp 15683 361 24X Fiche 50-000, 82/10/11,8210130323
- P Operating license stage documents & correspondence
- 8207180044 FUIA request for all internal non-public documents, memos, evaluation repts & other matl dealing w/nuclear plant operations
 HCINNIS, D News & Observer 82/08/17 Office of Administration ip 15860 064 24X Fiche 50-000,82/08/17,8207180044
- 6210040006 Forwards revised Tech Specs to Amend 72 to License DPR-62. correcting errors in total peaking factor values for Cycle 5.
 VASSALLO.D B Operating Reactors Branch 2 82/08/30 JONES, J A Carolina Pawer & Light Co 2pp 13577 275 24X
 Fiche 50-324, 82/08/30, 8210040006
- --8210040007 Revised Yech Specs to Amend 72 to License DPR-62, correcting errors in total peaking factor values for Cycle 5

 Operating Reactors Branch 2 82/08/30 1p 15577 277 24X
 Fiche 50-324,82/08/30,8210040005
- 8210120626 Advises that proposed interim changes for shift technical advisor training program acceptable up to Apr 1983 VASSALLO, D B Operating Reactors Branch 2 82/09/15 JONES, J A Carolina Power & Light Co 3pp 18672 266 24X Fichs 50-324, 82/09/15, 8210120626
- 8210280013 Responds to FOIA request for all internal, non-public documents, memos, evaluation repts & other mati dealing w/ nuclear plant operations Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/09/17 MCINNIS, D News & Observer 5pp 15840 065 24X Fiche 50-000, 82/09/17, 82:1038013
- --7903270357 Augmented offgas sys shall be used at all times & util should be informed CCLLINS.J T Effluent Treatment Systems Branch 79/05/03 TPPOLITO.T A Operating Reactors Branch 3 (Pre 790525) 1p 15860 087 24X Fiche 50-000.82/09/17.8210280013
- --7912280014 Advises of util 791025 interim commitment for demonstrating compliance w/40CFR190 Commitment acceptable, but must include direct radiation per section 6 of NUREGO-0473. Revision 2 DANOARTER Effluent Treatment Systems Branch 79/11/23 IFPOLITÜ.T Operating Reactors Branch 3 (Pre 800428) 1p. 19860 088 24K Fichs 80-000,82/09/17,8210280013
- --B101140002 Confirms B01126 telcon re possible willful violation of reporting requirements IE lacks specific details necessary to make referral determination WARD. W J Office of Inspection & Enforcement, Office of the Director B0/12/02 FORTUNA; R Office of Inspector & Auditor ip 15860 055 24% Fiche: 50-000, 82/09/17, 8210280013
- --81 04290774 Notifies that applicant should be informed that major change to raduaste treatment sys will require 100FRSO 90 review Requests info to show conformance w/App I & mod can mest acceptance criteria of BRP in NUREO-0800 GAMMILL-W P Effluent Treatment Bystems Branch 81/04/06 EPPOLITO.T A. Operating Reactors Branch 2. 1p. 15860-226 24X Fishs 50-000,82/09/17,8210280013
- --81 12020685 Forwards request for add1 licenses info re proposed second expansion of spent fuel pool & estimate of vol of solid waste generated by scrapping existing racks Info needed by 811118

 KRECER.W.E. Assistant Director for Radiation Protection 81/10/27. NOVAK.T. Assistant Director for Operating Reactors 2pp 15860 231 24X Fiche. 50-000, 82/09/17, 8210280013
- --- 31 12300287 Forwards Efficient Trantment Sys Branch safety evaluation input re spent fuel pool expansion application.per review of util 800416 submittal KREOSR. W E Assistant Director for Radiation Protection 81/11/27. NOVAK, T M Assistant Director for Operating Reactors. 13pp 15860 249 24% Fiche 50-000,82/09/17,8210280013
- --B2011202B0 Advises that Billi2 ltr recommended improvement of dose impact calculation methodology & licensee accepted by Bill25 ltr Other edit changes assured new methodology use every 31 days & nuclide dose factor inclusion in BTB.

 @AMMILL.W P Radiological Assessment Branch Bi/12/08 FPFOLITO: T A Operating Reactors Branch 2 ip. 15840 264 Piche 50-000, 82/09/17, 8210280013

- --8203080197 Advises that replacing Phrase 12 "Consecutive Months" w/phrase "Calendar Yr" in Tech Bpec 2.5.2 b acceptable Change would reduce recordseeping HDUSTON, R W Assistant Director for Radiation Protection 82/02/11 NDVAX, T M Assistant Director for Operating Reactors 2pp 15861 014 24X Fiche 50-000, 82/09/17, 8210280013
- --8205170128 Advises that revise of NUREO-0737, Itsm II F 1, has been satisfactorily completed & considered closed HQUSTON, R W Assistant Director for Radiation Protection 82/04/16 NOVAK, T M Assistant Director for Operating Reactors. 1p 18861 040 24% Fichs 50-000, 82/09/17, 8210280013
- --8206220591 Submits background info on conversation w/util re 820116 loss of RHR syc water event at facility.LER 82-005/01T MOLF.T R Director's Office 82/06/04 RUBIN.9 Director's Office 5pp. 15861 326 24X Ficher 50-000.82/09/17.8210280013
- --8207120140 Trip rept of 820324 visit to facility re aquipment environ qualification problems List of site visit/meeting participants & related info encl EL-ZEFTANY.M., WOLF, T R Director's Office 82/07/06 KICHELSON.C Director's Office 12pp 15861-314 24X Fiche 50-000,82/09/17.8210280013
- --8210280021 Recommends that facility content activity limits be changed to conform w/STS
 EISENBUT.D C. Division of Operating Reactors 74/07/04.
 GDLLER, K.R. Assistant Director for Operating Reactor Projects (Pre 771030). 3pp 15560 074 24X Fiche 50-000,82/07/17,8210280013
- --8210280024 Advises that util 780518 response re proposed plans for correcting problems concerning augmented offgas (vs. unacceptable Effluent Tech Specs should be amended COLLING.) T Effluent Treatment Systems Branch 78/06/02 LEAR.G Operating Resctors Branch 78/06/02 (Pre 800429) 2pp 15360 077 24X Fiche 50-000.82/09/17.8210280013
- --8210280027 Notifies that commitment schedule for implementing operable augmented offgas sys unacceptable Thermal recombinate for use in BMR offgas sys will not satisfy criteria COLLING, JT Effluent Treatment Systems Branch, 78/09/06 (PPDLITO, T Operating Reactors Branch 3 (Pre 800428) 3pp 15860 079 24% Fiche 50-000,82/09/17,8210280013.
- --8210280031 Requests technical assistance to review recent events at facilities & to assess safety & environ significance STELLO, V Division of Operating Reactors, 78/08/03 MULLER, D Division of 81te 8afety & Environmental Analysis 2pp. 13860.084 24% Fiche 50-000.82/09/17,8210280013
- --8210280047 Notifies that potential for criminality found re Region 4 investigation resulting from W Ward 801202 mema constraing facility FORTUNA: R A Office of Inspector & Auditor 80/12/03. Office of Inspector & Auditor 80/12/03. Office 82/09/17.8210280013
- --8210280095 Assumes responsibility for review of Case 81-17 for criminality No criminality indicated Case should be closed.

 BMITH, R M Office of Inspector & Auditor. 82708/24 Office of Inspector & Auditor. 82708/24 Office of September 1986 Office 07 Offi
- --8210280100 Notifies that on 820224.C Alderson advised that rept sent repossible willful violation of reporting requirements & faisification of QA & guard qualification records at facilities

 RESNER, M E Office of Inspector & Auditor 82/03/01 Office of Inspector & Auditor. 1p 15861 039. 24X Ficks. 50-000. 62/09/17. 6210280013.
- 8210010051 Atk receipt of 820823 ltr requesting temporary relief from commitments re-training of shift technical advisors. Program approved & request forwarded to NRR for evaluation O'REILLY, JP. Region 2. Office of Director 82/09/20 JONES, J. A Carolina Power & Light Co. 1p 15565:322, 24x Fiche 50-000, 82/09/20, 8210010051
- 8210050362 Application to amend Licenses DPR-71 & DPR-62, revising Tach Specs to clarify requirements for verifying operability of scram discharge vol vent & drain valves. Class I & II license amend fees and EURYL W Carolina Power & Light Co 82/09/29, VASBALLO, D B Operating Reactors Branch 2 2pp 15609:345 24X Fiche 50-384, 82/09/29, 8210050362
- --B21005037i Prposed Tech Spec 4. i. 3. i. ir a surveillance requirements verifying operability of scram discharge vol vent & drain valves.

 W Carolina Power & Light Co 82/09/27 2pp 15608.347 24X Picha: 50-324, 82/09/27

- 8210290110 Advise: that plant venting capability acceptable to resolve NUREO-0737. Thi item ii B i re high point vente VASSALLO, D B Operating Reactore Brench 2 62/10/01 JONES, J A Carolina Power & Light Co 3pp 15866 338 24X Fithe 50-324,82/10/01,8210270110
- --8210290113 "Operating Reactors TMI Lessons Learned, NUREC-0737 Response Evaluations (Program II):Project 1, RCB Vents for Brunswick 1 & 2," final technical evaluation rept Laurence Livermore Laboratory FIN A-0246-2 82/07/15 BUTCHER.E., BARNHART, B. Division of Licensing 4pp 15866 341 24X Fiche 50-324, 82/10/01.8210290110
- 82:0150030 Forwards submittal echedule for responses to NRC 820909 issues re TM1 Action Items II F 1.4,5 & & & II E 4 2 7. Tech Spec revisions, containment vent & purge, electrical distribution sys voitages & control of heavy loads IMMERMAN, S. R. Carolina Power & Light Co. 82/10/12 VASSALLO, D. 3 Gperating Reactors Branch 2 2pp 15701-268 24X Fiche 50-324, 62/10/12, 62:0150030
- 8210260244 Advises that response to NRC 820827 request to justify differences between existing central room & NUREO-0737, Item III D 3 4 suggestions will be provided by 830101. Requests re-evaluation of improvement cost-benefits EURY, L B Carolina Power & Light Co 82/10/21 VASSALLO. D 8 Operating Reactors Branch 2 1p 15799 353 24X Fiche 50-324, 82/10/21, 8210260244
- B210260323 Application for amend to Licenses DPR-71 & DPR-62.clarifying portions of B10021 submittal re hydraulic snubber surveillance EVRY.L H Carolina Power & Light Co B2/10/21 VASBALLO.D B Operating Reactors Branch 2 2pp 15799 338 24X Fiche 50-324.82/10/21.8210260323
- --8210760325 Revised Tech Specs re hydraulic snubber survaillance * Carolina Power & Light Co 82/10/21 2pp 15799 340. 24) Fiche 50-324,82/10/21.8210260323
- 8210260405 Hithdraws request for amend to Licenees DPR-71 & DPR-62, revising Tech Spec re reportability of imoperable reed switches in rod position indication sys to reduce number of routine LERs EURY-L H Carolina Power & Light Co 82/10/22 VASSALLO.D B Operating Reactors Branch 2 2pp. 15806-239, 24X Fiche 80-324, 82/10/22, 8210260405
- ~-8210260410 Proposed revisions to Tech Spec 6 9 i re monthly reportability of safety/relief valve challenges. Tech Spec supersedes 820407 eubmittal.

 * Carolina Power & Light Co 82/10/22 2pp. 15806 241 24X Fithe. 50-324,82/10/22,8210260405
- Q inspection reports: IE Bulletins & correspondence
- 8210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J M Division of Ruise and Records, 82/07/12 UDELL.R A Critical Mass Energy Project 9pp, 15665.027 24X Fichs 30-000.82/07/12.8210080015
- --B210080122 By stematic assessment of licensee performance notes refacility evaluation for Apr 1979-Har 1980.

 NRC No Detailed Affiliation Given 80/03/31 Apr 15667 S21 24% Fiche 50-000, 82/07/12, 8210080015.
- B210010132 Forwards IE Insp Repts 30-324/B2-31 & 50-325/B2-27 on B20809-13 No noncompliance noted VERRELLI.D.H Division of Project & Resident Programs 82/09/01, JONES, J.A. Caroline Power & Light Co. 2pp 15567:230. 24X Fiche: 50-324, 82/09/01, 8210010132
- --B210010137 IE Inep Repts 30-324/B2-31 & 50-325/B2-29 on B20B09-13 No noncompliance noted Major areas inepected ALARA radipactive matl transportation radioactive liquid effluent monitoring & natl control ALBRIOHT, R. H. BARR, K. P. Division of Engineering & Technical Programs 82/08/31 5pp. 15567 232. 24X Fiche 50-324, B2/09/01, B210010132
- 8210010112 Forwards eummary of 820824 enforcement meeting at Region 2 ofc restatus of action items contained in 820702 & 20 confirmation of action itrs
 0'REILLY, J.P. Region 2, Office of Director. 82/09/03 JONES, J.A. Carolina Power & Light Co. 1p. 15356-029 24x
 Fiche 50~324,82/09/03,8210010112

- ---8210010126 Summary of 820824 meeting w/util in Atlants, GA re status of action items contained in 820702 & 20 confirmation of action ltrs Util committed to formally submit long-term program details in Nov 1982

 LEMIS.R C Division of Project & Resident Programs 82/09/03

 Division of Project & Resident Programs 2pp 15366 030 243

 Fiche 50-324,82/09/03.8210010112
- 8210010170 Ack receipt of 820816 response to 820716 notice of violating & proposed imposition of civil penalties Rept on major program objectives to be submitted by 82101 should provide sufficient info re testing aspects of training programs AXELRAD, J Enforcement 81aff 82/09/15 JONES, J A Carolina fc.st & Light Co 2pp 15568 109 24X Fiche 50-325,82/09/15,8210010172
- --8210010193 Forwards IE Inep Repts 50-324/82-02 & 50-325/82-02 ep 820104-07. Enforcement action addressed to util (n. 820715 ltr.

 LEHIS,R C Division of Project & Resident Programs 82/07/18
 JONES, J A Caroline Power & Light Co 2pp 15568 124 24X
 Fiche 50-325,82/09/15,8210010170
- --8210010205 IE insp Repts 50-324/82-02 & 50-325/82-02 on 820105-07 Noncompliance noted Unit 1 instrument D-1 inoperable & level channel not tripped between 811225-31 OARNER, L., JULIAN. C., BURGER, C. Division of Project & Resident Programs 82/05/13 App 15568 126 24K Fichs 50-325,82/07/11 8210010170
- 8210010171 Ack receipt of B20702 & 0903 ltre informing NRC of strysteen to correct violations noted in IE Insp Repts 50-324/82-18 & 50-325/92-18 VERRELLI, D M Division of Project & Resident Programs 82/09/16 JONES, J A Carolina Power & Light Co ip 15568 091 241 Fiche 50-324, 82/09/16.8210010171
- --82:0010183 Suppls 820702 response to NRC 820604 ltr rs violations in IE Insp Repts 50-324/82-18 & 50-325/82-18 Corrective actions responsible operators counseled & 1A-1 battery charges clearance removal reviewed DIETZ.C R Carolina Power & Light Co 82/09/03 G'REILLY.J P Region 2. Office of Director. 3pp 15568 092 24X Fichs 50-324,82/09/16.8210010171
- --8210010188 Reeponds to NRC 820604 ltr re violations noted in IE 1-4; Repte 50-324/82-18 & 50-325/82-18 Corrective actions double verification program established on 820601 DIETZ.C R Carolina Power & Light Co 82/07/02 O'REILLY.J F Region 2, Office of Director 2pp 15568 095 24X Fiche 50-324,82/09/16.8210010171
- --B210010194 Forwards 1E inep Repts 50-324/82-18 & 50-323/82-18 4s 820415-0515 & notice of violation LDNO,F.J Division of Project & Resident Programs B2/05/04-UDNES,J A. Carolina Power & Light Co 2pp 15568 097 241 Fichs. 50-324, B2/09/16, B210010171
- --8210010199 Notice of violation from insp on 820415-0515 * Region 2, Office of Director 82/06/04 ip 15568 099 241 Fiche 50-324,82/09/16,8210010171
- --8210010205 IE Inep Repts 50-324/82-18 & 50-325/82-18 on 920415-05.1 Noncompliance noted Operating Procedure OP-43 & tap resort for Clearance 1-459 inadequately implemented MYERB, D O , GARNER, L W , BURGER, C W Division of Project & Resident Programe 82/06/04, 9pp 15568 100 24X Fiche, 50-324,82/09/16,821001071
- 8210010336 Advisee that 1E Insp Rept 50-325/82-36 was insystently labeled 50-325/82-30 VERRELLI, D M. Division of Project & Resident Programs 82/09/16 JONES J A. Caroline Power & Light Co 1p 15571 001 241 Fichs: 50-324, 82/09/16, 8210010336
- --8210010340 Forwards IE Insp Repts 50-324/82-32 & 50-325/82-35 to 820824-27. No noncompliance noted VERRELLII.D. M Division of Project & Resident Progress 62/07/3 JONES, J A Carolina Power & Light Co 2pp 15378 002 287 Fichs: 50-324/82/09/16/8210010336
- --B210010350 IE Insp Repts 50-324/82-32 & 50-325/82-36 on B20024 27 & noncompliance noted. Major areas inspected, pre-startup reviews, corporate nuclear sefety reviews, post-maint testing & plant mods involving Tech Base changes FREDRICKSON,P.; JACKSON,L. H.; UPRIGHT,C.M. Division of Engineer & Technical Programs. 82/09/10 4pp 15571 004 24% Fiche: 50-324,82/09/16,8210010336

- 8210010391 Ack receipt of 820907 ltr informing NRC of etepe taken to correct violations noted in IE insp Repts 50-324/82-25 & 50-325/82-25
 - EBNIS.R C Division of Project & Reeident Programs 82/09/22 JONES J A Carolina Power & Light Co ip 19572 269 24X Fiche 50-324.82/09/22.82i00i0391
- --B210010399 Responde to NRC B20B13 ltr re violations noted in IE Insp. Repts 50-324/82-25 & 50-325/82-25 Corrective actions plant operating procedures rewritten & signoffs added Operations engineer responsible for procedure changes
 DIETZ.C.R. Carolina Power & Light Co. 82/09/07 O'REILLY, J.P. Region 2. Office of Director 2pp 15572 270 24X
 Fische 50-324, 82/09/22, 82/0010391
- --B210010405 Forwards IE lnsp Repts 50-324/82-25 & 50-325/82-25 on B20615-0715 & notice of violation LEWIS.R C Division of Project & Resident Programs B2/0B/13 JONES.J A Carolina Power & Light Co Zpp 15572 272 24X Fiche 50-324.82/09/22.8210010391
- --8210010410 Notice of violation from insp on 820615-0715 * Division of Project & Resident Programs 82/08/13 2pp 15572 274 24X Fiche 50-324, 82/09/22,8210010391
- --B210010415 IE Insp Repts 50-324/82-25 & 50-325/82-25 on B20615-0715 Noncompliance noted failure to implement & maintain operating procedures for startup & shutdown HYERS,D O . OARNER,L W . STETKA,T Division of Project & Resident Programs B2/08/12 i3pp 15572 276 24X Fiche 50-324,82/09/22,8210010391
- 32:0150100 Ack receipt of 820913 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-324/82-26 & 50-325/82-28 LEHIS, R C Division of Project & Resident Programs 82/09/24 JONES, J A Carolina Power & Light Co ip 15701 164 24X Fiche 50-324,82/09/24,8210150100
- -8216150106 Responds to NRC 820817 itr re violations noted in IE linsp Repts 50-324/82-26 & 50-325/82-26 Corrective actions new comprehensive post-teeting program being developed DIETZ.C R Carolina Power & Light Co 82/09/13 O'REILLY, J P Region 2, Office of Director 2pp 15701 165 24X Fichs 50-324,82/09/24,8210150100
- 9210150113 Forwards IE Insp Repts 50-324/B2-26 & 50-325/B2-26 on 820712-16 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/08/17 JUNES.J A Carolina Power & Light Co 2pp 15701 167 24X Fiche 50-324,82/09/24,82/0150100
- -8210150120 Nutice of violation from insp on 820712-16 + Division of Project & Resident Programs 82/08/17 2pp 15701 169 24X Fiche 50-324, 82/09/24, 8210150100
- -8210150132 lE Insp Repts 50-324/82-26 & 50-325/82-26 on 820712-16.

 Noncoopliance noted failure to provide measures to preclude bypassing required testing

 ENINNER, P H , JACKSON, L H , UPRIGHT, C M Division of Engineering & Technical Programs 82/08/19 7pp 15701-171 24X

 Fiche 50-324,82/09/24,8210150100
- 210150108 Forwards IE Inep Repte 50-324/82-35 & 50-325/82-35 on B20908-10 Na noncompliance noted VERRELLI,D H Division of Project & Resident Programs B2/09/24 JGNES,J A Carolina Power & Light Co 2pp 15701 149 24X Flohe 50-324,82/09/24,8210150108
- -8210150144 lE Inep Repts 50-324/82-35 & 50-325/82-35 on 820908-10 No noncompliance noted Major areae inspected review & evaluation of changes to inservice insp program & program for document control & data retention COLEY, J L., BLAKE, J J Division of Engineering & Technical Programs 82/09/21 Gpp 15701 151 24X Fiche 50-324,82/09/24,82(0150108
- 210150162 Forwards IE Insp Repts 50-324/82-33 & 50-325/82-31 on B20901-03 & 10 No noncompliance noted Programs B2/09/24 VERRELLI, D M Division of Project & Resident Programs B2/09/24 VONES-J A Carolina Power & Light Co 2pp 15707-304 24X Fiche 50-324,82/09/24,8210150162
- -B210150170 IE Insp Repts 50-324/82-33 & 50-325/82-31 on 820701-03 & 10. No noncompliance noted Major Arese inspected IE Bulletin 79-14. "Seismic Analysis for As-Built Bafety-Related Piping Bys "

 ANO. W P , BLAKE, J Division of Engineering & Technical Programs 82/09/23 5pp 15707 306 24X Fiche. 50-324, 82/09/24, 8210150162

- 8210150008 Ack receipt of 820819 & 0915 itrs informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-324/82-23 & 50-325/82-23 LEWISI.R.C Division of Project & Resident Programs 82/09/30 JONES. J.A. Cercline Power & Light Co. ip 15698 349 24X Fiche 50-324.82/09/30.8210150008
- --8210150016 Revises response to NRC ltr re violatione noted in IE Insp Repte 50-024/82-23 & 50-029/82-23 Corrective actions assessment of inservice insp program in progress Violation will be fully addressed by 821231 DIETZ.C R Carolina Power & Light Co 82/09/15 D'REILLY.J P Region 2. Office of Director 2pp 15698 350 24X Fiche 50-024,82/09/30,8210150008
- --8210150023 Responds to NRC 920719 itr re violations noted in 1E Insp Repts 50-324/82-23 & 50-325/82-23 Corrective actions post-maint testing program revised & inservice insp program under review DIETZ-C R Carolina Power & Light Co 82/08/19 O'REILLY, J P Region 2, Office of Director 3pp 15698 352 24X Fiche 50-324,82/09/30,8210150008
- --8210150034 Forwarde IE Inep Repte 50-324/82-23 & 50-325/82-23 on 820615-18 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/07/i9 JONES.J A Carolina Power & Light Co 2pp 15698.355 24X Fiche 50-324,82/09/30,8210150008
- --B210130040 Notice of violation from insp on B20615-18 LEMIS.R.C Division of Project & Resident Programs 82/07/19 2pp. 15698 337 24X Fiche 50-324.82/07/30, B210150008
- --82i0150063 IE Insp Repts 50-324/82-23 & 50-325/82-23 on 820615-18
 Noncompliance noted failure to re-establish baseline data
 for RHR evc water pump & to include main steam giping in
 inservice insp program
 BLAKE J. J. ECONOMOB. N Division of Engineering & Technical
 Programs 82/07/15 4pp 15698 359 24X Fiche 50-324,82/07/30,
 8210150008
- 8210220139 Forwards IE Insp Repts 50-324/82-38 & 50-325/82-38 on 820907-10 No noncompliance noted. VERELLI, D M Division of Project & Resident Programs 82/10/04 JONES, J A Carolina Power & Light Co 2pp 15778 107 24X Fiche: 50-324, 82/10/04, 8210220139,
- --B2i0220147 IE Insp Repte 50-324/82-38 & 50-325/82-38 on 820707-10 No nancompliance noted Major areas inspected followop insp of NRC & licensee identified tasks to be completed prior to startup WHITENER, H L , KRUO, H E , JAPE, F Division of Engineering & Technical Programs 92/09/30 5pp 15778 109 24X Fiche 50-324,82/10/04/8210220139
- 8210220169 Forwards IE Insp Repts 50-324/82-36 & 50-325/82-33 on 820815-0915 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/10/04 JDNES, J A Carolina Fower & Light Co. 2pp 19778.045, 24X Fichs: 50-324, 82/10/04, 8210220169
- --8210220173 IE lasp Repte 50-324/82-36 & 50-325/82-33 on 820815-0915 No noncompliance noted Major areas inspected review of LERs, operational safety verification & audit of surveillance & maint activities.

 MYERS, D. O. OARNER, L. W., BURGER, C., Division of Project & Resident Programs. 82/10/01 8pp. 15778 047 24X Fiche: 50-324,82/10/04,8210220169
- 8210130036 Ack receipt of 820816 & 0924 itre informing NRC of steps taken to correct violations noted in IE insp Repte 50-324/82-20 & 50-325/82-20.

 LEWIS,R C. Division of Project & Resident Programs, 82/10/05.

 JONES, J. A. Carolina Power & Light Co ip 15701:135 24X Fiche, 50-324, 82/10/05, 8210150036.
- --921015003B Supple 820816 response to NRC 820719 ltr re violations noted in IE lnep Repts 50-324/82-20 & 50-325/82-20 Add1 info re revision to Procedure GGAD 80-1 to assure timely corrective actione to future audit findings provided.

 DIETZ, C. R. Carolina Power & Light Co. 82/09/24 O'REILLY, J. P. Region 2, Office of Director. 2pp 15701:136. 24X
 Fichs 50-324,82/10/05,8210150036
- --8210150045 Responds to NRC 820717 ltr re violations noted in IE Insp. Repts 50-324/82-20 & 50-325/82-20 Corrective actions. Procedure CGAD 80-i revises & frequency of plant audits increased to reduce audit ecope. DIETZ.C.R. Carolina Power & Light Co. 82/08/16. 0/REILLY.J.P. Region 2. Office of Director 3pp 15701.138 24X Fiche.50-324,82/10/05,8210150036

- 8210150048 Forwards IE Insp Repts 50-324/82-20 & 50-325/82-20 on 820807-08 & notice of violation W/o hotics of violation LEMIS.R C Division of Project & Resident Programs 82/07/19 JONES.J A Carolina Power & Light Co 2pg [5701 141 24X Fichs. 50-324,82/10/05,8210150036
- -8210150052 IE Insp Repts 50-324/82-20 4 50-325/82-20 on 820407-08 Nancomplience mated failure to establish measures to assure groups corrections to adverse GA conditions & failure to distribute audit within required timeframs BELISLE, GA, UPRIONT, CM Division of Engineering & Technical Programs 82/07/15 4pp 15701 143 24X Fache 50-324,82/10/03,8210150036
- 8210150288 Ack receipt of 820714 ltr informing NRC of steps teken to carrect violations noted in 1E Insp Repts 50-324/82-21 & 30-324/82-21 VERRELLI.D M Division of Project & Resident Programs 62/10/05 JDNES, J A Carolina Power & Light Co Ip 15704 126 24X Fichs 50-324: 82/10/05.8210150288
- --8210150295 Responds to NRC 820818 ltr re violations noted in IE Insp Repts 50-324/82-2: % 50-325/82-2: Corrective actions relief valves which can communicate w/primary containment added to Type C testing program & review of leakage continuing DIETZ-C R Carplina Power & Light Co 82/09/14 J'REILLY, J P Region 2. Office of Director 2pp 15706 127 24X Fichs 50-324,82/10/05,8210150288
- B208190233 IE Info Notice 80-35. Suppl 1, "Leaking & Dislodged I~125 implant Sadds " Svc list and! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fichs 50-000.82/10/04.8208190233
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter: Stainless Steel Recirculation Bys Piping at BWR Plants " Svc list encl DEYDUNG-R C Director's Office. Office of Inspection and Enforcement 82/10/14 Canadidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14:820819033B
- 8210220489 Ack receipt of 821006 ltr informing NRC of steps taken to correct violations noted in lE linep Repts 50-324/82-30 & 50-323/82-30
 VERRELLI, D M Division of Project & Resident Programs 82/10/18
 UTLEV.6 E Caroline Power & Light Co (p. 15777-087-24X
 Fiche 50-324,82/10/18,8210220487
- --82i0220492 Responds to NRC 820907 ltr re violations noted in IE Insp Repts 50-324/82-30 & 50-325/82-30 Corrective actions technician counseled re compliance w/Maint instruction MI-IO-2J fire Protection Procedure FP-14 will be revised DIETZ.C R Carolina Power & Light Co 82/10/06 G/PEILLY.J P Repien 2. Odfice of Director 2pp 15777 098 24X Fichs 50-324,82/10/18.6210220489
- ~-B210220494 Forwards IE Insp Repts 50-324/B2-30 & 50-325/B2-30 on 820715-0915 & notice of violation VERRELLI,D M Division of Project & Resident Programs B2/09/07. JONES: J. A Carolina Power & Light Co 2pp 15779 090 24X Ficha: 50-324, B2/10/18, 8210220489
- --8210220496 Notice of violation from insp on 620715-0015 * Division of Project & Resident Programs, 62/09/07 1 18779, 092 24X Fiche; 50-324, 82/10/16, 8210220499

311

1

标

11

- --B2i0220503 IE insp Repts 50-324/B2-30 & 50-325/B2-30 on 820715-0815
 Noncompilance noted:on B20805.safety-related aquipment Maint
 Instruction KI 10-2J incorrectly performed & Fire Protection
 Procedure FP-14 Step III A improperly implemented on B20718
 MYERS.D D , GARNER.L.N , CHASE.J. Division of Project & Resident
 Programs 82/09/03 9pp 13779 093. 24X Fichs 50-324,82/10/18,8210220489
- S Reportable occurrences, LERs & related correspondence
- 8210150291 Forwards LER 81-015/03L-0.
 DIET7.6.R Garolina Power & Light Co 81/02/27 HAYNES.J P.
 Ragion 2. Atlanta. Office of the Director (81/03/01) ip.
 15706.129. 24X Fiche:30-324.81/02/27.8210150291.
- --B210180308 LER B1-016/03L-0:on B10207, primary containment atmospheric organ analyzer indicated upscale Caused by deterioration of inlet robber tobing due to ago, allowing ambient sir to enter & mix w/analyzer sample flow PABTVA.M.J Carolina Power & Light Co B1/02/27. Region 2, Atlanta, Office of the Biretter (81/03/01) 2pp 15706/130. 24% Fiche 50-324,81/02/27,8210150271.

- 8210150041 Forwards LER 81-032/03L-0
 0/EFT2.C & Carolina Power & Light Co 81/03/25 0'REILLY.J P
 Region 2. Atlanta. Office of the Director (81/03/01) 3p
 15701 132 24X Fiche 50-324.81/03/25.821015004
- --9210150046 LER 81-032/03L-0 on 810223 while performing requires in as result of diesel generator 2 being out of svc for maint diesel generator 3 declared inoperable due to low control air pressure Caused by misaligned valve disc PASTVA: N U Caroline Power & Light Co G1/03/25 Regist 2 Atlanta, Office of the Director (81/03/01) 2pp 13701 133 & Fishe 50-324,81/03/25,8210150041
- RZ(0070416 Telp rapt of 810617 site visit to collect info #s loss #f
 RHR Baffle plate dividing water box of RHR HX 1A failed
 allowing svc water to bypass HX tubes Caused by escapaive
 differential pressure across baffle plate.
 IMBRO.E., GIANELLI.J. Director's Office 81/07/22 Director's
 Office 19pp 15637 308 24X Fichs 50-324.81/07/22,0216070415 :
- 8210070442 Discusses 810714 dissel generator trip caused by operalerror Operator did not munitor jacket water temp during adjustment of temp control manuel bypass valve LgR did not contain sufficient info Further action recommended CHIRAMAL.M Director's Office 81/12/07. MICHELBON.C Direct. Office 1p 15637 345 24X Fiche 50-324, 81/12/07, 8210070442
- S210010008 Responds to FOIA request for 19 catagories of dotuments nuclear reactor events & safety problems Forwards documents listed in App A
 FELTON. J H Division of Rules and Records 82/06/20 UrELL. Ps Critical Mass Energy Project 15pp 19727 005 24x Fishe 50-000 82706/28 8210010008
- --BiO730016B Discusses findings gathered during Blo617 sets visus to facility loss of RHR capability during Apr & May 1981 Unit has committed to mod of wash screen wash sys by 1982 Attendance list-chiorinator outage info & drawings end 18MBRO.E Director's Office Bl/07/22 Director's Office Bl/07/22 Director's Office 1999 15730 056 24% Fiche 50-000.82/06/28,8210010903
- B209130164 "Brunswick Nuclear Power Station Unit 2 Loss of RHR 1.1 Water on B20116 Engineering Evaluation Rept "
 WOLF, F.R. Reactor Operations Analysis Branch B2/08/31 12;;
 13611 263 24% Fiche 50-324,88/08/31,8209150164
- 8210010170 Ack receipt of 820816 response to 820716 notice of var's & proposed imposition of civil penalties Rept on major program objectives to be submitted by 821101 should provide sufficient info re testing aspects of training programs AXELRAD, J Enforcement Staff 82/09/15 JONES, J A Caraller & Light Co 2pp 15568 109 24X Fiche 50-325, 82/09/15, 8210; T
- --B210010205 IE Insp Repts 50-324/B2-02 & 50-325/B2-02 on G20105.11
 Noncompliance noted Unit 1 instrument D-1 inoperable & Isvet channel not tripped between 811226-31
 OARNERIC , UULIAN.C , BURGER C Division of Project & Resting Programs 82/05/13. App 15568 126 24K Fiche 50-325.82%
- 8210010298 Forwards updated LER 82-083/03L-1.
 DIETZ, C R Cerolina Power & Light Co 82/09/21 O'REFLLY, JF Region 2. Office of Director ip 15568; 325, 24X Fich*. 50-324, 82/09/21, 8210010298
- --8210010303 Updated LER 82-083/03L-1 on 820715, performance of NI revealed that drywell to torus vacuum breakers XIBA.C bit were leaking excessively, Caused by accumulation of dirk. scale & silicone base sealant on valve seating surfaces PABTVA:M J Carolina Power & Light Co 82/09/21 Regist Office of Director, 1p 15568-326 24X Fiche \$0-328,827077.
- 8210010473 Forwards LER 82-107/03L-0 DIETZ, C.R. Carolina Power & Light Co 82/09/24, B'AELLY-Jf Region 2: Office of Director 1p 18572-170 24X Fiche 50-324:82/09/24,821001043
- --B210010475 LER 82-107/03L-0. on 820826; review of fire proteines of dioxide sys surveillance procedures indicated storage hits weighing device had not undergone periodic calibr Caviel by failure to recognize accuracy restraint needs. PABTVA: M. J. Carolina Power & Light Co. 82/09/24 Regue? Office of Director. ip. 15572 171, 24X Fiche: 50-324,827672 8210010473

- 8210060320 Forwards updated LER 82-107/03L-1 DIET7.C R Carolina Power & Light Co 82/07/29 O'REILLY, J P Region 2. Office of Director 1p 15619 015 24X Fiche 50-324,82/09/29,8210060320
- --8210060327 Updated LER 82-107/03L-1 on 820826; review of fire protection carbon discade says surveillance procedures indicated storage bottle weighing device did not have periodic calibr Caused by failure to recognize need for accuracy restraints.

 PASTVA:N J Carolina Power & Light Co 82/09/29 Region 2, Office of Director Ip 15619 016 24% Fiche 50-324, 82/09/29, 8210060320
- 5210080221 Forwards LER 82-095/03L-0
 DIETZ.C R Carolina Power & Light Co 82/09/29 O'REILLY.J P
 Region 2. Office of Director 1p 15638 047 24X
 Fiche 50-324,62/09/29,6210080221
- --8210080230 LER 82-095/03L-0 on 820903, discovered that most recent 1LRT esceeded specified testing interval Caused by improper scheduling Scheduling program revised to reflect correct scheduling criteria PASTVA.M J Carolina Power & Light Co 82/09/29 Region 2, Dffice of Director ip 15638 048, 24X Fiche 50-324,82/09/29, 8210080221
- B210190754 Forwards LER 82-106/03L-0 Detailed event analysis encl DIETZ.C R Caroline Power & Light Co 82/10/08 O'REILLY.J P Region 2. Office of Director 2pp 15737 097 24X Fiche 50-324. B2/10/08. B210190754
- --8210190762 LER 82-106/03L-0 on 820917, while reviewing surveillance procedures, determined that emergency bus degraded voltage channel function test not sufficient to verify operability of emergency bus degraded voltage relays Test revised PASTVA.M J Carolina Power & Light Co. 82/10/08 Region 2, Office of Director Ip 15737 099 24X Fiche 50-324,82/10/08,8210190754
- 82:0190300 PND-II-92-109 on 921010.steam & water leak of 20 to 40 gallons per minute found in crecked weld of nonsafety-related heater drain pipe Plant shut down 80s 2-D could not be manually transferred from generator to transformer HEHL-C W , BURGER, C W Region 2, Office of Director 82/10/12 2pp 15742 159 24X Fiche 50-324,82/10/12,8210190300
- 8210190559 PND-II-82-110 on 821010 relief valve failed to reclose after testing w/reactor critical Reactor manually scrammed & unusual event declared Caused by failure of actuation solenoid Unit in cold shutdown during repairs.

 HEPL.C W , BURGER.C W Region 2, Office of Director. 82/10/12 lp 15737 146 24X Fiche 50-324,82/10/12,8210190659
- 8210260269 Forwards corrected LER 82-108/03L-0 DIETZ.C R Carolina Power & Light Co 82/10/14 O'REILLY, J. P Regison 2. Office of Director ID 15803 226 24X Fiche 50-324.82/10/14.8210260269
- --B210260318 Corrected LER 92-10B/O3L-0 on B20921 discovered fire house station RM-49 inoperable due to disconnected hose Cause unknown Hose reconnected Retraining programs will be revised to stress correct use of fire fighting equipment PASTVA.M J Carolina Power & Light Co B2/10/14 Region 2. Office of Director 2pp 15803 227 24% Fiche 50-324,82/10/14,8210260269
- 8210190748 Forwards LER 82-108/03L-0 DIETZ.C R Capolina Power & Light Co 82/10/15 D'REILLY, J. P Region 2. Office of Director ip 15737, 083. 24X Fiche 50-324, 82/10/15, 8210190748
- --E210190759 LER 82-108/03L-0 on 820921, fire hose station RW-49 inoperable due to disconnected fire hose Cause not stated Hose reconnected Employees instructed re use of fire fighting squipment for nonemergency use PASTVA. M J. Ceroline Power & Light Co 82/10/15 Region 2, Office of Director 1p 15737 084 24X Fiche 50-324,82/10/15,8210190748.
- 9210250205 Interim Pert 21 rept Detailed status of corrective actions taken will be sent by 821020
 SARSTEN.6 E United Engineers & Constructors: Inc. (subs of Raytheon Co.) 82/10/15 Director's Office of Inspection and Enforcement ip 13779 151 24X Fiche 30-324,82/10/15, 8210260205
- 3210270336 Fr wards updated LER 82-018/03L-2 DIETZ.C R Cerolina Power & Light Co 82/10/15 D'REILLY, J. P Region 2, Office of Director ip 15853 053, 24x Fiche 50-324, 82/10/15, 8210270336

- --8210270342 Updated LER 82-018/03L-2 on 820120, drywell floor drain flow integrator 1-016-FQ-K601 continuously indicated sump flow w/no pumps running Caused by integrator square root converter & flow transmitter out of calibr PASTVA:M J Carolina Power & Light Co 82/10/15 Region 2, Office of Director 2pp 15853 054 24X Fiche 50-324,82/10/19, 8210270336
- 8210290243 Forwards LER 82-112/03L-0 DIETZ: C R Carolina Power & Light Co 82/10/21 D'REILLY, J P Region 2, Office of Director 1p 15853 120, 24X Fiche 50-324,82/10/21,8210290243
- ~-B210370246 LER B2-i12/03L-0 on B20929, suppression chamber water temprecorder 2-CAC-TR-778 discovered intermittently recording temps on chart recorder Caused by out of adjustment recorder print actuation solemoid Solemoid adjusted.

 PASTVA.H J Carolina Power & Light Co 82/10/21, Region 2, Office of Director ip 15853 121 24X Ficha 50-324,82/10/21, 8210290243
- 8210270079 Forwards LER 82-113/03L-0 DIETZ-C R. Caroline Power & Light Co 82/10/22 U'REILLY, J P Region 2. Office of Director in 15854:012 24X Fiche-50-324, 82/10/22, 8210270079
- --8210270099 LER 82-113/03L-0-on 821003, during reactor startup coolunt enelysis, reactor coolant conductivity exceeded Tech Space Caused by breakdown of reactor water cleanup sys resins Resins allowed to decompose & reactor conductivity reduced PASTVA.M J Caroline Power & Light Co 82/10/22 Region 2, Office of Director 2pp 15854 013 24X Fiche:50-324.82/10/22, 8210290079
- DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8209140148 Forwards "Fire Protection of Cable Spreading Room," evaluating quantity of transient combustibles necessary to cause ignition of most limiting cable Info supple SIOSO4 exemption request HOME: P W Carolina Power & Light Co 82/09/08, DENTON, H R Offic of Nuclear Reactor Regulation, Director. 2pp 14782, O01 24X Fiche: 50-324, 82/09/08, 8209140148
- --8209140153 "Fire Protection of Cable Spreading Room"

 ** Caroline Power & Light Co 82/08/31. δig 14782 004. Ω4X
 Fiche: 50-324, 82/09/08, 8209140148
- 8210060316 Forwards revised Sections 5 & 6 to "Bafe-Bhutdown Capability Assessment & Proposed Mods" ZIMMERMAN. B R Carolina Power & Light Co 82/10/01 DENTON. H R Office of Nuclear Reactor Regulation: Director. 1p. 13616:033 MAX Fiche 50-324, 82/10/01, 8210060316
- --8210060323 Revised Sections 5 & 6 to "Safe-Shutdown Capability Assessment & Proposed Mods" " Carolina Power & Light Co 82/10/01 706pp 15616:034 24X Fiche: 50-324, 82/10/01, 8210060316.
- 8210130295 Forwards responses to BNHL & NRC Questions in a result B20804 radiation shielding study for proposed emergency operations facility/technical support ctr Written concurrence requested by 821025 ZINMERNAN.S R Carolina Power & Light Co 82/10/11 VABBALLO.D IS Operating Reactors Branch 2 3pp. 15678 240 24X Fiche.50-324,82/10/11.8210130275
- 8210220489 Ack receipt of 821006 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-30 & 50-325/82-30
 VERRELLI, D.M. Division of Project & Resident Programs 82/10/18.
 UTLEY, E.E. Carolina Power & Light Co. 1p. 15779 087. 24X
 Fiche. 50-324, 82/10/18, 8210220489
- --8210220492 Responds to NRC 820907 ltr re violations noted in IE Insp. Repts 50-324/82-30 & 50-325/82-30. Corrective actions, technician counseled re compilance w/Maint Instruction Mi-10-2J Fire Protection Procedure FP-14 will be revised DIETZ.CR. Caroline Power & Light Co. 82/10/06 0'REILLY, J. P. Region 2, Office of Director 2pp 15779 088, 24X Fiche 50-324, 82/10/18, 82/0220489
- --8210220496 Notice of violation from insp on 820715-0815. * Division of Project & Resident Programs. 82/09/07. 1: 15779.092. 24x Fiche.50-324.82/10/18.8210220489.

- --82i0220503 IE Insp Repts 50-324/82-30 & 50-325/82-30 on 8207i5-08i5 Noncompliance noted on 820805.seftty-related equipment Haint Instruction HI 10-2J incorrectly performed & Fire Protection Procedure FP-i4 Step III A improperly implemented on 8207i8 HYERS: D 0 , BURGER: C Division of Project & Resident Programs 82/09/03 9pp 15779 093 24% Fiche 50-324,82/10/18.8210220489
- B210280275 Forwards corrected pages to rept submitted in conjuction w/820908 cable spread room exemption request & Pages A 3-7-A 3-10 inadvertently omitted ZIMMERHAN.8 R Carolina Power & Light Co 82/10/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 15837-295 24X Fichs 50-024:82/10/22.8210280275
- --8210280278 Corrected & addit pages to "Fire Protection of Cable Spreading Room"

 4 Caroline Power & Light Co 82/10/22 8pp 15837 296 24X Fiche 50-324,82/10/22,8210280275

H General correspondence

- 8210010028 Requests NRC direct all official correspondence to EE Utley, util vice-president due to 820930 retirement of JA Jones
 JONES JA Carolina Power & Light Co 82/09/27 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 15865 314 24X
 Fiche 50-000 82/09/27,8210010028
- 8210130323 Requests changes to distribution list for NUREG-0020, "Licensed Operating Reactors Statue Summary Rept "
 ZIMMERMAN,B R Carolina Power & Light Co 62/10/11 BEESE,M R. ADP Systems Development Branch 2pp 15683 361 24X
 Fiche 50-000/82/10/11,8210130323
- P Operating license stage documents & correspondence
- 8207180044 FDIA request for all internal non public documents, memos, eveluation repts & other mati dealing w/nuclear plant operations
 MCINNIS D Rewe & Observer 82/08/17 Office of Administration ip 15860 064 24X Fiche 50-000.82/08/17.8207180044
- 8210120626 Advises that proposed interim changes for shift technical advisor training program acceptable up to Apr 1983, VASSALLO,D B Operating Reactors Branch 2 82/09/15 JONES.J A Carolina Power & Light to 3pp 15672 266 24X Fiche 50-324.62/09/15.8210120626
- 8210280013 Responds to FDIA request for all internal, non-public documents, memos, evaluation repts to other math dealing w/ nuclear plant operations forwards documents listed in App A. FELTON, J M Division of Rules and Recorde 82/07/17, MCINNIB, D Naws to Observer 5pp 15860 065 24X Fiche 50-000, 82/09/17, 8210280013
- --7905290357 Augmented offgas sys shall be used at all times & util should be informed CCLLINS,J T. Effluent Treatment Systems Branch 79/05/03 IPPOLITO,T A Operating Reactors Branch 3 (Pre 790625) ip 18860 087. 24X Fiche, 50-000, 82/09/17,8210280013
- --7912280014 Advises of util 791025 interim commitment for demonstrating compliance u/40CFR190 Commitment acceptable, but must include direct radiation per section 6 of NUREO-0473, Revision 2 BANGARI, R Effluent Treatment Systems Branch 79/11/23 IPPOLITO, T. Operating Reactors Branch 3 (Pre 800428) ip 15960 088 24X Fiche 50-000, 82/09/17, 8210280013.
- --Si01140002 Confirms B01126 telcon re possible willful violation of reporting requirements IE lacks specific details necessary to make referral determination WARD, W. J. Office of Inspection & Enforcement, Office of the Director B0/12/02 FORTUNA: R. Office of Inspector & Auditor ip 15860 095 24X Fiche. 50-000, 82/09/17.8210280013
- --BI04290774 Notifies that applicant should be informed that major change to redwaste treatment eys will require IOCFRSO 90 review Requests info to show conformance w/App I 4 mod can mast acceptance criteria of SRF in NUREO-0800.

 OMMILL.N P. Effluent Treatment Bystems Branch. BI/04/06 IPFOLITG.T. A Operating Reactors Branch 2. ip. 15860:226. 24X Fiche-50-000,82/09/17,8210280013
- --Bii2020885 Forwards request for add1 licenses info re proposed second expansion of spent fuel pool & estimate of vol of solid waste generated by scrapping existing racks Info needed by SIIII SI KREGER, W. E. Assistant Director for Radiation Protection, SI/10/27 NOVAK, T. Assistant Director for Operating Reactors, 2pp 13860;231 24X Fiche 50-000, 82/09/17, 8210280013.

- --8112300287 Forwards Effluent Treatment Sys Branch safety evaluating the spent fuel pool expansion application, per review of util 800416 submittal HREGER, WE Assistant Director for Radiation Protection 81/11/27 NOVAK, TM Assistant Director for Operating React 13pp 15840 249 24X Fiche 30-000,82/09/17,8210280013
- --B20i120280 Advises that Bill12 itr recommended improvement of display and calculation methodology & licenses accepted by Bill25 itr Other edit changes assured new methodology use every 31 days & nuclide dose factor inclusion in ETB GAMMILLIM P Radiological Assessment Branch. 81/12/08 IPPDLITO.7 A Operating Reactors Branch 2 ip 15860 264 Fithe 50-000, 82/09/17, 8210280013
- --8203080197 Advises that replacing Phrase 12 "Consecutive Honths' w/phrase "Calendar Yr" in Tech Spec 2 5 2 b acceptable Change would reduce recordseeping HOUSTON,R W Assistant Director for Radiation Protection 82/02/11 NOVAK,T M Assistant Director for Operating React: 2pp 15861 014 24X Fiche 50-000,82/09/17.8210280013
- --8205170128 Advises that review of NUREO-0737, Item II F 1-has bee eatisfactorily completed & considered closed HOUSTON,R H Assistant Director for Radiation Protection 82/04/16 NGVAK,T H Assistant Director for Operating React: ip 15861 040 24X Fiche 50-000,82/07/17,8210280013
- --8206220591 Submits background info on conversation w/utsl re 82 lose of RHR evc water event at facility.LER 82-005/017 WOLF.T R Director's Office 82/06/04 RUBIN.5 Director's Office 5pp 15861 326 24X Fiche 50-000.82/09/17.821028001
- --8207120140 Trip rept of 820324 visit to facility re equipment erqualification problems List of sits visit/meeting participants & related info enci
 EL-ZEFTAWY, M., WOLF, T.R. Director's Office 82/07/06
 MICHELSON, C. Director's Office 12pp 15861 314 24K
 Fiche 50-000, 82/09/17, 8210280013
- --8208310034 Forwards draft info notice re deficiencise in air filt & ventilation eys, Notice based on radioactive resin release at Pilgram 1 & on four related evente at other plants involving deficiencies in maint & teeting of filter eys MATTRON.R J. Division of Bysteme Interpation (poet 611003) 82/08/05 JORDAN.E L. Division of Engineering & Quality Assurance 5pp 15861 024 24X Fiche 50-000,82/09/17.821029:
- ---8210280024 Advises that util 780518 response re proposed plant for correcting probleme concerning augmented offgae systematic probleme to the space should be amended COLLING, J T Effluent Tech Beace should be amended COLLING, J T Effluent Treatment Systems Branch 78/06/02 LEAR, 0 Operating Reactors Branch 3 (Pre 800428) 2pp 15860.077 24X Fiche. 50-000, 82/09/17, 8210280013
- --B2102B0027 Notifiee that commitment schedule for implementing eggres, augmented offgas eye unacceptable Thermal recombiners for use in BMR offgae sye will not eatiefy criteria COLLINBLY T Effluent Treatment Systems Branch 78/09/05 IPPOLITO, T Operating Reactore Branch 3 (Pre 80042B) 3pp 15860.079. 24X Fiche 50-000, 82/09/17,82102B0013
- --B210280047 Notifies that potential for criminality found to Rights4 investigation resulting from W Ward 801202 memo constraing facility FORYUNA, R.A. Office of Inspector & Auditor 80/12/03 Office of Inspector &
- --B210280095 Assumes responsibility for review of Case Bi-17 for criminality No criminality indicated Case should be closed SMITH.R.M. Office of Inspector & Auditor 82/08/24 Office Inspector & Auditor 19 15861 027 24X Fiche 50-000,62/09/17. 8210280013
- --B210280100 Notifies that on B20224.C Alderson advised that test smit possible willful violation of reporting requirements & falsification of GA & guard qualification records at facilities.

 RESNER.M E Office of Inspector & Auditor 82/03/01 CHAIN Inspector & Auditor 92/03/01 CHAIN Inspector & Auditor 19 15861 037 24X Fiche 50-000.82/04/11

- 82:00:0051 Ack receipt of 820823 itr requesting temporary relief from commitments re training of shift technical advisors Program approved & request forwarded to NRR for evaluation O'REILLY, J P Region 2, Office of Director 82/09/20 JONES, J A Carolina Power & Light Co 1p 15565 322 24X Fische 50-000, 82/09/20, 8210010051
- B210050362 Application to amend Licenses DPR-71 & DPR-62 revising Tech Space to clarify requirements for verifying operablifity of scram distharge voi vent & drain velves Class I & II license amend fees enc! EURY.L W Cerolina Power & Light Co 82/07/29 VASSALLO, D B Operating Reactors Dranch 2 2pp 15608 345 24X Fishe 50-324, 82/09/29, 8210050362
- --82:0050371 Prposed Tech Spec 4 1 3 1 1 re surveillance requirements verifying operability of scram discharge voi vent & drain valves
 Cerolina Power & Light Co 82/09/29 2pp 15608 347 24X
 Fiche 50-324,82/09/29,8210050362
- 8210290110 Advises that plant venting capability acceptable to resolve MUREO-0737. TMI Item II B 1 re high point vents VASSALLO.D B Operating Reactors Brench 2 82/10/01. JONEO.J A Carolina Power & Light Co 3pp 15846 338 24X Fiche 50-324.82/10/01.8210270110
- --8210290113 "Operating Reactors TM1 Lessons Learned NUREG-0737
 Response Evaluations (Program II))Project 1.RCS Vents for
 Brunswick 1 & 2." final technical evaluation rept
 + Lawrence Livermore Laboratory FIN A-0246-2 82/07/15
 BUTCHER.E , BARNHARTIB Division of Licensing 4pp 15866 341
 24X Fiche 50-324,82/10/01,8210290110
- B210:50030 Forwards submitte: schedule for responses to NRC 820909 issues re TME Action Items II F 1.4.5 & 6 & II E 4 2 7. Tech Spec revisions, containment vent & purge, electrical distribution sys voltages & control of heavy loads ZIEMERMAN.S R Carolina Power & Light Co 82/10/12 VASSALLO, D 8 Operating Reactors Brench 2 2pp 15701 268 24X Fische 50-324, 82/10/12, 8210150030
- B210260244 Advises that response to NRC B20827 request to justify differences between existing control room & NUREO-0737. Item III D 3 4 suggestions will be provided by B30131 Requests re-eveluation of improvement cost-benefits
 EURY-L W Cerolins Power & Light Co 82/10/21 VABBALLO,D B Operating Reactors Branch 2 ip 15797 353 24X
 Fiche 50-324, 82/10/21, 8210260244
- B210260323 Application for amend to Licenses DPR-71 & DPR-62 clarifying portions of B10321 submittal re hydraulic snubber surveitlance EURY.L W Carolina Power & Light Co 82/10/21 VASSALLO.D B Operating Reactors Branch 2 2pp 15759 338 24X Fiche 50-324, 82/10/21.8210260323
- --B210260325 Revised Tech Specs re hydraulic snubber surveillance # Carolina Power & Light Co B2/10/21 2pp 15799.340 24x Fische 50-324,82/10/21.B210260323
- 8210240405 Withdrews request for amend to Licenses DPR-71 & DPR-42, revising Tech Spec re reportability of inoperable reed switches in rod position Indication sys to reduce number of routine LERS EURY. L W Ceroina Power & Light Co 82/10/22 VASSALLO, D. B Operating Reactors Brench 2 2pp 15806 239 24X Fische 50-324, 82/10/22, 8210260405
- --8210260410 Proposed revisions to Tech Spec 6 9 i re monthly reportability of sefety/relief valve challenges. Tech Spec supersedes 820407 submittel # Carolina Power & Light Co 82/10/22 2pp 15806 241 24% Fiche 50-324,82/10/22,8210260405.
- 3 Imspection reports, IE Bulietins & correspondence
- 3210030015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & sefety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON, J M. Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 9pp 15645 027 24X
 Fiche 50-000.82/07/12,8210080015
- ---B2100B0122 Systematic assessment of licensee performance notes re #aciiity evaluation for Apr 1979-Mar 1980 + NRC - No Detailed Affiliation Given B0/03/31. 6pp 13667 321. 24X Fiche. 50-000, 82/07/12,8210080015

- 8210010132 Forwards IE Insp Repts 50-324/82-31 & 50-325/82-29 on 820809-13 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/09/01 JONES. J A Carolina Power & Light Co 2pp 15567.230 24X Fichs 50-324, 82/09/01.8210010132
- --8210010137 iE insp Repts 50-324/82-31 & 50-325/82-29 on 820809-13 No noncomplience noted Major areas inspected ALARA radioactive met! transportetion redioactive liquid efficient monitoring that control ALBRIGHT.R H , BARR.K P Division of Engineering & Technical Programs 82/08/31 5pp 15567:232. 24X Fiche 50-324,82/09/01,8210010132
- 8210010112 Forwards summary of 820824 enforcement meeting at Region 2 ofc restetus of action items contained in 820702 & 20 confirmation of ection itrs
 O'REILLY, J.P. Region 2. Office of Director 82/09/09 JONES, J.A.
 Ceroline Power & Light Co. 1p. 15566-029 24X
 Fiche 50-324.82/09/03.8210010112
- --B210010126 Bummery of B20824 meeting w/util in Atlanta, GA re status of action items contained in B20702 & 20 confirmation of action items total committed to formally submit long-term program deteils in Nov 1982
 LEMIB, R C Division of Project & Resident Programs 82/09/03
 Division of Project & Resident Programs 82/09/03
 Fiche 50-324,82/09/03,8210010112
- 8210010170 Ack receipt of 820816 response to 820716 notice of violation & proposed imposition of civil peneitles, Rept on major program objectives to be submitted by 821101 should provide sufficient info re testing espects of training programs AXELRAD, J. Enforcement Staff. 82/09/15 JONES, J.A. Cerolina Power & Light Co. 2pp. 15568 109. 24X Fiche 50-325,82/09/15,6210010170
- --8210010193 Forwards IE Insp Repts 50-324/82-02 & 50-325/82-02 on 820106-07 Enforcement action addressed to util in 820715 itr LEMIB, R. C. Division of Project & Resident Programs. 82/07/16 JONES, J. A. Carolina Power & Light Co. 2pp. 15568:124. 24X Fiche 50-325, 82/07/15, 8210310170
- 8210010171 Ack receipt of 820702 & 0903 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-18 & 50-325/82-18 VERRELLI, D M Division of Project & Resident Programs 82/09/16 JONES, J A Cerolina Power & Light Co. 1p. 15568 091. 24X Fiche 50-324,82/09/16,8210010171
- --8210010183 Suppls 820702 response to NRC 820404 ltr re violations noted in 1E Insp Repts 50-324/82-18 & 50-325/82-18 Corrective ections: responsible operators counseled & IA-1 battery charger clearence removal reviewed DIETZ, C R Carolina Power & Light Co 82/09/03 D'REILLY, J. P. Region 2, Office of Director, 3pp 15568:092, 24X Fiche 50-324,82/09/16,8210010171
- --8210010188 Responds to NRC 820604 itr re violations noted in IE Insp Repts 50-324/82-18 & 50-325/82-18, Corrective actions: double verification program established on 820601 DIETZ,C R Caroline Power & Light Co. 82/07/02, G'REILLY, J. P Region 2, Office of Director. 2pp 15568:095 24X Fiche. 50-324, 82/09/16, 8210010171
- --8210010194 Forwards IE Insp Repts 50-324/82-18 & 50-325/82-18 on 820415-0515 & notice of violation LONG, FJ Division of Project & Resident Programs 82/06/04, JONES, J. A. Cerolina Power & Light Co. 2pp 15568:097, 24X Fiche:50-324,82/09/16:8210010171.
- --8210010199 Notice of Violation from insp on 820415-0515.

 # Region 2, Office of Director 82/06/04 ip 15568:099. 24X
 Fiche 50-324,82/09/16:8210010171
- --8210010205 IE Insp Repts 50-324/82-18 & 50-325/82-18 on 820415-0515. Noncomplience noted Denating Procedure DP-43 & teg removal for Clearance 1-459 inadequately implemented MYERS.D.O. OARNER.L.W., BURGER.C.W., Division of Project & Resident Progrems 82/06/04. 9pp 15568:100 24X Fiche:50-324,82/09/16,8210010171

- 8210010336 Advises that IE Insp Rept 50-325/82-36 was inadvertently labeled 50-325/82-30 VERRELLI.D M Division of Project & Resident Programs 82/09/fd JONES.J A Carplina Power & Light Co. 1p 15571 001 24X Fishe 50-324, 82/09/f6, 8210010336
- --8210010340 Forward: IE Insp Repts 50-324/82-32 & 50-325/82-36 on 820824-27 No montompilance noted VERRELLI.D H Division of Project & Resident Programe 82/09/10 UDNES.J A Carolina Power & Light Co 2pp 15571 002 24X Fish
- --8210010350 IE Insp Repts 50-324/82-32 & 50-325/82-36 on 820824-27 No noncompliance noted Major areas inspected pre-startup reviews, corporate nuclear safety reviews, post-maint teeting & plant mode involving Tech Spec changes FREDRICKSON, P. JACKSON, L. H. UPRIGHT, C. M. Division of Engineering & Technical Programs 82/09/10 4pp 15571 004 24X Fiche, 50-324, 82/09/16, 8210010336
- 8210010391 Ack receipt of 820907 ltr informing NRC of staps taken to correct violations noted in IE Insp Repts 50-324/82-25 & 50-325/82-25 LEHIS.R C Division of Project & Resident Programs 82/09/22 JONES. J A Caroline Power & Light Co ip 15572 269 24X Fiche 30-324.82/09/22.8210010391
- --8210010379 Responds to NRC 820813 ltr re violations noted in IE Inap Repts 50-324/82-25 & 50-325/82-25 Corrective actions plant operating procedures rewritten & signoffs edded Operations engineer responsible for procedure changes DIETZ, C R Carolina Power & Light Co 82/09/07 O'REILLY, J P Region 2. Office of Director 2pp 15372 270 24% Fiche 50-324,82/09/22,8210010391
- --8210010405 Forwards IE Insp Repts 50-324/82-25 & 50-325/82-25 on B20615-0715 & notice of violation LEHIS,R C Division of Project & Resident Programs 82/08/13 JONES, J A Carolina Power & Light Co 2pp 15572 272 24X Fiche 50-324,82/09/22,8210010391
- --8210010410 Notice of violation from insp on 820415-0715
 * Division of Project & Resident Programs 82/08/13, 2pp 15572:274 24X Fiche:50-324,82/09/22,8210010391
- --8210010415 IE Insp Repte 50-324/82-25 & 50-325/82-25 on 820615-0715 Noncompliance noted failure to implement & maintain operating procedures for startup & shutdown MYERS, D 0 , QARNER, L W , STETKA, T Division of Project & Resident Programs 82/08/12 13pp 15572 276 24X Fiche, 50-324, 82/09/22, 8210010391.
- 8210150100 Ack receipt of 820913 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-26 & 50-325/82-26 LEWIS.R C Division of Project & Resident Programs 82/09/24 JONES. J A Carolina Power & Light Co ip 15701 164. 24X Fiche 50-324.82/09/24.8210150100
- --8210150106 Responde to NRC 820817 itr re violations noted in IE Insp Repts 50-324/82-26 & 50-325/82-26 Corrective actions new comprehensive post-testing program being developed DIETZ.C R Carolina Power & Light Co 82/09/13 O'REILLY, J P Region 2. Office of Director 2pp. 13701:165, 24X Fiche 50-324,82/09/24,8210150100
- --8210150113 Forwards IE Insp Repts 50-324/82-26 & 50-325/82-26 on 820712-16 & notice of violation LEMIS.R C Division of Project & Resident Programs. 82/08/17 JUNES.J A Carolina Power & Light Co. 2pp 15701:167 24X Fiche 50-324,82/09/24,8210150100
- --8210150120 Notice of violation from insp on 820712-16
 * Division of Project & Resident Programs 82/08/17 2pp.
 15701:169 24X Fiche:50-324,82/09/24,8210150100
- --8210150132 IE Insp Repts 50-324/82-26 & 50-325/82-26 on 820712-16 Noncompliance noted failure to provide measures to preclude bypassing required testing.

 BKINNER:P H , JACKBON,L.H., UPRIGHT,C M, Division of Engineering & Technical Programs 82/08/19, 7pp 15701 171 24X
 Fiche 50-324,82/09/24,8210130100
- 8210150108 Forwards IE Inep Repts 50-324/82-35 & 50-325/82-35 on 820908-10 No noncompliance noted VERRELLI,D M. Division of Project & Resident Programs. 62/09/24. JUNEB.J.A. Carolina Power & Light Co. 2pp. 15701 149 24X Fiche 50-32 .82/09/24,8210150108

- --8210150114 IE insp Repte 50-324/82-35 & 50-325/82-35 on 820708-10 s; noncompliance noted Major areas inspected review & evaluation of changes to inservice insp program & program for document control & data retention COLEY.J L . BLAKE.J J Division of Engineering & Technical Programs 82/09/21 3pp 15701 151 24X Fiche 50-325,82/09/28 82(0150108
- 9210150162 Forwards IE Insp Repts 50-324/82-33 & 50-325/82-31 on 820701-03 & 10 No noncompliance noted VERRELLI.D M. Division of Project & Resident Programs 82/09/24 JONES.J A Carolina Power & Light Co 2pp 15707 304 24X Fiche 50-324.82/09/24.8210150162
- --82(0:50:170 IE Insp Repts 50-324/82-33 & 50-325/82-31 on 820901-03 & No noncompliance noted Major areas inspected IE Bulletin 77-14. "Seismic Analysis for As-Built Safety-Related Piping Sys"

 ANO. M. P. BLAKE, J. Division of Engineering & Technical Progress 62/09/23 5pp 15707 306 24X Fiche 80-324.62/09/24.8210150142
- 8210150008 Ack receipt of 820819 & 0915 ltrs informing NRC of eteps taken to correct violations noted in IG Insp Repts 50-324/82-23 & 50-325/82-23 LEWIS:R C Division of Project & Resident Programs 82/09/30 JONES:J A Carolina Power & Light Co 1p 15698 349 24x Fiche 50-324, 82/09/30, 8210150008
- -8210150016 Revises response to NRC ltr re violations noted in HE (-, 'Repts 50-324/82-23 & 50-325/82-23 Corrective actions assessment of inservice insp program in progress Violatica will be fully addressed by 821231
 DIETZ.C R Carolina Fower & Light Co 82/09/15 D'REILLY, J P Region 2. Office of Director 2pp 15698 350 24X
 Fichs 50-324,82/09/30,8210150008
- --8210150023 Responds to NRC 820719 ltr re violations noted in HE [--] Repts 50-324/82-23 & 50-328/82-23 Corrective actions post-maint testing program revised & inservice insp program under review DIETZ.C R Carolina Power & Light Co 82/08/19 O'REULY.JP Region 2. Office of Director 3pp 15698 352 24X Fiche 50-324,82/09/30,8210150008
- --8210150034 Forwards IE Insp Repte 50-324/82-23 & 50-325/82-23 on 820615-18 & notice of violation LEWIS.R C Division of Project & Resident Programs 62/07/19 JONES J A. Carolina Power & Light Co 2pp. 15698 355 241 Fichs 50-324.82/09/30.8210150008
- --82:0150040 Notice of violation from insp on 820415-18 LEWIS,R C Division of Project & Resident Programs 82/07/19 2pp 15498 357 24X Fiche 50-324,82/07/30,8210150008
- --8210150063 IE Insp Repts 50-324/82-23 & 50-325/82-23 on 820015-18
 Noncompilance noted failure to re-establish baseline data
 for RHE avc water pump & to include main steam piping in
 inservice inep program
 BLAKE, J J , ECONDHOS, N Division of Engineering & Technical
 Programs 82/07/15 4pp 15698 359 24% Fichs 50-324.62/07/31
 8210150008.
- 8210220139 Forwards IE Insp Repts 50-324/82-38 & 50-325/82-38 on 820907-10 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/10/Ct JONES, J. A Carolina Power & Light Co 2pp 15778 107 24x Fithe: 50-324, 82/10/04, 8210220139
- --8210220147 IE Insp Repts 50-324/82-38 & 50-325/82-38 on 820907-81% monocompliance noted Major areas inspected followup (neg ef NRC & licensee identified tasks to be completed prior to startup HHITENER H. L., KRUG, H. E., JAPE, F. Division of Engineering & Technical Programs. 82/09/30 5pp 15778 109 24X Fiche: 50-324,82710/04,8210220139
- 8210220169 Forwards IE Insp Repts 50-324/82-36 & 50-325/82-33 on 820815-0915 No noncompliance noted VERRELLI.D.M Division of Project & Resident Programs 82/10/83 JORES J.A. Carolina Fower & Light Co. 2pp 15778 045 241 Fiche: 50-324, 82/10/44, 8210220169
- --8210220173 IE Insp Repts 50-324/82-36 & 50-325/82-33 on 82685-ffils noncompilance noted Major areas inspected review of LERs, operational safety verification & audit of surveillance & maint activities

 MYERS, D O . CARNER, L W., BURGER, C. Division of Project & Briston, Programs. 82/10/01 8pp 15778 047. 24X Fiche 50-324.82/10/2 8210220169.

- 9210150036 Ack receipt of 820816 & 0924 itrs informing NRC of steps taken to correct violations noted in IE Insp Repts 30-324/82-20 & 50-325/32-20 LEHIS.R C Division of Project & Resident Programs 82/10/05 JONES, J A Carolina Power & Light Co 1p 15701 135 24X Fichs 50-324, 82/10/55,8210180036
- --8210150038 Suppls 820816 response to NRC 820719 itr re violations noted in 1E Insp Repts 50-324/82-20 & 50-325/82-20 Add1 info re revision to Procedure COAD 80-1 to assure timely corrective actions to future audit findings provided DIEY7.C R Carolina Power & Light Co 82/09/24 O'REILLY.J P Region 2. Office of Director 2pp 15701 136 24X Fiche 50-324,82/10/05.8210150036
- --8210150045 Responds to NRC 820719 itr re violations noted in IE Insp Repts 50-324/82-20 & 50-325/82-20 Corrective actions Procedure CQAD 80-1 revised & frequency of plant audits increased to reduce audit scope DIETI-C R Carolina Power & Light Co 82/08/16 O'REILLY.J P Region 2. Office of Director 3pp 15701 138 24X Fichs 50-324,82/10/05.8210150036
- ~-8210350048 Forwards IE insp Repts 50-324/82-20 & 50-325/82-20 on 820507-08 & notice of violation W/o notice of violation LEMIS.R C Division of Project & Resident Programs 82/07/19 JONES.J A Carolina Power & Light Co 2pp 15701 141 24X Fiche 50-324,82/10/05.8210150036
- --0210150052 IE Insp Repts 50-324/B2-20 & 50-325/B2-20 on 820607-08 Noncompliance noted failure to establish measures to assure prompt corrections to adverse GA conditions & failure to distribute audit within required timeframe BELISLE.0 A., UPRIGHT,C M Division of Engineering & Technical Programs 82/07/15 4pp 15701 143 24% Fiche 50-324.82/10/05, 9210150036
- 9210150288 Act receipt of 820714 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-21 & 50-325/82-21 VERRELLID H Division of Project & Resident Programs 82/10/05 JONES, J A Carolina Power & Light Co. 1p. 15706 126 24X Fiche 50-324,82/10/05,82/0150288
- --8210130295 Responds to NRC 820818 ltr re violations noted in IE Insp Repts 50-324/82-21 & 50-325/82-21 Corrective actions relief valves which can communicate w/primary containment added to Type C testing program & review of leakage continuing DIETX.C R Carolina Power & Light Co 82/09/14. O'REILLY, J P Region 2. Office of Director 2pp 15706.127 24X Fiche 50-324,82/10/05,8210150288
- i20Bi70233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 Implant Seeds " Syc list encl COBB.t. i Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 46pp 15761 250 24X Fichs 50-000,82/10/06,8208190233
- 208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diamster, Stainiess Bteel Recirculation Sys
 Piping at BNR Plants, "Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Endorcement 82/10/14 Consolidated Edison Co. of New York
 185pp 18810 128 24% Fiche 50-000, 82/10/14, 8208190228
- 210220489 Ack receipt of 821004 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-30 & 50-325/82-30.
 VERRELLI.D.M. Division of Project & Resident Programs 82/10/18
 UTLEY, E E Carelina Power & Light Co ip 15779.087 24X
 Fichs 50-324, 82/10/18,8210220489
- -8210220472 Responds to NRC 620907 ltr re violations noted in IE Insp. Repts 50-324/82-30 & 50-325/82-30 Corrective actions: technician counseled re compliance w/Maint Instruction MI-10-2J Fire Protection Procedure FP-14 will be revised DIETZ: C.R. Carolina Power & Light Co. 82/10/06 O'REILLY: J P. Region 2. 0ffice of Director 2pp 15779 088 24X Fichs 50-324,82/10/18,8210220489
- -8210220494 Forwards IE Insp Repts 50-324/82-30 & 50-325/82-30 on 820715-0815 & notice of violation.

 VERRELLIA M Division of Project & Resident Programs 82/09/07

 JCMSS.J A Carolina Power & Light Co 2pp 15777-090 24X

 Fiche. 50-324, 82/10/18, 8210220489
- -9210220476 Notice of violation from insp on 820715-0815 * Division of Project & Resident Programs. 82/09/07. ip 15779 092. 24X Fiche. 50-324. 82/10/18. 8210220489.

- --8210220503 IE insp Repts 50-324/82-30 & 50-325/82-30 on 820715-0815 Noncompliance noted on 820805, safety-related equipment Maint Instruction MI 10-2J incorrectly performed & Fire Protection Procedure FP-14 Step III A improperly implemented on 820718 HYERS, D O . OARNER, L W . CHASE, J Division of Project & Resident Programs 82/09/03 990 15779 093 24X Fiche 50-324,82/10/18,8210220489
- 8 Reportable occurrences, LERs & related correspondence
- 8210070416 Trip rept of 810617 site visst to collect info re loss of RMR Baffle plate dividing water box of RMR MX 1A failed allowing svc water to bypass MX tubes Caused by sicessive differential pressure across baffle plate IMBRO,E , OIANELLI, J Director's Office 81/07/22 Director's Office 19pp 15697 308 24X Fiche 50-324.81/07/22.8210070416
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fichs 50-000,82/06/28,8210010008
- --8107300168 Discusses fundings gathered during 810617 site visit re facility loss of RHR capability during Apr & May 1781 Util has committed to mod of wash screen wash sys by 1783 Attendance list,chlorinator outage info & drawings encl IMBRO.E Director's Office 81/07/22 Director's Office 17pp 15730 056 24X Fiche 50-000.82/06/28.8210010008
- 8209160299 Forwards LER 82-095/031-0 DIETZ.C R Carolina Power & Light Co 82/08/31 O'REILLY.J P Region 2. Office of Director ip 14894 178 24X Ficha 50-325.82/08/31.8209160299
- --B2091603ii LER 82-095/03L-0 on 820803 review revealed that RHR shutdown cooling suction valves food & food & vessel head spray valves fo22 & fo23 not tested on quarterly basis per inservice insp requirement Caused by program logic error POWLK.R M Carolina Power & Light Co 82/08/31 Region 2. Office of Director ip 14894 179 24X Fiche 50-325, 82/08/31, 8209160297
- B210010170 Ack receipt of 820816 response to 820716 notice of violation & proposed imposition of civil penalties Rept on major program objectives to be submitted by 821101 should provide sufficient info re testing aspects of training programs AXELRAD. J Enforcement Staff B2709715 JONES JA Carolina Fower & Light Co 2pp 19368 109 24X Fiche 50-325.82/09/15.8210010170
- --B210010206 IE Insp Repts 50-324/82-02 & 50-325/82-02 on 820104-07 Noncompliance noted Unit 1 instrument D-1 inoperable & level channel not tripped between 811226-31 OARNER, L Division of Project & Resident Programs 82/05/13 6pp 15568 126 24X Fiche 50-325,82/07/15,8210010170
- 8210280013 Responds to FOIA request for all internal non-public documents, memos, evaluation repts & other mati dealing w/
 nuclear plant operations forwards documents listed in App A
 FELTON, J M Division of Rules and Records 82/09/17 McINNIG.D
 News & Observer Spp 15860 065 24X Fiche 50~000,82/09/17,
 8210280013
- --7811200399 LERMI-78-051 on radioactive release reviewed in response to 780803 request Finds LER does not indicate root cause of the event malfunction of concentrated waste tank heaters due to corrosion Forwards recommendations for personnel COLLINS, J T Effluent Treatment Systems Branch 78/10/06 KNIOHTON, O. Environmental Evaluation Branch (Pre 790625) 3pp 15860 082 24X Fiche 50-000, 82/09/17, 8210280013
- 8210080181 Forwards LER 82-101/03L-0
 DIETZ,C R Carolina Power & Light Co 82/10/01 O'REILLY, J P
 Region 2, Office of Director 1p 15640 170 24X
 Fiche 50-325,82/10/01,8210080181
- --8210080183 LER 82-101/03L-0 on 820920, valve time testing not covered in operability test of loops A & B of LPCI/RHR sys PTS 08 2.2C & 26, Caused by personnel oversight during procedural development Procedures revised.
 PASTVA, N J Carolina Power & Light Co 82/10/01. Region 2, Office of Director %p. 15640:171. 24X Fichs 50-325, 82/10/01, 8210803181
- 8210080220 RO on 821001.analysis confirmed that pipe support P8-6647 could fail during seismic event Support upgraded to meet requirements
 DIETZ.C R Carolina Power & Light Co. 82/10/01 G'REILLY, J P. Region 2, Office of Director in 15699.090 24X
 Fithe: 50-325.82/10/01.8210080220.

1.

1 :.

. .

H

. 46

11

9. Ri q

147

,

- 8210130477 Forwards updated LER 82-093/03L-1 DIETZ.C R Carolina Power & Light Co 82/10/04 O'REILLY,J P Region 2. Office of Director 1p 15682 163 24X Fiche 50-025, 82/10/04, 8210130477
- --8210130483 Updated LER 82-093/03L-1 on 820813, review revealed inability of reactor protection syr logic functional test PT-01 1 10 to provide for electrical continuity testing of input signal contacts of backup scram logic circuitry solenoid; PASTVA.M J Carolina Power & Light Co 82/10/04 Region 2, 02/10/04 Region
- 8210130489 Forwards updated LER 82-024/03L-1 DIETZ.C R Carolina Fower & Light Co 82/10/04 O'REILLY.J P Region 2. Office of Director Ip 15484 193 24X Fichs 50-025: 82/10/04.8210130489
- --B210i30497 Updated LER 82-024/03L-1 on 8202i4 & 0220, open position indication for dryumll to suppression vacuum breaker XISH not achievable Caused by failure of vacuum breaker to stroke open fully Cause of 820220 event not determined PASTVA:M J Carolina Power & Light Co 82/i0/04 Region 2. Office of Director 1p 15684 194 24X Fiche 50-325,82/10/04.
- 8210170555 Forwards LER 82-100/01T-0 DIET7.C R Carolina Power & Light Co 82/10/11 O'RETLLY, J P Region 2. Office of Director 1p 15737 254 24X Fiche 50-325.82/10/11.8210170556
- --8210190674 LER 82-100/017-0 on 621001, determined that tailpipe for safety relief valve FOI3H could fail during seismic event Addi analysis not performed Addi support (PS-6647) added where tailpipe passes through deflector plate POULK, R M Carolina Power & Light Co 82/10/11 Region 2, Office of Director 1p 15737 255 24X Fiche 50-325, 82/10/11, 2210/0144
- \$210290346 Forwards supplemental LER 82-024/03L-2 DIETZ,C R Carolina Power & Light Co 82/10/13 O'REILLY,J P Region 2. Office of Director 1p 15893 106 24X Fiche 50-025, 82/10/13, 8210290346
- --8210290352 Supplemental LER 82-024/03L-2 on 820214, during periodic test, discovered that open position indication for drywell to suppression vacuum breaker XIBM could not be achieved Caused by failure of vacuum breaker to fully stroke open PASTVA.N J Carolina Power & Light Co 82/10/13 Region 2, 0ffice of Director 1p 15853 107 24X Fiche 50-325, 82/10/13, 82/10200346
- 8210260205 Interim Part 21 rept Detailed status of corrective actions taken will be sent by 821020 SARSIEN. © E United Engineers & Comstructors, Inc. (subs. of Raythron Co.) 62/10/15 Director's Office, Office of Inspection and Enforcement 1p 15799 151 24x Fiche 50-324,62/10/15,8210260205
- 8210260294 RD while performing insp of fire dampers per 820518 commitment, discovered ventilation duct located at penetration seal D0-2-034 on 23-ft elevation of dissel generator bldg did not have insp door DIETZ, C R Carolina Power & Light Co 82/10/15, D'REILLY, U P Region 2, Office of Director ip 15803 025 24X Fiche 50-325, 92/10/15, 8210260294
- 8210290325 Forwards updated LER 82-001/03L-1 DIETZ.C R Carolina Power & Light Co 92/10/15 O'REILLY, J P Region 2. Office of Director 1p 15859 048 24X Fiche 50-225, 82/10/15, 8210290325
- --82i029033: Updated LER 62-00i/03L-1 on 820ii6, surveillance revealed drywell equipment drain flow, 1-0i6-FG-K603 continuously indicating sump flow w/no pumps running Caused by integrator square root converter & flow transmitter out of callor. PABTVA, M J. Carolina Power & Light Co 82/10/15 Region 2, Office of Director 2pp 13853 049 24X Fiche 50-325,82/10/15,8210270325
- 6210260256 Forwards LER 82-104/03L-0 DIETZ.C.R Carolina Power & Light Co 82/10/18 O'REILLY, J P Region 2. Office of Director ip 15803 101. 24X Fiche 50-325, 82/10/18, 8210260256
- --B210250266 LER B2-104/03L-0 on B210D1, sixess flow check valve 1-B21-F047c failed to seat & isolate as required Probably caused by line crud deposit in valve seat Line flushed & valve satisfactorily tested PASTVAM J Carolina Power & Light Co B2/10/18 Region R. Office of Director 1p 15803 102 24X Fiche, 50-325, B2/10/16, B2/10/260284

- 9210260344 Forwards LER 92-103/03L-0 DIETZ:C R Carolina Power & Light Co 92/10/19 O'REILLY, J P Region 2. Office of Director ip 15804 244 24X Fiche 50-225, 82/10/18,8210260344
- --8210260369 LER 82-i03/03L-0 on 820924, required semiannual functions test of primary containment air lock interiock mechanism not addressed in procedures Caused by personnel oversight during initial review of Tech Specs
 PASTVA, M J Carolina Power & Light Co 82/10/18 Region 2.
 Office of Director 2pp 13804 245 24X Fiche 50-325,82/10/18
 8210260344
- DOCKET 50-327 SEGUDYAH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8209170068 Forwards revised pages to proposed physical security plantransmitted by 820623 ltr Pages withheld (ref 10CFR2 790) MILLS, L H Tennessee Valley Authority 82/09/01 ADERSH, E Licensing Branch 4 lp 14910 105 24X Fiche 50-327.82/09/01, 8209170068
- 8210060347 Forwards status rept of meteorological program for ravies a "Sequoyah Nuclear Flant Nowcast Manual" MILLS.L M Tennessee Valley Authority 82/10/01 ADENSAM.E Licensing Branch 4 5pp 18619 036 24X Fiche 50-327.82/10/01. 8210060347
- --8210060352 "Sequoyah Nuclear Plant Nowcast Manual "
 # Tannessee Valley Authority 82/09/30 70pp 15619 06; 211
 Fiche 50-327,82/10/01,8210060347
- B210260245 Forwards IE Safeguards Insp Repts 50-327/B2-26 & 50-328/B2-26 on B21006-0B No noncompliance noted VERRELLI, D Division of Project & Resident Programs B2/10/22 PARRIS, H O Tennessee Valley Authority 2pp 15799 i36 24x Fiche 50-327, B2/10/22, B210260245
- --8210260265 IE Insp Repts 50-327/82-26 & 50-328/82-26 on 021036 08 in noncompilance noted Major areas inspected review of security plan b implementing procedure security organization-mgt/ personnel/response Details withheld (ref 10CFR73 21) MODRE, D E , MCGUIRE, D R Division of Engineering & Technical Programs 62/10/22 ip 15799 i38 24X Fiche 50-327.62/10/32.
- P Operating license stage documents & correspondence
- 82:003:0008 Responds to FOIA request for 19 categories of documents and lear reactor events & safety problems Forwards documents listed in App & FELTON, J M Division of Rules and Records 82/06/28 UPELLR A Critical Mass Energy Project 15pp 15727 005, 24% Fiche 50-000, 82/06/28, 82:100:0008
- --8008050265 Discusses addi required info to better define patially cracking in reactor vessel notiles
 NOONAN, V B Assistant Director for Materials & Qualification
 Engineering 80/05/05 TEDESCO.R L Assistant Director for
- --BIO3050987 Discusses 810126 loss of annunciation event at facility Caused by capacitor shorting.Licensee will review event as addressed in IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bus During Operation " CHIRAMAL, M Director's Office 81/01/30 Director's Office 1p 15728 002, 24X Fiche, 50-000, 82/06/28, 8210010008
- 8210040426 Forwards request for add1 info re hydrogen control Coordinated util response suggested by mid-Dct 1982.state subj is generic to ice condenser plants W/o encl.
 NDVAK, T.M. Assistant Director for Licensing 62/09/17 PAPRILES Tennessee Valley Authority. Ip 15597 251 24%
 Fiche 50-327, 82/09/17,8210040426
- 8210210542 Notification of 820727 meeting w/iicenses in Saddq Dalwy 5 to discuss proposed delays in license requirements STAHLE: C. Licensing Branch 4 82/09/24 ADENBAM,6 0 Licensing Branch 4 2pp 15782:328 24X Fiche 50-327,82/09/24,821021032
- 8210120284 Forwards "Executive Summary Rept on Adequacy of Parents! |
 Hydrogen Mittigation Sys for Sequoyah Nucleaf Flant," in
 response to RL Tedesco 820413 itr.
 MILLS L M Tennessed Valley Authority, 82/09/27 ADENSALE
 Licensing Branch 4, ip 15653 078, 24% Fiche: 50-327, 82/09/27,
 8210120284

- --P210120289 "Erecutive Summary Rept on Adequacy of Permanent Hydrogen Mitigation Sys for Sequoyah Nuclear Plant " * Tennesser Valley Authority 82/09/30 31pp 15653 079 24X Fiche 50-327,82/09/27.8210120284
- B21CO50216 Informs that updated FSAR will be submitted in Jan 1983, in response to NRC request MLLS.L M Tennessee Valley Authority 82/09/30 ADENSAM, E Licensing Branch 4 lp 15611 236 24X Fiche 50-327, 82/09/30, 8210050216
- 6210190110 Forwards request for addl info on equipment temp response to Audrogen burns Coundinated util response suggested since subly generic to ice condenser plants ADERISAM.E. G. Licensing Branch 4 82/10/01 PARRIE.H 0 Tennessee Valley Authority 4pp 1576/ 226 24X Fiche 50-327, 82/10/01. 6210190110
- E210130150 Forwards add1 info re 820715 application for amend of Licenses DFR-77 & DFR-77 concerning steam generator water level low-flow reactor trip setpoint MILLG.L M Tennessee Valley Authority 82/10/07 DENTON.H R Office of Nuclear Reactor Repulation, Director 2pp 15673 082 24X Fiche 50-327.82/10/07.8210130150
- 6210180117 Forwards request for deferral of ASME Section X1 requirement to hydrostatically pressure test replacement portions of essential rau cooling water sys W/three oversite drawings Aperture cards are available in FDR MILLS.L M Tennessee Valley Authority 82/10/13 ADENSAM.E Licensing Branch 4 7pp 15718 134 24X Fiche 50-327,82/10/13, 8210180117
- 8210260148 Forwards proprietary response to NRC 820809 request for info re CLASIX code Encl withheld (ref 10CFR2 790) FAMMER D S Tennessee Valley Authority 82/10/18 ADENSAM E Licensing Branch 4 1p 15797 055 24X Fiche 50-327, 82/10/18, B210240148
- 6210260228 Forwards revised figures for incorporation into App B, peaking factor limit rept, to reload safety evaluation for Cycle 2 reload operations **AAMMER.D S** Tennassee Valley Authority 82/10/19 DENTGN, H R. Office of Nuclear Reactor Regulation, Director 7pp 15806-317 24% Fiche 50-327,82/10/19,8210260228
- Q Inspection reports, 1E Bulletins & correspondence
- 5210070007 Responds to FOIA request for eight categories of records resteem generators & steam turbines App A documents provided an R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON. / M Division of Rules and Records B2/08/i0 LONO, D J Winthrop. Stimson. Putnam & Roberts 9pp 15645-063 24X Ficha 50-000, 82/08/10, 8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to incenses iPPDLITO, T Operating Reactors Assessment Branch 92/04/01 WARGA'S Operating Reactors Branch 1 5pp 15645 i31 24X Fische 50-000, 82/08/10, 8210070007
- J2IDD10474 Forwards corrected notice of violation, revising notice issued w/IE Insp Repts 50-327/82-18 & 50-328/82-18 on 820705-0805
 LEWIG.R C Division of Project & Resident Programs 82/09/17
 PARRIS.H O Tennessee Valley Authority 2pp 15572 172 24X
 Fiche 50-327, 82/09/17,8210010476
- -8210010477 Corrected notice of violation from insp on 820706-0805
 Noncompliance noted activities affecting safety-related
 Punction of critical sys.structures & components not
 accomplished per drawings
 # Division of Project & Resident Programs 82/09/17 1p
 15572 174 24X Fiche 50-327,82/09/17.8210010476
- 210010130 Ack receipt of 820830 ltr informing NRC of steps taken to correct violations noted in 16 lnsp Repts 50-327/82-05 & 50-328/82-05
 LEISTER C Davision of Project & Resident Programs. 82/09/20 PARRIS.H C Tennessee Valley Authority 1p 15566 009 24X Fische 50-327.82/09/20.8210010130
- -8210010135 Reponds to NRC 820807 ltr re violations noted in 1E lnsp Repts 50-327/82-05 & 50-328/82-05 Corrective actions program initiated to schedule temporary employees for training in GA area KAMMER, D 8 Tennessee Valley Authority 82/08/30, O'REILLY, J. P Region 2, Office of Director 3pp i5566 010, 24X Fiche 50-327,82/07/20,8210010130,

- 8210150225 Act receipt of 820921 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-16 & 50-328/82-16 LEWIS.R C Division of Project & Resident Programs 82/10/05. PARRIS.H Ø Tennessee Valley Authority ip 15706 061 24X Fiche 50-327.82/10/05.82/0150225
- --8210150231 Responds to NRC 820820 ltr re violations noted in IE lnsp Repts 50-327/82-16 & 50-328/82-16 Corrective actions delinquent QA audit findings identified & corrective action escalation program developed MILLS.L H Tennessee Valley Authority 82/09/21 0'REILLY, J P Region 2. Office of Director 5pp 15706.062 24X Fiche 50-327,82/10/05.8210150225
- --82i0150237 Forwards IE lnsp Repts 50-327/82-16 & 50-328/82-16 on 820712-16 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/08/20 PARRIS.H O Tennessee Valley Authority 2pp 15706 057 24X Fiche 50-327,82/10/05,8210150225
- --8210150245 Notice of violation from insp on 820712-14 * Region 2, Office of Director 82/08/20, 2pp \$5706 069 24X Fiche 50-327,82/10/05,8210150225
- --8210150256 IE Insp Repts 50-327/82-16 & 50-328/82-16 on 820712-16
 Noncompliance noted operations GA manual not reviewed by
 GA staff & no measures established to assure that GA
 procedures & revisions implemented
 BELISLE, OA, PREDRICKSON, P. UPRIGHT, CM Division of Engineering
 & Technical Programs 82/08/18 12pp 15706 071 24X
 Fiche 50-327,82/10/05:8210150225
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COB9.L I Division of Fuel Facilities, Materials & Bafeguards, 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24x Fichs 50-000,82/10/06,8208190233
- 8208190238 lE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wail-Large-Diameter, Stainless Steel, Recirculation Sys Piging at BMR Plants " Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York, 115pp. 15810 125 24X Fiche 50-000, 82/10/14, 8208190238,
- 8210220469 Ack receipt of 821005 ltr informing NRC of steps taken to correct violation noted in JE Insp Repts 50-327/82-19 & 50-328/82-19
 LEWIS, R C Division of Project & Resident Programs B2/10/18 PARKES, H Q Tennesses Valley Authority ip 15779 103 24X Fiche 50-327,82/10/18,8210220469
- --8210220474 Responds to NRC 820703 ltr re-violation noted in IC Insp Repts 50-327/82-19 & 50-328/82-19 Corrective actions all affected analysts reminded to record data on TI-37 log sheet per Oaseous Effluent Requirements Procedure 8I-415 HILLB.L M Tennessee Valley Authority 82/10/05, 0'REILLY.JP. Region 2, Office of Director 2pp (5779,104 24X Fiche 50-327,82/10/18,8210220469
- --8210220480 Forwards IE Insp Repts 50-327/82-19 & 50-328/82-19 on 820816-20 & notice of violation VERRELLI.D H Division of Project & Resident Programs. 82/09/03 PARRIE.H O Tennesse Valley Authority 2pp 15779-106 24% Fiche.50-327,82/10/18,8210220469
- --8210220482 Notice of violation from insp on 820816-20 * Division of Project & Resident Programs 82/07/03, ip 19779.108 24X Fiche. 50-327.82/10/18.8210220469.
- --B210220485 IE Insp Repts 50-327/82-19 & 50-328/82-19 on 920816-20. Noncompliance noted on 820727.noble gas release rates not recorded on TI-37 log sheet B 35 for all seffuent radiation monitors declared inoperable due to power failure. COLLINS.T R. BARR.K P Division of Engineering & Technical Programs 82/09/02 7pp 15779 109 24% Fiche 50-327.82/10/18,8210220469
- 8210260245 Forwards IE Safeguards Insp Repts 50-327/82-26 & 50-328/82-26 on 821006-08. No noncompliance noted, VERRELLID Division of Project & Resident Programs, 82/10/22 PARRISH O Tennessee Valley Authority 2pp 19799 (36, 24X Fiche 50-327, 82/10/22, 8210260245
- --B210260265 IE Insp Repts 50-327/B2-26 & 50-328/B2-26 on B21004-08.No honcompliance noted Major areas inspected: review of security plan & implementing procedure, security organization-mgt/personnel/response.Details withheld (ref 100FR73,21; MODRE,D E., MCGUIRE,D,R Division of Engineering & Technical Programs, B2/10/22 ip 15799.138 24X Fiche 50-327,82/10/22,8210260245

- S Reportable occurrences, LERs & related correspondence
- 821012038D Advises that operator action necessary to protect BtW glants from excessive feeduater transients BSW plants do not employ high steam generator level turbine or reactor trips to protect against transients CRESELL.J 8 Director's Office 80/09/12 MICHELSON, C Director's Office. 34pp 19689 286 24X Fichs 50-327,80/09/12.
- 8210070122 Discusses 850125 loss of annunciation Event began w/loss of non-Class IE sys which supplies power to common annunciators inverter failure caused by capacitor short resulting in two wave-shaping SCR failures CHIRAMAL, M Director's Office 81/01/30 Director's Office 19 15449 003 24X fiche 50-327,81/01/30,8210070122
- 821001000B Responds to FQIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON. J H Division of Rules and Records 82/06/28 UDELL.R A Critical Hass Energy Project 15pp 15727 005 24X Fichs 50-000, 82/06/28 B210010000
- --B010210037 Forwards 800505 memo re underclad cracking in reactor vessel naizles Review re safety aspects & compliance w/Bection IX of ASHE Code concludes that problem should not be included on generic issues list BAER.R L Safety Program Evaluation Brench 80/07/17 KINTNER.L Licensing Branch 2 ip 15727 175 24X Fiche 50-000,82/06/28,8210010008
- --BilliBOOOI Recommends comprehensive assessment of plant operating conditions to determine epecific predetermined time related sequences of occurrence to emergency buses SRP should be revised re design features ASME. F Director's Office App 15731 049 24X Fiche 50-000,82/06/28,8210010008
- --B210010161 Discusses potential problem re Bequoyah reactor pressure
 noizle, supplementing B00222 memo Underclad cracks found by
 use of utrasonic equipment Addl items of recent origin
 discussed Related info enci
 DENYON, H R OFFice of Nuclear Reactor Regulation, Director
 BB/02/28 AHEARNEJ, OILINGKY, V, KENNEDY, P Commissioners
 7pp 15727 178 24X Fiche 50-000, 82/06/28,8210010008
- 6210060015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J H Division of Rules and Records 82/07/12 UDELL.R.A Critical Mass Energy Project 9pp. 15645 027 24X Fiche 50-000, 82/07/12, 8210080015
- --920519042B Forwards engineering evaluation rept. "Inadvantent Loes of Reactor Coolant Events at Bequoyah Nuclear Plant.Units i & 2 "Rept contains recommendations which should be incorporated in ongoing Task Interface Agreement 81-15 LANNINO, H. D. Director's Office 82/05/11 MICHELSON. C. Director's Office ip 15976 140 24X Fiche 50-000, 82/07/12, 8210080015
- --8205190441 "Inadvertent Loss of Reactor Coolant Events at Sequoyah Nuclear Plant; Units 1 & 2." engineering evaluation rept LANNING, W D Director's Office, 82/05/31, 23pp 15666-096, 24X Fiche, 50-000, 82/07/12, 9210080015.
- --82j0080197 NRC operations of usage chart re events at facilities. 4 NRC - No Detailed Affiliation Given 82/07/12 lp 15668:221. 24X Fiche 50-000; 82/07/12, 8210080015.
- 821001010B Forwards LER 82-107/01T-0 CREEM H J. Tennesse Valley Authority, 82/09/24, 0'REILLY, J P. Region 2. Office of Director, 19, 15566.037, 24X Fiche 50-327, 82/09/24, 821001018
- --8210010115 LER 82-107/01T-0:an 82091i, annulus door (A65) & access door (A64) left open causing both trains of amargency gas treatment sys to be declared insperable. Caused by insperability of interlocks on doors.

 CARVER, A M , HARDINO, M R Tennessee Valley Authority.

 Region 2, Defice of Director. 3pp. 15566:038 24X
 Fiche. 50-327,82/09/24.8210010108
- 8210060217 Forwards LER 82-111/03L-0 OREEM H. J. Tennesses Valley Authority 82/09/30, G'REILLY, J.P. Region 2. Office of Director, 1p. 15620:196, 24X Fiche: 50-327, 82/09/30, 8210060219

- --8210060221 LER 82-111/03L-0 on 820903,while in Mode 1, one contain pressure channel for remote shutdown monitoring instrumentation failed to meet surveillance requirements Caused by closed sense line isolation valve RODERS, H.R., HARDING, M.R. Tennessee Valley Authority 82/09/3 Region 2, Office of Director 1p 15620 197 24X Fiche 50-327,82/09/30,8210060219
- -8210130452 LER 82-108/03L-0 on 820907, during Mode 1, level channel LT-63-50 on refueling water storage tank declared insperable Caused by transmitter out of tolerance due to instrument drift Loop receilibr RODERS, HR , HARDING, HR Tennessee Valley Authority 82/10/0 Region 2, Office of Director ip 15681 188 24X Fiche 50-327,82/10/05,8210130442
- 8210130317 RO 82-003 on 820731, fire detector 74F in fire Zone 70 alarmed due to steam leak in spent resin storage tank area Fire zone removed from svc until 820909 Steam leak repaired & zone placed back in svc QREEN, H J Tennessee Valley Authority 82/10/07 O'REILLY, J P Region 2, Office of Director Zpp 15678 341 24% Fiche. 50-327, 82/10/07, 8210130317
- 8210220081 Forwards LER 82-112/03L-0 GREEN,H J Tennessee Valley Authority 82/10/08 O'REILLY,JP Region 2. Office of Director 1p 15779 072 24X Fiche 50-327,82/10/08.8210220081
- --8210220085 LER 82-i12/03L-0 on 820911.upper head imjection sys faciars inoperable due to failure to meet surveillance requirements Gaused by total dissolved nitrogen & air in accumulator exceeding 80 std cubic feet limit ROGERS.HR . HARDING.MR Tennesses Valley Authority 82/10/08 Region 2. Office of Director 2pp 15779 073 24X Fiche 50-327,82/10/08,8210320081
- 8210190712 RO 82-4 on 821012, biological shield blocks removed from equipment hatch for refueling outage, breaching fire barrier penetration Verification of fire detector operability established. GREEN.H.J. Tennessee Valley Authority 82/10/12 D'REFLLY, J.P. Region 2, Office of Director 2pp 15738 139 24X Fiche: 50-327, 82/10/12, 8210190712
- 8210190378 Forwards LER 82-117/03L-0 OREEN.H J Tennessee Valley Authority 62/10/14 D'REILLY, JP Region 2. Office of Director 1p 15741 216 24X Fiche 30-327, 62/10/14/8210190378
- --8210190386 LER B2-117/03L-0 on 820914 during 81-220 test on fire just BB-B start circuititime delay estpoint on relay 182 found out of 5% tolerance of 120-s Cause not stated Time delay setpoint readjusted to within 5% tolerance ROMINE, M D , HARDINO, M R Tennessee Valley Authority 62/10/13 Region 2. Office of Director 1p 15741 217. 24% Fiche 50-327, 82/10/14,8210190378
- 8210290277 Forwards LER 82-116/03L-0 GREEN.H J Tennesses Valley Authority. 82/10/14 G'REILLY, JP Region 2, Office of Director ip 15853 140 24X Fiche 50-327, 82/10/14:8210290277
- --8210290279 LER 82-116/03L-0 on 820916, both trains of RHR sys inspiral due to inadvertent closing of RHR suction valve 1-FCV-74-2 Caused by removal of power fuses to allow work on output relays RHR pump stopped & valve reopened w/auxiliary power ROGERG.H.R.. HARDING:H R Tennessee Valley Authority. 82/10/14 Region 2. Office of Director. 2pp 15853 141. 24X Ficke 50-327.82/10/14.8210290277
- DDCKET 50-328 BEGUGYAH NUCLEAR PLANT, UNIT 2 F. Becurity, medical, emergency & fire protection plans
- 820917006B Forwards revised pages to proposed physical security plattrensmitted by 820623 ltr Pages withheld (ref 100FR2, 790). MILLS, L. M. Tennesses Valley Authority 82/09/01. ADENSAME Licensing Brench 4 lp. 14910*105 24X Fiche*50-327, 82/09/01, 820917006B.
- 82100A0347 Forwards etatus rept of meteorological program for review "Sequoyah Nuclear Plant Noucast Hanual."

 KILLS, L. H., Tennessee Valley Authority. 82/10/01. ADENSAME Licensing Branch 4. Spp. 15619:056 24X Fiche: 50-327, 82/10/01, 8210060347.

- --E210050352 "Sequoyah Nuclear Plant Nowcast Manual"

 Tennessee Valley Authority 82/09/30 70pp 15619 061 24X
 Fiche 50-327,82/10/01.8210060347
- E210250245 Forwards IE Safeguards Insp Repts 50-327/82-26 & 50-327/82-26 on 821005-08 No noncompliance noted CEFRELLI-D Division of Project & Resident Programs 62/10/22 PARRISIN G Tennessee Valley Authority 2pp 15799-136 24X Fiche 50-327. 82/10/22,8210260245
- --0210260265 IE Insp Repts 50-027/82-26 & 80-028/82-26 on 821006-08 Ma moncempliance noted Major areas inspected review of security plan & implementing procedure security organization-mgt/personnel/hesponse Details withheld (ref 100FR70 21) MORRE, D E Division of Engineering & Technical Programs 62/10/22 ip 10799 108 24X Fiths 50-007, 82/10/22, 8210260245
- P Operating license stage documents & correspondence
- 6210040426 Forwards request for addl info re hydrogen control Coordinated wtil response suggested by mid-Uct 1982, since subj is generic to ice condenser plants W/o encl AUVAK.T M Assistant Director for Licensing 82/09/17 PARRIS.H Q Tennessee Valley Authority 1p 15597 251 24X Facae 50-327, 82/09/17, 8210040426
- E210320284 Forwards "Executive Summary Rept on Adequacy of Permanent Hydrogen Hitzgation Bys for Sequoyah Nuclear Plant," in response to RL Tedesco 820413 Itr HILLS.L M Tennessee Valley Authority 82/09/27 ADENSAM.E Licensing Branch 4 ip 15653 078 24X Fiche 50-327,82/09/27,8210120284
- --8210120289 "Executive Summary Rept on Adequaty of Permanent Hydrogen Finitigation Sys for Sequoyah Nuclear Plant "

 Fennesse Valley Authority 62/09/30 Sipp 15653 079 24X
 Fiche 50-327,82/09/27,8210120284
- 3210050216 Informs that updated FSAR will be submitted in Jan 1983, in response to NRC request MILLS.L M Tennessee Valley Authority 82/09/30 ADENSAM.E Licensing Branch 4 1p 15611 236 24X Fiche 50-327, 82/09/30, 8210050216
- P2:0190110 Forwards request for add1 info on equipment temp response to hydrogen burns Coardinated util response suggested since subj generac to ice condenser plants.

 ADENSAME 0 Licensing Branch 4 82/10/01 PARRIS.H 0 Tennessee Valley Authority 4pp 15761 226 24X Fiche, 50-327, 82/10/01.
- 1210\$3QL50 Forwards add1 info re 820715 application for amend of Licenses DPR-77 & DPR-79 concerning steam generator water level low-low reactor trip setpoint MILLSL H Tennessee Valley Authority 82/10/07 DENTON-H R Diffice of Nuclear Reactor Regulation. Director 2pp. 15673 082 24% Fiche 50-327,82/10/07,8210130150
- p.210180117 Forwards request for deferral of ASME Section XI requirement to hydrostatically pressure test replacement portions of estential raw cooling water sys W/three oversize drawings Aparture cards are available in PDR MILLS,L M Tennessee Valley Authority 82/10/13 ADENSAM,E Licensing Branch 4 7pp 18718 134 24X Ficha 50-327,82/10/13, 8210180117
- IZ10Z60148 Forwards proprietary response to NRC 820809 request for info rs CLASIX code Encl withheld (rs) 10CFR2 790)
 KAMMER.D 8 Tennessee Valley Authority 82/10/18 ADENSAM, E.
 Licensing Branch 4 ip 15779 050 24X Ficha 50-327, 82/10/18, 82(02A0148)
- Inspection reports, IE Bulletins & correspondence
- 21007Q007 Responds to FDIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELYON. J M Division of Rules and Records 82/08/10 LONG, D J. Winthrop, Stimson, Putnam & Roberts, 9pp 15445.063, 24X Fiche 50-000, 82/08/10, 8210070007.
- -B210070139 Forwards tabulated data on steam generator insp & maint at Pacilities. Data should be provided to licensees IPPGLITG.T. Operating Reactors Assessment Brench B2/04/01 VAROALS Deprating Reactors Branch 1 5pp. 15445-131 24X Fiche-50-000,82/08/10,8210070007

- 8210010476 Forwards corrected notice of violation, revising notice issued w/IE Insp Repts 30-327/82-18 & 50-328/82-19 on 820706-0805
 LEMIS.R C. Division of Project & Resident Programs 82/09/17
 PARRIS.H 0 Tennessee Valley Authority 2pp 15372 172 24X
 Fiche 50-327, 82/09/17, 82/100/10476
- --8210010477 Corrected notice of violation from insp on 820706-0805
 Noncompliance noted activities affecting safety-related
 function of critical sys, structures & components not
 accomplished per drawings
 # Division of Project & Resident Programs 82/09/17 ip
 15372:174 24X Fiche 50-327,82/09/17,8210010476
- 8210010130 Ack receipt of 820830 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-05 & 50-328/82-05 LEHIS,R C Division of Project & Resident Programs 82/09/20 PARRIS.H © Tennessee Valley Authority ip. 15566 009 24X Fiche 50-327,82709/20,8210010130
- --82i00i0135 Reponds to NRC 820809 ltr re violations noted in IE Insp Repts 50-327/82-05 & 50-328/82-05 Corrective actions program initiated to schedule temporary employees for training in QA area KAMMER.D B Tennessee Valley Authorsty 82/08/30 O'REILLY, J P Region 2. Office of Director 3pp. 15566 010 24X Fiche 50-327,82/09/20,8210010130
- B210150225 Ack receipt of B20921 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-16 & 30-328/82-16
 LEWIS,R.C Division of Project & Resident Programs B2/10/05, PARRIS.H 0 Tennessee Valley Authority 1p 15706:061, 24X Fiche 50-327,82/10/05,8210150225
- --8210150231 Responds to NRC 820820 ltr re violations noted in IE Insp. Repts 50-327/82-16 & 50-328/82-16 Corrective actions delinquent GA audit findings identified & corrective action escalation program developed MILLS.L.M. Tennessee Valley Authority 82/09/21 0'REILLY, J. P. Resion 2. Office of Director 5pp 15704 062 24X Fichs. 50-327, 82/10/05, 8210150225
- --8210150237 Forwards IE Insp Repts 50-327/82-16 & 50-328/82-16 on 820712-16 & notice of violation LEWIS.R.C Division of Project & Resident Programs, 82/08/20 FARRIS.H O Tennesses Valley Authority 2pp 15706-067, 24x Fiche 50-327,82/10/03,8210150225.
- --8210150245 Notice of violation from inep on 820712-16

 * Region 2, Office of Director 82/08/20. 2pp. 15706.069. 24x
 Fichs 50-327.82/10/08/8210150225.
- --8210150256 IE Insp Repts 50-327/82-16 & 50-328/82-16 on 820712-16
 Noncompliance noted operations GA manual not reviewed by
 GA staff & no measures established to assure that GA
 procedures & revisions implemented
 BELISLE.O A., FREDRICKSON.P., UPRIGHT,C M Division of Engineering
 & Technical Programs. B2/05/18. 12pp 15706.071. 24x
 Fiche 50-327,82/10/05,8210150225.
- 9208190233 IE Info Notice 80-35, Suppl t, "Leaking & Dislodged I-125 Implent Seeds " Syc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguerds. 62/10/06 Consolidated Edison Co of New York 66pp. 15761-200 24X Fiche-50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Btress Correston Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys-Fiping at BWR Plants," Syc list encl. DEYOUND, R.C. Director's Office, Office of Inspection and Enforcement, 82/10/14, Consolidated Edison Co. of Naw York, 115pp 15810; 125 24X Fiche 30-000, 82/10/14,8208190238
- 8210220469 Ack receipt of 821005 itr informing NRC of steps taken to correct violation nated in IE Insp Repts 50-327/82-19 to 50-328/82-19.

 LEMIS.R.C. Division of Project & Resident Programs. B2/10/18, PARTIS.H.O. Tánnessee Velley Authority. 1p. 15779:103, 24% Fiche.50-327,82/10/18.8210220469
- --8210220474 Responds to NRC B20903 itr re violation noted in IE Insp. Repts 50-327/82-19 & 50-328/82-19. Corrective actions all affected analysts reminded to record data on TI-37 log sheat per Gaseous Efficient Requirements Procedure 81-415 HILLS.L M Tennessee Valley Authority. 82/10/05. O'REILLY, J. Region 2. Diffice of Director 2pp. 15779:104. 24X Fiche: 50-327, 82/10/18, 8210220469

- --8210220480 Forwards IE Insp Repts 50-327/82-19 & 50-328/82-19 on 820816-20 & notice of violation VERRELLI, D M Division of Project & Resident Programs. 82/09/03 PARRIS.H O Tennessee Valleg Authority 2pp 15779 106 24X Fichs 50-327,82/10/18,8210220469
- --8210220482 Notice of violation from Insp on 820816-20 * Division of Project & Resident Programs 82/09/03 ip 15779 108 24X Fiche 50-327,82/10/18,8210220469
- --B210220485 IE Insp Repts 50-327/82-19 k 50-328/82-19 on B20816-20 Noncompliance noted on B20727.noble gas release rates not recorded on TI-37 log sheet B 35 for all effluent radiation monitors declared inoperable due to power failure COLLING.T R . BARR.K.P Division of Engineering & Technical Programs 82/09/02 7pp 15779 109 24X Fichs 50-327,82/10/18,8210220469
- 8210260245 Forwards IE Bafeguards Insp Repts 50-327/82-26 & 50-328/82-26 on B21006-08 No noncompliance noted. VERRELLI.D. Division of Project & Resident Progrems. B2/10/22 PARRIS.H G Tennessee Valley Authority 2pp 15799 136, 24X Fiche 50-327, B2/10/22, 8210260245
- --8210260265 16 Insp Repte 50-327/82-26 to 50-328/82-26 on 821006-08 No noncompliance noted Major arees inspected, review of security plan & implementing procedure security organization-mpt/personnel/response Details withheld (ref 100FR73 21) MODRE, D.E., MCGUIRE, D.R. Division of Engineering & Technical Programs. 82/10/22 lp 15799.138 24X Fiche 50-327,82/10/22,8210260245

S Reportable occurrences. LERs & related correspondence

- 8210080015 Add1 response to FOIA request for 19 cetegories of info re nuclear reactor events & safety problems Forwards documents listed in App A. Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON-J M Division of Rules and Records 82/07/12 UDELL-R A Critical Mass Energy Project 9pp 19565:027 24X
 Fiche. 50-000:82/07/12.8210080015
- --8205190428 Forwards engineering evaluation rept, "Inadvertent Loss of Reactor Coolant Events at Sequoyeh Nuclear Plants Units 1 & 2 "Rept contains recommendations which should be incorporated in engoing Task Interface Agreement 81-13, LANNING.W D Director's Office 82/05/11. MICHELSON.C Director's Office 1p 15876 140. 24X Fiche, 50-000, 82/07/12, 8210080015
- --B205190441 "Inadvertent Loss of Reactor Coulant Events at Sequoyah Nuclear Plant.Units 1 & 2." engineering evaluation rept LANNING. W D Director's Défice. 82/05/31. 23pp 15666 096. 24X Fiche. 50-000.82/07/12:8210080015
- 8210130572 Forwards LER 82-110/03L-0 GREEN-H J. Tennessee Valley Authority 82/10/05 D'REILLY, J P. Region 2. Office of Director 1p 15679:104 24X Fiche-50-328.82/10/05.8210130572

- ---8210290094 LER 82-115/01T-0 on 821002, inner & outer doors of upper containment personnel airlock were open simultaneousig dus to latch ber blocking outer door open Caused by door swing operating chain being out of adjustment, Chein adjusted KRKLO B , HARDINO, M R Tennessee Valley Authority 82/10/14 Region 2. Office of Director 2pp 15854 010 24% Fiche 50-328, 82/10/14, 8210290091
- 8210260188 Forwards LER 82-118/03L-0 OREEN.H J Tennessee Valley Authority 82/10/20 O'REILLY.JP Region 2. Office of Director ip 15799 032 24X Fiche 30-328,82/10/20.8210260188
- --8210260196 LER 62-118/03L-0 on 820921, diesel generator operability essential raw cooling water valves I-FCV-67-66 & 68 failed to open on diesel generator IA-A start signal Caused by circuit breekers baing left open during tasting ROMINE.W D . HARDING.N R Tennessee Valley Authority. 62/10/20 Region 2. Office of Director ip 15799 033 24X Fiche 50-328,82/10/20.8210260188
- 8210290274 Final rept for Deficiencies B & E & seventh interia rept for Deficiencies A & D re control of procurement activities Initially reported on BIO316 Final corrective actions noted Next rept expected by 830428 MILLS.L M Tennessee Valley Authority 82/10/21 O'REILLY, J.P. Region 2, Office of Director 4pp 15853 143 24X Fiche 50-000, 82/10/21, 8210290274

DOCKET 50-329 HIDLAND PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8207070419 Forwards application for Amend 106 to CP & OL applications, consisting of Revision 44 to FBAR Three hundred nimety-four drawings encl Aperture cards ere available in PDR COGK, J. M. Consumers Power Co. 82/06/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 13776 028 24% Fiche 80-327, 82/06/28, 8207070419
- --8207070422 Application for Amend 106 to CF & DL epplications, consisting Revision 44 to FBAR COOK.J N Consumers Power Co 82/06/28 20pp 13796 030 28K Fiche 50-329, 82/06/28, 8207070419.
- 8210080015 Add1 response to FOIA request for 19 categories of information reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref. FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 9pp 15665 027 24% Fiche: 30-000.82/07/12,8210080015
- 8210010437 Provides add1 info to 820812 itr re cooperative evaluation program w/NRC.per NRC 820720 request Program provides capability for rapid response to NRC concerns & supports mear—term approval of Itam II K. 3.30.

 COOK. J. H. Consumers Power Co. 82/09/10 DENTON. H. R. Division of Licensing. 6pp 13570 205 24X Fiche 80-329, 82/09/10.8210010437
- 8210270228 Forwards Amend 108 to application for CPs & OLs, consisting of Revisions 6 & 3 to security plan & safeguards contingency gian, respectively, Plans withheld (ref 10CFR73 21).
 COOK, J W Consumers Power Co. 82/07/23 DENTON, H R Division of Licensing 2pp 18853-284 24% Fiche-80-329, 82/07/23-8210290228
- --B210270229 Application for Amend 108 to application for CPs to Octoonsisting of revised drawings for security plan & anfequents contingency plan, Drawings withheld (ref 10CFR73, 21)
 COOK.J.W. Consumers Power Co. B2/09/28, 1p 15853:286 24X
 Fiche: 50-327, 82/09/23, 8210270228.
- B210220511 Forwards WPPBB 820825 & 0909 & CPC B20812 ltrs re Ekk puners group 820720 meeting w/NRC re resolution of NUREO-0737. Item II K. 3.30 on small break LOCA methods Appropriate action should be taken ADENBAM. E O Licensing Branch 4. 82/10/04 SHERON. B. W Resolution States Branch. 1p. 15786.091. 24X Fiche: 50-000, 82/10/04. 8210220511.
- B210120276 Forwards independent design adequacy review & "Performants Objectives & Criteria for Const Project Evaluations." INPO preliminary rept.
 COOK. J. M. Duke Power Co. B2/10/05. DENTON, H. Office of Nucleir Reactor Regulation, Director KEPPLER, J. G. Region G. Office of Director. JOpp 15651:322 24X Fiche:50-329,82/10/05.8210120276

- -2210120281 "Performance Objectives & Criteria for Const Project Exalvations," preliminary rept Institute of Nuclear Power Operations 82/09/30 67pp 15551 352 24X Fiche 50-329,82/10/05,8210120276
- RIOIGO267 Requests add1 info re util position on Reg Quide 1 58, Revision 1. "Qualification of Nuclear Power Plant Insp. Eran & Testing & Audit Personnel"
 ADEAMSAM.E G Licensing Dranch 4 B2/10/05 CDOK, J W Consumer. Power Co App 15746 007 24X Fiche 50-329,82/10/05,8210180267
- PiGl3G264 Forwards Amend 109 to application for CPs & OLs, consisting of Revision 45 to FSAR (CGX.J H Consumers Power Co 82/10/07 DENTON, H R Office of Ajelear Reactor Regulation, Director 3pp 15676 015 24X Fiche 50-329, 82/10/07, 8210130264
- ©210130266 Amend 107 to application for CPs & OLs.consisting of Fevision 45 to FBAR COOK, J W Consumers Power Co 82/10/11 2pp 15676 018 24X Fiche 50-329,82/10/07,8210130264
- 10150441 Discusses reasons why deletion of requirement for four point proof jacking of feedwater isolation valve pit is essential fart of remedial action to be achieved prior to excavation beneath feedwater isolation valve pit WARNICK.R F Region 3. Office of Director 82/10/08 MILLER.D B Consumers Power Co 2pp 15703 151 24X Fiche 50-329.82/10/08.
- 8210150441
- 10190354 Forwards Affidavit of Eve re Amend 109 (Revision 45 to FSAR) to application for CPs & OLs SULLIVAM,T J Consumers Power Co 82/10/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 15740 318 24X Fiche 50-329,82/10/15,8210190364
- 10210294 Forwards Revision 1 to NUS-4146, "Analysis of Flammable Concentrations at Midland Nuclear Plant From Natural Gas Pipeline Breaks," in response to NRC 820823 request for
- SOUCK.) H Consumers Power Co 82/10/19 DENTON,HR Office of Nuclear Reactor Regulation, Director 9pp 15764 104 24X Fache 50-329,82/10/19,8210210294
- 8210210301 "Proposed Oas Pipeline Leak Detection Sys " STONER,M A Stoner Associates, Inc 82/10/12 22pp 15764 112 24% Fiche 50-329,82/10/19,8210210294
- 8210210306 "Analysis of Flammable Concentrations at Midland Nuclear Plant From Natural Gas Pipeline Breaks," Revision i Seven oversize drawings encl Aperture cards available in PDR MATHANS J. FULFORD, P. J. KAIBER, Q.D. NUB Corp. NUB-4146 R01 E-2/10/07 58pp 15764 135 24X Fiche 50-327,82/10/19,8210210294
- NAC Safety Evaluation Report (SER), suppls & correspondence
- 10010278 Forwards "Failure Mode & Effects Analysis of Midland Non-Nuclear Instrumentation & Integrated Control Bys," in response to FSAR Questions 30 56-30 59. Info completes review
- of SER Confirmatory Item 22
 COCIN.J H Consumers Power Co 82/09/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15574.077 24X
 Fiche 50-329, 82/09/23, 8210010278
- 8210010284 "Failure Mode & Effects Analysis of Midland Non-Nuclear Instrumentation & Integrated Control Bys " ENIINNAR B., HINKB.R W., BWARTZELL, B.D. Babcock & Wilcox Co BAN-1743 82/07/31 Sipp 15574, 079 24X Fiche. 50-329, 82/09/23, 8210010278
- 10190920 Forwards proprietary reactor test data per BER.in support of util position re estimates of full power yrs estimated to result in drop in upper shelf energy UH Taylor affidevit enc t Test data eithheld (ref 100FR2 790 & 100FR9 12) COOK.J W Consumers Power Co 82/10/05 DENTON.H R Office of Nuclear Reactor Regulation, Director 7pp. 15735 022 24X Fiche 50-229.82/10/05,8210170520
- 10200099 Notification of 821109 meeting w/util, Stoner Associates & PNUS in Bethesda, MD to discuss SER Open Item 1 re ensite natural gas pipeline.
 HEERINAN R W Licensing Branch 4 82/10/13 ADENBAM, E, 0 Licensing Branch 4 82/10/13 ADENBAM, E, 0 Licensing Branch 4 89p 15767 317. 24X Ficher 50-329, 82/10/13, 8210200099
- 日の270039 Notification of 821020 meeting w/util & Summit Nuclear in Bethesde,代D to discuss SER confirmatory Item 26 re independent safety engineering group H近日NANAR 以 Licensing Branch 4 82/10/19 ADENBAM,E 0 Licensing Branch 4. 3pp, 15836:270 24X Fiche 50-327,82/10/19,8210270039.

- 8210210030 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF MIDLAND PLANT, UNITS 1 AND 2 Doctet Nos 30-329 And 50-330 (Consumers Power Company) # Office of Nuclear Reactor Regulation, Director MUREO-0793 #82/10/31 168pp Available at NRC #9 50 15785 015 24X Fiche 50-329, #2/10/31, #210210030
- F Security, medical, emergency & fire protection plans
- 8210130004 Releases public version of nuclear accident apps to smergsncy preparedness plan FELTON.J M Division of Rules and Records 82/09/23 Docum Hanagement Branch 1p 15695 001 24X Fiche 50-329,82/09/23, 8210130004
- --8210130005 Forwards public version of nuclear accident apps to Bay, Saginaw & Midiand County, MI emergency preparedness plans COOK, J W Consumers Power Go B2/09/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 15695 002 24X Fiche 50-329, 82/09/23, 82/0130004
- -8210130007 Public version of nuclear accident apps to Bay, Saginaw & Midland County, MI emergency preparedness plan * Consumers Power Co 82/09/01 437pp 15695 006 24x Fiche 50-329, 82/09/23, 8210130004
- 8210270228 Forwards Amend 108 to application for CPs & OLs, consisting of Revisions & & 3 to security plan & safeguards contingency plan, respectively Plans withheld (ref 10CFR73 21) COOK, J Consumers Power Co 82/09/23 DENTON, H R Division of Licensing 2pp 15853 284 24X Fiche 50-329, 82/09/23, 8210290228
- --B210290229 Application for Amend 108 to application for CPs & OLs, consisting of revised drawings for security plan & safeguards contingency plan Drawings withheld (ref 10CF873 21) IOURICA (1) Consumers Power Co 82/09/28 1p 15893 286 24X Fiche 50-329,82/09/23,8210290228
- 921008018B Informs that activities performed 920925 considered emergency measures to ensure safe fire protection of facility Remedial stop work order not violated MARNICK F Region 3, Office of Director 82/10/05 COOK, J W Consumers Power Co ip 15640.179 24X Fiche 50-329.82/10/05, 021008018B. 8210080188
- O Adjudicatory correspondence
- B210220294 Comments on petition for rulemaking PRM-50-32B re ejectromagnetic pulse in nuclear power plants Requests that 10CFR30 be amended to require provision for design features for protection against attacks & destructive acts MARSHALL,W H Mapleton Intervenors B2/08/31 Office of the Secretary of the Commission 2pp 15776 066 24X Fiche: 50-329, 82/08/31, 8210220294
- 8210040057 Response opposing B Stamiris 820904 motion for partial initial decision on QA adequacy Underpinning excavation work will not be authorized unless NRC satisfied w/util QA proposals Certificate of Svc encl WILCOVE, M N Hearing Branch 2 82/09/24 Atomic Safety and Licensing Board Panel 9pp. 15584.223 24X Fiche 50-329,82/09/24,8210040057
- 8210050221 Response to M Binclair resubmitted contention on Table 8-3 Contention should be deferred until Commission Issues policy statement Certificates of Bvc encl WEBT,A.E Consumers Power Co. WEBT,A E isham, Lincoln & Beale 82/09/28 Atomic Safety and Licensing Board Panel 8pp 19609.062 24% Fiche 50-329,82/09/28,8210050221
- 8210030223 Motion to compel M Sincleir to respond to applicant 820830 request for admission of truth of relevant matters of fact or alternatively; to deem matters of fact admitted Certificate of Svc encl Related correspondence STEPTOE, P. Consumers Power Co. STEPTOE, P. Isham, Lincoln & Beale 82/07/28 Atomic Safety and Licensing Board Panel 5pp. 15610:337. 24% Fiche, 50-327, 82/07/28, 8210050223
- --8210050229 Request for admission of truth of relevant matters of fact re Contention 5 Certificate of Svc encl.
 MILLER.M. I Consumers Power Co. MILLER.M. I. Isham, Lincoln & 8eale 82/08/30, Sinclair, M. 4pp 15610 344 24X
 Fiche: 50-329, 82/09/28, 8210050223.

- 8210050230 Responses opposing B Staminis 820913 addendum to 820824 cost benefit contention Good cause for late filling not demonstrated Centificate of Svc encl HEST.A E Consumers Power Co HEST.A E Isham, Lincoln & Beals 82/09/28 Abomic Safety and Licensing Board Pensi. 5pp 19611 019 24X Ficha 50-329,82/09/28.8216050230
- E210010062 Response apposing M Sinclair resubmitted Contention i Court of Appeals.DC Circust decision does not affect contention deferral Court stayed effect of decision until Commission policy statement issued Certificate of Sec encl WILCOVE.H N Hearing Branch 2 82/09/29 Atomic Safety end Licensing Board Panel Spp i5565 004 24% Ficha 50-329,82/09/29,6210010052
- B210010254 Memorandum memorializing B20927 telcon re board notification on soils remedial QA procedures that may affect ASLB consideration of B Batamiris motion for partial initial decision on QA adequacy in soils remedial work HARBOUR, J Abomic Safety and Licensing Board Penel 82/09/29 2pp 15574 058 24% Fichs 50-329,82/09/29,8210010254
- 82i004C018 Response to remainder of M Binclair revised contentions based on discovery No objection to Revised Contentions 6,34 & portions of 56 Opposes Contentions 34,43 & portions of 56. Winotice of appearance & Certificats of Svc. WILCOVE, M N. WRIGHT, N A Hearing Branch 2. 82/09/30 Atomic Safety and Licensing Board Panel. 17pp 15581 280 24X Fiche 50-329,82/09/30,8210040018
- 8210050215 Response to M Sinclair 820920 revised contentions. Set II
 Objects to Contentions 34(a),37 & 43 & portions of
 Contentions & & 57 Util nonconformance rept & Certificate of
 Svc enct
 STEPTOE, P P. Consumers Power Co STEPTOE, P P. Isham, Lincoln &
 Beals. 82/07/30 Atomic Safety and Licensing Board Panel 13pp
 1941 073 24X Fiche 50-329,82/09/30.8210050215
- 821005023B Forwards changed Interrogatories as notion to compet discovery responses, addressing same fiscuss as 820830 interrogatories M/o enci Related correspondence STAMIRIB.B Stamiris, B. 82/09/30 Atomic Safety and Licensing Board Panel. 1p 15609 050 24X Pichs 50-329,82/09/30,8210050230
- 8210050240 Motion to compel answers from util to 820830 ravised interrogatories re Contention 1b ASLB 820814 ruling on decommissioning supports need for comparative analysis of decommissioning estimates Related correspondence.
 8TAMIRIS, B. Stamiris, J 82/09/30 Atomic Sefety and Licensing Board Panel. 3pp 15610,336, 24X Fiche: 50-329,82/09/30,8210050840
- 8210060193 Response opposing M Sinclair resubmitted Contention 56 on station blackout Contention lacks requisite basis & specificity to stand alone Certificate of Svc encl.

 ERUNNER, J.E. Consumors Power Co. 82/09/30 Aboxic Safety and Licensing Board Panel. Opp 15614.237, 24X Fiche.50-329,82/09/30,8210050193
- 8210050246 Porwards AJ Boos 820930 ravised effidavit, correctly Identifying contention as Electair Contention 6.8vc list encl. Related correspondence.

 BRURNER, J E. Consumers Power Co. 82/10/01 STAMIRIB, B. Stamirie, B Jpp 15609-081 24X Fiche, 50-329, 82/10/01, 8210050246
- 8210070378 Objections to util refusal to ensuer 8 Stamiris
 Interropatories 4 through 11 & 18 Issues relevant to scope
 of contentions. Meeting should be scheduled to finalize
 decomplissioning plans. Related correspondence.
 MARSHALL, H H Hapleton Intervenors MARSHALL, H, H Marshall, H H
 82/10/02 About 86fsty and Licensing Board Panel. 2pp
 15633 248 24% Fiche: 50-327, 82/10/02, 8210070398
- 8210070132 Motion to compsi util to answer second set of interrogatories based on new into Interrogatories are narrow in scope, based on new into Interrogatories are narrow in scope, based on new into In FES & directly relevant to admitted Contention 5, Related correspondence BIEHOP, L. L. SinclaireM. BISHOP, L. L. Bishop, L. 82/10/04 Atomic Safety and Licensing Beard Panel Spp. 13627:043, 24X Fiche. 50-529, 82/10/04,8210070132.
- 8210070136 Responses to applicant & NRC 820903 & NRC 820910 responses to M Sinclair revised contentions Limiting Contention Si to litigation of util compliance w/existing requirements Contention 32 amended.

 SISHOP.L L. Sinclair.M. BISHOP.L L. Bishop. L.L. 82/10/04. Atomic Bafety and Licensing Board Panel. 11pp. 15627:020 24X Fiche: 50-329, 82/10/04, 8210070136.

- 82100A0229 Order allowing M Sinclair to reply to NRC & util 820929 respenses to Sinclair 820920 revised contentions by 821013 B Stamiria may reply to applicant 820923 & 20 & NRC 820929 responses to Stamiria contention by 821016 SECHNOFFER. C. Atomic 8afety and Licensing Board Panel 82/10/0: STANIRIG.8 Stamiria 8 SINCLAIR.M Sinclair.M 2pp 15620 24X Fiche 50-329.82/10/05.8210060229
- 8210070140 Response to request for production of documents BINCLAIR, M Binclair, M BINCLAIR, M Bishop, L L 62/10/06 4 13627 080 24% Fiche 30-329, 82/10/06, 8210070140
- 8210080082 Advises that NRC will voluntarily respond to B Stairsh
 M Binclair 820913 & 20 interrogatoris; respectively
 Objections to interrogatories for reasons other than
 noncompliance w/iOCFR2 720(h) not waived
 MRIGHT, N A Hearing Branch 2 82/10/06 BECHHOEFER, C. IMREDUA
 CCHAN, F.P. Atomic Safety and Licensing Doard Panel 2pp
 19643 277 24X Fichs 50-329, 82/10/06.8210080062
- 8210130482 Notice of appearance in proceeding Cartificate of Svc en STAHL.D M Consumers Power Co STAHL.D M Isham. Lincoln & Bea 82/10/06 4pp 15682 170 24X Ficha 50-327,82/10/06.8210130482
- 8210080066 Informs of agreements between perties rs NRC request the util not take depositions of listed persons & discovery on M Sinclair & B Stamiris tontentions alleging deficiencies in Zack Co QA PATON.H D Hearing Branch 2 82/10/07 BECHIOEFER.C. COMAN.F | HARBOUR.J Atomic Safety and Licensing Board Pansi 2pp 15643 035 24% Fiche 50-329.82/10/07.8210080066
- 8210130304 Hamorandum mamorializing 821006 telcon re issuente of SD issues to be considered at hearings, identification of witnesses, discovery & new contentions BECHHOEFER.C Atomic Gafety and Liesnsing Board Panel 82/10/03 4pp 15678 343 24X Fithe 50-327,82/10/08,8210130304
- 62:10130421 Notice of resumption of evidentiary hearings in consolidated CL/OM proceeding on 82:1027 & continuing on 82:1028-30 & in 101-05, to satent necessary Hearings to be held in Midland, MI BECHHOEFER. C Atomic Sefety and Licensing Board Panes: 02/10/09 ip 15680 245 24X Fiche 50-329,82/10/08,8210130421
- 8210180212 Response to B Stamiris 820930 motion to compile responses revised interrogatories. Util has no objection to responding voluntarily to amended interrogatories Certificate of Evencel. Related correspondence BRUNNER, J E. Consumers Power Co. 82/10/12 Atomic Sefety and Licensing Board Panel 3pp 15718 103 24X Fiche 50-329, 82/10/138210180212
- 8210200061 Response opposing util 820928 motion to compet response to util 820930 requests for admissions from M Sinclair Sincleir 820914 response raised relevant objections Certificate of 8vc encl Related correspondence 8 HEHO? L. L. Sinclair. M. BIGHOP. L. Harmon & Weiss 82/10/13 Atomic Safety and Licensing Board Panel 3pp 15754.135 24% Fiche 50-329,82/10/13,8210200061
- 8210200054 Repty to NRC & applicant responses to M Sinclair rivises Contentions 6,34,37,43,56 & 57. Contention 6, bases (e), (b) & (d)(4). Contention 43 & Contention 56, Basis 3, withdrawn Certificate of Svc enci BISHOP, L L Harmon & Heiss B2/10/15 Atomic Safety and Licensing Board Panel 7pp 15753 076 24K Fiche. 50-329, 82/10/15.8210200054
- 8210210970 Response to util 820923 & NRC 820928 response to 8 Sizeira new contention based on FES. Grass misrepresentation of overall costs & benefits to public represented by cost/benefit anelysis demands redress
 STAMIRIS, B Stamiris, B. 62/10/15 Atomic Safety and Licensing Board Panel 9pp 18763.168 24X Ficher: 50-329, 62/10/15, 621021637
- 8210200051 Lists sections of SER & SER Suppl 2 NRC will appropriate testimony relistues to be covered At 821027-1105 hearings Testimony relistues to be addressed during second will be filed on 821022.

 HILCOVEN N. Hearing Branch 2 82/10/18. BECHHOEFER.C., MARBOUR.J. COMAN.F.P. Atomic Bafety and Licensing Board Punel Opp. 15756-042 24% Fiche: 50-329.82/10/18.8210200051
- 8210210427 Order extending time until 821026 for Commission to sold review ALAB-691 CHILK, B.J. Office of the Secretary of the Commission 82/10/18 Commissioners, ip 15762-271 24X Fichs, 50-329, 82/10/18.

- 8210210290 Notice of rescheduled evidentiary hearings for 821115-20 & 22-23 EECHODEFER. C Atomic Safety and Licensing Board Panel 82/10/19 By 15765 073 24X Fiche 50-329, 82/10/19, 8210210290
- 6210220381 Response upposing M Sinclair 821004 motion to compet applicant to answer Sinclair second set of interrogatories based on new info Interrogatories vague. Incomprehensible & irrelevant W/Certificate of Svc Related correspondence. ERUNNER. J E Consumers Power Co 82/10/19 Atomic Bafety and Licensing Board Panel 14pp 15780 176 24X Fiche 50-329.82/10/19, 8210220391
- 8210220322 Mamorandum & order rejecting WH Marshall 820910 contentions based on SER & dismissing Contention 5 BER contentions filed late w/o any justification Marshall falled to revise Contention 5 per ASLB 79023 order after FES issued BECHMOEFER.C Atomic Safety and Licensing Board Panel 82/10/20 MARSHALLW H Marshall W H 9pp 15776 029 24X Fiche 50-329, 82/10/20,8210220322
- 2210260364 Forwards LERs as attachments to NRC 820728 responses to M Sinclair interrogatories MFLCOVE.H N Hearing Branch 2 82/10/25 BISHOP.L L Harmon & Wesse BISHOP.L L Sinclair.M ip 15804.165 24X Fiche 50-329.82/10/25.8210260364
- 1210260388 Forwards info in response to JW Cook 820914 ltr to H Denton re environ qualification of electrical & mechanical equipment wilcove. M M Hearing Branch 2 82/10/25 BRUNNER, J E Consumers Power Co 4pp 15803 344 24X Fiche 50-329, 82/10/25, 8210260388
- 210270161 Order extending time until 821029 for Commission to act to review ALAB-691
 CHJLK.S J Office of the Secretary of the Commission 82/10/26
 Commissioners in 15823 010 24X Fiche 50-329,82/10/26, 823.0270161

Utilaty Final Safety Analysis Report (FBAR) & amends

- 207070419 Forwards application for Amend 106 to CP & OL applications. consisting of Revision 44 to FBAR Three hundred ninety-four drawings enci Aperture cards are available in PDR COOK. J H Consumers Power Co 82/06/28 DENION.H R Office of Nuclear Reactor Regulation. Director 2pp 13776 028 24X Fiche 50-329, 82/06/28, 8207070419
- -8207070422 Application for Amend 106 to CP & UL applications, consisting of Revision 44 to FSAR COOK, J H Consumers Power Co 82/06/28 20pp 13796-030, 24X Fiche 50-329, 82/06/28,8207070419
- 9207070428 Revision 44 to FSAR W/394 oversize P&IDs.electrical & instrumentation control drawings.piping isomatrics.revision sheets & facing sheets Aperture cards are available in PPR + Consumers Power Co 82/06/30, 3933pp 13796 038 24X Fichs 50-329,82/06/28,8207070419
- '10130264 Forwards Amend 109 to application for CPs & OLs, consisting of Revision 45 to FSAR COOK. J U Consumers Power Co 82/10/07 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp, 15676,015 24X Fiche 50-329, 82/10/07, 8210130264
- 8210130266 Amend 109 to application for CPs & OLs, consisting of Revision 45 to FBAR CODK.JW Consumers Power Co 82/10/11 2pp. 15676 018 24X Fichs: 50-329, 82/10/07, 8210130264
- 8210130267 Revision 45 to FBAR

 # Consumers Power Co 82/09/30 626pp, 15676.020 24%
 Fichs 50-329,82/10/07,8210130264
- 10570344 Forwards Affidavit of Svc re Amend 109 (Revision 45 to FSAR) to application for CPs & DLs
 SULLIVAN, T J Consumers Power Co 82/10/15, DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 19740, 318 24X
 Fiche: 50-329, 82/10/15, 8210190344

Advisory Committee on Reactor Safeguards reports & correspondence

LO270417 Summary of ACRS Subcommittee on Midland Plant Units 1 & 2 320602 meeting in Mashington DC re application for OL
 ACRS - Advisory Committee on Reactor Sefeguards 82/08/16 ACRS - Advisory Committee on Reactor Sefeguards 25pp. 15833, 287 24% Fichs 50-329, 82/08/16, 8210270417.

- 8210270433 Summary of ACRS Subcommittee on Midland Plant Units 1 & 2 820520-21 meetings in Midland.MI re application for OL * ACRS - Advisory Committee on Reactor Safeguards 82/08/14 ACRS - Advisory Committee on Reactor Safeguards 78pp 15835 059 24X Fiche 50-329:82/08/16,8210270433
- 8210280034 Summary of 266th ACRS mosting on 820603-05 in Washington, DC re Midland OL review, pressure vessel integrity, seismir events in emergency planning, control room habitability & Subcommittee on Energy Research & Production questions ** ACRS Advisory Committee on Reactor Safeguards 82/10/08 ACRS Advisory Committee on Reactor Safeguards 40pp 15862 297 24% Fiche 50-329, 82/10/08, 8210280034

Q Inspection reports. IE Builetins & correspondence

- B210080015 Add1 response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents issted in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON. J. H. pivision of Rules and Records 82/07/12 UDELL, R. A Critical Mass Energy Project 9pp 15665 027 24X Fiche, 30-000, 82/07/12, 8210080015
- ---B203040536 Comments on 011218 corrections to facility assessment contained in NUREQ-0834 re hearings & discussion of systematic assessment of license performance Revision to NUREQ inappropriate issue classed MOSELEY, N C Systematic Assessment of Licensee Performance Review Group B2/01/04 LESSMAN, R H NRC No Detailed Affiliation Given ip 15668 256 24% Fiche-50-000, B2/07/12, B210080015
- --8203040538 Forwards performance element summary for Jul 1979-June 1980 in response to ABLB request for testimony on systematic assessment of license performance in general & facility assessment in particular WESBMAN,R H Director's Office. Office of Inspection and Enforcement 81/12/18 MOSELEY.N C Systematic Assessment of Licensee Performance Review Group. 2pp. 15648-254 24X Fiche 50-000,82/07/12,8210080015
- --8210080161 Systematic assessment of licensee performance notes re facility evaluation for Jul 1979-June 1980 NRC - No Detailed Affiliation Given 80/06/30 Spp. 15668 O71 24X Fiche S0-000,82/07/12,8210080015.
- 8210050139 Forwards IE Insp Repts 50-329/82-18 & 50-330/82-18 on 820713-0829 & notice of violation MARNICK, R. F. Region 3, Office of Director 82/09/22, COOK, J W. Consumers Power Co 2pp 15605, 193 24X Fiche: 50-329, 82/09/22, 8210050139.
- --8210050144 Notice of violation from insp on 820713-0825. WARNICK: R Region 3. Office of Director 82/07/22 3pp 15605:195 24X Fiche. 30-329,82/09/22.8210050139.
- --8210050154 IE Insp Repts 50-329/62-18 & 50-330/62-18 on 820713-0825, Noncompliance noted failure to translate requirements into drawings, in adequate procedure & failure to accomplish activities in accordance w/drawings GARDNER, R N , LANDSMAN, R B, SHAFER, W D Region 3, Office of Director, 82/09/21 7pp 15605-198 24X Fiche:50-329, 82/09/22, 8210050137
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leeking & Dislodged I-IR5 Implant Seeds," Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safaguards 82/10/06 Consolidate Edison Co. of New York 66pp 15761.230 24X Fiche, 50-000.82/10/06.8208190233.
- B210190739 Forwards IE Insp Repts 50-329/82-20 & 50-330/82-20 on 820820-0920. No noncompliance noted MARNICK: RF Region 3. Office of Director 82/10/06. COOK, J M Consumers Power Co 2pp 15737,076 24X Fiche 50-329,82/10/06,8210190739
- --8210170750 IE Insp Repts 50-329/82-20 & 50-330/82-20 on 820820-0920, No noncompliance noted Major areas inspected; remadial soils work activities training for soils activities, matls used by Zack Go & protective tagging procedures
 8UR0E86,8 L., COOK, R.J., QARDNER, R N Region 3, Office of Director 82/10/06, 5pp. 15737:078, 24X Fiche:50-329,82/10/06,8210190739
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter: Stainless Steel-Recirculation Sys Piping at SWR Plants "Syc list encl.
 DEYQUNO: R. C Director's Office. Office of Inspection and Enforcement 82/10/14. Consolidated Edison Co. of New York.
 115pp 15810-125. 24X Fiche: 50-000, 82/10/14,8208190238

DOCKETED HEMS

- 8210260190 Ack receipt of 820930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/82-03, 50-329/82-05, 50-329/82-05, 50-329/82-06 & 30-330/82-06 WARNICK, R. F. Region 3, Office of Director 82/10/20 COOK. J W Consumers Power Co. ip 15799 025 24X Fichs 50-329,82/10/20, 8210260190
- --8210260195 Responds to NRC 820426.0702 & 22 itrs re violations noted in IE Insp Repts 50-329/62-03,50-330/82-03.50-329/82-05, 50-329/82-05, 50-330/82-05 & 50-330/82-05 Corrective actions additionated in initiated since soldier piles installed COOK.J W Consumers Power Co. 82/09/30 KEPPLER.J. 0 Region 3, Gffice of Director 4pp 15797 026 24X Fishe 50-329,82/10/20,82/10/206190
- 8210290377 Ack receipt of 820930 itr informing NRC of eteps taken to correct violations noted in IE Insp Repts 50-327/82-07 & 50-320/82-07. WARNICK RF Region 3, Office of Director 82/10/26 COOK, J. W Consumers Power Co ip 13853 008 24% Fichs 50-329,82/10/26,8310306277
- --8210290390 Responds to NRC 820715 itr re-violations noted in IE Inep Repts 50-329/82-07 & 50-330/82-07 Corrective actions QC will inspect all hangers installed prior to 810101 Sample of hangers installed efter 820101 will elso be inspected CDDR-J W Consumere Power Co 82/09/30 KEPPLER, J @ Region 3, Office of Director is 15853'007 24X Fiche 50-327,82/10/26,8210290377
- 6210290154 Ack receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/82-06 & 30-330/82-06 HARNICK: R Region 3: Office of Director 82/10/27 COOK, J W Consumers Power Co. ip 15853 336 24X Fiche 50-329,82/10/27, 2010/920154
- --8210290163 Responds to NRC 820426 itr re violetions noted in IE Insp. Repts 50-329/82-06 & 50-330/82-06 Corrective actions: complete reinsp of electrical cables expected by end of Apr. 1983 COCKLO W Consumers Power Co. 82/10/15 KEPPLER. J. O. Region 3, Office of Director 2pp. 15853.337 24X Ficher 50-329, 82/10/27, 8210290134
- R. Pariodic operating reports & related correspondence
- 821003024B "QA Program Mgt Corrective Action Repts.Nonconformance Rapts.Quality Action Requests & Audit Finding Repts." Aug 1982 * Bechts! Corp 82/08/31 [.427pp 15598:001. 24X Fiche: 50-329, 82/08/31, 8210050248
- 8210080115 Forwards 39th quarterly rept for Oct-Dec 1782, per ALAB-106, COOK J. W. Consumers Power Co. 82/09/20 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 54pp 15440:026 24x Fichs. 50-329, 82/09/20, 8210080115.
- 8 Reportable occurrences, LERs & related correspondence
- 8210070107 Board Notification 82-94 informs of Zack Co-potential Part 21 rept on HVAC welder record discrepancies.

 NOVAK, T. M. Assistant Director for Licensing, 82/09/16, Atomic Safety and Licensing Board Panel. 4pp. 15649:202, 24x Fichs. 50-329, 82/09/16, 8210070107.
- 8210040337 PNO-III-82-100: on 820924, stop work order issued for angoing preparatory remedial soils work as result of insp which identified problems w/certification testing of GC personnel per confirmatory action its issued on 820927.

 048DNER; R., 8HAFER. M., WARNICK, R. Region 3, Office of Director. 82/09/27 ip. (5883:130. 24% Fiche: 50-327, 62/09/27, 8210040337.
- 8210050143 Interim deficiency rept re accident temp effects on containment level measurement. Detailed design & analysis of mods continuing. Effort integrated a/work required to selve SER Confirmatory Issue 16 (IE Bulletin 79-21).
 COOK. J. W. Consumers Power Co. 82/09/28. KEPPLER. J. Q. Region 3. Office of Director. 2pp. 15605:165. 24X Fiche: 50-329, 82/09/28, 8210050143.
- 8210240121 Interim Deficiency Rept 82-09 re quality program & mfg deficiency affecting Victoreen radiation monitoring aquipment. Initially reported on 820917. Caused by poor coordinately & QA breakdown. Next rept expected by 820107. COOK. J. W. Consumers Power Co. 82/10/15 KEPPLER, J. 9. Region 3. Office of Director. Bpp. 18799:068. 24x Fiche: 50-329, 82/10/15. REP0260121.

- 8210280076 Interim Deficiency Rept 9 re underrated terminal strips on Limitorque veive operators Initially reported on 810115 Underrated terminal blocks repleced w/Merathon 300 series blocks Next rept will be sent by 830131 CODK, J W Consumers Power Co 82/10/22 KEPPLER, J G Region 3. Office of Director 11pp 15837 147 24X Fiche 50-327,82/10/22, 2010/280074
- T Hearing transcripts on non-entitrust matters
- 8210130265 Testimony of AJ Hendron re evaluation of ultimate load carrying capacity of dissel generator bldg footings Profqualifications, supporting documentation & Certificate of Svc enci
 KENDRON, AJ Consumers Power Co HENDRON, AJ [111nois, Univ of, Urbana-Champaign 82/10/08 119pp 15677 285 24% Fiche 50-327, 82/10/08, 8210130265
- 8210130494 Testimony of AJ Handron re evaluation of seiemic shakedown settlement of diesel generator bldg in event of earthquake Prof quelifications & supporting documentation ent. HENDRON A J Consumers Power Co HENDRON A J Illinois, Univ of. Urbana-Changeign 82/10/08 75pp 15684 014 24X Fiche 50-329,82/10/08.8210130494
- --8210130505 Testimony of DF Lewis on behalf of epplicant re undergree, piping Addidant & supporting documentation encl LEWIS DF Consumers Fower Co LEWIS DF Bechtel Corp 62/10/07 80pp 15684 097 24% Fiche 50-329.62/10/08.821013049t
- 8210260527 Testimony of WO Coriey re cracking in svc water pump structure CORLEY, W O Consumers Power Co CORLEY, W O Portland Commit Association 82/10/14 Sipp 15804 315 24X Fiche 50-329, 82/10/14.8210260527
- 8210260504 Testimony of A Boos,EM Burke, JP Gould & P Shunmugarel resvc water pump structure, Aperture cards available in PDR BOOS, A, BURKE,E M, GOULD, JP Consumers Pawer Co 82/10/25 BDpp 15805 035 24X Fiche 50~329, 82/10/25, 8210260504
- DOCKET 50-330 HIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8207070419 Forwards application for Amend 106 to CP & OL epplications, consisting of Revision 44 to FBAR Three hundred ninety-four oversize drawings encl Aperture carde are available in PDR COOK.J W Consumers Power Co 82/06/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 13796-028 24X Fiche: 30-329,82/06/28,8207070419
- --8207070422 Application for Amend 104 to CP & DL applications con of Revision 44 to FBAR COOK J. H. Consumers Power Co 82/06/28 20pp 13796 030 ; Fiche: 50-329, 82/06/28 8207070419.
- 8210080015 Add1 response to FDIA request for 19 cetegories of info nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheid (ref FDIA Exemption 5). FELTON.J.M Division of Rules and Records 82/07/12 UDELL.R / Critical Mass Energy Project 9pp 15665 027. 24X Fiche: 50-000, 82/07/12, 8210080015.
- 8210010437 Provides add1 info to 820812 ltr re cooperative evaluate program w/NRC,per NRC 820720 request Program provides capability for rapid response to NRC concerns & supports near-term approval of Item II K.G.30. COOK.J.W. Consumers Power Co. 82/09/10. DENTON.H.R. Division Licensing. App. 15570-205 24X Fichs 50-329.82/09/10.821001041
- 8210290228 Forwards Amend 108 to application for CPs & CLs, consists of Ravisions 6 & 3 to security plan & safeguards contingency plan, respectively, Plans withheld (ref 100FR73 21) COOK. J W. Consumers Power Co 82/07/23 DENTON, H.R. Division Licensing. 2pp. 15853:284. 24X Fiche: 50-327, 82/07/23, 821027022
- --B210270227 Application for Amend 108 to application for CPs & CLs consisting of revised drewings for security plan & safeguards contingency plan Drawings withheld (ref 100FR73,21).

 COOK.J.W. Consumers Power Co 82/09/28, ip. 15853-285 248 Fiche: 50-329, 82/09/23, 8210270228.

- \$210220511 Forwards WPPSS \$20825 & 0909 & CPC \$20812 ltrs re B&W camers group \$20720 meeting w/NRC re resolution of MJREO-0737. Item II K 3 30 on small breat LOCA methods Apgropriate action should be taken ADENSAME 9 Licensing Branch 4 82/10/04 SHERON, B W Reactor Systems Branch 1p 15786 091 24X Fiche 50-000, 82/10/04. 8210220511
- E210120276 Forwards independent design adequacy review & "Performance Objectives & Criteria for Const Project Evaluations:" INPO preliminary rept CCCK.J W Duke Power Co 82/10/05 DENTON.H R Office of Nuclear Reactor Regulation, Director KEPPLER.J O Region 3, Office of Director 30pp 15651 322 24X Fische 50-329,82/10/05,8210120276
- ~~8210120281 "Performance Objectives & Criteria for Const Project Evaluations," preliminary rept 4 Institute of Nuclear Power Operations 82/09/30 67pp 15658 352 24X Fiche 30-329,82/10/05,8210120276
- S210380267 Requests add1 info re util position on Reg Guide 1 58, Revision 1. "Qualification of Nuclear Power Plant Insp. Exam & Testing & Audit Personnel I" ADENSAM.E 9 Licensing Branch 4 B2/10/05 COOK.J W Consumer: Power Co 4pg 15746 007 24X Fiche 50-327,82/10/05,8210180267
- 5210130244 Forwards Amend 109 to application for CPs & GLs, consisting of Revision 45 to F9AR COCK, J H Consumers Power Co 82/10/07 DENTON, H R Office of Muclear Reactor Regulation, Director 3pp 15676 015 24X Fiche 50-329, 82/10/07, 8210130264
- --82101302& Amend 109 to application for CPs & OLs.consisting of Revision 45 to FBAR COOK.J W Consumers Power Co 82/10/11 2pp 15676 018 24X Fiche 50-329,82/10/07,82101302&4
- E210150441 Discusses reasons why deletion of requirement for four point proof jacking of feedwater isolation valve pit is essential part of remedial action to be achieved prior to excavation beneath feedwater isolation valve pit WARNICK.R F Region 3. Office of Director 82/10/08 MILLER.D B Consumers Power Co 2pp 15703 151 24% Fiche 50-329,82/10/08. 8210150441
- 9210210294 Forwards Revision 1 to NUS-4146, "Analysis of Flammable Concentrations at Hidland Nuclear Plant From Natural Gas Pippline Breaks," in response to NRC 820823 request for info COUK. J W Consumers Power Co 82/10/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 15764 104. 24X Fische 50-329, 82/10/19, 8210210294
- --82:0210301 "Proposed Gas Pipeline Leak Detection Bys "
 SYONER, M A Stoner Associates, Inc 82/10/12 22pp 15764 112
 24X Fiche 50-329,82/10/19,8210210294
- --B210210305 "Analysis of Flammable Concentrations at Midland Nuclear Plant From Natural Que Pipeline Breaks." Revision 1 Seven oversite drawings enci Aperture cards available in PDR. NATHAN.S J., FULFORD.P J. KAISER.O D. NUS COTP. NUS-4146 ROI 62/10/07 SBpp 15764 135 24X Fiche 50-329.82/10/19.8210210294.
- MRC Safety Evaluation Report (SER), supple & correspondence
- 2210010278 Forwards "Failure Mode & Effects Analysis of Midland Mon-Nuclear Instrumentation & Integrated Control Bys." in response to FARR Questions 30 56-30 59 Info completes review of SER Confirmatory Itam 22 COCK. J W Consumers Power Co. 82/09/23 DENTON, H R Office of Muclear Reactor Regulation, Director 2pp 15574 077 24X Fiche 50-329, 82/09/23, 8210010278
- -8210010284 "Failure Mode & Effects Analysis of Midland Non-Nuclear Instrumentation & Integrated Control Bys " ENZINNAR 9., WINKS,R,W., SHARTZELL,B.D. Babcock & Wilcox Co. BAM-1749 82/07/31 61pp 15574 079. 24X Fiche: 50-329,82/09/23, 8210010278.
- 210190520 Forwards proprietary reactor test data per SER, in support of util position re estimates of full power was estimated to result in drop in upper shelf energy. JH Taylor affidavit and Test data withheld (ref 100FR2 790 & 100FR9, 12) CODK. J H Consumers Power Co 82/10/05 DENTON, H R Diffice of Muclear Reactor Regulation, Director 7pp 15735,022, 24% Fichs 50-329,82/10/05,8210190520
- 210200099 Notification of 821109 meeting w/util, Stoner Associates & AUS in Bethesda. MD to discuss BER Open Item 1 re onsite natural gas pipeline
 HERNAN, R W Licensing Branch 4, 82/10/13, ADENBAM, E 0, Licensin
 Branch 4 3pp, 15767, 317 24X Fiche 50-329, 82/10/13, 8210200099.

- 8210270039 Notification of 821020 meeting w/util & Summit Nuclear in Bethesda, MD to discuss SER confirmatory Item 26 re independent safety engineering group HERNANAR W Licensing Branch 4 82/10/19 ADENBAME 0 Licensing Branch 4 3pp 15836 290 24X Fichs 50-329,82/10/19,8210270039
- 8210210030 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF HIDLAND PLANT, UNITS 1 AND 2 Docist Nos. 50-329 And 50-330. (Consumers Power Company) = Office of Nuclear Reactor Regulation, Director NUREO-0793 82/10/31 168pp Available at NRC. 49 50 15785 015 24X Fiche 50-329, 82/10/31, 8210210030
- F Security, medical, emergency & fire protection plans
- 8210130004 Releases public version of nuclear accident apps to emergency preparedness plan PELTON, J M Division of Rules and Records, 82/09/23 Document Management Branch lp 15695 001 24X Fiche: 50-329, 82/09/23, 8210130004
- --8210130005 Forwards public version of nuclear accident apps to Bay.

 Saginaw & Midland County. HI emergency preparedness
 plans
 COUK. J H Consumers Power Go 82/09/08 DENTON. H R Office of
 Nuclear Reactor Regulation, Director 4pp 15695.002 24X
 Fitche 50-329,82/09/28.8210130004
- --B210130007 Public version of nuclear accident apps to Bay, Baginaw & Midland County MI emergency preparedness plan * Consumers Power Co B2/09/01 437pp 15695:006 24X Fiche 50-329, 82/09/23, 8210130004.
- 8210290228 Forwards Amend 108 to application for CPs & OLs, consisting of Revisions 6 & 3 to security plan & safeguards contingency plan respectively Plans withheld (ref 10CFR73 21), CODK.J W Consumers Power Co 82/09/23 DENTON, H R Division of Licensing, 2pp 19859-284 24X Fiche 50-329, 82/09/23, 8210290228
- --8210290229 Application for Amend 108 to application for CPs & DLs. consisting of revised drawings for security plan & safeguards contingency plan. Drawings withheld (ref 10CFR73 21)
 COOK. J. H. Consumers Power Co 82/09/28. 1p. 15853 286 24X Fiche 50-329.82/09/28.8210290228
- 8210080188 Informs that activities performed 820725 considered amergency measures to ensure safe fire protection of facility Remedial stop work order not violated MARNICK.R F Region 3. Office of Director 82/10/05 COOK, J & Consumers Power Co. ip 15640 177 24X Fiche 30-327.82/10/05.8210080188
- O Adjudicatory correspondence
- 8210220294 Comments on petition for rulemaking PRM-50-32B re electromagnetic pulse in nuclear power plants. Requests that 10CFR30 be amended to require provision for design features for protection against attacks & destructive acts MARBHALL.W.H. Mapleton Intervenors 82/08/31 Office of the Secretary of the Commission. 2pp. 15776:066 24X Fiche. 50-329. 82/08/31. 8210220294
- 8210040057 Response opposing B Stamiris 820904 motion for partial initial decision on GA adequacy. Underpinning excavation work will not be authorized unless NRC satisfied w/util GA proposals. Certificate of Svc enci HILCOVE; M N Hearing Branch 2, 82/09/24. Atomic Safety and Licensing Board Panel 9pp. 15584 223, 24X Fiche 50-329,82/09/24, B210040057
- 8210050221 Response to M Sinclair resubmitted contention on Table 8-3 Contention should be deferred until Commission issues policy statement. Certificates of Svc encl MEST.A E. Consumers Power Co. WEST.A E. Isham, Lincoln & Beels 82/09/28 Atomic Sefety and Licensing Board Panel. Spp. 15609 062. 24X Fiche: 50-329, 82/09/28.8210050221.
- 8210050223 Motion to compel M Binclair to respond to applicant 820830 request for admission of truth of relevant matters of fact or alternatively, to deem matters of fact admitted Certificate of Svc encl Related correspondence.

 STEPTOE.P. Consumers Power Co. STEPTOE.P. Isham, Lincoln & Beals, 82/09/28 Atomic Safety and Licensing Board Penel. Spp. 13610.339. 24% Fichar 50-329,82/09/28,8210050223.
- --B210050229 Request for admission of truth of relevant matters of fact re Contention 5 Certificate of Bvc encl. MILLER,M.I. Consumers Power Co. MILLER,M.I. Isham, Lincoln & Beale, 82/08/30. Sinclair,M. 4pp. 15610:344. 24X Fiche:50-329,82/09/28:8210050223.

- \$210050230 Responses opposing B Stamin's \$20713 addendum to \$20824 cost benefit contention Good cause for late filing not demonstrated Caytificate of Svc sncl WEST.A E Consumers Power Co WEST.A E Isham, Lincoin & Seels 82/09/28 Atomic Safety and Licensing Board Panel 5pp 15611 019. 24% Fichs 50-329,82/09/28,8210050230
- 8210010062 Response opposing M Sinciair resubmitted Contention I Court of Appeals,DC Circuit decision does not affect contention deferral. Court stayed effect of decision until Commission policy statement issued Certificate of Svc ancl WILCOVELM N Hearing Branch 2 82/09/29 Atomic Bafsty and Licensing Board Panel 5pp 15545 004 24X Fiche 50-329,82/09/29,8210010062
- 8210010254 Hemorandum memorializing 820927 telcon re board notification on voils ramedial OA procedures that may affect ASLB consideration of B Stamiris motion for partial initial decision on QA adsquacy in soils remedial work HARBOUR, J Atomic Safety and Licensing Board Panel 82/09/29 2pp 15574 058 24% Fiche 50-327,82/09/29,8210010234
- B21004001B Response to remainder of M Sinclair revised contentions based on discovery No objection to Revised Contentions 6:34 & portions of 56 Upposes Contentions 34:43 & portions of 56 W/notics of apparance & Certificats of SVC.
 MILCOVE, M N. WRIOHT, N. M. Harring Branch 2: 82/09/30 Atomic Safety and Licensing Board Panel 17pp 1558: 280 24% Fichs 50-329,82/09/30.8210040018
- B210050215 Response to A Binclair B20720 revised contentions, Set 11 Objects to Contentions 34(a),37 & 43 & portions of Contentions & 57 Util nonconformance rept & Certificate of Svc encl
 Svc encl
 BTEPTOE,P P Consumers Power Co STEPTOE,P P Isham, Lincoln & Biale 82/07/30 Atomic Safety and Licensing Board Panel 15pp.
 15611:073 24X Fiche 50-329,82/09/30,8210050215
- E21003023B Forwards changed interrogatories as motion to compel discovery responses, addressing same issues as E20830 interrogatories M/o encl Related correspondence STANTRIG.B. Stamiris. B. E2/09/30 Atomic Safety and Licensing Board Panel. 1p 15509.050 24X Fiche 50-329.82/09/30,821003023B
- 8210050240 Notion to compel answers from util to E20830 revised interrogatories re Contantion ib AELB 820814 ruling on decommissioning supports heed for comparative analysis of decommissioning estimates. Related correspondence STAMIRIS.B. Stamiris. B 82/09/30 Atomic Safety and Licensing Board Panel 3pp 13610:336 24X Fiche:50-329,62/09/30,8210050240
- E210060193 Response opposing M Binclair resubmitted Contention 56 on station blackout Contention lacks requisite basis & specificity to stand alone Certificats of Bvc enci BRUNNER.J E. Consumers Power Co 82/09/30 Atomic Safety and Licensing Board Panel. App 15614 237 24X Fichs.50-329,82/09/30,6210040193
- 8216050246 Forwards AJ Boos 820930 revised affidavit, correctly identifying contention as Bincheir Contention 6 Svc list and Related correspondence BRUNNER(J.E. Consumers Power Co. 82/10/01 STANIRIS, 8, Stamiris, B. 3pp. 15607 081 24X Fiche 50-329, 82/10/01, 8210050246
- 8210070378 Objections to util refusal to answer B Staniris
 Interrogatories 6 through \$1 & 10 Issues relevant to scope
 of contentions. Heating should be scheduled to finalize
 decomássioning plans. Related correspondence.
 MARSHALL.U H Hapleton Intervenors. MARSHALL.U.H. Mershell.U.H.
 62/10/02. Atamic Safety and Licensing Board Penel. 2pp.
 13633.248 24% Fichs.50-329,82/10/02.8210070398
- 8210070132 Motion to compal util to ensuar second set of interrogatories based on new info Interrogatories are narrow in acope, based on may info in FES & directly relayant to admitted Contention 5. Related correspondence.

 BISHOP, L. L. Sinclair, M. BISHOP, L. Bishop, L. B2/10/04. Atomic Safety and Licensing Board Fanel. 3pp. 13527:043 24X Fichs 50-329, 82/10/04.8210070132.
- 8210070136 Responses to applicant & NRC 820903 & NRC 820910 responses to M Sinclair revised contentions. Limiting Contention 31 to litigation of util templiance w/existing requirements. Contention 32 amanded 8156007. L. L. Sinclair, M. BIENOP, L. L. Bishop, L. L. 62/10/04, Atomic Safety and Licensing Scard Panel. 1ipp. 15627:020 24X Fichs: 50-327, 82/10/04, 8210070196.

- 6210060227 Order allowing M Sinclair to raply to NRC & util 620930 rasponses to Sinclair 620920 revised contentions by 621015 B Stamiris may reply to applicant 620923 & 28 & NRC 620928 responses to Stamiris contention by 621015 BECHEOFER, C Atomic Safety and Licensing Soard Panel 62/10/05 STAMIRIS, B. Stamiris, B. SINCLAR, M. Sinclair, M. 2pp 15620 010 24X Fiche 50-329,82/10/05,8210060229
- 8210070140 Response to request for production of documents.
 81NCLAIR.M Sincisir.M Sincisir.M Bishop. L 82/10/06 4pp
 15827.060 24% Fiche 50-329.82/10/06.8210070140
- B2100B0062 Advises that NRC will voluntarily respond to B Stemiris & K Sinclair 820713 & 20 interrogatories, respectively Objections to interrogatories for reasons other than noncompliance w/10CFR2 720th) not waived WRICHT, N A Hearing Branch 2 82/10/06 BECHACEFER, C. HARBOUR, J. COMMI, F P Atomic Safety and Licensing Board Panel 2pp 15643-277 24% Fiche 50-329, 82/10/06, 82100B0062
- 8210130492 Notice of appearance in proceeding Certificate of Sys entl SYAHL, D M Consumers Power Co. STAHL, D M Isham, Lincoln & Beals 82/10/04, 4pp 15682 170 24X Fichs 50-329,82/10/05,8210130492
- 8210080066 Informs of agreements between parties re NRC request that util not take depositions of listed persons & discovery on M Bincleir & B Staminis contentions alleging deficiencies in Tack Co GA PATON: M D Hearing Branch 2 82/10/07 BECHMOEFER.C., COMAN: F P. HARBOUR. J Atomic Safety and Licensing Board Pane; 2pp 15649 035 24% Fiche 50-329,82/10/07,8210080066
- 82(0130304 Memorandum memorializing 821004 telcon re issuance of BER. issues to be considered at hearings, identification of witnesses, discovery & new contentions 82CH-HOFER: C. Atomic Safety and Licensing Board Panel 82/10/08 4pp 15478 343 24X Fich* 50-329,82/10/08.8210130304
- 8210130421 Notice of resumption of evidentiary hearings in contestigated CL/CH processing on 821027 & continuing on 821028-30 & 1010-05 to extent necessary Hearings to be held in Middland, HI BECHHOEFER.C Atomic Bafety and Licensing Board Pane) 92/10/08 pt 15680 245 24K Fichs 50-329,62/10/08,6210130421
- 8210180212 Response to B Stamiris 820930 motion to compsi responses to revised interrogatories. Util has no objection to responding voluntarily to amended interrogatories. Certificate of Svc enci Related correspondence BRUNNER, J.E. Consumers Power Co. 82/10/12. Atomic Safety and Licensing Board Panel. 3pp. 1571B 103. 24% Fiche 50-329.82/80/12 6210180212
- 8210200051 Response opposing util 920728 motion to compel response to util 920830 requests for admissions from M Binclair Sinclair 920914 response raised relevant objections Certificate of 8vc enci Related correspondence BISHOP, L. L. Sinclair, M. BISHOP, L. L. Harmon & Wester B2/10/13 Atomic Safety and Licensing Board Penel. Spp. 13734-135 24x Fichs 50-327, 82/10/13, 8210200061.
- 9210200054 Reply to NRC & applicant responses to M Sintlair rivised Contentions 6:34,37,43.56 & 37 Contention 6:bases (a),45 & (d)(4), Contention 43 & Contention 56. Basis 3.withdrawn Cartificate of Svc enci BISHOP.L L Sintlair.M. BISHOP.L L Harmon & Weise 82/10/13. Atomic Bafety and Licansing Board Panel 7pp 15755.076 244 Fiche 50-329, 82/10/15,8210200054.
- S210210370 Response to util S20723 & NRC S20728 rasponse to B Steely, new contention based on FES Orois misrepresentation of overall costs & benefits to public represented by cost/ benefit analysis demands redress SYAMIRIS.B. Stamiris. B S2/10/15 Atomic Safaty and Licenty, Spend Panel 9pp. 13763-168 24% Fiche 50-327, 82/10/15, 8210210370
- 8210200051 Lists sections of BER & SER Suppl 2 NRC will spenics as testimony religious to be covered at 821027-1105 hearings. Testimony religious to be addressed during second whof hearings will be filed on 821022.

 HILCOVE.H.N. Hearing Branch 2, 82/10/18 BECHHOEFER.C. HARBOURJ.J. COMAN.F P. Atomic Safety and Licensing Boars Facel dop 15756:042 24X Fiche:50-329,82/10/18.8210200031
- 8210210427 Order extending time until 821026 for Commission to act to review ALAF-671.
 CHILK-B. J. Office of the Secretary of the Commission 82/10/18.
 Commissioners. ip. 15762:271 24X Fiche: 50-529.82/10/18.
 8210210427.

- B210210290 Notice of rescheduled evidentiary hearings for 821115~20 & 22~23 BECHMDEFER.C Atomic Safety and Licensing Board Panel 82/10/19 15785 073 24X Fiche 50~329.82/10/19.8210210290
- B2102203B1 Response opposing M Sinclair B21004 motion to compet applicant to answer Sinciair second set of interrogatories based on new into Interrogatories vague-incomprehensible k irrelevant H/Certificate of BV: Related correspondence BRUNIER.J E Consumers Power Co 82/10/19 Atomic Bafety and Licensing Board Panel 14pp 15780 176 24X Fiche 50~329,82/10/19, 82/20203B1
- 8210220322 Memorandum & order rejecting WH Marshail 820910 contentions based on SER & dismissing Contention 5 SER contentions filed late u/o any justification Marshall failed to revise Contention 5 per ASLB 790223 order after FEB issued EECHHUFFER, C Atomic Safety and Licensing Board Panel B2/10/20 MARSHALLW H Marshall, WH 79p 15776 029 24X Fiche 50-329, 82/10/20,8210220322
- 8210260364 Forwards LERs as attachments to NRC 820728 responses to M Sinclair interrogatories
 HICCOVE.N N Hearing Branch 2 82/10/25 DIGHOP.L L Harmon & Heiss BIBHOP.L L Sinclair.N ip 15804 145 24X
 Fiche 50-239.82/10/25
- 8210260383 Forwards info in response to JW Cook B20914 ltr to H Denton re environ qualification of electrical & mechanical equipment WILCOVE.M N Hearing Branch R 82/10/25. DRUNNER, J E Consumers Power Co 4pp 15803 344 24X Fiche 50-327, 82/10/25, 8210260388
- 8210270161 Order extending time until 821029 for Commission to act to review ALAB-691 COMMISSION TO SERVICE OF THE SECRETARY OF THE Commission 82/10/26 Commissioners ip 15823 010 24X Fithe 50-329.82/10/26. 8210270161
- K Utility Final Safety Analysis Report (FBAR) & amends
- G207070419 Forwards application for Amend 104 to CP & CL applications, consisting of Revision 44 to FSAR Three hundred minety-four drawings and Aperture cards are available in FDR COUK, J W Consumers Power Co. B2/06/28 DENTON, H R Office of Nuclear Reactor Rogulation, Director 2pp. 13796 028 24X Fiche 50-329, 82/06/28, 8207070419
- --820707042B Revision 44 to FBAR W/394 oversize P&IDs, electrical & instrumentation control drawings, piping isometrics, revision sheets & Facing sheets Aperture cards are available in PDR a Consumers Power Co. 82/06/30 3933pp 13796,03B 24X Fiche 50-329,82/06/28,8207070419
- 8210130264 Forwards Amend 109 to application for CPs & OLs, consisting of Revision 45 to FBAR
 COOK, J H Consumers Power Co 82/10/07 DENTON, H R. Office of Nuclear Reactor Regulation, Director 3pp. 15676-015. 24X
 Fiche 50-329, 82/10/07, 6210130264
- --D210130267 Revision 45 to FSAR
 # Consumars Power Co 82/07/30 626pp, 15676.020 24%
 Fichs 80-329,82/10/07,8210130264
- 6210190364 Forwards Affidavit of Svc re Amena 109 (Revision 45 to FBAR) to application for CPs & OLs
 SULLIVANI, J. Consumers Power Co. 82/10/15 DENTON, H. R. Office of Nuclear Reactor Regulation. Director 3pp 15740 318, 24X
 Fiche 50-329, 82/10/15, 8210190364
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8210270417 Summary of ACRS Subcommittee on Midland Plant Units 1 & 2 820602 meeting in Washington, BC re application for OL ACRS ~ Advisory Committee on Reactor Safeguards 82/08/16 ACRG ~ Advisory Committee on Reactor Safeguards 25pp, 15833:287 24X Fichs 50-329, 82/08/16, 82(0270417.
- B210270433 Summary of ACRS Subcommittee on Midland Plant Units 1 & 2 820520-21 meetings in Midland, Mi re application for OL * ACRS - Advisory Committee on Reactor Sefeguards. B2/08/16 ACRS - Advisory Committee on Reactor Sefeguards. 78pp 15835 059 24% Fiche 30-329,82/08/16,8210270433
- B210280034 Summary of 266th ACRB meeting on B20603-05 in Hashington DC re Midland OL review pressure vessel integrity reismic events in amergency planning, control room habitability & Subcommittee on Energy Research & Production questions a ACRS Advisory Committee on Reactor Bafeguards 62/10/08, ACRS Advisory Committee on Reactor Bafeguards 62/10/08, 257 24X Fiche, 50-329, 82/10/08, 8210280034.

G Inspection reports, IE Bulletins & correspondence

- 6210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5).

 FELTON J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X

 Fiche 50-000, 82/07/12, 8210080015
- --8203040536 Comments on Bil218 corrections to facility assessment contained in NUREC-0834 re hearings & discussion of systematic assessment of license performance Revision to NUREC inappropriate issue closed MOBELEY.N C Systematic Assessment of Licensee Performance Review Group 82/01/04 HESSMAN,R K NRC No Detailed Affiliation Given ip 15468 256 24x Fithe 50-000.82/07/12,8210080015
- --8203040538 Forwards performance element summary for Jul 1979-June 1980 in response to ASLB request for testimony on systematic assessment of license performance in general & facility assessment in particular.

 WESSHAM,R H Director's Office, Office of Inspection and Emforcement 81/2/19 MOSELEY,N C Systematic Assessment of Licensee Performance Review Oroup 2pp 15468 254 24K Fiche 50-000,82/07/12,8210080015
- --8210080161 Systematic assessment of licensee performance notes refecility evaluation for Jul 1979-June 1980

 * NRC No Detailed Affiliation Civen 80/06/30 Spp
 15668 071 24K Fiche 50-000,82/07/12,8210080015
- 8210050139 Forwards IE Insp Repts 50-329/82-18 & 50-330/82-18 on 820713-0825 & notice of violation WARNICK: R. Region 3. Office of Director 82/09/22 CQCK. J W. Consumers Power Co 2pp 15605 193 24X Fiche 50-329, 82/09/22, 9210050139
- --B210050146 Notice of violation from insp on 820713-0825, WARNICK,R F. Region 3. Office of Director 82/07/22 3pp 15605 195 24X Fiche 50~327,82/07/22,8210050137
- --8210050154 IE Insp Repts 50-329/82-18 & 50-330/82-18 on 820713-0825
 Noncompliance noted, failure to translate requirements into
 drawings, inadequate procedure & failure to accomplish
 activities in accordance w/drawings
 OARDNER, R N , LANDSHAN, R B , SHAFER, H D Region 3, Office of
 Director \$22/09/21 7pp 15605 198 24X Fiche, 50-329, 82/09/22,
 8210030139
- 8208190233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBI.L i Division of Fuel Facilibles, Materials & Safeguards, 82/10/06 Consolidated Edison Co of New York 66pp 15761:250 24X Fiche 50-000,82/10/06,8208190233
- 8210190739 Forwards 18 insp Repts 50-329/82-20 & 50-330/82-20 on 820820-0920 No noncompliance noted WARNICK, R.F. Region 3: Office of Director 82/10/06 COCK, J M Consumers Power Co 2pp 15737 076 24X Fiche: 50-329, 82/10/06, 82/10/90739
- --B210190750 IE Insp Repts 50-329/82-20 & 50-330/82-20 on 820820-0920 No noncompliance noted Major areas inspected remedial soils work activities training for soils activities matts used by Zact Co & protective tagging procedures BUROESS, B L, COUK, R J., CARDNER, R N Region 3, Office of Director 82/10/06 5pp 15737 078 24% Fiche 50-329, 82/10/06, 8210190739.
- 8208190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Syspiping at 8HR Plants "Syc list encl.

 DEYQUNG, R.C. Director's Office, Office of Inspection and Enforcement. 82/10/14. Consolidated Edison Co. of New York 115pp 15810 125. 24% Fiche. 50-000. 82/10/14, 8208190238
- 8210240190 Ack receipt of 820930 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-329/82-03, 50-330/82-03, 50-329/82-05, 50-330/82-05, 50-329/82-06 & 50-330/82-06 & 50-330/82-06 & 50-330/82-06 & 50-330/82-06 & 50-330/82-06 & 50-330/82-06 & 50-329/82-06 & 50-3
- --B210260195 Responds to NRC 820426.0902 & 22 ltrs re violations noted i; IE Insp Repts 50-329/82-03.50-330/82-04.50-329/82-05, 50-330/82-05.50-330/82-06. Corrective actions: additiontrols initiated since soldier piles installed. COOK, J, W. Consumers Fower Co. 82/09/30. KEPFLER, J G. Region 3, Office of Director. App. 15799.026. 24X Fiche: 50-329,82/10/20,8210260190

. [

14

H

di.

ij,

ı,

- --8210290380 Responds to NRC 820715 ltr reviolations noted in 1E lnsp Repts 50-329/82-07 & 50-330/82-07. Corrective actions QC will inspect all hengers installed prior to 810101. Sample of hengers installed after 820101 uill also be inspected COCK. J H Consumers Power Co 82/09/30 KEPPLER. J O Region 3. Office of Director ip 15853 009 24% Fiche 50-329,82/10/26. 8210290377
- 8210290134 Ack receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/82-06 & 50-329/82-06 WARNICK, R F. Region 3, Office of Director 82/10/27 COOK, J. H. Consumers Power Co. 1p. 15853 336 24X Fiche 50-329, 82/10/27, 82/0290134
- --B210290163 Responds to NRC B20426 itr reviolations noted in 1E Insp Repts 50-329/B2-06 & 50-330/B2-06 Corrective actions: complete reinsp of electrical cables espected by end of Apr 1983 COOK, J H Consumers Power Co 82/10/15 KEPPLER, J O Region 3, Office of Director 2pp 15853, 337 24X Fiche: 50-329, 82/10/27, 8210270154.

R Pariodic operating reports & related correspondence

- 8210050240 "GA Program Mgt Corrective Action Repts, Nonconformance Repts, Quality Action Requests & Audit Finding Repts," Aug 1982 * Bechtel Corp 82/08/31 1,427pp 15598 001 24X Fichs, 50-329, 82/08/31,8210050248
- 8210080115 Forwards 37th quarterly rept for Oct-Dec 1782, per ALA8-106 COOK.J W Consumers Power Co. 82/09/30. DEYOUNG.R.C Director's Office. Office of Inspection and Enforcement 54pp 19640-026 24X Fiche: 50-327, 82/09/30. 8210080115
- S Reportable occurrences. LERs & related correspondence
- 8210070107 Board Notification 82-94 informs of Zack Co potential Part 21 rept on HVAC welder record discrepancies. MOVAK, TN Assistant Director for Licensing 82/09/16 Atomic Bafaty and Licensing Roard Penel 4pp. 15649 202 24X Fiche 50-329, 82/09/16,8210070107
- 8210040337 PNO-III-82-100 on 820924, stop work order issued for ongoing preparatory remedial soils work as result of insp which identified problems w/certification besting of QC personnel per confirmatory action itr issued on 820927 GARDNERAR : BHAFER W. WARNICK R. Region 3. Office of Director. 82/09/27. ip 15583-130 24X Fiche. 50-329,82/09/27,8210040937.
- 8210050143 Interim deficiency rept relaccident temp effects on containment level measurement Datailed design & analysis of mode continuing. Effort integrated w/work required to solve SER Confirmatory Issue 16 (iE Bulletin 79-21).

 COOK. J. W. Consumers Power Co. 82/09/28. KEPPLER, J O. Region 3. Office of Director 2pp. 15605 165 24% Fiche. 50-329, 82/09/28, 8210050143.
- 8210260121 Interim Deficiency Rapt 82-07 re quelity program k mêg deficiency affecting Victoreen radiation monitoring equipment Initially reported on 820917 Caused by poor workmankip & GA breakfown Next rapt expected by 820107 CODK, J W Consumers Power Co 82/10/15 KEPPLER, J O Region 3, Office of Director 8pp. 15799 068 24X Fiche. 50-329, 82/10/15, 8210260121.
- 6210280076 Interim Deficiency Rept 9 re underrated terminal strips on Limitorque valve operators Initially reported on 610115 Underrated terminal blocks replaced w/Harathon 300 series blocks. Next rept will be sent by 630131 COOK, J W. Consumers Power Co. 82/10/22 KEPPLER, J O. Region 3, Office of Director. 11pp. 15837 147. 24X Fiche 50-329, 82/10/22, 8210280076.

T Hearing transcripts on non-antitrust matters

8210130365 Testimony of AJ Hendron re evaluation of ultimate load carrying capacity of diesal generator blds footings. Prof qualifications, supporting documentation & Certificate of Evc enci.

HENDRON, AJ, Consumers Power Co HENDRON, A.J Illinois, Univ of, Urbane-Champaign 62/10/08 119pp, 15677:285, 24X
Fishe: 50-329, 82/10/08,8210130265

- 8210130494 Testimony of AJ Hendron re evaluation of saismic shakedown sattlement of dissel generator bldg in event of sarthquate Prof qualifications & supporting documentation end HENDRON. A J Consumers Power Co HENDRON. A J Illinois. Univ cf. Urbana-Champeign 82/10/08 75pp 15684 014 24K Fiche 30-329.82/10/08.8210130494
- --8210130505 Testimony of DF Lewis on behalf of applicant re undergrave piping Affidavit & supporting documentation encl LEHIB.D F Consumers Power Co LEHIB.D F Bechtel Corp 82/10/07 80pp 15684 077 24X Fiche 50-329.62/10/08.8210130492
- 8210260527 Testimony of WG Corley re cracking in svc water pusp structure CGRLEY, W O Consumers Power Co CGRLEY, W O Portland Canana Association 82/10/14 81pp 15804 315 24X Fiche 50-329, 82/10/14,8210260527
- 8210260504 Testimony of A Boos, EM Burke, JP Gould & P Shunmugarel resvous water pump structure Aperture cards aveilable in PDR BOOS, A: BURKE, E M: GOULD, J P Consumers Powar Co 62/10/25 BOPP. 15805-035 24X Fiche 50-327
- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

 F Security, medical, emergency & fire protection plans
- 9210120392 Releases public version of emergency response organization notification list FELTON.J M Division of Rules and Records 82/09/24 Decument Management Branch 1p 15691 108 24X Fiche 50-331,82/09/24,8210120392
- --0210120399 Forwards public version of emergency response organisation notification list Enci list should be incorporated into Emergency Plan Implementing Procedure EPIP 1 2

 MEYER.K A Jowa Electric Light & Power Co 82/09/13 DENIONAS Office of Nuclear Reactor Regulation, Director 15pp 15691.109 24X Fiche 30-33168/09/24/8210120392
- 821005030B Forwards IE Bafeguards Insp Rept 50-331/82-10 on D20121-13 & notice of violation 4/o notice of violation MLLER.J R. Division of Engineering & Technical Programs 82/09/29 ARNOLD D. Towa Electric Light & Power Co. 2pp. 15610-090, 241 Fiche. 50-331, 82/09/29, 8210050308
- --8210050311 IE Gefeguards Insp Rept 50-331/82-10 on 82052:-23
 Noncompliance noted failure to maintain adequate detection
 aids & to provide adequate access control Details withheld
 (ref 10CRR73 21)
 CHRIBTOFFER.9. (REED.J R Region 3, Office of Director
 82/09/27 2pp 13410 092 24X Fiche 50-331.82/09/27.8210050508
- 8210260461 Confirms rescheduling of 1983 annual exercise to 821027 RODT/L D. Iowa Electric Light & Power Co. 82/10/12 KEPPLER.J & Region 3. Office of Director in 15806.223 24X Fiche.50-331.82/10/12.8210260461
- P. Operating license stage documents & correspondence
- 8210120038 Requests listing of all submittals re inservice testing program within 30 days in order to complete review VABBACLO.D.B. Operating Reactors Branch 2, 82/09/24, ARNOLD.D lows Electric Light & Power Co. 2pp 15689
- 8210130050 Requests remittance of add1 fee for review of 820820 application proposing Tech Bosc change for delay in implementation of surveillance requirements for functions1 teeting of mechanical snubbers.

 DIGOGIRM License Fee Management Branch 82/09/28 ARMOLD.DI lows Electric Light & Power Co 1p. 15694.360 24X Fiche: 50-331.82/09/28.8210130050.
- 8210130509 Forwards "Regulatory Performance Improvement Programs in response to 820604 request for plen to upgrade regulatory parformance LIU.L. Jour Electric Light & Power Co 82/09/30 KEPPI,ER.J Q Region 3, Office of Director 2pp. 15682.194. 24X Fiche: 50-931.82/09/30.8210130509.
- --8210130517 "Regulatory Performance Improvement Program "

 Inum Electric Light & Power Co 82/09/30, 31pp. 15582 194
 24X Fiche 50-331.82/09/30,8210130509

- '240150160 Responds to NRC 820809 itr re-schedule for providing addlented on NVREO-0737. Item II B 3. "Post-Accident Gampling "Updated comparison of post-accident sampling systematics of NVREO-0737 will be submitted 821101 FOOT/L P. Lows Electric Light & Power Go 82/10/08 DENTON. H. Office of Nuclear Reactor Regulation, Director 2pp 15698 3D4 24% Faces 50-231,82/10/08.8210150160
- -210260489 Forwards for review "RSIV Local Leak Rate Testing," per 10CFR50.hpp J & Reg Guide 10 1 MINECK.D L iowa Electric Light & Power Co 82/10/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 10 15807 130 24X Ficht 50-331, 82/10/15, 8210260489
- -8210260495 "MSIV Local Leak Rate Testing "
 = lowa Electric Light & Power Co 82/10/15 93pp 15807 131 24% Fiche \$0~331.62/10/15.8210260489
- ;210240138 Requests revision of scheduled commitment dates for FANREO-0737, Item II F 1. "Accident Monitoring " Five of six Profineering mod packages completed Bys should be operational by end of Nov 1982 RODT, L b lower Electric Light & Power Co 82/10/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 15797 092 24X Fiche 50-331, 82/10/18,8210260138
- Imagestion reports. IE Bulletins & correspondence
- -210040202 Forwards IE Insp Rept 50-331/82-15 on 820809-13.16 & 23 & motice of violation PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 82/09/10 ARNOLD.D Iowa Electric Light & Power Co 2p, 15283
- --8210040204 Notice of violation from insp on 620809-13, 16 t 23

 **PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 82/09/08 ip 18583 148 24% Fiche 50-331,82/09/10,8210040202
- --8210040208 IE Insp Rept 50-331/82-15 on 820809-13.16 & 23 Moncompliance noted failure to include gamma spectrometer in QC program & absence of callbr procedures

 JANUSKA: A 0 , ROZAK, 8 , SCHUMACHER, M C Region 3, Office of Director 82/09/08 12pp 13583 149 24% Fiche 50-331.82/09/10.
- 3210030305 Ack receipt of 820709 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-331/82-07
 SPESSAD, R L Division of Project & Resident Programs. 82/09/24
 ARNQLD. L love Electric Light & Power Co Ip 15510-084. R4X
 Fiche 50-331, 82/09/24, 8210030306
- --8210030307 Responds to NRC 820810 ltr re violations noted in IE Insp Rept 50-331/82-07 Corrective actions operators retrained & re-examined, operations manual modified & integrated plant agerating anstructions changed RUOTIL D Iowa Electric Light & Power Co 82/09/09 KEPPLER: J O Region 3, Office of Director 5pp 15610 083 24% Fiche 50-331,82/09/24,8210050306
- 8210050308 forwards IE Safeguards Insp Rept 50-331/82-10 on 820621-25 & notice of violation W/o notice of violation fileCR.J R Division of Engineering & Technical Programs. 82/09/29 ARNOLD.D I Dwa Electric Light & Power Co 2pp 15610 090 24X Fichs. 50-331. 82/09/29. 8210050308
- --B21005031: IE Safeguards lnsp Rept 80-331/82-10 on 620521-25
 Noncompliance noted failure to maintain adequate detection
 aids & to provide adequate access control Details withheld
 tref 10CFR73 21).
 CHRISTOFFER.O., CREED.J. R. Region 3. Office of Director
 B2/09/27 2pp 15610 092 24X Fichs 50-331.82/09/29, 8210050308
- E210190360 Forwards IE Insp Rept 50-031/82-04 on 820208-12,0308-10 & 0525-28 & notice of violation HORELIUS, C E Division of Engineering & Technical Programs, 82/10/05 ARMLD, D Towa Electric Light & Power Co, 2pp. 15740 024 24% Fithe 50-031,82/10/05,8210190360
- --B210190362 IE Insp Rept 50-331/82-04 on 820208-12,0308-10 & 0525-28 Nancampilance noted failure to meet Tech Spec requirements. Section 3 re facility audits & failure to implement requirements of 10GFR50 App B.Criterion XVIII & V. HULZMER, M M. SHAFER, W D. HAKKINS.F C. Division of Engineering & Technical Programs 82/10/01. 15pp. 15740-332. 24% Fiche 50-331,82/10/05.8210190360.

- B20Big0233 IR Info Notice 80-35. Suppl i. "Leaking & Dislodged I-125 Implant Seeds," Svc list encl COBB.L I. Division of Evel Facilities, Materials & Safaguards COBB.L I. Division of Evel Facilities, Materials & Safaguards 250-21/10/06 Consolidated Edison Co of New York & Sopp 15761 250-24X Fiche 50-000.B2/10/06.8208190233
- 8210130546 Forwards add1 info re IE Bulletin 80-ii, "Massnry Rell Design." consisting of Revision 1 to 180-day final rept All outstanding requests for info answered Info demonstrates structural adequacy of massnry walts RDDT.L.D lowe Electric Light & Power Co 82/10/06 DENYON.H R Office of Nuclear Reactor Regulation, Director 62pp. 15682 290 24% Fiche 50-331.82/10/06.8210130546
- 8210250336 Ferwards IR Insp Rept 50-331/82-11 on 820719-22 & notice of violation NRELIUS, C E Division of Engineering & Technical Programs 82/10/07 ARNOLD, 0 Iows Electric Light & Power Go 2pp 15790 311 24% Fishe 50-331,82/10/07,8210250336
- --8210250342 Notice of violation from insp on 820719-22 NGRELIUS.C E Division of Engineering & Technical Programs 82/10/07 2pp 15790 313 24K Fiche 50-331.82/10/07.8210250336
- --8210250350 IE Insp Rept 50-331/82-11 on 820717-22 Moncompliance noted failure to establish ref speeds for inservice testing of RCIC & HPCI pumps & inadequate preoperational testing of most to RHR ave water suppreformed under Design Change 760 CONNAUGHTON.K , HAKKINS.F.C Division of Engineering & lechnical Programs 82/09/23 7pp 15790-315. 24X Fichs 50-331.82/10/07, 8210250336
- 8210190643 Act receipt of 820928 ltr informing NRC of steps taken to correct violations noted in 1E lasp Rept 50-331/82-08 STREETER. JF Division of Project & Resident Programs 62/10/13 ARNOLD. D lowe Electric Light & Power Co ip 15737 214 24X Fichs 50-331.62/10/13.6210190443
- --8210170564 Responds to NRC 820827 itr re violations noted in II: Imap Rept 50-331/82-08 Corrective actions administrative procedures to be revised to include monthly review of document change form log to identify changes RDDT.L D Inua Electric Light & Power Co. 82/09/28, KEPPLER.J.Q Region 3, Office of Director Epp 15737 218 24X Fiche 50-331/82/10/13.8210170643
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel-Rectroulation Rys Piping at BMR Plants " Svo list and DEYGUNO: R O Director's Office, Office of Inspection and Enforcement 82/10/14, Consolidated Ediamon Cn of New York, 11Spp. 15810-125, 24x Ficher 50-000, 82/10/14, 820817023B
- R Pariodic operating reports & related correspondence
- 8210200093 Forwards monthly operating rept for Bept 1982 MINECK, D. L. Igua Electric Light & Power Co. 82/10/13 Director's Office, Office of Inspection and Enforcement 1p 18737 RIG 24X Fiche: 50-331, 82/10/13, 8210200093.
- --8210200096 Monthly operating rept for Bept 1982 WATEGM H E Ioua Electric Light & Power Co 82/10/13 7pp 15757:217 24X Fiche 50-331, 82/10/13, 8210200093
- 8. Reportable occurrences. LERs & related correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents fixted in App Alson of Rules and Records. 82/06/28, UDELL.H.A Critical Mass Entry Project 15pp. 15727:005. 24X Fiche: 50-000, 82/06/28, 8210010008.
- --8203120103 Bubmits engineering evaluation re loss of river water bys loop. One loop of river water sys became inoperable due to clogged filter.

 (OLF.TR Director's Office, 82/03/01 Director's Office 3pp. 19793 154 24% Fiche: 50-000, 82/06/28, 8210010008.
- 8210040369 Forwards LER 82-056/01T-0.
 MINECK.D L lows Electric Light & Power Co. 82/09/24 KEPPLER.J.O.
 Region 3, Office of Director. ip. 15587.130, 24X
 Fiche: 50-031.82/09/24.8210040369.
- --8210040376 LER 82-056/01T-0: on 820912. HPIC area style leak alarm activated by temp differential switch TDB-2220A: resulting from lask due to teap difference between ventilation intake & exhaust. Caused by false signal due to resistor failure HILL: K.L. Iowa Electric Light & Power Co. 82/09/24. Region G. Diffice of Director. Spp. 15587. 132. 24K Fichs. 50-331, 82/09/24.

- 8210130133 Forwards LER 82-057/03L-0 MINECK.D L fows Electric Light & Power Co 82/10/01 KEPPLER.J 0 Region 3, Office of Director 1p 15673 095 24X Fiche.50-331.82/10/01.8210130133
- --B210130137 LER 82-057/03L-0 on 820702, during normal operation, while investigating river water intake sys 1C-102 trouble alarm, mode switch MB-29058 found in off position Coused by lack of procedural guidance Procedures under review MILL.K L. Iowa Electric Light & Power Co 82/10/01 Region 3. Office of Director ip 15673 074 24X Fiche 50-331.82/10/01, 8210130333
- 8210130393 Forwards LER 82-D58/03L-0 MINECK.D L fows Electric Light & Power Co 82/10/01 KEPPLER, J Q Region 3. Office of Director 1p 15680 360 24X Fiche 50-331. 82/10/01.0210130393
- 8210130585 Forwards LER 82-057/03L-0 MINECK.D L Tows Electric Light & Power Co 82/10/01 KEFPLER.J G Region 3. Office of Director 1p 15679 061 24X Fiche-50-331, 82/10/01.8210130885
- --8210130590 LER 82-059/03L-0 on 920910, worken in reactor core isolation cooling (RCIC) room reported marked increase in room temp Caused by broken drive belt in RCIC room cooling unit IV-AC-15A due to random failure
 HILL,K L lowa Electric Light & Power Co 82/10/01 Region 3, Office of Director ip 15679 062 24X Fiche 50-331,82/10/01. 8210130585
- 8210230251 Forwards LER 82-063/03L-0 MINECK.D L. Jows Electric Light & Power Co. 82/10/11 KEPPLER.J G Region G. Defice of Director ip 15791 158 24X Fiche 50-331. 82/10/11.8210250251
- --8210230261 LER 82-063/03L-0.on 820927.reactor bldg isolation damper iV-AD-1783, reducing transport of airborns contamination from reactor bldg, failed to close upon receipt of isolation signal Caused by rust on pieton & cylinder HILLK L. Iowa Electric Light & Power Co. 82/10/08 Region 3. Office of Director ip 1579:159 24X Fiche, 50-931, 82/10/11, 024/15/252
- 8210250289 Forwards LER 82-062/03L-0 NINECK,D L Idwa Electric Light & Power Co 82/10/11 KEPPLER.J G Region 3. Office of Director 1g 13791 162 24X Fiche.50-331, 82/10/11:8210250289
- --BR10250300 LER 82-062/03L-0. on 820922, surveillance testing pressure differential switch PBS-4304, controlling reactor bldg to suppression chamber vacuum breaker CV-4304, tripped belgw Tech Spec limit, Caused by instrument drift Switch recalibr HTLL: K L lowa Electric Light & Power Co. 82/10/11 Region 3, Office of Director 1p 15791 163, 24X Fiche 50-331,82/10/11, 8210230289
- 8210250384 Forwards LER 92-061/03L-0 MINECK,D L. lows Electric Light & Power Co 82/10/12 KEPPLER,J Q Region 3. Office of Director 1p 15790.089 24X Fiche 30-331,82/10/12,8210250384.
- --8210250387 LER 82-061/03L-0 on 820714.RHR svc water pumps 1P-22A & 1P-22D failed to meet Tech Bpec requirements Caused by excessive clearances between pump impellers & casing wear rings due to pump wear. Impellers edjusted & pumps tested. HILL.K L. Inwa Electric Light & Power Co. 82/10/12 Region 3, 0ffice of Director. 1p. 15790 089, 24X Fiche: 50-331,82/10/12,8210250384
- DOCKET 50-333 JAMES A. FITZPATRICK NUCLEAR POWER PLANT
 F Security, medical, emergency & fire protection plans
- 8210050083 Forwards *Dispersion Hodel Description for Nine Hile Point/ Jems A Fitzpatrick Nuclear Stations: * upgraded meteorological sys featription per TMI Action Item III A. 2 BAYNE-U.P. Power Authority of the State of New York. 82/10/01. VASSALUO.D.B. Operating Reactors Branch 2 2pp. 18604:255 24X Fiche: 50-333, 82/10/01.8210030083

- --8210050085 "Dispersion Model Description for James A Fitzpatrick/Nins Hile Point Nuclear Stations " + Power Authority of the State of New York 82/10/01 17pp 15504 257 24X Fiche 50-333.82/10/01:8210030083
- 8210260334 Act receipt of 820805 ltr informing NRC of steps taken to correct violations moted in 1E Health Physics Apprelsal Rept 50-333/80-20 Full ALARA program implementation prior to 1983 refueling outage understood MARTIN.T T Division of Engineering & Technical Programs 82/10/21 MCNEILL.C A Power Authority of the State of New York 2pp 15802 342 24X Fiche 50-333,82/10/21,8210260334
- --8210260338 Supple response to NRC 820120 & 0702 ltrs re items noted in IE Health Physics Appraisal Rept 50-333/80-20 Corrective actions schedule for technician retraining setablished & engineering controls will be part of ALARA program MCNEILL.C A Power Authority of the State of New York 82/08/05 MARTIN.T T Division of Engineering & Technical Programs 3pp 15802 344 24X Fichs 50-333, 82/10/21,8210260334

H Gameral correspondence

- 8210190713 Informs that SS Zullo & RA Burns authorized to sign with itre to NRC.

 BAYNE.J.P Power Authority of the State of New York 82/10/23 Office of Nuclear Reactor Regulation, Director 2pp 15738, 209 24X Fiche 50-000
- P Operating license stage documents & correspondence
- 8210290410 Discusses additional considerations that should be addressed in future proposed Tech Spec mods to 115 kV offsite (reserve) ac power sys, in response to util 820914 request VASBALLO, D.B. Operating Resectors Branch 2 82/10/04 SINCLAIR. L. W. Power Authority of the State of New York 5pp 15863 250 24X Fiche 50-333, 82/10/04,8210290410
- 8210130031 Forwards add1 payment required for 820604 application to amend Tech Specs re mgt organization structure.per NRC 820714 1tr Add1 payment made under protest pending final determination of legality of fee schedule 8AYNE.J P Power Authority of the State of Naw York 82/10/08 HILLER W C License Fee Management Branch 3pp 15701:265 241 Fiche: 50-000, 82/10/08,8210150031
- 8210200028 Forwards 820226 submittal re results of review of NUREO-0612. "Control of Heavy Loads "
 BAYNE, J P Power Authority of the State of New York 82/10/13
 VASSALO, D. Licensing Branch 2 ip 13756 056 24X
 Fiche 50-333, 82/10/15,8210200028
- --8210200039 Forwards results of second phase review of heevy load handling operations & response to Sections 2 2:2 3 & 2 4 of Encl 3 to 801222 ltr Consequences of certain load drops do not meet NUREO-0612 guidelines.

 BANNE.JP Power Authority of the State of New York, 82/02/26 VASSALLO, D Deprating Reactors Brench 2 65pp 15756 057 24k Fiche 50-333,82/10/15.8210200028.
- 8210200074 Forwards response to 820806 request for add1 info #2 NUREO-0737. Item 11 D. i. "Relief & Sefety Valve Test Requirements" BAYNE.J.P Power Authority of the State of New York 82/10/15 VABBALLO.D B Operating Reactors Branch 2. 17pp 15757 263 24X Fiche: 50-333, 82/10/15.8210200074
- Q Inspection reports: 1E Bulletins & correspondence
- B210080015 Addl response to FOIA request for 19 categories of info ra nuclear reactor events & sefety problems Forwards documents listed in App A. Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J M. Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project. 9pp. 15665:027 24X Fiche 30-000, 82/07/12, 8210080015.
- --9210080134 Bystematic assessment of licensee performance notes #2 facility evaluation for Dec 1979-Nov 1980 # NRC No Detailed Affiliation Olven. 80/11/30 9pp 15647.349. 24X Fiche.50-000,82/07/12,8210080015.
- 8210040317 Forwards partial response to NRC 820414 request for addition or inservice inspirogram. Response to Items 8 & 10 w[1] be provided by 821208 or approx 30 days after start of next scheduled outage
 BAYNE, J. P. Power Authority of the State of New York. 82/09/28 VASSALLO.D.8 Operating Reactors Branch 2 10pp 15586 [57 941 Fiche 50-333, 82/09/28, 8210040317.

- E210070362 Forwards Page 12A to 820914 IE Insp Rept 50-333/82-19, inadvartently omitted due to administrative arror STARDSTECHIR Division of Project & Resident Programs 82/10/0 MCNEILL, C A Power Authority of the State of New York 19 15534 038 24X Fiche 50-333,82/10/04.8210070362
- --8210070357 Paga 12A to 1E Insp Rept 50-333/82-19 on 820914, instricted by amitted from original rept * Region 1. Office of Director 82/10/04 ip 15634 039 24; Fichs 50-333, 82/10/04,8210070362
- 8200190233 IE Info Notice 80-33. Buppl 1, "Leaking & Dislodged I-i25 Implant Seeds " Bvc list encl COBB.L I Division of Fuel Factilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 1576i 250 24% Fichs 50-000,82/10/06.8208190233
- 821015027: Ack receipt of 8209:7 ltr informing NRC of staps taken to correct violations noted in IE Insp Rept 50-333/82-15
 STARBSTECKI:R Division of Project & Resident Programe 82/10/07
 MCHEILL.C A Power Authority of the State of New York 1p
 15703 237 24% Fiche 50-233,82/10/07,8210150271
- --8210150283 Responds to NRC 820820 ltr ra violations noted in 1E Insp Rept 50-333/82-15 Corrective actions solid radwasta eye procedure revised issue dates of maint procedures revised & security quards instructed to monitor more closely MCNETULEC A Power Authority of the State of New York 82/09/17 STAROBTECKI.R Division of Project & Resident Programs App 15703 238 24X Fiche 50-333, 82/10/07,8210150271
- 9210210100 Forwards IE Insp Rept 50-333/82-ii on 820901-30, No noncempliance nated STAROSIECKI.R Division of Project & Resident Programs. 62/10/07 FITZPARRICK, J Power Authority of the State of New York 2pp 15745 307 24X Fiche 50-333.62/10/07.8210210100
- --82(0210115 IE Insp Rept 50-333/82-11 oh 620901-30 No noncompliance noted Major areas inspected action on previous insp findings.LER review.operational affety emification, surveillance & maint observations & NUREO-0737 teams LINVILLE,J C., DOERFLEIN.L T , KISTER,H B Region 1, Office of Director 82/10/06 12pp 15765 309 24X Fichs 50-333.82/10/07, 8210210100
- B208190298 IE Bulistin 82-03, "Stress Corresion Cracking in Thick-Wall-Large-Diameter, Stainless Strel. Recirculation Sys Pipfing at SNR Plants "Syc list encl DEYOUNG.R C. Director's Office, Office of Inspection and Enforcement 62/10/14 Consolidated Edison Co of New York 315pp 15810 125 24X Fichs. 50-000, 62/10/14.8208190238
- 8210190411 Forwards inservice insp summery rept for Winter 1981-82 outage & two metallurgical anetysas, "Metallographic Investigation of Type 304 Btainiass Steal Schedule 80 Fipe " Retults of insps acceptabla BAYNE.J P Power Authority of the State of Naw York 82/10/15 VASSALLO.D B Operating Reactors Branch 2. 2pp 18743-103 24) Fache 50-333, 82/10/15, 82/10/941
- --B210190420 "Metallographic Invastigation of Type 304 Stainless Steel Sichedule 80 Pipa " BUCHMEITAR D Battelle Memorial Institute, Columbus Laboratories, 82/03/25, 18pp 15743 105 24X Fiche 50-333,82/10/15.8210190411
- --B210170428 "Investigation of Flaws on Inside Burface of Type 304
 Stainless Steel Schedule 80 Pipa "
 * Battelle Memorial Instituta, Columbus Laboratories 82/07/30
 51pp 15749,123. 24X Fiche.50-333,82/10/15.8210190411
- ---B210190435 "Inservice Insp Summery & NIB-1 Data Rept.Winter 1981-82

 Outage "

 BANCIC, D. BURNB, R. A. Power Authority of the State of New York
 82/10/15 572pp. 15473.174 24X Fiche, 50-333, 82/10/15,
 B210190411.
- B250260334 Ack raceipt of 820803 ltr informing NRO of steps taken to correct violations noted in IE Health Physics Appraise!
 Hept 50-333/80-20 Pull ALARA program implementation prior to 1783 refueling outage understood.
 MARTIN.T T Division of Enginasing & Technical Programs 82/10/21 MCNEILL.CA Power Authority of the State of Naw York 2pp 15802:342. 24X Fichs 50-333,82/10/21,8210260334.
- --8210260338 Buppls response to NRC 820120 & 0702 itrs re itams noted in IE Health Physics Appraisal Rept 50-333/80-20 Corrective actions schedule for technician ratraining established & engineering controls will be part of ALARA program MCNEILL.C.A., Power Authority of the State of New York, 82/08/05 MARTIN.T.T. Division of Engineering & Technical Programs, 3pp. 15802.0344. 24X Ficha: 50-333,82/10/21,8210260334

- R Periodic operating reports & related correspondence
- 821020001B Forwards updated monthly operating rept for Jan 1982 MCNETLL, C A Power Authority of the State of New York B2/02/03 Management Information Branch 1p 15756 122 24X Fiche 50-333, 82/02/03, 8210200018
- --8210200024 Updated monthly operating rept for Jan 1982 ZUFELT.E Power Authority of the State of New York 82/02/28 12pp 15756 123 24X Fiche 50-333,82/02/03,8210200018
- 8210120240 Forwards monthly operating rapt for Sapt 1982 MCNEILL.C A Power Authority of the State of New York Director's Office. Office of Inspection and Enforcement 1p 15652 116 24% Fichs 30-333,82/10/04.8210120240
- --8210120243 Monthly operating mept for Bapt 1982 COOK. J Power Authority of the State of New York 82/10/04 7pp 15552 117 24X Fiche 30-333.82/10/04.8210120240
- S Reportable occurrences. LERe & related correspondence
- 8210040324 Forwards LER 82-042/03L-0

 MCNEILL, C A Power Authority of the State of New York 82/09/21

 HAYNEB, R C Region i, Office of Director ip 15586 185 24X

 Fichs 50-333, 82/09/21, 8210040324
- --8210040332 LER 82-042/03L-0 on 820826, testing of control rod hydraulic control unit accumulator pressure & leval suitches & pressure indication revealed &8 of 41; instruments out of calibr or not operating properly Caused by instrument drift KEITH.H N Power Authority of the State of New Yort 82/09/21 Region 1. Office of Director 2pp 15586 186 24X Fithe 50-333,82/09/21.8210040324
- 8210060285 Forwards LER 82-043/03L-0
 MCREILL, C.A. Powar Authority of the State of New York 82/09/24
 HAYNES, R. C. Region 1. Office of Diractor ip 15621 069 24X
 Fiche 50-333, 82/09/24, 8210060285
- --8210060292 LER 82-043/03L-0 on 820902. MSIV D inhord 10% switch would not reset when tested to satisfy Tech Spec 3 1-1 Caused by drift between ewitch operator & striker plate Switch striker plate modified XEITH. H N Power Authority of the State of New York 82/09/24 Region 1. Office of Director 1p 15821 070 24% Fiche 50-333, 82/09/24, 8210060285
- 8210220517 Discusses 820501 avent re oscillation of frequency k output power in amargency dissel generator sys Root cause of dissel generator failures unknown Efforts on flow blockage of cooling water to safety sys adequately address problem CHIRAMALIM Reactor Operations Analysis Branch 82/10/01 SEYRITIK V Reactor Operations Analysis Branch 7pp 13786.077 24X Fiche 50-833.62/10/01.8210220519
- 8210190069 Forward: LER 82-044/03L-0 MCNEILL, C.A. Power Authority of the State of New York 82/10/07 HAYNES.R.C. Region i. Office of Diractor ip 15742 134 24x Fiche 80-033, 82/10/07, 8210190069.
- --8210190077 LER 82-044/03L-0.on 820909, motor operator electrical breaker tripped while attempting to cycle LPCI injection valve Caused by electrical motor fault resulting in isolation failure created during attempted valve cycling FERNANDEZ.H. Power Authority of the State of New York Region I, Office of Director 1p 15742 135 24% Fiche: 50-333, 82/10/07, 8210190069.
- 8210220255 FNO-I-B2-066 on 821018, Quadrex Corp shielded van transporting four ampty spent fuel racks to Oak Ridge.TN collided w/automobile in North Syracuse.Ny Radiation surveys did not identify any damage to packaging CLEMONG.P. OREENMAN.E., BRUNNER.E Region i. Office of Director. 82/10/19, 1p. 15775 358 24X Ficha.50-333.82/10/19,8210220255
- S210260170 Forwards LER 82-018/03X-1 MCNEILL,G.A Power Authority of the Stata of New York B2/10/19 MAYMEBR.C Ragion 1, Office of Director. ip 15799:050 24X Ficha 50-333, 82/10/19, B210260170.
- --B210260175 LER 62-018/03X-1.on 620419, surveillance testing indicated four smoke detactore imperable Caused by failure to terminate connecting cabling properly, due to anadequate procedure preparation & raviaw Procedure to be revised.

 *** Power Authority of the State of New York. 82/10/19 Region in Office of Director App 15799.051 24% Fiche.50~333, 82/10/19,8210260170

- 8210260306 RD on 820628, combustion in offgas sys observed Caused by improper velve linear allowing more gas to recombiner then dilution flow rate could support Incident discussed w/shift supervisor & training will be developed MCNEILL, C.A. Power Authority of the State of New York 82/10/19 HAYNES R.C. Region i. Office of Director 3pp 15803 009 24X Fiche 50-333, 82/10/19, 8210260306
- B210260378 Forwards Updated LER 82-028/03x-1
 MCNEILL, C A Power Authority of the State of New York 82/10/19
 HAYNES, R C Region 1, Office of Director 1p 15804:252 24X
 Fiche 50-333, 82/10/19, 8210260378
- --8210260386 Updated LER 82-028/03X-1-on 820701, drywell equipment drain sump flow integrator found out of calibr & could not be edjusted Ceused by abnormel friction in drive gear train New geers purchased to rebuild unit.

 Power Authority of the State of New York 82/10/19 Region 1, Office of Director 2pp 15804 253 24X Fiche 50-333, 82/10/19,8210260378

DOCKET 50-334 BEAVER VALLEY POHER STATION, UNIT I

- F Security, medical, emergency & fire protection plans
- 8210010013 Forwards add1 info requested on 820726 re changes to guard training & qualification plan. Info withheld (ref 10CFR2, 790 & 10CFR2, 770 CAREY, J. J. Duquesne Light Co. 82/09/20 VAROA: 8 A. Assistant Director for Operating Reactors. 1p. 15565 147 24X Fichs. 50-334, 82/09/20, 8210010013
- 8210080045 Notification of 820930 meeting w/util in Bethesde.MD to discuse upgrading of meteorological eys TAM.P S. Operating Reactors Branch 1. 82/09/23 VARQA.B A Operating Reactors Branch 1 2pp 13669 317 24X Fiche. 50-334, 82/09/23, 8210080045
- 8210180016 Releases public version of revised emergency preparedness implementing procedures FELTON. J H Division of Rules end Records 82/09/29 Document Menagement Brench 1p 15717-318 24X Fiche 50-334,82/09/29, 821018014
- 8210260122 Releases public version of revised emergency plan implementing procedures. FELTON.J K Division of Rules and Records. 82/10/08 Document Hanegement Branch 1p. 15812 031 24X Fiche: 50-334,82/10/08.
- -8210260125 Forwarde public version of revised emergency plan implementing procedures, including Procedures EPP/IP 1.1 remotification, 1.2 recommunications & dissemination of info & 1.3 returnover status checklist SIEBER. J D Duquesne Light Co 82/09/14, VAROA.S.A. Operating Rectors Branch 1. Sep. 15812,032. 24X Fichs. 50-934, 82/10/06, 8210260122
- --8210260127 Public version of revised emergency pien implementing procedures including Procedures EPP/IP 1 ire notification, i2 re communications & dissemination of info & i.3 re tunnover status checklist LACEY.W J Duquesne Light Co. 82/09/15, 834pp, 13812.035, 24x Fichar 50-334, 82/10/08-8210260182.
- 8210280411 Informs that proposed changes to access control program contained in licensee 820702 ltr acceptable. Final approval cannot be granted until necessary changes to physical security giam submitted, VAROA. S.A. Operating Reactors Branch 1 82/10/08, CAREY, J. J. Duquesne Light Co. 2pp. 15859 334, 24X Fiche: 50-334, 82/10/08, 8210280411.
- 8210240458 Forwards supplemental info per 821014 discussion clarifying exemptions previously documented in fire protection App R review Bection 11.2. "Reactor Containment" & Section 11.6. "Primary Auxiliary Bidg."
 CARRY.J.J Duquesne Light Co. 82/10/22 VARGA.S. A. Operating Reactors Branch i 7pp 15806 200, 24x Fishe. 50-334.82/10/22, 8210260458
- P Operating license stage documents & correspondence
- 8210120120 Advises that no further ofc action planned re 800521 inoperability of RHR sys for 5-h since pipe crack study group will issue rept in 2 wts. Sys inoperability due to weld leak repair effort LANNINO, W. D. Director's Office 80/08/04. Director's Office, 1p 18692-284, 24X Fiche: 50-334, 80/08/04, 8210120120.

- 8210030487 Forwards request for add1 info re proposed changes to Tech Specs for leek rate testing of certain isolation valves using weter in lieu of eir or nitrogen Response requested within 30 deys of receipt of itr VARQA: 8 A Operating Reactors Branch i 82/09/21 CAREY. J J Duquesne Light Co 3pp 15626 283 24X Fiche 50-334.82/09/21, 8210050487
- 8210050165 Forwards util summary of efforts re rod position indication sys per 820713 commitment & 820720 itr Westinghouse companion rept expected by mid-Oct CAREY, J J Duquesne Light Co 82/09/29 VAROA, 8 A Operating Reactors Branch i 2pp 15605 122 24X Fiche 50-334,82/09/29,8210050165
- --8210050168 "Beaver Velley Fower Station.Unit 1 Analog Red Position indication Bys." special rept
 ORADA.K D. BIEBER.J D Duquesne Light Co 82/08/31 20pp
 13505 124 24% Fiche 30-334.82/09/29.8210050165
- 8210130561 Forwards addl info re proposed changes to Tech Boace for leak rate testing of certain isolation valves using water in lieu of gas. In response to NRC 820921 request M/27 oversite dreusings Aperture cards are available in PDR CAREV. J J Duquesne Light Co 82/10/05 VARQA, 8 A Operating Reactors Branch I 35pp 15679 015 24X Fiche 50-334.82/10/05, 8210130561
- 82:0150312 Forwards "Cycle 3 Startup Test Rept "Rept summarizes test performed & verifies Cycle 3 reload core design data after criticality & celibr of excore instrumentation at several different power levels

 CAREY, J J. Duquesne Light Co 82/10/05 HAYNES, R C Region 1, Office of Director 1p 15701 345 24X Fichs 50-334,82/10/05, 82:0150312
- --8210150316 "Cycle 3 Stertup Test Rept " # Duquesne Light Co 82/10/05 5pp 15701,346 24X Fiche 50-334,82/10/05.8210150312
- 8210190747 Forwards edd1 info re two-loop operation.per NRC 820817 request. Westinghouse reviewing Question 7 against analysis CAREV. J. Duquasna Light Co 82/10/08 VARCA.8 A Operating Reactors Brench 1. 6pp 15737 135. 24X Ficha 50-334, 82/10/08, 8210190747
- 8210270267 Forwards revised application for emend to License DPR-66. consisting of Proposed Change Request 36.Revision 3. Incorporating rediciogical affluent Yach Space into App A Offsite dose calculation manual & App B will follow CAREY. J. Duqueens Light Co. 82/10/22 VAROA. B. A. Operating Reactors Branch 1. Ip. 15828 287 24% Fichs 50-334.82/10/22, 82/0270267
- --B21027026B Revised application for emend to License DFR-66, incorporating proposed rediological efficient Tech Spece into App A.
 GAREY, J. J. Duquesne Light Co. B2/10/22 ip 15828, 268 24x Fiche 50-334, B2/10/22, B210270267.
- --8210270271 Proposed rediological effluent Tech Spets # Duquesne Light Co 82/10/22 116pp 15928 289 24X Fiche 50-334,82/10/22,8210270267
- Q Inspection reports: IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of inf nuclear reactor events & sefety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Examption 5), FELTON. J.M. Division of Rules and Records 82/07/12, UDELL,R Critical Mass Energy Project 9pp. 15665-027, 24X Fichel 50-000, 82/07/12, 8210080015.
- --B2100B0114 By stematic assessment of licensee performence notes facility evaluation for Bept 1979-Aug 1980 8 NRC No Datailed Affiliation Olven B0/08/21 16pp. 15667 299 24K Fiche 80-000, 82/07/12,82100B0015
- 8210070007 Responds to FOIA request for eight categories of recers steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App E. FELTON, J. M. Division of Rules and Records. 82/08/10 LONO, D. Winthrop, Btimson, Putnam & Roberts, 9pp 19645:063 24X Fiche: 50-000, 82/08/10, 82/0070007
- --8210070139 Forwards tabulated data on steam generator insp & eai facilities. Data should be provided to licensees IPPOLITO.T. Operating Reactors Assessment Branch, 82/04/01 VAROA.S. Operating Reactors Branch i. 5pp. 15645.131. 24X Fiche: 50-000, 82/08/10.8210070007

- NIPO233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 IJIat Seeds " Svc list encl.
 133.L 1 Division of Fuel Facilities, Haterials & Hafeguards 2710/05 Consolidated Edison Co of New York 66pp 13761:250 14 Fiche 50-000,62/10/06,6208190233
- C21023: Forwards IE Insp Rept 50-334/B2-21 on 620616-20 No categorial contest of Engineering & Technical Programs. 62/10/06 ATTMET T Division of Engineering & Technical Programs. 62/10/06 CAREY, J J Duguesne Light Co 2pp 15766 274 24X sche 50-334,62/10/06:8210210231
- 210210236 IE Insp Rept 50-334/82-21 on 820816-20 No noncompliance roted Hajor areas inspected administrative controls for safety-related maint-maint program & activities. surveillance testing & calibr programs & housekeeping & cleanliness testing & calibr programs & housekeeping & cleanliness StuMBERO.N. BISSETT.P., SHAUD.T. Region 1. Office of Director. 82/09/23 25pp 15766.296. 24X Ficher 50-334.82/10/06.8210210231
- 0130615 Ack receipt of 820930 ltr informing NRC of steps taken to oprect violations noted in IE Inap Rept 50-334/82-46.

 "IAROSTECKI.R Division of Project & Resident Programs 82/10/08.

 APEV.J J Duquesne Light Co ip. 13698, 328 24X

 Teche 50-334, 82/10/08, 8210150015.
- 2210150018 Responds to NRC 820830 ltr re violations noted in IE lnep Rept 50-334/82-16 Corrective actions: detector cables of R-8141 reconnected in correct position & maint manual changed to insert caution re proper handling CAREY. J Duquesne Light Co 82/09/30, 87AR08TECK1, R Division of Project & Resident Programs App 15690,329, 24X Fiche 50-334,82/10/08,8210150015
- IO220184 Advises that revised completion date for evaluation of calibr radiation beam uniformity is 821031, per IC Health Physics Appraisal Rept 50-334/81-05.
 CAREY, J. Duquesne Light Co. 82/10/08 HAYNCS, R.C. Region 1, Diffice of Director. 2pp. 15776-244 24X Fiche 30-334,82/10/08,8210220184
- OB190238 IE Bulletin 82-03, "Btress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel-Recirculation Bys
 Piping at BHR Plants " Syc list encl
 DEYOUND.R C Director's Office. Office of Inspection and
 Enforcement 82/10/14 Consolidated Editon Co of New York
 145pp 15810 128 24X Fiche: 50-000, 02/10/14, 8208190238

Persodic operating reports & related correspondence

- 210050076 Forwards revised Page 4 of "1781 Rept of Facility Changes, Taste & Experiments"

 CAREY, J J Duquesne Light Ca 82/09/23 HAYNGS, R C Region 1,

 Office of Director 1p 15615 329 24X Fiche 50-334,82/09/23,
 8210060076
- -821036938 Revised Page 4 of "1981 Rept of Facility Changes Tests & Experiments."

 t Duquesne Light Co 82/09/23 1p. 15615 330 24K Fichs 50-334,82/09/23,8210060076
- 210060088 Forwards NPDES discharge monitoring rapts for Aug 1982 FEITKNECHT.C Duquesne Light Co 82/09/28 REID.R W Operating Reactors Branch 4. 2pp 15615 022 24X Fichs 50-334,82/09/20. 8210060088
- -8210060096 NPDES dischargs monitoring repts for Aug 1982 SIEEDL L Duquesne Light Co 82/09/29 14pp, 15615:024 24X Fithe 50-324,82/09/28,8210040088
- 3 Reportable occurrences, LERs & related correspondence
- 3210280307 LER 81-025/03L-0 on 810216, increased laskage from reactor coplant (RC) loop 1A RTD manifold hot leg valve RC-20 reported, Caused by attempted maint to repair valve. Temp channels returned to avc.

 LACEY.W 8 Duquesne Light Co E1/03/17 Region 1, Philadelphia, Office of the Director (81/03/01) Rpg. 18837-283 24X
 Fiche 50-334,81/03/17,8210280307
- 8210040065 LER 81-02B/O3L-0. on 810219, during power operation, results of surveillance test revealed reactor coolant leskage of 2.09 gpm Caused by failure of giend flange on valve Split gland flange used as mod to repair vaive Work completed 810221. LACEY.W S Duquesne Light Co. B1/03/20 Region i, Philadelphia, Office of the Director (81/03/01) 2pp. 15981.218. 24X Fichs 50-334, 81/03/20, 8210040065

- 6210280271 LER B1-027/03L-0.on Si0218, at 98% power, all three chlorine detectors failed to meet min electrolyte drip rate criteria specified in surveillance test Caused by dirty wicks which prevented flow of electrolyte. Nicks cleaned.

 LACEY. W. B. Duqueane Light Co 81/03/20 Region 2, Atlanta, Office of the Director (81/03/01). 2pp. 15837 314 24% Fiche. 50-334, 81/03/20, 8210280271
- 8210280280 LER 81-025/031-0 on 810218.RC8 loop flow channel indication failed to meet min flow surveillance check requirement Caused by transmitter delta pressure transducer diaphragm leakage Transmitter replaced LACEV.W B Duquene Light Co 81/03/20 Region 1. Philadelphia. Office of the Director (81/03/01) 2pp 15837 047 24X Fiche 30-334.81/03/20.8210280280
- 8210130077 Forwards LERs 81-59/03L & 81-71/03L to tripping of battery charger output breaker 2 on thermal overload during surveifiance testing Recommends that licenses complete appropriate analyses & mods to prevent recurrence HICHELBON.C Director's Office 82/02/23 HAYNEB.R.C. Region 1. Office of Director. 2pp 15696 245 24X Fichs 50-334.82/02/23, 62/03/0077
- 8210010008 Responds to FDIA request for 19 categories of documents renuclear reactor events & sefety problems Forwards documents listed in App A FELTON, of Division of Rules and Records 82/06/29 UDELL.R A Crifical Mass Energy Project 15pp 15727 005 24X Fichs, 50-000, 82/06/28, 8210010008
- --8210030124 Bummary of Bi06i0 operating reactor events meeting LAINAS, Q.C. Assistant Director for Bafety Assessment 81/06/17 EISENHUT, D. Q. Division of Licensing 5pp 15729, 217 24X Fichs. 50-000, 82/06/28, 8210010008
- ~-8210060432 Discusses inadequate switchgear cooling at facility
 Implications of event suggest that lose of ventilation syscould have potential safety eignificance requiring addl
 generic review by NRC
 MICHELGON.C Director's Office. 82/02/23 HAYNES, R. C Region 1,
 Office of Director. 2pp 15732.304 24X Fiche: 50-000, 82/06/28,
 82/0010908
- 8210150179 Forwards LER 82-037/03L-0 LACEY.N. 8 Duqueene Light Co 82/09/27 HAYNES, R C Region 1. Office of Director, 2pp 15705, 262 24% Fiche 50-334, 82/09/27, 82/0150179
- --8210180208 LER 82-037/03L-0 on 820921.stwam generator iA level protection channel III signal comparator LO-FWA76A declarad inoperatis dus to faulty actuation & trip setpoint drift found during surveillence testing Hapan comparator replaced * Ducuesne Light Co. 82/09/27 Region 1. Office of Director 2pp. 15705-264 24X Fiche. 50-334. 82/09/27. 8210180199.
- 8210150185 Forwards LER 82-035/03L-0 LACEY-M. 8 Duquerne Light Co. 82/09/30 HAYNES, R.C. Region 1, Office of Director. 2pp. 15707 255 24X Fiche: 50-334,82/09/30, 8210150185.
- --B210150201 LER 82-D35/03L-0 on 820917. delta flux exceeded required target band Caused by low heater drain tank level, leading to load reduction. Control rods borated out to return delta flux to within target band.

 LACEY.H 8. Duquetne Light Co B2/09/30. Region 1. Office of Director 239. 18707.287 24X Fiche. 50-334.82/09/30,8210150185
- 8210190274 Forwards LER 82-034/03L-0 LACEY.M.8 Dequasos Light Co. 82/10/04 HAYNES.R C. Region J. Office of Director. 2pp. 15742 [85. 24X Fiche: 50-334, 82/10/04, 8210190274
- ---8210190282 LER 82-034/03L-0: on 820715, during surveillance test containment vacuum pump failed required discharge flow rate. Caused by buildup of dirt & debris in discharge line. Line cleaned & suction & discharge filters replaced, LACEV.M. S. Duquesma Light Co. 82/10/04. Region I. Office of Director 2pp 15742:187. 24x Piche 50-334.82/10/04,8210190274
- 8210210006 Forwards LER 82-032/03L-0
 LACEY, M. S. Duqueene Light Co 82/10/07, HAYNES: R. C. Region i. LACEY, M. S. Duqueene Light Co 82/10/07, HAYNES: S0-334, 82/10/07, 8210210006.
- --8210210010 LER 62-032/03L-0-on 820708, firs hose protection in intake structure lost when fire main tuptured in redundant underground supply leader Caused by overtorquing of flangs setscrews initiating crack.

 **A Duquesne Light Co. 92/10/07 Region 1, Office of Director.

 **2pp 15766,025. 24% Fiche.50-034,82/10/07.8210210006.

- 8210210065 Forwards LER 82-033/03L-0 LACEY, N B. Duquesne Light Go 82/10/08 HAYNES, R C. Region 1, Office of Director 2pp. 15765 341 24X Fichs 50-334,82/10/08,
- --8210210072 LER 82-033/03L-0 on 8209H; operators unable to reclose steam supply trip valve TV-MS-1058 of turbins driven auxiliary feedwater pump FH-P-2 Caused by washer lodged in valve trim
 - Line Isolated, # Duquesne Light Co B2/10/08 Region i, Office of Director. 2pp 15765:349 24X Fiche 50-334.82/10/08.8210210065
- 8210260163 Forwards updated LER 81-091/01X-1.

 LACEY,N S Duquesna Light Co 82/10/11 HAYNES,R C Region i.

 Office of Director. 2pp 15799 003 24X Fiche 50-334,82/10/11. 8210260163
- --8210260167 Updated LER 81-091/01X-1.on 811029.break in redundant underground 12-1nch supply header resulted in loss of fire weter sys Caused by external finger corrosion along pipe botton Total sys piping change-out not warrented buquesna Light Co 82/10/11 Region 1, 0ffice of Director 2pp 15799:005 24X Ficha.50-034.82/10/11.8210260163
- 8210260203 Forwards LER 82-040/03L-0 LACEY,N S Duquesne Light Co 82/10/14, HAYNES,R,C Region i. Office of Director. 3pp. 15804 248 24X Fiche 50-334,82/10/14,
- --8210240226 LER 82-040/03L-0 on 820919, alarm status lichts & visual riukovsko LER MR-040/USL-D on MROTIVA alam status lights & visual display on core cooling monitor found extinguished. Caused by loose connection. Connection repaired Monitor to be tested & inspected in conjunction w/Mestinghouse kit installation # Duquesne Light Co 82/10/10 Region I. Office of Director ip 15804: 251 24X Fiche: 50-334, 82/10/14, 8210260203
- 8210260478 Forwards LER 82-036/03L-0 LACEY.H B Duquesne Light Co 82/10/14. HAYNE8,R.C Region 1. Office of Director. 2pp 15807 283. 24X Fiche 50-334,82/10/14.
- --8210260487 LER 82-036/03L-0 on 820619, diesei engine cooling water inlet k outlet temps exceeded max allowable values rendering diesel generator 2 inoperable Caused by fouling of cooling water HX tubes. Tubes cleaned.

 LACEY, M.S. Duquesne Light Co. 82/10/14, Region i, Office of Director 2pp. 15807-255, 24X Fichs 50-034,82/10/14.8210260478,
- 8210220447 PNO-1-82-065 on 821018, reactor tripped on high level in stam generator due to erratic operation of feedwater control veive.Resulting feedwater isolation tripped motor-driven main feedwater pumps & auxiliery pumps started. NORRHOLNL . KEINIO:R Region 1. Office of Director. 82/10/18 lp 15778 245. 24X Fiche: 50-334: 82/10/18:8210220447.

DOCKET 50-335 ST, LUCIE PLANT, UNIT 1 F Security, medical, emergency & fire protection plane

- B210010155 Forwards IE lnsp Repts 50-335/B2-28 & 50-389/B2-37 on 820B09-13.No noncompliance noted DANCE, H.C. Division of Project & Resident Programs B2/09/OB. URRIO.R E Florida Power & Light Co. Epp. 15565:326 24X Fiche, 50-335, 82/09/08, 8210010155
- --8210010159 IE Insp Repts 50-335/82-28 & 50-389/82-37 on 820809-13 No noncompliance noted Major areas inspected:followup on emergency preparadness appraisal & exercise findings HUFFMAN 6. N. J. JENKINS: 0 R. Division of Emergency Preparadness & Operational Support. 82/09/02 18pp. 15565:328. 24X Fiche.50-335.82/09/08.8210010155.
- 8210050559 Releases public version of emergency preparedness open FELTON. J. M. Division of Rules and Records. 82/09/16. Docum Henagement Branch 19 15637-220. 24X Fiche. 50-335, 82/09/16. 8210050559
- --8210050567 Bubmite public version of clarification of emergency preparadness planning open items of emergency action levels, staffing augmentation & unannounced drills.

 UMRIGAR Florida Fower & Light Co. 82/09/03. EISENHUT, D. G. Division of Licensing. 2pp. 15637:221. 24% Fiche: 50-335, 82/09/16, B210050559.
- 8210190371 Forwards Revision 1 to 10CFR50.App R fire protection review. correcting typographical & aditorfal errors. WRIGER F florida Power & Light Co. 82/10/12, EIBENHUT, D. O Division of Licensing. 1p. 13741:218, 24X Fiche: 50-335,82/10/12, 8210170371.

- --8210190374 Revision 1 to 10CFR50.App R fire protection review 4 Florida Power & Light Co 82/10/12 200pp 15741 219 24x 4 Florida Power & Light Co 82/ Fiche 50-335, 82/10/12, 8210190371
- 8210190440 Extends invitation to observe 821019 demonstration of emergency response sys at Technology for Energy Corp. Knozville, TN UHRIO, R E Florida Power & Light Co 82/10/12 EISENHUT, D C Division of Licensing ip 15741 186 24% Fiche 50-000, 82/10/12.
- 8210260376 Ack receipt of 821013 ltr informing NRC of steps taken to correct violations noted in IE Bafeguards Insp Rept 50-335/82-30 50-33762-30 LEUIS.R C Division of Project & Resident Programs 82/10/22 UHRIO.R.E Florida Power & Light Co 1p 15806 138 24X Ficha 50-335,82/10/22,8210260376
- --02i02ò0391 Responds to NRC 820913 ltr re violations noted in 1E 8efeguards Insp Rept 50-335/82-30 Corrective actions withheid (ref 10CFR73 21) UHRIG.R E Florida Power & Light Co 62/10/13 G'REILLY, J P Region 2, Office of Director ip 15806 139 24X Fiche 50-335,82/10/22-8210260376
- --8210260510 Forwards IE Safaguards Insp Rapts 50-335/82-30 & 50-397/82-41 on 820816-20 & notice of violation Notice of violation & rapt details withheld (ref 10CR73 21) LEVIS.R C Division of Project & Resident Programs 82/87/1 UHRIG.R E Florida Fower & Light Co. 2pp 15806 140 24X Fiche. 50-335, 82/10/22, 8210240376
- --B210260515 IE Safeguards Insp Rept 50-335/82-30 k 50-389/82-45 on 820816-20. Noncomplience noted failure to comply w/security gian re vehicle control alarms & compensatory action Details withheld (ref 10GR73 21). OCODE, R. BTANBERRY, H. HCOUIRE, D. R. Region 2, Office of Director 82/09/10 2pp 13806 142 24X Fiche-50-335,82/10/22,8210260376.
- P Operating license stege documents & correspondence
- B210040043 Forwards Amend 53 to License DPR-67 k safety evaluation Amend deletes current Tach Spec requirements to periodically test insulation of certain Class IE electrical underground cables for environ damage CONNER, E. L. Operating Reactors Branch 3 82/09/21 UNRIG, R E Florida Power & Light Co 2pp. 15577; 278 24X Fiche 50-335, 82/09/21,8210040043.
- --B210040044 Amend 53 to License DPR-67, deleting current Tech Spec requirements to periodically test insulation of certain Class IE electrical underground cables for environ damage CLARKAR A Operating Reactors Branch 3 CLARK, R A Operating Reactors Branch 3 82/09/2 15577-280 24X Fiche 50-335,82/09/21,8210040043,
- --8210040046 Bafety evaluation supporting Amend 53 to Licanse DPR-67 # Office of Nuclear Reactor Regulation, Director 82/09/21 Jg i5577:285 24X Fiche:50-335.82/09/21 8210040043
- 821025004B Forwards corrected version of Amend 53 to License DFR-57 & safety evaluation. Tech Spec pages omitted from earlier version. CONNER.E.L Operating Reactors Branch 3 82/09/21 UHR19.R E Florida Power & Light Co 2pp. 15798:350, 24X Fiche.30-335,82/09/21,8210250048
- --B210250050 Corrected version of Amend 33 to License DPR-67 deleting requirement to test insulation of certain Class IE electrical undeground cables for environ damage. Tech Space omitted from earlier version.

 CLARK.R.A. Operating Reactors Branch 3 82/09/21 7pp 15798:332, 24X Fiche 50-335,82/09/21,8210250048
- --- BZ10250051 Corrected version of safety evaluation supporting Amena 53 to License DPR-67

 * Office of Nuclear Reactor Regulation: Director. 82/09/21. 2fp
 15798-359. 24% Fiche: 30-335,82/09/21,8210250048
- 8210050061 Forwards 820930 cover ltr to Franklin Research Cir ra affl info concerning equipment qualification.per NRC 820217 UHRIG.R.E Fioride Power & Light Co 82/09/30. CL Operating Reactore Branch 3 4pp. 15603:238. 24X Fiche: 50-335:82/09/30:8210050061.

- \$210050288 Informs that requirements stated in Genevic Ltr 82-12 restaff working hours adequately enforced by incorporation in afainistrative procedures Amend to Tech Specs unnecessary at present time

 URRIGARE Florida Power & Light Co 82/09/30 EISENHUT, D G.

 Division of Licensing ip 15619 212 24X Fiche 50-335.82/09/30.8210060288
- E210260551 Notifies of acceptability of 820108 response to NUREO-0737, Item II k G 25, "Loss of AC Power to Reactor Coolant Pump Seals "
 CLARK.R A Operating Reactors Branch G 82/09/30 UHRIQ.R E Florade Power & Light Co 2pp 15830 347 24X
 Fich# 50-335.82/09/30,8210260551
- 8210190310 Advises of request for proposal to provide criteria for special lifting devices to demonstrate equivalency w/ Guideline 4 of NUREQ-0612, "Control of Heavy Loads " Additing will be provided as soon as possible re 821007 telcon, G-NFID-RE Florida Fower & Light Co 82/10/12 CLARK, R A Operating Reactors Branch 3 2pp 13742 148, 24X Fiche 50-335, 82/10/12, 8210190310

G. Imagection reports. IE Bulletins & correspondence

- 8210220451 Responds to 820802 telcon request for add1 info re IE Insp Rept 30-335/82-17 Repts of inservice insps will be submitted within 90 days of completion Repts of previous insps available at corporate ofc H/o enci USRIO, RE Flarida Power & Light Co 82/08/19, 0'REILLY, J P Region 2. Office of Director 2pp 15778, 246 24X Fische 50-335, 82/08/19, 8210220451
- 8210010155 Forwards IE Insp Repts 50-335/82-28 & 50-389/82-37 on B20809-13 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/08 WHITO, R E Floride Power & Light Co 2pp 15565 326 24X Fiche 50-335, 82/09/08, 8210010155
- --8210010159 IE Insp Repts 50-335/82-28 & 50-389/82-37 on 820809-13 No noncompliance noted Major ereas inspected followup on emergency preparedness appraisal & exercise findings HUFFMAN.O N , JENKINS.C R Division of Emergency Preparedness & Operational Support 82/09/02 18pp 15565 328 24X Fichs 50-335,82/09/08.8210010135
- G210010075 Ack receipt of B20Bi3 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/82-17
 LEWIS:R C Division of Project & Resident Programs 82/09/i5
 UHRIO:R E Florida Power & Light Co ip 15567 170 24X
 Fichs 50-335:82/09/i5:8210010075
- --8210010078 Ack receipt of 820722 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/82-17
 Supplemental response due by 820812
 LEVIS.R C Division of Project & Resident Programs 82/08/13
 UHRIG.R E Florida Power & Light Co. 1p 15567 171 24X
 Fische 50-335,82/09/15.8210010075
- --8210010084 Ack receipt of & responds to violations noted in IE Insp Rept 50-335/82-17 on 820511-14 No proprietary info Corrective actions vendor requested to expedite issuance of steam generator insp info UHRIO:R E Florida Power & Light Co 82/07/22 0'REILLY, J P Region 2. Office of Director 2pp 15367 172 24X Fishe 50-335,82/09/15,8210010075
- --B210010092 Notice of violation from insp on 920511-14 - Division of Project & Resident Programs 92/06/18, ip 1\$567 176 24% Fiche 50-335,82/09/15,8210010075
- --B210010096 IE Insp Rept 50-335/82-17 on 820511-14 Nancompliance noted steam generator & other inservice insp repts not submitted in specified time

 OIRARD, E H , ECONOMOS, N Division of Engineering & Technical

 Pregrams 82/06/11 7pp 15567:177 24X Fiche 50-335,82/09/15,8210010075
- B210010142 Ack receipt of 820825 itr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-335/82-01
 DANCE:H C Division of Praject & Resident Programs B2/09/17
 #FRIOR.E Florida Power & Light Co ip 15567:247 24X
 Fiche: 50-335, 82/09/17, 8210010142,

- --8210010153 Responds to NRC 820406 itr re violations noted in IE Insp Rept 50-335/82-01 Corrective actions personnel verbally reinstructed re insp of design documents for proper erections, implementation & documentation UMRIG.R E Florida Power & Light Co. 82/08/25 O'REILLY, J.P. Region 2. Office of Director dop 15547:248 24X Fiche 50-335,82/09/17.8210010142
- 8210150345 Forwards IE Insp Repts 50-335/82-31 & 50-389/82-38 on 820830-0903. No noncompliance noted. DANCE, H C. Bivision of Project & Resident Programs 82/09/22. UKR10: R E Florida Power & Light Co ip. 15704 322. 24X Fichs. 50-335.82/09/22.8210150345
- --B210150338 IE Insp Repts 50-335/82-31 & 50-389/82-38 on 820830-0903. No nancompliance noted Major areas inspected radioactive liquid & passous effluent releases, reactor coolant chemistry & radioactive transportation activities. WRAY, J R, BARR, K P, Division of Engineering & Technical Programs 82/09/17 10pp 15704 323 24X Fichs, 50-335, 82/09/22, 8210150345
- 8210080264 Forwards response to IE Bulletin 80-11, "Masonry Wall Design." supplementing response to NRC 820805 request for add info. WRIO.R E Florida Power & Light Co 82/10/04 CLARK.R A Operating Reactors Branch 3. 37pp 15638, 129, 24% Fiche 50-335, 82/10/94,8210080264
- 8208190233 IE Info Notice 80-35, Suppl i. "Leaking & Dislodged I-125 Implant Seeds " Bvc list ancl COBB.L I Division of Fuel Facilities, Materials & Safeguards. 82/10/06 Comeolidate Edison Co of New York. 66pp 15761,850.
- 8208170238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall:Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants." Syc list encl. DEYOUND:R C Director's Office. Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co of New York. 115pp. 15810-125 24X Fiche, 50-000:82/10/14,8208170238
- 8210220280 Act receipt of 820930 itr informing NRC of steps taken to correct violations noted in IE Insp Repta 50-335/82-11 t 50-389/82-34

 DANCE,H.C Division of Project t Resident Programs B2/10/15. UHRIO,R E. Floride Power t Light Co ip, 15775:084. 24X Fiche 50-335,82/10/15.8210220280
- --B210220286 Responds to NRC 820701 ltr re violations noted in IE Insp Rept 50-335/82-11 Corrective actions. Equipment Clearance Order 1-8-30 corrected & personnel reinstructed. UHRIO:R E Florida Power & Light Ca 82/09/30 O'REILLY, J. P. Replon 2, Office of Director. 2pp. 15775.085 24X Fiche 50-335,82/10/15,8210220280
- --B210220291 Forwards IE Insp Rapts 50-335/82-11 k 50-389/82-34 on 820711-0810 & notice of Violation DANCE. H. C. Division of Project & Resident Programs 62/09/01. UHRIG.R.E. Florida Power & Light Co. 2pp. 15775:087. 24X Fiche 50-335, 82/10/15, 8210220280.
- --8210220297 Notice of violation from insp on 820711-0810. * Division of Project & Resident Programs 82/09/01 ip 15775 OB9 24X Fiche: 50-338, 82/10/15, 8210220280.
- --8210220303 IE Insp Repts 50-335/82-11 & 50-389/82-34 on 820711-0810 Noncompliance noted: on 820805. Equipment Clearance Order L-8-30 incorrectly identified suction & discharge drain valves Y-2317 & Y-2327 for charging pump A ELROD. & A. 8185, H.E., JULIAN.C.A. Division of Project & Resident Programs. 82/08/31 10pp. 15775: 090 24X Fiche 50-335.82/10/15, 8210220280
- 82102&0376 Ack receipt of 821013 itr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-335/82-30.

 LEMIS, R C Division of Project & Resident Programs. 92/10/22. URRIO, R E. Floride Power & Light Co. ip. 1580&.138. 24% Fiche 50-335.82/10/22,8210260376.
- --8210260391 Responds to NRC 820913 ltr re violations noted in IE Safeguards Insp Rept 50-335/82-30, Corrective actions withheld (ref 10CFR73.21), UHRIG.R.E Florida Power & Light Co. 82/10/13 0'REILLY, J. P. Region 2: Office of Director, ip. 15806:139. 24X Fiche.50-335,82/10/22,8210260376.

1

1 1

-

- --B210260510 Forwards IE Safeguards Into Repts 50-335/82-30 & 50-389/82-41 on 820816-20 & notice of violation Notice of violation & rept details withheld (raf 10CFR3 21) LEWIGER C Division of Project & Resident Programs. 82/09/13 URRIO,R E Florids Power & Light Co 2pp 15806:140 244 Fiche: 50-335.82/10/22.8210260376
- --B210260515 IE Safaguards Insp Rept 50-335/82-30 & 50-389/82-41 on B20316-20 Noncompliance noted, failure to comply w/security plen ra vehicle control alarms & compensatory action Datalis withheld (ref 10CFR73 21).

 GOODER R. STANSBERRY.W. MCGUIRE.D R. Region 2. Defice of Director B2/09/10 2pp [5506:142 24X Fiche 50-335,62/10/22, B210260376]
- 8 Reportable occurrences, LERe & related correspondence
- 8210150035 Ferwards LER 81-002/03L-0 BCHMIDT, A D Florida Power & Light Co. 81/02/20. Q'REILLY, J P Region 2, Atlanta, Office of the Director (81/03/01) ip 15701.147 24X Fichs:50-335,81/02/20,8210150035
- --8210150039 LER 81-002/03L-0 on 810122, digital data processing systemputer dropped off-line, resulting in loss of control alament assembly pulse counting backup position indication caused by softwars problem Problem under investigation PACE.P L. Florida Power & Light Co. 81/02/20 Region 2, Atlanta, Office of the Diractor (81/03/01) ip 15701 148 24X Fiche 50-335,81/02/20,8210150035
- 8210010164 Forwards LER 82-045/43X-0 WILLIAMS, J W Florids Power & Light Co 82/09/24 D'REILLY. J P Region 2. Office of Diractor ip 15567 279 24X Fichs 50-335.82/09/24.8210010164
- --BR10010174 LES 82-045/43X-0 on 820913, wash trough used to decontaminate respirators & similar itsms found not draining into raduasts sus Caused by error resulting from parsonnel turnover Drain remoted Dung area surveys will continue. PACE, P. L. Florida Power & Light Co. 82/09/24 Region 2, Office of Director. 2pp 15567-280. 24X Fichs 50-335,82/09/24,8210010164.
- 8210070425 "Rapt on Baint Lucie I Natural Circulation Cooldown on BOO611." IMBRO.E V. Director's Office. B2/09/24. 28pp 15644.289 24) Ficha 50-335.82/09/24.8210070425
- 8210130552 Forwards LER 82-040/03L-0 HILLIAMS.JW Florida Power & Light Co. 82/10/04. O'REILLY, J.P. Ragion 2, Office of Director 1p. 15684-007 24X Fiche:50-235.82/10/04.8210130552
- --9210130362 LER B2-040/03L-0-on 820902. short caused generator breakers to open & synchronizing inhibit timer to start Caused by pareonnel short circuiting relay during generator angative saguence relay tasting. Protection design reviews PACE, P Florids Power & Light Co. 92/10/04. Region 2. Office of Director. 5pp. 15484:008 24X Fiche:50-335.82/10/04, 8210130552.
- 8210130456 Forwards LER 82-041/031-0 HILLIAMS, J.W. Florida Power & Light Co. 82/10/06, O'REILLY, J.P. Region 2, Office of Director, 1p 13682; 147. 24X Fiche 50-333.82/10/06.8210130456
- --8210130462 LER 82-041/03L-0 on 820907, at 99% power, resctor/turbine trip occurred resulting in brief lose of vital buses & iodine spike. Caused by motor auxiliary contact initiating false lose of load & inhibit signals.

 PACE; P L. Fiorida Power & Light Co. 82/10/06, Region 2, Office of Director. App. 15682: [48. 24% Fiche. 50-335, 82/10/06, 8210130456.
- 8210260357 Forwards LER 82-044/03L-0 HILLIAMB.J.M. Floride Power & Light Co. 82/10/15, D'REILLY, J.P. Region 2, Office of Director. ip. 15803:178, 24X Ficha:30-335.82/10/15.8210260357.
- --8210260369 LER 82-044/03L-0: on 820923, pulse counting function for 21 control element assemblies found deleted during normal testing, Caused by personnel error. Methods for alerting operators investigated. PACE, P. L. Florida fower & Light Co. 82/10/15, Region 2: Office of Director 1p, 15803:179. 24X Fichs: 50-0335, 82/10/15, 8210260357.

- DOCKET 50-336 HILLSTONE NUCLEAR POWER STATION, UNIT 2
 F. Security, medical, emergency & fire protection plans
- 8210210587 Informs of new format for submittals containing safeguards info should be submitted similar to proprietory info Gover its should not contain safeguards info. Actual info should be in attachment CLARKAR A Operating Reactors Branch 3 82/09/29 CQUNBIL. 4 0 Northeast Nuclear Energy Co (sube of Northeast Utilities) 2pp 15784 316 24% Fichs. 50-336, 82/09/29, 8210210587.
- 6210210182 Forwards IE Insp Repts 50-245/82-17 & 50-334/82-19 on 620808-0925. No noncompilance noted STAROSTECKI, R Division of Project & Resident Programs 62/10/07 CDUNGIL.N Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 15746 041 24X Ficha 50-245-82/10/07, 6210210182
- --8210210196 IE Inep Repts 50-245/82-17 & 50-336/82-19 on 820808-0925 he noncompliance noted Major areas inspected.plant & refueling operations, equipment alignments & readiness, radiation protection & physical security SHEDLOSKY. J Y Division of Project & Resident Programs 82/10/05 15pp. 15766.043 24X Fichs 50-245,82/10/07,8210210182
- P Operating license stage documents & correspondence
- 8210280013 Responds to FOIA request for all internal non-public documents, memos, avaiuation rapts & other math dealing w/ nuclear piant operations. Forwards documents listed in App A FELTON, J. M Division of Rules and Records 82/09/17 HCKNNS.D News & Observer 5pp 15860 065 24X Fiche 50-000, 82/09/17, 8210280013
- ---0210280031 Requests technical assistance to review racent events et facilities & to assess eafsty & environ significance STELLO.V Division of Operating Reactore 70/08/03 MALLER.D Division of Sita Safety & Environmental Analysis 2pp 15860 084 24% Fiche, 50-000,82/09/17,8210280013
- 8210010207 Forwards "Haddam Neck Plant Procedura AUP 3 2-22-C RCS Venting of Noncondensible Gases" t "Hillstone Nuclear Power Station RCS Venting Procedura OP 2396." in response to THI Action Plan Item II B.i. "RCB High Point Vente" COUNSIL.W O. Connecticut Yankes Atomic Power Co COUNSIL.W.O Northwast Nuclear Energy Co. (subs of Northeast Utilities) COUNSIL.W.O. Northwast Utilities B2/09/22 CRUTCHFIELD.D Operating Reactors Branch 5 CLARK.R.A Operating Reactors Branch 3. 3pp 15568:048 24X Fichs:50-000.82/09/22, 8210010207
- --8210010214 Revision 2 to "Milietone Nuclear Power Station Unit 2 Plan Procedure OP 2398 RCS Venting Procedure." SCACE, B. E., Northeast Nuclear Energy Co (subs of Northeast Utilitias) 82/08/20. 11pp 15568-062 24X Fiche 50-000, 82/09/22, 8210010207.
- 82:00:03:12 Requests that processing of 8208:12 license amend application has postponed. Revised application changing radiological efficient Tech Specs will be docksted on or about 82:iii5 for both facilities.

 CDUNSIL.W.O. Connecticut Yankse Atomic Power Co COUNSIL.W O Northeast Nuclear Energy Co. (subs of Northeast Utilities).

 CDUNSIL.W.Q. Northeast Utilities 82/09/22. CLARK,R.A. Operating Reactors Branch 3. CRUTCHFIELD.D. Operating Reactors Branch 5. Opp. 18574-047. 24X Fichs 30-000.82/09/22.82:0010312
- 8210050179 Application for amend to License DPR-65 revising Tech Spec 3, 1 2, 2 to require both boric acid tanks & corresponding facility dependent flow paths to be operable in modes in which operablity is required for ECCS.

 CDUNGIL-W.Q. Northeast Nuclear Energy Go. (subs. of Northeast Utilities). CDUNBIL-W.Q. Northeast Utilities, 92/09/24.

 CLARK,R.A. Operating Reactore Branch 3. 2pp. 15603:353 24X Fichs: 50-336,82/09/24,8210050179
- --8210050187 Proposed revision to Tech Spac 3.i.2 R. requiring both toric acid tanks & corresponding facility dependent flow gaths to be operable in modes in which operability is required for ECCS.

 ** Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
 82/07/24. 3pp. 15603:355. 24X Fichs 50-336,82/07/24.8210050179
- 8210040237 Application to amend License DPR-65, revising Tech Specs as boric acid flow path requirements as utilized in reactivity control sys & ECCS. COUNSIL, M. O. Northeast Nuclear Energy Go. (subs. of Northeast Utilities, 82/09/24. CLARK, R. A. Uparating Reactors Branch S. 2pp. 15619:35f. 24X Fiche: 50-036. 82/09/24, 8210060237.

- -- 2210050238 Proposed Tech Specs restoring two boron injection Plaw paths & one associated heat tracing circuit

 Northeast Nuclear Energy Co (subs of Northeast Utilities)
 82/09/24 4pp 15619 303 24X Fichs 50-336,82/09/24,8210060237
- 2210050090 Provides justification for eddl time needed to complete valve mod resulting from plant shielding review.per NAMEO-0737. Item II B 2 Const for mod scheduled to begin in early Jen 1983 Completion expected by Apr. prior to startup COURSIL. 4 O Northwest Nuclear Energy Co (subs of Northwest Utilities 62/09/28 CLARK: A Operating Resectors Brench 3 2pp 15604 239 24X Fiche 50-336.82/09/28.8210050090
- 8210220020 Advises of resolution of seismic qualification of auxiliary Feedwater sys Sys able to perform designed safety-related function after SSE to assure sefe plant shutdown CLARK, R A Operating Reactors Brench 3 82/09/30 COUNSIL, W O Mortheast Nuclear Energy Co (subs of Northeast Utilities) 2pp 15786 309 24X Fiche 50-336, 82/09/30, 8210220020
- --8210220022 Befsty evaluation supporting seismic quelification of Auxiliary feedwater sys * Operating Reactors Branch 3 82/09/30 App 15786 3ii 24X Fichs 50-336.82/09/30,8210220020
- 8210130331 Discusses revision of administrative procedures to incorporate ravised working hour guidalines & provisions for authorizing deviations per 820208 & 0615 requests, TMi Item I A i 3, "Shift Manning" & Generic Ltr 62-12 COUNSIL.W Q, CAGNETYAJJP Northest Nuclear Energy Co (subs of Northest Utilities) COUNSIL.W Q Connecticut Yankes Atomic Power Co 62/10/01 EISEMHUT, D Q Division of Licensing 3pp 15679 127 24% Fiche 50-000,82/10/01,8210130331
- O Inspection reports: iE Bulletins & correspondence
- B210150699 Forwards request for eddl info to complete review of 801104 remponse to IE Bulletin 80-ii, "Mesonry Weil Dasign."
 Remponse expected within 60 days of 1tr receipt
 CLARK.R A Operating Reactors Brench 3 82/09/28 COUNBIL. H.O.
 Connecticut Yantee Atomic Power Co. COUNBIL. H.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 13pp. 15716-100. 24X
 Fiche 50-000.82/09/28,8210150699.
- 8210070352 Ack receipt of 820914 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/82-10 & 50-336/82-14
 MARTIN.T.T Division of Engineering & Technical Programs 82/10/0 COUNSIL.W O Northeast Nuclear Ensrgy Co (subs of Northeast Utilities). 1p 15634 051 24X Fichs 50-245,82/10/05,8210070352. 82/10/05
- -8210070356 Responds to NRC 820813 ltr re violations noted in IE Inep Repts 50-243/82-10 & 50-336/82-14 Corrective actions: controlled documents updated & Unit i control room drawing controlled documents updeted a unit 1 control communication desficiencies corrected afficiencies corrected COUNSIL.H O. Northeast Nuclear Energy Co (subs of Northeast Utilities 62/09/14 WARTIN.T T Division of Engineering & Technical Programs 3pp 15534 052 24X Fiche 50-245, 82/10/05, 8210070332
- 820B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seede," Bvc list encl COBB-L 1 Division of Fuel Facilities, Materiels & Bafeguerds, 82/10/04 Consolidated Edison Co. of New York 66pp 15761:250
- 8210190472 Forwards inservice insp rept of insp conducted during Dec 1981-June 1982 for insp period of Apr 1979-Aug 1982 MROCZKA:E J Northeast Nuclear Energy Co (subse of Northeast Utilities). 82/10/06 HAYNES,R C Region i, Diffice of Director. 1p 15740 182 24% Fiche 50-336,82/10/06:8210190472.
- ---BR10190474 Inservice insp rept on Dec 1981 to June 1982 for period Apr 1979 to Aug 1982 Rept describes exame performed on Class II piping sys. ** Northeast Nuclear Energy Co (subs. of Northeast Utilities). 82/08/13 12pp 15740 183. 24X Fiche 50-336.82/10/06.8210190472.
- 8210210182 Forwards IE Insp Repts 50-245/82-17 k 50-336/82-19 on 820808-0925 No noncompliance noted.

 STARGETECKI.R Division of Froject & Resident Programs. 82/10/07.
 COUNSIL.N 9 Northeast Nuclear Energy Co (aubs of Northeast Utilities) 2pp 15766.041. 24X Fiche.50-245,82/10/07,8210210182
- --8210210194 IE Insp Repts 50-245/82-17 & 50-336/82-19 on 820808-0925.No noncompliance noted Major ereas inspected plant & refueling operations, equipment alignments & readiness, radiation protection & physical security.

 SHEDLOSMY, J. T., LIPINSKI, D.R., ELABBER, T.C. Division of Project & Resident Progrems 82/10/05 15pp. 15766-043. 24X
 Fiche 50-245,82/10/07.8210210182.

- 820B190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Bixel, Recirculation Bys Piping at BMR Plants " Svc list encl DEYQUNG, RC Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810:125 24X Fiche 30-000,82/10/14,8208190238
- 8 Reportable occurrences, LERs & related correspondence
- 8210090016 "Rept on Millstone Unit 2 Loss of 123-Volt DC Ros Event on
- 8210130065 Discusses investigation of relative frequency of Valve overtrevel angmelies that could result in potential centrifugal pump runout exceeding NPBH No sefety problems observed in operation w/HPBi valves menually open IMBROLE V. Reactor Operations Analysis Branch 82/02/22 HICHELBON-CC Director's Office 4pp 15676:268 24% Fiche:50-336.82/02/22.8210130065.
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A IIS THE IN APP A
 FELTON, J H Division of Rules and Records, 82/06/28
 Critical Mase Energy Project 15pp 15727:005, 24X
 Fiche: 50-000, 82/06/28, 8210010008 82/06/28 UDELL.R A
- --8112010310 "Reat on Hillstone Unit 2 Lase of 125-Volt DC Bue Event on 810102 810102 " CHIRAMAL,M , IMBRO,E , QIANELLI,J Director's Office, 26pp 15791 065, 24% Fiche, 50-000,82/06/28,8210010008.
- --8210040430 Summerizes investigation of LER 50-336/81-26 re relative ziuusuusiu Bummeriide investigation of LER 30-336/B1-26 re reletive fraquency of valve overtravel abnormalitiee that could result in potential centrifugal pump runout excessing NPBH INBRO,E.V Director's Office B2/02/22, MICHELBON.C. Director's Office 4pp. 15732 293 24X Fichs 50-d00.82/06/28.8210010008
- 8210010376 Forwards LER 82-036/Q3L-0.
 MROCZKA, E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). HROCZKA, E.J. Northeast Utilities, 82/09/22, HAYNEER, C. Region 1. Office of Director 1p. 13573-051. 24X Fichs 50-336-82/09/22,8210010376
- --8210010385 LER 82-036/03L-0 on B20825, at 100% power level during 210010385 LER 62-034/03L-0 on B20825, at 100% power level during routine packing replacement of charging pump, crack discovered in charging pump block Gause not determined. Pump block to be replaced & failure analysis performed. CRISCIONE, J. L. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). E2/09/22. Region 1, Office of Director. lp. 15573-052, 24% Fiche 50-336,82/09/22,8210010376.
- 8210130228 Forwards LER 82-037/03L-0. ANOLUZZA POWARAS LER BZ-03/703L-0.

 RROCZKA, E J Northeast Nuclear Energy Co (subs. of Northeast Utilities) PROCZKA, E J Northeast Utilities B2/10/01

 NAYNES, R, C Region 1. Office of Director. 1p. 13675:226 2/

 Fiche 30-336, 82/10/01, 8210130228
- --8210130232 LER 82-037/03L-0:on 820902, while at 100% power, querterly survaillance test revealed blocking valve 2-RC-403 would not close Probable cause attributed to fellure to adjust packing for proper valve function.

 STADNICK B Northwast Nuclear Energy Co. (subs. of Northwest Utilities).

 STADNICK B Orthwast Nuclear Energy Co. (subs. of Northwest Utilities).

 STADNICK B Orthwast Nuclear Energy Co. (subs. of Northwest Utilities).

 24X Ficher 50-336, 82/10/01. 8210130228
- 8210210155 Forwards LER 82-039/03L-0 MRGCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MRGCZKA,E J. Northeast Utilities 82/10/13, HAYNEG,R C. Region 1, Office of Director 1p. 15746:075 24X Fiche 50-336,82/10/13,8210210155
- --8210210160 LER 82-039/03L-0. on 820914, packing for operator shaft in primary containment outer air lock door leaked & test pressure could not be asintained Caused by normal cyclic wear. Pecking tightened.

 KOMOSKY.O. Northeast Nuclear Energy Co. (subs of Northeast Utilities). 82/10/13. Region 1, Office of Director, ip. 15766 076. 24X Fichs.50-036, 82/10/13, 8210210155
- 8210220060 Forwards LER 82-038/03L-0. Datailed event analysis encl MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Usilities HROCZKA,E.J. Northeast Utilities 82/10/14, HAYNES,R.C. Region 1. Office of Director 2pp. 15778:197, 24X Fiche: 50-336, 82/10/14,8210220060

1

4, 1

- --B210220064 LER B2-03B/03L-0 on B2091B, survaillance testing indicated activity of 0 99 uCi dose equivalent I-ISI in primary coolant Caused by small number of degraded fuel pins BORCHERT,R Northeast Nuclear Energy Co (subs of Northeast Utilities) B2/10/14 Region i, Office of Director 1p 15778 199 24X Fiche 50-336,82/10/14,8210220060
- 8210260432 Forwards LER 82-040/03L-0 MRDC2KA,E J Northeast Nuclear Energy Co isubs of Northeast Utilities). MRDC2KA,E J Northeast Utilities. 82/10/17 HAYNES, R C. Region 1, Office of Director 1p 15806.291. 24X Fiche: 50-336, 82/10/17, 8210260432
- --B210260441 LER B2-040/03L-0:on S2071B, acceptance critaria not met when containment personnel airlock test performed Caused by leaking gasket on inner airlock door. Qasket replaced & successful leak test performed DUFFY, B Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/17. Ragion is Office of Director ip. 15906 292 24X Fiche: 50-336, 82/10/17, 8210260432

DOCKET 50-038 NORTH ANNA POWER STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8210250208 Forwards "Full-Scale Emergency Exercise North Anna Power Station, Sept 1982, Exercise Manuel," per NRC 820129 1tr.
 LEABBURG, R. H. Virginia Electric & Power Co. 82/08/30 0'REILLY, J. P. Region 2, Office of Director. ip 15791 205 24X Fichs: 50-338, 82/08/30, 8210250208
- --8210250212 "Full-Bcale Emergency Exercise North Anna Power Station Sept 1982: Exercise Manual " * Virginia Electric & Power Co 82/08/27 243pp 15791 206. 24% Fiche. 50-338. 82/08/30. 8210250208
- 8210010125 Forwards revised security training & qualification plans Plans withheld. LEASBURG,R.H Virginia Electric & Power Co. 82/09/17. DENTON.H.R Office of Nuclear Reactor Regulation. Director. VAROA.B.A. Operating Reactors Branch 1. 1p 15566.019 24X Fiche 50-000.82/09/17.8210010125
- 8210130105 Releases public version of emargency response plans FELTON. J. H. Division of Rules and Records 82/09/28. Document Management Branch. 1p 15693-001 24X Fiche: 50-338: 82/09/28: 8210130105.
- --B210130112 Forwards public varsion of emergancy response plans for Louise, Spotsylvania, Carolina, Hanover & Grange Counties, VA LEASBURG, R. H. Virginia Electric & Power Co. B2/09/20 O'REILLY, J. P. Region 2: Office of Director. ip. 15693, 002 24X Fiche, 50-338, 82/09/28, 9210130105
- --8210130114 Public version of facility emergency response planconsisting of radiological emergency response plans for Louisa.Spotsylvania.Caroline.Hanover & Orange Counties.VA. * Virginia Electric & Power Co. 82/08/30. 432pp. 15493-004 24X Fiche.50-338.82/09/28.8210130105.
- 8210050076 Submits correction to 820628 Revision 3 to response to NUREO-0737. Item I D 2, "Safety Parameter Display Sys "Correction should be included in schedular exceptions pertaining to emergency response capabilities.

 LEASBURG, R. H. Virginia Electric & Power Co 82/09/29. DENTON, H. R Office of Nuclear Reactor Regulation, Director. EISENHUT, D. O. Division of Licensing. ip. 13603;185 24X Fiche. 50-000;82/09/29, 8210050076
- 8210050335 Forwards revised pages to App R post-shutdown review. Revised pages concern results of study which calculated time available after stuck open power operated relief valve event before unsafe condition reached. LEASBUROR, H. Virginia Electric & Power Co. B2/09/30. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 3pp 15610:095, 24X Fichel 30-339, 82/09/30, 8210050335.
- 8210220454 Forwards IE Insp Repts 50-338/82-33 & 50-339/82-33 on 820918 No noncompliance noted, DANCE.H. C. Division of Project & Resident Programs, 82/10/04. LEASBURG.R. H. Virginia Electric & Power Co. 2pp. 15779;135 24X Fichs. 50-338, 82/10/04, 8210220454.
- --8210220461 IE Insp Repts 50-338/82-33 & 50-339/82-33 on 820918.No noncompliance noted. Major areas inspected, full-scale radiological exercise.

 HUFFHAN 0.N., MARSTON.R.R., JENKINS.G.R., Division of Engineering & Technical Programs. 82/09/30, 11pp. 15779:137 24X Fiche. 50-338,82/10/04.8210220454

O Adjudicatory correspondence

- 8210260348 Patition of Concerned Citizens of Louisa County for leave to intervane & request for hearing re proposed license amend to suthorize receipt & storage of Surry spent reactor fuel at North Anna Certificate of Svc encl DOVGHERTY.J B Dougharty, J B 82/10/22 Commissioners 8pp 15803 180 24% Fiche 50-338.82/10/22,8210260348
- 8210260355 Patition of Concerned Citizens of Louisa County for lawe to intervene & request for hearing re-proposed license amend authorizing increase in capacity of spent fuel pool Natice of appearance & Certificate of Svc ancl DOUOHERTY,J B. Duugharty, J B. 82/10/22 Commissioners 7pp 15802,350 24x Fiche 50-338,82/10/22,8210260335
- 8210260367 Petition of County of Louisa, VA & Board of Supervisors of County of Louisa, VA to intervene re-proposed license amend to permit receipt & storage of 300 spent fuel assemblies from Surry Certificate of Svc encl.

 COLEMAN, J. H. Louisa County, VA COLEMAN, J. M. Beveridge, Fairbants, & Diamond 82/10/22 Commissioners 13pp. 15803.111 24X Fiche, 50-338, 82/10/22, 8210260367
- 8210260373 Petition to intervene of County of Louisa.VA & Board of Supervisors of County of Louisa.VA re proposed license anend to expand fuel storage capacity Certificate of Svc encl COLEMAN.J M Louisa County. VA COLEMAN.J M Beveridge.Fairbants. & Diamond 82/10/22 Commissioners 15pp 15803 143 24X Ficha 50-338.82/10/22.8210260373
- B210280238 Notice of ASLS constitution, BJ Wolfercheirman & J R]ins & OA Ferguson, members LAZO,R M Atomic Befety and Licensing Board Panel B2/10/26 Zyp 15837:060 24X Fichs:50-338, B2/10/26, B210280238
- 8210280300 Notice of ASLB constitution, BJ Wolfercheirmen & J Kline & OA Ferguson: Members LAZO, RM Atomic Bafety and Licensing Board Panel, 82/10/26, 25p 15837 281, 24X Fiche, 50-338, 82/10/26, 9210280300.

P Operating license stage documents & correspondence

- 8208090114 Application for amend to Licenses NPF-4 & NPF-7, authorizing receipt & storage of 500 spent fuel assemblies from Surry Units 1 & 2 Rept entitled "Spent Fuel Btorage" encl LEASBURG.R.H. Virginia Electric & Power Co. 82/07/13, DENTON.N R Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3, 2pg 15367,244, 24X Fiche: 50-338,82/07/13,8208090114.
- --B210010246 Proposed Yech Specs allowing receipt & storage of 500 spent fuel assemblies from Burry # Virginia Electric & Power Co. B2/07/i3. 4pp 15569.246 24r Fichet 50-338, 82/07/i3, 82080901i4.
- --8210010247 "Spent Fuel Storage"

 * Virginia Electric & Power Co 82/07/31. 86pp 18569 251 24r
 Fiche. 50-338, 82/07/13, 8208090114.
- 8210040277 Advises of plans for const of new 230 kV transmission lins to connect North Anna power station to Louisa substation No Tech Bpec or ETB change required.

 LEABBURGOR, H. Virginia Eisetric & Power Co 82/09/27 DENTON:B R Office of Nuclear Reactor Regulation. Director CLARK.R.A Operating Reactors Branch 3. 2pp. 15591.204 24X

 Fiche. 50-338: 82/09/27.8210040277
- --B210040285 Responds to util 761109 ltr informing that 740102 k 76669 ltrs did not constitute application for const of 230 kV transmission line from North Anna to Louiss Bubstation Ref to line has been removed from FEB addendum YOUNOBLOOD, B. J. Environmental Projects Branch 2 76/11/26 PROPFITT, N. L. Virginia Electric & Power Co. 5pp 15591.206 241 Fiche: 30-338, 82/09/27, 8210040277.
- --B210040270 Advises that util 740102 & 760608 ltrs to NRC do not constitute application for const of 230 kV transmission line from North Anna to Louisa. Application: If required, will be filed prior to OL issuance for Unit 2.

 PROPERITY. M. L. Vinginia Electric & Power Co 76/11/09.

 RUBCHE. B. C. Office of Nuclear Reactor Regulation. Director YOUNDBLOOD. E. J. Environmental Projects Branch 2. ip. 15591:212

 24X Fiche: 50-338, 82/09/27, 8210040277.
- --8210040297 Forwards add1 info & answers to questions in NRC 750970 Hr re 230 kV transmission line.
 PROFFITT.W.L. Virginia Electric & Power Co. 76/08/30,
 RUSCHE.B.C. Office of Nuclear Reactor Regulation. Director YOUNGBLOOD.B.J. Environmental Projects Branch 2. 6pp. 15591 213
 24X Fiche: 50-338,82/09/27,8210040277.

- --8210040301 "Mgt of Transmission Line Rights of Way "

 * Enviro Audits 76/07/31 77pp 15591 219 24X
 Fichs 80-338,82/09/27,8210040277
- --8210040307 Requests addl info by 740830 to complete assessment of environ impact of 230 kV transmission line
 YOUNOELODD B J Environmental Projects Branch 2. 76/08/20
 PROFFITT, N L Virginia Electric & Power Co 2pp 15591 296 24:
 Fichs 50-338,82/09/27,8210040277
- --8210040315 Forwards one oversize topographical map & application to VA State Corp Commission for approval & certification of North Anna to Louisa transmission line in response to NRC 760630 request Aperture card is available in PRR PRDFFITT.W L Virginia Electric & Power Co 76/07/06 RUSCHE.B C Office of Nuclear Reactor Regulation, Director 15591.278 24X Fiche 50-338.82/09/27.8210040277
- ~-8210040320 Advises of need for NRC evaluation of environ impact of const & operation of North Anna ~ Gordonsville 230 kV transmission line, per util 740102 & 760608 ltrs. Addl info needed by 760707
 YDUNOBLODD B J Environmental Projects Branch 2 76/06/30
 PROFFITT, H L. Virginia Electric & Power Co 2pp 15591 327 24X
 Fiche 50~338,82/09/27,8210040277
- --B21Q040325 Advises that proposed 230 kV transmission line between North Anna & Louiss need not be evaluated in amend to environ rept for North Anna 1 & 2 Line is not part of North Anna utilization facility
 RAGONS. B Virginia Electric & Power Co 74/01/02 MULLER, D R
 Atomic Energy Commission 2pp 15591 329 24X
 Fishs 50-338,82/09/27.8210040277
- 8210120215 Application to amend Licenses NPF-4 & NPF-7, revising Tech Specs re staff working hours Request does not involve Unravisued safety question per 100FR50 59 LFASBURG, R H Virginie Electric & Power Co 82/10/01 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 1p. 15652:150 24X Fiche 50-33B, 82/10/01, 8210120215
- --B210120225 Proposed Tach Bpecs revising staff working hours Provision does not permit shift crew position to be unmanned upon shift change due to late on absent oncoming shift crewman.

 * Virginia Electric & Power Co 82/10/01 4pp 15652.151. R4X Fiche 50-338,82/10/01,8210120215
- 8210120265 Informs of implementation status of NUREQ-0737, Item 11 B 2, "Plant Shielding" per NRC 820517 request All required work completed
 LEASBURG, R H Virginia Electric & Power Co 82/10/01, DENTON, H R Office of Nuclear Reactor Regulation, Director E18ENHUT, D 9
 Division of Licensing 2pp 15651 230 24X Fiche 50-000, 82/10/01, 82/10/20265,
- 8210120277 Forwards errate to Topical Rept VEP-FRD-33, "VEPCO Reactor Core Thermai-Hydraulic Analysis Using COBRA IIIc/HIT Computer Code "
 LEASBURG, R H. Virginia Elactric & Power Co. 82/10/04 DENTON:H R. Office of Nuclear Reactor Regulation. Director EISENHUT.D Q. Division of Licensing 2pp 15652 330, 24X Fiche.50-000.82/10/04, 8210120297
- --8210120305 Errata to "VEPCO Reactor Core Thermal Hydraulic Analysis Using COBRA-111c/MIT Computer Code "

 * Virginia Electric & Power Co VEP-FRD-33 ERR. 82/10/04 lp. 15652 332 24x Fiche 50-000, 82/10/04.8210120297
- 9210290042 Forwards safety evaluation & technical evaluation rept re analysis of main steam line break w/continued feedwater addition Analysis acceptable W/o technical evaluation.
 GLARK,R A Derating Reactors Branch 3 82/10/04. LEASBURG,R H Virginia Electric & Power Co ip. 19877,271 24X Pichs 30-338,82/10/04,8210290042.
- --8210270071 Safety svaluation re mein steem line break w/continued faeduater addition Conteinment overpressurfaction will not result & auxiliary feedwater pumps can function during event.

 # Office of Nuclear Reactor Regulation, Director 82/10/04, App 15877 272 24% Fiche, 30-238, 82/10/04, 8210270042
- 6210290414 Forwards Amend 42 to License NPF-4; safety evaluation & notice of issuance t availability Amend revises average RCS temp at currently licensed thermal power level. ENGLE; L.R. Operating Reactors Branch 3 82/10/04 LEASBURG; R.H. Virginia Electric & Power Co. 4pp 15863; 255, 24X Fiche. 50-338, 92/10/04, 8210290414.

- --8210290416 Amend 42 to License NPF-4, revising avarage RCB temp from 580 3 F to 582 8 F at current licensed thermal power level of 2,785 MW CLARK, R A. Operating Reactors Branch 3. 82/10/04 9pp 15863 259. 24X Fiche 50-338,82/10/04,8210290414
- --8210290418 Safety evaluation supporting Amend 42 to License NPF-4

 * Office of Nuclear Reactor Regulation, Director 82/10/04 3pp.
 15863 268 24% Fiche 50-338:82/10/04,8210290414.
- --8210270421 Notice of issuance & availability of Amend 42 to License NPF-4 CLARK,R A. Operating Reactors Branch 3 B2/10/04 2pp 15863:271 24% Fiche 50-338,82/10/04,8210270414
- 8210270238 Forwards documents providing details of exams & evaluations performed by util & Westinghouse on failure of guide tube support pins, main loop isolation valve guide & RCS thermal sleaves.

 LEASBURO, R H Virginia Electric & Power Co 82/10/12 DENTON, H. R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 7pp i5829 180 24% Fiche 50-338, 82/10/12.8810270258
- --8210270260 "North Anna Unit 1 Loose Thermal Bleeve Safety Evaluation."

 Descriptions of impact of postulated blockags on 1981 model
 LOCA analysis & operator awareness surveillance program
 sncl.

 Westinghouse Electric Corp. 28630 1 82/09/30 44pp.
 15829-187 24X Fiche 50-338,82/10/12.8210270258
- 821022001i Gubmits addl info to 8207i3 request for amend to Licenses NPF-4 & NPF-7, Number of storage locations in nautron absorber spent fuel storage rack changed to 1.737 Fuel pool temps changed in Table 7 i
 LEASBURGER.H Virginia Electric & Power Co 82/10/18 DENTON.H R Office of Nuclear Reactor Regulation, Director. CLARKER A Operating Reactors Branch 3. 3pp 15778 211 24% Fichs; 50-338, 82/10/18, 8210220011
- 8210220178 Comments on systemation of significant dynamic loads in determining capacity of slings used per NUREO-0612 Rating can be safely expressed in terms of max static load LEABBURGOR H Virginia Electric & Power Co. 92/10/18 DENTON, H. R Office of Nuclear Reactor Regulation, Director. EIBENHUT, D Q. Division of Licensing. 2pp 15777:293 24X Fiche: 30-000:82/10/18, 9210/20178
- 8210260133 Forwards revised Table 7-1 to "Bummary of Info in Support of Increasing Spent Fuel Storage Capacity at North Anna Units 1 & 2 " Rept originally submitted w/820820 request for amend to Licenees NFF-4 & NPF-7 to replace storage racks LEASBURO.R H Virginia Electric & Power Go 62/10/21 DENTON.H R. Office of Nuclear Reactor Regulation, Director. CLARK.R A Operating Reactors Branch 3 2pp. 15799 102 24X Fiche: 50-338, 82/10/21,8210260133.
- --B210260136 Rsvised Table 7-1 to "Bummary of Info in Support of Increasing Spant Fuel Storage Capacity at North Anna Units i & 2."

 + Virginia Electric & Power Co. 82/10/21, ip. 15799-104 24X Fiche: 50-338, 82/10/21, 8210260133
- 8210270160 Advises that work re removal of RCB flow splitter plates completed. Ltrs from Westinghouse supporting continued operation of facility w/splitter plates removed and LEASBURGAR M. Virginia Electric & Power Ca. 92/10/25. DENTON, H.R Office of Nuclear Reactor Regulation, Director. CLARK, R A. Operating Reactors Breach 3. 74pp. 13830, 044 24X Fiche: 50-338, 82/10/25, 8210270160.
- 8210270204 Forwards Westinghouse "North Anna Unit 1 Steam Generatur Impacted Tube Ends Recovery Evaluation," photographs of steam generator A & C demaged tube sheets & summeries of end damage repairs & reactor coolant pump failure LEASBURG, R. H. Virginia Electric & Power Co. 82/10/26 DENTON, H R. Operating Reactors Branch 3. 2pp. 15822-268. 24X Fiche: 50-338, 82/10/26, 8210270204.
- --8210270208 "North Anna Unit 1 Steam Generator Impacted Tube Ends Recovery Evaluation" PAXBON,E., KELLER,H T., CHENO,W.W. Westinghouse Electric Corp. AEA-FRPE-282 82/10/31 68pp 15822:270 24X Fiche:50-338,82/10/26,8210270204.

1

ì

H

Q Inspection reports, IE Bulletins & correspondence

- 8210220200 Responds to NRC ltr re violations noted in IE Inep Repte 50-938/82-08 & 50-339/82-08 Corrective actions health physics technician counseled re correct procedures for entering high rediation area LEABURGOR H Virginia Electric & Power Co 82/07/29 O'REILLY, J. P. Region 2, Office of Director 5pp 13777:265. 24X Fiche: 50-338.82/07/29.8210220200
- 8210070007 Responds to FOIA request for eight categories of records restam generators & steam turbines App A documents provided in R Udell FOIA Request 91-313 Forwards documents listed in App B FELTON, J. H Division of Rules and Records. 82/08/10 LONO, D J Winthrop. Stimson, Putnam & Roberts. 9pp 15645:063 24X Fiche 50-000, 82/08/10.8210070007
- --8210070137 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licaness.

 IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VAROA:6. Operating Reactors Branch 1. 5pp 13645.131. 24X Fiche 50-000.82/08/10.8210070007
- 8210010221 Forwards IE Insp Repts 50-339/82-18 & 50-339/82-18 pn 820709-0805. No noncompliance noted DANCE-R.C. Division of Project & Resident Programs. 82/08/31 LEASBURO.R.H. Virginia Electric & Power Co 2pp. 15567 338 24X Fichs 50-338, 82/08/31.8210010221.
- --8210010225 IE Insp Repts 50-938/82-18 & 50-339/82-18 on 820709-0805 No noncompliance noted, Major areas inspected LERs refueling & outage activities, surveyllance & maint activities, operations & followup on significant events.

 OBMNSON.D F . SHYMLOCK.M B . JULIAN.C. Division of Project & Resident Programs 82/08/31 ipp, 155567:340 24X
 Fiche 50-338,82/08/31.8210010221
- 8210010300 Forwards IE Insp Repts 50-338/82-28 & 50-339/82-28 on 820816-19 No noncompliance noted.

 DANCE H C Division of Project & Resident Programs 82/09/03, LEASBURG, R H. Virginia Electric & Power Co. 29p 15568-317 24X Fichs 50-338, 82/09/03, 8210010300.
- --8210010314 IE Insp Repts 50-838/82-28 & 50-339/82-28 on 820816-19.No noncompliance noted Major areas inspected: thermal sleave removal, reactor coolant loop stop valves, tap screw fractures & broken control rad guide tubs support pins YORK-U-W BLAKE-J-J Division of Engineering & Technical Programs 82/09/02 opp 15568.319, 24X Fiche:50-338.82/09/03.8210010300
- 6210180187 Forwards IE Insp Repts 50-338/82-30 & 50-339/82-30 on 820831-0903 No noncompliance noted, 04000 Programs, 82/09/23 UANCE,H C. Division of Project & Resident Programs, 82/09/23 LEASBURG,R.H Virginia Electric & Power Co 2pp. 15707-262 24X Fichs 50-338,82/09/23,8210150187.
- --8210150174 IE Inep Repts 50-038/82-00 & 50-039/82-00 on 820831-0703. No noncompliance hoted Major areas inspected generator step-up transformer failure on 820822 & licensee recommendations & inspector follows items.

 RUFFIA B : CONLON.T.E. Division of Engineering & Technical Programs. 82/09/17. App. 15707.264. 24X Fiche 50-038,82/09/23,8210150187.
- 8210220454 Forwards IE Insp Regts 50-338/82-33 & 50-339/82-33 on 820918. No noncompliance noted.

 DANCE,H.C. Division of Project & Resident Programs. 82/10/04. LEASBURGOR. H. Virginia Electric & Power Co 2pp 15779:135. 24X Fichs. 50-338. 82/10/04. 9210220454.
- --8210220461 IE Insp Regts 50-338/82-33 k 50-339/82-33 on B20918, No noncompliance noted Major areas inspected full-ecale radiological exercise. HAFFMAN, O, N. HARBTON, R.R., JENKING, C.R. Division of Engineering & Tschnical Programs, 82/09/30, 11pp, 15779: 137, 24X Fiche, 50-338, 82/10/04, 8210220454
- SROB190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislooged I-125 Implant Seeds." Syc list enct. COBD.L.I. Division of Fuel Facilities, Hetsrials & Gafeguerds SR/10/06 Consolidated Edison Co. of New York. 66pp. 15741-250. 24x Fichs. 50-000, 82/10/06, 8208190233.
- 8208190208 IE Bulletin 82-03, "Stress Corrosion Cracking in Thirt-Hali.Large-Diameter: Stainless Steel Rectroviation Sysfiping at 84R Plants," Syc. light encl.
 DEYOUNG, C. Director's Office, Office of Inspection and
 Enforcement, 82/10/14, Consolidated Edison Co. of New York
 115pp 15810; 125. 24X Fiche; 50-000, 82/10/14, 8208190238.

- 8 Reportable occurrences. LERs & related correspondence
- 8009240202 Forwards analysis of 800523 trip & subsequent safety injection at facility Some operating nuclear plants lack controls restricting starting of electrical motors while emergancy diseal generator is undergoing load tests HICKELSON.C Director's Office 80/08/20 JORDAN.E L Division ca Reactor Operations Inspections. 3pp 13670 018 24X Fichs 50-338,80/08/20,8009240202
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor examts & sefety problems, Forwards documents listed in App A FELTON J. M. Division of Rules and Records 82/06/28 UDELL, R. A Critical Mase Energy Project 15pp 15727 005 24X Fiche 50-000,82/06/28,8210010008
- --BiiiiBOOO1 Recommends comprehensive assessment of plant operating conditions to determine specific predetermined time related sequences of occurrence to energency buses SRP should be revised re design features.

 ASHE-F Director's Office 81/10/16 MICHELSON, C Director's Office 4pp. 15731:049 24X Fiche: 50-000:82/06/28.8210010088
- 8210010140 Forwards LER 82-059/09L-0 CARTWRIGHT N Virginia Electric & Power Co 82/09/22 O'REILLY, J.P Region 2, Office of Director ip 15565 346 24X Fiche: 50-038, 82/09/22, 8210010140
- --0210010145 LER 62-038/03L-0. on 820826, manipulator crane erea monitor RM-RHS-162 failed to mast acceptance criteria of pariodic calibr & declared inoparable Caused by instrument drift greater than 3X response requirement Assembly replaced CARTHRIOHT, M. R. Virginia Eivetric & Power Co. 62/09/22 2, Office of Director 3pp. 15565-347 24X Fiche 50-338, 82/09/22 8210010140
- 8210010163 Forwards LER 82-059/03L-0 CARTURIOHTH R. Virginia Electric & Power Co 82/09/22 U'REILLY.J P. Region 2. Office of Director ip. 15567 274 24x Fiche. 80-338. 82/09/22. 8210010163
- --8210010168 LER 82-059/03L-0. on 820827, ventilation vent 8 gasedus radiation detector response found to exceed calibr test acceptance criteria Causad by gradual deterioration of shatomultipliar tube & prasmpliffer. Parts replaced CARTHRIGHT, W R Virginia Electric & Power Co. 82/09/22 Region 2.0 Office of Director 2pp 15567-275 24% Fiche 50-338, 82/09/22.8210010163
- 8210010207 Forwards LER 82-05D/0GL-0. CARTHRIOHT. H. R. Virginis Electric & Power Co. 82/09/22 O'REILLY, J. P. Region 2. Office of Director ip 13567 334. 24X Fiche 50-338.82/09/22.8210010209.
- --9210010219 LER 82-050/03L-0'on 820826, fire doors A80-1 & A80-2 between Units 1 & 2 rod control rooms & susiliary bldg & firs doors A57-1 & A57-2 between Units 1 & 2 cable vault rooms & susiliary bldg found not in periodic testing program. CARTHRIGHT. H.R. Virginia Electric & Power Co 82/09/22, Region 2, Office of Director. 1p. 15567-335 24X Fichs 50-338,82/09/22,8210010209.
- 82102R0227 Forwards LER 82-057/03L-0. CARTHRICHT.W.R. Virginia Electric & Power Co 82/10/07 O'REILLY.J.P. Ragion 2. Office of Director. ip 15775.126 24X Fichs: 50-338.82/10/07.8210220227.
- --8210220234 LER 82-057/03L-0. on 820910, setpoint for turbing impulse pressure comparator in instrument procedure found incorrect. Caused by typographical error during procedure revision. Procedure corrected & tard recalibr CARTHRIOHTH M.R. Virginia Electric & Power Co. 82/10/07. Region 2. Qffice of Director Spp. 13775-127. 24X Fiche.50-338, 82/10/07,8210220227
- 8210190264 Forwards LER 82-062/03L-0 CARTHRIOHT, M. R. Virginia Electric & Power Co. 62/10/12. O'REILLY, J. P. Region 2. Office of Director. 1p. 15742:192 24X Fiche: 50-338:82/10/12:8210190264.
- --B210170270 LER B2-062/03L-0; on B20917, cold leg injection line check valve found w/five corroded balts. Caused by small lesk at body to bonnet gasket. Btude & bonnet gasket replaced. CARTHRIGHT. H. R. Virginia Electric & Power Co. B2/10/12. Region 2. Office of Director. 2pp. 15742:193 24X Fiche: 50-038. B2/10/12.8210190264.
- 8210190329 Forwards LER 82-061/03L-0. CARTHRIGHT: M.R. Virginia Electric & Power Co. 82/10/12. 0/REILLY.J.F. Region 2: Office of Director. 1p 15742:061, 24% Fiche: 50-338: 82/10/12:8210190329.

- e210190337 LER 82-061/03L-0 on 820917, during chemistry log review, specific activity of primary coolant exceeded Tech Specs Causad by asgration of 1-131 through pinhole leeks in fuel cladding Specific activity returned to acceptable limits CARTHRIGHT. WR. Virginia Electric & Power Co 82/10/12 Ragion 2. Office of Director 4pp 15742 062 24X Fichs 50-338, 82/10/12,8210190329
- 110290337 Forwards LER 82-065/03L-0
 CARTHRIGHTNUR Virginia Electric & Powar Co 82/10/13
 D'AE-ZLLY, J P. Region 2. Office of Director 1p 15853 029. 24X
 Fich #: 50-338, 82/10/13, 8210290337
- 8210290347 LER 82-065/03L-0 on 820919; routine receibtr of pressurizer level transmitter LT-1-46i, revealed transmitter out of talibr Coused by inetromant drift Transmitter replaced. New transmitter calibr euccassfully CARTWRIGHT, W.R. Virginia Electric & Power Co. 82/10/13 Ragion 2. Office of Director ip 15853 030 24X Fiche 50-338, 82/10/13, 82:0290337
- 210280290 Forwards LER 82-063/03L-0 CARTHRIGHT H R Virginia Electric & Power Co 82/10/19 D'REILLY, J.P. Region 2, Office of Director ip 15803, 215 24X Fiche 50-338, 82/10/19, 8210260290
- -8210250293 LER 82-063/03L-0 on 820924, ambient temp eighal conditioner & control room delta temp racorder rasponsas found to exceed calltr procedura acceptance criteria. Gaused by instrument drift instruments recalltr CARTHARIGHT, W R Virginia Electric & Powar Co 82/10/19 Region 2. Office of Director 3pp 15803 216 24X Fiche 50-338, 82/10/19.8210260270
- OCKET 50-339 NORTH ANNA POWER STATION, UNIT 2
- Security, medical, emergancy & fire protection plane
- '210250208 Forwarde "Full-Scala Emergancy Exarcise, North Anna Power Station.Sept 1982.Exarcise Menual," per NRC 820129 ltr LEASBURG.R H Virginia Elactric & Power Go 82/08/30 O'REILLY.J P Region 2. Office of Director ip 15791.205 24X Ficha 50-338, 82/08/30, 8210250208
- --8210250212 "Full-Stale Emergency Exercise, North Anna Power Station, Sept 1982:Exarcise Manual " # Virginia Electric & Power Co 82/08/27 243pp. 13791: 206 24X Fiche 50-338,82/08/30,8210250209
- B2100:0125 Forwards reviewd security training & qualification plans Plans withheld.
 LEASBURG, R # Virginia Electric & Power Co. 82/09/17, DENTON, H.R. Office of Nuclear Reactor Regulation, Director ip 15366:013, 24X Fiche 30-000, 82/09/17, 9210010125
- 8210130105 Releases public vereion of emergency response plans.
 FELTON, J M Division of Rules and Racords 82/09/28 Document
 Management Branch ip 15693 001 24X Fichs. 50-338, 82/09/28,
 8210130105
- --8210130112 Forwards public version of amergancy rasponse plane for Louisa. Spotsylvania. Cerolina, Hanover & Orange Counties, VA LEASBURO, R. H. Virginia Elactric & Powar Co. 82/09/20 O'REILLY, J. P. Region 2, Office of Director. Ip. 15693'002. 24% Fiche: 50-338, 82/09/28, 8210130105.
- --B210:30:14 Public version of facility amargency response plan, consisting of radiological amargency response plans for Louise. Bpotsylvania: Cerolina; Hanovar & Oranga Counties, VA w Virginia Electric & Power Co B2/08/30 632pp 15693: 004, 24% Fiche: 50-338, 82/09/28, 8210130105.
- 8210050074 Submits corraction to 820428 Revision 3 to response to NUREQ-0737, Item I D 2, "Safety Parameter Display Sys," Correction should be included in schedular acceptione gertaining to emergency response capabilities.

 LEABBURG, R H Virginia Electric & Power Co. 82/09/29, DENTON, H.R Office of Nuclear Reactor Regulation, Director. 1p. 24X Fiche: 50-000, 82/09/29, 8210050076.
- B210050335 Forwards revised pages to App R post-shutdown review Revised pages concern results of study which reliculated time awailable after stuck open power operated relief valve event before unsafe condition reached LEABBURGAR H. Virginia Electric & Power Co. 82/09/30, DENTON:H R. Opfice of Nuclear Reactor Regulation, Director, CLARK, R. A. Operating Reactors Branch 3 3pp. 15610.093, 24X Fichs 50-338, 82/09/30, 8210050335

- 8210220454 Forwards IE Insp Rapts 50-338/82-33 t 50-339/82-33 on 820918 No noncompliance noted DANCE: N C. Division of Project & Rasident Programs 82/10/04 LEASBURG: R W. Virginia Elactric & Power Co. Rpp. 15779.135, 24X Fiche: 50-338,62/10/04.8210220454
- --8210220461 IE lnsp Repte 50-338/82-33 & 50-339/82-33 on 820918 No noncompliance noted Mejor areas inspected full-scala resiological exercise. HUFFMAN, 0 N. Division of Engineering & Tachnical Programs 82/09/30. 11pp. 13779.137. 24X Fiche.50-338.82/10/04,8210220454.
- O Adjudicatory correspondance
- 8210260348 Petition of Contarned Citizens of Louisa County for leave to intervene & request for hearing re proposed license amend to authorize receipt & storage of Surry spent reactor fuel at North Anna Certificate of Siv encl DOUGHERTY, J B Dougherty, J B 82/10/22 Commissioners Spp. 13803 180 24X Ficha 30-338,82/10/22,8210260348.
- 82:0260355 Petition of Concarned Citizans of Louisa County for leave to intervene & request for hearing re proposed licansa amand authorising increase in capacity of spent fuel pool Notice of appearance & Ceptificate of Svc ancl. DOUGHERTY. J. B. Dougharty, J. B. 82/10/22 Commissioners. 7pp 15802 350 24X Ficha 50-336.82/10/22,8210260355.
- 8210260367 Petition of County of Louisa. VA & Board of Supervisors of County of Louisa. VA to intervent re proposed license amend to patriff receipt & storage of 300 spant fuel assemblies from Surry Certificate of Svc wnc1
 COLEMAN. J M Louisa County. VA COLEMAN. J M Baveridge, Fairbanks, & Dismond 82/10/22 Commissionere 13pp. 15803.111. 24%
 Fiche. 50-338, 82/10/22, 8210260367.
- 8210260373 Petition to intervene of County of Louisa, VA & Board of Supervisors of County of Louisa, VA re proposed license amend to aspend fuel storage capacity Certificate of Suc encl.

 COLEMAN, J. M. Louisa County, VA COLEMAN, J. M. Baveridge, Fairbanks, & Diamond. 82/10/22, Commissioners. 15pp 15803, 143, 24X Fiche: 50-338, 82/10/22, 8210260373.
- 8210280238 Notice of ASLB constitution BJ Wolfe, chairman & J Kline & GA Ferguson, members LAZO, R. M. Atomic Safaty and Licensing Board Panel, 82/10/26 2pp. 13827 OGO 24% Ficha 50-338, 92/10/26, 8210280238
- S210280300 Notice of ASLB constitution SJ Wolfe, chairman & J Kline & GA Ferguson, members.
 LAZO,R.M Atomic Safety and Licenting Board Panel. 82/10/26. 2pp. 18837:291. 24X Fiche 50-338.82/10/26.8210280300
- P. Operating license stage documents & correspondence
- 8210010008 Responde to FOIA request for 19 categories of documents ranuclear reactor events & safety problems. Forwards documents listed in App A
 FELTON. J M Division of Rules and Records. 82/06/28 UDELL.R.A.
 Critical Mass Energy Project. 15pp. 15727 005 24x
 Fichs. 50-000, 82/06/28.8210010008
- --B008050265 Discusses addl required into to better define potential for cracking in reactor yessel nozzlas.

 NGONAN, V. B Assistant Director for Materials & Qualifications Engineering 80/05/05. TEDESCO, R. L. Assistant Director for Licensing. 2pp. 13727:176. 24x Fiche. 50-000.82/06/28,8210010008.
- 8208090114 Application for amend to Licenses NPF-4 & NPF-7, authorizing receipt & storage of 300 spent fuel assemblies from Surry Units 1 & 2. Rapt entitled "Spent Fuel Storage" encl. LEASBURG.R.H. Virginia Electric & Fouer Cb 82/07/13, DENTON, H R, Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Dereting Reactors Branch 3. 2pp 15569:244, 24% Fiche: 50-338, 82/07/13, 8208090114.
- --B210010246 Proposed Tech Specs allowing receipt & storage of 500 spent fuel assemblies from Surry

 * Virginia Electric & Power Co 82/07/13 App. 15569,246. 24x Fich: 50-338.82/07/13.8208090114.
- --8210010247 "Spent Fuel Storage,"
 4 Virginia Electric & Powar Co. 82/07/21, 84pp. 15549,251, 24x
 Fishe 50-338/82/07/13/8208090114.

- S210010103 Forwards application for amend to License NPF-7, to complete License Conditions 2 C(15)(h)(4) & 2 C(h)(15)(2) by end of second refueling outage LEABBURG.R H Virginia Electric & Power Co 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3. 3pp 15367.185 24X Fiche 50-339, 82/09/27, 8210010103
- --8210010107 Application for amend to License NPF-7. changing completion dates of License Conditions 2 C(15)(h)(4) & 2 C(h)(15)(2) to end of second refueling outage * Virginie Electric & Power Co 82/09/27 App 15547.189 24X Fiche-50-339,82/09/27,8210010103
- 8210040277 Advises of plans for const of new 230 kV transmission line to connect North Anna power station to Louise substation NO Tech Spec or ETS change required LEASBURGOR H Virginie Electric & Power Co 82/09/27 DENTON, H R Office of Nucleer Reactor Regulation, Director CLARK. R A Operating Reactors Brench 3 2pp 15591 204 24X Fiche 50-038, 82/09/27, 8210040277
- --8210040285 Responds to util 761107 ltr informing that 740102 & 760008 ltrs did not constitute application for const of 230 ½V transmission line from North Anna to Louisa Bubstation Ref to line has been removed from FEB eddendum YOUNOBLOOD: 8 J. Environmental Projects Branch 2 76/11/26 PROFFITT. W. L. Virginia Electric & Power Co Spp 15591.206 24X Fichs 50-338,82/09/27,8210040277
- --B210040270 Advises that util 740102 & 740408 ltrs to NRC do not constitute application for const of 230 kV transmission line from North Anna to Louisa Application, if required, will be filed prior to DL issuance for Unit 2
 PROFFITT, W L, Virginia Electric & Power Co 76/11/09, RUBCHE, B C Office of Nuclear Reactor Regulation, Director YOUNDELOOD, B J Environmental Projects Branch 2 ip 15591 212 24X Fiche. 50-339, 82/09/27, 8210040277
- --B210040297 Forwards addi info & answers to questions in NRC 760820 ltr re 230 kV transmission line PROFFITT, W L Virginia Electric & Power Co. 76/08/30 RUSCHE, B C. Office of Nuclear Reactor Regulation, Director YUNNOBLOOD, B J Environmental Projects Branch 2 6pp 15591.243 24X Fiche 50-338.82/09/27.8210040277
- --8210040301 "Mgt of Transmission Line Rights of Way " Enviro Audits, 75/07/31. 77gp 15391:219 24X Fiths 50-338,82/09/27,821004027.
- --8210040307 Requests add1 info by 760830 to complete assessment of environ impect of 230 iV transmission line. YOUNGELOOD, B J Environmental Projects Branch 2 76/08/20 PROFFITT.W L Virginia Electric & Power Co 2pp 15591.296 24X Fiche.50-338,82/09/27.8210040277.
- --B210040315 Forwards one oversize topogrephical map & application to VA State Corp Commission for approval & certification of North Anna to Louisa transmission line in response to NRC 760630 request Aperture card is available in PDR.
 PROFFITT, W L. Virginia Electric & Power Co. 76/07/06.
 RUSCHE, B C. @ffice of Nuclear Reactor Reguletion, Director 29pp. 15591.298 24X Fiche: 50-339, 82/09/27, 8210040277.
- --B210040325 Advises that proposed 230 kV transmission line between North Anna & Louise need not be avaluated in amend to environ rept for North Anna i & 2.Line is not part of North Anna utilisetion facility.

 RACONE: 8 Virginia Electric & Power Co 74/01/02 MULLER, D. R. Atomic Energy Commission. 2pp. 15591: 329 24x Fiche: 50-338, 82/09/27, 8210040277.
- 8210120215 Application to amend Licenses NPF-4 & NPF-7, revising Tech Space Te steff working hours. Request does not involve unreviewed safety question per 100FR30. 59 LEABURG.R.H. Virginia Electric & Power Co. 82/10/01. DENTON, FI R Office of Nuclear Reactor Regulation. Director. 1p. 15652.150. 24x Fiche 50-335.82/10/01.8210120215.
- --8210120225 Proposed Tech Specs revising staff working hours Provision does not permit shift crew position to be unmanned upon shift change due to late or absent oncoming shift crewman, # Virginia Electric & Power Co 82/10/01. 4pp 13652:131, 24x Fiche. 30-338, 82/10/01. 8210120215.
- 9210120265 Informs of implementation status of NUREG-0737. Item II. B.2, "Plant Shisiding" per NRC 920517 request All required work completed.

 LEASURG.R.H. Virginia Electric & Power Co. 82/10/01. DENTON, H.R. Office of Nucleer Reactor Regulation. Director. 2pp 15651-230. 24X Fiche. 50-000.82/10/01.8210120265.

- 8210120297 Forwards errata to Topicel Rept VEP-FRD-33. "VEFCO Reactor Core Thermel-Hydraulic Anelysis Using COBRA IIIc/HIY Computer Code."

 LEABSURG, R H Virginia Electric & Power Co 82/10/04 DENTON, R R Office of Nucleer Reactor Regulation, Director 2pp 15652 330 24X Fiche 50-000, 82/10/04, 8210120297
- --8210120305 Errete to "VEPCO Reactor Core Thermal Hydraulic Analysis Using COBRA-IIIc/MIT Computer Code " • Virginia Electric & Power Co VEP-FRD-33 ERR 13632 332 24X Fiche 50-000, 82/10/04, 8210120297
- 8210270042 Forwards safety evoluation & technical evoluation rept re analysis of main steam line breek w/continued feedwater eddition Analysis acceptable H/o technical evaluation CLARK, R A Operating Reactors Dranch 3 82/10/04 LEASEURO, R H Virginia Electric & Power Co ip 15877 271 24X Fiche 50-338, 82/10/04, 8210270042
- --8210290071 Bafety evaluation re main steam line break w/continued feedwater addition Contellment overpressurization will not result & auxiliery feedwater pumps can function during event
 - * Office of Nuclear Reactor Regulation, Director 82/10/04 6j; 15877 272 24X Fiche 50-338,82/10/04,8210290042
- 8210190321 Bubmits supplemental info re 820318 & 0927 requests for relief concerning License Condition 2 C(15)(h)(4) Gualified pressure switches unaveitable Nonqualified switches will be installed by 821031 Quelification expected by Jan 1993 LEABBURO, R H. Virginia Electric & Power Co. 82/10/13 DENTOW-H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Brench 3 ip 15742,058 24X Ficher 30-039,82/10/13,8210190321
- 8210220011 Submits addl info to 820713 request for amend to Licensis NPF-4 & NPF-7 Number of storage locations in neutron absorber spant fuel storage reck changed to 1.737 Fuel pool temps changed in Table 7 1

 LEABBURO, R. H. Virginie Electric & Power Co. 82/10/18 DENTON, M. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3 3pp. 15778 211 24X

 Fiche: 50-338, 82/10/18, 8210220011
- 8210220178 Comments on evaluation of significant dynamic toads in determining capacity of slings used per NUREO-0612 Rating can be safely expressed in terms of mar static load LEABBURG, R H. Virginie Electric & Power Co. 82/10/18 DENTOU.H.F. Office of Nuclear Reactor Regulation. Director 2pp 15777 273 24X Fiche 50-000;82/10/18.8210220178
- 8210260133 Forwards revised Table 7-1 to "Bummary of Info in Susport of Increasing Spent Fuel Storege Capacity at North Anna Units 1 & 2." Rept originally submitted w/820820 request for amend to Licenses NPF-4 & NPF-7 to replace storage racks LEABBURG.R H Virginia Electric & Power Co 82/10/21 DENTOW.H R Office of Nuclear Reactor Regulation, Director CLARK,R A Operating Reactors Branch 3 2pp 13797:102 24% Fiche: 50-338, 82/10/21, 8210260133.
- --8210260136 Revised Table 7-1 to "Bummary of Info in Support of Increasing Spent Fuel Storage Capacity at North Anna Units 1 k 2 "

 * Virginie Electric & Power Co. 82/10/21 ip 15757.104. 218 Fiche 50-338.82/10/21.8210260133
- Q Inspection reports, IE Bulletins & correspondence
- 8210220200 Responds to NRC ltr re violations noted in IE Insp Highs 50-338/82-08 & 50-339/82-08 Corrective actions health physics technician counseled re correct procedures for entering high radiation area.

 LEASBURG.R H. Virginia Electric & Power Co 62/07/29.

 O'REILLY.J.P. Region 2. Office of Director. 5pp 55777.265 242 Fiche: 50-338, 82/07/29, 8210220200
- 8210070007 Responds to FDIA request for eight categories of recensive steam generators & steam turbines. App A documents provided in R Udell FDIA Request 81-313. Forwards documents listed in App B.
 FELTON, J. M. Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts. 9pp 13645.063. 24% Fiche: 30-000.82/08/10.8210070007.
- --8210070137 Forwards tabulated data on steem generator insp & midt it facilities. Deta should be provided to licensees IPPOLITO, T. Operating Reactors Assessment Branch. 82/04/01 VAROA.S. Operating Reactors Branch 1. 5pp. 15645,131 24X Fiche: 50-000,82/08/10,8210070007.

- 8210010221 Forwards IE Insp Repts 50-339/82-18 & 50-339/82-18 on 820709-0803 No noncompliancs noted DANCE.H C Division of Project & Resident Programs 82/08/31. LEASBURC.R H Virginia Electric & Power Co 2pp 15567 338 24X Fichs 50-338,82/08/31.8210010221
- --8210010225 IE Insp Repts 50-339/82-18 & 50-339/82-18 on 820709-0805 No noncompliance noted Major areas inspected LERs, refueling & outage activities, surveyllance & maint activities, operations & followup on significant events
 JOHNSON, D F . SHYMLOCK, M B . JULIAN, C Division of Project & Resident Programs 82/08/31 11pp 15367 340 24X
 Fachs 50-338,82/08/31.8210010221
- B210010300 Forwards 1E Insp Napts 50-339/82-28 & 50-339/82-28 on B20916-19 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/03 LEASEURC.R H Virginia Electric & Power Co 2pp 15568 317 24X Fiche.50-33B.82/09/03.8210010300
- --8210010314 IE Insp Repts 50-338/82-28 & 50-339/82-28 on 820816-19 No noncompliance noted Major areas inspected thermai sleeve removal reactor coolant loop stop valves, cap screw fractures & broken control rod guide tube support pins YORK-J W. SLAKE-J J Division of Engineering & Technical Programs 82/09/02 6pp 15368 319 24X Fiche 50-338.82/09/03, 8210010300
- 8210150187 Forwards IE Insp Repts 50-338/82-30 & 50-339/82-30 on 820831-0903 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/23 LEASBURG.R H Virginia Electric & Power Co 2pp 15707-262. 24X Fichs 50-338,82/09/23,8210150187
- --8210150194 IE Insp Repts 50-338/82-30 & 50-339/82-30 on 820831-0903 No nancompliance noted Major areas inspected generator step-up transformer failure on 820822 & licensee recommendations & inspector failure items
 & Inspector failure items
 RUFF.A B , CONLON.T E Division of Engineering & Technical Programs 82/09/17 4pp 19707-264 24X Fiche 30-338,82/09/23,8210150197
- 8210220454 Forwards IE Insp Repts 50-339/82-33 & 50-339/82-33 on 820918 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/10/04, LEASBURO, R H Virginia Electric & Power Co 2pp 15779-135, 24X Fiche 50-338, 82/10/04, 8210220454
- --821022046i IE Insp Repts 50-338/82-33 & 50-339/82-33 on 820918 No noncompliance noted Major areas inspected, full-scale radiological exercise HUFFRIAN O N. MARBTONIR R. JENKINB.O.R. Division of Engineering & Technical Programs 82/09/30 lipp 13779 137, 24X Fiche 50-338,82/10/04.8210220454
- 8208190233 IE Info Notice 80-35, Suppl i. "Lwaking & Divlodged I-125 Implant Sweds " Svc list enc! COSB-L I Division of Fuel Facilities, Materials & Safeguerdx 82/10/06 Consolidated Edison Co of New York 66pp 15761 200, 24X Fiche 50-000,82/10/06,8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Mall-Large-Diameter Btainless Steel Recirculation Sys Piping at BMR Plants " Svc list encl DEYOUNGR C Director's Office Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York #13pp 15810 125 24X Fiche, 50-000, 82/10/14, 8208190238.
- 8 Reportable occurrences, LERs & related correspondence
- 8210080067 Trip rept of 810709 site visit to view extent of famege caused by failure of B phase mein transformer Transformers not designed to withstand severe electrical short circuits inside transformer CHIRAMAL.M Director's Office 81/07/14. MICHELSON.C Director's Office 3pp 15670-012. 24% Fiche 50-337.81/07/14,8210080067
- 821001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems. Forwards documents listed in App A FELTON. J M Division of Rules and Records. 82/06/28. UDELL.R A Critical Mass Energy Project. 15pp. 15727,005 24X Fiche. 50-000, 82/06/28, 8210010008
- --Boi0210037 Forwards 800505 msmo re underclad Cracking in reactor vessel nozzles. Revisw re safety aspects & compliance w/8ection IX of ASME ode concludes that problem should not be included on generic issues list.

 BAER.R L Bafety Program Evaluation Branch 80/07/17 KINTNER.L Licensing Branch 2. ip. 15727 175 24X Ficher 50-000, 82/06/28, 8210010008

- 8210080015 Add1 response to FOIA request for 19 categories of info renuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheid (ref FOIA Exemption 5).
 FELTON-J M Division of Rules and Records 82/07/12 UDELL,R. A Critical Mass Energy Project 9pp. 15665 027 24X
 Fichs 50-000,82/07/12,8210080015
- --8210080197 NRC operations of usage chart re events at facilities * NRC - No Details Affiliation Given 82/07/12 ip 19468-221 24X Fiche 50-000,82/07/12,8210080015
- 8207230301 Forwards LER 82-027/03L-0. CARTHRIGHT: Winginia Electric & Power Co 62/07/13 D'REILLY, J P. Region 2. Office of Director ip 13998 329 24X Fiche 30-339, 82/07/13, 8207230301
- --B207230303 LER B2-027/03L-0 on 820620 & 23 sxis1 flux difference went less than -5% from target on two occasions Caused by inability to establish stable axial flux difference target in new core
 CARTKRIGHT, W Virginia Electric & Power Co 82/07/13 Region 2, Office of Director 3pp, 13998 330 24% Fichs 50-339. 82/07/13.8207230301
- 8210010233 Forwarde LER 82-059/03L-0 CARTHAIGHT.WR Virginia Electric & Power Ga 82/09/22 G'REILLY.T P. Region 2. Office of Director 1p 15574 031 24X Fiche 50-339,82/09/22,8210010233
- --8210010236 LER 62-039/03L-O on 820830, steam generator B steam flow channel IV, providing steam line break & loss of heat sink protection, failed high Cause not determined Channel placed in tripped condition Problem cluared during troubleshooting CARTHRIGHT, H R Virginia Electric & Power Co. 82/09/22 Region 2, Dffice of Director 3pp 15574 032. 24X Fichs 50-339, 82/09/22,8210010233
- 8210080182 Forwarde LER 82-061/03L-0 CARTWRIOHT.W R Virginia Electric & Power Co 82/09/30 O'REILLY, J P Replon 2, Office of Director 1p 15640; 172 24X Fiche 30-339, 82/09/30, 8210090182
- --8210080185 LER 82-051/03L-0 on 820703, low head safety injection pump 2-81-P-1A containment sump suction valve MOV-2850A failed to open during periodic surveillance test Caused by sower cord wrapped around valve operator flexible extension.

 CARTHRIGHT, W.R. Virginia Electric & Power Co. 82/09/30 Region 2, 0ffice of Director 2pp 15540 173 24X Fiche 50-339, 82/09/30,8210080182
- 8210220415 Forwards LER 82-062/03L-0 CARTWRIGHT,W R. Virginia Electric & Power Co. 82/10/07 O'REILLY,J P. Region 2. Office of Director. 1p, 15778-355. R4X Fiche:50-339, 82/10/07.8210220415.
- --B210220421 LER 62-062/03L-0.on 620710 & 13, fire door 654-9 found not providing definitive seal for control ruom pressure boundary. Caused by out-of-plumb door installation Door removed, stops adjusted & door replaced CARTHRIOHT, M.R. Virginia Electric & Power Co 62/10/07 Region 2, Office of Director. 2pp 15778:356 24X Fiche: 50-339, 82/10/07:0210220415
- 8210220441 Forwards LER 82-060/03L-0. CARTWRIGHT.W R. Virginia Electric & Power Co. 82/10/07. O'REILLY, J. P. Region 2. Office of Director. 1p. 15778:353, 24X Fiche: 50-339, 82/10/07, 8210220441.
- --8210220450 LER 82-060/03L-0; on 820914, w/Unit 2 at 98% power, fire door 854-9 between emergency switchgear room & cable vault found blocked open w/o fire watch. Cause unknown Block removed & door persoility verified.

 CARTHRIGHT, W.R. Virginia Electric & Power Co 82/10/07. Region 2, Office of Director. ip. 15778; 354, 24% Fiche: 50-339, 82/10/07, 8210220441.
- 8210260281 Forwards LER 82-063/03L-0. CARTHRICHT, W.R. Virginia Electric & Power Co 82/10/19. O'REILLY-J.P. Region 2: Office of Director, 1p 15801;352 24X Fichs 50-339,82/10/19.8210260281.
- --8210260287 LER 82-063/03L-0; on 820926, individual rod position indication for rod 8-09 in centrol bank D deviated from group demand position by greater than 12 steps w/no rod motion. Gavised by instrument drift. Instrument recalibr. GARTHRIGHT, M. R. Virginia Electric & Power Co. 82/10/19 Region 2, Office of Director 2pp 15801:353, 24% Fichs:30-339, 82/10/19,8210260281.

- 8210260346 Forwards LER 82-065/03L-0 CARTURIOHT: W R Virginia Electric & Power Co 82/10/19 O'REILLY, J P Region 2. Office of Director 1p. 15803 188 24X Fiche: 50-339, 82/10/19, 8210260346
- --8210260360 LER 82-065/03L-0. on 821007, control power for A casing cooling pump found ds-emergized due to open circuit breaker Causs unidentified Circuit breaker closed CARTHRIGHT, N. R. Virginia Electric & Power Co. 82/10/19 Region 2, Office of Director 2pp 15803:189 24X Fichs 50-337, 82/10/19,8210260346
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 82:0040377 Responds to 820715 itr.Requests epplication be amended to include high drywall temp & design of level indication sys w/respect to leak or break of singls instrument tap or sensing line Addl info needed to verify acceptability YOUNOBLOOD.B J Licensing Branch 1. 82/09/21. TAUBER, H Detroit Edison Co 4pp 15597.203. 24X Fichs 50-341.82/09/21,8210040377,
- 8210010436 Forwards "Inservice Testing Program" for pumps & valves for 120-month insp period baginning w/fvel load par 10CFR30 55a.Rept supersides Revision O submitted w/810803 itr TAUEER.H Detroit Edison Co 82/09/22 KINTNER.L Division of Licensing ip. 15570 011 24X Fiche. 50-341:82/09/22.8210010456
- --821001046D "Inservice Testing Program "
 CLAUSG, J. M., MARTIN, J. B. NUTECH (Nuclear Technology, Inc.)
 DET-16-0201 R01 82/07/08 161pp. 15370 012 24X
 Fiche 30-341,82/09/22;8210010456
- 8210120026 Summary of 820715 masting woutil refacility GA concerning recent design & const deficiencies. Applicant considering another independent design review recore spray sys XINTRER, L. L. Licensing Branch i 82/09/22. Licensing Branch i 7pp 13689-189 24X Fiche 50-341,82/09/22,8210120026
- 8210120627 Forwards safety evaluation of plant-unique analysis rept for Mark I containment long-term program, technical evaluation rept of program audit & BNL technical evaluation of analysis rept LAIN48, 0 C. Assistant Director for Operating Reactors. 82/09/23 NOVAK, 1. H. Assistant Director for Licensing. 1p 15684.241 24X Fichs: 50-341, 82/09/23, 8210120627
- --8210120636 Bafety evaluation accepting plant-unique analysis rept for nment long-term program Possible im in single vent douncomer lateral load tified.

 >==1ed Affiliation Given 82/09/23 12pp.
 -he 50-341,82/09/23,8210120627.

t Long-Term Program - Structural

Institute/Franklin Research 82/08/25 NRC - No 584:254. 24X

- --8210120642 "Technical Evaluation of Fermi-2 Plant-Unique Analysis Rept " # Brookhaven National Laboratory NRC-20-82-213, BNL-04261, 82/09/30, NRC - No Detailed Affiliation Given 40pp 13684:300 24K Fiche:50-341,82/09/23,8210120627
- 8210010287 Forwards Amend 44 to application for DL.consisting of Amend 44 to FBAR.
 LANDGRAF.L C LeBosuf, Lamb, Leiby & Hackae LANDGRAF,L.C. Detroit Edison Co. 82/09/30 DENTON;H R. Office of Nuclsar Reactor Regulation, Director. 1p. 15573:187. 24X Fiche:50-341,82/09/30,8210010289
- --B210010295 Amend 44 to application for QL. HEIDELC M. Detroit Edison Co BE/09/28, ip. 15573'188. 24X Fiche: 50-041, 82/09/20, 8210010289.
- 8210080046 Confirms points agreed upon at NRC Caseload Forecast Panel 820824-26 site visit to assess plant const schedule. TAUBER:H. Detroit Edison Co. 82/10/01, DENYON.H R. Office of Nuclear Reactor Regulation, Director. 2pp. 15643:279. 24X Fiche: 50-341, 82/10/01. 8210080046.

- B210130158 Forwards Cartificate of Svc certifying svc of Amend 44 to amended & substituted application for licenses HATERIS R Detroit Edison Co B2/10/06 Office of Nuclear Reactor Regulation, Director 3pp 15673 074 24X Fichs 30-341, 82/10/06, B210130158
- 8210180188 Responds to NRC request for clarification of util 820715 itr rs strors in BWR water level indication. Existing sample of parating procedures adequate for successful termination of bounding event resulting in ref leg flashing TAUSER. H Detroit Edison Co 82/10/i1 KINTNER. L Division of Licensing. 3pp 15719 120 24X Fiche 50-341.82/10/i1.8210180180
- 82i0220414 Submits schedule for resolution of open items re Mart 1 containment. If resolution not apparent within 3 months of fuel load, will will work w/NRC to provide adequats justification for interim operation TAUBER.H Detroit Edison Co. 82/10/15 KINTNER.L L Division of Licensing. 3pp 15779.148 24X Fiche 50-341.82/10/15,8210220414
- 8210280222 Forwards Class II fee for application to amend CPPR-B7 MATERS.B R Detroit Edison Co 82/10/22 DIGGS.R M License Fee Management Branch ip 15837 090 24% Fichs 50-341,82/10/22, 8210280222.
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8210150639 Forwards status of add1 Mark I containment issues for supplemental BER input, identified since Mark I containment inng-term program LAIMAS.0 C Assistant Director for Operating Reactors, 82/10/06/NOVAK.T Assistant Director for Licensing ip 13715 290 241 Fiche 30-341.82/10/06.8210150639
- F Becurity, medical, emergency & fire protection plans
- 8210250195 Forwards summary evaluation of Mar 1982 svacuation time estimates. Beveral deficiencies noted Enumeration of special facilities missing & should be provided URBANIK.T. Texas A & M Univ 82/09/23 SIMONDS.J Division of Emergency Preparadness ip i5788'304. 24% Fichs 50-341.82/09/23 8210250195
- --8210250198 "Evaluation of Evacuation Time Estimate "
 * Texas A & M Univ 82/09/23 1p 15788 305 24x
 Fiche.50-341,82/09/23,8210250195
- 8210130284 Forwards maps documenting location of NRC monitoring stations consisting of 3B offsite environ TLDs deployed around facility W/a enci.

 KREUB: R.E. Detroit Edison Co. 82/09/24, OEBTHANN: M J Region 3. Office of Director 1p. 15678 263 24X Fichs. 30-341,82/09/24, 8210130284.
- O Adjudicatory correspondence
- B210040082 Forwards NRC response to Citizens for Energy & Employment 820904 answer. Name inadvertently omitted from Certificate of 8vc W/o encl.
 H000HEAD, C F Hearing Branch 1. 82/07/30 HINOCK, J. Minock, J. HINOCK, J. Citizens for Energy & Employment. ip 15581: 266 241 Fichs: 50-341, 82/09/30, 8210040082
- K Utility Final Bafsty Analysis Report (FBAR) & amends
- 8210010289 Forwards Amend 44 to application for DL, consisting of Acend 44 to FBAR.

 LANDGRAF, L. C. LeBosuf, Lamb, Leiby & MacRae. LANDGRAF, L. C. Datros Edison Co. 82/09/30. DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 1p. 15573, 187. 24X Fiche 50-341, 82/09/30. 8210010289
- --8210010295 Amend 44 to application for CL HEIDEL,C. H. Detroit Edison Co 82/09/20 ip. 15573.180 24I Fiche.50-341,82/09/30.8210010289.
- --8210010297 Amend 44 to F8AR

 * Detroit Edison Co. 82/09/30. 80pp 15573:189 24X
 Fiche: 50-341.82/09/30.8210010289.

DOCKETED ITEMS

Applicry Committee on Reactor Bafeguards reports & correspondence

10270398 Comments on analyses evaluating capability of facility biological shield to withstand asymmetric loadings resulting from double ended pine broak at reactor vessel notice safe analyses 791023 & 1204 requests 10045.7 Franklin Institute/Franklin Research Center ZUDANS

NOAMS I Franklin Institute/Franklin Research Center ZUDANS, Z AKB - Advisory Committee on Reactor Bafaguards 80/05/30 ALERMAN ACRE - Advisory Committee on Reactor Bafaguards 5p 1883 348 24X Fiche 50-341.80/05/30,8210270398

inspection reports. IE Bulletins & correspondence

10010456 Forwards "Inservice Testing Program" for pumps & valves for 120-month insp period beginning wifuel load per 1005R30 55a Rept supersedes Revision O submitted w/810803

TAUSER, H Detroit Edison Co. 82/07/22 KINTNER, L Division of Licenting ip 19570 011 24% Fich. 50-341.82/07/22.8210010496

8210010460 "Inmervice Testing Program" cLAUBS.J H . MARTIN.J B NUTCCH (Nuclear Technology, Inc.) DEF-16-0201 ROI B2/07/08. 161pp 15570:012 24X Fichs 50-341,82/09/22.8210010456

e210130374 IE Insp Rept 50-341/82-i1 on 820721-23 & 27-30 No noncompliance noted Hajor areas inspected 100FR50 55e repts. electrical hanger reinsp. 6A records. relay coordination activities & deviation disposition request NATULK R. WILLIAMS.C C Region 3, Office of Director 82/09/i0 lipp 15682 102 24X Fiche 50-341,82/09/27,8210130368

20170303 Submits list of tubes plugged in each steam generator following inservice insps GROUSF.RP Toledo Edison Co 82/10/04 KCPPLER.J.Q Region 3, Office of Director ip 15742 158 24X Fiche 50-341,82/10/04, 820189303

R0190233 IE Info Notice 80-35. Suppl i. "Leaking & Disiodged I-125 Replant Seeds " Svc fist encl (RDD. I. Division of Fuel Facilities, Meterials & Bafeguards. 82/16/06 Censolidated Edison Co of New York. 66pp. 15761: 250. 24X Fichs 50-900.82/10/06.8208190233

200130185 Clarifies NRC position concerning procedures for admitting IRC personnel to facility Lists of authorized personnel ently

KEPPLER, J O Region 3, Office of Director, 92/10/06 WELLS, D. A Detroit Edison Co 4pp. 15674 137 24X Fiche 50-341, 82/10/06. 8210130188

20230072 Forwards 1E Insp Rept 50-341/82-12 on 820701-0831 & notice of violation. SPE69ARD, R L Division of Project & Resident Programs 82/10/07, MELL® D. A. Detroit Edison Co 2pp 19789-341 24X Ficks. 50-341, 82/10/07, 8210250072

*210250075 Notice of violation from insp on 820701-0831 SPESBARD,R L. Division of Project & Resident Programs. 82/10/07. 2pp 15787-343 24X Fiche 80-341,82/10/07,8210250072

-8210230080 IE Insp Rept 50-341/82-12 on 820701-0831 Noncompliance noted failure to accomplish activities per GA procedure, to provide appropriate procedure & to perform resudit to verify corrective action implementation.

LITLE: B H . KONKLIN.J E Division of Project & Resident Programs 82/10/07 7pp. 13789.345. 24X Fiche 50-341,82/10/07,8210250072

210150322 Forwards responses to IE Bulletin 79-15, "Long-Term Operability of Deep Draft Pumps," Responses will be incorporated in FBAR amend Related procedures also encl. TAVEER: Detroit Edison Co 82/10/11 KINTNER, L. L. Office of Ruclear Reactor Regulation, Director Bpp 15702:001 24X Fiche: 50-341, 82/10/11.8210150322.

-8210150326 "Qoulds Pumps, Inc Type I Henual, Emergency Equipment Byc Water Pumps, "

* Qoulds Pumps, Inc 77/07/14, 53pp 15702,009 24X Fiche 30-341,82/10/11,8210150322

- ~-8210150335 "Instruction Manual.RHR 8vc Water Pumps,Enrico Fermi Atomic Power Plant Unit 2 " * Goulds Pumps, Inc 75/[1/19 43pp i5702 154 24X Fiche 50-341.82/10/11,8210180322
- --8210150343 "Seigmic-Stress Analysis of ASME Section III Class 3 Pumps "
 McDonald Engineering Analysis Co ME-229 75/09/03 54pp
 15702.209. 24X Fiche 50-341.82/10/11.8210150322
- --8210150346 "Sejemic-Stress Analysis ASME Section III Class 3 Pumps "
 * McDonald Engineering Analysis Co ME-230 75/09/03 56pp
 15702 264 24% Fiche 50-341,82/10/11,8210150322
- --8210150352 "Beismic-Stress Analysis Rept RHR Bvc Water Pumps "

 * McDonald Engineering Analysis Co. ME-146 74/01/28 40pp
 15702 320 24X Fiche 50-341,82/10/11,8210150322
- 8210190696 Ciarifies check valve info re inservice insp of pressure isolation valves per 810603 itr Design features provide better protection than check valve position monitoring for sys Info will be included in future FBAR amend TAUBER.H Detroit Edison Co 82/10/11 KINTNER.L L Division of Licensing 2pp 15736 198 24X Fiche 50-341.82/10/11.8210190696
- 8208190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Wail, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co of New York 115pp. 13810:125 24X Fiche 50-000, 92/10/14, 8208190238
- 8210260372 Ack receipt of 820924 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-341/82-08 MARELIUS, C.E. Division of Project & Resident Programs 82/10/18 HELLE, D.A. Detroit Edison Co. ip 15804-233 24X Fiche 50-341,82/10/18,8210260372
- --B2102603B2 Responds to NRC 820B10 itr re violations noted in IE Imap Rept 80-341/82-08 Corrective actions snubber reduction program accepted & implemented on 820609. All documentation forwarded to NRC upon completion HELLB, D A Detroit Edison Co 82/09/24. BPESBARD, R L Division of Project & Resident Programs 5pp 15804:234. 24% Fiche 50-341,82/10/18,8210260372
- 8 Reportable occurrences. LERs & related correspondence
- B210040127 Interim deficiency rept re defective 1-inch pipe couplings & caps mfg by Capital Mfg Co Initially reported on B20810 Installed couplings will be given visual insp & liquid penetrant exam Next rept expected by B30107 WELLB, D. A. Detroit Edison Co. B2/09/09 KEPPLER, J. G. Region 3, Office of Director. 2pp 15581-210. 24X Fichs 50-341, B2/09/09, B210040127.
- 8210040084 Interim deficiency rept re load-carrying capability of certain dryweli structural steel Intially reported on 820024. Fix involving reinforcing of affected members considered. Interim or final rept expected by 820120 WELLBROA Detroit Edison Co. 82/09/22 WEPPLER. J G. Region 3, 0ffice of Director. 1p. 19581 265. 24X Fiche: 50-341, 82/09/22, 8210040084.
- 8210190332 Final deficiency rept re cracking of 3/4-inch carbon steel pipe. Initially reported on 820430. Handfacturer installed eddy current tester to aid in GC of pipes. Faulty sections of pipe replaced WELLB, D. Detroit Edison Co. 82/09/24. KEPPLER, J. G. Region G. Office of Director. 3pp. 13742:088. 24X Ficher 50-341,82/09/24,8210190332
- B210190657 Interim deficiency rept re defective pipe support strut suivel bearings. Initially reported on B20514, Addi insprequirements for field inspectors wiff be developed per IE Circular Bi-05 Next rept will be submitted by 820204. HELLB, D. A. Detroit Edison Co. B2/10/08 KEPPLER. J. G. Region G. Defice of Director. 2pp 15737 147. 24X Fiche 50-341, 82/10/08, 8210190657.
- 8210250191 Final deficiency rept re stainless steel piping 8A 312TP316 t. 8A 312TP316HF installed in lieu of required 8A 312TP316L. Initially reported on 820317 Deviation disposition requests written Na instrument sample lines affected. MELLS,D.A. Detroit Edison Co. 82/10/12 KEPPLER,J.Q. Region 3, Office of Director. 2pp. 15788.298. 24X Fiche, 50-341, 82/10/12, 8210250191.

DOCKET 50-344 TROJAN NUCLEAR PLANT

- F Security, medical, emergency & fire protection plans
- 6210070012 Requests concurrence u/plan to Issue license emend incorporating encl license condition re implementation of UB/IAEA sefeguards agreement Notification of info desired to be uithheld requested within 30 days Encls withheld CLARK.R A Operating Reactors Branch 9 82/09/24 WITHERS.8 D Portland General Electric Co 3pp 15646 223 24X Fiche 50-344.82/09/24,8210070012
- B210190020 Releases public version of revision to radiological amergency response glan implementing procedure FELTON.J M Division of Rules and Records. B2/10/01 Document Management Branch 1p 15761:001 24% Fiche-50-344.82/10/01.
- --8210190024 Forwards public version of Revision 3 to Radiological Emergency Response Plan Implementing Procedure EP-7, "Operation of Technical Support Ctr "Receipt form encl. PUZEY, A M Portland General Electric Co 82/09/22 CLARX, R A Office of Nuclear Reactor Regulation, Director ip 15761 002 24% Fiche 50-344,82/10/01,8210190020
- --8210190026 Public version of Revision 3 to Rediological Emergency Response Plan Implementing Procedure EP-7, "Operation of Technical Support Ctr " YUNOT, CP Portland Caneral Electric Co B2/09/20, 28pp 15761 003 24X Fiche 50~344,82/10/01.8210190020
- 8210280210 Forwards request for add1 info re changes to physical security plan & safeguards contingency plan in response to 820719 it Encl withheld (ref 100FR73 21).

 CLARK.R A Operating Roactors Branch 3 82/10/26 HITHERB, 8 D Portland Operal Electric Co 1p 15837 106 24X Fiche 30-344, 82/10/26, 8210280210

P Operating license stage documents & correspondence

- 8210010053 Forwards systematic assessment of liconsee performance data package to be used in preparing performance analyses Analyses should be prepared following format of enci NRC App 0516.Part VI.Bection IV Analyses due 821008
 STERNBERO, D H Division of Resident, Reactor Project & Engineering Programs 82/09/24, JOHNBON.P H MALHROS.M H , CILLIS,M Region 5, Dfflice of Director 18pp 15565 119 24X Fiche 50-344.82/09/24, 8210010053
- B210040163 Advises that containment hydrogen monitors installed & calibr for hydrogen concentrations betwen 0 & 10% per TMI Action Item II F. 1. Main steam line monitors installed, however, calibr delayed until B2101 due to repaire.

 WITHERS, B D Portland Ganeral Electric Co B2/09/28., EISENHUT, D Q Division of Liceneing 2pp 15582.032 24% Fiche 50-344,82/09/28, B210040163
- 8210150354 Bummery of B20928-30 meeting & site visit w/util & Bechtel re masonry wall design Addl info requested re in-plane response effects on out-of-plane responses & documentation of verification of programs
 TRANHELL CH Operating Reactors Branch 3 B2/10/05 Operating Reactors Branch 3, 5pp. 13715.353 24X Fiche.50-344,82/10/05,

G. Inspection reports. IE Bulletins & correspondence

- 8210070007 Responds to FDIA request for eight categories of records resteam generators & steam turbines. App A documents provided in R Udell FDIA Request 81-313. Forwards documents listed in App B.
 FELTON.J. M. Division of Rules and Records. 82/09/10. LDNG, D. J. Winthrop, Stimson, Putnam & Roberts 9pp 15445:063. 24X Fichs. 50-000, 82/08/10.8210070007.
- --B210070139 Forwards tabulated data on steam generator insp & maint at facilities. Data should be provided to licensees.

 IPPOLITO, T. Operating Reactors Assessment Branch. 82/04/01.

 VARQA:S Operating Reactors Franch 1 5pp 15645: 131. 24X

 Fiche: 50-000, 82/08/10, 8210070007
- 8210130597 Ack receipt of 820908 ltr forwarding payment of civil penalty imposed by NRC 820812 order AXELRABJ.4 Director's Office, Office of Inspection and Enforcement, 82/09/17, WITHERS, B.D. Portland General Electric Co. 2pp 15492:343 24X Fiche.50-344.82/09/17,8210130597.

- 8210010053 Forwards systematic assessment of licensee performance fata package to be used in preparing performance analyses Analyses should be prepared following format of enci NRC App 0516, Part VI. Section IV Analyses dus 821008 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/09/24 JOHNSON, P H, MALHROS, M H, CILLIS, M Region 5, Office of Director 1899 15565 117 24X Fichs 50-244,82/09/24,82/09/053
- 82(0)90549 Forwards IE Insp Rept 50-344/82-21 on 820712 No noncompliance noted STERNBERG, DM Division of Resident, Reactor Project & Engineering Programs B2/10/01 HITHERS, B D Portland General Electric Co 2pp 15735 CO1 24X Fiche 50-344,82/10/01,8210190549
- --8210190556 IE Insp Rept 50-344/82-21 on 820712 No noncompliance noted Major areas inspected program for welding pressurier surge line ECKHARDT.J H, DODDS.R T Division of Resident, Reactor Project & Engineering Programs 82/10/01 3pp 15735 003 24K Fiche 50-344,82/10/01.8210190549
- 8210080249 Ack receipt of 820923 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-344/82-24 STERNBERO D M Division of Resident, Reactor Project & Engineering Programs 82/10/05 WITHERS, D Portland General Electric Colp 19 15638 093 24X Fiche 50-344.82/10/05.8210080249
- --8210080253 Responds to NRC 820903 itr re violations noted in [E lns; Rept 50-344/82-24 Corrective actions maint procedures revised to reflect change from motor to air operators on four auxiliary feedwater pump steam supply valves WITHERB: B D Portland General Electric Co 82/09/23 ENGELKEN.R H Region 5, Office of Director 4pp 15638 094 24: Fiche 50-344.82/10/05.8210080249
- 8208190233 IE Info Notice 80-35, Supp) 1: "Leaking & Dislodged [-125 implant Seeds " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguerds. 82/10/06 Consolidated Edison Co of New York 66pp 13761: 250 24X Fiche: 50-000, 62/10/06, 6208190233
- 821019073: Forwards IE Insp Rept 50-344/82-26 on 820809-9903 & notice of violation CREMS, J. Division of Resident, Reactor Project & Engineering Programs 82/10/06 WITHERS, B.D. Portland General Electric Co 2pp 15737 065 24X Fiche 50-344, 82/10/06, 821019073:
- --8210190733 Natice of violation from insp on 820809-0903 DODDS,R.T Division of Resident, Reactor Project & Engineering Programs 82/10/06 2pp 15737 067 24X Fiche 50-344,82/10/06, 8210190731.
- --8210190743 IE Insp Rept 50-344/82-26 on 820809-0903 Noncompliance noted safety injection sys actuation logic inoperable from 820818-20 MALHROS, M. H., DODDS, R. T., Division of Resident, Reactor Project & Engineering Programs 82/09/16 7pp 15737:069 24K Fiche 50-344,82/10/06,8210190731
- B210270413 Forwards safety evaluation of licensee B00430 & 020317 responses to IE Bulletin 80-04, "Analysis of PMR Main Steamline Break W/Continued Feedwater Action " Licensee responses acceptable CLARK, R A Operating Reactors Branch 3 82/10/07 WITHERS & D Portland Ceneral Electric Co 2pp. 15863 241 24X Fiche. 50-344, 82/10/07, 8210270413
- --B210290417 Bafety evaluation accepting licenses 800430 & B20317 enalyses of main steamline break w/continued feedwater action No further action re IE Bullatin 80-04 required. * Office of Nuclear Reactor Regulation, Director 82/10/07 75: 15863:243. 24X Fiche: 50-344, 82/10/07, 8210290413
- 8208190238 IE Bulletin 82-03, "Btress Corrosion Cracking in Thick-Wall, Large-Diameter, Btainless Steel, Recirculation Sys Plping at BMR Plants." Svc list encl.
 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement, 82/10/14 Consolidated Edison Co of New York
 113pp 13810:125, 24X Fiche 50-000, 82/10/14, 8208170238
- B. Reportable occurrences, LERs & related correspondence
- 8210250084 Forwards LER 82-018/03L-0 Datailed event analysis enct. YUNDT, C P., 8TEELE,R.L. Portland General Electric Co 82/10/11. ENGELKEN,R H. Region 5, 0ffice of Director 3pp. 15787:077 24X Fiche.50-344,82/10/11,8210250084

- -P210250093 LER 92-018/03L-0 on 820918, during normal operation, steam pressure transmitter PT-524 on steam generator 8 failed hash, causing associated protection sys bistable to trip & steam flow instrument FI-522 to fail high Cause unknown SATR-0 0 Portland General Electric Co 82/10/11 Region 5, Office of Director ip 15787 080 24% Fiche 50-344,82/10/11, 8210250084
- Q10250164 Forwards LER 92-017/03L-0 Detailed event analysis entl YUNDY.C P. BTEELE,R L Portland General Electric Co 82/10/11 ENGELXEN.R H Region 5, Office of Director 3pp 15787 330, 24X Fiche 50-344, 82/10/11.8210250164
- -B210250175 LER B2-017/03L-0 on B20916, boron concentration in north borst acid storage tank decreased below Tech Spec level Caused by dilution due to two leaking valves Bouth tank Level raised above BTS limit Valves repaired BAIR.0 0 Portland General Electric Co B2/10/11 Region 5, Office of Director 1p 15787 333 24X Fiche 50-344,82/10/11. B210250164
- Security, dedical, emergency & fire protection plans
- 3210-070-003 Releases public version of revised administrative memo & revised emergency plan supporting procedures FELT-0X. H Division of Rules and Records 82/09/17 Document Hanagement Branch ip 15646 222 24X Fiche 50-346, 82/09/17, 8210070003
- --8210070005 Forwards public version of Revision 17 to Administrative Memo 42-17. "Rediation Monitoring Teams" & Revision 190 to wasgency plan supporting procedures index Receipt form Enci
 Toledo Edison Co 82/09/08 NRC No Detailed Affiliation Coven ip 15546 218 24% Fiche 50-346,82/09/17.82100700003
- ~-8210070006 Public version of Revision 17 to Administrative Memo 42~17.

 "Radiation Monitoring Teams" & Revision 150 to emergency
 plan supporting procedures index
 HURRAY.T D Toledo Edison Co 82/09/30 2pp 15646,219 24X
 Fiche 50-346,82/09/17,8210070003
- B210050235 Requests add1 info re intended use of drawings & reactor safeguards program prior to submittal of info requested in 820324 ltr Request appears to duplicate Sandia Natl Labs program CRQUSE.R P Toledo Edison Co 82/09/28 STOLZ, J F Operating Reactors Branch 4 ip. 15609 052 24X Fiche 50-346.82/09/28. 8210050235.
- 8210250286 Forwards IE Safety Evaluation Rept 50-346/82~26 on 820901-30 No noncompliance noted HINO.J A Division of Emergency Preparedness & Operational Support 82/10/07 CROUSE, R P Toledo Edison Co 2pp 15791,106 24X Fiche 50-346,82/10/07,8210250286
- --8210250297 IE Safety Evaluation Rept 50-346/82-26 on 820901-30 No moncompliance noted Major areas inspected site emergency plan PLOSKI, T J , AXELSON, W L . PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 62/10/06 37pp 15791 108 24X Fiche 50-346,82/10/07,8210250286
- B210190623 Forwards revision to Industrial Security Plan AD 1808 Revision withheld (ref 10CFR2 790) CRQUEE.R P Toledo Edison Co 82/10/12 STOLI, J F Operating Reactors Branch 4 1p 15739, 360 24X Fiche 50-346, 82/10/12, 8210190623
- P Operating license stage documents & correspondence
- S210210348 Confirms 820916 telephone authorization of amend to License NPF-3 by adding one-time note to Tech Beac Table 4 3-11 resteam & Feedwater rupture control sys instrumentation surveillance requirements

 LAINABO C Assistant Director for Operating Reactors, 82/09/20, CROUSE.R.P. Toledo Edison Co 2pp 15784:274 24X

 Fichs 50-346.82/09/20,8210210548
- --8210210550 Amended Tech Spac Table 4 3-11 re steam & feedwater rupture control sys instrumentation surveillance requirements,
 4 Assistant Director for Operating Reactors 82/09/20 lp. 15784 278 24% Fishs 50-346, 82/09/20, 8210210348
- -- B210210353 Safety evaluation supporting change to Tech Spec Table 4 3-11 re steam & feedwater rupture control sys instrumentation surveillance requirements LAINAS, 0 C Assistant Director for Operating Reactors. 82/09/16, 1p. 15784: 279 24X Fiche: 30-346, 82/09/20, 9210210548

- --B210210556 Application for smargency change to Tech Spec Table 4.3-11.
 extending steam line pressure low switch surveillance
 period by 96-h. until midnight 820916 Safety evaluation encl
 PETERS.R F Toledo Edison Co. 82/09/17 DEAGAZID.A Office of
 Nuclear Reactor Regulation. Director 2pp 15784 280 24X
 Fiche 50-346,82/09/20.8210210548
- --8210210559 Proposed change to Tech Spec Table 4 3-11, extending steam line pressure low switch surveillance period by 96-h, until midnight 820916

 Toledo Edison Co 82/09/17 ip 15784 282 24X Fiche 50-346,82/09/20,8210210548
- 8210120001 Requests add1 info re secondary water chemistry monitoring & control by 821108 Info pertains to 771003 proposed amend to delete existing fech Spec on secondary water chemistry & incorporate model license condition STOLZ.JF Operating Reactors Branch 4 82/09/22 CRQUSE,R P Toledo Edison Co 4pp 15689 183 24X Fiche.50-346.82/09/22, 8210120001
- 8210040049 Informs that Class IV fee should be submitted for final review of 820715.30,0806 & 16 submittels DIO08.R M License Fee Management Branch. 82/09/23 CRGUSE,R P Toledo Edison Co. ip 15577 292 24X Ficher 50-346.82/09/23, 821004049
- 8210180025 Requests review of enci Franklin Research Ctr draft technical evaluation rept prepared on util 820101 responses to request for info re NUREG-0612. "Control of Heavy Loads at Nuclear Power Plants "
 DE AQAZIO, A W Operating Reactors Branch 4 82/09/23 CROUSE, R P Toiedo Edison Co. 2pp 15717 278 24X Fiche 50-346, 82/09/23, 82/0180025
- --8210180026 "Control of Heavy Loads (C-10), Toledo Edison Co.Davis-Besse Nuclear Power Station, Unit 1, " draft technical evaluation rept
 BONBEROER, C Franklin Institute/Franklin Research Center,
 NRC-03-79-118 TER-03237-530 82/08/27 CLEMENSON, F NRC No
 Detailed Affiliation Oiven, 38pp 15717 280 24X
 Fiche 50-346, 82/09/23-8210180025
- 8210050304 Responds to 820727 itr re NUREO-0737.item II K 2 10, "Anticipatory Reactor Trip Bys (ARTS) " Adequate features available to alert operator to remove bypass when automatic bypass removel not required CROUSE,R P Toledo Edison Co 82/09/27 STOLZ,J F Operating Reactors Branch 4 2pp. 15510 266 24X Fiche 50-344,82/09/29,8210050304
- 8210050333 Advises that schadule for responding to NUREO~0737. Item II B. 3, "Post-Accident Sampling Sys," will be provided by Mar 1983, in response to 820721 request CROUSE.R.P. Toledo Edison Co 82/09/29 BTGLZ, J F Licensing Branch 4. ip. 15610 094 24X Fiche 50-346.82/09/29.8210050333
- 8210050310 Forwards application to amend License NPF-3, revising Tech Spec Table 4 3-11 re steem & feedwater rupture control sys instrumentation surveillance requirements CROUSE, R. P. Toledo Edison Co. 82/09/30. BTGLZ, J. F. Operating Reactors Branch 4 lp 15601:352 24X Fiche 50-346,82/09/30, 6210030310
- --82100503i3 Application to amend License NPF-3, revising Tech Spec Table 4,3-11 re-steam & feedwater rupture control sysinstrumentation surveillance requirements.
 CROUSE, R P Toledo Edison Co B2/09/30 lp. 15601,353. 24X Fiche: 50-346,82/09/30.82100503i0
- --8210050318 Proposed revision to Tech Spec Table 4 3-11 re steam & feedwater rupture control sys instrumentation surveillance requirements. Serety evaluation enc! * Toledo Edison Co. 82/09/30 3pp 15401 354 24x Fiche 50-346,82/09/30,8210050310
- 8210150519 Discusses NRR actions taken under Task Interface Agreement 82-20 for steam generator auxiliary feedwater header damage. Licensee authorized to resume power operation at Ocones 3.

 EISENHUT, D © Division of Licensing 82/10/06 CLEMINSKI, J Division of Engineering & Technical Programs. 1p 15717.261 24x Fiche: 50-000, 82/10/06, 8210150519.
- 8210180135 Forwards fae for review of once through steam generator repairs & auxiliary feedwater sys mods.
 CRDUSER.P. Toledo Edison Co. 82/10/08 MILLER.W.O. License Fee Management Branch. 2pp. 15719 338. 24X Fiche 50-346,82/10/08.8210180135.

- B210210225 Responds to 810629 itr stating that no license amend application needed to incorporate model Tech Spec for snubber surveillence Response unacceptable since ANSI/ASME CM-4 not completed Amend requested STQLZ/JF Operating Reactors Branch 4 B2/10/13 CROUSE, R P Toledo Edison Co 2pp 15774 339. 24X Fiche 50-346, 82/10/13, 8210210225
- 8210270319 Advises that proposed Tech Spec changes requested by 800410 itr not received Model Tech Spece re definition of term "operable-operability" forwarded Proposed Tech Spec changes requested by 821108
 STOLL-1 F Operating Reactors Branch 4 82/10/13 CROUBE.R P Toledo Edison Co 2pp 15836 352 24X Fiche 50-346,82/10/13.
- --8210270325 Model Tech Specs re definition of term "operableoperability" & limiting conditons for operations & associated bases Time to place plant in hot standby relaxed to 6-h & cold shutdown within subsequent 30-h * Operating Reactors Branch & 82/10/13 3pp 15836 354 24X Fiche 30-346,82/10/13.8210270319
- B210270372 Forwarde Amend 46 to License NPF-3, safety evaluation & notice of issuance & availability Amend permits one-time extension to surveillance period for steam line pressure-low instrument STOLZ, J.F. Operating Reactors Branch 4 B2/10/13 GROUSE, R.F. Toledo Edison Co. 2pp. 15834 250 24X Fiche 50-346, 82/10/13, 021027037032
- --8210270382 Amend 46 to License NPF-3, permitting one-time extension to surveillance period for steam line pressure-low instrument STOLZ, J. F. Operating Reactors Brench 4 82/10/13 4pp 15834 253 24X Fiche 50-346:82/10/13
- --8210270386 Safety evaluation supporting Amend 46 to License NPF-3.
 4 Office of Nuclear Reactor Regulation, Director 82/10/13 6pp 1884 258 24X Fiche 50-346, 82/10/13, 8210270372
- --82102703B7 Notice of issuance & availability of Amend 46 to License NPF-3 STOLZ.JF Operating Reactors Branch 4 82/10/13 2pp 15834 261 24X Fiche 50-346,82/10/13.8210270372
- 8210210458 Forwards, under esparate cover, application for amend to License NPF-3 Amend increases estpoint margin for power operated relief valves, revises bases on auxiliary feadurer sys & aiters trip setpoints to account for instrument arror CRDUBER RP Tolde Edison Co 82/10/14 STOL.7.1 F Operating Reactors Branch 4 18pp 13763 047 24% Fithe 50-346,82/10/14,82/0210458
- 8210260283 Application to amend License NPF-3 revising Tech Specs to reflect changes to setpoints for pressurizer electromatic relief & code safety valves auxiliery feedwater sys & trip setpoints for borated water storage tank level MURRAY, T. D. Toledo Edieon Co. 82/10/14 STGLZ, J.F. Operating Reactors Branch 4. 18pp. 15803, 124. 24% Fiche 50-346, 82/10/14, 82102A0283
- 8210220013 Responde to 820713 ltr requesting implementation echedule for mods to ECCB evaluation models Mods will be undertaken as extension of NUREG-0737. Item II K 3 31. Schedule will be provided 60 days after NRC approval of Item II K 3,00. CROUSE: R. P. Toledo Edison Co 82/10/19 NOVAK: IM Assistant Director for Operating Reactors | p 15778 210 24X Fiche: 50-346, 82/10/19, 8210220013
- 8210270378 Forwards Amend 48 to License NPF-3, safety evaluation & notice of issuance & availability Amend changes calculational method to determine max allowable high flux trip setpoint when one or more safety valves inoperable DE AOAZIO, A W Operating Reactors Branch 4, B2/10/20, CROUSE, R. P. Toledo Edison Co. 2pp 15845:249 24% Fiche: 50-344,82/10/20, B210270378.
- --8210290382 Amend 48 to License NPF-3, reflecting change in calculational method for determining mer allowable high flux trip setpoint when one or more safety valves on eteam generator inoperable, STOLZ, J.F. Operating Reactors Branch 4 82/10/20, 7pp. 15865 252, 24X Fiche: 50-346, 82/10/20, 8210290378
- --8210290385 Bafeby evaluation supporting Amend 4B to License NPF-3 * Office of Nuclear Reactor Regulation Director 82/10/20, 3pp 15845 259 24% Fiche: 50-344, 82/10/20, 8210290378
- --8210290387 Notice of issuance & availability of Amend 48 to Licensa NFF-3 STGL7.J,F Operating Reactors Branch 4 82/10/20. 2pp. 15865 262. 24X Fiche: 50-346, 82/10/20,8210290378

- 8210260268 Responde to NRC 821007 itr requesting confirmation that manual valves used to isolate air start motors & fuel supply of smergency diesel generators during maint are controlled by locked valve procedure Procedure AD 1839 02 applicable CRDUSER P Toledo Edison Co 82/10/21 STOLZ, JF Operating Reactors Branch 4 ip 15805 221 24X Fiche 50-346.82/10/21.
- Q Inspection reports, iE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documente listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15645 027 24X
 Fiche 50-000, 82/07/12,8210080015
- --B2100B012B Bystematic assessment of licensee performance notes to facility svaluation for Nov 1979-Dct 1980

 * NRC No Detailed Affiliation Given B0/10/30 15pp 15667 334 24% Fiche 50-000 82/07/12 82100B0015
- 8210060314 Responds to IE Bulletin 81-01, "Burveillance of Mechanical Snubbers " Snubbers inspected during recently completed refueiling outage Nine snubbers identified as nonconforming CROUSE.R P Toledo Edison Co 82/09/14 KEPPLERIJ O Region 3. Office of Director. 6pp 13619 216 24X Fiche 50-346.82/09/14. 8210060314
- 8210050253 Ack receipt of 820708 itr informing NRC of steps taken to correct violations noted in IE insp Rept 50-346/82-18
 ETREETERJF Division of Project & Resident Programs BP/09/24
 CROUSE-R P. Toledo Edison Co ip 15610 271 24X
 Fiche 50-346,82/09/24,8210050253
- --8210050258 Responds to NRC 820810 ltr re violations noted in IE ing Rept 50-346/82-18 Corrective actione operations supervisor discussed event wishift eupervisors stressing importance of strict procedure compliance & review of locked valve status CROUSE/R P Toledo Edison Co 82/09/08 STREETER.J F Division Project & Resident Programs 2pp 15610 292 24X Fiche 50-346,82/09/248 8210050253
- 8210080285 Ack receipt of 820907 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-344/82-03 NRRELIUS, C E Division of Engineering & Technical Programs 82/10/04. CROUSE, R P Toledo Edison Co ip 15638-315 24X Fiche 50-344, 82/10/04, 82(0080285
- --8210080288 Responds to NRC 820816 itr re violations noted in IE Inig Rept 50-346/82-03 Corrective actions GA program will be updated to include review of regulatory requirements & commitments CROUSE:R P. Toledo Edison Co 82/09/07 NORELIUS:C E Olivisien of Engineering & Technical Programe 2pp 15638 316 24X Fichs 50-346,82/10/04,8210080285
- B20B190233 IE 1nfo Notice 80-35, Suppl 1, "Leaking & Disladged [-125 Impiant Beeds," Svc list enci, COBD.L.I. Division of Fuel Facilities, Materials & Sefeguards 82/10/06 Constituted Edison Co of New York 64pp. 15761 250 24X Fiche 50-000, 82/10/06, 820B190233
- 8210250286 Forwards IE Bafety Evaluation Rept 50-346/82-26 on 820901-30 No noncompliance noted HIND, J A Division of Emergency Preparedness & Operational Bupport 82/10/07 CRUBER P Toledo Edison Go 2pp. 15791-106 24X Fiche 50-346, 82/10/07, 8210250286
- --8210250297 IE Safety Evaluation Rept 50-346/82-26 on 820901-30 No noncompliance noted Major areas inspected eits emergency plan.
 PLOSKLIT J , AXELSON W L , PAPERIELLO, C J Division of Emergency Preparedness & Operational Support, B2/10/06 37pp 15791 106 24% Ficher 50-346/82/10/07,8210250286
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Syc list enci DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810-125 24X Fiche, 50-000, 82/10/14, 8208190238
- 8 Reportable occurrences, LERs & related correspondence
- 8012290118 Discusses conclusions of engineering evaluation of steam generator overfill transients at C-E & Westinghouse plants LANNING D Director's Office 80/10/29, MICHELSON, C Director's Office 9pp. 15692,262 24X Fiche 50-000,80/10/29,801229018B

- ELCO70115 Discusses LER 79-062/03L-1 re auxiliary feedwater sys pressure switches On 790521, several switches would not activate Failure caused by corrosion due to misapplication of static O ring switches
 CHIRAMAL, M Director's Office 81/12/07 MICHELSON, C Director's
 Office 3pp 15449 216 24X Fiche 50-346,81/12/07,8210070115
- E210070460 Concludes that problem of misapplication of static D ring diaphragm-type switches is indigenous to Davis-Besse plant Corrective action to replace Buna-N switches w/stainless tterl switches adequate
 CHIRAMAL, M Director's Office 81/12/07 MICHELSON, C Director's
 Cffice 3pp 19644 341 24X Fiche 50-346, 81/12/07, 8210070460
- \$210010000 Responds to FOIA request for 19 categories of documents reflectear reactor events & safety problems Forwards documents Exsted in App A FELTON,J H Division of Rules and Records 62/06/28 Cribical Mass Energy Project 15pp 15727 005 24X Fichs 50-000,82/06/28,8210010008
- --Billi80001 Recommends comprehensive assessment of plant operating conditions to determine specific predetermined time related sequences of occurrence to emergency buses SRP should be revised re design features

 ASHE.F Director's Office 81/10/16 MICHEL80N.C. Director's Office 4pp 15731 049 24X Firms 50-000:82/06/28,8210010008
- -- 0201190538 Evaluates LER 79-062/03L-1 re auxiliary feedwater sys everyous evaluates LER 79-062/03L-1 re auxiliary feedwater systems suitches Hisapplication of static U-ring diaphragm type sustches was limited to facility Replacement w/statoless steel disphragm switches seems adequate CHIRAMALLH Director's Office B1/12/07 MiCHELSON.C Director's Office 3pp 65825 291 24K Fiche 50-000,82/06/28, B210010008
- 8210050323 Forwarde LER 82-041/03L-0 MURRAY.T D Toledo Edison Co 82/09/22 KEPPLER, J Q Region 3, Office of Director 1p 15608 221 24% Fiche 50-346,82/09/22, 8210050323
- -- \$2:0050027 LER 82-041/03L-0 on 820821.setpoints of three main steam safety valves found out of tolerance Gaused by normal valve aging Two valves immediately reset & third valve adjusted at reduced main steam pressure.

 D'NEILLJ Toledo Edieon Co 82/09/23 Region 3, Office of Director 3pp 15608 222 24X Fiche 50-346, 82/09/22, 8210050323,
- 8210050355 Forwards LER 82-042/03L-0
 HURRAY.T D Toledo Edison Co 82/09/24 KEPPLER, J O Region
 Office of Director ip 15609 042 24x Fiche 50-346,82/09/24. E210050355
- --B210050361 LER 82-042/03L-0 on 820827, once-through steam generator 1 sevel exceeded Tack Spec I limit on Pull-range instrumentation Caused by operator error during plant shutdown on 820823 Operator error during plant shutdown on 820823 Operatore cautioned 8 Toledo Edison Co 82/09/24 Region 3, Office of Director 3pp 15509 043 24% Fiche 50-346,82/09/24,8210050355
- 821 0130356 Forwards LER 82-031/03X-2 MURRAY.T D Toledo Edison Co 82/09/28 KEPPLER, J O Region Office of Director 1p 15479 012 24X Fiche 50-346, 82/09/28, Region 3.
- --8210130366 LER 82-031/03X-2 on 820625 & 0706, fire barrier doors 500 & 426 found slightly open On 820629, fire barrier & negative pressure doop 302 found slightly open Caused by closure archanism failure to seat doors tightly due to design error, NOLFER Tolsdo Edition Co 82/09/28, Region 3, Diffice of Director 2pp 15679 013 24X Fiche, 50-346, 82/09/28, 8210130356
- 8210130404 Forwards LER 82-043/03L-0
 MURRAY, T D Toledo Edison Co 82/07/29, KEPPLER, J 0 Region 3,
 Office of Director 1p 15681 164 24X Fiche, 50-346, 82/07/29,
- 8210130124 Forwards LER 82-044/03L-0 NURRAY.T D Tolete Ed. 64:001 Co. 82/07/30 KEPPLER, J 0, Region 3, OPFice of Director 1p 15679 040 24x Fiche. 50-346,82/07/30, 8210130124

- -- 8210130128 LER 82-044/03L-0 on 820916, review revealed that steam & ANDIAULES LEM ME-UN47/UL-U ON MED916, review revealed that steam & feedwater rupture control sys monthly surveillance Procedure BT 5031.14 not completed in time allotted in Tech Space Caused by personnel error Test completed WERNER, B U Toledo Edison Co 82/09/30 Region 3, Office of Director 3pp 15673 041 24X Fiche 50-346.82/09/30,6210130124
- 8210180131 Forwards LER 82-045/03L-0 MURRAY: TO Tolado Edison Co 82/10/04 KEPPLER, J & Region Office of Director 1p 15719 335 24X Fiche 50-346, 82/10/04,
- --8210180137 LER 82-045/03L-O on 820904 auxiliary feedwater pump 1-i, suction valve FW786 observed closed for no apparent reason w/o operator touching close button Cause unknown Valve respense. VALUE FROM TO BE STANDARD TO S
- 8210190254 Forwards LER 82-046/03L-0 MURRAY.T D Toledo Edison Co 82/10/07 KEPPLER, J Q Region 3, Office of Director 1p 15742 143. 24X Fiche 50-346,82/10/07, 8210190254
- --821017026i LER 82-046/03L-0 on 820708, high decay heat flow alarm received Decay heat flow pump 2 & high pressure injection flow Pump 2 found not running Caused by failure af 24-volt dc gower supply for buffer cards Power supply replaced IBLEY.T Toledo Edison Co 82/10/07 Region 3. Defice of Director. 2pp 15742 144 24x Fiche 50-346.82/10/07.8210190254.
- 8210190358 Forwards revised LER 79-076/03X-1 HURRAY, T D. Toledo Editon Co 82/10/11 KEPPLER, J. O Region 3, Office of Director 1p. 15742 098 24X Fiche 50-346,82/10/11, 8210190358
- --8210190359 Revised LER 79-076/03X-1 on 790708, core flood tank 1-1 level alarm received Caused by faulty amplifier in level transmitter LT-CF382, resulting in incorrect reading Amplifier replaced & transmitter recalibr BDRYSIAK.M. RICHTER.L. Toledo Edison Co. 82/10/11. Region 3, Office of Director 2pp 15742 099 24X Fiche 50-346,82/10/11, 020100350 8210170358
- 8210250270 Forwards LER 82-047/03L-0 MURRAY, T D Toledo Edison Co 82/10/12, KEPPLER, J Q. Region Office of Director, 1p 15791 045, 24X Fiche: 50-346, 82/10/12,
- --8210250279 LER 82-047/03L-0 on 820913 & 15 containment radiation trip occurred Caused by component failure of output radiation monitor RE-2004 on safety features actuation sys Channel 1 Operational amplifier & output transistor replaced ELDRED. D T Toledo Edison Co 82/10/12 Region 3. Office of Director 3pg 15791 046 24X Fiche 50-346, 82/10/12, 8210250270,
- 6210250226 Forwards LER 82-048/03L-0 MURRAY, T. D. Toledo Edison Co. 62/10/14 KEPPLER, J. G. Region 3, Office of Director. Ip. 15788:358 24X Fichs 50-346,82/10/14, 6210250226
- ~-8210250231 LER 82-048/03L-0 an 620917, during flushing of vent line on concentrate storage tank, open fire door 101a blocked w/ temporary hose. Caused by personnel error General orientation training modified to require training on fire doors 6ENIUK.P Toledo Edison Co 82/10/14. Region 3, Office of Director 3pp. 15788:359 24% Fiche-50-346, 82/10/14,8210230226.
- 8210280075 Forwards LER 82-049/03L-0. MURRAY, T D Toledo Edison Co 82/10/19. KEPPLER, J Q. Region Office of Director ip 15837-165. 24X Fiche 50-346, 82/10/19, 8210280075
- --8210280078 LER 82-049/03L-0 on 820920 & 22, Channels 2 & 3 on containment post-accident radiation monitor RE 45978A were reading high Caused by problem in microprocessor seftware.

 New set of software installed & faulty actuator replaced.

 ELDRED, D T Taledo Edison Go. 82/10/19 Region 3, Office of Director. 2pp. 15837 166. 24X Fiche:50-346,82/10/19,8210280075
- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1 F. Security, medical, emergency & fire protection plans
- 8210010176 Ack receipt of 820827 ltr re emergency exercise scheduled
- For Feb 1983 STORR.J. Division of Emergency Preparedness & Operational Support. 82/09/17 MCDOMALD.R P Alabama Power Co. 1p. 15570 3AO 24X Fiche 50-348, 82/09/17, 8210010196.

- 8210010195 Forwards Revisions 4 & 5 to security plan Revisions withheld CLAYTON, F L Alabama Power Co 82/09/21 VAROA, B A NRC No Deteiled Affiliation Divan ip 15567 313 24X Fiche 50-348, 82/09/21, 8210010195
- B210190066 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records B2/10/01 Occument Management Branch Ip 15761 060 24X Fiche 50-348,82/10/01, 0210190044
- --B210190073 Public version of emergency pien implementing procedures, including Procedures FNP-0-EIP-11 re handling of injured presonnel & FNP-0-EIP-18 re site aree emergency Procedure request forms enci
 4 Alabama Power Co B2/09/21 35pp 13761 061 24X
 Fiche 50-348, B2/10/01. B210190066
- 8210180004 Forwards IE Safeguards Insp Repts 50-348/82-23 & 50-364/82-22 on 820921-24 No noncompliance noted VERRELLI.D Division of Project & Resident Programs 82/10/12 MCDDNALD.R P Alabama Power Co 2pp 15720 025 24X Fiche.50-348,82/10/12,8210180004
- --8210180007 IE Bafeguards Insp Repts 30-348/82-23 & 50-364/82-22 on 820921-24 No noncompliance moted Major areas inspected security plan & implementing procedures & security organization Details withheld (ref 100FR73, 21) STANSBERRY, W W , MCOUIRE, D R Division of Engineering & Technicel Programe 82/10/08 lp 15720 027 24X Fiche 50-348,82/10/12,8210180004
- 8210280158 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs to require audit on emergency preparadness program every 12 months, per 10CFR50, 54(t) & Oeneric Ltr 82-17 No amend fee required SER encl CLAYTON, F. L. Alabama Power Co. 82/10/25 VAROA, 8 A. Dffice of Nuclear Reactor Regulation, Director 2pp. 15837-194. 24X Fiche 50-348, 82/10/25, 8210280158
- --8210280165 Proposed Tech Specs, Section 6 5 2 8 requiring audit of emergency preparedness every 12 months, per 10CFR50 54(t) & Oeneric Ltm 82-17 4 Alabama Power Co 82/10/25 3pp 15837-196, 24X Fiche 50-348,82/10/25,8210280158

M Antitrust correspondence

- 8210060179 Notifies of Debevoise & Plimpton change of address as of 821001 Affirmation of Svc encl * Debevoise & Plimpton 82/10/01 3pp. 15614 108, 24X Fiche 50-349, 82/10/01, 8210050179
- P Operating license stage documents & correspondence
- 8210010008 Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems. Forwards documents listed in App A. FELTON.J M. Division of Rules and Records 82/06/28 UDELL.R.A Critical Mass Energy Project 15pp 13727, 005 24X Fiche 50-000. 82/06/28.82100100008.
- --8008050265 Discusses addl required into to better define potential for cracking in reactor vessel nozzles.

 NOONAN, V. S. Assistant Director for Materials & Qualifications Engineering. 80/05/05, TEDEBCORR L Assistant Director for Licensing. 2pp 15727-176 24X Fiche: 30-000, 82/06/28, 8210010008
- 8210010227 Confirms B20820 telcon arrangements re B20930 meeting w/util in Region 2 ofc to discuss fuel rod degradation resulting from baffle water-jet impingement Proposed agenda encl. O'REILLY, J.P. Region 2, Office of Director. 82/09/03, HCDONALD, R P. Alabama Power Co. 2pp 15557:336, 24X Fiche: 50-348, 82/09/03,8210010227.
- 8210280158 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs to require audit on amergency preparedness program every 12 months, per 10CFR50.54th & Generic Ltr B2-17. No amend fee required, SER encl CLAYTON, F.L. Alabama Power Co. 82/10/25, VARQA, 8.A. Office of Nuclear Reactor Regulation, Director 2pp. 15837.194, 24% Fiche: 50-349, 82/10/25, 8210280158,
- --8210280165 Proposed Tech Specs, Section 6, 5, 2, 8 requiring audit of emergency preparedness every 12 months, per 10CFRSO, 54(t) & Generic Ltr 82-17 **

 **A labema Fouer Co. 82/10/25, 3pp. 15837; 176, 24X

 Fiche: 50-348, 82/10/25, 8210280158,

- Q Inspection reports, IE Bulletins & correspondence
- 8210070097 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Usell FDIA Request 81-313 Forwards documents listed in App B FELTON.J M Division of Rules and Records 82/08/10 LCN9, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000: 82/08/10: 8210070007
- --8210070137 Forwards tabulated data on steam generator insp & saint si facilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VAROA.S Operating Reactors Brench 1 5pp 15445 131 24X Fiche 50-000,82/08/10,8210070007
- 8210010204 Forwards IE Inep Repts 50-348/62-21 % 50-364/62-20 on 820802-06 No noncompliance noted DANCE-H C Region 2. Office of Director 82/08/30 MCDDNALD-R P Alabama Power Co 2pp 15567 314 24X Fiche 50-348.82/08/30, 8210010204
- --8210010208 IE insp Repts 50-348/82-21 & 50-364/82-20 on 820802-06.No noncompliance noted Major areas inspected gipe supports & restraints & Types B & C containment leak rate testing BROOXB, E. JAPE, F. Division of Engineering & Technical Programs 82/08/25 4pp 15567-316 24X Fiche 50-348,82/08/30.8210010204
- 8210010043 Concurs w/actions outlined in util 820812 ltr re inspared in the line of line o
- 9210150072 Ack receipt of 820707 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/92-17 & 50-364/82-18 DANCE.H C Division of Project & Resident Programs 82/10/04 MCDDNALD.R P Alabama Power Co ip 15701 253 24X Fiche: 50-348.82/10/04.82/10/5040
- --8210150074 Responds to NRC 820818 itr re-violations noted in 1E Insp. Repts 50-348/82-19 & 50-344/82-18 Corrective actions Form NRC-3 posted at low level radwaste bldg CLAYTON.F L Alabama Power Co 82/09/09 DANCE.H C Region 2. Office of Director 2pp 15701 254 24X Fiche 30-348,82/10/04. 8210150072.
- --8210150078 Forwards IE Insp Repts 50-348/82-19 & 50-364/82-18 on 820726-30 & notice of violation DANCE, H C Division of Project & Resident Programs. B2/08/18 HGDDNALD, R, P Alabama Power Co 2pp 15701-256 24X Fiche. 50-348, 82/10/04, 8210150072
- --8210150082 Notice of violation from insp on 820726-30
 * Division of Project & Resident Programs 82/08/18 15701 258 24% Ficher 50-348,82/10/04,8210150072
- --8210150086 IE Insp Repts 50-348/82-19 & 50-364/82-18 on 820726-30 Noncompliance noted Form NRC-3. "Notice to Employers." not posted in new low level waste storage facility. PEERY.W H. BARR.K P Division of Engineering & Tachnical Programs 82/08/16 5pp 15701.259. 24X Fiche 50-348.82/10/04.8210150072.
- 8210220229 Forwards IE Insp Repts 50-348/82-22 & 50-364/82-21 on 820816-0915, No noncompliance noted DANCE, H. G. Division of Project & Resident Programs 82/10/04 MCDCNALD, R. P. Alabama Fouer Co. 2pp 15776.233, 24X Fiche: 50-348, 82/10/04, 8210220229.
- --8210220232 IE Insp Repts 50-348/82-22 % 50-364/82-21 on 8208]6-0913
 No noncompliance noted Hajor areas inspected:monthly surveillance & maint observation operational safety verification, plant tripe & LERs.
 BRADFORD. H. H., BROHNLEE, V.L. Division of Project & Resident Programs 82/10/04 7pp 15776 235. 24X Fiche:50-348,82/10/04,8210220229.
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Beeds." Svc list encl.
 COBB.L I. Division of Fuel Facilities, Materials & Gafeguards 82/10/06. Consolidated Edison Co. of New York. & App. 15761-252 24X Fiche: 50-000: 82/10/06, 8208190233.
- 8210180004 Forwards IE Safeguards Insp Repts 50-348/82-23 & 50-364/82-22 on 820921-24. No noncompliance noted. VERRELLI, D. Division of Project & Resident Programs. 82/10/16 MCD0MALD.R P Alabama Power Co. 2pp. 15720.025, 24X Fiche: 50-348, 82/10/12, 8210180004.

- -- P210180007 IE Safeguards Insp Repts 50-348/82-23 & 50-344/82-22 on 820-21-24 No noncompitance noted Major ereas inspected. security plan & implementing procedures & security organization Details withheld (ref 100FR73, 21) STAMSBERRY, W W. MCGUIRE, D R Division of Engineering & Technical Programs 62/10/08 ip 15720 027 24X Fiche 50-348,82/10/12, 82:0180004
- ECOB190238 if Bulietin B2-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter-Stainless Steel, Recirculation Sysfians at BWR Plants " Svc list and Expounds to Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 6208170238
- E210280410 Natification of 821029 masting w/util.Franklin Research Ctr & Brichtei in Dathesda MD to review calculations & cathodology re IE Bulletin 80-11. "Maschry Halls " REEVES! EA Operating Reactors Branch 1 82/10/20 VARGA, B. Operating Reactors Branch 1 2pp 15859 332 24X Fiche 50-348, 82/10/20, 8210280410
- R Pariodic operating reports & related correspondence
- E210190722 Forwards monthly operating lept for Sept 1982 CLAYTON, F. L. Alabama Power Co. 82/10/12 Management Information Stanch ip 15735 301 24% fiche 50-348, 82/10/12, 8210190722
- --P210190723 Honthly operating rept for Sept 1982 HAIRSTON-B 0 Alabama Power Co 82/10/04 Epp 15736-302 24X Fichs 50-348,82/10/12:8210190722
- S Reportable occurrences. LERs & related correspondence
- 6210070470 Discusses 810317 inadvertent actuation of safety injection mys Event caused by operator error during surveillance tracting & raises concern of potential common mode failure for faisel engines w/turbocharges CHIRAHAL. M Director's Office 81/04/24 HICHELSON, C Director's Office 2pp 15644-349 24X Fichs 50-348,81/04/24,8210070470
- B21Q-070111 Reviews purge valve info contained in T Austin 810306 memb Primary technical issue relates to valve operability during expected accident conditions Vital areas of concern not addressed in info include lower torque margin for closure BROWN,E J Director's Office 81/09/24 MICHELSON,C Director's Office 4pp 15646 359 24X Fiche: 50-348,81/09/24,8210070111
- 8210010038 Responds to FOIA request for 19 categories of documents re nuclear reactor syents & safety problems Forwards documents Itsted in App A FELTONI, J M Division of Rules and Records 82/06/28 UDELL,R,A Critical Mass Energy Project 15pp 15727 005, 24X Fische 50-000,82/06/28,8210010008
- --BR10030027 Discusses proposed watch list item potential common mode failure of dissel generators ACOD sequence coding & search procedure (SCSP) will be revised to include "fire" as searchable item to enable monitoring of similar events CHERAMAL, M. Office of Management and Program Analysis B1/04/24. MICHELSON, C Office of Management and Program Analysis Rpp 15729 044 24 Fiche: SO-000, 82/06/28, 8210010008
- B210010129 Forwards LERs 82-037/03L-0 & 82-052/03L-0 CLAYTON, F L Alabama Power Co 82/09/27 Region 2, Office of Director 19 13567 227 24X Fiche. 50-348, 82/09/27, 8210010129.
- --B210010139 LER 82-052/03L-0 on 820831, during control room emergency ventilation performance test, 8 train emergency air cleanup sys failed to mest acceptance criteria Caused by failurs of charcosi filter to meet efficiency requirements, HATRSTON, U. O Alabama Power Co 82/09/27 Repion 2, Office of Director 1p 19567 228 24X Fiche 50-348, 82/09/27, 8210010127,
- --8210010147 LER 82-037/03L-0 on 820905, A train auto trip logic for high steam ganerator differential pressure declared inoperable when failed cord indication received by automatic tester Caused by failures of universal card. Card replaced HAIRSTON, W O Alabama Fower Co 82/09/27 Region 2, Office of Director. ip 15567 229 24X Fiche 50-348,82/09/27,8210010127.
- 8210190409 Forwards LER 82-053/03L-0 CLAYTON:F L Alabama Power Co 82/10/08 Region 2, Office of Director. ip 15740 007. 24% Fiche, 50-348, 82/10/08, 8210190409,
- --B210190614 LER 82-053/03L-0.on 820912, containment atmosphere particulate radioactivity monitoring sys R-11 declared inoperable due to filter paper not advancing, Caused by failure of paper drive motor Notor replaced.

 HAIRSTON.H. Q Alabama Power Co. 82/10/08. Region 2, Office of Director ip. 15740:008 24X Fiche: 50-348, 82/10/08. 8210190609

- 82:0260453 Forwards LERs 82-054/03L-0.82-055/03L-0.82-039/03L-0 & 82-040/03L-0
 CLAYTON,F L Alabama Power Co 82/10/18 Region 2, Office of Director. 19 15806 175 24X Fichs: 50-348,82/10/18,8210260453
- --6210260463 LER 82-054/03L-0 on 820920, flow transmitter FT-497 failed low Caused by failure of NLP printed circuit card in 7300 process control sys Card repiaced & instrumentation koop associated w/transmitter returned to svc HAIRSTON: N Q Alabama Power Co 82/10/18 Region 2, Office of Director ip 18806 196 24% Fiche 50-348, 82/10/18, 8210260453
- --8210240470 LER 82-055/03L-0 on 820921, train 8 chloring detector declared inoperable due to nonadvancing detector tape Causad by faulty tape drive motor. Motors & light diffusion disc raplaced.

 HATRBTUN.H O. Alabama Power Co. 82/10/18 Region 2, Office of Director 1p 15806 197 24X Fiche-30-248, 82/10/18, 8210260453
- --8210260480 LER 82-039/03L-0 on 820919, svc water to component cooling water HX 2C isolated Causad by dislodged pin holding worm drive gear allowing differential pressure across valve disc to close valve Pin reinstelled & secured.
 HAIRBTON.H.O. Alabama Power Co 82/10/18 Region 2, Office of Director 1p 18805-198 24X Fiche 50-348-82/10/18, 6210260453
- --8210260490 LER 82-040/03L-0 on 820919.ioxs-of-voltags protection channel associated M/B2F sequencer phase 2-3 declared inopstable Gaused by failure of loss-of-voltage relay 27XF1 during testing Relay cleaned HAIRBTON.W O Alabama Power Co 82/10/18 Region 2, Office of Director 1p 15804 197 24X Fiche 50-34B,82/10/18.8210240453
- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8210190134 Forwards questions relactions of DE River Basin Commission in Point Pleasant Diversion Projectiper 820831 invitation. SCHWENCER.A. Licensing Branch 2 82/09/16 HANSLER, 0 Delaware River Besin Commission 5pp 15761.239 24X Fiche.50-352.82/09/16, 8210190134
- 8210030479 Forwards request for addi info re environ review, 9chedule for responding to questions requested within 7 days 9CHWENGER, A Licensing Branch 2 62/09/21 BAVEH, E O Philadelphia Elactric Ca 11pp 15626, 263, 24% Fiche 50-352, 82/09/21, 8210050479
- 8210040352 Forwards responses to 820708 potentially generic concerns re adsquacy of design margins of QE Mark II pressure suppression containment sys KEMPER. J. 8 Philadelphia Electric Co 82/09/30. 8CHMENCER, A. Licensing Branch 2 50pp 15589 QPB. 24X Fiche 50-352, 82/09/30, 8210040362
- 8210050326 Forwards supplemental util comments on Del-Aware Unlimited request for suppension or revocation of CP & corrected Page 14 of 820703 comments.

 CONNER. T. B. Conner & Wetterhahn 82/07/30, DENTON, H.R. Office of Nuclear Reactor Regulation, Director 21pp, 15608:162, 24X Fiche: 50-352:82/07/30.8210050326
- 8210180311 Summary of 820624-25 meetings w/util in Pottstown.PA re applicant response to NRG 820323 info request concerning probabilistic rist assessment. Attendee list encl ABELSON.H Licensing Branch 2. 82/10/05. Licensing Branch 2. 6pp 15746 011 24X Ficks 50-352, 82/10/05, 8210180311.
- 8210270167 Notification of 821017-22 meetings w/util & Bechtel in Ban Francisco,CA to discuss structural engineering design audit ABELSON:H Licensing Branch 2. 82/10/05. BCHHENCER.A. Licensing Branch 2. 4pp. 15876-230 24x Fiche: 50-352.82/10/05,8210270167.
- 8210150124 Forwards Revision 5 to "Probabilistic Risk Assessment" for facility, consisting of responses to NRC 820810 request for add1 info & corrections to typographical errors 8RADLEY.E J. Philadelphia Electric Co 62/10/12 8CHWEMCER.A R. Licensing Branch 2. ip. 15706:134. 24X Fichs: 50-352,82/10/12.8210150126.
- --8210150133 Revision 5 to "Probabilistic Risk Assessment."

 * Philadelphia Electric Go 62/09/30. 214pp 15706; 136. 24X
 Ficher50-352, 82/10/12, 8210150126.
- 8210260158 Advises that response to License Qualifications Branch 820901 request for add! Info will be submitted via FSAR revision in Dec.1982
 BRADLEV.E.J. Philadelphia Electric Co. 82/10/22. SCHWENCER.A. Licensing Branch 2. 2pp. 15799.010. 24X Fiche 50-952,82/10/22,8210260158

- C Utility Environmental Report (ER), amends & correspondence
- 8210150397 Forwards Affidavit of Svc re distribution of Ravision 10 to FBAR & Revision & to environ rept, per NRC 810706 itr BRADLEY, E J Philadelphia Electric Co. 82/10/12 DENTON. H. R Office of Nuclear Reactor Regulation, Director 5pp 15703 281 24X Ficha 50-352,82/10/12,8210150397
- F Security, medical, emergency & fire protection plans
- 8209:70149 Forwards util response to NRC 820728 comments on physical security plan Response withheld (ref 10CFR2 790), Affidavit requesting that response be withheld from public disclosure encl BRADLEY, E.J. Philadelphia Electric Co. 82/09/19, DENTON, H.R. Office of Nuclear Reactor Regulation, Director, App. 14907, 250 24X Fichs 50-392, 82/09/13, 8209170149
- @ Adjudicatory correspondence
- 8210180204 Application for approval of patition to amend Contentiona V-22.V-23 & V-24 Info new & relevant Certificate of Evc encl.

 8UGARMAN, R. J. Del-Aware Unlimited, Inc. BUGARMAN, R. J. Bugarman, R. J. 82/09/20 Commissioners 6pp. 15718-141 24X

 Fiche 50-352, 82/09/20, 8210180204
- --8210180208 Trial brief supporting request to smend Contentions V-22, V-23 & V-24 Nsw info re Merrili Creek.DE River Basin Commission findings of inadequate weter to supply diversions & Unit 2 cancelation available Certicate of Sec encl SUOARMAN.R J Bal-Aware Unlimited, inc BUOARMAN.R J Sugarman, R J B2/07/20 Atomic Safety and Licensing Board Panel 30pp 13734 320 24% Fiche 50-352,82/07/20,8210180204
- 8210010244 Response opposing DE River Basin Commission motion to quash subscena Intervenor does not seek additestimony from O Hansler but believes deposition inedmissible. Certificate of Svc encl Related correspondence SUGARHANIR J Del-Aware Unlimited, Inc BUGARHANIR J Bugarmen, R J 82/09/27 Commissioners 3pp. 13568; 280. 24% Fiche, 30-352; 82/09/27, 8210010244
- 8210180217 Motion to strike EH Bourguard testimony re impacts of intake of biological species. No expertise shown by witness re subjunctor of testimony Related correspondence SUOARMAN.R.J. Del-Aware Unlimited. Inc SUOARMAN.R.J. Sugarman. R.J. 82/09/27 Commissionere 2pp 15718.101 24X Fiche 50-352.82/09/27.8210180217
 - for change of hearing schedule, for consolidation all uss & to strike NRC testimony, ASLB should inclusion to Commission Certificate of Byc

ted, Inc. SUGARMAN.R.J Sugarman, s, 16pp. 15718,064 24%

rension of proceedings & T-rushce of initial

BUGARMAN, R J. 15718: 080.

- 8210180224 Motion to strike MT Hasnik testimony due to prejudice bias & fact that testimony not based on FEB Related correspondence 8U0ARHAN R. J. Bel-Auere Unlimited: Inc. 8U0ARHAN R. J. Bugarman R. J. B2/09/27. Commissioners. 3pp. 15718:061. 24X Fiche.50-352:82/09/27,8210180224.
- 8210180253 Motion to strike J Lear testimony. Testimony shows extreme bias & goes beyond witness statement of purpose. Related correspondence, SUGARMAN, R. J. Bel-Aware Unlimited, Inc. BUGARMAN, R. J. Bugarman, R. J. B2/09/27 Commissioners. 3pp 15718:056, 24X Fiche: 50-032, 82/09/27, 8210180253.
- 8210040087 Advises that NRC witness A Policostro will be available to testify only on 821004-05. Testimony should be scheduled out of turn.
 HODEDON: A.P. Hearing Branch 2, 82/09/29, BRENNER; L., MORRIB, P. A., COLE, R.F. Atomic Bafety and Licensing Board Panel. 2pp. 15581: 037 24X Fiche: 50-352,82/09/29,8210040087.
- 8210030326 Forwards supplemental util comments on Del-Aware Unlimited request for suspension or revocation of CP & corrected Page 14 of 820703 comments.

 CONNER.T. B Conner & Metterhehm. 82/09/00. DENTON.H. R. Office of Nuclear Reactor Regulation. Director. 21pp. 13608:162. 24X Fiche: 50-332.82/09/30.8210030326

- 821003008B Response opposing Del-Aware 820927 motion to striss NRC testimony of J Lehr & MT Maenik. Del-Aware concerned w/wsight to be eccorded testimony, not requirements for receipt Notice of appearance & Certificate of Bvc encl HODDON: A.P. Hearing Branch 2 82/10/01 Atomic Safety and Licensing Board Panel opp 15604 276 24X Fiche, 50-352:82/10/0821005008B
- B210050197 Answer opposing Dei-Aware Unlimited, Inc 820927 motion for mod to hearing schedule, for consolidation or to strike ARC testimony Del-Aware setopped from asserting impropristy or itlegality of ABLB authority on cooling water contentions CONNER.T B Philadelphia Electric Co CONNER.T B Conner & Hetterhahn. 82/10/01 Atomic Safety and Licensing Board Panel 26pp. 15611.129 24X Fiche 50-332, 82/10/01, 8210050197
- 8210050392 Response in opposition to Del-Aware 820927 motion to stritestimony of EH Bourquard ra deeign. configuration & const of Point Pleasant intale Assertions do not affect relevance of testimony or witness qualifications.
 CONNER.T B Philadelphia Electric Co CONNER.T B Conner & Hetterhahn. 82/10/01 Atomic Safety and Licensing Board Famil App. 15608 277 24% Fiche 50-352.82/10/01.8210050392
- 8210070199 Requests schedule for submitting discovery rept be postgoned until all necessary parties available Counsel for all parties involved in hearing on water issues Related correspondence DORGEY, J. A. DORBEY, J. A. Limerick Ecology Action 82/10/04 BRENNER, L. COLE, R. F., MORRIG, P. A. Atomic Bafety and Licensing Board Panel 2pp 15634-267 24X Fiche 50-352,62/10/8210070199
- B210280207 Forwards Commonwealth of PA Public Util Commission 82082 order:Corps of Engineers 820924 notice of intent to issue germit & Commonwealth of PA Dept of Environ Resources 820902 permits HODODON:A P Hearing Branch 2. 82/10/13. BRENNER:L.. MORRIE.P. COLE.R F Atomic Bafety and Licensing Board Panel 79pp. 15839 057 24X Fiche 50-352,82/10/13.8210280207.
- 8210200040 Response opposing Dei-Aware modified Contention V-24
 Contention goes beyond scope of contentions as initially
 submitted & lacks adequate basis & specificity
 Certificate of EVC enci.
 HODDDON.A.P Hearing Branch 2 82/10/15 Atomic Safety and
 Licensing Board Panel 10pp 15755.094. 24X Fiche: 50-352.82/IC
 8210200040
- 8210200066 Answer apposing Dei-Aware Unlimited, Inc revised proposed Contention V-24, Buby of contention previously litigated, rejected by ABLB & irrelevant Certificate of Byc encl CONNER, T, B Philadelphia Ejectric Co. CONNER, T B Conner & Wetterhahn 82/10/15 Atomic Bafety and Licansing Board Panel 33pp. 13754: 140. 24X Fiche, 30-352, B2/10/15, B210200086
- 8210210383 Confirmatory memorandum & order extending time for util, & Limerick Ecology Action to file joint rept on informal discovery until 830124
 BRENNER: A tomic Safety and Licensing Board Panel 82/10/20 15763-201. 24X Ficha.50-352,82/10/20,8210210383.
- 8210220332 Confirming memorandum & order.confirming ABLS 621004 éss of Del-Awere Unlimited.Inc 820927 motion to postpone hearings starting on 821004.ABLS will not be addressing ultimate cost/benefit during hearings.

 BRENNER.L Atomic Safety and Licensing Board Panel 82/10/20 Del-Awere Unlimited, Inc. 5pp. 15775.399. 24X

 Ficher 50-352.82/10/20.8210220332

H General correspondence

- B210130465 Opposes issuance of OL DEAN.V. Affiliation Unknown B2/09/14, BRENNER.L. Atomic Bafe and Licensing Board Panel. 2pp. 15703:048, 24K Fithe: 50-302, 82/09/14, 8210130465
- K. Utility Final Bafety Analysis Report (FBAR) & amends
- 9210150397 Forwards Affidevit of Byc re distribution of Revision if FBAR & Revision 6 to environ rept.per NRC 810706 ltr BRADLEY.E.J. Philadelphia Electric Co 82/10/12. DENICH.H.R Office of Nuclear Reactor Regulation, Director 5pp 15703.291 24X Fiche: 50-352:82/10/12:8210150397

- O Advisory Committee on Reactor Safeguards reporte & correspondence
- 8207180085 Forwarde comments on probabilistic risk assessment etudy in response to 820518 request Lack of completeness noted in consideration of initiating events Total of 3 man-days
- consideration or initiating events local or 5 man-days expended in review DAVIS.P R AFRILIATION Unknown DAVIS.P R ACRS Advisory Consistes on Reactor Safeguards S2/09/05 OKRENT.D ACRS Advisory Committee on Reactor Safeguards Spp 13832:038 24X Fichs 50-352,82/09/05.B207180085
- O Inspection reports, IE Bulletins & correspondence
- P210080019 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety probleme Forwards documents listed in App A Documente in App B completely withheld (ref FOIA Examption 5) 82/07/12 UDELL,R A
 - FLINN.J H Division of Rules and Records 82 Critical Mass Energy Project 7pp 15665.027 Fishe 50-000,82/07/12,8210080015
- --8105040420 Discusses review of util response re insp rept unresolved item identified during post-tensioning fuel pool girders fapacity of anchorage eys is capable of meating design requirements Unresolved item can be closed JORDAN. E. L. Director's Office 81/09/24 MARTIN. T. Region 1, Philadelphia, Office of the Director 2pp 15668 125 24X Fich : 50-000, 82/07/12, 8210080015.
- 8210040224 Forwards "Limerick Generating Station Unit i Preservice Insp Pragram Plan for Nuclear Piping Sys." Vols 1 & 2; in response to NRC 810706 eupplemental request for add info KEMPER.J S Philadelphia Electric Co 82/09/24 BCHMENGER.A Licasing Branch 2 3pp 15591 331 24X Fiche 50-352.82/09/24, 8210040229
- --8210040228 "Preservice Inep Program Plan for Nuclear Piping Sys." Vols 1 & 2 Twenty-two overeize drawings encl Aperture carde are available in PDR are available in PDR + Nuclear Energy Bervice, Inc. 82/07/12 737pp. 18891.334 24X Fichs 50-352,82/09/24,8210040224
- 8210210069 Forwarde IC Insp Repts 50-352/82-12 & 50-353/82-09 on B20908-10 No noncompliance noted
 HARTIM-T T Division of Engineering & Technical Programe 82.
 KEMPER.J B Philadelphia Electric Co. 2pp. 15765.334 24X
 Fiche 30-352,822/10/05.8210210069
- --8210210082 IE Insp Repts 80-352/82-12 & 50-353/82-09 on 820908-10. No noncompliance noted Major areas inspected foundation & backfill matte supporting & proximate to safety-related structures VARELA, A A , DURR, J P Division of Engineering & Technical Programs 82/09/26 5pp. 15765-336 24X Fiche 50-352-82/10/05, 8210210067
- 8208190233 IE Info Notice 80-35, Buppl 1. "Leaking & Dielodged I-125 Implant Seeds," Svc list encl. COBP.L I Division of Fuel Facilities, Materials & Bafeguards. 82/10/06 Consolidated Edison Co. of New York 64pp 15761,250 24X Fiche 50-000.82/10/06,8208190233.
- 8210290208 Forwards IE Insp Repts 50-352/82-11 k 50-353/82-08 on B20816-0917 No noncompliance noted
 STARGSTECKI, R Division of Project & Resident Programs 82/10/08
 KEMPER, J S Philadelphia Electric Co. 2pp. 15853-275
 24X Fiche 50-352, 82/10/08, 8210290208
- --8210270210 IE Insp Repts 50-352/82-11 & 50-353/82-08 on 820816-0917 No noncompliance noted Major areas inspected electrical cable pulling-housekesping-welding & small-borne pipe supports CHAUDHARY. 8. K., HCCABE. E. C. Division of Project & Resident Programs 82/10/16. 2pp 15853 277. 24% Fiche 50-352, 82/10/08, 8210270208
- 8210220367 Ack receipt of BR0921 ltr informine NRC of stepe taken to correct violations noted in IE Insp Rept 50-352/82-10
 MARIIN-T.Y Division of Engineering & Technical Progrems 82/10/1
 KEMPERIJ.S Philadelphie Electric Co. 1p. 15779-194 24X
 Fiche.50-352,82/10/13,8210220367. 82/10/13.
- --8210220374 Responds to NRC 820824 ltr re violations noted in IE Insp Rept 50-352/82-10 Corrective actions: 100X insp of all Rept au-32/82-10 Corrective actions: 100x insp or --previously inspected instrument supports performed &
 trashing course on instrument installation conducted.
 KEMPER, J B. Philadelphía Electric Co. B2/09/21. HA
 Region I, Office of Director. 4pp 15779.195. 24X
 Piche.50-352,82/10/13,8210220367. HAYNES, R. C.

- 8208190238 IE Bulletin 82-03, "Btress Corrosian Cracking in Thick-Wall, Lerge-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche: 50-000, 82/10/14, 8208190238.
- T Hearing transcripts on non-antitrust matters
- 8210060234 Transcript of 821004 hearing in Norristown, PA Pp 738-961 Bupporting documentation enti 4 Atomic Befety and Licensing Board Panel 82/1 15621 226 24% Fiche 50-352,82/10/04.8210060234 82/10/04 299pp
- 8210070097 Transcript of 821005 hearing in Norristown, PA Pp 962-1,274 Supporting documentation encl.

 # Atomic Bafety and Licensing Board Panel 82/10/05 360pp
 15629 354 24X Fiche 50-332, B2/10/05, B210070097
- 8210080050 Transcript of 821006 hearing in Norristown PA Pp 1,275-1,531. Supporting documentation and * Atomic Safety and Licensing Board Panel 82/10/06 349pp. 15643-297 24% Fichs 50-352.82/10/06.8210080050
- 8210120183 Transcript of 821007 hearing in Norristown, PA Pg 1,532-1,728 * Atomic Bafety and Licensing Board Panel 82/: 15655.215 24X Fiche 50-352,82/10/07,8210120183 82/10/07 199pp.
- 8210130239 Transcript of 821008 OL hearing in Morristown, PA Pp 1,729-2,025 Supporting documentation encl * Atomic Safety and Licensing Doard Panel 82/10/08 323pp 156/4:162. 24X Fiche 50-352.82/10/08.8210130239.
- 8210200020 Transcript of 821018 hearing in Betheada.MD 8p 2,026-2,236 Eupporting documentation encl. * Atomic Safety and Licensing Board Panel 82/10/18 221pp 18736 331 24% Fiche 30-332.82/10/18.8210200020.
- 8210210104 Transcript of 821019 hearing in Bethesda, MD. Pp 2,237-2,505 Bupperting documentation encl # Atomic Safety and Licensing Board Panel 82/10/19. 283pp 15766-360 24X Fiche 50-352.82/10/19.8210210104.
- 8210260130 Transcript of 821022 hearing in Bethesda, MD Pp 3,078-3,374 Supporting documentation encl.

 + Atomic Befety and Licensing Board Panel. 82/10/22. 303pp. 15801 046 24% Fiche 80-352,82/10/22,8210260130.
- 8210270062 Transcript of 821025 hearing in Bethesda, MD. Pp 3,375-3,741 Supporting documentation and a story of the 82/10/25 561pp.
- 8210280173 Transcript of 821026 hearing in Bethesda, ND Pp 3,742-4, 038, Rupporting documentation encl.

 * Atomic Safety and Licensing Board Panel. 82/10/26. 312pp.
 15842 136. 24X Fiche 50-352,82/10/26,8210280173.
- DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8210190134 Forwarde questione re actions of DE River Basin Commission in Point Pleasant Diversion Project per 820831 invitation. SCHHENGER, A. Liceneing Brench 2. 82/09/16. HANBLER, O. Delaware River Basin Commission Spp. 13761: 239. 24% Fiche: 30-332, 82/09/16. 8210190134
- 8210050479 Forwards request for addl info re environ review Bchedule for responding to queetions requested within 7 days 8CHMENCER.A. Liceneing Branch 2. 82/09/21 BAUER, E, 0 Philadelphia Electric Co. 11pp. 15426:263, 24X Fiche.50-352,82/09/21.8210050479.
- 8210040362 Forwards responses to 820708 potentially generic concerns re adequacy of design margins of 9E Mark II pressure suppression containment sys. KEMPER, J.S. Philadelphia Electric Co. 82/09/30. BCHHENCER, A. Licensing Branch 2. 30pg. 18589.028. 24X Fiche 50-352,82/09/30, prioriced. B210040362.

- 8210050326 Forwards supplemental util comments on Dal-Aware Unlimited request for suspension or revocation of CP & corrected Page 14 of 820903 comments CONNER.T D Conner & Mettathahn 82/09/30 DENTON.H R Office of Nuclear Reactor Regulation, Director 2ipp. 15608 162 24X Fiche 50-352.82/09/30.8210050326
- 8210180311 Summary of 820624-25 meetings w/util in Pottstown.PA reapplicant response to NRC 820323 info request concerning probabilistic risk assessment Attsndee list and ABELEON.H Licensing Branch 2 82/10/05 Licensing Branch 2 6pp 15746 011 24X Fiche 50-352.82/10/05,8210180311
- 8210290167 Notification of 821019-22 mastings w/otil & Bachtei in San Francisco, CA to discuss structural engineering design audit ABELSON: H Licensing Brench 2 82/10/05 BCHMENCER, A Licensing Branch 2 4pp 15876 230 24X Fichs 50-352,82/10/05,82/0290167
- 6210150126 Forwards Revision 5 to "Probabilistic Risk Assessment" for facility, consisting of rasponess to NRC 6200810 raquest for add1 info & corrections to typographical errors

 RABLEV. E. J. Philadelphia Electric Co. 62/10/12 SCHHENCER, A. R. Licensing Branch 2 ip 15706 134 24% Fiche 50~352,82/10/12,8210150126
- --8210150133 Revision 5 to "Probabilistic Risk Assassment" * Philadalphia Electric Co 82/09/30 214pp 15706 136 24X Fiche: 50-352, 82/10/12, 8210150126
- 8210260158 Advises that response to License Qualifications Branch 820701 request for addl info will be submitted via FBAR ravision in Dec.1982
 BRADLEY.E J Philadalphia Electric Co 82/10/22 SCHWENCER, A Licensing Branch 2 2pp 15799 010 24X Fiche.50-352.82/10/22.8210260158
- C Utility Environmental Report (ER), amends & correspondence
- 6210150397 Forwards Affidavit of Svc re distribution of Revision 10 to FBAR & Revision 6 to anviron raps, per NRC 810706 ltr BRADLEY, E. J. Philadalphia Electric Co. 62/10/12 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 5pp 15703 281. 24X Fichs 50-382, 62/10/12, 8210150397
- F Security, medical, emergancy & fire protection plans
- 8209170149 Forwards util rasponse to NRC 82072B comments on physical security plan Response withheld (ref 10CFR2 790) Affidavit requesting that response be withheld from public disclosure enci BRADLEY, E. J. Philadelphia Electric Co. 82/09/13 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp 14907 250, 24X Fichs. 50-352.82/09/13,8209170149.
- O Adjudicatory correspondence
- 8210180204 Application for approval of patition to amend Contentions V-22.V-23 & V-24 Info new & relevant Certificate of Svc enci.

 SUGARMAN, R. J. Del-Aware Unlimited, Inc. SUGARMAN, R. J. Sugarman, R. J. S2/09/20 Commissioners 6pp 15718, 141 24x Fiche. 30-332, 82/09/20. 8210180204
- --8210180208 Trial briaf supporting raquest to amend Contentions V-22, V-23 & V-24, New info re Merrill Creek.DE River Basin Commission findings of inadequate water to supply diversions & Unit 2 cancelation available. Certicate of Syc encl. BUOARMAN.R. J Bu-Awara Unlimited, Inc. BUOARMAN.R. J Bugarman, R. J 82/09/20 Atomic Bafety and Licansing Board Panel, 30pp. 15734; 320. 24% Fichs. 50-352, 82/09/20, 8210180204.
- B2100:0244 Response opposing DE River Basin Commission motion to quash subposes intervenor does not each addl testimony from O Hansler but believes deposition inadmissible. Certificate of Svc encl Related correspondence.

 SUGARMAN, R. J. Dal-Aware Unlimited, Inc. SUGARMAN, R. J. Sugarman, R. J. B2/09/27 Commissioners. 3pp. 15568:280 24X

 Ficha: 50-352,82/09/27.8210010244
- 8210180217 Motion to strike EH Bourguard testimony re impacts of intexts of fiological species No expertise shown by witness re subjusted or respondence.

 8UGARMAN, R. J. Del-Aware Unlimited, Inc. SUGARMAN, R. J. Sugarman, R. J. 82/09/27, Commissioners. 2pp 15718.101, 24x

 Fiche. 50-352, 82/09/27, 8210180217

- \$210180223 Motion for change of hearing schedule, for consolidation all water cooling issues & to strike NRC testimony ABLB should certify issue of inclusion to Commission Certificate of Sycenci Related correspondence
 SUOARMAN, R J Dei-Aware Unlimited, Inc BUOARMAN, R J Bugarran, R J B2/09/27 Commissioners 16pp 15718 064 24X
 Fiche 50-352,82/09/27,8210180223
- ~-8210180226 Brief supporting motion for suspension of proceedings to consolidation or to strike NRC testimony Issuance of initial decision before full NEPA consideration will substantially prejudice Del-Awara Interests & public in general BUGARMAN, R. J. NEILL. J. M. Del-Awara Unlimited, Inc. SUGARMAN, R. J. SUGARMA
- 8210180224 Motion to strike MT Masnik testimony due to prejudice bias b fact that testimony not based on FES Related correspondence SUGARHAN, R J Bullet Unlimited. Inc SUGARHAN, R J Sugerran, R J 82/09/27, Commissioners Spp 15718 061 24X Fiche 50-352,82/09/27,8210180224
- 8210180253 Motion to strike J Lear tastimony Teetimony shows extract blac & goae beyond witness statement of purpose Related correspondence.
 800ARMAN.R J Dei-Aware Unlimited. Inc R J 82/09/27 Commissioners 3pp 15718 056 24x
 Fiche 30-332.82/09/27.8210180253
- B2100400B7 Advises that NRC witness A Policostro will be available to testify only on B21004-05 Testimony should be echeduled out of turn HODODON, A P Hearing Branch 2 B2/09/29 BRENNER, L, MORRIB, P A, COLE, R F Atomic G
- B210050326 Forwards supplemental util comments on Del-Aware Unlighted request for suspension or revocation of CP & corrected Page 14 of 820903 comments CONNER.T B Conner & Wetterhahn 82/09/30 DENTON.H R Defice of Nuclear Reactor Regulation, Director 21pp 15608 162 24x Fiche, 50-352, 82/09/30, 82/0050326
- 8210050088 Response opposing Dei~Aware 820927 motion to etrika NRC testimony of J Lehr & MT Masnik Del-Aware concerned w/weight to be accorded testimony not requirements for receipt Natice of appearance & Certificate of Svc enci HODODON: A P Hearing Branch 2 B2/10/01. Atomic Sefety and Licensing Board Panel Opp 15604 276 24X Fiche 50-352.02/10/01.
- 8210050197 Answer opposing Del-Aware Unlimited Inc 820927 motion for mod to hearing schedula for consolidation or to strike NRC testimong Del-Aware estopped from asserting impropriety or illegality of ABLB authority on cooling water contantions CONNER.T B. Philadelphia Electric Co. CONNER.T B. Conner & Wetterhahn 82/10/01 Atomic Safety and Licensing Scard Panel 20pp. 13611 129 24x Fiche 50-352,82/10/01.8210050197
- 8210050382 Response in opposition to Del-Awara BR0927 motion to strite treatmony of EH Bourquard we design, configuration & const of Point Pleasant intake Assertions do not affect relevance of testimony or witness qualifications CONNER.T B. Philadelphia Elactric Co. CONNER.T B Conner & Metterhahn R2/10/01 Atomic Bafety and Licensing Board Panel App. 15608.277 24% Fiche 50-352,82/10/01.8210050382
- 8210070199 Requests schedule for submitting discavary rept be postponed until all necessary parties available. Counsy! for all parties involved in hearing on water issues. Related correspondence.

 DORSEY, J. A. Dorsey, J. A. DORSEY, J. A. Limerick Ecology Action 82/10/04 BRENNER, L., COLE, R. F., MORRIB, P. A. Akemic Bafakg and Licensing Board Panel. 2pp 15634.267 24X Fiche.50-352, 82/10.8210070199.
- 8210280207 Forwards Commonwealth of PA Public Util Commission B2081 order, Gorps of Engineere 820924 notice of intent to leave parmit & Commonwealth of PA Dept of Environ Resources 820902 permits HDDDDDN-A.P Hearing Branch 2 82/10/13 BREANER.L , HORRIE.F COLE.R.F. Atomic Bafaty and Licensing Board Panel. 79pp 15839-057. 24X Fichs.50-352,82/10/13,8210280207.
- B210200040 Response opposing Del-Aware modified Contention V-24
 Contention goes beyond scope of contentions as initially
 submitted & lacks adequate basis & specificity.
 Contificate of Evc encl.
 HDD0DDN:A.P. Hearing Branch 2, B2/10/15, Atomic Gafety and
 Licensing Board Panel 10pp 15755:094, 24X Ficher 50-352.82/10,
 8210200040.

- 9210200065 Answer opposing Del-Aware Unimited, Inc revised proposed Contention V-24 Subj of contention previously litigated, rejected by ASLB & irrelevant Certificate of Svc enci CONNER. T B Philadelphia Electric Co CONNER. T B Conner & Wetterhahn 92/10/15 Atomic Bafety and Licensing Board Panel 33pp 15754 140 24% Fiche 50-352, 82/10/15,8210200066
- 82102i0383 Confirmatory memorandum & order extending time for util,NRC & Limerick Ecology Action to file joint rept on informal discovery until 830124 BRENNER, L. Atomic Safety and Licensing Board Panel 82/10/20 3pp 15763
- 8210220332 Confirming memorandum & order confirming ASLB 821004 denial of Del-Aware Unlinited Inc 820927 motion to postpone hearings starting on 821004 ASLB will not be addressing ultimate cost/benefit during hearings REENNER, L Atomic Safety and Licensing Board Panel 82/10/20 Del-Aware Unlimited Inc 5pp 15775 359 24% Fiche 50-352, 82/10/20, 8210220332

H General correspondence

- 0210150459 Opposes issuance of OL BEAN,V Affiliation Unknown 82/09/14 BRENNER,L Atomic Safety and Licensing Board Panel 2pp 15703 048 24X Fiche 50-352.82/09/14,821015045.
- K Utility Final Bafety Analysis Report (FBAR) & amends
- B210150377 Forwards Affidavit of Svc re distribution of Revision iO to FSAR & Revision & to environ rept,per NRC 810706 ltr BRADLEY,E J Philadelphia Electric Co 82/10/12 DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp i5703 281 24X Fichs 50-332,82/10/12,82(0150397
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180085 Forwards comments on probabilistic risk assessment study in response to 820518 request Lack of completeness noted in consideration of initiating events Total of 3 man-days expended in review DAVIS.P R. Affiliation Unknown DAVIS.P R ACRO Advisory Committee on Reactor Safeguards B2/09/05 DKRENT.D ACRB Advisory Committee on Reactor Safeguards 5pp 15852 038 24X Fithe 50-352.82/09/05.8207180085
- O Inspection reports, IE Builetins & correspondence
- 8210040224 Forwards "Limerick Generating Station Unit 1 Preservice Insp Program Plan for Nuclear Piping Sys." Vols 1 & 2, in response to NRC 910706 supplemental request for addl info KEMPER, J S Philadelphia Electric Co 82/09/24 BCHWENCER, A Licensing Branch 2 3pp. 15591 331 24X Fiche 50-352,82/09/24, 6210040224
- 9210210059 Forwards IE Insp Repts 50-352/82-12 & 50-353/82-09 on BZ0908-10 No noncompliance noted.

 MARTIN T T Division of Engineering & Technical Programs 82/10/05 KEMPER, J B, Philadelphia Electric Co 2pp 15765 234, 24X Fiche 50-352, BZ/10/05, BZ10210069.
- --B2102100B2 1E Insp Repts 50-352/82-12 & 50-353/82-09 on 820908-10 No noncompliance noted Major areas inspected foundation & backfill matts supporting & proximate to safety-related structures

 VARELA:A A , DURR, J P Division of Engineering & Technical Programs. 62/09/26 Spp i5765 336 24X Fiche.50-352.82/10/05, 6210210069.
- 8208170293 IE Info Notice 80-95, Suppl 1, "Leaking & Disiodged 1-125 Implant Baeds," Svc list encl. CDBs.L 1. Division of Fuel Facilities, Materials & Bafeguards E2/10/06. Consolidated Edison Co of New York 66pp. 15761 250. 24X Fiche, 50-000, 82/10/06, 8208170233
- 821027020B Forwards IE Insp Repts 50-352/82-11 & 50-353/82-08 on 820816-0917 No noncompliance noted STAROSTECKIR. Division of Project & Resident Programs. 82/10/08 KEMPER, J & Philadelphia Electric Co 2pp. 15853 275 24X Fiche.50-352,82/10/08,8210270208.
- --BR10290210 IE Insp Repts 50-352/B2-11 & 50-353/B2-08 on BR0814-0917 No noncompliance noted Major areas inspected:electrical cable pulling/housekeeping.weiding & small-bore pipe supports CHAUDHARY.8.K., MCCABE.E.C. Division of Project & Resident Programs 82/10/16. 2pp, 15853:277 24X Fiche.50-352,82/10/08,8210290208.

- S208190238 IE Builetin 82~03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Rectroviation Sys Piping at BMR Plants " Svc list enc! DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50~000.82/10/14.8208190238
- T Hearing transcripts on non-antitrust matters
- 8210060234 Transcript of 821004 hearing in Norristown.PA Pp 738-961 Supporting documentation enci * Atomic Sefety and Licensing Board Panel 82/10/04 299pp 15621 226 24X Fiche 90-332.82/10/04.8210060234
- B210070097 Transcript of 821005 hearing in Norristown,PA Pp 962-i,274 Supporting documentation enci * Atomic Safety and Licensing Doard Panel B2/10/05 360pp 15629 354 24% Fiche 50-352,82/10/05,3210070097
- 8210080050 Transcript of 821006 hearing in Norristown,PA Pp 1,275-1,531 Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/10/06 347pp 15643 297 24X Fiche 50-352.82/10/06.8210080050
- B210120183 Transcript of B21007 hearing in Norristown.FA Pp 1.532-1.728 * Atomic Safety and Licensing Board Pane* B2/10/07 199pp 19455 215 24x Fiche 90-352.82/10/07.8210120183
- 8210130239 Transcript of 821008 QL hearing in Norristaum, PA Pp 1,729-2,025 Supporting documentation enci * Atomic Safety and Licensing Doard Panel 82/10/08 323pp 15674 162 24% Fiche 50-352.82/10/08.8210130239
- B210200020 Transcript of B21018 hearing in Bethesda, MD Pp 2,026-2,236 Supporting documentation encl * Atomic Safety and Licensing Board Fanel B2/10/18 221pp 15736 331 24% Fiche 50-352,82/10/18,8210200020
- 8210210104 Transcript of 821019 hearing in Bethesda, MD Pp 2,237-2,505 Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/10/19 283pp 15766 360 24X Fiche 50-352,82/10/17.8210210104
- B210250115 Transcript of B21021 hearing in Bethesda, MD Pp 2,738-3,077 Supporting documentation encl * Atomic Safety and Licensing Board Panel B2/10/21 374pp 15793 074 24% Fiche 50-352.82/10/21,8210250115
- 8210260130 Transcript of 821022 hearing in Bethreda, MD Pp 3,078-3,374 Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/10/22 303pp 15801 046 24% Fiche 90-352,82/10/22,8210260130
- 8210270062 Transcript of 821025 hearing in Bethesda, MD Pp 3, 375-3, 741 Supporting documentation enci * Atomic Safety and Licensing Board Panel 82/10/25 861pp, 15823 035 24X Fiche 50-352, 82/10/25, 8210270062.
- B210280173 Transcript of 821026 hearing in Bethesda, MD, Fp 3, 742-4, 038 Supporting documentation encl * Atomic Safety and Licensing Board Panel B2/10/26 312pp 15842 136 24X Fiche 30-352, 82/10/26, 8210280173
- DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

 G Inspection reports, IE Bulletins & correspondence
- 8210060318 Ack receipt of 820819 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-354/82-07
 8TAROSTECKI,R. Division of Project & Resident Programs, 82/09/30
 MARTIN,T, J Public Service Electric & Oas Co of New Jersey, 1p
 13616 028 24X Fiche 50-334,82/09/30,8216060318
- --8210060326 Responds to NRC 820722 ltr re violations noted in IE Insp Rept 30-354/82-07 Corrective actions vendor procurement quality supplier plan amended to require bend testing of Neison studs per AMB D1.1 requirements MARTIN.T J Public Barvice Electric & Cas Co of New Jersey. 82/08/19. HAYNES.R.C Region 1. Office of Director. 4pp. 15616-029 24X Fiche 50-354.82/09/30.8210060318
- 8210210091 Forwards IE Insp Rept 50-354/82-10 on 820830-0903, No noncompliance noted.

 MARTIN.T.T Division of Engineering & Technical Programs. 82/10/05

 MARTIN.T.J Public Bervice Electric & Gas Co. of New Jersey. 2pp 18765-321. 24X Fiche: 50-354,82/10/05,82(1021009)

- --8210210097 IE Insp Rept 50-354/92-10 on 820830-0903 No noncompliance noted Major areas inspected electrical & instrumentation review of design procedures & licensee sys to implement & control field design changes
 FINKELA E , BETTENHAUSEN.L Division of Engineering & Technical Programs 82/09/23 App 15765 323 24X Fiche 50-354.82/10/05, 6210210091
- 8208190233 IE Info Notice 90-35, Suppl 1, "Leaking & Disindged I-125 Implant Seeds " Syc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06.8208190233
- 8210210109 Forwards 1E Insp Rept 50-354/82-11 on 820908-10 & notice of violation MARTIN,TT Division of Engineering & Technical Programs 82/10/06 MARTIN,TJ Public Service Electric & Oas Co of New Jersey 2pp 19766 034 24X Fiche 50-394,82/10/06,8210210109
- --8210210117 Notice of violation from insp on 820908-10 * Region 1, Office of Director 82/10/06 lp 15766 036 24% Fiche 50~354,82/10/06,8210210109
- --8210210125 IE Insp Rept 50-354/82-11 on 820708-10 Noncompliance noted failure to follow procedure re reactor pressure vessel internal cleanliness during const GRAYLE H Region 1. Office of Director B2/10/04 App 13766 037 24X Fishe 50-354,82/10/06.8210210109
- 9208190238 IE Bulletin B2-03, "Stress Corrasion Cracking in Thick-Wall, Large-Diameter, Stainless Bteel, Recirculation Sys Piping at BWR Plants" Svc list enci
 DEYMUND, R C Director's Office, Office of Inspection and
 Enforcement B2/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fichs 50-000, 82/10/14,8208190238
- DOCKET 50-355 MOPE CREEK NUCLEAR STATION, UNIT 2

 G Inspection reports, IE Bullstins & correspondence
- 8208190233 I& Info Notice 80-35, Suppl i, "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl COBB.L i Division of Fuel Facilities, Materials & Safeguards 82/10/06 Constitated & Edison Co of New York 6App 15761 250 24% Fiche 50-000, 82/10/06, 8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall. Large-Diameter. Stainless Steel, Recirculation Sys Piping at BNR Plants" Svc list enci OEYOUNGR C Director's Office. Diffice of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000, 82/10/14/8208190228
- DOCKET 59-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
 - 344 Forwards request for add1 info re seismic loading used in a analysis of scram discharge vol piping BLOOD, B J Licensing Branch 1 82/09/23, BCROMANN, E. A. nnsti Gas & Electric Co 3pp 15691 098 24X 50-358, 82/09/23, 8210120344
 - 32 Amend 139 to application for QL, consisting of Revision 87 to ubmittal includes response to NRC 820708 & 22 ltrs remargins of Mark I & II containment sys & piping ion criteria, respectively
 NN.E A Cincinnati Gas & Electric Co 82/09/30 DENTON, H
 of Nuclear Reactor Regulation, Director 2pp 15609, 295, the SO-358, 82/09/30, 8210050332
 - 94 Forwards info addressing implementation of interim actions ntrol of heavy loads discussed in NUREQ-0612 All mactions will be completed prior to fuel loading at ty ... B R Cincinnati Que & Electric Co. B2/10/07 DENTON, H of Nuclear Reactor Regulation, Director 1p. 15678:310, 24x 50-338;82/10/07,8210130274
 - 0297 Tech Specs 3 9 7 & 4 9 7 re crene travel spent fuel storage incinnati Gas & Electric Co 81/06/06 App 15678.311 24x e 50-358,82/10/07,8210130294
 - IB7 Forwards Certificate of 8vc for Amend 139 to application for e in form of Revision 87 to FSAR
 NN.E A Cincinnati Cas & Electric Ca 82/10/09 DENTON, H, R
 of Nuclear Reactor Regulation, Director 2pp 15704, 056
 che 50-358, 82/10/08, 8210150387

- 8210180154 Forwards supplemental Info to 820407 itr re setalic qualification of equipment Info consists of rept. "Seisnic Qualification Rept on ITE Series 5600 Motor Control Ctr "SYLVIA:B R Cincinnati Gas & Electric Co 82/10/12 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 15718 184 24 Fiche 50-356, 82/10/13, 8210180154
- ---8210180163 "Beiseic Quelification Rept on ITE Beries 5600 Motor Conf Ctr." Revision 1 + Structural Dynamics Research Corp 11410 R01 82/10/07. 272pp 15718 185 24X Fiche 50-358, 82/10/13, 8210180154
- 8210290330 Requests, within 20 days of receipt notarized list of all relevant documentation & repts prepared for 820708-09 meetings re welfer qualifications KEPPLER. J O Repion 3. Office of Director 82/10/27 EORGHALDLE & Cinclinati Gas & Electric Co 2pp 15853 051 24X Fiche. 50-358. 82/10/27. 8210290330
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8210260498 Forwards revised rept "Seismic-Stress Analysis of Horizonti Pumps," in response to SER Item 3 10 re specific concerns w/reactor bidg closed cooling water pumps (8092) BORGMANNE A Cincinnati Cas & Electric Co 82/10/21 DENIGN, H F Office of Nuclear Reactor Regulation, Director 1p 15806 324. 20 Fiche 50-338, 82/10/21, 8210260488
- --8210260493 "Seismic-Stress Analysis of Horizontal Pumps "
 MCDONALD.C K McDonald Engineering Analysis Co MC-884
 82/08/30 91pp 15806 325 24X Fiche 50-358.82/10/21,821026048
- G Adjudicatory correspondence
- 8210070402 Brief in support of revised exceptions to ASLD 820621 initial decision Certificate of Byc enci CONNER.T B Conner & CONNER.T B Conner & Wetterhahn 82/10/04 Atomic Safety and Licensing Appeal Panal 57pp 15633 250 24X Fiche 50-358,82/10/04.8210070402
- 8210150449 Motion for leave to file reply brief to applicant & MRC responses to Miami Power Project 820820 petition to reconsider & vacate 820730 order directing ASLB to dismiss Project eight proposed contentions.

 BERNABELL Miami Valley Power Project BERNABELL Government Accountability Project 82/10/11 Commissioners ip 15703 [P 24x Fiche 50-388,82/10/11,8210150449
- --8210150437 Reply to applicant & NRC responses to Miami Valley Pour Project 820820 petition to reconsider & vacate 820730 order directing ASLB to dismiss Project eight proposed contentions Cartificate of Svc enci DEVINE: T, BERNABELL, Miami Valley Power Project DEVINE; T Government Accountability Project 82/10/11 Commissioners 40pp 15703 145 24X Fichs 50-358,82/10/11,8210150449
- 8210210391 Forwards suppl to Miami Valley Power Project 820820 petitis to suspend facility const DEVINE.T Miami Valley Power Project DEVINE.T Obvernment Accountability Project 82/10/18 PALLADINO.N., OIL(NSKY.V., AHEARNE.J F. Commissioners ip 15764 049 24X Ficher 50-338, 82/10/18, 8210210391
- --B210210400 Suppl to Miami Valley Power Project B20820 patition to suspend facility const.including add bases for immediate suspension of const & requested remedy Certificate of Size enci DEVINE, T. Hiami Valley Power Project DEVINE, T. Quvernment Accountability Project S2/10/18, Commissioners 30pp 15764 050, 24X Fiche, 50-358, 82/10/18, 8210210391
- 8210290299 Motion to strike Miami Valley Power Project 821011 tajiy brief supplementing patition for reconsideration of Commission 820730 order & reply to NRC & util responses No permission given to file brief. Certificate of 8vc encl WETTERHAHN, M. J. Cincinnati Cas & Eiestric Co. HETTERHAHN, M. J. Conner & Wetterhahn 82/10/26. Commissioners App. 15833 09c 24X Fichs 50-358,82/10/26,8210290299
- H Ceneral correspondence
- 8209270242 Forwards TH Applegate 1tr to NJ Palladino per telebn request. KEPPLER, J O Region 3. Office of Director 82/09/24 HICKEY,P Shaw, Pittman, Potts & Trowbridge. 1p. 14974 163 24X Fiche: 50-358, 82/09/24, 8209270242

19

- 8209270271 Comments on alleged NRC attempt to cover up teriousness of problems at facility Subj will be brought to attention of Congress & Administration of APPLEGATE.T W Affiliation Unknown 82/09/24 PALLADINO, N J Commissioners ip 14994 166 24X Fiche 50-358,82/09/24, 8209270242
- 210060423 Add1 response to FDIA request for taps recordings of F Oltz 010223 & Obd4 interviews & any other recordings re Zimmer investigation Forwards three tapes of Govt Accountability Project 010226 meeting & R Daker 010203 interview M/o encis fELFON.J M Division of Rules and Records 02/09/29 HICKEY, J P Shaw, Pittman, Patts & Troubridge 1p 15636 253 24x Fiche 00-358, 62/09/29.8210060423

Utility Final Sofety Analysis Report (FSAR) & amends

- 210050302 Amend 139 to application for OL. consisting of Revision 87 to FSAR Bubmittal includes response to NRC 820708 & 22 itrs refestion margins of Mark I & II containment sys & piping ibration criteria, respectively UDROMANN. E.A. Cincinnati Oas & Electric Co. 82/09/30 DENTON. H Diffice of Nuclear Reactor Regulation, Director 2pp 15609 295 244 Fiche 50-386, 82/09/30, 82100500322
- C10150387 Forwards Certificate of Svc for Amend 139 to application for license in form of Revision 87 to FSAR BORGMANN, C. Cincinnati Gas & Electric Co. 82/10/08 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 15704 056 24% Fiche 50-358,82/10/08,8210150387
- 1 Inspection reports, 1E Bulletins & correspondence
- 6210080015 Add) response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON J H Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project 9pp 15645 027 24X Fiche 90~000.82/07/12.8210080015
- --8210080170 Systematic assessment of licensee performance notes refacility evaluation for Oct 1979-Bept 1980 • IRC - No Detailed Affiliation Given 80/09/30 9pp 15668 107 24X Firhe 50-000,02/07/12,8210080015
- 8210080166 Forwards IE Insp Rept 50-358/82-14 on 820831 & 0901-02 & 07 No noncompliance noted PAPERIELLO,C J Division of Emergency Preparedness & Operational Support 82/09/22 BOROMAN,E A Cincinnati Oas & Electric Co 2pp | 15640 144 24X Fiche 50-358,82/09/22,8210080166
- --82100B0171 IE Insp Rupt 50-35B/82-14 on B20B31 & 0901-02 & 07 No noncompliance noted Major areas inspected preoperational equiron monitoring & protection.mgt controls & internal audits & program implementation & results CESTMANN.H J. ROZAK.S., SCHUMACHER.M Region 3, Office of Director B2/09/21 Bpp 13640 146 24X Fiche 50-358,82/09/22,82100B0166
- 6208190233 IE lnfo Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Emplant Seeds " Syc list enci COBB-t. 1 Division of Fuel Facilities, Materials & Safeguards 62/10/06 Consolidated Edison Co of New York 66pp 15761:250 244 Fiche 50-000.82/10/06,8208190233
- 620B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall. Large-Diameter. Stainless Steel, Recirculation Sys Fiping at BMR Plants "Svc list encl DEYBUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14, Consolidated Edison Ca of New York \$15pp 15810 125 24% Fiche 50-000. 82/10/14,8208190238
- 8210190635 Advises of 821019 enforcement conference meeting in Cincinnation to discuss recent insp findings.per 821012 toloom myduti KEPPLER. J O Region 3, Office of Director. 82/10/15 BORGMANN, E A Cincinnati Oas & Electric Co ip 13740 053 24X Fiche 50-338, 82/10/18,8210190635
- 8210290278 Ack receipt of 820723 & 0824 ltrs informing NRC of add1 steps taken to correct violations noted in NRC 820621 ltr & IE Insp Rept 50-358/81-27 NCRELIUS, C E Division of Engineering & Technical Programs, 82/10/26 BORCMANN, E A Cincinnati Gas & Electric Co 3pp 15854 249 24% Fiche 50-358,82/10/26,8210290278

- --8210290281 Supplements \$20824 response to violations noted in 1E Insp. Rept \$0-358/81-27 Tuelve of 34 pipe lugs in process of penetrant eram Twenty-two renaining welds due penetrant inspected BOROMANN. E. A. Cincinnati Gas & Electric Co. 82/09/30 KEPPLER.J G. Region 3. Office of Director 1p 15854 252 24x Fiche 50-358,82/10/26.8210290278
- --8210290285 Amends response to 820723 Itr per 820621 review & comments in initial 820223 response Sampling program for RHR sys inadequate BORGMANN.E A Cincinnati Qas & Electric Co 82/08/24 KEPPLER.J Q Region 3. Office of Director 4pp 15854 253 24x Fiche 50-358.82/10/26.8210290278
- --B210270290 Responds to B20602 ltr re review & comments per 820223 interim ltr concerning adequacy of shop & field welds Full compliance will be achieved by 821001 & will resolve nutual concerns for Items 1.2 & 6 of IE Insp Rept 50-358/881-27 BDROMANN.E A Cincinnati Oas & Electric Co 82/07/23 NORELIUS.C E Division of Engineering & Technical Programs Spp 15854 257 24% Fiche 50-358,82/10/26.8210290278
- 8210270330 Requests, within 20 days of receipt, notarized list of all relevant documentation & repts prepared for 820708-09 meetings re welder qualifications KEPPLER, J O Region 3, Office of Director 82/10/27 BOROMANN, E A Cincinnati Oas & Electric Co 2pp 15853 051 24X Fichs 50-358, 82/10/27, 8210270330
- S Reportable occurrences, LERs & related correspondence
- B210050137 Interim deficiency rept re nonconforming Kerotest packless diaphragm seal valves Valves appear to be open per indication of handwheel position, but are actually closed Resolution undetermined Finel rept expected by 821115
 BORGMANN,E A Cincinnati Gas & Electric Co 82/09/20 KEPPLER, J G Region 3, Office of Director 2pp 15605 050 24X
 Fiche 50-356, B2/09/20, B210050137
- 8210060271 Interim deficiency rept re Item M-33 fittings w/high-stress stamp Util performing documentation reviews & field walkdowns to identify field inscalled fittings which may be stamped improperly Next rept will be submitted 833131 BDROMANN.E A Cincinnati Gas & Electric Co 82/09/22 XEPPLER, J Q Region 3, Office of Director 200 15621 083 24X Fiche 50-358,82/09/22,8210060271
- 8210130372 Interim deficiency rept re possible carbon steel in stainless welds Analysis of weld by Matcut. Inc scheduled to be completed 821008 Results will be provided to NRC by 821115
 BOROMANN,E A Cincinnati Que & Electric Co 82/09/22 KEFPLER, J G Region 3, Office of Director 2pp 15681 167 24X Fiche 50-358, 82/09/22, 8210130372
- 8210060358 Interim deficiency rept re Item M-46 on turning vane failures in HVAC sys Extension of 2 was until 821014 requested to complete further analysis required for scheduled interim rept BORGMANN.E A Cincinnati Qas & Electric Co 82/09/30 KEPPLER, J G Region 3, Office of Director ip 15618 353 24X Fishe 50-338, 82/09/30, 8210060358
- 82:0150443 Interim deficiency rept re diesel generator control logic Initially reported on 820909 Preliminary engineering evaluation concludes that sequence can be corrected by tripping diesel generator w/ESF actuation signal BDROMANN,E A Cincinneti Gas & Electric Co 82/09/30 KEPPLER.J G Region 3. Office of Director 3pp 15703 153 24x Fiche 50-358,82/09/30,8210150443
- 8210060309 Deficiency rept to Item E-27 concerning improperly incorporated DDC Item determined not reportable per 10CFR50 55(e) BDRCHANN,E A Cincinnati Gas & Electric Co 82/10/01 KEPPLER,J Q Region 3, Office of Director ip 15619 194 24X Fiche 50-358, B2/10/01, 8210060309
- 8210190627 PNO-111-82-111 on 821011.util issued stop work order for all assential work activities performed by Catalytic, Inc., involving structural steel & welding rework IE may meeting w/util planned during wk of 821018 to discuss inap findings SCHWEIBINZ.E , HUNTER.D . WARNICKER Region J. Office of Director 82/10/13 1p 15740 033 24X Fiche 50-358,82/10/13,8210190627
- 8210260279 Interim deficiency rept re turning vane failures in HVAC sys Three additellures discovered since 820702 Failures believed to be fatigue induced Failed vanes repaired Testing to continue Next rept by 830115
 BOROMANN.E.A Cincinnati Oas & Electric Co 82/10/13 KEPPLER, J Q Region S, Office of Director 2pp 15803 220 24X
 Fiche 50-358,82/10/13,8210260279

- DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210290063 Forwards "Evaluation & Action Plan for San Onofre Nuclear Cenerating Station Units 2 & 3 re TMI Incident " DRAKE, J H Southern California Edison Co 79/08/ió DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15859 052 24% Fiche 50-361,79/08/ió.8210290063
- --8210290069 "Evaluation & Action Plan for San Onofre Nuclear Generating Station Units 2 & 3 re TMI Incident " Southern California Edison Co 79/08/3i 4Spp 15859 054 24X Fiche 50-361.79/08/16.8210290063
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A Critical Mass Energy Project 15pp 19727 005 Fiche 30-000, 82/05/28, 8210010008 UDELL,R A 82/06/28
- cracking in reactor vassel notiles
 NDONAN,V S Assistant Director for Materials & Qualifications
 Engineering 80/05/05 TEDESCOR L Assistant Director for
 Licensing 2pp 15727 176 24X Fiche 50-000.82/06/28.8210010008
- F Security, medical, emergency & fire protection plans
- 8210190625 Forwards Revision 7 to physical security plan Revision withheld (ref 1005R73 21)
 BASKIN.K P. Southern California Edison Co. 82/10/15 EISENHUT.D.G. Office of Nuclear Reactor Regulation. Director 1p 15740 035 24X Fiche 50-206.82/10/13.8210190625
- G Adjudicatory correspondence
- 62:0040009 Notifies that LJ Chandler will represent NRC at oral argument per ASLAB 820908 order SW Perry of FEMA will be CHANDLER.L J Hearing Branch 2 82/09/24 Safety and Licensing Appeal Panel 1p 155 Fiche 50-361.82/09/24.8210040007 EHDEMAKER.C J Atomic 155B1 315
- 8210050267 Memorandum & order setting medical arrangements question for hearing Listed questions should be answered by all parties. providing expert testimon; where required issue of terminating procedures will be certified to Commission KELLEY, J. Atomic Safety and Licensing Board Panel Opp 1961 155 24X Fiche 50-361.82/10/01.8210059267 B2/10/01
- 82:0060184 Memorandum & order certifying question to Commission of feasibility of ASLB continuing proceeding initiated by ASLB feasibility or non-B221001 order KELLEY, J. L. Atomic Safety and Licensing Board Panel 82/10. Commissioners 4pp 15613 181 24% Fiche 50-361,82/10/05. 82/10/05

- 8210180075 Brief re medical svcs issues certified by Commission order No advance planning required by 10CFR50 47(b)(12) for medical svcs for general public Necessary arrangements can be made on ad hoc basis Certificate of Svc encl CHANDLER, L J Hearing Branch 2 82/10/14 Commissioners 28pp 15719 270 24X Fiche 50-361/82/10/14.8210180095
- 8210220240 Response supporting util 821008 objections to ABLB 621001 prehearing nemorandum & order re medical arrangements
 Scheduling of any hearing should await guidance from
 Commission, resolving certified issues W/Certificate of Svc
 CHANDLER.L. J. Hearing Branch 2 82/10/20 Atomic Safety and
 Licensing Board Panel 7pp 15775 131 24X Fiche 50-%61,82/10/20,8210220240
- P Operating itemme stage documents & correspondence
- 8210010212 Forwards Amend 8 to License NPF-10, safety evaluation be notice of issuance & availability Amend changes date for operability of post-accident sampling sys to Jan 1983 be revises associated Tech Specs (per TMI Action Item [] B 3) EISENHUT.D 0 Division of Licensing 82/09/17 DIETCH.R Boothers California Edison Cu COTTON.C D. BERNATH.L San Diego 03. L Electric Co 4pp 15567 320 24X Fiche 50-361.82/09/17.0210010212
- --82:00:02:15 Amend 8 to License NPF-10, changing date for operability of post-actions among an electric energing date for operable post-actions among associated Tech Specs (par TM1 Action 1tem 11 B 3) EISENHUT, D Q Division of Licensing 82/09/17 5pp 1556-24K Fiche 50-361,82/09/17,8210010212 82/09/17 5pp 1556/ 124
- --8210010222 Safety evaluation supporting Amend 8 to License NPF-10 * Office of Nuclear Reactor Regulation, Director 82/09/17 : 15547 329 24X Fiche 50-361.82/09/17.8210010212
- --8210010229 Notice of issuance & availability of Amend () to License KERRIGAN, J Licensing Branch 3 82/09/17 2pp 1554/,}32 241 Fiche 50-361,82/09/17,8210010212
- 8210210498 Confirms 820908 telephone authorization of Tech Spec changes as requested by 820907 & 08 ltrs re reactor coolant flow-low contained in Table 2 2-1 NOVAK. T M Assistant Director for Licensing 82/09/27 DIFf(II.R Southern California Edison Co COTTON, G D., BERNATIL Gain Diego. Gas & Electric Co 3pp 15772 350 24X Fiche 50-161.82/09/2/. 8210210498
- 8210040117 Proposed Change NPF-10-46 to Tech Spec 3 3 4 re turbine clouduli/ Proposed Change MPF-10-46 to Tech Spec 3 3 4 Fe turbine overspeed protection Change will allow entry into Modes 3 & 2 while preventing possibility of turbine overspeed by requiring MSIVs & bupasses to be closed BASKIN. K.P. Southern California Edison Co. 82/09/30 MERRICAN. J.D. Licensing Branch 3 ip 15614 334 24X Fiche 50-361. 82/09/30. 8210060117
- --8210060119 Proposed Change NPF-10-46 to Tech Spec 3 3 4 allowing entry anto Modes 3 & 2 while preventing possibility of turbing gyerspeed 92/09/30 lp 19814 335 24x Fiche 50-361,82/09/30,8210060117
- 8210070164 Forwards evaluation of Unit 2 license conditions relative to potential applicability to Unit 3 license conditions in response to NRC request BASKIN K P Southern California Eduson Co 82/10/04 KIRRIGAN J D Licensing Branch 3 App 15627 009 24X Fiche 50-361.82/10/04, 3210070144

821007016

- 8210060368 Outlines augmented shift manning requirements for period of initial criticality of Unit 3, for 1-month period after initial attainment of 100% power on Unit 2 & to control rotation of operators between units, per 820720 meeting DIETCH: 8 Southern California Edison Co 82/10/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 13619 033 24% Fiche 50-361.82/10/05,8210060368
- 8210070082 Discusses use of radwaste solidification sys Unit 2 license condition does not prevent util from using Chem-Nuclear Sys. Inc process to solidify wet solid radwaste produced at Unit i Safety evaluation will be performed

 BASKIN.K P Southern California Edison Co 82/10/05
 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15620, 162 24g
 Fiche 50-206, 82/10/05, 8210070082
- 8210130571 Forwards Amend 9 to License NPF-10:safety evaluation & notice of issuance & availabilty, Amend changes Tech Specs to allow operation in Modes 2 & 3 w/turbine overspeed protection systinoperable
 KERRIOAN.J Licensing Branch 3 82/10/07, DIETCH.R Sguthern
 KERRIOAN.J Licensing Branch 3 82/10/07, DIETCH.R Sguthern
 California Edison Co COTTON.G D , BERNATH.L Ban Diego Gas L
 Electric Co 3pp 15677 090 24X Fiche 50-361.82/10/07,821013057g

- --8210130573 Amend 9 to License NPF-10 changing Tech Specs to allow operation in Modes 2 & 9 w/turbine overspeed protection sys inoperable
 - Fiche 50-361 82/10/07.8210130571
- --8210130577 Safety evaluation supporting Amend 9 to License NPF-10 * Office of Nuclear Reactor Regulation, Director 82/10/07 2015679 097 24X Fiche \$0-361.82/10/07.8210130571
- --B210130582 Notice of issuance & availability of Amend 9 to License
 - NERSES, V Licensing Branch 3 82/10/07 5pp 15679 099 24X Fiche 50~361 82/10/07.8210130571
- 8210190560 Forwards corrected page to rept re small earthquake swarm which occurred on 811110 Revised info does not alter conclusions stated in rept

 PASFIN A P Southern California Edison Co 82/10/15 KERRIGAN, J D

 Licensing Branch 3 2pp 15736-137 24x Fiche 50-361,82/10/15, 6210190560
- 6210190534 Notifies that info gained during Unit 2 natural circulation test program will be incorporated into overall Unit 2 & 3 operating training program per NUREO-0737, Item 1 & 1 Listed tests will not be reporated for Unit 3 SASKIN.FP Southern California Edison Co 82/10/18 KERRIGAN.J D Lacensing Branch 3 2pp 15751 314 24X Fiche 50-361,82/10/18. 8210190534
- 6210260416 Forwards Application 13 to amend License NPF-10, revising App A Tech Specs to change response time for ECC8 miniflow values

 DIETCH R Southern California Edison Co 82/10/21 DENTON H R

 Office of Nuclear Reactor Regulation, Director 2pp 15806 294
 24x Fiche 50-361.62/10/21,8210260416
- --6210260424 Application 13 to amend License NPF-10, revising App A Tech Specs to change response time for ECCS miniflow valves DIETCHLR Southern California Edison Co 82/10/21 10pp 15805 296 24% Fiche 50-361,82/10/21,8210260416
- --8210260435 Proposed Tech Specs & 8 2.6 8 3.6 8 4.6 11.4 12 % 6 13 re administrative controls for revision in response time for ECCS miniflow velves 4 Southern California Edison Co 82/10/21 6pp 15806 306 24x Fithe 50-361.82/10/21 8210260416
- O Inspection reports, IE Bulletins & correspondence
- 5210010042 Confirms 821021 mgt meeting in Rosemead, CA to discuss systematic assessment of licensee performance Anticipated meeting attendees & agenda encl CREMS, J. Division of Resident, Reactor Project & Engineering Programs 82/09/27 PAPAY.L T Southern California Edison Co Gpp 15565 317 24% Fiche 50-206.82/09/27,8210010042
- 원교10190478 Forwards IE Insp Repts 50-361/82-27 & 50-362/82-19 on 원교20905-17 No noncompliance nuted BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82/10/05 PAPAY.L T Bouthern California Edison Co 4pp 15740 245 24X Fiche 50-361,82/10/05,8210190478

- 9208190238 IE bulletin 62-03. "Stress Corrosion Cracking in Thick-Mall, Large-Diameter, Stainless Stoel, Recirculation Sys Piping at BMR Plants." Svc list encl DEYDUNO, R C Director's Office. Office of Inspection and Enforcement 62/10/14 Consolidated Edison Co of New York 115pp 15910 125 24X Fiche 50-000, 62/10/14, 8208190238
- 8210250222 Ack receipt of 820929 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/82-25 & 50-362/82-16
 BISHOP,T W Division of Resident, Reactor Project & Engineering Programs 82/10/18 PAPAY,L T Southern California Edison Co 1, 15789 326 24% Fithe 50-361,82/10/18 8210250222
- --3210250227 Responds to NRC 820831 ltr re violations noted in IE Insp Repts 50-361/82-25 & 50-362/82-16 Corrective actions Operating Instruction 5023-2-4 revised on 820831 to include proper caution PAPAY.L T Southern California Edison Co 82/09/29 ENGELKEN.R H Region 5, Office of Director 4pp 15789 327 24x fiche 50-361.82/10/18.8210250222
- S Reportable occurrences. LERs & related correspondence
- 8210050151 Forwards LER 82-080/03L-0 Detailed event analysis submitted RAY.H B Southern California Edison Co 82/09/22 ENGELKEN.R H Region 5, Office of Director 2pp 15609 053 24X Ficha 30-361, 82/09/22,8210050151
- --8210050234 LER 82-080/03L-0 on 820823 during Made 4 feeder breaker testing after returning breaker 2A0101 to svc.feeder breaker 2A0104 failed to open Cause unidentified Event considered isolated No further attion deemed necessary RAV.H 8 Southern California Edison Co 82/09/22 Region 5, Office of Director 1p 15A09 055 24X Fiche 50-361.62/09/22, 8210050151
- 8210050261 Forwards LER 82-076/03L-0 Detailed event analysis submitted RAY, H 9 Southern California Edison Co 82/09/23 ENSELKEN, R H Region 5. Office of Director 2pp 15609 176 24X Fiche 50-361, 82/09/23, 8210050261
- --8210050266 LER 82-096/03L-0 on 920825.ECCS subsystem high pressure safety injection pump 2P-017 feiled to develop 1,400-psia discharge pressure during operability test Caused by excessive leakage past miniflow bypass valve 82-1204-NU-184 RAY.H B Southern California Edison Co 82/09/23 Region 3, Uffice of Director 1p 15609 198 24X Fiche 50-361,82/09/23.8210050261
- 8210030381 Forwards LER 82-i03/03L-0 Detailed event analysis submitted RAY.H B Southern California Edlson Co 82/09/23 ENGELKEN.R H Region 5, Office of Director 2pp 15608 251, 24X Fiche 50-361, 82/09/23,8210050381
- ---8210050390 LER 82-103/03L-0 on 820825.hot leg sample isolation valve 2HV-0517 breater 2BJ-23 tripped on overload in attempt to close valve during semiannual ESF subgroup relay test Caused by burned out operator motor replaced RAY.H B Southern California Edison Co. 82/09/23 Region 5. Office of Director 1p 15608 253 24X Fiche 50-361,82/09/23,8210050381.
- 821005000B Forwards LER 82-098/03L-0 Detailed event analysis submitted RAY.H 8 Southern California Edison Co 82/09/24 ENGELKEN.R H Region 5. Office of Director. 2sp 15605 205 24X Fiche 50-361.82/09/24.821005000B

- --8210050024 LER 82-097/03L-0 on 820925, condentate storage tank T-121 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY, H B Southern California Edison Co 62/09/24 Region 5, Office of Director ip 15604 345 24X Fiche 50-361,62/09/24, 8210050016
- --8210050027 LER 82-102/03L-0 on 820827; condensate storage tank T-121 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY.H D Bouthern California Edison Co 82/09/24 Region 5. Office of Director ip 15604 346 24X Fiche 50-361,62/09/24. 8210050016
- -8210050032 LER 82-104/03L-0 on 820901.condensate storage tank T-121 water level fell below Tech Spec limit Caused by inadequate mateup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY.H B Southern California Edison Co B2/09/24 Ragion 5. Office of Director 1p 15604 347 24X Fiche 50-361,82/09/24, 8210050616
- --8210050037 LER 82-106/03L-O on 820903, condensate storage tank T-121 water level fell below Tech Spec limit Caused by madequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control produced RAY-M B Bouthern California Edison Co 82/09/24 Region 5, Office of Director ip 15604 348 24X Fiche 50-361,82/09/24, 8240050016
- --8210050044 LER B2-108/03L-0 on B20930, condensate storage tank T-121 water level fell below Tech Spec limit Caused by Inadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY.H B Southern California Edison Co 82/09/24 Region 5, Office of Director 1p 15604 349 24X Fiche 50-361,82/09/24, D230050014
- --9210050044 LER 62-107/03L-0 on 62090A, condensate storage bank T-121 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY.H B Southern California Edison Co 82/09/24 Region 5, Dffice of Director ip 13504 350 24X Fiche 50-361,82/09/24,8210030016
- --8210030048 LER 82-110/03L-0 on 820712.condensate storage tank T-121 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAV.H B Southern California Edison Co 82/09/24 Region 5, Office of Director Ip 15404 351 24X Fiche 50-361,62/09/24, 8210050016
- --9210050050 LER 92-111/031-0 on 920709, condensate storage tank T-121 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec tange & automatic level control proposed RAY.H B Bouthern Galifornia Edison Co 82/09/24 Region 5, Office of Director 1p. 15604 352 24X Fiche 50-361.82/09/24, 82/0950016

- --B210130274 LER B2-099/01T-0 on B20913. Train A control room emerging air cleanup sys failed to start after receiving spurious toxic gas isolation signal Caused by improper positioning of tirk ley on breaker 200418 of fan E418

 RAY. H B Bouthern California Edison Co 82/09/27 Regions 5. Office of Director ip 15678 354 247 Fiche 50-361.82/09/27. B210130269
- 8210130278 Forwards LER 82-076/03L-1 Detailed event analysis submitted RAY, H B Bouthern California Edison Co 82/09/30 ENDELKEN, H H Region 5, Office of Director 2pp 15678 t6/ 24x
- --8210130285 LER 82-076/03L-1 on 920725, steam generator indicator 2PDI-0979-1 failed channel check test & was placed in bypass condition prior to Hode 2 entry Caused by Inadvertantly valved out indicator RAY.H B Southern California Edison Co 82/09/30 Registry 5. Office of Director 1p 15678 169 24X Fiche 50 361,82/09/30,8201030278
- B210130497 Forwards LER 82-105/03L-0 Detailed event analysis submitted RAYH B Southern California Edison Co 82/09/30 CNOFLML84. 8 II Region 5, Office of Director 2pp 15683 097 24x Fichs 50-361. 82/09/30, 8210130499
- --8210130508 LER 82-105/03L-0 on 820831, during Mode 2 operation. aviiling feedwater pump 2P-504 declared inoperable Caused by leady threaded plug on pump discharge casing Threads cleaned, graffol applied & plug reinstalled RAY.H B Southorn Catifornia Edison Co 82/09/30 Region 5: Office of Director ip 15883 099 24X Fichs 50-161, 82/09/30, 8210130499
- 8210130469 Forwards LERS 82-107/03L-0.82-119/03L-0.862-121/03L-0. Detailed event analysis submitted RAYH B Southern California Edison Co 82/10/01 FNQFLM6 F2. R H Region 5. Office of Director 2pp 15682 155 24X Fiche 50-361.82/10/01.8210130469
- --8210130478 LER 82-107/03L-0 on 820902.condensate storage tarik T-120 water level fell below Tech Spec limit while in Mode 2 Caused by inadequate makeup water control Corrective actions include better planning & Linely water transfer RAY.H B Southern California Educado Co 82/10/01 Region 5 Office of Director ip 15682 157 24X Fiche 50-161, 122/10/01, 8210130469
- ~~8210130485 LER 82-119/03L-0 on 820719, condensate storage tank [-120 water level fell below Tech Spec limit while in Node 2 Caused by inadequate makeup water control Corrective actions include better planning & timely water transfer RAY. H B Bouthern California Edison Co 82/10/01 Region 3. Office of Director ip 15682 158 24X Ficho 50-361, [12/10/0]. 8210130449
- --8210130493 LER 82-121/03L-0 on 820920, condensate storage tack 1-10 water level fell below Tech Spec limit while in Made 2 Caused by inadequate makeup water control Corrective acts 574 include better planning & timely water transfer RAY.H B Southern California Edison Co 82/10/01 Region 5. Office of Director 1p 15682 159 24X Fiche 50-361, 82/3 0/01 8210130469
- 8210190309 Forwards LER: 82-116/03L-0,82-117/03L-0 & 82-112/03L 0
 Detailed event analysis enc1
 RAY.H D Southern California Edison Co 82/10/08 ENGELMEN.RH
 Region 9, Office of Director 2pp 15742 150 24X
 Ficher 50-361,82/10/08,8210190309
- ~-8210190317 LER 82-116/03L-0 on 820917.condensate storage tank I-10 water level fell below Tech Spec limit Cauced by inadequake makeup water control to tank T-121 & overly restrictive Tech Spec limit Design & Tech Spec change proposed RAY.H B Southern California Edison Co 82/10/00 Region 5 Diffice of Director 1p 15742 152, 24X Fiche 50-361.02/10/06.
- ~-B210190323 LER 82-117/03L-0 on 820918, condensate storage tanh 1-10 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank T-121 & overly restrictive Tech Spec limit Design & Tech Spec change proposed RAY.H B Southern California Edison Co 82/10/08 Region 5. Office of Director 1p 15742'153 24X Fiche 50-361.82710/6. 6210190309
- ~-B210190328 LER B2-112/03L-0 on 820910, condensate storage tank 1-120 water level fell below Tech Spec limit Gaused by inadequals makeup water control to tank T-121 & overly restrictive Tech Spec I init Design & Tech Spac Change proposed RAY.H B Southern California Edison Co 82/10/08 Region & 82/10/08 Office of Director ip 15742 194. 24X Fiche 50-361, 62/10/08 8210190309.

- G210190250 PMO-V-B2-041 on B210DA.Lus Angeles Times investigative reporter contacted Region 5 re former Bechtel Power Corp QC inspector addi allegations concerning welding practices Investigation of allegations planned MIRSCH.D F. BISHOP.T W Region 5. Office of Director B2/10/14 Ip 15742 195 24X Fiche 50-361.B2/10/14, B210190250
- 8210250137 Forwards LER 82-11B/03L-D Detailed event analysis submitted RAY,H B Southern California Edison Co 82/10/15 ENGELKEN,R H Region 5. Office of Director 2pp 157B7 002 24X Fishe 50-361, 82/10/15. 8210250137
- --B210250140 LER 82-118/O3L-0 on 820917, low nitrogen actuator pressure discovered in steam generator feedwater isolation valve 2HV-4052 Caused by leakage at plug to check valve located on accumulator remporary instrument valve installed RAY.H B Southern California Edison Co B2/10/15 Region 5, Office of Director ip 15787 004 24X Fiche 50-361,82/10/15,6210250137
- B210250207 Notifies that followup repts to LERs B2-094 & 82-103 will be provided by 82130 Delay due to addl evaluation needed for torrective action RA/.H B Southern California Edison Co B2/10/15 ENGELKEN.R H Region 5, Office of Director 1p 15787 362 24X Fichs 50-361.82/10/15.8210250207
- 8210259214 Forwards LER 82-115/03L-0 Detailed event analysis submitted RAY.H 8 Southern California Edison Co 82/10/15 ENGELKEN.R H Region 5. Office of Director 2pp 15788 289 24% Fiche 50-361.82/10/15.8210250214
- --0210250218 LER 82-115/O3L-D on 020916, during Mode 2 operation, control etement assembly 47 slipped & dropped in excess of 7 inches Caused by defective timing card Affected solid state chip replaced RAV.H B Southern California Edison Co 92/10/15 Region 5, Office of Director ip 15788 291 24X Fiche 50-361,82/10/15,8210250214
- 8210250269 Forwards LER 82-113/03L-0 Detailed event analysis submitted RAN.H B Southern California Edison Co 82/10/15 ENGELKEN.R H Region 5, Office of Director 2pp 15791 042 24X Fiche 50-341,82/10/15,8210250269
- --B210250273 LER 62-113/03L-0 on B20916, routine operator insp during gaseous waste processing revealed interstage rupture disc of waste gas compressor CO10 breached Caused by excess buildup of interstage pressure within compressor Disc replaced RAY. H B Southern California Edison Co B2/10/15 Region 5, Office of Director ip 15791 044 24X Fiche 50-361, B2/10/15, B210250269
- 8210280080 Forwards LER 82-114/017-0 Detailed event analysis submitted RAV.H B Southern California Edison Cp 82/10/19 ENGELKEN.R H Region S, Office of Director 2pp 15837 168 24X Fache 50-361.82/10/19.8210280080
- --8210280086 LER 82-114/01T-0 on 821017, during surveillance testing in Mode A.containment cooling fan 2E-402 failed to start Caused by faulty fan breaker Breaker replaced RAY.H B Southern California Edison Co 82/10/19 Region 5, Office of Director 1p 13837 170 24X Fiche 50-361,82/10/19,8210280080
- T Hearing transcripts on non-antitrust matters
- B210130209 Transcript of 821006 oral argument in Ban Diego.CA Pp 1-144 m Atomic Safety and Licensing Appeal Panel 82/10/06 145pp 15673 126 24X Fiche 50-361.82/10/06.8210130209
- V Operator Examinations
- 8210210184 Summary of 820914 & 20 meetings w/util re util 820802 request that NRC warve required written & ural tests & grant Unit 3 reactor operator & senior reactor operator licenses to currently licensed Unit 2 operators RODO.H Licensing Branch 3 82/10/01 Licensing Branch 3. 6pp 15772 353 24X Fiche 50-361,82/10/01,8210210184
- DOCKET 50-362 SAN ONDFRE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8210290063 Forwards "Evaluation & Action Plan for Ban Onofre Nuclear Generating Station Units 2 & 3 re TMI Incident " DRAKE, J M Southern California Edison Co 79/08/16 DENTON, H R Gifice of Nuclear Reactor Regulation, Director 2pp 15859 052 24X Fiche 50-361,79/08/16,8210290063

- --8210270069 "Evaluation & Action Plan for San Quofre Nuclear Generating Station Units 2 & 3 re TMI Incident "

 * Southern California Edison Co 79/08/31 48pp 15859 094 24X Fiche 50-361.79/08/16.8210290063
- 8210010008 Responds to FOIA request for 19 rategories of documents renuclear reactor events & safety problems Forwards documents listed in App A
 FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A
 Critical Mass Energy Project 15pp 15727 005 24X
 Fiche 30-000.82/06/28.8210010008
- --8008050265 Discusses addl required info to better define potential for cracking in reactor vessel noirles
 NODNAN,V B Assistant Director for Materials & Qualifications
 Engineering 80/05/05 TEDESCO.R L Assistant Director for
 Licensing 2pp 15727 176 24X Fiche 50-000,82/06/28.8210010008
- 8210050492 Discusses plan of action for issuance of DL Operator licensing & Tech Spec preparation could impact 821015 fuel load date Lists areas needing review to determine whether license conditions are required NOVAK,T M Assistant Director for Licensing 82/09/17 EISCHUIT.D Q Division of Licensing 2pp 15626 302 24X Fiche 50-362, 62/09/17.8210050492
- 82:10180258 Notification of 820920 meeting w/util in Bethesda.MD to discuss operator staffing & licensing ROOD.H Licensing Branch 3 82/09/17 MERRIGAN.J Licensing Branch 3 4pp 15746 32: 24X Fichs 50-362.82/07/17.8210180258
- 8210070164 Forwards evaluation of Unit 2 license conditions relative to potential applicability to Unit 3 license conditions in response to NRC request BASKIN.K P Southern California Edison Co 82/10/04 KERRIGAN.J Licensing Branch 3 4pp 15627 009 24X Fiche 50-361.82/10/04, 8210070164
- 8210060368 Outlines augmented shift manning requirements for period of initial criticality of Unit 3.for 1-month period after initial attainment of 100% power on Unit 2 & to control rotation of operators between units, per 920720 meeting DIETCH.R Southern California Edison Co 92/10/05 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15619 053 24% Fiche 50-361,82/10/05.8210060368
- 82:0170560 Forwards corrected page to rept re small earthquake swarm which occurred on 81:110 Revised info does not alter conclusions stated in rept BAGKIN.K P Southern California Edison Co 82/10/15 KERRIGAN.J [Licensing Branch 3 2pp 15736 137 24X Fiche 50-361,82/10/15.8210170560
- 8210190534 Notifies that info gained during Unit 2 natural circulation test program will be incorporated into overall Unit 2 & 3 operating training program.per NUREO-0737. Item I 0 i Listed tests will not be repeated for Unit 3

 BABKIN.K P Bouthern California Edison Co 82/10/18 KERRIGAN. J D Licensing Branch 3 2pp 15751 314 24X Fiche 50-361.82/10/18.8210190534
- F Security, medical, emergency & fire protection plans
- 8210190625 Forwards Revision 7 to physical security plan Revision withheld (ref 10CFR73 21)
 868KIN.K P Bouthern Callfornia Edison Co 82/10/15 ELT Diffice of Nuclear Reactor Regulation, Director 1p 157 24X Fiche, 50-206, 82/10/15, 8210190625
- G Adjudicatory correspondence
- B210040009 Notifies that LJ Chandler will represent NRC at or argument.per ABLAB B2090B order SW Perry of FEMA will be available CHANDLER.L J Hearing Branch 2 82/09/24 BHDEMAKER.C J Bafety and Licensing Appeal Panel 1p 18581 318 24X Fiche: 50-361, 82/09/24. 8210040009
- 8210050267 Memorandum & order setting medical arrangements qualified questions should be answered by all parties, providing expert testimony where required Issue of termineting procedures will be certified to Commission KELLEY, J. L. Atomic Bafety and Licensing Board Panel 82/18pp 13611 155 24% Fiche 50-361,82/10/01,8210050267
- 8210060184 Memorandum & order certifying question to Commissifeselbility of ABLB continuing proceeding initiated by ABLI 821001 order

 KELLEY.J L Atomic Safety and Licensing Board Panel. 82/1 Commissioners. 4pp 13613 181. 24X Fiche 30~361,82/10/088210060184

- 8210130309 Objections to ASLB 821001 memorandum & order re medical arrangements Order proposes hearing on issues beyond scope of Commission emergency planning regulations & requires evidence beyond NUREG-0654 stds Declaration of Svc encl PICOTT.D R Southern California Edison Co PICOTT.D R Orrick, Herrington & Subcliffe 82/10/08 Atomic Safety and Licensing Board Panel 11pp 15678 170 24X Fiche 50-941, 82/10/08, 82/10/2019
- 8210150454 Position on ASLB request for Commission direction on whether to proceed to hearings Further hearings on medical sycs issue should be deferred pending Commission determination & issuance of guidance Declaration of Syc encl PIGOTT.D R Bouthern California Edison Co PIGOTT.D R Orrick, Herrington & Sutcliffe 82/10/13 10pp 15703 112 24X Fiche 50~361.82/10/13.8210150454
- 82(0150482 Brief re certified questions on definition & implementation of 10CFR50 47(b)(12) re medical aves Applicant interprets iOCFR50 47(b)(12) as applying to individuals who are contaminated & traumatically injured. W/Declaration of Svc PICOTT.D R Southern Callfornia Edison Co PICOTT.D R Orrick. Herrington & Butcliffe 82/10/13 20pp 15703 008 24X Fichs 50-341.82/10/13.8210150482
- 8210150470 Brief re required medical svcs for general public in response to Commission Order CLI-82-27 Agrees w/ASLB re definition of contaminated injured individuals per 10CFR50 47(b) (12) Certificate of Svc encl MCCLUNO, C E GUARD MCCLUNO, C E Gallagher, P M MCCLUNO, C E Flemning, Anderson, McCluno, C E Flemning, Anderson, McCluno, C E 92/10/13 34pp 15713 110 24X Fiche 50-361.82/10/13.8210150470
- 8210180075 Brief re medical svcs issues certified by Commission order No advance planning required by 10CFR50 47(b)(12) for medical svcs for general public Necessary arrangements can be made on ad hoc basis Certificate of Svc encl CHANDLER, L J Hearing Branch 2 82/10/14 Commissioners 24pp 15719 270 24X Fiche 50-361,82/10/14,8210180095
- 8210220240 Response supporting util 821008 objections to ASLR 821001 prehearing memorandum & order re medical arrangements 8cheduling of any hearing should awart guidance from Commission, resolving certified issues W/Certificate of 8vc CHARDLER, L. J. Hearing Branch 2 82/10/20. Atomic Safety and Licensing Board Panel 7pp 15775 13t 24X Fichs 50-361,82/10/20, 62/0220240
- G Inspection reports, IE Bulletins & correspondence
- 8210060109 Forwards 1E Insp Rept 50-362/82-17 on 820823-0903 No moncompliance noted BISHOP.T W Region 5, Office of Director 82/09/16 PAPAY.L T Southern California Edison Co 2pp. 15614 336 24X Fiche 50-362,82/09/16,8210060109
- ~-B210060124 IE Insp Rept 50-362/82-17 on B20823-0903 No noncompliance noted Major areas inspected operational staffing & staff training; comparison of as-built plant to FBAR description, test program records safety committee & test results SIEWART, J P Region 5. Office of Director KIRSCH.D F Division of Resident, Reactor Project & Engineering Programs 82/09/16 Spp 15614 338 24K Fithe 50-362,82/09/16,8210060109
- 8210010267 Forwards list of open items that require resolution before finding of readiness for operation may be endorsed by Region 5 per insp Procedure 74300B Licensee established 821115 as fuel load data.
 ENGELMENS H Region 5. Office of Director 82/09/24 TAYLOR, J M, Division of Resident, Reactor Project & Engineering Programs. 7pp 15573 114 24X Fiche 50-362, 82/09/24, 8210010267
- 8210010042 Confirms 821021 mgt meeting in Rosemead.CA to discuss systematic assessment of licensee performance Anticipeted meeting attendese & apenda encl.
 CREHS.V L Division of Resident, Seactor Project & Engineering Programs 82/09/27 PAPAV.I. J. Bouthern California Edison Ca. 3pp 15565:317 24X Fiche:50-204.82/09/27.8210010042
- 8210190478 Forwards IE Insp Repts 50-361/82-27 & 50-362/82-19 on 820905-17 No noncompliance noted BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82/10/05 PAPAYLLT Southern California Edison Co 4pp 15740:245. 24x Fiche 50-361.82/10/05.8210190478
- --8210190501 IE Insp Repte 50-361/B2-27 & 50-362/82-19 on 820905-17. No noncompliance noted Major areas inspected TMI action plan requirements, Unit 2 low power level testing data review & precritical testing data review KIRBCH.D F. KENDONCA, M. Division of Resident, Reactor Project & Engineering Programs. 82/10/05, 14pp 15740: 249 24X Fiche: 30-361, 82/10/05, 82/0190478

- 8208190233 IE lnfo Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Suc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 64pp 15761 25 24% Fiche 50-000.82/10/06.8208190233
- 9210250173 Forwards IE Insp Rept 50-362/82-20 on 820913-17 No noncompliance noted 800K.H E Division of Radiological Safety & Safeguards Program 82/10/08 PAPAY.L T Southern California Editon Co 2pp 15787 134 24X Fichs 50-362.82/10/08.8210250173
- ~-8210250178 IE Insp Rept 50-362/82-20 on 820913-17 No noncompliance noted Major areas inspected preoperational radiation protection program ALARA environ monitoring program, solid, liquid & gaseous radwaste mgt b status of NUREO-0737 items CILLIS,M, WEMSLAWSKI,FA, BOOK,HE Division of Radiological Safety & Safegourd's Program 82/10/00 16pp 15787 136 PAX Fiche 50-362,82/10/08,8210250173
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- 8210250222 Ack receipt of 820929 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/82-25 % 50-362/82-16
 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82/10/18 PAPAY.L T Southern California Edison Co: 15789 326 24X Fiche 50-361.82/10/18.8210250222
- 8 Reportable occurrences, LERs & related correspondence
- B210190250 PNG-V-G2-041 on B21006. Los Angeles Times investigative reporter contacted Region 5 re former Bechtel Power Corp GC inspector addi allegations concerning welding practices investigation of allegations planned KIRSCH, D F , DISHOP: T W Region 5, Office of Director 82/10/14 p 15742 195 24% Fiche 50-361, G2/10/14, G210190250
- T Hearing transcripts on non-antitrust matters
- 8210130209 Transcript of 821006 oral argument in San Diego, CA Pp 1-l4 * Atomic Safety and Licensing Appeal Panel 82/10/06 145pp 15673 126 24X Fiche 50-361,82/10/06,8210130209
- V Operator Examinations
- 8210210184 Summary of 820914 & 20 meetings w/util re util 820802 request that NRC waive required written & oral tests & grant Unit 3 reactor operator & senior reactor operator licenses to currently licensed Unit 2 operators ROGD: H Licensing Branch 3 82/10/01 Licensing Branch 3 6pp 13772 353 24% Fiche 50-361.82/10/01.8210210184
- DOCKET 50-343 FORKED RIVER NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8210070102 Forwards Info resolving 14 Tech Spec open items discussed at 820913 meeting Marked-up Tech Specs encl BABKIN, K P Southern California Edison Co B2/10/04, KERRIGAN, J 1 Licensing Branch 3 36pp 15649 244 24X Fiche 50~263,82/10/04. 8210070102
- DUCKET 50-364 JQSEPH M FARLEY NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records. 82/06/28 UDELL,R & Critical Mass Energy Project 50pp 15727 005 24X Fichet 50-000, 82/06/28,8210010008

- --8008050265 Discusses addi required info to better define potential for cracking in reactor vessel notiles MODNAN, V S Assistant Director for Materials & Qualifications Engineering 80/05/05 TEDESCO.R L Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000.82/06/28,8210010008
- F Security, medical, emergency & fire protection plans
- G210010196 Ack receipt of G20B27 itr re emergency exercise scheduled for Feb 1983
 SIONR, J Division of Emergency Preparedness & Operational Support G2/09/17 MLDONALD R P Alabama Power Co ip 15570 360 24X
 Fiche 50-348, G2/09/17, G210010196
- B210010195 Forwards Revisions 4 / 5 to security plan Revisions withheld CLAYTON:F L. Alabama Power Co. B2/09/21 VARGA:S A. NRC No. Detailed Aff; liation Given ip 15567 313 24X Fiche 50-348. B2/09/21, B210010195
- B250190066 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 82/10/01 Document Management Branch ip 15761 060 24X Fiche 50-948,82/10/01, 1820190066
- B210180004 Forwards IC Safeguards insp.Repts 50-348/82-23 & 50-364/82-22 on 820921-24 No noncompliance noted VERRELLI, D. Division of Project & Resident Programs 82/10/12 MCDDMALD, R.P. Alabama Power Co. 2pp 15720 025 24X Fiche 50-348, 02/10/12.8210180004
- --B210180007 IE Safeguards Insp Repts 50-348/82-23 & 50-344/82-22 on 620721-24 No noncompliance noted Major areas inspected security plan & implementing procedures & security organization Details withheld (ref 100FR73 21) STANSBERRY, W W Division of Engineering & Technical Programs 82/10/08 ip 15720 027 24X Fiche 50-348,82/10/12,8210180001
- G210280158 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs to require audit on emergency preparedness program every 12 months, per 100FR50 54(t) & Generic Ltr G2-17 Ho amend fee required SER encl CLAYION, F L Alabama Power Co 82/10/25 VARGA, S A Dffice of Nuclear Reactor Regulation, Director 2pp 15837 194 24X Fiche 50-348, 82/10/25, 8210280158
- --8210280165 Proposed Tech Specs, Soction 6 5 2 8 requiring audit of emergency preparedness every 12 months, per 10CFR50 54(t) & Generic Ltr 82-17

 4 Alabama Power Co 82/10/25 3pp 15837 176 24X fishe 50-348,82/10/25,8210280158
- if Antitrust correspondence
- B210060179 Notifies of Debevoise & Plimpton change of address as of 821001 Affirmation of Bvc enc!

 * Debevoise & Plimpton 82/10/01 3pp 15614 108 24X Fiche 30-348.82/10/01.8210060179
- P Operating license stage documents & correspondence
- B210010227 Confirms B20820 telcon arrangements re B20930 meeting w/util in Region 2 ofc to discuss fuel rod degradation resulting from baffle water-yet impingement Proposed agenda encil O'REILLY, J P Region 2, Office of Director B2/09/03 MCDONALD, R P Alabama Power Co 2pp 15567 336 24X Fiche 50-34B, B2/09/03, 8210010227
- 62:0040038 Forwards Amend 17 to License NPF-B, safety evaluation & notice of issuance & availability Amend extends for one-time only.visual surveillance interval for inaccessible hydraulic snubbers until 82:002 refusing outage REEVES,E A Operating Reactors Branch 1 82/09/22 CLAYTON,F L Alabama Power Co 2pp 15577 264 24X Fiche 50-364,82/09/22,82:0040038
- ---8210040039 Amend 17 to License NPF-B, extending for one-time only, visual surveillance interval for inaccessible hydraulic snubbers until next refueiing outage scheduled to begin 821022 VAROA. B A Operating Reactors Branch 1 82/09/22 App 15577 266 24% Fiche 50-324, 82/09/22, 8210040038

- --8210040040 Safety evaluation supporting Amend 17 to License NPF-B

 4 Office of Nuclear Reactor Regulation, Director B2/09/22 3pp
 15577 270 24X Fiche 50-364-82709/22 8210040038
- ~-8210040041 Notice of issuance & availability of Amend 17 to License NPF-B VARGA,S A Operating Reactors Branch 1 82/09/22 2pp 15377 273 24X Fiche 50-364,82/09/22,8210040038
- 8210050066 Commits to functional testing of circuit breakers, completing outstanding issue re 820726 request for extension of License Condition 2 C (1916b)
 CLAYTON, F.L. Alabama Power Co. 82/09/27 VARGA, 8 A. Office of Nuclear Reactor Regulation, Director 2pp 15603 227 24X
 Fiche 50-364. 82/09/27, 8210050066
- B210050089 Informs that installation of water tight fittings on Victoreen radiation detectors per TMI Action Item II F 1 will be delayed until next refueling outage.contingent upon receipt of matl CLAYTON, F L Alabama Power Co B2/09/30 VARGA. S A Office of Nuclear Reactor Regulation, Director 3pp 15604 241 24X Fiche 30-364: 82/09/30.8210050089
- 8210130527 Forwards proprietary & nonproprietary versions of "Evaluation of Impact of Reduced Testing of Turbine Valves," WCAP-10161 & WCAP-10162, respectively Proprietary version withheld (ref 100FR2 790) CLAYTON, F.L. Alabama Power Co. 82/10/08 VARGA, S.A. Office of Nuclear Reactor Regulation, Director Spp. 15683 006 24X Fiche 50-364,82/10/08,8210130527
- --82iDi3O535 Nonproprietary version of "Evaluation of Impact of Reduced Testing of Turbine Valves"

 RAHE, E P Westinghouse Electric Corp WCAP-10162 82/09/30
 77pp 15683 Oli 24X Fiche 50-364,82/10/08,8210130527
- 8210150338 Application for one-time change to Tech Spec 3/4 4 7 2, modifying leak test acceptance criteria Change necessary to preclude potential for delay in return to power from refueiing outage CLAYTON.F L Alabama Power CO 82/10/11 VAROA.S A Office of Nuclear Reactor Regulation, Director 5pp 15705 344 24X Fiche 50-364.82/10/11.8210150338
- --8210150344 Proposed Tech Spec Pages 3/4 4-17 & 3/4 4-19 re RCS operational leakage & RCS pressure isolation valves Safety evaluation enci
 4 Alabama Power Co 82/10/11 App 15705 351 24X Fiche 50-364,82/10/11.8210150338
- 8210250090 Application to amend License NPF-8, deleting license conditions redundant to generic regulatory items Change does not invoive unreviewed safety question Safety evaluation encl
 CLAYTON,F L Alabama Power Co 82/10/19 VAROA,S A Office of Nuclear Reactor Regulation, Director 8pp 15787 101 24X Fiche 50-364,82/10/19,8210250090
- B210260418 Advises that util confident that current emergency procedure provides adequate guidance for cooldown under natural circulation conditions Full compliance w/License Conditions 2 C (9)(b) & 2 C (12)(c) demonstrated CLAYTON,F L Alabama Power Co B2/10/21, VARGA, 8 A Office of Nuclear Reactor Regulation, Director. 2pp 15806 315 24X Fiche 50-364,82/10/21,8210260418
- 8210260437 Bubmits final documentation of full compliance w/License Condition 2 C (12)(6) re safety-grade means for RCS depressurization per Technical Position RBB 5-1, Revision 1 CLAYTON.F L Alabama Power Ca 82/10/21 VARGA.8 A Office of Nuclear Reactor Regulation, Director 2pp 15806 244 24X Fiche 50-364,82/10/21.8210260437
- B210280282 Advises that revised Hestinghouse performance Gode PAD-3 3 as described in HCAP-8270.Addendum 1, adequately defines fuel burnup for successive fuel cycles CLAYTON.F L Alabama Power Go 82/10/22 VARQA, S A NRC No Detailed Affiliation Given 1p 15837 043, 24X Fiche 50-344,82/10/22,8210280282
- 8210280158 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs to require audit on emergency preparedness program every 12 months, per 10CFR50 54(t), & Generic Ltr 82-17 No amend fee required SER enci CLAYTON, F.L. Alabama Power Co. 82/10/25 VAROA, S.A. Office of Nuclear Reactor Regulation, Director 2pp 15837 194 24X Fiche, 50-348, 82/10/25, 8210280158

- --8210280165 Proposed Tech Specs. Section 6.5 2 8 requiring audit of emergency preparedness every 12 months, per 10CFR50 54(t) & Centric Ltr 82-17 a Alabama Power Co. 82/10/25 3pp. 15837 196 24X Fiche 50-348,82/10/25,8210280158
- Q Inspection reports: IE Bulletins & correspondence
- 8210070007 Responds to FUIA request for eight categories of recurds restam generators & steam turbines App A documents provided in R Udell FUIA Request 81-313 Forwards documents listed in App B

 FELTON.J.K. Division of Rules and Records 82/08/10 1000.0 J

FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007

- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VAROA.8 Operating Reactors Branch 1 3pp 15645 131 24X Fiche 50-000, 82/08/10, 82:0070007.
- 8210010204 Forwards 1E Insp Repts 50-348/82-21 & 50-364/82-20 on 820802-06 No honcompliance noted DANCE, H C Region 2. Office of Director 82/08/30 MCDONALD, R P Alabama Power Co 2pp 15567 314 24X Fiche 50-348, 82/08/30, 8210010204
- --821001020B IE Insp Repts \$0-348/82-21 & 50-364/82-20 on 820802-06 No noncompliance noted Major areas inspected pipe supports & restraints & Types B & C containment leak rate testing BROOKSE: JAPE.F Division of Engineering & Technical Programs 82/08/25 4pp 15567 316 24% Fiche 50-348,82/08/30,8210010204
- B210010043 Concurs w/actions outlined in util 920812 ltr re inspared by IE Bulletin 79-13 except in areas of re-radiographing steam generator feedwater nozile-to-pipe & weld retention of records

 LEMIS R C Division of Project & Resident Programs B2/09/13 MCDONALD R P Alabama Power Co 2pp 15570 361 24X

 Fiche 50-348,82/09/13,8210010043
- B2101\$0072 Ack receipt of B20907 itr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-348/82-17 & 50-348/82-18 DANCE.H C Division of Project & Resident Programs 82/10/04 MCDDNALD,R P Alabama Power Co ip 15701 232 24X Fichs 50-348,82/10/04,8210150072
- ~-8210150074 Responds to NRC 820818 itr re-violations noted in 1E Insp. Repts 50-348/82-17 & 50-344/82-18 Corrective actions Form NRC-3 posted at low level radwaste bidg CLAYTON,F L Alabama Power Co 82/09/09 DANCE.H C Region 2, Office of Director 2pp 15701 254 24X Fiche 50-348,82/10/04,82/10/50072
- ~~8210150078 Forwards lE Insp Repts 50-348/82-19 & 50-364/82-18 on 820726-30 & notice of violation

 DANCE-H C Division of Project & Resident Programs 82/08/18 HCDONALO.R P. Alabama Power Co 2pp 15701 256 24%

 Fiche 50-348.82/10/04.8210150072
- ~-8210150082 Notice of violation from Insp on 820724-30 * Division of Project & Resident Programs 82/08/18 tp 15701,258 24X Fiche 50-348,82/10/04,8210150072
- --8210150086 IE Insp Repts 50-348/82-19 & 50-364/82-18 on 820726-30 Noncompifance noted Form NRC-3. "Notice to Employees," not posted in new low level waste storage Pacility PERRY, H. W. BARR. K.P. Division of Engineering & Technical Programs 82/08/16 Spp 15701 259 24X Fiche 50-348,82/10/04, 8210150072
- 8210220229 Forwards IE Insp Repts 50-348/82-22 & 50-364/82-21 on 820816-0915 No noncompliance noted, DANCE-H C Division of Project & Resident Programs 82/10/04 MCDDNALD,R P Alabama Power Co 2pp 15776 233 24% Fichs 50-348, 82/10/04, 8210220229
- --8210220232 IE Insp Repts 50-348/82-22 k 50-344/82-21 on B20816-0915 No noncompliance noted Major areas inspected; monthly surveillance & maint observation operational safety verification plant trips & LERS BRADFORD.N. H , BROWNLEE, V.L Division of Project & Resident Programs B2/10/04 7pp 15776 235 24X Fiche 50-348,82/10/04,82/10220229,
- B208190233 IF Info Notice 80-35. Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Syc list encl. COBBL. I Division of Fuel Facilities, Materials & Bafeguards 82/10/05 Consolidated Edison Co of New York 66pp 15761 250 24X Firms 30-000, 82/10/05, 8208190233

- 9210180004 Forwards 1E Sareguards Insp Repts 50-348/82-23 & 50-364/82-22 on 820921-24 No noncompliance noted VERRELLI, D Division of Project & Resident Programs 82/10/12 MCDQNALD, R P Alabama Power Co 2pp 15720 025 24X Fiche 50-348, 82/10/12, 8210180004
- --0210180007 IE Safeguards insp Repts 50-348/82-23 \$ 50-364/82-22 on 820921-24 No noncompliance noted Major areas inspected security plan & implementing procedures & security organization Details withheld (ref 100FR73 21)
 STANSBERRY, N. N. MCGUIRE, D. R. Division of Engineering & Technical Programs 82/10/08 lp 15720 027 24% Fiche 50-348.82/10/12, 8210180004
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Pipling at BUR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Chison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14,8208190238
- 8210280410 Notification of 821029 meeting w/wtil Franklin Research (tr. b. Brittel in Bethesda MD to review calculations & methodology re 16 Bulletin 80-11. "Masoney Walls"
 REEVES. E. A. Operating Reactors Branch 1 82/10/20 VARGA, S. Operating Reactors Branch 1 2pp 15859 332 24X
 Fiche 50-348.82/10/20.8210280410
- R Periodic operating reports & related correspondence
- 8210190767 Forwards monthly operating rept for Sept 1982 CLAYTON, F. L. Alabama Power Co. B2/10/12 Management Information Branch ip 1973A 238 24% Fiche 50-344, 82/10/12,821019076/
- --8210190773 Monthly operating rept for Sept 1982 HAIRSTON,W 0 Alabama Power Co 62/10/04 8pp 15736 239 24x Fiche 50-364,82/10/12-8210190767
- 5 Reportable occurrences, LERs & related correspondence
- 8210070111 Reviews purge valve info contained in T Austin 810306 memo Primary trechnical issue relates to valve operability during expected accident conditions Vital areas of concern addressed in info include lower torque margin for closure BROWN, E J Director's Office 81/09/24 MICHELSON, C Director's Office 81/09/24 MICHELSON, C 201070111
- B21001000B Responds to FOIA request for 17 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/04/28 MDELL, R A Critical Mass Energy Project 15pp 19727 009 24x Fichs 50-000,82/04/28,8210010008
- --8210090124 Summary of 810610 operating reactor events meeting LAINAS:0 C Assistant Director for Safaty Assessment 81/06/1/ EISENHUT, D Q Division of Licensing Spp 13729 217 24X Fiche 50-000,82/06/28.8210010008
- 8210010129 Forwards LERs 82-037/03L-0 & 82-052/03L-0 CLAYTON: F L Alabama Power Co 82/09/27 Region 2, Office of Director 1p 18567 227 24% Fiche 50-340,82/09/27.8210010129
- --8210010147 LER 82-037/03L-0 on 820905.A train auto trip logic for high steam generator differential pressure declared inoperable when failed cord indication received by automatic tester Causad by failure of universal card Card replaced HAIRBITON.W 0 Alabama Power Co 82/09/27 Region 2, Office of Director 1p 15567 289 24X Fiche 50-348.82/09/27.8210010129
- B210240453 Forwards LERy 82-054/03L-0182-055/03L-0,82-039/03L-0 & 82-040/03L-0 CLAYYON:F L Alabama Power Co 82/10/18 Region 2. Office of Director 1p 15806 195 24X Fiche 50-348,82/10/18,8210260453
- --8210260480 LER 82-039/03L-0 on 820919, svc water to component cooling water HX 2C isolated Caused by dislodged pin holding worm drive gear allowing differential pressure across valve disc to close valve Pin reinstalled & secured HAIRSTON.H 0 Alabama Power Co 82/10/18 Region 2, Office of Director ip 15806 198 24X Fiche, 50-348, 82/10/18, 8210260453
- --8210260490 LER 82-040/03L-0 on 820919, loss-of-voltage protection channel astociated w/82F sequencer phase 2-3 declared inoperable Caused by failure of loss-of-voltage relay 27XF1 during testing Relay cleaned HAIRSTON.H.O. Alabama Power Co. 82/10/18 Region 2, Office of Director 19 15806 199 24X Fichs 50-348,82/10/18,8210260453

- S2 10290289 Forwards LER 82-033/03L-1 CLAYTDN.F L Alabama Power Co 82/10/19 Region 2. Office of Director 1p 15959 073 24% Fiche 50-364.82/10/19.8210290289
- G210290292 LER 82-033/03L-1 on 820817, breaker to containment isolation valve inadvertantly opened Caused by personnel error while implementing tagging order Breakers positioned & returned to svc

 HAIRSTON, M. G. Alabama Power Co. 82/10/19. Region 2, Office of Director (p. 15854-0/4, 24% Fiche 50-364, 82/10/19, 8210290289)
- COCKET 50 366 EDWIN 1 HATCH NUCLEAR PLANT. UNIT 2

 F Security, medical, emergency & fire protection plans
- B≥ 10060275 Application to amend License NPF-5, deleting App A Tech Specs on bldg settlement & withdrawing 781201,790814 & 1008 submittals re differential & total settlement values based on consolidation settlement SECKHAM. J T Georgia Power Co 82/09/27 Office of Nuclear Regulation. Director 5pp 15621 172 24X Fichs 50-366, 82/09/27, 8210040275
- --8210060278 Tech Specs 3/4 7 7 re penetration fire barriers
 4 Georgia Power Co 82/09/27 ip 15621 177 24X
 Fich 50 366,82/07/27.8210060275
- ©210190013 Releases public version of revised emergency plan implementing procedure FELTCN, J.M. Division of Rules and Records 82/09/29 Document Nanagement Branch 1p 15760 328 24X Fiche 50-321.82/09/29. 8210190013
- --8210190016 Forwards public version of Revision 4 to Emergency Plan Implementing Procedure HNP-8026, "High Radiation Area Entrance Control"
 SORRELL, C Georgia Power Co 82/09/23 Office of Nuclear Reactor Regulation, Director ip 15760 329 24X Fiche 50-321,82/09/29,8210190013
- --8210190017 Public version of flavision 4 to Emergency Plan Implementing Pracedule HNP-8026. "High Radiation Area Entrance Control" e Georgia Power Co. 82/09/22 12pp 15760 330 24X Fiche 50-321,82/09/29,8210190013
- E210190942 Releases public version of pages to emergency plan FELTON.J M Division or Rules and Records 82/10/01 Document Annagement Branch 1p 15761 037 24X Fiche 50-321,82/10/01,8210190042
- 8210170046 Forwards public version of Pages M-1 & M-2 to emergency
 plan
 SURREIL.E C Guorgia Power Co B2/09/22 Office of Nuclear
 Reactor Regulation. Director ip 15761 038 24X
 Fiche 50-321.82/10/01.8210170042
- --8210190051 Public version of Pages M-1 & M-2 to emergency plan • Georgia Power Co 82/03/31 2pp 15761 039 24X Fiche 50-321,82/10/01.8210190042
- □ 210080227 Forwards IE Sateguards Insp Repts 50-321/82-31 & 50-361/82-29 on 820920-23 No moncompliance noted DANCE.H C Division of Project & Resident Programs 82/10/04 KELLY.R J Georgia Power Co 2pp 15638 057 24X Fiche 50-321, 82/10/06, 8210080227
- P Operating license stage documents & correspondence
- ©210050275 Application to amend License NPF-5, deleting App A Tech Specs on bidg settlement & withdrawing 781201,790814 & 1008 submittals re differential & total settlement values based on consolidation settlement [ECKHAM.J] To Deorgia Power Co. 82/09/27 Office of Nuclean Reactor Regulation, Director 5pp 15621 172 24X Fiche 50-366, 82/09/27, 8210060275
- ---8210060278 Tech Spets 3/4 / 7 re penetration fire barriers a Georgia Power Co 82/09/27 lp 15621 177 24X Fiche 50-366,82/09/27.8210060275

- 8210050330 Forwards schedule for qualification testing of analog transmitter trip sys.in response to 801001 request GUCHALL T Georgia Power Co 82/09/28 EISENHUT.D 0 Office of Nuclear Reactor Regulation, Director 3pp 13610
- 8210060231 Forwards remittance & copies omitted from 820927 ltr re bidg settlement BECKHANN J T Georgia Power Co 82/10/01 Office of Nuclear Reactor Regulation, Director fp 15620 012 24X Fiche 50-366.82/10/01.8210060231
- 8210120047 Application to amend App A of License NPF-5, changing Tech Spec Figures 3 2 3-1 & 3 2 3-2 to reflect changes in operating limit min critical power ratios resulting from reanalysis of pressurisation transients by GE BECKHAH. J T Georgia Power Co 82/10/04 Office of Nuclear Reactor Regulation. Director 29p 15651 242 24X Fiche 50-366. 82/10/04. 8210120047
- --8210120050 Proposed Tech Spec Figures 3 2 3-1 & 3 2 3-2, reflecting changes in operating limit min critical power ratios # Georgia Power Co 82/10/04 3pp 15651 244 24X Fiche 50-366,82/10/04,8210120047
- 8210220270 Forwards corrected Page 6-4 for 820611 Tech Spec change request re designation of unit status for shift manning requirements Original submittal inadvertently reversed OUCHALT Georgia Power Co 82/10/15 Office of Nuclear Reactor Regulation, Director 1p 15775 049 24X Ficha 50-366,82/10/15,821020290
- --8210220278 Corrected Page 6-4 to 820611 Tech Spec change request re designation of unit status for shift manning requirements → Georgia Power Co 82/10/15 Ip 15775 050 24X Fishe 50-364 82/10/15 8210220270
- Q inspection reports, [E Bulletins & correspondence
- 8210010113 Forward: IE lnsp Repts 50-321/82-26 & 50-366/82-25 on 820809-13 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/07 KELLY.R J Georgia Power Co 2pp (5567 204 24% Fiche 50-321,82/09/07,82(0010113
- --9210010118 IE Insp Repts 50-321/82-26 & 50-366/82-25 on B20809-13 No noncompliance nuted Major areas inspected lab GC program chemistry & radiochemistry procedurest, airborne effluent sampling & accountability & mobile lab EVANS.C D. HONTGOMERY.D M. Division of Emergency Preparedness & Operational Support B2/09/02 lipp 15567 208 24x Fiche 50-321,82/09/07.8210010113
- 8210010309 Forwards 1E Insp Repts 50-321/82-28 & 50-366/82-26 on 820727-0827 No noncompliance noted DANCE,H C Division of Project & Resident Programs 82/09/10 KELLY,R J Georgia Power Co 2pp 19568 274 24% Fichs 50-321,82/09/10.8210010309
- --8210010327 IE Insp Repts 50-321/82-28 & 50-364/82-26 on 820727-0827 No noncompliance noted Major areas inspected Tech Spec compliance operator performance overall plant operations, GA practices & station & corporate mgt practices Fatations & corporate mgt practices ROSERS, R F , HOLMES-RAY, P , BROWNLES, V L Division of Project & Resident Frograms 82/09/10 App 15568 276 24% Fiche 50-321,82/09/10/8210010309
- 8210010019 Ack receipt of 820907 itr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-321/82-19 O'REILLY, J P Region 2. Office of Director 82/09/16 KELLY, R J Georgia Power Co ip 15565 300. 24X Fiche 50-321.82/09/14, 8210010019
- --8210010022 Responds to NRC 820806 ltr re violations noted in IE Insp. Repts 50-321/82-19 & 50-366/82-19 Corrective actions procedures being revised to include tighter controls on changes to fuel movement data packages

 BECKMAM, J T Georgia Power Co 82/09/07 Q'REILLY, J P Region 2, Office of Director 3pp 15565-301 24X Fiche 50-321, 82/09/16-8210010019
- --8210010025 Forwards lE Insp Repts 50-321/82-19 & 50-366/82-19 on 820421-0525 & notice of violation O'REILLY,J P Region 2. Office of Director 82/08/06 KELLY,R J Georgia Power Co 2pp 15565 304 24X Fiche 50-321,82/09/16,8210010019

- ~~82i0010031 IE Insp Repts 50~32i/92~19 & 50~366/82~19 on 82042i-0525 Noncompliance noted fuel loaded into core w/o all control rods fully inserted RUCERS.R F Division of Project & Resident Programs BROWNLEE,V L Region 2. Office of Director 82/07/29 7ep 15565-307 24X Fiche 50~32i.82/07/16.82i0030019
- 8210040047 Ack receipt of check in payment of civil penalty proposed on 820713 Corrective measures described in 820812 & 0907 ltrs will be stamined in future insp. AXELRAD. J. A. Director's Office, Office of Inspection and Enforcement 82/07/23 XELLY,R. J. Georgia Power Co. 2pp. 15577 290 24X Fiche 50-321.82/07/23.8210040047
- 820B190233 lE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 COMPANY OF THE CONTROL OF THE CONTROL OF THE CORP. L. F. D. VISION OF FUEL Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co. of New York 66pp. 157/24X Fiche 50-000, 82/10/06/8208190233
- 8210080227 Forwards IE Safeguards insp Repts 50-321/82-31 & 50-366/82-29 on 820920-23 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/1 KELLY: R J Georgia Power Cq 2pp 15638 057 24X Fiche 50-321 ams 82/10/06 24X
- --8210080228 IE Safeguards Insp Repts 50-321/82-31 & 50-366/82-29 on 210080220 IE Safeguards Insp Repts 50-321/82-31 & 50-326/82-89 on 820720-23 No poncompliance noted Major areas inspected physical barriers, lighting, assessment aids, detection aids, access control & vehicles Details withheld (ref 10CPR70 21) MOURE, D E , MCOUIRE, D R Division of Engineering & Technical Programs 82/10/05 ip 15638 059 24% Fichs 50-321,82/10/06,8210080227
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Gracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list enc!

 DEYQUNO, R C Director's Office, Office of Inspection and En
- 8210220277 Ack receipt of 820927 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/82-24 & 50-366/82-22 LENIS.R C Division of Project & Resident Programs 82/10/14 KELLV.R J Georgia Power Co 1p 15775 028 24X Fithe 50-321.82/10/14.8210220277
- --8210220267 Responds to NRC 820823 ltr re violations noted in IE insp Repts S0-321/62-24 & 50-366/82-22 Corrective actions written plan will be prepared to schedule b integrate lecture series to meet addit training needs QUCMA.L T Georgia Pawer Co 82/09/27 O'REILLY, J.P. Region 2, Office of Director 4pp 15775 029 24X Fiche 50-321,82/10/14, B210220277
- --8210220292 Forwards 1E Insp Repts 50-321/82-24 & 50-366/82-22 on B20728-30 & notice of violation LEHFS R C Division of Project & Resident Programs KELLY-R J Georgia Fower Co 2pp 15775 033 24: Fiche 30-321, B2/10/14, B210220277 82/08/23
- --8210220299 Notice of violation from insp on 820724-30 4 Division of Project & Resident Programs 82/08/23 2pp 18775 035 2AX F(rhs 50-20: B2/10/14.821022027)

- S Reportable occurrences, LERs & related correspondence
- 6210120171 Discusses 610406 discovery that undervoltage relays of second offsite source would not operato, preventing closure second offsice source would not operate, preventing closure of all diesel generator breakers Licensee will be proposing design mod to correct problem of non-Class IE interlock CHIRAMALIM Director's Office BI/04/21 Director's Office Spp 15692 202 24x Fiche 50-391.81/04/21,82[0]:0171
- B21001009B Responds to FUIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App FELYON, J M FELTON, J M Division of Aules and Records 82/06/28 UDCLL, h A Critical Mass Energy Project 15pp 15/27 005 24x Fiche 50-000,82/06/28.8210010008
- --8104270103 Discusses 1E daily rept for 810406 re alternate officity source interlock w/emergency diesel generators at Unit 1 Licensee will propose mod to correct non-Class IF interlock preventing automatic operation of safety sys CHTRAMALM Director's Office 81/04/21 Director's Office 3pp 15729 041 24X Fiche 50-000.82/06/28.8210010008
- --9210010083 Recommends ACRS action on occurt LERs is HPCI failure to auto start after MSIV failure to single cooling supply line on RIRR pump motors
 BOEHRIERT, P ACRS Advisory Committee on Reactor Safeguards
 80/06/13 KERR, H ACRS Advisory Committee on Reactor
 Safeguards ip 15727 138 24X Fiche 50-000,82/06/28,0210010008
- --8210010089 Discusses failures of EPCI & RCIC sys subsequent to 79060; event culminating in 790627 loss of both sys BBEHNERTIP ACRS Advisory Committee on Reactor Safeguards 79709706 KERR.W ACRS Advisory Committee on Reactor Safeguards 2pp 15727 142 24X Fiche 90-000.82706728, 8210010008
- --8210010095 Forwards PNO-79-139 re failure of RCIC & MPCI sus following PRODUCTIONS FORWARDS PREMINE 134 FE FAITURE OF RCIC & MPCI sys Foltows:
 Jow Waster level reactor scram

 BDEHNERT, PACRS - Advisory Committee on Reactor Safeguards
 79/06/29 KERR, WACRS - Advisory Committee on Reactor
 Safeguards 1p 15727 144 24X Fiche 50-000.112/06/28.1210010008
- --8210010099 Requests detailed rept on PNO-77-139 re failure of backup NOTION Requests detailed rept on required a failure of back core cooling sys Generic implications required KENNEDY, R T Commissioners 79/06/07 ODESICK, L V Office of the Executive Director for Operations 1p 1972/153 24x Fiche 50-000,82/06/28,8210010008
- --B210010105 Reiterates 790607 request for dotailed rept re failure of backup core cooling sysper PND-79-137 & PND-79-136 Response requested by 790703 KENNEDY: IT Commissioners 79/07/02 GDSSICK: U Office of the Executive Director for Operations 1p 19727 154 24X Fiche 50-000, 82/06/28, 8210010008
- --B210010109 Forwards response to 790607 request for info re failure of backup cooling sys Corrective measures will be followed to assure reliable state of operational readiness STELLO.V Office of Inspection & Enforcement, Office of the Director 79/07/02 KENNEDY RT Commissioners Spp 15727 157 24X Fiche 30-000.82/06/28,8210010008
- ---8210040367 Requests info to LER 80-111/03L-0 concerning isolation of HPCF sys at facility Nature of nonrepetitive event questioned HDELLER, D.W. ACRS Advisory Committee on Reactor Safeguards QUESTIONES

 HDELLER.D W ACRS - Advisory Committee on Reactor Safeguards
 80/09/16 HCCRELESB.T ACRS - Advisory Committee on Reactor
 Safeguards 2pp 15727 261 24X Fiche SO-000.82/06/2B.
- 82[0010094 Forwards LER 82-083/03L-0 NIX.H C Osorgia Power Co 82/09/21 O'REILLY, J P Region 2, Office of Director Ip 15565 256 24X Fiche 50-366,82/09/21. 8210010094
- --8210010098 LER 82-083/03L-0 on 820825, w/plant in hot shutdown, reactor bldg to suppression chamber vacuum breaker had no closed indication & declared inoperable Caused by Ionse limit switch mount bracket & out of adjustment actuator
 TIPPS, S B Georgia Power Co 82/09/21 Region 2, Office of
 Director 2pp 15565 257 24% Fiche 50-366, 82/09/21, 82:0010094
- 8210050080 Forwards LER 82-091/03L-0 NIX-H C Georgia Power Co 82/09/23 O'REILLY, J P Region 2, Office of Director ip 15604 252 24X Fiche 50-366, 82/09/23.

- -B210050084 LER 82-091/03L-0 on 820825, during scram recovery, H ADS safety relief valve failed to open manually & diguell pressure & temp acceeded Tech Specs Cause unknown Pressure & temp returned to allowable levels 1
- E210060246 Forwards LER 82-090/031-0 MIX.H C Georgia Pawer Co 82/09/23 O'REILLY, J P Region 2, Orfice of Director 1p 15619 317 24X Fiche 50-366, 82/09/23, 8210060246
- --8210060248 LER 82-090/03L-0 on B20831.during quarterly surveillance,

 B oxygen analyzer failed to calibr due to instrument
 rluctuation Caused by worn pump head assembly on sample
 pumps Upper % lower pump heads replaced Analyzer rocalibr
 GULNER.H L Georgia Power Co 82/09/23 Region 2, Office of
 Director 2pp 15619 J18 24X Fiche 50-366, 82/09/23, 8210040244
- 8210050287 Forwards LCR 82-100/031-0 N(X,H C Georgia Power Co 82/09/23 O'REILLY, J P Region 2, Office of Director 1p 15619 213 24X Fiche 50-366,82/09/23, 021006087
- -8210000289 LER 82-100/03L-0 on 620828, while performing RCIC turbine enhanced disphragm pressure instrument FTAC procedure, two inopenative switches discovered Caused by component failure due to water damage Switches replaced TIPPS.5.8 Georgia Power Co. 82/09/23 Region 2, Office of Director 2pp 19019-214 P4X Fiche 50-366, 82/09/23, 8210060287
- \$216060317 Forwards updated LER \$2-079/03X-1
 NIA.H C Georgia Power Co 82/09/23 O'RETILY.J P Region 2,
 Office of Director 1p 15618 J45 24X Fiche 50-366.82/09/23,
 8210060317
- 8210060324 Updated LER 62-079/03X-1 on 820727 diesel generator C tripped affor 37 minutes of normal operation during surveillance test Caused by failure of connecting rod bearing 8 Engine repaired IPPS 5 8 Georgia Power Co 82/09/23 Region 2 Office of Director 2pp 15618 346 24% Fiche 50-366.82/09/23.8210060317
- 1210080234 Forwards LER 82-102/031-0 N14,H C Georgia Powoi Co 82/09/28 D'REILLY, J P Region 2, Difice of Director 1p 15638 074 24% Fiche 50-366,82/09/28, 8210080234
- --B210080240 LER 82-102/03k-0 on B20830, w/unit steady-state at 2,258 NWT, discovered B20812 scheduled monthly fire hose station safety-related areas surveillance procedure not completed before 820819 grace period expiration TIPPS, 8 B Goargia Power Co 82/09/28 Region 2, Office of Director 2pp 15638 075 24X Fiche 50-366, B2/09/28, B210080234
- 3210130183 Forwards LER 62-101/03t 0 NIA,H C Overgra Power Co 62/09,28 O'REILLY, J P Region 2, Office of Director 1p 15673 009 24X Fiche 50-366.82/09/28. 6210130183
- --8210130185 LER 82-101/O3L O on 820829, imboard MSIV in loop C failed closed Caused by improper stem to disk thread engagement Disk & stem assembly replaced in both C loop MSIVs Valves tested & returned to svc
 TIPPS, 9 B Georgia Power Co 82/09/28 Region 2, Office of Director 2pp 15673 010 24% Fiche 50-366, 82/09/28, 8210130183
- 8210130406 Forwards LER 82-109/03L-0 NICH C Georgia Power Co 82/09/28 O'REILLY, J.P. Region 2. Office of Director ip 15880 261 24X Fiche 50-366,82/09/28. 8210130406
- --B210130414 LER 82-107/03L-0 on B2090B, performance of RCIC preventative maint procedure disclosed inoperability of RCIC trip & throttie valve & RCIC sys Caused by closure of turbine trip & throttie valve Trip & throttie valve opened TIPPS.5 B Georgia Pouer Co B2/09/28 Region 2. Office of Director 2pp 15680 262 24X Fiche 50-366/82/09/28.8210130406
- 8210130541 Forwards updated LER 82-00B/03X-2 NIA.H C Opengia Power Co 82/07/28 O'REILLY, J P Region 2, Office of Director ip 15683 301 24X Fiche 50-366,82/07/28, 8210130541
- --B210130549 Updated LER B2-00B/03X-2 on B20126.during steady-state operation.i15 control rod drive accumulator low pressure alarm switches found in need of callbr Gaused by instrument drift Betpoints reset Fill valves being overhauled TIPPS B B Georgia Power Co B2/09/28 Region 2. Office of Director 2pp 15683 302 24X Fiche 50-366,82/09/28.8210130541

- 82:0130220 Forwards LER 82-110/03L-0 NIX.H C Georgia Pawer Co 82/09/30 O'REILLY, J P Region 2. O+tice of Director ip 15675 232 24X Fiche 50-366,82/09/30, 82:0130220
- --B210130223 LER 82-110/03L-0 820909.during steady-state operation, performance of monthly drywell procedure disclosed integrator output outside acceptable range Caused by instrument drift Drywell equipment drain sump pumps secured TIPPS.8 B Georgia Power Co B2/09/30 Region 2. Office of Director 2pp 15675 233 24X Fiche 50-366.82/09/30.8210130220
- B210190504 Forwards LER B2-107/03L-0 NIC, N C Georgia Power Co 82/10/05 O'REILLY, J P Region 2, Office of Director 1p 15736 OOL 24X Fiche 50-366.82/10/05, B210190504
- --B210170511 LER 82-107/03L-0 on 820906, w/unit at 1,831 MWt, unreviewed spet release order discovered Caused by Personnel oversight Personnel reinstructed on importance of complying w/Tech Spec & B3 c Procedure reviewed & signed TIPPS.S & Georgia Power Co 82/10/05 Region 2, Office of Director (p. 15736 002 24X Fiche 50-366.82/10/05,8210190504
- 8210170575 Forwards LER 82-108/03L-0 NIA:H C Georgia Power Co 82/10/05 O'REILLY, J P Region 2, Office of Director 1p 15739 337 24X Fiche 50-366, 82/10/05, 6210170575
- --B210190402 LER 82-108/03L-0 on 820907, discovered that manthly surveillance procedure re emergency buses 2E,2F & 20 undervoltage relay instrument FT not performed by 820902 per Tech Specs Caused by personnel error Personnel counseled TIPPS:5 B Georgia Power Co 82/10/05 Region 2, Office of Director ip 15739 338 24X Fiche 50-344,82/10/05,8210190595
- 8210290357 Forwards updated LER 79-098/01X-1 NIA: H C Georgia Power Co 82/10/07 D'REILLY, J P Region 2, Office of Director Ip 15853 086 24X Fiche 50-366,82/10/07, 8210270357
- --B210270364 Updated LER 79-098/01X-1 on 790902 plant engineering personnel reviewed wirting diagrams & confirmed problem w/APCI cable separation Caused by design error HPCI cable renauted per pesign Change Request 79-380 on 810822 SUMMER.H L Georgia Power Co 82/10/07 Region 2, 0ffice of Director 2pp 15853 087 24X Fiche 50-366,82/10/07,8210290357
- 82:0270374 Forwards LER 82-111/03L-0 NIX.H C Georgia Power Co 82/10/12 O'REILLY, J P Region 2, Office of Director 1p 15853 010 24X Fiche 50-366.82/10/12, 82:10270374
- --8210290381 LER 82-111/03L-0 on 820918, shift technical advisor ran P-1 (periodic core performance log) w/o benefit of OD-1 (low power range monitor) P-1 indicated FRTP of 0 627 & core max fraction of limiting power density of 0 653 SUMMER, H L Georgia Power Co 82/10/12 Region 2, Office of Director ip 15853 Oii 24X Fiche 50-366,82/10/12,8210290374
- B210290206 Forwards LER 82-105/03L~0 NI(.H C Georgia Power Co B2/10/14 O'REILLY, J P Region 2, Office of Director ip 15853 291 24X Fiche 50~366,82/10/14, B210290206
- --8210290207 LER 82-105/03L-0 on 820918, during selection of rods to increase power, rod out permissive light went out, Caused by blown power fuse Fuse replaced TIPPS.S B Georgia Power Co 82/10/14 Region 2, Office of Director (p 15853 292 24X Fiche 80-366.82/10/14,8210290206
- 8210290075 Forwards LER 82-106/03L-0 NIX.H C Georgia Power Co 82/10/19 D'REILLY, J. P Region 2: Difice of Director 1p 15853 149 24X Fiche 50-366, 82/10/19, 6210290075
- --8210270080 LER 82-106/03L-0 on 820722, during steady-state operation.
 RCIC sys supply valve position indicator lights found
 extinguished Caused by breaker being turned off Breaker
 turned on Investigation initiated
 TIPPS.S B Georgia Power Co 82/10/17 Region 2, Office of
 Director Ip 15853 150 24X Fiche 50-366,82/10/17,8210290075
- DOCKET 50-367 BAILLY GENERATING STATION

 G Adjudicatory correspondence
- 8210040022 Notice of withdrawal of appearance in proceeding LEWIS, S.H. Hearing Branch 2 82/09/29 3pp 15581 257 24X Fiche 50-367, 82/09/29, 8210040022

- G Inspection reports, IE Bulletins & correspondence
- 6210090162 Forwards notice of site inspito be conducted on B21018 in conjunction w/ongoing restoration work per ASLB 820506 order terminating proceedings on application for CP extension SMORB.E M Northern Indiana Public Service Co 82/10/01 DENTON.IR Defice of Nuclear Reactor Regulation, Director Spp 15605 144 247 Fiche 50-267, 02/10/01.8210050162
- S Reportable occurrences, LERs & related correspondence
- 6210050512 Responds to FBIA request for insp & enforcement records re accidents of F Lawson & H Dillon at facility. Union Electric CP & other NRC safety matls or manuals Forwards two documents Renaining records available in PDR FELTON. J M Division of Rules and Records 82/09/21 100E, M V Igoe, V M 2pp 15426-244 24X Fiche 50-000, 82/09/21, 8210050512
- --8210050518 Region 3 daily rept for 780807 4 Region 3. Chicago, Office of the Director 78/08/07 ip 15626 246 24X Fiche 50-000,82/09/21.8210050512
- DOCKET 50-368 APKANSAS NUCLEAR DNE, UNIT 2 F Security, medical, emergency & fire protection plans
- 8210D10175 Forwards IE Safeguards Insp Repts 50-313/82-25 & 50-348/82-22 on 820818-20 No noncompliance noted SEIDLE, N.C. Division of Resident, Reactor Project ** Engineering Programs 62/09/16 CAVANAUGH, N. Arkansas Fower ** Light Co. 2015567 282 24% Fiche 50-313,82/09/16.8210010175
- --8210010178 IE Safeguards Insp Repts 50-313/02-25 & 50-368/8R-22 on 820819-20 No noncompliance noted Major areas inspetted security organization mgt.physical barriers & access control of packages Details withheld (ref 10CFR2 790) EVANS.C A Division or Vendor & Technical Programs 82/07/14 Ip 15567 284 24X Fiche 50-313.82/09/16.8210010175
- 8210190497 Forwards IE Insp Repts 50-313/62~11 & 50-348/82-09 on 820518-20 No noncompilance noted SEIDLE, N C Division of Resident, Reactor Project & Engineering Programs 82/09/28 CAVANAUGH, N Arkansas Power & Light Co 2pt 24% Fiche 50-313,82/09/28.8210190497
- -8210190516 IE Insp Repts 50-313/82-11 % 50-368/82-09 on 620518-20 No noncompliance noted Major areas inspected licenses ince & capabilities during Full-scale exercise of y plans & procedures M Division of Resident, Reactor Project & Engineering 82/09/24 17pp 24% Fiche 50-313,82/09/28,8210190497

- 8210260178 Ack receipt of 820929 ltr requesting addl time to respond to violations noted in Emergency Piepaledness Appraisal Repts 50-313/62-22 & 50-368/82-21 Response to App C due by 830501 SEIDLE.W C Division or Resident. Reactor Project & Engineering Programs 82/10/19 CAVANAUGH.W Arkansas Power ** Light Co lp 15799 037 24% Fiche 50-313.82/10/19.8210260178
- --8210260180 Responds to NRC 820625 ltm re App C to IE Emergency
 Preparedness Appraisal Repts 50-313/82-22 & 50-368/82-21
 Deficiencies resolved in emergency plan amends &
 implementing procedure revisions
 CAVANAUGH, W. Artansas Power & Light Co. 82/09/29 COLLING. & f
 Region 4. Office of Director 4pp. 15799 038 24X
 Fiche 50-313,82/10/19 8210260178
- P Operating license stage documents & correspondence
- B21001000B Responds to F01A request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FCLTON.J H Division of Rules and Records 82/06/28 UDELL.P A Critical Mass Energy Project 15pp 15727 005 24x Fiche 50-000, 82/06/28.8210010008
- --B106100203 Discusses evaluation of HPSI pump operability w/o svc uater Operability of HPSI pumps w/o svc water not adequately justified based on info submitted by licensee IMBRO.C Director's Office 81/05/22 Director's Office App 15727 185 24X Fiche 80-000/82/06/28/8210010008
- 8210190908 Responds to 020831 submittal re Tech Spec revision for snubber surveillance License amend application should be submitted to incorporate applicable portion of 801120 model Tech Specs within 60 days CLARK, R.A. Operating Reactors Branch 3 82/09/21 CAVANAUOH, WATJansas Power & Light Co. 2pp. 15740 301 24X Fiche 50-313,82/09/21.8210190008
- 8210130409 Responds to NRC 810619 ltr transmitting Amend 24 to Ficence NFF-6 re-serred reactor contant pump shaft event reanalysis Event description & results of Cycle 2 serred retur event enci MARSHALL, JR Ankansas Power & Light Co 82/10/05 CLARK, R A Operating Reactors Branch 3 8pp 15601 010 24X Fiche 50-368, 82/10/05, 8210130409
- B210200022 Provides preliminary info as result of fuel insp that revealed noed to modify some Batch C fuel assemblies to provide addi space for avial growth of fuel rods SCHEMER.A E Combustion Engineering, Inc. 82/10/05 DEVEUNG.R C Director's Office. Office of Inspection and Enforcement 2pp 15755 004 24% Fiche 50-368,82/10/05.8210200022
- B210150002 Forwards response to B20120 % 0301 requests for addl info re RCB high point vents Credible missiles generated by failure of RCB vent valves not postulated based on valve design Leak detection provided for by monitoring pressure HARSHALLIJR Arkansas Fower & Light Co B2/10/06 B70LZIJF Operating Reactors Branch 4 CLAKK.R A Operating Reactors Uranch 3 4pp 15696 309 24X Fiche 50 313.82/10/06.8210190002
- 8210150494 Submits info re status of waste gas tys & schedule for installation of redundant hydrogen/diygen analysers. Conceptual diagram of proposed upgraded waste gas tys redundant analyser panel encl MARSHALL, J.R. Arkansas Power & Light Co. 82/10/12 STDLZ, J.F. Operating Reactors Branch 4 CLARK, R.A. Operating Reactors Branch 3 4pp (5714 184 24X Fiche 50-313,82/10/12,8210150494
- 8210250159 Application to amend License NPF-6, changing Tech Specs to allow for removal of surveillance capsule & analysis of specimen CAVANAUGH.W Arkansas Power & Light Co B2/10/15 CLARK.R A Operating Reactors Branch 3 3pp 15787 313 24X Piche 50-368.82/10/15.8210250159
- --8210250161 Proposed Tech Bpec change allowing for removal of surveillance capsule & analysis of specimen

 Arkansas Power & Light Co 82/10/15 1p 15787 316 247 Fichs. 50-368, 82/10/15. 8210250159
- 8210270101 Forwards nine revised oversize P&IDs Drawing transmittal list encl Aperture cards are available in PDR 8HIVELY.C Arkaneas Power & Light Co 82/10/18 NRC - No Detailed Affiliation Given 2pp 15829 325 24X Fiche 50-368.82/10/18.8210270101

Q Inspection reports. IE Bulletins & correspondence

- 6210080015 Add1 response to FOIA request for 19 categories of info 18 nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Elemption 5) FELTON, J.M. Division of Rules and Records 82/07/12 UDELL, R.A. Critical Mass Energy Project 9pp 15665 027 24% Fiche 30-000, 82/07/12, 8210080015
- £210080112 Systematic assessment of licensee performance notes refacility evaluation for 790101-800819
 4 NRC No Detailed Affiliation Given 80/08/19 Spp 15667 291 24X Fiche 50-000, 82/07/12, 8210080015
- R210010175 Forwards IE Safeguards Insp Repts 50-313/82-25 & 50-388/82-22 on 820918-20 No noncompliance noted SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs 82/09/16 CAVANAUGH W Arkansas Power & Light Co 29, 15567 282 24X Fiche 50-313.82/09/14.8210010175
- --8210010178 IE Safeguards Insp Repts 50-313/82-25 & 50-368/82-22 un 820818 20 No noncompliance noted Major areas inspected security organization mot physical barriers & access control or packages Details withheld tref 10CFR2 790) EVMI3, C A . KELLY, J A F Division of Vendor & Tochnical Programs 82/09/14 1p 15567 284 24% Fiche 50-313.62/09/16.8210010175
- B*:019049/ Forwards (E Insp Repts 50-313/82-11 & 50-368/82-09 on 820518-20 No noncompliance noted SEIDLE.W C Division or Resident, Reactor Project & Engineering Programs 62/09/28 GAVANAUOH.W Arkansas Power & Light Co 2(15735-344 24X Fiche 50-313,82/09/20.8210190497
- 9210190516 If. Insp Repts 50-313/82-11 & 50-368/82-09 on B20518-20 No noncompliance noted Major areas inspected licensee performance * capabilities during full-scale exercise of energoncy plans & procedures
 ROHRER, D. M. ; HUNNICUTT D. M. Division of Resident, Reactor Project & Engineering Programs
 62/09/24
 17pg 15735-346 24x
 Fiche 50-313,82/09/28-8210190497
- 0210120246 Ack receipt of 820211 ltr informing NRC of steps taken to correct violations noted in IE lasp Repts 50-313/81-30 & 50-368/81-29
 9510LE.U C Division or Resident, Reactor Project & Engineering Programs 82/10/01 CAVANAUGH, W Arkansas Power & Light Co lp 15652 110 24x Fichs 50-313, 82/10/01, 8210120246
 - 8210123252 Responds to NRC 620104 Itr re violations noted in IL Insp Repts 50 313/61-30 / 90-368/81-29 Corrective actions formal training sessions will be conducted w/appropriate station personnel to stress importance of individual responsibility MARSHALL J R Arkansos Power & Light Co 82/02/11 MADSEN.G L Division of Resident Reactor Project & Engineering Programs Upp 15652 111 24X Fiche 50-313.62/10/01.6210120246
- 6210200022 Provides preliminary info as result of fuel insp that revealed need to modify some Batch C fuel assemblies to provide adult space for axial growth of fuel rads SCHERER, A E Combustion Engineering, Inc 82/10/05 DEYOUNG, R C Director's Orfice. Office of Inspection and Enforcement 2pp 13753 004 24X fiche 30-366.82/10/05.8210200022
- 8210220270 Forwards IE Insp Repts 50-313/82-12 & 50-368/82-25 on 820524-27 No noncompliance noted SEIULE-H C Division of Resident, Reactor Project & Engineering Programs 82/10/05 CAVANAUOH, M Alkensas Power & Light Co 2pp
- --8210220281 IE Insp Repts 50-313/82-12 & 50-368/82-25 on 820524-27 No noncompliance noted Major areas inspected radiochemistry program, including organization, staffing, braining program, sample collection & sample treatment & analysis NICHOLAS. J B , MURRAY. B Region 4, Office of Director 82/09/09 25pp 19775 003 24x Fiche 50-313,82/10/05,8210220270
- 8208190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24

- 8210120241 Ack receipt of 820719 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-20 & 50-368/80-20 & SEIDLE: W C Division of Resident, Reactor Project & Engineering Programs 82/10/06 CAVANAUGH: W Arkansas Power & Light Co ip 19652 113 24X Fiche 50-313,82/10/06,8210120241
- --8210120247 Provides status update on gaseous radioactive waste sysmods, in response to violations noted in IE Insp Repts 50-313/80-20 & 50-368/80-20 High airborne activity incidents in auxiliary bldgs significantly reduced MARSHALL.J R Artaness Power & Light Co 82/07/15 GCIDLE, W C Division of Resident. Reactor Project & Engineering Programs 3pp 15452 114 24X Fiche 50-313.82/10/06.8210120241
- 8208190238 IE Bulletin B2-03, "Btress Carrosion Cracking in Thick-Wall.Large-Diameter, Stainless Steel, Recirculation Sys Piping at BBR Plants "Svc list encl DEYOUNO, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Cansolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000, 82/10/14, 8208190238
- 8210220377 Categorizes upen itoms identified in IE Emergency Preparedness Repts 50-313/82-11 & 50-368/82-09 by need for Immediate consideration & type of response acceptable Notification of expected response date due within 10 days SEIDLE.W C Division of Resident. Reactor froject & Engineering Programs 82/10/19 CAVANAUGHW Arkansas Power & Light Co 4pp 19779 175 24X Fiche 50-313,82/10/19.8210220377
- 8210260178 Ack receipt of 820929 ltr requesting addl time to respond to violations noted in Emergency Preparedness Appraisal Repts 50-313/82-22 & 50-368/82-21 Response to App C due by 830501 SEIDLE: C Division of Resident, Reactor Project & Engineering Programs 82/10/19 CAVANAUGH: R Arkansas Power & Light Co Ip 15799 037 24X Fiche 50-313,82/10/19,8210260178
- --8210260180 Responds to NRC 820629 ltr re App C to IE Emergoncy Preparedness Appraisal Repts 50-313/62-22 & 50-368/82-21 Deficiencies resolved in emergency plan amends & implementing procedure revisions CAVANAUGH, W Arkansas Power & Light Co 82/09/29 COLLING, J T Region 4. Office of Director 4pp 15799 038 24X Fiche 50-313, 82/10/19, 8210240178
- B Reportable occurrences, LERs & related correspondence
- B012290118 Discusses conclusions of angineering evaluation of steam generator overfull transfents at C-E & Westinghouse pients LANNING.U D Director's Office B0/10/29 MICHELSON.C Director's Office 3pp [5692-262 24X Fiche 50-000.80/10/29.8012290118]
- 8210080028 Advises that Sept 1980 blockage of flow by silt to bearing oil coolers & seal water coolers of all high pressure safety injection pumps considered AD Util failed to justify pump operability w/o water IMBRD.E Director's Office 81/05/22 Director's Office 4pp 15669 303 244 Fiche 30-368,81/05/22,8210080028
- 8210190009 Discusses repetitive failures of emergency feedwater flow valves at facility due to valve operator hydraulic problems Recommends that hydraulic valve operators be added to branch watch list IMBRO.E V Reactor Operations Analysis Branch 82/02/24 MIGHELSON.C Director's Office 3pp 15760 303 24X Fiche 50-368.82/02/24.8210190009
- 921001009B Responds to FOIA request for 19 categories of documents ro nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDECL, R A Critical Mass Energy Project 15pp 15727 009 24X Fiche 50-000,82/06/28,6210010008
- --8107010161 Discusses inoperability of instrumentation due to extreme cold weather IS should issue suppl to IE Bullotin 79-24 requesting Tech Spec changes which require daily surveillance during extreme weather MICHELSON C Director's Office 81/06/15 DENTON H R Office of Muclear Reactor Regulation, Director Spp. 15727 208 24X Fiche 50-000, 82/06/28, 821001000B
- --8203120016 Discusses repetitive failures of emergency feedwater flow value as reported in LERs due to valve operator hydraulic problems LERs encl
 IMBRG.E V Director's Office 82/02/24 MICHELBUN.C Director's Office 76pp 15732 308 24X Ficher50-000,82/06/28,8210010008

- 8210050346 Confirms 820922 telcon w/NRC resident inspector re discovery that clearance between top of fuel rads & bottom of upper flow plate on batch C fuel assemblies may not prevent pin contact Mod planned LER 82-030/017-0 will follow LEVINE, J M Arkansas Power & Light Co 82/07/23 COLLINS, J Region 4, Office of Director 1p 15610 125 24X Fiche 50-368, 82/09/23,8210050346
- 8210190545 Forwards LER 82-030/017-0
 MARSHALL.J R Arkansas Power & Light Co 82/10/06 SEIDLE.W C
 Division of Resident. Reactor Project & Engineering Programs 19
 15735 006 24% Fight 50-368,82/10/06.8210190545
- ---P210190558 LER 82-030/017-0 on E20722: measurements revealed shoulder gap clearances on certain batch C fuel assemblies may not be sufficient to prevent pin contact Caused by design models & annealed guide tubes growing at lesser rate RODERS P Arkansas Pouer & Light Co B2/10/06 Region 4, Office of Director App 15735 007 24% Fiche 50-368.82/10/06.82/10/058
- 8210250272 Forwards LER 82-031/01T-0 MARSHALL.J R Arkansas Power & Light Co 82/10/13 SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs 1; 13770 064 24X Fiche 50-366.82/10/13.8210250272
- --B210250298 LER 82-031/01T-0 on 821001 after disassembling emergency feedwater pump turbing steam supply check valve for insp. disc studinut washer & locking pin discovered missing Caused by vibration fatigue Parts replaced ROGERS.F Arkansas Power & Light Co 82/10/13 Region 4. Office of Director 4pp 15770 065 24X Fichs 50-368.82/10/13, 8210250292
- 8210260120 Forwards LER 82-029/03L-0 MARSHALL, JR Arkansas Power & Light Co 82/10/15 SEIDLE.W C Division of Resident, Reactor Project & Enginesring Programs 1p 15799 074 24% Fichs 50-368.82/10/15.8210260120
- ---B210260123 LER 82-029/03L-O on 820918 four electrical cables discovered pulled through fire curtain Caused by personnel error while performing station battery capacity test Personnel unaware of fire curtain in wall opening Haint personnel counseled ROOERS, P. Arkansas Power & Light Co. B2/10/15 Region 4. Office of Director 2sp 15799 077 24X Fiche 50-268.82/10/15, E210260120
- 8210260474 PND-1V-82-038 insp of svc water sys identified deficiencies in plps supports Deficiencies include hanger installation not in accordance w/design.incorrect as-built drawings & workmanship defects
 JOHNEDIN.W D Region 4. Office of Director 82/10/20 1p 15806 236 24x Fiche 50~368,82/10/20.8210260474
- DOCKET 50-3A9 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8210010008 Responds to FDIA request for 19 categories of documents re nuclear reactor events 0 safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Crifical Nats Energy Project 15pp 15727 005 24X Fiche 50-000,82/06/28,8210010008
- F Security, medical, emergency & fire protection plans
- 9210150006 Ack receipt of 820723 itr informing NRC of steps taken to correct improvement items noted in IE Emergency Preparednyss Appraisal Rept 50-369/02-06

 LEWIGLR C Division of Project & Resident Programs 82/09/13 FARKER. W C. Duke Power Co ip 15698 214 24X Fiche 50-369, 62/09/13, 8210150006
- --82t0150012 Forwards response to NRC 820625 ltr re improvement items noted in IE Emergency Preparedness Appraisal Rept 50-369/82-06 on 820301-12 Corrective actions lesson plans for emergency response training complete PARKER, N O Duke Power Co 82/07/23 D'REILLY, J, P Region 2, Office of Director 10pp 15698 215 24% Fiche 50-369,82/08/13,8210150006

- --8210150020 Forwards IE Emergency Preparedness Appraisal Rept 50-365/82-06 on 820301-12 Na violations, deviations or emergency preparedness deficiencies noted O'REILLY, J P. Region 2. Office of Director 82/06/25 PARKER, N O Duke Power Co 7pp 19698 225 24X Fiche 50-309, 82/08/13,8210150006
- --B210150025 IE Emergency Preparedness Appraisal Rept 50-369/82-06 on 820301-12 No violations or deficiencies noted Major areas imagected evaluation of adequacy of emergency preparedness program Evaluation encl SIKONDS, G E. JENK INS, G R. Division of Emergency Preparedness & Operational Support 82/06/22 46pp 15698 226 24X Fiche 50-369,82/08/13,8210150006
- 8210150014 Forwards IE Insp Rept 30-349/82-71 on 820830-0903 No noncompliance noted DANCE, H G Division of Project > Resident Programs 82/09/24 TUCKER, H B Dute Power Co 2pp 15698 333 34X Fiche 50-369, 82/09/24,8210150014
- --8210190021 IE Insp Rept 50-369/82-31 on 820830-0903 No noncompliance noted Major areas inspected emergency preparedness MARSTON, R R , JENKINS, O R Division of Emergency Preparedness & Operational Support 82/09/23 11pp 15498 335 24X Fiche 80-369,82/09/24.8210190014
- B210190097 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records B2/09/29 Document Management Branch lp 15761 127 24% Fiche 50-369,82/09/29,8210190097
- --8210190103 Forwards public version of levised emergency plan implementing procedure. Including Procedure AP/0/A/5500/27 recare & transportation of contaminated injured individuals from site to offsite medical facility TUCKER, H B Duke Power Co 82/09/15 DENTON, H R Office of fluctear Reactor Regulation. Director 2pp 19761 128 24X Fiche 50-369, 82/09/29, 82/0190097
- --821019010B Public version of revised omergency plan implementing procedures, including Procedure AP/O/A/5500/27 re cere & transportation of contaminated injured individuals from site to offsite medical facility GLOVER. HS Duke Power to 82/08/30 92pp 15761 130 24% Fiche 50-369, 82/09/29, 8210190097
- 8210070072 Notifies that local alarms missing from control room fire james will be installed by 830701.per Jan 1979 fire protection review Issue not considered significant safety concern TUCKER.H B Dute Power Co 82/09/30 DENTON,H R . ADENSAM. C Office of Nuclear Reactor Regulation. Director 1p 15628 164 24X Fiche 50-367, 82/09/30. 8210070072
- 8210180234 Responds to util 820520 ltr re Revision 13 to physical security plan Changes consistent w/provisions of 100cR50 54(p)
 ADEMSAME 0 Licensing Branch 4 82/09/30 TUCKER.H D Duke Power Co 2p 15745 337 24% Fiche 50-369,82/09/30,0210180254
- B210150518 Forwards revised McQuire Nuclear Btation Fire Protection Rgvisu " Submittal supersedes all previous revisions TUCKER.N D Dute Power Co 82/10/07 DENTON.H R . ADENSAM.E Q Dffire of Nuclear Reactor Regulation. Director ip 15714 219 24x Fiche 50-369, 82/10/07, 8210150518
- 82(0270132 Releases public version of revised emergency plan implementing procedures FELTON-J M Division of Rules and Records 62/10/08 Document Management Branch ip 15835 136 24X Fiche 50-369,82/10/08,82/10/270132
- ---8210270137 Forwards public vertion of revised emergency plan implementing procedures, including Procedure EP/O/A/5000/05 re notification of unusual event.EP/O/A/5000/06 re alert & EP/O/A/5000/08 re general emergency TUCKER, H B Duke Power Co BZ/09/28 DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp 15835 137 24X Fiche 50-369, BZ/10/08, BZ10270132
- --GZ10270144 Public version of revised 4margency plan implementing procedures, including Procedure EP/0/A/5000/05 re notification of Unyoual event EP/0/A/5000/06 re alert & EP/0/A/5000/08 re general emergency OLOVER,M 8 , OILBERT,O D Duke Power Co 62/09/13 62pp 15835 139, 24X Fiche 50-367,82/10/08.6210270132

DOCKETED ITEMS

- B210280016 Releases public version of revised smergency plan FELTON, J M Division of Rules and Records 82/10/12 Document Namagement Branch Ip 15863 006 24X Fiche 50-369, 82/10/12, B21030014
- --8210280017 Forwards public version of Revision 7 to emergency plan TUCKER.H B Duke Power Co 82/09/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 15863 007 24X Fiche 50-369,82/10/12-8210280016
- --8210280020 Public version of Revision 7 to emergency plan HCINTOSH.H D. Duke Power Co. B2/07/30 28pp 15863 007 24X Fishe 50-369,82/10/12-8210280016

H General correspondence

82:0130046 Responds to 820712 itr request that NRC continue to send capies of correspondence to util on McGuiro Since McGuiro proceedings complete t documents in LPDR, request denied ADENSAM, E 0 Licensing Branch 4 82/07/28 RILEY, J L Carolina Environmental Study Group ip 15496-284 24X Fiche 50-000, 82/07/28, 82:0130046

K Utility Final Bafety Analysis Report (FSAR) & amends

- 82(0040254 Forwards application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Dutside Centainment for McGuire Nuclear Station "TUCKER, H B Duke Power Co 82/10/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Granch 4 3pp 15595 032 24X Fiche 50-369, 82/10/01,8210040234
- --8210040273 Application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pips Fallures Dutaide Containment for Higuire Nuclear Station" TUCKER.H B Dute Power Co. 82/10/01 16pp 15595 035 24X Fichs 50-369, 82/10/01.8210040254
- ---8210040279 Revision 6 to "Evaluation of Effects of Postulated Pipu Failures Dutside Containment for McGuire Nuclear Station" * Duke Power Co MDS/PD0-77-1 82/10/01 3pp 15595 051 24x Fiche 50-369,82/10/01,8210040254
- --8210040286 Revision 43 to FBAR Fourteen aperture cards available in PDR

 * Duke Power Co 82/10/01 303pp 15595 054 24X
 Fiche 50-369,82/10/01,8210040254
- 8210130262 Forwards figures to Revision 43 to FSAR, included in 821001 application for Amend 69 to License NPF-9 & CPPR-84 Subjusti Inadvertently omitted TUCKER, H B Duke Power Co 82/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p 15675 293 24X Fiche 50-369, 82/10/07, 8210130262
- --8210130263 Figures for Revision 43 to FBAR + Duke Power Co 82/10/07 42pp 15675 294 24X Fiche 50-369,82/10/07,8210130262

P Operating license stage documents & correspondence

- \$21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records \$2706/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82706/28.821001000B
- 8210040424 Forwards request for add1 info re hydrogen control Coordinated util response suggested by mid-Oct 1782, since sub; is generic to its condenser plants NOVAK.T M Assistant Director for Licensing 82/09/17 TUCKER.H B Duke Power Co 10pp 15597 241 24X Fiche 50-369, 82/09/17, 8210040424
- 8210180389 Notifies that 790330 application requesting extension of const completion dates exempt from fee requirements since no review commenced on application prior to issuance of OL Refund forthcoming MILLER, W O License Fee Management Dranch 82/09/24 PARKER, W C Buke Power Co ip 15746 359 24X Fiche 50-369,82/09/24,8210180389

- 8210040254 Forwards application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Outside Containment for McGuire Nuclear Station "TUCKER, H S Duke Power Co 82/10/01 DENTON H R Office of Mucker Reaction Regulation. Director ADENSAR, E G Licensing Branch 4 3pp 15595 032 24% Fiche 50-369, 82/10/01, 8210040254
- --8210040273 Application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Outside Containment for McGuire Nuclear Station"

 TUCKER:H B Oute Power Co 82/10/01 16pp 19599 035 24X
 Fishe 50-369,82/10/01,8210040254
- --8210040277 Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Outside Containment for McGuire Nuclear Station" • Duke Power Co MDS/PDG-77-1 82/10/01 3pp 15595 051 74x Fiche 50-369, 82/10/01.8210040254
- 8210130262 Forwards figures to Revision 43 to FSAR, included in BP1001 application for Amend 69 to License NPF-7 & CPPR-84 Subj. matl Inadvertently omitted TUCKER. H B Duke Power Co. 82/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G. Licensing Branch 4 ip 15675 273 24X Fiche 50-369.82/10/07.8210130262
- 82/10/30467 Responds to Openeric Ltr 82-16 re NUREO-0/37 Tech Specs for Unit 1 will be upgraded to latest NRC requirements 2 combined w/Unit 2 Tech Specs upon issuance of Unit 2 OL in Mar 1983
 TUCKER. H B Duke Power Co 82/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E Q NRC No Detailed Affiliation Given ip 15682 154 24%
 Fiche 50-367.82/10/07.8210(30467
- 8210280407 Requests info demonstrating that Unit 2 equipment meets same seismic & dynamic qualification requirements as Unit 1 Info requested by 821027
 ADENBAM.E 0 Licensing Branch 4 82/10/08 TUCKER.H B Duke Pow Co 2pp 15859 327 24x Fiche 50-369.82/10/08.8210280407
- 8210230304 Forwards revised requests for rollef from hydrostatic testing requirements on foedwater sys for steam generators & Unit 1 safety injection eys ASHE Code Section XI impractical TUCKER.H II Duke Pawer Co 82/10/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 8pp 15790 205 24X Fiche 50-369.82/10/19.8210250304
- 8210260331 Application for amend to License NPF-9, changing Tech Spet re containment penetration Type C leak rate tests Amend requires exemption from 1007R50. App J THIES, A C Duke Power Co 82/10/21 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM.E C Licensing Granch 4 Jpp. 15803 178 24X Fiche 50-369.82/10/21,8210260331
- --8210260336 Proposed change to Tech Spec 4 & 1 2d, requiring that Type C penetration tests be performed at 2d-month interval, deviating from 10CFR30, App J requirement to perform test during each refueling shutdown
 4 Duke Fouer Co 82/10/21 4pp 15803 201 24X
 Fiche 50-369,82/10/21,8210260331
- a inspection reports, IE Bulletins & carrespondence
- 8210070097 Responds to FUIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FUIA Request 81-313 Forwards documents listed in App B. FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, 9timson, Putnam & Roberts 9pp 15649 063 24X Fiche 50-000. 82/08/10.8210070007
- --8210070137 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VARGA/S Operating Reactors Branch | 5pp 15645 131 24X Fiche, 50-000, 82/08/10, 8210070007
- 8210150006 Ack receipt of 820723 ltr informing NRC of steps taken to correct improvement items noted in IE Emergency Preparedness Appraisal Rept 50-364/82-06
 LEWIS.R.C. Division of Project & Resident Programs 82/08/13
 PARKEN,W.O. Duke Power Co. 1p. 156-98-214 24X
 Fiche 50-367, 82/08/13, 8210150006

- --8210150012 Forwards response to NRC 920525 ltr re improvement items noted in IE Emergency Preparedness Appraisal Rept 50-359/82-06 on 820301-12 Corrective actions lesson plans for emergency response training complete PARKER.W O Duke Power Co 82/07/23 0'REILLY, J.P. Region 2, Office of Director 10pp 15698 215 24X Fiche 50-369,82/08/13,82/0150006
- --8210180020 Forwards IE Emergency Preparedness Appraisal Rept 50-359/82-06 on 820301-12 No violations deviations or emergency preparedness defficiencies noted O'REILLY.J P Region 2. Office of Director 82/06/25 PARKER.H O Dute Power Co 7pp 15698 225 24X Fache 50-369,82/08/13,8210150006
- --8210150025 IE Emergency Preparedness Appraisal Rept 50-369/82-06 on 820301-12 No violations on deficiencies noted Hajor areas inspected evaluation of adequacy of emergency preparedness program Evaluation encl SIMONDS.O E. JENKINS.O R. Division of Emergency Preparedness & Operational Support 82/06/22 46pp (5698-226-24X Fiche 50-369.82/08/13.8210150006
- 9210010424 Forwards IE Insp Repts 50-369/82-29 % 50-370/82-23 on 820726-0820 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/08 TUCKER.H B Duke Power Co 2pp 15569 343 24% Fishe 50-369, 82/09/08,8210010424
- --8210010436 1E Insp Repts 50-369/82-27 % 50-370/82-23 on 820726-0820 Na noncompliance noted Major areas inspected maint, surveillance, but functional test, operational safety verification, significant event following & plant transients BENIS.P R. HOPKINS.P. GRYANT, J.C. Division of Project & Resident Programs 82/09/08 App. 15569-345 24X Fiche 50-369.82/09/08, 8210010424
- 8210010451 Forwards 1E Insp Repts 50-369/82-28 & 50-370/82-22 on 820817-20 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/09/08 TUCKER. H B Duke Power Co 2pp 18572 297 24X Fiche 50-369, 82/09/08, 8210010451
- --8210010459 IE Insp Repts 50-369/82-28 & 50-370/82-22 on 820817-20 No noncompliance noted Major areas inspected preoperational test procedure review & test uitnessing JOHNSON, A K., WHITENER, H.L., JAPE, F. Davision of Engineering & Technical Programs 82/09/07 6pp 19572 299 24X Fiche 50-369, 82/09/08, 8210010451
- 8210010282 Ack receipt of IE Insp Rept 50-369/82-27 No proprietary info TUCKER. H B Duke Power Co 82/09/10 O'REILLY, J P Region 2, Office of Director 1p 15573 109 24% Fiche 50-369, 82/09/10, 8210010282
- 8210010090 Ack receipt of IE Insp Repts 50-347/82-24 & 50-370/82-20 No proprietary info TUCKER, H B Dute Power Co 82/09/15 O'REILLY, J P Region 2, Office of Director ip 15545 259 24X Fiche 50-349, 82/09/15, 8210010090
- 8210150014 Forwards 1E Insp Rept 50-369/82-31 on 820830-0903 No noncompliance noted DANCE,H G Division of Project & Resident Programs 82/09/24 TUCKER,H B Duke Power Co 2pp 15698 333 24X Fiche 50-369, 29/09/24, 821015/014

- 8210220202 Ack receipt of IE lnsp Repts 50-369/82-28 & 50-3/0/02-22 No proprietary info TUCKER. H B Dute Pawer Co 82/10/08 O'REILLY, J P Region , Office of Director ip 15776 357 24X Fiche 50-369.82/10/04, 8210220202
- 8210220204 Ack receipt of IE Insp Repts 50-349/82-29 \$ 50-170/81 21 No proprietary info TUCKER.H B Duke Power Co 82/10/08 O'REILLY, J.P. Region 2 Office of Director 1p 15776 352 24X Fiche SO 369, 82/10/08 8210220204
- 8208190238 IE Bulletin 82-03, "Stress Corrusion Cracking in Inici Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants "Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 [25 24X Fiche 50-000, 82/10/14,8208190238
- A Periodic operating reports & related correspondence
- 8210190742 Forwards monthly operating rept for Sept 1982 TUCKER, H B Duke Power Co 82/10/15 Director's Office. Office of Inspection and Enforcement 1p 15737 085 24X Fiche 50-369, 82/10/15,8210190742
- --8210190751 Monthly operating rept for Sept 1982 REAVIS.J A Duse Power Co 82/10/15 6pp 15/3/ 086 241 Fiche 50-369-82/10/15.8210190742
- 5 Reportable occurrences, LERs & related correspondence
- G210010000 Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents Listed in App A FELTON.J M Division of Rules and Records S2/06/20 UDFIL:# A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000. 82/06/28,8210010008
- --Bi10050018 Requests addl info from util re Bi0914 safety injectic. a natural circulation event during performance of loss of control room test info needed includes data just prior to trip & up to 1-h following event SANDS; S P Director's Office Bi/09/22 DIRKEL, R licensity Branch 1 1p 15730 272 24X Fiche 50-000, 82/06/28, 82t0036CmJ
- ~-8210050124 Summary of 810610 operating teactor events meeting LAINAS.0 C Assistant Director for Eafety Assessment (81/06/1/EISENHUT.D C Division of Licensing 5pp 15729 21/ 24X Fichs 50-000, 82/06/28, 8210010008
- 8210010424 Forwards 1E Insp Repts 50-369/82-29 & 50-370/82-2) on 820726-0820 No noncompliance noted DARCE, H C Division of Project & Resident Programs 82/07/00 TUCKER. H B Duke Power Co 2pp 15569 343 24X Fichs 50-369, 82/09/08,8210010424
- --8210010436 IE Insp Repts 50-369/82-29 % 50-370/82-23 on 820/λδ-000 ks noncompliance noted Major areas inspected maint, surveillance, hot functional test, operational safety verification, significant event followup & plant transients BEMIS.P R , HOPKINS.P , BRYANT.J C Division of Project & Residina Programs 82/09/08 App 15569 345 24% Fiche 50-369.02/09/09 B210010424
- 8210130177 Forwards LER 82-069/03L-0 Detailed event analysis encl TUCXER.H B Duke Power Co 82/10/01 O'REILLY, J P Region 2 Office of Director 3pp 15673 022 24X Fiche 50-369,82/10/01, 8210130177
- --B210130180 LER 82-069/03L-0 on 820903, investigation of saveral spins of fire detection says zone alarms resulted in says being declared inoperable Caused by water in data gathering panel creating ground condition affecting entire says NARDUCI, P B Duke Power Co B2/10/01 Region 2, Diffice of Director ip 15673 025 24X Fiche 50-369,82/10/01.8210130177
- 8210220318 Forwards LER 82-070/03L-0 TUCKER, H B Duke Power Co 82/10/15 O'REILLY, J P Region 2. Office of Director 1p 15776 043 24X Fiche 50-369,82/10/15 8210220318
 - --B210220327 LER B2-070/03L-0 on B20916.one of two required oxygen analyzers failed to alarm after simulated high oxygen concentration generated Caused by misposition of toggle switch Switch returned to correct position NARDOCI.P.B Dute Power Co B2/10/15 Region 2. Office of Director Ip 15776 044 24X Fiche 50-369.82/10/15.8210220318

- DOCKET 50-370 WILLIAM 8 MCGUIRE NUCLEAR STATION, UNIT 2
- A Applacation/construction stage documents & correspondence
- Mai001000B Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents issted in App A
 FELTON, J II Division of Rules and Records 82/06/28 UDELL.R A
 Critical Mass Energy Project 15pp 15727 005 24X
 Fishe 50-000, 82/06/28, 8210010008
- --8008050265 Discusses addi required info to better define potential for cracking in reactor vessel nozzles NOCYARL'S Assistant Director for Materials & Qualifications Engineering 80/05/05 TEDESCORL Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000/82/06/28/8210010008
- Ballo040424 Forwards request for add1 info re hydrogen control coordinated util response suggested by mid-Oct 1982, since subj is generic to tre condenser plants HOVAK.T II Assistant Director for Licensing 82/09/17 TUCKER.H B Buse Power Co. 10pp. 1559/ 241 24x Fiche 50-369,82/09/17. 8210040424
- 8210180389 Notifies that 790330 application requesting extension of const completion dates exempt from fee requirements since no review commenced on application prior to issuance of QL Refund forthcoming MILER. If O License Fee Management Branch 82/09/24 PARKER. W C Dube Power to ip 15746 359 24% Fishe 50-369.82/09/24. 82101803897
- 6210040254 Forwards application to amend License NPF-9 & CPPR-64, consisting of Revision 43 to FSAR & Revision 6 to Evaluation of Effects of Postulated Pipe Failures Outside Containment for McOure Nuclear Station "

 1UCKER.H B Duke Power Co 62/10/01 DENTON, H R Office of Huclear Reactor Regulation, Director 3pp 15595 032 24X Fiche 50-369, 82/10/01, 8210040254
 - 8910040873 Application to amend Livense NPF-9 & CPPR-84, consisting of Revision 43 to ESAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Fallures Dutside Containment for REGuire Nuclear Station "
 TUCKET, N Duke Power Co 82/10/01 16pp 15595 035 24X Fiche 50-369, 82/10/01. 8210040254
- 5210]30262 Furwards figures to Revision 43 to FSAR, included in 821001 application for America 59 to License NPF-9 & CPPR-84 Subjust1 inadvertently omitted TiukER, Is 5 Duke Power Co 82/10/0/ DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 24X Fiche 50-349, 82/10/07, 8210130262
- 821028040/ Requests info demonstrating that Unit 2 equipment meets same seibmic & dynamic qualification requirements as Unit i Info requested by 821027
 ADENSAM, E.G. Licensing Dranch 4 82/10/08 TUCKER, H.B. Duke Power Co. 2pp. 15859-327 24X Fiche 50-369, 82/10/08, 8210280407
- 6210180128 Forwards [1st of important differences in Unit 1 & 2 design features, in support of review of proposed OL for Unit 2 TUCKER, II Duke Power Co. 62/10/11 DENTON-HR. Office of Nuclear Reactor Regulation, Director ADENBAM, E. O. Operating Reactors Oranch 4 2pp 15719 333 24X Fiche 30-370.82/10/11, 6210180128
- E210250304 Forwards revised requests for relief from hydrostatic testing requirements on feedwater sys for steam generators & Unit I safety injection sys ASME Code Section XI impractical TUCKER.H B Duke Power Co 82/10/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 8pp 15790 205 24X Firms 50-369, 82/10/19,8210250304
- F Security, medical, emergency & fire protection plans
- 0210170097 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/09/29 Document Management Branch ip 15761 127 24X Fiche 50-369.82/09/29. 82/019097

- --8210190103 Forwards public version of revised emergancy plan implementing procedure, including Procedure AP/0/A/5500/27 recare & transportation of contaminated injured individuals room site to offsite medical facility TUCKER.H B Duke Power Co 82/09/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15761 128 24X Ficha 50-369.82/09/29.8210190097
- --8210190108 Public version of revised emergency plan implementing procedures, including Procedure AP/O/A/5500/27 recare & transportation of contaminated injured individuals from site to offsite medical facility
 GLOVER, HS Duke Power Co 82/08/30 42pp 15761 130 24X Fiche 50-367.82/07/25,8210190077
- 8210070072 Notifies that local alarms missing from control room fire tones will be installed by 830701 per Jan 1979 fire protection review Issue not considered significant safety concern TUCKER.H B Duke Power Co 82/09/30 DENTON.H R ADENSAM, E G DEfice or Nuclear Reactor Regulation, Director ip 15628 164 24% Fiche 50-369, 82/09/30, 8210070072
- 8210160254 Responds to util 820520 ltr re Revisson 13 to physical security plan Changes consistent w/provisions of 10CRES 54(p)
 ADENSAM, E 0 Licensing Branch 4 82/07/30 TUCKER, H B Duke Power Co 2pp 15745 337 24X Fiche 50-367-82/07/30,8210180254
- 8210150518 Forwards revised McGuire Nuclear Station Fire Protection Review "Bubmittal supersedes all previous revisione TUCKER, H B Dute Power Co 82/10/07 DENTON, H R , ADENSAM, E Q Office of Nuclear Reactor Regulation, Director ip 15714 219 24% Fiche 50-369, 82/10/07,8210150518
- --8210150522 Revised "McQuire Nuclear Station Fire Protection Review "
 4 Duke Power Co 82/09/30 179pp 15714 220 24X
 Fiche 50-369.82/10/07.8210150518
- 8210270132 Releases public version of revised emergency plan implementing procedures FELTON, J H Division of Rules and Records 82/10/08 Document Management Branch ip 13635-136 24X Fiche 50-369,82/10/08, 8210270132
- --8210270139 Forwards public version of revised emergency plan implementing procedures including Procedure EP/O/A/3000/05 re notification of unusual event, EP/0/A/5000/06 re alert & EP/O/A/5000/08 re general emergency TUCKER.H B Duke Power Co 82/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15835 137 24X Fiche 50-369, 82/10/08, 8210270132
- --8210270144 Public version of revised emergency plan implementing procedures, including Procedure EP/O/A/5000/05 re notification of unusual event, EP/O/A/5000/06 re alert & EP/O/A/5000/08 re general emergency gLOVER.M S , 031,8ERT.6 D Dute Power Co 82/09/13 82pp 15835 139 24X Fiche 50-369,82/10/08,8210270132
- 8210190740 Forwards evaluation of facility concerning applicable requirements of 1007850, App R Device locations & cable routes omitted due to similarity w/Unit 1
 TUCKER, H B Duke Power Co 62/10/12 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 Spp 15736 250 24X Fiche 50-370, 82/10/12, 8210190740
- 8210280016 Releases public version of revised emergency plan FELTON.J M Division of Rules and Records 82/10/12 Document Management Branch ip 15863 006 24X Fiche 50-369,82/10/12,8210280016
- --8210280017 Forwards public version of Revision 7 to emergency plan TUCKER.H B Duke Power Co 82/09/28 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15869 007 24X Fiche 50-364:82/10/12,8210280016
- --8210280020 Public version of Revision 7 to emergency plan MCINTOSH; N D Duke Power Co 82/09/30 28pp 15863 009 24X Fiche 50-369,82/10/12,8210280016

H Ownerat correspondence

8210130046 Responds to 820912 ltr request that NRC continue to send copies of correspondence to util on McGuire Since McGuire proceedings corplete & documents in LPDR request denied ADENSAM.E.O Licensing Branch 4 82/09/28 RILEY.U L. Carolina Environmental Study Oroup 1p 15496 284 24X Fiche 50-000, 82/09/28,8210130046

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8210040254 Forwards application to amend License NPF-7 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Outside Contracts for Michigan Children Parkers." Containment for McGuire Nuclear Station "
 TUCKER,H B Dute Power Co B2/10/DI DENTGN.H R Office of
 Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch
 4 Jpp 15995 032 24X Fichs 30-349,82/10/DI.B210040254
- --8210040286 Revision 43 to FSAR Fourteen aperture cards available in Duke Power Co 62/10/01 303pp 15595 054 24x

Fiche 50-369, 82/10/01, 8210040254

- 8210130262 Forwards figures to Revision 43 to FBAR, included in 821001 application for Amend 67 to License NPF-9 & CPPR-84 Subj matt inadvertently omitted TUCKER. H B Duke Power Co 82/10/07 DENTON H R Office of Nuclear Reactor Regulation. Director ADENSAM E 0 Licensing Brand 1 p 15675 293 24% Fichs 50-369, 82/10/07, 8210130262 Licensing Branch
- --8210130263 Figures for Revision 43 to FSAR * Duke Pouer Co 82/10/07 42bp 13675 274 24x Fiche 30-369,82/10/07.8210130262
- Q Inspection reports, IE Bulletins & correspondence
- 8210010424 Forwards IE Insp Repts 50-369/82-29 & 50-370/82-23 on 820724-0820 No noncompliance noted DANCE.H C Division of Project & Resident Programs
 TUCKER.H B Duke Power Co 2pp 15569 343 24x
 Fiche 50-369.82/09/08.8210010424
- -8210010434 IE 1map Repts 50-369/82-29 & 50-370/82-23 on 820726-0820 No riodiousa it imp Repts 30-36976247 & 30-370762-23 on 820725-0820 Nr moncompliance noted Major areas inspected maint, surveillance, bot functional test operational safety werification, significant event followup & plant transients DEMIS.P R . MCPKINS.P . DRYANT.J C Division of Project & Resident Programs 82/09/08 App 15569 345 24X Fiche 50-369.82/09/08, 8210010424
- 8210010451 Forwards IE Insp Repts 50-349/82-28 & 50-370/82-22 on 820317-20 No noncompliance noted
 DANCE-H C Division of Project & Resident Programs 92/09/08
 TUCKER-H B Duke Power Co 2pp 15572 297 24X
 Fiche 50-369, 82/09/08, 8210010451
- --8210010459 IE Insp Repts 50-369/82-28 & 50-370/82-22 on 820817-20 No noncompliance noted Major areas inspected preoperational test procedure review & test witnessing JDHNSDN A H. WHITENER: Rt. J. JAPE, F. Division of Engineering & Technical Programs 82/09/07 6pp 15572 299 24X Fiche 50-369, 82/09/08, 8210010451
- 8210010090 Ack receipt of IE Insp Repts 50-349/82-24 & 50-370/82-20 No proprietary info
 TUCKER.H 8 Oute Power Co 82/09/15 O'REILLY, J P Region 2,
 Office of Director 1p 15565 259 24% Fiche 50-369,82/09/15.
- 8210010387 Ack receipt of IE Insp Rept 50-370/82-19 No proprietary 1676
 TUCKER, H B Duke Power Co 82/09/15 O'REILLY, J P Region 2.
 Office of Director 1p 15549 211 24K Fiche 50-370, 82/09/15, 8210010387
- 8210150053 Forwards IE Insp Rept 50-370/82-25 on E20831-0903 No noncompliance noted of Project 4 Resident Programs 82/09/22 TUCKER.H B Duke Power Co 2pp 15701 119 24X Fiche 80-370.82/29/22.8210180053
- --B210150052 IE Insp Rept 50-370/82-25 on B20831-0903 No noncompliance noted Major areas inspected preoperational test procedure reviews & witnessing JOHNSON, A H., JAPE, F. Division of Engineering & Technical Programs 82/09/15 4pp 15701 121 24X Fiche 50-370,82/09/22,8210150053
- 8210010093 Ack receipt of IE Insp Rept 50-370/82-21 No proprietary TOTKER, H. B Duke Power Co 82/09/23 O'REILLY, J.P. Region 2, Office of Director ip 15565 003 24X Fiche 50-370, 82/09/23.
- 8210150116 Forwards IE Insp Repts 50-369/82-32 & 50-370/82-26 on 820831-0903 No noncompliance noted DANCE-H C Division of Project & Resident Programs 82/09/24, TUCKER, H B Duke Power Co 2pp 15698 018 24X Fiche 50-369, 82/09/24, 8210150116

- --8210150123 IE Insp Repts 50-369/82-32 % 50-370/82-26 on 820831-0903 No noncompliance noted Major areas inspected licensee actions on previous enforcement matters, licensee identified items & hanger weld fabrication ECONDMOS.N., BLAKE, J. D. Division of Engineering & Technical Programs 82/08/22 Spp 15698 020 24% Fiche 50-369.82/09/24, 8210150116
- 8210220328 Forwards 1E Insp Rept 50-370/82-28 on 820914-17 No noncompliance noted noncompliance noted
 DANCE, H C Division of Project & Resident Programs 82/09/29
 TUCKER, H B Dute Power Co 2pp 15776 | 145 24X
 Fiche 50-370, 82/09/29, 8210220328
- --8210220337 IE 1msp Rept 50-370/82-28 on 820914-17 No noncompliance Toked Hajor areas insperted preoperational toet procedure task package reviews

 UDINSON.A H Division of Project & Resident Programs JAPE.;
 DIVISION of Engineering & Technical Programs 82/09/28 App 15776 147 24% Fiche 50-370, 82/09/29, 8210220328
- 8208170233 IE Info Notice 80-35, Suppl 1, "Loaking & Dislodged 1 125 Implant Seeds "Syr list enci CODBL I Division of Fuel Facilities, Materials & Gafeguards 82/19/06 Consolidated Edison Co of New York 66pp 1576 82/10/06 Consolidated Edison Co of New York 66pp 24% Fiche 50-000,82/10/06,8208170233
- 8210220202 Ack receipt of 16 Insp Repts 50-369/82-28 & 50-370/82-22 No proprietary info TUCKER-H B Duke Power Co 82/10/08 O'REILLY, J P Region 2, Orfice of Director 1p 15774 357 24% Fithe 50-349,82/10/08, 8210220202
- 8210220204 Ack receipt of IE Inap Repts 50-369/82-29 & 50-370/82-23 No proprietary info TUCKER, H B Duse Power Co 82/10/0B O'REILLY, J P Region 2, Office of Director ip 15776 352 24X Fiche 50-369, 82/10/0B. 8210220204
- 9209190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Flants " Svc list encl
 DEVOUNG.R C Director's Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New
 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190229 of New York
- S Reportable occurrences, LERs & related correspondence
- 8210010424 Forwards IE Insp Repts 50-369/82-27 & 50-3/0/82-23 on 200726-0820 No noncompliance noted
 DANCE, H C Division of Project & Resident Programs
 TUCKER, H B Duke Power Co 2pp 15569 342 24X
 Fiche 50-369, 82/09/08, 8210010424
- --8210010436 IE Insp Repts 50-369/82-29 & 50-370/82-23 on 820726-0820 #10010436 IE Insp Repts 30-369782-29 % 50-370782-29 on B207.
 noncompliance noted Major areas inspected maint,
 surveillance, hot functional test.operational safety
 verification, significant event followup & plant transients
 BEMIS.PR Division of Project & Resident Programs 82/0
 dpp 15569 345 24% Fiche 50-369,82/09/08,8210010424
- 8210290045 Significant Deficiency Rept SD 370/82-05 re problem w/SSPS on-line testing circuits Initially reported on 820720 Test procedures revised to ensure relay test circuits in SSPS operate properly
 TUCKER.H B Duke Power Co 82/10/20 O'REILLY.J P Region 2.
 Office of Director 3pp 15853 331 24X Fiche 50-370,82/10/20,
- DOCKET 50-373 LABALLE COUNTY STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents ro nuclear reactor events & safety problems Forwards documents 1 nuclear reactor events & safety problems Forwards documents 1 isted in App A FELTON, J H Division of Rules and Records B2/06/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24x Fiche 50-000, 82/06/28, 8210010008
- --8008050265 Discusses addl required info to better define potential f Cracking in reactor vessel notices

 NOONAN.V S. Assistant Director for Materials & Qualifications
 Engineering 80/09/05 TEDESCO.R L. Assistant Director for
 Licensing 2pp 15727-176 24X Fiche 50-000-82/06/28.8210010008

- f Security, medical, emergency & fire protection plans
- 8269290125 Releases public version of revised generating station 2014-10127 Releases public version or revised generating station emergency plan corporate command ctr emergency plan in the procedure FELTON.JM Division of Rules and Records 82/09/16 Docum Management Branch 1p 15544 122 24X Fiche 50-000.82/09/16

- -8209290189 Furwards public version of Revision 4 to generating station emergency plan corporate command str Emergency Plan Implementing Procedure EUF-3, "Environ/Emergency Coordinator " Receipt form encl PAUDUSNI.J E Commonwealth Edison Co 82/09/01 DENIUN, H R NRC No Detailed Affiliation Given 1p 15564 123 244 Fisch 50-000.82/09/16.8209290125
- 0209290225 Public version of Revision 4 to generating station emergency plan corporate command the mergency Plan Implementing Procedure EOF-3, "Environ/Emergency Coordinator PAJOWSKI J E E Commonwealth Edison Co 82/08/31 24X Fiche 50-000, 82/09/16, 8209290125 15564 124
- \$10060379 Forwards IE Insp Rept 50-373/82-19 on 820317-19,24-26 & OldOpOJAY Forwards It inspirept 30-3/3/82-14 on labout/214,24-26 of 0409 No noncompliance noted ITTLE.U.S. Division of Engineering & Technical Programs 82/09/21 REFD, C. Commonwealth Edison Co. 2pp. 15618-330 24X Fiche 50-3/3.82/09/21.82/0060379
- H2100603B4 iE insp Rept 50-773/82-19 on 820317-19.24-26 & 0408 No PRODUCTION IN THE PROPERTY OF STATE OF THE PROPERTY OF A CAUCH PROPERTY OF THE PROPERTY OF THE
- 210050052 Ack receipt of 820723 itr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-373/82-39 NILLER, J. R. Division of Engineering & Technical Programs 82/09/30 REED. C. Commanuealth Edison Co. 2pp. 15805 188 24X Fiche 50-373,82/09/30.8210050052
- P210059056 Forwards response to NRC 020824 Itr re viplations noted in IE Safeguards insp Rept 50-373/62-39 Response withheld (ref IOCFR73 21) 82/09/23 K DE(OEORGE, L O Commonwealth Edison Co 82/09/2 Region 3, Office of Director 2pp 15605 190 Fiche 50-373,82/09/30.8210050052 KEPPLER, J G
- 10130376 Advises that installation of offsite dose calculation sus program fully operational tracking model & operational A-model will be delayed until 021231 to complete prime computer initallation computer initallation SWARTZLE D. Commonwealth Edison Co. 02/10/06 DENTON, H.R. D. of Nuclear Reactor Regulation, Director 2pp i5682 098 24X Fiche 50-000, 02/10/06, 8210130376 Diffice
- 10290047 Releases public version of revisions to Guad Cities. Zion & TOWN UNITED SET PUBLIC VERSION OF PEVISIONS to Quad Cities, Zi Presden emergency plan annexes & revised generating station emergency plan telephone directory FELTQN. J M Division of Aules and Records 82/10/08 Docum Management Branch 1p 15877 313 24X Fiche 50-000,82/10/08,8210290047 Document
- 8210290000 Forwards public version of Revision 3 to Guad Cities & Zion EMBLY-VUODO FORWARDS public version of Revision 3 to Guad Cities & Zidemorgency plan annoles, Revision 2 to Drasden emergency plan annoles, Revision 0 to Oyron emergency plan annoles, trevised generating station emergency plan telephone directory MOORE, RD Commonwealth Edison Co 82/07/30 DENTON, HR NRC - No Detailed Affiliation Given Spp 15877 314 24X Fiche 50-000, 82/10/08, 8210290047
- 8210290088 Public version of revised generating station emergency plan GALLE, D F Commonwealth Edison Co 82/08/12 43pp 15878 218 24% Fich 50-000.82/10/08.8210270047
- 10220358 Provides info re organization & performance of depts 1022U39H Provides into re organization & performance of deparesponsible for radiation protection activities,per 820702 commitment Training coordinator assigned in Apr 1782 to improve health physics training programs
 TRAMM, TR Commonwealth Edison Co 82/10/14 DENTON.HR Office Noclear Reactor Rogulation, Director 9pp 15776 287 24X Fiche 50-000, 82/10/14, 8210220358

G Adjudicatory correspondence

- 8210040366 Responds to appeal re denial of FOIA request for four affidavits concerning allegations of improper const practices at facility Forwards requested info Page 4 of E Greve affidavit withheld (ref FOIA Exemption 7)
 DIRCKS.W J Office of the Executive Director for Operations 82/08/24 STEPTOE, P F Isham Lincoln & Beals 2pp 15597 303 24% Fische 50-373.82/08/24,8210040366
- --82i0040375 Forwards four affidavits re safety problems at facility Proprietary info deleted from two affidavits DEVINCT Institute for Policy Studies B2/05/11 FDRTUNA.R Director's Office. Office of Inspection and Enforcement 1p i5597 3i5 24X Fiche 50-373,82/08/24.8210040366
- --8207140491 Affidavit re results of sloppy concrete pours holes & honeycombs in concrete Accumulated debris not disposed of prior to pour & too much concrete poured at one time Worker Health not main concern of supervisors SWARTZ.D W Affiliation Unknown 82/06/24 10pp 15597 316 24X Fiche 50-373.82/08/24.8210040366
- ---8207140494 Affidavit re safety-related const flaws in installation of pipes & supports Pipes & hanger supports not placed as specified GREVE.E Affiliation Unknown 82/04/22 App 15597 326 24X Fichm 50-373,82/08/24.8210040366
- --8207140497 Affidavit re damage to fire protection equipment such as sprinklers throughout plant during const Concerns raised over core drillings of concrete reinforcement bars in containment walls & pedestal Hangers not as specified a Affiliation Unknown 82/04/21 App 18597 332 24% Fiche 30-373,82/08/24.8210040366
- --8207(40500 Affidavit re sioppy workmanship leading to const damage Const crews core drilled through reinforcement bars, containment wail & reactor vessel pedestal around 694 foot elevation of Unit i 4 Affiliation Unknown 82/04/21 3pp 19597 338 24X Fichs 50-373, 82/08/24 8210040366

H General correspondence

- 8210070042 Responds to 820816 ltr re third party review Forwards ltr responding to util selection of CF Braun & program for review of NAAC sys NOVAK, T M Assistant Director for Licensing 82/09/10 MORELLA, S L Affiliation Voknown 2pp 15646 226 2-Fichs 50-373-82/09/10.8210070042
- --82i0070045 Responds to 820813 itr re third party review Forwards itr responding to util selection of CF Braun & program for review of HVAC sys K/O stated anci NOVAK.T M Assistant Director for Licensing 62/09/10 DEVINE.T Affiliation Unknown 1p 13646 228 24X Fiche 50-373,82/09/10, 8210070042
- --8210070051 Responds to 820Bi3 ltr re third party review Forwards ltr responding to util selection of CF Braun & program for review of HVAC sys W/o stabed encl NOVAK.T M Assistant Director for Licensing 82/09/10 HOWARD, A T Affiliation Unknown ip 1844 229 24X Fiche 50-370, 82/09/10.8210070042
- --BR10070055 Responds to B20B24 ltr re third party review Forwards ltr responding to util selection of CF Braun & program for review of HVAC sys H/o stated encl NDVAK.T M Assistant Director for Licensing 82/09/10 000DIE.U S Iillnois, Btate of 1p 15646 230 24X Fichs 50-373,82/09/10.8210070042
- --8210070041 Responds to 820824 1tr re third party review Forwards 1tr responding to util selection of CF Braun & program for review of HVAC sqs W/o stated encl NOVAK, T M Assistant Director for Licensing 82/09/10 ROREM B L Affiliation Unknown to 15646 231 24X Fiche 50-373,82/09/10,8210070042
- --B210070066 Responds to B20824 ltr re third party review Forwards ltr responding to util selection of CF Braun & program for review of HVAC sgs Revisions also encl NOVAK.T H Assistant Director for Licensing 62/09/10 0000L.E H Citizens Against Nuclear Power 1p 15646 232 24X Fiche 50-373.82/09/10.8210070042

P Operating license stage documents & correspondence

- B208040341 Forwards INEL draft technical evaluation rept based on util response to 801222 generic ltr. "Control of Heavy Loads "Conference call to resolve open Items planned in approx 4 wis W/o encl SCHMERGER.A Licensing Branch 2 82/07/02 DELOEORGE.L O Commonwealth Edison Co 2pp 14978 002 24X Fiche 50-373,82/07/02,8208040341
- 8210010015 Discusses util 820824 & 27 technical proposals for independent HVAC sys review required by License Condition 2 C (33)(b) Selection of CF Braun as reviewer acceptable Listed comments on program should be considered MDVAK.T H Assistant Director for Licensing 82/09/08 REED.C Commonwealth Edison Co 4pp 15577 242 24X Fiche 50-373,82/09/08,8210010015
- B210040221 Forwards Revision 10 to "Mark II Design Assessment Rept" containing Confirmatory assessment of containment design adequacy for pool dynamic loads developed in conjunction w/long-term program described in NUREO-0808 SCHROEDER.C W Commonwealth Edison Co 82/09/24 SCHWENCER.A Licensing Branch 2 2pp 15587 179 24% Fiche 50-373,82/09/24,8210040221
- --8210040223 "Mark | 1 Design Assessment Rept." Revision 10
 * Commonwealth Edison Co 82/09/20 82pp 15587 181 24X
 Fiche 50-373, 82/09/24, 8210040221
- 8210050097 Forwards evaluation of draft BMR owners group rept re alternative design mods of automatic depressurization sys (ADS) logic Incorporation of manual ADS inhibit switch w/timer recommended
 SCHROEDER: C W Commonwealth Edison Co 82/09/30 SCHWENCER: A Licensing Branch 2 30pp 15604 353 24X Fiche 50-373,82/09/30,82/095097
- 8210130241 Responds to NRC 920706 request for add1 info re high energy line breaks on postulated nonsafety power buses, nonsafety control sys or nonsafety sensors, including instrument line failures
 SCHROEDER.C W Commonwealth Edison Co 82/10/04 SCHHENCER.A
 Licensing Branch 2 11pp 15674 151 24X Fiche 50-373, 82/10/04, 8210130241
- 8210130233 Informs that EMD Mi 9644 mod re diesel generator prelube oil pump mod is superior to NRC proposed fix & meets functional requirements of License Condition 2 C 21 b Prelube would degrade reliability of diesel generators SCHROEDER.C W Commonwealth Edison Co 82/10/06 SCHWENCER.A Licensing Branch 2 6pp 15675 220 24X Fiche 50-373,82/10/06,8210130233
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Hanual" GOLDEN, J C Commonwealth Edison Co 82/10/06 CASE, E C Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000, 82/10/06, 8210260526
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual"

 * Commonwealth Edison Co 82/09/30 83pp 15805 139 24X Fiche 30-000, 82/10/06, 8210260526
- 8210260151 Forwards supplemental response to EG&O draft technical evaluation rept of util 820622 ltr re NUREO-0612, "Control ef Heavy Loads at Nuclear Power Plants"
 SWARTZ-E D Commonwealth Edison Co 82/10/19 EISENHUT, D O Division of Licensing 17pp 13803 300 24X Fiche 30-373,82/10/19,8210260151
- O Inspection reports, IE Bulletins & correspondence
- 8210060379 Forwards 1E Insp Rept 50-373/82-19 on 820317-19,24-26 & O408 No mancompliance noted LITILE, W.B. Division of Engineering & Technical Programs 82/09/21 REED, C. Commonwealth Edison Co. 2pp 15618 330 24X Fiche 50-373,82/09/21,8210060379
- --8210060384 IE Insp Rept 50-373/82-17 on 820317-19,24-26 to 0408 No noncompliance noted Major areas inspected licensee action on previous insp findings re fire protection program HENDEZ.R. OROBE.J. HILLIAMS.C.C. Division of Engineering to Technical Programs 82/07/14 13pp 15618 332 24X Fiche.50-373,82/09/21.8210060379
- 8210190589 Forwards IE High Meeting Repts 50-373/82-44 & 50-374/82-12 on 820830 & 0913 No noncompliance noted LITTLE, H 8 Division of Engineering & Technical Programs 82/09/29 REED, C Commonwealth Edison Co 2pp 15739 287 24X Fiche 50-373, 82/09/29, 8210190589

- --821019060! IE Mgt Meeting Repts 50-373/82-44 % 50-374/82-12 on 620830 & 0913 No noncompliance noted Major areas discussed voids found in wall at 710 5-ft elevation on Column Line 16 JACKIN.: N . LIPINSKI.R Division of Engineering & Technical Programs 82/09/20 16pp 15739 289 24X Fiche 50-373 B2/09/29, 8210190589
- 8210050052 Ack receipt of 820723 ltr informing NRC of steps taken to correct violations noted in [E Safeguards Insp Rept 50-073/82-39 M(LLER. J.R. Division of Engineering & Technical Programs 82/09/30 REDIC Commonwealth Edison Co. 2pp 15605 188 24X Fiche 50-373.82/09/30.8210050052
- --8210050056 Forwards response to NRC 820824 ltr re violations noted in IE Safeguards Insp Rept 50-373/82-39 Response withheld (ref 10CFR73 21)
 DELOEDREL D Commonwealth Edison Co 82/09/23 KEPPLER. J C Region 3. Office of Director 2pp 15405 190 24X
 Fiche 50-373,82/09/30,8210050052
- 8210060266 Ack receipt of 820916 ltm informing NRC of steps taken to correct noncompliance noted in 1E Insp Rept 50-373/02-37 SPESSARD.R L Division of Project & Resident Programs 82/10/04 REED.C Commonwealth Edison Co 1p 15621 079 24X Fishe 50-373.82/10/04.8210060266
- --B21006026B Responds to NRC B20B17 itr re-noncompliance noted in II Insp Rept 50-373/82-37 Corrective actions training conducted on B20709 w/entire instrument maint shop, covering LAP 300-9 & LIP 0M-02 which was documented for training records DELOEOROE, L O Commonwealth Edison Co 02/07/16 KEPPLER, J O Region 3, Office of Director 3pp 15421-080 24x Fiche 50-373,82/10/04.8210060266
- --8210190694 IE Insp Rept 50-373/82-42 on 820806-0901 No noncompliance noted Major areas inspected startup testing review of startup test results complete review of safety relief valve U special startup test procedure MAURA,F. ROBINSON.D. JACKIH.I Division of Engineering & Technical Programs 82/09/29 4pp 15738 148 24X Fiche 50-373,82/10/04.8210190682
- 6208190233 IE Info Notice 80 35, Suppl 1: "Leaking & Distanged I-125 Implant Seeds " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Enfequence 82/10/06 Consolidated Edison Co of New York 66pp 15761 290 24% Fiche 50-000.62/10/06.6208170233
- 8210290105 Forwards 1E Insp Repts 50-373/82-41 & 50-374/82-09 on 820802-31 & notice of violation STREETER, J F Division of Project & Resident Programs D2/10/07 REED, C Commonwealth Edison Co 2pp 15787 152 24X Fiche 50-373,82/10/07.8210250105
- --9210250109 Notice of violation from insp on 820802-31 STREETER J F Division of Project & Resident Programs 82/10/07 Sp 15787 154 24% Fiche 50-373.82/10/07.82/10/250105
- --8210250116 IE Insp Repts 50-373/82-41 & 50-374/82-09 on 820802-31 Noncompliance noted unsupervised trainme performed reactivity manipulations GULDEMOND. W 9 . WRIGHT. 0 . MADISON. A Division of Project & Resident Programs 82/10/04 7pp 15787-155 24X Fiche 50-373, 82/10/07. 8210250105
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall. Large-Diameter: Stainless Steel, Recirculation Sys Piping at DNR Plants " Svc list enci DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190228
- 8210280122 Ack receipt of 820920 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/82-30 Corrective actions acceptable SPE88ARD, R L Division of Project & Resident Programs 82/10/22 REED, C Commonwealth Edison Co. 2pp 15837 108 24x Fiche 50-373,82/10/22,8210280122
- --8210280125 Forwards response to NRC 820817 ltr re violations noted in 1E Insp Rept 50-373/82-30 Corrective actions onsite review conducted on 820324 to determine abnormal trend in LERs associated w/personnel errors # lifted leads relanded DELOEDROEL O Commonwealth Edison Co 82/07/20 KEPPLER, J Q Region 3, Office of Director 7pp 15837 110 24X Fiche 50-373,82/10/22,8210280122

- R Periodic operating reports & related correspondence
- 8210130200 Forwards monthly operating rept for Sept 1982 LIEDERICH G J Commonwealth Edison Co 82/10/07 Mahagement Information Branch 1p 15675 243 24X Fiche 50-373,82/10/07. 8210130200
- --8210130215 Monthly operating rept for Sept 1982 ULLRICH J Commonwealth Edison Co 82/10/07 14pp 15675 244 24X Fiche 50-373,82,10/07,8210130200
- S Reportable occurrences LERs & related correspondence
- G_10040131 Forwards LER 82-098/03L-0 DIEDERICH: 0 J Cummonwealth Edison Co 82/09/15 KEPPLER, J 0 Reginn 3, Office of Director 1p 15581 215 24X Fiche 50 373 82/09/15.8210040131
- 0210040134 LER 82-098/03L-0 on 82082A.discovered that rigid restraint installed on line 1816/88-1/2 inch in place of snubber Caused by mechanical contractor design & installation error Snubber installed & evaluation completed SPENCER.D Commonwealth Edison Co 82/09/15 Region 3. Office or Director 2pp 15581 216 24% Fiche 50-373,82/09/15, 82/034131
- #21(060251 Forwards LER #2 097/03L-0 DIEDERIUM, G J Commonwealth Edison Co #2/09/20 KEPPLER, J @ Region J Office of Director 1p | 15621 201 | 24X Fiche 50 373.#2:09/20.#210060251
- -BZ10040252 LER 82-099/03L-0 on 820830 svc water liquid process radiation monitor dribted high 3 declared inoperative Caused by electronic failure of gamma detector Work request initiated to correct problem LUETT.II Commonwealth Edison Co 82/09/20 Region 3, Office of Director 2pp 15821 202 24% Fiche 50-373, 82/09/20, 8210060251
- 8210190462 Forwards NPDES noncompliance repts FIEDERICH.G J. Commonwealth Edison Co. 82/09/29 KEPPLER, J.G. Hegion 3, Office of Director 2pp. 15951-141 24X Fichs 50-373-82/09/29, 8210190462
- 9210190468 NPDFS noncompliance notification on 920801.total suspended solids & tron in outfell 001c low yol waste radwaste discharge tanks exceeded allowable limits Caused by mechanical problems w/radwaste evaporators a Commonwealth Edison Co 82/09/29 ip 15951 143 24X fiche 50-7373.82/07/27,8210190462
- -8210190481 NPDES noncompliance notification on 820910.oii & grease in outfall OOIc low you waste raduate discharge tanks exceeded allowable limit Caused by mechanical failure of radwaste graporator resulting in poor quality water s Commonwealth Edison Co 82/09/29 Ip 15740 IBO 24X fiche 50 373,82/09/29.8210190462
- 821019048/ Forwards NPDES noncompliance repts DIEDERICH, G J Commonwealth Edison CD 82/07/29 KEPPLER, J G Region J, Office of Director 2pp 15738 325 24X Fiche 30 373,82/09/29,8210190487
- -8210190494 NPDES noncompliance notification on 820903, total iron in outfall 1001c low vol waste regeneration wastes solution discharge tank excepted allowable limit Caused by temporary hydrogen peroxide sys not operating properly Commonwealth Edison Co. 8209/29 lp 15735 327 24X Fiche 50-373,82/09/29.8210190487
- 6210170498 Forwards NPDES noncompliance repts
 DIEDERICH G J Commonwealth Edison Co 82/09/29 KEPPLER, J 0
 Region 3, Office of Director 2pp 15705 340 24X
 Fiche 50-373.82/09/29,8210170498
- --8210170503 NPDES noncompliance notification on 820913.pH at outfall Ofic low vol waste wastewater treatment facility fell out of specs Caused by acid waste generated from Unit 2 const activities Work request initiated to install pH monitor commonwealth Edison Co 82/09/29 lp 15735 343 24X Fiche 50-373.82/07/29.8210170498
- 8210190509 Forwards NPDES noncompliance repts
 DIEDERICH, 0 J Commonwealth Edison Co 82/09/29 KEPPLER, J 9
 Region 3, Office of Director 2pp 15740 199 24X
 Fiche 50-373, 82/09/29, 8210190509

- --8210190514 NPDES noncompliance notification on 820914, total suspended solids & from at outfall Odic low vol waste wastewater treatment facility exceeded allowable limits Caused by upset pH due to Unit 2 const activities

 ** Commonwealth Edison Co. 82/09/29 ip 15740 202 24X Fiche 50-373, 82/09/29, 8210190509
- 8210190522 Forwards NPDES noncompliance repts
 DIEDERICK: 0 J Commonwealth Edison Co 82/09/29 KEPPLER, J G
 Region 3: Office of Director 2pp 15751 319 24X
 Fiche 50-373, 82/09/29, 8210190522
- --0210190525 NPDES noncompliance notification on 020909, total iron at outfall Olic low vol waste wastewater treatment facility exceeded allowable limit Caused by upset ph due to Unit 2 const activities Work request initiated to install monitor 4 Commonwealth Edison Co 08209729 1p 15751 321 24X Fiche 50-373, 82709729, 8210190522
- 8210200002 Forwards NPDES noncompliance repts for facility DIEDERICH, G. J. Commonwealth Edison Co. 82/09/29 KEPPLER, J. G. Region 3. Office of Director 2pp. 15756-327 24X Fiche 50-373, 82/09/29, 8210200002
- --8210200007 NPDEB noncompliance notification on 820914, buildup of resin fines & other fine solids carried through strainers & sumps into discharge tank Cause hot stated Regenerative waste solution discharge tank will be cleaned a Commonwealth Edison Co 82/09/29 ip 15756-330 24X Fiche 50-373,82/09/29,8210200002
- 82:0130234 Forwards LER 82-107/03L-0 DIEDERICH O J Commonwealth Edison Co 82/09/30 KEPPLER, J G Region 3, Office of Director 1p 15675 216 24X Fiche 50-373, 82/09/30, 8210130234
- --B210130236 LER 82-107/03L-O on 820812.control rad drive pump A tripped off on low suction pressure & control rad drive pump B failed to start Caused by low CY storage tank level & valve 100109 condensate/CRD reject being abnormally closed UNITERHOFF, D Commonwealth Edison Co 82/09/30 Region 3, Office of Director 3pp 15675 217 24X Fiche 50-373.82/09/30, 93/0130234
- 82:0190344 Forwards LER 92-103/03L-0 DIEDERICH.O J Commonwealth Edison Co 82/10/04 KEPPLER.J Q Region 3. Office of Director ip 15737 245 24X Fiche 50-373,82/10/04,8210190344
- --B210190346 LER B2-103/03L-0 on B20919.Hi Rad alarm sounded Operator checked chart recorder & noticed A RHR svc water radiation monitor read downscale Alarm caused by trip in power supply to monitor Power supply recet KAY.D L Commonwealth Edison Co B2/10/04 Region J, Office of Director 2pp 15737 246 24X Fiche 50-373,82/10/04.8210190344
- 8210190050 Forwards LER 82-104/03L-0
 DIEDERICH/O J Commonwealth Edison Co 82/10/05 KEPPLER. J Q
 Region 3. Office of Director 1p 15742 136 24X
 Fiche 50-373.82/10/05.8210190050.

- 8210190606 Revised Final Deficiency Rept B2-10 re RCIC underground piping Replacement piping work complete except for tie to Unit 1 RCIC sys inside bldg which requires 4-day outage Work will be completed during first available outage SCHROEDER, C W Commonwealth Edison Co 82/10/08 KEPPLER, J 0 Region 3, Office of Director 1p 15739 353 24X Fiche 50-373,82/10/08.8210190606
- 8210250152 Forwards LER 92-102/03L-0 DIEDERICH G J Commonwealth Edison Co 82/10/15 KEPPLER J G Region 3. Office of Director 1p 15789 311 24X Fichs 50-373 82/10/15 8210250152
- -8210250163 LER 92-102/031-0 on 820916, reactor vessel low water level scram setpoint DPIS-1B21-NO248 found out of calibr Caused by instrument drift Required tolerance under revision Instrument to be calibr weekly WINTERHOFF, D. Commonwealth Edison Co. 82/10/15 Region 3, Defice of Director 2pp 15789 312 24X Fiche 50-373, 92/10/15, 8210-30152
- 8210260210 Forwards LER 82-110/03L-0 DIEDERICH.O J Commonwealth Edison Co 82/10/18 KEPPLER.J 0 Region 3. Office of Director 1P 15804 266 24X Fiche 50-373.82/10/18.8210260210
- --8210260221 LER B2-110/O3L-O on 620920 standby liquid control tank level measured low Caused by evaporation Trending of evaporation rate initiated under AIR 1-82-513 Tank level raised * Commonwealth Edison Co 62/10/19 Region 3, Office of Director 2pp 15804 267 24X Fichs 50-373,82/10/18,8210260210
- 8210260227 Forward's LER 82-111/03L-0 DIEDERICH.O J Commonwealth Edison Co 82/10/18 KEPPLER.J Q Region 3. Office of Director lp 15804 259 24X Fiche 50-373.82/10/18.8210260227
- --B21026023B LER B2-111/03L-0 on B20927, high airborne activity discovered in raduaste reboiler room Caused by insufficient weld penetration of tee between valves IB21-F538 & IB21-F532 Tee cut out & replaced Reboiler returned to svc + Commonwealth Edison Co B2/10/18 Region 3, Office of Director 2pp 15804 260 24% Fiche 50-373, B2/10/16, B210260227
- 8210260311 Forwards LER 82-108/03L-0 DIEDERICH,O J Commonwealth Edison Co 82/10/18 KEPPLER,J G Region 3. Office of Director 1p 15799 355 24X Fichs 50-373, 82/10/16,8210260311
- --9210260313 LER 92-109/03L-0 on B20920.LIS-NB-187.ADS accumulator backup N2 channel functional & calibr discovered not performed as specified by Tech Spec Caused by surveillance procedure not entered into program Procedure revised WINTERMOFF.D Commonwealth Edison Co B2/10/18 Region 3. Office of Director 2pp 15799 356 24X Fiche 50-373.B8/10/18. B210240311
- 8210260115 Forwards LER 82-114/01T-0 DIEDERICH G J Commonwealth Edison Go 82/10/19 KEPPLER.J G Region 3. Office of Director 1p 15799 109 24X Fiche 50-373.82/10/19.8210260115
- --B210260118 LER 92-114/01T-0 on 821005, installed configuration of HVAC duct hanger 1382 did not match design Drawing M-1538 Caused by misinterpretation of FCR by draftsman Sargent & Lundy Drawing H-1538 will be revised prior to 821008 OIESEKER, J Commonwealth Edison Co 82/10/19 Region 3, Office of Director 2pp 15797 110 24% Fiche 50-373,82/10/19, 8910260115

- --821026032: LER 82-106/03L-0 on 820920, during performance of LOS-PC-QI, valve 1833-F019 did not close Caused by foreign mat1 blocking valve open Outboard isolation valve 1833-F020 closed Blockage removed prior to work initiation HEFALA, J Commonwealth Edison Co 62/10/19 Region 3. Office of Director 2pp 15797 336 24X Fiche 50-373.82/10/19, 2010/2017
- T Hearing transcripts on non-antitiust matters
- B21021050B Forwards Commission determination statement releasing B20822 transcript of discussion of full power QL Pp 1-66 CMILK, S. Office of the Secretary of the Commission B2/10/0°; Public Document Branch 2pp 15784 204 24% Fiche 50-373.82/10/05, B210210505B
- --8210210512 Transcript of 820622 closed meeting in Washington, DC rediscussion of full gover OL Pp 1-66

 Commissioners 82/06/22 70pp 15/84 206 24x

 Fiche 50-373,82/10/05.8210210508
- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J H Division of Rules and Records B2/06/28 UDELL.R A Critical Mass Energy Project 15pp 19727 005 24X Fiche 50-000. B2/06/28.821001000B
- --8008050265 Discusses add1 required info to better define potential for cracking in reactor vessel noirles NODNAN,V S Assistant Director for Materials & Qualifications Engineering 80/05/05 TEDESCO.R L Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000.82/04/28.8210018008
- 8208040341 Forwards INEL draft technical evaluation root based on util response to 801282 generic ltr. "Control of Heavy Loads "Conference call to resolve open items planned in approx 4 wks W/o encl SCHWENCER.A Licensing Branch 2 82/07/02 DELGEORGE,L C Commonwealth Edison Co 2pp 14978 002 24X Fiche 50-373,82/07/02,8208040341
- E210040221 Forwards Revision 10 to "Mark 11 Design Assessment Rept" containing confirmatory assessment of containment design adequacy for pool dynamic loads developed in conjunction w/ long-term program described in NURCO-0808 SCHREEDER.C W Commonwealth Edison Co 82/09/24 SCHWENCER.A Licensing Branch 2 2pp 15587 179 24X Fiche 50-373,82/09/24.8210040221
- --8210040223 "Mark II Design Assessment Rept." Revision 10 * Commonwealth Edison Co 82/09/30 82pp 15587 181 247 Fiche 50-373,82/09/24,8210040221
- 9210050097 Forwards evaluation of draft BiRT owners group rept re alternetive design mods of automatic depressurization sys (ABB) logic incorporation of manual ABS inhibit switch w/timer recommended SCHRCEDER, C W Commonwealth Edison Co B2/09/30 SCHWENCER, A Licensing Branch 2 30pp 15604 353 24X Fiche 50-373,82/09/30,8210050097
- B210130241 Responds to NRC 820706 request for add1 info re high onergy line breaks on postulated nonsafety power buses, nonsafety control sys or nonsafety sensors.including instrument line failures SCHRDEDER.C W Commonwealth Edison Co 82/10/04 SCHMENCER.A Licensing Branch 2 lipp 15674 151 24X Fiche 90-373,82/10/04, B210130241
- 8210130233 informs that EMD MI 9644 mod re diesel generator prelube oil pump mod is superior to NRC proposed fix k meets functional requirements of License Condition 2 C 21 b Prelube would degrade reliability of diesel generators SCHROEDER; C W Commonwealth Edison Co 82/10/06 SCHHENCER. A Licensing Branch 2 6pp 15675 220 24X Fichg 50-373,82/10/06.8210130233
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" GULDEN.J C Commonwealth Edison Cp 82/10/06 CASE.E 0 Office of Nuclear Reactor Regulation, Director 2pp 15805:137 24X Fiche 50-000.82/10/06

- B210260542 Revision 3 of Chapter 9 of 'Offsite Dose Calculation Manual" * Commonwealth Edison Co 82/09/30 83pp 15805 139 24X Fiche 50-000 82/10/06.8210260526
- 6210240151 Forwards supplemental response to EG&O draft technical evaluation rept of util 820622 ltr re NUREG-0612. "Control or Heavy Loads at Nuclear Power Plants"

 SMARTZ.E D. Commonwealth Edison Co. 82/10/19 EISENHUT.D 0
 Division of Licensing 17pp 15803 300 24x Fiche 50-373,82/10/19,6210220151

F. Security medical emergency & fire protection plans

- 6.0%, 90125 Releases public version of revised generating station emergency plan corporate command ctr emergency plan implementing procedure FELTON J M Division of Rules and Records 82/09/16 Document Hanagement Branch ip 19564 122 24% Fiche 90-000, 82/09/16, app. 3-90125
 - 8209293189 Forwards public "ersion of Revision 4 to generating station emergency plan comporate command of Emergency Plan Employmenting Procedure FDF-3 "Environ/Emergency Coordinator " Receipt form encl PAJEST JE Commonwealth Edison to 82/09/01 DENTON, H.R. NRC No Detailed Affiliation Given to 15564-129 24X Fiche 50-000 86/09 to 82/09/0125
 - 8209270-25 Public version of Revision 4 to generating station emergency plan corporate command Ctr Emergency Plan Implementing Procedure Edf 3. "Envision/Emergency Coordinator"

 PAJUNSKI J E (communestin Edison Co. 82/08/31 | lipp 15554 12: 24/Fiche 50-000, 02/09/16, 8209290125
- 6.10120376 Advises that installation of offsite dose calculation sysprogram fully operational tracking model & operational A model will be delayed until 821231 to complete prime computer installation SWARTZ E.D. Commonwealth Edison Co. 82/10/06 DENION, R. Offsce w. Nuclear Reactor Regulation. Director 2pp 15682 098 247 inche 50 000 82/10/06.8/10130876
- LUIG-90-947 Releases public version of revisions to Quad Cities. Zion & Urgsden emergency plan americs & revised generating station emergency plan telephone directory FLTON / H Division or Rules and Records 82/10/00 Document Management Branch 1p 1597/313 24% Fiche 50-000.82/10/00.02/10290047
 - MAIO270060 Forwards public version of Revision 3 to Quad Cities & Zion emergency plan annexes Revision 2 to Dresden emergency plan annexes Revision 2 to Dresden emergency plan annex & revised generating station emergency plan telephone directory MUGRE R D. Commonwealth Coison Co. 82/07/30 DENTON, H R. NRC No Detailed Affiliation Given 5pp. 15877-314 24X Fiche 50 000 82/10/08 9/10290047
 - 82]0290088 Public version of revised generating station emergency plan telephone dijectory GALLE D.P. Commonwealth Edison Co. 62/08/12 43pp. 15878 RIB 24X Fiche 50-000.02/10/08.02]0290047
- 0210220358 Provides info re organization to performance of depts responsible for radiation protection activities, per 820702 consistent Training coordinator assigned in Apr 1982 to improve health physics training programs TRAMILTR Commonwealth Edison Co. 82/10/14 DENTON, H.R. Office or Nuclear Reactor Regulation, Director 9ep 15776-287 24X Fishe 50-000, 82/10/14, 8210220358

G Adjudicatory correspondence

- @2(0040366 Responds to appeal re denial of FDIA request for four affidavits concerning allegations of improper const practices at facility forwards requested info Page 4 of E Oreve affidavit withheld (ref FOIA Elemption 7) DIRCKE. W J Office of the Elecutive Director for Operations 82/08/24 STEPTOE. P P Isham. Lincoln & Beale 2pp 15597 302 24c Fiche 50-374.82/08/24 6210040366
- --8210040375 Forwards four affidavits re safety problems at facility Proprietary info deleted from two affidavits DEVINE, T Institute for Policy Studies 82/03/11 FORTUNA, R Director's Office Office of Inspection and Enforcement ip 15597 315 24X Fiche 50-374, 82/08/24, 8210040366

- --8207140491 Afridavit re results of sloppy concrete pours, holes & honeycombs in concrete Accumulated debris not dispased of prior to pour & tos much concrete poured at one time Worker health not main concern of supervisors
 SMARTZ.D W Affiliation Unknown 82/06/24 10pp 15597 316 24% Fiche 50-374,82/08/24,8210040366
- --8207140494 Affidavit re safety-related const flaws in installation of pipes & supports flipes & hanger supports not placed as specified GREVE.E Affiliation Unknown 92/04/22 6pp 15597 326 24X Fiche 50-374,82/08/24.8210040366
- --8207149497 Affidavit re damage to fire protection equipment such as sprinklers throughout plant during const Concerns raised over core drillings of concrete reinforcement bars in containment walls & pedestal Hungers not as specified # Affiliation Unknown 82/04/21 6pp 19597 332 24% Fiche 50-374,8210040346
- --8207140500 Affidavit re sloppy workmanship leading to const damage Const crews open drilled through reinforcement bars, containment until it reactor vessel pedestal around 694 foot elevation of Unit 1

 # Arfiliation Unknown 82/04/21 3pp 15597 338 24X
 Fiche 50-374,82/08/24,8210040366
- 8210260501 Advises of State of IL intent to file comments on concrete element design margin summary Comments will be incorporated into 10CFR2 206 show cause request GOODIC, J S 111:nois State of 62/10/15 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 15806 209 24X Fiche 50-374:082/10/15.8210260501

@ Inspection reports. IE Bulletins & correspondence

- E210190589 Forwards 1E Mgt Meeting Repts 50-373/82-44 & 50-374/82-12 pm 820830 & 0913 No noncompliance noted LITEL, N S Division of Engineering & Technical Programs 82/09/29 REED. C Commonwealth Edison Co 2pp 15739 287 24X Fiche 50-373, 82/09/29, 8210190589
- 8210170601 [E Mgt Heuting Repts 50-373/82-44 & 50-374/82-12 on 820830 & 0913 No noncompliance noted Major areas discussed voids found in wall at 710 5-ft ejevation on Column Line 16 JACKIW: I N . LJPINSKI.R Division of Engineering & Technical Programs 82/09/20 16pp 15739 289 24X Fiche 50-373.82/09/29.8210190589
- 6208190233 IE 1nfo Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl CODD, L 1 Division of Fuel Facilities, Materials & Safaguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000.82/10/06.8208190233
- 8210250105 Forwards 1E Insp Repts 50-373/82-41 & 50-3/4/82-09 on 820802-31 & notice of violation STREETER, J F Division of Project & Resident Programs 82/10/07 REED. C Commonwealth Edison Co. 2pp 15787 152 24X Fiche 50-373, 82/10/07, 8210250105
- --8210250109 Natice of violation from insp on 820802-31 BTREETER, J. F. Division of Project & Resident Programs 82/10/07 1p 18787 154 24% Fiche 50-373,82/10/07,8210250105
- --8210250116 IE Insp Repts 50-373/82-41 & 50-374/82-09 on 820802-31 Noncompliance noted unsupervised trainer performed reactivity manipulations GULDEMDND, N O, HRIGHT, O, MADISON, A Division of Project & Resident Programs 82/10/04 9pp 15787 155 24X Fiche 50-373,82/10/07.8210250105
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter: Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYQUNO.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238

8 Reportable occurrences, LERs & related correspondence

82j0190505 Revised Final Deficiency Rept 82-10 re RCIC underground piping Replacement piping work complete except for tie to Unit 1 RCIC sys Inside bldg which requires 5-day outage Hork will be completed during first available outage SCHROEDER, C W Commonwealth Edison Co 82/10/09 KEPPLER, J G Region 3, Office of Director 1p 15739 353 24X Fiche 50-373, 82/10/08, 8210190606

- DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8209220135 Forwards pump & valve inservice test plan for approval Requests relief from ASME Code Section XI per (OCFR50 55a MAUXIN.L V Louisiana Power & Light Co 82/09/13 NOVAK.T H Assistant Director for Licensing 4pp 14938 001 24X Fiche 50-382.82/09/13,8209220135
- 6210180255 Forwards description of open items found as result of review of 820825 submittal re-purge valve operability Schedule for response requested PERRIGAN, J.D. Licensing Branch 3 82/09/23 MAURIN, L.V. Louisiand Power & Light Co. 4pp. 15746-239 24X Fiche 50-382,82/09/23,8210180255
- 8210040ii0 Requests test exception to delete stuck contro) rod physics test Test has potential for placing reattor in unsafe configuration MARIN.L V Louisiana Fower & Light Co 82/09/27 NOVAK,T M Assistant Director for Licensing 3pp 15580 347 24X Fiche 50-382,82/09/27,8210040110
- 8210040191 Summarizes 820903 site meeting re pending revision to FSAR. Chapter 14 HAURINLL V Louisiana Power & Light Co 82/09/27 NOVAK.T M Assistant Director for Licensing 2pp 15583 187 24X Fiche 50-382.82/09/27.8210040191
- 8210260532 Notifies of acceptance of Revision A of Torrey Pines Technology dA program plan EISENHUT.D O Division of Licensing 82/09/28 MCLENDON,O D Louisiana Power & Light Co 2pp 15830 191 24X Fiche 50-382.82(09/28.8210260532
- 8210210317 Forwards portions of Franklin Research Ctr technical evaluation rept "Control of Heavy Loads" re ANSI 6td N14 4-1978 to assist in preparing response on special lifting devices, per 820921 conference call commitment KERRIGAN. J D Licensing Branch 3 82/09/29 MAURIN. L V Louisiana Pouer & Light Co. Spp. 15782 082 24X Fiche 50-382.82/09/29, 8210210317
- 8210260285 Notification of 821003-05 meeting w/util in Taft,LA to audit facility training program
 BLACK-5 Licensing Branch 3 82/09/29 KERRICAN.J Licensing Branch 3 3pp 15830-153 24% Fiche 50-382,82/09/29,8210260285
- 8210150347 Forwards Revision B to "Independent Design Review of Waterford Steam Electric Station Unit 3 Emergency Feedwater Sys." Program plan MCLENDOI, 0 D Louisiana Power & Light Co 82/10/04 NOVAK, T M Assistant Director for Licensing 2pp 15704 282 24X Fiche 50-382, 82/10/04, 8210150347
- --82101503\$3 Revision B to "Independent Design Review of Waterford Steam Electric Station Unit 3 Emergency Feedwater Bys." program plan * Torrey Pines Technology 82/09/13 18pp 15704 284 24X Fiche 50-382,82/10/04.8210150347
- 9210250355 Forwards response to 820513 Human Factors Engineering audit of facility control room Revised rept will be issued 821104 Util purchasing full scope control room simulator to study recommended changes MAURIBLE V Louisiana Power & Light Co 82/10/20 NQVAK.T M Assistant Director for Licensing 9pp 15790 036 24X Fiche 50-362,82/10/20,8210250355
- F Security, medical, emergency & fire protection plans
- 821004016B Forwards suggested dates & schedule for conducting ambrgency preparedness drills exercise for score & appraisal for facility HAURIN-L V Louisiana Power & Light Co 82/09/24 NOVAK, Y M Division of Licensing 2pp 15582 315 24X Fiche 50-382,82/09/24,821004016B
- B210010370 Forwards summary of five qualification tests, ANI acceptance itrs & excepts from five qualification test rapts Repts include "Fire Qualification Test on Silicone Foam Floor Pametration Seals"

 HAURINL V Louisiana Power & Light Co B2/09/28 NOVAK, T M Assistant Director for Licensing 161pp 15569 001 24X

 Fiche 50-382, 82/09/28, 8210010370

- 82(0260362 Forwards revised test of racility info safety brochure Revision improves readability & reflects comments received from NRC & FEMA Test will be incorporated into printer proof by 821(12) per ASLB requirement Comments requested by 821(02) MAURIN.L V. Louisiana Power & Light Co. 82/10/22 NOVAK, T. M. Division of Licensing. 20pp. 15803-158-24X Fiche 90-382/82/10/22, 82/10/260362
- G Adjudicatory correspondence
- 8210010435 Certifies svc on 820924 of applicant response to comments of parties on emergency public info blockure Svc list encl RIDGHAY,D A Lauisiana Power & Light Co 82/09/27 2pp 15570 203 24% Fiche 50-382.82/09/27,8210010435
- 62(0040059 Memorializes 820928 telcon between ASIB, NRC & Joint Intervenors deferring 620929 telcon to set hearing date until Joint Intervenors pleadings on emergency into brochure riled

 TURK, S.E. Hearing Branch 1 82/09/29 HOLFF, S.J., JORDAN, W.H., FOREMAN, H. Atomic Safety and Licensing Bound Panel 2pp
 15581-252 24% Fiche 50-302.82/09/29,8210040059
- B210050366 Motion to diamies license application for failure to comply w/discovery Intervenors unable to prepare adequately for defense of interests against impact of facility on lives & livelihoods GROESCH.O L. Joint Intervenors-Waterford 82/09/29 Atomic Safety and Licensing Board Panel. 2pp. 15607-013 24x Fiche 50-382, 02/09/29, 0210050366
- -8210050372 Request for production & copy of certain documents
 Documents should be delivered within 15 days in order to
 avoid prejudicing intervenors in subsequent proceedings
 GROESCHIO L. Joint Intervenors Naterford 82/07/29 touisiana
 Power & Light Co. 2pp. 15609-015 C4X Fiche 50-382-82/09/29.
- -8210050378 Motion to disallow introduction of second evacuation brochere, grant judgment on first brochure & allow new evidence & testimony to be presented on synergism & evacuation contentions Cortificate of Svc encl GROESCH, O. L. Joint Intervenors-Materford B2/07/29 Atomic Safety and Licensing Board Panel App. 15609 01/ 24X Fiche 50-382,82/07/29,8210050366
- 8210040061 Advises that NRC does not oppose Joint Intervenois Lequert for cross-eramination of NRC & FEMA employees of 8709001 afridavits Cross-eramination must relate to scope of drinct testimony which may be introduced by MRC &/or FEMA TURK S E Hearing Oranch 1 82/09/30 WOLFE, 5 / JORDAN, W H , FOREMAN, H Atomic Safety and Itemsing Board Panel 2pp 15381 250 24% Fiche 90-382,82/09/70,8210040061
- 8210040188 Response opposing Joint Intervenors 820729 mution result) emergency info brochure & reopened hearings Ruling on adequacy of util emergency info brochure should be deferred Certificate of Sice encl.

 TURK.S E Hearing Branch 1 82/10/04 Atomic Safety and Licensing Board Panel Sipp 15613-227 24X Fiche 50-362.62/10/0.8210040188
- 5210070124 Response opposing Joint Intervenors B20727 motion to reoper Requests not founded in fact or law & fly in face of any sense of administrative discipling & procedural regularity Some requests defy logic Certificate of Svc encl CNURCHILL, B H Louisiana Power & Light Co CHURCHILL, B H Shaw, Pittman, Potts & Trowbridge B2/10/04 Atomic Safety and Licensing Board Panel 15pp 15627 046 24% fiche 50-382,82/10/04 8210070124
- 8210070197 Hemorializes 821001 telcon w/NRC.util.Joint Intervenors & ASLB NRC & applicant to file responses to Joint Intervenors motions by 821006 Svc list enc!
 RIDOMAY.D A Shau. Pittman. Potts & Troubridge RIDOMAY.D A Louisians Power & Light Co B2/10/04 WOLFELS J Atomic Safety an Licensing Board Panel 5pp 15634 267 24% Fiche 50-382,82/10/04,8210070197
- 8210080070 Objections to Joint Intervenors 820927 request for production of documents 5 opposition to motion to dismiss application for failure to make discovery NRC regulations for discovery not followed H/Certificate of Svc TURK.8 E Hearing Branch 1 82/10/06 Joint Intervenors-Waterford 14pp 15643 016 24X Fiche 50-382,82/10/06 82/1080070
- 8210080086 Erratum to applicant 821004 response to Joint Intervenors motion to reopen record Certificate of Byc encl CHURCHILL, B W Louisiana Power & Light Co CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge 82/10/06 Atomic Safety and Licensing Board Panel 3pp 15640 217 24X Fiche 50-382,82/10/06,8210080086

1

- 8210080070 Response apposing Joint Intervenors 820727 motion to dismiss for failure to make discovery to objections to request for production of documents Discovery requests prohibited by Commission rules ChupChill.B U Louisiana Power & Light Co CHURCHILL.B W Shaw. Pattnan. Poits & Trombridge 62/10/06 Atomic Safety and Licensing Boa-d Panel 13pp 15540 223 24X Fiche 50-382,82/10/06, 8210080076
- 8210210372 Hemorialises 821013 conference call w/Joint Intervenors te procedures for appealing ASLB actions Svc list dnc1 RIDGMAY.D A Shaw. Pittman. Potts & Trombridge RIDGMAY.D A Louisiana Power & Light Co 82/10/18 WOLFE.S J Atomic Safety and Licensing Board Panel 4pp 15764 164 24% Fiche 50-382,82/10/18,0210210372
- 6:10210404 Henorandum & order denying Joint Intervenors 820929 motion to dismiss for failure to make discovery & granting portion of motion requesting production > copying of documents WILFE/S J Atomic Safety and Licensing Board Panel 82/10/18 Joint Intervenors-Waterford 9pp 15765 135 24X Fiche 50-382 82/10/18.8210210404
- 8210210412 Menorandum * order granting portion of util 820723 motion, allowing util initially proposed public info brochure to be withdrawn * reopening record to receive evidence on adequacy of util revised brochure wolff, and Licensing Board Panel 82/10/18 Louisiana Power * Light Co 11pp 15765 088 24x Fiche 50-382,82/10/18.8210210412
- D21021015d Forwards JW Benton 2 AL Lookabough affidavit re emergency into brochure Artidavit identical to 820901 affidavit but includes lookabaugh signature TURK S.E. Hearing Dianch 1 82/10/19 WOLFE, S.J., JORDAN, W.H., FOREMAN, H. Atomic Sarety and Licensing Board Panel 3pp 15764 077 24x Fiche 50-382,82/10/19.8210210152
- -6210210159 Arfidavit of JN Denton 5 AL Lookabaugh re emergency info brockurs Util has revised brockurs incorporating FEMA comments Guidance criteria on ed info on radiation met BENTON J W . LOOKABAUGH A L NRC - No Detailed Affiliation Given BENTOM J W . Edgeral Energency Management Agency 82/09/30 Ypp 15786 080 24% Firks 50-382 82/10/19.8210210152
- 8210210466 Order admitting three exhibits into evidence to be cited in upcoming partial initial decision on Unrosolved Bafety Livies A 45 re shutdown PMR & A-46 re seismic qualitication of equipment WOLFE.5 J Alumic Sofety and Licensing Doard Panel B2/(0/19 Opp. 15/63-047 247 Fiche 50 382 82/10/19,8210210466
- 6.10220477 Advises that time for Commission to act to review ALAB-690 engined Commission declined review Decision became final agency action on 821018 UNILPS J Office of the Secretary of the Commission 82/10/21 Office of the Executive Legal Director Ip 15779 129 24X fische 50-182:82/10/21.8210220473
- 5216250288 Informs of util pending application for SNM license Util requested license be effective as of 830131 until plant OL issued No ASLB action necessary TURK, S.E. Hearing Branch 1 82/10/22 FOREMAN, H., WOLFE, S.J., JORDAN, M. H. Atomic Sefety and Licensing Board Panel 1p 15791 164 24x Fiche 50-382, 82/10/22, 8210250288
- 8210260423 Advises that author 621018 itr memorializing 821013 telcon should have included FEMA representative cassidy as participant Svc list encl RIDOMAY.D A Shaw. Pittman. Potts & Trombridge RIDOMAY.D A Louisiana Power & Light Co 82/10/22 WOLFE.B J Atomic Bafety and Licensing Board Panel 2pp 15806 050 24% Ficha 50-382.82/10/22, 6210260423
- 8210280387 Provides list of correspondence from applicant to NRC & FEMA since record closed on 820512 Some ltrs & svc list encl flated correspondence CHURCHILL, B H Shaw, Pittman. Potts & Trowbridge CHURCHILL, B H Louisiana Power & Light Co 82/10/25 GROEBCH G Affiliation Unknown 8pp 15845 169 24X Fishe 50-382,82/10/25.8210280387

H General correspondence

8210210167 Requests copying syds for end documents Record reppened to admit into evidence BZOBZ7 Itr & appended affidavit.util 820910 response & 820909 attachment W/o end is WOLFE. 8 J Atomic Safety and Licensing Board Panel 82/10/19 Alderson Reporting ip 15766 074 24X Fiche 50-382,82/10/19,8210210167

- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8210270190 Forwards Amend 29 to FSAR.addressing organization & training program
 MAURIN.L V Louisiana Power & Light Co 82/10/20 Office of Nuclear Reactor Regulation. Director 3pp 15827 269 24X
 Fiche 50-382,82/10/20.8210270190
- --8210270193 Amend 29 to FSAR Twenty-five aporture cards available in PDR
 + Louisiana Power & Light Co 82/10/31 308pp 15827 274 24X
 Fiche 50-382,82/10/20.8210270190

M Antitrust correspondence

- 8210270327 Forwards notice of finding of no significant antitrust changes & time for filing request for le-evaluation TOALSTON:A Antitrust & Economic analysis Branch (Utility Finance) 82/10/14 CUMBS:T Docketing & Bervices Branch ip 15836 359 24X Fiche 50-382.82/10/14.8210270327
- --8210270332 Notice of issuance & availability of notice of finding of no significant actitust changes & time for filing request for re-evaluation
 TOALSTON, A Antitrust & Economic analysis Branch (Utility
 Finance) 82/10/12 3pp 15836 360 24X Fiche 50-382/82/10/14.
 8210270327
- O inspection reports, IE Bulletins & correspondence
- 8210120058 Forwards 1E Insp Rept 50-382/82-12 on 820503-07 No noncompliance noted MADSEN,G L Division of Resident. Reactor Project & Engineering Programs 82/09/24 MAURIN,L V Louisiana Power & Light Co 2pp 15653 110 24% Fiche 50-382,82/09/24,8210120058
- --8210120073 IE Insp Rept 50-382/82-12 on 820503-07 No noncompliance noted Major areas inspected chemistry/radiachemistry program including organization, staffing qualifications, training, facilities, equipment & lab instrument calibr NICHOLAS. J B., MURRAY. B. Division of Resident. Reactor Project & Engineering Programs 82/09/01 46pp 15653 112 24x Fiche 50-382,82/09/24,8210120058
- 8210190431 Forwards IE Insp Rept 50-582/82-18 on 820816-20 & notice of violation MADSEN. O L Division of Resident, Reactor Project & Engineering Programs 82/09/30 MAURIN, L V Louisiana Power & Light Co 2p; 15741 154 24X fiche 50-382,82/09/30,8210190431
- --8210190437 Notice of violation from insp on 820816-20 + Division of Resident. Reactor Project & Engineering Programs 82/09/30 ip 15741 156 24X Fiche 50-382,82/09/30.8210190431
- --8210190452 IE Insp Rept 50-382/82-18 on 820816-20 Noncompliance noted failure to fallow procedures/instructions for control of weld insp/documentation of safety-related structural steel platforms

 JOHNSON, C E , ROBERDS, J , CROSSHAN, N A Division of Resident,
 Reactor Project & Engineering Programs 82/09/21 9pp
 15741 157 24% Fiche 50-382, 82/09/30,8210190421
- 8208190233 IE 1nfo Notice 80-35, Suppl 1, "Leaking & Dielodged I-125 Implant Geeds " Svc list encl CDBp.L 1 Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Syx list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York (15pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210040078 Interim Significant Const Deficiency Rept 62 re insp & acceptance of undersized field welds in 1/2-inch stainless steel sampling schedule 160 piping Initially reported on 820820 Mercury Co will build up welds by 821222 MAURINL V Louisiana Power & Light Co 82/09/20 COLLINS, J T Region 4, Office of Director 3pp 15581 267, 24% Fichs 50-382,82/09/20,8210040078.

- 821013D174 Interim deficiency rept re possible failure of GE Type MFA relays Initially reported on 820513 Corrective action not completed Final rept will not be submitted until 830420 MAURIN.L V Louisiana Power & Light Co 82/09/30 COLLINS.J T Region 4. Office of Director ip 15673 045 24X Fiche 50-382.82/09/30, 8210130174
- 6210130245 Second interim dericiency rept re Significant Const
 Deficiency 43 on main/emergency feedwater sys Corrective
 action not completed Final rept will be submitted by
 821222
 MANTIM.L V Louisiana Power & Light Co 82/09/30 COLLINS. J T
 Region 4. Defice of Director 1p 15678 [0] 24X
 Fiche 50-382.82/09/30.8210130245
- 6210130564 Second interim deficiency rept on Significant Const Deficiency 48 re design application of break flanges at elevated temps Corrective action described in 820326 rept not completed Next rept to be submitted by 830117 MAURIN.L V Louisiana Power 2 Light Co 82/09/30 COLLINS, J T Region 4. Office of Director ip 15683 300 24X Fiche 50-382-82/09/30, 8210130564
- 8210130243 Second interim deficiency rept re reactor containment bldg liner plate nuclear coating failure Corrective action not yet completed Final rept to be submitted by 830323 MANRIM.L V Louisiana Power & Light Co 82/10/01 COLLINS, J T Region 4. Defice of Director ip 15678 100 24X Fiche 50-382:82/10/01/8210130243
- 8210130551 Fourth interim Significant Const Deficiency Rept 33 rechilled water pipe supports Corrective action not yet complete Final rept expected by 830311 MAURIN, L. V. Louisiana Power & Light Co. 82/10/01 CGLLINS, J. T. Region 4. Office of Director 1p. 15684-013 24X Fiche 50-382.82/10/01.8210130551
- 8210190542 Interim deficiency rept re Potential Reportable Deficiency 86 on disparity in UHS tornado case test results Initially reported on 820830 Equipment not significantly impacted at 104 F Deficiency not reportable per 10GFR50 55(e) MAURIN-L. V Louisiana Power & Light Co. 82/10/06 MADSEN.0 L. Division of Resident, Reactor Project & Engineering Programs 3pp 15751 330 24% Fiche 50-382,82/10/06.8210190542
- 8210190345 First interim deficiency rept re Significant Const Deficiency 63, "Procurement of Spare/Replacement Parts " Further info detailing investigation & evaluating questionable purchase orders will be provided by 830418 MAURIN. L V Louisiana Power & Light Co 82/10/08 COLLINS, J T Region 4. Office of Director 3pp 13742 095 24X Fiche 50-382,82/10/08,8210190345
- 8210230217 Third interim deficiency rept re inadequate clearance between process piping sys & bor type pipe supports & restraints Nineteen hangers remain to be reworked Final rept will be transmitted by 830708 MAURIN.L V Louisiana Power & Light Co 82/10/15 COLLINS.J 1 Region 4. Office of Director ip 15788 337 24X Fiche 50-382,82/10/15,8210850217
- 9210250242 Interim Significant Const Deficiency Rept 32 re failure to perform stress analysis for welded pipe support attachments prior to fabrication initially reported on 810810 Eleven hangers need reworking Final rept will be sent by 830624 MAURIN.L V Louisians Power & Light Co 82/10/15 COLLING, J T Region 4. Office of Director ip 15788 338 24X Fiche 50-382,02/10/15,8210250242

- DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION. UNIT 1
- £ NRC Safety Evaluation Report (SER), supple & correspondence
- 8210040052 Responds to SER, Suppl 3, Section 3 (1 5(1) relaging bimplementation of surveillance bimaint program Procedures written bischedules will be completed by 821005 CURTIS, N W. Pennsylvania Power & Light to 82/09/24 SCHWENCER, A Licensing Branch 2 3pp 15581 308 24% Fishe 50 387, 82/09/24, 6210040032
- 921013034) Updates 920924 response to SER Suppl J. Section J 11 5(1) re surve(llance & maint program per License Condition C(18)(a) Schedules complete for components requiring Surveillance/ replacement during first yr operation CURTIS,N N Pennsylvania Power & Light Co 82/10/06 SCHMENGER A Licensing Branch 2 lp 15679 137 24% Fiche 50-387, 02/10/06 0210130341
- F Security, medical, emergency % fire protection plans
- 8210010417 Forwards description of actions to be taken to correct deficiencies in physical security plansper 820901-02 discussions Revised plan forthcoming Encl withheld (ref IOCFR73 21) CURTIS.N W Pennsylvania Power & Light Co. 82/09/16 SCHWENCER, Licensing Branch 2 Ip 15572 1/5 24X Fiche 90-387.82/09/16.
- 8210210234 Notification of 821005 meeting w/util in Allentown.PA to discuss station blackout test plan PERCH.R L. Licensing Branch 1 82/09/2/ YOUNGBLOOD.8 J Licensing Branch 1 3pp 15774 333 24% Fiche 50-387,82/09/2/,8210210234
- 8210190158 Releases public version of emergoncy plan implementing procedure FELTON.J M Division of Rules and Records 82/09/28 Document Management Branch 1p 15758 020 24% Fiche 50-387,82/09/28, 8210190158
- --8210190166 Forwards public version of Revision O to Emergency Plan implementing Procedure EP-IP-048. "Estimation of Core Damage During Emergency " Receipt form encl * Pennsylvania Power & Light Co 82/09/17 NRC - No Detailed Affiliation Oliven (p. 15758-021 24X Fiche 50-387,82/09/28,
- --8210190173 Public version of Revision O to Emergency Plan Implementing Procedure EP-IP-048. "Estimation of Core Damage During Emergency "Revision 6 to procedure manual table of contents encl

 * Pennsylvania Power & Light Co 82/09/17 25pp (5758 023 24% Fichs 50-387, 62/09/28, 6210190158
- 8210060199 Advises that emergency operations facility & technical support ctr is operational Status of emergency response computer sys provided in 820916 Itr CURTIS,N W Pennsylvania Power & Light Co 82/10/01 SCHWENCER,A Licensing Branch 2 1p 15614 015 24X Fiche 50-387,82/10/01,8210060199
- 8210130430 Responds to inquiry re supplemental interim findings on adequacy of offsite emergency plans adequate Conditions should be imposed to assure completion of corrective actions KRIMM.R W Federal Emergency Management Agency 82/10/04 ORIMES.B K Division of Emergency Preparedness 1p 19681 192 24/ Fiche 50-387.82/10/04.8210130430
- 8210290201 Forwards IE Insp Rept 50-387/82-30 on 820712-15 No noncompitance noted MARTIN, T T Division of Engineering & Technical Programs 82/10/08 KENYONIB D Pennsylvania Power & Light Co 2pp 15854 015 24K Fiche, 50-387, 82/10/08,8210290201
- 8210250256 Forwards application for Amand 11 to License NPF-14 & proposed Yech Spec changes Amand deletes Fire Zone 1-6A in access area from Tech Bpecs CURTIS.N W Pennsylvania Power & Light Co 82/10/19 8CHWENCER.A Licensing Branch 2 ip 15791 153 24X Fiche 50-387.82/10/19. 8210200236

- --8210250264 Application for Amend 11 to License NPF-14, deleting File Zone 1-64 from Tech Spec 3 7 6 2 re sprinkler sys CURTIS,N W Pennsylvania Power & Light Co 82/10/19 1p 15771 154 244 Fiche 50 387.82/10/19.8210250256
- --8210250276 Proposed Tech Spec changes re spray & sprinkfor systallowing for continuous fire watch w/backup fire suppression equipment equipment

 * Pennsylvania Power % Light Co #2/10/19 1p 15791 155 24X

 Fishe 50-387, 82/10/19, 8210250256
- 8210290230 Application for Amend 13 to License NPF-14, revising License Condition 2 D to reflect Changes J.K. L & M. revision to Chapter II & security training & qualification plan including Revision I & Change A Class II amend fee enc? MENYON, B D Pennsylvania Power & Light Co 82/10/25 SCHWENCER, A Licensing Branch 2 2pp 15853 181 24X Fiche 50-387, 82/10/25, 8210290230
- 8210290318 Advises that mod to fire resistant wrap matl on cable trays in Fire Zone 1-20 remote shutdown panel completed per util 820831 commitment Mod satisfies License Condition C(7)
 - Bayusai commissionent non sacrifies citerie condition (17)
 requirements
 CURTIS.N W Pennsylvania Power & Light Co 82/10/25 SCHWENCER.A
 Licensing Branch 2 ip 15853 100 24% Fiche 50-387,82/10/25,
 82/10290318

) Adjudicatory correspondence

210280258 Order directing util to inform ASLB, by 821103, of how util will inplement change of leak rate monitoring sys per hearing testimony NRC to inform ASLB, by 821110, of related lech Specs % relationship to NURCO-0313.Revision | IOMMKINS, B A Atomic Sarety and Licensing Appeal Panel 82/10/26 Pennsylvania Power & Light Co 3pp 15837 024 24X Fiche 50-387, 82/10/26, 8210280258

General correspondence

- 210220351 Advises that 821006 telegram opposing facility will be sent to all parties to are parties GILINSKY, V Commissioners 82/10/20 DALTON, C Affiltation Unknown in 15779 127 24X Fiche 50-387, 82/10/20, 8210220351
- -8210220357 Opposes granting facility OL since no suitable evacuation plan exists
 - DALTON, C Affiliation Unknown 82/10/06 G(LINSKY, V Commissioners 1p (5779/128 24X Fiche 50-387, 82/10/20, 8210220351

Insurance & indemnity information

- '\$0220102 Forwards Endorsements 19.16 & 17 to NELIA Policy NF-262 CURTIS.N W Pennsylvania Power & Light Co 82/10/18 SCHWENGER Licepsing Branch 2 5pp 15778 172 24X Fiche 50-387,82/10/18, 8210220102 SCHWENGER, A
- 10220175 Forwards Endorsements 1-4 to MAELU Policy MF-107 CURTIS.N W Pennsylvania Power & tight Co 82/10/18 SCHWENCER.A Licensing Branch 2 1p 15778 001 24X Fiche 50-387.82/10/18, 8210/20175
- Operating license stage documents & correspondence
- 10210417 Forwards action plan for investigation of small pipe program concerns per 870730 mesting commitment 4ERYUN-9 D Pennsylvania Power & Light Co 82/08/04 MARTIN,T T Juyision of Engineering & Technical Programs 12pp 15763 074 24x 16hs 50-387,82/08/04,8210210417
- lOOA0391 Forwards rept of outlined actions & conclusions resulting from util investigation & Commission concerns re-small pipe programs presently 1.18,25 & 27 meetings ERYDRAB D Pennsylvania Power & Light Co 82/09/10 MARTIN,T T Mysten of Engineering & Tochnical Programs 120pp 15615 195 4X Fiche 50-387,82/09/10,8210060391
- 0180274 Summary of 820909 meeting w/util.Teledyne Engineering Svcs TEB), Bechtel & Nutech re conclusion of TEB final rept saved on review of feedwater sys inside containment List attandess encl
 RSH,R L Licensing Branch i 82/09/24 Licensin
 b 15746 336 24X Fiche 50-387.82/09/24.8210180274 ERSH, R L Licensing Branch 1
- 0190153 Summary of 820909 meeting w/util & Stannard & Co re onfiguration of gas pipeline near plant afte ERCH.R L Licensing Branch i 82/09/24 Licensing Branch i pp 15741 246 24% Fische 50-387.82/09/24.8210190153

- 8210210303 Notification of 820929 senior mgt meeting w/util in Bethesda MD to discuss plant status PERCH.R L Licensing Branch 2 82/09/27 YOUNDBLOOD.B J Licensing Branch 1 3pp 15774 357 24x Fiche 50-387,82/09/27. 8210210303
- 8210050325 Discusses offects of change in dissel generator start time from 10-s to 25-s on LOCA analysis in FSAR Chapter 6.3 Large recirculation discharge break peak clad temp not affected by delayed start time CURTISIN W. Pennsylvania Power & Light Co. 82/09/29 SCHMENCER, A Licensing Branch 2. 3pp. 15608-212 24X Fiche 50-387,82/09/29. 8210050325
- 8210050370 Provides interim justification for operability of feedwater sys check valves Calculations & ASME/ANSI sids provide adequate assurance that guillotine break of feedwater piping would not occur as result of operational transient CURTIS.N W Pennsylvania Power & Light Co 82/09/29 SCHWENCER.A Licensing Branch 2 2pp 15609 046 24X Fiche 50-3B7.82/09/29, 8210050370
- 8210210244 Requests written response addressing specific & general issues noted in Teledyne final rept on independent design review of plant feedwater sys inside containment NOVAK.T K Assistant Director for Licensing 82/09/30 CURTIS: Pennsylvania Power & Light Co 2pp 15774 331 24X Fiche 50-387,82/09/30,8210210244 82/09/30 CURTIS.N W
- 8210210288 Advises that util revised process control program containing methodology & parameters for solidification of radwaste acceptable Program meets Tech Spec 6 13 I requirement YOUNOBLOOD, B J Licensing Branch 1 82/09/30 CURTIS, N W Pennsylvania Power & Light Co 2pp 15774 345 24X Fiche 50-387, 82/09/30, 8210210289
- 210130122 Advises that final rept on automatic depressurfiation by scheduled for completion in Oct Option 4 of BWR owners group will be implemented Detailed design info will not be generated until NRC approval is received CURTIS-N W Pennsylvania Power & Light Co 82/10/01 BCHWENCER Licensing Granch 2 3pp 15673 001 24% Fiche 50-387,82/10/01,8210/30122 #210130122 Advises that final rest on automatic degressurfiation sus
- 8210260241 Forwards rept of systematic assessment of licensee performance & related correspondence HAYNES, R.C. Region I. Office of Director 82/10/01 KAYFMAN.J T Fennsylvania Power Co. 3pp. 15803-056 24X Fiche 50-387.82/10/01, 8210260241
- ~-8210260247 Systematic assessment of licensee performance for Mor 1981-Feb 1982 Overall performance acceptable * Region 1, Office of Director 82/06/01 31pp 15803 059 24x Fiche 50-387,82/10/01.8210260241
- --8210260257 Advises of completion of systematic assessment of licenses performance & notifies of 820617 site meeting to discuss assessment STAROSTECKI, R Division of Project & Resident Programs KAUFHAN, J T Pennsylvania Power & Light Co 2pp 158 24X Fiche 50-387,82/10/01,0210260241 15903 090
- --8210260270 Responds to 820604 systematic assessment of licensee performance Items discussed include licensed operators, health physics & chemistry staffs, operating procedures, punch list status & open items
 CURTIG,N W Pennsylvania Power & Light Go 82/07/02
 STAROSTECKI,R Division of Project & Resident Programs 9pp 13803 072 24X Fiche 50-387, 82/10/01.8210260241
- 8210080083 Forwards responses to Phase 2 finding & observations in final rept of Teledyns independent design review Program results re as-built reconciliation process will be available 82:101 CURTIS,N W Pennsylvania Power & Light Co 82/10/04 SCHWENCER.A Licensing Branch 2 8pp 15640 211 24X Fiche 50-387,82/10/04, 8210080083
- 8210270115 Forwards Amond 3 to License NPF-14, safety evaluation & notice of issuance & availability Amend changes Tech Spacs re essential svc water pump timer settings & dissel youngsLoop, B J Licensing Branch 1 82/10/04 CURTIS,N W Pennsylvania Power & Light Co 2pp 15866 345 24X Fichs 50-337, 82/10/04, 82/0270115
- --8210290128 Amend 3 to Licensa NPF-14, changing Tech Spacs re assential syc water pump timer settings & diesel surveillance requirement YOUNDI COD. B J Licensing Branch 1 82/10/04 7pp 15864 347 84X Fiche 50-387,82/10/04.8210290115

- --B210270130 Safety evaluation supporting Amend 3 to License NPF-14

 Diffice of Nuclear Reactor Regulation, Director 82/10/04 2pp
 15956 354 24X Fiche 50-387.82/10/04.8210290115
- --8210270136 Notice of issuance & availability of Amend 3 to Licensi NPF-14 KANE, U.F. Licensing Branch ! 82/10/04 2pp (5866-356 24X Fiche 50-387,82/10/04,8210270115
- 8210250010 Staff requirements memo summarizing 820930 discussion & possible vote on full power OL Decision deferred pending investigation review CHILF-5 J Office of the Secretary of the Commission 82/10/05 Office of the Secretary of the Commission 1p 15808 180 24X Fiche 50-387.82/10/05.8210250010
- 8210080142 Forwards application for Amend 9 to License NPF-14 adding into to minimite equipment damage due to high drywell temp KENYON. B D Pennsylvania Power & Light Co 82/10/06 SCHMENCER. A Licensing Branch 2 2pp 15640 131 24X Fiche 50-387, 82/10/06. 8210080142
- --8210080146 Application for Amend 9 to License NPF-14, adding info to minimize equipment damage due to high drywell temp KENYOKI BD Pennsylvania Power & Light Co 82/10/06 ip 13640 133 24X Fiche 50-387, 82/10/06 8210080142
- --8210080151 Marked-up proposed Tech Specs re minimizing equipment damage due to high drywell temp « Pennsylvania Power & Light Co 82/10/06 5pp 15640 134 24X Fiche 50-587, 82/10/06, 8210080142
- 5210190297 Forwards plan for expanded reconciliation sampling program to show adequacy of engineering judgments made in large pipe design process Final rept will be available 821112 Requests NRC allow operation up to 35% power CURTISIN W Pennsylvania Power & Light Co 82/10/14 BCHHENCER. A Licensing Branch 2 App 15742 168 24% Fiche 50-387.82/10/14. 8210190297
- 8210250256 Forwards application for Amend 11 to License NPF-14 & proposed Tech Spec Changes Amend deletes Fire Zone 1-6A in access area from Tech Specs CURTIS, N. W. Pennsylvania Power & Light Co. 82/10/19 SCHWENCER, A Licensing Branch 2 1p 1579; 153 24X Fiche 50-387, 82/10/19, 9210250256
- --8210250264 Application for Amend II to License NPF-14, deteting file Zone 1-6A from Tech Spec 3 7 6 2 re sprinkler sys CURTIS,N H Pennsylvania Power & Light Co 82/10/19 ip 13791 IS4 24X Fiche 50-387, 82/10/19,8210250256
- ~-0210250276 Proposed Tech Spec changes re spray & sprintier sys.allowing for continuous fire watch w/backup fire suppression equipment
 # Pennsylvania Power & Light Co 82/10/19 ip 15791 155 24X
 Fiche 50-307.82/10/19.8210250256
- 8210290367 Forwards application for Amend 10 to License NPF-14, changing Tech Spec Table 3 8 4 1-1 to include more conservative Type 2 molded case circuit breakers & to add previously omitted Type 3 molded case circuit breakers CURTIS.N W Pennsylvania Power & Light Co 82/10/19 SCHWENCER, A Licensing Branch 2 2pp 15790 179 24X Fishe 50-387, 82/10/19. 8210230367

- 8210260366 Forwards application for Amend 12 to Lictuse NPT-14, changing Jech Specs 4 if 2 7 1.4 if 2 / 2 t Page 3/4 8-18 re radioactive effluents main condenser t electrical power sys CURTIS. If II Pennsylvania Power t Light Co 62/10/22 SCHWENTER. A Licensing Branch 2 ip 15804 239 24X fiche 50-387,83/10/22. 8210260366
- --8210260379 Application for Amend L. to License NPF 14, changing (ech Specs 4 1f 2 7 f.4 1f 2 7 2 % Page 7/4 8-18 re radioactive effluents; main condense; 7 electrical power sys CURTIS, N W Pennsylvania Power Light Co. B2/10/22 lp 15804 240 24% Fiche 50 387,82/10/22,8210260366
- --8210260385 Proposed changes to Toch Specs 4 11 2 7 1.4 11 2 7 2 Page 3/4 B-18 re radioactive effluents, main condunser % electrical power sys # Pennsylvania Power * Light Co #8/10/22 Jpp 15804 241 212 Fiche 50-687, 82/10/22 8210260366
- 8210290230 Application for Amend 13 to License APF-14, revising litense Condition 2 B to reflect Changes J K t B N. revision to Chapter 11 b security training b qualification plan including Revision 1 b Change A Class 11 amend fee encl KENYON, B B Pennsylvania Power & Light Co B2/10/25 \$CHWINCER A Licensing Branch 2 2pp 15857 181 (4X Ficho 50-387,82/10/25,8210290230
- O Inspection reports: 1E Bulletins & correspondence
- B210260241 Forwards rept or systematic assessment of litensee performance & related correspondence HAVNES, R.C. Region to Office of Director D2/10/01 MAUFMAN, J.J. Fennsylvania Power Co. 3pp. 15803-056. 24X fiche 50-387-02/10/01 R210260241
- --g210260247 Systematic assessment of licensee performance for Mai 1984-Feb 1982 Overall performance acceptable P Region 1, Office of Director 02/04/01 31pp 15803 059 291 Fiche 50-387,82/10/01.8210260241
- --8210260297 Advises of completion of systematic assessment of licentee performance & notifies of 820617 site meeting to discuss assessment STAROSTECKI.R Division of Project & Resident Programs 82/06/04 KAUFMAN, U.T. Pennsylvania Power % Light Co. 29p 1580,1090 24X Fiche 50-287, 82/10/01.8210260241
- --8210260270 Responds to 820604 systematic assessment of liconsequence performance items discussed include licensed operators, health physics & chemistry staffs, operating procedures, punch list status & open items
 CURTIS.N M Pennsylvania Pawer & Light to D2/07/02
 STARDSTECKI.R Division of Project & Rosident Programs Spp
 15803 092 24X Fishe 50-307,02/10/01,0210260241
- 8208190233 IE lnfo Notice 80 35. Suppl 1. "Leaking & Disladged 1-12". Implant Seeds " Svc list encl COBD.L. I Division of Fuel Facilities, Materials & Safoguards 82/10/06 Consolidated Edison Co of New York & App. 15761 2"8 24% Fiche 50-000.82/10/06.9208190233
- 821029020[Forwards 1E Insp Rept 50-307/B2-30 on 820712-19 No noncompliance noted HARTINI T Division of Engineering & Technical Programs 82/10/08 KENYON, B.D. Pennsylvania Power & Light Co. 2pp 15854 015 -/4X Fiche 90-387, 82/10/08, 8210290201
- --B210290207 IE Insp Rept 50-387/82-30 on 820712-14 No moncompliance noted Major areas inspected security say power supply access control.lighting assessment alds.detection aids & communications Details withheld (ref 1007R73 R1) DVMLAP.J M. GODY.A T Rogion 1. Office of Director 82/10/96 by 15854 017 24% Fichs 50-387.82/10/08.8210290201
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter Stainless Steel, Recirculation Bys Piping at BWR Plants " Bvc list encl DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 80-000, 82/10/14, 8208190238
- 8 Reportable occurrences, LERs & related correspondence
- 8210010177 Forwards LER 82-014/03L-0
 KEISER, H W Pennsylvania Power & Light Co 82/09/22 HAYNES, R C
 Region 1. Office of Director 1p 15567 285 24X
 Fiche 30-387, 82/09/22, 8210010177

- --B210010180 LER 82-014/03L-0 on 820824, prior to initial criticality, unit taken from Operational Condition 5 to 4 w/o shutdown cooling mode of RHR in operation as required by Tech Spec Initial startup procedure superseded by normal startup procedure where the procedure will be procedure to the procedure of th
- 8210010228 LER 82-016/01P on 820918, turbine bldg vent monitor system to be gas nonitor declared out of svc Grab sampling once per 8-h initiated Mechanical vacuum pump in svc until 820920 contrary to Tech Specs Cause not stated PEISER. H W Pennsylvania Power & Light Co 82/09/22 HAYNES. R C Region 1, Office of Birector ip 15568 261 24% Fiche 50-387.82/09/22.8210010228
- 82:0010393 Forwards LER 92-015/03L-0 VEISER:H W Pennsylvania Power & Light Co 82/09/22 HAYNES:R C Region t, Office of Director 1p 15572 264 24X Fiche 50-387, 82/09/22:8210010393
- --8210010402 LER 82-015/OSL-0 on 820924, from start of initial fool load until 820825, spray pond level & temp not monitored Caused by ontaxion of Tech Spec 4 7 1 3 requirements from procedures Procedure repritten

 KUCZYNISKI. L. A. Pennsylvania Power & Light Co. 82/09/22 Region
 1. Office of Director 1p. 15572 265 24X Fiche 50-387, 82/09/22, 8210010393
- 6210040086 Forwards LER 92-017/03L-0 KEISER, H W Pennsylvania Power & Light Co 82/09/24 HAYNES, R (Region 1, Office of Director 1p 15581 015 24X Fiche 50-387, 82/09/24, 8210040086
- --8210040088 LER 82-017/03L-0 on 820826, sprinkler sys for fire zone 1-5A was out of svc Detector reset initiated on Fire protection panel in control room but required reset of priorities (RSP) not performed RSP initiated KUCZYKISKILL A Pennsylvania Power & Light Co 82/09/24 Region 1. Office of Director 1p 15581 014 24X Fiche 50-387,82/09/24,8210040086
- 5210040118 Forwards LER 62-012/01T-0 KEISER:H W Pennsylvania Power & Light Co 82/09/24 HAYNES:R & Region 1: Office of Director 1p 1958: 193 24X Fishe 50-387: 82/09/24: 8210040110
- --8210040122 LER 82-012/017-0 on 820910.potential existed for overload of Class IE electrical sys due to concurrent loading of emergency ever water pumps & existen RMR or core eyrey pumps during intermediate LOCA Caused by inadequate evaluation CISEMHULF T Pennsylvania Power & Light Co 82/09/24 Region I. Office of Director 2pp 15981 194 24X Fiche 30-387. 62/09/24.8210040110
- 8210130352 Forwards LER 82-020/03L-0 KEISER: H W Pennsylvania Pover & Light Co 82/10/01 HAYNES, R C Region L Office of Diroctor Jp 15679 125 24X Fiche 30-387, 82/10/01, 8210130352
- --8210130361 LER 82-020/03L-O on 820903.after both RHR sys trains removed from syc.pressure & temp were not recorded Caused by operator misjudgment Operators instructed to log & follow ali action statements
 MITCHELL.D G Pennsylvania Power & Light Ca 82/10/01 Region
 L. Office of Director 1p 19679 126 24X Fiche 50-387,82/10/01.
 8210130352
- 8210130363 Forwards LER 82-018/03L-0 KRISER, H W Pennsylvania Power & Light Co 82/10/01 HAYNES, R C. Region i. Office of Director 1p 15682 113 24X Fichs 90-387, 82/10/01, 8210130363
- --8210130371 LER 82-018/03L-0 on 820702. w/mode switch in refuel, three out of four source range monitors were inoperable Caused by Inadvertent stressing of cables during undervessel work Procedure revised to reduce cable wear HITCHELL, D 0 Pennsylvania Power & Light Co 82/10/01 Region 1, Office of Director 1p 15582 114 24X Fiche 50-387,82/10/01,8210130363
- --8210130387 LER 82-019/01T-0 on 820920, during power ascension testing, turbine bidg vent monitor sys became inoperable Gaused by failure to remove mechanical vacuum pump from svc Pump stopped & steam jet air ejectors placed in svc MITCHELL.D Q Pennsylvania Power & Light Co 82/10/01 Region 1. Office of Director 1p 15681 007 24X Fiche.50-387.82/10/01, 8210130377

- 8210130405 PNO-1-82-064 on 821006.anchor for 6-inch RHR sys line found to have weld gne-third specified length Failure of support would overstress containment penetration Authorization to exceed 5% power postponed MCCABE.E C , KEMIO Region 1. Office of Director 82/10/07 ip 15680 260 24% Fichd 50-387.82/10/07.8210130405
- 8210210440 Forwards LER 82-021/03L-0 KEISER:H W Pennsylvanse Power & Light Co 82/10/08 HAYNEB:R C Region 1. Office of Director ip 15763 045 24X Fiche 50-387.82/10/08.8210210440
- --8210210446 LER 82-021/03L on 820910, while performing surveillance of rad worth minimizer, selection error indicating light did not operate properly Caused by one 28-volt conductor being pulled loose from 119th Assembly due to stress MITCHELL, D.O. Pennsylvania Power & Light Co. 82/10/08 Region 1, Office of Director ip 15763 046 24% Fiche 50-387,82/10/08,8210210440
- B210210285 Forwards LER 82-019/03L-0 KE18ER: H W Pennsylvania Power & Light Co 82/10/11 HAVNES: R C Region 1. Office of Director 1p 15765 086 24X Fiche 50-387. 82/10/11, 8210210285
- --0210210293 LER 82-019/03L-0 on 020912.during startup testing.

 Operational Condition 2 entered prior to completion of required daily surveillances Caused by incorrect identification of condition Evant will be reviewed MITCHELL,D G Pennsylvania Power & Light Co 02/10/11 Region 1. Office of Director 1p 15765 087 24X Fiche 50-387,02/10/11, 8210210285
- 8210210433 Forwards reissued LER 82-016/017-1 KEISER:H W Pennsylvania Power & Light Co 82/10/11 HAYNES:R C Region I. Office of Director ip 15763 015 24X Fiche 50-387.82/10/11.8210210433
- --8210210436 Reissued LER 82-016/017-1 on 820920, methanical vacuum pump left in svc after vantilation monitoring sys nobie gas monitor became inoperable on 820918 Caused by operator not noting all parts of applicable action statements MITCHELL.D O Pennsylvania Power & Light Co 82/10/11 Region 1. Office of Director 2pp 15763 016 24% Fichs 50-387. 82/10/11.8210210433
- 82(0210020 Final deficiency rept re improper field mounting of Agastat 7000/E7000 relays Initially reported an 820702 Corner mounted screws & relays will be reworked by 821026 Also reported per Part 21 CURTIS,N W Pennsylvania Power & Light Co 82/10/12 HAYNES,R C, Region 1. Office of Director 4pp 15766 Q17 24X Fiche 50-387,82/10/12.8210210020
- 8210210137 Final deficiency rept re pump motor start times for emergency syc water.core spray & RHR sys Initially reparted on 820910 Low pressure vessel interlock deleted from RHR & core spray pump start Also reported per Part 21 CURTIS.N W Pennsylvania Pawer & Light Co 82/10/12 HAYNES.R C Region 1. Office of Director. 4pp 15766 103 24X Fiche 50-387.82/10/12,8210210137
- 8210250347 LER 82-026/01P-0 confirms 821013 telcon re failure to complete graunding of reactor protection sys cabling prior to fuel loading as required by License NPF-14 KEISER, H W Pennsylvania Power & Light Co 82/10/14 HAYNES, R G Region i, Office of Director ip 15790 047 24X Fiche 50-387, 82/10/14, 8210250347
- 8210250357 LER 82-025/01P-0 confirms 821013 teicon re inability to comply w/action statement Chlorine detectors inoperable Action statement requires one control room emergency outside air supply sys in recirculation mode KEJGER.H W Pennsylvania Power & Light Co 82/10/14 HAYNES,R.C Region 1. Office of Director. 1p 15791 015 24X Fiche 50-387.82/10/14.8210250357.
- 8210290367 Forwards LER 82-022/03L-0 KEIGER, H W. Pennsylvania Power & Light Co 82/10/14 HAYNES, R. C Region 1. Office of Director 1p 15790 137 24X Fiche 90-387, 82/10/14, 8210250369
- --82;0250377 LER 82-022/03L-0 on 820916, while cleaning control rad drive (CRD) suction strainers.CRD pumps tripped Caused by low suction pressure due to pressure fluctuations from cucling condensate reject valve Suction trip logic modified MITCHELL.D O Pennsulvania Power & Light Co 82/10/14 Region 1. Defice of Director lp 15790 138 24% Fiche 50-387,82/10/14,8210250369

- 8210250381 Forwards LER 82-023/03L-0 VEISER:N W Pennsylvania Power & Light Co 82/10/14 HAYNES:R C Region 1. Office of Director :p 15790 134 24X Fiche 50-387: 82/10/14:8210250381
- --8210250385 LER 82 023/03L-O on 820915 during startup testing of steam relief valve acoustic monitoring systhmee monitors failed to operate correctly Event was initial callbr of monitors using steam Monitors adjusted the steated by laced in svc MITCHELL.D O Pennsylvania Power 5 Light Co 82/10/14 Region 1. Orfice or Director 1p 15790 135 24X Fiche 50-387.82/10/14, 6210250381
- 8210260539 LER 82-024/01P-0 on 821015, potential for unanalyzed accident resulting from single failure of spray pond bypass valve reported Redundancy provided by automatic transfer to B loop on failure of A loop pumps to start REISER: H W Pennsylvania Power A Light Co 82/10/18 HAYNES: R CRegion I. Office of Director 1p 15805 136 24X Fiche 50-387, 82/10/18, 8210260509
- 8210280215 Forwards LER 82-027/03L-0 VEISER.H W Pennsylvania Power * Light Co 82/10/19 HAYNES.R (Region 1. Office of Director 1p 15837 004 24Y Fiche 50-387.82/10/19 8210280215
- --6210280219 LER 82-027/03L-0 on 820920 two drywell/suppression chamber vacuum breakers gave false position indications during stroking Caused by loose couplings connecting limit switch to vacuum relief valve shaft Set screu replaced MITCHELL.D G Pennsylvania Power & Light Co 62/10/17 Region 1, Orfice of Director 1, 15837 005 24X Fiche 50-387, 82/10/17, 8210280215
- T Hearing transcripts on non-antitrust matters
- 8210130113 Unoffical transcript of 820730 public meeting in Washington, DC re-briefing on full power OL amend Pp 1-97 Supporting documentation encl Commissioners 82/09/30 158pp 15696-083 24X
 Fiche 50-387, 82/09/30, 8210130113
- (Onsite Storage of Low Level Waste
- \$210270411 Notification of contract execution Mod 3 to "Environ Assessment of Low Level Waste Storage at PA Power & Light Co. Susquehanna Steam Electric Station " Contractor Science Applications. Inc FLEENOR.C M Administrative Contracts Branch NRC-02-B1-064 B2/09/30 DAVIS.J , LOYSEN,P Office of Nuclear Material Safety & Safeguards, Director 1p 15833 277 24X Fiche 50-387, 82/09/30, 8210270411
- --8210270413 Mod 3.extending period of performance to 830131.revising billing instruction info & substituting Hamual Chapter 3202. to "Environ Assessment of Lou Level Haste Storage at PA Power & Light Co. Susquehanna Steam Electric Station "ARCHER:C D Science Applications, Inc. HAMAN, I F Technical Assistance Contracts Branch NRC-02-81-064 82/09/30 2pg 15833 278 24X Fiche 50-387.82/09/30.8210270419
- DOCKET 50-388 SUGBUEHANNA STEAM ELECTRIC STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8210210417 Forwards action plan for investigation of small pipe program concerns per 820730 meeting commitment KENYON, B D Pennsylvania Power & Light Co 82/08/04 MARTIN.T T Division of Engineering & Technical Programs 12pp 15765 074 24x Fiche 50-387, 82/08/04, 8210210417
- 8210060391 Forwards rept of outlined actions & conclusions resulting from util investigation & Commission concerns re small pipe programper 820911; 18,25 & 27 meetings

 KENYON, B D Pennsylvania Power & Light Co 82/09/10 MARTIN, T T Division of Engineering & Technical Programs 120pp 15615 195

 24% Fiche 50-387, 82/09/10, 8210060391
- 8210260241 Forwards rept of systematic assessment of licenses performance & related correspondence HAYNEG, R C Region 1, Office of Director 82/10/01 KAUFMAN, J T Pennsylvania Power Co 3pp 15803 054 24X Fiche 50-387,82/10/01,8210260241
- --8210260247 Systematic assessment of licensee performance for Mar 1981-Feb 1982 Overall performance acceptable. * Region 1. Office of Director 82/06/01 31pp 15803 059 24X Fiche 50-387,82/10/01.8210260241

- --8210260257 Advises of completion of systematic assessment of linease, performance A notifies of B20017 site meeting to discuss assessment
 STAROSTECKI, R. Division of Project * Resident Programs 8a/0A/u4
 KAUFING J T. Pennsylvania Puwer & Light Co. 2pp. 1580J 090
 244 Fiche 50-387,82710-01-8210260241
- -8210260270 Responds to 820604 systematic assessment of licensee performance Items discussed include licensed operators, health physics 'chemistry staffs operating procedures punch list status & open items
 CURTIS:(I W Pennsylvania Power / Light (a 82/0//02 STAROSTECKI R Division of Project & Resident Programs Ypp 15803 092 24X Fichs 50 3(37.62/10/01.821026024)
- F Security, medical emergency & fire protection plans
- 0210010417 Forwards description of actions to be taken to correct dericinecies in physical security plan per 820701 (2) discussions Revised plan forthcoming Enct withheld (ref 100F873 21) CURTISH W Pennsylvania Power 5 Light on 82709716 SCHWINCIA Licensing Branch 2 lp 15572 175 24K Fiche 50 JB7 82709716 M210010417
- GZ10190150 Releases public version of emergency plan implementions procedure FELTON.J M Division of Rules and Records U2/09/20 Document Management Branch ip 15/58 020 24x Fiche 50 JUT.82/09/20, 8210190150
 - 8210190166 Forwards public version of Revision 0 to Emergency Plan Implementing Procedure (P-1P-04B, "Estimation of Core Dawage Ouring Emergency "Receipt form enc! * Pennsylvania Power 'Light Co 62/09/17 tHC No Detailed Affiliation Given 16 15758 021 24% fiche 50-387,82/097/9, 8210190158
- 8210190173 Public version of Revision O to Emergency Plan Implemented Procedure EP-IP-048, "Estimation of Core Damage During Emergency "Revision o to procedure manual table of contents enci • Pennsylvania Power & Light Co 62/09/17 25pp 15/58 0.1 24X Fiche 50-387, 82/09/28, 0210190158
- 8210130430 Rosponds to inquiry re supplemental interim findings on adequacy of affects emergency preparedness for facility State & local emergency plans adequate Conditions should be imposed to assure completion of corrective actions RRIMMAR W Federal Emergency Management Agency GP/10/04 GRIMES B K Division of Emergency Preparedness 1p 15681 172 24X Fiche 50-387,82/10/04,8710130430
- G Adjudicatory correspondence
- 8210280278 Order directing util to inform ASLB, by 821103, of how util will implement change of leak rate monitoring sys per hearing testimony NRC to inform ASLB, by 821100, of related Tech Specs & relationship to NURFG-0313. Revision 1
 TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 82/10/26 Pennsylvania Power & Light Co. 3pp 15837 024 24X
 Fiche 50-387, 82/10/26, 8210280258
- H General correspondence
- 9210220351 Advises that 821006 telegram opposing facility will be sent to all parties of the sent to all parties of the sent o
- --8210R20357 Opposes granting facility OL since no suitable evacuation plan exists DALTOR: Affiliation Unknown 82/10/06 GILINGKY, V Commissioners ip 15779 128 24X Fiche 50-387, 82/10/20, 8210920351
- Q Inspection reports, IE Bulletins & correspondence
- 8210260241 Forwards rept of systematic assessment of licensee performance & related correspondence HAYNES, R C Region I. Office of Director 82/10/01 KAUFMAN.J T Pennsylvania Power Co 3pp 19803 056 24X Fiche 50-387,82/10/01
- ---8210260247 By stematic assessment of licensee performance for Mar 1981-Feb 1982 Overall performance acceptable # Region 1. Office of Director 82/06/01 31pp 15803 059 24r Fiche 50-387,82/10/01,8210260241

- --8210260257 Advises of completion of systematic assessment of licensee performance & notifies of 820617 site meeting to discuss assessment STARGSTECKI, R. Division of Project & Resident Programs 82/06/04 KAUFHAN, J. T. Pennsylvania Power & Light Co. 2pp. 15803 090 24% Fiche 50-287, 82/10/01,8210260241
- --B210260270 Responds to B20604 systematic assessment of licensee performance Items discussed include licensed operators, health physics & chemistry staffs, operating procedures, punch list status & open items CURTIS,N W Pennsylvania Power & Light Co B2/07/02 STAROSTECKI,R Division of Project & Resident Programs 9pp 15803 092 244 Fiche 50-387, 82/10/01, 8210260241
- 8208190233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged 1-125 Implant Seeds " Svc list enc! CODB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & App 15761 250 24/ Fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corresson Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants " Svc list enct DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- S Reportable occurrences. LERs & related correspondence
- 8210010268 Interim deficiency rept re inadequate clearance in Pacific Scientific shock suppressors & ITT Orignell pipe clamps Initially reported on 820820 final rept will be submitted by 830201 Also reported per Part 21 CURTIS:N W Pennsylvania Power & Light Co 82/07/23 HAYNES,R C Region 1, Office of Director 4pp 15573 110 24% Fiche 50-388,82/09/23,8210010268
- 3210210020 Final deficiency rept re improper field mounting of Agastat 7000/E7000 relays Initially reported on B20702 Corner mounted screws & relays will be reworked by 821026 Also reported per Part 2! CURTISIN W Pennsylvania Power & Light Co 82/10/12 HAYNESIR C Rogion 1. Office of Director App 15766 017 24X Fiche 50-287, 82/10/12, 8210210020
- 1210210137 Final deficiency jept re pump motor start times for emergency svc water core spray & RHR sys Initially reported on 820910 Low pressure vessel interlock deleted from RHR & core spray pump start Also reported per Part 21 CURTISIN W Pannsylvania Power & Light Co 82/10/12 HAYNES.R C Region 1, Office of Director App 15764 103 24X Fiche 50-387,82/10/12.8210210137
 - Onsite Storage of Low Level Waste
- 210270411 Notification of contract execution; Mod 3 to "Environ Assessment of Low Level Waste Storage at PA Power & Light Co. Busquehanna Steam Electric Station " Contractor Science Applications, Inc FLEEHOR. of Administrative Contracts Branch NRC-02-81-064 82/09/30 DAVIS.J., LOYSEN.P Office of Nuclear Material SaPoty & Safeguards, Director ip 19833 277 24% Fiche 50-387,82/09/30, 8210270411
- -8210270413 Mod 3, extending period of performance to 830131, revising billing instruction info & substituting Manual Chapter 3202, to "Environ Assessment of Low Level Naste Storage at PA Power & Light Co. Susquehama Staam Electric Station" ARCHER, C D Science Applications, Inc HAGAN, T F Technical Assistance Contracts Branch NRC-02-81-004 82/09/30 2pp 15833 278 24X Fiche 50-387, 82/09/30, 8210270411
- CMET 80-389 BT LUCIE PLANT, UNIT 2
 Application/construction stage documents & correspondence
- 10190014 Forwards background info for meeting to discuss engineering verification program & measures used to assure program independence W/o encls independence W/o encls independence W/o encls NERSEB, V Licensing Branch 3 82/09/09 DENTON. H R Office of Nuclear Reactor Regulation, Director EIGENNUT, D Q Division of Licensing VOLLMER, R H Division of Engineering 2pp 15760 316 24% Fiche 50-389,82/09/09.8210190014
- 10080340 Discusses NRC understanding of core load schedule List of licensing actions not yet resolved to NRC satisfaction encl. 40VAN,T H Assistant Director for Licensing 82/09/10 UHRIG,R E Tlorida Power & Light Co Sep 15643 323 24X Tiche 50-389, 82/09/10, 8210080340

- 8210010017 Forwards response to rindings identified in 820831-0901 audit of electrical area UHRICA E Florida Power & Light Co 82/09/24 EISENKUT, D G Division of Licensing 3pp 15565-144 24X Fiche 50-389, 82/09/24, 82/00
- 8210040334 Forwards minutes of 820723 meeting w/util & C-E task Force managers in Windsor,CT re engineering verification program BLODESTIT H Ebasco Services. Inc. (subs. of Enserch Corp.) 82/097/27 E18ENDUT D G Division of Licensing 3pp. 15584 170 24X Fiche 50-389,82/09/29 8210040334
- 8210210028 Authorizes use of ASME Cade Case N-316 for application in const of camponents Use of code case should be documented in FSAR KERRIOAN, J D Licensing Branch 3 82/09/29 UHRIG.R E Florida Power & Light Co 2pp 15782 201 24% Fiche 50-389.82/09/29, 8210210028
- 8210210251 Notification of 821000 meeting w/util in Bethesda, MD to discuss procedure for leak testing pressure isolation valves Meeting agenda enci NERSES, V Licensing Branch 3 82/09/29 KERRIOAN, J Licensing Branch 3 4pp 15774 327 24X Fiche 50-389,82/09/29,8210210251
- 82:0050416 Forwards Suppl) to "Near-Term OL Summary Human Engineering Rept on St Lucie Unit 2 Control Room" URRIO,R E Florida Power & Light & 82/77/30 EISENHUT.D G Division of Licensing 1p 19607 125 24x Fiche 50-389.82/09/30. 82:0050416
- --8210050419 Suppl : to "Near-Term OL Summary Human Engineering Rept on St Lucie Unit 2 Control Room ' 4 Florida Power & Light Co 82/09/07 179pp 15607 126 24% Fiche 50-389, 82/09/00.8210050416
- 8210060276 Forwards training program on Loose parts monitoring syswhich property qualities plant personnel to operate sys Submittal completes action to satisfy NRC request UMRIO:R E Florida Power & Light Co 82/09/30 EISENHUT D 0 Division of Licensing 2pp 1562: 170 24% Fiche 50-389.62/09/70, 8210060274
- 8210060288 Informs that requirements stated in Generic Ltr 82-12 restaff working hours adequately enforced by incorporation in administrative procedures Amend to Tech Specs unnecessary at present time
 UHRIGAR E Florida Power & Light Co 82/09/30 EISENHUY, D G
 Division of Cicensing Ip 15619 212 24X Ficho 50-335,82/09/30,8210060288
- 8210180268 Trip rept of caseload forecast panel 820608-10 site visit to assess const progress Meeting agenda & attendance list encl MERSES, V Licensing Branch 3 82/10/01 Licensing Branch 3 8pp 15746 328 24X Fiche 50-389.82/10/01.8210180268
- 8210210591 Forwards finel NRR input for plant Cycle 3 systematic assessment of licenses performance evaluation Contributors listed NERGES.V Licensing Branch 3 82/10/01 EISENHUT, D 0 Division of Licensing 6pp 19784 318 24X Fiche 50-389,82/10/01,8210210591
- B210130289 Forwards util responses to NRC concerns to inadequate core cooling instrumentation, per 820914 telcon w/NRC dualification testing of heated junction thermocouple sys scheduled for completion by 821015

 VHRIO.R E Florida Power & Light Co 82/10/03 EIBENHUT, D Q Division of Licensing 4pp 15678 306 24X Fiche 50-389, 82/10/05, 8210130289
- 8210270339 Forwards status of control room design review Requests addition to progress wimplementing corrections for human engineering discrepancies & control room man-machine operations

 KERRIOAN.J D Licensing Branch 3 82/10/07 UHRIG.R E Florida

 Power & Light Co 7pp 15851 342 24X Fiche 50-389,82/10/07,82/10/07
- 8210130301 Forwards list of engineering & const items that are not appected to be completed at core load & justification for operation prior to completion of items UHRIG.R E Florida Power & Light Co 82/10/08 EIBENHUT.D Q Division of Licensing 19pp 15678 IB4 24X Fiche.50-089,82/10/08,82(0)30301
- 8210190348 Forwards add1 info re oneste ac power sys bus tie interlocke UHRIG.R E Florida Power & Light Co 82/10/12 EISENHUT.D O Division of Licensing 2pp 15737 243 24X Fiche 50-389.82/10/12, E210190348

- 8210250313 Informs that all generic itrs through 82-14 applicable to facility have been reviewed & required responses submitted UHRIO, R E Fibrida Power & Light Co 82/10/20 EISENHUT, D 0 Division of Licensing 1p 15790 063 24X Fiche 50-389,82/10/20,8210250313
- 8210260114 Forwards minutes of 821006-07 meeting w/util. Ebasco & C-b task force managers re engineering verification program 8LODOSTY.T H Ebasco Services, Inc (subs of Enserch Corp.) 82/10/20 EISENHUT. D 9 Division of Licencing 4pp 15799 112 244 Fiche 50-389, 82/10/20, 8210260114
- 6210280254 Forwards proprietary "Final Assessment of St Lucie 2 Fuel Structural Integrity Under Faulted Conditions." (CEN-187(1)-P. Reylsion I-P 8 "St Lucie 2 Fuel & CEA Design Summary Evaluation Rept." CEN-222(1)-P. Repts withheld UHRIO.R E Florida Power & Light Co 82/10/24 EISENHUT.D 0 Division of Licensing 7pp 15845 316 24X Fiche 50-389,82/10/26,6210280254
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8210180263 Notification of 821005 meeting w/util & C-E in Windsor.Cf to discuss review of closeout of SER Section 4.2, "Fuel Sye Design," open items MERGEB, V. Licensing Branch 3. 82/09/28 KERRIGAN, J. D. Licensing Branch 3. 3pp. 15746-325. 24X Fiche 50-389,82/09/28,8210180263
- 8210180237 Requests addition to fuel analysis in order to complete review of SER confirmatory issue MERRIOAN.J D. Licensing Branch 3 82/10/01 UHRIO.R E. Florida Power & Light Co. 2pp. 15745-258 24X Fiche 50-389, 82/10/01, 82/10/80/37
- 6210120257 Forwards Alden Research Lab. "Performance Evaluation of Containment Sump at Full-Scale. St Lucie Nuclear Power Station 2" Submitted completes commitment to provide BER confirmatory info on vertex testing URRIO.R E Florida Power & Light Co 62/10/06 EISENHUT.D 0 Division of Licensing 19 15676 051 24X Fiche 50-389,92/10/06.8210130257
- --821013D287 "Performance Evaluation of Containment Sump at Full-Scale, Bt Lucie Nuclear Power Station 2" DURGIN,W H Aiden Research Laboratory 106-82/M7KF 82/09/30 41pp 15678,052 24X Fiche 50-389/82/10/06/8210130257
- 8210280057 Forwards proprietary "Response to NRC Questions on Implementation of 8t Lucie Unit 2 Rod Bow 4 Orid Specing Penalties" to resolve action items identified in SER (NURGE-0843). Highbeld (ref 100FR2.790).
 UHRIG.R E Florida Power & Light Co 82/10/25 EISENHUT, D G. Division of Licensing Sep 15837 241 24% Fiche 50-369.82/10/29, 82/10/20067.
- F Security, medical, emergency & fire protection plans
- B210010185 Forwards IE Insp Repts 50-338/82-28 & 30-389/82-37 on 820809-13. No noncompliance noted.

 DANCE, H. C. Division of Project & Resident Programs 82/09/08. URRIGO, R. G. Florida Power & Light Co. Rep 15865 326 24X Fichs. 50-335, 82/09/08. 8210010185

- 8210190056 Forwards request for addl into re 10CFR50.App R Sections III 0 % III L info required to complete review of fire protection of safe shutdown capability KERRIGAN, J D Licensing Branch 3 82/09/29 UHRIG.R E Florida Power & Light Co 3pp 15761 046 24% Fiche 50-389,82/09/29,8210190056
- B210130348 Forwards response to Question 410 52 re fire protection requirements
 UHRIO,R E Florida Power & Light Co 82/10/07 EISENHUT,D G
 Division of Licensing 2pp 15682 036 24% Fiche 50-389,82/10/07,8210130348
- 8210260376 Ack receipt of 821013 Itr informing NNC of steps taken to correct violations noted in IE Sareguards Insp Rept 50-335/82-30
 LENIS, R.C. Division of Project // Resident Programs 82/10/2/UNRIG, R.E. Florida Power // Light Co. ip 15806 IJB 244
 Fiche 50-335, 82/10/22, 8210260376
- --8210260510 Forwards IE Safeguards Insp Repts 50-335/82-30 & 50-389/82-41 on 820816-20 & notice of violation Notice of violation & rept defails withheld (ref 100CR73 21) LEWIS.R C Division of Project & Resident Programs 62/09/13 UMRIO.R E Florida Power & Light Co 2pp 15806 140 24X Fiche 50-335,62/10/22.62/10260376
- --8210260515 IC Bafeguards Insp Repts 335/82-30 &50-389/82-41 on 820816-20 Nancompliance noted failure to comply wiscourity plan re vehicle control, alarms & compensatory action Details withheld (ref 10CFR/3 21) gODDE, R Region 2. Office of Director 82/09/10 2pp 15806 142 24X Fiche 50-335, 82/10/22.8210260376

M Antitrust correspondence

- S210120416 Notification of contract execution, Mod 2 to "Economic Assistance for St Lucia 2 Antitrust Proceeding (II) "Contractor JM Kuhiman MCLEAREN. T Technical Assistance Contracts Branch Fin B-7543 82/10/05 DENTON-H R Office of Nuclear Reactor Regulation, Director ip 13689 222 24X Fiche 50-389, 82/10/05,8210120416
- --8210120423 Mod 2.deobligating funds.to "Economic Assistance for 8t Lucie 2 Antitrust Proceeding (II) "
 KUHLMAN.J M Kulhman. J M (AGAN.T F Technical Assistance Contracts Branch FIN 8-7543 82/10/05 ip 15687 223 24x Fiche 50-389,82/10/05,8210120416
- O Inspection reports. IE Bulletins & correspondence
- 9210220214 Advises that weld re-exam completed on 920621, in response to IE lnsp Rept 50-389/82-13 Results made available to sits inspector
 UHRIO, R.E. Florida Power & Light Co. 82/08/12 O'REILLY, J.P.
 Region 2, Office of Director in 15777 394 24X
 Fiche 50-389, 82/08/12, 8210270214
- 9210010213 Forwards IE Insp Rept 50-389/82-40 on 820817-20 No nancompliance noted DANCE: H C Division of Project & Resident Programs 82/08/31 UHR10: R E Florida Power & Light Co 2pp 15568 043 24X Fiche 50-389, 82/08/31
- ---B210010216 IE Insp Rept 50-369/82-40 on 820817-20 No noncompliance noted Major areas inspected (instrumentation cable & termination work & work activities, cable & termination GC records & followup on licensee identified items (IERRINEATHER, N., CONLON, T.E. Division of Engineering & Technical Programs 82/08/27 3pp 15568-045 24X Fiche 50-389,82/08/31,8210010213
- B210010155 Forwards IE Insp Rapts 50-335/B2-28 & 50-389/B2-37 on B20809-13 No noncompliance noted DANCE H C Division of Project & Resident Programs B2/09/08 UHRIO:R.E. Florida Power & Light Co 2pg 15565-326 24K Fiche 50-335, B2/09/08 B210010155
- --B210010169 IE Insp Repte 50-335/82-28 & 50-389/82-37 on 820809-13 No noncompliance noted Major areas inspected followup on emergency preparedness appraisal & exercise findings HUFFMAN, O, N., JENKINB, O R Division of Emergency Preparedness & Operational Support 82/09/02 [8pp 15565 328 24X Fichs, 50-335, 82/09/08, 8210010155

- 8210120655 Forwards draft input to systematic assessment of licenses performance for review & comments Comments should be submitted by 820910 for consideration in final rept W/o
- NERSES. V Licensing Branch 3 82/09/09 EISENHUT, D 0 Division of Licensing HATTSON, R L Division of Systems Integration (post 811005) THOMAS. H Division of Human Factors Safety 1p 15572 334 24% Fiche 50-389, 82/09/07,8210120655
- 9210010301 Forwards IE Insp Rept 50-389/82-41 on 820824-27 No noncompliance noted PANCE, H C Division of Project & Resident Programs 82/09/10, UHRIO, R E Florida Power & Light Co 2pp 15568 310 24X Fiche 50-389, 82/09/10, 8210010301
- -82i0010305 IE Insp Rept 50-389/82-41 on 820824-27 No noncompliance noted Major areas inspected safety-related pipe support & restraint sys & seismic analysis for as-built safety-related piping sys YORK, J W . BLAKE, J Division of Engineering & Technical Programs 82/09/09 5pp 15568 312 24X Fiche 50-389,82/09/10,8210010301
- 210150345 Forwards IE Insp Repts 50-335/82-31 & 50-369/82-38 on 820830-0903 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/22 UHR10, R E Florida Power & Light Co 1p 15704 322 24X Fiche. 50-335, 82/09/22, 8210150345
- -B210150358 IE Insp Repts 50-335/82-31 & 50-389/82-38 on B20830-0903 No noncompliance noted Major areas inspected redinative liquid & gaseous effluent releases, reactor coolant chemistry & radioactive transportation activities WRAY.J R. BARR.K P Division of Engineering & Technical Programs \$2/09/17 10pp 15704 323 24% Fiche 50-335,82/09/22, B210150345.
- *10150262 Forwards IE Insp Rept 50-389/82-42 on 620830-0903 No noncompliance noted DANGE.N C Division of Project & Resident Programs 82/09/27 UNR30.R E, Fiorida Power & Light Co 2pp 15703 261 24X Fichs 50-389-82/09/27.8210150262
- 82:0150269 IE Insp Rept 50-389/82-42 on 820830-0903 No noncompliance noted Major areas inspected preoperational test procedure review, test witnessing & test procedure verification & plant tour TAYLOR, P. A. JAPE, F. Division of Engineering & Technical Programs 82/09/23 4pp. 15703 263 24X Fiche, 50-389, 82/09/27, 8210150262
- 10210591 Forwards final NRR input for plant Cycle 3 systematic assessment of licensee performance evaluation, Contributors listed VERSEB.V Licensing Branch 3 82/10/01, EISENHUT, D Q Division of licensing App 15784 318. 24% Fiche 50-389, 82/10/01, 8210210591
- 28170293 IE Info Notice 80-35, Suppl 1. "Leaking & Disindeed I-125 mplant Seeds." Svc list enci 1986. I. Division of Fuel Facilities. Materials & Gafequards 12/10/06 Consolidated Edison Co of New York 66pp 15761 250, 14X Ficha: 50-000, 82/10/06, 8208190293
- Gi90238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-'all, Large-Diameter, Stainless Bteel, Recirculation Bys iping at BWR Plants "Syc list entl EYQUNO, R C. Director's Office, Office of Inspection and nforcement 82/10/14 Consolidated Edison Co of New York 15pp. 15810 125. 24X Fiche 50-000, 82/10/14, 8208190238.
- 0220280 Ack receipt of 820930 Itr informing NRC of steps taken to orrect violations noted in IE Insp Repts 50-335/82-11 k 0-395/82-34
 ANCE,H G. Division of Project & Resident Programs 82/10/15
 4810.R E. Florida Power & Light Co ip. 15775 084 24X iche.50-339,82/10/15,8210220280.
- 210220291 Forwards IE Insp Repts 50-335/82-11 & 80-389/82-34 on 820711-0810 & notice of violation. DANCE, H C. Division of Project & Resident Programs 82/09/01 UHRIG.R.E. Fioride Power & Light Co. 2pp 15775 OB7. 24X Fiche 50-335,82/10/15,8210220280
- *10220303 IE Insp Repts 50-335/82-ii & 50-389/82-34 on 9207ii-D8i0 Noncompliance noted on 820805, Equipment Clearance Order L-8-30 incorrectly identified suction & discharge drain valves V-2317 & V-2329 for charging pump A. ELROD, 8 A , BIBB, H. E. , JULIAN, C A. Division of Project & Resident Programs. 82/08/31. 10pp. 15775:090 24X Fiche: 50-335, 82/10/15, 8210220280.

- 8210260376 Ack receipt of 821013 itr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-335/82-30
 LEWIS,R C Division of Project & Resident Programs 82/10/22 UHRIO,R E Fioriad Power & Light Co ip 19806 138 24X
 Fiche, 50-333, 82/10/22, 8210260376
- ~-8210260510 Forwards JE Safeguards Insp Repts 50-335/82-30 & 50-389/82-41 on 820816-20 & notice of violation Natice of violation trept details withheld (ref 10CFR73 21) LEHIS.R C Division of Project & Resident Programs 82/09/13 UHR10.R E Florida Power & Light Co 2pp 15806 140 24X Fiche 50-335,82/10/22.8210260376
- ~-8210260515 IE Safeguards Insp Rept 50~335/82~30 & 50~389/82~41 on 820816~20 Nancompliance noted failure to comply w/security plan re vehicle control.alarms & compensatory action Details withheld (ref 10CFR73 21)

 600DE, R: STANBBERRY, W: MCGUIRE, D: R: Region 2, Office of Director 82/09/10 2pp 15806 142 24X Fiche 50~335.82/10/22, 8210260376
- R Periodic operating reports & related correspondence
- 8210040072 Forwards joint Ebasco & C-E task force program weekly status summary for 820920-25
 BLODOETT, TH Ebasco Services, Inc (subs of Enserch Corp.)
 82/09/24 EISENHUT.D 9 Division of Licensing App. 15581 272
 24X Fiche 50-389, 82/09/24, 8210040072
- 8210060371 Forwards const/startup progress rept for Aug 1982 Target fuel load date of 821028 still valid URIO.R E Florida Power & Light Co 82/10/01 EIGENHUT.D G Division of Licensing 2pp 15618 328 24% Fiche 50-389,82/10/01,8210040371
- 8210150431 Forwards weekly status summary of joint Ebasco & C-E verification program for 821004-08
 BLODGETT: TH Ebasco Services: Inc (subs of Enserch Corp.)
 B2710708 EISENHUT-ID D Division of Licensing 4pp 15704 015
 24X Fiche 50-389.82/10708.8210150431
- 8210260466 Forwards joint Ebased & G-E task force engineering verification program weekly statum summary for 821011-15 BLODGETT H Ebased Services. Inc (subs of Enserch Corp.) 82/10/15 EISENHUT, D.O. Division of Licensing 4pp 15807 228 24X Fiche 80-389, 82/10/15, 8210260466
- 8210250317 Forwards const/startup monthly progress rept for Sept 1982 UHRIG: R E Florida Power & Light Co 82/10/19 EISENHUT, D O Division of Licensing 2pp 15790 292 24X Fiche 50-389, 82/10/19, 8210250317
- S Reportable occurrences, LERs & related correspondence
- 8210040236 Final deficiency rept re-orderaize fillet walds Initially reported on 820831 Insp program revised & all undersized flange & socket fitting waids will be repaired GC breakdown not responsible for event UHRIO.R E Florida Power & Light Co 82/09/30 O'REILLY, J P Region 2, Office of Director 3pp 15619-357 24X Fiche 50-389,82/09/30.8210060236
- 8210130090 Final deficiency rept re incorrect shaft bearings on diesel generator motors 2A1 & 2A2 Initially reported on 820826 Shaft bearings replaced w/self-aligning bearings. Not reportable per 10CFR80 55s.but reportable per Part 21 UHRIGHR & Florida Power & Light Co 82/10/01 0'REILLY, J P Region 2, Office of Director. 2pp 15673 119 24X Fiche 50-389, 82/10/01.8210130090
- B210130536 Interim deficiency rept re fan belts on diesel generators 2A & 28 Initially reported on 820210 Final rept will be submitted by 821130 UHRIG,R E Florida Power & Light Co B2/10/01 O'REILLY, J P. Region 2, Office of Director Ip 15682 193, 24X Fiche, 50-387, 82/10/01.8210130536
- 8210220167 Interim deficiency rept re failure of reactor shutdown cooling bypass valves to respond to command signals Initially reported on 820430 Util still reviewing problem Final rept will be submitted by 821030.

 UMRIO,R E Florida Fower & Light Co 82/10/06. O'REILLY, J. P. Rept on 2, Office of Director ip 15776 362. 24X Fiche 50-389, 82/10/06,8210220167

DOCKETED HEIMS

DOCKET 50-390 WATTS BAR NUCLEAR PLANT. UNIT 1

- A Applacation/construction stage documents & correspondence
- 210D1CO38 Responds to FDIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed an App A
 FELTON.J H Division of Rules and Records 82/06/28 UDELL.R A
 Critical Mass Energy Project 15pp 15727 005 24x
 Fishe 50-000, 82/06/28, 8210010008
- -8008050265 Discusses addit required info to better define potential for cracking in reactor vessel notiles.
 NODNAN.V S. Assistant Director for Materials & Qualifications
 Engineering 80/05/05 TEDESCO.R L. Assistant Director for
 Licensing 2pp 15727 176 24X Fiche 50-000, 82/06/28, 8210010008
- 210180331 Forwards evaluation of Apr 1982 site audit of safety-related electric & mechanical equipment Resolution of specific concerns in single submittal requisted NDVAK.T M. Assistant Director for Licensing 82/09/23 PARRIS.H O Tennessee Valley Authority 39pp 15746 282 24X Fiche 30-390, 82/09/23.8210180331
- 110170084 Summary of 820717 meeting w/util & Black & Veatch in Bethesda.MD re applicant plans to perform independent design verification of auxiliary feedwater sys Attendance list & viewgraphs enci KENYON.T J Operating Reactors Branch 4 82/10/01 Operating Reactors Tranch 4 13pp 15761 102 24X Fithe 50-370,82/10/01.
- :1028020B Forwards revised FSAR Section 17 2.consisting of Table 17 2-1.1sting critical structures sys & components Info will be included in Anend 48 to FSAR MILLS.L M Tennessee Valley Authority 82/10/25 ADENSAM.E Licensing Branch 4 14pp 15839 293 24X Fiche 50-390,82/10/25, 8210280308

NRC Safety Evaluation Report (SER), suppls & correspondence

- 10050405 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE WATTS BAR NUCLEAR PLANT, UNITS: AND 2 Docket Nos 50-390 And 50-391 (Tennessee Valley Authority) # Office of Nuclear Reactor Regulation, Director NUREG-0847 801 82/09/30 29pp Available at NRC 44 50 15625 299 24X Fiche 50-390.82/09/30.8210050405
- Security, medical, emergency & fire protection plans
- 10220225 Requests NRC perform preliminary review of util program for watchtower power block security concept Meetings suggested for 821102-03 as part of review Agenda encl HLLS.L M Tennessee Valley Authority 82/10/18 EISENHUT, D C 31v1sion of Licensing 2pp 15776 226 24% Fiche 50-390,82/10/18, R210220225

- Q inspection reports. IE Bulletins & correspondence
- B210080015 Add1 response to FOIA request for 19 categories of infoie nuclear reactor events 5 safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON.J M Division of Rules and Records B2/0//12 UDFil.H A Critical Mass Energy Project 9pp t5665 027 24x
 Fiche 50-000, 82/07/12, 8210080015
- --B210080167 Systematic assessment of licensee performance nates to racility evaluation for Aug 1979-Jul 1980 4 MRC - No Detailed Affiliation Given 00/07/31 App 15868 101 24X Fishe 50-000, 02/07/12, 0210080015
- 821022023 Bubmits addi into to 820324 response to 1E Imsp Rept 50-390/82-03 Revision of FSAR Table 14 2-1 & Chapter 9 will not be complete until 821015 MILLS.L M Tennessee Valley Authority 82/08/11 O'REILLY, J P Region 2, Office of Director 1p 15774 210 24X Fiche 50-390,82/08/11,8210220223
- 5210010452 Forwards IE insp Repts 50-390/82-31 & 50-391/82-28 on 620824-27 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 62/09/09 PARRIS.H & Tennessee Valley Authority 2pp 15572 305 24x Fiche 50-390, 82/09/09, 8210010452
- --8210010462 IE Insp Repts 50-390/82 II & 50-391/82-261 un H20024-27
 No noncompliance noted Major areas inspected
 instrumentation, installation & nonconforming lepts &
 conceptual design requirements
 HUNTIN D. CONLONIT E Division of Engineering & Technical
 Programs 62/09/07 4pp 155/2 J07 24X Fiche 50 390.62/09/09
 8210010432
- 8210150304 Forwards IE Insp Repts 90-340/02-32 & 50-341/02-29 on 820824-27 No noncomptiance noted VERRELLI.D M Division of Project & Resident Programs 02/04/10 PARRIS.H 0 Tennessee Valley Authority 2pp 15707-295 24x Fiche 50-370, 92/04/10, 02(0150304
- --B210150315 IE Insp Repts 90-370/H2-32 & 50-391/H2-29 on H208,14 P/ No noncompliance noted Major areas inspected engineering design work MCFARLAND.C R . DLBDAGE.A O . UPRIGHT.C M Division of Project & Resident Programs 82/09/10 5pp 15707 297 P4X Fichs 50-390,82/09/10.8210180304
- 8210150323 Forwards IE Insp Repts 50-390/02-30 & 50-391/82-27 on 820721-0820 No noncompliance noted WERRELLI, D M Division of Project & Rosident Programs 02/04/16 PARRIS, H 0 Tennessee Valley Authority 2pp 15/21 270 24X Fiche 50-390, 82/09/16, 8210150323
- --B210150331 IE Insp Repts 50-390/02-30 & 50 391/BR -27 on 820721-0020 k noncompliance noted Major areas inspected literases action on previous insp findings & review of periodic & special repts HEATHERLY, T. L., QUICK, D.R. Division of Project & Resident Programs 82/09/16 5pp 19721 272 24X Fiche 50-390,02/09/t6,8210150323
- 9210010333 Act receipt of 820826 itr informing NRC of steps taken to correct violations noted in IC lasp Repts 50-390/81-03 & 50-391/81-03 & VERRELLI.B M Division of Project & Resident Programs 82/09/17 PARRIE.H 9 Tennessee Valley Authority 1p 15568 238 24X Fiche 50-390, 82/09/17,8210010333
- --B210010341 Suppls response to NRC B20414 ltr re violations noted in IE Insp Repts 50-370/B1-03 & 90-371/B1-03 Corrective actions leak integrity of body bonnet joint verified prior to startup & component tolerance wiil be confirmed MILLS.L H Tennessee Vallen Authority 82/09/24 Corrective 10

1

١.

١.

- 3210220315 Forwards IE Insp Repts 50-390/62-34 & 50-391/82-31 on 820914-17 No noncompliance noted VERRELLI D M Division of Project & Resident Programs 82/09/30 PARRIS, N G Tennessee Volley Authority 2pp 15776 036 24X Fiche 50-390,82/09/30,8210220315
- -82[0220323 IE In-sp Repts 50-390/82-34 & 50-391/82-31 on 820914-17 No noncompliance noted Major areas inspected instrumentation cable / termination. Observation of work work activities, review of quality records & licensee identified items RUFF.A B . CONLON. T E Division of Engineering & Technical Programs 82/09/29 3pp 15776 040 24% Fiche 50-390.82/09/30, 8210220315
- F10150207 Ack receipt of 820825 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-18 & 50-391/82-15 Add1 info requested by 820923 telcon VERKELLI.D M Division of Project & Resident Programs 82/10/04 PARKIS.H G Tennessee Valley Authority ip 15706-083 24X Fiche 50-390, 82/10/04,8210150209
- 8210150230 Responds to NRC 650707 ltr re violations noted in IF Insp Repts 50-390/82-18 & 50 J91/82-15 Corrective actions personnel instructed in application of EP 1 26 to limited GA sys MILLS.L M Tennessee Valley Authority 62/09/24 0'REILLY, J P Region 2. Office of Director 4pp 15706 084 24X Fiche 50-390, 82/10/04, 8210150209
- 8210150241 Responds to NRC B20702 ltr re violations noted in IE insp Repts 50-390/82-10 & 50 391/82-15 Corrective actions program to instruct all personnel in all procedures affecting design work implemented MILS.L M Tennessee Valley Authority B2/08/25 O'REILLY.J P Region 2. Office of Director 30p 15706 088 24X Fiche 50-390.82/10/04/8210150309
- E2[6:90251 Responds to NRC #20707 lr; re violations noted in it Insp. Repts 50-390/82-15 to 391/82-15 Corrective actions EP 1 28. "Control of Documents Affecting Quality," will require independent verification of procurement specs. MILLS,L N. Temposae Valley Authority 82/08/20 0'REILLY, J.P. Region 2. Office of Director 3pp 15706 091 24% Fiche 50-390.82/10/04.85/0150209
- 62:0150260 Discusses IE Insp Repts 50-370/82-18 & 60-391/82-15 on (2042) -0520 & forwards corrected App A (notice of riolation) LEMIS.R C Division of Project & Resident Programs 82/07/07 PARMIS.H 0 Tennesses Valley Authority 2pp 15706 094 24X Fiche 50-390.62710/04 02/0150209
- .10150268 Corrected notice of violation from insp on 820421-0820 Noncompliance noted nonconforming condition rept not initiated for recagnized diesel generator tube oil deficiencies

 Region 2, Office of Director 82/07/07 2pp 15706 096 24x Fiche 50-390.82/10/04.8210150209
- *210150278 Forwards IE Insp Repts 50-390/82-16 & 50-391/82-15 on 620421-0520 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/06/08 PARRIS.H G Tennesses Valley Authority 2pp 15706 098 24X Fight 50-390.82/10/04.8210150209
- 210150205 Notice of violation from insp on 820421-0520 * Region 2 Office of Director 82/05/08 2pp 15705 100 24x Fichs 50-390.827/10/48.8210150207
- 2101503D3 IE Insp Repts 50-990/82-18 t 50-391/82-15 on 820421-0520 Moncompliance noted failure to design for environ effects, follow corrective action procedures & conduct adequate addits MCDDNALD, J A , HEATHERLY, T L , QUICK, D R Division of Project & Resident Programs 82/06/08 App 15706 102 24X Fiche 50-390,82/10/04.8210150209
- 8190233 1£ Info Notice 80-35. Suppl 1: "Leaking & Dislodged 1-125 tplant Seeds " Svc list enci

 DB.L I Division of Fuel Facilities. Materials & Bafeguards

 2/10/06 Consolidated Edison Co of New York 66pp 15761 250

 4x Fiche 50-000.82/10/06.8208190233
-)150349 Forwards Pages 5 & 6 to 1E Insp Repts 50-390/82-32 & >-391/62-29 inadvertently omitted from 820910 transmittal IRRELLI.D M Division of Project & Resident Programs 82/10/07 MRIS.H G Tennessee Valley Authority 2pp 15704,318, 24% Iche 50-390,82/10/07.8210150349
- 10150355 Pages 5 & 6 to IE lnsp Repts 50-390/82-32 & 50-391/82-29 inadvertently omitted from B20910 transmittal * Region 2. Office of Director B2/10/07 2pp I5704 320 24X Fiche 50-390,82/10/07,8210150349

- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter:Stainless Steel:Recirculation Sys Piping at BWR Plants " Svc List encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 8210220459 Ack receipt of 820715 itr informing NRC of steps taken to correct violations noted in JE Insp Repts 50-390/81-26 & 90-391/81-24 NERRELLI.D M Division of Project & Resident Programs 82/10/18 PARKIS.H G Fennessee Valley Authority ip 15779 133 24X Fiche 50-390.82/10/18.8210220459
- 8210220466 Advises that corrective actions per violations noted in IE finep Repte 50-390/81-26 & 50-391/81-24 will be completed by 821103
 MillS.L M Tennessee Valley Authority 82/09/15 G'REILLY, J P Region 2, Office of Director 1p 15779 134 24X
 Fiche 50-390,82/10/18.8210220459
- 8210220472 Ack receipt of 820924 ltr informing NRC of steps taken to correct violations noted in IE Insp Ropts 50-390/82-18 & 50-391/82-15 VERRELLID M Division of Project & Resident Programs 82/10/18 PARRIS.H 0 Tennesse Valley Authority 1p 15779 102 24X Fiche 50-390.82/10/18.821022047
- S Reportable occurrences, LERs & related correspondence
- 8210080168 Sixth interim deficiency rept re qualification of epoxy grout for safety-related applications Initially reported on 820827 Support mods or add1 supports recommended Drawing revisions in progress Completion expected by mid-May 1783 MILLS,L M Tennesses Valley Authority 82/09/23 0'REILLY, J P Region 2. Office of Director 3pg 15640 154 24X Fiche 50-390.82/09/23,8210080168
- 8210050314 First interim deficiency rept re incorrect insulation weights used in piping analysis initially reported on 820825 QA document being prepared to substantiate insulation data Next rept will be submitted by 830423 MILLS.L M Tennesses Valley Authority 82/09/24 O'REILLY, J P Region 2, Office of Director 2pp 15610 281 24X Fiche 50-390.82/09/24.8210050316
- 8210090247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns initially reported on 811228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MICLS, L M Tennessee Valley Authority 82/07/24 0'REILLY, J P Region 2, Office of Director 3pp 15639, 104 24X Fiche 50-000, 82/07/24, 8210080247
- 0210050062 First interim deficiency rept re failure to consider seismic & inertial loadings on ladders Initially reported on 620626 Ladder, platform or walkway found deficient will be modified or stiffened Next rept expected by 630124 MILLS,L M Tennessee Valley Authority 62/09/27 0'REILLY,J P Region 2. Office of Director 2pp 15603 236 24X Fiche 50-390, 62/09/27, 8210050042
- 8210050099 Second interim deficiency rept re potential for setpoint program for overpressure mitigating sys to exceed IOCFR50. App 0 requirements Initially reported on 820521 Vtil procuring solenoid-actuated valves Next rept by 820331 MILCS.L M Tennessee Valley Authority 82/09/27 O'REILLY, J P Region 2. Office of Director 2 pp 15603 242 24X Fiche 50-390, 82/09/27,8210050099
- 8210050114 Add1 info to final deficiency rept re seismic supports for auriliary feedwater control valves initially reported on 600624 Corrective actions on Unit 1 completed 820831 Unit 2 valves will be installed during normal const schedule MfLLS.L. M Tennessee Valley Authority 82/09/27 0'REILLY, J P Region 2. Office of Director ip 15603 256 24% Fiche 50-390,82/09/27,8210050114
- 8210030293 First interim deficiency rept re six sheared motor pinion keys in Limitorque Model SB-0-25 motor operators Initially reported on 820830 Valves w/motor operators being tabulated. Next rept will be submitted by 821122 MILLS.L M Tennessee Valley Authority 82/09/28 0'REILLY.J P Region 2, Office of Director 2pp 15609 070 24X Fiche 50-000.82/09/28,8210050293
- 8210030158 Second interim rept re undocumented minor mods to structural & miscellaneous steel Initially reported on 820510 Approx 95% of 250 features had preliminary insp/punchlist completed Next rept to be submitted by 830228 MILLS.L M Tennesses Valley Authorsty, 82/09/29 O'REILLY, J P Region 2, Office of Director 2pp 15605:134 24% Fiche 50-390,82/09/29,8210050158

- 8210050280 First inters deficiency rept resolid-state protection systest procedures Initially reported on 820831 Util reviewing Westinghouse proposal for Interimprocedural change which would provide for failure detection Next rept by 821210 HILLS, L.M. Tennessee Valley Authority 62/09/29 0'REILLY, J.P. Regson 2. Office of Director 2pp 15621 164 24X Fiche 50-370, 82/09/29, 8210060280
- 8210060205 Fourth interim deficiency rept re inadequate loading criteria for structural steel & supports Initially reported an 811117 General notes revised to clarify drawings Field mapping of platform steel contanting Next rept by 800310 MillEL M Tennessee Valley Authority 82/09/30 0'REILLY, J P Region 2, Office of Director 2pp 15614 041 24X Fiche 50-390, 82/09/30, 8210060205
- 8210060279 First interim deficiency rept re selection of undersized away struts Initially reported on 820901 Selection methods & adequacy of Sergen-Paterson struts under evaluation Next rept expected by 830225 MILLS.L M Tennessee Valley Authority 82/09/30 0'REILLY, J P Region 2, Office of Director 2pp 15621 166 24X Fiche 50-390, 82/09/30, 82/0060279
- 8210090255 First interim deficiency rept re inadequate QA program for masonry block work (Instially reported on 820902 Const personnel investigating & replying to audit Next rept due on 821214
 MILLS.L M Tennessee Valley Authority 82/10/01 Q'REILLY, J P Region 2, Office of Director 2pp 15638 116 24X
 Ficks 50-390,82/10/01.8210080255
- 8210050260 First interim deficiency rept re interpretation of radiograph test film on wolded pipe by Swepco Tube Corp Initially reported on 820901 Evaluation continuing Next rept will be submitted on 830217 MILLS.L K Tennesse Valley Authority 82/10/01 G'REILLY, J P Region 2. Office of Director 2pp 15638 201 24% Fiche 50-370, 82/10/01.8210080280
- 8210080291 First interin deficiency rept re failure to terminate cables IPS111. IPS112. (PM1850. IPM1852, IPM1857. IPS152 & IPS153 InItially reported on 820901 Cables terminated & personnel retrained Next rept will be submitted by 821123 MILLS.L N Tennessee Valley Authority 82/10/01 O'REILLY. J P Region 2. Office of Director 20p 15638 308 24X Fache 50-390. 82/10/01. 8210080291
- 8210080160 First interim deficiency rept re corrosion in high pressure fire protection sys Initially reported on 820903 Corrosion analysis in progress to determine potential deficiencies in safety-related areas Next rept expected by 830531 MILLS.L.M. Tennessee Valley Authority 82/10/04 0'REILLY, J.P. Region 2. Office of Director 2pp 15640 142 24x Fiche 50-000. 82/10/04.8210080160
- 82:0080310 First interim deficiency rept rellack of piping sys analysis tracking Initially reported on 820902 Util investigating corrective actions to answer engineering change notices are not closed out until work is completed HILLSIL M Tennesses Valley Authority 82/10/04 D'REILLY, J P Region 2, Office of Director 2pp 15638 042 24X Fiche 50-390.62/10/04.8210080310
- 8210130247 Sixth interim deficiency rept re differential settlement of rock supported structures Initially reported on 810707 Individual safety-related components at interferes of structures being svaluated. Next rept by 830304 MILLS.L. H. Tennesser Valley Authority 82/10/05 D'REILLY, J.P. Region 2. Office of Director ip 15675 009. 24x Fiche 50-390, 82/10/05, 8210130247
- 8210130384 Suppl to final deficiency rept re essential raw cooling water seismic support Initially reported on 810504 Completion of Bergen-Patterson review expected by 821101 Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 82/10/05 O'REILLY, J P Region 2, Dffice of Director ip 1568:003 24X Fiche 50-390, 82/10/05.8210130384
- 82:0130560 Second interim deficiency rept re frequency criteria for piping supports. Initially reported on 820713 Investigation continuing Next rept expected by 82:1220, MILLS.L.M. Tennesses Valley Authority 82/10/05 0'REILLY, J.P. Region 2. Office of Director. 1p 15683-299 244

- 821022009B First interim deficiency rept re qualification of process piping w/instrument lines attached Initially reported on 820909 Affected piping being reanalyzed to account for effect on instrument line piping Next rept by 830429 MILLS.L H Tennessee Valley Authority 82/10/08 0'REILLY, J.P. Regjon 2. Office of Director 2pp 15777 362 24X Fiche 50-390.82/10/08.8210220098
- 8210190307 Final deficiency rept re failure to meet pipe support luq criteria initially reported on 820607 Lug parameter limit discrepancy corrected MILLS, L.M. Tennessee Valley Authority 82/10/12 O'REILLY, J.P. Region 2. Office of Director 2pp 15742 155 24X Fiche 50-390.82/10/12.8210170307
- 8210290328 Second interim deficiency rept re use of nonconservative calculational method to evaluate General Const Spec 0-32 spacing violations initially reported on 820528 Next rept uill be sent by 830528 MHLLS.L H Tennessee Valley Authority 82/10/12 O'REILLY, J P Region 2, Office of Director 2pp 15853 044 24X Fisch 50-000-82/10/12, 8210290328
- 9210190337 First Interim Deficiency Rept 50-390/82-100 re as-built & as-analyzed configuration discrepancies Initially reported on 820910 Response to IE Bulletin 79-14 will be carried out in two phases insp & review of findings Next rept by 830325 MILLS.C.M Tennessee Vailey Authority 82/10/13 G'REILLY.J.P. Region 2. Office of Director 2pp 15742 102 24X Fiche 50-390.82/10/13.8210190357
- 8210290236 Third inter(m deficiency rept re potentially overstrossed embedded plates initially reported on 820412 Investigation continuing & const activities deferred until sufficient infogathered to determine completion of project ATLLS/L M Tennessee Valley Authority 82/10/14 O'RE[LLY, J P Region 2, Office of Director 2pp 15853 229 24X Fiche 50-000:82/10/14,8210290236
- 8210290052 Second Interim deficiency rept re use of incorrect response spectra in Gilbert/Commonwealth piping analysis Initially reported on 820426 Reanalysis continuing Next rept expected by 820422 Also reportable per Part 21 MILLS: L M Tennessee Valley Authority 82/01/15 O'REILLY, J P Region 2. Office of Director ip 15853 334 24X Fiche 50-390:82/10/15,8210290052
- 8210290178 Sixth interim deficiency rept re rerouting of high pressure fire protection piping initially reported on 8/0130 Three areas may contain worst case condition No deficiencies identified in two areas Next rept provided by 82:210 MILLS.L.H. Tennessee Valley Authority 82/10/15 0'REILLY.J.P. Region 2. Office of Director [p. 15853 311 24X Fachs 50-390, 82/10/15, 8210290178
- 8210260320 First interim deficiency rept re addition of locking devices to handwheel operated valves Initially reported on 820916 Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820310 MILLS, L.M. Tennessee Valley Authority 82/10/18 0'REILLY, J.P. Region 2. Office of Director 2pp [5602 359 24% Fiche 50-000.82/10/18.8210260320
- 8210260451 Fourth interim deficiency rept re failure to include documented piping insulation insps in GC program Institutly reported on 811009 Const Specs N30-881 & N3C-912 revised to provide scope of insp requirements Next rept by 830425 MILLS,L H Tennesse Valley Authority 82/10/18 0 (REILLY, J P Region 2, Office of Director 2pp 15807 104 24X Fiche 50-390,82/10/18,8210260451
- 8210240186 Second interim deficiency rept re underdesign of essential raw cooling water intake pumping station doors & hatches Initially reported on 820407 Fiethead screws added to door frame for reinforcement Next rept expected by 830331 MILLS,L M Tennesses Valley Authority 82/10/19 D'REILLY, J P Region 2, Dffice of Director Zpp 15799 034 24X Fiche 50-390, 82/10/19, 8210240186
- 8210260370 Eighth interim deficiency rept re improper classification of essential raw cooling water sys piping & components initially reported on Bl03242 investigation ongoing Next rept will be submitted by B30427 MILLS.L H Tennessee Valley Authority 82/10/19 D'REILLY.J P Region 2, Office of Director ip i5803 104 24X Fichs 30-390.82/10/19.8210260390
- B210260100 Second interim deficiency rept re lack of seismic analysis on auxiliary bldg platform Initially reported on B20426 Documentation for all attachments to suspect platforms being investigated Next rept expected by B30217 MILLS,L M. Tennessee Valley Authority B2/10/20. O'REILLY, J P Region 2. Office of Director 2pp 15799 122. 24X Fiche 50-390, B2/10/20, B210260100

0260408 Second interim deficiency rept re potentially deficient alve yoke holddown nut Initially reported on 820601 Util waiting Hestinghouse resolution for NSSS valves Also eportable per Part 21

Waiting Hestinghouse resolution for Mada valves Kisu eportable per Part 21 HLLS.L M Tennessee Vailey Authority 82/10/20 O'REILLY. J P egian 2 Office of Director 2pp 15803 109 24X 1che 50-390.82/10/20.8210260408

0290266 Fourth interim deficiency rept re failure of Limitorque star operators during valve closure initially reported on 20126 Mestanghouse. Limitorque 3 util investigating problem strept expected an 830128 Part 21 considered applicable ILLS.L.M. Tennessee Valley Authority 82/10/21 0'REILLY, J.P. 3190. 2. Office of Director ip 15854 046 24X iche 50-390. 82/10/21, 8210290266

1290274 Final rept for Deficiencies B & E & seventh interim rupt for ificiencies A & D re control of procurement activities intially reported on 810316 Final corrective actions noted it rept expected by 830428 LLS.L M Tennessee Valley Authority 82/10/21 O'REILLY, J P gion 2, Office of Director 4pp 15853 143 24% che 50-000.82/10/21.8210270274

ET 50-391 WATTS BAR NUCLEAR PLANT. UNIT 2

pplication/construction stage documents & correspondence

DIGOOB Responds to FDIA request for 19 categories of documents reclear reactor events & safety problems Forwards documents sted in App A TRIN, J M DIVISION of Rules and Records 82/04/28 UDELL, R A LICAL Mass Energy Project 15pp 15727 005 24X he 50-000, 82/04/28, 8210010008

18050265 Discusses add1 required info to better define potential for racking in reactor vessel notiles RODAN, V S Assistant Director for Materials & Qualifications ngineering 80/05/05 TEDESCO.R L Assistant Director for icensing 2pp 15727 176 24X Fiche 50-000.82/06/28.8210010008

90084 Summary of 820917 meeting w/util & Black & Veatch in hesda MD re applicant plans to perform independent design iffication of auxiliary readwater sys Attendance list & wgraphs encl
YON T J Operating Reactors Branch 4 82/10/01 Operating ctors Branch 4 13pp 1576/102 24X Fiche 50~390,82/10/01.0190084

30208 Forwards revised FSAR Section 17 2.consisting of Table 2-1, listing critical structures, sys & components Info 1 be included in Amend 48 to FSAR .S.L M Tennessee Valley Authority 82/10/25 ADENSAM. E Insing Branch 4 14pp 15839 293 24X Fiche 50-390, 82/10/25. X202026

: Safety Evaluation Report (SER), supple & correspondence

0405 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE 5 BAR NUCLEAR PLANT.UNITS 1 AND 2 Docket Nos 50-390 And 191 (Tennesses Valley Authority)

IFfice of Nuclear Reactor Regulation. Director NUREO-0847 801 9/30 29p Available at NRC \$4 50 15625 299 24X 8 50-390, 62/09/30, 8210050405

urity, medical, emergency & fire protection plans

0225 Requests NRC perform preliminary review of util program for htower power black security concept Meetings suggested 821102-03 as part of review Agenda encl 8.L M Tennessee Valley Authority 82/10/18 EISENHUT, D 0 sion of Licensing 2pp 15776 226 24% Fiche 50-390.82/10/18, 220225

0174 Forwards revised security plansincluding updated table of ints & revised Page A-5 Revision withheld (ref 173 21) 3.L M Tennessee Valley Authority 62/10/20 ADENSAM. Esting Branch 4 lp 15797 048 24X Fiche 50-390, 62/10/20, 760174

187 Confirms that evacuation time estimate study reviewed by iocal & TN state authorities Population density & ibution info provided by TN Dept of Civil Defense based '80 census' L M Tennessee Valley Authority 82/10/20 ADENBAME 0 sing Branch 4 2pp 15779 030 24X Fiche 80-000, 82/10/20,

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8208290018 Summarizes 268th ACRS meeting on 820812-14 in Washington, DC re full power CLs for Grand Guif 1 & Watts Bar I & II, systematic evaluation & integrated reliability assessment of Oinna & Control room habitability
 SHENMON, P ACRS Advisory Committee on Reactor Safeguards
 8208706 PALLADINO, N J Commissioners 3pp 15649 233 24X
 Fiche 50-000.82/08/26.8208270018
- Q Inspection reports. IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000.82/07/12.8210080015
- --82100B0167 Bystematic assessment of licensee performance notes refacility evaluation for Aug 1979-Jul 1980

 + NRC No Detailed Affiliation Given 80/07/31 App
 15668 101 24% Fiche 50-000, 82/07/12, 8210080015
- 8210010452 Forwards IE Insp Repts 50-390/82-31 & 50-391/82-28 an 820824-27 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/09/04 PARRIG.H Q Tennessee Valley Authority 2pp 15572 305 24X Fiche 50-390.82/09/09.8210010482
- --8210010462 IE Insp Repts 50-390/82-31 & 50-391/82-28 on 820824-27
 No noncompliance noted Major areas inspected instrumentation, installation & nonconforming repts & conceptual design requirements HUNT.M D . CONLON.T & Division of Engineering & Technical Programs 82/09/07 4ap 15572 307 24X Fiche 50-390,82/09/08210010452
- 8210150304 Forwards IE Insp Repts 50-390/62-32 & 50-391/62-29 on 820824-27 No noncompliance noted VERRELLIID M Division of Project & Resident Programs 62/09/10 PARIS. H 0 Tennesses Valley Authority 2pp 15707 295 24X Fiche 50-390. 82/09/10, 8210150304
- --8210150315 IE Insp Repts 50-390/82-32 & 50-391/82-29 on 820824-27 noncompliance noted Major areas inspected engineering design work MCFARLAND, C R. DEBBAOS, A O . UPRIGHT, C M Division of Project Resident Programs 82/09/10 5pp 18707 297 24X Fichs 50-390,82/09/10,8210150304
- 8210190323 Forwards 1E Insp Repts 50-390/82-30 & 50-391/82-27 on 820721-0820 No noncompliance neted VERRELLI, D M Division of Project & Resident Programs 82/09/16 PARRIS, H O Tennessee Valley Authority 2pp 15721 270 24X Fichs 50-390, 82/09/16, 8210150323
- --82j0150331 IE Insp Repts 50-390/82-30 & 50-391/82-27 on 620721-0BE noncompliance noted Major areas inspected licensee action on previous insp findings & review of periodic & special repts HEATHERLY, T L , QUICK, D R Division of Project & Resident Programs 62/09/16 5pp 15721 272 24X Fiche 50-390,82/09/18210150323
- 8210010333 Ack receipt of 820826 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/81-03 t 50-391/81-03.

 VERRELLI.D H Division of Project & Resident Programs 82/09/17 PARRIS, H O Tennessee Valley Authority 1p 15368 238 24% Fiche 50-390, 82/09/17.8210010333
- --8210010341 Suppls response to NRC 820414 1tr re violations noted in IE Insp Repts 50-390/81-03 & 50-391/81-03 Corrective actions: leak integrity of body connet joint verified prior to startup & component tolerance will be confirmed HILLS, L. H. Tennessee Valley Authority 82/08/26 O'MEILLY, J. F. Region 2. Office of Director 3pp 15568-239 24X Fiche 50-390,82/09/17.6210010333
- 8210150024 Forwards Page 4 of IE Insp Repts 50-390/82-32 & 50-391/82 on 820824-27; omitted from 820910 submittal due to administrative oversight W/o encl VERRELLI.D M. Division of Project & Resident Programs 82/09/28, PARIS,H O Tennessee Valley Authority 2pp 18696 337 24X Fithe, 50-390, 82/09/28, 8210150026
- 8210050344 Forwards response to Questions G121 20 & G121 22 per 920: request for info re preservice insp program MILLS, L. M. Tennesses Valley Authority, 82/09/29, ADENBAN, E Licensing Branch 4 4pp. 15610 121 24X Fiche 50-390, 82/09/29, 8210050344.

- --8210220323 IE Insp Repts 50-390/82-34 & 50-391/82-31 on 820914-17 No noncompliance noted Major areas inspected instrumentation cable & termination observation of work, work activities, review of quality records & licensee identified items RUFF.A B . CONLON.T E Division of Engineering & Technical Programs 82/09/29 3pp 15776 040 24X Fichs 50-390.82/09/30, 8210220315
- 8210150209 Ack receipt of 820825 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-390/82-18 & 50-391/82-15 Add info requested by 820923 tolcon VERRELLI.D M Division of Project & Resident Programs 82/10/04 PARRIS.H G Tennessee Valley Authority Ip 15705 083 24X Fiche 30-390, 82/10/04 8210150209.
- --8210150230 Responds to NRC 820707 Itr re violations noted in IE Insp. Repts 50-370/B2-18 & 50-391/82-15 Corrective actions personnel instructed in application of EP 1 26 to limited OA sys MILLS.L M Tennesace Valley Authority 82/09/24 O'REILLY, J.P. Repion 2. Office of Director 4pp 15706 084 24% Fichs 50-390, 82/10/04, 8210150209
- --B210150241 Responds to NRC B20702 ltr re violations noted in 1E Insp. Repts 50-370/82-18 & 50-371/82-15 Corrective actions program to instruct all personnel in all procedures affecting design work implemented HILLS.L.M. Tennessee Valley Authority 82/08/25 O'REILLY.J.P. Region 2. Office of Director Jpp 15706 088 24X Fishs 50-370, 82/10/04, 82/050209.
- --8210150251 Responds to NRC 820707 itr re violations noted in TE Insp Repts 50-390/82-18 & 50-391/82-15 Corrective actions EP 1 28. "Control of Documents Affecting Quality," will require independent verification of procurement specs HILLB.L H Tennessee Valley Authority 82/08/20 (1/REILLY, J P Region 2. Office of Director 3pp 15706 091 24X Fishe 50-390, 82/10/04/8210150209
- --8210150240 Discusses IE Insp Repts 50-390/82-18 & 50-391/82-15 on 820421-0520 & forwards corrected App A (notice of violation)

 LEMIS.R C Division of Project & Resident Programs 82/07/07 PARRIS.H G Tennessee Valley Authority 2pp 15706 094 24X Fiche 50-390, 82/10/04, 8210150209
- --8210150268 Corrected notice of violation from insp on 820421-0520 Noncompliance noted nonconforming condition rept not initiated for recognized diesel generator tube oil deficiencies

 * Region 2. Office of Director. 82/07/07 2pg 15704 096 24x Fiche 50-390, 82/10/04, 8210150209
- --8210150278 Forwards IE Insp Repts 50-390/82-18 & 50-391/82-15 on 820421-0520 & notice of violation LEWIS.R C Division of Project & Resident Programs 82/06/08 PARRIS.H O Tennesce Vailey Authority 2pp 15706 098 24X Fiche 50-390,82/10/04,8210150209
- --8210150285 Notice of violation from insp on 820421-0520, 4 Region 2, Office of Director 82/05/08 2pp 15706 100 24% Fiche 50-390, 82/10/04,8210150209
- --8210150303 1E Insp Repts 50-390/82-18 & 50-391/82-15 on 820421-0520 Noncompliance noted failure to design for environ effects, follow corrective action procedures & conduct adequate audits

 MCDONALD. J. A., HEATHERLY, T. L., QUICK, D. R. Division of Project & Resident Programs 82/06/08 bp 15706 102 24X

 70:0150209

70/82-32 & ...mittal mm 82/10/07 4 318 24X

50-391/82-29 .5704:320 24X

- 8208190238 IE Guiletin B2-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Syc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 92/10/14, 8208190238
- B210220459 Ack receipt of B20915 ltr infolming NRC of steps taken to correct violations noted in IE Insp Repts 50-390/81-26 & 50-391/81-24 VERRELLI.D M Division of Project & Resident Programs B2/10/10 PARRIS.H 0 Tennessee Valley Auchority in 15779 133 24X Fiche 50-390.82/10/18.82/0220459
- --8210220466 Advises that corrective actions per violations noted in & Insp Repts 50-390/861-26 & 50-391/81-24 will be completed by 821032
 HILLS.L H Tennessee Valley Authority 82/09/15 O'REILLY, J.P. Region 2, Office of Director in 15779 134 24x
 Fiche 50-390.82/10/18.0210220459
- 8210220472 Act receipt of 820924 itr Informing NRC of steps taten to correct violations noted in IE Insp Repts 50-390/82-18 & 50-391/82-15 VERRECLLID M Division of Project & Resident Programs 82/10/16 PARRISIN G Tennessee Valley Authority 1p 15779 102 24X Fiche 50-390, 82/10/16.8210220472
- S Reportable occurrences, iERs & related correspondence
- 821008016B Sixth interim deficiency tept re qualification of epoxy grout for safety-related applications initially reported on 820827 Support mods or addi supports recommended Drawing revisions in progress Completion expected by mid-May 1983 MILLS, L M Tennessee Vailey Authority 08/07/23 0'REILLY, J P Region 2. Office of Director 19p 15440 154 24x Fiche 50-170, B2/07/23, 8210080160
- 8210050316 First interim deficiency rept re incorrect insulation weights used in piping analysis Initially reported on 820825 OA document being prepared to substantiate insulation deta Next rept will be submitted by 830423 HILLS.L M Tennessee Valley Authority 82/07/24 O'REILLY, J P Region 2. Office of Director 2pp 15610 201 24x Fiche 50-390,82/07/24,8210050316
- G210080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on B1228 Program developed to insure piping sys aperate within design parameters Next rept provided by 921217 HILLS.L M Tennessee Valley Authority B2/07/24 O'REILLY.Jp Region 2. Office of Director 3pp 15638 104 24x Fiche 50-000:08/09/24.8210080247
- 8210050042 First interim deficiency rept re failure to consider seisaic & inertial loadings on ladders Initially reported on 920824 Ladder-platform or walkway found deficient will be modified or stiffened Next rept expected by 830124 HILLS.L M Tennessee Valley Authority 82/09/27 0'RCILLY.JP Region 2. Office of Director 2pp 15603 234 24x Fiche 50-340.82/09/27.8210050062
- 8210090114 Add1 info to final deficiency rept re setamic supports for auxiliary feedwater control valves initially reported on 800624 Corrective actions on Unit 1 completed 820031 Unit 2 valves will be installed during normal const achequie MILLS.L M Tennosses Valley Authority 82/09/27 0/REILLY.JP Region 2. Office of Director 1p 13603 256 24x Fiche \$0-390.82/09/27.8210050114
- 8210050293 First interim deficiency rept re six sheeted motor pinion keys in Limitorque Model 80-0-25 motor operators Initially reported on 820830 Valves w/motor operators being tabulated Nax's rept will be submitted by 821122 MILLS.L M Tennessee Valley Authority 82/07/28 O'REILLY, J P Region 2. Office of Director 2pp 15609 070 24X Fichs 30-000, 82/07/28,8210050293
- 8210030158 Second interim rept re undocumented minor mods to structwal & miscellaneous stael Initially reported on 820510 Approx 75% of 250 features had preliminary insp/punchlist completed Next rept to be submitted by 830228 MILLB.L H Tennessee Valley Authority, 82/09/29 Q'REILLY, J P Region 2. Office of Director, 2pp 15605 154 24% Fichs 30-390,82/09/29,8210050158
- 8210060280 First interim deficiency rept re solid-state protection in test procedures initially reported an 820831 Util reviewing Hestinghouse proposal for interim procedural change which would provide for failure detection Next rept by 821210 MfLLBs. M Tennessee Valley Authority 82/09/29 Q'REILLY, J P. Region 2, Office of Director 2pp 15621 164 24X Fiche: 50-390, 82/09/29, 8210060280

- 8210060205 Fourth interim deficiency rept re inadequate loading criteria for structural steel 5 supports Initially reported on 811117 General noise revised to clarify drawings Field mapping of platform steel continuing Next rept by 830310 MILLS.L M Tennessee Valley Authority 82/09/30 0'REILLY, J P Region 2. Defice of Director 2pp 15614 041 24X Fiche 50 390.82/09/30,8210060205
- 82:0060279 First interim deficiency rept re selection of undersized sway struts Initially reported on 820901 Selection methods & adequacy of Bergen-Paterson struts under evaluation Next rept expected by 830225
 MILLS L M Tennessee Valley Authority 82/09/30 0'REILLY, J P Pegion 2. Office of Director 2pp 15621 166 24X
 Fiche 50 390.82/09/30.8210060279
- 02:10080255 First interim deficiency rept re inadequate QA program for masonry block work initially reported on 820902 Const personnel investigating & replying to audit Not rept due on 82:1214
 MILLS.L M Tennessee Valley Authority 82/10/01 D'REILLY, J P
 Region 2. Ofrice of Director 2pp 15608 116 24x
 Fiche 50-390.82/10/01.82:1080255
- 8210080280 First interim deficiency rept re interpretation of radiograph test film on welded pipe by Swepco Tube Corp Initially reported on 820901 Evaluation continuing Nest rept will be submitted on 830219 RELESTED TRANSPORTED TO PROJECT OF THE PROJECT OF THE
- 6.10080291 First interim deficiency cept re failure to terminate cables iPS111. IPS12. IPM1850. IPM1852. IPM1857. iP8182 & IPS151 initially reported on 820901 Cables terminated & personnel retrained Next rept will be submitted by 821123 MILGAL M Tennessee Valley Authority 82/10/01 O'REILLY, J.P. Region 2 Office of Director 2 pp 1563H 308 24% Fiche 50-390. 82/10/01, 8210080291
- 82:10080160 First interim deficiency rept re corresion in high pressure stre protection sys initially reported on 820903 Corrosion analysis in progress to determine potential deficiencies in safety-related areas Next rept expected by 830531 MILLG-L M Tennessee Valley Authority 82/10/04 0'REILLY, J P Region 2. Office of Director 2pp 15640 142 24X Fiche 50-000, 82/10/04, 8210080160
- 82:0080310 First interim deficiency rept re lack of piping sys analysis tracking Initially reported on 820902 Util investigating corrective actions to ensure engineering change notices are not closed out until work is completed MILLS-L M Tennesses Valley Authority 82/10/04 O'REILLY, J P Region 2. Office of Director 2pp 1563B 042 24X Fiche 50 390.82/10/04.8210080310
- 32:0130247 Sixth interim deficiency rept re differential settlement of rock supported structures Initially reported on 810707 individual safety-related components at interfaces of structures being evaluated Next lept by 823,504 MILLS.L.M. Tennesses Valley Authority 82/10/05 O'REILLY, J.P. Region 2. Office of Director 1p. 15676 009 24% Fische 50-390, 82/10/05, 8210130247
- iZi0120540 Second interim deficiency rept re frequency criteria for piping supports initially reported on 820713 investigation continuing Next rept espected by 821220 HILLS, L.M. Tennessee Valley Authority 82/10/05 0'REILLY, J.P. Region 2. Office of Director 1p 15683 279 24X Fiche 50-390, 82/10/05, 8210130340
- 210130379 Third interim deficiency rept re incorrect pipe support design by EDS initially reported on Bili19 Util requested EDS to be more thorough in review of isometric models to analysis results Also reportable per Part 21 MILLS.L. M. Tennessee Valley Authority B2/10/06 O'REILLY, J.P. Region 2. Office of Director 2pp 15692:096 24X Fiche 50-390, 82/10/06, 8210130379
- 210220078 First interim deficiency rept re qualification of process piging w/instrument lines attached Initially reported on 820907 Affected piging being reanalyzed to account for sefect on instrument line biging Next rept by 830427 MILLS.L.M. Tennessee Valley Authority 62/10/08 0'REILLY.J.P. Region 2. Office of Director 2pp 15777, 362 24X Fiche 50-390, 82/10/08, 8210220098
- '10190307 Final deficiency rept re failure to meet pipe support lug criteria Initially reported on 820507 Lug parameter limit discrepancy corrected BILLB, L. M. Tennessee Valley Authority 82/10/12 0'REILLY, J.P. Region 2, Office of Director 2pp 15742 155 24X Fiche 50-390, 82/10/12, 8210190307

- 8210270328 Setund interim deficiency rept re use of nonconservative calculational method to evaluate General Const Spec 0-32 spacing violetions initially reported on 820528 Next rept unil be sent by 830528 MILLS.L M Fennessee Valley Authority 82/10/12 O'REILLY.J P Region 2. Office of Director 2pp 15853 064 24X Fiche 50-000.82/10/12.8210270328
- 8210270049 Supplemental final deficiency rept re defective 6 9 kV OE circuit breaker Instally reported on 811218 Repaired breaker not reinstalled by 821001 due to revised delivery date Breaker to be in place by 821201 MILLS.L M Tennessee Valley Authority 82/10/14 O'REILLY.J P Region 2. Office of Director 1p 15853 335 24X Fiche 50-391,82/10/14,8210270049
- 8210290236 Third interim deficiency rept re potentially overstressed embedded plates initially reported on 820412 investigation continuing & const activities deferred until sufficient info gathered to determine completion of project MILLS.L M Tennessee Valley Authority 82/10/14 O'REJLLY, J P Region 2. Office of Director 2pp 15853 229 24X Fiche 50-000.82/10/14.8210270236
- 8210270052 Second interim deficiency rept re use of incorrect response spectra in 01 bert/Commonwealth piping enalysis Initially reported on 820426 Reanalysis continuing Neit rept expected by 820422 Also reportable per Part 21 MILLGIL M Tennessee Valley Authority 82/01/15 0'REILLY, J P Region 2: Office of Director 1p 15853 334 24X Fiche 50-370,82/10/15.8210279052
- 8210270178 Sixth interim deficiency rept re rerouting of high pressure fire protection piping initially reported on 810130 Three ereas may contain worst case condition No deficiencies identified in two areas Next rept provided by 82:210 MILLS.L M Tennessee Valley Authority 82/10/15 0'REILLY.J P Region 2. Office of Director ip 15853 311 24X Fiche 50-390, 82/10/15, 8210270178
- 8210260320 First interim deficiency mept re addition of locking devices to handwheel operated valves initially reported on 820916 Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820310 MILLS.L.M. Tennessee Valley Authority 82/10/18 0'REILLY, J.P. Region 2. Office of Director 2pp 15802-339 24X Fiche 50-000, 82/10/18, 8210260320
- 8210260451 Fourth interim deficiency rept to failure to include documented piping insulation insps in GC program initially reported on 811007 Const Spaces N30-881 & N3C-912 revised to provide scope of insp requirements Next rept by 830425 MILLS,L M Tennesses Valley Authority 82/10/18 D'REILLY, J P Region 9. Office of Director 2pg 15807 104 24X Fiche 50-390, 82/10/18, 8210260451
- 8210260186 Second interim deficiency rept to underdesign of essential raw cooling water intake pumping station doots & hatches initially reported on B20407 Flathead screws added to door frame for reinforcement Next rept expected by 830331 MILLS:L M Tennessee Valley Authority 82/10/19 O'REILLY, J P Region P. Office of Director 2pp 15799 034 24X Fiche 50-390, 82/10/19, 8210260186
- 8210240390 Eighth interim deficiency rept re improper classification of essential raw cooling water sys piping & components Initially reported on 810324 investigation ongoing Next rept will be submitted by 830427 MILLSrL M Tennessee Valley Authority 82/10/19 O'REILLY, J P Region 2, Office of Director ip 15803 104 24X Fiche: 50-390, 82/10/19, 8210240390
- 82102&0100 Becand interim deficiency rept re lack of seismic analysis on auxiliary bidg platform initially reported on 82042&
 Documentation for all attachments to suspect platforms being investigated Next rept expected by 830217
 MILLS, L. M. Tennessee Valley Authority 82/10/20 D'REILLY, J. P. Region 2. Office of Director 2pp 15797, 122 24X
 Fiche 50-370, 82/10/20, 8210240100
- 82102&0408 Second interIm deficiency rept re potentially deficient valve yoke holddown nut Initially reported on 820601 Util awaiting Hestinghouse resolution for NSSS valves Also reportable per Part 21 HILLS, L M Tennessee Valley Authority 82/10/20 0'REILLY, J P Region 2. Office of Director 2pp 15803 109, 24% Fichs 50-390,82/10/20,8210260408
- 8210290266 Fourth interim deficiency rept re failure of Limitorque motor operators during valve closure initially reported on 820126. Hestinghouse Limitorque & util investigating problem Next rept expected on 830128 Part 21 considered applicable HiLLS.L.M. Tennessee Valley Authority 82/10/21 0'REILLY, J.P. Region 2, Office of Director ip 15854 046 24X Fiche 50-370.82/10/21,8210290266

- 8210290274 Final rept for Deficiencies B & E & seventh interim rept for Deficiencies A & D re control of procurement activities initially reported on 810316 Final corrective actions noted Next rept expected by 830428 MILLS.L M Tennessee Valley Authority 82/10/21 O'REILLY.J F Region 2. Office of Director 4pp 15853 (43 24X Fiche 50-000.82/10/21.8210290274
- DOCKET 50-395 VIROIL C SUMMER NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 821001000B Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed to App A FELTON.J H Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fishs 50-000.82/06/28.8210010008
- --800E050265 Discusses add1 required info to better define potential for gracking in reactor vessel noirles
 NDDNAN, V S Assistant Director for Materials & Qualifications
 Engineering 80/05/05 TEDESCO.R L Assistant Director for
 Licensing 2pp 13727 176 24X Fiche 50-000.82/06/28.8219010008
- & MRC Safety Evaluation Report (SER), supply & correspondence
- B210050175 Supple B20723 & 0024 ltrs re documentation to illustrate that pressurizer safety valve position indication sys is so smarcally qualified, per SER Buppl 4 Info completes responses needed to resolve Licensing Conduction B & 23C DIXON.O H South Carolina Electric & Cas Co B2/09/29 DENTON.H F Office of Nuclear Reactor Regulation, Director 7pp 15404 ii7 24X Fiche 30-395,82/09/29,8210050i75
- F Security, medical, emergency & fire protection plans
- 8210050324 Documents steps taken to fulfill commitments made in Section 8 i 2 of radiation emergency plan re emergency drills & ejercises Relief from requirement to hold another full-scale ejercise prior to full power operation requested DIYON. D # South Carolina Electric & Gas Co 82/09/23 DENTUN. H R Office of Nuclear Reactor Regulation. Director 6pp 15508 215 24% Fiche 50-395,82/09/23.8210050324
- 8210050242 Notifies that full scale emergency drill will not be conducted until Mar 1983 due to unavailability of FEMA personnelsper 820923 commitment DIYON, O H South Carolina Electric & Gas Co 82/09/29 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 1p [5619 321 24X Fichs 50-395, 82/09/29, 8210060242
- 8210080248 Ack receipt of 820727 1tr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-395/82-45

 LEMIS.R C Division of Project & Resident Programs 82/10/06

 DIXON, O W South Carolina Electric & Gas Co 1p 15638 078 24X

 Fiche 30-395/82/10/06.82/0080248
- --B210080250 Responds to NRC 020831 ltr reviolations noted in IE Safeguards Insp. Rept 50-395/82-45 Corrective actions utihheld (ref 10CFR73 21) DIXON.O N South Carolina Electric & Oas Co 82/09/29 O'REILLY, J. P. Region 2, Office of Director 2pp 15638 099 24) Fische 50-395,02/10/06.8210080248
- --8210080254 Forwards IE Safeguards Insp Rept 50-395/82-45 on 820806 & notice of violation Notice of violation withheld (ref 10CFR72 21)

 LEWIS.R C Division of Project & Resident Programs 82/08/31 DIXON, 0 W South Carolina Electric & Gas Co 2pp 19638, 101 24X Fiche 50-375, 82/10/06, 82(0080248

- 8210250312 Confirmatory action for re 821007 discussions at site concerning volnerability of security computer sys noted during 821004-08 insp Enc) withheld (ref 10CFR73 21) KEPPLER, J. G. Region 3. Office of Director 82/10/18 DOLAN, J. E. American Electric Power Service Corp. DOLAN, J. E. Indiana & Michigan Electric Co. 2pp. 15790 189 24% Fiche 50-395,82/10/18,8210250182
- 8210260172 Provides current completion schedule for installation of fire barriers & detectors Fire barriers will be installed by 821115 & fire detectors by end of first quarter 1983 DI/ON.O W South Carolina Electric & Gas Co 82/10/21 BENION H M Office of Nuclear Reactor Regulation. Director 1p 15/79/049 24X Fiche 50-395.82/10/21.8210260172
- 8210260157 Application to amend License NPF-12 in response to General Lit 82-17, changing Tech Specs re emergency plan implementing procedures audits DIXDN.O W South Carolina Electric & Oas Co 82/10/22 DENTENDED OF 15799 OOB 24/ Fiche 50-395.82/10/22.82(0260159
- --8210260166 Proposed Tech Spec changes re frequency of emergency plan & implementing procedures audits + South Carolina Electric & Gas Co | 62/10/22 | 1p | 15799 (80) 24x Fiche 50 | 375, 82/10/22, 8210260159
- G Adjudicatory correspondence
- 9210150458 Second suppl to motion to reopen record for reconsideration of motion for stay, allowed per ABLB 820924 memorandum & order Btds for stay mot CM Anderson engineering rept recontainment cadwelds encl
 BURBEY, B. Bursey, B. 82/10/07 Atomic Safety and Licensing Board
 Panel 23pp [5705-006 24] Fiche 50-375.82/10/07,82(0150458
- 82:01502:7 Memorandum confirming ruling at B2:000 telcon denying intervence B2:1007 motion for reconsideration of ASLB denial of motion to stay implementation of initial decision authorizing issuence of full-term CL GROSBHAM.H Atomic Safety and Cicensing Board Panel 82/10/i. 3pp 15705 280 24X Fiche 50-375.82/10/12.82:101502:7
- 8210250229 Memorandum & order denying B Dursey motion to reopen record on cadualding Intervenor failed to sustain burden of demonstrating existence of genuine issue of safety significance NRC investigation rept to be placed in LPDR GROSSHAN, H. Atomic Safety and Licensing Board Panel 82/10/22 BURSEY, B. Bursey, B. Spp. 15789 331 24X Fiche 50-395,82/10/22,8210250229
- H Ceneral correspondence
- 8210210443 Expresses concern w/allegations of compromised const. (N. stds for cadwelds & inadequacy of response to allegations Hearings should be reopened to examine & refute allegations before granting further facility licenses BASS. J. Affiliation Unknown 82/10/12 OROSSMAN. H. Atomic Safet and Licensing Board Panel 3pg 15763 073 24X Fiche 50-375. 82/10/12. 8210210443
- P Operating license stage documents & correspondence
- 9210080309 Summary of 820915 meeting w/util & Dames & Moore in Bethesda: MD re confirmatory seismic analysis program Licensee must provide program & Schedule for resolving License Condution 25 & ACRB commitment ANNE, MF Licensing Branch 1 82/09/24 Licensing Branch 1 6pp 15663 332 24X Fishe 50-395,82/09/24,6210080309
- 82(0050210 Advises that Westinghouse performed stress evaluation of main reactor coalant loop againg withermal sleeves removed Nozzies qualified to withstand all applicable design transients
 DIXON, D.W. South Carolina Electric & Gas Co. 82/09/29 DENTON, R. Office of Nuclear Reactor Regulation, Director 3pp. 15611 260 24X Fishe 50-395, 82/09/29, 82(0050210
- 8210080276 Requests resolution of provision to remove & reinstall USC SMA-1 per 820924 ltr re confirmatory program for pad test CLARK.N E. WHORTON.R B. South Carolina Electric & Gas Co 52/10/01 JACKBON.R NRC No Detailed Affiliation Oliven 2pp 13638 300 24% Fiche 50-395.82/10/01.8210080276
- 8210120248 Forwards proprietary & nonproprietary versions of "Interia Power Operation Evaluation Rept" Proprietary version withheld (ref 10CFR2 790)
 DIXON,O W Bouth Carolina Electric & Gas Co. 82/10/04
 Diffice of Nuclear Reactor Regulation, Director 94p 15456 055
 24X Fiche. 50-395, 82/10/04, 8210120248

- --8210120250 Nonproprietory version of "Interim Power Operation
 - Evaluation Rept # Hestinghouse Electric Corp 92/09/30 15pp 15656 064 Fiche 50-395,82/10/04-8210120248 24 X
- 82(0)80156 Application to amend License NPF-12.changing Tech Specs re thermal design flow. Fire detection instruments &
- thermal design flow.Fire detection instruments a overpressure protection sys DixQN,O W South Carolina Electric & Qas Co 82/10/08 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 15719 170 24x Fiche 50-395, 82/10/08, 8210180156
- 8210180162 Proposed Toch Spec changes re thermal design flow, fire detection instruments? averpressure protection sys South Carolina Electric & Gas Co 82/10/08 54pp 15719 173 24% Fiche 50-395,82/10/08,8210180156
- t. 16190352 Forwards Technical Rept 82-1, "Seismic Activity Near VC Surmer Muclear Station Jan-Mar 1982" & "Geological Studies in Area of Induced Seismicity at Monticello Reservoir, 80, " fourth technical rept
- Fourth technical rept DI(OH,O W South Carolina Electric & Gas Co 82/10/12 DENTUN Office of Nuclear Reactor Regulation, Director ip 15735 079 24x Fiche 50-195 82/10/12.8210190352
- --8210190444 "Seismic Activity Near VC Summer Nuclear Station. Jan-Mar 1982.' Technical Rept 82-1 TALWANI F South Carolina, Univ of 82-1 82/03/31 17pp 15735 030 24x Fiche 50-395.82/10/12.8210190352
 - 8210197457 "Geologic Studies in Area of Induced Seismicity at Monticella Resorvair, SC." fourth technical rept Thirteen oversize figures enci Aperture cards are available in PDR SECOR D T , PITCHER.D M , PECK L S South Carolina Electric & Gas Ca 82/06/JO 153pp 15735 048 24X Fiche 50-395,82/10/12, B210190352
- 8210190505 Forwards cover it: ;nadvertently omitted from 821004 vubmittal of interim power operation evaluation rept
 PIC(DN.O W South Carolina Electric & Oas Co 82/10/12 DENTON, H R
 Office of Nuclear Realito Regulation, Director 1p 15735 310
 24% Fiche 50-395 82/10/12 8210190505
- -0210170508 Forwards affidavit requesting interim power operation evaluation rept be withhold (ref 10CFR2 770)
 WIESEMANIJAR A Westinghouse Electric Corp. 82/09/30 DENIONIH R
 Office of Nuclear Reactor Regulation. Director 8pp. 157:35-311 24x Fiche 50-395,02/10/12,0210190505
- 8210190553 Responds to Generic Ltr 82-16 re NUREG-0737 Tech Specs All TMI Items discussed in Encl 1 of generic 1t implemented pecs All TMI Items discussed in Encl 1 of generic 1t implemented DIKON.O W South Cololina Flectric & Gas Co 82/10/12 DENION H R Orfice of Nuclear Reautor Regulation. Director 1p 15735 013 24x Fiche 50-395.82/10/12 8210190553
- 8210190492 Forwards "Independent Bosign Verification Turbine Driven POPULAR Forwards "Independent Dosign Verification Turbine Driven
 Portion Emergency Feedwater Sys." final rept
 DUILDP.P Stone & Webster Engineering Corp 82/10/15 DENTON.H R
 Office of Nuclear Reactor Regulation, Director ip 16030 245 24X
 Fiche 90 395,82/10/15,82(0190492
- i3210190900 "Independent Seismic Design Verification Turbine Driven Portion Emergency Feedwater Sys." final rept One oversize drawing encl Aperture card is available in PDR # Stone & Webster Engineering Corp 82/10/15 105pp 16030 246 24X Fiche 50-395.82/10/15.8210190492
- 62[01905]3 Forwards response to questions re DG O'Brien, Inc Qualification Rept ER-307 for triaxial plugs for containment penetrations Cable failure not result of plug design or configuration since plug passed test when encl in conduit DI/CRI-D W South Carolina Electric & Gas Co 82/10/15 DENTON, H R Office of Nuclear Reactor Regulation. Director 15pp 15737 224 24% Fiche 50-395, 82/10/15, 8210190513
- 82(0250330 Application for amend to License NPF-12, providing acceptable tolerances to be used in procurement of sample gases used for callbr of associated instruments & permitting entry into Mode 2 on 821020 BI(ON: D W South Carolina Electric & Gas Co 82/10/19 DENTON. Orfice of Nuclear Reactor Regulation. Director 1p (5790 004 24. Fiche 50-495.82/10/19 82:0250330 DENTON, H R
- --8710250339 Proposed Tech Specs providing acceptable tolerances to be used in procurement of sample gases used for callor of associated instruments & permitting entry into Mode 2 on 821020 # South Carolina Electric & Gas Co 24X Fiche 50-395,82/10/19.8210250330
 - 82/10/19 4pp 15790 005

- 82(0260140 Request for temporary relief from Tach Spec requirements re containment hydrogen monitors in order to allow entry into Mode 2 under action statement for initial criticality Relief will prohibit delay of initial criticality
 DIXON,O W South Carolina Electric & Gas Co 82/10/20 DENTON.
 Office of Nuclear Reactor Regulation. Director ip 15799 091
 24X Fiche 50-395.82/10/20.8210260140
- 8210260159 Application to amend License NPF-12 in response to Generic Ltr 82-17, changing Tech Specs re emergency plan implementing procedures audits
 DIXON,O W South Carolina Electric & Gas Co 82/10/22 DENTON,H R
 Office of Nuclear Reactor Regulation. Director 1p 15799 00B
 24% Fiche 50-395.82/10/22.8210260159
- --8210260166 Proposed Tech Spec changes re frequency of emergency plan & implementing procedures audits + South Carolina Electric & Gas Co | 62/10/22 | 1p | 15799 009 24% Fiche 50-395,62/10/22,6210260159
- Q Inspection reports, IE Bulletins & correspondence
- 8210010167 Revises 810707 \$ 1116 responses to 1E Bulletin 81-02. "Failure of Gate Type Valves to Close Against Differential Pressure " Valve 81300 in Table 1 to 811116 ltm not modified vince value net functional requirements as configured DIXON, D W South Carolina Electric & Gas Co 82/09/0 (REILLY, J P Region 2, Office of Director 2pp 1. Fiche 50-395, 82/09/08, 8210010167 82/09/08 15567 277 24X
- 8210010466 Forwards IE Insp Rept 50-395/82-41 on 820701-0813 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/08 DI(ON.D W South Garolina Electric & Oas Co 2pp 15572 153 Fiche 50-395,82/09/08,8210010466 24 X
- --8210010469 IE Insp Rept 50-395/82-41 on 820701-0813 No noncompliance noted Major areas inspected plant tour open item review. TMI action plan item review & surveillance test procedures performance SKOLDS.J.L. BROWNLEE,V.L. Division of Project & Resident Programs 82/09/08 Sipp 15572 155 24x Fiche 50-375.82/09/08. 8210010466
- 8210010467 Forwards IE Insp Rept 50-395/82-47 on 820806-07.12 & 13 No noncompliance noted

 DANCE H C Division of Project & Resident Programs 02/09/09
 DIXON, O W South Carolina Electric & Oas Ca 2pp 15972, 165
 Fiche 50-393, 62/09/09, 8210010467
- --8210010472 IE insp Rept 50-395/82-47 on 820806-07.12 & 13 No noncompliance noted Major areas (napected initial fuel Toading
 BURNETT.P T , JAPE.F Division of Engineering & Technical
 Programs 82/09/02 3pp 15572 169 24% Fiche 50-395, 82/09/09, 9210010467
- 8208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-12b Implant Seeds" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & Cop 15741 25 82/10/06 Consolidated Edison Co of New York 66pp 24x Fiche 50-000, 82/10/06, 8208190233
- 8210080248 Ack receipt of 820929 itr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-395/82-45.
 LEUIS.R C Division of Project & Resident Programs 82/10/06
 DIXON.O W South Carolina Electric & Gas Co 1p 15638 078 24X
 Fiche 50-395, 82/10/06.8210080248
- --8210080250 Responds to NRC 820831 itr re violations noted in IE Bafeguards Insp Rept 50-395/82-45 Corrective actions withheld (ref 10CFR73 21) BIXON,D W South Carolina Electric & Gas Co 82/09/29 D'REILLY,J P Region 2, Office of Director 2pp 15638 099 Fiche 50-095,62/10/06.8210080248 24 X
- --8210080254 Forwards IE Safeguards Insp Rapt 50-395/82-45 on 820806 & notice of violation Notice of violation withheld (ref 100FR73 21) (ref 100:R/3 21) LEWIS.R C. Division of Project & Resident Programs 82/08/31 DIXON,O W South Carolina Electric & Gas Co 2pp 1563B 101. 24X Fiche 50-395,82/10/06,8210080248
- --8210080259 IE Safeguards Insp Rept 50-395/82-45 on 820806 Noncompliance noted failurs to control designated vehicles Details withheld (ref 10CFR73 21) SKOLD8, J L , MCOUIRE, D R Division of Engineering & Technical Programs. 82/08/26 1p 15538 103 24% Fiche 50-395,82/10/06. 8210080248

n

- B208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svc list enc.)
 DEYOUNG, R. C. Director's Office, Office of Inspection and En
- 8210250312 Confirmatory action ltr re 821007 discussions at site concerning vulnerability of security computer sys noted during 821004-09 insp Encl withheld (ref 10CFR73 21) KEPPLER, J O Region 3. Defice of Director 82/10/18 DDLAN, J E American Electric Power Service Carp DDLAN, J E Indiana & Michigan Electric Co 2pp 15790 169 24% Fiche 50-399, 82/10/18,8210250312
- S Reportable occurrences. LERs & related correspondence
- 821001034B Final significant deficiency rept re-penetration gap raquirements of safety-related piping sys Initially reported on B20726 Mods to piping penetrations for insulation &/or smalling handled through field change request program DIXON, D W South Carolina Electric & Oas Co B2/09/22 O'REILLY.J P. Region 2. Office of Director 2pp 15573 103 24% Fiche 50-395, 82/09/22, 821001034B
- 8210220340 Forwards LER 82-005/03L-0 Detailed event analysis encl DIXDN 0 W South Carolina Electric & Gas Co 82/10/15 O'REILLY J P Region 2. Office of Director 3pp 15776 261 24X Fiche 50-395, 82/10/15, 8210220340
- --8210220346 LER 82-005/03L-0 on 820916, five smoke detectors at 400-ft & 412-ft elevations of control bldg disabled, rendering preaction appinither sqs automatic actuation capability inoparable Caused by need to perform uelding in 400-ft area KOON, A.R. South Carolina Electric & Gas Co. 82/10/15 Region 2. Office of Director ip 15776 264 24X Fiche 50-395, 82/10/15, 8210220340
- 8210220438 Forwards LER 82-004/03L-0 Detailed event analysis encl DIXON O W South Carolina Electric & Gas Co 82/10/15 O'REILLY, J P. Region 2: Office of Director 4pp 15778 258 24X Fiche 50-395, 82/10/15, 82/0220438
- --8210220443 LER 82-004/03L-0 on 820915, test signal generated rausing B train RHR header isolation valve to shut & isolate suction Pump manually tripped Surveillance test procedure revised to line up alternate RHR train w/valve locked out FIELDS, C South Carolina Electric & Gas Co 82/10/15 Region 2, Office of Director 1p 15778 262 24X Fiche 50-395,82/10/15,821020438
- 8210290284 Forwards LER 82-006/03L-0 Detailed event analysis enci DIXON,O W South Carolina Electric & Gas Co 82/10/21 O'REILLY,J P Region 2. Office of Director 3pp 15853 136 24X Fiche 50-395,82/10/21,8210290284
- --8210290286 LER #2-006/03L-0 on 820922, several high range monitors failed high Caused by moisture accumulation in detector preamp connections Plant completed initial fuel load but was not critical Monitors replaced except RM-G190 FIELDS, C South Carolina Electric & Cas Co 82/10/21 Region 2. Office of Director ip 15853 139 24X Fiche 50-395.82/10/21, 8210290284

- DOCKET 50-397 MPPSS NUCLEAR PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 8210070141 Forwards "WA Nuclear Project 2 Environ Equipment Qualification Rept for Safety-Related Equipment," Vols 1.2 & 3. in response to NRC 800221 itr Rept will be incorporated into FSAR amond 80UCHEY, 0 D (Hashington Public Power Supply System 82/09/18CHWENCER.A Licensing Branch 2 p 15630 360 24% Fiche 50-397.82/09/15.8210070141
- --8210070144 "WA Nuclear Project 2 Environ Equipment Qualification Rept For Safety-Related Equipment." Vols 1.2 & 3 * Hashington Public Power Supply System 82/09/30 590pp 15532 019 24X Fichs 50-397.82/09/15.8210070141
- 8210130168 Advises that manual block valve CAG-VX-82e will be utilized as containment isolation valve in lieu of relocating check valve on air line to inside containment Change will be incorporated in future FSAR amend 80UCHEY. 6 D Washington Public Power Supply System 82/09/20 SCHWENCER. A Licensing Branch 2 3pp 15674 114 24X Fiche 50-397.82/09/20.8210130168
- B210060223 Forwards corrections & clarifications to Amend 23 to FSAR Section B 3 re onsite power sys Next FBAR amend will be revised to include encl corrections
 BOUCHEY, G D Hashington Public Power Supply System 82/09/22
 SCHHENCER, A Licensing Branch 2 68pp 15620 117 24x
 Fiche 50-397. 82/09/22, 8210060223
- 8210080068 Forwards NRC position paper closing out Licensing Review Group [1 channel box deflection issue SCHNENCER, A Licensing Branch 2 82/09/22 FERGUSON, R L Hashington Public Power Supply System Spp 15667 355 24X Fiche 50-297, 82/09/22, 8210080068
- 8210050348 Forwards final response to 820708 concerns re adequacy of design margins of Mark II containment sys Issues raised by QE do not represent significant safety concerns for facility
 80UCHEV.0 D Hashington Public Power Supply System 82/07/24
 BCHHENCER, A Licensing Brench 2 10pp 15610 104 24X
 Fiche 50-397, 82/09/24, 8210050348
- 8210290227 Notification of 821006 meeting w/util in Bethesda.MB to discuss cable segaration criteria concerns AULUCK, R. Licensing Branch 2 82/09/27 ECHWENCER, A. Licensing Branch 2 32/09/27 ECHWENCER, B210290227
- 8210040255 Forwards add1 info re organizational changes in preparation for ACRB 821004 meeting Formal revisions to FSAR & operational QA program description will be submitted upon completion
 BOUCHEY, O D Hashington Public Power Supply System B2/09/28
 BCHWENCER, A Licensing Dranch 2 ip 15575 009 24X
 Fiche 50-397, 82/09/28,8210040255
- 8210190764 Forwards update to pump & valve inservice test program plan, per util 820708 ltr M/21 oversite drawings Aperture cards are available in PDR BOUCHEV, 0 D Washington Public Power Bupply System 82/10/07 SCHWENCER, A Licensing Branch 2 lp 15799 l61 24X Fiche 50-397, 82/10/07, 8210190764
- --8210260113 Revision I to "Pump & Valve Inservice Test Program Plan"
 HOYLE, T , RENDERGER, D , MARTIN, J Washington Public Pawer Supply
 System 82/08/28 157pp 15799 162 24% Fiche 50-397,82/10/07,82/10190764
- 8210270446 Staff requirements memo re 821007 affirmation/discussion & vote on extension of const completion dates for MPPSS, purging of classified mat! (n ALAB-453 & emergency preparedness & risks associated w/fuel loading CHILK:8 J Office of the Secretary of the Commission 82/10/08 Office of the Secretary of the Commission 82/10/08 Fiche 50-000, 82/10/08, 8210270446
- B210210327 Confirms B21005 telcon re use of ABME Code Case N-310-1.
 "Certification of Bolting Matia Section III.Div 1. Class 1.
 2. 3. MC & CS " Util will implement code case as agreed
 BOUCHEY. 0 D Washington Public Power Supply System B2/10/11
 BCHHENGER. A. Licensing Branch 2 2pp 15764 216 24X
 Fiche 50-397. B2/10/11. B210210327
- 8210270072 Notification of 821110 meeting w/util in Bethesda: MD to discuss adequacy of GA program in light of recent deficiencies disclosed at several plants AVLUCK.R Licensing Branch 2 82/10/19 SCHWENCER.A Licensing Branch 2 3pp 13836 293. 24X Fichs 50-397.82/10/19.8210270072

- G210260442 Requests representation at Mar 1983 environ site visit & at 830502 question & answer period LEWIS.M D Washington, State of 82/10/20 WHEELER, L NRC No Detailed Affiliation Given 1p 15806 153 24X Fithe 50-397, 82/10/20, 8210260442
- E NRC Safety Evaluation Report (SER), supple % correspondence
- 6210060319 Commits to implementing mod of control logic on pressure interlocks of low pressure ECCS injection valves by fuel load Commitment dependent on timely equipment delivery Info closes SER Outstanding Issue 1 7(8)
 800CHEV. & D. Washington Public Power Supply System 62/09/28
 80CHMENCER. A. Licensing Branch 2 2pp 15619 013 24X
 Fiche 50-397. 62/09/28 8210060319
- 6210050126 Requests revision to Suppl 2 of SER.NUREG-0892 Sections 4 2 3 2(7): 4 2 3 3(1) & 4 2 3 3(3) to indicate resolution of cladding rupture concern & to reflect that PCT margin is not required BBUCHEY 6 D Hashington Public Power Supply System 82/09/30 SCHMENCER.A Licensing Branch 2 1p 15605 041 24X Fices 50-397, 82/09/30, 8210050124
- 8210050156 Forwards marked-up correct Table 1 2 of SER (NUREO-0872) re comparison of facility principal design features to similar facilities, per ACRS Subcommittee on NNP-2 meeting BOUCHEY.O D Washington Public Power Supply System 82/07/30 SCHMENGER.A Licensing Branch 2 3pp 15605 156 24X Fiche 50-397. 82/09/30.8210050156
- 6.10190574 Forwards supplemental response to NUREO-0612. "Control of Heavy Loads." Revision 1 to close out SER Outstanding Issue 30 BOUCHEY. © 0 Mashington Public Power Supply System 82/10/04 SCHUENCER. A Licensing Branch 2 22pp 15736 005 24X Fiche 50-397. 82/10/04.8210190576
 - 22[0]90582 "Reactor Vessel Head Removal & Replacement "

 4 Washington Public Pouer Supply System 61/12/17 16pp
 15726 000 24% Fiche 50-397, 82/10/04/8210190576
 - U210190586 "HPCS Pump Removal. Overhaul % Reinstallation "

 « Nashington Public Power Supply System 81/07/23 19pp
 15735 046 24% Fiche 50-397, 82/10/04, 8210190576
- EL10216049 Forwards recommondations on proposed plant operating procedure changes, equipment mods & discussion of design basis ashfall Advance warning alrangements in Section II A rulfill commitment per supplemental SER Section 2 5 i 3 l BOUCHEY, O D Washington Public Power Supply System 82/10/04 SCHMENCER, A Licensing Branch 2 4pp 15765 345 24X Fiche 50-397. 82/10/04.8210210049
- 6210210148 Informs that hydrostatic test of diesel engine auxiliary piping to 125% of design pressure performed in response to supplemental SER Item 9 5 4 1, Open Item 15 & FSAR Question 040 084 Exemption requested for intake 5 exhaust lines 98UCHEV. 6 D. Hashington Public Power Supply System 62/10/04 SCHIMCHER. A. Licensing Branch 2 3pp 15766 087 24X fiche 50-377. 82/10/04.8210210148
- 8210210276 Advises that Section 14 2 14 3 17 will be amended to remove any 16f to containment hot pipe penetration testing SER Outstanding Issue 21 (NURSO-0892) closed w/o need for acceptance criteria Diagrams repenetration assembly enci SDUCHEV.O D Washington Public Power Supply System 82/10/04 SCHMENGER.A Licensing Branch 2 6pp 15766 124 24X Picks 30-397.82/10/04.8210210276
- F Security, medical, emergency & fire protection plans
- 8210060445 Forwards "Dne-Hour ASTM EJ19 Firm Simulation Facility Firm Tests Water Hose Stream Impact Tests & Electrical Circuitry Continuity Tests on Nuclear Facility Class IS Cable Trays & Conduit Test "Rept withheld (ref 10CFR2 790) UNUCHEY. O D Washington Public Power Supply System 82/09/20 SCHMENCER. A Licensing Branch 2 3pp 15615 001 24X Fichs 50-397. 82/09/20.8210060445
- 8210130194 Submits add1 info to suppl test rept data in util B20802 & 0920 ltrs to NRC re Thermo-Lag 330-1, subliming coating envalope sys (ITL Rept 82-5-359A) for fire protection of cable raceway sys discussed in App R BOUCHEY, O D Washington Public Power Supply System 62/10/04 SCHWENGER, A Licensing Branch 2 4pp 15674 I41 24X Ficha 50-397, 82/10/04/8210130194

- 8210210049 Forwards recommendations on proposed plant operating procedure changes equipment mods & discussion of design basis ashfall Advance warning arrangements in Section II A rulfill commitment per supplemental SER Section 2 5 i 3 i 30UCHEV.0 D Washington Public Power Supply System 82/10/04 SCHWERGER.A Licensing Branch 2 App 15765 345 24X Fichs 50-397, 82/10/04,8210210049
- 82:0190708 Forwards Test Rept 82-5-3558. "Three-Hour Fire Endurance Tests on Thermo-Lag 330-1 Subliming Coating Envelope Sys for MPPSS Nuclear Projects "(//o encl BOUCHEY.G D Washington Public Power Supply System 82/10/05 SCHWENCER.A Liconsing Branch 2 3pp 15736 151 24X Fiche 50-397, 82/10/05.8210190708
- 82:0130575 Notifies of meeting w/Yakima Indian Nation tentatively scheduled on 82:022 to discuss emergency plan coordination, in response to NRC 82:0744 request BOUCHEY.0 D Hashington Public Power Supply System 62/10/06 SCHWENCER:A Licensing Dranch 2 ip 15679 108 24X Fiche 50-397, 82/10/06,82:10130575
- G Adjudicatory correspondence
- 8210130336 Order CLI-82-27 referring Coalition for Safe Power petitions for hearing to ASLB ABLB chairman should appoint ASLB to determine whether 10CFR 714 requirements met & to conduct required hearing Wiseparate views of Commissioner 0.11insky CHILK, S.J. Office of the Secretary of the Cammission 62/10/08 21pp 15681 350 24X Fichs 50-397,82/10/08.8210130336
- 6210200056 Notice of ASLB constitution H Grossman, chairman & EE H111 & LW Little, members COTTER.B P Atomic Safety and Licenaing Board Panel 82/10/14 2pp 15755 027 24X Fiche 50-397, 82/10/14.8210200056
- 8210180147 Lists changes to be made in Commission 821008 Order: CLI-82-29 STUCKY,8 W Docketing & Services Branch 82/10/15 Office of the Executive Legal Director ip 15719 266 24X Fiche 50-397, 82/10/15:8210180147
- 8210290315 Notice of ASLB reconstitution H Grossman.chairman & OO Bright & J Harbour.members LAZO.R M Atomic Safety and Licensing Board Panel 82/10/25 2pp 15853 078 24X Fiche 50-397.82/10/25.8210290315
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8210080075 Forwards Amend 26 to FBAR BDUCHEY.O D Washington Public Fower Supply System B2/09/28 SCHWENCER.A Licensing Branch 2 2pp 15640 338 24x Fiche 50-397. 82/09/28.8210080095
- --8210080100 Amend 2b to FSAR

 + Washington Public Power Supply System 82/07/31, 757pp
 15640 339 24X Fiche 50-397, 82/09/28, 8210080095
- 8210210045 Forwards transmittal ltr % Certificate of 8vc for Amend 26 to FSAR H/o transmittal ltr 8DUCKEY, 0 Hashington Public Fower Supply System 82/10/05 8CHWENCER,A Licensing Branch 2 2pp 15765 352 24X Fiche 50~397, 82/10/05.8210210045
- Q Inspection reports: IE Bulletins & correspondence
- 8210080195 Forwards revised corrective actions to NRC notice of violations 79-10/01,79-10/03,80-09/09 & 80-08/22 noted in IE Insp Rept 50-397/81-22 All future liquid penetrant erams will be performed by Dechtel approved subcontractor MATLOCK.R 0 Washington Public Power Supply System 82/04/16 ENGECKEN.R H Region 5. Office of Director 3pp 15640 190 24X Fiche.50-397,82/04/16.8210080195.
- 0210190646 Provides additinfoirs preservice inspiprogram plan for scram discharge sys per 820012 telcon Boundary diagram for control rod drive sys enci BOUCHEY, O D Hashington Public Power Supply System 82/09/22 SCHWENCER, A Licensing Branch 2 Spp 15739 101 24% Fiche 50-397, 82/09/22.8210190646
- 8210190366 Forwards IE Insp Rept 50-397/82-18 on 820816-31 No noncompliance noted STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs 82/07/28 MATLOCK.R Q Washington Public Power Supply System 2pp 15741.166 24X Fiche 50-397.82/07/28,8210190366

- --8210190368 IE insp Rept 50-397/82-18 on 820816-31 No noncompliance noted Major areas inspected reactor pressure vessel hydrotest, mechanical contractor retords review program & corrective activities & work reverification program TOTH.A D. DDDDS, R T. Division of Resident. Reactor Project & Engineering Programs 82/09/27 14pp 15741 168 24X Fiche 50-397,82/09/28,8210190366
- 8210190542 Forwards JE Insp Rept 50-397/82-22 on 820830-0903 No noncompliance noted STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/09/28 MATLOCK, R C Washington Public Power Supply System 2pp 15736 126 24% Fiche 50-397,82/09/28,8210190562
- --8210190569 IE Insp Rept 50-397/82-22 on 820830-0903 No noncompliance noted Major areas inspected facility organization, preoperational testing operational QA program & independent insp WILLETI, D J , DDDDS, R Division of Resident, Reactor Project & Engineering Programs 82/09/27 Spp 15736 130 24% Fiche 50-397,82/09/28,8210190562
- 8210190665 Forwards 1E Insp Rept 50-397/B2-17 on 820726-30,0809-13 & 0830-0903 Mo noncompliance noted STERMBERG.D M Division of Resident, Reactor Project & Engineering Programs 82/10/01 MATLOCK, R & Washington Public Power Supply System 2pp 15737 256 24% Fiche 50-397,82/10/01,8210190665
- --8210190678 IE insp Rept 50-397/82-17 on 820726-30.0809-13 & 0830-0903 No noncompliance noted Major areas inspected electrical installation, safety-related piping & employee concerns ELIN.J O. D'ANGELO A J. DODDS:R T Division of Resident, Reartor Project & Engineering Programs 82/09/30 9pp 15737 258 24% Fiche 50-397, 82/10/01.8210190665
- 8210070299 Ack receipt of 820831 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/82-14
 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/10/04 MAZUR, D W Washington Public Power Supply System 1p 15634 236 24% Fiche 50-397, 82/10/04,8210070299
- --8210070302 Responds to NRC 820802 ltr re violations noted in It Insp. Rept 50-397/82-14 Corrective actions Dechtel procedures reviewed to ensure that AE approvals obtained & GC Admanistrative Instruction 15 issued MATLOCK, R. O. Washington Public Power Supply System 82/08/31 STERNERO, D. M. Division of Resident. Reactor Project & Engineering Programs 6pp 15634 239 24X Fiche 50-397,82/10/04,8210070299
- B208190233 iE Info Notice 80-35. Suppl 1: "Leaking & Disindged 1-125 Implant Seeds " Syc list encl COBB.L I Division of Fuel Facilities. Haterials & Safeguards 82/10/06 Consolidated Edison Co of New York 64pp 15741 250 24% Fiche 50-000, 82/10/04.8208190233
- 8210280241 Forwards IE Insp Repts 50-397/62-20 & 30-13720/82-01 on 820821-0903 & notice of violation BOOK.H E Division of Radiological Safety & Safeguards Program 82/10/12 MATLOCK.R O Mashington Public Power Supply System 2pp 15837 325 24X Fiche 50-397, 82/10/12,8210280241
- --B210280244 Notice of violation from insp on B20831-0903 WENSLAMSAI, F.A. Division of Radiological Safety & Safeguards Frogram B2/10/12 1p 15837 327 24X Fiche: 50-397, B2/10/12, 8210280241
- --8210280248 IE Insp Repts 50-397/82-20 & 30-13720/82-01 on 820831~0903 Noncompliance noted receipt of radioactive matl not authorized by License 46-17946-01 YUHAB: 0 P . WENSLAHSKI.F A . BOOK.H E Division of Radiological Safety & Safeguards Program 82/10/08 lipp (5837-328 24X Fichs 50-397,82/10/12-821028024)

- 8210080304 Interim deficiency rept re improper installation of contrety expansion anchors & unacceptable concrete & grout work Initially reported on 820403 Corrective actions continuing Next rept will be submitted on 821216 MATLOCK.R & Washington Public Power Supply System 82/05/28 ENGELKEN.R H. Region 5. Office of Director . Opp 15638 325 241 Fiche 50-397.82/07/28,821080304
- 82(0130217 Final deficiency rept to high resistance cable grounding of 4 16 kV diesel generators initially reported on 820506 Manufacturers advised that equipment can operate for indefinite period w/line-to-ground fault w/o damage MATLOCK R O Washington Public Power Supply System 82/09/20 ENGELKEIN R M Region 5. Office of Director Jpp 15675 240 21% Fiche 50-397,82/09/28,8210130217
- 8210080275 Final deficiency rept re 4 16 kV breakers DG 1-7 % DG 2 6 & interim deficiency rept re emergency diesel generators DG-1 & DG-2 airstart circuits initially reported on 820070 % 0709; respectively Next rept will be submitted by 821220 MATLOCK.R G Washington Public Power Supply System 82/09/30 ENCELKBIR M Region 5. Office of Director 3pp 15638 302 2K Fiche 50-397,82/09/30,8210080275
- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT I

 A Application/construction stage documents & currespondence
- B210130033 Summary of 820816-19 meeting w/utilibasco & Westinghause re design review of instrumentation & control sus for reactlities Followup meeting scheduled for 820914-16 in New York City,NY LICITRALE A Licensing Branch 3 82/09/08 Licensing Branch 3 5pp 15696 272 24% Fische 50-400.82/09/08.8210130053
- 8210010051 Ack receipt of 820823 Itr requesting temporary relief from commitments re-training of shift technical advisors Program approved t request forwarded to filter for evaluation O'REILLY. J P. Region 2, Office of Director 82/09/20 JONES, Ja Carolina Power & Light Co. Ip. 15565-322 24X Fiche 50-000-82/09/20,8210010051
- 8210270324 Requests add1 info re instrumentation & control sys Info should be in form of response to IE Bulletin 79-21 re level measurement errors due to environ temp effects on level instrument ref legs Requests submittal date within 2 wks KERRIGAN. J D. Licensing Branch 3 82/09/23 JUNES, J A. Caroling Power & Light Co. 2pp 15836 357 24% Fiche 50-400.82/09/23, 8210270324
- B210210035 Forwards request for add1 info on FSAR Section 440-0.
 "Peactor Sqs "
 KERRIOAN.J Licensing Branch 3 82/09/29 JONES, J A Carolina
 Power & Light Co 9pp 15773 262 24X Fiche 50-400.82/09/29.
 8210210035
- 8210210258 Notification of 821012 meeting w/util & Ebasco in Bethrsis. MD to discuss review of RCPB matls
 KADAH81,N P Licensing Aranch 3 82/09/29 KERRIGAN. J Licensing a
 Branch 3 3pp 15774 324 24% Fiche 50-400.82/09/29.8210210258
- 8210210320 Summary of 820714-16 meetings w/util.Westinghouse & Lbasco at Ebasco ofc re design review of instrumentation & control sys Attendance list enct LICITRA.E A Licensing Branch 3 82/09/29 Licensing Branch 3 4pp 15782 087 24% Fiche 50-400.82/09/29.8210210320
- 8210050106 Forwards 21 responses to Reactor Bys Dranch (440 Series) questions discussed at Reactor Bys Branch safety review meeting held on 820921 Remaining 17 Items will be addressed to near future MCDUFFIE.M A Carolina Power & Light Co 82/09/30 DENTON.H R Office of Nuclear Reactor Regulation, Director 27pp [5603 261 24X Fiche 50-400, 82/09/30, 8210050104
- 8210050125 Forwards responses to Instrumentation & Control Bys Brench 820730 questions re FSAR, confirming info discussed during 820816-17 & 0914-16 meetings HCDUFFIE.M A Carolina Power & Light Co 82/09/30 DENTON H R Office of Nuclear Reactor Regulation, Director 56pp 15604 282 24X Fiche 50-400, 82/09/30, 8210050125
- 8210210312 Summary of 82092; meeting w/applicant;Westinghouse.Ebasco & E040 at site re Reactor Sys Brench 820424 questions concerning FBAR Attendance list encl
 KADAMBI.N P Licensing Branch 3 82/10/01 Licensing Branch 3 4pp 15782 078 24X Fiche 50-400;82/10/01.8210210312

- 8210150305 Advises that commercial operation date for Unit 1 changed from Fall 1985 to Spring 1986 No funds to be allocated in 1983 for const work on Unit 2 Most of requested rate hike disallowed W/Certificate of Svc Related correspondence FLYNN, 8 F Carolina Power & Light Co 82/10/06 KELLEY, J L. ORIGHT. 0.. CARPENTER, J H. Atomic Safety and Licensing Board Panel 4pp 15701 336 24X Fiche 50-400.82/10/06.8210150305
- 8210150647 Notification of canceled 821012 meeting w/util & Ebasco in Bathesda.MD to parform review of RCPB matl KADAHBI.N P Licensing Branch 3 82/10/08 KERRIGAN.J Licensing Branch 3 39 15715 305 24X Fiche 50-400.82/10/08
- 8210190512 Submits const completion scheduls. Unit 1 schedulsd for operation in Spring 1936, resulting in 6-month delay in fusi load Schadule for Unit 2 completion due Dac 1982 Present licensing revisw schedule should be maintained MCDUFFIE. M A Caroline Power & Light Co 82/10/14 DENYON, H R Offics of Nuclear Resource Regulation, Director ip 15735, 309 24X Fiche: 50-400, 82/10/14, 8210190512
- B210260462 Bubmits formal clarification of responses to safety review questions from Containment Sys Branch (480 Bariss)
 MCDUFFIE.H A Carolina Power & Light Co BZ/10/20 DENTON.H R
 Diffice of Nuclear Rescor Regulation. Director 7pp 15806 052
 24X Fiche 50-400,82/10/20,8210260462
- --8210260481 Informs that Topical Rspt AAF-TR-7101, "Design & Tasting of Fan Coolsr-Filter Sys for Nuclear Applications," acceptable Partial "Equipment Qualification Data Packages" encl TEDEBCOR & Atomic Ensrgy Commission, Daputy Director for Yachnical Review (Pre-1975) 72/11/10 FIBH.J F American Air Filter Co 54pp 15806 061 24X Fichs 50-400,82/10/20.

Utility Environmental Report (ER), amende & correspondence

- 210200032 Forwards responses to soviron rept review Questions 240 3. 291, 13 & 291 i5, comparing environ impact on Buckhorn Creek of aperation of one unit w/o Cape Fear River Makeup Bys MCDUFFIE: M A Caroline Power & Light Co 82/10/19 DENTON: H R Office of Nuclear Reactor Regulation. Director 21pp 15737 308 24X Fiche 50-400: 82/10/19: 8210200032
- 210200084 Forwards Amend 4 to environ rept. Summary of changes encl MCBMFFIS. H A Carolina Power & Light Co 82/10/15 DENTON. H R Office of Nuclear Reactor Regulation. Director 2pp 15783 212 24X Fiche 50-400,62/10/15,6210200084
- -8210200086 Amend 4 to snviron rept. Aparture cards available in PDR w Caroline Power & Light Co. 82/10/15 279pp 15783 214 24) Fithe 50-400, 82/10/15, 821020084.
- NRC Draft/Final Environmental Statements, supple & correspondence
- '102(0212 Notifies of scheduls changs for DEB Reservoir meanalysis has lead to delay in receipt of hydrological info. Statement will be issued by 82(217.
 NOVAK, T.M. Assistant Director for Licensing 82/10/12 UTLEY, E Carolina Power & Light Co 2pp 15774'336 24X
 Fichs 50-400, 82/10/12, 821(0210212

Escurity, medical, amergency & firs protection plans

- 10010037 Forwards request for add1 info, based on review of 820826 industrial security plan, safaguards contingency plan & security personnel training & qualification plan Encluithheld (ref 100FR2 790)

 KERRIGAN, J.D. Licensing Branch 3 92/09/20 JONES, J.A. Carolina Pawer & Light Co. 2pp 15585 315 24X Fichs, \$0-400, 82/09/20, 3210010037.
- 10010349 Ack receipt of 820902 ltr informing NRC of steps taken to orrect violation noted in IE Insp Repts 50-400/82-24 & 30-401/82-24 Response insufficient to determine if orrective action adequate EHIER G. Division of Project & Resident Programs 82/09/22 INSES.J.A. Carolina Power & Light Co 2pp 15549 213 24X iche-50-400,82/09/22.8210010349

- --8210010397 JE Insp Repts 50-400/82-24 & 50-401/82-24 on 820620-0720 Noncompliance noted failure to identify & correct nanconforming conditions on two field welds on Class IE electrical cable tray supports MACHELL.0 F , BURGER.C W Division of Project & Resident Programs 82/08/03 9pp 15569 220 24% Fiche 50-400.82/09/22,8210010349
- G. Adjudicatory correspondence
- B210120103 Add1 response to FOIA request for nine categories of records generated by present KRC Commissioners; primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents
 FELTON, J. M. Division of Rules and Records B2/07/12 UDELL: R A Critical Mass Energy Project 3pp 15690 117 24X
 Fiche 50-000: 82/07/12: 8210120103
- --B210120123 Forwards memorandum & order re Council of NC objection to util request for examption to perform certain site preparation work Memorandum addresses exemption question & sets out history of Commission regulation. Section 50 12 ROBERTS. T M Commissioners 81/12/09 PALLADING, N , OILINSKY, V , BRADFORD, J Commissioners ip 15690 124 24X Fichs 50-000, 82/07/12, 82/0120103
- --8210120132 Memorandum & order rs Council of NC objection to util request for exemption per revised NEPA regulation to perform certain site preparation work NEPA does not bar preliminary work Site preparation work properly authorized BENDER, P. C. Atomic Energy Commission 74/06/11 Atomic Energy Commission 8pp. 15690 125 24X Fichs 50-000,82/07/12,
- B21001032B Bupplemental statement rs validity of psychological stress contentions Lats filing criteria not applicable If contentions not admitted, snc1 arguments should be considered amends to original contentions READ, D.F. Chapel Hill Anti-Nuclear Group Effort 82/09/17 Atomic Bafety and Licensing Board Panel 14pp 15569 174 24X Fichs.50-400, 82/09/17, B21001032B
- 8210010337 Suppl to Chapsl Hill Anti-Nuclear Group Effort/Environ Law Project 820713 renswed & reformed motion to postpone proceedings originally submitted on 820316 Suppl based on new info Cartificata of Svc encl.
 READ, D.F. Chapsi Hill Anti-Nuclear Group Effort 82/09/24
 Atomic Safety and Licensing Board Penel 7pp 15569 166 24X
 Fichs 50-400, 82/09/24,8210010337
- B210130192 Requests clarification of dockst numbers for Harris & Perry plants Hixup may be causing prejudics to intervenors since documents go to incorrect LPDR HIATT, B.L. Ohio Citizens for Responsible Energy 82/10/04 Docksting & Bervices Brench. 1p 15707, 260. 24X Fichs 50-000, 82/10/04,8210180192
- B210150305 Advisss that commercial operation date for Unit 1 changed from Fail 1985 to Baring 1986. No funds to be allocated in 1983 for comet work on Unit 2 Most of requested rate hike disallowed W/Certificats of Byc Related correspondence FLYNN, 8 F Carolina Power t Light Co. 82/10/06 KELLEY, J. L., BRIGHT, 0 D. CARPENTER, J. H. Atomic 88 febty and Licensing Board Panel 4pp. 15701.336, 24X Fiche 50-400.82/10/06.8210150305
- 8210150340 Objections to ASLS 820922 prehearing conference memorandum & order Certificate of Svc encl.
 READ, D F Chapsi Hill Anti-Nuclear Group Effort 82/10/08
 Atomic Safety and Licensing Board Panel 7pp 15705-357 24X
 Fichs. 50-400, 82/10/08, 8210150340
- 8210200053 Responds to ASL8 B20922 order ruling on contention & svc of documents, RULing an Contention IVc & on mation re svc of documents should be reconsidered Arrangements for svc unacceptable since pertiss unrelated, W/Certificate of Bvc. WILSON, RD. Witson, R. 82/10/14. 5pp. 15753.088 24X Fiche 50-400.82/10/14.8210200053
- 8210200007 Forwards objections to & requests for clarification of ASLB 820722 memorandum & order & response to Chapel Hill Anti-Nuclear Group Effort supplemental statement repsychological stress contentions Certificate of Svc enci BAXTER, T A Shaw, Pittman, Potts & Troubridgs, BAXTER, T A Carolina Power & Light Co. 82/10/15 KELEY, J L, BRIGHT, O D. CARPENTER, J H. Atomic Safety and Licensing Board Panel, App 13755:001 24X Fichs: 30-400.82/10/15,82102000009

DOCKETED ITEMS

- --8210200013 Response opposing Chapel Hill Anti-Nuclear Group Effort 820927 supplemental statement re psychological stress contentions ASLB obligated to follow Commission policy statement on psychological stress issues BAXTER, T.A. Carolina Power & Light Co. BAXTER, T.A. Shaw, Pittran, Potts & Trowbridge 82/10/15 Atomic Safety and Licensing Board Panel 5pp 15755-005 24X Fiche 50-400, 82/10/15.8210200009
- --B210200021 Objections to & requests for clarification of ASLB B20922 memorandum & order Add1 info re util plans on proposed Cape Fear River intake facility provided Ruling on H Eddleman Contention 132 should be clarified to specify bases O'NEILL.JH Caralina Power & Light Co O'NEILL.JH Shaw. Pittman. Potts & Troubridge B2/10/15 Atomic Safety and Licensing Board Panel 17pp 15755 010 24x Fichs 50-400,82/10/15.8210200007
- B210210308 Notice of appearance in proceeding Certificate of Svc entl GREENBLATT.D Eddleman, N GREENBLATT.D Greenblatt D B2/10/15 Atomic Safety and Licensing Board Panel 3pp 15764 241 24X Fiche 30-400.82/10/15.8210210308
- 8210210376 Dbjections to ASLB 820922 memorandum & order reflecting decisions made at prehearing conference Objects to rulings on syc of util documents contentions & cancelation of Unit 2 Centificate of Syc enc! EDDLEMAN W Eddleman W 82/10/15 14pp 15763 150 24X Fiche 50~400.82/10/15.6210210376
- B210210417 Response to ASLB B20922 memorandum & order re use of security plan experts as witnesses CREENBLATT.D Eddleman, W PAYNE.M T Kudzu Alliance RUNKLE.J Chapel Hill Anti-Nuclear Group Effort 82/10/15 App 15763 076 24X Fiche 50-400,82/10/15.8210210419
- 8210200062 Forwards consolidated list of admitted & deferred contentions per ASLB 820722 order Agreement should be reached on wording b numeration to facilitate hearings & avoid misunderstandings M/o pnc!

 BARTH.C A Hearing Branch 1 82/10/18 RUNKLE.J Conservation Council of North Carolina EDDLEMAN W Eddleman W READ.D F Chapel Hill Anti-Nuclear Group Effort 10 16756 (52 24X Fiche 50-400, 82/10/18, 8210200062
- 8210250068 Complains about svc of documents & LPDR copy machine EDDLEMAN, W Eddleman, W 82/10/19 KELLEY, J L , CARPENTER, J H , BRIGHT, O O Atomic Safety and Licensing Board Panel 2pp 15787 045 24% Fichs 50-400.82/10/19.8210250068
- H General correspondence
- 8210010028 Requests NRC direct all official correspondence to EE Utley, util vice-president, due to 820930 retirement of JA Jone JONES, J A Carolina Fower & Light Co 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director Jp 15365 314 24x Fiche 50-000, 82/09/27, 8210010028
- 8210130323 Requests changes to distribution list for NUREG-0020. "Licensed Operating Reactors - Status Summary Rept" ZIMMERMAN, 8 R Carolina Power & Light Co 82/10/11 BEEBE, M R ADP Systems Development Branch 2pp 15683 361 24x Fiche 50-000, 82/10/11, 8210130323
- Q Inspection reports. IE Bulletins & correspondence
- 8210010086 Forwards IE Insp Repts 50-400/82-29 & 50-401/82-29 on 820830-0902 No noncompliance noted VERKELLI, D M Division of Project & Resident Programs 82/09/13 JONES, J A Carolina Power & Light Co 2pp 15565 260 24% Fichs 50-400,82/09/13,8210010086

- 8210010349 Ack receipt of 820902 ltr informing NRC of steps taken to correct violation noted in IE insp Repto 50 -400/82-24 % 50-401/82-24 Response insufficient to determine if corrective action adequate LEMIS.R C Division of Project & Resident Programs 62/09/22 JUMES.J A Carolina Power & Light Co 2pp 15569 213 24X Fiche 50-400, 82/09/22,8210010349
- -82(0010360 Responds to NRC 820804 ltr re violation noted in [6 limp Repts 50-400/82-24 & 50-401/82-24 Corrective actions Hanger ED 2622 & Item 1436-10 reinspected & repaired New inspector under training in GC welding required to pass written insp PARSONS:R M Carolina Power & Light Co 82/09/02 O'REILLY. J P Region 2. Office of Director 2pp 15569 215 24X Fiche 50-400,82/09/22.8210010349
- --8210010368 Forwards IE Insp Repts 50-400/82-24 % 50-401/82-24 un 820620-0720 % notice of violation LEHIS,R C Division of Project & Resident Programs 82/08/04 JONES, J A Carolina Power & Light Co 2pp 15569 217 24% Fiche 50-400,82/09/22,8210010349
- -82100103/3 Notice of violation from insp on B20620-0720

 * Division of Project & Resident Programs B2/08/04 ip
 15567 219 24% Fiche 50-400, 82/09/22,8210010349
- --8210010397 IE Insp Repts 50-400/82-24 & 50-401/82-24 on 820620-0720
 Noncompliance noted failure to identify & correct
 nonconforming conditions on two field welds on Class IE
 electrical cable tray supports
 MACMELLO F , BURGERO W Division of Project & Resident Prograss
 82/08/03 9pp 15569 220 24X Fiche 50-400/82/09/22/82(0010)42
- E210220160 Forwards IE Insp Repts 50-400/82-30 \$ 50-401/82-30 on 820820-0910 No noncompliance noted VERRELLI,D K Division of Project \$ Resident Programs 82/10/04 JONES, J A Carolina Power & Light Co 2pp 15778 072 24X Fiche 50-400,82/10/04,8210220160
- --8210220163 IE Insp Repts 50-400/82-30 & 50-401/82-30 on 620820-0910 h. noncompliance noted Major areas inspected followup on previously (dentified items, concrete, piping & personnel training MAXNELL, 0 F , BURGER, C W Division of Project & Resident Programs 82/09/30 6pp 157/8 074 24X Fiche 50-400, 82/10/04, 82/10/20160
- 8208190233 IE Info Notice 80-35. Suppl !, "Leaking & Pislodged (-125 implant Seeds " Svc list enc! COBD.L ! Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York & App 15761 250 24X Fache 50-000.82/10/06.8208190233
- 8210220127 Ack receipt of 820923 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50~400/82-26 & 50-401/82-26 LEHIS.R C Division of Project & Resident Programs 82/10/12 UTLEY.E E Carolina Power & Light Co lp 15778 122 24X Fiche 50-400, 82/10/12. 8210220127
- --8210220132 Responds to NRC 820830 ltr re violations noted in II Insp.
 Rept 50-400/82-26 Corrective actions refresher training
 course conducted for rebar inspectors
 PARSONS,R H Carolina Power & Light Co 82/09/23 G'REILLY, J P
 Region 2, Office of Director 2pp 15776 123 24X
 Fiche 50-400,82/10/12,8210220127
- --8210220137 Forwards IE Insp Repts 50-400/62-26 & 50-401/62-26 on 820802-06 & notice of violation
 LEWIS.R C Division of Project & Resident Programs 62/08/30
 JONES, J A Garolina Power & Light Co 2pp 15778 125 24%
 Fiche 50-400,82/10/12,8210220127
- ~~8210220141 Notice of violation from insp on 820802-04 * Division of Project & Resident Programs 82/08/30 ip 15778 127 24X Fiche 50-400,82/10/12.8210220127
- --B210220145 IE Insp Repts 50-400/B2-26 & 50-401/B2-26 on B20B02-06 Noncompliance noted failure to analyze cut rebars for acceptability (MRIGHT,R W. DEBBAGE,A C. UPRIGHT,C M. Division of Engineering & Technical Programs B2/0B/25 13pp 15778 128 24X Fiche 50-400,B2/10/12,B210220127
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Fighing at BMR Flants "Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125, 24% Fiche 50-000,82/10/14.8208170238

- 3 Reportable occurrences | ERs & related correspondence
- 121018014) Part 21 rept re seismic pipe hangers previously accepted by GC weld inspector Iritially reported on 820913 Hangers will be reinspected reworked. Correctly documented Final rept expected by 830701
 CHIANGIN J Carolina Power & Light Co. 82/09/13. 0'REILLY, J' Region 2. Office of Director. 4pp. 19719-226. 24% Fiche 50-400. 82/09/13. 6210180141
- 6210180193 Part 21 rept re ravity pipe support shop welds Initially revorted on 820813 fine criteria being reviewed Deficient supports reformed to Bergen-Paterson for insp Next rept will be completed by 830701 CHIANOLIN J Carolina Power & Light Co 82/09/13 O'REILLY, J P Region 2, Office of Director 4pp 15719 114 24X Fiche 50-400.82/09/13.8210180193
- SELCOBOIRO Deficiency rept to use of ASTM-A307 nuts & bolts for boiled connection in lieu of required ASTM-A325 nuts % bolts. Initially reported on 820903 Ebasco Sycs currently evaluating problem All bolts replaced/leinspected PARSONS.R M. Carolina Power * Light Co. 82/09/30 O'REILLY.J P. Rejion 2, Ofrice of Director ip 15640 169 24x Fiche 50-400.82/09/30 8210080180
- 6210080283 Interim deficiency tept re sheared pinion keys on Limitarque valve motor operators Initially reported on 820903
 Restinghouse discussing problem w/Limitorque Final rept will be submitted by 830401 Also reported per Part 21
 PARSONS.R M Carelina Power & Light Cu 82/10/01 0/REILLY.J P Region 2. Office of Director 3pp 15630 320 24x
 Fishe 50-400, 82/10/01, 8216080283
- F210130547 Addendum 2 to 820317 deficiency mept re inadequately welded atude on embedded strip plates Addendum provides info re shipment of embeds (fup [I strip plates & crane rail plates) & any associated problems PARSON.R M Carolina Power & Light Co 82/10/05 D'REILLY, J PRegion 2, Office of Director Spp 15493 113 24) Fiche 50-400.02/10/05.0210130567
- 6210220484 Interim deficiency lept re defective governor drive coupling in emergency diesel engine-generator sets from Transamerica DeLaval Institutiy reported on 820909 (oupling will be replaced Also reportable per Part 21 PARSONS.R M Carolina Power / tight Co 82/10/07 D'REILLY.J P Region 2. Office of Director 4pp 15779 079 24X Fiche 50-400.82/10/07.8210270484
- 8210220075 Interim deficiency rept is design error in solid state protection sys Initially reported on 820909 Nestinghouse centinuing to review design & has revised to 4t procedures to verify contact clasure Also reported per Part 21 PARSONS.8 M Caralina Power / Light Co 82/10/08 0'REILLY, J P Region 2, Office of Director 4pp 15778 185 24X Fiche 50-400.82/10/08.621/22/0075
- 8210220412 Final deficiency rept re grout concrete interface failure on equipment pad frame initially reported on 820907 Embed frame renoved Concrete cuib chipped completely but & curb Arrame replaced PARSONS.R M Carolina Power & Light Co 82/10/08 O'REILLY, J P Region 2, Ofrice of Director 4pp (5778-358-244 Fiche 50-400,82/10/08,8210220412
- G210290260 Interim deficiency rept re gops botwoen mating surfacus of connections between structural steel members which also had A490 belts w/A325 nuts initially reported on 920618 Ebasco Svs. Inc evaluating problem PARBONS.R M Carolina Power & Light Co 82/10/13 0'REILLY, J PRegion 2. Office of Director 1p 15833 196 24X Fiche 50-400.82/10/13.8210270260
- 0210290258 Interim deficiency rept re grease between mating surfaces of structural connection designed as friction connection Initially reported on 820915 Ebasco Svcs. Inc currently evaluating problem Results expected by 830415 PARSONS-R M Carolina Power & Light Co 82/10/14 0'REILLY. J P Region 2. Office of Director 1p 15853 197 24X Fiche 50-400.82/10/14.8210290258
- 8210260378 Final deficiency rept re use of ABTM A307 bolts in lieu of A325 bolts specified in containment recirculating summ i cover structural steel Initially reported on 820703 Yield stress would not be exceeded Matter not reportable PARSONSIR IS Carolina Power & Light Co. 82/10/15 D'REILLY, J. P. Region 2. Office of Director 1p. 15806 135 24X Fiche 50-400, 82/10/15, 9210260378

- DOCKET 50-401 BHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8210130053 Summary of 820916-19 meeting w/util/Ebasco & Westinghouse re design review of instrumentation & control sys for facilities Followup meeting scheduled for 820914-16 in New York City, NY LICITRALE A Licensing Branch 3 82/09/08 Licensing Branch 3 5pp 15496 22 24K Fishe 50-400, 82/09/08 8210130053
- 8210010051 Ack receipt of 820823 ltr requesting temporary relief from commitments re training of shift technical advisors Program approved & request forwarded to NRR for evaluation O'REILLY.JF Region 2. Office of Director 82/09/20 JONES.J A Carolina Pawer & Light Co ip 15565-322 24X Fiche 50-000.82/09/20.8210010051
- 8210270324 Requests add1 info re instrumentation & control sys Info should be in form of response to IE Bulletin 79-21 re level measurement errors due to environ temp effects on level instrument ref legs Requests submittal date within 2 wis KERRIGAN-J D Licensing Branch 3 82/09/23 JONES.J A Carolina Power & Light Co. 2pp 15836-357 244 Fiche 50-400.82/09/23, 8210270324
- 0210031035 Forwards request for add1 info on FBAR Bection 440-0.
 "Reactor Bys"
 KERRIOAN, J. Licensing Branch 3 82/09/29 JONES, J. A. Carolina
 Power & Light Co. 7pp 15773 262 24X Fiche 50-400,82/09/29,
 8210210035
- 8210210258 Notification of 821012 meeting w/util & Ebasco in Bethesda. MD to discuss review of RCPB matls KADAMBI,N P Licensing Branch 3 G2/09/29 KERRIGAN,J Licensing Branch 3 Jpp 15774 324 24% Fiche 50-400,82/09/29.8210210258
- B210210320 Summary of 820914-16 meetings w/util.Westinghouse & Ebasco at Ebasco ofc re design review of instrumentation & control sys Attendance list encl LICITRALE A Licensing Branch 3 82/07/27 Licensing Branch & App 15782 087 24X Fichs 50-400.B2/07/29.8210210320
- 8210050106 Forwards 21 responses to Reactor Sys Branch (440 Series) questions discussed at Reactor Sys Branch safety review meeting held on 820921 Remaining 17 items will be addressed in near future MCDUFFIE,M A Carolina Pawer & Light Co 82/09/30 DENTON,H R Office of Nuclear Reactor Regulation. Director 27pp 13603 261 24% Fiche 50-400,82/09/30,8210050106
- 8210050125 Forwards responses to Instrumentation & Control Sys Branch 820730 questions re FBAR.confirming info discussed during 820916-19 & 0914-16 meetings MCDUFFIE.M A Carolina Power & Light Co 82/09/30 DENYON, H R Office of Nuclear Reactor Regulation, Director 54pp 15604 282 24% Fiche 50-400, 82/09/30, 8210050125
- 6210210312 Summary of 820921 meeting w/applicant.Westinghou E0&0 at site re Reactor Bys Branch 620426 questions concerning FBAR Attendance list encl KADAMBIN P Licensing Branch 3 B2/10/01 App 15782 078 BAY Fich- 50-400 27/10/0

- --B210260481 Informs that Topscal Rept AAF-TR-7101. "Design & Testing of Fan Cooler-Filter Sys for Nuclear Applications." acceptable Partial "Equipment Qualification Data Packages" enc! TEDESCO.R L. Atomic Energy Commission. Deputy Director for Technical Review (Pre-1975) 72/11/10 F15H, J.F. American All Filter Co. 54pp 15806-061 24% Fiche 50-400.82/10/20. 6210260462
- C Utility Environmental Report (ER), amends & correspondence
- 8210200032 Forwards responses to environ rept review Questions 240 % 291 13 & 291 15. comparing environ impact on Buckhorn Creek of operation of one unit w/o Cape Fear River Makeup Sys MCDUFFIE, M A Carolina Power & Light Co 62/10/15 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 21pp 15757 308 24X Fiche 50-400, 82/10/15. 8210200032
- 6210200084 Forwards Amend 4 to environ rept Summary of changes enc1 MCDUFFLE:M A Carolina Power & Light Co 62/10/15 DENTON, H R Office of Nuclear Reactor Regulation Director 2pp 15753 212 24X Fiche 50-400:82/10/15:8210200084
- --8210200086 Amend 4 to environ rept Aperture cards available in PDR
 4 Carolina Power & Light Co 82/10/15 279pp 15753 214 243
 Fiche 50-400,82/10/15,8210200084
- 8210280054 Forwards affidavit re distribution of Amend 4 to environ rept III rept II
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8210210212 Notifies of schedule change for DES Reservoir reanalysis has lead to delay in receipt of hydrological info Statement will be issued by 821217
 NOVAK.T M Assistant Director for Licensing 82/10/12 UTLEY.C E Carolina Power & Light Co. 2pp (5774-336) 24X
 Fiche 50~400.82101/12.8210210212
- F Security, medical, emergency & fire protection plans
- 8210010037 Forwards request for addl info,based on review of 820626 industrial security plans safeguards contingency plan & security personnel training & qualification plan Encl withheld (ref 10CFR2 790)

 KERRIGAN, J D Licensing Branch 3 82/09/20 JONES, J A Carolina Power & Light Co 2pp 15565 315 24X Fiche 50-400, 82/09/20, 8210010037
- 8210010349 Ack receipt of 820902 itr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-400/82-24 & 50-401/82-24 Response insufficient to determine if corrective action adequate LEMIS.R C Division of Project & Resident Programs 82/09/22 JONES.J A Carolina Power & Light Co 2pp 15569 213 24X Fiche 50-400.82/09/22.8210010349
- --8210010397 IE Insp Repts 50-400/62-24 & 50-401/62-24 on 620620-0720 Noncompliance noted failure to identify & correct nonconforming conditions on two field welds on Class IE electrical cable tray supports MACUELL. G F Division of Project & Resident Programs 62/08/03 9pp 15569 220 24% Fiche 50-400/62/09/22,8210010349

G Adjudicatory correspondence

- 8210120103 Add1 response to FOIA request for nine categories of records generated by present NRC Commissioners primarity Chairman Palladino & Commissioner Roberts & White House Forwards App B documents FELTON.J M Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project 3pp 15690 117 24X Fichs 50-000,82/07/12,8210120103
- --8210120123 Forwards memorandum & order re Council of NC objection to util request for exemption to perform certain site preparation work Hemorandum addresses exemption question & sets out history of Commission regulation. Section 50 12 ROBERTS-T M Commissioners 81/12/07 PALLADINO, N Commissioners 1p 15690 124 24X Fiche 50-000.82/07/12, 8210120103
- --B210120132 Memorandum & order re Council of NC objection to util request for exemption per revised NEPA regulation to perform certain site preparation work. NEPA does not bar preliminary work Site preparation work properly authorized BENDER.P C Atomic Energy Commission 74/06/11 Atomic Energy Commission 79/06/11 Atomic Energy Commission 9pp. 15570 125 24X Fiche, 50-000, B2/07/12, S2/0120103

- 8210010328 Supplemental statement re-validity of psychological stress contentions. Late filing criteria not applicable if contentions not admitted encil arguments should be considered amends to original contentions.

 READ, D F Chapsi Hill Anti-Nuclear Group Effort 82/09/17

 Atomic Safety and Licensing Board Panel 14pp 15569 174 24X

 Fiche 50-400, 82/09/17, 8210010328
- 6210010337 Suppl to Chapel Hill Anti-Nuclear Group Effort/Environ law Project 620713 renewed & reformed motion to postpone proceedings, originally submitted on 820316 Suppl based on new info Certificate of Svc enci READ, D.F. Chapel Hill Anti-Nuclear Group Effort 82/09/24 Atomic Safety and Licensing Road Panel 7pp 15569 166 24X Fiche 50-400.82/09/24.8210010337
- 8210150192 Requests clarification of docket numbers for Harris & Peyrq plants Mixup may be causing prejudice to intervenors since documents go to incorrect LPDR HIATT.8 L Ohio Citizens for Responsible Energy 82/10/04 Docketing & Services Branch ip 15707 260 24X Fiche 50-000.82/10/04.8210150192
- 8210190305 Advises that commercial operation date for Unit 1 changed from Fall 1785 to Spring 1986 No funds to be allocated in 1783 for const work on Unit 2 Most of requested rate hike disallowed W/Certificate of Svc Related correspondence FLYNN.S F Carolina Power / Light Co 82/10/06 KELLEY.J L, BRIGHT, C O . CARPENTER, J H Atomic Safety and Licensing Board Parel 4pp 15704 336 24X Fiche 50-400.82/10/06.8210150305
- 8210150340 Objections to ASLB 820922 prehearing conference memorandum 3 order Certificate of Svc enci READ, D F Chapel Hill Anti-Auclear Group Effort 82/10/08 Atomic Safety and Licensing Board Panel 7pp 15705 357 24y Fichs 50-400.82/10/08.8210150340
- 8210200053 Responds to ASLB 820922 older ruling on contention & five of documents Ruling on Contention IVC % on motion roleve of documents should be reconsidered Arrangements for secunacceptable since parties unrelated W/Certificate of Sec WILSON, R.D. Wilson, R. 82/10/14 5pp. 15753 088 24% Fiche 50-400, 82/10/14,8210200053
- 62102(0348 Response to ASLB 620922 memorandum & order Objects to portion of order dealing w/svc of documents & comments on security plan & structure of discovery process Notice of appearance & Certificate of Svc uncl RUNKLE, J D Conservation Council of North Carolina RUNKLE, J b Arfilsation Unknown 62/10/14 6pp 15764 204 24X Fiche 50-400, 82/10/14, 8210210348
- 821020009 Forwards objections to & requests for clarification of ASB 820922 memorandum & order & response to Chapol Hill Anti-Nuclear Group Effort supplemental statement repsychological stress contentions Certificate of Svc encl BAXTER. TA Shaw, Pittman, Patts & Troubridge BAXTER. TA Carolina Power & Light Co. 02/10/15 KELLEV.J L. BRIGHT. O. CARPENTER.J H. Abomic Safety and Licensing Board Panel App. 13755 001 24X Fiche 50-400, 82/10/15. G210200009
- --B210200013 Response opposing Chapel Hill Anti-Nuclear Group Effort B20927 supplemental statement re psychological stress contentions ASLB obligated to follow Commission policy statement on psychological stress issues BAYTER. TA Carolina Power & Light Co BAXTER. TA Shaw. Pittman. Potts & Troubridge B2/10/15 Atomic Safety and Licensing Board Panel Spp 15755 005 24X fichs 50-400. B2/10/15, B2/10/200009
- --8210200021 Objections to \$ requests for clarification of ASLO 820922 memorandum \$ order Addl info re util plans on proposed Cape Fear River intake facility provided Ruling on H Eddleman Contention 132 should be clarified to specify bases O'NEILL.JH Capolina Power & Light Co O'NEILL.JH Shaw. Pittman, Potts & Troubridge 82/10/15 Atomic Safety and Licensing Board Panel 17pp 15755 010 24X Fiche 50-400,82/10/15.8210200009
- 8210210308 Notice of appearance in proceeding Certificate of Svc entl OREENBLATT.D Eddieman. W OREENBLATT.D Greenblatt. D 82/10/15 Atomic Bafety and Licensing Board Panel 3pp 15764 241 241 Fiche 30-400, 82/10/15, 8210210308
- 8210210376 Objections to ASLB 820922 memorandum & order reflecting decisions made at prehearing conference Objects to rulings on svc of util decuments, contentions & cancelation of Unit 2 Certificate of Svc encl EDDLEMAN.M. Eddlemen. W 82/10/15 14pp 15763 150 24X Fiche 50-400, 82/10/15,8210210376

- 6210210419 Response to ASLB 820922 memorandum % order re use of sacurity plan experts as withesses GREENBLATT D Eddleman, W PAYNE, M T Kudzu Alliance RUNKLE, J Chapel Hill Anti-Noclear Group Effort 82/10/15 4pp 15763 076 24% Fiche 50-400,82/10/15,8210210419
- 6210700062 Forwards consolidated list or admitted & deferred contentions per ASLB 820922 order Agreement should be reached on wording 5 numeration to facilitate heatings & avoid misunderstandings N/o encl 8ARTM, C A Heating Branch 1 82/10/18 RUNKLE, J Conservation Council or North Carulina EDDLEMAN, W Eddleman, W READ, D F Chapel Hill Ant-Nuclear Group Effort Ip 15756 152 24X Fiche 50-400, 82/10/18, 8210200062
- 6210250048 Complains about sic of documents & LPDR copy machine EDDLEMAN.N Eddleman, V 82/10/19 KELLEY, J L , CARPENTER, J H , BRICHT, C O Atomic Safety and Licensing Buard Panel 2pp 15787 045 24x Fiche 50-400,82/10/19,8210250048

H General correspondence

- 52)0010028 Requests NRC direct all official correspondence to EE Utley, util vice-president due to 820930 retirement of JA Jone JCFS. J A Carolina Power & Light Co 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation. Director ip 15565-314 24% Fiche 50-000.82/09/27.6210010028
- 6210130323 Requests changes to distribution list for NUREO-0020, 'Licensed Operating Reactors - Status Summary Rept "
 ZIMMERMAN'S R Carolina Power tight Co 82/10/11 DEEPE, M.R.
 ADP Systems Development Dranch 2pp 15683 361 24x
 Fiche 50-000, 82/10/11, 8210130323
- 4 Inspection reports. IE Dulletins & correspondence
- 6210010086 Forwards IE 10sp Repts 50-400/82-27 % 50-401/82-29 on 620830-0902 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs B2/09/13 JDF-25.J A Carolina Power & Light Co 2pp 15565 260 24X Fiche 50-400, 62/09/13, 6210010086
- -B210010091 IE Insp Repts 50-400/82-29 b 50-401/82-29 on B20830-0902 Nu noncompliance noted Majoi areas inspected Const progress, safety-related piping RCPB piping steel structures & reactor vessel internals KLEINSORGE, W.P. BLAYE J.J. Finision of Engineering & Technical Programs 82/09/10 10pp 15565-262 24X Fiche 50-400.82/09/13, 6210010006
- F210010102 Forwards IE Investigation Repts 50-400/82-23 & 50-401/82 23 on 820603-23 No noncompliance noted CREILLY, J.P. Region 2, Orice of Director 82/09/13 JONES, J.A. Carolina Power & Light Co. 2pp. 15566-041 24X Fiche 50-400, 82/09/13, 8210010102
- --B210010111 IE Investigation Repts 50-400/B2-23 & 50-401/B2-23 on 020606-23 No noncompliance noted Major areas investigated allegations re-forging of GC inspector initials on weld data rept VORSE, J Y . URYC.D , ALDERSON.C E Region 2, Office of Director B2/09/09 3pp 15566 043 24x Fiche 50-400.B2/09/13,B210010102
- 5210010349 Ack receipt of 820702 ltr informing NRC of steps taken to currect violation noted in 1E this Repts 50-400/82-24 & 50-401/82-24 Response insufficient to determine if corrective action adequate
 LEWIS.R C Division of Project & Resident Programs 82/09/22
 JONES.J A Carolina Power & Light (a 2pp 15569 213 24X Fiche 50-400, 82/09/22,8210010349
- -8210010360 Responds to IRC 820804 itr reviolation noted in IE Insp Repts 50-400/82-24 & 50-401/82-24 Corrective actions Hanger ED 2622 & Item 1436-10 reinspected & repaired New Inspector under training in GC welding required to pass written insp PARSONG,R M Carolina Power & Light Co 82/09/02 D'REILLY, J P Region 2, Office of Director 2pp 15569 215 24X Fiche 50-400,82/09/22,8210010349
- --8210010368 Forwards IE insp Repts 50-400/82-24 & 50-401/82-24 on 820620-0730 & notice of violation LEHIB, R C Division of Project & Resident Programs 82/08/04 JUNES, J A Carolina Power & Light Co 2pp 15569 217 24X Fiche 50-400,82/09/22.8210010349
- --8210010397 IE Insp Repts 50-400/82-24 & 50-401/82-24 on 820620-0720 Noncompliance noted failure to identify & correct nonconforming conditions on two field welds on Class IE electrical cable tray supports MACNELL, 0 F , BURGER, C M Division of Project & Resident Programs 82/08/03 9pp 15567 220 24% Fiche 50-400, 82/09/22, 8210010349

- 8210220160 Forwards IE Insp Repts 50-400/82-30 & 50-401/82-30 on 820820-0910 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/10/04 JDNES, J A Carolina Power & Light Co 2pp 15778 072 24X Fiche 50-400, 82/10/04, 8210220160
- --B210220163 IE Insp Repts 50-400/82-30 & 50-401/82-30 on B20820-0710 No noncompliance noted Major areas inspected foilowup on previously identified items.concrete.piping & personnel training MAXHELL.OF, BURGER.C W Division of Project & Resident Programs B2/07/30 6pp 15778 074 24% Fishe 50-400.82/10/04.8210220160
- 820B170233 IE Info Notice 80-35, Suppl I, "Leaking & Disiodged [-125 Implant Seeds " Svc Iist encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24< Fiche 50-000.82/10/06.8208190233
- 8210220127 Ack receipt of 820923 ltr Informing NRC of steps taken to correct vialations noted in IE lnsp Repts 50-400/82-24 & 50-401/82-26 LEMIS.R C Division of Project & Resident Programs 82/10/12 UTLEY.E E Carolina Power & Light Co Ip 15778 122 24X Fiche 50-400.82/10/12.8210220127
- ---8210220137 Forwards IE Insp Repts 50-400/82-26 & 50-401/82-26 on 820802-06 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/08/30 JONES, J A Carolina Power & Light Co 2pp 15778 125 24X Fichs 50-400,82/10/12,8210220127
- --8210220145 IE Insp Repts 50-400/82-26 & 50-401/82-26 on 820802-06 Noncompliance noted failure to analyze cut rebars for acceptability WRIGHT, R W , DEBBAGE, A Q , UPRIGHT, C M Division of Engineering & Technical Programs 82/08/25 13pp 15778 128 24X Fiche 50-400,82/10/12,8210220127
- 62/08/1902/38 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter Beainless Steel, Recirculation Sys
 Piping at BUR Plants "Svc list encl
 DEYOUNO, R C Director's Office. Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche 50-000.82/10/14.82/08/1902/38
- S Reportable occurrences. LERs & related correspondence
- 9210180193 Part 21 rept re faulty pips support shop welds initially reported on 820813 insp criteria being reviewed Deficient supports returned to Bergen-Paterson for insp Naxt rept will be completed by 930701 CHANGI,N J Carolina Power & Light Co 82/09/13 O'REILLY, J P Region 2. Office of Director 4pp 15719 114 24X Fiche 50-400, 82/09/13, 6210160193
- R210080180 Deficiency rapt re use of ASTM-A307 nuts & bolts for bolted connection in lieu of required ASTM-A325 nuts & bolts Initially reported on 920703 Ebasco Svcs currently evaluating problem A11 bolts replaced/reinspected PARSONS; R M Carolina Power & Light Co 82/09/30 D'REILLY, J P Region 2, Office of Director 1p 15640 169 24X Fiche 50-400, 82/09/30, 8210080180
- 8210080283 Interim deficiency rapt re sheared pinion keys on Limitorque valve motor operators initially reported on 820703 Westinghouse discussing problem w/Limitorque Final rept will be submitted by 830401 Also reported per Part 21 PARSONS.R II Carolina Power & Light Co 82/10/01 O'REILLY.JP Region 2. Office of Director 3pp 15638 320 24X Fiche 50-400.82/10/01.8210080283
- 8210130567 Addendum 2 to 820319 deficiency rept re inadequately welded study on embedded strip plates Addendum provides info re shipment of embeds (Type II strip plates & crane rail plates) & any associated problems
 PARSON,R M Carolina Power & Light Co 82/10/05 O'REILLY, J P
 Region 2, Office of Director 5pp. 15683 II3 24X
 Fiche 50-400, 82/10/05,8210130567
- 8210220484 Interim deficiency rept re defective governor drive coupling in smergency diesel engine-generator sets from Transamerice Delayai Initially reported on 820909 Coupling will be reglaced Also reportable per Part 21 PARBONS,R M Carolina Power & Light Co 82/10/07 O'REILLY, J P Region 2, Office of Director 4pp 15779 079 24X Fiche 50-400,82/10/07,8210220484

- 5210220075 Interim deficiency rept re design error in solid state protection sys Initially reported on 820909 Westinghouse continuing to review design & has revised test procedures to verify contact closure Also reported per Part 21 PARSONS.R H Carolina Power & Light Co 82/10/08 D'REILLY, J P Region 2: Orfice of Director 4pp 15778 185 244 Fiche 50-400, 82/10/08, 8210220075
- GZ10220412 Final deficiency rept re grout concrete interface failure on equipment pad Frame Initially reported on 820909 Embed frame removed Concrete Curb chipped completely out & curb PARSONS, R H Carolina Power & Light Co 82/10/08 Region 2, Office of Director 4pp 15778 358 24x Fiche 50-400, 82/10/08, 8210220412
- 6210290260 Interim deficiency rept to gaps between making surfaces or connections between structural steel members which also had A490 bolts w/A225 nuts initially reported on 820618 Ebasco Svcs Inc evaluating problem PARSONS.R M Carolina Power & Light Co 82/10/13 0'REJILLY, J R Region 2. Office of Director 1p 15853 174 24x Fiche 50-400, 82/10/13 6210290260
- 8210290259 Interim deficiency rept re grease between mating surfaces of structural connection designed as friction connection. Initially reported on 820915 Ebasco Svcs.inc currently evaluating problem Results espected by 930415 PARSONS.R H Carolina Power & Light Co. 62/10/14 D'REILLY, J. P. Region 2. Office of Director 1p. 19853 197 24X Fiche 50-400.62/10/14.8210290258
- 8210260398 Final deficiency regt or use of ABTM A307 bolts in lieu of A325 bolts specified in containment recirculating sump I cover structural steel [nitially reported on 820703 Yield stress would not be exceeded Matter not reportable PARSONS,R If Caroline Power & Light Co 82/10/15 O'REILLY, J.P. Pegion 2, Office of Director 1p 15806 135 24X Fiche 50-400, 82/10/15, 8210260398

DOJKET 59-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

- O Adjudicatory correspondence
- 6210120103 Add1 response to FD1A request for nine categories of records generated by present NAC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards documents FFLTON, J H Division of Rules and Records 82/07/12 Critical Mass Energy Project 3pp 15690 117 24X Fiche 50-000,82/07/12,8210120103 82/07/12 UDELL, R A
- --8210120123 Forwards memorandum & order re Council of NC objection to contents of the second of the
- --B210120132 Memorandum & order re Council of NC objection to util request for exemption per revised NEPA regulation to perform certain site preparation work NEPA does not bar preliminary work Site preparation work properly authorized BENDER:P C Atomic Energy Commission 74/06/11 Atomic En-Commission Bpp 15870 123 24% Fishe 50-000,82/07/12: Atomic Energy 8210120103

DUCKET 50-403 SHEARON MARRIS NUCLEAR POWER PLANT, UNIT 4 arm correspondence

> request for name categories of records ioners, primarity Chairman i'alte House Forwards

> > rds 82/07/12 190 [17 24X UDELLIR A

> > > NC objection to

ķ

-- 8210120132 Memorandum & order re Council of NC objection to util request for exemption per revised NEFA regulation to perform certain site preparation work NEPA does not bar preliminary work Site preparation work properly authorized BENDER.P C Atomic Energy Commission 74/06/11 Atom Commission Spp 15690 125 24X Fiche 50-000.82/07/12. Commission 8210120103

DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

- 8210070016 Forwards request for add1 info re 820708 application for (Pertension of Unit 3 Info needed to assess environ impact of allowing CP for Unit 4 to expire ADENSAM.E 0 Licensing Branch 4 82/09/22 FERCUSON.J H Virginia Electric & Power Co 3pp 15646 301 24X Fiche 50-404.82/09/22.8210070016
- 8210040277 Advises of plans for const of new 230 kV transmission line C1UJ4V2// AGVISES OF Plans for Const of new 230 kV transmiss to connect North Anna power station to Louisa substation No Tech Spec or ETS change required LEASBURG, R H Virginia Electric & Power Co 82/09/27 DE Office or Nuclear Reactor Regulation. Director CLARK, R A Operating Reactors Branch 3 2pp 15591 204 24x Fichs 50-338.82/09/27.8210040277
- ~8210040325 Advises that proposed 230 kV transmission line between Nulls Anna & Louisa need not be evaluated in amend to environ rept for North Anna 1 & 2 Line is not part of North Anna utilization facility ACGONE, S. Virganta Electric & Power Co. 74/01/02 MULLER, D. R. Atomic Energy Commission 2pp 15591 329 24X
 Fiche 50-338, 82/09/27, 8210040277
- 8210180418 Advises that RL Tedesco no lenger emplayed by NRC T Novik is Assistant Director for Licenaing ADENSAM.E O Licenaing Branch 4 82/10/01 FERGUSON.J H Virginia Electric & Power Co 2pp 15745 288 24X Fiche 30-404.82/10/01. 821018041B
- O Inspection reports, IE Bulletins & correspondence
- 8210010380 Forwards IE Insp Rept 50-404/82-10 on 820830-0902 No noncompliance noted DAKCE, H.C. Division of Project & Resident Programs 82/09/13 LEASBURG, R.H. Virginia Electric & Power Co. 2pp. 15573 081 24x Ficha 50-404,82/09/13,8210010380
- --8210010384 IE Insp Rept 50-404/82-10 on 820830-0902 No noncompliance noted Major areas interected storage, preventive maint, measuring & test equipment calibr & followup on licensee measuring & test equipment calibr & followup on licensee identified items
 MERRIMEATHER, N. CONLON.T E Division of Engineering & Technical Programs 82/09/09 4pp 15573 083 24% Fiche 50-404,82/09/13,8210010380

DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4

- A Application/construction stage documents & correspondence
- 8210070014 Forwards request for add1 info re 820708 application for CP eluviusia rorwands request for Addl info re 820708 application for (
 settension of Unit 3 Info needed to assess environ impact of allowing CP for Unit 4 to expire
 ADENSAM, E 0 Licensing Branch 4 82/09/22 FEROUSON, J H Virgin Electric & Power Co Spp 15446 301 24% Ficha 50-404.82/09/22, 8210070016
- 8210040277 Advises of plans for const of new 230 kV transmission lint to connect North Anna power station to Louisa substation
 NO Tech Spec or ETB Change required
 LEABOURGER H Virginia Electric & Power Co 82/09/27 DENTON
- ~-8210040325 Advises that proposed 230 kV transmission line between Marth Anna & Louisa need not be evaluated in amend to environ rept for North Anna 1 & 2 Line is not part of North Anna utilization facility RAQQNE, 8 Virginia Electric & Power Co 74/01/02 MULLER.D R Atomic Energy Commission 2pp 15591 329 24X Fiche 50-338,82/09/27,8210040277

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

- F Security, medical, emergency & fire protection plans
- 6210040184 Forwards [E Investigation Rept 50-409/82-09 on 620615-17 No noncompliance noted HIMO J A Division of Emergency Preparedness & Operational Support 62/09/09 LINDER:F W Dairyland Power Cooperative 2pp 15582 001 24x Fiche 50-409,82/09/09,8210040184
- -8210040185 IE Investigation Rept 50-409/82-09 on 820615-17 No noncompliance noted Major areas inspected procedures & records & personnel interviews or health physics technicians listed in 820308 emergency plan. Revision i PHILLIP, G. A., PAGLIARO, J. A., WARNICK, R. F. Region 3, Office of Director 82/09/02 27pp 15582 003 24X Fiche 50-409, 82/09/09, 8210040184
- 6210040152 Forwards response to 820510 request for add1 info re rewrite or Section 8 of fire protection rule 10CFR50 48 Revised procedures re complete loss of electrical power themselver reactor couldown from outside coult of toom encit INDER. F. Dairyland Power Cooperative 82/09/28 CRUTCHFIELD. D. Decrating Reactors Branch 5 90pp 15582 353 24X Fiche 50-409.82/09/28.8210040152
- 8210130365 Forwards info re containment leak testing, per NRC 820824 request Info withheld (ref IOCFR73 21)
 LINDER, F. Dairyland Power Cooperative 82/09/28 CRUTCHFIELD, D. Operating Reactors Branch 5 1p 19630 246 24X
 Fiche 50-407, 82/09/28, 8210130365
- t-210150497 Forwards 1E Insp Rept 50-409/82-12 on 820701-0831 No noncompliance noted STREETER, J.F. Division of Emergency Proparedness & Operational Support 82/09/28 LINDER, F.W. Dairyland Power Cooperative 2pp 15721 280 24% Fiche 50-409,82/09/28,8210150497
- --B210150502 IE Insp Rept 50-409/82-12 on 820701-0831 No noncompliance noted Hajor areas inspected operational safety verification, menthly maint k surveillance observation. LER fullowup & fire protection/prevention annual insp BRANCH.M W Division of Emergency Preparedness & Operational Support WALKER.R B Region 3. Office of Director 82/09/21 /pp 15721 282 24x Fiche 50-409/02/09/28.8210150497
- 92(0050339 Provides status of technical support for & emergency operations facility Dasic technical support for & emergency operations facility established & used in emergency erectises
 LINDER.F. Dairyland Powel Cooperative 82/09/29 EISENHUT.D 0
 Division of Licensing App (5610-114 24X Fishe 50-409.82/09/29, 8210050339
- 0210280045 Releases public version of revised emergency plan & revised emergency plan implementing procedures FELTON. J H Division of Rules and Records 82/10/08 Document Management Branch 1p 15861 347 24X Fiche 50-409.02/10/08.
- -8210280048 Forwards public version of Revision 3 to emergency plan & revised implementing procedures including Procedures EPP-2 re organization & operations during emergencies & EPP-14 re emergency plan training (INDER, F. Dairyland Power Copperative 82/09/27 CRUTCHFIELD, D. Operating Reactors Branch 5 1p 15841 348 24X Fiche 50-409,82/10/08.8210280045
- -B210280051 Forwards public version of Revision 3 to emergency plan & revised emergency plan implementing procedures. Including Procedures EPP-2 re organization & operations during emergencies & EPP-14 re emergency plan training LIMBER.F Dairyland Power Cooperative 82/09/15 KEPPLER.J G Region 3. Office of Director 2pp 15861 349 24X Fiche 50-409, 82/10/08.8210280045
- --8210280053 Public version of Revision 3 to emergency plan + Dairqland Power Cooperative 82/09/03 25pp 15861 351 24X Fiche 50-409,82/10/08,8210280045
- --8210280055 Public version of revised emergency plan implementing procedures including Procedures EPP-2 re organization & operations during emergencies & EPP-14 re emergency plan training LINDER.F Dairyland Power Cooperative 82/07/03 114pp 15862 015 24% Fiche 50-405, 82/10/08,8210280045

- 8210220176 Responds to NRC 820715 ftr re iE Emergency Preparadness Insp. Rept 50-409/82-1t on 820803 Corrective actions Tech Spec change to emergency operating facility data acquisition sysmill be installed & operating during Oct 1982 LINDER: F. Dairyland Power Cooperative 82/10/11 HIND. J. A. Division of Emergency Preparadness & Operational Support 9pp. 18777-295 24X Fiche 50-409.82/10/11,8210220176
- 8210250349 Forwards revisions to physical security, contingency & training & qualification plans Revisions withheld (ref 10CFR73 21) at 10 Cooperative 82/10/20 CRUTCHFIELD. D Operating Reactors Branch 5 2pp 15790 045 24x Filhs 50-409.82/10/20.8210250349
- 8210260371 Requests that R Walker be added to Enci 1 of 820715 ltr to provide for unescorted access to vital & protected areas KEPPLER.J O Region 3. Office of Director 82/10/20 LINDER.F W Dairyland Power Cooperative 1p 15803 106 24X Fiche 50-409,82/10/20.8210260371
- 8210270129 Forwards IE Safeguards Insp Rept 50-409/82-16 on 820920-24 & notice of violation betails & notice of violation withhold (ref 10CFR73 21)
 MILLER, J. R. Division of Engineering & Technical Programs 82/10/26
 LINDER, F. W. Dairgland Power Cooperative 2pp 15852 355 24X
 Fiche 50-409, 82/10/26, 8210270129
- --8210290137 IE Safeguards Insp Rept 50-409/82-16 on 820920-24 Noncompliance noted security equipment not alarm equipped & not tested properly Details withheld (ref 10CFR73 21) PIRTLE-0 L . OREED.J R Region 3. Office of Director 82/10/20 2pp 15693 357 24X Fiche 50-409.82/10/26.8210290129
- J Insurance & indemnity information
- 8210220009 Responds to NRC 820812 questions re util request for exemption from requirements of 10CFR50 54(w) concerning property insurance
 LINDER.F Dairyland Power Cooperative 82/09/13 SALTZMAN. J
 Assistant Director for State & Licensee Relations 5pp 15778 214
 24X Fichs 50-409,182/09/13, 8210220009
- P Operating license stage documents & correspondence
- 8210010389 Forwards revised Page 36g to Tech Specs.per 820915
 proposed anend to License DPR-45
 LINDER.F Dairyland Power Cooperative 82/09/23 CRUTCHFIELD.D
 Operating Reactors Branch 5 ip 15574 291 24X
 Fiche 50-409.82/09/23.8210010389
- ---8210010374 Revised proposed Page 36g to Tech Specs re radioactive gaseous efficient monitoring instrumentation

 * Dairyland Power Cooperative 82/09/23 ip 15574 292 24X Fiche 50-409,82/09/23,8210010389
- 8210040067 Forwards safety evaluation of util 820305 to 0826 assessments of SEP Topic XV-1. "Decrease in Feedwater Temp, Increase in Foedwater Flow & Increase in Steam Flow " Evaluation will be basic input to integrated safety assessment Topic complete CRUTCHFICLD.D Operating Reactors Branch 5 82/09/29 LINDER, F Dairyland Power Cooperative 15pp 15581 220 24X Fiche 50-409, 82/09/29, 8210040067
- --8210050068 "ECCS Repts (F-47).TMI Action Plan Requirements.Dairgland Fower Cooperative.ACBMR," request for addl info VUSBURY.F M., OVERBECK.G J Franklin Institute/Franklin Research Center NRC-03-BI-I30 RAI-C5506-196 82/08/25 CHOW.E NRC-No Detailed Affiliation Given 3pp 15603 231 24X Fiche 50-409,82/09/29.8210050065
- 6210050067 Application to amend License DPR-45, revising Tech Specs re safety valves installed on RCS. LINDER,F Delryland fower Cooperative 82/09/29 CRUTCHFIELD,D Operating Reactors Branch 5 5pp 15603 176. 24X Fichs 50-407. 82/09/29,8210050067
- --8210050070 Proposed Tach Specs re sefety valves installed on RCS * Dairyland Power Cooperative 82/09/29 26pp 15603 201 24x Fiche 50-409,82/09/29,8210050067

- E210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820907 Itr Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in Licensee/NRC interface KACICH-R M SEP Dwners Croup 82/10/07 ETSEHHUT, D & Division of Licensing 7pp 15682 179 24X Fiche 50-000,82/10/07,8210130326
- 6210180183 Provides guidance & clarification for response to NUREG-0737. Item IT 8 3 "Post-Accident Sampling Sys," per 820830 request for additinfo CRUTCHFIELD. D. Operating Reactors Branch 5 62/10/07 LINDER.F Dairyland Power Comperative Spp 15718 179 24X Fiche 50-409, 82/10/07.8210180183
- 8210220272 Forwards final topic evaluation for sys aspects of safe shutdown requirements for SEP Topics V-10 B.V-11 B & VII-3, "RHR Reliability," "RHR Interlock Requirements," & "Sys Required for Safe Shutdown," respectively CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/07 LINDEK.F Dairyland Power Cooperative 53pp 15775 140 24% Fiche 50-409, 82/10/07, 8210220272
- 8210150203 Forwards completed Table Loriginally submitted w/NRC 82082/ evaluation of SEP Topic VI-4, "Containment Isolation Sys " Containment most made since 1964 comply w/DRN--NSIC-5 LINDER: Dairyland Power Copperative 82/10/08 CRUTCHFIELD.D Operating Reactors Branch 5 Jpp 15701 320 24x Fichs 50-409:82/10/08.8210150203
- 8210150375 Forwards safety evaluation re SEP Topic XV-9, "Startup of Inactive Loap or Rectroviation Loap at Incorrect Temp " Plant in conformance w/SRP Sections 15 4 4 5 15 4 5 requirements & analysis acceptable CRUTCHFIELD.D Operating Reactors Branch 5 82/10/12 LINDER.F Baryland Power Cooperative 7pp 15715 166 24X Fiche 50-409, 82/10/12, 82/0150375
- 8210190446 Provides unresolved safety issue status in response to 820606 request LINDER: Posityland Power Cooperative 82/10/13 LAINAS.0 C Assistant Director for Safety Assessment 7pp 15740 162 24X Fiche 50-409: 82/10/13:8210190446
- 82:0200015 Forwards evaluation of SEP Topic VI-1. "Organic Matls & Post-Accident Chamistry " Design meets licensing criteria for topic based on consideration of unique noncirculating ECCS design.
 CRUTCHFIELD. B Operating Reactors Branch 5 82/10/14 LINDER:F Dairyland Power Cooperative 6pp 15757 334 24x Fiche 30-407.82/10/14.8210200015
- 8210200025 Forwards evaluation of SEP Topic XV-16. "Radiological Consequences of Failure of Small Lines Carrying Primary Cociant Dutside Containment LACBUR " Facility meets current licensing criteria for topic CRUTCHFIELD.D Operating Reactors Branch 5 82/10/14 LINDER.F Dairyland Power Cooperative 5pp 15755 028 24X Fiche' 50-407, 82/10/14, 8210200025
- 821020003i Forwards evaluation of SEP Topic XV-20. "Radiological Consequences of Fuel Damaging Accidents " Evaluation will be included in integrated safety assessment Thyroid dose at exclusion area boundary within 10CFR100 requirements CRUTCHFIELD.D Operating Reactors Branch 5 82/10/14 LINDER.F Dairyland Power Cooperative 5pp 15757 329 24X Fiche 50-409-82/10/14-821020003i
- 8210200038 Forwards evaluation of SEP Topic XV-19, "LDCA Resulting From Spectrum of Piping Breaks Within RCPB (Radiological) LACSBR," Util meets current licensing criteria for topic CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/14, LINDER, F. Dairyland Pouer Cooperative 5pp 15757 299 24X Fiche 50-407-82/10/14, 210200038
- 8210220447 Forwards safety evaluation & supporting technical rept for licensee BIE208 proposed electrical sys design mods & Tech Spec changes re degraded grid voltage protection Proposed changes acceptable SEP Topic VIII-I A complete.
 CRUICHFIELD.D Operating Reactors Branch 5 82/10/14 LINDER, F Dairyland Power Cooperative 7pp 15778 339 24X
 Fichs 50-409, 82/10/14.8210220449
- 8210200016 Forwards evaluation of SEP Topic II-2 C re atmospheric transport & diffusion characteristics for accident analysis. Section V X/Q values appropriate for estimating exposures & should be used in all but steam line break calculations CRUTCHFIELD. Operating Reactors Branch 5 92/10/15 Linder, F Deiryland Power Cooperative 4pp 15752 357 24X Fiche 50-409, 82/10/15, B210200016

f

1

- 8210210246 Advises NUREG-0737. Item II K 3 27. "Common Ref Level." complete since util committed to eliminate potential operator confusion when changing water level instrumentation by integrating Items II K 3 27 ½ i D 1 CRUTCHFIELD. D Operating Reactors Branch 5 82/10/15 LINDER.I Dairyland Power Cooperative 2pp 15766 245 24X Fiche 50-409.82/10/15.8210210246
- 8210260319 Advises that TMI Items 11 D 3 % II F 1 2. "Reactor Vessel Liquid" % "Stack Effluent Sampling Sys." respectively, were completed on 820927 prior to refueling outage TMI Item III D 3 4 will be completed by 830101 LINDER.F Dairyland Power Cooperative 82/10/20 EISENHUI.D C Division of Licensing 1p 15805 227 24X Fiche 50-409,82/10/20 8210260319
- 8210290307 Submits summary of review of SEP Topic III-3 A re effects of design basis flood on containment & turbine bldg structures Response satisfies NRC requirement for addit flooding effects into LINDER: F Dairyland Power Cooperative 82/10/22 CRUTCHFIELD, P Operating Reactors Branch 5 3pp 15853 167 24x Fiche 50-409, 82/10/22, 9210290307
- B210290151 Forwards summary of outages of manual depressurization system in 1976-1980 per NRC 820929 request re TM1 Action Item II K 3 17 Sus performed adequately during reporting period Sys used for testing only LINDER: F Dairyland Power Cooperative 82/10/25 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15853 151 24X F(che 50-409, 82/10/25, 821029015)
- 8210280289 Forwards evaluation of SEP Topic iX-1. "Fuel Storage." bases on 820226 safety assessment rept & 820831 addl info Fuel storage facilities acceptable Evaluation will be basic input to integrated safety assessment CRUTCHFIELD.D Operating Reactors Branch 5 82/10/26 LINDER.J Dairyland Power Cooperative 7pp 15837 033 24X Fiche 50-409.82/10/26.8210280289
- a Inspection reports, IE Builetins & correspondence
- 8210040184 Forwards IC investigation Rept 50-409/82-09 on 620615 17 No noncompliance noted MINO.J A Division of Emergency Preparedness & Operational Support 82/09/09 LINDER:F W Dairyland Power Cooperative 2pp 15582 001 24X Fiche 50-409.82/09/09.8210040184
- --8210040185 iE Investigation Rept 50-409/82-09 on 820615-17 No noncompliance noted Major areas inspected procedures & records & personnel interviews re health physics technicians listed in 820308 emergency plan. Revision i PHILLIP, 0 A . PAGLIARO, J A . MARNICK, R F . Region 3, Office of Director 82/09/02 27pp 15582 003 24X Fiche 50-407.82/09/03, 8210040184
- 8210130400 Forwards IC insp Rept 50-409/82-14 on 820809-13 & netice of violation
 KEPPLER, J G Region 3, Office of Director 82/09/24 LINDER, F H
 Dairyland Power Cooperative 2pp 15682 072 24X
 Fiche 50-409, 82/09/24, 8210130400
- --921013D403 Notice of violation from insp on 820B09~13 KEPFLER, J O Region 3, Office of Director 82/09/24 15682 074 24X Fiche 50-409, 82/09/24, 82;0130400
- --B21013040B IE Insp Rept 50-409/B2-14 on B20809-13 Noncompliance noted radiation levels in excess of DOT regulations, failure to meet burial sites acceptance criteria & uncontrolled release of radioactive liquide PAUL.R A Division of Engineering & Technical Programs OREOER.L R Region 3, Office of Director B2/09/20 Bpp 15682 076 24X Fiche 50-409,82/09/24.8210130400
- --B210130416 Discusses apparent violation of 10CFR47 by util re radvasty shipment containing radioactive low-specific activity on 820730 Readings from util & Chem Nuclear Sys, Inc instruments show apparent discrepancy SHAFER, PW Deiryland Power Cooperative 82/08/17 QREGER, L & Division of Project & Resident Programs 12pp 15682 084 24X Fiche 30-409,82/09/24,8210130402
- 8210150497 Forwards IE Insp Rept 50-409/82-12 on 820701-0831 No noncompliance noted BTREETER, J. F. Division of Emergency Preparedness & Operational Support 82/09/28 LINDER, F.W. Dairyland Power Cooperative 255 15721 280 24X Fiche 50-409.82/09/28,8210150497

- --8210150502 IE Insp Rept 50-409/82-12 on 820701-0831 No noncompliance noted Major areas inspected operational safety verification, monthly maint & surveillance observation, LER followup & fire protection/prevention annual insp RANCH, M W Division of Emergency Preparedness & Operational Support WALKER, R D Region 3. Office of Director 82/09/217pp 15721 282 24% Fiche 50-409.82/09/28.8210150497
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implent Seeds " Svc list entl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000, 82/10/06, 8208190233
- 8210130211 Confirms conversation between J Taylor & R Maiker rascheduling mgt meetings for 821017 at facility to discuss systematic assessment of licensee performance Second meeting will fallow to discuss regulatory improvement program SPESSARD, R L Division of Project & Resident Programs 82/10/07 LINDER; F W Dairyland Power Cooperative 1p 15674 116 24X Fiche 50-407, 82/10/07, 82/0130211
- 0210220176 Responds to NRC 820915 itr re IE Emergency Preparedness Insp Rept 50-409/82-11 on 820803 Corrective actions Tech Spec change to emergency operating facility data acquisition sys will be installed & operating during Oct 1982 LINDER: F Dairyland Power Cooperative 82/10/11 HIND. J A Division of Emergency Preparedness & Operational Support 9pp 15777 295 24X Fiche 50-409.82/10/11.8210220176
- 8210190638 Ack receipt of 820910 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/82-07 SPEGSARD, R L Division of Project & Resident Programs 82/10/13 LINDER, F W Dairyland Power Cooperative 1p 15740 049 24X Fiche, 50-409, 82/10/13, 8210190638
- --8210190404 Responds to NRC 820812 ltr reviolations noted in IE Insp. Rept 50-409/82-07 Corrective actions Tech Spec limits for primary system activity & chemistry entered onto water chemical and iochemical analyses rapt LINDER. F. Dairyland Power Cooperative 82/09/10 KEPPLER. J. O. Region 3. Office of Director 3pp. 15740-050 24X Fiche 50-409.82/10/13.8210190638
- 620819023B IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Piants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.820819023B
- 8210190433 Confirms J Taylor & R Waiker conversation re scheduling of two mpt meetings Meetings will be held 821105 at LaCrosses, Wilto discuss systematic assessment of liconsee performance & regulatory improvement program EPESBARD, R L Division of Project & Resident Programs 82/10/15 LINDER, F W Dairyiand Power Cooperative ip 15741 165 24X Fiche 50-409, 62/10/15,8210190433
- 82(02)0336 Forwards evaluation of SEP Topic III-3 C, "Inservice Inspot Water Control Structures," based on licensee 820129 safety assessment Insportant does not conform w/intent of Reg Outde 1 127 & should be modified CRUICHFIELD, D Operating Reactors Branch 5 82/10/15 LINDER, F Dairyland Power Cooperative 9pp 15765 054 24% Fiche 50-409, 82/10/15, 8210210336
- 8210250105 Confirms conversation between J Taylor & R Walker re rescheduling two mpt meetings Meetings will be held 821109 to discuss systematic assessment of licenses performance & regulatory improvement program SPEESARD, R L Division of Project & Resident Programs 82/10/18. LINDER, F, W Dairyland Power Cooperative Ip 15787 079 24X Fichs 50-409, 82/10/18, 8210250105
- 8210270127 Forwards IE Safequards Insp Rept 50-409/82-16 on 820720-24 & notice of violation Details & notice of violation withheld (ref 100FR73 21) HILLER.J.R Division of Engineering & Technical Programs 82/10/26 LINDER.F W Dairyland Power Cooperative 2pp 15853.355. 24X Fiche.50-409.82/10/26.8210270129
- --8210270137 IE Bafeguards Insp Rept 50-407/82-14 on 820720-24 Noncompliance noted security equipment not alarm equipped & not tested properly Details withheld (ref 100FR73, 21) PIRTLE: 0 L., QREED, JR. Region 3, Office of Director 82/10/20 2pp 15853:357. 24X Fiche. 50-407, 82/10/24, 8210270127

- S Reportable occurrences, LERs & related correspondence
- 9210050353 PNO-1II-82-091A on 820926, plant returned to svc following removal of blockage in emergency high pressure core spray sys lines Blockage caused by all entering sys through interconnection w/svc water sys Silt removad HALKER, JORDAN, M Region 3, Office of Director 82/09/29 lp 15608 295 24X Fichs 50-409, 82/09/29, 8210050353
- 8210190448 Forwards LER 82-017/03L-0 Detailed event analysis submitted LINDER, F. Dairyland Power Cooperative 82/10/11 KEPPLER, J. G. Ragion 3. Office of Director 2pp 15740 170 24X Fiche 50-409, 82/10/11, 8210170448
- --8210190454 LER 82-017/03L-0 on B20926, during Mode 4, high pressure svc water containment isolation valve closed Caused by air leak due to losse fitting on valve operator air supply line Air supply line fitting tightened 5 valve reopened GGDDMAN, L 8 Dairyland Power Cooperative 82/10/11 Region 3, Office of Director ip 15740 172 24X Fiche 50-409,82/10/11.
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2
- 8210210322 Requests changes to NRC correspondence distribution list TB Conser replaces LM Trasten & CD Hobelman JM Keib should be added to list MANGAN, C V Niggare Mahawk Power Corp 82/09/10 DIRCKS, H J Uffice of the Elecutive Director for Operations ip 15764 222 24X Fiche 50-410, 82/09/10. 8210210322
- Q Inspection reports, IE Bulletins & correspondence
- 8210040170 Advises that util response to IE Bulletin 80~14 will be submitted by 830131 instead of 820730 MANNO, 8 F Nigara Mohauk Power Corp 82/07/23 HAYNES, R C Region 1. Office of Director 1p 15582 314 24X Fiche 50~410,82/09/23,8210040170
- 8208190233 IE info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Syc list encl COBD. I I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06,8208190233
- 8210270415 Notification of 821020 enforcement conference in Region 1 ofc w/wbil to discuss CA intep BAUMACK. W NRC No Detailed Affiliation Given 82/10/13 DIRCKS.W J Office of the Executive Director for Operations STELLO.V Regional Operations & Generic Requirements DEYOUNG.R C Director's Office. Office of Inspection and Enforcement ip 15833 203 24X Fiche 50-410.82/10/13.8210270415
- 8208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Syc list encl DEYQUNO, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.62/J0/14.8208190238
- 8 Reportable occurrences, LERs & related correspondence
- 8210040071 Final deficiency rept to control bldg termination cabinet support sills Initially reported on 820615 Holded stude to be replaced by diffiled-through anchor bolts field directly to base concrete Hork will be completed by 820930 MANO,8 F Niagara Hohawk Power Corp 82/09/29 STARQSTECKI.R Division of Project & Resident Programs 2pp 15581 276 24X Fiche: 50-410, 62/09/23, 8210040071
- 8210040190 Final deficiency rept re Rosemount Model 1152 transmitters w/gutput Codes A & D Transmitters do not use A or D amplifier boards. Deficiency per 10CFR50 S5s not valid Reportable par Part 21 by GE MANNO. S F Niagara Mohauk Power Corp 62/09/23 STAROSIECKI.R Division of Project & Resident Programs 2pp 15583 189 24X Fiche 50-410.82/09/23.8210040190
- 8210130129 Interim deficiency rept re AGME III Class 1 juints welded w/AGME Class 2 k 3 welding procedures Contrary to 820831 itr, deficiency deamed reportable per 10CFR50 55(e) MANNO, S. F. Niagara Mohawk Power Corp. 82/10/06 8TAROSTECKI, R Division of Project & Resident Programs 1p 15497 069 24X Fiche 50-410, 62/10/06, 8210150129

- 8210250378 Interim deficiency rept re insufficient environ &/or seismic qualification documentation of listed control room equipment [initially reported on 820921 Final rept will be submitted by 821231 MARNO, S.F. Miagara Mohauk Power Corp. 82/10/15 STAROSTECK[, R. Division of Project & Resident Programs. 2pp. 15790 139 24X Fiche 50-410, 82/10/15. 8210250378
- DICKET 50-412 BEAVER VALLEY POWER STATION. UNIT 2
- A Application/construction stage documents & correspondence
- 6210120031 Summary of 820831 meeting w/util in Bethesda.MD recontents of CL application "to Introduce project mpt personnel Application trequested deferral of FSAR Chapter 18 until finalization of NUREG-0800 DOCLITICE t
- Q inspection reports. IE Bulletins & correspondence
- 8210050211 Forwards [E Insp Rept 50-412/62-10 on 820809-13 No noncompliance noised MARTIN.T 7 Division of Engineering & Technical Programs 62/09/17 MCOLEVER.E J Duquesne tight Co 2pp 15615 089 24X Fiche 50-412.822/09/17
- --B210060215 tE Insp Rept 50-412/82-10 on 820809-13 No noncompliance noted Hajor areas inspected records re reactor pressure vessel storage 5 maint at site vessel lift & transportation 5 final rigging 6 installation VARELA.A A. DURB.J P Region 1 Office of Director 82/09/11 6pp 15515 071 24X Fiche 50-412-82/09/17-8210060211
- 5208190233 IC Info Nutice 80-35. Suppl 1. "Leaking & Dislodged 1-125 Implant Seeds" Svc list encl COBO.L I Division of Fuel Facilities. Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 19761 250 24% Fiche 50-000.82/10/06.8208190233
- 62/8190238 IE Bulletin 92-03, "Stress Corrosion Cracking in Thick-Hall-Large-Diameter-Stainless Steel Recirculation Sys Piping at BUR Plants" Svc list encl DEYGUNG-R C Director s Office. Office of Inspection and Enforcement 82/60/14 Consolidated Edison Co of New York 115pp 15819 125 24X Fiche 50-000-82/10/14:8208170238
- S Reportable occurrences, LERs & related correspondence
- 8210070155 Final Significant Deficiency Rept 82-05 re misapplication of torquing equipment on emergency diesel generators shaft spider assemblies Retorquing of all fasteners to verdors specified value of 5.000 ft lb has been performed MODLEVER.E J Buquesne Light Co 82/09/24 HAYNES.R C Region 1, Office of Director 2pp 15627 069 24X Fiche 50-412.82/09/24, 8210070155
- 6210070233 Interim deficiency rept to Westinghouse solid state protection sys Initially reported on 620830 Vendor reviewing on-line test circuitry design Next rept will be submitted by 830520 MOCLEYER, E. J. Duquesne Light Co. 62/09/29 MAYNES, R. C. Region 1 Office of Director. 3pp. 13634-303 24X Fiche 50-412,82/09/29,8210070233
- 8210260143 Interim Significant Difficiency Rept 82-06 re sheared pinlon keys in Linitorque notar operators supplied by Histinghause Initially reported on 820701 Keys replaced Hestinghause will provide data for completing corrective action MOLLEVER, E. J. Duquesne Light Co. 82/10/07 HAYNES, R. Region I, Office of Director 4pp. 15799 085 24% Fiche 50-412,82/10/07, 20(428-0142)
- 6210260135 Interim Bignificant Deficiency Rept 82-02 re gossible inaccuracy in two RCS wide-range pressure transmitters initially reported on 820512 New Hestinghouse (nfo being evaluated Next rept expected by 830228 MOOLEVER, E. J. Duquesne Light Co. 82/10/18 HAYNES, R. Region I. Office of Director App. 15799 079 24X Fiche 50-412,82/10/18, 8210260135

1 !

1

- DOCKET 50-413 CATAMBA NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 821001000B Responds to FOIA request for 19 categories of documents rancilear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records B2/06/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fichs 50-000, 82/06/28, 8210010008
- --BOOSOSO265 Discusses addl required info to better define potential far cracking in reactor vessel noisles NDDNAN-V S Assistant Director for Materials & Qualifications Engineering 80/05/05 TEDESCO, R L Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000,82/06/28,8210010008
- 8210050264 Forwards summary of 820406-07 meeting in Bethesds. HD & 820419-22 meeting in Charlotte. NC w/Mechanical Engineering Branch. Hestinghouse & BNML relitems in NRC 820129 ltr W/sight oversize drawings Aperture cards are in PDR TUCKER. H B Dute Power Co 82/09/27 DENTON, H R Diffice of Nuclear Reactor Regulation. Director ADENSAM, E G Licensing Branch 4 343pp 15406 060 24% Fiche 50-413.82/09/27,8210050264
- 8210070092 Forwards minutes of meeting held during wk of 820419
 w/Mestinghouse & Mechanical Engineering Branch.discussing
 resolution of FSAR Item 109 re fuel damping values Minutes
 withheld (ref 10CFR2 790)
 TUCKER.H B Dute Power G 82/09/29 DENTON,H R Office of
 Nuclear Reactor Regulation, Director ADENSAM,C G Licensing Branch
 4 2pp 15628 079 24X Fiche 50-413,82/09/28,8210070092
- 82100503B4 Forwards revised FSAR pages reflecting organizational changes & changes to Chapter i3 Changes will be included in Revision 7 to FSAR
 TUCKER.H B Duke Power Co 82/09/29 DENTON,H R Office of Nuclear Reactor Regulation. Director ADENSAM,E C Licensing Branch 4 28pp 15408 281 24X Fiche 50-413,82/09/29,8210050384
- G2iO190071 Notification of 821006 meeting w/util in Charlotte, NC to discuss matts design General Dosign Criterion 51 JABBOUR, KN Licensing Branch 4 82/09/29 ADENSAM, E 0 Licensing Branch 4 3pp 16761 095 24X Fiche 50~413, 82/09/29, 8210196071
- 8210050130 Provides fifth Quarterly update of projected const completion date Plant 90% complete as of 820718 Fuel load scheduled for Oct 1984
 TUCKER.H B Duke Power Co 82/09/30 DENTON,H R Office of Nuclear Reactor Regulation, Diroctor ADENBAM,E G Licensing Branck 4 2pp 19605 045 24X Fichs 50-413,62/09/30.8210050130
- 8210060311 Informs that review of plant operations relative to void formation in vessel head during transients completed Assessment of facility procedures in training program per Generic Ltr 81-21 enc!

 TUCKER: H B Duke Power Ca 82/09/30 DENTON: H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q Licensing Branch 4 4pp 13617 170 24X Fiche 30-413, 82/09/30, 8210060311
- 8210150094 Application for Amend 2B to CPPR-116 & CPPR-117, consisting of Revision 6 to FBAR & Revision 1 to license application TUCKER.H B Dute Power Co 82/10/12 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM,E Q Licensing Branch 4 22pp 15499 001 24X Fiche 50-413.82/10/12,8210150094
- 8210220026 Summary of 820907-09 sits visit & meetings w/util re Instrumentation & Control Sys Branch concorns & open items Responses to open items will be provided by end of Oct 1982 Summary & status of concerns & open items encl JABBOUR, K N Licensing Branch 4 82/10/15 Licensing Branch 4 9pp 15786 292 24X Ficho 50-413.82/10/15.8210220026
- 9210260201 Revises WO Parker 920701 itr reschedule for submission of info meeded to resolve concerns identified in DO Eisenhut 801222 the & NURSEQ-0612 Info requested in Bections 2 2 & 2 4 of Enc.) 2 to be submitted by 821124 TUCKER.H B Dute Power Co 82/10/21 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E O Licensing Branck 1p. 15804 271 24X Fiche 50-413,82/10/21.8210260201
- D NAC Draft/Final Environmental Statements, supple & correspondence
- B210040322 Comments on historic & archeologic impacts, water quality-entrainment, thermal discharge & post-operational monitoring discussions in DES BLANCHARD. B Interior. Dept of B2/09/30 ADENSAM, E 0 Licensis, Branch 4 3pp 19586 195 24X Fiche 50-413, B2/09/30, B210040322

- 32/0/30117 Advises that DES is rated LO-1 Normal operation of facility will not have significant impact on environ No add1 info
- needed MODRE.S N Environmental Protection Agency 82/10/06 JUBBOUR.K N Division of Licensing 2pp 15673 007 24X Fiche 50~413,82/10/06,8210130117
- 1210130487 Forwards comments on DES (NUREG-0921) re operation of
- Tacilities
 LOCHSTET, H A Pennsylvania State Univ 82/10/06 Division of Licensing 7pp 15682 140 24X Fiche 50-413,82/10/06.8210130487
- 210130506 Comments on DES List of water users in downstream order to be contained in FES:encl TURNER, L E South Carolina. State of 82/10/07 JABBOUR, K N Division of Licensing 3pp 15682 253 24% Fichs 50-413,82/10/07.
- RIO250102 Forwards comments on DEG,per 10CFR51 TUCKER.H B Dute Power Co 82/10/07 DENTON.H R Office of Nuclear Reactor Regulation, Director EISENHUT.D & Licensing Dranch 4 14pp 15791 191 24X Fishe 50-413.82/10/07.8210250102
- 210180106 Advises that review of DES for facility has been completed PROBUSION ADVISES THAT FEVIEW OF HES FOR FACILITY HAS BEEN CREMER.D L. South Carolina, State of 82/10/08 C. Nuclear Reactor Regulation, Director 1p 15719 318 Fiche 30-413,82/10/08,8210180104 Office of
- 210180169 Comments on DES (NUREG-0921) & public health & safety ampacts of proposed plant operation
 VILLFORTH, J C Food & Drug Administration 82/10/12 JABBDUR, K N
 Division of Licensing 2pp 15719 166 24X Fiche 50-413,82/10/12.
 B210180169
- 10240150 Requests encl comments on DES be transmitted to appropriate NRC of DES summary of cost/benefit in Table 6 I deficient RILEY, J L Carolina Environmental Study Group 82/10/22 JABBOUR, K N Division of Licensing 3pp 15797 015 24% Fiche 50-413, 82/10/22, 8210260150
- NRC Safety Evaluation Report (SER), supply & correspondence
- 10280065 Forwards responses to name (tems an EG Adensam 820609 ltr reauxiliary feedwater system draft BER.Section 7 1 3 1
 TUCKER.H B Duke Power Co 82/10/19 DENTON.H R Office of
 Nuclear Reactor Regulation, Director ADENSAME G Licensing Branch
 4 9pp 15837 263 24X Fiche 50-413.82/10/19.8210280065
- Security, medical, emergency & fire protection plans
- 07170053 Forwards Revision 3 to security plan Revision withheld (ref Licensing Branch
- 10190611 Responds to 810723 request for schedule for installation of public notification sys at facilities Final design of sys & schedule for installation not finalized Info submittal anticipated by 821201
 TUCKER, H B Duke Power Co 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAN, E G Licensing Branch 1, NEWTON, F Federal Emergency Management Agency 2pp, 15737 221
 24X Fiche 50-413,82/10/08.8210190411
- Adjudicatory correspondence
- 0050202 Response opposing Palmetto Alliance & Carolina Environ Study Proup 820922 supplemental patitions to intervana (GOARRY., J.M. Duka Power Co. MCGARRY., J.M. Debavoise & Liberman 32/10/04 Atomic Safety and Licensing Board Panel 7/199 24X Fiche 50-413,82/10/04,8210050202
- 121005020B Response to Charlotte-Mecklenberg Environ Coalition 820919 revised Contention 4 Contention acceptable Notice of appearance & Certificate of Svc encl MCOARRY, J M Duke Power Co MCOARRY, J M Debevoise & Liberman 82/10/04 Atomic Safety and Licensing Board Panel 4pp. 15602 350 24% Fiche 50-413.82/10/04.8210050202
- O060191 Statement of position on DES contentions Objects to all almetto Alliance/Carolina Environ Study Group contentions xcept Contention 4 as specified Gertificate of Svc encl. OHNSON, 0 E Hearing Branch 4 B2/10/04 Atomic Safety and icensing Board Panel 26pp 15613 264, 24X Fiche, 50-413, 82/10/04, 210060191.

- 8210080081 Motion to compel util to respond to Palmetto Alliance 820703 second set of interrogatories & requests to produce Centificate of Syc enti CUILD.R Palmetto Atliance GUILD.R Guild.R 82/10/0/4 Atomic Safety and Licensing Board Panel 5pp 15640 199 Fiche 50-413, 82/10/04,8210080081
- 8210180182 Order extending time until 821112 for Commission to act to PIOIBOIBE Under elsemming - review ALAB-687 CHILK.S J Office of the Sucretary of the Commission B2/10/14 Commissioners ip 15719 134 24X Fiche 50-413,82/10/14.
- 8210200071 Provides response to ASLB questions at 821007-08 second special prehearing conference Questions relate to risks from McGuire facility & scope of evacuation costs listed in DES Table 5 11 JOHNSON, G E Hearing Branch 4 82/10/18 KELLEY, J L , FOSTEK, R F , CALLIHAN, D Atomic Safety and Licensing Board Panel 2pp 15757 192 24% Fiche 50-413,82/10/18,8210200071
- 6210210187 Motion for order to protect NRC from answering Palmetto Alliance Interrogatories 1 % 36 on Contention 8 % Interrogatory 1 on Contention 27 Requests are for large amount of matt w/d regard to relevance UDHN90N.0 E Hearing Branch 4 82/10/19 Atomic Safety and Licensing Board Panel 3pp 15765 159 24% Fiche 50-413.82/10/19, 8210210187
- --8210210197 Responses to second set of interrogatories & requests to produce re Palmetto Alliance Contentions 8 & 27 Prof qualifications, NUREO/CR-2644 & Certificate of Svc encl OUNSON, C E. Hearing Branch 4 82/10/19 Palmetto Alliance 134pp 15765 162 24X Fiche 50-413,82/10/19,8210210187
- 8210250125 Responses to Palmetto Alliance 820927 third set of interrogatories & requests to produce Related correspondence CARR.A V Dute Power Co 82/10/17 Palmetto Atliance 15787 243 24X Fiche 50~4[J.82/10/19.8210250125 Palmetto Alliance 62pp
- 8210250282 Motion for protective order relieving applicants from requirement to respond to Palmetto Alliance 820727 third set of interrogatories & requests to produce Certificate of Svc enci Related correspondence CARR. A V Dute Power Co 82/10/19 Atomic Safety and Licensing Board Panel 4pp 18791 078 24X Fiche 50-413.82/10/19.8210250202
- 8210250370 Forwards EIA re spent fuel storage of Oconee spent fuel at McGurre Unit i spent fuel pool,dtd Dec 1978 Copies also sent to intervenors W/o encl JOHNSON,O E Hearing Branch 4 82/10/21 KELLEY,J L . FOSTER,R F . CALLIHAN,O Atomic Bafety and Licensing Goard Panel Jp 15790 188 24X Fiche 50-413,82/10/21.8210250370
- 8210260415 Answer apposing Palmetto Alliance 821004 motion to compa) answers to interrogatories ASLB should issue order denying answers to interrogatories ASLB should issue order denying action as lacking merit Motion devoid of supporting arguments Certificate of Svc enci CARR, AV Duke Power Co 62/10/22 Atomic Safety and Licensing Board Panel 20pp 15806 HIS 24X Fiche 50-413.82/10/22, 2210360415 8210260415
- 8210270002 Answers ASLB question re Palmetto Alliance/Carolina Environ Study Group Contention if DEG totaled risks to public of accidents from each unit JOHNSON.O E Hearing Branch 4 82/10/25 KELLEY, J.L., FOSTER, R.F., CALLIMAN.D Atomic Safety and Licensing Board Panel ip 15817 011 24X Fiche 50-413,82/10/25,8210270002
- B210270010 Advises that NRC does not intend to file response to Palmetto Alliance 821004 motion to compel discovery from applicants NRC responded to requests on 821017
 JOHNBON.0 E Hearing Branch 4 B2/10/25 KELLEY.J L , FOSTER.R F . CALLIHAN.D Atomic Bafety and Licensing Board Panel ip 15822 340 24% Fichs 50-413,82/10/25,82/0270010
- H General correspondence
- 8210130046 Responds to 820912 1tr request that NRC continue to send ziusauone responds to 820712 itr request that NRC continue to send copies of correspondence to util on McGuira Since McGuira proceedings complete & documents in LPDR.request denied.

 ADENBAM.E Ø Licensing Branch 4 B2/09/28 RILEY.J L Carolina Environmental 84049 Croup ip 15696-284 24X

 Fiche 50-000, 82/09/28, 8210130046

- V Utility Final Safety Analysis Report (FSAR) & amends
- 6210150094 Application for Amend 28 to CPPR-116 & CPPR-117, consisting or Revision 6 to FSAR & Revision 1 to license application TUCKER.H B Dute Power Co 82/10/12 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH,E G Licensing Branch 4 22pp 15699 001 24x Fiche 50-413,82/10/12,8210150094
- --8210150101 Revision 6 to FSAR

 Duke Power Co 82/10/12 761pp 15699 023 24X
 Fiche 50-413, 82/10/12-8210150094
- Q Inspection reports, 1E Bulletins & correspondence
- C2100B0015 Add1 response to FDIA request for 19 categories of info re nuclear reactor events % safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FDIA Exemption 5) FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X Fichs 50-000, 82/07/12. B210080015
 - 0210080156 Systematic assessment of licenses performance notes re racility evaluation for Sept 1977-Aug 1980 * NRC - No Detailed Affiliation Civen BO/08/31 5pp 15668 057 24x Fiche 50-000, 82/07/12,8210080015
- 3210010106 Forwards 1E Insp Repts 50-413/82-22 & 50-414/82-20 on 820824-27 No noncompliance noted DANCE: NC Division of Project & Resident Programs 82/09/13 TUCKER: NR Duke Power Co 2pp 15567 174 24X Fiche 50-413, 82/09/13, 8210010106
- --8210010110 IE Insp Repts 50-413/82-22 & 50-414/82-20 on \$20824-27 No noncompliance noted Major areas inspected independent inspectforthreview of quality records for containment structures / supports & insertice review of program COLEY.J L. RLAKE.J J. Division of Engineering & Technical Programs 82/09/09 10pp 15567 176 24% Fiche 50-413,82/09/10,8210010106
- B210010131 Ack receipt of B20907 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-413/82-18 & 90-414/82-16 & EHIS,R C Division of Project & Resident Programs 82/09/22 TUCKER-H B Dute Power Co ip 15565 351 24X Fiche 50-413.82/09/22.8210010131
- --8210010134 Responds to NRC 820809 ltr re violations noted in IE Insp. Repts 50-413/82-18 & 50-414/82-16 Corrective actions matis personnel training uill be completed by 820915 & paint storage warehouse will be upgraded by 821015

 IUCKER.H B Duke Power Co 82/09/07 O'REILLY, J.P. Region 2. Office of Director 4pp 15565 352 24X Fiche 50-413,82/09/22,821001013!
- --8210010338 Forwards IE Insp Repts 50-413/82-18 & 50-414/82-16 on E20712-16 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/08/09 TUCKER.H B Duke Power Co 2pp 15565 356 24X Fiche 50-413.82/09/22
- --8210010141 Notice of violation from insp on 820712-16 # Division of Project & Resident Programs 82/08/09 2pp 15565 358 24% Fiche 50-413,82/09/22,8210010131

- --8210220471 IE Insp Repts 50-413/82-24 & 50-414/82-22 on 820826-0910 N nancompliance noted Major areas inspected review of nonconforming items & followup of IE circulars VANDOORN. D K., BRYANT, J C. Division of Project & Resident Programs 82/09/28 3pp 15779 118 24X Fiche 50-413,82/09/29,8210220467
- 8208190233 iE Info Notice 80-35. Suppl 1. "Leaking & Dislodged 1-125 Implant Seeds " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 640p 15761 250 244 Fiche 50-000, 82/10/06, 8208190233
- 8210220134 Ack receipt of 1E Insp Repts 50-413/82-22 \$ 50-414/82 20 Na proprietery info TUCKER.H B Dute Power Co 82/10/08 G'REILLY, J P Region 2, Orfice of Director ip 15778 114 24X Fiche 50-413.82/10/08, 92102301
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thich-Wali, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants " Svc list encl DEYDUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 185p 15810 125 24X Fiche 50-000.82/10/14.8208190238
- S Reportable occurrences. LERs & related correspondence
- 9210080208 Significant Deficiency Rept SD 413-414/82-18 re radiographic exams not performed on flux core welding filler matt ordered to EFA 5 20 Initially reported on 820703 Vendor committed to radiograph all matls Action to be completed by 830301 TUCKER.H B Duke Power Co 82/10/01 0/REILLY.J Region 2, Office of Director 3pp 15640 096 24X Fiche 50-413,82/10/01.
- 8210290119 Significant Deficiency Rept SD 413/82-19 re linear indications identified on Kerotest valve body 9J-551 on 820819 Initially reported on 820909 Valve returned to manufacturer Final rept will be submitted by 821108 TUCKER.H B Dute Power Co 62/10/08 O'REILLY.JP Region 2, Office of Director 2pp 15854 024 24% Fiche 50-413,82/10/08,8210290119
- 8210290354 Significant Deficiency Rept SD 413-414/82-20 re inappropriate governor drive matl coupling supplied for diesel generator Initially reported on 820708 Manufacturer recommends replacement w/neoprene matl TUCKER. H B Duke Power Co 82/10/08 O'REILLY, J P Region 2, Office of Director 3pp 15853 040 24X Fische 50-413,82/10/08, 0210270354
- 8210290290 Significant Deficiency Rept 413-414/82-ii re potential failure to activate safeguards sys due to possible failure of switch contacts, shunting proving lamp Revision to solid state protection sys will be made by Hestinghouse TUCKER, H B Dute Power Co 82/10/20 G/REILLY, J P Region 2, Orfice of Director 3pp 19854 096 24X Fiche 50-413,82/10/20, 32(10)2055
- T Hearing transcripts on non-antitrust matters
- 8210130207 Transcript of 821007 prehearing conference in Charlotte, NC Pp 380-567 * Atomic Safety and Licensing Board Panel 62/10/07 188pp 19673 272 24X Fiche 50-413.82/10/07.8210130207
- 8210130233 Transcript of 821008 prehearing conference in Charlotte, NC Pp 548-455

 * Atomic Safety and Licensing Doard Panel 82/10/08, 68pp 15675 124 24X Fiche 50-4[3:82/10/08;8210130238
- V Operator Examinations

å

8210260065 Bummary of 820909 meeting w/util in Cornelius, NC rs cold licanse exam scheduls MILBON, B.A. Division of Engineering & Technical Programs JABBOUR, K.N. Licensing Branch 4 82/10/01 Division of Engineering & Technical Programs 21pp 15810 340 24X Fichs 50-413, 82710/01.8210260065

- DDCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 82:00:0008 Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.82100:0008
- --8008050265 Discusses additequired info to better define potential for cracking in reactor vessel noticles
 NOONANLY 8 Assistant Director for Materials & Qualifications
 Engineering 80/05/05 TEDESCO.R L Assistant Director for
 Licensing 2pp 15727 178 24X Fiche 50-000,82/06/28,8210010000
- 8210050264 Forwards summary of 820406-07 meeting in Bethesda, HD & 820419-22 meeting in Charlotte, NC w/Mechanical Engineering Branch, Westinghouse & BNUL relitems in NRC 820129 itr W/eight oversize drawings Aperture cards are in PDR 7UCKER, H B Dute Power Co. 82/09/27 DENTON, H R. Office of Nuclear Reactor Regulation. Director. ADENSAM, E.O. Licensing Branch 4 343pp 15606-060 24X Fiche 50-413-82/09/27, 8210050264
- 8210070092 Forwards minutes of meeting held during wk of 820419 u/Mestinghouse & Mechanical Engineering Branch discussing resolution of FSAR Item 109 re fuel damping values Minutes withheld (ref 10CFR2 790) TUCKER-H II Duke Pewer Co 82/09/28 DENION.H R Office of Nuclear Reactor Regulation, Director ADENBAME G Licensing Branch 4 2pp 15628 079 24X Fiche 50-413.82/09/28,8210070092
- E210050384 Forwards revised FSAR pages reflecting organizational changes to changes to Chapter 13 Changes will be included in Revision 7 to FSAR TUCKER. H B Duke Power Co. 82/09/29 DENION. H R Office of Nuclear Reactor Regulation. Director ADENSAM. E Q Licensing Dranch 4 28pp 15408 281 24X Fiche 50-413.82/09/29.8210050384
- B210190071 Notification of B21006 meeting w/util in Charlotte,NC to discuss matts design General Design Criterion 51 JABGOUR,K N Licensing Brench 4 B2/09/29 ADENSAM.E Q Licensing Branch 4 3pp 15761 095 24X Fiche 50-413,82/09/29,8210190071
- B210060311 Informs that review of plant operations relative to void formation in vessel head during transients completed Assessment of facility procedures in training program per Generic Ltr B1-21 anci
 TUCKER: H 3 Duke Powor Co B2/09/30 DENTON: H Office of Nuclear Reactor Regulation. Director ADENBAM.E Q Licensing Branch 4 4pp 15619 170 24% Fiche 50-413.02/09/30.8210060311
- 8210150094 Application for Amend 28 to CPPR-116 & CPPR-117, consisting of Revision & to FBAR & Revision I to license application TUCKER. H D Dute Power Co 82/10/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 15699 001 24X Fichs 50-413,82/10/12,8210150094
- 8210220026 Summary of B20907-09 site visit & meetings w/util re Instrumentation & Control Sys Branch concorns & open items Rasponses to open items will be provided by end of Oct 1982 Summary & status of concerns & open items encl JAUBDUR.K N Licensing Branch 4 82/10/15 Licensing Branch 4 9pp 15786 292 24% Fishe 50-413.82/10/15.8210220026
- 8210260201 Revises MD Parker 820701 ltr re schedule for submission of info meeded to resolve concerns identified in DO Elsenhut 801222 ltr & NUREG-0612 Info requested in Sections 2 2 & 2 4 of Encl 2 to be submitted by 821124

 TUCKER.H B Duke Power Co 82/10/21 DENTON.H R Office of Nuctear Reactor Regulation, Director ADENSAM.E 0 Licensing Branch 4 ip 15804 271 24X Fiche 50-413,82/10/21.8210260201
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8210040322 Comments on historic & archeologic impacts,water quality, entrainment thermal discharge & post-operational monitoring discussions in DES BLANCHARD. B Interior. Dept of 82/09/30 ADENSAM, E Q Licensing Branch 4 3pp 15586 195 24X Fiche 50-413, 82/09/30, 8210040322
- 8210130117 Advises that DEB is rated LO-1.Normal operation of facility will not have significant impact on environ No addl info medded MODRE.S N. Environmental Protection Agency 82/10/06 JUBBOUR.K N Division of Licensing 2pp 15673 007 24X Fiche 50-413.82/10/06.8210130117

- 82i0i30487 Forwards comments on DES (NUREC-0921) re operation of facilities LOCHSTET.W A Pennsylvania State Univ 82/10/06 Division of Licensing 7pp 19682 140 24% Fiche 50-413,82/10/06,821013048/
- 8210130504 Comments on DES List of water users in downstream order, to be contained in FES, encl TURNER, L E South Carolina, State of 82/10/07 JABBOUR, K N Division of Licensing 3pp 15682 253 24X Fiche 50-413,82/10/07, 8210130504
- 8210250102 Forwards comments on DEG.per LOCFR51 TUCKER,H B Buke Power Co 82/10/07 DENTBN,H R Office of Nuclear Reactor Regulation, Director EISENRUT.D C Licensing Branch 4 14pp 1579 191 24K Fische 50-413,82/10/07,8210250102
- 8210180106 Advises that review of DES for facility has been completed Clearance valid for 1 yr CROMER.D.L. South Garolina, State of 82/10/08 Office of Nuclear Reactor Regulation, Director 1p 15719 318 24X Fiche 50-413,82/10/08,8210180106
- 8210(80169 Comments on DES (NUREO-0921) & public health & safety impacts of proposed plant operation VILLEDRITH.J C. Food & Drug Administration 82/10/12 JABBOUR.K & Division of Licensing 2pp (5719 166 24% Fiche 50-413,02/10/12,020)180169
- 8210260150 Requests encl comments on DES be transmitted to appropriate NRC ofc DES summary of cost/benefit in Table 6 1 deficient RILEY, J L Carolina Environmental Study Group 82/10/22 JABBOUR, K N Division of Licensing 3pp 15/99 015 24X Fiche 50-413,82/10/22,8210260150
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8210280065 Forwards responses to nine items in EQ Adenson 820609 itr re auxiliary feedwater sys.per draft SER.Section 7 1 3 1 TUCKER.H B Duke Power Co 82/10/19 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM,E Q Licensing Branch 4 9pp 13837 263 24X Fiche 50-413.82/10/19.8210280065
- F Security, medical, emergency & fire protection plans
- B209170053 Forwards Revision 3 to security plan Revision withhold (ref 10CFR73 21) TUCKER, H B Duke Power Co 82/08/18 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Litensing Branch 4 2pp 14910 095 24X Fiche 50-413, 82/08/18, 8209170053
- 621019061\$ Responds to 810723 request for schedule for installation of public notification sys at facilities Final design of sys & schedule for installation not finalized Info submittal anticipated by 821201

 TUCKER, H B Duke Power Co 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E Q Licensing Branch A NEWTON, F Federal Emergency Management Agency 2pp 15737 221 24X Fiche 50-413,82/10/08,8210190611
- Q Adjudicatory correspondence
- 8210050202 Response opposing Palmetto Alliance & Carolina Envi Group 820922 supplemental petitions to intervene MCGARRY, J M Dute Power Co MCGARRY, J M Debevoise 82/10/04 Atomic Safety and Licensing Board Panel 15602 279 24K Fiche 50-413,82/10/04.8210050202
- --8210050208 Response to Charlotte-Meckienberg Environ (
 revised Contention 4 Contention acceptable Notice of
 appearance & Certificate of Svc enc.)
 MCOARRY,J M Duke Power Co MCOARRY,J M Debevoi82/10/04 Atomic Sefety and Licensing Board Panel
 15502 330 24% Fiche 50-413, 82/10/04.8210050202
- 8210060191 Statement of position on DES contentions Objet Palmetto Alliance/Carolina Environ Study Oroup content except Contention 4 as specified Certificate of Svc er JUHNSON, O E Hearing Branch 4 82/10/04 Atomic E Licensing Board Panel 26pp 15613 264 24X Fiche: 8210060191
- 82100800B1 Motion to compel util to respond to Palmetto 820903 second set of interrogatories & requests to pro Centificate of Svc encl GUILD.R. Palmetto Alliance GUILD.R. Guild, R. 82, Atomic Safety and Licensing Soard Panel 5pp 15640 Fiche, 50-413, 82/10/04, 82100800B1

JUUINELED HEITIU

- 8210180182 Order extending time until 821112 for Commission to act to review ALAB-687
 CHILKS J Office of the Secretary of the Commission 82/10/14
 Commissioners ip 15719 134 24X Fiche 50-413.82/10/14, n210180182
- 8210200071 Provides response to ASLB questions at 821007-08 second special prehearing conference Questions relate to risks from McQuire facility & scope of evacuation costs listed in DES Table 5 11
 JOHNSON G E Hearing Branch 4 82/10/18 KELLEY.J L , FOSTER.R F . CALLIHAN.D Atomic Safety and Licensing Board Panel 2pp 15757 192 24X Fiche 50-413.82/10/18.8210200071
- 8210210187 Motion for order to protect NRC from answering Palmetto Alliance interrogatories (\$ 36 on Contention 8 & Interrogatory (on Contention 27 Requests are for large amount of nat) u/o regard to relevance JOHNSON. 0 E Hearing Branch 4 82/10/19 Atomic Safety and Licensing Board Panel 3pp 15765 159 24X Fiche 30-413.82/10/19, 8210210187
- --B21021019/ Responses to second set of interrogatories & requests to produce re Palmetto Alliance Contentions 8 & 27 Prof qualifications, NUREC/CR-2644 & Certificate of Svc enct JUHUSON, 6 E. Hearing Granch 4 B2/10/19 Palmetto Alliance 134pp 15765 162 24% Fiche 50-413,82/10/19,82(0210167
- 8210250125 Pesponses to Palmetto Alliance 820927 third set of interragatories & requests to produce Related correspondence CARR.A V Duke Power Co 82/10/19 Palmetto Alliance 62pp 15787 243 24x Fiche 50-413.82/10/17,8210250125
- 8210250282 Motion for protective order relieving applicants from requirement to respond to Palmetto Alljance 820927 third set of interrogalories ? requests to produce Certificate of Svc encl Related correspondence CARR.A V Duke Power Co 82/10/19 Atomic Safety and Licensing Board Panel 4pp 15791 078 24X Fiche 50-413,82/10/19,8210250282
- 8210250370 Forwards EIA re spent fuel storage of Doonee spent fuel at McGuire Unit I spent fuel pool, dld Dec 1978 Copies also sent to intervenors M/D enci JOHNSON.G E Hearing Branch 4 82/10/21 KELLEY.J L , FOBTER.R F , CALLIHAM.D Atomic Safety and Licensing Board Panel ip 15790 188 24X Fichs 50-413.82/10/21,8210250370
- 8210260415 Answer apposing Palmetto Alliance 821004 motion to compel answers to interrogatories ASLB should issue order denying motion as lacking merit Motion devaid of supporting arguments Certificate of Svc encl CARR.A V Duke Pawer Ca 82/10/22 Atomic Safety and Licensing Board Panel 20pp 15806 115 24x Fiche 50-413,82/10/22.
- 8210270002 Answers ASLB question re Palmetto Alliance/Carolina Environ Study Group Contention 11 DES totaled risks to public of accidents from each unit JONNSON, 0 E Hearing Branch 4 82/10/25 KELLEY, J. L., FOBTER, R. F. CALLIHAN, D. Atomic Safety and Licensing Board Panel 1p 19817 011 24X Fische 50-413.82/10/25,8210270002
- 8210270010 Advises that NRC does not intend to file response to Palmetto Attiance 821004 motion to compel discovery from applicants NRC responded to requests on 821019
 JOHNSON, G E Hearing Branch 4 82/10/25 KELLEY, J L , FOSTER, R F , CALLIHAN, D Atomic Safety and Licensing Board Panel 1p
 15822 340 24% Fiche 50-413,82/10/25,8210270010

at NRC continue to send
e Since McGuire
equest denied
B RILEY.J L Carolina
24X

- K Utsisty Final Safety Analysis Report (FEAR) & amends
- 8210150074 Application for Amend 28 to CPPR-116 & CPPR-117, consisting of Revision 6 to FBAR & Revision I to license application TUCKER:H B Duis Power Co 82/10/12 DENTON-H R Office of Nuclear Reactor Regulation, Director ADENSAN,E 0 Licensing Branch 4 22pp 15699 001 24% Fiche 50-413,82/10/12,8210150094
- --8210150101 Revision 6 to FSAR

 * Duke Power Co 62/10/12 761pp 15699 023 24X
 Fichs 50-413,82/10/12.8210150094

Q Inspectson reports, IE Bulletins & correspondence

- 8210080015 Addl response to FDIA request for 19 categories of info to nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref. FDIA Exemption 5)
 FELTON, J. M. Division of Rules and Records 82/07/12 UDELL, R. A. Critical Mass Energy Project 7pp 15665 027 24X
 Fichs 50-000, 82/07/12, 8210080015
- --8210080156 Systematic assessment of licensee performance notes re facility evaluation for Sept 1979-Aug 1980 + NRC - No Betailed Affiliation Given 80/08/31 5pp 15648 057 24% Fiche 50-000, 82/07/12,8210080015
- 8210010106 Forwards IE Insp Repts 50-413/82-22 & 50-414/82-20 on B20824-27 No noncompliance noted BANCE: A C Division of Project & Resident Programs 82/09/13 TUCKER: H R Dute Power Co 2pp 15567 194 24X Fiche 50-413. 82/09/13 8210010106
- --8210010110 IE Insp Repts 50-413/82-22 & 50-414/82-20 on 620824-27 h; noncompliance noted Major areas inspected independent inspeffortreview of quality records for containment structures & supports & inservice review of program COLEY, J. L. BLAKE, J. Division of Engineering & Technical Programs 82/09/09 10pp 15567 196 24X Fiche 50-413-82/09/13 8210010106
- 9210010131 Ack receipt of 920907 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/82-18 & 50-414/82-16 LEMIS.R C Division of Project & Resident Programs B2/09/22 TUCKER.H B Dute Power Co 1p 15563 351 24X Fiche 50-413, 82/09/22, RE10010131
- ~-6210010134 Responds to NRC 820809 itr re violations noted in It Ims, Reptx 50-413/82-18 & 50-414/82-16 Corrective actions matts personnel training will be completed by 820915 & paint storage warehouse will be upgraded by 821015

 TUCKER.H D Duke Power Co 82/09/07 D'REILLY.J P Region 2. Office of Director 4pp 15565 352 24% Fiche 50-413.82/09/22. 8210010134
- --821001013B Forwards IE Insp Repts 50-413/82-18 & 50-414/82-16 on 820712-16 & notice of violation LEWIS.R C Division of Project & Resident Programs 82/08/09 TUCKER:18 D Duke Power Co 2pp 19565-356 24X Fiche 50-413.82/09/22,8210010131
- --8210010141 Notice of violation from insp on 820712-16 * Division of Project & Resident Programs 82/08/09 15565 358 244 Fiche 50-413,82/09/22,821001013
- --82(0010143 IE Insp Repts 50-4)3/82-18 & 50-414/82-16 on 820712-16 Noncompliance noted failure to Initiate nonconforming team item repts re coatings storage temps & failure to conduct civil work activities surveillances MRIGHT.R W , DEBBAGE.A O , UPRIGHT, C M Division of Engineering & Technical Programs 82/09/02 ilep 15965 360 24X Fichs 50-413.82/09/22.82(001013)
- 8210150069 Ack receipt of IE Insp Repts 50-413/82-20 & 50-414/82-18
 No proprietary info
 TUCKER, H B Duke Power Co 82/09/24 O'REILLY, J P Region 2,
 Office of Director 1p 15696 348 24X Fiche 50-413,82/09/24,
 8210150069
- 8210220467 Forwards IE Insp Repts 50-413/82-24 & 90-414/82-22 on 820826-0910 No noncompliance noted DANCE:H C. Division of Project & Resident Programs 82/09/29 TUCKER:H B Duke Power Co 2pp 15779 116 24X Fiche 50-413.82/09/29.8210220467
- --8210220471 IE insp Repts 50-413/82-24 & 50-414/82-22 on 820826-0916 to noncompliance noted Major areas inspected review of nonconforming items & following of IE circulars VANDOORN D K . BRYANT J C Division of Project & Resident Programs 82/09/28 Opp 15779 ii8 24X Fiche 50-413/82/09/28. 8210220467
- 8208190233 IE 1nfo Notice 80-35. Buppl 1. "Leaking & Dislodged 1-12" Implant Seeds " Svc list enc!. COBs.L I. Division of Fuel Facilities. Materials & Gafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 2% 24X Fiche 50-000.82/10/06.8208190233
- 8210220134 Ack receipt of IE Insp Repts 50-413/82-22 & 50-414/82-20 % proprietary info TUCKER, H B Dute Power Go 82/10/08 O'REILLY, J P Region 2. Office of Director 1p 15778 114 24X Fiche. 50-413.82/10/09. 6210220134

- 8208190238 IE Dulletin 82-03. "Stress Corresion Cracking in Thick-Wall.Large-Diamater. Stainless Steel. Recirculation Sys Piping at BWR Plants " Svc list encl DEYQUNO.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fichs 50-000.82/10/14.8208190238
- 5 Reportable occurrences, LERs & related correspondence
- 8210080208 Significant Deficiency Rept SD 413-414/82-18 re radiographic elas not performed on flux core weiding filler matl ordered to SFA 5 20 Initially reported on 820903 Vendor committed to radiograph all matls Action to be completed by 830301 TUCKER.H B Duke Power Co 82/10/01 O'REILLY, J P Region 2, Office of Director 3pp 15640 086 24% Fiche 50-413.82/10/01. 8210080208
- 8210290354 Significant Deficiency Rept SD 413-414/82-20 re inappropriate governor drive mati coupling supplied for disset generator Initially reported on 820908 Manufacturer recommends replacement w/neoprene mati TUCKER. H B Duke Power Co 82/10/08 D'REILLY, J P Region 2, Office of Director 3pp 15853 040 24X Fiche 50-413,82/10/08, 8210290354
- 8210290250 Significant Deficiency Rept 413-414/82-11 re potential failure to activate safeguards sys due to possible failure of switch contacts, shunting proving lamp Revision to solid state protection sys will be made by Westinghouse TUCKER, H D Duke Power Co 82/10/20 O'REILLY, J P Region P. Office of Director 3pp 15854 096 24X Fiche 50-413,82/10/20,82/0290250
- T Hearing transcripts on non-antitrust matters
- 8210130207 Transcript of 821007 prehearing conference in Charlotte.NC Pp 380-567

 * Atomic Bafety and Licensing Board Panel 82/10/07 188pp 15673 272 24X Ficho 50-413, 82/10/07, 8210130207
- B21013023B Transcript of B2100B prehearing conference in Charlotte.NC Pp 568-655 * Atomic Safety and Licensing Board Panel B2/10/0B BBpp 15675 126 24X Fiche 50-413, B2/10/0B B21013023B
- V Operator Examinations
- 8210260065 Bummary of 820909 meeting w/util in Cornelius.NC re cold license ozam schadule WILSON.B A Division of Engineering & Technical Programs JABIOUR.K N Licensing Brench 4 82/10/01 Division of Engineering & Technical Programs 21pp 15810 340 24X Fiche 30-413.82/10/01.8210260065
- DOCKET 50-416 ORAND OULF NUCLEAR STATION, UNIT 1

 E NRC Safety Evaluation Report (SER), supple & correspondence
- 8210190566 Advises of completion of thermocouple qualification testing per SER Suppl 3 Thermocouples considered qualified for statement by dynamic loads including variable pool swell Final test rest will be reviewed upon receipt DALE.L. F. Mississippi Power & Light Co. 82/10/14 DENTON.H R Office of Nuclear Reactor Repulsation, Director 2pp 15736 133 24X Fiche 50-416.82/10/14,8210190566
- 8210200064 Forwards comments & status of util review of DL & SER Info provided to assist in generation of fourth suppl to SER & full power DL DALE.L F Mississippi Powsr & Light Co 82/10/14 DENYON,H R Offics of Nuclear Reactor Regulation, Director 34pp 15756 153 24X Fiche: 50-416, 82/10/14, 8210200064
- 8210200005 Forwards outline of in situ test for HPCS standby svc water pump flow induced vibration Test will be performed prior to startup following first refueling outage Commitment to conduct test resolves EER Suppl 2. Section 3 io concerns DALG/L F Mississippi Power & Light Co 62/10/18 DENYON, H R Office of Nuclear Reactor Regulation, Director 7p 15754 341 24X Piche. 50-416.82/10/18.8210200005
- E210200030 Forwards evaluation of Valve disc pin overstressing, addressing concerns & closing supplemental SER 2, Section 22 2 (Issus II E 4,2), "Purge Valve Operability"

 DALE: L F Mississippi Power & Light Co 82/10/18 DENTON, H R Office of Nuclear Reactor Asgulation, Director 7pp 15757 19424X Fiche 50-416,82/10/18,8210200030

- 8210200073 Forwards info re monitoring trend analysis program per commitment to summarize vibration monitoring analysis program for deep draft pump reliability per SER Section 1 10 (13)

 DALE, L. F. Mississippi Power & Light Cu. 82/10/18 DENTON, H. R. Office of Nuclear Reactor Regulation. Director 2pp. 15754 133 24X Fiche 50-416, 82/10/18, 8210200073
- B210220425 Forwards add1 info is qualification of hydraulist control units affected by variable pool swell loads Test response spectra-required response spectra comparisons should be sufficient to close concern in SER Suppl 3. Section 3 10 DALE, L.F. Mississippl Power & Light Co. 62/10/19 DENTON-H R Office of Nuclear Reactor Regulation. Director 7pp 19779 153 24X Fiche 30-416,82/10/19.8210220425
- F Security, medical, emergency & fire protection plans
- 82(0150013 Responds to noncompliance re emergency accountabilisty noted in IE Insp Rept 50-416/82-27 Interpretion of "onsite" questionable Other utils make same distinction of site boundary being same as protected area DALE, L.F. Mississippi Power & Light Co. 82/07/19 O'REILLY. J P. Region 2. Office of Director 2pp. 15698 346 24% Fiche 50-416.82/07/19,8210150013
- 8210070040 Rejeases public version of corrections to emergency action level table FELTON.J M Division of Rules and Records 82/09/17 Document Management Branch ip 15646 341 24% Fiche 50-416.82/09/17, 8210070040
- --8210070044 Forwards public version of corrections to Table 4-1 re emergency action levels, in response to NRC questions on Revision 6 to emergency plan Encl changes will be incorporated into plan by 821031 DALE.L F Mississippi Power & Light Co 82/09/09 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15646 341 24X Fiche 50-416,82/09/17.8210070040
- --B210070048 Public version of corrected Table 4-1 re emergency action levels initial & final notification forms enci
 4 Mississippi Pawer & Light Co B2/07/09 App 15646 345 P4X Fiche 50-416.82/07/17.8210070040
- 8210010234 Forwards Revision 5 to physical security plan Revision withheld (ref 10CFR2 790) MCGAUGHY.JP Hississippi Power & Light Co 82/07/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 15574 060 24X Fiche 50-416.82/09/22.8210010234
- 6210010023 Requests delay in implementation of emergency response facility Facility will be structurally complete by 821001 commitment date, but several important sys will not yet be installed Schedule should be developed between NRC & util DALE, L.F. Mississippi Power & Light Co. 82/09/29 DENTON, H.R. Office of Nuclear Reactor Regulation, Director Spp. 15565 141 24% Fiche 50-416,82/09/29.8210010023
- O Adjudicatory correspondence
- 8210040115 Order granting State of I time to respond to ASLO 820831 or applicant arguments due 821011 No will be granted LAURENSONJ A Atomic Safety and Louisiana, State of 3pp 1558 8210040115
- 8210150462 Brief supporting State or participate as interested state Or untimely petition Certificate of S LINDSEY, I D Louisiana, State of Licensing Board Panei 31pp 157 8210150462
- 8210210393 Memorandum & order denuir intervention ABLB unable to consist in proceeding Commission retained to grant full power OL LAURENSON, A , BRIGHT, O O , HARBC Board Panel 82/10/20 Louisia 24X Fiche 50-416,82/10/20,8210210C

- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8208290018 Summarijes 268th ACRS meeting on 820812-14 in Washington, DC re full pouer OLs for Grand Gulf 1 & Watts Bar 1 & [1], systematic evaluation & integrated reliability assessment of Ginna & control room habitability SHEMMON P ACRS Advisory Committee on Reactor Safeguards 82/08/06 PALLADINO, N J Commissioners 3pp 15649 233 24X Fiche 50-000.82/08/26.820829018
- B2102703B0 Summary of ACRS Grand Gulf Subcommittee 820B11 meeting in Hashington.DC re DL review * ACRS - Advisory Committee on Reactor Safeguards B2/09/09 ACRS - Advisory Committee on Reactor Safeguards 16pp 15834 30J 24
- P Operating license stage documents & correspondence
- 6210130024 Forwards Amend 3 to License NPF-13, safety evaluation & notice of issuance & availability Amend grants additione-time Tech Spec exceptions for Phase 1 operations & changes to Tech Specs re valves & stroke times EISEMHUT.D G Division of Licensing 62/07/20 MCGAUOHY, J P Mississippi Power & Light Co 3pp 15692 312 24X Fiche 30-416, 62/09/20, 8210130024
- --8210139027 Amend 3 to bitches NPF-13 granting addl one-time Tech Specexceptions for Phase I operation & changes to Tech Specs re valves & stroke times
 EISENHUT.D G Division of Licensing 82/09/20 16pp 15692 315
 24% Fiche 50-416,82/09/20,8210130024
- --021013003B Safety evaluation supporting Amend 3 to License NPF-13 4 Office of Nuclear Reactor Regulation, Director 62/09/16 3pp 15592 326 24% fiche 50-416.82/09/20.8210130024
- --8210130043 Notice of issuance % availability of Amend 3 to Licunsu NPF-13 SCHWENCER. A Licensing Branch 2 82/09/20 3pp 15692 329 249 Fiche 50-416.82/09/20.8210130024
- 8210220032 Advises that postponement of associated startup test acceptable Recirculation flow control test under cold plant conditions should be deleted SCHWENCER. A Licensing Branch 2 82/09/28 MCGAUGHY, J P Mississippi Power & Light Co 2pp 15786 283 24% Fiche 30-416, 82/09/28, 8210220032
- 8210040053 Advises of delay in response to Humphrey concerns recontainment issues pending 821001 conference discussion u/GE on local encroachments. Action Plans 1-4 Commitment based on 820929 telcon u/Containment Sys Branch DALE-L F Hississippi Power & Light Co 82/09/30 DENTON H R Office of Nuclear Reactor Regulation. Director ip 15581 307 24X Fiche 50-416. 82/09/30, 8210040053
- 8210040244 Discusses independent design review per License Condition 2 C(43) Design verification program to provide addition assurance that design & constructies meet 10CFR50, App B requirements will be performed by Cygna Energy Svcs DALE, L.F. Mississiphi Power & Light Co. 82/09/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 15595-001, 24% Fiche 50-416, 82/09/30, 8210040264
- 9210040353 Forwards responses to 820826 request for add1 info re Items 1-8.including current status & submittal schedule for outstanding items TF Plunkett prof qualifications encl DALE.C.F. Mississippi Power & Light Co. 82/09/30 DENTON, H.R. Dffice of Nuclear Reactor Regulation, Director 8pp. 13593 341 24% Fiche 50-416.82/09/30,8210040353
- B210050295 Responds to request for add1 info re HPCS svc water pump Add1 testing or mod not required Suggests meeting w/Equipment Qualification Branch to discuss evaluation results on B2100B in Bethesda.HD DALELL F Mississippi Power & Light Co B2/10/04 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 15619 305 244 Fiche 50-416.82/10/04.8210060295
- 8210260264 Advises that util will reissue plant emergency operating procedures in accordance w/INPO writer guide & Revision 2 of BNR owners group emergency planning guidelines Revised procedures to be submitted by 821029

 PALE-L F Mississippi Power & Light Co G2/10/12 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15803 031 24% Fiche 50-416,82/10/12,8210260264

- B210190494 Forwards addi info per License Condition 2 C (5) re PMP effects on facility Specific fizes will be implemented on schedule consistent w/57 power Fizes will consist of sealing doors & modifying pump house floor penetrations DALE/L F Mississippi Power & Light Co B2/10/14 DENTON, H R Dffice of Nuclear Reactor Regulation. Director 2pp 15740 196 24X Fiche 50-416,82/10/14.8210190494
- B210190921 Provides info in response to Human Factors Engineering Branch 820913 informal request ro meeting human performance environ conditions in piant remote shutdown panel area DALE.L. F. Mississippi Power & Light Co. B2/10/14 DENTON.H R. Office of Nuclear Reactor Regulation. Director 2pp 19751 236 24X Fiche 50-416.82/10/14.8210190521
- 8210210217 Bubmits addl info re design & testing of automatic depressurfication sys air sys.including response to NUREO-0737. Item II K 3 28 air sys testing & air sys makeup provisions Revision to FSAR Subsection 18 i 30 i2 enci DALEIL F Mississippi Power & Light Co 82/10/18 DENIGN, N R Office of Nuclear Reactor Regulation, Director 3pp 15766 340 24X Fiche 50-416,82/10/18,8210210217
- B210260412 Requests that License Condition 2 C (44)(1)(a) be revised to require submittal re automatic depressurization sys logic mode by 821215 Previous submittal date of 821027 erroneously requested due to revised BMR owners group schedule DALEL F Mississippi Power & Light Co 82/10/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15803 10/24X Fiche 50-416,82/10/21,8210260412
- B210270277 Forwards addi info re containment design, in response to J Humphrey questions Status rept per util 820715 ltr & GE proprietary info enci Proprietary info withheld Affidavit & 11 oversize drawings encl Aperture cards are in PDR DALE: L F Mississippi Power & Light Co 82/10/22 DENION. H R Office of Nuclear Reaclair Regulation. Director 82pp 15852-198 24% Fiche 50-414.82/10/22.8210270277
- 8210280135 Provides addl responses to NRC concerns re adequacy of onsite communication sys in areas exhibiting high ambient noise levels, use of 2-way radio sys & work stations requiring communications w/control room or shutdown panel DALE.L F Mississippi Power & Light Co 82/10/26 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 15837 130 24X Fiche 50-416, 82/10/26, 8210280135
- B210290102 Outlines commitments made during 821025 telcon re design & testing of automatic depressurization air sys Integrated leak test on sys will be performed every 16 months

 Justification for interim operation listed

 DALE, LF Mississippi Power & Light Co 82/10/26 DENTON, HR

 Office of Nuclear Reactor Regulation, Director 2pp 15854 001

 24X Fiche 50-416,82/10/26,8210290102
- Q Inspection reports. IE Buildtins & correspondence
- 82:01:50013 Responds to noncompliance to emergency accountability noted in IE Insp Rept 50-416/82-27 Interpretion of "onsite" questionable Other utils make same distinction of site boundary being same as protected area DALE/L F Mississippi Power & Light Co 82/07/19 O'REILLY, JP Region 2. Office of Director 2pp 15698 344 24X Fithe 50-416/82/07/17,8210150013
- 6210010442 Forwards IE Insp Repts 50-416/82-61 & 50-417/82-13 on 820817-20 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/09/03 8TAMPLEY,N L Missiseippi Power & Light Co 2pp 15570 175 241 Fiche 50-416,82/07/03.8210010442
- --8210010447 IE Insp Repts 50-416/82-61 & 50-417/82-13 on 820817-20 M noncompliance noted Major areas inspected const deficiency repts for Unit 1 & observation of safety-related piping work activities at Unit 2 BLAKE.J.J Division of Engineering & Technical Programs 82/09/02 4pp 15570 177 24X Fiche 30-416,82/09/03.8210010442
- 8210010148 Forwards IE Insp Rept 50-416/82-63 on 820815-18 No noncompliance noted VERRELLI, D H Division of Project & Resident Programs 82/09/07 STAMPLEY, N L Hississippi Fower & Light Co 2pp 15570 354 241 Fiche 50-416, 82/09/07, 8210010148
- --821001015) IE Insp Rept 50-416/82-63 on 820815-18 No nancompilante noted Major areae inspected, open vessel criticality & associated tests
 BURNETT: P T , VOOT-LOHELL, R , JAPE, F Division of Engineering & Technical Programs 82/09/03 4pp, 15970 356, 24X Fiche 50-416,82/09/07,8210010148

. 1

1

- 150005 Ack receipt of 020031.0907 & 20 itrs informing NRC of steps ten to correct violations noted in IE Insp Rept -416/02-55 VIS.R C Division of Project & Resident Programs 82/09/24 NPD FV.N L Mississippi Power & Light Co ip 15696 314 24X
- 115, R C DIVISION OF PROJECT & ABSTORNE PROGRAMS 62/07/24 AMPLEY, N L Mississippi Power & Light Co ip 15696 314 24) he 50-416, 82/07/24, 8210150005
- O1500il Suppis 82083i response to NRC 820730 itr re vioiations noted n IE Insp Rept 50-416/82-55 Corrective actions Anubar nstallations will be identified as temporary alterations & laced under temporary alteration program (CGAUGHY, J P Mississippi Power & Light Co 82/09/20 PREILLY, J P Region 2. Office of Director 2pp 15696 315 24% iche 50-416,82/09/24,8210i50005
- Oi900i9 Suppls 82083i response to NRC 820730 ltr re violations noted in IE Insp Rept 50-416/82-55 Corrective actions plant definistrative procedure will be revised to clarify emporary alteration program & delete use of chit log sys COAUOHY, J P Mississippi Power & Light Ca 82/09/07 (REILLY, J P Region 2, Office of Director 3pp 15696 317 24X iche 50-416.82/09/24.8210150005
- D150024 Responds to NRC B20730 ltr re violations noted in IC Insp spt 50-4i6/82-55 Corrective actions IOCFR50 59 evaluations erformed for temporary alterations & temporary alteration rocedure revised
- TOLUCIY, J P Mississippi Power & Light Co 82/08/31
 "REILLY, J P Region 2, Office of Director 2pp 13676 320 24X
 Iche 50-416.82/09/24.8210150005
- #E50328 Notice of violation from insp on 820616-0716 Division of Project & Resident Programs 82/07/30 2pp #676:324 24X Fiche 50-416, 82/07/24,8210150005
- i3003R IE Insp Rept 50-4i6/82-55 on 820616-07i6 Noncompitance ted failure to perform safety evaluation for temperary terations to facility & failure to foliow writton ecodures
- ONER, A G , SCOTT. D E , CHABE. J W Division of Project & Resident ograms 82/07/30 8pp 15696 326 24X Fiche 30-416.82/09/24.
- 0384 Ack receipt of 820907 ltr informing NRC of steps taken to ect violations noted in IE Insp Rept 50-414/82-55
 5.8 C Division of Project & Resident Programs 82/09/24
 PLEV.N L Mississippi Power & Light Co Ip 15704 048 24X 8 50-414,82/09/24,8210150384
- D233 IE Info Notice 80-35, Suppl i, "Loaking & Dislodged I-125 ent Seeds " Syc list enci L I Division of Fuel Facilities, Materials & Safeguerds D/OA Cansolidated Edison Co of New York 66pp i 576i RUO Tiche 50-000,82/10/04.8208190233
- 1238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Large-Diameter Stainies Steel, Recirculation Sys 19 at BMR Flants "Svc list encl NO.R C Director's Office, Office of Inspection and coment 62/10/14 Consolidated Edison Co of New York 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 132 Forwards responses to Instrumentation & Control Bys Branch 4 questions re util evaluation of IE Info Notice 79-22. iffication of Control Bys" & control sys failures Info C raview available in NREO-0831
 L.F. Mississippi Power & Light Co 82/10/25 DENTON.H R e of Nuclear Reactor Regulation, Director 10pp 15837 120 ichm.50-416.82/10/25.8210280132
- odic operating reports & related correspondence
- 104 Forwards monthly operating rept for Bept 1782 OHY, J. F. Hiscissippi Power & Light Co. 82/10/14 DEYOUND, R C ctor's Office, Office of Inspection and Enforcement 2pp 309 24X Fiche 50-416/82/10/14/8210180104
- 30107 Monthly operating rept for Sept 1982 -ARDSDN, J D. Mississippi Power & Light Co 82/10/15, Spp 19 311. 24X Fiche. 50-416, 82/10/14, 8210180104

- S Reportable occurrences, LERs & related correspondence
- B2100:000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents iisted in App A FELTON, J H Division of Rules and Records B2/06/28 UDELL, N A Critical Mass Energy Project 15pp 15727 005 24Y Fiche 50-000. B2/06/28, B2100:0008
- --8204210287 Forwards deficiency rept re failure of control rod drive hydraulic sys scram pilot valves Problems w/va'tage of reactor protection sys power supplies adequately addressed CHIRAMAL.M Director's Office 82/03/31 MICHELSON.C Director's Office 2pp &&Olf 190 24% Fiche 50-000.82/04/20.8210010008
- 82i0080015 Addl response to FOIA request for 17 categories of info is nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (rof FOIA Exemption 5)
 FELTON J M Rivision or Rules and Records 82/07/12 URELL, R A Critical Mass Energy Project 9pp 15665 027 24X
 Fithe 50-000.82/07/12,8210080015
- --B2061101B6 Forwards review b evaluation of BWR scram pilot valve failures due to low voltage Aug 1981 event at facility reviewed Applicability of event to operating BWRs described HICHELSON. C Director's Office B2/06/01 BENTON.H R Office of Nuclear Reactor Regulation. Director DEYOUNG.R C Director's Office, Office of Inspection and Enforcement Spp 15666 i27 24X Fiche 50-000.82/07/12.8210080015
- 8210010243 Forwards LER 82-055/03L-0 MCGAUGHY.JP Nistissippi Power & Light Co 82/09/27 O'REILLY.JP Region 2. Office of Director 1p 15568 286 24) Fiche 50-416. 82/09/27.8210010243
- --8210010248 LER 82-055/03L-0 during 820829-090B, discharge basin flow trip channel inoperable Caused by approved alteration of trip circuitry to discharge glycol-contaminated water w/o normal dijution Trip circuitry restored after discharge SPARKG. 0 L. Hississippi Power & Light Co. 82/09/27 Region &, Office of Director. 2pp. 15568 287 24X Fiche 50-416.82/09/2/, 8210010243
- 8210050193 Forwards LER 82-047/03L-0 STAMPLEY, N L Hississippi Power & Light Co 82/09/28 O'REILLY, J P Region 2, Office of Director 1p 15609 253 24. Fiche 50-416, 82/09/28, 82/0050193
- --B2i0050203 LER 82-047/03L-0 on B20830 reactor vessel & head flange temps not monitored consistently Caused by mechanical group personnel failing to adhere to procedure Procedure under revision SPARKS, G L Mississippi Power & Light Co 82/09/20 Region 2, Office of Director 2pp 15609 254 24X Fiche 50-416,82/09/20, 8210030193
- 82;006020; Forwards LER 82-062/03L-0 MCOAUCHY. J P Mississippi Power & Light Co 82/09/29 O'REILLY. J P Region 2. Office of Director ip 15614 016 24X Fithe 50-416.82/09/29.821006020[

- 8210080120 Forwards LER 62~071/03L~0 MCGAUGHV, JP Hississippi Power & Light Co 82/10/04 G'REILLY JP Region 2. Office of Director 1p 15640 127 247 Fiche 50-416.82/10/04.8210080120
- 6210080127 LER 82-071/03L-0 on 820703, smoke detectors in fire romes 2-4 alarmed w/no fire of funes present On 820727, detectors alarmed again No cause stated Detectors cleaned BrRD-R Mississippi Power & Light Co 82/10/04 Region P. Office of Director ip 15640 128 24x Fiche 50-416.82/10/04, 82/1080120
- 8210080277 Forwards LER 82-067/03L-0 MCGAUGHY. J P Mississippi Power ! Light Co 92/10/04 O'REILLY. J P Region 2: Office of Director 1p (5638 998 24X Fiche 50-416.82/10/04.8210080277
- -8210089281 LER 62 069/03L-0 on 820703, supervisory alarm for fire door separating RHR A piping room & east passageway alarmed & would not clear Caused by out-of-adjustment door microswitch Switch adjusted & tested to assure operability ALBERT, J h Mississippi Power & Light Co 82/10/04 Region 2, Office of Director 1p 15638 299 24X Fiche 50-416.82/10/04, 821008027/
- 8210080282 Forwards LER 82-063/031-0
 MCFAUGHY, J P Mississippi Power & Light Co 82/10/04
 O'REILLY, J P Region 2. Office of Director 1p 15638 199 24X
 Fiche 50-416 82/10/04,82(0080282
- -8210080287 LER 82-063/03L-0 on 820902.various fire rated cable penetrations discovered not sealed in several field termination cabinets located in control room Penetrations removed to allow cable removing WALKER.K L. Mississippi Power & Light Co. 82/10/04 Region 2, Orlice or Director Ip. 15638-200. 24X Fichs 50-416,82/10/04,82/10/8080282
- 02:10080186 Forwards LER 82-0/0/031-0 MCGAUGHY, J P Mississippi Power & Light Co 82/10/05 ORELLY, J P Region 2: Orfice of Director 1p 15640 177 247 Fithe 50-416.02/10/05.0210080186
- -- 9210080192 LER 82-070/03L-0 on 920907.13 & 16. smoke detector P65 rone 2-01 sensed smoke in standby svr water pumphouse Caused by smoke blown from nearby burn pit liken wind changed directions, alarm cleared Detector cleaned DIFFERENT, PM Kississippi Power & Light Co 92/10/05 Region 2. Office of Director Ip 15640 178 24X Fithe 50-416.82/10/05.8210080196
- 82:10080284 Forwards LER 82-066/03L-0 MCGAUGH1,J P Mississippi Power & Light Co 82/10/05 G'REILLY,J P Region 2. Office of Director 1p 15638 318 24x Fiche 56-416.82/10/05.8210080284
- -8210080287 LER 82-Q46/03L-0 on 820709, smoke detector some covering hallway area elevation 93-ft auxiliary bldg & HPCS pump room alarmed & would not clear Caused by dust accumulation on ionitation smake detectors Detectors cleaned 8YRO,R Mississippi Power & Light Co. 62/10/05 Region 2. Office of Director ip 15638 319 24% Fiche 50-416,82/10/05,82/0680284
- 6210080275 Forwards LER 82-045/03L-D MC6AUGHY.JP Mississippi Power & Light Co 82/10/05 O'REILLY.JP Region 2. Office of Director Ip 15638 323 24x 50-416.62/10/05.8210080275

- 8210220158 Forwards LER 82-064/03L-0 MCGAUGHY.J P Mississippi Fower & Light Co 82/10/08 O'REILLY.J P Region 2. Office of Director 1p 15778 080 24x Fiche 50-416.82/10/08.8210220158
- --8210220162 LER 82-064/03L-0 on 820914, two independent chlorine detection sys inoperable Caused by chlorine gas detector failing due to clogging of internal flow paths Detector cleaned, repaired & returned to svc SPARKS, G L. Mississippi Power & Light Co. 82/10/08 Region 2, Office of Director 2pp 15778 081 24X Fiche 50-416,82/10/08, 8210220158
- 82:0220181 Forwards LER 82-068/03L-0 MCGAUGHY, J P Mississippi Fower & Light Co R2/10/08 O'REILLY, J P Region 2, Office of Director 1p 15776 254 24x Fichs 50-416, 82/10/08, 82:0220181
- --8210220191 LER 82-068/03L-0 on 820909, reactor pressure vessel flamps head flamps temp not monitored periodically per Tech Specs Caused by operator error Required parameters verifying acceptable value read & recorded SPARKS.G C. Mississippi fower & Light Co. Q2/10/08 Region &, Office of Director 2pp 15776-255 24X Fiche 50-416, 82/10/08. 8210220181
- 8210220259 Forwards LER 067/0%.-0 MCOAUGHY.J P Mississippi Power & Light Co 82/10/08 O'REILLY.J P Region 2. Office of Director 1p 15775 130 2AX Fichs 50-416, 82/10/08, 8210220259
- --8210220262 LER 82-067/03L-0 on 820910, smoke detectors in zone covery; auxiliary bldg coiridor area alarmed & would not reset Caused by accumulation of dust on ionization smoke detector combined w/high sensitivity setting Detector ribaned PACE. B L Mississippi Power & Light Co 82/10/08 Region 2, Office of Director ip 15775 139 24% Fiche 50-416, 82/10/08, 8210220259
- 0210220458 Forwards LER 02-073/03L-0 MCGAUGHY.J P Mississipp: Fower & Light Co 0'REILLY.J P Region 2, Office of Director Fichs 50-416, 02/10/08, 0210220450 ip 15779 125 24X
- ~-8210220462 LER 82-073/03L-0 on 820907, smoke detectors alarmed w/no fer present Caused by paint fumes resulting from maint painting activities in area Bmoke detectors cleaned BYRD, R Mississippi Power & Light Co 82/10/08 Region ?, Office of Director ip 15777 126 24X Fiche 50-416,82/10/08. 821022458
- 0210220045 Forwards LER 02~077/03L~0 MCGAUCHY, J P Hississiphi Power & Light Co 02/10/11 U'MEHLKY, J P Region 2. Diffice of Director 1p 15778 175 24K Fiche 50-414, 02/10/11, 0210220065
- --8210220067 LER 82-079/03L-0 on 820710, discovered temp monitoring of specific safety-related areas not conducted every 12-h Data recorded once every 24-h from 820824-0911 Caused by inadvertent emission from aperating log procedure HHITE, A J Mississippi Power & Light Co 82/10/11 Region a. Office of Director ip 15778 196 24X Fiche 50-416.82/10/11, 8210220065
- 8210190417 Forwards LER 82-077/01T-0 MCGAUGHY, J P Mississippi Power & Light Co 82/10/12 O'REILLY, J P Region 2, Office of Director ip 18741 014 24# Fishs 30-416, 82/10/13, 82/0190417
- --8210190424 LER 82-077/01T-0 on 920930, two penetrations found not sealed from auxiliary bldg to control bldg Penetrations for electrical conduit not sealed during const Penetration sealed DIFFERENT, P M Mississippi Power & Light Co 82/10/13 Region 2, 0ffice of Director 2pp 15741 013 24x Fiche 50-416. 82/10/13,8210190417
- 8210190561 Forwards LER 82-075/99X-0 MCGAUGHY, JP Mississippi Power & Light Co 82/10/13 O'REILLY, JP Region 2. Office of Director 1p 15735 020 24X Fiche. 50-416. 82/10/13. 8210190561.
- --BZ10190567 LER 82-075/79X-0 on BZ0915, steam tunnel fire door 10200 discovered open w/no fire watch stationed during preparation for non-nuclean heatup Caused by need for tunnel maint Hourly fire watch established Door closed following maint CHENAULT. H H Mississippi Power & Light Co. BZ/10/13 Region Z. Office of Director ip 15735, 021 24X Fiche 50-416.82/10/13 BZ10190561

- 8210220131 Forwards LER 82-080/011-0 MCGAU0HY, J P Mississippi Power & Light Co 82/10/18 U'REILLY, J P Region 2, Office of Director 1p 15778 115 24X Fiche 90-416.82/10/18.8210220131
- --8210220130 LER 82-080/017-0 on 821004, during cold shutdown insp on Div 2 standby diesel generator, capscrew to rear crankcase cover of engine block found defective Caused by fatigue during engine operation Capscrews replaced CHENAULT, H H Mississippi Power & Light Co 82/10/18 Region 2, Office of Director 2pp 15778 116 24X Fiche 50-416, 82/10/18, 8210220131
- 6210220269 Forwards LER 82-086/03L-0 MCGAUGHY, J P Massissippi Power & Light Co 82/10/18 O'REILLY, J P Region 2, Office of Director 19 15776 200 24X Fichs 50-416, 82/10/18, 8210220269
- --8210220274 LER 82-086/03L-0 on 820916, fire detection Zone 2-6 troubir light alarmed & would not clear Caused by improperly seated move detector allowing open circuit Detector reseated, tested & returned to svc

 BYRD, R Mississippi Power & Light Co 82/10/18 Region 2, Office of Director 1p 15776 201 24X Fiche 50-416, 82/10/18, 82/2020A9
- 8210220278 Forwards LER 82-083/03L-0 MCGAUCHY.JP Mississippi Power & Light Co 82/10/18 O'REILLY.JP Region 2, Office of Director ip 15775 047 24X Fiths 50-416.82/10/18.8210270278
- --8210220282 LER 82-083/03L-0 on 820918, during cold shutdown, nine fire barrier penetrations were broken in auxiliary & control bidgs Caused by addl electrical conduit being rauted due to implementation of Design Change 82-3594
 ALBERT, J M Kississippi Power & Light Co 82/10/18 Region 2, Office of Director ip 15775 048 24X Fiche 50-416, 82/10/18, 8210220278
- 8210220284 Forwards LER 82-081/03L-0
 MCGAUGHY, J P Mississippi Power & Light Co 82/10/18
 O'REILLY, J P Region 2, Office of Director ip 15775 045 24X
 Fichs 50-416, 82/10/18, 8210220284
- --B2102202B9 LER 82-0B1/03L-0 on 820916, containment ventilation monitoring sys affiliant flowrate monitor failed to give proper indication Possibly caused by clugged flow sensor Haint work order issued to remove, inspect & clean sensor CHENAULT.W H Mississippi Power & Light Co B2/10/18 Region 2: Office of Director ip 10775 046 24X Fiche 50-416.82/10/18, 82/202084
- 8210220428 Forwards LER 82-085/03L-0 MCGAUGHY, J P Mississippi Fower & Light Co 82/10/18 O'REILLY, J P Region 2, Office of Director 1p 15779 162 24X Fiche 50-416, 82/10/18, 0210220428
- --B210220431 LER B2-085/03L-0 on B20916, three secondary containment panetrations opened for cable routing per planned maint activity Fire match extablished Penetrations sealed BYRD, R Mississippi Power & Light Co B2/10/18 Region 2, Office of Director ip 15779 163 24X Fiche 50-416, B2/10/18, B2/1020428
- 8210260445 Interim Deficiency Rept 3 re corroded terminal boards on pressure flow & level transmitters Initially reported on 820421 Corroded transmitters being analyzed by independent 145 Final rept will be sent by 821215 MCOAUGHY.JP Mississippi Power & Light Co 82/10/18 O'REILLY.JP Region 2. Office of Director 2pp 15805 248 24X Fichs 50-416, 82/10/18, 8210260445
- 8210260513 Final deficiency rept to extensive internal corrosion of Dikkers safety relief valve actuators Initially reported on 820521 Actuators cleamed, refurbished, tested & returned to original design condition Also reported per Part 21 MCGAUGHY, JP Mississipsi Power & Light Co 82/10/18 0'REILLY, JP Region 2, Office of Director 5pp 15805 128 24X Fichs 50-416, 82/10/18, 8210260513
- 62:0270050 Forwards LER 82-074/03L-0 MCGAUGHY.J P. Mississippi Power & Light Co 82/10/23 0'REILLY.J P. Region 2: Office of Director 1p 15894 020 24X Fiche 30-414:82/10/23.9210270030
- --B210290055 LER 82-074/03L-0 on B20923 review revealed only one ECCB operational during B20722 fuel load Caused by personnel & procedural error resulting in operators not being fully aware of ECCS status Equipment problems corrected BYRD.R W Mississippi Power & Light Co B2/10/23 Region 2, Diffice of Director 3pp 15854 021 24X Fichs 50-416,82/10/23. B210290050.

- 8210270124 Forwards LER 82-076/03L-0 MCGAUGHY. J P Mississippi Power & Light Co 82/10/23 O'REILLY, J P Region C. Office of Pirector Ip 15854 018 24) Fiche 50-416, 82/10/23, 8210270124
- --8210290135 LER 82-079/03L-0 on 820923, smoke detectors in Zones 2-06. 2-07.2-17 & 2-20 of auxiliary bldg alarmed & would not clear No snoke or fire present Alarms deactivated Caused by dust accumulation Detectors cleaned ALBERT. J H Mississippi Power & Light Co 82/10/23 Region & Office of Director ip 15854 019 24X Fiche 50-416.82/10/23 8210290124
- 8210290340 Forwards LER 82-088/03L-0 MCGAUDHY, J P Hississippi Pawer & Light Co 82/10/23 O'REILLY, J P Region 2, Office of Director to 15853 031 24x Fiche 50-416, 82/10/23,8210290340
- --8210270345 LER 82-088/03L-0 on 820923 discovered that Surverblance Procedure 06-EL-1831-M-1002 allowed for bench test of drywell equipment drain sump pump running timers but did not specify in-sys testing Procedure revised BYRD, R Mississippi Pouer* Light Co 82/10/23 Region 2. Office of Director 2pp 15853 032 24X Fiche 50-416.82/10/23. R2/10/20730
- --8210290081 LER 82-082/03L-0 on 820925. Channels CLD of control room vent radiation monitors were outside required Tech Spec tolerences Caused by monitors being out of calibr Channels recalibr CHENAULT, W H. Mississippi Power & Light Co. 82/10/25 Requin 2, Office of Director ip 15853 148 24X Fiche 50-416.82/10/25, 82/10290073
- B210290311 Forwards LER 82-089/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 82/10/25 O'REILLY, J P Region 2, Office of Director 1p 15853 110 24X Fichs 50-416, 82/10/25, 821029031i
- --8210270332 LER 82-087/03L-D on 820725 IPCS failed Surveillance lest 06-0P-1621-M-0001 due to failure of LPCS min flow valve (E21-F011) Caused by lailure of valve to cycle Motor replaced, tested & sys returned to syc on 820730 MHITE.A J Mississippi Power & Light Co 82/10/25 Region 17, 0Ffice of Director 1p 15853 111 24X Fishe 50-416.82/10/25, 8210290311
- 8210290348 Forwards LER 82-090/97X-0 MCGAUCHY, J P Mississippl Pawer & Light Co 82/10/25 O'REILLY, J P Region 2, Office of Director 1p 15853 024 24X Fiche 50-416, 82/10/25, 8210290348
- --B210270351 LER B2-090/97X-0 on B20920, five penetration room fire door alarm doors found inoperable, voiding ability to monitor door position Cause unknown Hourly fire watch established Alarms retested & returned to aperablity ALDERT, J M Mississippi Power & Light Co B2/10/25 Region 2, Office of Director ip 15853 025 24X Fiche 50-416.82/10/25, 8210290348
- DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210040053 Advises of delay in response to Humphrey concerns recontainment issues pending 821001 conference discussion W/9E on local encroschments. Action Plans 1-4 Commitment based on 820927 teicon w/Containment Sys Branch
 DALELL F Mississippi Power & Light Co 82/09/30 DENTON, H R
 Office of Nuclear Resolutor Regulation, Director 19 15581 307 24
 Fiche 50-416, 82/09/30, 8210040053
- 8210040353 Forwards responses to 820824 request for add1 info re Items i-8, including current status & submittal schedule for outstanding Items TF Plunkett prof qualifications enci

 DALE, L F Mississippi Power & Light Co 82/09/30 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 8pp 15593 348
 24X Fiche 80-416,82/09/30,8210040353
- 8210060295 Responds to request for add1 info re HPCS svc water pump Add1 testing or mod not required Suggests meeting w/Equipment Ovalification Branch to discuss evaluation results on 821008 in Bathesda, MD DALE, L. F. Hississippi Power & Light Co. 82/10/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp 15519 305 24X Fiche, 50-416, 82/10/04, 8210060295

- 821(2)10217 Submits addition of the design is testing of automatic depressuritation systam risks, including response to MURGO-0737, item 11 k 3 28, air systesting & air systmakeup provisions Revision to FSAR Subsection 18 1 30 12 encl DALE. L. F. Mississippi Power & Light Co. 82/10/18 DENTON, H. R. Office of Muclear Reactor Regulation. Director 3pp. 15766-340. 24X Fiche 50-416.82/10/18.8210210217
- 8210270277 Forwards additinform containment design. In response to J Humphrey questions Status rept per usil 820715 ltr & OE proprietary info withheld Affidavit & II oversize drawings encl Aperture cards are in PER DALEL F Mississipp: Power & Light Co. 82/10/22 DENTON, H & Office of Nuclear Reactor Regulation. Director 82pp 15852 198 24% Fiche 50-416, 82/10/22, 8210270277
- 8210280135 Provides addit responses to NRC concerns re adequacy of onsite communication says in areas exhibiting high ambient noise levels, use of 2-way radio says & work stations requiring communications w/control room or shutdown panel DALE, L.F. Mississippi Power & Light Co. 82/10/26 DENION, H.R. Office of Nuclear Reactor Regulation, Director 3pp. 15837 130 24% Fiche 50-416, 82/10/26, 82/10280135
- B210290102 Outlines commitments made during G21025 telcon re design & tosting of automatic depressoriation air sys integrated light test on sys will be performed every 18 months Justification for interim operation listed DALE(L.F. Mississippi Power & Light Co. 82/10/26 DENTON, H. Office of Nuclear Reactor Regulation, Director 2pp. 15854 001 24X Fiche 50-416,82/10/26 8210290102
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 6210190566 Advises of completion of the morouple qualification testing per SER Suppi 3 Thermocouples considered qualified for seismic & hydrodynamic Loads including variable pool swell Final test rept will be reviewed upon receipt DALE.L F Mississippi Power & Light Co. 82/10/14 DENTON H R Office of Nuclear Reactor Regulation. Director 2pp 15736 133 24X Fiche 50-416.82/10/14, 8210190566
- 8210200025 Forwards outline of in situ test for HPCS standby svc water gump flow induced vibration Test will be performed prior to startup foliowing first refueling outage Commitment to conduct test resolves SER Suppl 2.Bection 3 10 concerns DALE.L.F. Hississippl Power & Light Co. 82/10/18 DENTON.H R Office of Nuclear Reactor Regulation. Director 7p 15754 341 E4X Fichs 50~416.82/10/18.8210200005
- 8210200030 Forwards evaluation of valve disc pin overstressing, addressing concerns & closing supplemental BER P.Bection 22 2 (issue if E 4 2), "Purge Valve Operability " DALE,L.F. Mississippl Power & Light Co. BR/10/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 15757 194 24X Fichs 50-416,62/10/18.8P10200030
- 8210200073 Forwards info re monitoring brand analysis program per commitment to summarize vibration monitoring analysis program for deep draft pump reliability per BFR Section (10 fi3) DALELL F Mississippi Power & Light Co. 02/10/19 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 15754 133 24X Fiche 30-416, 82/10/18. 02/10/0073
- 62:0220425 Forwards addi info re qualification of hydraulic control units affected by variable pool swell loads Test response spectra-required response spectra comparisons should be sufficient to close concern in 68R Suppl 3. Section 3 10 DALE-L F. Mississippi Power & Light Co. 82/10/19 DENTON-H R Diffice of Nuclear Reseator Regulation, Director 7pp 15779 153 24X Fiche 50-416-82/10/19, 8210220425
- F Security, medical, emergency & fire protection plans

- --B210070044 Forwards public version of corrections to Table 4-] re
 emergency action levels.in response to NRC questions on
 Revision 6 to emergency plan Encl changes will be
 incorporated into plan by 821031
 BALE, L. F. Mississippi Power & Light Co. 82/09/09 DENTON, H. R.
 Offsice of Nuclear Reactor Regulation, Director 2pp. 15646-343
 24X Fiche 50-416,82/09/17.8210070040
- --B210070048 Public version of corrected Table 4-1 re emergency actical levels initial & final notification forms and A Mississippi Power & Light Co. 82/09/09 app. 15646-345 4) Fiche 50-416,82/09/17,8210070040
- B210010234 Forwards Revision 5 to physical security plan Revision withheld (ref 100FR2 790) MCGAUGHY, J.P. Mississippi Power & Light Co. B2/09/22 DENTOWN R. Office of Nuclear Reactor Regulation, Director 2pp. 15574 060 244 Fichs. 50-416.82/09/22,8210010234

G Adjudic≥tory correspondence

- 8210040115 Order granting State of LA 820921 motion for extension of time to respond to ASL8 820831 order LA response to NRC & applicant arguments due 821011 No further extension of time will be granted LAURENSON, J. A. Atomic Safety and Licensing Board Panel 82/09/30 Lyuisiana, State of 3pp 15581 186 24X Fiche 50-416, 82/09/30 8210040115
- 8210150462 Brief supporting State of LA Jul 1982 petition to participate as interested state Good cause shown for untimely petition Certificate of Svc encl LimpSey, I D Louisiane, State of 82/10/11 Atomic Bafety and Licensing Board Panel Sipp 15703 073 24X Fiche 50-416,82/10/16 82/10/042
- 8210210393 Memorandum & order denying State of LA 820726 getition for intervention ABLB unable to consider challenges to Table 8-3 in proceeding Commission retained jurisdiction over decision to great full power OL LAURENBON, J A , BRIGHT 0 O . HARBGUR, J Atomic Safety and Licensing Board Panel 82/10/20 Louisiana, State of 17pp 15763 IB4 24% Fiche 50-416,82/10/20,8210710393
- Q Inspection reports, IE Builetins & correspondence
- 82:0150013 Responds to noncomplianca re emergency accountability noted in IE Insp. Rept. 50-416/82-27 Interpretion of "onsite" questionable Other utils make same distinction of sits boundary being same as protected area DALE-L.F. Mississippi Power & Light Co. 82/07/19 O'REILLY.Ji Region 2, Office of Director 2pp. 13698-346 24X Fiche 50-416.82/07/19,82:0150013
- 8210010442 Forwards IE Insp Repts 50-416/82-61 & 50-417/82-13 on 820817-20 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/09/03 8TAMPLEY, N L Mississippi Power & Light Co 2pp 15570 175 24
- --B210010447 IE Insp Repts 50-416/B2-61 & 50-417/B2-j3 on 820817-20 % noncompliance noted Major areas inspected const deficiency repts for Unit i & observation of safety-related piping work activities at Unit 2 BLAME. J J Division of Engineering & Technical Programs 82/09/02 App 15570 177 24X Fiche 50-416,82/09/03,821001042
- 8208190233 IE Info Notice 80-35, Suppl i, "Leaking & Disiodeed 1-125 Implant Baads " Svc list and, COB3, L I. Division of Fuel Facilities, Materiais & Bafeguards BZ/10/04 Consolidated Edison Co of New York, 6App. 13768 253 24X Fichs 50-000,82/10/06,8208190233
- 8208190838 JE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Mail; Large-Diameter: Stainless Steel: Recirculation Sys Piping at BMR Flants " Syc list entl DEYOUND, R. C Director's Office Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co of New York 115pp 15810, 125 24X Fiche 50-000.82/10/14.8208190238
- 8210280132 Forwards responses to Instrumentation & Control Bys Branch 820714 questions re util evaluation of IE Info Notice 79-22. "Qualification of Control Bys" & control sys failures Info re NRC review available in NUREO-0831 DALE, L.F. Mississippi Power & Light Co. 82/10/25 DENTON.H 8 Office of Nuclear Reactor Regulation. Director 10pp (5837 129 24% Fichs: 80-416,82/10/25,8210280132

- S Reportable occurrences, LERs & related correspondence
- 8210080223 Interim deficiency rept re unqualified Bettis air actuators on Henry Pratt valves (initially reported on Bil029 Stope espanded to include other actuators Subj. not reportable per 10CFR50 55(e) Final rept expected by 830331 MCOAUGHY, J.P. Mississipp) Pawer & Light Co. 82/10/01 0'REILLY, J.P. Region 2. Office of Director. 4pp. 15638-049 24X Fiche 50-416, 82/10/01, 8210080223
- B2(0270193 Final Deficiency Rept PRD-B2/36 re caduell rebar splice testing Initially reported on 820720 Spec Change Notice j issued requiring splice testing of each bar size All splices reviewed MCGAUOHY, JP Mississippi Power & Light Co B2/10/20 O'REILLY, JP Region 2, Office of Director 5pp 15854 004 24X Fiche 50-417.82/10/20.0210270193
- BOCKET 50-423 MILLSTONE NUCLEAR POWER STATION. UNIT 3
- A Application/construction stage documents & correspondence
- 8210080105 Informs that bolt mati discussed in util 820817 ltr miq & tested to mati spec requirements of SA-540. Orade 823, Class 2. in response to D Bellers request for addl info Expeditious approval of ASHE Code Case N-310~1 requested COUNSIL.41 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/09/28 GRANT. J Licensing Branch 1 ip 15440 274 24x Fighe 50-423, 82/09/28, 8210080105
- 3210130331 Discusses revision of administrative procedures to incorporate revised working hour guidelines & provisions for authorizing deviations per 802008 k 0615 requests, TMI item i A i 3. "Shift Manning" & Generic Ltr 82-12 CDUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utslittes) CAONETTA. J P Connecticut Vankee Atomic Power Co CAONETTA. J P Northeast Utslittes 82/10/01 EISENHUT, D G Division of Licensing 3pp 15679 127 24X Fiche 50-000.82/10/01, 8201010331
- I Inspectson reports, lE Bulletins & correspondence
- 208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Distodged I-125 Implant Seeds " Svc 11st entl COBB.C. I Division of Fuel Facilities, Materials & Safeguards 82/10/046 Constituted Edison Co of New York 64pp 15761 250 244 Fiche 30-000.62/10/06.8208190233 W
- 210210241 Forwards IE Insp Rept 50-423/82-11 on 820802-31 & 0701-10 & notice of Violation STAROSTECKI.R Division of Project & Resident Programs 82/10/04 COUNSIL.N O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 15766 247 24X Fiche 50-423,82/10/06.8210210241
- -8210210248 Notice of violation from lnsp on 820802-31 & 0901-10 * Region 1. Office of Director 82/10/06 ip 15766 247 24x Fiche 50-423,82/10/06,0210210241
- -82(021026) IE Insp Rept 50-423/82-11 on 820802-31 & 0901-10
 Noncompliance noted failure to follow design specs when
 storing electrical cables & follow requirements of document
 control procedure for use of const drawings
 MATTIA-J C. ELSASSER, T Division of Project & Resident Programs
 82/10/04 9pp 15766 250 24X Fiche 50-423,82/10/06.82102/0241
- 208190238 IE Bulietin 82-03. "Stress Corrosion Cracking in Thick-Wall,Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants " Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York LISpp 15810 125 24X Fiche 50-000.82/10/14,8208190238
- Reportable occurrences, LERs & related correspondence
- *10210340 Interim deficiency rept re failure of pinion gear shear keys in Limitorque Model 880 (SD-25) Initially reported on 820804. Vtil currently awaiting info from vendor Next rept espected by 821115 (STATE OF THE PROPERTY OF THE PROPE
- 10170555 Final deficiency rept re design & const of metal shavings in containment recirculation pump motor instally reported on B20331 Event not considered reportable significant deficiency per 10CFR50 556 COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W O Northeast Utilities B2/10/08 HAYNES, R C Region). Office of Director 2pp 15736 124 24X Fichs 50-423, 82/10/068 8201070555

- 8210250329 Interim deficiency sept re clacking of control rod guide tube support pins Initially reported on 800405 Westinghouse evaluating problem Next rept will be provided by 821116 CDUNSIL.W G. OPEKA.J F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA.J F. Northeast Utilities. 82/10/12 HAYNES:R C. Region 1, Orfice of Director. 1p. 15790-328. 24% Fiche 50-423, 82/10/12, 8210250329
- 9210250290 final deficiency rept re missing Wostinghouse design thermal sleeves in 2-inch chemical 5 vol control sys (SD-24) initially reported on 920712 Affected thermal sleeves will be eliminated COUNBILLY G. OPEKA.J F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA.J F. Northeast Utilities 82/10/13 HAYKES.R G. Region I. Office of Director 2pp. 15791 160 74X Fiche 50-423,82/10/13.821020390
- DOCKET 50-424 ALVIN W VOGTCE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8210080312 Summary of 820831 meeting w/util in Bothesda.HD re requirements of Reg Guide | 88. "Collection. Storage & Haint of Nuclear Power Plant QA Records "Applicant concerned that tornado criteria not uell defined GRANT.J M Licensing Branch | 82/09/17 Licensing Branch | 3pp | 15463-338 | 24X Fiche 50-424.82/09/17,8210080312
- 8210120341 Forwards request for addl 10f0 re QA controls for field change notices Response due by 821020 YOUNOBLOOD B J Licensing Branch 1 82/09/20 DUTTIN D E Grards. Pager Co App 15591 053 24× Fiche 50-424.82/09/20.8210120341
- 8210080314 Summary of 820714 meeting w/utils & Bechtel Civil & Minerals, inc in Bethesda, MD re Millett Fault Study Final rept will be submitted by mid-Oct GRANT, JM Litensing Branch 1 82/07/23 Litensing Branch 5pp 15663
- 8210070168 Informs that FSAR will be submitted by 830/01 instead of 830901 Environ rept. security plan t antitrust info scheduled for 830901 DUTTON.D Georgia Power Co 82/10/01 EISENMUT.D G Division of Licensing ip 15627 008 24X Fiche 50-424.82/10/01.8210070168
- 6210150362 Forwards "Studies of Postulated Militett Fault," Vols 1 & (, in response to USOS Open File Rept 82-156, which postulates existence of fault near facility Postulated fault not capable DUTTON, D Georgia Power Co 82/10/15 EISENNUT, D 0 Division of Licensing 2pp 15711 011 24X Fiche 50-424,82/10/15,8210150342
- --8210150373 "Studies of Postulated Millett Fault." Vols [& 2 fharty oversize figures enci Apprture cards are available in PDR + Bechtel Curp 82/10/31 807pp 157(1 013 24X Fiche 50-424,82/10/15,8210150362
- 8210270246 Responds to NRC 820920 request for add1 info re controls for field change notices Field change notice program will not result in marginally acceptable design DUTTON.D E Georgia Power Co. 822107/15 EISENNUT.D G Division of Licensing 13pp 15829 238 24X Fichs 50~424.82/10/15,8210270246
- O Inspection reports, IE Bulletins & correspondence
- 8210010182 Forwards IE Insp Repts 50-424/82-21 & 50-425/82-21 on 820817-20 No noncompliance noted DANCE-H C Division of Project & Resident Programs 82/09/09 MELLY: R J Georgia Power Co 2pp 15567 306 24X Ficke 50-424.82/09/09.8210010182
- --8210010187 IE Insp Repts 50-424/82-21 % 50-425/82-21 on 820817-20 No noncompliance noted Major areas inspected licensee action on previous insp items, storage & preventive maint of electrical & instrumentation equipment & IE circular followup RUFF.A 8 , CONLON-T E Division of Engineering & Technical Programs 82/09/08 4pp 15547 308 24X Fiche 50-424.82/09/09, 8210010182
- 8210150096 Forwards [E Insp Repts 50-424/82-19 & 50-425/82-19 on 820711-0810 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/09/15 KELLY, R J Georgia Power Co 2pp 15701 185 24X Fichs 50-424

- --8210150103 IE Insp Repts 50-424/82-19 % 50-425/82-19 on 820711-0810 No nancompliance noted Major areas inspected primary containment fabrication. equipment handling & protection, structural steel installation? Steem generator mod SAUNDERS. H F BROWNLEE. V. L. Division of Project & Resident Programs 82/09/09 5pp 15701 187 24% Fiche 50-424-82/09/15, 8210150096
- \$210220155 Forwards IE Insp Repts 50-424/82-22 & 50-425/82-22 on 820311-0910 No noncomplaince noted DANCE.H C Davisson of Project / Resident Programs 82/09/29 KELLY.R J Georgia Fower Co 2pp 15778 083 24X Fiche 50-424, 82/09/29, 8210220155
- -- 3210220159 IE Insp Repts 50-424/82-22 % 50-425/82-22 on 620811-0910 No noncompliance noted Major areas inspected primary containment fabrication, reber welding, concrete placement & steen generator node SANDERS, W.F. BROWNLEE, V.L. Division of Project & Resident Programs 82/09/29 5pp 15778 085 247 Fiche 50-424,82/09/29, 6210220155
- 8208190233 IE info Notice 80-35. Suppl 1. "Leaking & Dislodged 1-125 Implant Seeds " Svc list enc) COSG LI Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 450 244 Fiche 50-300.62/10/06.8208190233
- SEOBIGO238 IE Bulletin 82-03. 'Stress Corrosion Cracking in Thick-MalliLarge-Diameter: Stainless Steel, Recirculation Sys Piping a' BPR Plants "Syc list enc! EtyOLNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidates Edison Co of New York 115pp 15810 125 24x Fiche 50-000. 92/10/14.8208190238
- 8210220204 Ack receipt of 820928 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/82-20 % 50-425/82 20 DANCE, H C Division of Project & Resident Programs 82/10/15 PELLY, R J Georgia Power Co 1p 15774 339 24(Fiche 50-424,82/10/19 82:02/20204
- -8210220208 Responds to NRC 820827 ltr re violations noted in JE (hep Repts 50-424/82-20 5 50 425/82-20 Corrective actions contractor Procedure v-18 revised to address transition between different wall thicknesses FOSTER.D Of Georgia Power Co. 82/09/28 DANCE.H C. Region 2 Orfice of Director 2pp 15776 340 24X Fiche 50-424,82/10/15/6210220204
- F210220211 Forwards IE Insp Repts 80-424/82-20 % 50-425/82-20 on 920809-13 % notice of violation DANCE, IC Division of Project & Resident Programs 82/08/27 KELLY, R J Georgia Power Co 2pp 157/6-342 24X Fiche 50-424,82/10/15 E210220204
- --8210220213 Notice or itolation from inspired 820809-13 4 Region 2, Giffice or Director 87/09/27 2pp 15776 344 (4x Fiche 50-424 82/10/15.8/10220204
- --82(GE20218 IE Insp Repts 55-424/82-20 & 50-425/82-20 on 820809-13 Nancoppliance noted visual (nt) procedure inadequate for piping but welds > fai/ute to follow procedure for removal of arc strikes CDLET.JL . BLAKE J Division of Engineering & Technical Programs G2/08/26 App 15776 346 24X Fiche 50-424,82/10/15,8210220204
- S Reportable occurrences. LERs & related correspondence
- 9210220078 Interim deficiency rept recontrol cable length/siling Initially reported on 920/92 Deficiency determined reportable under 100FRSO 55(e) Final rept expected by 8210/22 FOSTER. D. Georgia Power Co. 92/10/09 D'REILLY, J. P. Region 2, 07/10/09 D'REILLY, J. P. Region 2, 07/10/09 D'REILLY, J. P. Region 2, 07/10/07, 2016/20078
- 82:019062: FND-II-82-112 area media interest occurred following licensee 82:015 issuance of news release re geological survey rept stating that no active earthquake fault exists in vicinity of const site CLARK, K M . GILLILAND J T Region 2 Office of Director 82/10/15 2pp 187:37 217 244 Fichs 50-424-82/10/15-8210190621

- DOCKET 50-425 ALVIN W VOSTLE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8210080312 Summary of 820831 meeting w/util in Bethesda.MD re requirements of Reg Guide 1 88, "Collection, Storage & Maint or Nurlear Power Plant QA Records " Applicant concerned that tornado criteria not well defined GRANT.J.M. Licensing Branch 1 82/09/17 Licensing Branch 1 3pg 15663 338 24% Fiche 50-424,82/09/17,8210080312
- 8210120341 Forwards request for addl info re QA controls for field change notices Response due by 821020 YOUNGBLOOD, B J Licensing Branch 1 82/09/20 DUTTON, D E Georgia Power Co dpp 15691 053 24X Fiche 50-424,82/09/20.8210120341
- 8210080314 Summary of 820914 meeting w/utils & Bechtel Civil & Minerals, Inc. in Bethesda. MD re-Millett Fault Study Final rept will be submitted by mid-Oct ORANT, J M Licensing Branch 1 82/09/23 Licensing Branch 1 5pp 15663 353 24X Fiche 50-424,82/09/23,8210080314
- 8219070168 Informs that FSAR will be submitted by 830701 instead of 830901 Environ rept, security plan & antitrust info scheduled for 830901 DUTION, D. Georgía Power Co. 82/10/01 EISENHUT, D.G. Division of Licensing 1p 13627 008 24X Fiche 50-424.82/10/01.8210070168
- E210150362 Forwards "Studies of Postulated Millett Fault," Vols 1 & 2, in response to USGS Open File Rept 62-156. which postulates eristence of fault near facility Postulated fault not capable DUTTCN.D Georgia Power Co 82/10/15 EISENHUT.D 0 Division of Licensing 2pp 15711 011 24X Fiche 50-424.82/10/15,8210150363
- --8210150373 "Studies of Postulated Millett Fault." Vols 1 & 2 Therig oversize figures ent! Aperture cards are available in PDR * Bechtel Corp 82/10/31 809pp 15711 013 24X Fiche 50-424.82/10/15.8210150362
- 0210270246 Responds to NRC 020920 request for add1 info re controls for tield change notices Field change notice program will not result in marginally acceptable design DUTTON.D E Georgia Power Co 02/10/15 EISENKUT.D 0 Division of Licensing 13pp 15029 230 24X Fiche 50-424.02/10/15.0210270246
- Inspection reports. IE Bulletins & correspondence
- E2:00:00:02 Forwards IC Insp Repts 50-424/02-21 & 50-425/02-21 on 820817-20 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/09 KELLY.R J Georgia Power Co 2pp 15567 306 24X Fiche 50-424,82/09/09,8210010182
- --8210010187 IE Insp Repts 50-424/82-21 & 30-425/82-21 on 820817-20 No noncompliance noted Major areas inspected licensee action on previous insp items, storage & preventive maint of electrical & instrumentation equipment & IE circular following RUFF, A B , CONLON, T E Division of Engineering & Technical Programs 82/09/08 4pp 15547 308 24X Fiche 50-424,82/09/09,8210010182
- 8210150076 Forwards IE Insp Repts 50-424/82-19 & 50-425/82-19 on 820711-0810 No noncompliance noted DANCE: N C Division of Project & Resident Programs 82/09/15 KELLY: R J Georgia Power Co 2pp 15701 185 24X Fiche 90-424
- --82iDi5Di03 IE Inep Repts 50-424/82-19 & 50-425/82-19 on 820711-0310 No noncompliance noted Major areas inspected primary containment fabrication, equipment handling & protection, structural steel installation & steam generator mod SAUNDERS. W F . BROWNLEE, V L Division of Project & Resident Programs 82/09/09 5pp 15701 187 24X Fiche 50-424,82/09/15,8210150096
- 8210220155 Forwards IE insp Repts 50-424/82-22 & 50-425/82-22 on 820811-0910 No noncompliance nated OANCE,H C Division of Project & Resident Programs 82/09/29 KELLY,R J Georgia Power Co 2pp 15778:083 24% Fiche 50-424.82/09/29,8210220155
- --B210220159 IE Insp Repts 50-424/82-22 t 50-425/82-22 on 820811-0910 Na noncompliance noted Major areas inspected primary containment fabrication, rebar welding, concrete placement & steam generator mods
 SANDERS, N F , BROWNLEE, V L Division of Project & Resident Programs 82/09/29 Spp 15778 085 24X Fiche 50-424,82/09/29,8210220155

OBI90233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 Inplant Seeds " Svc list enci COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edican Co of New York 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24K Fiche 50-000,82/10/06.8208190233

OB190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation Sys
Piping at BMR Plants " Svc list onc!
DEYOUNG.R C Director's Office. Office of Inspection and
Enforcement 82/10/14 Consolidated Edison Co of New York
115pp 15810 125 24X Fiche 50-000.82/10/14.8208140238

10220204 Ack receipt of 820928 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/82-20 \hbar correct viola 50-425/82-20

DANCE, H C Division of Project & Resident Programs NELLY, R J Georgia Power Co ip 15776 339 24X Fiche 50-424, 02/10/15, 02/02/0204

8210220208 Responds to NRC 820827 ltr re violations noted in III Inop Repts 50-424/82-20 t 50-425/82-20 Corrective actions contractor Procedure X-18 revised to address transition FOSTER, D C Georgia Power Co 82/09/28 DANCE, H C FOSTER.D D Georgia Power Co 82/09/28 DANCE.H C Region 2.
Office of Director 2pp 15776 340 24X Fiche 50-424.82/10/15.
6210220204

3210220211 Forwards IE Insp Repts 50-424/82-20 & 50-425/82-20 un BOORDY-13 & notice of violation

DANGE, H C Division of Project & Resident Programs

KELLY, R J Georgia Power Co 2pp 15776 342 24X

Fiche SO-424, 82/10/(b) 8210220204 82/08/27

3210220213 Notice of violation from this on 820809-19 • Region 2, Office of Director 82/08/27 2pp 15776 344 24X Fiche 50-424,827/07/5,8210220204

1210220218 1E Inso Reats 50-424/82-20 & 50-425/82-20 on 820809-13 Noncompilance noted visual insp procedure inadequate for piping butt welds & failure to follow procedure for removal arc strikes COLEY, J L . BLAKE, J 82/08/26 6pp 15 .J Division of Engineering & Technical Programs 15776-346 - 24X Fiche 50-424,62/10/15,8210220204

Reportable occurrences. LERs & related correspondence

022007B Interim deficiency rept to control cable length/sizing nitially reported on GEO922 Deficiency determined aportable under IOCFRSO 55(e) final rept expected by CSTER.D O Georgia Power Co 82/10/08 O'REILLY, J.P. Region frice of Director ip 15778 184 24X Fiche 50-424,82/10/08, Region 2.

21022007B

0190621 PNO-II-82-112 area media interest occurred following icansee 621015 Issuance of news release re geological urvey rept stating that no active earthquake fault exists a vicinity of const site LARKAK H . GILLILAND. J T Region 2, Office of Director 82/10/15 pp 15737 217 24X Fiche 50-424.82/10/15.8210190621

4ET 50-434 BURRY POWER STATION, UNIT 3 Reportable occurrences, LERs & related correspondence

1290267 Part 21 deficiency rept re potential galling problem between tem b bunnet of 1 25-inch & larger A105 carbon steel & 162-F22 valves supplied Feb 1981-Aug 1982 Valves should be riviced & stem &/or bornet replaced FABELLE, D Conval, Inc. 82/10/11 HAYNES.R C Region 1, Office Director 17pp 15834 232 24K Fiche 50-000.82/10/11.

LET 50-435 SURRY POWER STATION, UNIT 4 teportable occurrences. LERs & related correspondence

1290267 Part 21 deficiency rept re potential galling problem between em & bonnet of 1 25-inch & larger AiO3 carbon steel & 82-f22 vaives supplied feb 1781-Aug 1782 Valves should be eviced & stem \$/or bonnet replaced
ABELLE, D Conval, Inc. 62/10/11 HAYNES,R C Region 1, Office Director 17pp 15854 232 24X Fiche 50-000.82/10/11, 1028046

DOCKET STN-50-437 FLOATING NUCLEAR PLANT

G Adjudicatory correspondence

6210150404 Order extending time until 821022 for Commission to art to review ALAB-666 & ALAB-689
CHILK-S J Office of the Secretary of the Commission 82/10/12 Commissioners ip 19704-024 24% Fiche 50-437.82/10/12.82/1050404

8210260460 Order extending time until B21112 for Commission to act to review ALAB-686 & ALAB-689 CHICK'S J Office of the Secretary of the Commission 82/10/22 Commissionum tp 15007 224 24% fiche 50-437.82/10/22.

Q Inspection reports. IE Bulletins * correspondence

8208170233 1E Info Notice 80-35. Suppl 1. "Leaking & Dislodged I 12; Implant Seeds " Svc list encl CDBB.L 1 Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 24/ 24/ Fiche 50-000,82/10/06,8208190233

8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diamefer, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl BEYDUNG.R C Birector's Office. Office of Inspection and Envorcement 82/10/14 Consolidated Edison Cv of New York [15pp | 15810 | 125 | 24x Fiche 50-000, G2/10/14, 8208190238

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT I A Application/construction stage documents & correspondence

6210280013 Responds to FOIA request for all internal non-public documents, nemos, evaluation repts & other mail dealing w/ nuclear plant operations Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/09/17 MCINNIb.D News & Observer 5pp 15860 065 24% Fiche 50-000,82/09/17. 8210280013

--8210280100 Notifies that on 820224.C Alderson advised that rept sent re possible willful violation of reporting requirements & falsification of GA & quard qualification records at facilities
RESNER.HE Office of Inspector & Auditor 82/03/01 Office Inspector & Auditor 82/03/01 Office Inspector & Auditor 82/03/01 Office 102/03/01 Office 102 Office of

8210070348 Forwards responses to NRC 820903 questions on facilities, "Bellefonte Site," "Rept on Old Bellefonte Historical Site in Northern AL" & "Archaediggical Survey of Scottsboid - Lim Rocf 161 kV Transmission Line & Fort Payne "MILSIL M Tennessee Valley Authority 82/10/04 ADENSAM. E Licensing Branch 4 32pp 13564 001 24% Fiche 50-438,82/10/04,82/0070348

--8210070355 "Bellefente Site " FURATO,E M Alabama, Univ of, | JA 300 77/ 1564 032 24X Fiche 50-438, 02/10/04:8210070348 77/09/30 2ABna

--8210070358 *P--+ on Did Patterate Hills NANCE C R 1546"

--0210

- n Inspection reports. IE Bulletins & correspondence
- \$10220180 Forwards IE Insp Repts 50-438/82-17 % 50 439/82-17 on BE0607-10 & notice of violation LONG, F L Division of Project & Resident Programs B2/06/28 PARRIS, H C Tennessee Valley Authority 2pp 15776 246 24% fiche 50-438 82/06/28, 8210220180
- 8210220183 Notice of violation from inspin 820607-10 * Division of Project 3. Resident Programs 82/06/28 18776 248 244 Fiche 50-438,82/06/28 8210220180
- --B210220189 (E Insp Repts 50-438/82-17 % 50-439/82-17 on 820607-10 Mencompliance noted space heaters not energized on dissel generator IRT-EMB-0016-8 / discrepancies between cable bend radil ? vertical cable tray fittings identified MONITH D : MERRIMEATHER.N . COMLON 7 E Division of Engineering & Technical Programs 62/06/25 5pp 15776 249 24% Fiche 50-438.82/06/28.8216220180
- E210010037 Advises of upcoming const inspite be conducted during E20920-1001 & 1011-15 Areas to be inspected listed on encl Preinspicist to be held on 620830 to obtain preliminary into LENIS.R C Division of Project & Resident Programs 82/08/31 PARRIS.H G Tennessee Valley Authority 3pp 15565 163 24% Fiche 50-438.82/08/31,8210010037
- 5210010421 Ack receipt of 820907 ltr informing NRC of steps taken to carrect violations noted in 1E insp Repts 50-438/82-12 & 50-439/82-10 & VERRELLI.0 M Division of Project & Resident Programs 82/09/17 ARRIS.N G Fennessee Valley Authority ip 15569 351 24X Fiche 50-438/82/09/17. #210010421
- --8210010427 Forwards revised response to NRC 820321 ltr re violations noted in IE Insp Repts 50-436/82-12 Corrective actions 9A program 2 procedure to require GC insp before fitup of piping components revised MILLS-L M Tennessee Valley Authority 62/09/07 O'REILLY.JP Region 2 Office of Director 3pp 15569 352 24X Fiche 50 438-82/09/17.8210010421
- 5210150149 Forwards IF insp Repts 50-438/82-27 & 50-439/82-27 on 620830-0903 No moncumpliance noted VERRELLI.D M Division of Project & Resident Programs 82/09/21 PARRIS, N G Tennéssee Valley Authority 2pp 15697 282 24% Fiche 50-438,82/09/21.8210150149
- 8210150164 IE Insp Repts 50-433/82-27 & 50-439/82-27 on 820830-0903 No noncompliance noted Major areas inspected structural concrete * Licensee action on previously identified items HARRIS.J R CONLON TE Division of Engineering & Technical Programs 82/09/17 4pp 15697 284 24X Fiche 50-438.82/09/21, 8210150149
- 9210010191 Ack receipt of 820913 ltr informing NRC of steps taken to correct violations noted in JE Insp Repts 50-438/82-18 & 30-439/82-80 VERRELLIB M Division of Project & Resident Programs 82/09/22 (FARRIS.M G Tennessee Valley Authority 1p 15568 078 24% Fiche 50-438.82/09/22.8210010191
- -6210010197 Responds to NRC 820726 ltr re-violations noted in IE Insp Repts 50-438/82-18 % 50-439/82-16 Corrective actions QC Investigation ropts initiated for each discrepant item KAMMER. D 8 Tennessee Valley Authority 82/09/13 D'REILLY, J P Region 2. Office of Director 3pp 15568 079 24X Fiche 50-438.82/09/22,8210010191
- --G210060200 Forwards IE lnsp Repts 50-438/82-18 & 50-439/82-18 on 820608-11 & notice of violation M/o notice of violation VERRELLID M Division of Project & Resident Programs 82/07/26 PARRISH C Tennesses Valley Authority 2pp 15568 082 24X Fiche 50-438.82/09/22.8210010191
- --8210010203 IE Insp Repts 50-438/82-18 & 50-439/82-18 on 820408-11 Noncompliance noted failure to follow procedure for hanger insps YORK, J H. ECONOMOS, N. Division of Engineering & Technical Programs 82/07/23 App 15548 084 24% Fiche 50-438, 82/09/22, 6210010191
- 8210150171 Ack receipt of 820707 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/82-22 & 50-439/82-22 & EMISS RC Division of Project & Resident Programs 82/09/23 PARRIS, H O Tennessee Valley Authority ip 15707 184 24X Fiche 50-438, 82/09/23, 8210150175

- --8210150181 Responds to NRC 820812 Itr reviolations noted in It Insp.
 Repts 50-438/82-22 & 50-439/82-22 Corrective actions hold placed on further installation of shielded power cable in cable tray sys Investigation continuing MILLS.L.H. Tennessee Valley Authority 82/09/09 O'REILLY.JP Region 2, Office of Director 2pp 15707 185 24X Fiche 50-438, 82/09/23, 8210150171
- --8210150189 Forwards IE Insp Repts 50-438/82-22 & 50-439/82-22 on 820713-16 & notice of violation LEHIS, R C Division of Project & Resident Programs 82/08/12 PARRIG.H G Tennessee Valley Authority 2pp 15707 187 24x Fiche 50-438,82/09/23.8210150171
- --8210150195 Notice of violation from Insp on 920713-16 • Division of Project & Resident Programs 82/08/12 tp 15707 189 24X Fiche 50-438.82/09/23.821015017(
- ~-8210150207 IE Insp Repts 50-408/82-22 & 50-439/82-22 on 820713-16 Noncompliance noted discrepancies between cable bend radii & vertical cable tray fittings GIBRONS.T S. CONLON.TE Division of Engineering & Technical Programs 82/08/11 3pp 13707 190 24X Fiche 50-438.82/09/23, 8210150171
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl CDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 46pp 15761 250 24% Fiche 50-000,82/10/06,8208190233
- 8210220387 Ack receipt of 820210 ltr re violations noted (n IE Supplemental Investigation Repts 50-439/81-26 & 50-439/81-26 on 820707-08 Violation against provisions of Energy Reorganization Act withdraum O'REILLY, J.P. Region 2. Office of Director 82/10/12 PARRIS.H & Tennessee Valley Authority 2pp 15780 299 24X Fichs 50-438, 82/10/12, 8210220387
- --8210220406 IE Supplemental Investigation Repts 50-438/81-26 & 50-439/81-26 on 820707-08 No noncompliance noted Major areas investigated response to Section 210 of Energy Reorganization Act of 1974
 URYC, B. MURPHY. D. D. ALDERSON. C. E. Region 2. Office of Director 82/09/21 3pp 15780 261 24X Fiche 50-438.82/10/12.82102203H7
- --8210220422 Responds to NRC B20111 ltr re violations noted in IC Investigation Repts 50-438/81-26 & 50-439/81-26 Denies that employee terminated in violation of Energy Reorganization Act &C procedure revised correcting second violation MILLS,L H Tennessee Valley Authority 82/02/10 0/REILLY.JP Reson 2, 0ffice of Director 5pp 19780 264 24X Fiche 90-438,82/10/12.8210220387
- --D210720432 Forwards four exhibits inadvertantly omitted from 820111 ltr transmitting IE Investigation Repts 50-438/81-26 & 50-439/81-26 ALDERSON.C E Region 2: Atlanta. Office of the Director (81/03/01) 82/01/19 PARRISH C Tennessee Valley Authority 6pp 15780 267 24X Fiche 50-438, 62/10/12, 8210220387
- --8210220446 IE Investigation Repts 50-438/81-26 & 50-439/81-26 on 810831-1001 Noncompliance noted employee discharged in violation of Energy Reorganization Act of 1974 & OC not performed in accordance w/Procedure QAP-17 1 VORSE, J Y , ALDERSON, C E Region 2, Atlanta, Office of the Director (81/03/01) 81/12/08 24pp 15780 275 24X Fiche 50-438,82/10/12,8210220387
- B208190238 IE Bulletin 82-03, "Beress Corresion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, RecIrculation Sys Piping at BHR Plants " Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp (5810) 125 24X Fiche 50-000, 82/10/14, 8208190238
- 8210220237 Ack receipt of 820812 & 0924 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-439/82-22 & 50-439/82-22 & 50-439/82-22 & EMIS.R C Division of Project & Resident Programs 82/10/15 PARRIS.H C Tennessee Valley Authority, 1p 15776 206 24X Fichs 50-438,82/10/15,8210220237
- --B21022027! Responds to NRC 820812 ltr reviolations noted in IE Insp.
 Repts 50-438/82-22 & 50-439/82-22 Reviews 820909 ltr re
 date full compliance expected Compliance will be achieved by
 821220
 MILLS, L. H. Tennessee Valley Authority 82/09/24 D'REILLY, J.P.
 Region 2, Office of Director 2pp 15776 207 24X
 Fiche 50-438, 82/10/15, 8210220237

- S Reportable occurrences, LERs & related correspondence
- \$210010011 Third Interim Deficiency Repts 50-438/81-77 & 50-439/81-76 re allowable stresses for pipe support design Initially reported on 61:207 Deficiency details being evaluated Next rept by 62:1217
 MILLS.L M Tennessee Valley Authority 82/09/20 O'REILLY, J P Region 2. Office of Director 2pp 15565 148 24X
 Fiche 50-438.82/09/20,82:0010011
- B210080222 Second interim deficiency rept re B&W design of RCS supports 5 restraints Initially reported on B20618 Welds & shear bars at interface points potentially understired Investigation continuing Next rept expected by B21220 MILLS.L H Tennessee Valley Authority B2/07/24 0'REILLY, J P Region 2. Office of Director 2pp 15638 081 24X Fiche 50-438.82/07/24,8210080222
- 6210080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on Bil228 Program developed to insure piping sys operate within design parameters Next rept provided by 82:217 MILLS.L M Tennessee Valley Authority 82/09/24 0'REILLY, J P Region 2. Office of Director 3pp 15638 104 24X Fiche 50-000.82/09/24.8210080247
- 8210080272 Seventh interim deficiency rept re imprecise specs in utii procurement document resulting in improper seismic qualification of B&H equipment in local instrument panels instally reported on 801125 Util awaiting B&W input MILLS, L M Tennessee Vailey Authority 82/09/24 O'REILLY, J P Region 2. Office of Director 2pp 15638 306 24X Fiche 50-438.82/09/24.8210080292
- J219050119 Fifth interim deficiency rept re failure of boits & nuts to meet ASTM requirements Initially reported on 810924 Engineering interpretation/recommendation awaited Also reported per Part 21 Mext rept expected by 830110 MILLS,L M Tennessee Valley Authority 82/09/27 O'REILLY, J P Region 2, Office of Director 2pp 15601 349 24X Fiche 50-438,82/09/27.8210050115
- 210050117 Supplemental deficiency rept re Lambda power module failures initially reported on 801218 Addi discrepancies identifised w/power supplies Corrective action will be completed by 830301 Aiso reported per Part 21 MILLS.t. M. Tennessee Valley Authority 82/09/27 O'REILLY, J.P. Region 2. Office of Director 1p 15601 351 24X Fiche 50-438,82/09/27.8210050119
- 210050074 Fourth interim deficiency rept re seismically unqualified auxiliary bldg fuel handling zone ventilation fans Initially reported on 810506 Contract awarded to provide qualified coils in fans Next rept by 830222 MILLS, L M Tennessee Valley Authority 82/09/28 O'REILLY, J P Region 2, Uffice of Director 2pp 15604 234 24X Fiche 50-438, 82/09/28, 8210050074
- 210050249 Fanal deficiency rept re use of insoluble give for purge dams in stainless steel piping initially reported on 820322 Glove residue left in piping six will not cause safety problems Glue will dissolve HILLSLL M Tennessee Valley Authority 82/09/28 O'REILLY. J P Regton 2. Office of Director 5pp 15007 076 24X Fiche 50-438,82/09/28,82/0050247
- 210050273 Fers' interin deficiency rept re six sheared motor ginion teys in Limitorque Model SB-0-25 motor operators Initially reported on 820830 Valves w/motor operators being tabulated Neit rept will be submitted by 821122 MILLS.L M Tennesses Valley Authority 62/07/28 O'REILLY, J P Region 2. Office of Director 2pp 15609 070 24X Fiche 50-000.82/07/28.8210050293
- '10050407 First interin deficiency rept re design problems w/steam generators Initially reported on 820830 BbM proposed preliminary design change to inject warm feedwater into header Most rept by 821129 Also reportable per Part 21 MILLS.L H Tennessee Valley Authority 82/09/28 O'REILLY, J P Region 2. Office of Director 1p 15603 004 24X Fechs 50-438, 82/09/28, 8210050407
- '10060274 Seventh interim deficiency rept re discrepancies in ITT Grannel weld depositions initially reported on 800905 ITT Grannel revision of affected hanger detail sheets near completion Aiso reported per Part 21 Next rept by 830315 MILLS.L M Tennessee Valley Authority 82/07/27 D'REILLY, J P Region 2, Office of Director 2pp 15621 178 24X Fiche 50-438, 82/09/29, 8210060274

- 8210080307 Third interim deficiency rept re defective weldalets on NAVCO spool pieces installed in DHR sys & makeup & purification sys plping Initially reported on 820224 Next rept due on 830208 Also reported por Part 21 MILLS.L M Tennessee Valley Authority 82/10/01 D'REILLY.J P Region 2, Office of Director 2pp 15438 117 24X Fiche 50-438 82/10/01,8210080307
- 8210080160 First interim deficiency mept to corrosion in high pressure fire protection sys initially reported on 820703 Corrosion analysis in progress to determine potential deficiencies in safety-related areas Next rept expected by 830831 MILLS.L M Tennessee Valley Authority 82/10/04 0/REILLY.J P Region 2. Office of Director 2pp 15640 142 24X Fiche 50-000.82/10/04.8210080160
- 8210080278 Fourth interim deficiency rept re Viking flow control valves in fire protection sys initially reported on Bili24 Engineering Change Notice 1584 initiated implementing affected drawing revisions Also reportable per Part 21 MILLS.L N Tennessee Valley Authority 82/10/04 O'REILLY, J P Region 2. Office of Director 2pp 15638 294 24X Fiche 50-438.82/10/04,8210080278
- 8210130407 Fourth interim deficiency mept nonconservative FSAR analysis for loss of normal feedwater event Initially reported on 810316 ASME code idmits will be exceeded following loss of feedwater Also reported per Part 21 MILLS.L M Tennesses Valley Authority 82/10/05 O'REILLY.JP Region 2. Office of Director 2pp 15681 008 24X Fiche 50-438.82/10/05,8210130407
- 8210220071 Final deficiency rept re attachment of pipe supports to 6-inch strip plates Initially reported on Bil231 Field mods for unacceptable supports scheduled for completion by 831001 MILLS.L M Tennessee Valley Authority 82/10/07 O'REILLY.JP Region 2, Office of Director 2pp 15778 189 24% Fiche 50-438,82/10/07.8210220071
- 8210220350 First interim deficiency rept re diesel generator bldg coble tray support welds made as fillet welds instead of grove welds initially reported on 820908 Supports being reworked Process spec revised Next rept to be submitted by 830124 MILLS.L. N. Tennessee Valley Authority 82/10/08 O'REILLY, J.P. Region 2. Office of Director 2pp 15776 273 24X Fiche 50-438,82/10/08.8210220350
- 8210170528 Final deticioncy rept re overpressurization of makeup & purification piping & valves Initially reported on 820928 Valves visually examined for signs of distress & site personnel retrained re hydrostatic systest procedures MILLS.L.M. Tennesses Valley Authority 82/10/12 O'REILLY, J.P. Region 2. Office of Director Jpp 15751 314 24X Fiche 50-438.82/10/12.8210190528
- 8210270328 Second interim deficiency rept re use of nonconservativa caiculational method to evaluate General Const Spec G-32 spacing violations initially reported on 820528 Next rept will be sent by 830328 MILG.L M Tennessee Valley Authority 82/10/12 O'REILLY, J P Region 2, Office of Director 2ps 19853 064 24X Fichs 50-000, 82/10/12, 8210270328

- 8210200322 First interin deficiency rept re generic deficiencies in solid state control sys % basic control room switch modules supplied by Consolidated Controls Corp Initially reported on 820716 Next rept by 830519 Also reported per Part 21 MILLS.L M Tennessee Valley Authority 82/10/18 0'REILLY, J P Region 2. Office of Director 2pp 15799 342 24X Fiche 50-438.82/10/18 8210240322
- 62:10260251 Final deficiency rept re-work releases allowing const to cut reinforcing steel to install anchor bolts for pipe supports (initially reported on 820727 Personnel instructed to review sesign drawings more carefully MILLS.L.H. Tennessee Valley Authority 82/10/19 0'REILLY, J.P. Region 8 Office of Director 2pp 15797-350 24X Fiche 50-438.82/10/19.8210260251
- F610260105 Third interim deficiency meptine governor lube oil confer Initially reported on 820308 Supplier has provided drawing a procedure to reforate cooler below governor Vendor working to identify cause Also reportable per Part 21 MILLS.L. M. Tennessee Valley Authority 82/10/20 O'REILLY, J.P. Region 2. Office of Director 2pp 15779 120 24X Fiche 50-438.82/10/20,8210/260105
- 6210260107 Second interim deficiency rept re failed valve control unit Initially reported on 820727 Vendor has not responded w/recommended disposition Neil rept will contain add! Info re vendor reply Also reportable per Part 21 MILS L H Tennessee Valley Authority 82/10/20 D'REI(LY, J P Region 2 Office of Director 2pp 15799 117 24X Fiche 50-438, 82/10/20, 8210260107
- e210290274 Final rept for Deficiencies B & E & seventh interim rept for Deficiencies A & D re control of procurement activities Initially reported on B10316 Final corrective actions noted Next rept expected by B30428 MILLS.L M Tennessee Valley Authority B2/10/21 D'REILLY, J P Region 2. Office of Director 4pp 15853 143 24X Fiche 50-000 B2/10/21, B210290274
- 8210270248 Revised final deficiency rept re-structural tubing exceeding AMS allowables initially reported on 810813 Design drawings which dictate configuration of 86 cable tray supports altered to ensure seismic qualification MICLS: L. H. Tennessee Valley Authority 82/10/22 O'REILLY, J.P. Region 2. Office of Director 3pp 15853 122 24X Fishe 50-438, 82/10/22, 8210270248

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- FE10280013 Responds to FQIA request for all internal non-public documents memos, evaluation repts & other mat1 dealing w/ nuclear plant operations forwards documents listed in App A FELTON J M Division of Rules and Records 82/09/17 MCINNIS, D Meus & Observer 5pp 15860 065 24X Fiche 50-000.82/09/17, 8210280013
- --B210280100 Notifies that on 820224.C Alderson advised that rept sont re
 possible willful violation of reporting requirements &
 ralsification of GA & guard qualification records at
 facilities
 RESNER.M.E. Office of Inspector & Auditor B2/03/D1 Office of
 Inspector & Auditor 1p 15861 039 24% Fiche 50-000.82/09/1/,
 B210280013
- 5210070348 Forwards responses to NRC 820903 questions on facilities,
 "Bellefonte Site." "Rept on Old Bellefonte Historical Site
 in Northern AL" & "Archaeological Survey of Scottsboro Lim
 Rock idi kV Transmission Line & Fort Payne "
 MILLS.L M Tennessee Valley Authority 82/10/04 ADENSAM, E
 Licensing Branch 4 32pp 15664 001 24X Fiche 50-438,82/10/04,
 8210070348

- F Security, medical, emergency & fire protection plans
- 8210260187 Confirms that evacuation time estimate study reviewed by both local & TN state authorities Population density & distribution info provided by TN Dept of Civil Defense based on 1980 census MILLS.L.M Tennessee Valley Authority 82/10/20 ADENSAM.F & Licensing Branch 4 2pp 15797 030 24X Fiche 50-000.02/10/70.
- O Inspection reports, IE Bulletins & correspondence
- 8210220180 Forwards IE Insp Ropts 50-438/82-17 & 50 4397/82-17 on 820607-10 & notice of violation LOMO,FL Division of Project & Resident Programs 82/06/28 PARRIS.H 0 Tennessee Valley Authority 2pp 157/6 246 24x Fiche 50-438,82/06/28,8210220180
- --8210220187 IE Insp Repts 50-438/82-17 to 50-439/82-17 on B2060/-10 Noncompliance noted space heaters not energized on diesel generator IRT-EMB-0010-8 t discrepancies between cable bend radix tectical cable tray fittings identified HUNT.M D . MERRIWEATHER.N . CONLON.T E Division of Engineering t Technical Programs 82/06/25 Spp 15776 247 24x Fiche 50-438,02/06/28,8210220180
- 8210010039 Advises of upcoming const inspite be conducted during 820920-1001 & 1011-15 Areas to be inspected listed on encl Preinspivisht to be held on 820830 to obtain preliminary into LEMIS.R C Division of Project & Resident Programs 02/08/31 PARRIS.H 0 Tennosee Valley Authority 3pp 15365 143 24X Fiche 50-438.82/08/31.82(0010037
- B210010421 Ack receipt of 820707 itr informing NRC of steps Laber to correct violations noted in IE Insp Repts 90-438/82-12 & 50-439/82-12 VERRELLI, D M Division of Project & Resident Programs 02/09/1/PARRIS,N G Tennessee Valley Authority ip 19369 381 24x Fiche 50-43B,82/09/17.8210010421
- 6210150149 Forwards IC Insp Repts 50-438/82-27 % 50 439/82-27 on 820830-0903 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/09/21 PARRIS, H O Tennessed Valley Authority, 2pp 19697 202 24x Fiche 50-438, 82/09/21, 8210150149
- --8210150164 IE Insp Repts 50-438/82 27 & 50-439/82-27 on 890810 0903 h; noncompilance noted Major areas inspected structural concrete & licensee action on previously identified teams HARRIS, J.R., CONLON, T.E. Division of Engineering & Technical Programs 82/09/17 4pp 15697 284 24X Ciche 50-438,82/09/21.
- G210010191 Ack receipt of 820913 itr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-408/82-10 to 50-439/82-18

 VERRECLI.D M Division of Project & Resident Programs 82/09/22 PARRIS.H 0 Tennessee Valley Authority ip 15560 078 24x

 Fiche 50-438.82/09/22,8210010191
- --8210010197 Responds to NRC 020726 ltr re violations noted in IL Insp.
 Repts 50-438/82-18 t 50-439/82-16 Corrective actions 0C
 investigation repts initiated for each discrepant item
 KAMMER,D S Tennessee Valley Authority 02/09/13 0'REJLLY,JP
 Region 2, Office of Director 3pp 15568 079 24X
 Fiche 50-438,82/09/22,8210010191
- --8210010200 Forwards IE Insp Repts 50-438/82-18 & 50-439/82-18 on 820608-11 & notice of violation M/o notice of violation VerReLLI,D M Division of Project & Resident Programs 02/07/26 PARRIS,H 0 Tennessee Valley Authority 2pp 15560-082 24x Fichs 50-438,82/09/22,8210010171
- --8210010203 IE Insp Repts 50-438/82-18 t 50-439/82-18 on 820600-11 Noncompliance noted failute to follow procedure for hangar insp YORK, J W , ECONOMOS, N Division of Engineering & Technical Programs 82/07/23 6pp 15568 084, 24X Fiche 50-438.82/09/22.
- 92(015017) Ack receipt of 820909 itr informing NRC of steps talen to correct violations noted in IE Imap Repts 50-439/82-22 & 50-439/82-22 & LEWIS.R C Division of Project & Resident Programs 82/09/23 PARRIS.H C Tennessee Valley Authority 1p. 19707 184, 24x Fiche 50-438, 82/09/23, 82(015017)

- --0210150181 Responds to NRC 820812 ltr re violations noted in IE Insp Repts 50-438/82-22 & 50-439/82-22 Corrective actions hold placed on further installation of shielded power cable in cable tray sys Investigation continuing MILLS.L.M. Tennessee Valley Authority 82/09/09 O'REILLY, J.P. Region 2. Office of Director 2pp 15707 185 24X Fiche 50-438,82/09/23.8210150171
- --9210150189 Forwards IE insp Repts 50-438/82-22 & 50-439/82-22 on 820713-16 & notice of violation LEHIS.R C Bivision of Project & Resident Programs 82/08/12 PARRIS.H G Tennessee Valley Authority 2pp 15707 187 24) Fiche 50-438,82/09/23-8210150171
- --8210150195 Notice of violation from insp on 820713-14 • Division of Project & Resident Programs 82/08/12 lp 15707 189 24% Fiche 50-438.82/09/23.8210150171
- --8210150207 IE Insp Repts 50-438/82-22 & 50-439/82-22 on 820713-16 Noncompliance noted discrepancies between cable bend radii & vertical cable tray fittings OIBBONS.T S , CONLON.T E Division of Engineering & Technical Programs 82/08/11 3pp 15707 190 24X Fichs 50-438-82/09/23, 8210150171
- 8208190233 IE Info Notice 80-35. Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl COBB.t I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,82/10/06,8208190233
- 8210220397 Ack receipt of 820210 ltr re violations noted in iE Supplemental Investigation Repts 50-438/81-26 & 50-439/81-26 on 820707-08 Violation against provisions of Energy Reorganization Act withdrawn O'REILLY, J P Region 2, Office of Director 82/10/12 PARRIS, H O Tennessee Valley Authority 2pp 15780 259 24X Fiche 50-438, 82/10/12,8210220387
- --8210220406 [E Supplemental Investigation Repts 50-438/81-26 & 50-439/81-26 on 820707-08 No noncompliance noted Major areas investigated response to Section 210 of Energy Reorganization Act of 1974 URYC, B. MURPHY, D.D. ALDERSON, C.E. Region 2, Office of Director 82/09/21 3pg 15780 261 24X Fiche 50-408.82/10/12,8210220387
- --8210220422 Responds to NRC 820111 ltr re violations noted in IE. Investigation Repts 50-438/81-26 & 50-439/81-26 Denles that employee terminated in violation of Energy Reorganization Act GC procedure revised correcting second violation MILLG.L M Tennesses Valley Authority, 82/02/10 D'REILLY, J P. Region 2. Office of Director Spp 15780 264 24X Fichs 50-438,82/10/12.8210220387
- --B210220432 Forwards four exhibits inadvertantly omitted from 820111 ltr transmitting IE Investigation Repts 50-438/81-26 & 50-439/91-26 & ALDERSON.C E Region 2, Atlanta, Office of the Director (81/03/01) 62/01/19 PARRIS,H 0 Yennessee Valley Authority 6pp 15780 269 24% Fichs 50-438,82/10/12,8210220387
- ~-8210220446 IE Investigation Repts 50-438/81-26 & 50-439/81-26 on 810831+1001, Noncompliance noted employee discharged in violation of Energy Reorganization Act of 1974 & GC not performed in accordance w/Procedure QAP-17 1 VDRSE, J Y , ALDERSON, C E. Region 2, Atlanta, Office of the Director (61/03/01) 81/12/08 24pp 15780 275 24X Fiche 50-438,82/10/12,8210220387
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Plping at BMR Plants "Svc list encl DEYGUND.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York | 15pp. 15810 125 24X Fiche 50-000. 82/10/14, 8208190238
- 8210220237 Ack receipt of 820812 & 0924 ltrs informing NRC of steps taken to correct violations noted in IE lnep Repts 50-4398/82-22 & 50-4398/82-22 EMHS, R C Division of Project & Resident Programs 82/10/15 PARRIS, H O Tempssee Valley Authority 1p. 15776 206 24X Fichs 50-438, 82/10/15, 8210220237
- --B210220271 Responds to NRC B20B12 ltr re-violations noted in IE Insp Repts 50-438/82-22 & 50-439/82-22 Revises B20909 ltr redate full compliance expected. Compliance will be achieved by B21220 MILLS.L.M. Tennessee Valley Authority B2/09/24 O'REILLY, J.P. Region 2. Office of Director 2pp 15776 207, 24X Fiche 50-438, B2/10/15, B210220237

- S Reportable occurrences. LERs & related correspondence
- 8210010011 Third Interim Deficiency Repts 50-438/81-77 & 50-439/81-76 re allowable stresses for pipe support design Initially reported on 81:207 Deficiency details being evaluated Nert rept by 82:217
 MILLS, L. M. Tennessee Valley Authority 82/09/20 0'REILLY, J.P. Region 2. Office of Director 2pp 15565 148 24X
 Fiche 50-438,82/09/20,8210010011
- 8210080222 Second Interim deficiency rept re 112W design of RCS supports to restraints Instially reported on 820618 Wolds & shear bars at interface points potentially undersized investigation continuing Next rept expected by 821220 MILLS.L.M. Tennessee Valley Authority 82/07/24 0'REILLY.J.P. Region 2, Office of Director 2pp 15638 081 24X Fiche 50-438.82/09/24,8210080222
- 8210080247 Third & final deficiency repts re resolution of unanticipated vebratory loading concerns initially reported on 811228 fragram developed to insure piping sys operate within design parameters Next rept provided by 821217 MILLS.L M Tennessee Valley Authority 82/09/24 O'REILLY, J P Region 2. Office of Director 3pp 15638 104 24X Fiche 50-000,82/09/24,8210080247
- 8210080272 Seventh interim deficiency rept re imprecise specs in utili procurement document resulting in improper 4eismic qualification of BSW equipment in local instrument panels instially reported on 801125 Util awaiting BSW input MILLS.L.M. Tennesse Valloy Authority 82/09/24 0'REILLY.J.P. Region 2, Office of Director 2pp 15638 306 24% Fiche 50-438,82/09/24,8210880292
- 8210030115 Fifth interin deficiency rept re failure of bolts & nots to meet ABTM requirements Initially reported on 810724 Engineering interpretation/recommendation awaited Also reported per Part 21 Next rept expected by 830110 MILLS.L M Tennessee Valley Authority 82/09/27 O'REILLY.J P Region 2. Office of Director 2pp 15601 349 24X Fiche 50-438,62/09/27,8210050115
- 8210050319 Supplemental deficiency rept re Lambda power module failures Initially reported on 803218 Addi discrepancies identified w/power supplies Corrective action will be completed by 830301 Also reported per Part 21 MILLS.L M Tennessee Valley Authority #22/09/27 D'REILLY, J P Region 2. Office of Director 1p 15601 351 24X Fiche 50-438,82/09/27,8210050119
- 8210050094 Fourth interim deficiency rept re seismically unqualified auxiliary bldg fuel handling ione ventilation fans initially reported on 810506 Contract awarded to provide qualified coils in fans Next rept by 630222
 MILLS, L. M. Tennessee Valley Authorfty 82/09/20 D'REILLY, J.P. Region 2. Dffice of Director 2pp 15604 234 24X
 Fiche 50-438,82/09/28,8210050094
- 8210050249 Final deficiency rept re use of insoluble glue for purge dams in stainless steel piping Institutive reported on 820322 Older residue left in piping sys will not cause safety problems Glue will dissolve MILLS.L M Tennessee Valley Authority 82/09/28 O'REILLY.J P Region 2. Office of Director Spp 15609 076 24X Fiche 50-438.82/09/28.8210050249

しししいにっぱし こうにごひ

- 8210030140 First interim deficiency rept re corrosion in high pressure sire protection sys Initially reported on 820703 Corrosion analysis in progress to determine potential deficiencies in safety-related areas Next rept expected by 83053 MILLSIL M Tennessee Valley Authority 82/10/04 0/REILLY J P Fegion 2, Office of Director 2pp 15440 142 24X Fiche 50-000,82/10/04,8210080160
- 82(0080278 Fourth interim deficiency rept to Viking flow control valves in time grotection sys Initially reported on 811124
 Engineering Change Notice (504 initiated implementing affected drawing revisions Also reportable per Part 21
 MILLS.L. M. Tennessee Valley Authority 82/10/04 0'REILLY. J.P.
 Region 2. Office of Director 2pp (5698-296-24X
 Fiche 50-438, 82/10/04, 82(0080278)
- 6210130407 Fourth interim deficiency rept nonconservative FSAR analysis for loss of normal feedwater event initially reported on 810316 ASME code limits will be exceeded following loss of feedwater Also reported per Part 21 MILLS.L M. Tennessee Valley Authority 82/10/05 0'REILLY.J P. Region 2. Office of Director 2pp 15681 008 24% Fiche 50-438,62/10/05.8210130407
- 8210220071 Final deficiency rept re attachment of pipe supports to abounch strip plates initially reported on 811231 Field mods for unacceptable supports scheduled for completion by 831001 FILLS. A Tennesser Valley Authority 82/10/07 D'REILLY. J P Region 2. Office of Director 2pp 15778 189 24% Fiche 50-438.82/10/07.8210220071
- 8210220350 First interim deficiency rept re diesel generator bldg cable tray support welds made as fillet welds instead of grove welds. Initially reported on 820908 Supports being reworked Process spec revised Mext rept to be submitted by 830124 MILLS.L. H. Tennessee Valley Authority 82/10/08 0'REILLY. J.P. Region 2. Office of Director 2pp 15776 273 24X Fiche 50-438 82/10/08.8210220350
- 8210290328 Second interim deficiency rept re use of monconservative calculational method to evaluate General Const Spec G-32 spacing violations Initially reported on 820828 Next rept will be sent by 830528 MILLS.L M Tennassee Valley Authority 62/10/12 D'REILLY, J P Region 2. Office of Director 2pp 15853 064 24X Fiche 50-000, 82/10/12-8210290328
- 52.10290059 Sixth interim deficiency rept re piping potential safety concern Initially reported on 801121 BMW amalyses completed except for in-core piping Next rept by 830523 Also reported ger Part 21 MILLS.L M Tennessee Valley Authority 82/10/14 0/REILLY, J P Region 2, Office of Director 2pp 15854 024 24x Fiche 50-438,82/10/14,8210290057
- 8210290236 Third interin deficiency rept re-potentially overstressed embedded plates initially reported on 820412 investigation continuing & const activities deferred until sufficient info gathered to determine completion of project MILLS.L M Tennessee Valley Authority 82/10/14 O'REILLY, J.P. Region 2. Office of Director 2pp 15853 229 24X Fiche 50-000,82/10/14,8210290236
- 9210270324 Third interim deficiency rept re Bresser safety valve. Model 31709NAs suffering unacceptable internal damage during steam test initially reported on 610707 EPRI L 0&M repts evaluated Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 62/10/14 0/REILLY. J P Region 2. Office of Director 2pp 15853 101 24% Fiche 50-438.82/10/14.8210270324
- 8210250320 First interim deficiency mept re addition of locking devices to handwheel operated values initially reported on 820916 Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820910 MILLS.L M Tennessee Valley Authority 82/10/18 O'REILLY, J.P. Region 2. Office of Director 2 pp 15802 359 24X Fiche 50-000. 82/10/18.8210260320
- 8210250322 First interim deficiency rept re generic deficiencies in solid state control sys & basic control room switch modules supplied by Consolidated Controls Corp Initially reported on 820916 Next rept by 830319 Also reported per Part 2! HILLS.L H Tennessee Valley Authority 82/10/18 O'REILLY, J P Region 2, Office of Director 2pp 15799 342 24X Fiche 50-438,82/10/18,8210260322
- 8210260251 Final deficiency rept rework releases allowing const to cut reinforcing steel to install anchor builts for pipe supports Initially reported on 820727 Personnel instructed to review design drawings more carefully MILLS.L M Tennessee Valley Authority 82/10/19 0'REILLY, J P Region 2, Office of Director 2pp 15799 350 24X Fiche 50-438.82/10/19.8210260251

- 8210260105 Third interim deficiency rept re governor lube ail cooler initially reported on 820308 Supplier has provided drawing by procedure to relocate cooler below governor Vendor working to identify cause Also reportable per Part 2! MILLS.L M Tennessee Valley Authority 82/10/20 0'REILLY.JP Region 2. Office of Director 2pp 15797 120 24X Fiche 50-438, 82/10/20.8210260105
- 8210290274 Final rept for Deficiencies B & E & seventh interio rept for Deficiencies A & D re control of procurement activities. Initially reported on 810316 Final corrective actions noted Next rept expected by 830428 MILLS.L M Tennessee Valley Authority 62/10/21 D'REILLY, J.P. Region 2, Office of Director 4pp 15853 143 24X Fiche 50-000, 82/10/21, 8210270274
- 8210270248 Revised final deficiency ropt re structural tubing escending AMS allowables initially reported on BiO813 Design drawings which dictate configuration of 86 cable tray supports altered to ensure seismic qualification MILLS: I. X. Tennessee Valley Authority 82/10/22 O'REILLY, JP Region 2. Office of Director 3pp 15853 122 24X Fiche 50-438, 82/10/22, 8210270248
- DECKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8210130010 Requests submittal of addl fee for 820721 application for extension of const completion dates DIGOS:R License Fee Management Branch 82/09/27 DAVIDSON.D R Cleveland Electric 111uminating Co 1p 15692 332 24X Fiche 50-440.82/09/27,8210130010
- 8210130179 Advises that response to NRC 820904 itr re degraded core hydrogen control will be provided by 821201 DAVIDSON,D R Cleveland Electric Illuminating Co 82/09/29 SCHHENGER,A Licensing Branch 2 ip 19673 019 24X Fiche 50-440,82/09/29,8210130179
- 8210190326 Forwards slide presentation from 820813 meeting re-safety relief hydrodynamic loads Position similar to criteria outlined in NURGE-0763 Encls withheld (ref 106FR2 790) DAVIDSON.D R Cleveland Electric Illuminating Co 82/10/08 SCHMENCER.A Licensing Dranch 2 2pp 15742 059 24X Fishe 50-440.82/10/08.8210190326
- 8210260419 Forwards NEDE-22203, "Reactor Internals Vibration Predictions," dtd Aug 1982 Rept contains proprietary infore internals vibration program & peak amplitude predictions per engineering analysis Rept withheld (ref 10CFR2 790) DAVIDBON, D.R. Cleveland Electric Illuminating Co. 62/10/08 SCHMENCER, A. Licensing Branch 2 1p 15806-114 24X Fiche 50-440,82/10/08.8210260419
- 6210190619 Confirms 621006 telcon re preoperational testing progras
 Util not required to continue sending preliminary
 preoperational test procedures Current status of procedures
 & implementation will be forwarded monthly
 LITTLE.W 8 Division of Engineering & Technical Programs 62/10/15
 HICKS,O R Clevoland Electric Illiminating Co ip 15737 223
 24% Fiche 50-440.82/10/15,8210190619
- 8210210079 Forward's proprietary util 821008) to & attachments resistive relief valve hydrodynamic loads, inadvertently omitted from original submittal Nonproprietary info to be provided by 821105
 DAVIDSON D R Cleveland Electric Filluminating Co 82/10/15
 SCHHENCER: A Licensing Branch 2 ip 15762 235 24%
 Fiche 50-440, 82/10/15, 8210210079
- B210270073 Notification of 821109 meeting w/util.C-E & 9Al in Bibbul MD to discuss pool dynamic load criteria application to plant specific design STEFANO.J Licensing Branch 2 82/10/19 SCHWENCER.A Licensing Branch 2 3pp 15834 296 24X Fiche 50-440.82/10/19.8210270073
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8210260235 Comments on FES for facility Applicant aware of effluent limits No add 1 adverse environ impacts within EPA field of expertise anticipated BACKLEY, B T Environmental Protection Agency 82/10/19 SCHLENGER, A Licensing Branch 2, 1p 15799 354 24X Fiche 50-440, 82/10/19, 8210260235,

RRC Safety Evaluation Report (SER), supple & correspondence

210150233 Forwards response to SER Confirmmatory Issue 16 re beitline weld matls Info revises response to Questions 123 1,123 2 4 123 3 & should respive issue of matl surveillance capsules DAVIDSON, DR Cleveland Electric Illuminating Co 02/09/22 SCHKENGER, A Licensing Branch 2 42pp 15706 010 24X Fiche 50-440,82/09/22.8210150233

- 210130173 Advises that responses to MRC 820908 ltr re SCR Gutstanding Issue 21 concerning reanalysis of transients & accidents & development of emergency operating procedures will be provided by 821027 DAVIDSON. D R Cleveland Electric Illuminating Co 82/09/2B SCHMENCER.A Licensing Branch 2 tp 15673 044 24X Fiche 50-440, 62/09/28.8210130173
- 210190333 Responds to SER Confirmatory Items 32 & 45 re accident monitoring instrumentation & location of plant area radiation monitoring instrumentation Items also address TMI Items II F 1 3.11 F 1 4.11 F 1 5 & 1I F 1 6
 DAVIDSON, D R Cleveland Electric Illuminating Co 82/10/14
 SCHWENCER, A Licensing Branch 2 3pp 15742 120 24X
 Fiche 50-440. 82/10/14.8210190333
- 210170AB3 Forwards response to SER Confirmatory Issues 28,30 & 33 re instrumentation & control Three oversize drawings encl Aparture cards are available in PDR DAVIDSON, D R Cleveland Electric Illuminating Co 82/10/14 SCHMENCER.A Licensing Branch 2 6pp 15751 013 24x Fiche 50-440, 82/10/14.8210170683

Security, medical, emergency & fire protection plans

- '07180055 FOIA request far all documents since 1979 re drug or alcohol abuse by persons at facilities SANICKI,5 G News-Herald Milloughby, OH 82/08/30 FELTON, J H Division of Rules and Records 1p 19758 359 24X Fishe 50-440, 62/08/30, 820/180055
- 10190199 Responds to FOIA request for all documents since 1979 redrug or alcohol abuse by persons at facilities Forwards documents identified during 820913 tolcon FELTON. J M Division of Rules and Records, 82/09/15 SAWICKI. 8 G News-Herald Willoughby. OH 1p 15758 360 24X Fiche 50-440. 62/09/15. 8210190199
- 8210170204 Provides info re drug & alcohol abuse, fire support deficiencies, theft & forced entry observed at facilities Author name deleted * Affiliation Unknown 82/09/15 NRC No Detailed Affiliation Oiven 2pp 18758 361 24X Fiche 50-440,82/09/15,8210190199
- 8210190207 Ack receipt of itr expressing concerns re security administration at facility NRC does not impose security requirements on licensee prior to onsite receipt of reactor fuel Contacting util suggested info partially deleted PHILLIP, 0 A Region 3, Chicago, Office of the Director (81/03/01) 81/07/16 Affiliation Unknown 1p 15758 363 24% Fiche 50-440,62/09/15,8210190199
- iO(90011 Notification of 821006 meeting w/util in Bethesda:MD to discuss responses to NRC questions re emergency plan & status of plan finalization STEFANO.J Licensing Branch 2 82/09/23 SCHWENCER, A Licensing Branch 2 3pp 15760 318 24X Ficha 50-440,82/09/23,8210190011
- 10260572 Releases public version of revised emergency plan FELTON.J H Division of Rules and Records 62/10/08 Document Management Branch 1p 15832 026 24X Fiche 50-440,82/10/08. 8210260572
- B210260575 Forwards public version of Revision O to emergency plan DAVIDSON, D. R. Commonwealth Edison Co. B2/09/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15832 027 24X Ficha 30-440, 82/10/08, B210260572
- 3210260579 Public version of Revision O to smargency plan • Commonwealth Eduson Co 82/09/22 29/pp 15832 029 24X Fiche 30-440, 62/10/08-8210260572

Adjudicatory correspondence

10070075 Forwards responses to interrogatories from Sunflower
Alliance requiring FEMA reply
KRIMH.R W Federal Emergency Management Agency 82/07/07
RRINES, B K Division of Emergency Preparedness 35pp 15428 127
24% Ficha 50-440.82/09/09.8210070075

- 8210010335 Reply to applicant 820721 motion to amend ASLB 820716 memorandum & order re scheduling Moving filing date of testimony will prejudice intervenors Applicant suggestion to delay hearing until 830222 should be granted HIATT.5 L. Ohio Citizens for Responsible Energy 82/07/27 Atomic Safety and Licensing Beard Panel 1p 15569 163 24% Fiche 50-440, 82/07/27, 8210010335
- 8210010366 Seventh set of interrogatories Certificate of Svc encl Related correspondence HIATTS L Dha Cittizens for Responsible Energy 82/09/27 Office of the Executive Legal Director 8pp 15573 095 24X Fiche 90-440,82/09/27,8210010366
- 82100103/7 Reply opposing applicant 820913 motion to rescind ASLB 810804 procedural order requiring intervenors to respond to NRC 2 applicant answers to late filed contentions Certificate of Byc encl HLATT.8 L Ohio Citizens for Responsible Energy 82/09/27 Atomic Safety and Lizensing Board Panel 5pp 15573 054 24X Fiche 50~440, 82/09/27, 8210010377
- 8210010386 Requests article from Nuclear News noted in ASLB 820916 memorandum & order by provided to all parties since magazine unavailable in public & univ libraries HIATT'S L. Ohio Citizens for Responsible Energy 82/09/27 BLOCH, P.B., KLINE, J.R., SHON, F.J., Atomic Bafety and Licensing Board Panel 1p 15569 212 24X Fiche 50-440,82/09/27,8210010386
- 8210010416 Sixth set of interrogatories Certificate of Svt encl Related correspondence HIATT'S L. Dhio Citizens for Responsible Energy 82/09/27 Cleveland Electric Illuminating Co tOpp 15372 173 24x Fiche 50~440.82/09/27.8210010416
- 8210010250 Response apposing applicant motion to revise procedures for late filed contentions No prejudice demonstrated Proof of Svc encl HILT.D.D. Sunflower Alliance HILT.D.D. Hilt, D.D. 82/09/28 Atomic Safety and Licensing Board Panel 2pp 15568 262 24X Fiche 50-440,02/09/28.8210010250
- 8210010323 Motion for 5-day extension to file motion to compel discovery against NRC Addi time necessary due to other business & personal illness Proof of Svc enci WILT-D D Sunflower Alliance WILT-D D Wilt, D D 82/09/20 Atomic Safety and Licensing Board Panel Ip 19569 192 24X Fiche 50-440,82/09/28,8210010223
- 8210010345 Answer to fourth set of interrogatories Certificate of Svc encl MILLMORE, R L. Cleveland Electric [lluminating Co. HILLMORE, R L. Shaw, Pittman, Potts & Troubridge 82/09/28 Ohio Citizens for Responsible Energy 17pp 15574 001 24% Fiche 50-440,82/09/28, 8210010345
- 8210010457 Forwards RF Zucker & RA Pender original affidavits to be substituted for photocopies in applicant 820928 answer to OR Citizens for Responsible Energy fourth set of interrogatories Related correspondence WILLMORE.R L Shaw, Pittman, Potts & Trowbridge WILLMORE.R L Cleveland Electric Illuminating Co 82/09/29 Docketing & Services Branch 3pp 15572 311 24X Fiche 50-440, 82/09/29, 8210010457
- 8210040019 Notice of withdrawal of appearance in proceeding LEWIS, S. H. Hearing Branch 2 82/09/29 3pp 15581 262 24X Fiche 50-440,82/09/29,8210040019
- B210040019 Certifies svc of NRC response to Sunflower Alliance motion seeting admission of late contention on shift rotation & GE Johnson motice of appearance on B20930 JOHNSON, 00 Hearing Branch 4 82/09/30 2pp 15581 348 24X Fiche 50-440, 82/09/30, 8210040015
- 8210040017 Response opposing Sunflower Alliance 820910 motion seeking admission of late contention on shift rotation Contention beyond Commission regulatory requirements, lacks basis & nazus & is untimely JOKNSON, 0 E Hearing Branch 4 82/09/30 Atomic Safety and Licensing Board Panel 8pp 15581 297 24X Fiche 50-440.82/09/30, 8210040017
- 8210040023 Notice of appearance in proceeding JOHNSON, C E Hearing Branch 4 82/09/30 lp 15581 256 24X Fiche. 50-440, 82/09/30, 8210040023
- 8210050173 Third set of interrogatories re Issue 3 & requests for production of documents Proof of Svc enci Related correspondence WILT.D D Sunflower Alliance WILT.D D Wilt, D D 82/09/30 NRC No Detailed Affiliation Given 7pp 15604 138 24X Fiches 50-440. 82/09/30, 8210050173

- 8210050228 Fourth request for production of documents re Contention I, Issue I an energency evacuation planning Proof of Svc encl Related correspondence HILT: D D Sunflawer Alliance HILT: D D Wilt. D D 82/09/30 Office of the Ejecutive Director for Operations 2pp 15610 351 244 Fiche 50-440, 82/09/30, 82/0050228
- 8210050242 Requests extension of discovery time on Contention 1 lasses not ready for hearing as final emergency plans not yet in place Plans must be reviewed prior to hearing Proof of Svc enci Related correspondence WILT.D D Sunflower Alliance WILT.D D Wilt, D D 82/09/30 Atomic Safety and Licensing Board Panel 2pp 15610 334 24X Fiche 50-440, 82/09/30, 8210050242
- 5210050252 Third set of interrogatories w/requests for production of Jocuments re Issue 3 on adequaty of applicant QA program Proof of Svc enci Related correspondence WILT, D.D. Sunflower Alliance WILT, D.D. Wilt, D.D. 82/09/30 Cleveland Electric Illuminating Co. 12pp. 15610-274 24X Fiche 50~440,82/09/30,8210050252
- 8210050255 Third set of interrogatories & request for production of documents re Issues 1,3 & 11 on offsile emergency evacuation plans QA & local economic benefits, respectively Certificate of Svc enc?
 HILLMORE R L Cleveland Electric Illuminating Co WILLMORE, R L Shaw, Pittman, Potts & Troubridge 82/09/30 Sunflower Alliance 12pp 15609 199 24x Fishe 50-440, 82/09/30, 8210050255
- 6210050374 Response in opposition to Sunflower Alliance. Inc 820910 motion to compel applicant answer to second set of interrogatorics Applicants will respond shortly Certificate of Sic enct
 SILBERG, J.E. Cleveland Electric Illuminating Co. SILBERG, J.E. Shau, Pattman, Potts & Troubridge 82/09/30. Atomic Safety and Licensing Board Panel. 20pp. 15608-256. 24X Fiche 50-440.88/09/30, 8210050374.
- 8210050207 Seventh set of interrogatories directed to applicant & eighth set of interrogatories directed to ARC pursuant to ASLB 810728 Memorandum & Order LBP-81-24 Certificate of Svc enc. Related correspondence
 HIATT, S.L. Dhio Citizens for Responsible Energy 82/09/30
 Cleveland Efectric 311uminating Co 5pp 15614 157 24X
 Fiche 50-440, 82/09/30, 8210060207
- 82100500A9 Response supporting applicant B20913 motion to revise procedures for late filed contentions Allowing intervenors to raise new matter in reply constitutes amend to contentions Certificate of SVC encl CUTCHIN.J M. Hearing Dranch 4. 82/10/04. Atomic Safety and Licensing Poard Panel. Bpp. 15603 168 24% Fiche 50-440.82/10/04, 82(0050069
- 9210150192 Requests clarification of doctet numbers for Harris & Petry plants Mixup may be causing prejudice to intervenors since documents go to incorrect LPDR HIAIT.S L Obto Citizens for Responsible Energy 82/10/04 Docteting & Services Branch ip 15707 260 24% Fische 50-000.82/10/04,9210150192
- 8210060303 Response opposing DH Citizens for Responsible Energy 920920 motion to compet discovery of NRC 5 util ASLB chairman comments did not allow intervenors to broaden contention or scope of discovery CUICHIN-J M Hearing Branch 4 82/10/05 Atomic Safety and Licensing Board Panel 6pp 15617 017 24% Fiche 30-440, 82/10/05, 8210060303

- 8210150161 Confirms 821005 telcon re time for filing util response to OH Citizens for Responsible Energy motion to compel answers to Sunflower second set of interrogatories Answer to be filed by 821012 Svc list encl Related correspondence SILBERG, J E Shew, Pittman, Potts & Troubridge SILBERG, J E Cieveland Electric Illuminating Co 82/10/06 HIATT, B Ohio Citizens for Responsible Energy 2pp 15697 067 24% Fiche 50-440, 82/10/06, 82(0150161
- 8210120337 Hemorandum & Order denying Sunflower Alliance, Inc 820520 request for extension of time for discovery on Issue i Info has been made available BLOCH, P B Atomic Safety and Licensing Board Panel B2/10/08 Sunflower Alliance ip 15652 183 24X Fiche 50-440,82/10/08, 82010337
- 8210130027 Memorandum & order denying OH Cititens for Responsible Energy 820907 motion to sever proceedings No reason provided for ASLB to reconsider 810909 ruling on identical motion by Synflower Alliance 810909 and Licensing Board Panel 82/10/00 Ohio Cititens for Responsible Energy ip 13478 283 24X Fiche 50~440, 82/10/08, 8210130329
- 8210130333 Memorandum & order admitting Contention 12 re inadequals consideration of economic consequences of accidents Preponderance of considerations favors admission of contention BLOCH.P B. KLINE.J R. SHON.F J. Atomic Bafety and Licensing Scale Panel 82/10/08 Ohio Citizens for Responsible Energy 5pp 13682 059 24X Fiche 50-440.82/10/08.8210130333
- B210150228 Confirms conversations w/OH Citizens for Responsible Energy & Judge Blach relections of time for util to respond to OH Citizens for Responsible Energy B20920 motion to compel discovery on NRC & util Response due B21016 W/svc list SILBERO, J.E. Shaw, Pittman, Potts & Troubridge SILBERO, J.E. Cleveland Electric Jiluminating Co. B2/10/OB BLQCH.P.B., KLINE.J.R., SHQN.F.J. Atomic Bafety and Licensing Board Panel 49, 15706 COB. 24X Fishe 50-440, 82/10/OB, 8210150228
- 8210150467 Answer to sixth set of interrogatories Certificate of Burenci HILLMORE.R L. Cleveland Electric Illuminating Co. WILLMORE.R L. Shaw. Pittman. Potts & Troubridge 82/10/12 Ohio Citizens for Responsible Energy 10pp 18703-050 24X Fiche 50-440.82/10/12.
- B2101B0211 Reply opposing NRC & applicant responses to OH Citizens for Responsible Energy motion for leave to file Contentions 21-26 Good cause specificity & basis requirements met Certificate of Sec encl HATT.8 L. Dhio Citizens for Responsible Energy 82/10/12 Atomic Safety and Licensing Board Panel 14pp 15718 110 24% Fiche 50-440-82/10/12.8210180211
- 8210150175 Advises that documents requested by Bunflower Alliance fourth request directed to Executive Director for Operations available in PDR CUTCHIN.J M Hearing Branch 4 82/10/13 WILT, D D Wilt, D D WILT, D D Sunflower Alliance 1p 15707 183 24X Fiche 50-440, 82/10/13, 82/10/175
- 8210150275 Advises that NRC will not voluntarily respond to any discovery requests in Bunflower Alliance third set of interrogatories & requests for documents.except Request (? Remainder of discovery broader than Issue 3 CUICHIN.J M Hearing Branch 4 82/10/13 WILT.D D Wilt, D.D Wilt, D.D Bunflower Alliance 3pp 15705.001 24x Fiche 50-440.82/10/13,8210150275
- 8210180155 Advises of correction to util response to Interrogatory 68 of CH Cittlens for Responsible Energy sixth set of interrogatories Conclusion of response remains unchanged Related correspondence
 HILLNORE, R L Shaw, Pittman, Potts & Troubridge WILLHORE, R L
 Cleveland Electric Illuminating Co 82/10/14 HIATT.8 Ohio Cittlens for Responsible Energy ip 15719 269 24X
 Fiche 50-440.82/10/14,8210180155
- 8210190377 Answers to 820907 Fifth set of interrogatories Profqualifications & Certificate of Syc encl JOHNSON & E Operations & Administrative Division 82/10/13 Bhio Citiens for Responsible Energy 15pp 15740 300 24% Fichs 50-440-82/10/15,8210190377
- 8210190475 Answer opposing Sunflower Alliance 820928 motion to establishe to file motion to compel discovery against NRC No basis for unlimited request provided Certificate of Svc encl CUTCHIN-J M Hearing Branch 4 82/10/15 Atomic Safety and Licensing Board Panel, 4pp 15740 241 24x Fiche 50-440,82/10/15 cm 10190475

1 1

- 8210210351 Objects to issuance of ASLB 821008 memorandum & order re request to extend discovery on Issue i Order issued ASLB should request responses from all parties on expedited schedule W/Certificate of Svc Related correspondence HIATT.S L Ohio Citizens for Responsible Energy 82/10/15 8LOCM.P B . KLINE,J R . SHON,F J Atomic Safety and Licensing Bourd Panel 1p 15764 010 24X Fiche 50-440.82/10/15.8210210351
- --8210210358 Seventh discovery progress rept.pursuant to ASLB 810909 memorandum & order.LDP-81-35 Interrogatories submitted to applicant & NRC re Issues 4.5.6.7.8 & 9 Discovery re Issue 9 forthcoming HIATT.S L Onto Citizens for Responsible Energy 82/10/15 2pp 15764 011 24X Fiche 50-440, 82/10/15.8210210351
- --0210210355 Motion to extend discovery on Issue 9 to 821101 to permit review of documents referenced in applicant responses to 820830 interregatories & foilowed discovery Certificate of Svc encl Related correspondence
 HIATT, S. L. Onio Citizens for Responsible Energy 82/10/15
 Atomic Bafety and Licensing Board Panel 3pp 15764 013 24X
 Fiche 50-440,82/10/15,821021035
- 8230210284 Answer opposing OH Citizens for Responsible Energy 820920 motion to compel discovery on NRC & util Interrogatories not relevant to & beyond scape of Issue & Certificate of Svc encl Related correspondence
 STLEERG. J E Cleveland Electric filuminating Co GILBERG. J E Shaw, Pittman, Potts & Trombridge 82/10/18 Atomic Safety and Licensing Roard Panel 3App 15765 099 24X Fiche 50-440, 82/10/18, 0210210284
- 3210210333 Amended answer to Interrogatory 13 of Sunflower Alliance second set of interrogatories Certificate of Svc encl Related correspondence SILBERO, J E Cleveland Electric Illuminating Co SILBERO, J E Shaw, Pittman, Potts & Troubridge 82/10/18 Sunflower Alliance Spp 15763 177 24% Fiche 30-440.82/10/18.8210210333
- 32102204B) Requests attachment to NRC 7B0203 ltr to GE be provided to allow progress on Issue 4 Document needed before intervenor can decide if yepdates to interrogatories necessary Related correspondence HIATT, B. L. Ohio Citizens for Responsible Energy 82/10/18 SILUERRO, J. Shaw, Pittman, Potts & Trowbridge BILUERRO, J. Cleveland Electric Illuminating Co. ip 15779 078 24X Fiche 50-440, 82/10/18.82102204B1
- 3210210476 Memorandum & order denying Sunflower Alliance 820910 motion to compel applicant to answer second set of interrogatories of util agrees to stipulation on potassium iodide subcontention. Interrogatory 36 need not be answered BLOCH, P. R. KLINE, J. R. SHON, F. J. Atomic 8afoty and Licensing Board Panel 82/10/19 (Develand Electric Illuminating Co. 6pp 15762 265 24X Fiche 50-440,82/10/19,8210210476
- #210220305 Answer to 820930 seventh sot of interrogatories Certificate of Byc enc!
 WILLMORE,R L. Cleveland Electric Illuminating Co. WILLMORE,R L.
 Shaw, Pittman, Potts & Trowbridge B2/10/19 Ohio Citizens for Responsible Energy 13pp 15776 053 24x Fiche 50-440,82/10/19,8210220305
- 1210220309 Seventh discovery progress rept Certificate of Svc enci HILLMORE.R L Cleveland Electric Illuminating Co WILLMORE.R L Shaw, Pittman, Potts & Troubridge 82/10/19 4pp 15776 049 24 Fiche 50-440.82/10/19.8210220309
- 1210220396 Hotion for leave to file answer to OH Citizens for Responsible Energy (OGRE) 821012 reply to util & NRC answers to DCRE motion for leave to file Contentions 21-26 WILLMORE, R L Cleveland Electric Hiuminating Co WILLMORE, R L Shaw, Pittman, Potts & Troubridge 82/10/19 Atomic Safety and Licensing Board Panel 2pp 15777 312 24X Fiche 50-440,82/10/19,8210220396
- -8210220405 Answer to CH Citizens for Responsible Energy 821012 reply to NRC & applicant response to Citizens motion to file Contentions 21 through 26 Citizens did not meet burden of proof for admission of new contentions W/Certificate of Svc WILLMORE.R L. Cleveland Electric Illuminating Co WILLMORE.R I. Shaw, Pittmen, Potts & Trowbridge 82/10/19 Atomic Safety and Licensing Board Penel 15pp 15777 314 24X Fiche 50-440,82/10/19,8210220396
- 1210250331 Reply brief supporting motion to submit add1 contention Good cause for late filing demonstrated Applicant shift rotation plans may not be incorporating circadian principles WILT.D.D. Bunflower Alliance. WILT.D.D. Wilt, D.D. 82/10/19 Atomic Safety and Licansing Board Panel 3pp 15790.325 24X Fiche, 50-440, 82/10/19,8210250331

- 8210250297 Answer to DH Citizens for Responsible Energy 821015 motion to extend discovery on Issue 9 repolymer degradation No justification exists for extending discovery cutoff date Cortificate of Svc enci SILBERG, J E (Develand Electric Illuminating Co SILBERG, J E Shew, Pittman, Potts & Troubridge 82/10/20 Atomic Safety and Licensing Board Panel Spp 15790 175 24X Fiche 50-440, 82/10/20, 82(0250279
- 8210250322 Supplemental answers to Sunflower Alliance.Inc second set of interrogatories Certificate of Svc encl
 SILBERO.JE Clevelend Electric Illuminating Co SILBERG.J E. Shaw. Pittman, Potts & Troubridge 82/10/20 Sunflower Alliance
 17pp 15790 226 24X Fiche 50-440.82/10/20.8210250322
- 8210250365 Advises that NRC will not voluntarily respond to CHI Catarenter Responsible Emergy seventh set of anterrogatories except for interrogatories listed Requests irrelevant & will not lead to discovery of admissible evidence CUTCHIN.J M Hearing Branch 4 62/10/22 HIATT, 5 L Ohio Citizenter Responsible Emergy 2pp 15790 175 24X Fiche 50-440, 82/10/2/, 8210250365
- 8210260033 Answers to 820830 fourth set of documents Certificate of Svienci enci MRIGHT, N.A. Hearing Branch 2 82/10/22 Chio Citizens for Responsible Energy 12pp 15799 124 24X Fiche 50-440, 82/10/22. 8210240033
- #21028021A Responds to 821018 ltr resvo of documents to parties
 Tolcons could expedite matters in future Svc list and
 Related correspondence
 SILBERO, JE Shaw, Pittman, Potts & Trombridge 82/10/22
 HIATT, B L Ohio Citizens for Responsible Energy 7pp 1583/356
 24X Fiche 30-440,82/10/28.8210280216
- 8210280231 Update to response to Interrogatory 4-2 of DH Citizens for Responsible Energy 820928 fourth set of interrogatories Related correspondence WILLMORE.R L Shaw, Pittman, Potts & Trowbridge WILLMORE.R L Cleveland Electric Illuminating Co 82/10/22 HIATT.S Ohio Citizens for Responsible Energy 1p 15837 081 24x Fiche 80-440.82/10/22,8210280231
- 8210260383 Answers to listed interrogatories of 820927 seventh set of interrogatories NRC will not voluntarily answer remaining interrogatories Certificate of Svc encil CUTCHIN.J H. Hearing Branch 4 82/10/25 Ohio Citizens for Responsible Energy Tipp 15803 348 24% Fiche 50-440,82/10/25,833030438
- 8210260375 Discovery rept for previous two months per ASLB 810909 memorandum & onder CUTCHIN,J M Hearing Branch 4 82/10/25 BLOCK,P B , SHON,F J , KLINE,J R Atomic Safety and Licensing Board Panel ip 15803 34J 24X Fiche 50-440,82/10/25,8210260395
- 8210280246 Forwards RB Coffey original affidavit to be included in applicant 821020 supplemental answers to Sunflower Alliance second set of interrogatories Related correspondence HILLMORE.R L Shew. Pittman. Potts & Troubridge WILLMORE.R L Cleveland Electric Illuminating Co 82/10/25 Docketing & Services Branch 2pp 15837 094 24X Fiche 50-440.82/10/25.
- 8210270237 Requests enci RF Zucker & RV Tanney original affidavits he substituted for photocopies in applicant 821017 answers to OH Citizens for Responsible Energy seventh set of interrogatorias will MORGER L. Shaw, Pittman, Potts & Trowbridge WILLHORE, R. L. Cieveland Electric Illuminating Co. 82710726 Docketing & Bervicts Branch Opp. 15834-069 24X Fiche 50-440.82710726. 8210270287.
- 8210280346 Answer apposing OH Citizens for Responsible Energy 821015 motion to extend time for discovery on Issue 9 No justification for extension provided Certificate of 8vc encl CUTCHIN, J M Hearing Branch 4 82/10/27 Atomic Safety and Licensing Board Panel. 5pp 15838 301 24X Fiche 50-440.82/10/27, 8210280346
- K Utility Final Bafety Analysis Report (FSAR) & amonds
- 8210040146 Forwards Amend 9 to FSAR Certificate of Svc encl, DAVIDSOM D R Cleveland Electric Hilminating Co 82/09/20 DENTOM H R Office of Nuclear Reactor Regulation, Director 3pp 15594-251 24X Fiche. 50-440.82/09/30.8210040146
- --8210040130 Amend 9 to FBAR 4 Cleveland Electric Illuminating Co 82/09/30 573pp 13584 254. 24% Fiche 50-440,82/09/30.8210040144

M Antitrust correspondence

- 6210120268 Confirms B21007 telcon & forwards NRC 820809 ltr to City of Cleveland.Div of Light & Power 820908 % 10 responses VOGLER.B H Hearing Branch 2 82/10/08 LAMSDALE.J Squire, Sanders & Denpsey ip 15652 318 24X Fithe 50-440.82/10/08.
- u Inspection reports. IE Bulletins & correspondence
- 8210060305 Forwards IE insp Repts 50-440/82-11 & 50-441/82-10 on 820931-0902 No noncompliance naked LITHER IS Division of Engineering & Technical Programs 82/09/22 DAVIDSON D R Cleveland Electric Illuminating Co 2pp 15619 195 24X Fiche 50-440 82/09/22.8210060305
- --8210060308 IE Insp Repts 50-440/82-11 & 50-441/82-10 on 820831-0902 Nu noncompliance noted Major areas inspected preservice insp procedures & work activities, previous insp findings & IE Bulletin 80-08 activities when S. Denisted Procedures & WARD. K D. DANIELSON. D II. Region 3. Office of Director 82/09/14 Spp 15419 197 24% Fiche 50-440.82/09/22.8210040305
- 8210190763 Forwards IE Investigation Repts 50-440/81-19 & 50-441/81-19 on 811027-820317 & notice of violation REPPLER, J G Region 3. Office of Director 82/09/27 DAVIDSON, D R Cleveland Electric Illuminating Co 3pp 15736 318 24% Fiche 50-440, 82/09/27, 8210190763
- --8210190771 Notice of violation from investigation on 811027-820319 KEPPLER, J O Region 3. Office of Director 82/09/24 9pp 15736 321 24X Fiche 50-440,82/09/27,8210190763
- --8210190787 IE Investigation Repts 50-440/81-19 % 50-441/81-19 un 811027-620319 Noncompliance noted Gould Inc Drawings E-35-51-956 E231 & E233 inadequately reviewed & instructions not incorporated into cable pulling procedures KEIL.C H. NAIDU.K R , BRAWND.C D Region J. Office of Director 82/09722 95pp 15736 330 24X Fiche 50-440.62/09/27,8210190/63
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-12"; Implant Seeds " Svc list end! COBB.L J Division of Fue) Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000 82/10/06,8208190233
- 820Bi90238 IE Builetin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Stoel, Recirculation Sys Piping at BMR Plants " Svc list enc! DEYQUNG.R C Director's Giffice Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 1980 125 24X Fiche 50-000, 82/10/14.8208190238
- d210260333 Ack recript of 821008 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/82-09 h 50-441/82-08 hORELIUS.C E Division of Project b Resident Programs 82/10/21 DAVIDSON, D R Cleveland Electric Illuminating Co ip 15803 193 24x Fichs 50-440/82/10/21/8210260333
- --8210260337 Responds to NRC 820910 ltr re violations noted in IE Insp Repts 50-440/82-09 & 50-441/82-08 Corrective actions Kaiser Engineer Procedure GAP-22 revised to require annual evaluation Detailed hardware insp performed 820728 DAVIDSON, D.R. Cleveland Electric Illuminating Co. 82/10/08 NORELIUS.C.E. Division of Project & Resident Programs 6pp 15803 192 24X Fiche 50-440, 82/10/21/8210260333
- S Reportable occurrences, LERs & related correspondence
- 8210050132 Final deficiency rept to nonconforming Transamerica Dalava) standby diesel generator ASPE Section Ill.Class 3.piping welds initially reported on 820329 Weld into k required repair/rework will be completed by 830401 DAVIDSON, D.R. Cleveland Electric Illuminating Co. 82/09/24 MEPPLER, J.G. Region 3. Office of Director 2pp. 15605-047 24X Fiche 30-440.82/09/24.8210050132
- 8210130364 Third interim deficiency rept re rejection of previously accepted containment vessel radiographs Initially reported on 820405 All potentially rejectable radiographs submitted to Hartford Steam Boiler insp Co for review DAVIDSON.D R Cleveland Electric Illuminating Co 82/09/30 KEPPLER.J O Region 3. Office of Director 2pp 15681 169 24% Fiche 50-440.82/09/30.8210130364

- DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- B2(0130010 Requests submittal of add1 fee for B20721 application for extension of const completion dates D1605.R License Fee Hanagement Branch Cleveland Electric [11uminating Co lp 15492 332 24% Fichs 50-440.82/09/27.8210130010
- B210130179 Advises that response to NRC 820906 ltr re degraded cure hydrogen control will be provided by D21201 DAVIDSON, D R Cleveland Electric Illuminating Co 82/09/29 SCHMENGER.A Lizensing Branch 2 1p 15673 019 24X Fiche 50-440, 82/09/29, 8210130179
- 8210190326 Forwards slide presentation from 820813 meeting re-safety relief hydrodynamic loads Posttion similar to criteria outlined in NVRGE-0763 Encls withheld (ref 10CFR2 790) DAVIDSON, D.R. Cleveland Electric Illuminating Co. 82/10/08 SCHWENCER.A Licensing Branch 2 2pp 15742 059 24X Fichs 50-440.82/10/08.8210190326
- 8210260419 Forwards NEDE-22203, "Reactor Internals Vibration Predictions," dtd Aug 1982 Rept contains proprietary infore internals vibration program & peak amplitude predictions per engineering analysis Rept withheld (ref 10CFR2 790) DAVIDSON,D R Cleveland Electric Illuminating Co 82/10/08 SCHWENCER,A (Censing Branch 2 ip 15806 114 24X Fichs 50-440,82/10/08,6210260419
- 6210190619 Confirms B21006 telcon repreoperational testing program Util not required to continue sending proliminary preoperational test procedures Current status of procedures & implementation will be forwarded monthly LITLE, W S Division of Engineering & Technical Programs 62/16/13 HICKE, OR Cieveland Electric Illuminating Co Ip 15717 3-1; 244 Fiche 50-440.82/10/15.8210190619
- B210210079 Forwards proprietary util B2100B ltr & attachments is salaty relief velve hydrodynamic loads, inadvertently omitted from original submittal Nonproprietary info to be provided by B2110B DAVIDSON, D.R. Cleveland Clectric Illuminating Co. 82/10/13 SCHHENGER, A. Licensing Branch 2 lp 15762 233 24X Fiche 50-440, B2/10/15,8210210079
- B210270073 Notification of 821109 meeting w/util.C-E & OAI in Betheid:
 MD to discuss pool dynamic load criteria application to
 plant specific design
 STERAND, J Licensing Branch 2 82/10/19 SCHWENCER, A Licensing
 Branch 2 3pp 15836 276 24X Fiche 50-440,82/10/19,82102700/3
- D NRC Draft/Final Environmental Statements, supply & correspondence
- 8210260295 Comments on FES for facility Applicant aware of offluent limits No add1 adverse environ impacts within EPA field of expertise anticipated BACKLEY:B T Environmental Protection Agency 82/10/19 SCHWENGER:A Licensing Branch 2 ip 19799 354 24X Fiche 50-440; 82/10/19.8210260235
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8210130173 Advises that responses to NRC B20908 ltr re SER Gutstanding Issue 21 concerning reanalysis of transients & accidents & development of emergency operating procedures will be provided by 821029

 DAVIDBON.D R Cleveland Electric Illuminating Co 82/09/20 SCHMENGERA Licenzing Brench 2 ip 19673 044 24X

 Fiche 50-440, 82/09/28, 8210130173
- 8210190333 Responds to SER Confirmatory Items 32 & 45 re accident monitoring instrumentation & location of plant area radiation monitoring instrumentation Items also address TKI Items II F 1 3,11 F 1 4,11 F 1 5 & II F 1 4
 DAVIDBON,D R. Cleveland Electric Illuminating Co 82/10/14
 SCHHENGER,A Licensing Branch 2 Spp 15742 120 24X
 Fiche 50-440, 82/10/14, 8210190333

- 8210190683 Forwards response to SER Confirmatory Issues 28,30 & 33 re instrumentation & control Three oversize drawings encl Aperture cards are available in PDR DAVIDSON,D R Cleveland Electric Illuminating Co 82/10/14 SCHMENGER.A Licensing Branch 2 dep 15751 013 24% Fichs 50-440,82/10/14,8210190683
- F Security, medical, emergency & fire protection plans
- 8207180055 FOIA request for all documents since 1979 is drug or alcohol abuse by persons at facilities SANICKIS O News-Herald Willoughby, OH 82/08/30 FELTON, J M Division of Rules and Records ip 15758 359 24X Fiche 50-440
- 0210190199 Responds to FOIA request for all documents since 1979 redrug or alcohol abuse by persons at facilities Forwards documents identified during 820913 telcon FELTON.J K Division of Rules and Records 82/09/15 SAWICKI,S & News-Herald Willoughby, OH 1p 15758 260 24X Fiche 50-440,82/09/15,8210190199
- --B210190204 Provides info re drug & alcohol abuse, fire support deficiencies, theft & forced entry observed at facilities Author name deletod # Affiliation Unknown 82/09/15 NRC ~ No Detailed Affiliation Given 2pp 15758 361 24X Fiche 50-440, 82/09/15, 8210190199
- --8210190209 Ack receipt of Itr expressing concerns re security administration at facility NRC does not impose security requirements on licensee prior to onsite receipt of leactor fuel Contacting util suggested Info partially deleted PHILLIP.0 A Region 3. Chicago, Office of the Director (81/03/01) 81/07/16 Affiliation Unknown in 15758 363 24X Fiche 50-440,82/09/15.8210170179
- 8210190011 Notification of 821006 meeting w/util in Bethesda.MD to discuss responses to NRC questions re pmergency plan & status of plan finalization STEFANOIJ Licensing Branch 2 82/09/23 SCHWENCER.A Licensing Branch 2 3pp 15760 318 24X Fiche 50-440,02/09/23,8210190011
- 8210240572 Releases public version of revised emergency plan FELTON, J.H. Division of Rules and Records 82/10/08 Document Hanagement Branch Ip 15832 024 24X Fiche 50-440,82/10/08, 8210260572
- --8210260575 Forwards public version of Revision O to emergency plan DAVIDSOND R Commonwealth Edison Co 82/09/22 DENTON H R Offics of Nuclear Reactor Regulation, Director 2pp 19832 02/ 24X Fichs 50-440,82/10/08.8210260572
- --8210260579 Public version of Revision O to emergency plan 4 Commonwealth Edison Co 82/09/22 291pp 15832 027 24X Fiche 50-440.82/10/08.8210260572

O Adjudicatory correspondence

- 6210070075 Forwards responses to interrogatories from Bunflower Alliance requiring FEMA reply KRIMM.R W Federal Emergency Management Agoncy 82/09/09 GRIMES.B K Division of Emergency Preparedness 35pp 15628 12/ 24X Fiche 50-440.82/09/09.8210070075
- 8210010335 Reply to applicant 820721 motion to amend ASLB 820716 memorandum & order re scheduling Moving filing date of testimony will prejudice intervenors Applicant suggestion to delay hearing until BSORRE should be granted MIATT-S L Ohio Citizens for Responsible Energy 82/09/27 Atomic 8afety and Licensing Board Panel 1p 15569 163 24% Fiche 50-440, 82/09/27, 8210010335
- 8210010366 Beyenth set of interrogatories Cartificate of Svc encl Related correspondence HIATT, S.L. Ohio Citizens for Responsible Energy 82/09/27 Office of the Executive Legal Director, 8pp 15573 095 24X Fiche 50-440,82/09/27,8210010366
- 8210010377 Reply opposing applicant 820913 motion to rescind ASLB BIO804 procedurel order requiring intervenors to respond to MRC & applicant ensuors to late filed contentions. Certificate of Bvc and HIATT.8 L Ohio Citiens for Responsible Energy 82/09/27 Atomic Safety and Licensing Board Penel, 5pp 15573-054, 24X Fiche 30-440,82/09/27,8210010377

- 8210010386 Requests article from Nuclear News noted in ASLB 820916 memorandum & order be provided to all parties since magazine unavailable in public & univ libraries HIATT.S L Dhio Cititens for Responsible Energy 82/09/27 BLOCH.P B . KLINE, J R . SHON.F J Atomic Safety and Licensing Bowrd Panel 1p 15569 212 24% Fiche 50-440.82/09/2/.8210010386
- 8210010416 Sixth set of interrogatories Certificate of Svc encl Heluted correspondence HIATT, S. Dhio Citizens for Responsible Energy 82/09/27 Cleveland Electric Illuminating Co 10pp 15572 173 24X Fiche 50-440,82/09/27,8210010416
- 8210010250 Response opposing applicant motion to revise procedures for late filed contentions No prejudice demonstrated Proof of Syc encl WILT.D D Sunflower Alliance WILT.D D Wilt. D D 82/09/28 Atomic Safety and Licensing Board Panel 2pp 15568 262 247 Fiche 50-440.82/09/28.8210010250
- 8210010323 Motion for 5-day extension to file motion to compel discovery against NRC Add time necessary due to other business & personal lilness Proof of Svc enci HILT, D D Sunflower Alliance HILT, D D Wilt, D D 82/09/24 Atomic Safety and Licensing Board Panel 1p 15569 192 24% Fichw 50-440,82/09/28,8210010323
- 8210010345 Answer to fourth set of interrogatories Certificate of Sycenci enci WILLMORE.R L. Cleveland Electric Illuminating Co. WILLMORE.R I Shaw, Pittman, Potts & Trowbridge 82/09/20 Dhio Citizens for Responsible Energy 17pp 15574 001 24X Fichs 50-440.82/09/28 8210010345
- 9210010457 Forwards RF Zucker & RA Pender original affidavits to be substituted for photocopies in applicant 820928 answer to DH Citizens for Responsible Energy fourth set of interrogatories Related correspondence WILLMORE.R L. Shaw. Pitteman. Potts & Troubridge WILLMORE.R L. Cleveland Electric Illuminating Co 82/09/29 Docketing & Services Branch 3pp 15572 311 24X Fiche 50-440.82/09/29.8210010457
- 8210040019 Notice of withdrawal of appearance in proceeding LEWIS.5 H Hearing Branch 2 82/09/29 3pp 15581 262 24X Fiche 50-440.82/09/29.8210040019
- B210040015 Certifies svc of NRC response to Bunflower Alliance motion seeking admission of late contention on shift rotation & GE Johnson notice of appearance on 820730

 JOHNSON: 0 E Hearing Branch 4 82/09/30 2pp 15581 348 247

 Fiche 50-440.82/09/30,8210040015
- 8210040017 Response opposing Sunflower Alliance 820910 motion seeking admission of late contention on shift rotation Contention beyond Commission regulatory requirements, lacks basis & nexus & is untimely
 JOHNSON.0 E Hearing Branch 4 82/09/30 Atomic Safety and
 Licensing Board Panel 8pp 15581 297 24X Fiche 50-440,82/09/JD, 8210040017
- 8210040023 Notice of appearance in proceeding JOHNSON.G E Hearing Branch 4 82/09/30 ip 1558] 256 Fiche 50-440.82/09/30.8210040023
- B210050173 Third set of interrogatories re Issue 3 & requests production of documents Proof of Svc enci Related correspondence WILT.D D Sunflower Alliance WILT.D D Wilt. D D 82/0 NRC No Detailed Affiliation Given 7pp 15604 136 24X Fiche 30-440,82/09/30.8210050173
- 8210050228 Fourth request for production of documents re Cont Issue 1 on emergency evacuation planning Proof of Svc enc? Related correspondence HILT.D D Sunflower Alliance HILT.D D Hilt. D D 82/0 Office of the Executive Director for Operations 2pp 156 24X Fiche 50-440.82/09/30.8210050228
- B210050242 Requests extension of discovery time on Contention not ready for hearing as final emergency plans not yet in place Plans must be reviewed prior to hearing Proof of Svc enci Related correspondence
 WILT, D.D. Sunflower Alliance WILT, D.D. Wilt, D.D. B2/04
 Atomic Bafety and Licensing Board Panel 2pp 15610-334
 Fiche, 30-440, B2/09/30, B210050242
- 8210050252 Third set of interrogatories w/requests for product documents re leave 3 on adequacy of applicant GA program Proof of Svc encl Related correspondence HILT.D.D Sunflower Alliance HILT.D.D Wilt, D.D 82/05 Cleveland Electric Illuminating Co 12pp 15510 274 24X Fiche: 50-440, 82/09/30, 8210050252

- 0210050255 Third set of interrogetories & request for production of documents re issues 1.3 % [I on offsite emergency evacuation plans.04.7 local economic benefits.respectively Certificate of Svt encl HILLMORE.R L Cleveland Electric II] uminating Co WILLMORE.R t Shaw, Pittman, Potts & Trowbridge 02/09/30 Sunflower Alliance 12pp 15609 199 24% Fiche 50-440.82/09/30 6210050255
- 8210G50374 Response in opposition to Sunflower Alliance. Inc. 820910 motion to compel applicant answer to second set of interrogatories Applicants will respond shortly Certificate or Svc encl
 SILBERG. J E Cleveland Electric illuminating Co. SILBERG. J E. Shaw Pittman, Potts & Trowbridge 82709730 Atomic Safety and Licensing Board Panel. 20pp. 15608-256. 24x Fiche 50-440.89709730. 8210050374
- 8210060207 Seventh set of interrogatories directed to applicant % eighth set of interrogatories directed to NRC.pursuant to ASLB 810728 Hemorandum / Order.LBP 81-24 Certificate of Svc encl Related correspondence HIATT-S L Ohio Citizens for Responsible Energy 82/09/30 Cleveland Electric [1]Musnating Co 5pp 15614 15/ 24X Fiche 50-440.82/09/30.8210060207
- 8210050069 Response supporting applicant 820913 motion to levise procedures for late filed contentions Allowing intervenors to raise new matter in reply constitutes amend to contentions Certificate of Svc encl CVTCHIN. J H. Hearing Branch 4 82/10/04 Atomic Safety and Licensing Board Panel 8pp 15603 188 24% Fiche 50-440.82/10/04.
- 8210150192 Requests clarification of docket numbers for Harris & Peiry plants Mirop may be causing prejudice to intervenors since documents go to incorrect LPDR HIAIT.S L. Objo Citizens for Responsible Energy 82/10/04 Docketing & Services Branch | Ip 24% Fiche 50-000.82/10/04. 8210150192
- 8210060303 Response opposing OH Citizens for Responsible Energy 820920 motion to compet discovery of NRC A vtil ASLB chairman comments did not allow intervenors to broaden contention or scope of discovery CUTCHIN.J M Hearing Granch 4 82/10/05 Atomic Sarety and Licensing Board Panel App 15619 017 24% Fiche 50-440.82/10/05, 82/10/050303
- --6210060321 Response to applicant 820921 motion to amend schedule set earth in ASLB 820916 order NRC does not object to extending period between filing of testimony & commencement of hearing Certificate of Svc encl CyfCHIN-J H. Hearing Dranch 4. 82/10/05. Atomic Safety and Licensing Board Panel Spp. 15619 023. 24% Fiche 50-440, 82/10/05 82/06/0303.
- 6210070405 Answer opposing Sunflower Alliance 820430 application to lift 820930 discovery cutchf date for Issue; Intervenor has had over I I.2 yes to file discovery No good cause shown Centificate of Svc encl Related correspondence HILLMORE.R L Cleveland Electric Illuminating Co WillMORE.R L Shaw. Pittman, Potts & Troubridge 82/10/05 Atomic Safety and Licensing Board Panel 6pp 15633 307 24% Fiche 50-440-82/10/05, 6210070405
- 8210070137 Memorandum & order denying util B20913 motion to revise procedures for late-filed contentions if intervenor introduces new matl in reply, applicants will be allowed to respond BLGCN-P B XLINE-JR SHON-F J Atomic Safety and Licensing Board Panel 82/10/06 Cieveland Electric illuminating Co 4pp 19407 OIA 247 Fishs 50-440.82/10/06.8210070137

- 8210130327 Memorandum & order denying OH Citizens for Responsible Energy 820707 motion to sever proceedings No reason provided for ASLB to reconsider 810707 ruling on identical motion by Sunflower Alliance
 BLOCH.PB Atomic Safety and Licensing Board Panel 82/10/08
 Chia Citizens for Responsible Energy ip 15678 283 24X
 Fichs 50-440.62/10/08.8210130327
- 8210130333 Memorandum & order admitting Contention 12 re inadequate consideration of economic consequences of accidents Preponderance of considerations favors admission of contention BLOCH.P B . KLINE, J R . SHON, F J Atomic Safety and Licensing Donal Panel 02/10/08 Onto Citizens for Responsible Energy 5pp 15682 059 24% Fiche 50-440.82/10/08.8210130333
- G210150228 Confirms conversations w/OH Citizens for Responsible thesi; & Judge Bloch re extension of time for util to respond to OH Citizens for Responsible Energy 820920 motion to compel discovery on NRG & wtil Response due 821018 M/svc list SILBERG.J E Shaw, Pittman. Potts & Trowbridge SILBERG.J (Cleveland Electric Illuminating Co 82/10/08 BLOCH.P D. KLINEJ R. SHON,F J Atomic Bafely and Licensing Board Panel 27, 15706 008 24% Fiche 50~440,82/10/08,82/10/50228
- G210150467 Answer to sixth set of interrogetories Certificate of but encl MiLLKORE, R. L. Cleveland Electric Illuminating Co. Williams, R. L. Shaw, Pittman, Potts & Trombridge 62/10/12 Ohio Citizens fur Responsible Energy 10pp 15703-050 24% Ficho 50~440,62/10/12 6210150467
- 8210180211 Reply opposing NRC & applicant responses to (MI Cilliens for Responsible Energy motion for leave to file Contentions 21-26 Good cause specificity & besis requirements met Certificate of Svc encl
 HIATT-S L. Ohio Citizens for Responsible Energy 82/10/L2
 Atomic Safety and Licensing Board Panel 14pp 15718 110 21X
 Fiche 50-440-82/10/12.8210180211
- 8210150175 Advises that documents requested by Sunflower Alliance fourth request directed to Executive Director for Operations available in PDR GUICHIN.J M Hearing Branch 4 82/10/13 Wilt.D D Wilt. Bi Wilt.D D Sunflower Aillance 1p 15/07 183 24X Fiche 50-440.82/10/13.8210150175
- 8210150275 Advises that NRC will not voluntarily respond to any discovery requests in Sunflower Alliance third set of interrogationies & requests for documents, except Request 19 Remainder of discovery broader than Issue 3 CUTCHIR. J M Hearing Branch 4 82/10/13 WILT. D D Wilt. U CHILL D Sunflower Alliance 3pp 15705 001 24X Fiche 50-440.82/10/13.8210150275
- 8210180155 Advises of correction to util responso to Interrogatory of OH Citizens for Responsible Energy sixth set of interrogatories Conclusion of response remains unchanged Related correspondence WILLMORE, R. I. Shaw, Pittman, Potts & Trowbridge WILLMORE, R. I. Cieveland Electric Iiluminating Co. 82/10/14 HIATT, S. Chio. Citizens for Responsible Energy ip 15719-269 24X Fiche 50-440, 82/10/14, 82/10/80155.
- 82/0190377 Answers to 020907 fifth set of interrogatories Prof qualifications & Cartificate of Svc encl JOHNSON, O E Operations & Administrativo Division 82/10/13 Ohio Citizens for Responsible Energy 15pp 15740 300 24X Fiche 50-440.82/10/15.8210190377
- 8210190475 Answer opposing Sunflower Alliance 820928 motion to sit time to file motion to compol discovery against NRC No basis for unlimited request provided Certificate of Svc encl CUICHIN.J H. Hearing Branch 4 82/10/15 Atomic Safety and Licensing Board Panel App 15740 241 24X Fiche 50-440,02/10 8210190475.
- 8210210351 Objects to issuance of ABLB 821008 memorandum & order request to extend discovery on Issue | Order issued ABLB should request responses from all parties on expedited schedule W/Certificate of Svc Related correspondence HIATT, S L. Ohio Citizens for Responsible Energy B2/10/15 BLOCKIP, B KLINE, J R . SHON, F J A tomic Bafety and Licensing Panel ip 15764 010 24K Fiche. 50-440, 82/10/15,8210210351
- --B210210358 Seventh discovery progress rept, pursuant to ASLO BLOY memorandum & order, LBP-81-35 Interrogatories submitted to applicant & NRC re Issues 4, 5, 6, 7, 8 & 9 Discovery re Issue 9 forthcoming
 HIATT, B L Ohio Citizens for Responsible Energy 82/10/15 15764 011 24X Fiche 30-440, B2/10/15, B210210351

- --8210210364 Motion to extend discovery on Issue 9 to 821101 to permit review of documents referenced in applicant responses to 820830 interrogatories & followup discovery Certificate of Svc encl Related correspondence HIAFT.S L Ohio Citizens for Responsible Energy 82/10/15 Atomic Safety and Licensing Board Panel 3pp 15764 013 24X Fiche 50-440,82/10/15.8210210351
- 8210210284 Answer opposing OR Citizens for Responsible Energy 820920 notion to compel discovery on NRC & util Interrogatories not relevant to & beyond scope of Issue & Certificate of Svc encl Related correspondence
 SILBERG. J E Cleveland Electric Illuminating Co SiLBERG. J E Shaw, Pittman, Potts & Trowbridge 82/10/18 Atomic Safety and Licensing Board Panel 36pp 15765 099 24X Fiche 50-440,82/10/18,82102/0284
- 8210210353 Amended answer to Interrogatory 13 of Sunflower Alliance second set of interrogatories Certificate of Svc encl
 Related correspondence
 SILBERO. J E Cleveland Electric Illuminating Co SILBERO. J E
 Shaw. Pittman. Potts & Trombridge 82/10/18 Sunflower Allianre
 Spp 15763 177 24X Fiche 50-440.82/10/18.8210210353
- 8210220481 Requests attachment to IRC 780203 itr to GE be provided to altow progress on Issue 4 Document needed before intervenor can decide if updates to interrogatories necessary Related correspondence HIATTS 4. Ghip Citizens for Responsible Energy 82/10/18 SILBERO, J Shaw, Pittman, Potts & Trowbridge SILBERG, J Cleveland Electric Illuminating Co 1p 15779 078 24X Fiche 50-440, 02/10/18,8210220481
- B210210476 Memorandum & order denying Bunflower Alllance 820910 motion to compel applicant to answer secund set of interrogatories if util agrees to stipulation on potassium indide subcontention. Interrogatory 36 need not be answered BLOCH P B . KLINE, J R . SHON, F J Atomic Safety and Licensing Bourd Panel B2/10/19 Cleveland Electric Illuminating Co 6pp 15762 265 24X Fiche 50-440,82/10/19.8210210476
- B210220305 Answer to 820930 seventh set of Interrogatories Certificate or Svc enci WILLMORF.R L Cleveland Electric Illuminating Co WILLMORE.R L Shaw, Pittman, Potts & Trowbridge 82/10/19 Ohio Citizens for Responsible Energy 13pp 19776 093 24X Fiche 50-440,82/10/19, 8210220305
- B210220309 Soventh discovery progress rept Certificate of Svc on: I WILLMORE,R L Cleveland Electric Illuminating Co WILLMORE,R L Shaw, Plttman, Potts V Trowbridge 82/10/19 4pp 15776 049 ,4X Fiche 50-440,82/10/19.8210220309
- 8210220376 Motion for leave to file answer to OH Citizens for Responsible Energy (OCRE) 821012 reply to util & NRC asswers to OCRE motion for leave to file Contentions 21-26 HILLMORE.R L Cleveland Electric Illuminating Co MILLMORE.R L Shaw Pittman, Potts & Trowbridge 82/10/19 Atomic Safety and Licensing Board Panel 2pp 13777 312 24X Fiche 50-440,82/10/19,8210220374
- --B210220405 Answer to OH Citizens for Responsible Energy 821012 reply to NRC & applicant response to Citizens motion to file Contentions 21 through 26 Citizens did not ment burden of proof for admission of new contentions W/Centificate of Bvc WILLMORE, R. L. Claveland Electric 191uminating Co. WILLMORE, R. L. Claveland Electric 191uminating Co. WILLMORE, R. L. Bhaw, Pittman, Potts & Troubridge 82/10/19 Atomic Safety and Licensing Board Panel 15pp 15777 314 24X Ficke 50-440, 82/10/19, 8210220396
- B210250331 Reply brief supporting motion to submit add1 contention Oned cause for late filing demonstrated Applicant shift rotation plans may not be incorporating circadian principles HILT, D D Sunflower Alliance. WILT, D D Wilt, D D 82/10/19 Atomic Safety and Licensing Spard Panel 3pp 15790 325 24X Fichs 50-440, 82/10/19, 8210250331
- 8210250299 Answer to CH Citizens for Responsible Energy 821015 motion to extend discovery on Issue 9 re polymer degradation No justification exists for extending discovery cutoff date Certificate of 8vc enc!
 SILBERG.J E. Claveland Electric Illuminating Co SILBERG.J E Shaw. Pittman. Patts & Frombridge 82/10/20 Atomic Safety and Licensing Board Panel 5pp 18790 195 24X Fithe 50-440.82/10/20, 0210230299
- 8210250312 Supplemental answers to Sunflower Alliance. Inc second set of interregatories Certificate of Svc encl
 SILBERG, J E Clayeland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 82/10/20 Sunflower Alliance 17pp 15790 226 24% Fichs. 50-440, 82/10/20, 8210250322

- 8210250365 Advises that NRC will not voluntarily respond to DH Citizen for Responsible Energy seventh set of interrogatories except for interrogatories listed Requests irrelevant & will not lead to discovery of admissible evidence CUTCHIN.J M Hearing Branch 4 82/10/22 HIATT 5 & Dhio Citz/enfor Responsible Energy 2pp 19790 175 24X Fiche 50-440.82/10/22, 8210250365
- 8210260033 Answers to 820830 fourth set of documents Contificate of by encl
 MRIGHT, N.A. Hearing Branch 2 82/10/22 Ohio Citizens for Responsible Energy 12pp 15779 124 24X Fiche 50-440.82/10/2, 8210260033
- 8210280216 Responds to 821018 ltr re svc of documents to parties Telcons could expedite matters in future Svc list encl Related correspondence SILDERO, J E Shaw. Pittman. Potts : Trowbridge 82/10/22 HIATI'S L Oho Citizens for Responsible Energy 9pp 15837 J36 24X Fiche 50-440,82/10/22,8210280216
- 8210280231 Update to response to Interrogatory 4 2 of QH ()tizen, for Responsible Energy 020928 fourth set of interrogatories Related correspondence WILLMORE.R L Shaw. Pittman. Putts & Trawbridge WILLMORE.R L Cleveland Electric Illuminating Co 02/10/22 HIATT.S Ohio Citizens for Responsible Energy 1p 15837 081 24x Fiche 50-440. 82/10/22. 8210280231
- 9210260383 Answers to listed interrogatories of 920927 seventh set of interrogatories NRC will not voluntarily answer remaining interrogatories Certificate of Svc encl CUTCHIN.J M Hearing Branch 4 82/10/25 Ohio Citizens for Responsible Energy (1pp 15803 348 24X Fiche 50-440,82/10/25,821026383
- 8210260395 Discovery rept for previous two months per ASLB 810907 memorandum to order CUTCHIN.J M. Rearing Dranch 4 82/10/25 BLCKII.P.B. SHON.I.J. KLINE.J R. Atomic Safety and Licensing Board Panel 1p 1580J 14; 24X Fiche 50-440.82/10/25,8210260395
- 8210280246 Forwards RB Coffey original affidavit to be included in applicant 821020 supplemental answers to Sunflower Alliance second set of interrogatories Related correspondence WILLMORE, R L. Shaw, Pattman, Potts 9 Trombridge WILLMORE, R t Cleveland Electric Illuminating Co. 82/10/25 Docketing & Services Branch 2pp 15837-054 24X Fiche 50-440,82/10/25. 8210280246
- B210290287 Requests encl RF Zucker & RV Tanney original affidavits he substituted for photocopies in applicant 82:1019 answers to OH Citizens for Responsible Energy seventh set of interrogatories WILLMORE.R L Show. Pittman. Polts & Trowbridge WILLMORE.R C Cleveland Electric Illuminating Co B2/10/26 Docketing & Services Branch 3pp 15854 069 249 Fiche 50-440,82/10/26.8210290287
- 8210280346 Answer opposing OH Citizens for Responsible Energy 8210th motion to extend time for discovery on Issue 9 No justification for extension provided Certificate of Svc enci CUTCHIN, J K Hearing Branch 4 82/10/27 Atomic Safety Licensing Board 7 8210280346

- 4 Inspection reports IE Buildins & correspondence
- 5210060305 Forwards (E Insp Repts 50 440/82-11 % 50-441/82-10 on 820931-0902 No noncompliance noted LITTLE:N S Division of Engineering & Technical Programs 82/09/2/DAVIDSON, D R Cleveland Electric Illuminating Co 2pp 15617 195 24% Fichs 50-440.82/04/22/8210060305
- 0210060308 IE Insp Repts 50-440/62-11 5 50-441/82-10 on 020831-0902 Nu noncompliance noted Major areas inspected preservice insp procedures? upry activities previous insp findings & 16 Bulletin 80 08 activities
 Bulletin 80 08 activities
 WARD, N. D. ANIELSON, D. M. Region 3 Office of Director 82/09/14 5pp 15619 197 244 Fishe 50-440 02/09/22,0210060305
- 8210130763 Forwards 16 Investigation Repts 50-440/81-17 & 50-441/01 ly on 811027-820319 & notice of violation MEPPLER J G. Region 3. Office or Director 82,09/27 DAVIDSON, D.R. Clevelard Electric Illuminating Co. 3pp. 15736-318 24X Fiche 50-440-82/07/27 6210190765
- --82(019077; Nutice of violatium from investigation on 81(027-820319 AEPPLERJ G Region 3 Office of Director 82 09/24 9pp 15735 321 247 Fiche 50-440 82/09/27,8210190763
- -821017374" IE investigation Repts 50-440/81-19 & 50-441/81-19 on 611027-820319 Nonconfliance noted Gould Inc Drawings E-39-51 958 231 % 2633 Inadequately reviewed & instructions not incorporated into cable publing procedures NEIL C H NAIDU F R. BRANDD C Region 3. Office of Director 62/09/22 95pp 1573()30 24% Fiche 50-440.02/09/27, 821019076)
- 보급08190급33 1E Info Notice Bu 35, buppl 1, Leaking * Dislodged 1-1/b Implant Seeds " Svo list enr! COBO, I Division of Fuel Facilities, Materials % Safeguards EZ/10/06 Consolidated Edison Co of New York copp 15/61 간에 근심
- S208190235 IE Bulletin 82-05 Stress Cutrosion Cracking in Thick-Well. Large-Dial eter Statiles Steel Recirculation Sys Piping et BuR Plants "Sec list encl BEYOUNG R.C. Director's Office. Office of Inspection and Environment 87:10-14 Consolidated Edison Co. of New York 115pp 1501C 125 24 Fiche 50 000-82/10/14.8208(90238
- -8210260337 Responds to NRC 820710 ltt te violations noted in 16 (msp. Repts 50-440/82-09 % 50-441,82-38 Corrective actions Maiser Engines: Procedure QAP 22 revised to require annual evaluation Detailed hardware insp. performed 320728 NAVID50N.D R. Claveland Electric Illuminating Co. 82/10/08 (3081195,0 % Division of Project % Resident Programs 6pp. 15803-1921 24X Fiche 50-440, 82/10/21, 8210260333
- S Reportable occurrences, LFRs & related correspondence
- 5210050132 Final deficiency rept to nonconforming Transamerica Balazat standby diesel generator ACME Section III.Class 3.fiping welds Initially reported on 820327 Held Insp. A required repair/rework will be completed by 830401 DAVIDSON.D R Cleveland Electric Illuminating Co 82/09/24 EFFLER.J G Region 3. Office of Director 2pp 15605 047 249 Fiche 50 440.82/09.24.8210050132
- 8210139364 There interin deficiency rept re rejection of previously accepted containment vessel rediographs Initially reported on 820405 All potentially rejectable radiographs submitted to Hartford Steam Boiler Insp Co for review DAVIDSON. O R Cleveland Flettic Illuminating Co 82/09/30 KEPFLER, J G Region 3, Office of Director 2pp 15681 169 24X Fiche 50-440, 82/09/30.8210130364
- A Application/construction stage documents & correspondence
- 8210120517 Notification of 820924 meeting w/applicant in Seabrook,NH to inspect onsite radiological monitoring sys as part of GL sarety review MHEELER, L. L. Licensing Branch 3 82/09/17 KERRIGAN, J D Licensing Branch 3 3pp 15572 235 24% Fiche 50-443,82/09/17, 8210120617

- 8210070160 Forwards draft results of analysis of associated circuits addressing question raised at 820910 meeting Once concurrence received response will be issued as amend to FSAR, closing out Open Item 26
 BAXTER: F Yankee Atomic Electric Co 82/09/20 SRINIVASAN. M Power Systems Branch 12pp 15645 049 24% Fiche 50-443,02/09/20 8210070160
- 8210180378 Requests assignment of reviewers for Bechtel work packages All three packages should be ready for NRR review by 821004
 Task Interface Agreement TIA 82-55 w/Region 4 enci
 KERRIGAN.J D Licensing Branch 3 62/09/20 LEAR.9 Hydrologia & Geotechnical Engineering Branch 3 805NAK.R Mechanical Engineering Branch SCHAUER.F Structural Engineering Granch 2pp 15/45 JC-24X Fiche 50-443.82/09/20.8210180378
- 8210010465 Forwards "Response to NRC Generic Request for Add) Info He NUREG-0612, Control of Heavy Loads " DEVINCENTIS J Yankee Atomic Electric Co DEVINCENTIS J Publis Service Co of New Hampshire 02/09/24 KERRIGAN J D Licentin. Branch 3 lp 15572 017 24X Fiche 50-443, 82/09/24, 8210010465
- --8210010470 "Response to NRC Generic Request for Add1 Info Ne NUREO-0612. Control of Heavy Loads" * Public Service Co of New Hampshire 82/09/30 :34pp 15572 018 24X Fiche 50-443, 82/09/24,8210010465
- 8210040112 Forwards response to NRC generic request for add] info re NUREQ-0612. "Control of Heavy Loads " H/d enc!
 DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Public Bervice Co of New Hampshire 82/09/24 KERRIGAN.J B Licensine Dranch 3 ip 13581 143 24X Fiche 50-443.82/09/24,8210040112
- 8210040193 Forwards responses to Hydrologic & Geotechnical Engineering
 Branch 820727 Series 240 requests for addl info.Guestions
 240 38,240 39 & 240 41 Response to Question 240 40
 rothcoming
 DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public
 Service Co. of New Hampshire 82/09/30 KERRIGAN, J. B. Licensing
 Branch 3 14pp 15583 168 24X Fiche 50-443,82/09/30, [221004019]
- 8210050197 Responds to Mechanical Engineering Branch G2061ff request for addl info Response includes "Prying Effect on Concrete Espansion Anchor Boits Due to Pipe Support Base Plake Flexibility" Draft responses submitted G2072B DEVINCENTIS. J Public Service Co of New Hampshire 82/07/30 KERRIGAN, J B licensing Branch 3 3p 15609 085 24X Fiche 50-443,82/09/30,82100501/9
- --8210050206 "Prying Effect on Concrete Expansion Anchor Bolts Due to Pipe Support Base Plate Flexibility " OALUNIC, B., MCKENNA, H., RIGAMONTI, G. United Engineers & Constructors, Inc. (subs of Raytheon Co.) 77/07/20 (10pp) 15609 088 24% Fiche 50-443, 82/07/30,8210050199
- 8210050393 Requests add1 info re analysis proving any challenges to Class IE circuits from associated circuits do not prevent sare shutdown of plant info re NUREG-0737, Item II E 4 2. Position 6 on containment isolation valves required KERRIONH, J. Licensing Branch 3 82/10/01 TALLMAN, W.C. Public Service Co. of New Hampshire 9pp 15608 324 24X Fiche 50-443,82/10/01.8210050393
- 8210070105 Forwards revised response to Guestion 440 136 re Reactori,; Branch 820727 request for addition concerning steam generator tube rupture
 DEVINCENTIS.J Yanke Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 82/10/05 KERRIGAN.J B Licensing Branch 3 4pp 15428 074 24X Fiche 50-441.02/10/05.020070105
- 6210130436 Forwards revised responses to Mechanical Engineering Dratt 820301 to 05 Requests for Addl Info 210 3-210 69.originally submitted in viil 820421.30 to 0510 ltrs,per 820511-13 meeting Responses will be incorporated into FSAR Amend 47 DEVINCENTIB.J Yankee Atomic Electric Co DEVINCENTIB.J Public Service Co of New Hampshire 82/10/06 KERRIGAN.J B Licensing Branch 3 124pp 15681 193 24X Fiche 50-443.82/10/06.821013045
- 82i0130510 Forwards revised FBAR Section 6 2 2 providing justification for excluding inert cover gas on sodium hydroxide storage tank info will be incorporated in Amend 48 to OL application
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Fublic Service Co of New Hampshire 82/10/07 KERRIGAN, J Licensime Branch 3 4pp 15714 189 24X Fiche 50-443.82/10/07.8210150510
- 8210180001 Forwards notes from 820914 & 15 Instrumentation & Controls
 Sys Branch review meetings.per NRC 820216 & 0323 requests
 Notes also include items discussed at 820323-25,0512 & 13 &
 0715 & 16 meetings & NUREG-0737 action items
 DEVINCENTIS.J Yankse Atomic Electric Co DEVINCENTIS.J Public
 Service Co of New Hampshire 82/10/14 KERRIGAN.J Licensing
 Branch 3 95pp 15720 031 24X Fiche 50-443,82/10/14,8210180003

ì

```
250307 Requests advanced notification of scheduled NRC meetings re
gouse/ Requests advanced notification of scheduled NRC meeting:
cilities to enable ample time for Atty General Ofc to
range for staff attendance
RDER.E T New Hampshire. State of 82/10/18 WHEELER.L L
gensing Granch 3 ip 15790 069 24X Fiche 50-443,82/10/18,
10250307
```

270006 Forwards request for info re onsite audit for seismic & namic qualification review & pump & valve operability mpletion of enci forms requested within 3 wks Specific terof audit to be mutually agreed to by NRC & applicant RRIGARN, J D Licensing Branch 3 82/10/21 TALLMAN, W C Public Price C of New Hampshire 25pp 15816 348 24X che 50-443,82/10/21,8210270006

280119 Forwards response to Powor Sys Branch & Equipment alification Branch 821001 Request for Add! Info 430 149 re alwsis on associated circuits.per 820910 & 1020-21 etings w/NRC vincentis.J Yankee Atomic Electric Co DEVINCENTIS.J Public rvice Co of New Hangshire 82/10/26 MIRAGLIA.F J Licensing anch 3 10pp 13837 136 24X Fiche 50-443.82/10/26.8210280119

RC Draft/Final Environmental Statements, supple & correspondence

120029 Forwards comments from State of NH to be included in NRC parter remains comments from State of PMI to be included in NAC 0730 ltr re facilities DES W/o entil RAGLIA.F J Licensing Branch 3 82/08/24 TALLMAN.W C Public ruce Co of New Hampshire ip 15689 196 24X che 50-443.82/08/24.8210120029

ecurity, medical, emergency & file protection plans

120128 Summary of 820720 meeting w/utils & United Engineers & nstructors in Dethesda.MD re associated circuits esentation outline & details of preliminary review & alysis of associated circuits FSAR change end.
DX.J Power Systems Branch 82/09/24 SRINIVASAN,M Power stems Branch 100pp 15692 050 24X Fiche 50-443,82/09/24.

djudicatory correspondence

D60194 Forwards Seacoast Anti-Pollution League objection to & tion for reconsideration of ASLD 820913 order & motion to rify objections to ASLAD
CKUS.R A Backus.R A BACKUS.R A Seacoast Anti-Pollution
agou 82/09/30 HQYT,H F. LUEBKE.E A, HARBOUR.J Atomic Safety
d Licensing Board Panel 2pp 15614 220 24X
che 50-443,82/09/30.0210060194

10060206 Objection to & motion for reconsideration of ASLB 820913 order & motion to certify objections to ABLAD Contention 8uppl 4 should be admitted BACKUS, R A Beacoast Anti-Poliution League BACKUS, R A Buckus, R A 8209730 Atomic Sefety and Licensing Board Panel /pp 19514 222 24X Fiche 50-443,82/09730.8210060194

10060214 Affidavit of P Brown Hearings underway before appropriate state agencies re New England Clectric Transmission Corp & New England Populications for const of transmission lines
BROWN.P Seacoast Anti-Poliviton League 82/09/30 8pp
18514 227 24X Fiche 50-443,82/09/30.8210060194

050262 Grder allowing parties to file reply to New England alition on Nuclear Pollution objections & motion & State NH motion for reconsideration of ASLB 820913 memorandum & der Reply due by 821019 YF.H F Atomic Bafety and Licensing Board Panel 82/10/01 12pp 610 204 24% Fiche 50-443,82/10/01,8210050262

200026 First set of interrogatories & request for documents on stantions | A 2.I B 1.I B 2 & I C RDAN.W 5 , CURRAN.D New England Coalition on Nuclear Pollution RDAN.W 5 Harmon & Weiss 82/10/13 Public Service Co of New mpshire 14pp 15755 CGG 24X Fiche 50-443,82/10/13,8210200026

10200035 First set of interrogetories & request for documents on Contentions 1 A 2.1 B 1.1 B 2 & 1 C.

JGRDAN, M S , GURRAN, D New England Coelition on Nuclear Pollution

JGRDAN, M S Harmon & Meiss 82/10/13. Office of the Executive
Legal Director 12pp 15755 047 24% Fiche 50-443,82/10/13. 9210200026

10200042 First set of interrogetories & request for documents on Contentions II B 1, II B 3, II B 4 & II B.5
JARDAN, H B , CURRAN, D New England Coalition on Nuclear Poliution
JARDAN, H S Harmon & Heiss B2/10/13 Public Service Co of
New Hampshire Bpp 15755 059. 24X Fiche 50-443,82/10/13.
8210200226

- --0210200047 First set of interrogatories & request for documents on Contentions II 8 1.[[8 3.1] B 4 & II B 5 Certificate of JORDAN. H S . CURRAN. D New England Coalition on Nuclear Pollution JORDAN. H S . Harmon & Heiss 82/10/13 Office of the Escrutiv Legal Director 9pp 15755 067 24% Fiche 50-443.82/10/1J. 8210200026
- 8210270153 Response opposing New England Coalition on Nuclear Power objections to prehearing conference memorandum & order & motion to certify objections to ASLAB Issues in objections already considered Certificate of Svc encl GAD, R K Public Service Co of New Hampshire GAD R K Rope & Gray 82/10/26 Atomic Safety and Licensing Goard Panel வந்து 15829 327 24X Fiche 50-443,82/10/26,82(0270153)
- 8210270166 Response opposing State of ISH objection 5 motion for reconsideration of ASLB 820913 order No errors committed in ruling on ISH contentions ASLB should not certify rulings since certification not requested Certificate of Svc end GAD.R K Public Service Co of New Hampshire GAD.R K Popcing Gay 82/10/26 Atomic Safety and Licensing Doard Panel Popling 15630 t17 24X Fiche 50-443,82/10/26,8210270166

H General correspondence

8210120270 Requests that DR Lewis be added to svc list TAYLOR, J. Atomic Safety and Licensing Board Panel 82/10/08 Public Service Co. of New Hampshire (p. 15652-317 24X Fiche 50-443, 82/10/08.8210120270

- O inspection reports. IE Bulletins & correspondence
- 8210070392 Forwards IC Insp Repts 50-443/82-09 to 50-444/82-09 on 820824-27 No honcompliance noted MARTIN. T T Division of Fingineering to Technical Programs 82/09/22 TALLMAN, W C Public Service Co of New Hampshire 2pp 156.1J J31 24X Fiche 50-443,82/09/22,8210070392
- --8210070400 IE Insp Repts 50-443/82-07 & 50-444/82 09 on 820824 &/ No noncompliance noted Major areas inspected procedures & work activities re concrete const of reactor containment bldg done, structural welding within containment bldg & dA review VARELAAA . DURR.J.P. Region (. Office of Director 82/09/20) 7pp 15633 333 24x Fichs 50-444, 82/09/22-8210070322
- 8208290124 FOIA request for IE Insp Rept 50-443/82-06 % LOCFRSO BACHAND,D Affiliation Unknown B2/09/28 CARR, J NRC No Detailed Affiliation Civen 1p 15758 351 24X Fiche 50-443, 82/09/28, 8208290124
- 8210190035 Responds to FOIA request for IE Insp Rept 50-443/82-06 A 10CFRSO Forwards documents W/o enci FELTON. J K Division of Rules and Records 82/10/04 SACHAND, D Affiliation Unknown 1p 15758 352 24X Fishe 50-443,82/10/04. B210190035
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged [-12", CODE THE NOTE OF THE NOTE OF THE CODE AND THE CODE OF THE CODE OF
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation Sys Piping at BWR Plants " Evc list enc! DEYOUNG!R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York ## 15pp 15810 125 24% Fiche 50-000.82/10/14.8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210190126 Corrected version of final deficiency rept re misapplication of torquing equipment by Beloit Power Sys Instally reported on 820820 Corrective procedure provided by vendor will preclude potential problems
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/09/20 STAROBTECKI, R Division of Project & Resident Programs 2pp [5742 132 24X]
 Fiche: 50-443, 82/09/20, 8210190126
- 8210190136 Corrected version of final deficiency rept re Robertshaw Controls thermostatic valves Initially reported on 820820 Corrective actions described by vendor will practude potential problems
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/09/20 STANDSTECKI, R Division of Project & Resident Programs | 3pp | 15742 227 24X Fich = 50-443, 02/09/20, 8210190136

- 8210(90363 Final deficiency ropt re cracked welds in containment annular steel end connections installly reported on 820910 Metallurgical investigation performed welding & installation procedure revised & cracked connections replaced DEVINCENTIS J Public Service Co of New Hampshire 82/10/12 STAROSTECKI.R Division of Project & Resident Programs 3pp 15740-321 24x Fishe 50-443,82/10/12,8210170363
- 5210260330 Interim defictency rept re sheared pinion keye in Limitorque Model SB-0-25 mptor operators Initially reported on 820902 Caused by use of inappropriate key math Limitorque A Hestinghouse continuing investigation DEVINCENTIS J Yankee Atomic Electric Co DEVINCENTIS J Public Service Co of New Hampshire 82/10/18 STAROSTECKI, R Division of Project & Resident Programs 2pp 15802 340 24% Fiche 50-443,82/10/18,8210240330
- b210260149 Interim deficiency rept re power surges in solid state protection sys which may disable protection circuit Initially reported an 820805 litem reportable based on 820806 bestinghouse lite Final rept eigented by 820115 DEVINCENTIS. J. Yankee Alomic Electric Co. DEVINCENTIS. J. Public Service Co. of New Harpshire 62/10/19 STAROSTECK! R. Division of Project & Resident Programs ip 15799 018 24% Fiche 50-443, 82/10/19, 8210260149
- THILKET 50-444 SEABROOF NUCLEAR STATION. UNIT 2
- A Application/construction stage documents & correspondence
- E210120617 Nati+ication of 820924 meeting w/applicant in Seabrook,NH to inspect obsite radiological monitoring sys as part of OL sarety review.

 HHZELER. L Licensing Branch 3 82/09/17 KERRIGAN J D
 Licensing Branch 3 3pp 19672 235 24X Fiche 50-440,82/09/17,8210120617
- 8210070160 Forwards drart results of analysis of associated circuity addressing question raised at 820910 meeting Once concurrence received, response will be issued as amend to FSAR, flosing out Open Item 26 BAXTER: F Yankee Atomic Electric Co. 82/09/20 SRINIVASAN, M Power Systems Branch 12pp 15645-049 24% Fiche 50-443, 82/09/20, 6210070160
- 6210180378 Requests assignment of reviewers for Dechtel work packages
 All three packages should be ready for ARR review by 821004
 Task Interface Agreement TIA 88-75 W/Region 4 encl
 FERRIGAN. J D Licensing Branch 3 82/09/20 LEAR. 0 Mydrologic &
 Geotechnical Engineering Branch 808NAW. R Mechanical Engineering
 Branch SCHAUER; Structural Engineering Branch 2pp 15/45 300
 24X Fiche 50-443,82/09/20.8210180378
- 6210010455 Forwards "Response to NRC Generic Request for Addl Info He NMRCO-0612-Control of Heavy Loads" DEVINCENTIS. J Yanher Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/09/24 MERRIGAN. J B Licensing Branch 3 lp 15572 017 24X Fiche 50-443.82/09/24.8210010445
- --8210010470 "Response to NRC Generic Request for Addi Info Re NUREG-0612.Control or heavy Loads " + Public Service Co of New Hampshire 82/09/30 134pp 15572 018 24X Fiche 50-443.82/09/24.8210010465
- E210040112 Forwards response to NRC generic request for add1 info re NAMEG-D612. "Control of Heavy Loads" W/o enci DEVINCENTIS. J Public DEVINCENTIS. J Public Service Co of New Hampshire B2/09/24 KERRIDAN. J B Licensing Branch J Ip 15581 143 24X Fiche 50-443.82/09/24.8210040112
- E210040193 Forwards responses to Hydrologic & Geotechnical Engineering Branch 820727 Series 240 requests for add1 info. Questions 240 52,240 39 & 240 41 Response to Question 240 40 forthcoming DEVINCENTES. J. Yankee Atomic Electric Co. DEVINCENTIS. J. Public Service Co. of New Hampshire B2/09/30 KERRIGAN. J. B. Licensing Branch 3 14pp 15583 168 24X Fichs 50-443,82/09/30.8210040193
- 6210050199 Responds to Mechanical Engineering Branch 820618 request sor addition Response includes "Prying Effect on Concrete Espansion Anchor Bolts Due to Pipe Support Base flate Flexibility" Draft responses submitted 820728 020728 OCUINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/09/30 KERRIOAN JB Licensing Branch 3 3p 13609 085 24X Fiche 50-443.82/09/30,8210050199
- --8210050206 "Prging Effect on Concrete Expansion Anchor Bolts Due to Pipe Bupport Base Plate Flexibility " GALUNIC.B . MCXENNA.M . RIGAMONTI.O United Engineers & Constructors, Inc (subs of Raytheon Co) 79/07/20 BBpp I5507 088 24X Fache 50-44J, 82/09/30, 8210050199

- 8210050393 Requests add1 info re analysis proving any challenges to Class IE circuits from associated circuits do not prevent safe shutdown of plant info re NUREG-0737. Item II E 4 2, Position A on containment isolation valves required KERRIGAN, J Licensing Branch 3 82/10/01 TALLMAN, N C Public Service Co of New Hampshire 9pp 15608 324 24x Fiche 50-443, 82/10/01,8210050393
- 8210070105 Forwards revised response to Question 440 136 re Reacter (, Branch 820727 request for add) info concerning steam generator tube rupture DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/10/05 KERRIGAN, J B Licentify Branch 3 4pp 15628 074 24X Fiche 50-443.82/10/05.0210070105
- 8210130436 Forwards revised responses to Mechanical Engineering Brs-1
 820301 & 05 Requests for Add1 Info 210 3-210 69, originally
 submitted in util 820421.30 & 0510 Itrs, per 820511-13
 meeting Responses will be incorporated into FSAR Amend 4/
 DEVINCENTIS-J Yankee Atomic Electric Co DEVINCENTIS-J Public
 Service Co of New Hampshire 82/10/0/06 RERIIGAN J D Licensiri
 Granch 3 126pp 15681 193 24X Fiche 50-443, 82/10/06 REIOLANA
- 8210150510 Forwards revised FSAR Section & 2 2 providing justificalise for excluding inert cover gas on sodium hydraxide storage tank info will be incorporated in Amend 48 to OL application
 DEVINCENTIS. J Yankee Atomic Electric Go DEVINCENTIS. J Public Service Co of New Hampshire 82/10/07 KERRIGAN. J Licensing Branch 3 4pp 15714 189 24X Fiche 50-443.82/10/07.82(0)50516
- 8210180001 Forwards notes from 820914 & 15 Instrumentation & Controls

 Gys Branch review meetings, per NRC 820216 & 0323 requests

 Notes also include items discussed at 820323-25,0312 & 13 &
 0715 & 14 meetings & NNREG-0737 action items

 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 82/10/14 & RERRIGAN. J Licensing

 Branch 3 93pp 19720 031 24X Fiche 50-443,82/10/14.8210180011
- 82(0250307 Requests advanced notification of scheduled NRC meetings refactivities to enable ample time for Atty General Ofc to arrange for staff attendance
 KINDER.E T New Hampshire. State of 82/10/18 WHEELER,t !
 Licensing Branch 3 ip 15790 069 24X Fiche 50~443,82/10/18.
- 8210270006 Forwards request for info re onsite audit for select & dynamic qualification review & pump & valve operability Completion of enci forms requested within 3 Ms Specific date of audit to be mutually agreed to by NRC & applicant KERRIGAN, J D Licensing Branch 3 82/10/21 TALLMAN, M C Public Service Co of New Hampshire 25pp 15816 348 24X Fiche 50-443,82/10/21,8210270006
- 8210280117 Forwards response to Power Sys Branch & Equipment Qualification Branch 821001 Request for Add 1 Info 430 149 re analysis on associated circuits, per 820910 & 1020-21 meetings U/NRC DEVINCENTIB. J Yankee Atomic Electric Co DEVINCENTIB, J Publis Service Co of New Hampshire 82/10/26 MIRAGLIA,F J 114001119 Branch 3 10pp 13837 136 24% Fishe 50-443,82/10/26.62103/0017
- D NRC Draft/Final Environmental Statements, supply & correspondence
- 8210120029 Forwards comments from State of NH to be included in PAL 820730 ltr re facilities DES W/o encl MIRAOLIA: F J Licensing Branch 3 82/08/24 TALLMAN, W C Public Service Co of New Hampshire Ip 13689 196 24X Fiche 50-443, 82/08/24, 8210120029
- F Securaty, medical, emergency & fire protection plans
- 821012012B Summary of 820720 meeting w/utils & United Engineers & Constructors in Dethesda.MD re associated circuits Presentation outline & details of preliminary review & analysis of associated circuits FRAR change encl MNOX-J Power Systems Branch 82/09/24 SRINIVASAN.M Power Systems Branch 82/09/24 SRINIVASAN.M Power Systems Branch 100pp 15692 050 24X Fiche 50-443.82/09/24.8210120128
- G Adjudicatory correspondence
- 8210060194 Forwards Seacoast Anti-Pollution League objection to kmotion for reconsideration of ASLB 820913 order k motion to certify objections to ASLAB BACKUS, R A BACKUS, BACKU

- --8210060206 Objection to & motion for reconsideration of ASLB 820913 order & motion to certify objections to ASLAB Contention Suppl 4 should be admirted BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A B2/09/30 Atomic Safety and Licensing Booard Panel 7pp 15614 222 24% Fithe 50-443, 82/09/30, 8210060194
- --B210060214 Affidavit of P Brown Hearings underway before appropriate state agencies re New England Electric Transmission Corp. Litew England Power Poul applications for const of transmission lines. BROWN.P Seacoast Anti-Pollution League 82/09/30 Bpp (5514 227 24% Fiche 50-443, 82/09/30, 8210060194
- 0210050262 Order allowing parties to file reply to New England Coalition on Nuclear Pollution objections & motion & State of Nil motion for reconsideration of ASLB 820913 memorandum & order Reply due by 821019

 HOYF.H F Atomic Safety and Licensing Board Panel 82/10/01 2pp 13610 284 24% Fiche 50-443,82/10/01.8210050262
- 8210200026 First set of interrogatories & request for documents on Contentions I A 2.1 D i,I B 2 & I C
 JORDAN, M 9. CURRAN, D New England Coalition on Nuclear Pollution
 JORDAN, M 6 Harmon & Meiss 82/10/13 Public Service Co of New Hampshire 14pp 15755 033 24X Fiche 50-443,82/10/13,8210200026
- --8210200035 First set of interrogatories & request for documents on Contentions I A 2.1 B 1.1 B 2 & I C
 JURDAN, W S , CURRAND New England Coalition on Nuclear Pollution
 JURDAN, W S Harmon & Weiss B2/10/13 Office of the Executive
 Legal Director 12pp 15755 047 24X Fiche 50-443,82/10/13.
 8210200026
- --8210200042 First set of interrogatories & request for documents on Contentions II B i.11 B 3.11 R 4 & 11 B 5
 JORDAN, W S , CURRAN, D New England Coalition on Nuclear Pollution JORDAN, W S Harmon & Weiss 62/10/13 Public Service Co of New Hampshire 8pp 15755 059 24X Fiche 50-443,82/10/13.82/10/200026
- --B210200049 First set of interrogatories & request for documents on Contentions II B 1.11 B 3.11 B 4 & 11 B 5 Certificate of Svc spct JORDALL N S . CURRAN. D New England Coalition on Nuclear Pollution JORDAN. N S Harmon & Weiss B2/10/13 Office of the Executive Legal Director 9pp 15755 067 24X Fiche 50-443, B2/10/13. B210200026
- 8210270153 Response opposing New England Coalition on Nuclear Power objections to prehearing conference memorandum & order & motion to certify objections to ASLAB Issues in objections already considered Certificate of Svc encl CADLR K Public Service Co of New Hampshire GADLR K Roper & Gray 82/10/26 Atomic Sefety and Licensing Board Panel 63pp 15627 327 24% Ficho 50-443,82/10/26,8210270153
- B210270166 Response opposing State of NH objection & motion for reconsideration of ASLB 820913 order No errors committed in ruling on NN contentions ASLB should not certify rulings since certification not requested Certificate of Svc encl QAD, R K Public Bervice Co of New Hampshire GAD, R K Ropeu & Gray 82/10/26 Atomic Safety and Licensing Board Panel 22p; 15830 117 24X Fiche 50-443,82/10/26.8210270166
- H General correspondence
- 8210120270 Requests that DR Lewis be added to svc list TAYLOR.J Atomic Safety and Licensing Board Panel 82/10/08 Public Service Co of New Hampshire 1p 15652 317 24X Fiche 50-443, 82/10/08,8210120270
- G Inspection reports, IE Bulletins & correspondence
- 8210070392 Forwards IE Insp Repts 50-443/82-09 & 50-444/82-09 on 820824-27 No moncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/09/22 TALLMAN.H C Public Service Co of New Hampshire 2pp 15403 331 24x Fichs 50-443.82/09/22;8210070392
- --8210070400 IE Insp Repts 50-443/82-07 & 50-444/82-07 on 820824-2/ No noncompliance noted Major areas inspected procedures & work activities re concrete const of reactor containment bidg dome.structural welding within containment bidg & QA review VARELA, A A . DURR.J P Region I. Office of Director 82/09/20 7pp 15633 333 24X Fiche:50-443,82/09/22.8210070392
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds." Evc list encl. COBB.L. Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidate Edison Co of New York 66pp 15761 250 24X Fichs 50-000, B2/10/06, 8208190233

- 8208190238 IE Bulletin 82-03, "Stress Corrasion Cracking in Thick-Wall, Large-Diameter: Stainless Steel, Recirculation Sys Piping at BMR Plants " Syc list encl DEYQUNOR, RC Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp [5810 125 24X Fiche 50-000, 82/10/14, 8208190238
- S Reportable occurrences. LERs & related correspondence
- 6210190126 Corrected version of final deficiency rept re misapplication of torquing equipment by Beloit Power Sys Initially reported on 820820 Corrective orocedure provided by vendor will preclude potential problems
 DEVINCENTIS. J Yantee Atomic Electric Co DEVINCENTIS. J Public Service Co of New Hampshire 82/09/20 STARDSTECKI. R Divirion of Project & Resident Programs 2pp 15742 132 24x
 Fiche 50-443. 82/09/20. 8210190126
- 8210190136 Corrected version of final deficiency rept re Robertshaw Controls thermostatic valves initially reported on 820820 Corrective actions described by vendor will preclude potential problems
 DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 82/09/20 STARDSTECKI.R Division of Project & Resident Programs 3pp 15742 227 24X
 Fiche 50-443.82/09/20.82/0190136
- 8210190363 Final deficiency rept re cracked welds in containment annular steel end connections Initially reported on 820910 Metallurgical investigation performed welding & installation procedure revised & tracked connections replaced DEVINCENTIS. J. Yankee Atomic Electric Co. DEVINCENTIS. J. Public Service Co. of New Hampshire 68/10/12 STAROSTECKI.R. Division of Fraject & Resident Programs 3pp. 15740-321 24X
 Fiche 30-443, 82/10/12,8210190363
- B210240:30 Interim deficiency rept re sheared pinion keys in Limitorque Model SB-0-25 motor operators Initially reported on 820702 Caused by use of inappropriate key matl Limitorque & Westinghouse continuing investigation DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/10/18 STARQSTECKI.R Division of Project & Resident Programs 2pp 15802 340 24% Fiche 50-443.82/10/18.8210260330
- 8210260149 Interim deficiency rept re power surges in solid state protection sys which may disable protection circuit initially reported on 820805 Item reportable based on 820806 Westinghouse Itr Final rept expected by 830115 DEVINCENTIS, J Yankes Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/10/19 STARGSTECKI, R Division of Project & Resident Programs | p | 15799 018 24X Fiche 50-443, 82/10/19, 8210260149
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA . UNIT 1
- A Application/construction stage documents & correspondence
- 8210220513 Notification of 820913 meeting w/util in Bethesda,MD to discuss procedures generation package CLIFFORD,J W Procedures & Yest Review Branch 82/08/27 ZIEMANN,D L Procedures & Test Review Branch 2pp 15786 089 24x Fiche 50-445.82/08/27.8210220513
- 8210210025 Summary of 820625 meeting w/util & Gibbs & Hill in Dethesda, MD re equipment qualification BURWELL.8 B Licensing Branch 1 82/09/30 Licensing Branch 1 17pp 15782 180 24X Fichs 50-445.82/09/30.8210210025
- F Security, medical, emergency & fire protection plans
- 8210040020 Releases public version of applicant motions & affidavits & State of IX emergency mgt plan
 FELTON, J H Division of Rules and Records 92/09/21 Document Management Branch 1p 15577 273 24X Fiche 50-445,82/09/21.
 8210040020
- --8210040042 Public version of State of TX emergency mgt plan.including Hood County, Somervell County & City of Olen Rose, TX emergency operations plans CLEMENTS, W D. ADAMS, J B., LANSFORD, R A Teras. State of 82/05/24 801pp 15578 269 24X Fiche 50-445,82/09/21,8210040020
- 8210070109 Forwards "Evaluation of Hood & Bommervell Counties & State of TX Radiological Emergency Plans for Comanche Peak Steam Electric Station " Offsite protection adequate Joint exercise planned for early 1983
 THOMAS.L H Federal Emergency Management Agency 82/07/29 DIRCKS.W Office of the Executive Director for Operations 1p 15628 165 24X Fiche 30-445.82/07/29,8210070109

- --8210070112 "Evaluation of Hood & Sommervell Counties & State of fx Radiological Emergency Plans for Comanche Peak Steam Electric Station "
 Federal Emergency Management Agency 82/09/29 57pp 15628 166 24X Fiche 50-445.82/09/29.8210070109
- 6210130576 Forwards response to license condition on physical security program approval & pages to FSAR security plan Response & plan withheld (ref 100FR2 790 % 100FR73 21)
 GARY, R. J. Teras Utilities Generating Co. 82/10/08 YDUNGBLOOD, B. J. Licensing Branch 1 1p. 15679 060 29X Fiche 50-445,82/10/08, 6266136776
- 6210180005 Forwards Amend 35 to FEAR consisting of Revision 5 to emergency plan CARN: R J Telas Utilities Generating Co 82/10/12 DENTON. H R Difice of Nuclear Regulation. Director 2pp 15/20 126 24X Fich 50-445, 82/10/12, 8210180006
- --8210180008 Amend 35 to FSAR consisting of Revision 5 to emergency plan JONES.R A Texas Utilities Generating Co 82/10/12 199pp 15720 128 24X Fiche 50-445, 82/10/12, 8210180006
- B210280259 Forwards FEMA interim finding on plant offsite emergency preparedness, consisting of FEMA memo to NRC & attachments ROTHSCHILD.M V Hearing Brench i 82/10/27 MILLER.H E. COLF.R., MCCCLLONS, A Atomic Safety and Licensing Board Panel 59pp L5838 147 24x Fiche 50-445 82/10/27,8210280259
- G Adjudicatory correspondence
- G210040020 Releases public version of applicant motions % affidavits & State of TX emergency mot plan FELITON, JM Division of Rules and Records B2/09/21 Document Management Branch 1p 15577 273 24X Fiche 50-445.82/09/21, P210040020
- 8210040024 Public version of applicant motion for summary disposition of intervenor Citizens Assoc for Sound Energy Contention 22 re emergency planning SANFORD, J C Teras Utilities Generating Co SANFORD, J C Debevoise & Liberman 82/08/23 Atomic Safety and Licensing Board Panel 16pp 15577 294 24X Fische 50-445,82/09/21.
- --8210040026 Public version of statement of matl facts not genuinely at issue re energency planning

 **Texas Vilities Generating Co 82/09/23 Atomic Safety and Licensing Board Panel 5pp 15577 310 24% (Tiche 50-445, 82/09/21,8210040020
- ~-8210040030 Public version of affidavit of RA Jones re intervenor Citizens Assoc for Sound Energy Contention 22 concerning energency planning JONES-RA Teras Utilities Generating Co 82/08/20 http: t5577 315 24X Fiche 50-445, 82/09/21,8210040020
- --B210040033 Public version of BT Lancaster affidavit re intervenor Citizens Assoc for Sound Energy Contention 22 concerning energency plan exercises & drills LANCASTER.B T Texas Utilities Generating Co. B2/0B/20 7pp 15577 326 24X Fiche 50-445, 82/09/21.6210040020
- --9210040037 Public version of affidavit of RE Linnemann re intervenor Citizens Assoc For Sound Energy Contention 22 concerning sycs of medical personnel for radiation emergencies U/resumes, notice of appearance & Certificate of Syc LINMEMANN.R E Texas Utilities Generating Co LINNEMANN.R E Radiation Management Corp 82/08/20 21pp 15577 333 24X Fiche 50-445.82/09/21.8210040020
- --8210040042 Public version of State of TX emergency mgt plan,inrluding Mood County, Scmervell County & City of Olen Rose, TX emergency operations plans CLEMENTS.W D. ADAMS.J B., LANSFORD, R.A. Texas, State of 82/05/24 801pp 15578 269 24X Fiche 50-445,82/09/21, 8210040020
- B2t0040089 Order denying NRC B20B24 request for reconsideration of ABIR B20804 order to show cause re NRC failurs to disclose identity of informants Limited and individuals B K must be identified MILLER.N E Atomic Safety and Licensing Board Panel B2/09/30 Office of the Executive Legal Director 14pp 15586 001 24X Fiche 50-445, B2/09/30, B210040089

- 8210130277 Brief on status of record re findings needed for docistall, per ASLB 820922 memorandum & order ABLB should close record on all issues order prompt submittal of proposed findings & issue decision Certificate of Svc encl REYNOLDS.N S . HORIN.W A Teras Utilities Generating Co REYNOLDS.N S . Debevoirs & Liberman 82/10/08 35pp 19678 205 244 Fiche 50-445.82/10/08.8210130297
- 8210150183 Forwards exceptions to ASLB 820930 order denying reconsideration, filed per 100FR2 762(a) Motion seeking etay of effectiveness of order to be filed on 821012 M/o enc! TURK, S. E. Hearing Branch 1 82/10/08 SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 2pp 19707 178 24x Fiche 50-445,82/10/08,8210150183
- 8210150366 Exceptions to ASLB B20930 order denying reconsideration of ASLB B20804 order to show cause why sanctions should not be imposed on NRC for failure to disclose informants Certificate of Svc enci TURK, S E Hearing Branch I 82/10/08 Atomic Safety and Licensing Appeal Panel 7pp 15704 307 24X Fiche 50-445.82/10-8210150366
- 8210150224 Response to ASLB 820922 memorandum & order for briefs un necessary documents & info to close evidentiary record Certificate of Svc encl ELLIS. J. Cifirens Association for Sound Energy 82/10/09 6(Ipp. 15705-286
- 8210130292 Responds to ASLB 820922 memorandum & order re record stat ASLB should close record on Contention 22 & Contention 5 W/exception of portions on issues of Board Notification 82-90 & Malsh/Doyle allegations N/Certificate of Svc ROTHSCHILD,M U , MIZUNO.0 8 Hearing Branch I 82/10/11 Jipp 15678 102 24X Fiche 50-445,82/10/11,8210130292
- 9210150124 Application for stay of effectiveness of ASLB 620930 (and denying reconsideration ruling that NRC did not show good cause for failure to comply w/orders to disclose informants 3 ordering disclosure Certificate of Svc encl
 TURK S E Hearing Branch 1 82/10/12 Atomic Safety and Licensing Appeal Panel 13pp 15698 001 24X Fiche 50-449, 82/10/12,8210150124
- B210150464 Notice of ASLAB constitution AS Rosenthal, chairman & MR Johnson & TS Moore, members SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel (127/11/12), p 15703 105 24X Fiche 50-445, 82/10/12, 8210150464
- 8210250104 Response to ASLB directive re Citizens Assoc for Dound Energy exhibits Requests listed documents from Assoc Exhibits 190A-449 be accepted into evidence Certificate of Svc encl Related correspondence ELLIS.J Citizens Association for Bound Energy 82/10/10 5/19pp 15792 089 24% Fiche 50-445.82/10/18.8210250104
- 8210280355 Motion for reconsideration of ASLB ruling re attachments
 J Dule deposition/testimony Clean copies of drawings will
 be provided-but intervenor should be allowed to ref
 documents Certificate of Svc encl Related correspondence
 ELLIS.J Citizens Association for Bound Energy 82/10/23 At
 Safety and Licensing Board Panel 8pp 15837 001 24X
 Fiche. 50-445, 82/10/23, 8210280355
- 8210280259 Forwards FEMA interim finding on plant offsite emergency preparedness, consisting of FEMA memo to NRC & attachments ROTHSCHILD, H U Hearing Branch i 82/10/27 HILLER, H E . CUIt, MCCOLLOM, K A Atomic Safety and Licensing Board Panel. 59pp 15838.147 24X Fiche 50-445,82/10/27,8210280259
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8210180006 Forwards Amend 35 to FSAR consisting of Revision 5 to emergency plan GARY,R J Texas Utilities Generating Co 82/10/12 DENTON, H & Office of Nuclear Reactor Regulation, Director 2pp 13720 1.4 24X Fiche 50-445,82/10/12,8210180006
- --8210180008 Amend 35 to FSAR consisting of Revision 5 to emergency
 JONEB.R A Texas Utilities Generating Ca 82/10/12 199pp
 15720 128 24X Fiche 50-445,82/10/12.8210180006
- O Inspection reports. IE Bulletins & correspondence
- 8210070364 Forwards IE Insp Rept 50-445/82-20 on 820801-31 No noncompliance noted MADSEN, G L. Division of Resident, Reactor Project & Engineering Programs 82/09/22 QARY, R J Texas Utilities Generating Co 15634 040 24X Fiche 50-445, 82/09/22, 8210070364

- --8210070369 IE Insp Rept 50-445/82-20 on 820801-31 No noncompliance noted Major areas inspected preoperation test review procedure, plant tour & status KELLEY. D.L., WESTERMAN. T.F. Division of Resident, Reactor Project & Engineering Programs 82/09/17 Spp 15634 042 24X Fiche 50-445.82/09/22.8210070364
- 6210190816 Forwards IE Insp Rept 50-445/82-14 on 820803-20 No noncompliance noted MADBEN.G L. Division of Resident, Reactor Project & Engineering Programs 82/09/27 GARV.R J Texas Utilities Generating Co 2p 15736 139 24x Fiche 50-445,82/09/29,8210190816
- --8210170820 iE Insp Rept 50-445/82-14 on 820803-20 No noncompliance noted Major areas inspected pipe whip restraints & licensee method of QC insp of skewed welds STEWART,R C . TAYLOR.R O . WESTERMAN,T F Division of Resident, Reactor Project & Engineering Programs 82/07/28 8pp 15736 141 24X Fiche 50-445,82/07/29.8210190814
- 6210190772 Forwards IE lnsp Repts 50-445/82-18 & 50-446/82-07 on 820907-10 No noncompliance noted MADBEN.G L Division of Resident, Reactor Project & Engineering Programs 82/10/01 OARY.R J Texas Utilities Generating Co 2p
- --8210190776 IE Insp Repts 50-445/82-18 & 50-446/82-09 on 820907-10 No noncompliance noted Major areas inspected const activities, including site tour, observation of welding, eram of safety-related piping & welding on main control panels QILBERT.L D , TOMLINSON, D P , MESTERMAN, T F Division of Resident, Reactor Project & Engineering Programs 82/09/29 1p 15737 130 24X Fiche 50-445,82/10/01,8210190772
- 8208190233 IE info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list ent! CDBB.L I Division of Fuel Factlities, Materials & Safeguards 62/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bulietin 92-03, "Stress Corrasion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list enci DEYDUNG, R C Director's Office Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 92/10/14, 8208190238
- S Reportable occurrences. LERs & related correspondence
- 821004031B Interim deficiency rept re conduit supports Initially reported on 820823 Evaluation continuing Completion anticipates by 821082 BARY.R J Texas Utilities Generating Co. 82/09/20 HADSEN, G L. Division of Resident, Reactor Project & Engineering Programs 1; 15386-167 24% Fiche 50-445.82/09/20.821004031B
- 8210260375 Daficiency rept re overtorquing of safaty-relief valves Initially reported on 820910 Evaluation in progress & will be completed by 821130 OARV.R J Texas Utilities Generating Co 82/10/06 MADSEN. G L Division of Resident. Reactor Project & Engineering Programs | Ip 15803 362 24X Fiche 50-445,82/10/06,8210260375
- 821025033B Interim deficiency rept re defective Limitorque pinion keys Initially reported on 820818 Matter not reportable per 10CFR50 55(e) based on investigation CARY, R J Texas Utilities Generating Co 82/10/12 MADBEN, G L Division of Resident, Reactor Project & Engineering Programs Jp 15790 331 24X Fichs 90-445.82/10/12.8210250338
- 8210250346 Interim deficiency rept re linear indications identified in dicasi generator auxiliary skid initially reported on 820707 Evaluation continuing Next rept expected by 821217 GARY.R J Texas Utilities Generating Co 82/10/14 MADSEN, 0 L Division of Resident, Reactor Project & Engineering Programs 1p 15790 336 24X Fichs 50-445,82/10/14,8210250346.
- DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA . UNIT 2
- A Application/construction stage documents & correspondence
- E210220513 Notification of 820913 meeting w/util in Bethesda.MD to discuss procedures generation package CLIFFORD,JW Procedures & Test Review Branch 82/08/27 ZIEMANN,DL Procedures & Test Review Branch 2pp 15786 089 24X Fiche, 30-445, 82/08/27, 8210220513
- 8210210025 Summary of B20625 meeting w/util & Oibbs & Hill in Bethesda, MD re equipment qualification.
 BURNELL: 8 B. Licensing Brench 1 82/09/30 Licensing Brench 1 87pp 15782 180 24X Fiche. 30-445. 82/09/30, 8210210025.

- F Security, medical, emergency & fire protection plans
- 8210040020 Releases public version of applicant motions & affidavits & State of TX emergency mpt plan FELTON.J M Division of Rules and Records 82/09/21 Document Management Branch ip 15577 293 24X Fiche 50-445.82/09/21. 8210040020
- --B210040042 Public version of State of TX emergency mgt piam, ancluding Hood County, Samervell County & City of Glen Rose, TX emergency operations plans CLEMENTS, W D , ADAMS, J B , LANSFORD, R A Texas, State of B2/05/24 801pp 15578 269 24X Fiche 50-445, 82/09/21, 8210040020
- B210070109 Forwards "Evaluation of Hood & Sommervell Counties & State of TX Radiological Emergency Plans for Comanche Peak Steam Electric Station "Offsite protection adoquate Joint exercise planned for early 1983
 THOMAS, L M Federal Emergency Management Agency 82/09/29
 DIRCKS, W Office of the Executive Director for Operations 10
 15628 165 24X Fiche 50-445,82/09/29,8210070109
- --B210070112 "Evaluation of Hood & Summervell Counties & State of IX Radiological Emergency Plans for Comanche Peak Steam Electric Station"

 * Federal Emergency Management Agency 82/09/29 57pp 15628 166 24X Fiche 50-445,82/09/29,8210070109
- 8210130576 Forwards response to license condition on physical security program approval & pages to FSAR security plan Response & plan withheld (ref 10CFRZ 770 & 10CFR73 21)

 OARY,R J Teras Utilities Generating Co 82/10/08 YOUNGBLOOD. II J
 Licensing Branch 1 ip 15677 060 24X Fiche 50-445,82/10/08.
- 8210180006 Forwards Amend 35 to FSAR consisting of Revision 5 to emergency plan GARY, R. J. Teras Utilities Generating Co. 82/10/12 DENTON. II R Office of Nuclear Reactor Regulation. Director 2pp 15720 126 24X Fiche 50-445,82/10/12.9210180006
- --8210180008 Amend 35 to FSAR consisting of Revision 5 to emergency plans JONES.R A Teras Utilities Generating Co. 82/10/12 199pp 15720 128 24X Fichs 50-445,62/10/12.8210180006
- 8210280259 Forwards FEMA interim finding on plant offsite emergency preparedness; consisting of FEMA memo to NRC & attachments ROTHSCHILD, M U Hearing Branch 1 82/10/27 MILLER, M E Atumic Safety and Licensing Board Panel 59pp 15838 147 24X Fiche 50-445, 82/10/27, 8210280259
- G Adjudicatory correspondence
- 8210040020 Releases public version of applicant motions & affidavity & State of TX emergency mgt plan FELTON. J M Division of Rules and Records 82/09/21 Document Management Branch 1p 15577 293 24X Fiche 50-445.82/09/21. 8210040020
- --8210040024 Public version of applicant motion for summary disposition of intervenor Citizens Assoc for Sound Energy Contention 22 re emergency planning
 SAMFORD, J C Texas Utilities Generating Co SAMFORD, J C
 Debevoise & Liberman 82/08/23 Atomic Safety and Licensing
 Board Panel 16pp 15577 274 24X Fiche 50-445,82/09/21.
 8210040020
- --B210040026 Public version of statement of mati facts not genuinely at issue re emergency planning

 * Texas Utilities Generating Co B2/08/23 Atomic Bafety and Licensing Board Panel Spp 15577 310 24% Fiche 50-445, 82/09/21:8210040020
- --8210040030 Public version of affidavit of RA Jones re intervenor Citizens Assoc for Sound Energy Contention 22 concerning emergency planning JONES.R A Texas Utilities Generating Co. 82/09/20 Hpp 15577:315 24X Fiche 50-445,82/09/21.8216040020
- --8210040033 Public version of BT Lancaster affidavit re intervenor Citizens Assoc for Sound Energy Contention 22 concerning emergency plan exercises & drills LANCASTER.B T Tesas Utilities Generating Co 82/08/20 7pp 15577

- --8210040037 Public version of affidavit of RE Linnemann re intervenor Citizens Assoc for Sound Energy Contention 22 concerning syes of nedical personnel for radiation emergencies W/resumes, notice or appearance & Contificate of Sye Linnemann, R E Teras Utilities Generating Co. Linnemann, R E Radiation Management Corp. 82/08/20. 21pp. 15577-333. 24X Fiche 50-445,82/09/21.8210040020
- 82:0040089 Order denying NRC 820824 request for reconsideration of ASLN 820804 order to show cause re NRC failure to disclose identify of informants Ltr-designated individuals 8 K must be identified MILLER. M E Atomic Safety and Licensing Board Panel 82/09/30 06/ice of the Executive Legal Director 14pp 15581 001 24X Fiche 50-445, 82/09/30, 8210040089
- 8310130299 Brief on status or record re findings needed for detision, per ASLB 820922 memorandum & order ASLB should close record on all issues, order prompt submittal of proposed findings & issue decision Certificate of Svc encl REYNOLDS.NS , MORIN.NA A Teras Utilities Generating Co REYNOLDS.NS Debevoise & Liberman 82/10/08 35pp 15678 205 24% Fiche 50-445.82/10/08.8210130299
- 8210150183 Forwards exceptions to ASLE 820930 order denying reconsideration, filled per 10CFR2 782(a) Motion seeking stay of effectiveness of order to be filed on 821012 W/o enci FURKLS E Hearing Branch I 82/10/08 SHGEMAKER C J Atomic Sarety and Licensing Appeal Panel 2pp 15707 178 24X Fiche 50-445, 82/10/08, 8210150183
- 6210150366 Exceptions to ASLB 820930 order denying reconsideration of ASLB 620804 order to show cause why sanctions should not be imposed on NRC for failure to disclose informants Certificate of Svc encl 100K.S E Hearing Branch 1 82/10/08 Atomic Safety and Licensing Appeal Panel 7pp 15704 307 24X Fiche 50-445,82/10/08, 8210150366
- 0210150224 Response to ASLB 820922 memorandum & order for briefs on necessary documents & info to close evidentiary record Certificate of Svc enci ELLIS. J Citizens Association for Sound Energy 82/10/09 60pp 15705 286 24X Fiche 50-445.82/10/09.8210150224
- 8210130272 Responds to ASLB 820722 memorandum & order re record status ASLB should close record on Contention 22 & Contention 5 w/exception of portions on issues of Board Notification 82-90 & Walsh/Doyle allegations W/Certificate of Svc ROINSCHILD.M V . HiZUND.G S Hearing Branch 1 82/10/11 33pp 15678 102 24% Fiche 50-445,82/10/11.8210130272
- B210150124 Application for stay of effectiveness of ASLB B20930 order denying reconsideration.ruling that NRC did not show good cause for Failure to comply whorders to disclose informants to ordering disclosure Certificate of Svc encl TURK, S.E. Hearing Branch | B2/10/12 Atomic Safety and Licensing Appeal Panel | 13pp | 15698 001 24% Fiche 50-445, 82/10/12,8210150124
- d210150464 Notice of ASLAB constitution AS Rosenthal, chairman & KR Johnson & TS Moore, members SHUEHAKER, C. J. Atomic Safety and Licensing Appeal Panel 82/10/12 to 15703 105 24X Fiche 50-445.82/10/12:8210150464
 - SLB directive re Citizens Assoc for Sound

 "sted documents from Assoc
 ted into syldence Gertificate of
 fence
 ion for Sound Energy 82/10/18 55pg
- Joyle deposition/testimony Clean copies of drawings will be provided but intervenor should be allowed to ref documents Certificate of Svc encl Related correspondence ELLIS, J Citizens Association for Sound Energy 82/10/23 Atomic Safety and Licensing Board Panel 8pp 15839 001 24x Fiche 50-445,82/10/23,6210280355
- 8210280259 Forwards FEMA interim finding on plant offsite emergency preparedness, consisting of FEMA memo to NRC & attachments ROTHSCHILDIN U Hearing Branch 1 82/10/27 MILLER M E . COLE, H . MCCOLLOM, K A Atomic Safety and Licensing Board Fanel 59pp 15838 147 24% Fiche 50-445,82/10/27,8210280259
- K Utality Final Bafety Analysis Report (FSAR) & amends

1

8210180006 Forwards Amend 35 to FBAR consisting of Revision 5 to emergency plan GARY.R J Texas Utilities Generating Co 82/10/12 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15720 126, 24X Fichs 50-445, 82/10/12, 8210180006

- --8210180008 Amend 35 to FSAR consisting of Revision 5 to sarger; | JONES, R A Teras Utilities Generating Co 82/10/12 [v/pp 15/20 128 24X Fiche 50-445, 82/10/12, 82/10/80006
- O Inspection reports, 1E Bulletins & correspondence
- 8210190772 Forwards IE (nsp Repts 50-445/82-18 & 50-446/82 07 gm 820907-10 No noncompliance noted MADBEN. O L Division of Resident, Reactor Project & inginisering Programs 82/10/01 GARY.R J Texas Utilities Concrating Co *** 15737 128 24X Fiche 50-445.82/10/01.6210170772
- --B210190776 IE Insp Repts 50-445/B2-18 & 50-446/B2-09 on (j.v.o) 15 p. noncompilance noted Major areas inspected const activities including site tour observation of welding exam of safety-related piping & welding on main control panels GILBERT'. D . TOMLINSON D P . MESTERMAN, T F Division of Resistance Project & Engineering Programs B2/09/29 ip 10/J? Electron 244 Fiche 50-445/82/10/01/8210190772
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dielodged 1-ff? Implant Seeds " Svc list encl COBB, L I Division of Fuel Facilities, Naterials & Sufegueres 82/10/06 Consolidated Edison Co of New York 6660 15/64 (24% Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulistin 82-03, "Stress Corrosion Cracking in Thirt-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants " Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 1155p 15810 125 24X Fiche 30-000, 82/10/14, 0208190218
- S Reportable occurrences. LERs & rolated correspondence
- B21004031B Interim deficiency rept re conduit supports Initially reported on B20823 Evaluation continuing Completion anticipated by 821022 GARY, R. J. Texas Utilities Concrating Co. 82/09/20 MADIAN, U. Division of Resident, Reactor Project & Engineering Programs 1: 15366-167 24X Fiche 50-445,82/09/20,8210040318
- 8210240375 Deficiency rept re overtorquing of safety-relief valves Initially reported on 820910 Evaluation in progress & ufil be completed by 821130 OARY,R J Texas Utilities Generating Co 82/10/06 HAB',N. U I Division of Resident. Reactor Project & Engineering Programs II 18803 362 24X Fiche 50-445,88/10/06.8210260375
- 82(0280338 Interim deficiency rept re defective Limitorque pinten keys Initially reported on 820818 Matter not reportable per 10CFR80 55(e) based on investigation OARY.R J Texas Utilities Generating Co 82/10/12 Nabill 9 i Division of Resident, Reactor Project & Engineering Programs la 15790 331 24X Fichs 50-445.82/10/12.8210250338
- 8210250346 Interim deficiency rept re linear indications identified in diesel generator auxillary skid initially reported on 820709 Evaluation continuing Next rept expected by 821217 GARY.R J Texas Utilities Generating Co 82/10/14 MADMAN 9 L Division of Resident, Reactor Project & Engineering Program 18 15790 336 24X Fichs 50-445.82/10/14.8210250346
- DOCKET STN-50-447 GESSAR-238
- A Application/construction stage documents & correspondence
- 8207120147 Forwards NEDO-21471-01, "Analytical Model for Estingting Drag Forces on Rigid Submerged Structures Caused by LOCA & Safety Relief Valve Ramshead Air Discharges, Suppl for Y-Guencher Air Discharges "BUCHHOLZ, R H General Electric Co 80/06/18 PARR, D D Literates Branch 3 Ip 13008-001 24X Fiche 50-447,80/06/18,8207120147
- --8207120253 "Analytical Model for Estimating Drag Forces of Rigid Submerged Structures Caused by LOCA & Safety Relief Valve Ramshead Air Discharges, Suppl for X-Guencher Air Discharges " LASHER, L E , TOWNSEND, H E , ROSERS, A E Openeral Electric Co NEDD-21471-01 S01 79/10/31 lipp 13808 002 24X Fiche 50-447,80/06/18,8207120147
- 8210040380 Notification of 820923 meeting w/OE in Bethesda, MD for Technical Update Meeting A on GESSAR-II probabilistic riet assessment LYNCH, N D Licensing Branch 2 82/09/17 THOMAS, C O Standardization & Special Projects Branch App 15597 207 28x Fiche 50-447, 82/09/17, 8210040380.

- 8210050398 Forwards Amend 7 to application for final design acceptance review of OESBAR-230 correcting typographical errors & clarifying discrepancies in portions of Chapters 1.3.4.6 & 15
 VILLAR General Electric Co 82/09/23 EISENHUT, D @ Division of Licensing 1p 15777 001 24X Fiche 50-447,82/09/23,8210050398
- --8210050408 Amend to application for final design acceptance review of OESSAR-236, correcting typographical errors & clarifying discrepancies in portions of Chapters 1.3.4.6 & 15 VILLA: R Opensal Electric Co 82/07/23 App 15777 002 24X Fiche 50-447.82/09/23,8210050398
- --8210220174 Amend 7 to GESSAR II * General Electric Co 82/09/23 259pp 15777 004 24X Fiche 50-447,82/09/23,8210050398
- 8210050328 Submits GE understanding of major agreements & ground rules re NRC review of GESBAR II, in response to NRC request at 020915 meeting Concurrence requested SHERH00D.0 0 General Electric Co 82/10/01 DISENHUT.D 0 Division of Licensing 2pp 15610 252 24X Fiche 50-447,82/10/01,8210050328
- B21022046B Nobjification of B21015 meeting w/util to discuss inclusion of external events in probabilistic risk assessment review LYNCH, M D Licensing Branch 2 B2/10/07 THOMAS, C Standardization & Special Projects Branch 3pp 15786 204 24% Fiche 50-447, B2/10/07, B21022046B
- 8210220463 Notification of 821015 meeting w/util to discuss major issues identified in probabilistic risk assessment & impact on review sthedule LYNCH M D Licensing Branch 2 82/10/08 THOMAS.C Standardization & Special Projects Branch 3pp 15786 207 24X Fiche 50-447, 82/10/28,0210220463
- 8210270046 Forwards Amend 8 to DESSAR II.responding to NRC 811203 acceptance review 1tr re geotechnical, radiation sources & failure mode & effects analysis & committing applicant to address NRC acceptance criteria SHERMOOD, 0 Q General Electric Co 82/10/18 EISENHUT, D Q Division of Licensing 2pp 15816 001 24X Fiche 50-447,82/10/18, pp. 10270046
- --8210270081 Amend 8 to 238 GESBAR II application for review responding to NRC 811231 questions re gentechnical radiation sources & failure mode & effects analysis & committing applicant to address NRC acceptance criteria VILLAR General Electric Co 82/10/18 345pp 15816 003 24% Fiche 50-447.82/10/18.8210270046
- K Utility Final Bafety Analysis Report (FBAR) & amends
- B21005039B Forwards Amend 7 to application for final design acceptance review of OESBAR-23B, correcting typographical errors & clarifying discrepancies in portions of Chapters i, 3.4, 4, 5, 15
 VILLA, R. General Electric Co. 82/09/23 EIBENHUT, D. 0 Division of Licensing is 15777 OOI 24X Fiche 50-447, B2/09/23, B210050398
- --0210220174 Amend 7 to 0686AR 11 * General Clectric Co 62/07/23 259pp 15777 006 24X Fiche 50-447,82/09/23,8210050398
- DOCKET STN-50-454 BYRON STATION, UNIT I
- A Application/construction stage documents & correspondence
- 8210010271 Forwards five oversized P&IDs referred to in util 920909 ltr to NRC re waterhammer prevention. Aperture cards are available in PDR TRAMH.TR Commonwealth Edison Co 92/09/22 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 15573 122 24X Fiche 50-000, 82/09/22, 9210010271
- 8210080313 Bummary of 820708 & 0? meetings w/utils, Sargent & Lundy, Aerojet Energy Conversion Co & Rockford League of Women Voters in Chicago, IL & at plant site re vol reduction sys Questions re Topical Rept AECC-2-P encl KIPER, K L Licensing Branch | 82/09/23 Licensing Branch 1 12pp 13663 341 24X Fiche 50-454,82/09/23,8210080313
- 8210030123 Submits final quarterly rept re const completion date Unit 1 const & testing schedule still keyed to fuel loading on 830831 DELQEOROE. L. O Communication Co. 82/09/27 DENTON. H R Office of Nuclear Reactor Regulation, Director. 1p 15605 170 24X Fichs 50-454, 82/09/27. 8210030123

- 8210280429 Forwards addit question re vol control sys.in response to applicant answer to NRC Guestion G321 43 Response requested within 30 days
 YDUNOBLOOD, B J Licensing Granch 1 82/10/04 DELCEGRGE, L C Commonwealth Edison Co. 3pp. 15860 042 24X Fiche 50-000, 82/10/04 8210280429
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manuai" GOLDEN, J C Commonwealth Edison Co 82/10/06 CASE, E G Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24x Fiche 50-000, 82/10/06.8210260526
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" * Commonwealth Edison Co 82/09/30 B3pp 15805 139 24x Fiche 50-000, 82/10/06. 8210260526
- 8210280420 Forwards request for add1 info re venting of high points in RCS. method of depressurization to cold shutdown & depressurization following steam generator tube rupture events Response requested within 30 days YOUNOBLOOD, B J Licensing Branch i 82/10/07 DELGEORGE, L O Commonwealth Edison Ca 4pp 15060 009 24x Fiche 50-000.82/10/07, 6210280420
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 82:00:02:02 Submits add1 info re reactor collant pump locked rotor by sheft break transients at facilities Info closes Confirmatory Issue 34 of Byron SER TRAMM.TR Commonwealth Edison Co 62/09/22 DENTON.HR Office of Nuclear Reactor Regulation, Director 4pp 15568 073 24X Fiche 50-000.82/09/22,82:00:10202
- 821025010B Forwards revised FSAR info re protection against possible turbine missifes Revisions to turbine missife analysis rept encl Info closes out SER Outstanding Item 2

 TRAMM.T R Commonwealth Edison Co 82/10/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 15pp 15769 276 24X Fiche 50-000.82/10/19.8210250108
- F Security, medical, emergency & fire protection plans
- B210270363 Forwards list of deviations from Chemical Engineering
 Branch Technical Position 7 5 1 re fire protection program
 Deviations listed include lighting & communication &
 hydrogen line routing Justification of deviations requested
 YOUNOBLOOD, B J Licensing Branch 1 82/10/05 DELEGORGE, C C
 Commonwealth Edison Co 7pp 15965 240 24% Fiche 50-000 B2/10/05.
- 82(0130376 Advises that installation of offsite dose calculation syprogram fully operational tracking model & operational A model will be delayed until 82(23) to complete prime computer installation SWARTZ,E D Commonwealth Edison Co 82/10/06 DENTON,M R Office of Nuclear Reactor Regulation, Director 2pp 15682 098 24X Fiche 90-000,82/10/06,8210130376
- 8210130370 Forwards Revision 7 to modified amended security plan Revision withheld (ref 10CFR2 790 & 10CFR73 21) DELGEORGE, L D Commonwealth Edison Co 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 15680 323 24X Fiche 50-454, 82/10/08, 8210130370
- B210270047 Releases public version of revisions to Quad Cities, Zion & Dresden emergency plan annexes & revised generating station emergency plan telephone directory FELTON.J M Division of Rules and Records 82/10/08 Document Management Branch 19 [5877 313 24X Fiche 50-000, 82/10/08, 8210290047
- --B210290060 Forwards public version of Revision 3 to Guad Cities & Zion emergency plan annexes. Revision 2 to Dresden emergency plan annex. Revision 0 to Byron emergency plan annex & revised generating station emergency plan telephone directory MOORE. R D Commonwealth Edison Co B2/07/30 DENTON. H R NRC No Detailed Affiliation Given 5pp 15877 314 24X Fiche 50-000,82/10/08.8210290047
- --8210290077 Public version of Revision 3 to Quad Cities & Zion emergency plan annexes. Revision 2 to Dresden emergency plan annex & Revision 0 to Byron emergency plan annex & Commonwealth Edison Co 82/06/30 325pp 15877 319 24X Fiche 50-000, 82/10/08, 82/10290047
- --8210290088 Public version of revised generating station emergency plan telephone directory QALLE,D P Commonwealth Edison Co 82/08/12 43pp 15878 218 24% Fiche.50-000,82/10/08,8210290047

8210220359 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 cornstent Training coordinator assigned in Apr 1982 to improve health physics training programs IRAMM, T.R. Commonwealth Edison Co. 82/10/14 DENION, H.R. Office Apr Nuclear Reactor Regulation, Director 9pp 15776-287 24% Fiche 50-000, 82/10/14 8210220358

G Adjudicatory correspondence

- 5210050391 Motion for clarification of portions of ASLB 820910 merorandum & order ruling on motions for summary disposition of certain contentions Certificate of Svc encl Related correspondence
 BiELAWSKI.A P Commonwealth Edison Co BIELAWSKI.A P Isham.
 Lincoln & Deale 82/09/28 Atomic Safety and Licensing Board Panel 6pp 15608 225 24% Fiche 50-454,82/09/28,8210050391
- 8°100a0182 Confirms 820928 telcon.in which NRC withdrew interrogatories 77-1 & 77-2 based on withdrawn Contention 70 Answers to remaining interrogatories due by 821015 RAMSON.R J. Hearing Branch 4 82/10/04 ROSE.B. Cherry, M. M. /Cherry Flynn & Kanter ROSE.B. League of Homen Voters of Roctford.IL 1p 15614 120 24x Fiche 50-454,82/10/04,8210060182
- R210070127 Motion for leave to file answers to util amended second round of interrogatories t day lake RDSE.3 League of Nomen Voters of Rociford, IL ROSE, B Cheriy, M /Cherry Flynn & Kanter 82/10/05 Atomic Safety and Licensing Board Panel 2pp 15627 084 24X Fiche 50-454,82/10/05,8210070127
- -8210070129 Answers to amended second round of interrogatories Certificate of Svc enc! ROSE, B. League of Homen Voters of Rockford, IL. ROSE, B. Cherry, M. M. /Cherry, Flynn, 2 Kanter 82/10/05 Commonwealth Ediron Co 344pp 15427 086 24% Fiche 50-454,82/10/05,8210070127
- 8210130373 Response opposing Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 820923 motion to reconsider summary disposition of Contention I on GA/GC New info would not change decision W/Certificate of Syc MILLER.M I Commonwealth Edison Co MILLER.M I Isham, Linculn & Deale 82/10/08 Atomic Safety and Licensing Board Panel Lapp 15480 247 24X Fichs 50-454.82/10/08.8210130373
- e210130095 Response supporting applicant 820928 motion for clarification of portion of ASLB 820910 memorandum % order denging NRC % applicant motions for summary disposition titigable issues should be delineated Wcertificate of Svc GULDBERO, S.C. Hearing Branch 4 82/10/12 Atomic Safety and Licensing Board Panel 5pp | 15673-110 24X Fiche 50-454.82/10/13.8210130095
- 8210150087 Response opposing Details Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 820923 motion for reconsideration of summary disposition of Contention (f) Introduction of new facts not allowed W/Certificate of Svc GOLOBERG, S.C. Hearing Branch 4 62/10/12 Atomic Safety and Litemsing Board Panel 14pp 15701 200 24x Fiche 50-454,82/10/12,8210150067
- 5210150383 Memorandum % order ruling on applicant disclosure obligations Applicant 820827 motion requesting mod of ASLB 820726 memorandum & order denied Relevant or new info must ovided, per Commission precedents

 7 Atomic Safety and Licensing Board Panel 82/10/12 Edison Co 7op 15704 058 24% Fiche 50-454,

- --8210180146 Affidavit of LA Bowen Util does not intend to install 151 sensors on feedwater bypass sys piping Existence of constant feedwater flow precludes water hammer event similar to event at Krsko BONEN, L. A. Commonwealth Edison Co. 62/10/05 34pp 19719 14-24X Fiche 50-454,82/10/14,8210180142
- 8210180166 Confirming order canceling 821014 prehearing confirence Janockford, IL Discovery gragress discussed during 821014 teleon MARGULIES, M.B. Atomic Safety and Licensing Board Panel 82/10/15 p. 15719 168 24% Fiche 50-454.82/10/15.8210180166
- 82(0180170 Order granting Rockford League of Women Voters motion & leave to file instanter answers to util amended second round of interrogatories 1 day late MARGULIES.N B Atomic Safety and Licensing Board Panel #2/10/1° League of Momen Voters of Rockford, IL 1p 15719 165 24x Fiche 30-454, 82/10/15,8210180170
- 8210210274 Answers to first set of interrogetories, pursuant to A'+5 821020 memorandum & order Verification & Proof of Svc encl Related correspondence
 JOHNSON B League of Homen Voters of Rockford, IL 82/10/15
 Defice of the Executive Legal Director 48pp 15766 190 24x
 Fiche 50-454, 82/10/15, 8210210274
- 82(0210278 Reply to amended first request for production of dorles-il Proof of Svc encl Related correspondence ROSE, B League of Homen Voters of Rockford, IL ROGE, B (Agray * H /Cherry, Flynn & Kanter 82/10/15 Office of the Liecutis, Legal Director 3pp 15765 150 24% Fiche 50~454, G2/10/19, 8210210278
- 8210210384 First interrogatories & request for documents βroof of 6, encl Related correspondence ROSE, B League of Women Vaters of Rockford, IL RO46, β Cherry M /Cherry, Flynn & Kanter 82/10/15 Commonwealth Edison 6, 22p 13764 016 24% Fiche 50-454,82/10/15,82102101014
- 6210210346 Motion for leave to file reply to new matters resist by applicant & NRC in response to Alliance motion to reconsider disposition of Contention I re GA & GC CASSELLD W Dekalb Area Alliance for Responsible Inergy CASSELLD W Simils/ppi Alliance for the Environment (4Alt) 62/10/18 Atomic Safety and Licensing Board Panel 10 19764 210 24X Fichs 50-454,82/10/18.8210210346
- --8210210347 Reply to new matters raised by applicant & NR(in resp.*..
 to Alliance motion to reconsider summary disposition of
 Contention I re QA & QC Disposition should be donized since
 issues of matl fact exist Certaficate of Svc enc!
 CASSEL, D W DeKalb Area Alliance for Responsible Energy
 CASSEL, D W Sinnissippi Alliance for the Environment (6Mf.)
 82/10/18 Atomic Safety and Licensing Doard Panel 5pp
 15764 211 24X Fiche 50-454, 62/10/18, 8210210,146
- 8210250071 Corrects two typographical errors & minor missistenent in Rockford League of Homen Vaters answers to NRC amended first set of Interrogataries ROSE, B. ROSE, B. Cherry, M. M. /Cherry, Flynn & Kanter (13/10/2.3) Docketing & Services Branch ip 15787-047 24X Fiche 50-454, 82/10/20,8210250071
- 8210240380 Forwards author 821022 ltr to NRC transmitting first set so interrogatories. ROSE.8 Cherry, M M /Cherry, Flynn & Kanter ROSE.8 I isague set Women Voters of Rockford, IL 82/10/22 MAROULIES, H D Alomic Safety and Licensing Board Panel 1p 15804 205 24X Fiche 50-454, 82/10/22, 8210240380
- --8210260384 Forwards proposed interrogatories & motion for production of documents
 ROBE, B. Cherry, M. M. / Cherry, Flynn & Kanter ROBE, B. League at ,
 Homen Voters of Rockford, IL. 82/10/22 OOLDBERD, B. C. Mearing
 Branch 4 ip 18804 206 24X Fiche 50-454, 82/10/22, 8210220369.
- --8210260392 Proposed first set of interrogatories Proposed Aption froproduction of documents by NRC & Proof of Svc enclasses the League of Homen Voters of Rockford/IL 82/10/22 Office of the Executive Legal Director 26pp 15804 207 24K Fiche 50-454,82/10/22,8210260380
- 8210270216 Notice of ASLB reconstitution IW Smith, chairmen & TAD Callinan & RF Cole members LAZO,R M Atomic Safety and Licensing Board Panel 92/10/25 #31 515823 006 24% Fiche 50-454,82/10/25,8210270216

:

- 8210290293 Forwards original B Johnson verification for Rockford League of Momen Voters answers to NRC amended first set of interrogatories on Contentions 39 & 109 Related correspondence
 ROSE, B Cherry, M M /Cherry, Flynn & Kanter ROSE, B League of Wonen Voters of Rockford. IL 82/10/26 Decketing & Services Branch 2pp 15854 075 24% Fiche 50-454,82/10/26,8210290293
- 8210280347 Response opposing Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 821018 motion for leave to submit reply to NRC & util responses to intervenor 820723 motion for reconsideration W/Certificates of Svc GOLDERO, S.C. Hearing Branch 4 82/10/27 Atomic Safety and Licensing Board Panel 5pp 15838 351 24X Fiche 50-454,82/10/27,8210280347
- B210290105 Ark receipt of Rockford League of Women Voters proposed interrogatories to NRC & motion For production of documents NRC will shortly advise League of which interrogatories will be answered GOLDBERG, S.C. Hearing Branch 4 82/10/28 ROSE, B. Cherry, M. M./Cherry, Flynn & Kanter ROSE, B. League of Women Voters of Rockford, IL. 1p 15854 003 24% Fiche 50-454,82/10/28,8210290105

H General correspondence

- 82:0070176 Responds to 820929 ltr requesting NUREG-0782 & CMNI-20 MUREO can be ordered from NRC Div of Technical Info & Document Control BMI rept available from NT18

 OCLDBERG-8 C Hearing Branch 4 82/10/06 VON ZELLEN, B Northern Illinois Univ 1p 15634 262 24X Fiche 50-454, 82/10/06, 82:0070176
- % Utility Final Safety Analysis Report (FBAR) & amends
- 8210040060 Forwards affidavit stating that distribution of FSAR Amend 39 has been made in accordance w/Encl 1 of NRC 781020 ltr TRAMM.TR Commonwoalth Edison Co 82/09/23 DENTON, HR Office or Nuclear Reactor Regulation, Director 2pp 15583 191 24X Fiche 50-000,82/09/23,8210040060

M Antitrust correspondence

- 8210070180 Forwards, for roviou & comment, draft OL antitrust review finding of no significant change W/o encl VOOLER, B H Hearing Branch 2 82/10/06 CUTLER, M Justice. Dept of 1p 15634 277 24% Fiche 50-454, 82/10/06, 8210070180
- O Inspection reports, IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Buppl 1, "Leaking & Disladged J-125 laplant Speds " Syr list encl CO3D.L I Division of Fuel Facilities, Materials & Safeguards 82/f0/06 Consolidated Edison Co of New York 66pp 15761 200 24X Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulistin 82-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter: Stainless Steel, Recirculation 8ys Piping at BWR Plants" 8vc list encl
 DEYOUNO.R C Director's Office, Office of Inspection and Enforcement 92/10/14 Consolidated Edison Co of New York 115pg #5810 128 24% Fiche 50-000, 692/10/14, 8208190238
- 82102603B7 Confirms 821026 meeting at Region 3 oft to discuss util response to IE Insp Repts 30-454/82-03 & 30-459/82-04 SPESSARD: R L Division of Project & Resident Programs 62/10/17 REED. C Commonwealth Edison Co Ip 15803 105 24X Fishe 30-434, 822/10/17, 82102403B7
- B210260307 Ack receipt of B21014 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-454/82-14 NDRELIUS: C E Division of Engineering & Technical Programs B2/10/22 REED, C Commonwealth Edison Co ip 15799 321 24X Fiche 50-454:82/10/22,8210280307
- --- E21026030B Responds to NRC 820913 ltr re violations noted in IE Insp Rept 50-494/82-14 Cerrective actions piping contractor initiated revision to BIP 4 000 to include mod to hardware removal/alteration rept form BELOEDROG. O Commonwealth Edison Co 82/10/14 KEPPLER, J 0 Region J, Office of Director 4pp 13799 322 24X Fiche 50-454,82/10/22.8210260307

- DOCKET STN-50-455 BYRON STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210010271 Forwards five oversized P&IDs referred to in util 820909 itt to NRC re waterhammer prevention Aperture cards are available in PDR IRAMM. T R Commonwealth Edison Co. 82/09/22 DENTON. H R. Office of Nuclear Reactor Regulation, Director 2pp 15573 122 247 Fiche 50-000.82/09/22.8210010271
- 8210080313 Summary of 820708 & 09 meetings w/utils, Sargent & Lundy, Aerojet Energy Conversion Co & Rockford League of Women Voters in Chicago, IL & at pland site re vol reduction sys Guestions re Topical Rep* AECC-2-P encl KIPER, K L Licensing Branch 1 82/09/23 Licensing Branch 1 12pp 15663 341 24X Fiche 50-454.82/09/23.8210080313
- 8210280429 Forwards add1 question re vol control sys, in response to applicant answer to NRC Question Q321 43 Response requested within 30 days VOUNOBLOOD. B J Licensing Branch 1 82/10/04 DELGEORGE, L I) Commonwealth Edison Co 3pp 15860 042 24% Fiche 50-000. B2/10/04, 8210980439
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" GOLDEN, J C Commonwealth Edison Co 82/10/06 CASE, E G Offict of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000, 82/10/06, 8210260526
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Hanual"

 * Commonwealth Edison Co 82/09/30 83pp 15805 139 249 Fiche 50-000,82/10/06,8210260526
- 9210280420 Forwards request for addI info re venting of high points in RCS,method of depressuritation to cold shutdown 2 depressuritation following steam generator tube rupture events Response requested within 30 days YOUNOSLOOD, D. J. Licensing Branch 1 02/10/07 DELOEORGE, L. O. Commonwealth Edison Co. 4pp. 15860 007 24% Fiche 50-000,82/10/07.
- E NRC Safety Evaluation Report (SER). suppls & correspondence
- B210010202 Submits add1 info re reactor coolant pump locked rotor & shaft break transients at facilities Info closes Confirmatory Issue 34 of Byron SER TRAMM, TR Commonwealth Edison Co 82/07/22 DENTON, HR Office of Nuclear Reactor Regulation, Director 4pp 15568 073 24% Fiche 50-000, 82/09/22, 8210010202
- B210250108 Forwards revised FBAR info re protection against possible turbine missiles Revisions to turbine missile analysis rept encl Info closes out SER Outstanding Item 2 TRAMM.T R Commonwealth Edison Co 82/10/19 DENTON.H R Office of Nuclear Reactor Regulation. Director 15pp 15789 296 24X Fiche 50-000.82/10/19.8210250108
- F Security, medical, emergency & fire protection plans

DOCKEIED HEIMS

- --8210290060 Forwards public version of Revision 3 to Guad Cities & Zinn emergency plan anneies. Revision 2 to Dresden emergency plan annei, Revision O to Byron emergency plan annes & revised enerating station energency plan anner & revised generating station energency plan telephone directory MODRE.R D Commonwealth Edison Co 82/07/20 DENTON.H R NRC - Nr Detailed Affsilation Given 5pp 15877 314 24/ Fiche 30-000.82/10/08.8210290047
- --8210290077 Public version of Revision 3 to Guad Cities & Zion emergency plan annexes. Revision 2 to Dresden emergency plan annex * Revision 0 to Byron emergency plan annex * Commonwealth Edison Co 82/06/30 325pp 15877 319 6 325pp 15877 319 24X # Cornenweelth Edison Co 82/00 Fiche 50-000, 82/10/08, 8210290047
- --8210290088 Public version of revised generating station emergency plan GALLE, D P Commonwealth Edison Co 82/08/12 43pp 15878 21B 24% Fiche 50-000,82/10/08.8210290047
- 8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs TRAMIS. I R Commonwealth Edison Co. 82/10/14 DENTON, H R. Off Of Nuclear Reactor Regulation. Director 9pp 15776-287 24X Fiche 50-000 82/10/14, 8210220358 Difice

G Adjudicatory correspondence

- 8210050371 Motion for clarification of portions of ASLB 820910 memorandum & order ruling on motions for summary disposition of certain contentions Certificate of Svc encl Related of certain convenients.

 correspondence
 BIELAWSKI, A P Commonwealth Edison Co BIELAWSKI, A P Isham,
 Lincoln & Deale 62/09/28 Atomic Safety and Licensing Board
 Panel 6pp 13608 225 24% Fiche 50-454, 82/09/28, 8210050391
- 8210040182 Confirms 820928 teleon, in which NRC withdrow Interrogatories 77-1 & 77-2 based on withdrawn Contention 70 Answers to remaining interrogatories due by 92/015

 RANSSIN:R J Hearing Branch 4 82/10/04 ROSE, B Cherry M

 //Cherry, Flynn & Kanter ROSE, B League of Women Voters of
 Rociford.RL 1p 156/4 120 24X Fiche 50-454,82/10/04,8210060162
- 8210070127 Motion for leave to file answers to util amended second round of interrugatories 1 day late
 ROSE, B. League of Women Voters of Rockford, IL. ROSE, B. Cherry, M.
 M. Zherry, Flynn & Kanter 82/10/05 Atomic Safety and Licensing
 Board Panel 2pp 15527 084 24X Fiche 50-454,82/10/05.8210070127
- --8210070129 Answers to amended second round of interrogatories Certificate of Svc encl ROSE:B League of Homen Voters of Rockford, IL ROSE,B Cherry, M M /Cherry, Flynn & Kanter 82/10/05 Commonwealth Edison Co 344pp 15627 086 24X Fiche 50-454.82/10/05,8210070127
- 8210130373 Response opposing Detail Area Alliance for Responsible elUlaudud Response opposing Details Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 800927 motion to reconsider summary disposition of Contention 1 on GA/GC New info would not change decision W/Certificate of Svc HILLER: M I Commonwealth Edison Co MILLER: M I Isham, Linco Miller: M I Commonwealth Edison Co MILLER: M I Isham, Linco Beale 82/10/08 Atomic Safety and Licensing Board Panel 15680 247 24X Fiche 50-454,82/10/08.8210130373 Isham, Lincoln &
- 8210130095 Response supporting applicant 820928 motion for clarification of portion of ASLB 820910 memorandum & order denying NRC & applicant motions for summary disposition Litigable issues should be delineate W/Certificate of Svc GDLDBERGS C Hearing Branch 4 82/10/12 Atomic Safety and Licensing Board Panel Spp 15673 110 24X Fichs 50-454,82/10/12,8210130095
- 62:0150097 Response opposing Dekalb Area Alliance for Responsible Enerou/Binnissippi Alliance for Environ 62:0923 motion for ition of summary disposition of Contention 1(h) new facts not allowed H/Certificate of Syc marine Respond 4 Deliver Atomic Eafety and Atomic Safety and 'X Fiche 50-454,82/10/12,

- 8210150190 Confirms 821012 & 13 telcons Ref to specific ensures to ctil interrogatories may be suitable response to NRC interrogatories deneral ref unresponsive NRC does not object interrogatories General for Universionality and Goes not object to extension to answer listed interrogatories RAHSON.R J Hearing Branch 4 82/10/13 ROSE.B Cherry. M M /Cherry, Flynn & Kanter ROSE.B League of Women Voters of Rockford, IL 1p 15707 261 24X Fiche 50-454,82/10/13,82101*01*0
- 8210180151 Forwards original verification of Rockford League of World Voters answers to util amended second round of roters answers to tril amendes second round of interrogatories Related correspondence ROSE. B. Cherry. M. M./Cherry. Flynn & Kanter B2/10/13 Docketing & Services Branch 2pp 15719 267 24X Fiche 30-454. B2/10/13, B210180151
- 8210180142 Forwards LA Bowen 821005 affidavit per ASLB 621012
 memorandum % order ruling on disclosure obligation Info
 provided re DeKalb Area Alliance for Responsible Energy/
 Sinnisisppi Alliance for Energy Contention 9a
 GALLO, J Isham, Lincoln & Reale GALLO, J Commonwealth Editon Ca
 62/10/14 MARGULIES H B , CALLIHAN, A D Atomic Safety and Licensing,
 Board Panel COLE, R F Atomic Safety and Licensing Appeal Panel
 2pp 15719 230 24X Fiche 50-454,82/10/14,8210180142
- -8210180144 Affidavit of LA Bowen Util does not intend to initiall terp sensors on feedwater bypass sys piping Existence of conitiant feedwater flow precludes water hammer event similar to event at Krsko
 BOWEN, L A Commonwealth Edison Co 24X Fiche 50-454,82/10/14.8210180142
- 8210180166 Confirming order canceling 821014 prehearing conference is Rockford, IL Discovery progress discussed during 821014 telcon MARGULIES,M B Atomic Safety and Licensing Board Panel 92/10/15 Ip 15719 168 24X Fiche 50-454,82/10/15,8210180166
- 8210180170 Grder granting Rockford League of Homen Voters motion for leave to file instanter answers to util amended second round of interrogatories i day late MARQULIES.M B Atomic Safety and Licensing Board Fanel 82/10/15
- 8210210274 Answers to first set of interrogatories, pursuant to ALP 821020 memorandum & order Verification & Proof of Svc encl Related correspondence

 JOHNSON, D. League of Momen Vaters of Rockford, IL 62/10/15

 Office of the Erecutive Legal Director 48pp 15766-130 24r

 Fiche 50-454, 82/10/15, 8210210274

Fiche 50-454, 82/10/15, 8210180170

- B210210278 Reply to amended first request for production of documents 210210278 Reply to amended first request for production of documents Proof of Svc encl Related correspondence ROSE, B League of Women Voters of Rockford, IL ROSE, D Cherry, M /Cherry, Flynn & Kanter 82/10/15 Office of the Esecutive Legal Director 3pp 15765 150 24x Fiche 50-454.82/10/15, 8210210278
- 8210210384 First interrogatories & request for documents Proof of bes encl Related correspondence ROSE: B Loague of Homen Voters of Rockford, IL ROSE: B Chirry M /Cherry, Flynn & Kanter 82/10/15 Commonwealth Editon Co 22pp 15764 016 24% Fiche 50-454.82/10/15.8210210384
- 8210210346 Motion for leave to file reply to new matters reject by applicant & NRC in response to Alliance motion to reconsider disposition of Contention I re GA & GC CASSEL, D W Defails Area Alliance for Responsible Energy CASSELL, D W Sinnissippi Alliance for the Environment IBAFE B2/10/18 Atomic Safety and Licensing Board Panel | p 15764 210. 24X Fiche 50-454,62/10/16.8210210346
- --8210210347 Reply to new matters raised by applicant & NRC in response to Alliance motion to reconsider summary disposition of Contention i re GA & GC Disposition should be denied since issues of math fact exist Certificate of Byc encl CASSEL.D W DeKalb Area Alliance for Responsible Energy CASSEL.D W Sinnissippi Alliance for the Environment (BAFE) 82/10/18 Atomic Safety and Licensing Board Panel 5pp 13764 211 24X Fiche 50-454,82/10/18.8210210346

. 1

- 8210250071 Corrects two typographical errors & minor misstatement in Rockford League of Homen Voters answers to NRC amended first set of interrogatories ROSE, B., ROBE, B. Cherry, M. M./Cherry, Flynn & Kanter 62/10/20 Docteting & Services Branch ip 15787 047 24X Fiche 50-454,82/10/20,8210250071
- 8210260380 Forwards author 821022 ltr to NRC transmitting first set of ROSE/SO FORWARDS BUTTON BEIOZE IEF TO DRG TRANSMITTING
 ROSE, B. Cherry, M. H. /Cherry, Flynn & Kanter ROSE, D.
 Homen Voters of Rockford, IL. 82/10/22 MARCKLIES, H. B.
 Safety and Licensing Board Panel 1p. 15804;205 24)
 Fiche 50-454, 82/10/22, 8210260380 ROSE, D. League of n B Atonic 24X

- --8210260384 Forwards proposed interrogatories & motion for production of documents

 ROSE, B Cherry, M M /Cherry, Flynn & Kanter ROSE, B Loaque of Homen Voters of Rockford, IL 82/10/22 GOLDBERG, S C Hearing Branch 4 lp 19804 206 24X Fiche 50-454, 82/10/22, 8210260300
- --8210260392 Proposed first set of interrogatories Proposed motion for production of documents by NRC & Proof of Svc encl 4 League of Homen Voters of Rockford. IL 82/10/22 Office of the Executive Legal Director Ropp 15804 207 24X Fiche 50-454,62/10/22.8210260380
- 3210270216 Notice of ASLB reconstitution TW Smith, chairman & AD Callihan & RF Cole, members LAZO.R M Atomic Safety and Licensing Board Panel 02/10/25 2pp 15823 006 24% Fiche 50-484,82/10/25 8210270216
- E210290305 Answers to NRC amended first set of interrogatories
 Certificate of Svc entl
 RDSE.B League of Nomen Voters of Rockford, IL 82/10/25 Dffile
 of the Executive Legal Director 15pp 15855 021 24X
 Fiche 50-454,82/10/25,8210290305
- 8210270273 Forwards original B Johnson verification for Rockford Leanur of Momen Voters answers to NRC amended first set of interrogatories on Contentions 37 & 107 Related correspondence ROSE, B Cherry, M /Cherry, Fiynn & Kenter ROSE, B League of Homen Voters of Rockford, IL 82/10/26 Docketing & Services Branch 2pp 15854 075 24X Fiche 50-454.82/10/26,8210270273
- E32(0280347 Response apposing Dekalb Area Alliance for Responsible Energy/Sinmissippi Alliance for Environ B21018 motion for leave to submit reply to MRC & util responses to intervenor B20723 motion for reconsideration M/Certificates of Svc GOLDERRO, S C Hearing Branch 4 B2/10/27 Atomic Safety and Lizensing Board Panel 5pp 15838 351 24X Fiche 50-454,82/10/27, B210280347
- 8210290105 Ack receipt of Rockford League of Women Voters proposed interrogatories to NRC & motion for production of documents NRC will shortly advise League of which interrogatories will be answered GOLDGERO, B C Hearing Branch 4 82/10/28 ROSE, B Cherry, N M /Cherry, Flynn & Manter ROSE, B League of Women Voters of Rockford, IL ip 15854 003 24% Fiche 50-454,82/10/28,82102901(15
- 14 General correspondence
- P210070174 Responds to B20929 ltr requesting NUREQ-0782 & OMNI-20 NUREG can be ordered from NRC Div of Technical Info & Decument Control BMI rept available from NI B CDLOBERG. S C Hearing Branch 4 B2/10/06 VON ZELLEN. B Northern Illinois Univ 1p 15634 262 24X Fiche 50-454, 62/10/06, 82/1070174
- M Utility Final Bafaty Analysis Report (FSAR) & amends
- \$2210040060 Forwards affidavit stating that distribution of FSAR Amend 39 has been made in accordance w/Encl 1 of NRC 781020 ltr TRAMM-TR Commonwealth Edison Co. 82/09/23 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 15583 191 24X Fiche 50-000, 82/09/23, 8210040060
- II Antitrust correspondence
- D210070180 Forwards.for review & comment.draft OL antitrust review finding of no significant change W/o encl VOOLER, B H Hearing Branch 2 B2/10/06 CUTLER, M Justice.Dept of 1p 15694 297 24X Fiche 50-454.82/10/06, B210070180
- Q Inspection reports, IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-12h Implant Seeds " Svc list encl. COBB-L. I Division of Fuel Facilities, Materials & Safeguards 82/10/05 Consolidated Editarn Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06,8208190233
- 8208170238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Mall:Large-Dlameter:Stainless Steel, Recirculation Sys Figing at BHR Plants "Syc list encl BEYBUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 165pp 15810 125 24x Fiche 50-000, 82/10/14,8208170238

- 8210260387 Confirms 821026 Meeting at Region 3 ofc to discuss util response to IE Insp Repts 50-454/82-05 & 50-455/82-04 SPESBARD.R L Division of Project & Resident Programs 82/10/19 REED.C Commonwealth Edisson Co 1p 15803 105 24X Fiche 50-454, 82/10/19,8210260387
- DOCKET STN-50-456 BRAIDWOOD STATION. UNIT 1
- A Application/construction stage documents & correspondence
- 8210010202 Submits addi info re reactor coolant pump locked rotor & shart break transients at facilities info closes Confirmatory Issue 34 of Byron SER TRAMM. T.R. Commonwealth Edison Co. 82/09/22 DENTUN. H.R. Office of Nuclear Reactor Regulation, Director 4pp 15568 073 24% Fiche 50-000, 82/09/22, 8210010202
- 8210010271 Forwards five oversized P&IDs referred to in util 820400 ltr to NRC re waterhammer prevention Aperture cards are available in FDR
 TRAMM.TR Commonwealth Edison Co. 82/09/22 DENION.RR Office of Nuclear Reactor Regulation. Director 2pp 18873 122 247
 Fiche 50-000, 82/09/22, 8210010271
- 8210050073 Application for enend to CPPR-132 & CPPR-133. revising completion dates to 870430 & 880430, respectively DELGEOROE, L.D. Commonwealth Edison Co. 82/07/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 15603 1811 24% Fiche 50-456.82/09/30.8210050073
- --8210050077 EIA supporting request for extension of dates for completion of const of units extending Unit 1 to 870430 & Unit 2 to 880430 # Commonwealth Edison Co 82/09/30 &pp 15603 183 24X Fichs 50-454,82/09/30,82(0050073
- 8210280429 Forwards addit question re vol control sys.in response to applicant answer to NRC Guestion GD21 43 Response requested within 30 days
 YQUNOBLOOD.D J Licensing Branch 1 82/10/04 DELGEORGE.L O Commonwealth Edison Co. 3pp 15840 042 24X Fiche 50-000.82/10/04.8210280429
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" GOLDEN, J C Commonwealth Edison Co 82/10/06 CASE, E 0 Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000, 82/10/06, 8210260526
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" # Commonwealth Edison Co 82/09/30 839p 15805 139 24X Fiche 50-000,82/10/06,8210260526
- 8210280420 Forwards request for add) info re venting of high points in RCB, method of depressurization to cold shutdown & depressurization following steam generator tube rupture events Response requested within 30 days YGUNOBLOOD, B J Licensing Branch 1 82/10/07 DELGEORGE, L O Commonwealth Edison Go App 15860 007 24X Fiche 50-000, 82/10/0/, 8210280420
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 821025010B Forwards revised FSAR info re protection against possible turbine missiles Revisions to turbine missile analysis rept encl Info closes out SER Untstanding Item 2
 FRAMM.TR Commonwealth Edison Co. 82/10/19 DENTON, H.R. Defire of Nuclear Reactor Regulation, Director 15pp 15789 296
 Fiche 50-000, 82/10/19,8210250108
- F Security, medical, emergency & fire protection plans
- 8210290363 Forwards list of deviations from Chemical Engineering Branch Technical Position 9 5 1 re fire protection program Deviations listed include lighting & communication & hydrogen line routing Justification of deviations requested YOUNOBLOOD, B J Licensing Branch | 82/10/05 DELGEDROE, L O Commonwealth Edison Co 7pp 15865 240 24X Fiche 50-000, 82/10/05, 82/10270363
- B210130376 Advises that installation of offsite dose calculation sysprogram fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation
 SMARTZ.E D Commonwealth Edison Co 82/10/06 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15682.098 24X
 Fiche 50-000, 82/10/06,8210130376

821022035B Provides info re organization & performance of depts responsible for radiation protection activities.per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs TRAMM.T R Commonwealth Edison Co 82/10/14 DENYON.H R Office of Nuclear Reactor Regulation, Director 9pp 15776-287 24X Fichs 50-000.82/10/14.821022035B

G Adjudicatory correspondence

- 8210050259 Green directing all parties to file complete status repts w/ASLB Repts should contain present status of application, documents filed by NRC or util, const plans & future projections & basis for scheduling projections MILLER.M E Atomic Safety and Licensing Board Panel 82/10/01 Commonwealth Edison Co 1p 15610 290 24X Fiche 50-456.82/10/01, 8210050259
- 8210250211 Status rept on plants in response to ASLB 821001 order Unit 1 scheduled for futil load on 850430 & Unit 2 on 860430 Dates will be confirmed or revised in Jan 1983 Certificate of Svc enci MILLER, M J Commonwealth Edison Co MILLER, M J isham, Lincoln & Beale 82/10/19 5pp 15768 242 24X Fiche 50-456, 82/10/19, 8210250211
- 8210220453 Response to ALSB 821001 order to file status rept on plant Schedule for Issuance of NRC documents & considerations to be used in developing prehearing & hearing schedule listed Notice of appearance & Certificate of Svc encl HASSELL.D F Hearing Branch 1 82/10/20 13pp 15778 325 24x Fiche 50-456,82/10/20,8210220453

K Utility Final Safety Analysis Report (FSAR) & amends

- 6210040060 Forwards affidavit stating that distribution of FSAR Amend 39 has been made in accordance w/Encl 1 of NRC 781020 ltr TRAMM.T R Commonwealth Edison Co 92/09/23 DENTON.H R Defice of Nuclear Reactor Regulation, Director 2pp 15383 191 24% Fiche 50-000.82/09/23, 8210040060
- O inspection reports. IE Bulletins & correspondence
- 8210040230 Act receipt of 820817 ltr informing NAC of steps taken to correct violations noted in IE Insp Repts 50-455/82-01 & 50-457/82-01 Denies request to withdraw Violation I Concurs that Violation 2 does not constitute noncompliance NARELIUS.C E Division of Engineering & Technical Programs 82/09/27 REED.C Commonwealth Edison Co 2pp 15586 114 24X Fiche 50-456. 82/09/27, 8210040230
- --8210040246 Responds to NRC 820707 ltr re violations noted in 1E 1116p Repts 50-456/82-01 & 50-457/82-01 Disputes Violations 1 & 2 Post-tensioning sequence adequately controlled Corrective action re Comstock nonconformance repts taken DELGEORGE, L. D. Commonwealth Edison Co. 82/08/17 KEPPLUR, J. G. Region 3, Office of Director 9pp. 15586 116 24X Fiche 50-456, 82/09/27, 8210040230
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implent Seeds " Svc list encl CDBS.L 1 Division of Fuel Facilities. Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYDUNG, R C Director's Office, Diffice of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238

's & related correspondence

re breakdown of GA procedures
ifety-related mechanical
702 All affected
rent Procedure GCP-B22
B2/10/08 KEPPLER, J O Region
'1 24X Fichs 50-456, 82/10/08,

069 sufety-

8910h 0/13.

- DOCKET STN-50~457 BRAIDWOOD STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210010202 Submits addl info re reactor coolant pump locked rotor k shaft break transients at facilities info closes Confirmatory Issue 34 of Byron SER TRAHM.T R Commonwealth Edison Co 82/09/22 DENTUN.H R Office of Nuclear Reactor Regulation, Director 4pp 15568 073 241 Fiche 50-000.82/09/22.8210010202
- 82100:0271 Forwards five oversized P&IDs referred to in util 02090/ 1: to NRC re waterhammer prevention Aperture cards are available in PDR
 TRAMM.T R Commonwealth Edison Co 82/09/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 15573 122 24x
 Fiche 50-000.82/09/22.8210010271
- B210050073 Application for amend to CPPR-132 & CPPR-133, revising completion dates to 870430 & 880430, respectively DELOEDROE, L.O. Commonwealth Edison Co. 82/07/30 DENION, H.R. Office of Nuclear Reactor Regulation, Director 2pp (8801 841 24X Fiche 50-454, 82/07/30, 8210050073
- --8210050077 EIA supporting request for extension of dates for complete of const of units extending Unit 1 to 870430 & Unit 2 to 880430

 ** Commonwealth Edison Co 82/09/30 2pp 15603 183 24x Fiche 50-456,82/09/30.8210050073
- 8210280429 Forwards add1 question re vol control sys.in response to applicant answer to NRC Question Q321 43 Response requested within 30 days YOUNOBLODD. B J Licensing Branch i 82/10/04 DELQEORGE, L O Commonwealth Edison Co 3pp 15860 042 24X Fiche 50-800.82/10/04
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" GGLDEN.J C Commonwealth Edison Co 82/10/06 CASE,C Q (Iffice ex Nuclear Reactor Regulation, Director 2pp 15805-137 24x Fiche 50-000,82/10/06
- --8210260542 Revision 3 of Chapter 7 of "Offsite Dose Calculation Hanual" • Commonwealth Edison Co 82/09/30 83pp 15805 139 24r Fiche 50-000,82/10/06.8210260326
- 8210280420 Forwards request for add1 info re venting of high possits is a RCS, method of depressurization to cold shutdown & depressurization following steam generator tube rupture is avents. Response requested within 30 days YOUNGBLOOD, B J Licensing Branch I B2/10/07 DELCEORGE, L D Commonwealth Edison Co. 4pp 15860 009 24% Fiche 30-000, 02/12:01 8210280420
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8210250108 Forwards revised FBAR info re protection against postable turbine missiles Revisions to turbine missile analysis rept enc! Info closes out BER Outstanding Item 2
 TRAMM.T R Commonwealth Edison Co 82/10/19 DENTEN.IF R Office of Nuclear Reactor Regulation, Director 15pp 15787 276 24x Fiche 50-000.82/10/19.8210250108
- F Security, medical, emergency & fire protection plans
- 6210290363 Forwards list of deviations from Chemical Engineering Branch Technical Position 9 5 1 re fire protection program Deviations listed include lighting & communication & hydrogen line routing Justification of deviations requested YOUNCHLOOD, B J Licensing Branch 1 82/10/05 DELGEOROS, L O Commonwealth Edison Co 7pp 15865 240 24X Fiche 50-000, 82/10/05
- B210130376 Advises that installation of offsite dose calculation squ program fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation SWARTZ.E D Commonwealth Edison Co 82/10/06 DENTON.N R Office of Nuclear Reactor Regulation, Director 2pp 15682 090 24x Fiche 50-000/82/10/06/8210130376
- 8210220338 Provides info re organization & performance of depte responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs

 TRANM, TR Commonwealth Edison Co 82/10/14 DENTON, NR Office of Nuclear Reactor Regulation, Director 9pp 15776 287 248 Fiche 50-000, 82/10/14, 8210220358

DOCKETED ITEMS

Adjudicatory correspondence

- 8210050259 Order directing all parties to file complete status repts W/ASLB Repts should contain present status of application, decuments filed by NRC or wtil, const plans & future projections & basis for scheduling projections
 MILLER, H E Atomic Safety and Licensing Board Panel 82/10/01
 Commonwealth Edison Co ip 15610 290 24X Fiche 50-456,82/10/01,82(0050259
- 8210250211 Status rept on plants in response to ASLB 821001 order. Unit 1 scheduled for fuel load on 850430 & Unit 2 on 860430 Dates will be confirmed or revised in Jan 1983 Certificate of Svc encl HILLER, N J Communwealth Edison Co MILLER, N J Isham, Lincoln & Beals 82/10/19 5pp 15788 242 24X Fiche 50-456, 82/10/19, 82(0250211
- ₽210220453 Response to ALSB 821001 order to file status rept on plant Schedule for issuance of NRC documents & considerations to be used in developing prehearing bearing schedule listed Notice of appearance & Certificate of Svc encl MASSELL.D F Hearing Dranch i 82/10/20 13pp 15778 325 24y Fiche 50-456.82/10/20.8210220453
- M Utility Final Safety Analysis Report (FSAR) & amends
- ### B210040050 Forwards affidavit stating that distribution of FSAR Amend
 39 has been made in accordance w/Encl I of NRC 781020 ltr
 IRAMH, T R Commonwealth Edison Co 82/09/23 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 2pp 24X
 Fiche 50-000, 82/09/23, 8210040050
- Q Inspection reports, IE Builetins & correspondence
- 8210040230 Ack receipt of 820B17 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/82-01 & 50-457/82-01 Denies request to withdraw Violation I Concurs that Violation 2 does not constitute noncompliance NONELIUS, C E Division of Engineering & Technical Programs 82/09/27 REED, C Commonwealth Edison Co 2pp 15586 li4 24X Fiche 50-456/82/09/27.8210040230
- --821004024& Responds to NRC 820707 ltr re violations noted in IL Insp. Repts 50-456/82-01 & 50-457/82-01 Disputes Violations 1 & 2 Post-tensioning sequence adequately controlled Corrective action re Comstock nonconformance repts taken DELOEOROE, L. Q. Commonwealth Edison Co. 82/08/17 KEPPLER, J. G. Region 3. Office of Director 7pp 15586 116 24X Fichs 50-456, 82/09/27, 8210040830
- 8203;90233 lE info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Speds " Syc list encl COBD, L I Division of Fuel Factificies, Materials & Safeguards 62/10/06 Cansolidated Edison Co of New York 64pp 15761 250 24% Fiche 50-000,82/10/06,8208190233
- B208190238 IE Bulletin B2-03. "Stress Corresion Cracking in Thick-Hali, Large-Diameter: Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list enc! DEYGUNO.R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 1159p 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- S. Reportable occurrences. LERs & related correspondence
- 8210040249 Deficiency Rept B2-06 re containment post-tensioning bushing thread failure Initially reported on 820820 Caused by undersize major thread diameter of bushing Thread measurements will be verified before stressing TRAMM: T R Commonwealth Edison Co 82/09/23 KEPPLER. J 0 Region 3. Office of Director 2pp 15581 358 24% Fiche 50-457.82/09/23, 8210040247
- E210190299 Interim deficiency rept re breakdown of QA procedures concerning control of erection of safety-related mechanical equipment Initially reported on 820902 All affected squipment will be rechecked using current Procedure GCP-B22 TRAMLTR Commonwealth Edison Co 82/10/08 KEPPLER, J Q Region 3. Office of Director 7pp 15742 161 24X Fiche 50-456,82/10/08,8210190299
- 9210190662 Interim deficiency rept re untimely reinsp of 3,069 safety-related pipe hanger welds Initially reported on 820908
 Contractor will inspect hanger supports installed before
 June 1981 prior to fuel load
 IRAMNIT & Commonwealth Edison Co 82/10/13 KEPPLER, J 0 Region
 3, Office of Director 2pp 15739 092 24X Fiche 50-456,82/10/13,8210190662

- DOCKET 50-458 RIVER BEND STATION. UNIT :

 K Utility Final Safety Analysis Report (FSAR) & amends
- 8210040215 Forwards Amend 6 to FSAR.consisting of "Failure Modes & Effects Analysis " Certificate of Svc encl CAHILLN J Oulf States Utilities Co 82/09/27 EISENHUT, D G Division of Licensing 4pp 15587 263 24X Fishe 50-458.82/09/27, 8210040215
- --8210040220 Amend & to FSAR * Gulf States Utilities Co 82/09/30 480pp 15587 267 e/4). Fiche 50-458.82/09/27,8210040215
- Q Inspection reports. IE Bulletins & correspondence
- 8210050387 Forwards IE Insp Rept 50-458/62-10 on 820623-27 No noncompliance noted MADSEN.G L Division of Resident. Reactor Project & Engineering Programs 82/09/20 CAMILL.W J Gulf States Utilities Co 214 15603 008 24X Fiche 50-458.62/09/20.6210050387
- --8210050399 IE Insp Rept 50-458/82-10 on 820823-27 No noncompliance noted Major areas inspected previous insp findings, site tour, observation of work & review of records for welding & nondestructive exam of safety-related piping OILBERT.L D . CROSSMAN, W A . HUNNICUTT.D M Division of Resident, Reactor Project & Engineering Programs 62/09/14 4pp 15603 010 24X Fiche 50-458,82/09/20,8210050387
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking % Dislodged ! L.", Implant Seeds " Svc list oncl COBB.L ! Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 2°,0 24X Fithe 50-000, 82/10/06, 8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Syc list encl DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208170238
- S Reportable occurrences. LERs & related correspondence
- B210050201 Interim Deficiency Rept DR-71 re QA program inconsistencies in mfg of personnel air locks Initially reported on 820827 Investigation not yet complete Next rept expected by 430115 BOOKER, J E Quif States Utilities Co 62/09/27 COLLINS, J T Region 4. Office of Director ip 15609 294 24X Fiche 50-450, 62/09/27, 6210050201
- 8210050350 Interim deficiency rept re defective math used in coupling drive element of Transamerica Delaval standby dieset/ generators Initially reported on 820827 Final rept will be provided by 821027 Also reported per Part 21 800KER, J E Guif States Utilities Co 82/09/27 COLLING, J T Region 4, Office of Director ip 15608 254 24X Fiche 50-458,82/09/27,0210050350
- 8210050219 Final deficiency rept re indications found on shop radiographs of containment penetration bellows Initially reported on 820603 investigation determined no reportable deficiency exists

 BODKER, J E Oulf States Utilities Co 82/09/29 COLLING, J T Region 4, Office of Director ip 15611 245 24X

 Fiche 50-458,82/09/29,8210050219
- 8210050317 Interim deficiency rept re improper installation (torquing) & insp of frilled-in expension-type anchors Initially reported on 820830 Investigation continuing Final status rept will be provided by 821115
 BOOKER, J E Quif States Utilities Co 82/09/29 COLLING, J T Region 4, Office of Director ip 15401 357 24X
 Fiche 50-458, 82/09/29, 8210050317.
- 8210130516 Interim deficiency rept re unsatisfactory insp performed by former field QC inspector initially reported on 820327 Re-evaluation of insp continuing Next rept to be provided by 821027 BOOKER, J E Oulf States Utilities Co 82/09/30 COLLING, J T Region 4. Office of Director ip 15683 109 24X Fiche 50-458, 82/09/30, 8210130516
- 8210130182 Interim Deficiency Rept 73 re improperly instailed spring nots in OE supplied power generation control complex termination cabinets Initially reported on 820902 Investigation continuing Next rept expected by 830121 BODKER, J E Oulf States Utilities Co 82/10/03 COLLINS, J T Region 4, Office of Director ip 19673 012 24X Fiche 50-458, 82/10/05, 8210130182

- 8210190518 Final deficiency rept re weld surface imperfections in Graver shop weld for containment personnel airlock Initially reported on 820702 Imperfections do not affect safe plant operation Deficiency not reportable per 10CFR0S0 55e BOOXER. J E Gulf States Utilities Co 82/10/06 COLLING. J T Region 4. Office of Director 19 15751 243 24x Fiche 50-458.82/10/06.8210190518
- 8210190367 Interin Deficiency Rept DR-65 re cracking & spailing of surface concrete around penetrations Initially reported on 820806 Investigation continuing Next rept will be provided by 821203 UGGVER. J & Gulf States Utilities Co 82/10/07 COLLINS. J Region 4. Office of Director 1p 15742 101 24X Fiche 50-458, 82/10/07.8210190367
- 8210190529 Interim Deficiency Rept FR~74 re incorrect installation of I/A-inch drilled in expansion type anchor bolts used to support emergency lighting battery unit Initially reported on 920830 investigation incomplete Final rept due by 830128 BODKER, J E Gulf States Utilities Co 82/10/08 COLLING, J I Region 4, Office of Director tp \$5740 034 24x Fiche 50-458.82/10/08.8210170629
- U210250118 Final Deficiency Rept DR-63 ie use of improper stud mail in valve fabrication Initially reported on 820029 Studs being replaced w/special mail Condition not reportable per 1007650 55:e)
 BOOKER, J. E. Gulf States Utilities Co. 82/10/12 COLLINS, J. F. Region 4. Office of Director 1p. 15787 018 24% Fishe 50-458 82/10/12.8210250118
- B210260272 Final Deficiency Rept DR-46 re improperly retained rod end bushings that may disengage from Bergen Paterson shubber & sway strut assemblies Initially reported on B20426 Generic part number changed on B1 drawings for riser clamps BOCKER.1 E Gulf States Utilities Co B2/10/14 COLLINS.J { Region 4. Office of Director 3pp 15801 355 24% Fiche 50~458.82/10/14.8210260292
- 8210260286 Interim Deliciency Rept DR-75 re error found in GHDSH computer program used in reactor blig hydrodynamic analysis initially reported on 920921 Investigation to determine significance of error continuing Next rept by 830114 BODKER, J.E. Quif States Utilities Co. 92/10/15 COLLINS, J. Region 4, Office of Director 1p. 15803-217 24% Fichs 50-458, 82/10/15.8P10260286
- COCKET 50-459 RIVER BEND STATEON, UNIT 2
- k Utility Final Safety Analysis Report (FSAR) & amends
- 8210040215 Forwards Amend 6 to FSAR consisting of "Failure Modes & Effects Analysis " Certificate of Byr encl CAMICLA J Gulf States Utilities Co 82/09/27 EISENHUT, D C Division of Licensing 4pp 15587 263 24% Fiche 50-458
- --8210040220 Amend & to FSAR

 " Gulf States Utilities Co 82/09/30 480pp 15587 267 24X
 Fiche 50-438.82/09/27.8210040215
- a Inspection reports. IE Bulletins & correspondence

- DOCKET 50-460 MPPSS NUCLEAR PROJECT, UNIT 1

 A Application/construction stage documents & correspondence
- 8210220511 Forwards WPPSS 820825 & 0909 & CPC 820812 ltrs re BEH owners group 820720 meeting w/NRC re resolution of NUREO-0737. Item II K 3 30 on small break LOCA methods Appropriate action should be taken ADENSAM.E O Licensing Branch 4 82/10/04 SHERON, B H Reactor Systems Branch ip 15786 091 24X Fiche 50-000, 82/10/09 82102/091
- 8210290446 Staff requirements memo re B21007 affilmation/discussors vote on extension of const completion dates for MPPSG, purging of classified math in ALAB-653 & emergency preparedness & risks associated w/fuel loading CHILK.5 J Dffice of the Secretary of the Commission 112/10/69 Uffice of the Secretary of the Commission 2pp 15063 [89] .4r Fiche 50-000.82/10/08.8210290446
- G Adjudicatory correspondence
- S210040016 Response to Coalition for Safe Power 820710 request for hearing D petition to intervene Current petition does not satisfy requirements Contention must be submitted Winotice or appearance & Certificate of Svc.
 YOUNGN A Hearing Branch 4 82/09/30 Atomic Safety and Licensing Board Panel 12pp 15581 316 24X Fishe 50-460.02/6/11
- 82(0130336 Order CLI-B2-29, referring Coalition for Safe Power petiti , for hearing to ASLB ASLB chairman should appoint ASLB to determine whether 10CFR2 714 requirements met & to conduct required hearing M/separate views of Commissioner Ollinsiy CHIKKS J Office of the Secretary of the Commission O/10/488 21pp 15681 350 24K Fiche 50-397, 82/10/20, 8210130336
- 8210150480 Memorandum & order granting Coalition for Safe Power les i to amend petition to intervene per order, within 15 days after svc Util complete answer to original & amended petition due within 10 days after amended petition served SMITH, I W. Atomic Safety and Licensing Board Panel B2/10/1; Coalition for Safe Power Topp 15702 001 24x Fichs 50-460,82/10/13,8210150480
- B210200056 Notice of ASLB constitution H Grossman.chairman & Et (111) & LN Little.members COTTER.B P Atomic Safety and Licensing Board Panel (02/10/14 2pp 19755 027 24% Fiche 50-397.82/10/14.8210200056
- B210180147 Lists changes to be made in Commission 021000 Order. CLI-82-29 STUCKY,S W Docketing & Services Branch B2/10/15 Office of the Executive Legal Director Ip 19719 266 24X Fiche 58 397. B2/10/15.8210180147
- 821027018! Notice of ASLB reconstitution H Grossman.chairman h (a) Bright & J Harbour.members LAZO.RM Atomic Safety and Licensing Board Panel (12/10/25), 15629 315 24X Fiche 50-460.82/10/25,8210270181
- 8210270315 Natice of ASLB reconstitution H Grossman, chairman b GO Beight & J Harbour, members LAZO.R M Atomic Safety and Licensing Board Panol B2/10/27 -19 15853 078 24% Fiche 50-397, 82/10/25, 8210290315
- 4 Inspection reports, IC Bulletins & correspondence
- 8210070378 Ack receipt of 820909 ltr informing NRC of steps taken to correct violations noted in insp on 820501-28
 STERNUERG,D M Division of Resident, Reactor Project & Engineeriagropams 82/10/04 R001,R W Mashington Public Power Supply System 1p 15634 017 24X Fichs 50-460, 82/10/04.0210070378
- ~-8210070387 Responds to NRC 820624 ltr re violations noted in it 10.3.
 820501-28 Corrective actions subcontractor procedures for
 installation of electrical penetration assemblies submitted
 by approved by engineer
 ROOT:R Washington Public Power Supply System 82/07/07
 BISHOP:T W Division of Resident: Reactor Project & Engineering
 Programs App 15634 018 24X Fiche 50~460.82/10/04.82100/03/3
- 8208190233 (E Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1 12 Inplant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safguaria 82/10/06 Consolidated Edison Co of New York 66pp 157al 2-5 24% Fiche 50-000, 82/10/06, 8208190233

- B210130415 Ack receipt of B20709 & 30 ltrs informing NRC of steps taken to correct violations noted in IE insp on B20401-30
 SIERNBERG,D M Division of Resident. Reactor Project & Engineering Programs B2/10/06 ROUTER Washington Public Power Supply System ip 15681 319 24X Fiche 50~460,82/10/06,82/10/30415
- --8210130425 Updates response to NRC 820608 ltr re violations noted in IE insp on 820401-30 Corrective actions local grinding to expose weld root performed on four welds Cause of undersized welds due to improperly prepared weld bevels ROOT.R W Hashington Public Power Supply System 82/09/30 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs Spp 15681 320 24% Fiche 50-460.62/10/06.82101J0415
- --B210130432 Responds to NRC B20408 ltr re violations noted in lt into on B20401-30 Corrective actions local grinding conducted to expose weld root b base metal surfaces Partial penetration butt weld underslied BOOT, R W Washington Public Power Supply System 82/09/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 7pp 15481-325 24X Flohe 50-440.82/10/06,82/10/30415
- 3208190238 IE Bulletin 02-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys-Ploing at 8WR Plants "Syc list encl DEVOLUNG, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000, 82/10/14, 8208190238
- 3210280185 Ack receipt of 821012 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-460/82-08 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/10/22 RG0Tr. W Washington Public Power Supply System 1p 15837 006 24X Fiche 50-460, 82/10/22,8210280185
- --8210280190 Responds to NRC 820607 itr re-violations noted in It Insp. Rept 50-460/82-08 Corrective actions const package systemitiated to track work operations in field 4 craft personnel instructed to perform work per package system ROOT, R W. Mashington Public Power Supply System 82/10/12 STERNBERO, D.M. Division of Resident, Reactor Project & Engineering Programs 4pp 15837 007 24X Fiche 50-460,82/10/22,8210280185
- 3210280286 Act receipt of 821012 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Rept 50-460/82-07 STERNBERO, D H Division of Resident, Reactor Project & Engineering Programs 82/10/22 ROOT.R W Washington Public Power Supply System 1p 15845 194 24X Fiche 50-460, 82/10/22,8210280286
- --8210280297 Responds to NRC B20B04 ltr re violations noted in II Insp.
 Rept 50-460/82-07 Corrective actions GCRFI sys deleted &
 insp repts will be written when question as to validity/
 accuracy of requirements of item occurs
 ROOT, R W Washington Public Power Bupply Bystem 62/10/12
 STERNDERGO D M Division of Resident, Reactor Project & Engineering
 Programs 3pp 1845 175 24X Fiche 50-440, 62/10/22, 6210280284
- S Reportable occurrences, LERs & related correspondence
- B210D7033B InterIm deficiency rept re emergency diesel generator governor lube oil cooler initially reported on B20126 Lube oil cooler will be moved to elevation below oil level per Transamerica Delaval instructions & drawings ROOT, R W Hashington Public Power Supply System B2/09/15 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 2pp 15634 071 24X Fiche 50-460,82/09/15,8210070338
- B210070297 Interim deficiency rept re unsuitability of isoprene mathused in governor drive coupling elements Initially reported on 820819 Field change notice issued to implement changeout of element mathus neoprene Also reported per Part 21 ROOT, R W Mashington Public Power Supply Bystem 82/09/20 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 2pp 15634 178 24X Fiche 50-460.82/09/20.8210070R97
- 82:00703:1 Interim deficiency rept re use of lumped mass loads in performance of pipe stress analysis Initially reported on 820305 Paremetric studies may resolve trivial mass changes interim status repts will be provided on semiannual basis ROOTAR H Washington Public Power Supply System 82/09/20 STERNBERG.D H Division of Resident, Reactor Project & Engineering Programs Spp. 15634 145 24X Fiche 50-460,82/09/20,8210070311

- DOCKET 50-46: CLINTON POWER STATION. UNIT 1
- A Application/construction stage documents & correspondence
- B209290072 Forwards 581 oversize electrical, instrumentation & control drawings, identified in Table (7-1 of FSAR Aperture cards are available in PDR
 HULLER, O E Illinois Power Co B2/09/20 THOMAS, C O
 Standardization & Special Projects Branch lp 15540 196 24X
 Fiche 50-461, B2/09/20, B209290072
- B210050460 Requests add1 info re 820722 submittal on meteorological measurements sys.data acquisition & assessment scheme for emergency plan & 81016 submittal on hydrogen ignition sys Schedule for responding to questions requested within 2 wis THOMAS.C O Standardization & Special Projects Granch 62/09/2/HULLER.C [1]inois Power Cu 7pp 15626 250 24X fiche 50-461.82/09/22.8210050460
- 8210040104 Responds to 820326 request for add1 info re hydrodynamic water hammer analysis of control rod drive sys HULLER: 0 E []linois Power Co 62/09/24 THOMAS: C 0 Standardization & Special Projects Branch 3pp 15580 351 *'4% Fiche 50-461,82/09/24.8210040104
- 8210040070 Disapproves 820920 request for concurrence re partial lift of Stop Work Order 016 re electrical conduit installation Matrix of commitments & completion status for each item required SPESSARD, R L. Division of Project & Resident Programs 82/09/27 OERSTNER, W C. 11linois Power Co. 2pp. 15581 278 24x Fiche 50-461.82/09/27.8210040070
- B210130490 Advises that response to Questions 810 57.810 58 & 810 59 of NRC 820922 litrine degraded core hydrogen control & emergenty plan dose assessment reporting sys will be provided via FSAR amend by B21130 MULLER.C E Illinois Power Co 82/10/08 THOMAS.C O Standardization & Special Projects Branch in 15682 169 247 Fiche 50-441.82/10/08.8210130490
- 8210130325 Provides quarterly update re const schedule Fuel loading & commercial operation projected for Jan & Aug 1984, respectively KOCH.L J Illinois Power Co 82/10/11 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 15678 281 24X Fiche 50-46182/10/11.8210130325
- 8210]50357 Provides schedule for submitting add1 info for NRC review of hydrogen ignition sys/in response to NRC 820922 questions re degraded core hydrogen control & emergency plan dose assessment rept sys Questions will be addressed by 83010; WULER, G E Illinois Power Co 82/10/11 THOMAS, C O Standardization & Special Projects Branch ip 15704 317 ,24X Fiche 50-461,82/10/11.8210]50357
- 8210280340 Responds to 820902 questions re ECCS NRC review of util info on Humphrey concerns will be reported in SER suppl No further concern over Kuo Sheng incident warranted re Contention 10 Portions of ACRS transcript entl GODDARD.R J Hearing Branch 3 82/10/15 WILLMAN.F L 1111NO State of 24pp 15036 327 24X Fiche 50-461,62/10/15.82102803
- 8210260204 Confirms 821006 discussion w/util & LL? immited resumption of work, per 820901 confirmat itr Concurrence assumes that listed changes wil implemented prior to conducting nondestruct; KEPFLER, J. Q. Region 3, Office of Directo Illinois Power Co 821026---
- 8210280213 Provides initial response to 820901 confirmatory action itre course of action in progress to assure that facility will be constructed in accordance w/FSAR Viewgraph of facility project update and HALL-D P Ilinois Power Co 82/10/20 KEPPLER, J Q Region 3, Office of Director 43pp 15838 258 24X Fiche 50-461,82/10/20,8210280213
- 8210280089 Forwards operability analyses to demonstrate capability of containment vent/purge butterfly isolation valves to function as designed info resolves TM1 Action Item 11 E 4 2(6) & SER Outstanding Issue 100 MULLER.0 E 111inols Power Co 82/10/22 THOMAS, C 0 Standardization & Special Projects Dranch 369pp 15843 088 24X Fiche 50-461,82/10/22,8210280089

- E NRC Bafety Evaluation Report (SER), supply & correspondence
- 8210050278 Requests incorporation of Licensing Review Group 11 program re channel box deflection concern into future suppl to SER, superseding SER Section 4 2 3 13 info MULLER.0 E lilinois Power Co 82/09/28 THOMAS.C 0 Standardization & Special Projects Branch 2pp 15611 187 24X Firhe 50-461, 82/09/28.8210050278
- B2100502B9 Confirms commitment to revise emergency operating procedure, to address common vessel ref level for fuel ione level meter Info should close out SER Confirmatory item 39 WULLER, O E Illinois Pover Co 82/09/28 THOMAS, C O Standardization & Special Projects Branch 1p 15609 084 24X Fiche 50-461, 82/09/28, 8210050289
- 8210050281 Forwards Sargent & Lundy analysis of feedwater check valves Analysis indicates that feedwater check valve will withstand worst case loadings w/o losing pressure boundary integrity Info should close out SER issue
 HULLER.O E Illinois Power Co 82/09/30 THOMAS.C D
 Standardization & Special Projects Branch 7pp 15609 179 24X
 Fiche 50-461,82/09/30.8210050281
- 8210280089 Forwards operability analyses to demonstrate capability of containment vent/purge butterfly isolation valves to function as designed info resolves FMI Action Item If E 4 2(6) & SER Clutstanding Issue IOa HULLER, G E Illinois Power Co 82/10/22 THOMAS, C O Standardization & Special Projects Branch 369pp 15843 088 24X Fiche 30-461, 62/10/22, 8210280089
- F Security, medical, emergency & fire protection plans
- 8210050460 Requests add1 info re 820722 submittal on meteorological measurements sys.data acquisition & assessment scheme for emergency plan & 816016 submittal on hydrogen ignition sys Schedule for responding to questions requested within 2 wks THOMASIC O Standardization & Special Projects Branch 82/09/22 HULLER, O Illinois Power Co 7pp 15626 250 24% Fiche 80-461.82/09/22,8210050460
- 8210130470 Forwards Revision 4 to physical security plan Revision withheld (ref 10CFR2 790) KOCH-L J Illinois Power Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 15682 160 24X Fiche 50-461, 82/09/30, 8210130470
- 8210130490 Advises that response to Questions 810 57,810 58 & 810 59 of NRC 820922 ltr re degraded core hydrogen control & emergency plan dose assessment reporting sys will be provided via FSAR amend by 821130 HULLER, 0 E Illinois Power Co 82/10/08 THOMAS, C O Standardization & Special Projects Branch ip 15682, 169 24X Fiche 50-461, 82/10/08, 8210130490
- 8210150357 Provides schedule for submitting add1 info for NRC review of hydrogen ignition sys.in response to NRC 820922 questions re degraded core hydrogen control & emergency plan dose assessment rept sys Questions will be addressed by 830101 WULLER.0 E Illinois Power Co 82/10/11 THOMAS.C O 8tandardilation & Special Projects Branch ip 18704 317 24X Fiche 50-461.82/10/11.8210150357

.

- Q Inspection reports, IE Bulletins & correspondence
- B210130547 Forwards IE Investigation Rept 50~461/82-02 on 820105 52.5 KEPPLER, J G Region J. Office of Director 82/08/04 CERSTALA, MI Illinois Power Co 2pp 15683 307 24X Fiche 50-461, 62/08/04, 8210130547
- --8210130557 IE Investigation Rept 50-461/82-02 on 820105-0303 Figure violations noted in GA program for safety-related electrical work QC personnel not granted sufficient freedom to perform duties PHILLIP.0 A , FOSTER.J E . LOVE.R S Region 3. Office of Direct B2/06/07 53pp 15683 309 24X Fiche 50-461.82/08/04. B210130547
- 8210040270 Confirms 820924 verbal approval re limited work resumption 820927 per confirmatory action its Scope of work limited to insp of remedial work associated w/nonsafety-related seismic electrical trays in Seismic Category I bidgs NORELIUS, C E Division of Engineering & Technical Programs 82/09/28 GERSTNER, W C Illinois Power Co ip 15594 360 24% Fiche 50-461.02/09/28.8210040270
- 8210070336 EN-82-032 on 821006, notice of violation & proposed imposition of civil penalty to be issued to licensee Action based on numerous violations in electrical area & licensee failure to exercise control over contractor FLACK.E. AXELRAD.J Director's Office, Office of Inspection and Enforcement 82/10/04 ip 15634-084 24X Fiche 50-461,82/10/04 8210070336
- 8210130451 Discusses IE insp on 820105-0303 & forwards notice of violation & notice of proposed imposition of civil penalty KEPPLER.J 9 Region 3. Office of Director 82/10/05 CERBTMR # C 2 Illinois Power Co 2pp 15681 332 24X Fiche 50-461,82/10/05, 8210130451
- --B210130459 Notice of violation & notice of proposed imposition of 1, penalty in amount of \$40,000 Noncompliance noted failure to exercise adequate oversight & control of principal contractor for assuring execution of QA program KEPPLER, J O Region 3, Office of Director 82/10/05 13pp 15691 334 24X Fiche 50-441, 82/10/05, 8210130451
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Distodged 1-125 Implant Seeds " Svc liet enc! COBB.L I Division of Fuel Facilities, Materials & Safeguard & 82/10/04 Consolidated Edison Co of New York 66pp 13761 a'd) 24X Fiche 50-000, 82/10/06, 8208190233
- 8210130181 Forwards revised Pages 3.11.12 & 14 to 820223 "Clinton Power Station Preservice Insp Program" HULLER.0 E 1111nois Power Co 82/10/06 THOMAS.C 0 Standardisation & Special Projects Branch ip 15673 013 241 Fiche.50-461.82/10/06.8210130181
- --8210130184 Revised Pages 3,11.12 & 14 to "Clinton Power filation Preservice Imap Program " * Illinois Power Co 82/10/06 5pp 15673 014 24x Fiche 50-461,82/10/06.8210130181
- 8210130240 Submits confirmatory action 1tr per 820930 mesting No further work will be allowed until completion of NRC approval of overlasp program plan SPESBARD, R L Division of Project & Resident Programs 82/10/04 OERSTNER, W G Illinois Power Co 2pp 15475 124 24X Fiche 50-441, 82/10/04, 8210130240
- 8210250224 Forwards IE Insp Rept 50-461/82-08 on 820601-0731 No noncompliance moted KNOP:R C Division of Project & Resident Programs 82/10/06 0ERBYNER:W.C Illinois Power Co 2pp 15788 349 24X Fiche' 50-461:82/10/06/8210250224
- --8210250232 IE Insp Rept 50-461/82-08 on 820601-0731 No nencompliants noted Hajor areas inspected const activities, including mall laydown & storage areas, pipe & structural welding, program control & numerous stop work recovery activities LIVERMORE, H H , HAYES, D W Division of Project & Resident Programs 82/09/30 App 15788 351 24X Fiche 50-461.82/10/65 8210250224.
- 8210280170 Forwards IE Mgt Meeting Rept 50-461/82-17 on 820930 Me noncompliance noted KEPPLER.J.O Region 3. Office of Director 82/10/13 GERSTNER w: Illinois Power Co 2pp 15845 048 24X Fiche 50-461.82/10/12 8210280170

- --8210280174 IE ligt Meeting Rept 50-461/82-17 on B20730 No noncompliance noted Major areas discussed status of stop work recovery & overinsp programs, master mpt plan & recommendations from audit Related viewgraphs enc!

 MEFFLER.J G , MAYES,D W Division of Project & Resident Programs MNOP,R C Division of Project & Resident Programs B2/10/13 42pp 15845 050 24% fische 50-461.82/10/13.8210280170
- --8210280174 IE Mgt Meeting Rept 50-461/82-17 on 820930 No noncompliance noted Major areas discussed status of stop work recovery & overlosp programs, master mgt plan & recommendations from audit Related viewgraphs enci KEPPLER.J G Region 3. Office of Director SPESSARD,R L Division of Project & Resident Programs 82/10/13 42pp 15845 050 24X Fiche 50-461.82/10/13.8210280170
- 82:08190238 IE Dulletin 82:03, "Stress Corrosion Cracking in Thick-Halli-Large-Diametor:Stainless Steel, Recirculation Sys Piping at DWR Plants "Svc list encl DEVOUND, R C Director's Office. Office of Inspection and Enforcement 82:10/14 Consolidated Edison Co of New York 115pp 15850 125 24X Fiche 50-600.82/10/14.8208190238
- 8210280050 Forwards full payment for 821005 notice of proposed imposition of civil penalties re violations noted in IE Imposition Rept 50-461/82-02 CERSTMER.W C Illinois Power Co 82/10/21 Director's Office. Office of Inspection and Enforcement 4pp 15837-252 24X Fiche 50-461.82/10/21.8210280050
- 5 Reportable occurrences. LERs & related correspondence
- 6210190350 Interim Deficiency Rept 82-08 re lack of distribution control for instrument data sheet Initially reported on 820902 Condition could result in errors in documentation & instrument requirements Document control tightened MALL, D.P. Illinois Pawer Co. 82/10/01 REPPLER, J.G. Region 3, Office of Director. 4pp. 15742-091 RAX Fiche 50-461, 82/10/01, 82/10/350
- 0210190354 Final Deficiency Rept 02-05 ie loss of structural steel inspretored Initially reported on 020625 Measures taken to document destroyed drawings 5 revise 06 requirements GERSTHER.W C Illinois Power Co 082/10/01 KEPPLER, J 0 Region), Orfice or Director 3pp 15742 104 24X Fiche 50-461.82/10/01, 8210190354
- 0210190416 Interim Deficiency Rept 82-09 to small bore/instrumentation piping support dosign calculations Initially reported on 820902 Review of all calculations to determine extent of errors underough Next rept due in 90 days HALLil P Illinois Pawer Ca 82/10/01 KEPPLER, J 0 Region 3. Ortice of Director 3pp 15740 353 24X Fiche 50-461,82/10/01, 62:0190416
- G210190633 PNO-111-B2-108 on G21005.util announced hiring of 5&W Engineering to augment const mgt plogram & assess site const organization Majority of safety-related work stopped since June 1982, tending upgrading of GA program LIVERUDRE.H: HAVES.D. KNUP.R. Region 3. Office of Director D2/10/06 Ip 15737 359 24X Fiche 50-461.62/10/06.8210190633
- 8210280160 Interim Part 21 Ropt 82-07 re breakdown in const 9A program insp & corrective action procedures Initially reported on 820708 Stop work action issued until investigation complete Results expected in 90 days MALL D P Illinois Power Co 82/10/19 KEPPLER. J 0 Region 3. Office of Director 5pp 19837 210 24X Fiche 50-461.82/10/19.8210280160
- DOCKET 50-462 CLINTON POWER STATION, UNIT 2
- @ Inspection reports, IE Bulletins & correspondence
- 8208190203 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Syc list encl COBB.L I Division of Fuel Faculities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York A6pp 15761 250 244 Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Mall-Large-Dlameter Stainless Steel.Recirculation Sys Piping at BRR Plants " Syc list encl BEYQUNG, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York (15pp 15810 125 24X Fiche 50-000.82/10/14.8208190238

- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1

 G Adjudicatory correspondence
- B210070120 Motion for termination of proceedings Util decided to cance) plant Certificate of Svc encl
 NENMAN.J R Houston Lighting & Power Co NEWMAN.J R
 Lowenstein.Neuman.Reis.Aielrad & Toll 82/10/06 Atomic Safety
 and Licensing Board Panel 3pp 15627 061 24x
 Fiche 50-466.82/10/06.8210070120
- 8210070147 Withdrawal of application for CP NEMMAN, J R Houston Lighting & Power Co NEMMAN, J R Lowenstein, Newman, Reis, Azelrad & Toll 82/10/06 1p 15627 075 24% Fiche 50-466, 82/10/26, 8210070147
- 8210190390 Response to util 821006 motion for termination of proceeding NRC does not object to motion Certificate of Syc enci BLACK,R L Hearing Branch 3 82/10/15 Atomic Safety and Licensing Board Panel 3pp 15740 348 24X Fiche 50-466.82/10/15, 201018080
- G Inspection reports, IE Bulletins & correspondence
- 8208190233 lE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I-12'. Implant Seeds " Svc list ent]
 COBGL I Division of Frei Facilities, Materials & Safeguards
 82/10/06 Consolidated Edison Co of New York 66pp 15761 250
 244 Fiche 50-000, 82/10/06. 8208190233
- 820B19023B IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys
 Piping at BWR Plants "Svc list encl
 DEYOUNG:R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- DOCKET STN-50-470 CESSAR SYSTEM BO
- B Utility Preliminary Safety Analysis Report, amends
- 8210280202 Withdraws App C to CESSAR-F supporting operation of Sys 80 NBSB at reduced power level w/two pumps from NRC review Partial loop operation not required for issuance of final design approval SCHERER. A E Combustion Engineering, Inc 82/10/25 THOMAS. C Standardization & Special Projects Branch 1p 15837 049 24 Fiche 50-470.82/10/25.8210280202
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8210150306 Forwards proprietary & nonproprietary "Statistical Combination of Uncertainties, Part II" & "Statistical Combination of Uncertainties, Part III," re SER Confirmatory Item 7 Proprietary versions withheld (ref 10CFR2 790) SCHERER, A E Combustion Engineering, Inc 82/10/08 EISENHUT, D & Division of Licensing App 19715 173 24X Fiche 50-470,82/10/08,8210150306
- --8210150313 "Statistical Combination of Uncertainties, Part II, Uncertainty Analysis of Limiting Safety Sys Settings for C-E Sys 80 NSB " * Combustion Engineering, Inc 82/07/30 50pp 15715 175 Fiche 50-470, 82/10/08, 8210150306

VZ DOOKETED Ham

--B210220253 "Comparison of Finite Element & Lumped Mass Beismic Analysis Hethods for Belected SNUPPS Bidgs," Revision I + Standardired Nuclear Unit Power Plant System 82/06/18 24pp 15775 327 24X Fiche 50-000.82/10/18.8210220252

8210260274 Submits plant-specific rept re NUREG-0737. Item [I D 1. "Relief & Safety Valve Testing " Acceptable operability of SNVPPS safety valves demonstrated Evaluation of safety & relief valve discharge piping & support expected by 821231 PETRICK.X A Standardized Nuclear Unit Power Plant System 82/10/20 DENTON.H Office of Nuclear Reactor Regulation, Director 3pp 15803 026 24X Fiche 50-000.82/10/20.8210260274

E NRC Safety Evaluation Report (SER), suppls & correspondence

8210040373 Forwards Suppl 1 to SER (NUREG-0881) W/o encl YDUNOBLOOD, B J Licensing Branch 1 62/09/07 KOESTER, G L Kansar Gas & Electric Co 3pp 15597 200 24X Fiche 50-482,82/09/07, 8210040373

F Security, medical, emergency & fire protection plans

B2(0210272 Natification of 82)019 meeting w/utils & SNUPPS organization in Bethesda.MD to discuss matters re fire protection for alternate shutdown panel EDISON.6 E , HOPKINS.J D Licensing Branch 1 62/09/27 YOUNGBLOOD.B J Licensing Branch 1 4pp 15774 341 24X Fiche 50-000, 82/09/27,8210210272

G Adjudicatory correspondence

8210200050 Notice of ASLB reconstitution JA Laurenson chairman & GC Anderson & HC Parton members COTTER B F Atomic Safety and Licensing Board Panel 82/10/14 2pp 15757 224 24X Fiche 50-482 82/10/14 8210200050

H General correspondence

8210120199 Informs of mgt organization changes FBAR w]l) be revised to reflect changes
KOESTER: 0 L. Kansas Oas & Electric Co. 82/10/06 DENTON: H R
Office of Nuclear Reactor Regulation: Director 3pp. 15451 232
244 Fiche 50-482:82/10/06:8210120199

X Utility Final Safety Analysis Report (FSAR) & amends

8210080240 Forwards Revision 10 to FSAR, including FSAR changes transmitted by 820706, 13 & 0827 ltrs
PETRICK, N A Standardized Nuclear Unit Power Plant System 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 13638 333 24X Fiche 50-000,82/09/30,8210080260

--B2100B0266 Revision IO to FSAR 4 Standardized Nuclear Unit Power Plant System 82/07/30 40%pp 1563B 335 24X Fiche 50-000,82/07/30,8210080260

Q Inspection reports. IE Builetins & correspondence

E210190596 Forwards IE Insp Rept 50-482/62-11 on B20701-0B31 No noncompliance noted EEIDLE.H C Division of Resident, Reactor Project & Engineering Programs B2/09/22 KOESTER, C L Kansas Cas & Electric Co 2pp 15739-339 24X Fiche 50-482/82/09/22/8210190596

~~8210190608 IE Insp Rept 50-482/82-11 on 820701-0831 No noncompilance noted Major areas inspected followup on previous lasp fladings: records review for post-tensioning sys installation & raceways & power cable installation activities VANDEL.7 E . NORTON J F . HUNNICUTT.D M Division of Resident. Reactor Project & Engineering Programs 82/09/20 12pp 15739 341 24X Fiche 50-482,82/09/22,8210190596

6208190233 IE Info Notice 80-35, Suppl ir "Leaking & Dislodged I-126 Implant Seeds " Syc list encl CD85.L I Division of Fuel Facilities, Materials & Safeguerds 62/10/06 Consolidated Efison Co of New York 65pp 15761 250 24X Fichs 50-000, 82/10/06, 8208190233

8208190238 IE Bulletin 82-09. "Stress Corrosion Gracking in Thick-Wall, Large-Diameter, Btainless Steel, RecIrculation Sys Fipting at BMR Plants " Svc list and DEYGUNO.R.C Director's Office, Office of Inspection and Enforcement E2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238

8210280225 Advises that IE Insp Rept 50-482/8)-18 has been canceled Rept will not be issued SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs 82/10/25 KOESTER. G.L. Kansas Gas & Electric Co. 19 15837 086 24X Fiche 50-482,82/10/25,8210280225

5 Reportable occurrences, LERs & related correspondence

6210040364 Interim deficiency rept re potential defect in diesel generator thermostatic valve units AE awaiting receipt of additecthical info from vendor to finalize rework plan Rept on status of insp by 630120 Also reported per Part 21 KOESTER, GL Kansas Gas & Electric Co 82/07/23 SE(DLL, W C Division of Resident, Reactor Project & Engineering Program | 15589 027 24X Fiche 50-482,82/09/23,8210040364

DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1

A Application/construction stage documents & correspondence

B210040370 Informs that util proposed exception to Reg Ouide i 146 se qualifications of GA audit personnel unacceptable Util should provide clear commitment to Reg Guide i 146 by B21005 VOUNOBLOOD, B J Licensing Branch i B2209703 SCHNEILDF Univaselectric Co 3pp 15597 197 24X Fiche 50-403, B210040173

8210210309 Notification of 821020 meeting w/utils & SNUPPB in Catthersburg, MD to discuss electrical power sys EDISON.0 E. HOPKINS.J B. Licensing Branch 1 82/09/27 YOUNGBLOOD.B J. Licensing Branch 1 4pp 15782 074 24x Fiche 50-000, 82/09/27, 8210210309

8210050299 Responds to 820903 ltr re commitments to Rag Guide 1 14/ ge Revision 2 of FSAR site addendum Commitment will be revised, w/o stated clarification, in next revision to FSAR addendum SCHINELL, D F Union Electric Co 82/09/28 YOUNGBLOOD, B J Licensing Branch 1 4pp 15609 072 24X Fiche 50-483,82/09/49, 8210050299

8210220252 Forwards Revision 1 to "Comparison of Finite Clement & Lumped Mass Seismic Analysis Methods for Bolected SNUPPS Bldgs "

PETAICK.N A Standardized Nuclear Unit Power Plant System 82/10/18 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 13775-326 24X Fiche 50-000.02/10/16.821022022

--8210220253 "Comparison of Finite Element A Lumped Mass Gerral Charlet Methods for Selected SNUPPB Bldgs: "Revision 1 4 Standard: ed Nuclear Unit Power Plant System 82/06/18 44pt 15775 327 24X Fiche 50-000,82/10/18.821022022

G210260274 Submits plant-specific rept re NUREQ-0737, Item [] D i. "Relief & Safety Valve Testing " Acceptable operability of SNUPPB safety valves demonstrated Evaluation of safety & relief valve discharge piping & support expected by D21231 PETRICK,N A Standardized Nuclear Unit Power Plant System B2/10/20 DENTOR,H Office of Nuclear Reactor Regulation, Directed Spp 15803 026 24X Fiche 50-000,82/10/20,8210260274

F Security, medical, emergency & fire protection plans

8210070152 Advises that no radiological emergency response plan or seg operating procedure has been developed or accepted by Montgomery or Oasconade Counties, MO. as reported in RW Kriam 820817 memo REED. J @ Affiliation Unknown 82/09/23 GRIMES, B Division of Emergency Preparedness KRIMM, R W Federal Emergency Management Agency 3pp 15627 071 24X Fiche 50-483, 82/09/23, 82100/0157

8210210272 Notification of 821019 meeting w/utils & ENUPPS organisates in BethesdamD to discuss matters re fire protection for alternate shutdown panel EDISON. G E . HOPKINS. J B Licensing Branch 1 82/09/27 YOUNGBLOOD. B J Licensing Branch 1 4pp 15774 341 24X Fiche 50-000. 82/09/27.8210210272

O Adjudicatory correspondence

B210060197 Final particularization of J Reed amended Contentions 1,5 g 3 Certificate of Svc enc] REED, J G Reed, J G 82/10/O1. Atomic Safety and Licensing boar, Panel 42pp 15614 176 24X Fiche 50-483,82/10/O1.8210060197

DOCKETED ITEMS

- BZIO120202 Forwards revised schedule stipulated at 82090B prehearing conference reflecting 2-wk extension for discovery of undisputed contentions Original interrogatories no longer appropriate Svc list enci Related correspondence DAITER. T.A. Shaw Pittman. Potts & Trowbridge DAXTER. T.A. Union Electric Co. 82/10/06 OLFASON. J.P. ORIGHT, O.D., KLINE, J.P. Atomic Safety and Licensing Doard Panel. 4pp. 15652 293 24X Fiche 50-483, 82/10/06, 8210120262
- #2102103c5 Objections to JG Reed #21001 particularization of Contentions | 11 & 12 Contention | 11 seeks greater specificity re energency planning for re-entry & recovery than specified by regulations Certificate of Svc encl DAXTER.1 A Union Electric Co DAXTER.7 A Shaw, Pittman, Potts & Troubridge #2710718 Atoms Safety and Licensing Board Panel 24pp 19763 214 24% Fiche 50-483,82/10/18.8210210365
- Falluatulati Forwards revised interrogatories & requests of JO Reed for production of documents Responses due 821113 & objections due 621027, per stipulated schedule Requests replace util 200715 interrogatories & requests Certificate of Svc enci BA/TER.T A Shaw, Pittman, Potts & Troubridge BAYTER.T A Union Electric Co. 82/10/20. REED.J C. Reed. J G. 4pp. 15768 308 241 Fiche 50-483, 82/10/20. 8210250248
- -8210250253 Revised interrogatories? requests for production of documents BAKTER, I A Union Electric Co BAYTER, I A Shaw, Pittman, Potts ' Troubridge 82/10/20 REED, J G Reed, J G 25pp 15788 312 24x Fiche 50-483,82/10/20,8210250248
- EZICZ70159 Response to J Reed 821001 final particularization of amended Contentions 1,2 * 3 Objects to admission of Contentions 7 11,12 * 14 % portions of 3,13 % 15 Certificate of Sic encl
 PERLIS.R G Hearing Branch 3 82/10/25 Atomic Safety and Licensing Board Panel 16pp 15830 028 24X Fiche 50-483,82/10/25, 0210270159
- . Utility Final Safety Analysis Report (FSAR) & amends
- E21003026U Forwards Revision to to FBAR, including FBAR changes transmitted by 820706.13 & 0827 itrs
 PETRICK, N A Standardized Nuclear Unit Power Plant System 82/09700 DENIENG N Office of Nuclear Reactor Regulation, Director 2pp 15630 333 24% Fiche 50-000,82/09/30,8210080260
- 8210080266 Revision 10 to FSAR + Standardized Nuclear Unit Power Plant System 82/09/30 409pp 15638 375 24; Fiche 50-000.82/09/30.8210080260
- a Inspection reports. IE Bulletins 3 correspondence
- B210130514 Forwards IE Insp Rept 50-483/B2-10 on B20801-31 & notice of violation SPESSARD, R L. Division of Project & Resident Programs 82/09/16 SCHWELL, D F. Union Clectric Co. 2pp. 15682 241 24X Fiche 50-483, 62/09/16, 8210130514
- 8210130523 Notice of violation from insp on B20801-31 SPESSARD, R L Division of Project & Resident Programs 82/09/16 2pp 15682 243 244 Fishe 50-483,82/09/16,8210130514
- --8210133529 IE Insp Rept 50-483/82-10 on 820801-31 Noncompliance noted failure to follow cable installation procedures & failure to identify nonconforming electrical penetrations NEISLER.J H , KONKLIN.J E Division of Project & Resident Programs 82/09/16 7pp 15682 245 24% Fiche 50-483,82/09/16,8210130514
- 82(0130484 Ack receipt of 820723 ltr informing NRC of steps taken to correct violations noted in IE insp Rept 50-483/82-06 SPESSARD, R L. Division of Project & Resident Programs 82/10/05 SCHNELL D F Union Citetric Co ip 15684 176 24X Fiche 50-483,82/10/05,8210130484
- --8210130555 Responds to NRC 820825 itr re violations noted in 1E Insp Rept 50-483/82-06 Corrective actions review of all completed work assisgnments for non-Q non-scheduled raceway within Seismic 11/1 boundaries in process SCHNELL, D.F. Union Electric Co. 82/09/23 SPESSARD, R.L. Division of Project & Resident Programs 2pp 15684 197 24X Fiche 50-483,82/10/05.8210130484
- 8203190233 lE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Applant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 200 24% Fiche 50-000.82/10/06.8208190233

- 8208190238 iE Builetin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter.Stainless Steel.Recirculation Sys Piping at BMR Plants " Svc list enc! DEYCUNO,R C Director's Office. Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000.82/10/14.8208190239
- S Reportable occurrences, LERs & related correspondence
- B207180037 FOIA request for insp & enforcement records re accidents of F Lawson & H Dillon at facility. Union Electric Co CP & other NRC safety manuals or matis 100E. V M 1goe, V M 82/08/12 KEPPLER, J O Region 3, Office of Director 1p 15626 243 24X Fiche 50-483.82/08/62.8207680037
- 8210050512 Responds to FOIA request for insp & enforcement records re accidents of F Lawson & H Dillon at facility. Union Electric CP & other NRC safety matls or manuals Forwards two documents Renaining records available in PDR FELTON.J H Division of Rules and Records 82/09/21 IQUE.M V Igoe. V M 2pp 15626-244 24X Fiche 50-000.82/09/21.821005051.2
- --8210050518 Region 3 daily rept for 780807 * Region 3. Chicago. Office of the Director 78/08/07 1p 15626 246 24X Fiche 50-000, 82/09/21,8210050512
- -6210050522 FNO-III-78-062 on 780804, two workers seriously injured whin hit by support girder for polar crane rail GSHA notified SCHWEIBINZ E R , HAYES, D W , HEISHHANN R F Region 3. Chicago, Office of the Director 78/08/04 ip 15424 247 24X Fiche 50-000,82/09/21,8210050512
- DOCKET STN-50-485 STERLING POWER NUCLEAR PROJECT, UNIT 1
- Q Inspection reports. 1E Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1. "Leaking & Distodged I-125 implant Seeds " Svc list encl CDB.L. | Division of Fue) Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 1576: 250 24% Fiche 50-000, 02/10/06, 8208190233
- 8208190238 IC Builetin 62-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter: Stainless Steel, Recirculation Sys Piping at BWR Plants " Sve list enci DEYDUNG, R C Director's Office. Office of Inspection and Entercement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000,88/10/14-8208190238
- DOCKET STN-50-488 PERKINS NUCLEAR STATION, UNIT 1

 Q Inspection reports, 1E Bulletins & correspondence
- 8208190233 IE lnfo Notice 80-35, Suppl 1. "Leaking & Dislodged 1-125 Implant Seeds " Svc list enci COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/04 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,82/10/04,8208190233
- 9208190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at 8WR Plants " Syc list encl DEYOUNO, R Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14-8208170238
- DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

 O Inspection reports, IE Suiletins & correspondence
- 8208190233 IE lnfo Notice 80-35. Suppl i, "Leaking & Dislodged 1-125 lmplant Seeds " Svc list encl COBG.L I Division of Fuel Facilities, Materials & Safeguards 82/10/04 Consolidate Edison Co of New York 64pp 15741 250 24X Fiche 50-000,82/10/04.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracting in Thick-Wall. Large-Dlameter. Stainless Steel. Recirculation Sys Piping at BMR Plants " Svc list encl
 DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche 50-000. 82/10/14, 8208190238

DOCKET SIN-50-490 PERKINS NUCLEAR STATION, UNIT 3

8208(90233 lE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Sve list encl COBB.L I Division of Fuel Facilities, Meterials & Safeguards E2/10/04 Consolidated Edison Co of New York 66pp 1576) 250 24% Fiche 90-000,82/10/06.8208(90233

8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Mall-Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants " Svc list encl DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14.8208190238

DOCKET STM-50-491 CHERDKEE NUCLEAR STATION, UNIT 1

8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-12" Implant Seeds " Svc list encl CORD.L I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 M50 24% Fiche 50-000,82/10/06,8208190233

820B190238 IE Bulletin 82-03, "Stress Corrosien Cracking in Thick-Hall-Large-Diameter. Stainless Steel Refirculation Sys Piging at SWR Plants " Svc list encl DEYOUND. R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238

DOCKET STN-90-492 CHEROKGE NUCLEAR STATION, UNIT 2 9 Inspection reports, IE Gulletins & correspondence

G208190233 IE Info Notice 80~35, Suppl 1, "Leaking & Dislodged [-12]:
implant Seeds " Svc list encl
CDB,L I Division of Fuel Facilities, Materials & Safeguards
62/10/06 Consolidated Edison Co of New York 66pp 15761 250
24/

8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter-Stainless Steel Recirculation Sys Piping at BUR Plants " Svc list encl DEYBUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 11500 15810 125 24% Fishe 50-000, 62/10/14, 6208190238

DOCKET STN-50-493 CHERDIEE NUCLEAR STATION, UNIT 3

G Inspection reports, IE Builetins & correspondence

8208190233 IE Info Notice 80-35. Suppl 1, "Leaking & Dislodged 1-125 implant Seeds " Svc list encl COBB.L 1 Division of Fuel Facalities, Materials & Safequards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fache 50-000,82/10/06,8208190233

8208190238 IE Bullwin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants " SVc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 62/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 80-000.62/10/14,6208190238

DOCKET STN-50-498 SOUTH TEXAS PROJECT. UNIT 1

A Application/construction stage documents & correspondence

8210250358 Requests labest revision to Form NRC-3, "Notice to Employees," per amend of 10CFR19, 30, 40, 50, 60, 70, 72 & 150 to provide employee protection against discrimination as consequence of reporting infe to NRC OPREA. 9 W Houston Lighting & Power Co 82/08/09 COLLINS, J T Region 4, OFFice of Director 2pp 15790 341 24X Fichs 50-498, 62/08/09, 8210250358

8210250263 Bubmits updated schedulas for const activities to be restarted during remainder of 1782.per util 820514 ltr W/ two oversite charts Aperture cards are everiable in POR OPREA.O W Houston Lighting & Power Co 82/08/30 COLLING.J T. Region 4, Defice of Director. Epp. 13791:029, 24x Fiche 50-498,82/08/30.8210220263

8210040422 Forwards Task Interface Agreement 82-44, complete wife, plan for Quadrez Rept re Brown & Root design of project Idea input needs to be generated during Bept 1982, in order for Region 4 to issue final rept in Oct 1982 (In order for Region 4 to issue final rept in Oct 1982 (In order for Region 4 to issue final rept in Oct 1982 (In order for Region 4 to issue final Oct 1982 (In order for Region 1) (In o

8210250259 Advises that add; safety-related const sullyity to be restarted in 1982 has been identified since util (1200) if Updated schedule for const activities to be restarted during 1982 encl Wione oversize thank Aperture card is in PPN OPREA.O W Houston Lighting & Power Co B2/09/20 (44t [6.] J. Region 4. Office of Director 9pp 15791 01V 24x Fiche 50-498.82/09/20.0210250259

8210200052 Forwards responses to Questions 24t 1 through "41 A 17th expedite geotechnical review lafe will be incorporated into FBAR amend GOLDDERG, J H. Houston Lighting & Power Co. 112/10/til. laftAs. 1 Assistant Director for Licensing 77pp 13/51 Ottl. 14x Fiche 50-498.02/10/18.0210200032

8210220237 Forwards Revision O to "Control Room Dasign Partist Fell Plan" GULDBERO.J H Houston Lighting S Power Co (は/10/m) かたみ まる Ass(Stant Director for Licensing Spp 15775 191 248 Fiche 50-498,82/10/20.8210220239

--B210220241 Rovision O to "Control Room Design Roview Program Plant Houston Lighting & Power Co B2/10/11 129pp 15//5 144 Fiche 50-490, 82/10/20, 0210220239

Q Adjudicatory correspondence

821005024) Proposed opinion, findings of fact, conclusions of law & in form of partial initial decision Certificate of the erel CUTERREZ, J M. Hearing Branch 3. 82/10/04. 21/pp. 19au/ 705. Fiche 30-478, 82/10/04. 8210030241

8210180172 Memorandum & Order LBP-02-91 granting ("itsiens Conserval About Nuclear Power motion to adopt Citizens for Iquitable Utils contentions re Contention 4 & denying motion re Contentions 3-0 American Bridge contentions 3-0 American Bridge contentions 3-0 American Bridge contentions dismissed BECHNOFFER C Atomic Safety and Licensing Board Panel Cafficily Citizens Concerned About Nuclear Power, Inc 17pp 13717 443 3 Fiche 50-490,82/10/15.8210180172

8210210363 Forward: applicant reply to Citizens Concerned Abaud Main Power. Inc & NRC proposed findings of fact & conclusions of law NEGRAN, J.R. Lowenstein, Newman, Reis, Azotrad & Toll Phirway J.R. Houston Lighting & Power Co. 82/10/18 SECHMENTER.C., LANGUE HILLE E. Atomic Bafety and Licensing Board Panel & 19 1358 2. 24X Fishe 50-498,02/10/18,0210210363

--0210210368 Reply to Citizens Concerned About Nuclear Paver Inc a we proposed findings of fact & conclusions of law Certificate of Box enci # Houston Lighting & Power Co # Lowensteam Newman. Rata #1816. A Toll 82/10/18 Atomic Bafety and Licensing four Paret 9909 15763 241 24% Tiche 50-498.62/10/18.0210/180787

G Inspection reports, IE Bulletine & correspondence

8210080015 Add1 response to FOIA request for 17 categoriss of the gas nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld fraff FOIA Exemption 51
FELTON, J. H. Division of Rules and Records 02/07/12 UDGLC. & A Critical Mass Energy Project 9pp 18665 027 24%
Fiche 50-000.82/07/12.8210080015

--8210080163 Bystematic Assessment of licensee performance mother ay facility evaluation for Aug 1979-Jul 1980

N NRC - Nu Detailed Affiliation Given 80/07/31 13;)
13468 077 24X Fiche 50-000,82/07/12,8210080013

DOCKETED HEMS

- -8210190419 IE insp Repts 50-498/82-14 & 50-499/82-14 on 820823-27 No noncompliance noted Major areas inspected GA program re design engineering procurement & const CROSSIANNW A. HILL.W.H. BOARDMAN, J.R. Division of Resident, Reactor Project & Engineering Programs 82/09/24 lipp 15741 003 24X Fiche 50-498,82/09/28,82/0190413
- 6208190233 IE info Notice 80-35, Suppl 1. "Leaking & Dislodged 1-125 Implant Seeds "Svc list encl COBDL | Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 19761 250 24x Fiche 50-000.62/10/06.8208190233
- 6208190238 IE Bulletin B2-03. 'Stress Corrosion Cracking in Thick-Mail. Carge-Diameter, Stainless Steel, Recirculation Sys Mail. Carge-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svc list enci DEYOUNG, R C Director's Office, Office of inspection and Enforcement 82/10/14 Consolidated Edison Co of New York LISpp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 6210220122 Ack receipt of 820909 ltr informing NRC of steps taken to correct violations noted in IE insp Rept 50-498/82-02 MADSEM C L Division of Resident, Reactor Project & Engineering Programs 62/10/14 0/9786A G W Houston Lighting & Power Co lp 15777 332 24X Fiche 50-498/82/10/14.8210220122
- --B2:0220125 Responds to NRC 820811 ltr re violations noted in IE Insp Repts 50-498/82-02 & 50-499/82-02 Corrective actions deficiency reporting procedures revised & employees retrained CPREA. G W CPREAL W Houston Lighting & Power Co 82/09/07 COLLINS, J T Region 4. Difice of Director App 15777 333 24X Fiche 50-498, 82/10/14.8210220123
- S Reportable occurrences, LERs & related correspondence
- B210250112 Supplemental deficiency rept re beam to column connection design in containment bldg.per NRC request info expected by B21217 Brown & Root, inc reanalysis received in Aug & Submitted to Becktel for review

 GPAEA, O U Houston Lighting A. Power Co 82/08/19 CDLLINS, J T
 Region 4. Office of Director Rep 15787 022 24X
 Fiche 50-498. 62/08/19, 8210250112
- 8210050327 Final deficiency rept re possible exceeding of design pressure loading of isolation valve cubicle autiliary feedwater pump compartment walls in event of feedwater bypass line break initially reported on B20901

 OPREA, 0 U Houston Lighting & Power Co B2/09/29 COLLINS, J T

 Region 4, Office of Director 4pp 15610 254 24X

 Fiche 50-498, B2/09/29, B210030329
- 3210250249 Fifth interim deficiency rept re vendor fabricated structural steel initially raported on BIO108 Bechtel will assure that surveillance insp of 100% of all welded math was or will be performed prior to shipment Nort rept by 830509 OPREA.0 U Houston Lighting & Power Co B2/10/15 COLLINS, J 7 Region 4. Office of Director 3pp 15788 339 24x Fiche 50-498, 82/10/15, 8210250249
- 8210260452 Final deficiency rept re NVAC design instially reported un 810508 Chillers added to existing auxiliary bldg chillers, mixing boxes deleted make-up air balanced & electrical penetration enhaust sus down-graded

 OPREA O W Houston Lighting & Power Co 82/10/20 (
 Region 4. Office of Director 14pp 18807 106 24x)
 Fitche 50-4788 82/10/20.8210260452 COLLINS, J T
- DOCKET STN-50-499 BOUTH TEXAS PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 62:0250358 Requests latest revision to Form NRC-D, "Notice to ctuesous and wests latest revision to form NRC-3, "Notice to Employees," per amend of lOCFRIP, 30.40, 30, 60, 70, 72 £ 150 to provide employee protection against discrimination as consequence of reporting info to NRC OPREA, G W Houston Lighting & Power Co 82/08/09 COLLINS, J T Region 4. Office of Director 2pp 15/70 341 24X Fichs 30-498.82/08/09,8210230358
- 8210250263 Submits updated schedules for const activities to be riugables Submits updated schedules for const activities to be restarted during remainder of 1982, per util 820514 ltr W/ two oversize charts Aperture cards are available in PDR DFREA.O W Houston Lighting & Power Co 82/08/30 CULLINS, J T Region 4, Office of Director 8pp 15791 029 24X Fiche 50~498,82/08/30,8210250243

- 8210040422 Forwards Task Interface Agreement 82-44, complete w/review plan for Quadrez Rept re Brown & Root design of project NRR input needs to be generated during Sept 1982, in order for Region 4 to issue final rept in Oct 1982 MIRAGLIA.F J Licensing Branch 3 82/08/31 MULMAN, L C Accident Evaluation Branch PARR, O D Auxiliary Systems Branch BERLINGER, C Core Performance Brench 2pp 15597 237 24X Fiche 50-498, 82/08/31, 8210040422
- 8210250259 Advises that addl safety-related const activity to be restarted in 1982 has been identified since util 820830 Itr Updated schedule for const activities to be restarted during OPRE OF A PROPERTY OF THE PROP RO COLLINS, J T 24X
- 8210200075 Forwards info requested at 820722 meeting Submittal includes geotechnical info on essential cooling water pipelinas soil profiles boundaries of four low density backfill areas & contaminated backfill GOLDBERG.J H Houston Lighting & Power Co 82/10/12 NOVAK.1 H Assistant Director for Licensing 84pp 15756 231 Fiche 50-498 82/10/12 8210200075 24X
- 8210200052 Forwards responses to Guestions 241 1 through 241 6, in order to expedite geotechnical review Info will be incorporated to expecte genterminal review into will be incorporated into FBAR amend GOLDBERG, J H Houston Lighting & Power Co 82/10/18 N Assistant Director for Licensing 77pp 15753 010 24X Fiche 50-498, 82/10/18, 8210200052 NOVAK, T M
- 8210220239 Forwards Revision O to "Control Room Design Review Program NOVAR. I M
 - GOLDBERG, J. H. Houston Lighting & Power Ca. B2/10/20 Assistant Director for Licensing Gep. 15775-193 24X Fishe 50-498.82/10/20.8210220239
- + Houston Lighting & Power Co 82/10/11 129pp 15775 194 24x Fiche 50-498,82/10/20.8210220239
- G Adjudicatory correspondence
- 8210090241 Proposed opinion, findings of fact, conclusions of law & order in form of partial initial decision Certificate of Svc encl OUTIERREZ, J M Hearing Branch 3 82/10/04 217pp 15607 306 24X Fiche 50-498, 82/10/04, 8210050241
- 8210180172 Memorandum & Order LBP-B2-91 granting Citizens Concerned About Nuclear Power metion to adopt Citizens for Equitable Utils contentions re Contention 4 & denying motion re Contentions 5-B American Dridge contentions dismissed BECH-IOEFER, C. Atomic Safety and Licensing Board Panel 82/10/15 Citizens Concerned About Nuclear Power, Inc. 17pp 15719 148 & Fiche 50-498,82/10/15,8210180172
- 8210210363 Forwards applicant reply to Citizens Concerned About Nuclear Power, Inc & NRC proposed findings of fact & conclusions of NEWHAN, J. R. Lowenstein, Newman, Reis, Axelrad & Toll NEWMAN, J R
 - NewHork O. Covenstain, Newman, Reis, Azerra & Tott NewHorl II Houston Lighting & Power Co 82/10/18 BECHMOEFER, C., LAMB, J. C., HILL, E. Atomic Safety and Licensing Board Panel ip 13763 240 24x Fichs 80-498,82/10/18,82
- --8210210368 Reply to Citizens Concerned About Nuclear Power, Inc & NRC proposed findings of fact & conclusions of law Certificate of Bay encl
 - of Byc enci

 4 Houston Lighting & Power Co * Lowenstein Neumann Reis, Ax

 5 Toll 82/10/18 Atomic Safety and Licensing Roard Pane?

 77pp 19763 241 24X Fiche 50-498.82/10/18,8210210363
- Q Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FDIA request for 19 categors nuclear reactor events & safety problems Forwards docu-listed in App A Documents in App B completely withheld FOIA Exemption 5) FELTON, J M Division of Rules and Records, 82/07/12 Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000,82/07/12,8210080015
- --B210080163 Systematic assessment of licensee performan facility evaluation for Aug 1979-Jul 1980
 + NRC No Detailed Affiliation Given 80/07/31.
 15668 079 24X Fiche 50-000.82/07/12.8210080015
- 8210190413 Forwards IE Insp Repts 50-498/82-14 & 50-499/8 #200823-27. No noncompliance nated #27.82-14 & 30-4997. #200823-27. No noncompliance nated #4808EN.0 L Division of Resident, Reactor Project & El Programs #27.09728. OPREA.0 W Houston Lighting & Pi 15741 OOI. 24% Fiche 50-498, 82/09728. 8210190413

- --82101904)9 IE Insp Repts 50-498/82-14 & 50-499/82-14 on 820823-2/ No noncompliance noted Major areas inspected GA program re design, engineering procurement & const CROSSMAN.W A . HILL, W K . BOARDMAN.J R Division of Resident, Reactor Project & Engineering Programs 82/09/24 lipp 15741 003 24% Fiche 50-498.82/09/28,8210190413
- 8208190233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L 1 Division of Fuel Facilities, Materials & Safeguards 82/10/04 Consolidated Edison Co of New York 6App 15761 250 244 Fichs 50-000.82/10/06.8208190233
- 820B19029B IE Bulletin 62-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants "Svz list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15910 125 24X Fiche 50-000. B2/10/14. 820819023B
- 8210220122 Ack receipt of 820909 1tr informing NRC of steps taken to correct violations noted in IE insp Rept 50-498/82-02 MADSEN. O. L. Division of Resident, Reactor Project & Engineering Programs 82/10/14, QPREA. O. W. Houston Lighting & Power Co. ip 15777 332 24X Fiche S0-498,82/10/14,8210220122
- --8210220125 Responds to NRC 820811 ltr reviolations noted in 16 Insp. Repts 50-478/82-02 & 50-479/82-02 Corrective actions deficiency reporting procedures revised & employees retrained DREA/G W Houston Lighting & Power Co 82/09/09 Chilling, J Facebook Corrective App. 15777 333 24X Fiche 50-498.82/10/14,8210220122
- 5 Reportable occurrences, LERs & related correspondence
- 8210250112 Supplemental deficiency rept to beam to column connection design in containment bldg.per NRC request Info expected by 821217 Brown & Root.Inc reanalysis received in Aug & submitted to Bechtel for review CPREA.0 W Howston Lighting & Power Co 82/08/19 COLCINS.J T Region 4. Defice of Director 2pp 15787 022 24% Fiche 50-498.82/08/19.8210250112
- B210050327 Final deficiency rept re possible exceeding of design pressure loading of isolation valve cubicle auxiliary feedwater pump compartment walls in event of feedwater bypass line break initially reported on B20901 OPREA.9 W Houston Lighting & Power Co B2/09/29 COLLINS, J T Region 4, Dffice of Director 4pp 15610 254 24X Fiche 50-498,82/09/29,8210050329
- 8210250249 Fifth interim deficiency rept re vendor fabricated structural steel Initially reported on Bioloß Bachtel will assure that surveillance insp of 100% of all welded mati was or will be performed prior to shipment Next rept by 830509 OPREA:Q W Houston Lighting & Power Co 82/10/15 COLLINS, J T Ragion 4. Office of Director 3pp 15788.339 24% Fiche 50-498.82/10/15.8210250249
- 8210260452 Final deficiency rept re HVAC design Initially reported on BIO508. Chillers added to existing auxiliary bldg chillers, mixing boxes deleted, make-up air balanced & electrical penetration exhaust sys down-garded OPREA:0 W Howston Lighting & Power Co 82/10/20 COLLING, J T Region 4. Office of Director 14pp 15807 106 24X Fiche 50-498, 82/10/20, 8210260452
- DECKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3
- A Application/construction stage documents & correspondence
- 8210180214 Summary of 820831-0702 caseload forecast panel site visit woutil in Satsop, HA re info to use as input to OL review scheduling progress & projected fuel load date.

 WHEELERL Litensing Branch 3 82/09/17 Licensing Branch 3 2pp 15746 113 24X Fiche 50-508,82/09/17,8210180214
- --8209210550 Notification of 820831 & 0901-02 meetings w/util in Sattop, MA to review const progress in order to obtain info for use as input to OL review Scheduling process Related mattenci WHEELER, L. Licensing Branch 3 82/08/20. MIRAGLIA: F. Licensing Branch 3 103pp. 14746:117 24X Fichs. 50-508.82/09/17. 8210180214
- 8210120197 Advises that fuel load date scheduled for Dec 1985, per NRC request Schedules do not preclude achieving fuel load 6 months earlier. Planning details provided basis for discussions w/NRC Caseload Forecast Panel on 820831-0902. BOUCHEY, O D Washington Public Power Bupply System 82/10/01 EISENHUT, D. 0 Division of Licensing 1p. 15651 229 24X Fiche 50-508, 82/10/01, 8210120197

- 8210280416 Approves use of ASHE Code Case N-249-2, in response to 820921 request Scope of approval limited to use of code case for strap 2 rivet malls in ITT-Grinnel Figures 215 for stiff clarges KERRIOAN, J D Licensing Branch 3 82/10/08 FERGUSON, R L Hashington Public Power Supply System 2pp 15859 358 24x Fiche \$0-508, 82/10/08, 82102804(6
- 8210270012 Forwards responses to FSAR questions transmitted w/NRi B20820 Itr Responses to questions re environ rept will be sent under separate rover BOUCHEY, G.D. Washington Public Power Bupply System 82/10/2. KERRIGAN, J.D. Licensing Dranch 3 300pp 15815 001 24x Fiche 50-508, 82/10/22, 8210270012
- H General correspondence
- 8210010020 Advises that EPA (Region X) deleted from distribution II I for FSAR & general info amends EPA informed util that FGAR, energency preparedness plantine protection plan & general info not required COUCHEY, C D Washington Public Power Supply System 82/09/22 EISENHUT, D Q Division of Licensing 2pp 15365 150 -4X Fiche 50-508. 82/09/22, 8210010020
- K Utility Final Safety Analysis Report (FSAR) & Smends
- B210120194 Forwards Amend 1 to FBAR.updating design description to correcting typographical errors
 BOUCHEY. B Washington Public Power Supply System (92/10/06 KERRIOAN.J D Licensing Branch 3 3pp 15657 137 24X
- --8210120200 Amend 1 to FSAR

 # Washington Public Power Supply System 82/10/31 216/pp 15657 140 24X Fiche 50-508,82/10/06,8210120194
- G Inspection reports. IE Bulletins & correspondence
- 8210060155 Forwards 10 Insp Repts 50-508/82-17 & 50 509/02 0/ bu 820801-31 & notice of violation StERNBERG.D M Division of Resident, Reactor Project & Engineering Programs 82/09/24 LEDDICK.R S Washington Public Power Supple System 2pp 15614 056 24X Fiche 50-508.82/09/24.02100/017.
- --8210060197 Notice of violation from insp on 820801-j1 BODDS.R T Division of Resident, Reactor Project & Inginesting Fragrams 82/09/24 ip 15414 058 24% Fichs 50 508,8240/.4 8210060155
- --B210060163 IE insp Repts 50-508/B2-17 to 50-509/B2-07 on H/QHD1 in Nancompliance noted on B20B10 nonsafety-related Q decising attached to containment bldg safety-related structural atest at 375-ft level using nonqualified procedure ALBERT. W G . DODDS, R T Division of Resident, Reactor Project Engineering Programs B2/09/22 9pp 15614 059 24x Fiche 50-508, B2/09/24, B210060155
- 8210070158 Ack receipt of 820528 itr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-508/82-06 & 50-509/82-09 STERNBERO.D M Division of Resident, Reactor Project & Ingeneral Programs 82/10/04 LEDDICK, R S Washington Public Power Imp81s System Ip 15627 064 24X Fichs 50-508,82/10/04.82(1000158)
- --92i0070161 Responds to NRC 820426 ltr re violations noted in it in Repts 50-508/82-06 & 50-507/82-03 Corrective Actions two shutdown cooling HXs placed in care & maint program to insure monthly monitoring of maint on nitrogen purge LEDDICK, R S Washington Public Power Supply System 92/05/mit BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 15627 065 24X Fishs 50-508,82/10/04,023007015
- 8208190233 IE Info Notice 80-35, Suppl i, "Leaking & Bislodged I lab Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safegueris 82/10/06 Consolidated Edison Co of New York 64pp 13761 pic 24X Fiche 50-000/82/10/06/8208190233
- 8208170238 JE Builetin 82-03, "Stress Corrosion Cracking in Intel Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svo list encl DEVGUNO. R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 13810 125 24X Fiche 50-000.82/10/14, 8208190238

- DOCKET STN-50-509 WPPSS NUCLEAR PROJECT. UNIT 5
- a inspection reports. IE Bulletins & correspondence
- 8210060155 Forwards 18 Insp Repts 50-508/82-17 % 50-509/82-07 on 820801-31 % notice of violation STERNUERG, D M DIVISION of Resident, Reactor Project & Engineering Programs 82/09/24 LEDDICK, R S Washington Public Power Supply System 2pp 15614 Q56 24% Fiche S0-508.82/09/24.8210060155
- -8210040143 IC lnsp Repts 50-508/82-17 & 50-509/82-07 on 820801-31 Noncompliance noted on 820810 nonsafety-related 0 decking attached to containment bidy safety-related structural steel at 395-ft level using nonqualitied procedure ALBERT.W 9 . DODDS.R T Division of Resident. Reactor Project & Engineering Programs 82/09/22 9pp 15614 059 24X Fiche 50-508,82/09/24,8210040155
- 6210070150 Ack receipt of 870528 lti informing NRC of steps taken to correct violations noted in IE Insp Repts 50-508/82-03 & 50-508/82-03 M Division of Resident, Reactor Project & Engineering Programs 82/10/04 LEDDICK,R & Washington Public Fower Supply System ip 13627 064 24% Fiche 50-509,82/10/04.8210070150
- -02100/0141 Responds for NRC 020426 ltm re violations noted in IC Insp.
 Repts 90-500/62-04 & 50-509/82-03 Corrective actions
 two shutdown cooling HXs placed in care & maint program to
 insure monthly moniforing of maint on nitrogen purge
 LLDDICK.R 8 Washington Public Power Supply System 82/05/28
 BISHOP.T W Division of Resident, Reactor Project & Engineering
 Programs 4pp 19427 045 24X Fiche 50-508,82/10/04,8210070198
- DUCKET 50-51 I WPPGS HULLEAR PROJECT, UNIT 4
- à Inspection reports. IE Bulletins & correspondence
- 62100707/B Ack receipt of 820909 Itr informing NRC of steps taken to correct violations noted in Insp on 820501-28

 5468NBCRG, D M Division of Resident, Reactor Project & Engineering Programs 02/10/04 R001/R W Washington Public Power Supply Gystem Ip 15434 017 244 Fiche 50-440.82/10/04.8210070378
- 02:0070397 Responds to NRC 620624 ltr re violations noted in 10 insp on 02001-20 Corrective actions subcontractor procedures for initaliation of electrical penetration assemblies submitted & approved by engineer RODT, R H Washington Public Power Supply System 82/07/09 BIGHOP, T W Davisson of Resident, Reactor Project & Engineering Programs 4pp 15639 016 24% Fiche 30-460,82/10/04,8210070378
- #210130415 Ack receipt of 820707 & 30 ltrs informing NRC of steps taken to correct violations noted in IC insp on 820401-30 STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs 82/10/06 ROOT.R W Mashington Public Power Bupply System ip 15481 319 24X Fiche 50-440, 82/10/06, 8210130415
- --8210133423 Updates response to NRC 820608 ltm re violations noted in IE insp on 820401-30 Corrective actions local grinding to expose weld root performed on four wolds Cause of understred welds due to improperly prepared weld bevels ROOT, R W Rashington Public Power Supply System 82/07/30 SIERNIBERGO, D M Division of Resident, Reactor Project & Engineering Programs Spp 15681 320 24X Fiche 50-460.82/10/06.8210130415
- 8710130432 Responds to NRC 820608 ltr re violations noted in IE inspon 820401-30 Corrective actions local grinding conducted to spose weld root & base metal surfaces Partial penetration butt weld undersized RDDI.R H Hashington Public Power Supply System 82/09/09 BISHJP,T W Division of Resident. Reactor Project & Engineering Programs 7pp 15681 325 24X Fiche 50-460,82/10/06.8210130415
- S Asportable occurrences, LERs & related correspondence
- 821007033B Interim deficiency rept re emergency diesel generator governor lube oil cooler initially reported on 820126 Lube oil cooler will be moved to elevation below oil level per Transamerica Delaval instructions & drawings RODI.R W Mashington Public Power Supply System 82/09/15 STERNDERO, D M Division of Resident, Reactor Project & Englneering Programs 2pp 15634 071 24X Fiche, 50-460, 82/09/15, 8210070338
- 8210070297 Interim deficiency rept re unsultability of isoprene methode in governor drive coupling elements Initially reported on B20819 Field change notice issued to implement changeout of element mail to neoprene Also reported per Part 21 RCOILR W. Washington Public Power Supply System 62/09/20 STERNOERO, D. M. Division of Resident, Reactor Project & Engineering Programs Rep. 15634 178 24X Fiche 50-460,82/09/20,8210070297

- 8210070311 Interim deficiency rept re use of lumped mass loads in performance of pipe stress analysis initially reported on 820305 Parametric studies may resolve trivial mass changes interim status repts will be provided on semiannual basis RODT, R W Washington Public Power Supply System 82/09/20 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 3pp 15634 145 24% Fiche 50-460,82/09/20,8210070311
- DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT. UNIT 1
- G Adjudicatory correspondence
- 8210150476 Hemorandum & order directing applicants to rept details of status of applications for CPs to ASLB within 30 days of svc of order SNITH.I W Atomic Safety and Licensing Board Panel 82/10/13 Portland General Electric Co ip 15703 047 24x Fiche 50-514,82/10/13,8210150476
- G Inspection reports, 1E Bulletins & correspondence
- 8208190233 IE lnfo Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06,8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Syc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2
- G Adjudicatory correspondence
- 8210150476 Memorandum & order directing applicants to rept details of status of applications for CPs to ASLB within 30 days of svc of order SMITH, I W Atomic Safety and Licensing Board Panel 82/10/13 Portland General Electric Co 1p 15703 047 24X Fiche 30-514,82/10/13,8210150476
- Q Inspection reports, 1E Bulletins & correspondence
- 8208170233 IE Info Notice 80-35, Suppl 1. "Leating & Dislodged I-125 Implant Beeds" Svc list encl COBB.L 1 Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consalidated Edison Co of New York 66pp 13761 290 24X Fiche 50-000, 82/10/06.8208170233
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Dlameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810-125 24X Fiche 50-000, 82/10/14, 8208170238
- DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence

- 8210010411 Ack receipt of 820913 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-518/82 08 & 50-520/82-08 WERRELLI, D.M. Division of Project & Resident Programs 82/09/22 PARRIS.H O Tennessee Valley Authority 1p 15572 181 24X Fiche 50-518.82/097/22.8210010411
- --821001042D Forwards response to NRC 820812 ltr re violations noted in IE Insp Repts 50-518/82-08 & 50-520/82-08 Corrective actions 6C investigation rept written to prevent use of protective coatings & PVC conduit covered & stored KAMMER, D S Tennessee Valley Authority 82/09/13 O'REILLY, J P Regson 2. Office of Director 3pp 15572 182 24X Fiche 50-518,82/09/22,8210010411
- --8210010426 Forwards IE Insp Repts 50-518/82-08 & 50-520/82-08 on 820720-29 & notice of violation VERBELLI.D M Division of Project & Resident Programs 82/08/12 PARRIS.H G Tennessee Valley Authority 2pp 15572 185 24X Firth
- --8210010431 Notice of violation from insp on 820720-23 4 Division of Project & Resident Programs 82/08/12 1p 15572 187 24X Fiche 50-518,82/09/22,8210010411
- --8210010433 IE Insp Repts 50-518/82-08 & 50-520/82-08 on 820720-23
 Nancompliance noted failure to follow procedures on storage
 & preventive maint of safety-related matis
 MERRIMEATHER, N. CONLON, T.E. Division of Engineering & Technical
 Programs 82/08/11 5pp 15572 188 24X Fiche 50-518,82/09/22,8210010411
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl CDB, L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000, 82/10/06, 8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Plping at SMR Plants " Svc list encl DEYGUNG, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 13810 125 24% Fiche 30-000, 82/10/14,6208190238
- 8 Reportable occurrences. LERs & related correspondence
- 8210050247 Third & final deficiency repts to resolution of unanticipated vibratory loading concerns initially reported on Bil228 Program developed to insure plping sys operate within design parameters Next rept provided by 821217 HILLS, L. H. Tennessee Valley Authority 82/09/24 0'REILLY, J.P. Region 2, Office of Director 3pp 15638 104 24X Fiche 50-000,82/09/24,8210080247
- 8210050273 First interim deficiency rept re six sheared motor pinion keys in Limitorque Model 88-0-25 motor operators initially reported on 820830 Valves w/motor operators being tabulated Next rept until be submitted by 821122 MILLS.L M Tennessee Valley Authority 82/07/28 0'REILLY, J.P. Region 2. Defice of Director 2pp 15607 070 24X Fiche 50-000, 82/09/28, 8210050273
- 8210270328 Second interim deficiency rept re use of nonconservative calculational method to evaluate General Const Spec 0-32 spacing violations Initially reported on 820528 Next rept will be sent by 830528 MILLS, LM Tennessee Valley Authority 82/10/12 G'REILLY, JP Region 2. Office of Director 2pp 15853 064 24% C'-he-50-000, 82/10/12, 8210270328

- 8210260320 First interim deficiency rept re addition of locking design to handwheel operated valves initially reported on 820916 Canst activities deferred Analyses of locking devices continuing Neit rept will be sent by 820310 MILLS.L H Tennessee Valley Authority 82/10/18 9'REICLY.J# Region 2. Office of Director 2pp 15802 359 24X Fiche 50-000.82/10/18.8210260320
- 8210290274 Final rept for Deficiencies B & E & seventh interim replá Deficiencies A & D re control of procurement activities Initially reported on 810316 Final corrective actions noted Next rept expected by 830428 MILLS,L M Tennessee Valley Authority 82/10/21 O'RE111Y, JP Region 2, Office of Director 4pp 15853 143 24x Fiche 50-000.82/10/21.8210290274
- DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8210040430 Informs of decision to refund fees remitted w/DD(K)1 application to delete certain requirements from primary water quality monitoring Fees should not be charged in cases where licensee has effective NPDES permit MILLER.H.O. License Fee Management Branch B2/09/21 PANHID.N.G. Tennessee Valley Authority 1p 15597 263 24X Fiche 50-000.B2/09/21.B210040430
- Q Inspection reports. IE Bulletins & correspondence
- 9210150318 Forwards 1E insp Repts 50-518/82-11.50-519/82-1().
 50-520/82-11 & 50-521/82-09 on 820816-18.25 & 0910 No noncompliance noted
 VERRELLI.D M Division of Project & Resident Programs 632/09/sq.
 PARRIS.H 0 Tennessee Valley Authority 2pp 15705 25%, 24x
 Fiche 50-516.82/09/20.8210150318
- --8210150334 IE insp Repts 50-518/82-11.50-519/82-10.50 520/82 it t 50-521/82-09 on 820816-16.25 & 0910 No noncompliance insted Major areas inspected open items independent insp effort (A-1 & A-2) & site deferral preparation (A-1 & A-2) SCHAPKER.J F. CANTRELL.FS Division of Project & Rosadent Programs 92/09/20 4pp 15705 258 24X Fichs 50-516.82/8//... 9210150318
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Distouged 1 pm Implant Seeds " Svc list enc! COBD.L [Division of Fuel Facilities, Materials & Safgguards 82/10/06 Consolidated Edison Co of New York 66pp 15/61,*CO 24% Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stross Corrosion Cracking in Thick Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Syc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New Yort 115pp, 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- S Reportable occurrences. LERs & related correspondence
- 8210270187 Interim deficiency rept re deferral of const activities Initially reported on 820623 Commitments made in rept-audit findings & response to violations deferred until restart of design & const MILLB/L M Tennessee Valley Authority 82/10/14 O'REILLY, J P Region 2. Office of Director ip 15853 312 24% Fiche 50-000,82/10/14,82(0270)87
- DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

 A Application/construction stage documents & correspondence
- 8210040430 Informs of decision to refund fees remitted w/B01031 application to delete certain requirements from primary water quality monitoring Fees should not be charged in cases where licensee has effective NPDES permit MILLER.W O License Fee Management Branch 82/09/21 PARRITER Tennessee Velley Authority 19 15597 263 24X Fiche 30-000, 82/09/21, 8210040430
- Q Inspection reports, IE Bulletins & correspondence
- 9210150318 Forwards IE Insp. Repts 50-518/82-11, 50-519/82-10, 50-520/82-11 & 50-521/82-09 on 820816-18,25 & 0910 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 87/09/20 PARTS,H G Tennessee Valley Authority 2pp 15705-256 241 Fiche 50-518,82/09/20,8210150318

- --82:0150334 IE Insp Repts 50-516/82-11.50-519/82-10.50-520/82-11 & 50-521/82-09 on 820816-18.25 & 0910 No noncompliance noted Major areas inspected open items; independent insp effort (A-1 & A-2) & site deferral preparation (A-1 & A-2) SCHAPKER.J F. CANTRELL.F S Division of Project & Resident Programs 82/09/20 App 15705 258 24X Fiche S0-518.82/09/20, 8210150318
- 0210010431 ACF receipt of 820713 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Repts 50-510/82-08 & 50-520/82-08 VERRELLI.D M Division of Project & Resident Programs 82/09/22 PARRIS.H G Tennessee Valley Authority Ip 13572 181 24X Fiche 50-518.82709722.8210010411
- --B210010420 Forwards response to NRC 820812 ltr re violations noted in IE Insp Repts 50-518/82-08 & 50-520/82-08 Corrective actions QC investigation rept written to prevent Use of protective coatings & PVC conduit covered & stored MAMMER.D S Tennessee Valley Authority 82/09/13 O'REILLY.J P Region 2. Office of Director 3pp 19572 182 24X Fiche 50-518,82/09/22,8210010411
- --8210010426 Forwards JE Insp Repts 50-518/82-08 & 50-520/82-08 on 820720-23 & notice of violation VERRELLI, DM Division of Project & Resident Programs 82/08/12 PARRIS.H G Tennessee Valley Authority 2pp 15572 185 24X Fiche 50-518 82/09/22/82/8210010411
- --8210010431 Notice of violation from insp on 820720-23 d Division of Project & Resident Programs 82/08/12 1p 15572 187 24X Fiche 50-518,82/09/22,8210010411
- --B210010433 IC Insp Repts 50-518/82-08 % 50-520/82-08 on 820720-23 Noncompliance noted failure to follow procedures on storage t preventive maint of safety-related matis MERRIMEATHER, N. . CONLON. T. E. Division of Engineering & Technical Programs 82/08/11 5pp 15572 188 24% Fiche 50-518,82/09/22, 8210010411
- 0208190233 IE Info Notice 80-35. Suppl 1, "Leaking & Dislodged I 125 Implant Seeds " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24x Fiche 50-000-82/10/06-8208190233
- 0208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Hall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants" Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Entercement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000, 02/10/14, 8208190238
- 3 Reportable occurrences, LERs & related correspondence
- 9210080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on 811228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MILLS, I M Tennessee Valley Authority 82/09/24 0'REILLY, J P Region 2. Office of Director 3pp 15638 104 24X Fiche 50-000, 82/09/24, 8210080247
- 2210050293 First interim deficiency rept re six sheared motor pinion keys in Limitorque Model SB-0-25 motor operators Initially reported on 820830 Valves w/motor operators being tabulated Next rept will be submitted by 821122 MILLS.L M Tennessee Valley Authority B2/09/28 0'REILLY, J P Region 2. Office of Director 2pp 15609 070 24X Fiche 50-000.82/09/28.8210030293
- B21029032B Second Interim deficiency rept re use of nonconservative calculational method to evaluate General Const Spec 0-32 spacing violations Initially reported on 82052B Next rept will be sent by 83052B MILLS.L M Tennessee Valley Authority 82/10/12 O'REILLY, J P Region 2. Office of Director 2pp 15853 064 24X Fiche 50-000, 82/10/12, 821029032B
- B210290187 Interim deficiency rept re deferral of const activities Initially reported on B20623 Commitments made in rept, audit findings & response to violations deferred until restart of design & const HJLL8.L M Tennessee Valley Authority 82/10/14 O'REILLY, J P Region 2, Office of Director in 15853 312 24X Fiche 50-000:82/10/14.8210290187

- 8210290236 Third interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Investigation continuing & const activities deferred until sufficient info gathered to determine completion of project HILLS.L M Tennessee Valley Authority 82/10/14 D'REILLY.J P Region 2. Office of Director 2pp 15853 227 24X Fiche 50-000, 82/10/14, 8210290236
- 8210260320 First interim deficiency rept re addition of locking devices to handwheel operated valves Initially reported on 820916 Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820310 MILLSIL H Tennessee Valley Authority 82/10/18 D'REILLY, J P Region 2, Office of Director 2pp 15802 359 24X Fiche 50-000, 82/10/18, 8210260320
- 8210290274 Final rept for Deficiencies 8 & E & seventh interim rept for Deficiencies A & D Te control of procurement activities initially reported on 810316 Final corrective actions noted Next rept expected by 830428 MIKLS.L M Tennessee Valley Authority 82/10/21 D'REILLY. J P Region 2. Office of Directur 4pp 15853 143 24X Fiche 50-000.82/10/21,8210290274
- DOCKET BIN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4
- A Application/construction stage documents & correspondence
- B210040430 Informs of decision to refund fees remitted w/B01031 application to delete certain requirements from primary water quality monitoring fees should not be charged in cases where licensee has effective NPDES permit MILLER.W O License Fee Management Branch B2/09/21 PARRIS.H O Tennessee Valley Authority | p | 15597 263 24X Fiche 50-518, B2/09/21, B210040430
- G Inspection reports, IE Bulletins & correspondence
- 8210150318 Forwards IE Insp Repts 50-518/82-11.50-519/82-10, 50-520/82-11 \$ 50-521/82-09 on 820816-18.25 & 0910 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/09/20 PARRIS.H 0 Tennessee Valley Authority 2pp 24X Fiche 30-518.82/09/20.8210150318
- --8210150334 IE Insp Repts 50-518/82-11, 50-519/82-10, 50-520/82-11 & 50-521/82-09 on 820816-18, 15 & 0910 No noncompliance noted Major areas inspected open items, independent insp effort (A-1 & A-2) & site deferral preparation (A-1 & A-2) & site deferral preparation (A-1 & A-2) & Steelenson of Project & Resident Programs 82/09/20 4pp 24% Fiche 50-318,82/09/20,8280150318
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York AApp 15761 250 24X Fiche 50-000,82/10/06,8208190233
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking In Thick-Wall Carge-Diameter, Stainless Steel, Recirculation Sys Plping at BNR Plants "Syc list encl DEYOUNO.R C Director's Office, Office of Inspection and Enrortement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125, 24% Ficke 50-000, 82/10/14,820819023B
- S Reportable occurrences. LERs & related correspondence
- 8210290187 Interim deficiency rept re deferral of const activities initially reported on 820623 Commitments made in rept, audit findings & response to violations deferred until restart of design & const MILLS, L.M. Tennessee Valley Authority 82/10/14 0'REILLY, J.P. Region 2, Office of Director 1p 15853 312, 24% Fiche 50-000, 82/10/14, 8210290187
- DOCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8210270158 Summary of 820721 meeting w/applicants in Gethesda.MD re program to investigate May Junction monocline MDGN.C W Licensing Branch 4. 82/10/05 Licensing Branch 4 4pp 15876 224. 24X Fishe 50-522.82/10/05.8210270158

- B Utility Preliminary Safety Analysis Report. amends
- B210210337 Forwards Amend 27 to PSAR
 MYERS, R V Puget Sound Power & Light Co 82/10/08 Dffice of
 Nuclear Reactor Regulation, Director 3pp 15764 311 24X
- --8210210339 Amend 27 to PSAR

 4 Puget Sound Power & Light Co 82/10/08 101pp 15764 314
 24Y Fichs 50-529, 82/10/08.8210210337
- 8210260430 Forwards Affidavit of Svc certifying distribution of PSAR Amend 27 to listed persons on 821020 THOMSEN.FT Perkins, Cois, Stone, Glsen & Hilliams 82/10/22 Office of Nuclear Reactor Regulation, Director 3pp 15806 033 24X Fiche 50-522.82/10/22,8210260440
- C Utility Environmental Report (ER), amends & correspondence
- 6210070169 Forwards Amend 7 to application for site certification/environ rept Amend revises info re need-for-power, alternative energy sources, socioeconomics & exclusion area boundary Verrification & distribution list encl HYRRS, R V Puget Sound Power & Light Co 82/09/16 Office of Nuclear Reactor Regulation, Director 6pp 15634 348 24X Fiche 50-522, 82/09/16, 8210070189
- --8210070193 Amend 7 to application for site certification/environ rept * Puget Sound Power & Light Co 82/09/16 250pp 15634 354 24x Fiche 50-522,82/09/16.8210070189
- 9210010382 Forwards Affidavit of Svc for Amenó 6 to application for site certification/environ regt
 THOMSEN F T. Perkins. Cois. Stone, Disen & Williams 92/09/27
 Office of Nuclear Reactor Regulation, Director 3pp 15574 293
 24X Fiche 50-522, 82/09/27, 8210010382
- 8210130190 Forwards Affidavit of Svc for Amend 7 to application for site certification/environ rept
 THOMSEN, T Perkins, Coie, Stone, Olsen & Williams 82/10/07
 Office of Nuclear Reactor Regulation, Director 3pp 15674 104
 24X Fiche 50-522,82/10/07,8210130190
- O Adjudicatory correspondence
- 8210050389 Responds to util 920917 first set of interrugatories Certificate of Svc encl Related correspondence BELL,N Coalition for Safe Power 82/09/28 Puget Sound Power & Light Co 4pp 15608 231 24X Fiche 50-522,82/09/28,8210050389
- B210050169 Supplement to petition to intervene consisting of contentions & bases for contentions of the contention of the contention of the contention of the contention of the content of
 - 10050171 Applicant response to Coalition for Bafe Power B20910 first set of interrogatories Certificate of Svc encl. Related correspondence
 THOMSEN.F T Puget Sound Power & Light Co THOMSEN.F T Perkins. Coie. Stone. Olsen & Williams B2/09/29. Coalition for Safe Power 34pp 15604 145 24X Fiche 50~522.82/09/29.8210050171
 - of and of interrogatories Certificate of Syc

Federation THATCHER, T.L. Oregon T.L. Thatcher, T.L. 82/10/04, pp. 15643 268 24X

> bai Fish Commission Indom & order Ise appeal in

THOMSEN, FT Puget Sound Power & Light Co
Coie, Stone, Olsen & Williams 82/10/06
Licensing Appeal Panel 3pp 15680 320
24X Fiche 50-522, 82/10/06,
92/0/30367

:10:30498 Response to 820917 first set of interrogatories
THOMSEN: F.T Puget Sound Power & Light Co THOMSEN: F.T Perkins,
Coie: Btone: Olsen & Williams 82/10/06 Natural Resources
Defense Council: 8pp 15683 089 24% Fiche: 50-522; 82/10/06.
82:0130498

H0120271 Notice of appearance in proceeding Certificate of Svc encl DEWEY, L. S. Hearing Branch 3 82/10/08 3pp 15652 314 24X Fiche 50-522, 82/10/08, 8210120271

- 8210120288 Brief supporting Columbia River Inter-Tribal Fish Commission 820923 appeal of ASLB 820908 memorandum & order denying Columbia petition to intervene Columbia has met injury in fact test Certificate of Svc encl DEWEY.L S Hearing Branch 3 82/10/08 Atomic Bafety and Licensing Appeal Panel 20pp 15453 058 24X Fiche 50-522, 82/10/08.8210120288
- 8210200045 Response to Vakima Indian Nation 820930 suppl to pelilien t intervene containing list of contentions Objects to Contentions 4-10 Certificate of Svc encl THOMSEN, F I perblish Co. Cois, Stone, Client & Williams 82/10/14 Atomic Safety and Licensing Board Penel 16pp 15756 026 24X Fichs 50 522.12/10/14
- 8210190373 Notice of withdrawal of appearance in proceeding Certifical of Svc encl
 BLACK.R L. Hearing Branch 3 82/10/15 3pp 1574t 2tt 24x
 Fiche 30-522.82/10/15.8210190373
- 821020005B Response to 820910 first set of production requests
 Certificate of Svc encl Related correspondence
 FRANTIS P Puget Sound Power & Light Co FRANTIS P
 Lowenstein Newman Reis Arstrad & Toll 82/10/15 Coelition Icu
 Safe Power 82pp 15753 093 24X Fiche 50-522, 8//10/15, 8/10/2006
- 8210220429 Response to Yakima Indian Nation 820930 supplitu petition to intervene, setting forth contentions Contentions 1, 2, 3 to 6 should be admitted & consolidated w/similar contentions Certificate of Svc encl
 DEMEYLE 8 Hearing Branch 3 82/10/20 Atomic Safety and Licensing Board Panel 21pp 15780 190 24X Fiche 50-522,83/10/8210220429
- H General correspondence
- 8210220434 Requests all parties be informed of Natl Hildlife federat & OR Environ Council correct address THATCHER: TL National Wildlife Federation 82/10/19 1986; etc. & Secretary of the Commission 1p 15778 269 24X Fiche 50-522, 82/10/19, 8210220434
- O Inspection reports, IE Builetins & correspondence
- 8208190233 iE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1 La Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Enfeguards 82/10/06 Consolidated Edison Co of New York App 19/61 J 24X Fiche 50-000.82/10/06,8208190233
- 8208170238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thirt Wall, Large-Diameter, Stainless Steel, Recirculation Sysping at BMR Plants "Syc list enci BEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edition Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8200170230
- DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

 A Application/construction stage documents & correspondence
- 821029015B Summary of 820921 meeting w/applicants in Bethesda. Htt s., program to investigate May Junction monacline HOON.C W Licensing Branch 4 82/10/05 Licensing Branch 4 4pp 15874 224 24X Fiche 50-522,82/10/05,821029015B
- B Utility Preliminary Bafaty Analysis Report, amends
- 8210210337 Forwards Amend 27 to PBAR

 MYERS,R V Puget Sound Power & Light Co 82/10/08 Uffice &
 Nuclear Reactor Regulation, Director 3pp 15764 311 24x
 Fiche 50-522,82/10/08,8210210337
- ~-8210210339 Amend 27 to PSAR 4 Puget Sound Power & Light Co 82/10/08 101pp 15764 134 24X Fiche 50-522, 82/10/08,8210210337
- 8210260430 Forwards Affidavit of Svc certifying distribution of proceed 27 to listed persons on 821020
 THUMSEN,F T Perkins, Cole, Stone, Disen & Williams 82/10/22
 Office of Nuclear Reactor Regulation, Director 3pp 13806 Op 24X Piche. 50-322,82/10/22,8210260430

- Utility Environmental Report (ER), amends & correspondence
- 10070189 Forwards Amend 7 to application for site certification/environ rept Amend revises info re need-for-power, alternative energy sources, socioeconomics & exclusion area boundary Verification & distribution list encl MYERG, R V Puget Sound Power & Light Co 82/09/16 Office of Nuclear Reactor Regulation, Director &pp 15634-348 24X Fichs 50-522, 82/09/16, 8210070189
- -8210070193 Amend 7 to application for site certification/physron rept 4 Puget Sound Power % Light Co 82/09/16 250pp 15634 354 24% Fiche 50-522,82/09/16.8210070189
- 210010382 Forwards Affidavit of Svc for Amend 6 to application for site certification/environ rept 1HOMSERIF T Perkins, Coie, Stone, Olsen & Williams 82/09/27 Orrice of Nuclear Reactor Regulation, Director 3pp 15574 293 24/ Fiche 50-522,82/09/27,8210010382
- 3210130190 Forwards Affidavit of Svc for Amend 7 to application for site certification/environ rept
 JHDMSEN F T Perkins, Cole. Stone. Olsen & Williams 82/10/0/
 Office of Nuclear Reactor Regulation. Director 3pp 15474 104
 24x Fiche 50-522.82/10/07.8210130190
- s Adjudicatory correspondence
- មិន10050389 Responds to util 820917 first set of interiogotories Certificate of Svc encl Related correspondence BELLIN Coalition for Safe Power 82/09/28 Puget Sound Power & Light Co app 15608 23t 24X Fiche 50-522,82/09/28,8210050588
- 6210050169 Supplement to petition to intervene consisting of contentions & bases for contentions MOVIS.J B Hovis, R L 82/09/29 Atomic Safety and Lirensing Board Panel 62pp 15605 052 24X Fiche 50-522,82/09/29.8210050169
- GZ10050171 Applicant response to Coalition for Safe Power B20910 first set of interrogatories Certificate of Svc encl Related correspondence
 THOMSEN,F T Puget Sound Power & Light Co. THOMSEN,F T Perking, Coie: Stone, Olsen & Williams GZ/09/29 Coalition for Safe Power 34pp 15604 145 24) Fiche 50-522, BZ/09/29, BZ10050171
- 8219080073 Response to first set of interrogatorius Certificate of Sve enci HATCHER, T.L. National Wildisfe Federation THATCHER, T.L. Oregon Environmental Council THATCHER, T.L. Thatcher, T.L. 82/10/04 Pupet Sound Power & Light Co. 9pp. 15443 P68 24X Fiche 50-522, 82/10/04, 8210080073
- 8210130367 Response to Columbia River Inter-Tilbal Fish Commission 820923 notice of appeal of AGLB 820903 memorandum % order denying intervention Applicants will not oppose appeal in order to maintain schedule for proceeding two maintain schedule for proceeding two maintain schedule for proceeding two maintains appeal Sound Power & Light Co THOMSEN.F T Perking. Cole. Stone. Oisen & Hilliams 82/10/06 Atomic Safety and Licensing Appeal Panel 3pp 15680 320 24X Fiche 50-522/82/10/04. 8210130367
- 6210130498 Response to B20917 first set of interrogatories
 IHONSEN.F T Puget Sound Power & Light Co
 Core. Stone. Glach & Williams B2710704 Natural Resources
 Defense Council 8pp 15683 089 24X Fiche 50-522,82/10/04,
 6210130498
- B210120271 Notice of appearance in proceeding Certificate of Svc encl DEWEY.L S Hearing Branch 3 82/10/08 3pp 19652 314 24X Fiche 50-522.82/10/08.8210120271
- \$210120288 Brief supporting Columbia River Inter-Tribal Fish Commission 820923 appeal of ASLB 820908 memorandum & order denging Columbia petition to intervene Columbia has met injury in fact test Certificate of Svc enc.

 DENEY.L 8 Hearing Branch 3 82/10/08 Atomic Safety and Licensing Appeal Panel 20pp 15453 058 24% Fiche 50-522, 82/10/08, 8210120288
- 8210200045 Response to Yakima Indian Nation B20730 suppl to petition to intervene containing list of contentions Objects to Contentions 4-i0 Centificate of Svc encil THOMSEN.F T Puget Sound Power & Light Co THOMSEN.F T Perkins, Coix, Stone, Clasen & Williams B2/10/14 Atomic Bafety and Licensing Board Panel 15pp 15756 026 24X Fiche 50-322,82/10/14, B210200045

- 8210190373 Notice of withdrawal of appearance in proceeding Certificate of Svc encl BLACK.R L Hearing Branch 3 82/10/19 3pp 15741 211 24X Fiche 50~522.82/10/15.8210190373
- 8210200058 Response to 820910 first set of production requests
 Certificate of Svc encl Related Correspondence
 FRANTZ.S P Puget Sound Power & Light Co FRANTZ.S P
 Lowenstein Newman, Reis, Axelrad & Toil 82/10/15 Coalition for
 Safe Power 82pp 15753 093 24X Fichs 50-522,82/10/15,8210200058
- 8210220429 Response to Yakima Indian Nation 820930 suppl to petition to intervene setting forth contentions Contentions 1.2.3 & 6 should be admitted & consolidated w/similar contentions Certificate of Svc enci DEMEY.L S Hearing Branch 3 82/10/20 Atomic Safety and Licensing Board Panel 21pp 15780 190 24% Fiche 50-522.82/10/20,8210220429
- H General correspondence
- 8210220434 Requests all parties be informed of Natl Wildlife Federation & OR Environ Council correct address
 THATCHER: T L. National Wildlife Federation 82/10/19 Office of the Secretary of the Commission 1p 15778 269 24X
 Fiche 50-522, 82/10/19, 8210220434
- O Inspection reports. IE Bulletins & correspondence
- 820Bi90233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Beeds" Svc isst enci COBO.L 1 Olvision of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fichs 50-000,82/10/06,8208170233.
- 0208190238 IE Bulletin 82-03. "Atress Corrosion Cracking in Thick~Wali, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants " Svc list encl DEYOUNG, R C Director's Office. Defice of inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15010 125 24X Fiche 50-000, 82/10/14, 8208190238
- DOCKET STN-50-528 PALO VERDE NUCLEAR STATION. UNIT 1

 A Application/construction stage documents & correspondence
- 82i0180308 Notifies that commitment re accuracy of calibr stds per Amend 9 Page 17 2-56 not acceptable Justification should be provided or 2nd & 3rd paragraphs should be revised MIRADLIA.F J Licensing Branch 3 82/09/17 VAN BRUNT.E E Arisona Public Service Co 2pp. 15746 355 24X Fiche 50-528.82/09/17.8210180308
- --8209210413 Discusses branch position on Amend 9 to FBAR re revised commitment regarding accuracy of calibr stds Justification must be provided or commitment must be revised in order to be acceptable HAABB. WP Quality Assurance Branch 82/08/31 MIRAGLIA. F. J Licensing Branch 3 2pp 15746 357 24X Fiche 50-528.82/09/17.8210180308
- 8210120025 Discusses organizational arrangement for technical support of facility operation Updated arrangement should be provided by 82115 KERRIQAN.J D Licensing Branch 3 82/09/23 VAN BRUNT, E E Apriona Public Service Co 2pp 15689.187 24X Fiche 50-528,82/09/23.8210120025
- 8210180243 Forwards draft final nonradiological protection plan Comments requested KERRIOAN,J D Licensing Branch 3 82/09/23 VAN BRUNT,E E Florida Power & Light Co 2pp 15746 243, 24X Fiche 50-528,82/09/23,8210180243
- --8210180248 Draft final nonradiological environ protection plan 4 Licensing Branch 3 62/09/23 13pp 15746 245 24X Ficha 50-528,82/09/23,8210180243
- 8210210026 Forwards request for add1 info to complete review of "Probabilistic Risk Assessment of Tornado Missile Damage to Station UMS." Bechtel Staty 13-MS-10B KERRIGAN.J D Licensing Branch 3 82/09/29. VAN BRUNT, E E Arizona Public Bervice Co 4pp 15782 197 24X Fiche. 50-528, 82/09/29, 8210210026
- 8210060245 Forwards Revision i to "Pump & Valve Inservice Testing ProgrammPalo Verde Nuclear Generating Station " VAN BRUNT,E C Arisona Public Service Co 82/10/01 NOVAK, T Division of Licensing 2pp. 15620 243 24% Fiche 50-528,82/10/01. 8210060245

- --8210060247 "Pump & Valve Inservice Testing Program, Palo Verde Nuclear Generating Station." Revision 1 * Arizona Public Service Co 82/08/17 179pp 15620 245 24X Fiche 50-528, 82/10/01-2210060245
- 8210130143 Forwards application to amend CPPR-141.CPPR-142 & CPPR-143, extending const completion date for Unit 1 to 830831 VAN DRUNT,E E Arigona Public Service Co 81/10/12 Office of Nuclear Reactor Regulation. Director 3pp 15706 351 24X Fiche 50-528.82/10/12.6210150163
- --8210150176 Application to amend GPPR-141, CPPR-142 & CPPR-143, extending const completion date for Unit 1 to 830831 VAN BRUNTLE Aricona Public Service Co 82/10/12 7pp 15706 354 24X Fiche 50-528, 82/10/12.8210150163
- B210190717 Requests NRC review results of PMR design analyses to approve removal of pipe whip restraints Meeting w/NRC to discuss request 2 facilitate eichange of info & questions suggested VAN BRUNIF, E E Arizona Public Service Co 82/10/14 NOVAK, T M Assistant Director for Licensing 2pp 15738 211 24X Fiche 30-528 62/10/14, 8210190717
- 8210190463 Forwards responses to Auxiliary Sys Branch 820929 request for add1 info re probabilistic risk assessment of tornado missile damage to UHS VAN BRUNT,E E Arizona Public Service Co 82/10/15 NOVAK,T H Assistant Director for Litensing 9pp 15740 289 24X Fiche 50-528,82/10/15,8210190463
- 8210280057 Advises that util will provide comments on draft environ protection plam by 821129 VAN BRUNT.E E Artiona Public Service Co 62/10/21 NOVAK.T M Assistant Director for Licensing ip 15837 261 24X Fiche 50-528.82/10/21.8210280057
- 8210280139 Advises that util will respond by 821129 to NRC 820929 ltree schedule for resolution of remaining outstanding & confirmatory issues
 VAN BRUNT, E.E. Ariona Public Service Co. 82/10/21 OVAK, T.H.
 Assistant Director for Licensing (p. 15837-832, 24X
 Fiche 50-528, 82/10/21, 8210280139
- 8210280199 Forwards Proof of Svc for 821012 application to amend CPPR-141.CPPR-142 & CPPR-143
 VAN BRUNT, E E Arizona Public Service Co 82/10/21 Office of Nuclear Reactor Regulation. Director 3pp 15837 001 24X
 Fiche 50-528
- 8210270211 Forwards proposed amended pages to FBAR Section 6 2 b, providing Type C testing of valves associated w/Containment Penetrations 94,67 & 77 using air Affiday1t encl VAN BRUNT, E E Arizona Public Service Co 82/10/22 NDVAK, T H Assistant Director for Licensing 17pp 15829 318 24X Fiche 50-528,82/10/22,8210270211
- E NRC Safety Evaluation Report (SER). supple & correspondence
- 8210210500 Forwards SER, Suppl 3 *e OL application W/o encl KERRIOAN.J D Licensing Branch 3 82/09/23 VAN BRUNT, E E Arizona Public Service Cu Jap 15782 263 24x Fichs 50-528, 82/09/23, 8210210300

ETY EVALUATION REPORT RELATED TO THE OPERATION OF PALO R GENERATING STATION, UNITS 1, 2, AND 3 Docket GO-529, And 50-530 (Arliana Public Service

Regulation, Director NUREG-0857 803

'n 13 1 2 3 concerning

0/04 NOVAK, T H 50~528, 82/10/04,

Octobably invures or easign mods incorporated into listed drawings to provide two devices in series for adequate primary & backup protection of circuits Mods close SER confirmatory item discussed in Section B 4 3

VAN BRUNT. E Ariona Public Service Co B2/10/25 NOVAK, T M Assistant Director for Licensing, 2pp 15838 356 24X

Fiche 50-528,82/10/25,8210280274

- @ Adjudicatory correspondence
- 8210130417 Notice of corrections to Joint Applicants reply to PL Houriham proposed findings of fact & conclusions of law BISCHOFF.C A Joint Applicants-Palo Verde BISCHOFF.C A Bischoff C A 82/10/05 2pp 15680 224 24X Fiche 50-528.82/10/05. 8210130417
- --8210130486 Corrected pages to Joint Applicants reply to PL Hourishin proposed findings of fact & conclusions of law Certificate of Svc encl
 # Joint Applicants-Palo Verde 82/10/05 15pp 15680 226 .4g
- 0210130247 Forwards Suppl 3 to SER W/o encl DEMEY.L 5 Hearing Branch 3 82/10/13 LAZO,R M . COLE.R C . CALLIHAN, D Atomic Safety and Licensing Board Panel ip 15704 357 24% Fiche 50-528.02/10/13.0210130247
- 8210150497 Memorandum of law supporting West Valley Agricultural Protection Council Inc petition to intervene Substantial new info only recently discovered Certificate of Svc encl BERLIN.K Affiliation Unknown BERLIN.K Affiliation Unknown 82/10/13 Atomic Safety and Licensing Beard Panel 24pp 15713 207 24x Fiche 50-528,62/10/13,8210150499
- --8210150512 Petition of West Valley Agricultural Protection Councilial to intervene, request for preparation of supplemental or revised EIA & request for reopening record Certificate of Svc enci

 BERLIN,K Affiliation Unknown BERLIN,K Affiliation Unknown 82/10/13 Atomic Safety and Licensing Board Panel 300pp 15713 233 24X Fiche 50-528.82/10/13.8210150479
- 8210150474 Notices of appearance in proceeding Certificate of Bv. 81113 BERLIN,K., DERWIN,E F., LASOTA, J. Affiliation Unknown 82/10/14 4pp 15703 043 24X Fiche 50-528,82/10/14,8210150474
- B210270171 Motion for 2-wk extension of time to answer West Valley
 Agricultural Protection Council. Inc B21013 petition to
 intervene Complete petition not received Certificate of Syc
 encl
 BISCHOFF, C.A. Jaint Applicants-Paid Verde BISCHOFF, C.A. Bischute
 C.A. B2/10/22 Atomic Safety and Clicensing Board Panel hpp
 15822 349 24x Fichs 30-528.82/10/22.8210270171
- 8210290297 Response of Mest Valley Agricultural Protection Council to Joint Applicants 821022 motion for extension of time to answer Council petition to intervene Tenday extension should be granted Certificate of Svc enc!

 BERLIN, K. Affiliation Unknown 82/10/26 Atomic Safety and Licensing Beard Panel Opp 15853 160 24X Fiche 50-528.02/10/26.

 9210290297
- 8210280262 Brder granting Joint Applicants 821022 motion for extension of time to answer West Valley Agricultural Protection Council, Inc 821014 potition to Intervene Joint Applicants have 2 wks after evc of complete petition to file answer LAZO,R M Atomic 8afety and Licensing Board Panel 82/10/27 Joint Applicants-Palo Verde 2pp 15837 310 24X Fichs 50-528, 82/10/27.8210280262

M Antitrust correspondence

- 8210040292 Forwards page inadvertently omitted from first response to requirements contained in Reg Quide 7 3

 VAN BRUNTLE Artions Public Service Co 82/09/28 Office of Nuclear Reactor Regulation. Director 2pp 15587 138 24X

 Fichs 50-528,82/09/28,8210040292
- --B210040305 Forwards Sait River Project Agricultural Improvement & Fro District & AZ Public Svc Co revised responses to requirements contained in Reg Ouide 9 3 Corrected copy VAN BRUNTLE & Artiona Public Service Co B2/05/10 Office of Nociser Reactor Regulation: Director 9pp 15587, 140 24X Fiche 50-528,82/09/28,8210040292
- G Inspection reports, IE Bulletins & correspondence
- 9210090155 Responds to NRC 811119 itr re violations noted in IE Insp. Rept 50-528/81-12 on 810817-21 Corrective actions procedure for piping sys final insp. MPP/QCI No 2023, deleted & included in other procedures
 VAN BRUNTLE E Arizona Public Service Co 82/06/16 DIGHOP.T W Division of Resident, Reactor Project & Engineering Programs Opp. 13640-137, 24x Fichs 50-528,62/06/16.8210080155

1

- 21006034) Forwards IE Insp Rept 50-528/82-23 on 820823-0917 No noncompliance noted STERUBERG, D H Division of Resident, Reactor Project & Engineering Programs 82/09/23 ANDOGNINI.6 C Arizona Public Service Co 2pp 15619 046 24x Fiche 50-528.82/09/23.8210060341
- -8210060345 [E Insp Rept 50:528/82-23 on B20823-0917 No noncompliance nated Hajor areas inspected startup testing, document control.maint.startup dA % sys releases & organization FIGRELLI.G., JOHNSTION.G., YOUNG.T. Division of Resident, Reactur Project & Engineering Programs B2/09/22 Spp [5619-04B 44% Fiche 50-528, 82/09/23, 821006034]
- 0210060413 Forwards Relief Request 8 for exemption from preservice exam requirements.supplementing 820406 relief requests VAN DRUNT.E E Arizona Public Service Co 82/10/01 NOVAK.T N Assistant Director for Licensing 3pp 15615 007 24X Fiche 50-528.82/10/01.8210060413
- 6210070210 Provides corrected supplemental response to [E Bulletin B]-02. "Failure of Gate Type Valves to Close Against Differential Pressure " No Westinghouse Flectro Motor Div gate valves used in plant design Twenty-five manhours used VAN BRUNT.E E Arijona Public Service Co 82/10/01 ENGELKEN.R H Region 5. Office of Director 2pp 15634 264 24X Fiche 50-528.82/10/01.8210070210
- 6208190233 IE Info Hotice 80-35. Suppl 1: "Leaking & Disladged 1-125 [mplant Seeds " Svc list encl COOB L ! Division of Fuel Facilities. Materials % Safeguards 82/10/06 Consolidated Edisjn Co of New York 66pp 15761 250 24x Fiche 50-000.82/10/06.8208190233
- 8210130443 Commits to performing guide tube surveillance insp an representative bundles or first reload per NUREO-0852, Section 4 2 3 i VAN DRUHT, E E Arizona Public Service Co 82/10/06 NOVAK. 7 Assistant Director for Licensing 2pp 15682 013 24X Fiche 50-528.82/10/06.8210130443
- 6210220394 Corrected cupy of commitment to perform guido tubo wear surveillance insp described in NUREO-0852 Section 4 2 3 is per NUREO-0857 Section 4 2 5 leguiroment Commitment will be incorporated into neit FSAR amend VAN BRUNT, E E Alizona Public Service Co. 82/10/06 NDVAK, [Assistant Director for Licensing 2pp 15779 203 24X Fiche 50-526,82/10/06,8210270394
- 6210259351 Forwards IE Inap Repts 50-528/82-25,50-529/82-09 & 50-530/82-10 on 820830-0903 * notice of violation STERNBERG, D M Division of Resident, Feactor Project & Engineering Programs 82/10/08 VAN BRUNT, F E Artiona Public Service Co 2pp 15790 026 24X Fiche 50-528-82/10/08,8210250351
- --8210259361 Notice of violation from insp on 820830-0903 YOUNG T Division of Resident, Reactor Project & Engineering Programs 82/10/08 2pp 15790 028 24X Fiche 50-528.82/10/08, 8210250351
- --8210250375 IE Insp Rupts 50~528/82 25.50-529/82-09 & 50-530/82-10 on 820830-0903 Noncompliance noted 29 inches of wold metal found missing from control room panels & defective instrument repts not prepared ECKMARDIJ H. HERNANDEZ, 9. YOUNG, T. Division of Resident, Reactor Project & Engineering Programs 82/10/07 App 15790 030 24X Fiche 50-528 82/10/04,8210250354
- 8210280368 Forwards IE Insp Repts 30-520/82-26.50-529/82-10 & 50-530/82-11 on 820713-0903 No noncompliance noted STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 82/10/13 VAN BRUNT, E Arizona Public Service Co 2pp 15845 155 24X Fiche 50-528.82/10/13.8210280368
- --8210280372 IE Insp Repts 50-528/82-26.50-529/82-10 & 50-530/82-11 on 820713 0903 No noncompliance noted Major areas inspected const activities associated w/grouting of temporary underground pipting & containment post-tensioning VORDERORUEGGEN, YOUNG.T Division of Resident, Reactor Project & Engineering Programs 82/10/07 12pp 15845 157 24X Fiche 50-528,82/10/13.8210280368
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Bteinless Steel, Recirculation Sys Piping at BNR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 19pp 15810 125 24X Fichs 50-000, 82/10/14, 6208190238

R Pariodic operating reports & related correspondence

- B210120264 Forwards biweekly status rept of independent QA evaluation of Palo Verde Nuclear Generating Stations Units 1,2 & 3 for period 820711-24
 SIMON, WA Torrey Pines Technology 82/10/04 TURLEY, K.L. Arizona Public Service Co. 15pp. 15652-278. 24X Fiche 50-528, 82/10/04. 8210120264
- 8210220198 Forwards "Independent QA Evaluation of Palo Verde Nuclear Openerating Stations Units 1.2 & 3." Blueekly Status Rept 7 for period ending 821008 SIMON, WA Torrey Pines Technology 82/10/18 TURLEY, K L Arizon. Public Service Co ip 19776 211 24X Fiche 50-528,82/10/18,8210220198
- --B210220244 "Independent GA Evaluation of Palo Verde Nuclear Cenerating Stations Units 1.2 \$ 3." Blueckly Status Rept 7 for period ending 821008 4 Torrey Pines Technology 82/10/18 14pp 15776 212 24X Fiche 50-528,82/10/18

8 Reportable occurrences, LERs & related correspondence

- B210070321 Final deficiency rept re mounting failures of C-E supplied valve position indicating suitthes initially reported on 820535 Nenconformance Rept SE-0487/0542 dispositiened to rework broken brackets Not reportable per 10CFR50 55(e) VAN BRUNT.E E Arizona Public Service Co 82/09/09 STERNBERG.D M Division of Resident, Reactor Preject & Engineering Programs App 15634 117 24X Fiche 50-528,82/09/09,8210070321
- 8210070213 Interim Deficiency Rept DER 82-46 re ITT-Darten pressure transmitters failing to meet required overpressure range initially reported on 920824 C-E Issuing purchase order suppl te obtain correct transmitters Next rept by 821118 VAN BRUNT.E E Arizona Public Service Co 82/09/15 9TERNBERG.D N Divisien of Resident. Reactor Project & Englosering Programs 3pp 15634 258 24X Fiche 50-528,62/09/15,8210070213
- B210070229 Requests add1 time to submit Final Deficiency Rept DER B2-9 re thermowells in diesel generator lube oil sys by Cooper Energy not procured to ABME code Initially reported on B20316 info should be finallied by 821116 VAN BRUNT.E E Arizona Public Service Co 82/09/15 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp i3634 281 24% Fiche 50~528,82/09/15,8210070229
- B210070320 Final deficienty rept re weld procedure not prequalified by Ametek-Straza for reactor not leg pipe stops Initially reported on 820514 Roview of documentation rovaled no further deviations Item not reportable per 10CFR90 55(e) VAN BRUNT.E E Arizona Public Service Co 82/09/15 STERNDERO,D M Division of Resident. Reactor Project & Engineering Programs Spp 15624 114 24X Fiche 50-528.82/09/15.8210070320
- 8210070337 Interim Deficiency Rept DER 82-45 re unqualified motor operators installed w/C-E/Borg-Harner safety injection sys valves Initially reported on 820826 Motor operators returned to mfg for mod Next rept expected by 821117
 VAN BRUNTLE E Arizona Public Service Co 82/09/15 STERNBERG, D of Division of Resident, Reactor Project & Engineering Programs Upp 13634 068 24X Fiche 50-528,82/09/15,8210070339
- B210070374 Final Deficiency Rept DER 82-18 re Westinghouse pump motors initially reported on 820423 Notors found w/deteriorating epoxy coatings & metal particles in tube oil C-E determined incident not reportable per 10CFR50 35e VAN DRUNTICE Arizone Public Service Co 82/09/16 STERNDERG.D M Bivision of Resident, Reactor Project & Engineering Programs 5pp 15634 022 24% Fiche 50-528,82/09/16.8210070374
- 8210070394 Final deficiency rept re steam generators loose internal nuts & couplings Nonconformance repts will be dispositioned to repair defects to conform w/C-E drawing requirements Unit 2 & 3 will be inspected for similar defects VAN BRUNT.E E Aritona Public Service Co 52/09/21 STERNDERG.D M Division of Resident, Reactor Project & Engineering Programs 4pp 13634 055 24X Fiche 50-528,82/09/21,8210070354
- 8210330187 Interim deficiency rept re Dragon Valva Co instrument line check valves seized open by welding heat Initially reported on 820901 Corrective action plan under review Next rept will be provided by 821206
 VAN BRUNTLE E. Arizona Public Service Co 82/09/30 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 13674 131 R4X Fiche, 50-528, 82/09/30, 8210130187

- B210250100 Interim Deficiency Rept DER 82-50 no potential damage of flexible conduit couplings between auxiliary & control bldgs during seismic event initially reported on 820910 Bechtel establishing min acceptance criteria Final rept by 821230 VAN BRUNT.E E Arizona Public Service to B21070B STERNBERC, D M Division of Resident. Reactor Project & Engineering Programs Sept. 2012 State Stat 15787 111, 24x Fiche 50-528,82/10/08,8210250100
- 8210250305 Fina) Deficiency Rept DER 82-47 re stoom generator 2 pipe support welded to sway struts instead of attached by approved brackets initially reported on 820905 Beam attachments replaced w/sway strut rear end brackets VAN BRURT.E E Artiona Public Service Co 82/10/08 STERNBERG.D to Division of Resident. Reactor Project & Engineering Programs Spp 15790 094 24X Fiche 50-528,82/10/08.8210250305 STERNBERG, D H
- 8210250326 Interim Deficiency Rept DER 82-51 re Pullman-Kellogg pipe lining failure in essential cooling water sys Initially reported on 820910 Condition under evaluation Final rept expected by 021202 VAN BRUNT. E. E. Arisona Public Service Co. 82/10/08 STERNBERG, D. N. Division of Resident. Reactor Project & Engineering Programs Supp 15790-322 24X Fiche 50-528.82/10/08.8210250326
- 9240260275 Final Deficiency Rept DFR 82-19 re Class IF GF motor control ctr burned out due to damage during testing Noncomformance SE-0567 dispositioned to replace damaged components Test ne-upov elspusitioned to replace damages components lest procedures revised providing spec warning re diamage VAN BRUNT,E E Actiona Publis Service Co BEZ/10/14 STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs App 15803 222 24% Fiche 50-528.82/10/14/82/02/0275

DOCKET STN-50-529 PALO VERDE MUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8210180308 Notifies that commitment re accuracy of calibr stds per 210190303 Notifies that commitment re accuracy of calibr stds Amend 9 Pags 17 2-86 not acceptable Justification should be provided or 2nd & 3rd paragraphs should be revised HIRAOLIA, F.J. Licensing Branch 3 82/09/17 VAN BRUNT, E.C. Arijona Public Bervice Co. 2pp. 15746-395 24X Fiche 50-528, 82/09/17, 8210180308
- ~-B209210413 Discusses branch position on Amend 9 to FBAR re revised commitment regarding accuracy of calibr side Justification must be provided or commitment must be revised in order to be acceptable HANSS, W.P. Guality Assurance Granch 82/08/31 MIRAGLIA, P. J. Licensing Branch 3 2pp 15746-357 24% Fiche 50-528,82/09/17, HAASB, W.P.
- 8230120025 Discusses organisational arrangement for technical support of facility operation Updated arrangement should be provided by 821115 KERRIGAN. J B Licensing Branch 3 82/09/23 VAN BRUNT, E Arlione Public Bervice Co 2pp 15689 187 24X
 Fiche 50-528, 82/09/23, 8210120025
- 8210(80243 Forwards draft final nonradiological protection plan Comments requested
 KERRIGAN, J D Licensing Branch 3 82/09/23 VAN BRUNT, E E
 Florida Power & Light Co 2pp 15746 243 24X
 Fiche. 30-888. 82/09/23, 8210180243
- --B210180248 Draft final horradiciogical environ protection plan 4 Licensing Branch 3, 82/09/23 13pp 15746 245 24X Fiche 50-528,82/09/23,8210180243

- "" for add info to complete review of ant of Tornado Missile Damage to -NB-10B 92/09/29. VAN BRUNTIE E 15782 197 24X 3

- 8210060245 Forwards Revision i to "Pump & Valve Inservice Testing Program.Palo Verde Nuclear Generating Station "
 VAN BRUNT.E E Artrona Public Service Co 92/10/01 NOVAK.T Division of Licensing 2pp 15620 243 24X Fiche 50-528.82/10/01.
- --8210060247 "Pump & Valve Inservice Testing Program.Palo Verda Nuclear Congraphing Station " Restator 1

15620 245 24%

-142 & CPPR-143,

Defice of 51 24X

- -- B210150176 Application to amend CPPR-141.CPPR-142 & CPPR-143, enterdus Comst completion date for Unit I to 830831

 VAN BRUNT.E E ATITODA Public Service CO 82/10/12 7pp
 15706 354 24X Fiche 50-528.82/10/12.8210150163
- 8210190717 Requests NRC review results of PWR design analyses to approve removal of pipe whip restraints Meeting w/NRC to discuss request & facilitate eichange of info & questions Suggested

 VAN BRUNTLE E Artiona Public Service Co 82/10/14
 Arsistant Director for Licensing 2pp 15738 211
 Fiche 50-528, 82/10/14,8210190717 82/10/14 NOVAK, 1 M 5738 211 24%
- 8210190463 Forwards responses to Auxiliary Sys Branch 820929 request for addl info re probabilistic risk assessment of tornado missile demage to UHS

 VAN DRUNITE E Arizona Public Service Co. 82/10/15 NOVAK, | H
 Assistant Director for Licensing 9pp 15740 289 24X

 Fiche 50-528 82/10/15.8210190463
- 9210280057 Advises that util will provide comments on draft environ protection plan by 821129

 VAN BRUNTLE E Aftrona Public Service Co 82/10/21 A Assistant Director for Licensing ip 15837 261 24X Fiche 50-528.82/10/21-8210280037
- 8210280139 Advises that util will respond by 821129 to NRC 820929 line reschedule for resolution of remaining outstanding & confirmatory issues VAN BRUNT.E E Arizona Public Service Co DVAK. T H Assistant Director for Licensing ip 15837 133 24X Fiche 50~528, 82/10/21, 8210280139
- B210280199 Forwards Proof of Svc for 821012 application to amend CPPR-141: CPPR-142 & CPPR-143 VAN BRUNT,E E Aritona Public Service Co 82/10/21 Office Nuclear Reactor Regulation. Director 3pp 15837 001 24X Fiche 50-528, 82/10/21, 8210280199
- 8210270211 Forwards proposed amended pages to FSAR Section 6 2 6. providing Type C testing of valves associated w/Containment Penetrations 44,67 & 77 using air Affidavit enc! VAN BRUNT.E E Arizona Public Service Co 82/10/22 NOVAP. (H Assistant Director for Licensing 17pp 15829 318 24x Fiche 50-528.82/10/22.821027021
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8210210500 Forwards SER, Suppl 3 re OL application W/o encl KERRIGAN, J D Licensing Branch 3 82/09/23 VAN DRUNT, E E Arizona Public Service Co 3pp 15782 263 24X Fiche 50-528, 82/09/23, 8210210500
- 8210060006 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PALG VERDE NUCLEAR GENERATING STATION, UNITS 1.2, AND 3 Docket No. 50~528,50-529, And 50-530 (Aprilona Public Service Company, et al) Company Rt ea , 4 Office of Nuclear Reactor Regulation, Director NUREO-085/ 503 82/09/30 3Bpp Available at NRC \$4.75 15636 268 24X Fiche 50-528, 82/09/30, 8210060006
- 8210190315 Advises that position re SER. Section 13 1 2 3 concerning operations superintendent not filled Resume will be forwarded to NRC when position is occupied VAN BRUNT. E E Arizona Public Service Co 82/10/04 NOVAK, T H Division of Licensing 2pp 15742 146 24% Fiche 50-528.82/10/18210190315
- 8210280274 Informs of design mods incorporated into listed drawings provide two devices in series for adequate primary & backup protection of circuits Mods close SER confirmatory item discussed in Section 8 4 3 VAN BRUNT, E. E. Arisona Public Service Co. 82/10/25 NOVÁK, T. H. Assistant Director for Licensing 2pp 15838 356 24X Ficha 50-528.82/10/25.8210280274
- G Adjudicatory correspondence
- 8210130417 Notice of corrections to Joint Applicants reply to Pt. Hourthan proposed findings of fact & conclusions of law BISCHOFF, C.A. Joint Applicants-Palo Verde BISCHOFF, C.A. Bit C.A. 82/10/05, 2pp 15680 224 24X Fiche 50-528,82/10/05. Bitt
- --B210130486 Corrected pages to Joint Applicants reply to PL Hours proposed findings of fact & conclusions of law Certificate of Byc encl 4 Joint Applicants-Palo Verde 82/10/05 15pp 15680 22& Fiche. 50-528, 82/10/05, 8210130417

- \$210150247 Forwards Suppl 3 to SER W/o encl DENEYLL S Hearing Branch 3 82/10/13 LAZO,R M . COLE.R F . CALLIHAN D Atomic Safety and Licensing Board Panel 1p 15704 337 24% Fithe 50-528,82/10/13.8210150247
- B210150499 Memorandum of law supporting West Valley Agricultural Protection Council Inc petition to intervene Substantial new info only recently discovered Certificate of Svc enci 3EALIN.K Affiliation Unknown BERLIN.K Affiliation Unknown B2/10/13 Atomic Safety and Licensing Board Panel 24pp 15713 209 24% Fiche 50-528,82/10/13.8210150499
- -a210150512 Petition of West Valley Agricultural Protection Council, Inc to intervene, request for preparation of supplemental or revised EIA & request for reopening record Certificate of Svc encl BERLIN, Affiliation Unknown BERLIN, K Affiliation Unknown
 - 82/10/13 Atomic Safety and Licensing Board Panel 300pp 15713 233 24% Fiche 50-528,82/10/13,8210150499
- 8210150474 Notices of appearance in proceeding Certificate of Syc enci BERLIN.K., GERWIN.E.F., LASOTA.J. Affiliation Unknown B2/10/14 4pp 15703 043 24X Fiche 50~528.62/10/14.6210150474
- 6210270171 Motion for 2-wk extension of time to answer West Valley Agricultural Protection Council, Inc. 821013 position to intervene Complete petition not received Certificate of Sycientics.
 - BISCHOFF, C A Joint Applicants-Palo Verde BISCHOFF, C A Bischoff, C A 82/10/22 Atomic Safety and Licensing Board Panel 5pp 15822 349 24X Fiche 50-\$28.82/10/22.8210270171
- 8210290297 Response of West Valley Agricultural Protection Council to Joint Applicants 821022 motion for extension of time to amswer Council petition to intervene Tenday extension should be greated Certificate of Svc encl
 BERLIN.K Affiliation Unknown 82/10/26 Atomic Safety and Licensing Board Panel App 15853 160 24% Fiche 50-528,82/10/26,8210290297
- 8210280262 Order granting Joint Applicants 021022 motion for extension of time to answer West Valley Agricultural Protection Council Inc 021014 petition to intervene Joint Applicants have 2 uts after svc of Complete petition to file answer LAZDAR H Atomic Safety and Licensing Noard Panel 02/10/27 Joint Applicants/Palo Verde 2pp 15037 310 24% Fiche 50-528, 62/10/27, 6210280262

M Antitrust correspondence

- 8210040292 Forwards page inadvertently omitted from first response to requirements contained in Reg Guide 7 3
 VAN BRUNTLE E Arizona Public Service Co 82/09/28 Office of Nuclear Reactor Regulation, Director 2pp 15597 138 24X
 Fishe 50-528, 62/09/28, 6210040292
- --8210040305 Forwards Salt River Project Agricultural Improvement & Power District & AZ Public Svc Co revised responses to requirements contained in Reg Guide 9 3 Corrected copy VAN BRUNTLE E Arizona Public Bervice Co 82/05/10 DFFice ut Huclear Reactor Regulation, Director 9pp 15587 140 24X Fiche SO-52B, 82/09/28, 8210040292
- O Inspection reports: IE Duiletins & correspondence
- 621007021Q Provides corrected supplemental response to IE Builetin 81-02, "Failure of Gate Type Valves to Close Against Differential Pressure "No Westinghouse Electro Motor Div gate valves used in plant design Tuenty-five manhours used VAN BRUNT, E E Arizona Public Service Co 82/10/01 ENGELKEN, R H Region 5, Office of Director 2pp 15634 264 24X Fiche 50-528, 82/10/01, 8210070210
- 8208190233 IR Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 Inplant Seeds " Svc list enc! CODB.L I Division of Fuel Facilities, Materials & Safeguards 62/10/06 Consolidated Edison Co of New York 66pp 1576i 250 24/ Fiche 50-000,82/10/06.8208190233
- 8210250351 Forwards IE Insp Repts 50-528/82-25,50-529/82-09 & 50-530/82-10 on 820830-0903 & notice of violation STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 82/10/08 VAN BRONT, E Arizona Public Service Co 2pp 15790 026 24X Fiche 50-528,82/10/08,8210250351
- --8210250261 Notice of violation from insp on 820830-0903 YOUNG.T Division of Resident, Reactor Project & Engineering Programs, 82/10/08 2pp 15790 028 24X Fiche 50-528,82/10/08, 8210250351

- --8210250375 IE Insp Repts 50-528/82-25.50-529/82-09 & 50-530/82-10 on 820830-0903 Noncompliance noted 27 Inches of weld metal found missing from control room panels & defective instrument repts not prepared ECKMARDT.J H. HERNANDEZ,G. YOUNG,T. Division of Resident, Reactor Project & Engineering Programs 82/10/07 App 15790 030 24X Fiche 50-528,62/10/08.8210250351
- 8210280368 Forwards iE insp Repts 50-528/82-24.50-529/82-10 & 50-520/82-11 on 820713-0903 No noncompliance nated STERNBERG. D M Division of Resident. Reactor Project & Engineering Programs. 82/10/13 vAn BRUNT. EE Arizona Public Service Co 2pp 15845 155 24% Fiche 50-528.82/10/13.8210280368
- --8210280372 IE Insp Repts 50-528/82-26,50-529/82-10 & 50-530/82-11 on 820713-0903 No noncompliance noted hajor areas inspected const activities associated w/grouting of temporary underground piping & containment post-tensioning VORDERURUECOEN, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/10/07 12pp 15845 157 24X Fiche 50-528,82/10/13,8210280368
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wali, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000,82/10/14,8208190238
- A Persodic operating reports & related correspondence
- 8210120264 Forwards biweekly status rept of independent QA evaluation of Palo Verde Nuclear Operating Stations Units 1.2 & 3 for period 820711-24
 61MON-W A Torrey Pines Technology 82/10/04 TURLEY.K L Arizona Public Bervice Co 15pp 15652 278 24X Fiche 50-528,82/10/04,8210120264
- 8210220198 Forwards "Independent OA Evaluation of Palo Verde Nuclear Generating Stations Units 1.2 & 3," Biweekly Status Rept 7 ton period ending 821008 SIMON, WA Torrey Pines Technology 82/10/18 TURLEY, K. L. Arizon, Public Service Co. ip 15776 2[1 24X Fichs 50-528, 82/10/18, 8210220198
- --82:0220244 "Independent OA Evaluation of Palo Verda Nuclear Generating Stations Units 1.2 & 3." Biweekly Status Rept 7 for period ending 82:008

 * Torrey Pines Technology 82/30/18 14pp 15776 212 24X
 Fiche 50-528.82/10/18.8210220198
- S Reportable occurrences. LERs & related correspondence
- 8210070391 Interim Defictioncy Rept DER 82-43 re improperly crimped termination lugs on Comstp main control panels Initially reported on 820813 Extensive investigation & evaluation underway Final rept expected by 821212

 VAN BRUNT, E E Arizona Public Service Co 82/09/09 STERNDERO, D M Division of Resident, Reactor Project & Engineering Programs Spp 15663 343 24x Fichs 50-529, 82/09/09, 8210070391
- 8210070229 Requests add1 time to submit Final Deficiency Rept DER 82-9 re thermowells in diesel generator lube oil sys by Geoper Energy not procured to AGME code Initially reported on 820314 info should be finalized by 821116 VAN BRUNT.E E Arizona Public Bervice Co 82/09/15 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 15634 281 24% Fichs 50-528.82/09/15.82/0070229
- 8210070320 Final deficiency rept re weld procedure not prequalified by Ametek-Straza for reactor hot leg pipe steps initially reported on 820514 Review of documentation revealed no further deviations Item not reportable per 10CFRSO 55(a) VAN BRUNT,E E Arizone Public Bervice Co 82/09/15 STERNBERG,D M DAVISION of Resident, Reactor Project & Engineeping Programs Spp 15634 114 24X Fiche 50-526.82/09/15.8210070320
- 8210070339 Interim Deficiency Rept DER 92-45 re unqualified motor operators installed w/C-E/Borg-Marner safety injection system valves initially reported on 820826 Motor operators returned to mfg for mod Next rept expected by 82:117
 VAN BRUNT,E E Arizona Public Service Co 82/09/15, SYERNBERG,D M Division of Resident Reactor Project & Engineering Programs Spp 13634 048 24X Fiche 50-528,82/09/15,8210070339
- 9210130495 Final deficiency rept re law pressure safety injection & containment spray pump casing hold-down bolts under-torqued Condition determined not regartable per 10CFR50 55(e) VAN BRUNT, E E Arizona Public Service Co 92/09/29 STERNBERG, D M Division of Residents Reactor Project & Engineering Programs. 4pp 154802 165 24X Fiche 50-529,82/09/29.8210130495

- 8210130544 Revised interim deficiency rept re Pullman pipe for main feedwater lines w/multiple linear indications or laminations Final rept will be submitted by 821123 VAN DRUNT,E E Arizona Public Service Co. 82/09/30 STERNBERG,D M Division of Resident. Reactor Project & Engineering Programs App 15692 283 24X Fiche 50-529,82/09/30,8210130544
- DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 82i0180308 Notifies that commitment re accuracy of calibr stds per Amend 9 Page 17 2-55 not acceptable Justification should be provided or 2nd & 3rd paragraphs should be revised MIRACLIA, F J Licensing Branch 3 82/09/17 VAN BRUNT, E E Arizona Public Service Co 2pp 15746 355 24X Fithe 50-528.82/09/17.82i0180308
- --B209210413 Discusses branch position on Amend 9 to FBAR re revised commitment regarding accuracy of calibr stds Justification must be provided or commitment must be revised in order to be acceptable

 HAASS.W P Quality Assurance Branch 82/08/31 MIRAGLIA.F J
 Licensing Branch 3 2pp 15746 357 24X Fiche 50-528.82/09/17, pp. 10.10748
- 8210120025 Discusses organizational arrangement for technical support of facility operation Updated arrangement should be provided by 821115
 KERRIGAN.J D Licensing Branch 3 82/09/23 VAN BRUNT.E E Arizona Public Service Co 2pp 19689 187 24X
 Fiche 50-528.82/09/23.8210120025
- 8210180243 Forwards draft final nonradiological protection plan Comments requested KERRIGAN, J Licensing Branch 3 82/09/23 VAN BRUNT, E E Florida Power & Light Co 2pp 15746 243 24X Fiche 50-528,82/09/23,8210180243
- --821018024B Draft final nonradiological environ protection plan + Licensing Branch 3 82/09/23 13pp 15746 245 24X Fich: 50-528, 82/09/23 8210180243
- B210210026 Forwards request for add1 info to complete review of "Probabilistic Risk Assessment of Tornado Missile Damage to Station UHS." Bechtel Study 13-NS-109
 KERRIGAN, J D. Licensing Branch 3 B2/09/29 VAN BRUNT, E E Abizona Public Service Co. 4pp. 15782 197 24X
 Fiche 50-528.82/09/29.8210210026
- 8210060245 Forwards Revision 1 to "Pump & Valve Inservice Testing Program, Paio Verde Nuclear Generating Station "
 VAN BRUNT, E E Artiona Public Service Co 82/10/01 NOVAK, T Division of Licensing 2pp 15620 243 24X Fiche 50-528, 82/10/01. 8210060245
- --8210060247 "Pump & Valve Inservice Testing Frogram, Palo Verde Nuclear Generating Station," Revision 1 Antiona Public Service Co 82/08/17 179pp 15620 245 24X Fiche 50-528, 82/10/01, 8210060245

- 0210280057 Advises that util will provide comments on draft environ protection plan by 021129
 VAN BRUNTLE E Arizona Public Service Co 082/10/21 NOVAK. f M Assistant Director for Licensing p 15837 261 24X Fiche 50-528. 82/10/21.0210.021020057
- 8210280139 Advises that util will respond by 821129 to NRC 820929 its re-schedule for resolution of remaining outstanding & confirmatory issues

 VAN BRUNT, E E Artione Public Service CO 82/10/21 BVAK. FH Assistant Director for Licensing 1p 15837 133 24X

 Fiche 80-528.82/10/21.8210280139
- 0210200199 Forwards Proof of Svc for 821012 application to amend CPPR-141, CPPR-142 & CPPR-143 VAN BRUNT, E. E. Arizona Public Service Co. 82/10/21 Office of Nuclear Reactor Regulation, Director Jpp. 15837 001 24X Fiche 50-528, 82/10/21, 8210280199
- 8210270211 Forwards proposed amended pages to FSAR Section 6.2 b. providing Type C testing of volves associated w/Containment Penetrations 44.67 k.77 using air Affidavit encl VAN BRUNT, E.E. Ariiona Public Service Co. 62/10/22 NOVAK, 7 K.Assistent Director for Licensing 17pp i5929 318 24X Fiche 50-528, 82/10/22, 82/0270211
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8210210500 Forwards 8ER, Suppl 3 to OL application W/o ent]
 KERRIOAN, J D Licensing Branch 3 82/09/23 VAN GRUNT, E E
 Arizona Public Service Co 3pp 15782 263 24X
 Fichs 50-528, 82/09/23, 8210210500
- B210060006 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PAID VERDE NUCLEAR GENERATING STATION UNITE 1.2. AND 3 Docket Nos \$0-528,50-529, And 50-530 (Arizona Public Service Company, et ai)

 # Bffice of Nuclear Reactor Regulation. Director NUREO-0857 bol 82/09/30 38pp Available at NRC \$4.75 15636 268 24X Fiche 50-528,82/09/30,8210060006
- 8210190315 Advises that position re SER. Section 13 1 2 3 concerning operations superintendent not filled Resume will be forwarded to NRC when position is occupied VAN BRUNT.E E Artiona Public Service Co 82/10/04 NOVAK. I II Division of Licensing 2pp 15742 146 24X Fiche 50~520.82/10/04, 8210190315
- B210280274 Informs of design mods incorporated into listed drawings to provide two devices in series for adequate primary & backup protection of circuits Mods close SER confirmatory item discussed in Section 8.4.3

 VAN BRUNT, E.E. Arizona Public Service Co. B2/10/25 NOVAK, T.H. Assistant Director for Licensing 2pp. 15838-356. 24X

 Fichs 50-528,82/16/25,8210280274
- G Adjudicatory correspondence
- 8210130417 Notice of corrections to Joint Applicants reply to PI Hourikan proposed fundings of fact & conclusions of law BISCHOFF, C A Joint Applicants-Palo Verde BISCHOFF, C A Bischeff, C A 82/10/05 2pp 15680 224 24X Fiche 50-528,82/10/05,82/10/05
- --B210130486 Corrected pages to Joint Applicants reply to Pt Hourihan proposed findings of fact & conclusions of law Certificate of Svc entl
 4 Joint Applicants-Palo Verde 82/10/05 15pp 15680 226 .4: Fichs 50-928,82/10/05,8210130417
- B210150247 Forwards Suppl 3 to SER W/o encl DENEY, L B Hearing Branch 3 82/10/13 LAZO,R M . COLE,R F . CALLIHAN, D Atomic Safety and Licensing Board Panel Ip 15704 357 24X Fiche 50-528.82/10/13,8210150247
- 82:0150499 Memorandum of law supporting West Valley Agricultural Protection Council, Inc petition to intervene Bubstantial new info only recently discovered Certificate of Svc encl BERLIN,K Affiliation Unknown, BERLIN,K Affiliation Unknown 82:10/13 Atomic Safety and Licensing Board Panei 24pp 15713 209 24X Fiche 50-528.82/10/13,8210150499
- --9210150512 Petition of West Vailey Agricultural Protection Council; to intervene, request for preparation of supplemental or revised EIA & request for reopening record Certificate of Syc enci
 BERLIN.K Affiliation Unknown BERLIN.K Affiliation Unknown B2/10/13 Adonic Safety and Licensing Board Panel 300pp
 18713 233 24X Fiche 50-528, 82/10/13.8210150499

DOCKETED ILLINS

- GR10150474 Notices of appearance in proceeding Certificate of Svc encl GERLIN.K., GERMIN.E.F., LASOTA, J. Affiliation Unknown 62/10/14 App. 15703 043 24% Fiche 50-528/82/10/14/8210150474
- 8210270171 Metion for 2-wk extension of time to answer West Valley Agricultural Protection Council Inc 821013 petition to invervee Complete petition not rerelived Certificate of Sycencl EISCHOFF.C A Joint Applicants-Palo Verde BISCHOFF.C A Bischoff. C A 82/10/22 Atomic Safety and Licensing Board Panel Syp 1992 347 24% Fichs 50-528 82/10/22,82102/0171
- 9210290297 Rasponse of Nest Valley Agricultural Protection Council to Join' Applicants 821022 motion for extension of time to answer Council petition to intervene Ten-day extension should be granted Certificate of Svc encil BERLINIA Affiliation Unknown 82/10/26 Atomic Safety and Licensing Board Panel 6pp 15853 160 24X Fiche 50-528,82/10/26,6210290297
- 8210280262 Order granting Joint Applicants 821022 motion for extension or time to answer West Valley Agricultural Protection Council Inc 821014 petition to intervene Joint Applicants have 2 ats after svr of complete petition to file answer LAZOR M Atomic Safety and Licensing Board Panel 82/10/27 Joint Applicants-Palo Verde 2pp 15837 310 24X Fiche 50-528.82/10/27.8210280262
- m Antitrust correspondence
- GRICO40292 Forwards page inadvertently omitted from first response to requirements contained in Reg Ouide 9 3 VAN BRUNTLE E Arizona Public Service Co 82/09/28 Office of Nuclear Reactor Regulation, Director 2pp 15587 138 24X Fiche 50-528, 82/09/28, 8210040292
- --8230040305 Forwards Salt River Project Agricultural Improvement & Power District & AZ Public Svc Co revised responses to requirements contained in Reg Guide 9 3 Corrected copy VAN BRUNT. E E Arizona Public Service Co 82/05/10 Office of Huclear Reactor Regulation, Director 9pp 1558/140 24X Fiche 50-528,82/09/28,8210040292
- @ Inspection reports, 1E Bulletins & correspondence
- 6210070210 Provides corrected supplemental response to 1E Bulletin BI-02. "Failure of Gate Type Valves to Close Against Differential Pressure " No Westinghouse Electro Motor Div gate valves used in plant design Twenty-five manhours used VAN BRUNT, E Arizona Public Bervice Co B2/10/01 ENGELKEN. R II Region 5. Office of Director 2pp [3634 264 24X Fiche 50~528.82/10/01.8210070210
- 8208170233 IE Info Notice BO-35, Suppl L. "Loaking & Dislodged I-12: implant Seeds: Svc list enc! COSS,L L Division of Fuel Facilities, Materials & Safeguards 82/10/04 Consolidated Edison Co of New York & App. 15761 250 244 Fich 50-00 82/10/04,0208190233
- 8210250351 Forwards IE Insp Repts 50-528/82-25.50-529/82-09 & 50-530/82-10 on 820830-0903 & notice of violation SERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/10/08 VAN IRNNT, E C Artiona Public Service Co 2pp 18790 026 24% Fiche 50-528.82/10/08.8810250351
- --B210250375 IE Insp Repts 50-528/82-25.50-529/82-09 % 50-530/82-10 un 820830-0903 Mancompliance noted 29 inches of weld metal found missing from control room panels & defective instrument repts not prepared ECKMARDI.J H. HERNANDEZ, O. YOUNG, T. Division of Resident. Reactor Project & Engineering Programs 82/10/07 App 15790 030 24X Fiche 50-528.82/10/08.8210250351
- 8210280368 Forwards IE Insp Repts 50-528/82-26.50-529/82-10 & 50-530/82-f1 on 820713-0903 No noncompliance noted STERMSERO.D M Division of Resident, Reactor Project & Engineering Programs 82/10/13 VAN DRUNT, E E Arizona Public Service to 2pp 15845 155 24X Fiche 50-528-82/10/13.8210280368
- --0210280372 IE insp Repts 50-528/82-22,50-529/82-10 & 50-530/82-11 on 820713-0903 No noncompliance noted Major areas inspected const activities associated w/grouting of temporary underground piping & containment post-tensioning VORDERBRUEGGEN, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/10/07 12pp 15848 137 24X Fiche 50-528,82/10/13,8210280368

- 8208190238 IE Bulletin 82-03, "Stress Corrosson Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recarculation Sys Piping at BWR Plants " Svc list enct DEYOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000, 82/10/14-8208190238
- R Periodic operating reports & related correspondence
- 8210120264 Forwards biweekly status rept of independent QA evaluation of Palo Verde Nuclear Generating Stations Units 1.2 & 3 for period 820911-24

 SIMON: H A Torrey Pines Technology 82/10/04 TURLEY, K L Arizona Public Service Co 15pp 15652 278 24X Fiche 50-528.82/10/04, 82/10/0264
- 8210220198 Forwards "Independent GA Evaluation of Palo Verde Nuclear Generating Stations Units 1.2 & 3," Biweekly Status Rept 7 for period ending 821008 SIMON.W A Torrey Pines Technology 82/10/18 TURLEY, K L Arison. Public Service Co 1p 15774 21(24X Fiche 50-528.82/10/18.
- --B210220244 "Independent GA Evaluation of Palo Verde Nuclear Generating Stations Units 1.2 % J." Biweekly Status Rept 7 for period ending S21008

 * Torrey Pines Technology 82/10/18 14pp 15776 212 24X Fichs 30-528, 82/10/18, 8210220198
- S Reportable occurrences. LERs & related correspondence
- 8210070219 interim Defictency Rept DER 82-44 re ITE-Gould load ctrs w/mproperty crimped ampere termination lugs Initially reported on 820813 Bechtei pursuing matter w/Gould Brown Boverl to determine disposition Next rept by 821207 VAN BRUNT.E E Ariona Public Service Co 82/09/09 STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs 2np 15437 163 28X Fichs 50-530,82/09/09,8210070219
- 8210070229 Requests add1 time to submit Final Deficiency Rept DER 82~9 re thermowells in dissel generator lube oil sys by Cooper Energy not procured to ASME code Instituting reported on 820316 Info should be finalized by 821116 VAN DRUNT, E E Arizone Public Service Co 82/09/15 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs App 15434 281 24X Fiche 50-528,82/09/15,8210070229
- 8210070320 Final deficiency rept re weld procedure not prequalified by Ametek-Straza for reactor hot leg pipe stops initially reported on 820514 Review of documentation revealed no further deviations item not reportable per 100FRSD 55(e) VAN DRUNT, E E Arziona Public Service Co 82/09/15 STERNBENO, D M Division of Resident, Reactor Project & Engineering Programs 13pp 15634 114 24X Fiche 50-528,82/09/15,8210070320
- 8210070339 Interim Deficiency Rept DER 82-45 re unqualified motor operators installed w/C-E/Borg-Warner safety injection systalves initially reported on 820826 Motor operators returned to mfg for mod Next rept expected by 821117

 VAN BRUNT, E E Arizona Public Service Co 82/09/15 STERNBERG, B M Division of Resident, Reactor Project & Engineering Programs Dpp 15634 048 24X Fiche 50-528,82/09/15,8210070339
- 8210130446 Fine; Deficiency Rept DER 81-55 re const svc water line leak under auxiliary bldg Initially reported on 820105 Foundation of auxiliary bldg not adversely affected All temporary air, water & gas lines near Category | bldgs taken out of svc VAN BRUNT, E E Aritona Public Bervice Co. 82/07/27 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 4pp 15682 015 24X Fiche 50-530,82/07/29.8210130446
- B210130491 Interim deficiency rept re Puliman 24-inch pipe spools winternal surface indications violating min wall thickness initially reported on B20831. Bechtel Engineering investigating cause Final rept will be submitted by B21119 VAN BRUNT.E E Arizona Public Service Co B2/09/30 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs App 15682 115 24X Fiche 50-530.82/09/30.8210130491
- B210130544 Revised interim deficiency rept re Pullman pipe for main feedwater lines w/multiple limear indications or laminations final rept will be submitted by B21123 VAN DRUNT, E E Ariona Public Service Co B2/09/30 STERNBERO.D M Division of Resident, Reactor Project & Engineering Programs 4pp 15682,283 24% Fiche 50-529,82/09/30.8210130544

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

- A Application/construction stage documents & correspondence
- 8210120103 Addl response to FDIA request for nine categories of records generated by present HRC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents

 FELYON, J H Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 3pp 15690 117 24x

 Fiche 50-000, 82/07/12, 8210120103
- --9210120140 Agrees w/recommendation that Commission adopt modified DDF schedule circulated at 811216 meeting Forwards changes to schedule for Commission review of Section 50 12 request for CRBR ROBERTS.T M Commissioners 81/12/21 PALLADING.N , GILINSKY,V , BRADFORD.J Commissioners 200 15690 133 24X Fiche 50-000,82/07/12.8210120103
- --8210120143 Dbjects to action outlined in Commissioner Gilinsky 8112.41 memo no CRBR licensing exemption ROBERTS, TH Commissioners 81/12/22 PALLADING, N., GILINSKY, V., BRADFORD, J. Commissioners 2pp 15690 135 24X Fiche 30-000, 82/07/12, 8210120103
- 8210070029 Partial response to FDIA request for documents re CRBR E15 & all comments, evaluations & documents from BNWL re EIS Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/16 WEISS, E R Harmon & Weiss 8pp 15648 004 24x Fiche 50-537,82/07/16, R210070299
- --B210070039 Forwards updated schedule for CRER environ review HURT, D NRC No Detailed Affiliation Given 82/04/29 MULLEN.S. GASKIN, C. JUNES, B NRC No Detailed Affiliation Given 2pp 15448 014 24% Fisch 50-537,82/07/14,8210070029
- --82(0070070 Discusses lead of responsibilities for CRBR fuel cycluenviron review Overall schedule should be established for NMSS for inclusion of executive operating plan
 DAVIS.J G NRC No Detailed Affiliation Given 82/02/12
 CUMNINGHAM, R E NRC NO Detailed Affiliation Given 2pp
 15640 028 24X Firms 50-537, 82/07/16, 8210070029
- --B210070071 Advises that continued delay of DDE environ input will result in schedule compression for CRBR fuel cycle environ review DAVIS-JO Office of Nuclear Material Safety & Safeguards, Director 82/02/12 DENTON, HR Office of Nuclear Reactor Regulation, Director 10 1548 030 24X Fiche 50-537, 82/07/14, 8210070029
- --B2100700B4 Requests contentions for CRBR licensing which have implications in areas of fuel cycle-safeguards & waste most discussed during 81070A meeting LOWENDERO, H Office of Nuclear Material Safety & Safeguards, Director 81/10/09 CHECK.P S Clinch River Breeder Reactor Program Defice 3pp 15648 033 24% Fiche 50-537, 82/07/16, 8210070029
- --8210070089 Ack receipt of 811020 members CP review schedule Severe problems in meeting deadlines anticipated due to time constraints & personnel limits LOWENBERO. H Office of Nuclear Material Safety & Safeguards, Director 81/10/23 CHECK.P S Clinch River Breeder Reactor Program Office 2pp 15448 036 24X Fiche 50-537.82/07/16.8210070029

review of CP application activities in response to late schedula dates impossible ""structure of internat

> led Affiliation Given 81/11/02 fillation Given 2pp 15648 03B

- --82[007010] Advises that R Browning will be contact for Div of Waste Mgt & T Johnson & R Boyle will provide technical review for low level & high level waste matters re CRBR fuel cycle review MARTIN. J B NRC No Detailed Affiliation Given 82/02/10 CUMMINGHAM. R NRC No Detailed Affiliation Given Ip 15448 047 24% Fiche 50-537, 82/07/16.8210070029
- --82(0070118 Provides info re resources allocated to CRBR as of Bauliji in response to 820511 request BROWN R S Program Support Branch 82/05/12 WINNINGHAM, J Resource Analysis Branch 1p 15648 052 24X Fiche 50-537, 82/07/16. 82(0070027
- --8210070151 Provides guidance to standardize resumes of starf member consultants who may participate in environ review hearings. J Dee educational & prof qualifications encl.

 LOMENBERO.H Office of Nuclear Material Safety & Safeguards. Director 82/03/26 DROWNING.R E Division of Wart Management DUBE.R J Division of Safeguards MACEDINALD.(1 Transportation Branch 2pp 15448 194 24% Fiche 50-517. 82/07/16.8210070029
- --8210070157 Discusses resource utilization for CRBR fuel cycle inviperiew Projected expenditures for remainder of FY82 provided (DERNBERO:H Office of Nuclear Material Safety & Safeguards, Director 82/07/02 DAVIS.J G Office of Nuclear Material Safety & Safeguards. Director 2pp 15649 178 24X Fiche 50-537, 82/07/14.8210070027
- --82)0070163 Provides highlights for wk ending 820618 re CRBR funt anviron review Minor corrections to FES update submitted to CRBR program ofc LONENDERG. H. Office of Nuclear Material Safety & Safeguards. Director 82/06/24 DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director Ip 15648 200 20X Fiche 50-537, 02/07/16, 0210070029
- --8210070179 Provides highlight items for CRDR fuel cycle environ is for uk ending 820604 Discovery items requiring input received on 820604 CWMINGHAM R E Division of Fuel Cycle & Material Safety 82/06/07 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director ip 15448 232 24X Fiche 50-537.62/07/1/8210070029
- --8210070182 Provides highlight items re CROR fuel cycle environ reafor ut ending 820521 Collection & resolution of NRC comments scheduled for 820601 COMMINONAM, R.E. Diffice of Nuclear Material Safety & Bareguards, Director 82/05/27 DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director 1p 15648 233 24% Fiche 50-537, 82/07/16, 8210070029
- --8210070222 Provides highlight items re CRBR fuel cyclo environ review de ending 820423 Final version of dRIGEN 2 Code received from ORNL
 LONENBERG. H. Office of Nuclear Material Safety & Safeguards. Director 82/04/29 CUNNINGHAM.R. Office of Nuclear Material Safety & Safeguards. Director 1p 15448 248 24x Fiche 50-537, 82/07/14.8210070029
- --8210070225 Submits schedule for CRBR fuel cycle environ review LGWENBERG.H Office of Nuclear Material Safety & Safeguards, Director 82/04/27 ROUSE.L C Advanced Fuel & tentucleur Licensing Branch MACDUNALD.C E Transportation Branch DUBE.R J Division of Safeguards 2pp 15648 250 24% Fiche 50-537, 82/07/16, 8210070027
- --0210070251 Forwards revised ORIGEN 2 outputs for CRBR LOWENDERO.H Office of Nuclear Material Safety & Safeguards. Director 82/04/23 ROUSEL C Advanced Fuel & Up Fuel Licensing Branch MACDONALD.C E Transportation Branch PAGE.R 0 Uranium Fuel Licensing Branch ip 15448 252 24% Fiche 50-537.82/07/16.8210070029
- --8210070253 Forwards revised ORIGEN 2 output for CRDR Averaging procedures altered for agreement between flows & physical mass
 CROFFIA O Glai Ridge National Laboratory 82/04/20 LGHENNILR
 Office of Nuclear Material Safety & Safeguards, Director 1Jpp
 13648 253 24% Fiche 50-537, 82/07/16.8210070029
- --8210070256 Forwards backup calculations for Table D 4,CRBR fuel c suppl Related info encl HILL.OF Battelle Memorial Institute, Pacific Northwest Laboratory 82/06/09 LOWENBERG, H Office of Nuclear Materia Bafety & Safeguards, Director Bopp 1564H 266 24X Fiche 30-337,82/07/46.8210070029

- --B210070259 Provides highlights to CRBR fuel cyclo environ review for ut ending 820416 Revised ORIGEN 2 Code prepared by CRNL LONENDERG, H. Office or Nuclear Material Safety V. Safeguards, Director 82/04/22 DAVIS J. G. Office of Nuclear Material Safety V. Safeguards, Director ip 15648-352 24X Fiche 50-537, 82/07/16, 8210070029
- --8210370266 Clarifies responsibility for dose assessment calculation for CRSR activities LOWENBERG H Office of Nuclear Material Safety & Sareguards, Director 82/04/12 COMMENT J Radiological Assessment Branch MILLS.W A Human Factors Engineering Branch ROUSE L C Advanced Fuel & Spont Fuel Licensing Branch ip L5547 087 24/ Fiche 50-537.02/07/16.8210070029
- --E210079E73 Provides clarification of DQE Amend XIII submittals per 820323 telcon Full Pu ' II throughputs used as basis for additionative release religious for conservative estimation of erriuments
 of erriuments
 of FIDERG. H. Office of Auclear Material Safety *
 Sateguards, Director 82/03/25 ROUSE/L C Advanced Fuel & Spent Fuel Licensing Branch (MCDDNALD) C E Transportation Branch Bucker R J Division of Safeguards ip 15449 089 24X
 Fiche 50-537,82/07/14.8210070029
- -7210670276 Notification of 820414-15 meeting w/BNHL in Bethesdu, ND to discuss contract under FIN 8-2477 Discussion will include preliminarly source term data 3 initial ORIGEN 2 data LOWENDERG H Office or Nuclear Material Safety 7. Saregoards: Director FIN 8-2177 82/03/23 ROUSE, L C Advanced Fuel 7 Spent Fuel Litensing Branch MACDONALD, C E Transportation Branch DUBFR J Division of Sareguards 1p 15649 090 74X Fiche 50-537.82/07/16 8210070029
- --P.16070.M2 Advises that proposal submitted by BNWL meets objectives of statement of work for review & assessment of CRDR environ impact impa
- -8210070245 Provides quidance for designation or specialists for environ review proceeding List of experts followed by individual statement of qualitrations must be propared (DEFINERG.H. OFFICE or Nuclear Material Safety & Sareguards Director 82/03/19 BROWNING.R.E. Division of Watte Hanagement DUKE.R.) Division of Safeguards MACDUNALD.C.E. Transportation 91 auch Ppp 15649 093 24X Fiche 50-537, 82/07/16 82100700/9
- --8210070.93 Submits schedule of meetings w/technical assistance contractor & DDE re LHBR environ review LOREMBERG.H Difice or Nuclear Material Safety 's Safegoards Director 82709723 ROUSE.L C Advanced Fuel & Spint Fuel Licensing Brinch MACDONALD.C E Transportation Branch DUSE.R J Division of Sareguards 1p 15649 100 24X Fiche 50-53 (82707716.821)070029
- --PJ10070278 Confirms 62072, menting w/DOF to review 820219 draft input to CROR feel cyclo review LOKENBERG.H Office of Nuclear Material Safety & Saregourds, Director 82/02/23 ROUSE, L C Advanced Fuol & Spint Fuel Licensing Branch MACDONALD.C E Transportation Branch BUBER J Division of Safeguards ip 15649 101 24% Fiche 50-537, 62/07/16. 8210070029
- ~-P210070701 Provides broad assessment of CRBR fuel cycle environ effects Amend XII fairly represents 50-yr dose commitments from fuel fabrication & reprocessing ROUSC.1. C Advanced Fuel & Spent Fuel Licensing Branch 82/02/05 LOWENDERG. M Diffice of Nuclear Material Bafety & Safeguards Director 1p 15649 102 24X Fiche 50-537,82/07/16.8210070029
- --8210070306 Provides results of review of DDE draft Amend XIII to CHIR fuel cycle environ review Addi info needed re data used as basis for DQE determination of environ impact AYER, J.E. KRC. - No Detailed Affiliation Given 82/02/20 LONGABERG: NRC. - No Detailed Affiliation Given 82pp 1549-103 24X Fiche 50-537, 82/07/16,8210070029
- --8210070310 Forwards resumes of JE Ayer & AT Clark for CRBR fuel cycli environ review
 RDJSE, C Advanced Fuel & Spent Fuel Licensing Branch 82/03/31
 LDMENBERG.H Office of Nuclear Material Safety &
 Safeguards.Director 5pp 15649 (05 24X Fiche 50-537,82/07/16,8210070029
- 6207110033 FOIA request for documents by Science Applications. Inc for CRBR project including FES. site suitability rept & BER WEISS-ER Harmon & Weiss 82/07/26 FELTON, J M Division of Rules and Records 1p 15597 264 24% Fiche 50-537.82/07/26, 820710033

- 8208270699 Summary of 820723 meeting w/util,DQE & Project Mgt Corp in Bethesda,MD re review of CRRR probabilistic risk assessment in areas of success criteria for shutdown heat removal sys, logic & event trees & fault trees
 STARK.R M Clinch River Breeder Reactor Program Office 82/08/13
 Clinch River Breeder Reactor Program Office 400 14683 045 349
 Fiche 50~537,82/08/13,8208270699
- B210040343 Responds to FOLA request for all documents re work performed by Science Applications, Inc for CRBR project Forwards documents listed in App A FELTON, J M Division of Rules and Records B2/08/20 WEISS, E R Harmon & Weiss 2pp 15597 265 24X Fiche 50-537, 82/08/20, PRINCE OF A RESPONSE OF
- --8210040346 Forwards draft itr repts for CRDR Tasks 1-A, 1-D & probabilistic risk assessment review plan Comments requested JOHNSON.8 Science Applications, Inc. NRC-03-82-096 82/05/26 SILVER.H NRC ND Detailed Affiliation Given 4pp (5597 26/24% Fiche 50-537,82/08/20,8210040343
- --8210040349 Advises that answers to NRDC interrogatories for CRBR review will be completed per 820609 tetcon Plan & schedule submitted URNSON, B Science Applications, Inc. NRC-03-82-096 82/06/10 SILVER, H /RRC No Detailed Affiliation Given 2pp 15597 271 248 Fiche 50-537, 82/08/20, 8210040343
- --8210040350 Confirms action item re risk reduction per 820607 telcon Info re diversity of CRIR heat transport sys encl LINER, R T Science Applications, Inc. NRC-03-B2-096 82/04/i1 IRIC - No Detailed Affiliation Given 2pp 15597 273 24% Fiche 50-537,82/08/20,8210040343
- --8210040351 Forwards comments on applicant 820618 proposed probabilistic risk assessment plan Items addressed include content, resource allocation & phenomenological tasks UDINSON, B Science Applications Inc NRC-03-82-096 82/07/07 SPANU, A NRC No Detailed Affiliation Qiven 3pp 15597 275 24% Fiche 50-537,82/08/20,8210040343
- --B210040355 Forwards questions for applicant re frequency of simultaneous loss of thise main cooling loops, discussed during 820715 meeting LINER.R., ATEFI, B. Science Applications, Inc. NRC-03-82-074 SHIFT, J. NRC NO Detailed Affiliation Given Rep 19577 278 24X Fiche 50-537, 82/08/20, 8210040343
- 8210060442 Responds to FOIA request for input to Chapter 7 & App J of FES & suppl to CROR Documents listed in App A available in PDR App B documents completely withheld advice & opinions (ref FOIA Exemption 5)
 FELTON.J M Division of Rules and Records 82/08/24 WEISS.t R Harmon & Weiss App 15636 040 24% Fiche 50-537.82/08/24.8210060442
- --B210060451 Forwards list of transients within 10 miles of CROR per 820217 request FERREIL.C NRC No Detailed Affiliation Given 62/02/17 THADAMI,M NRC No Detailed Affiliation Given 3pp 15636 12/24X Fiche 50-537.82/08/24.8210060442
- --B210060453 Submits representative meteorological data for input into CRAC computer code for CROR site BFICKLER. I Accident Evaluation Branch B2/04/13 PASEDAG, W Accident Evaluation Branch 19 15434 130 24x Fiche 50-537,82/08/24.8210060442
- --8210060455 Forwards site description of CRIR per 820513 request FERRELL.C NRC No Detailed Affiliation Given 82/05/13 THADAMIN NRC No Detailed Affiliation Olven 17pp 15436 134 24X Fiche 80-837.82/08/244,8210060442
- --8203190016 Forwards draft statement of work for technical assistance contract re-probabilistic assessment & reliability program for comment by 820305 Detailed breakdown of FY82,FY83 & FY84 time required for wach subtask forthcoming THADANI.A Reliability & Risk Assessment Branch 82/03/03 SPET81 NRC No Detailed Affiliation Given 13pp 15636 152 24X Fiche 50-537.82/08/24.8210060442
- B2101501B6 Forwards response to NRC 820407.0514 & 0607 ltrs re request for add1 info Responses to Questions CS 421 26.43,51 & 53 & CS 760 162.164 & 176 will be incorporated into future FBAR amend LONGENECKER, J Energy Dept of, Clinch River Breeder Reactor Plant 82/08/24 CHECK, P S Clinch River Breeder Reactor Program Office 39pp 15707 195 24X Fiche 50-537,82/08/24,8210150186

- 9203290086 FOIA request for rept to EPA. "Pu & Human Tissues re Emoking Age: Residence Near Rocky Flats & Eastern CO " JOHNSON, C Affiliation Unknown 82/09/01 Office of Administration 1p 15636-207 24X Fiche 50-537.82/09/01, 8208290886
- 8210050454 Summary of 820715 meeting w/applicants in Bethesda. MD re review of thermal margin beyond design basis & seismic margin beyond design basis issues BECKER, A. Clinch River Breeder Reactor Program Office 82/09/20 Clinch River Breeder Reactor Program Office 4pp 15626-221 24y Fiche 50-537, 82709/20, 8210060654
- 8210050477 Comments on CRBR probabilistic risk assessment program plan submitted in 820021 ltr Plan responsive to NUREG-0718, Item 11f 19 8 requirements Details encl CHECK.P S Clinch River Breeder Reactor Program Office 82/09/2.J LONGENECKER.J Energy-Dept of, Clinch River Breeder Reactor Plant 6pp 15626 257 24X Fiche 50-537,82/09/23,8210050477
- B210120445 Notification of B21004-0B meetings w/DDE.Project Mgt (urp & TVA in Bethesda.MD to discuss direct heat removal sys STARK.R M Clinch River Breeder Reactor Program Office 82/09/2/CHECK.P S Clinch River Dreeder Reactor Program Office 3pp 15671 183 24X Fiche 50-537, 92/09/27-8210120445
- 8210040251 Conforms that microfiche containing CACECO input/output for extreme sodium-concrete penetration case & explanatory info has been delivered to CRBR program of CLONGENECKER. J Energy. Dept of 82/09/28 CHECK.P S Clinich River Breeder Reactor Program Office ip 15581-357 24X Fiche 50~537.82/09/28.8210040251
- 8210040304 Forwards TN Historical Commission BE0908 itr to TVA concurring that archelogical & historical field survey is not warrented prior to transmission line tower const LONGENECKER. J Energy Dept of. Clinch River Breeder Reactor Plant 82/09/28 CHECK.P S Clinch River Breeder Reactor Program Office 2pp 15587 149 24X Fiche 30-537.82/09/28.8210040304
- 9210130069 Notification of 821005 meeting w/BDE.Project Mgt Corp & IVA in Bethesda.MD to discuss working structural & seismic review STARK.R H Clinck River Breeder Reactor Program Office 82/09/28
 - STARK, R H Clinck River Breeder Reactor Program Office 82/09/26 CHECK, P S Clinck River Breader Reactor Program Office 3pp 15696 264 24X Fiche 50-537, 82/09/28, 8210130069
- B210040167 Forwards 1tr rept in support of CRER thermal margins beyond design base instrumentacion development per DDE 820514 submittal refeture info for review of CRER LONGENECKER, J. Energy, Dept of, Clinch River Drasder Reactor Plant B2/09/29 CHECK, P.S. Clinch River Breader Reactor Program Office 11pp 15582 034 24X Fiche 50-537, B2/09/29, B210040167
- 8210060426 Responds to FOIA request for rept to EPA, "Pu & Human Tissues re Smoking, Age. Residence Near Rocky Flats & Eastern CO" & related documents No info available Forwards request to EFA for response FELTON. JM Davision of Rules and Records 82/09/29 JOHNSON.C J Affiliation Unknown ip 19636 208 24% Fiche 50-537,82/09/29,8210060426
- 8210060217 Forwards responses to Questions C5 421 27.30.31.34 & 58 to ESF.instrumentation & control drawlings for safety-related sys & adequacy of reactor vessel level gauges: per 820409 request Responses will be incorporated in future PSAR amend LONGENECKER.J Energy. Dept of. Clinch River Breeder Reactor Plant 82/10/04 CHECK.P S Clinch River Breeder Reactor Program Office.

- B210130311 Summarizes B20728 meeting w/NRC re CRBR leak detection serfor primary coolant boundary Test results enci LONGEMECKER. J Energy, Dept of B2/10/07 CHECK, PS (linch River Breeder Reactor Program Office ip 15678 135 24X Fishe 50-537, B2/10/07.B210130311
- --B210130315 "Liquid Metal to Qas Leak Detection Instruments" MATLIN, E. WITHERSPOON, J. JOHNSON, J. L. Rockwell International Corp. 82/10/07 15pp. 15678 136 24% Fiche 50-547,83/10/07, 9210130311
- 6210C20023 Notification of 621019 meeting w/DOC, Project Mgt ('orp & 14', in Bethesda, MD to review control room design STARK, R M Clinch River Breeder Reactor Program Office (12/10/17 CHECK, P S Clinch River Breeder Reactor Program Office 15786 304 24X Fiche 50-537, 62/10/14: 8210R20023
- B210210022 Forwards summary of 820917 ARME Code comparison working meeting w/CRBR project of c.LASL. Mestinghouse % WLLCO in Bethesda. MD to resolve concerns to utilization of 1974 ASMF Code for design of containment vessel LONGENECKER. J. Energy. Dept of 82/10/15 CHECK. P. 6 (110 h River Breeder Reactor Program Office 14pp 15745 J/B /4X Fiche 50-537.82/10/15.8210210022
- B210210273 Forwards summary of CRUR/NRC hypothetical core disturble accident energetics B20921 meeting re plenum fission gas compaction.role of structures in energetic termination & fuel removal & energetic potential LONGENECKER. J Energy. Dept of B2/10/15 CHECK.P & Climb River Breeder Reactor Program Office 5lpp 15766.1711 Mx Fiche 30-537.82/10/15, 8210210273
- 8210260302 Forwards add1 info resulting from Mechanical Engineering Branch 820908-09 meetings & response to Items 17.19.32.4.60 Responses to Items 3.4.34.49.51 & 54 will be provided by 821025 LONGENECKER, J. Energy. Dopt of 82/10/20 CHCCK P. Limin River Broeder Reactor Program Office 6pp 16072-297 .44 Fichs 50-537, 82/10/20.9210260302
- 8210260168 Summarizes 821019 control room philosophy exchange meeting Visugraphs encl
 LONGENECKER, J Energy, Dept of Gd/10/21 CHECK.P (1 (1) 11 th River Breeder Reactor Program Office 38pp 19004 276, 44x
 Fiche 50-537.82/10/21.8210260168
- 8210260401 Forwards summary of Decay Heat Romoval Themai Hydrauless 821020 meeting w/KRC re-resolution of items concorning CROR project LONGENECKER. J Energy, Dept of 82/10/21 CHCCK. P. 1. (line River Breeder Reactor Program Office Spp 13805 Pd.) ,44 Fithe 50-537.82/10/21.8210260401
- B Utility Preliminary Safety Analysis Report, amends
- 8209300353 Forwards Amend 71 to PSAR Amend includes responses to requests for add1 inforrevisions to Chapter 7, "Instrumentation & Controls," Bections 17E & 171 & other updates & revisions Certificate of Svc enci LONGENECKER, J Energy, Dept of, Clinch River Dreeder Reactor #101 & 2797/30 CHECKER B Clinch River Breeder Reactor #101 & 4pp 15560 197 24X Fiche 50-537,82/07/30,8209300353
- --8209300355 Amend 71 to PBAR

 4 Clinch River Breader Reactor Program Office 82/09/KD 58-1, 1550 201 24X Fiche 50-537,82/09/30.8209300353
- 8210130246 Forwards Certificate of Bvc confirming distribution of the T1 to PSAR LONGENECKER, J Energy, Dept of B2/10/07 DENTON, H R threath Nuclear Reactor Regulation, Director 2pp 15676 010 24x Fiche 50-537, B2/10/07, B210130246
- C Utility Environmental Report (ER), amends & correspondence
- 8210070029 Partial response to FOIA request for documents re CRER & all comments, evaluations & documents from BNML re EIS
 Forwards documents listed in App A
 FELTON, J N Division of Rules and Records 82/07/16 WEISU-E **
 Harmon & Weiss 8pp. 15648 004 24X Fichs 50-537.82/07/16.
 8210070027

- -8210070128 Forwards drart Amend XIII to CRBR environ rept.consisting of rinor editorial changes LONEUBERG H Office of Nuclear Haterial Safety & Safeguards, Director 82/02/24 ROUSE, L C Advanced Fuel & Spunt Fuel Licensing Branch MACDOMADIC E Transportation Branch Budg.R J Division of Sareguerds 48pp 15648 136 24X Fiche 50-537.82/07/16.82100/0029
- --8210070131 Forwards add1 input to Amend XIII to CRBR environ rept to toccommonic impact N/o encl LONEMBERG.H Diffice of Nuclear Material Safety & Salequards.Director 82,04/26 ROUSELL C. MACDOHALD.C E. DUBE RJ NRC - No Detailed Aftiliation Given 2pp 15648 184 247 Firts 50-537.82/07/16 8210070029
- --B210070134 Requests review of DDE revised environ rept. Section 5 / 1 re fuel cycle Revision includes detailed explanation of method used to calculate doses from transportation W/o encls LONENDERGO H Office or Nuclear Hateria) Safety & Sateguards Director B2703715 ROUSE. L C Advanced Fuel & Sport Fuel Licensing Branch MACDDNALD.C E Transportation Branch DJBE.F J Division of Safeguards 2pp 15648 186 24X Fiche 50-537.82/07/16.8210070029
 - 0210070138 Dutines revised Amend XIII to fuel cycle environ rept
 Updated version contains supplemental safeguards infoestinated costs & modified Kr-85 disposal scheme
 LONENBERO. Office or Nuclear Material Safety %
 Safeguards Director 82/03/23 Advanced Fuel & Spent Fuel
 Licensing Branch MACDOMALD. C & Transportation Branch
 EJBE.R J Division of Safeguards
 Fiche 50-53/ 82/07/16 8210070029
- --8210070142 Requests review of Amend XIV.containing revised environ ript Section 5.7) refuel cycle W/o encl LOMENBERG.H Office of Nuclear Material Safety & Sareguards, Directel 82/05/04 ROUSC.L C Advanced Fuel & Spirit Fuel Licensing Branch MACDONALD.C E Transportation Branch DUBE.R J Division of Sareguards ip 15648 190 24X Fiche 50-537 82/07/16.8210070029
- --BZ10070170 Advises that DOE has been notified of omissions, props & intensistencies found in Amend XIV to environ rept 10kEMBERG.H Office of Nuclear Material Bafety & Safeguards, Director B2/06/16 CHFCK,P S Clinch River Breeder Reactor Program Office 2pp 15648 227 24X Fiche 50-537 82/07/16.8210070029
- --B2100701/4 Provides highlight items re CRBR fuel cycle environ review for uk ending 820611 Amend XIV to environ rept under review (OKENBERG H Office or Nuclear Material Safety & Safeguards, Director B2/06/16 DAVIS.J 9 Office of Nuclear Material Safety & Safeguards, Director 1p 19648 234 24X Fiche 50-537 82/07/16/8210070029
- --E21007019% Discusses status & changes to Amend XIV to environ rept, per B20514 telcon w/DDE Rept will be modified to cover protection for rail shipments LOWENDERG. B. Office or Nuclear Material Safety & Saseguards. Director 82/05/14 ROUSE. L. C. Advanced Fuel & Spunt Fuel Licensing Branch MACDONALD. C. Transportation Branch PACE. R. G. Unanium Fuel Licensing Branch 2pp (5648 238 P4X Fiche 30-537,82/07/16.8210070029
- --8210070200 Forwards socioeconomic impact portion of environ rept for inclusion w/Amend XIV LOWENDERG.H Office of Nuclear Material Safety & Safeguards, Director 82/05/07 ROUGE.L C Advanced Fuel & Spint Fuel Licensing Branch MACDONALD.C E Transportation Branch PAGE.R J Uranium Fuel Licensing Branch 3pp 15648 240 24X Fiche 50-537, 82/07/16, 8210070029
- --BZ10070206 Advises that DDE failed to meet schedule of milestone for safeguards info & revised CRDR environ rept New target date scheduled for BZ0511 LONENBERG, H Division of Fuel Cycle & Material Bafety BZ/05/05 DAVIS

- ~-821007026D Forwards revision to Amend XIII to environ rept, provided by DDE on 820415
 LCHENBERG.H Office of Nuclear Material Safety & Sareguards. Director 82/04/20 ROUSE.L C Advanced Fuel & Spirit Fuel Licensing Branch MACDONALD.C E Transportation Branch DUBE.R J Division of Safeguards 86pp 15648 393 24X Fiche 50~537,82/07/16,8210070029
- ~-8210070262 Provides highlights of CRBR fuel cycle environ review for wk ending 820413 DDE plans to submit draft Amend XIII to environ rept during wk of 820419
 LONENBERG.H Office of Nuclear Material Safety & Safeguards. Director 82/04/13 DAVIS, J O Diffice of Nuclear Material Safety & Facely & Safeguards. Director 2pp 15649 077 24X Fiche 50-537, 82/07/16, 8210070029
- --B210070280 Discusses radiological dose assessment for licensing of CRBR DDE will submit environ rept on fuel cycle used to fabricate reprocess transport \$ safeguard fuel LOMENBERO, H Office of Nuclear Material Safety & Safeguards Director B2/03/19 CONGEL.F J Radiological Assessment Branch 1p 15649 091 24X Fiche 50-537, B2/07/16, B210070029
- --8210070291 Forwards corrected pages to Amend XIII package of CRBR environ rept
 LONENBERG.H Office of Nuclear Naterial Safety &
 Safeguards Director 82/03/16 RDUSE.L C Advanced Fuel & Brent
 Fuel Licensing Branch MACDONALD.C E Transportation Branch
 DUBE,R J Division of Safeguards 5pp 15649 095 244
 Fichs 50-537.82/07/16.8210070029
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8210070029 Partial response to FOIA request for documents re CRBR EIS & all comments, evaluations & documents from BNWL re EIS
 Forwards documents listed in App A
 FELTON.J M Division of Rules and Records 82/07/16 WEISB, E R
 Harmon & Weiss Bpp 15648 004 24% Fiche 50-537,82/07/16.
 B210070029
- --8210070037 Provides info re revision to CRBR Fuel cycle environ review schedule FES contributions due 820614 Review responsibilities identified EVANS, I. J. NRC No Detailed Affiliation Given 82/03/23 MCCORKLE, C. SHERR, T., ERICKSON, B. NRC No Detailed Affiliation Given 2pp 15648 012 24% Fishe 50-837, 82/07/16, 8210070029
- --8210070043 Discusses plans for 820408-09 meeting w/BNWL in Silver Spring, MD to discuss CRBM environ review Draft updates of EIS sections on transportation & Fuel Fabrication will be provided HURT.D. NRC No Detailed Affiliation Given 82/03/22 DUBE.D. NRC No Detailed Affiliation Given 19 15648 Q16 24X Fiche 50-537, 82/07/16, 8210070029
- --B210070047 Discusses plans for B20512 & 13 meeting w/DNML re draft update of safeguards portion of E18 HURT.D NRC No Detailed Affiliation Given B2/04/21 GABKIN,C . MULLEN.B . BAKER,P NRC No Detailed Affiliation Given Ip 15448 017 R4X Fiche 50-537.82/07/16.8210070029
- --8210070050 Advises that BNML contractors will be available on 820407-08 to discuss CRBR environ review Transportation section of El^o will be reviewed on 820407 HURT, D. NRC No Detailed Affillation Given 82/03/31 D. NRC No Detailed Affillation Given 12/03/31 D. NRC No Detailed Affillation Given 15648 OIB 24X Fiche 50-537.82/07/14.8210070029

- --82(0070067 Advises that work task sheet uill serve for basis of plan supporting environ review effort Safeguards portion of DDE environ rept should be reviewed to determine if sufficient info has been included for confirmatory review BURNETI, R F Division of Bafeguards B2/02/17 LOWENBERO, H Office of Nuclear Material Safety & Safeguards, Director 2pp 15648 026 24X Fiche 50-537, 82/07/16.82:0070029
- --8210070084 Requests that BNML handle all safeguards-related arras of EIS & interrogatory updates except those concerning threats by clandestime fission explosives in response to B20303 memor MCCORKLE.O NRC No Detailed Affiliation Given B2/03/04 EVANS, B WRC No Detailed Affiliation Given 1p 1564B 032 24% Fiche 50-537,82/07/16.8210070029
- --8210070101 Advises that 820305 deadline for draft suppl to EIS cannot be net due to delay in receipt of info from DDE LONENDERO. H. Office of Nuclear Material Safety & Safety & Safety & Caroline Core Rector Program Office 2pp 15648 043 24X Ficha 50-537. 82/07/16, 8210070029
- --B210070119 Forwards safeguards portion of FEB update.including Section 7 3 % App E LOWENDERG.H Office of Nuclear Material Safety & Safeguards.Director B2/06/09 CHECK.P S Clinch River Breeder Reactor Program Office 20pp 15648 093 24X Fiche 50-537,82/07/16,8210070029
- --B210070123 Forwards updated responses to comments on 1976 DES,
 NUREQ-0137 re safeguards & fuel cycle info re radwaste
 shipments, disposal site & licensed burial site included
 LOWENBERG, H. Office of Nuclear Material Safety &
 Bafeguards, Director. 82/05/15 LEECH.P. Clinch River Broedor
 Reactor Program Office. 15pp. 15648-073 24X
 Fiche 50-537, B2/07/16, B210070029
- --8210070126 Forwards update to FES, including App D, "Environ Effects of CRBR Fuel Cycle & Transportation of Radioactive Matls" & Section 5 7 2 7, "Fuel Cycle Impacts "
 LOHENBERG. H Office of Nuclear Material Safety & Safeguards. Director 82/06/19 CHECK. F S Clinch River Breeder Reactor Program Office 50pp 15648 088 24X
 Fiche 50-537, 82/07/16, 8210070029
- --8210070163 Provides highlights for wk ending 820618 re CRBR fuel cycle environ review Minor corrections to FES update submitted to CRBR program ofc LOMENBERG, H Diffice of Nuclear Material Safety & Safeguards, Director 82/06/24 DAVIS, J 0 Diffice of Nuclear Material Safety & Bafeguards, Director Ip 15448 200 24X Fiche 50-537, 82/07/16, 8210070029
- --8210070166 Forwards replacement pages for fuel cycle portion of CkHk FES update Pages correct minor errors LOMENDERG, H Office of Nuclear Material Safety & Safeguards, Director B2/06/21 CHECK.P S Clinch River Greader Reactor Program Office 25pp 15648 201 24X Fiche 50-537, B2/07/16, B210070029
- --8210070186 Provides highlight items re CRBR fuel cycle environ review for wk ending 820514 Draft fuel cycle portion of EIS in progress LOKENBERD, H Office of Nuclear Material Safety & Safeguards, Director 82/05/20 DAVIS, J 0 Office of Nuclear Material Safety & Safeguards Director ip 15648 235 24% Fiche 50-537, 82/07/16,8210070029

- --8210070223 Notifies that BNAL will be available to review (MBM | 1).
 on 820512
 LCMENDERG.H Office of Nuclear Haterial Safety &
 Safeguards. Director 82/04/26 ROUSE.t. C Advanced turl 1 'j. '8
 Fuel Licensing Branch MACDUNALD.C E Transportation Brauth
 PAGE.R G Uranium Fuel Licensing Branch to 1964H 249 41
 Fiche 50-537,82/07/16.8210070029
- --8210070313 Submits responses to Contention 6. Interrogatories 15 ft. 61.62.63 & 64 on CROR hearing re E1S update

 AYER, J E , CLARK, A T Advanced Fuel b Spont Fuel Historising Bia
 82/06/09 LOMENDERO, H Office of Nuclear Material Lafety b

 Safeguards, Director 4pp 15649 110 24X Fitho 50 517 ft. 417/417/17

 8210070029
- --B210070315 Discusses potential need for add1 funding for (1414 11), update project (RELSON, I Battello Memorial Institute, Pacific Northwest Laboratory 82/06/24 LCMENDERO: M Office of Nucleus Materials Safety & Safeguards, Director 2pp 15649 114 24X Fiche 50-537, 82/07/16/8210070029
- --B210070318 "CRBR EIS Update," monthly progress rept for Hay I'm... NELSON, I C Dattelle Hemorial Institute, Pacific Northwest Laboratory B2/06/17 LONENBERG, II Office of Nucleus Nates (21 Safety & Safeguards, Director Jpp 15647 116 24x Fiche 50-537, 82/07/16,8210070029
- --8210070923 Forwards final draft submittal of CRBR II's update in the Section 5 7 2 6.5 7 2 7.7 2 5 7 3 M/o encl
 NELSON-I C Battolle Memorial Institute, Pacific Noi thuset
 Laboratory 82/05/21 (OMENBERG.N Office of Noileas Material
 Safety & Safeguards.Director in 19649 [19], "4X
 Fiche 50-537.82/07/16.8210070029
- ~-8210070327 Confirms changes to final CRBR E16 draft update per intelection w/NRC safeguards staff
 NELSCH.! Battelle Memorial Institute. Pacific Northwest
 Laboratory 82/05/18 LOMENBERG.H Office of Nuclear Material
 Sarety & Safeguards.Director 1p 15649 120 P4x
 Fiche 50-537,82/07/16,8210070029
- --8210070332 "CRAR EIS Update," monthly progress rept for Apr 151.
 NELSON, I C Dattelle Memorial Institute, Pacific Northwest
 Laboratory 82/05/17 LOWENDERG, M Office of Norther Paleite.
 Bafety & Safequards, Director 3pp 15649 121 194x
 Fiche 50-537, 82/07/14, 8210070029
- --8210070335 Forwards second draft of CRDR EIS update.including 'ecc 5 7 2 6. "Transportation of Radioactive Math," Section 5 7 2 6. "Transportation of Radioactive Math," Section 5 6 2 7 "Foel Cycle Impacts" & Section 7 3. "Safequentds Considerations " W/o anci NELSON.I C Battolla Hemorial Institute. Pacific No. Lines Laboratory 82/05/07 LOWENBERG.H Office of Notlean Material Barety & Safeguards.Director 1p 19649 124 24x Fiche 50-537.82/07/16.8210070029
- --8210070347 "CRBR EIS Update," monthly progres rept for Max 140 NELSON, I C Battelle Momorial Institute, Pacific Northwest Laboratory 02/04/12 LOMENDERG, H Office of Noticer Maiss 4 a Safety & Bafeguards, Director 3pp 15449 125 44x Fiche 50-537, 82/07/16, 8210070027
- --B210070465 Forwards back-up notes & refs for fuel cycle parti .
 update Related info encl
 NELSON, I Battelle Memorial Institute, Pacific Northwest
 Laboratory 82/06/24 LOMENBERG, H Office of Nuclear Material
 Safety & Safeguards, Director 57pp 15649 128 24x
 Fiche 50-537,82/07/16.8210070029
- B207110034 F01A request for input to Chapter 7 & App J of 69% b ' . to GRBR
 to GRBR
 ME185.E R Harmon & Weiss 82/07/26 FELTON, J H 02/23 ton #
 Rules and Records 1p 15636 039 24X Fiche 50-537. 내고시아니다.
- B210060442 Responds to FOIA request for input to Chapter / f. App | FES & suppl to CRBR Documents listed in App A available in PDR App B documents completely withheld advice & opinions (ref FOIA Exemption 5)
 FELTON. J M Division of Rules and Records B2/08/24 William Harmon & Weiss App 15636 040 24% Fiche 50-537.8%/UM/-4 8210060442
- --8201150176 Forwards Accident Evaluation Branch input to \$15 \$45 \$60 Facility Section 7 requires suppl to address NRC 6000618 statement of interim policy Info presented in Sections \$4.5 to 7 requires no update

 KREOER.W E Assistant Director for Radiation Protection

 81/12/18 CHECK.P 8 Clinch River Breeder Reactor Program at 3pp 15636 044 24% Fiche 50-537.82/00/24.8210060444

- --8206080467 Forwards Accident Evaluation Branch input to final environ statement update re Class 9 accidents MDUSTDIAR W Assistant Director for Radiation Protection 82/05/28 CHECK.P S Clinch River Greeder Reactor Program Office 9pp 15636 049 24% Fiche 50-537.82/08/24,8210060442
- --E207140138 Forwards Accident Evaluation Branch revised evaluation of four classes of come distuptive accident included as App J to proposed FES addendum.per B Morris verbal request Calculated risks of accidents not different from LHR risks HOUSTON, R W Assistant Director for Radiation Protection 82/07/01 CHECK.P S Clinch River Oreeder Reactor Program Uffice 42pp 15636 058 24% Fiche 50-537.82/08/24.8210060442
- --8210060447 Draft input to Class 9 accident analysis for CRBR FFB RAMBLE.E Science Applications, Inc 82/06/30 NRC - No Detailed Affiliation Given 20pp 15636 100 24X Fiche 50-537.82/08/24.8210060442
- --8202240446 Forwards population data input for DES Section 5 9 4 9 2 for yr 2010, per request REGAM, W.H. Siting Analysis Blanch 82/02/10 HULMAN, L.G Accident Evaluation Branch 3pp 15636 124 24X Fiche 50-537, 82/08/24, 8210060442
- --9201350087 Provides description of aspects of liquid pathway for updute of accident analysis section of FES suppl Liquid pathway consequences small due to absence of large water stores LEAR.O Hydrologic & Coutechnical Engineering Branch B1/12/22 HQUSTON.R 4 Accident Evaluation Branch 2pp 15636 132 24X Fiche 50-937.82/08/24,8210060442
- --8203050073 Confirms tentative schedule for roview of CRBR program probabilistic risk assessment study to be included in FEB suppl HULMAN, C Accident Evaluation Branch 82/02/17 THADANI, A Reliability & Risk Assessment Branch 1p 15636 165 24X Fiche 50-537 82/08/24.8210060442
- --8210060458 Forwards comments on draft math for FES update per 820501 request Section 7.2 should include brief discussion on U herafluoride Related info encil CHECK.P.S. Clinch River Breedo: Reactor Program Office 82/05/28 LOMENSERG.H. HRC No Detailed Affiliation Given 14pp 15636-166. 24X Fiche 50-597. 82/08/24.8210060442
- --0204290400 Forwards marked up Tablo 7 2 of IES Revisions reflect differences in current site atmospheric dispersion values from reg guide values used for original FES calculations HOUSTON.R W Assistant Director for Radiation Protection 82/04/07 CHECK.P S Clinch River Breeder Reactor Program Dfisce 2pp 15636 (69 24x Liche 50-537.02/08/24,8210060442
- --0203220512 Advises that schedule for review of probabilistic risk assessment proposed in 820217 memo no longer applicable input to review will be provided upon request FULMANL Q Accident Evaluation Branch 82/03/09 THADANI A Reliability & Risk Assessment Branch 1p 15636 192 24X Fiche 50-537.82/08/24.8210060442
- E210080053 Ack receipt of BP090B ltr commenting on draft suppl to 11.6 Comments will be considered in FES CHECK.PS Clinch River Breeder Reactor Program Office B2/09/23 CHONO.L R Affiliation Unknown ip 15669 319 24X Fiche 50-537.82/09/23.8210080053
- --0210080055 Comments on draft suppl to FEG re decommissioning of CHNR CHONG.L R Affiliation Unknown 82/09/08 NRC ~ No Detailed Affiliation Given 2pp 15669 320 24x Fiche 50-537,82/09/23, 8210080053
- F Security, medical, emergency & fire protection plans
- 8210070029 Partial response to FD1A request for documents re GRBN E15 & all comments, evaluations & documents from BNWL re E15
 Forwards documents itsed in App A
 FELTON, J M Division of Rules and Records 82/07/16 WE185.L R
 Harmon & Weiss Spp 15648 004 24% Fiche 50-537, 82/07/16.
 8210070029
- --8210070047 Discusses plans for 820512 & 13 meeting w/BNHL re draft update of safeguards portion of EIS HURT.D NRC No Detailed Affiliation Given 82/04/21 GASKIN.C. MULLEN,S., BAKER,P. NRC No Detailed Affiliation Given 1p 15648 017 24X Fiche 50-507.82/07/16.8210070029
- --8210070064 Provides update of EIS review Document requires updated mation reactor safeguards Interrogatories may be issued to clarify or constrain issues

 EVANS-L J NRC No Detailed Affiliation Given 82/03/01

 MCCORKLE.O NRC No Detailed Affiliation Given 2pp 1564B 024

 24X Fiche 50-537,82/07/16,8210070029

- --8210070067 Advises that work task sheet will serve for basis of plan supporting environ review effort Safeguards portion of DBE environ rept should be reviewed to determine if sufficient info has been included for confirmatory review BURNETT.R F Division of Safeguards 82/02/17 LOWENBERO.H Office of Nuclear Material Safety & Safeguards.Director 2pp 19649 026 24% Fiche 50-537, 82/07/16,8210070029
- --8210070084 Requests that BNML handle all safeguards-related areas of EIS & interrogatory Updates except those concerning threats to clandestine fission explosives, in response to 820303 memo HCCORKLE, 0 NRC No Detailed Affiliation Given 82/03/04 EVANS, B NRC No Detailed Affiliation Given 1p 15448 032 24X Fiche 50-537,82/07/16,8210070029
- --8210070086 Requests contentions for CRBR licensing which have implications in areas of fuel cycle safeguards & waste mgt discussed during 810906 meeting LQMENBERG,H Office of Nuclear Material Safety & Safeguards, Director 81/10/09 CHECK,P 5 Clinch River Broads) Reactor Program Office 3pp 15648 033 24X Fichs 50-537, 82/07/16, 8210070029
- --B210070119 Forwards safeguards portion of FES update, including Section 7 3 & App E
 LCMENDERG,H Office of Nuclear Material Safety &
 Safeguards, Director 82/06/09 CHECK,P S Clinch River Breeder
 Reactor Program Office 20pp 19648 053 24X
 Fiche 50-537, 82/07/16,8210070029
- --8210070123 Forwards updated responses to comments on 1976 DES, NUREG-0139 re safeguards & fuel cycle Info re radwaste shipments, disposal site & licensed burial site included LOMENBERG.H Office of Nuclear Material Safety & Safeguards, Director 82/06/15 LEECH.P Clinch River Breeder Reactor Program Office 13pp 15648 073 24X Fiche 50-517.82/07/16,8210070029
- --8210070138 Outlines revised Amend XIII to fuel cycle environ rept
 Updated version contains supplemental safeguards info,
 estimated costs & modified Kr-85 disposal scheme
 LOMENBERO, H. Office of Nuclear Material Safety &
 Safeguards, Director 82/03/23 Advanced Fuel & Spent Fuel
 Licensing Branch MACDONALD, C.E. Transportation Branch
 DUBE, R.J. Division of Safeguards 2pp 15648 188 24X
 Fiche 50-537,82/07/16,8210070029
- --B210070148 Forwards updated list of staff members & contractor personnel who may be called to testify on fuel cycle or safeguards issues at CRBR hearings
 LOWENSERG.H Office of Nuclear Material Safety & Safeguards, Director 82/05/06 TREBY.S & Office of the Erecutive Legal Director 2p 15648 192 24X
 Fiche 50-537,82/07/16,8210070029
- --8210070154 Submits list of staff members & Contractors who may provide testimony on GRBR fuel cycle safeguards LUMENBERG.H Defice of Nuclear Material Safety & Bafeguards, Director 82/03/16 JONES, 8 NRC -- No Detailed Affillation Oliven 2pp 15648 196 24X Fiche 50-537,82/07/16, 821070029
- --8210070206 Advises that DDE failed to meet schedule of milestone for safeguards info & revised CRBR environ rept New target date scheduled for 82051(LOMENDERO, H. Division of Fuel Cycle & Material Safety 82/05/05 DAVIS.JO Office of Nuclear Material Safety & Safeguards, Director 19 15648 244 24X Fiche 50-537, 82/07/16, 8210070029
- --B210070264 Forwards add) info re add1 safeguards cost info for CMBR fuel cycle environ review LUKENBERG.H Office of Nuclear Material Safety & Safeguards. Director 82/03/26 RQUSE.L C Advanced Fuel & Sprnt Fuel Licensing Branch MACDUNALD.C E Transportation Branch DUBE.R J Division of Safeguards ip 15649 079 24% Fiche 50-537,82/07/16,8210070029
- --B210070269 Provides weekly rept on CRBR fuel cycle environ review activities for wk ending 820326 DDE submitted supplemental info re draft Amend XIII concerning request for safeguards costs
 LOHENBERO, H. Office of Nuclear Material Bafety & Safeguards, Director 82/03/31 CUNNINGHAM, R. Division of Fuel Cycle & Material Safety 1 p. 15649 OBB 24X
 Fiche 50-537, B2/07/16.8210070029

Q Adjudicatory correspondence

- 8210120103 Add1 response to FDIA request for nine categories of records generated by present NRC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents

 FELTON, J M Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 3pp 15690 117 24%

 Fiche 50-000, 82/07/12, 8210120103
- --8210120123 Forwards memorandum & order re Council of NC objection to util request for exemption to perform certain site preparation work Memorandum addresses exemption question & sets out history of Commission regulation. Section 50 12 ROBERTS, TM Commissioners B1/12/09 PALLADING, N, OILINSKY, V, BRADFORD, J Commissioners B1/12/09 124 24X Fiche 50-000, 82/07/12, 8210120103
- 8208270074 FDIA request for CRAC & CRAC 2 analyses for facilities CURRAN, D. Harmon & Roiss 82/09/10 Office of Administration 1p 15626 239 24X Fiche 50-000,82/09/10,8208270074
- 8210010064 Motion for summary disposition of NRDC & Sierre Club Contentions 6 & Za(i) No factual issues requiring adjudication exist & dismissal of contentions warranted as matter of law Mati facts as to which there is no issue encl JONES. U W. SWANSON, D T Hearing Branch | 82/09/29 Atomic Bafety and Licensing Board Panel | 12pp | 15565 274 24X Fiche 50-537, 82/09/29, 8210010064
- --8210010079 Affidavit of K Lowenberg on Contentions 6(a) & (b) Concern that fuel cycle analysis be CROR-specific fully addressed by environ rept & draft FES suppl Analysis will be detailed in final FES suppl Prof qualifications enci LOMENBERG, H Office of Nuclear Material Safety & Safeguards, Director 82/09/29 4pp 15565 286 24X Fiche 50-537, 82/09/29, 8210010064
- --8210010082 Affidavit of P Leech on Contention 7(a)(1) Concern to CRBR achieving objectives of LMFBR program impact statement & suppl superseded by theing changes given in suppl Prof qualifications & Certificate of Svc encl LEECH.P Clinch River Breeder Reactor Program Office 82/09/28 5pp 15565 290 24X Fiche 50-537.82/09/29.8210010064
- 8210050184 Corrected notification of pending litigation, including omitted sentence from 820924 notice Certificate of Svc encl EDOAR, 0 L Project Management Corp BEROHOLZ, W.E. Energy, Dept of EDOAR, 0 L Edgar, 0 L 82/09/29 24pp 15404 00; 24x Fiche 50-537, 82/09/29,8210050184
- B210050582 Responds to FDIA request for CRAC & CRAC 2 analyses for facilities No analyses exist for Shoreham Nuclear Plant Analyses for CRDR furnished under FDIA B2-344
 FELTON, J M Division of Rules and Records B2/09/29 CURRAN, D Harmon & Weiss Ip 15626 240 24% Fiche 50-000, B2/09/29, 8210050582
- B2100601B3 Angwers to twenty-seventh set of interrogatories Certificate of Svc encl
 EWANSON, D T. JONES, B W. MIZUNG, G S Hearing Branch 1 82/10/01
 Natural Resources Defense Council 176pp 15613 001 24X
 Fiche 50-537. 82/10/01. 8210060183
- B210060185 Siith set of interrogatories Certificate of Svc encl EDGAR, O L Project Management Corp BEROHOLZ, W E Energy, Drpt of EDCAR, O L Edgar, O L 62/10/04 Natural Resources Defense Council 14pp 15613 198 24x Fiche 50~537.82/10/04.8210060185
- 8210040195 Proposed findings of fact on Contentions 1,2 & 3 re site suitability FINAMORE, B A , TOUSLEY, D R Natural Resources Defense Counci! TOUSLEY, D R 61erra Club 82/10/04 77pp 156:3 293 24X Fiche 50-537, 82/10/04, 8210060195
- 8210060200 Second set of admissions & seventh set of interrogatories, per ASLB 820831 scheduling order Certificate of Svc enci EDOAR.O L. Project Management Corp BEROHOLZ.W E Energy, Dept of EDOAR.O L. Edger, O L. 82/10/04 Natural Resources Dofense Council App 15614 170 24X Fiche 50-537.82/10/04.8210060200
- 8210070192 Informs that time provided for Commission to act to review ALAB-65B expired Commission declined review Decision became final agency action on 821004 CHILK, B. J. Office of the Secretary of the Commission 82/10/05. Office of the Executive Legal Director (p. 15637, 135 24X Fiche: 50-537, 82/10/05, 8210070192

- 8210120302 Confirms 821005-06 discussions listing NRC personnel to avideposed on various contentions on 821012-13
 FINAMORE, B A Natural Resources Defense Council 82/10/0/
 SMANSON, D Hearing Branch 1 3pp 15653 038 24X
 Fiche 50-537, 82/10/07, 8210120302
- 8210120327 Withdrawal of 821004 proposed findings of fact on Contentions 1.2 & 3 re site suitability Intervenors failed to note ASLB 820831 withdrawal of request for filing proposed findings Certificate of Svc enci FINAMORE.B A . WEISS.E R Natural Resources Defense Council WEISS.E R Sierra Club 82/10/07 5pp 15653 028 24% Fiche 50-537.82/10/07.8210120327
- 8210130435 Notice of pending litigation Certificate of Svc enri EDGAR.G L. Project Management Corp. BERCHOLZ,W E. Energy, Dipt of 82/10/07 7pp 19681 171 24% Fiche 50-537,82/10/07, 8210130435
- 8210130268 Confirms 821007 discussion, listing addi NRC personnel to be available for deposition re Contentions 5(a) & 7(b) on 821013 FINAMORE, B A Natural Resources Defense Council & Finamure D & 82/10/08 JONES, B Hearing Branch 1 2pp 15678 290 24x Fiche 50-537, 82/10/08,8210130268
- 8210130343 Answer supporting NRC 820929 motion for summary disposition of intervenor Contentions 6(a) & (b) & 7(a)(1) No genuine issue of matl fact exists Certificate of Svc encl Related correspondence
 BERCHOLZ,N E Energy, Dept of EDGAR,O & Project Management Corp 82/10/12 Atomic Safety and Licensing Board Panel Upp 15682 038 24% Fichs 50-597,82/10/12,8210130343
- 8210200080 Confirms 821005 & Oé telcons NRDC wall have no watnesses for LWA-1 hearings other than TB Cochman NRC considers facture to update discovery to be affirmative statement that previous responses still correct SWANSON.D T Hearing Granch | 02/10/15 FINAMORIC B A Naturel Resources Defense Council 3pp 15753 001 24X Fiche 50-537.02/10/15.8210200080
- 8210200047 Answer to 820917 third request for production of documents Certificate of Bvc enci BMANSON D T Hearing Dranch | 82/10/18 Natural Nespurces Defense Council App 15755 088 24% Fiche 50-537.02/10/18. 8210200047
- 8210200092 Supplemental responses to discovery requests Prof qualifications & Certificato of Svc encl HIBBITTS,H W Joint Applicants-Clinch River Broader Renctor 82/10/18 Natural Resources Defense Council 27pp 19/52 11/ 24% Fiche 50-537, 82/10/18, 8210200082
- 8210210357 Response to 821004 sixth set of interrogatories Related correspondence FIRAMORE, BA, WEISS, ER Natural Resources Defense Council WEISS, ER Sierra Club 82/10/18 Atomic Safety and interests Board Panel 26pp 15763 346 24X Fiche 50-537.82/10/10.8210210357
- 8210210453 Response to applicant 821004 soventh set of Interrogaturies & second set of admissions Related correspondence FINAMORE, B A. WEISS, E R. Natural Resources Defense Council FINAMORE, B A. Sierra Club. 82/10/18 Joint Applicants Clarch River Breeder Reactor. 8pg. 15763-065 24X Fiche 50 53/.82/10/16 8210210453
- B210210232 Answer to NRC motion for summary disposition of MADC/hierra Club contentions Motion should be granted for Contentions 6(a) & 6(b)(2) & denied for Contentions 6.6(b)(1), (3) & (4) & 7(a)(1) No matl facts at issue Related correspondence TOUBLEY, D. R., FINAMORE, B. A. Natural Resources Defense Council FINAMORE B. A. Sierra Club B2/10/19 Atomic Safety and Literra-Board Panel 17pp 15766 264 24X Fiche 50-537,62/10/19.
- --B210210240 Affidavit of TB Cockran re environ analyses for fuel cyct timing objective Prof qualifications & Certificate of Evc encil Related correspondence
 COCKRAN, TB Natural Resources Defense Council B2/10/19 13-6 281 24 Fiche 50-537.82/10/19.8210210232

i I

8210220268 Motion for qualification of TB Cochran as expert interrogator, allowing Cochran to cross-examine on Contentions 1,2,3,4,5(b),6,7(a),7(b),8 ii.excluding Contentions 1(b),3(a) & ii.exclud

- -- P230220276 Arfidavit of ER Weiss UCS scientist R Pollard allowed to not
 - 2)0220276 Arfidavit of ER Weiss UCS scientist R Pollard allowed t as expert witness for UCS b as cross-examiner of other witnesses during TMI restart hearing NEISS.ER Natural Resources Defense Council WEISS.ER Unic of Concerned Scientists WEISS.ER Harmon & Weiss 82/10/20 2pp 15775 056 24X Fiche 50-537,82/10/20,8210220268
 - 8210220279 Affidavit of TB Cochran listing qualifications to be considered as expert interrogator COCHRAN, T B Natural Resources Defense Council 82/10/20 5pp 15775 058 24X Fiche 50-537 82/10/20.8210220268
- -8210220203 Arfidavit of TB Cochian clarifying testimony at 820026-2/ hearings Shock wase production not required for nuclear explosion to occur COCHRAN T B Natural Resources Defense Council 15775 063 24X Fiche 50-577, 82/10/20 8210220268 62/10/20 Jpp
- 821022028B Request to derer cross examination of C Johnson until 821213-17 portion of LWA-1 hearings Johnson will not be in US during 821114-19 portion of hearings LEISS.E R. FINAMORE.B A. Natural Resources Defonse Council MEISS.E R. Sierra Club. #2/10/20. Atomic Safety and Liconsing Board Panel. 3pp. 15775-046-24X Fische 50-537.82/10/20. 6210220268
- --8210220295 Motion to regulate conduct of cross-examination Util & NRC should cross-examing witnesses first Util & NRC used cross-eramination for rehabilitation Certificate of Svc enci TOUSLEY.D R . FINAMDRE,B A Naturel Resources Defense Counc)!
 TOUSLEY.D R Sierra Club 82/10/20 Atomic Safety and
 Licensing Board Panel 7pp 15775 069 24% Fiche 50-537.
 52/10/20,8210220268
- 6210250353 Forwards NRC signed % notarrized affidavits re answers to NRDC & Sierra Club 821001 twenty-seventh set of Interrogatories

 LMM/SON, D T Hearing Branch 1 82/10/20 FINAMORG, B , WEISS, F R
 Natural Resources Defense Council 21pp 15790 343 24X
 Fiche 50-537, 82/10/20 8210750353
- @210260397 Supplamental response to second set of admissions & seventh set of interrogatories

 FiraMDRE B A . MEISSE R Natural Resources Defense Council

 FiraMDRE B A . Sierra Club B2/10/21 Joint Applicants-Clinch

 River Breeder Reactor App 15803 331 24X Fiche 50-537.82/10/21, 0210260397
- -8210260404 Statement of qualification for intervenor expert witnesser 18 Cochran & C Johnson Prof qualifications & Certificate of Sic encl
- e210270015 Forwards documents to be placed in PDR Documents respond to 210270015 Forwards documents to be placed in run becomenes respon NRDC & Sierra Club 820917 third request for production of documents & Bierra Club 2/th set of interrogatories SWEEREY.M F Office of the Executive Legal Director 82/10/22 SCOTT.S Document Management Branch 4pp 15818 092 24X Fiche 50 000, 82/10/22, 8210270015
- --8210270020 "Greater Commitment Needed to Solve Continuing Problems at TMI." rept to Congress
 • General Accounting Office EMB-81-106 81/08/26 122pp
 15818 096 24X Fiche 50 000,82/10/22.8210270018
- --8210270023 "INEL as Site for Large LMFBR "
 * 16aho, State of 81/01/31 95pp 15818 218 24x
 Fiche 50-537,82/10/22,8210270015
- --8210270035 "AIRDOS Computer Code for Estimating Population & Individual Doses Resulting From Atmospheric Releases of Radionocities From Nuclear Facilities "
 MORE, R E Dak Ridge National Laboratory ORNL-TM-4687
 /5/01/31 80pp 15819 317 24X Fiche 50-537.82/10/22,8210270015
- --8210270041 "ALLDOS Computer Program for Calculation of Radiation
 Doses From Airborne % Waterborne Roleases "
 STRENOE.D L . NAPIER.D A . PELCOUNT, R A Battelle Memorial
 Institute, Pacific Northwest Laboratory PNL-3524 80/10/31
 152pp 15820 034 24% Fiche 50-537,82/10/22,8210270015
- --8210270052 "CONCEPT 5 User Manual " #RNL-5470 79 /01 /31 HUDSDN.C R Dak Ridge National Laboratory DRNL-5470 191pp 15820 186 24X Fiche 50-537,82/10/22,8210270015

- --8210270056 Advises that listed mods made to CONTAC & CONCEPT computer codes to improve usefulness & accuracy of CONCEPT code HUDBON.C R Oak Ridge National Laboratory 81/09/02 BDWERS.H 1 Oak Ridge National Laboratory 2pp 15821 017 24X Fiche 50-537.82/10/22.8210270015
- --0210270060 "Energy Economic Data Base (EEDB) Program, " Phase 4 final rioz/0000 "chargy Economic Data Base (EBB) Program, Phase 4 Frept & fourth update
 ALLEN.R E United Engineers & Constructors, Inc (subs of
 Raytheon to UE&C-ANL-810930 81/09/30 421pp 15821 019
 24X Fiche 50-537,82/10/22.8210270015
- ---8210270044 Computer runs for 400 MH, 800 MH & 1.200 MH PMRs 4 NRC No Detailed Affiliation Given 82/04/03 24pp 15822 080 24X Fiche 50-537, 82/10/22, 8210270015
- -82(0270068 Provides info re verification of reasonableness of applicant cost estimates for CRBR Applicant cost estimate may be low due to low escalation rate & inadequate contingency allowance for design & regulatory evolution BOMERS.H I Dak Ridge National Laboratory FIN B-0741 82/06/15 TOALSTON.A Antitrust & Economic analysis Branch (Utility Finance) 7pp (5822 099 24X Fiche 50-537.82/10/22,8210270015
- --B210270069 Computer printout for 1.000-yr dose ECKERMAN, K F NRC No Detailed Affiliation Given 75. 28pp 15822 104 24% Fiche 50-537.82/10/22,8210270015
- 82(026035) Corrected Page 4 to applicant 821018 supplemental responses to NRDC & Sierra Club discovery requests Certificate of Svc enci EDDAR O L Project Management Corp 82/10/25 Natural Res Defense Council 5pp 15799 358 24X Fiche 50-537,82/10/25.
- 8210270178 Order ruling on NRC 820927 motion for summary disposition Contentions 6(a) & 6(b)(2) dismissed but Contention 7(a)(1) retained Portions of Contentions 6(b)(3) & 6(b)(4) deleted LINENDERGER.O., MILLER.M.E. Atomic Safety and Licensing Board Panel 82/10/26 Office of the Executive Legal Director lopp 15820 025 24x Fiche 50-537.62/10/26.8210270178
- O Inspection reports. IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 COBP.L I Division of Feel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 44op 1376 82/10/06 Consolidated Edison Co of New York 65pp 24% Fiche 50-000,82/10/06,8208190233
- 8208190239 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-CB19023B IE Unletin B2-03, "Byress corrosion cracking in Thick Mail, Large-Diameter: Statiless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl
 DEYDUNO,R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24% Fiche 50-000, 82/10/14, 8208190238
- T Hearing transcripts on non-antitrust matters
- 8210040257 Transcript of ACRS CRBR Working Group on Sys Integration 820930 meeting (n Washington, DC Pp 1-242 Viewgraphs encl * ACRS Advisory Committee on Reactor Safeguerds 82/09/30 359pp 15594 001 24% Ficha 50-537, 82/09/30, 2210040257
- 8210280133 Transcript of ACRS CRBR Thermal Hydraulic Working Group 821026 queting in Hashington, DC Pp 1-278 Supporting documentation encl * ACRS - Advisory Committee on Reactor Safeguards 82/1 435pp 15839 307 24% Fiche 50-537,82/10/26,8210280133
- 8210290184 Transcript of ACRS Subcommittee on CRBR 821027 meeting in Washington.DC Pp 1-233 Supporting documentation encl * ACRS Advisory Committee on Reactor Safeguards 82/10/27 308pp 15855 048 24X Fiche 50-537.82/10/27.8210290184
- DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION: UNIT 1
- A Application/construction stage documents & correspondence
- 8210120348 Forwards NUREO-0885, "Steam Generator Tube Experience," per telephone request M/o enci VOUNDELOOD, B. J Licensing Branch 1 82/09/13 PILALIS, L Public Service Co of Indiana, Inc 19 15690 300 24X Fiche 50-546, 82/09/13, 8210120348

- 8210210023 Summary of B20917 meeting w/util, Bechtel & Sargent & Lundy in BethesdarMD re SRP conformance review required by 10EFRSD 35 DODLITTLE.E.L. Licensing Branch 1 62/09/27 Licensing Branch 1 5pp 15782 203 24X Fiche 50-546.82/09/27.8210210023
- 8210290008 Provides info on procedures for tendering OL application.
 FBAR & environ rept Two copies of FBAR should be sent
 directly to E080, who will perform acceptance review NRC
 will perform acceptance review of environ rept
 YOUNDBLOOD B J Licensing Branch 1 82/10/06 SHIELDS, S W Public
 Service Co of Indiana. Inc App 15877 073 24X
 Fiche 50-546,62/10/06,8210290008
- G Inspection reports. IE Bullotins & correspondence
- 8210080015 Add1 response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents itsted in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON.J H Division of Rules and Records 82/07/12 UDELL.R A Critical Hass Energy Project 9pp 15665 027 24X
 Fiche 50-000.82/07/12.8210060015
- --82i008Di59 Systematic assessment of licenses performance notes refacility evaluation for Jul 1979-June 1980

 * NRC No Detailed Affiliation Given 80/06/30 9pp
 13668 062 24X Fiche 50-000.82/07/12.8210080015
- 8210130221 Forwards IE Insp Repts 50-546/82-15 & 50-547/82-15 on 820827-28 No moncompliance moted KNOP-R C Division of Project & Resident Programs 82/09/21 SHIELDS: 8 W Public Service Co of Indiana, Inc 2pp 15674 145 24X Fichs 50-546,82/09/21,8210130221
- --9210130222 IE Insp Repts 50-546/82-15 & 50-547/82-15 on 820827-28 No noncompliance nuted Major areas inspected Unit 1 reactor vessel installation activities & IOCFR21 reportable items PELXE.P R . KONKLIN.J E Division of Project & Resident Programs 82/09/20 Spp 15674 147 24X Fichs 50-546.82/09/21.8210130821
- 8208190233 | E Info Notice 80-35, Suppl 1. "Leaking & Dielodged i-185 Implant Seeds " Svc iist enci COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York App 15761 250 24X Fiche 50-000,82/10/06,9208190233
- 8208190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl DEYDUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000, 82/10/14, 8208190238
- 8 Reportable occurrences, LERs & related correspondence
- 8210250130 Interim deficiency rept re incorrect fabrication of several pieces of structured steel Initially reported on 820010 Procedures established to inspect for deficiencies & to repair remaining steel Next rept expected by 830210 SKIECDS.8 W Public Service Co of Indiana Inc 82/10/15 KEPPLER.J © Region 3. Office of Director 2pp 15787 016 24X Fiche 50-546, 82/10/15,8210250130
- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210120348 Forwards NUREO-0886, "Steam Generator Tube Experience," per telephone request W/o encl YOUNOBLOOD, B J Licensing Branch i 82/09/i3 PILALIS, L Public Service Co of Indiana, Inc. 1p. 15670-300 24X Fiche 50-546, 82/09/i3, 8210120348
- B210210023 Summary of B20917 meeting w/util.Bechtel & Bargent & Lundy in Bethesda,MD re SRP conformance review required by iOCFR50 35 DOGLIYTLE.E L Licensing Branch I, B2/09/27 Licensing Branch I 5pp 15782 203 24% Fiche 50-546, B2/09/27, B210210023
- 8210270008 Provides info on procedures for tendering OL application. FSAR & environ rept Two copies of FSAR should be sent directly to EG&O, who will perform acceptance review NRC will perform acceptance review of environ rept YOUNGBLOOD. B. J. Licensing Branch I. 82/10/06 SHIELDS, S. M. Public Bervice Co of Indiana. Inc. 6pp. 15877-073 24X Fiche 50-546, 82/10/06, 8210270008

- O Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info we nuclear reactor events & safety problems Forwards documents 1 issted in App A Documents in App B completely withheld (ref FOIA Eremption 5) FELTON.J M Division of Rules and Records 82/07/12 UDCLL.# A Critical Mass Energy Project 9pp 15645 027 24X Fiche 50-000 82/07/12 8210080015
- --8210080159 Eigstematic assessment of licensee performance notes re racility evaluation for Jul 1979-June 1980 4 NRC - No Detailed Affiliation Civen 80/06/30 9pp 13568 062 24X Fiche 50-000.82/07/12.8210080015
- 8210130221 Forwards 1E Insp Repts 50-546/82-15 & 50-547/82-15 on 820827-28 No noncompliance noted KNOP.R C Division of Project & Resident Programs 82/09/21 SHIELDS.S W Public Service Co of Indiana, Inc 2pp 176/4 143 24X Fiche 50-546,82/09/21.8210130221
- --8210130222 lE insp Repts 50-546/82-15 & 50-547/82-15 on 820927 .ii N noncompliance noted Major areas inspected Unit 1 reactor vessel installation activities & 10CFR21 reportable (test PELKE, P R . KONKLIN, J E Division of Project & Resident Programs 82/09/20 Spp 15674 147 24X Fiche 50-544,82/09/21,02101:81:31
- 8208190233 iE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I はい Implant Seeds " Svc iist encl COBB,L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15/61 よい 24X Fiche 50-000/82/10/06/8208190233
- 8208190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick Wall, Large-Diameter, Stainiess Steel, Recirculation Sys Piping at BWR Plants "Svc list enci DEYDUNG, R C Director's Office, Office of inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190239
- 5 Reportable occurrences, LERs & related correspondence
- 8210250130 interim deficiency rept re incorrect fabrication of several pieces of structured steel Initially reported on 820610 Procedures established to inspect for deficiencies & to repair remaining steel Next rept sepected by 830210 SHIELDS.S W Public Service Co of Indiana. Inc 82/10/15 KEPPLER, J G Region 3. Office of Director 2pp 13787 016 .4x Fiche 50-546.82/10/15.8210250130
- DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1

 Q Inspection reports, IE Bulletins & correspondence
- 820Bi90233 IE Info Notice 80-35, Suppl i, "Leaking & Disindeed I I ar Implant Seeds " Svc list enci COBD.L I Division of Fuel Facilities, Materials & Bafequards 82/10/06 Consolidated Edison Co of New York 64pp 19761 at 4 24X Fiche 50-000.82/10/06.8208190233
- 8208190238 iE Bulietin 82-03, "Btress Corrosion Cracking in Thick WalisLarge-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New Yorl 115pp 13810 125 24X Fiche 50-000, 82/10/14, 8208190238
- DOCKET SYN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2
 O Inspection reports. IE Builetins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I 최고도 Impiant Seeds " Svc list encl COBB.L i Division of Fuel Facilities, Materials & Bafeguards B2/10/04 Consolidated Edison Co of New York 66pp [5/6] 같던 24X Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thack-Mail-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Syc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14, Consolidated Edison Co of New York 113pp 15810 125 24X Fiche 50-000.82/10/14,8208190238

DOCKET STR-50-556 BLACK FOX STATION, UNIT 1

- A Application/construction stage documents & correspondence
- E210330395 Informs that implementation of erosion control plan will adequately stabilize soil in areas found to be eroding during site visit in May MOVAK.TH Assistant Director for Licensing 82/09/24 WEST.J & Public Service Co of Oflahoma 2pp 15692 341 24X Fiche 50-556 82/09/24.8210130395
- i) Inspection reports. IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 Inplant Seeds " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 2h0 24/ Fiche 50-000.82/10/06.8208190233
- \$268190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall. Large-Diameter. Stainlies Steel. Recirculation Sys Piping at BMR Plants "Svc list enc! REYDUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24x Fiche 50-000. 82/10/14.6208190238
- DOCKET STN-50-\$57 BLACK FOX STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B210130595 informs that implementation of erosiun control plan will adequately stability soil in areas found to be eroding during site visit in May MCVAK.TH Assistant Director for Licensing B2/09/24 HEST.JE Public Service Co of Oklahoma 2pp 19692 341 24X Fiche 50-556.82/09/24.8210130995
- a Inspection reports. IF Bulletins & correspondence
- 623B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 [mplant Seeds" "Svc list encl CDBB, L Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & 66pp 15761 250 244 Fiche 50-000 92/10/06, 92081908233
- G2UB19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Bleel, Recirculation Sys Piping at BWR Plants "Svc list encl DEYOUNG, R C Director's Office, Office of Enspection and Enforcement B2/10/14 Consolidated Edison Co of New York 155p 15810 125 244 Fiche 50-000, 02/10/14.020017022B
- GOCKET STN-50-566 YELLON CREEK NUCLEAR PLANT, UNIT 1
- 5258190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 implant Seeds " Svc list encl COBB.L I Pivision of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 24/0
- 623B190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Hall.Large-Diameter.Stainless Steel.Recirculation Sys Piping at DWR Plants " Syc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50~000,82/10/14.8208190238
- S Reportable occurrences, LERs & related correspondence
- 82(0080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on Bil229 Program developed to Insure piping sys operate within design parameters Next rept provided by 82:1217 MILLS.L.H. Tennessee Valley Authority 82/09/24 O'REILLY, J.P. Region 2. Office of Director 3pp 15638 104 24X Fiche 50-000, 82/09/24, 8210080247
- 8210050285 First interin deficiency rept re failure to consider swismic & inertial loadings on ladders, platforms & walkways Initially reported on 820826 Const activities deferred until decision re const completion reached MILLS.L M Tennessee Valley Authority 82/09/27 O'REILLY, J P Region 2, Office of Director 2pp 15611 176 24X Flohe 50-566, 82/09/27, 8210050285

- 8210050293 First interim deficiency rept re six sheared motor pinion keys in Limitorque Model 56-0-25 motor operators Initially reported on 820830 Valves w/motor operators being tabulated Next rept will be submitted by 821122 MILLS.L.H. Tennessee Valley Authority 82/09/28 O'REILLY, J.F. Region 2, Office of Director 2pp 15609 070 24X Fiche 50-000, 82/09/28, 8210050293
- 8210270328 Second interim deficiency rept re use of nonconservative calculational method to evaluate Deneral Const Spec 0-32 spacing violations (nitially reported on 820528 Next rept will be sent by 830528 MILLS.L H Tennessee Valley Authority 82/10/12 O'REILLY, J P Region 2. Office of Director 2pp 15853 064 24X Fiche 50-000-82/10/12,8210270328
- 8210290187 Interim deficiency rept re deferral of const activities Initially reported on 820623 Commitments made in rept.audit findings & response to violations deferred until restart of design & const MILLS.L M Tennessee Valley Authority 82/10/14 0'REILLY, J P Region 2, Office of Director ip 15853 312 24% Fiche 50-000.82/10/14,8210290187
- 8210290236 Third interia deficiency rept re potentially overstressed embedded plates initially reported on 820412 lovestigation continuing & const activities deferred until sufficient info gathered to determine completion of project MILLS.C. M. Tennessee Valley Authority 62/10/14 0'REILLY, J.P. Region 2. Office of Director 2pp 15853 229 24X Fache 50-000,82/10/14,8210290236
- 8210260320 First interim deficiency rept re addition of locking devices to handwheel operated valves initially reported on 820916 Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820310 MILB.4. M Tennessee Valley Authority 82/10/18 O'REILLY. J P Region 2. Office of Director 2pp 15802 359 24% Fiche 50-000.82/10/18.0210260320
- 8210270274 Final rept for Deficiencies D & E & seventh Interim rept for Deficiencies A & D re control of procurement activities Initially reported on 810316 Final corrective actions noted Next rept expected by 830428 MILLS.L M Tennessee Valley Authority 82/10/21 O'REILLY, J P Region 2, Office of Director 4pp 15853 143 24X Fiche 50-000.82/10/21.8210270274
- DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2
 Q inspection reports, IE Buildtins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Beeds " Gyc list enc! CODD.L ! Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fisthe 30-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Mall Large-Diameter. Stainless Steel Recirculation Sys Piping at BMR Plants " Svc Ilst encl DEYOUNQ.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 9 Reportable occurrences. LEAs & related correspondence
- 8210080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on Bil228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MILLS.L M Tennessee Valley Authority 82/09/24 D'REILLY. J'Region 2, Office of Director 3pp 15638 104 24X Fiche 50-000.82/09/24.8210080247
- 8210050285 First interim deficiency rept re fallure to consider & Inertial loadings on ladders, platforms & walkways Initially reported on 820826 Const activities deferred until decision re const completion reached HILLS.L M Tennessee Valley Authority 82/09/27 O'REILLY. Region 2. Office of Director 2pp 15611 176 24X Fiche 50-556, 82/09/27. 8210050285
- 8210050293 First InterIm deficiency rapt re six sheared motor pi keys In Limitorque Model 88-0-25 motor operators Institutly reported on 820830 Valves w/motor operators being tabulated Next rept will be submitted by 821122 MILLS,L M Tennessee Valley Authority 82/09/28 O'REILLY, Region 2. Office of Director 2pp 15009.070 24X Fiche 50-000.82/09/28.8210050293

OCKETED HEIMS

- 8210290328 Second interim deficiency rept re use of nonconservative calculational method to avaluate General Const Spec 0-32 spacing violations initially reported on 820528 Neit rept be sent by 830528 MILLS.L H Tennesses Valley Authority 82/10/12 0'REILLY.J P Region 2. Office of Director 2pp (5853 064 24% Fiche 50-000.92/10/12.8210290328
- 8210270187 Interim deficiency rept re deferral of const activities Initially reported on 820623 Commitments made in rept, audit findings & response to violations deferred until restart of design & const MTLLS.t M Tennessee Valley Authority 82/10/14 0'REJLLY, J P Region 2, Office of Director 1p 15853 312 24X Fiche 50-000, 82/10/14.8210270187
- 8210290236 Third interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 investigation continuing & const activities deferred until sufficient info gathered to determine completion of project MILLS, L.M. Tennessee Valley Authority 82/10/14 0'REILLY, J.P. Region 2. Office of Director 2pp 15853 227 24% Fiche 50-000, 82/10/14, 8210290236
- 8210260320 First interim deficiency rept to addition of locking devices to handwheel operated valves initially reported on 820716 Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820310 MILLS.L. M. Tennessee Valley Authority 82/10/18 O'REILLY.J.P. Region 2. Office of Director 2pp 19802 357 24X Fichs 50-000.82/10/18.8210260320
- 82:0270274 Final rept for Deficiencies B & E & seventh interim rept for Deficiencies A & D re control of procurement activities Initially reported on 810314 Final corrective actions noted Next rept expected by 830428 MILLS.L H Tennessee Valley Authority 82/10/21 O'REILLY, J P Region 2, Office of Director 4pp 15853 143 24X Fiche 50-000.82/10/21.8210290274

DOCKET STN-50-584 OIBBSAR, GIBBS & HILL

- A Application/construction stage documents & correspondence
- 8210270124 Forwards QA program Topical Rept OIBBAR 17-A, Amend & KEDDIS, N N Qibbs & Hill. Inc (subs of Dravo Corp.) 62/10/25 HAGS, W P Quality Assurance Branch ip 15827 (15 24X Fichs 50-584, 62/10/25, 8210270124

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DUCKET 70-0007 ICN PHARMACEUTICALS, INC , IRVINE, CA

- B210050225 Forwards 1E Insp Rept 70-0007/82-01 on 820505-0505 No noncompliance noted KINNEMAN.J D Division of Engineering & Technical Programs. 82/09/30 BAIETTI.A L ICN Pharmaceuticals.Inc., ICN-C&R Development 2pp 15520 048
- --8210060227 IE Insp Rept 70-0007/82-01 on 820505-0605 No noncompliance ' "acility decuntamination surveyed & site closed out cense 37-00345-03 terminated M. KINNEMAN.J D. Division of Engineering & Technical 92/08/02 10pp 15620.050

CA

--- CANDOS O O

for

- --8210060356 IE Safeguards Insp Rept 70-0025/82-08 on 920913-16 No noncompliance noted Major areas inspected measurement control program & independent insp safeguards effort Details withheld (ref 10CFR2 790)
 NELEON, 0 B Division of Radiological Safety & Safeguards Program 82/09/27 ip 15615 193
- DOCKET 70-0027 BABCOCK & WILCOX CO , LYNCHBURG, VA
- 8210270232 Forwards mods to B&W upgrade physical security plan.made during implementation Mods withheld (ref 10CFR2 790) KELLY.J W Babcot & Wilcor Co 82/06/10 EVANS, L J Fuel Facility Safeguards Licensing Branch 2pp 15836 070
- 8210010353 Forwards IE Safeguards Insp Rept 70-0027/82-19 on 820973-2 No noncompliance noted GIBSON.AF Division of Engineering & Technical Programs 82/09/1 ECKERT.JP Babcock & Wilcox Co 2pp 15549 233
- --B210010361 IE Safeguards Insp Rept 70-0027/B2-19 on B20023-26 No noncompliance noted Major areas inspected MC 65206B measurement control & statistics Details withheld (ref 10CFR2 790) SABADDS,J W, MCALPINE,E J Division of Engineering & Technolas Programs 82/09/10 ip 15569 235
- 8210150229 Forwards IE insp Rept 70-0027/82-20 on 820830-0901 No noncompliance noted GIBBONAF Division of Engineering & Technical Programs 82/69/1 ECKERT, J.P. Babcock & Wilcox Cd. 2pp. 15701 356
- --8210150239 IE Insp Rept 70-0027/82-20 on B20830-0901 No noncomplet noted Hajor areas inspected review of lab GC program, radiochemistry procedures & records & liquid & gaseous sampling & accountability EVANS.C D. MCNTGOMERY.D M Division of Emergency Preparedness: Operational Support 82/09/16 4pp 15701 358
- 8210220497 Forwards page changes to radiological contingency plan to clarify procedure for notifying NRC state & locality of declared state emergency Provisions for assessing offsite radiological impact of radiological emergency also revised KELLY.J W Babcock & Wilcox Co 82/09/29 PAGE.R Q Uranium Fu Licensing Branch 4pp 13786-317
- 8210210341 Forwards IE Safeguards Insp Rept 70-0027/82-25 on 820927-1001 No noncompliance noted 01BSDN.AF Division of Engineering & Technical Programs 8://ID/ ECKERT,JP Babcock & Hitcox Co 2pp 15764 307
- --B210210342 IE Safeguards Insp Rept 70-0027/82-25 on 820927-1001 21: noncompliance noted Najor areas inspected socurity plan & implementing procedures, records & repts, locks, keys & detection aids Details withheld (ref 100FR73 21) 000DE.R W , MCGUIRE.D R Division of Engineering & Technical Programs 82/10/14 ip 15764 309
- DOCKET 70-0033 TEXAS INSTRUMENTS, INC , ATTLEBORG, MA
- 8210070239 Forwards IE Insp Rept 70-0033/82-04 on 820901-03 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 82/09/2: 00ETZ.H K Texas Instruments, Inc 2pp 15637 146
- --8210070240 IE Insp Rept 70-0033/82-04 on 820901-03 No noncompliant noted Major areas inspected review of operations closeout surveys; environ programs & licensee/licensing meeting ROTH, J. KEIMIG, R. Division of Project & Resident Programs SHUM, E. Office of Nuclear Material Safety & Safeguards, Directum 82/09/21 4pp 15637 146
- 8210290238 Forwards IE Insp Rept 70-0033/82-03 on 820831-0902 No noncompliance noted MARTIN,T T Division of Engineering & Technical Programs 82/10 00ETZ,W H Texas Instruments, Inc 2pp 15853 198
- --8210290241 IE Insp Rept 70-0033/82-03 on 820831-0902 No nancompti noted Hajor areas inspected licensus closeout survey rept. Independent measurements in general mfg area-chemical & metallographic labs & roof schausts JOHAMSENJ J. LADUN.R . KINNEMANJ D Division of Engineering & Technical Programs 82/10/12 lipp. 15853 200.

- EGLEET 70-0036 COMBUSTION ENGINEERING, INC . WINDSOR, CT
- 8210210583 Provides schedule for review of license renewal application Comments & recommendations on application.notification of scheduled insp & action required to meet schedule requested CRGW.H T Uranium Fuel Licensing Branch 82/10/01 HILLER.J R Division of Engineering & Technical Programs 2pp 15782 360
- 8210180316 Requests transfer of C-E fee funds from deferred revenue to ratis revenue account per review of amend to License ENM-33 HILLER.W D. License Fee Management Branch 82/10/06 MANION.W E Finantial Operations Branch 1p 15746-017
- BOCKET 70-0135 BABCOCK & WILCOX CO . APOLLO, PA
- EZIO130303 Ack receipt of 820728 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/82-07 & 70-034/82-04 SIARDSTECKI, R Division of Project & Resident Programs 82/10/04 CARLEON, R V Babcock & Wilcox Co Ip 15678 181
- DOCKET 70-0143 NUCLEAR FUEL SERVICES: INC . ERWIN: TN
- B210270235 Application for amend to License SNM-124 to allow use of rimishing unit for transhing highly enriched U in Bidg 110 MICHEL C J Nuclear Fuel Services. Inc (subs of Getty Oil Co) B2704714 2NXON,W A Division of Fuel Cycle & Material Bafety 2pp 18074 073
- @310200571 Forwards Revision 8 to physical sefeguards plan incorporating personnel search to detect 3 g unshielded U. enriched to 90% U-238 to allow wider range of flexibility Revision withheld (ref 10CTR73 21) MICHEL: C J Nuclear fuel Services: Inc (subs of Getty Oil Co) 82/06/01 EVANS.L J Fuel Facility Safeguards Licensing Branch Ip 15814 358
- e210150061 Confirms 820721 commitment to submit groundwater monitoring program to NMSS by 821015 KANSEN.N C Nuclear Fuel Services. Inc. (subs. of Getty Cil Cn.) 62/07/27 GIBEON.A F Division of Engineering & Technical Programs 1p. 15701-264
- 8210010164 Ack receipt of IC lnsp Rept 70-0143/82-28 No proprietary into Ambier, H C Nuclear Fuel Services, Inc (subs of Getty Oil Cu) 82/08/30 (3850N.A F Division of Engineering & Technical Programs 19 15368 090
- 62:102:605:6B Forwards Page 3-2 to application for renewal of Certificate of Compliance 5492 for Model RMG-181-I inadvertantly emitted from original MICHEL.C J. Nuclear Fuel Services. Inc. (subs. of Getty Di) Co.) 92/08/30 MACDONALD.C E. Transportation Branch ip 15914-355
- --8210260569 Page 3-2 to application for renewal of Certificate of Compliance 5492 for Model RMO-181-1 HACDONALD.C & Transportation Branch 82/08/25 ip 15814 386
- 8210010162 Concurs w/decision to terminate use of environ impingers in conjunction w/snyiron samples; based on review of 820527 results of environ impinger air measurements for Jan-Mar 1982 (ISSON A F Division of Engineering & Technical Programs 82/09/03
- classon, A.F. Division of Engineering & Technical Programs 82/09/03 MANSER, W.C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) ip 15567-273
- 8210010344 Forwards IE Insp Rept 70-0143/82-32 on 820823-27 No noncompliance noted GISSON:A F Division of Engineering & Technical Programs 82/09/10 MANEER.N C Nuclear Fuel Services, Inc (subs of Oetty Oil Co) 2pp 15369 236
- --8210010371 IE lnsp Rept 70-0143/82-32 on 820823-27 No noncompliance noted Hajor areas inspected facility operations, storage & internal control & records & repts Details withheld (ref 10CFR2 790)
 10DD.0 A MCALPINE.E J Division of Engansering & Technical Programs 82/09/10 ip 15569 238

- 8210150197 Forwards IE Safeguards Insp Rept 70-0143/82-33 on 820806-0903 No noncompliance noted 01850N.A.F. Division of Engineering & Technical Programs 82/09/14 MANSER.W.C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 2pp 15715-273
- --8210150204 IE Safeguards Insp Rept 70-0143/82-33 on 820806-0903 No noncompliance noted Major areas inspected licensee action on previous inspectodine events & facility operation Details withheld (ref 10CFR2 770)
 LEE.T D , MCALPINE,E J Division of Engineering & Technical Programs 82/09/14 App 15715 275
- 8210040048 Ack receipt of check in payment of civil penalty proposed on 820809 Corrective action discussed in 820903 ltr will be examined during future insp.
 AXELRADIJA Director's Office, Office of Inspection and Enforcement 82/09/21 MANSER, W.C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 2pp. 15977 208
- 8210010052 Denies 820127 % 0507 requests that IE Insp Rept 70-0143/81-04 not be placed in PDR 0/REILLY.J P. Region 2. Office of Director 82/09/22 MANSER,W C Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.) ip
- 82(0010313 Forwards IE Safequards Insp Rept 70-0143/82-34 on 820907-10 No noncompliance noted OIBSON.A F Division of Engineering & Technical Programs 82/09/22 MANSER.H C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 15568 283
- ---8210010317 IE Safeguards Insp Rept 70-0143/82-34 on 820907-10 No noncompliance noted Major areas (nepected shipping & receiving of SNM Details withheld (ref 10CFR2 790) JONES, D W. RICHARDS, B L. NCALPINE, E. J. Division of Engineering & Technical Programs 82/09/22 ip 15568 285
- B210150473 Ack receipt of check for \$2,500 sent in payment of civil penalty proposed on 820809 Corrective action specified in 820703 it will be examined at future inspective AXELRAD. J A Enforcement Staff 82/09/22 MANSER. W C Nuclear Fuel Services. Inc (subs of Oetty Oil Co) 2pp 15714 172
- --B210150477 Responds to NRC B20809 itr re violations noted in IE Insp Rept 70-0143/82-23 Corrective actions withheld (ref 100FR2 790) Payment of civil penalty encl MANSER, H C Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) B2/09/03 Director's Office, Office of Inspection and Enforcement 1p 19714 174
- 8210040085 Order establishing addl extensions of time Parties may submit questions to be posed in oral session by 821107 Oral session will be held between 821215-830115 CHILK, S. J. Office of the Secretary of the Commission 82/10/01 2pp 15581 037

821

- --8210150376 Forwards IE Safeguards insp Rept 70-0143/82-29 on 820802-06 & notice of violation Details & notice of violation uithheld (ref 10CFR73 21)
 GLSHINSKI.J A Division of Engineering & Technical Programs 82/08/25 MANSER.W C Nuclear Fuel Services, Inc. (subs. of Gutty Gil Co.) 2pp 15704 273
- --82101503BD IE Safaguards insp Rept 70-0143/82-29 on 820802-06 Noncompliance noted failure to review & audit safaguards contingency plan Datails withheld (ref 10CFR73 21) PERRY, C.D., TILLMAN, A., MCGUIRE, D.R. Division of Engineering & Technical Programs 82/08/24 2pp 15704 275
- 82/0/30393 Motion for Commission to direct DDE to make available to NRDD.under suitable protections, classified info covered by enci FOIA requets Deadline for filing testimony should be suspended Certificate of Svc enci HEISS.ER Natural Resources Defense Council HEISS.ER Harmon & Weiss 82/10/08 Commissioners 12pp 15680 324
- 8210130281 Advises that organization will appear at hearing but will not present direct oral testimony Comments provided on Issues A.B & C
 MISDRENER.J M Oil.Chemical & Atomic Workers Intl 82/10/12
 CHILK.S J Office of the Secretary of the Commission 3pp 15678 278
- 8210150472 Order denying NRDC 821012 motion to suspend deadline for filing testimony until NRDC FOIA requests resolved Motion would be unnecessary if NRDC had filed FOIA request on more timely basis Commissioner Ahearne separate views encl CHIKLS J Office of the Secretary of the Commission 82/10/14 Natural Resources Defense Council Opp i5703 040
- 8210180103 Submittal of R Burnett 820930 testimony representing consolidated testimony of all NRC ofcs
 FORMER.R L. Regulations Division 82/10/14 2pp 15718 025
- --82i0180107 Testimony of R Burnett Present safeguards program adequate to protect public health & safety License should be revoked if amend not sustained W/Certificate of Svc BURNETT.R F Division of Safeguards 82/09/20 30pp 15718 02/
- B210200001 Forwards memorandum of law re license amend process & TB Cochran testimony Testimony & Exhibit 28 withheld SCHERR.B J Natural Resources Defense Council B2/10/15 STUCKY.S H Docketing & Services Branch (p 1575
- --8210200004 Nemorandum of law on license amend process Amend unlawfully substitutes "reasonably athewable" set in place of lagislatively orderned std of protection of public health & safety Certificate of Svc enci Exhibit 28 withheld MEISS ER Natural Resources Defense Council 82/10/15 Commissioners 240pp 15755 105
- B210200057 Response opposing NROC motion for Commission to direct production of documents FOIA process cannot be used as substitute for discovery Commission has no authority to order production of DDE documents Certificate of Svc encl LEIKEN.L., BERGHOLZ,W E Energy, Dept of B2/10/18 Commissioners Spp 15756-048
- 8210250050 Forwards Page 50 of written testimony filed w/Commission on 821015 LEIKENLL Energy, Dept of 82/10/21 CHILK,5 J Office of the Secretary of the Commission 1p 15787 090
- ---B210280061 Page 50 of testimony filed w/Commission on B21015, inadvertently omitted Certificate of Svc encl ← Energy, Dept of 82/10/21 3pp i5787 091
- DOCKET 70-0223 CALIFORNIA, UNIV OF, LOS ANGELES, CA
- 8210290023 Partial response to FDIA request for documents re UCLA Lab & research reactors Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/09/03 HJR9CH, D Government Accountability Project 2pp. 15864 195
- --B2iO29004B Discusses insp of activities authorized under License R-71 & SNM-974 on 780520 No honcompliance noted Major areas inspected control of SNH & selective exams of procedures & personnel interviews ENGELKEN, R H Region 5, San Francisco. Office of the Director 75/06/10 BROWN, H V California, Univ of, Lus Angeles 1p 15864 262 24X Fichs 30-142,82/09/03,8210290023

- DOCKET 70-0278 DOW CHEMICAL CO , MIDLAND, MI
- 8210180028 Responds to FOIA request for seven categories of documents re Dow Chemical Co & incineration of low level radwaste Request for fee waiver granted Forwards listed documents FELTON.J M. Division of Rules and Records 82/08/20 MII/44 A MARTHIBATION Unknown 2pp
- --8210180424 Provides info re use of Dow Chemical Co radiation protest, manual, per AEC 581219 itr Requests info on licensing of irradiated U
 BEAMER, W. H. Dow Chemical Co. 58/12/24 JOHNSON, L. Atoms trans. Commission 2pp 15748 331
- DOCKET 70-0364 BABCOCK & WILCOX CO , APOLLO, PA
- 8210280452 Forwards corrected Page 8 of Amend 17 to ticense "IH 414 issued 820831 License Condition 36 C should reflect conditions contained in Amend 12 issued 810225 ROUSEL C Advanced Fuel & Spent Fuel Licensing Branch INTO Fuel AUSTIN.H A Babcock & Wilcox Co ip 19859 011
- --8210280453 Corrected Page 8 to Amend 17 to License GNM-414, revisits
 License Condition 36 C
 ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch (12) July
 15857 012
- 8210070307 Forwards IE Insp Rept 70-0364/82-05 on 82072) & notice of violation
 MARTIN.T T Division of Engineering & Technical Programs (12707) I
 CARLSON/R V Babcock & Wilcol Co 2pp 15604 (2)
- --8210070312 Notice of violation from insp on 02072,)

 # Division of Engineering & Technical Programs (02/07/24 ***)
 15434 125
- --8210070316 IE Insp Rept 70-0364/82-05 on 820723 Noncompliance Priss escessive dose rate at external surface of vehicle & factore to label package correctly CLEMONS.P E. GREENMAN.E G. Division of Engineering & Techniss
- S210130303 Ack receipt of 820928 Itr informing NRC of tipps taken to correct violations noted in IE Insp Repts 70-0135/02 0/ L 70-0364/82-06 STARDSTECKI, R Division of Project & Resident Programs III/IU/C+ CARLSDN, R V Babcock & Wilcor Co Ip 15678 181
- ~-82i0130308 Responds to NRC 820701 ltr re violations noted in It in page 15. Repts 70-0135/82-07 & 70-0364/82-06 Corrective actions amount of uranate drying belt encl adjusted & more effectively designed reflector installed AUSTIN.M A Dabcock & Wilcox Co 82/09/28 STAROBITCKI.OR Division of Project & Resident Programs 2pp 136/0 187
- DOCKET 70-0371 UNC NAVAL PRODUCTS, INC , UNCASVILLE, CT
- 8210040372 issues Amend 18 to License 8NM-368, authorizing new aturage shelves & new fuel handling criteria for raw fuel storage room, in response to 820510 application & 020404,0707 & OBI2 suppls PAGE,R 0 Uranium Fuel Licensing Branch 82/09/07 XIRK,N & United Nuclear Corp 2pp 15577 214
- --B210040397 Safety evaluation supporting Amend 18 to License 'Het art BIDINGER O H. (ROWH T Uranium Fuel Licensing Branch ()2/t2/JI 2pp 15597 216
- 8210250016 Forwards revised fundamental nuclear mail control program
 H/o enci
 COLLOPY, T J United Nuclear Corp 82/09/07 EVANS, L J Fuel
 Facility Safeguards Licensing Branch ip 15808 259
- 8210220168 Forwards IE Safeguards Insp Rept 70-0371/82-10 on 826(16-1) No noncompliance noted MARTINIT T Division of Engineering & Technical Programs Bartorial AMY, 0 0 United Nuclear Corp 2pp 15778 055
- ---8210220172 IE Safeguerds Insp Rept 70--0371/B2-10 on B20816-19 Pdnoncompliance noted Major areas inspected security plan & implementing procedures lighting & review of open items Details withheld (ref iOCFR73 21) SMITH.0 C. QODY.A T. Division of Engineering & Technical Programs. 82/10/07 ip 15778 057

- 8210220177 Forwards IE Safeguards Insp Rept 70-0371/82-09 on 820809-13 No noncompliance nated MARTIM T Division of Engineering & Technical Programs 82/10/14 AMY.C O United Nuclear Corp 2pp 15777 304
- --0210220179 [E Safeguards Insp Rept 70-0371/82-09 on 820809-13 No noncompliance noted Major areas inspected measurement control program Details withheld (ref 10CFR2 790) ZIBULSKY, H. (DDY, A T Division of Engineering & Technical Programs 62/10/07 lp 15777 306
- DOCKET 70-0398 COMMERCE, DEPT OF, WASHINGTON, DC
- 921CO60138 Ack receipt of 820917 ltr informing NRC of steps taken to correct violations noted in IE lusp Repts 70-0398/82-03 & 30-0398/82-03 MARTIN.T T Division of Engineering & Technical Programs 82/09/30 PEVEYIL E Commerce. Dept of National Bureau of Standards 1p 15414-304
- --8210060147 Responds to NRC 820908 litr re violations nated in IL lisp Repts 70-0398/82-03 & 30-03918/82-03 Corrective actions instructions issued re Spec /A container reuse & labeling & posting of containers for CF-252 source PEVEY.L E Commerce.Dept of National Dureau of Standards 82/09.17 MARIN.T T Division of Engineering & Technical Programs 2pp 19614 305
- DOCKET 70-0416 COLORADO STATE UNIV , FT COLLING, CO
- 6210220004 IE Insp Findings & Licensee Ack dtd 620921 of License SKM-380 Insp findings no violations observed SPITZBERG, D B Region 4. Office of Director 82/09/21 13pp
- DELKET 70-0633 PARI AMERICAN WORLD AIRWAYS, INC., PATRICK AFD, FL
- 8210010116 IE Insp Findings & Licensee Ack dtd U20901-02 of License ENM-575 Insp findings no nancompliance noted FRAMALIN I Region 2, Office of Director 82/09/02 ip 15567 219
- COLKET 70-0607 UNION CARBIDE CORP , TUXEDO, NY
- G510270067 Forwards integrated site wide emergency preparedness plan Agreement itrs enci RUZICKA.W G Union Carbide Corp 82/09/03 CUNNINGHAM.R E Division of Fuel Cycle & Material Safety ip 15836 128
- B210220260 Forwards IC Sareguards Insp Rept 70-0687/82-06 on 820907-10
 No noncomptiance nuted
 MARTIN T I Division of Engineering & Technical Programs 82/10/13
 MCGOVERN, J J Union Carbide Corp 2pp 15776 325
- --0210220264 IE Safeguards Insp Rept 70-0607/02-06 on 920907-10 No noncompliance noted Major areas inspected nuclear maticontrol & accounting including measurement & statistical controls Details withheld (ref 100FRZ 790) 218ULSKY, H. RATTA, A. D. GODY, A. T. Division of Engineering & Technical Programs 62/10/07 ip 19774-32/
- DOCKET 70-0753 WHEATON COLLEGE, WHEATON, IL
- 6216220343 Hemorandum & order directing OE to file rept on intention to submit applications to renew OL & SNM license, within 15 days of sic of order FRYEL JH Atomic Safety and Licensing Board Panel 92/10/21 General Electric Co 3pp 19776 265 24X Fiche 50-070, 82/10/21, 8210220343
- DOCKET 70-0754 GENERAL ELECTRIC CO . PLEABANTON: CA
- 8210080302 Forwards IE Insp Repts 70-0754/82-03 on 820812 & 70-0754/82-04 on 820910 & 14 Excessive Pu contamination Levels found in Advanced Fuels Lab Dlog 102 basement, front isb & sodium room areas in 820812 insp BOOK-H E Division of Radiological Bafety & Bafeguards Program 82/10/05 ROUSEL C Advanced Fuel & Spent Fuel Licensing Branch 2pp 15638 008

- --82100803ii IE Insp Rept 70-0754/82-04 on 8209i0 & 14 Major areas inspected walls, floors, pipelines & fixture Pu cuntamination levels in Advanced Fuels Lab Bldg 102 Surfaces within guidelines for release of area for unrestricted use RIEDLINGER, D A. PANG.J F., ZURAKORSKI.P R. Division of Radiological Safety & Safeguards Program 82/09/28 19pp 15408 029
- 8210190473 Forwards IE Insp Rept 20-0754/82-04 nn 820910 % 14 No noncompliance noted BOUK-H E Division of Radiological Safety & Bafeguards Program 82/10/05 BARMITZEL, R W General Electric Co 2pp 15740 220
- 8210200087 Notice of ASLB reconstitution UH Frye, chairman & H Foreman & GA Linenberger, members COTTER, B P Atomic Safety and Licensing Board Panel 82/10/14 2pp 15753 176 24X Fiche 50-070 82/10/14 8210200087
- DOCKET 70-0820 UNITED NUCLEAR CORP . WOOD RIVER JCT . RI
- 8210270218 Forwards well results Sr-90(pCi/L).Apr 1980-Mar 1982 MELGESON.K A United Nuclear Corp 82/06/17 CROW.W T NRC - Nu Detailed Affiliation Given 2pp 158/36/041
- 8210250012 Forwards corrected copy of fertilizer analysis performed & reported on 800718 Analysis consistent w/n ture of crushed apatite fertilizer

 #ELICESON.K A United Nuclear Corp 82/06/22 CROW.W T Uranium Fuel Licensing Branch 2pp 15808 181
- 8210270206 Forwards corrected copy of Controls for Environ Pollution.
 Inc 800718 fertilizer analysis, per 820311 request Fluoride
 concentration analysis consistent w/nature of crushed
 apatite fertilizer
- HELDESON:K A United Nuclear Corp 82/06/22 GROW,W T Uranium Fuel Licensing Branch 2pp 15835 031
- 8210200104 Forwards "Water Solubility Test Performed on Soll," used by analytical vendor HELOESONIK A United Nuclear Corp. 82/08/18 CROW.W.T. NRC - Nu Detailed Affiliation Olven Ip. 15767-307
- --B2(0200106 "Water Solubility Test Performed on Soli," for United Nuclear Corp.Woodriver Junction.RI MUELLER.JJ Controls for Environmental Pollution. Inc. B2/07/ NRC - No Detailed Affiliation Given 9pp 15767 308
- 8210250014 Forwards response to NRC comments on licensee 820412 detailed soil decontamination plan Revised plan will not be presented but comments will be incorporated into plan GREGG, R.J. United Nuclear Corp. 82/08/31 CROW.W.T. NRC No Detailed Affiliation Given 6pp 15808 253
- 821026010B Forwards response to NRC comments on B20412 detailed suil decontamination plan Conduit to river will be surveyed per required criteria Site characterization survey will be forwarded under separate cover GREO,R J United Nuclear Corp 82/08/31 CROW,W T NRC No Detailed Affiliation Given 6pp 18808 353
- 8210270213 Forwards response to NRC Comments 1-13 on 820412 "Detailed Spil Decontamination film " Revisions will be incorporated into final survey rept GREOG.R J United Nuclear Corp 82/08/31 CRDW.W T NRC No Detailed Affiliation Given 6pp 15836 035
- 8210260038 Forwards site characterization survey w/addendum re dose commitment data for Lagoon A area soi) sample analyses HELCESON,K A United Nuclear Corp 82/09/02 CROW,W T NRC - No Detailed Affiliation Given ip 15809 001
- --8210260041 Exposure tables for Dec 1981 * Controls for Environmental Pollution, Inc 81/12/31 41pp. 15809 002
- --B210260049 "Macadam & Soil Statistical Analysis & Evaluation of Analytical Data for Decommissioning of Woodriver Junction Facility "

 * Controls for Environmental Pollution, Inc. 81/97/14 443pp. 15809 042
- 8210270173 Provides info on & justification for two imperative actions to be taken as preventive maint re reaf over main processing bldg & ofc areas & steelwork in process area OREGO, R. J. United Nuclear Corp. 82/09/07 GROW, W.T. NRC No Detailed Affiliation Given Spp. 15835-329

- B2102902il Requests detailed survey rept for maint to be performed on roor & steelworks, including map showing grid sizes & locations & survey results for each grid Time should be scheduled so Region I can conduct survey prior to painting CROW-HT Uranium Fuel Licensing Branch 82/09/28 GRECO.R J United Nuclear Corp in 15876 287
- DOCKET 70-0824 BABCOCK & WILCOX CO . LYNCHBURG, VA
- 821022021 Responds to MRC ltr re violations noted in IE lnsp Rept 70-0824/82-09 Corrective actions cutting & walding permit form revised W/o encl OLSEN A F Babcock & Wilcox Co 92/08/18 TRDUP, O L Region 2, Office of Director 1p 15775 130
- B2(0150130 Forwards tE Insp Rept 70-0824/82-05 on 820901-03 No noncompliance noted OIBSON A F Division of Engineering & Technical Programs 82/09/16 ENGELDER, T C Babcock & Wilcox Co 2pp 15498-318
- --82i0i50i36 iE insp Rept 70-0824/82-05 on 82090i-03 No noncompliance noted Major areas inspected external & internal radiation control. Contamination surveys & source leak testing XAMLE-J B. METZGER, J R. BARR, K. Division of Engineering & Technical Programs 82/09/15 4pp 15698 320
- 9210010388 Forwards IR Safeguards Insp Rept 70-0824/82-06 on 820909 & 17 No noncompliance noted OTBEONAF Division of Engineering & Technical Programs 82/09/22 ENGELDER: T C Babcock & Hilcox Co 2pp 19572 289
- --B210010378 IE Safeguards insp Rept 70-0874/82-06 on 820909 & 1/ Nu moncompliance noted Major areas inspected MC-85206 measurement control program (scrap/waste) Rept details withheld (ref 100FR2 790) CLAY, E. L. MCALPINE, E. J. Division of Engineering & Technical Programs 82/09/22 ip \$5572.291
- 8210210194 Forwards IE Bafeguards Insp Repts 50-013/82-03 & 70-0824/82-10 pn 820930-1001 No noncompliance noted OIBBON: A F Division of Engineering & Technical Programs 82/10/11 ENGELOBER: T C Babcot & Wilcot Co 2pp 15765 304 24x Fiche: \$0-013, 82/10/15, 8210210194
- --B210210206 IE Safeguards Insp Repts 50-013/82-03 & 70-0824/82-10 on 820930-1001 No noncompliance noted Major areas inspected physical protection of low enriched SNN Details withheld (ref 10CFR2 790)

 GODDE, R. HCGUIRE, D.R. Division of Engineering & Technical Programs 82/10/15 ip 15765-306 24X Fiche 50-013,82/10/15,82/10/10/15
- DOCKET 70-1100 COMBUSTION ENGINEERING, INC. WINDSOR, CT
- 8210220440 Forwards typical American Nuclear Insurers insp rept. BHEERAN.R E Combustion Engineering. Inc. 02/09/16, NRC - No Detailed Affiliation Oiven Spp. 15786 214
- 8210060365 Forwards IE Safequards Insp Rept 70-1100/82-07 on 820824-27 No noncompliance noted MARTIK. T. Dyvision of Engineering & Technical Programs 82/09/28 LICHTENBERGER Combustion Engineering, Inc. 2pp 15615.188
- --8210060370 IE Safeguards Insp Rept 70-1100/82-07 on 820824-27, No noncompliance noted Hayar areas inspected, facility organization, operation & mot of matis control sys Details withheld (ref 100FR2, 790) DELLA RAFFA, A., GODY, A.T. Division of Engineering & Technical ms. 82/09/21 19 15415, 190

ceipt of 820910 ltr informing NRC of steps taken to one noted in IE Insp Rept 70-1100/82-04.

Project & Resident Programs. 82/09/29 oring, Inc. ip 13883 100

s violations noted in IE Imap adjustable windows for chemistry labs set at

- BOCKET 70-1113 GENERAL ELECTRIC CO , WILMINGTON, NO
- 8210220518 Advises that groundwater munitoring program will by implemented before 821101 MAKILD.C North Carolina, State of 82/09/15 CROH.W 1 Urina: *Recovery Licensing Branch ip 15786 085
- B21G150064 Forwards IE Safeguards Insp Rept 70-1113/82-10 on 020/07-11 No noncompliance noted G1g80N, AF Division of Engineering & Technical Programs DP/69-21 LONG, J.A. General Electric Co. 2pp. 15715-270
- --BR10150067 IE Safeguards Insp Rept 70-1113/82-18 on 020/0/-10 had noncompliance noted Major areas inspected measurement control program & followsp of previous insp findings Details withheld (ref 10CFR2 790)

 BATES, J W. SABADOS, J W. MCALPINE, E J Division of Engineering | Technical Programs 82/09/24 ip 15713 271
- 82i0270425 Notification of contract execution. Hod 2 to "flA No of Stations SNM-iO97" Contractor Science Applications, Inc. FLEENOR.C M. Administrative Contracts Branch FIN 19 737 1 82/09/30 DAVIS.J., LOYSEN.P. Office of Nuclear Material infesty 1 Bafeguards, Director 1p 1983 357
- --B210270428 Mod 2, deobligating unexpended balance of contract furtatassance of no cost settlement after termination, to 'fla re OE SNM License SNM-1097" ARCHER: C D Science Applications, inc HAGAN, T fighths with Assistance Contracts Branch FIN 8-7337-1 102/09/20 Jep 1883 388
- 8210210514 Forwards draft litense conditions re effluent & phosphin nonradiological monitoring requirements Conditions (notice stack monitoring of fluoride release & groundwater monitoring on nonradiological parameters (ROWH T Uranium Recovery Licensing Branch B2/10/0) MAKILD (North Carolina, State of App. 19782 201
- 8210220205 Ack receipt of iE Insp Rept 70-1113/82-20 on 120/11 1 J N proprietary info VAUCHANG M General Electric Co 82/10/12 GIMBRAN J DEVEN of Engineering & Technical Programs ip 13/76 373
- 82:0220420 Ack receipt of 820714 ltr informing NRC of steps taken to correct violations noted in iC lnsp Rept 70-1117/H2 /A OLGHINSKI, J A Division of Engineering & Technical Programs 82/10/12 LONG, J A General Electric Co ip 15780 211
- --8210220427 Responds to NRC 820820 ltr re violations unted in lt Rept 70-lii3/82-i6 Corrective actions meetings between supervisors & radiation technicians conducted & new survey squipment ordered VAU04AN.C M Ceneral Electric Co 82/09/14 CLGHRGhl. F A Division of Engineering & Technical Programs 3pp 15/40 213
- --8210220430 Forwards IE Insp Rept 70-1113/82-16 on 820/26 to 8 vK & notice of violation OLSHANBRIJ A Division of Engineering & Technical Programs 82/08/20 LONG, J A General Electric Co 2pp 15/80 215
- --8210220437 Notice of violation from insp on 820726 30 t C(s)-1-Q\$

 # Division of Engineering & Technical Programs 62/08/-0
- --B210220442 IE Insp Rept 70-iii3/B2-i6 on B20726-30 \$\(\theta\) OS Noncompliance noted contamination limits exceeded for release of mati to restricted area HOGEY, C M , BARR, K P Division of Engineering & Technical Programs 82/08/19 10pp i3780 218
- 8210220308 Ack receipt of 820930 ltr informing NRC of steps total correct violation noted in IR Insp Rept 70-113/82-17 OIBBON.AF Division of Engineering & Technical Programs Balchov, J.A. General Electric Co. ip 15778 304
- --BR10220320 Responds to NRC 820702 itr re-violation noted in RE Rept 70-1113/82-17 Corrective actions withheld cred 10CFR2 790) VAUDHAN, C.M. General Electric Co. 82/07/30 DLGHINDK ... P Division of Engineering & Technical Programs ip 187/9 36
- DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP . PITTSBUNGH. PA
- 8210150433 Advises that portion of fee for Amend 7 to Licence SJ will be refunded MILLER W.O. License Fee Management Branch 82/10/07 MARD). Westinghouse Electric Corp. 1p. 15715.360.

SOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA

- E21GOID:189 Ack receipt of IE Safeguards Insp Rept 70-1151/82-16 on 820815-19 No proprietary info FOSTER, H Westinghouse Electric Corp 82/09/10 O'REILLY, J P Region 2, Office of Director ip 15567 312
- 321u270434 Amend 11 to License SRM-f107, authorizing disposal of mott containing trace quantities of enriched U as of 820818 PACE,R G Dranium Recovery Licensing Branch 82/10/12 NORDI.A J Hestinghouse Electric Corp. jp. 15833-281
- --0210270436 Safety evaluation supporting Amend 11 to License StM-(10) redisposal of trace quantities of enriched U BIDHOGER.G H. CROW.W T Uranium Recovery Licensing Branch 82/10/12 1p 15033 202

DOCKET 70-1201 BABCOCK & WILCOX CO . LYNCHBURG. VA

- e210010121 Forwards IE Insp Rept 70-1201/82-13 on 820830-0901 No noncompliance noted CIBSON A F Division of Engineering & Technical Programs 82/09/10 ALTO, R A Babcock & Wilcox Co 2pp 15567 220
- 8210010127 IE Insp Rept 70~1201/82~13 on 820830~0901 No honcompliance noted Major areas inspected health physics procedures, externel & inhernal reduction controls instrument rallbr, containination surveys leak testing & reduction work permits KAHLE.J B., BARH, K.P. Division of Engineering & Technical Progress 82/09/10 bpp 15567-222
- 8210150215 Forwards iC insp Rept 70-1201/82-14 on 820901-02 No noncompliance noted GIBSON A F Division of Engineering & Technical Programs 82/09/17 ALTO, R A Babtock & Wilcos Co 2pp 15721 316
- -8210150219 iE insp Rept /o·1201/82 i4 on B20901-02 No noncompliance noted Major areas inspected review of lab GC program & radiochemistry procedures & records & FVANS.C D. MONTGGMERY.D M. Division of Emergency Preparadness & Operational Support B2/09/15 7pp 15721 218
- a210210216 Forwards iE Safeguards Insp Rept 70-1201/82-1/ on 820929-30 No noncompliance noted G1380N.A.F. Division of Engineering & Technical Programs 82/10/15 ALTO.P.A. Babcock & Miccox Co. 2pp. 15765-301
- --8210210223 IE Safeguards Insp Rept 70 i20i/82-i/ on 820929-30 Nu noncompliance noted Major areas inspected general requirements for physical protection of low enriched SWI Details withheld (ref (DCFR72 21) GODDE R W. MCGUIRL D R Division of Engineering & Technical Programs 82/10/15 ip 15765-303

BOSKET 70-1257 EXXON NUCLEAR CO . INC . RICHLAND, WA

- 6210220025 Advises of issuance of Amend 7 to Licopse BNM-1227, authorizing sewer discharge of process liquids & changing shviron monitoring requirements PAGE:R G Urahium Fuel Licensing Branch 82/09/29 MALODY, C W Eilon Nuclear Co., Inc. (subs. of Exxon Gorp.) 2pp. 15786 301
- --8210220028 Safety evaluation supporting Amend 7 to License SNM-12:7 deleting License Conditions 19-17 & revising Section 3 reliquid effluent & monitoring controls BIDINGER.O H. CROW.W T Uranium Fuel Licensing Branch 82/09/29 be 19786-303
- 8210260389 Forwards IE Sateguards Insp Rept 70-1257/82-10 on 820920-24 No noncompliance noted NoRDERHOGAL R Division of Radiological Bafely & Safeguards Program 82/10/18 NILSON,R Exton Nuclear Co , Inc (subs of Exton Corp) 2pp 15803 322
- 8210260402 IE Safeguards insp Rept 70-1257/82-10 on 820920-24 No noncompliance mated Major areas inspected followup actions for Closing out notice of deviation records k rept audits & independent insp Details withheld (ref 10CFR2 790) WIEDERA V . NORDERHAVG. L. R. Division of Radiological Safety & Safeguards Program 82/10/18 ip 15803 326

DOCKET 70-1510 NUCLEAR ASSURANCE CORP . ATLANTA, GA

- 8207110023 FOIA request for correspondence between Nuclear Assurance Corp & MRC re 1982 irradiated fuel shipments between Chaik River, Ontario & Savannah River, NC RESNIKOFF, M. Cumcil on Economic Priorities 62/06/23 Division or Rules and Records ip 15849 109
- 8210050430 Responds to FDIA request for correspondence between Nuclear Assurance Corp & NRC re 1982 irradiated fuel shipments between Ontario & NC Forwards App A documents App U documents withheld (ref FDIA Exemption 3) FELTON, J M Division of Rules and Records 82/08/17 REGNIKOFF, M Council on Economic Priorities 3pp 15626 172
- --B204200405 Forwards decontrolled version of routs for transport of spent fuel route requested in SILII3 ltm Submittal meets IOCFR73 37 requirements for shipment & is approved SHERR.T S Material Transfer Safeguards Licensing Branch B2/04/02 DANESE.F L Nuclear Assurante Corp 14pp 15626 207
- --8210050444 Requests revision to route from Alexandria Bay, NY to Savannah River: NC: approved by NRC on 820402 Ruute change medessary in Byracuse: NY DANESE: F L Nuclear Assurance Corp 82/09/25 Division of Safeguards ip 15026-221
- --8210050451 Forwards "Spent Fuel Route Survey, Byracuse, NY Dypass." approving detour around const per 820525 request SHERR.T S Office of Nuclear Material Safety & Safeguards, Director 82/06/03 DANESC.F L Nuclear Assurance Cotp 1p 15626 222
- --8210050456 "Spant Fuel Route Survey, Syracuse, NY Bypass " EHERR, 7 S Office of Nuclear Material Safety & Safeguards, Director 82/06/30 2pp 15626 223
- 8210270423 Addi response to FOIA request for correspondence between Nuclear Assurance Corp & NRC re 1982 fuel shipments Forwards documents listed in App A App 8 documents partially withheld (ref FOIA Exemption 3) FELTON, J M Division of Rules and Records 82/09/23 RESNIKOFF, M Council on Economic Priorities 3pp 15849 110
- --8210270427 Confirms 820616 telcon re indefinite delay of six spent fusi shipments from AECL Chalk River facility to DQE Savannah River facility DANEEE.FL Nuclear Assurance Corp 62/06/16 GODY, A Region 1, Office of Director 1p 15849 [1]
- --0210270429 Confirms 820816 teleph re route approval for reactor fuel shipments between AECL Chalk River facility & DOE Savannah River facility Eight shipments planned w/pussible increase to 11
 DANKSEF L Nuclear Assurance Corp 82/08/17 HILLMAN.C
 Division of Safeguards 2pp 15849 114
- --8204200408 Forwards decontrolled version of route for transport of spent fuel route requested in 811113 ltr Submittal meets iOCFR73 37 requirements for shipment & is approved Info partially withheld (ref FOIA Exemption 3) SHERR: IS Material Transfer Safeguards Licensing Branch 82/04/13 DANESE: F. L. Nuclear Assurance Corp. 24pp. 15849 iib
- --B204220144 Advises that Billi3 request for apent fuel route meets
 10CFR73 37 requirements & is approved Data re initial
 arrangements w/law anforcement agencies & approved route
 enci Safeguards info withheld (ref FOIA Exemption 3)
 SHERR: 18 Material Transfer Safeguards Licensing Branch
 82/04/14 DANESE, F.L. Nuclear Assurance Corp 32pp 15849 130
- --8210270437 Notifies of plans for sames of spent fuel shipments from ACCL Chalk River facility to DDE Bavannah River facility Schedule encl DANESE, F. L. Nuclear Assurance Corp 82/06/03 QDDY, A. Region 1, Defice of Director 2pp 15849 171
- --8210270438 Forwards schedule for add1 spent fuel shipments
 DANESE.F L Auctear Assurance Corp 82/08/13 900Y, A Region J.
 Office of Director 2pp 15849.173

DUCKET 70-1621 DUQUESNE LIGHT CO , PITTSBURGH, PA

8210060020 Forwards Endorsements 59 \$ 51 to NELIA Policy NF-226 & MAELU Policy MF-87, respectively BARNETT, J E Conover & Associates, Inc. Insurance, 82/09/30 DINITZ, I Antitust & Economic analysis Branch (Utility F(nance) 3pp 15615 010

- DOCKET 70-1739 TRI-STATE MOTOR TRANSIT CO . JOPLIN, MQ
- 8210150805 Forwards route overview re planned thetk call frequency for shipment of strategic quantity of SNM W/o encl RUTEHKROCER.R. Tri-State Motor Transit Co (subs of Georgia Pacific Corp) 82/09/01 HILLMAN.C NRC - No Detailed Affiliation Given Ip 15716 334
- ~-B210150609 Submits review of 820901 application for matls safeguard amend HILLMAN, C.R. Division of Safeguards 82/09/16 MILLER, W.D. License Fee Management Branch 1p 15716 335
- DOCKET 70-2116 LAWRENCE GENERAL HOSP . LAWRENCE, MA
- 8210210437 Ack recespt of 820924 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 30-01878/82-01 & 70-2116/82-01 MRTIN, T T Division of Engineering & Technical Programs 82/10/14 NOYES, A H Lawrence General Hosp Lawrence, MA 1p 19762 296
- --8210210448 Responds to NRC 820826 ltr re violations noted in 1b Insp Repts 30-01878/82-01 k 70-2116/82-01 corrective actions personnel util be monitored following 1-131 therapy & elution & preparation area util be surveyed on daily basis NDVESA W Lawrence General Hosp Lawrence MA 82/09/24 Region 1. Office of Director 2pp 15762 257
- DOCKET 70-2650 ST JOHN'S MERCY MEDICAL CTR , ST LOUIS, MO
- 8210250190 Discusses IE insp of Licenses 24 00794-03 & SNM-1792 on 820927 No noncompliance noted Major areas inspected radiation safety, procedures & representative records, observations, independent measurements & Interviews HIEDEMAN, D. G. Division of Project & Resident Programs 82/10/13 FARRELL, J. T. St. Johns Mercy Medical Hosp. St. Louis, MD. 1p. 15787-342
- DOCKET 70-2748 SCIOTO MEMORIAL HOSP , PORTSHOUTH, OH
- E207070319 Ack receipt of B20621 ltr informing NRC of steps taken to correct violations noted in 1E insp of Licenses 34-15938-01, 34-15938-02 b BMM-1788 SRENIAMBKI.D J Division of Engineering & Technical Programs 82/06/30 CAES, K Scioto Memorial Hosp Portsmouth, OH ip 13734 170
- --8207070324 Responds to NRC 820512 ltr revialations noted in IE insp of Licenses 34-15938-01,34-15938-02 & SNH-1788 Corrective actions implemented procedure to survey dases & sites of injections outside of hasp EMMERTIR M Scioto Memorial Hosp Portsmouth.DH 82/06/21 SRENIAMSKI,D J Division of Engineering & Technical Programs 2pp. 13734-171
- DOCKET 70-2789 MISSOURI, UNIV OF, COLUMBIA, MO
- 8210080293 Discusses IE insp of Licenses 24-00513-35 & SNM-1799 on 820915 & forwards notice of violation MIEDEMAN.D Q Region 3, Diffice of Director 82/10/05 TOLAN, J Missouri, Univ of, Columbia 2pp 15638 311
- --B210080297 Notice of violation from insp on B20915 Noncompliance noted madiation monitor not functional in battery mode WIEDEMAND O Region 3, Office of Director B2/09/29 ip 15638-313
- DOCKET 70-2792 LOWER BUCKS HOSP . BRISTOL, PA
- 8210080306 IE Insp Findings & Licensee Ack dtd 820716 of Licenses \$NM-1800 & 37-06572-02 Insp findings, no noncompliance noted * Region 1. Office of Director 82/07/16 ip 15638 123
- DOCKET 70-2873 PUERTO RICO, UNIV OF, MAYAGUEZ, PR
- 8210010231 IE Imap Findings & Licensee Ack dtd 820701 of License SNM-1836 Imap findings no violations observed BROWN, R A Region 2, Office of Director 82/09/01 ip. 1586B 247

- DOCKET 70-2942 HARPER-GRACE HOSPS , DETROIT, MI
- B210050204 Ack receipt of B20922 ltr informing NRC of steps taken to correct violations noted in IE insp of Licenses 2I-04127-02. 21-04127-04:21-04127-07. 21-04127-08 \$ SMM-1881 SRENIAMSKI,D J Region 3. Office of Director 82/10/01 (ARALL., Larger-Grace Hosps Detroit.MI ip 15409 048
- --8210050213 Responds to NRC 82090B ltr re violations noted in 11 trs; of Licenses 21-04127-06 & 21-04127-08 Corrective actions timer accuracy determination made & included in spot checks CARALIS.0 P Harper-Orace Hosps Detroit,M1 82/09/26 SRENIAMSKI.D J Region 3. Office of Director ip 15609 oly
- DOCKET 70-2944 DUKE POWER CO . CHARLOTTE, NO
- 8210150617 Application to renew License SNM-1885, requesting litense extension to 831231
 TUCKER, H B Duke Power Co 82/09/07 DAVIS, J O (liftice of Nicle Material Safety & Safeguards, Director CUNNINGHAM, R L Pivzzier a Fuel Cycle & Material Safety | p 19716-099
- 6210290383 Issues Amend I to License SNM-1885, changing litense expiration date to 831231 or upon conversion of CPPR-84 to DL PAGE,R G Uranium Recovery Licensing Branch 82/10/1, The Main 48 Duke Power Co. Zpp. 15845-244
- --8210290392 Reviews 820907 application for Amend 1 to literase 'fed | requesting expiration date be extended to 831211 Extension should be granted KETZLACIEN . CROWN I T. Uranium Recovery Licensing Oranich 82/10/12 Uranium Recovery Licensing Oranich 1p 1588/b .'Ar
- DOCKET 70-2946 LOUISIANA POWER & LIGHT CO . NEW DRILAND IA
- 8210260003 Forwards Revision I to physical protoction plan for lics SNM-1886 Revision consists of changes made to plan three on agreements reached during 820624 tolcon Revision withheld (ref 100FR2 770) HULLER, 0 E [11] nois Power Co 62/06/28 BURNLTT, R I lityles af Safeguards 1p 15814 251
- 8207150432 Forwards updated pages to SNM application is persunnel changes
 MAURIN,L V Louislana Power & Light Co 82/07///
 Nuclear Material Safety & Safeguards, Director ip 14(9)) 1/2
- --8209150436 Updated pages to SNM license application * Louisiana Power & Light Co 82/07/23 10pp 14890 jm)
- --B209150438 Application to extend GNM license until Haterford a received MAURIN,L V Louisiona Power & Light Co 02/01/04 (Milice Nuclear Material Bafety & Bafeguards, Director 279) (481/14 1
- DOCKET 70-2949 ARIZONA PUBLIC BERVICE CO . PHOENIX. AZ
- B210260563 Forwards Palo Verde Nuclear Generating Stateon physics security plan Amend 2 in support of 810817 application for SNM licents Amend withheld (ref 10CFR2 770) ANDOMINIOG C Arizona Public Service Co D2/08/18 (1884 Nuclear Material Safety & Safeguards, Director 19 19814 14.6
- DUCKET 70-2955 EDLOW INTERNATIONAL CO . WASHINGTON, DL
- 8210210537 Forwards responses to 820520 request for addl by for application for GNM license SRAM, A Edlow International Co 82/06/21 SERINE to item. Fuel Licensing Branch 8pp 15782 220
- --8210210543 Application for license to store U herafluorida en SK max EDLON, J Ediow International Co 82/03/11 PAGER Q tap Fuel Licensing Branch 34pp 15782 228
- DOCKET 70-2957 FLORIDA POWER & LIGHT CO . MIAMI, FL
- B2102B0415 Forwards License BNM~1902,Amend 7 to Indemnity Apt mi B-74 & safety evaluation PAGE,R 0. Uranium Retovery Licensing Branch - B2/10/14 (外面 Florida Power & Light Co - 2pp - 15859 339

DUCKELED II.

- --8210283417 License SNM-1902 for FL Power & Light Co. authorizing receipt passession. Insp & storage of U-235, Pu-238, 239, 240 & 241, U-235, Cs-137, Pu-238, 239 & Am-241 PAGE, R. G. Uransum Recovery Licensing Branch 82/10/14 Jpp 15859 341
- --8210283421 Safety evaluation he review of 820319 license application t supplis for matis license Application acceptable SERINI.D L , CROW.W T Urahium Recovery Licensing Branch 82/10/14 | Jap | 19859 344
- DOCKET 70-2948 CLEVELAND ELECTRIC ILLUMINATING CO . CLEVELAND. OH
- G3(026009 Forwards application for SNI license for storage only of unirradiated reactor fuel 7- associated radioactive matipAVIDSON DR Cleveland Electric Illuminating Co 82/08/30 pAVIS.J C Office of Nuclear Material Safety & Bafeguards Director
- -- 8210269011 Application for StM license for storage only of unirradiated reactor fuel & associated radioactive mati
 DAVIDSON D R Cloveland Electric Illuminating Co 82/08/30 15814 253

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0030 GENERAL ATOMIC CO

8210270187 Supple 820623 request for NRC comment re acquisition by GA Technologies. Inc of licenses held by QA Co QA Technologies. Inc adopts QA QA program lopical Rept QA-A13010A, Amend & AGMCH, M H GA Technologies. Inc (General Atomic Co 82/08/30 Urfice of Nuclear Reactor Regulation, Director ip 15835-27) Office of Nuclear Reactor Regulation, Director

DOCKET 71-0481 MONROE X-RAY CO . INC.

- 5210010005 Forwards OA program for pending licenserin accordance 210010005 Forwards Un programmed State of 10C1R71 Urrequirements of 10C1R71 HEAD, T G Horrer X Ray Co , Inc 82/07/09 MACDONALD, C E Terespondation Branch ip 15577 221
- --02100:0024 GA program for pending license in accordance w/requirements of 10CFR71 • Montoe x-Ray Co , Inc 82/07/09 Spp 15577 222
- DOCKET 71-5908 MODEL BOT-6M TYPE B. BABCOCK & WILCOX CO
- 8210120331 Forwards Revision 9 to Certificate of Compilance 5908 for Model DDT-6M Type B MACDONALD.C E Transportation Branch 82/09/13 AUSTIN.M Babluck MACDONALD.C E Transportatio Mileox Co 3pp 15689 279
- -- 8210120384 Certificate of Compliance 5708, Revision 7, for Model DOT-6K Type 9 MACDONALD.C & Transportation Branch 82/09/13 4pp 15689 PB2
- DOCKET 71-5924 MODEL GE-100, GENERAL ELECTRIC CO
- 8210150348 Submits revised certification drawings for GE Model 100.per 820716 Itr Notes consistent w/Model 700 drawings Cask weight listed on drawings should be used to correct weight on Certificate of Compliance 5926 CUMNINGHAM, O E General Electric Co 82/09/07 MACDONALD, C E Transportation Branch (Opp. 15715 343
- DOCKET 71-5939 MODEL GE-1500, GENERAL ELECTRIC CO
- 82(0270057 Forwards revised certification drawings for QE Model 1500 per 820722 itr Changes listed Three aperture cards available CUNNINGHAM G E General Electric Co E Transportation Branch Spp 15836 113 82/09/08 MACDONALD, C E
- BOCKET 71-6115 MODEL RIG10-0032, ENERGY, DEPT OF
- 8210280343 Forwards Revision 1 to Certificate of Compliance 6115 for Hadel Riolo-0032 MACDONALD.C E Transportation Branch 82/09/21 Energy, Dept of 1p 15859 193 BAUER, R H

- --8210280345 Certificate of Compliance 6115, Revision 1, for Model R1010-0032 MACDONALD, C E Transportation Branch 82/09/21 3pp 15859 194
- DOCKET 71-6344 MODEL FSV-1, GENERAL ATOMIC CO
- 8210250122 Requests registration as user of Model FBV-1 MATHIB: O Hoston Edison Co B2/07/22 MACDONALD.C E Transportation Brench 12 15778 361
- 8210280322 Forwards Revision & to Certificate of Compliance 6346 for Model FSV-1 MACDONALD.C E Transportation Branch 92/10/01 MDI Technologies, Inc./General Atomic Co. 1p. 15859-046 MOWRY, W R GA
- --8210280326 Certificate of Compliance 6346, Revision 6, for Model FSV-1 MACDONALD, C.E. Transportation Branch 82/10/01 4pp 15859 04/
- 8210150653 Notification of registration as user of Model FSV-1 in response to 820922 request MACDONALD,C E Transportation Branch 82/10/13 MATHIS,C J Boston Edison Co. 1p 15715-308
- DUCKET 71-6947 MODEL FSV-9, GENERAL ATOMIC CO
- 8210120146 Forwards Revision 4 to Certificate of Compliance 6347 for Model FSV-3 Model FEV-3 MACDONALD.C E Transportation Branch B2/10/01 MOWRY.W R CA Technologies, Inc /Oeneral Atomic Co 2pp 15492 171
- --8210120150 Certificate of Compliance 4347 Revision 4 for Model FSV-3 MACDONALD C & Transportation Branch 82/10/01 4pp 15492 173
- DOCKET 71-4574 MODEL HN~200, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8210290439 Requests registration as user of Models GE-1600, CNS-1600, CNS-6-80-2, CNS-8-120, CNS-14-195H, CNS-21-300, HN-600, HN-200 & HN-100, Series B. 1, 2 & 3 HAURIN, L Louisiana Power & Light Co 82/09/07 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director 1p 15863 187
- DOCKET 71-6601 MODEL CNS 8-120, CHEM-NUCLEAR BYSTEMS, INC
- 8210280388 Responds to 82072/ ltr re cause of defects in cask lid bolts of CMS-B-120 shipping cask Preliminary investigations determined defects caused during bolt mfg PDPPE.L K Chem-Nuclear Systems, Inc. 82/08/25 MA Transportation Dranch 3pp 15859 259 82/08/25 MACDONALD, C F
- 8210290438 Requests registration as user of Models CE-1600, CNS-1600, CNS-6-80-2, CNS-8-120, CNS-14-195H, CNS-21-300, HN-600, HN-200 & FIN-100. Series 5.1.2 % 3
 MAURIN, L V Lewisiana Power & Light Cq 82/09/07 DAVIS, J Q Office of Nuclear Material Safety & Safeguards.Director 15863 187
- DOCKET 71-6639 MODEL MH-1A, ARMY, DEPT OF
- 8210270074 Forwards "SAR for Packaging of TRIGA & MTR Irradiated Fuel Assemblies in MK-IA Spent Fuel Shipping PRICHARD.R P Energy. Dept of 82/07 Transportation Branch 4pp 15848 109 82/09/07 MACDONALD, C E
- --8210270079 Certificate of Compliance 4639, for Model MH-1A ROEDER, J. R. Energy, Dept. of 82/06/18 Zpp. 15848 :
- --8210270085 "SAR for Packing of TRIOA & MTR Irradiated Fuel Assemblies in MH-1A Spent Fuel Bhipping Cask " Fourteen oversize drawings encl Aperture cards available in PDR # Ridihalgh, Eggers & Associates 82/05/31 354pp 15848 115
- DOCKET 71-6677 MODEL LP-12, ENERGY, DEPT OF
- 8210280334 Forwards Revision 3 to Certificate of Compliance 6677 for Model LP-12 MACDONALD,C E Transportation Branch, 82/09/17 BTETSON.N Energy, Dept of, 19 15859 129

- --8210280337 Certificate of Compliance 6677, Revision 3, for Model LP-12 MACDOUALD, C & Transportation Branch 82/09/17 3pp 15859 138
- DOCKET 71~6678 MODEL LP-50, ENERGY, DEPT OF
- 8210280338 Forwards Revision 3 to Certificate of Compliance 6678 for Model LP-50 MACDONALD.C E Transportation Branch 82/09/17 STETSON.N Energy Dept of 1p 15859 133
- --B210280342 Certificate of Compliance 6678, Revision 3, for Model LP-50 MACDQNALD, C E Transportation Branch 82/09/17 3pp 19859 134
- DOCKET 71-4698 MODEL NFS-4, MUCLEAR FUEL SERVICES, INC
- 8210290155 Forwards pages inadvertently omitted from 820720 responses to NRC ltr W/o enci JOHNSON, C.R. Nuclear Assurance Corp. 82/09/02 MACDONALD, C.E. Transportation Branch 1p 15876-223
- DOCKET 71-6703 MODEL RG-1. GENERAL ATOMIC CO
- 8210120180 Forwards Revision 3 to Certificate of Compliance 6703 for Model RG-1 MACBUNALD, C Transportation Brench 82/10/01 MOWRY, W E GA Technologies, Inc / General Abomic Co 2pp 19692 211
- --B210120192 Certificate of Compliance 6703 Revision 3 for Model AU-1 MACDONALD C E Transportation Branch 82/10/01 3pp 15692 213
- DOCKET 71-6745 MODEL FSV-2, GENERAL ATOMIC CO
- 8210280329 Forwards Revision 3 to Certificate of Compliance 6745 for Model FBV-2 MACDONALD, C E Transportation Branch 82/10/01 MOWRY, W R GA Technologies, Inc /General Atomic Co ip 15859 125
- --B2102B0333 Certificate of Compliance A745.Revision 3.for Model FSV-2
 HACDDNALD.C E Transportation Branch B2/10/01 3pp 15899 126
- DOCKET 71-9001 MODEL 1F-300, GENERAL ELECTRIC CO
- B210120138 Forwards Revision 14 to Certificate of Compliance 9001 for Model IF-300 MACDONALD, C E Transportation Branch 82/09/30 BAWSON, D M General Electric Co 2pp 15692 187
- --8210120166 Certificate of Compilance 9001, Revision 14, for Model IF-300 MACDDNALD, C E Transportation Branch 82/09/30 Spp 15692 189
- DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC
- 821028044B Requests revision to maint manual covering NL1-1/2 spent fuel shipping casks to further define maint schedule JOHNSON, C.R. Nuclear Assurance Corp. 82/09/09 MACDONALD, C.E. tation Branch ip 15859 121
 - wards Revision 8 to Certificate of Compliance 9010 for ation Branch 82/09/24 JOHNSON, C R
 - 9010 Revision 8, for Model NLJ-1/2 nch R2/09/24 6pp 15690 184
- 82:10150428 Advises that licensing action for amend of Certificate of Compliance 90:10 terminated on 820826 No addl fees required MILLER, W O License Fee Management Branch 82/10/07. JOHNSON, C R Nuclear Assurance Corp Ip 15715 388
- DOCKET 71-9034 MODEL TRIGA-1, GENERAL ATOMIC CD
- 8210120169 Forwards Revision 4 to Certificate of Compliance 9034 for Model TRICA-1 MACDONALD.C E Transportation Branch 82/10/01 MOHRY, H E GA Technologies, Inc /General Atomic Co 2pp 15692 197

- --E210120174 Certificate of Compliance 9034, Revision 4, for Hodel TRIC4--MACDONALD.C E Transportation Dranch 82/10/01 3pp 15692 19;
- DOCKET 71-9037 MODEL TRIGA-2, GENERAL ATOMIC CO
- 8210120339 Forwards Revision 4 to Certificate of Compliance 903) for Model TRIOA-2 MACQUALD.C E Transportation Granch 82/10/01 MOWRY.W R LA Technologies, Inc./General Atomic Co. 2pp. 15690 177
- ~-8210120340 Certificate of Compilance 9037.Revision 4.for Hodel IRICA MACDONALD.C E Transportation Branch 82/10/01 3pp 15640 FFY
- DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO
- 821029043B Requests registration as user of Models GE-1600, CNS-16400, CNS-6-180-2, CNS-6-120, CNS-14-1994, CNS-21-300, IN-400, IN-200 & NA-600, Series 5, 1,2 & 3 MAURIN, L V Louisiana Power & Light Ca B2/09/07 DAVIS, J O Dirice of Nuclear Material Safety & Safeguards, Director Ip 15863 187
- 8210280382 Requests registration as user of Model GE-1600 BORST,F J Public Service Co of Colorado 82/09/08 MACDONALD,C & Transportation Branch 2pp 15899 257
- B210150691 Notification of registration as user of Mode) QC-1600 in response to B20908 request MACODNALD,C E Transportation Branch B2/10/13 BORST,! J Pub Service (a of Colorado ip 15715 319
- DOCKET 71-9057 MODEL FPD-100, GENERAL ATOMIC CO
- 9210280311 Forwards Revision 3 to Certificate of Compliance 905/ fe, Model FPD-100 MACDUNALD,C E Transportation Branch 82/10/01 MOHRY,W R GA Technologies, Inc /Oeneral Atomic Co ip 15839 042
- --8210280316 Certificate of Compliance 9087. Revision 3, for Hidel Fit MACDONALD.C E Transportation Branch 82/10/01 3ep 1387.
- BOCKET 71-9079 MODEL HN-100, SERIES 2 & ZA, HITTMAN NUCLEAR
- 6210260023 Requests registration as user of Model HN-100 Beriga .' a SCOTTID J Commonwealth Edison Co 92/09/03 MACDMALD.(' f Transportation Branch | Eq. 1588-360
- 821029043B Requests registration as user of Models GE-1600.CNR Late CNS-6-80-2.CNB-6-120.CNS-14-193H.CNS-21-300.HN-600.HR-200 & HN-100.Series S. 1.2 & 3 MADRIN.L V Louisiana Power & Light Co 82/09/07 DAVIB. J C Office of Nuclear Material Safety & Safeguards.Director to 15863 187
- DOCKET 71-9080 MODEL 9080, HITTMAN NUCLEAR & DEVELOPMENT COMP
- 8210270438 Requests registration as user of Models GE-1600.CM3-14. CM5-6-80-2.CM5-8-120.CM5-14-175H.CM3-21-300.HM-300.HM-800 & HM-100.Series S. 1.2 & 3 MAURIN.L V Louisiana Power & Light Co 82/09/07 DAVIG. J O Diffice of Nuclear Material Safety & Bafeguards Director 1p 15963 187
- DOCKET 71-9081 MODEL CN8-1400, CHEM-NUCLEAR BYBTEMS, INC
- 8210270438 Requests registration as user of Models GE-1400, CNS-f. CNS-6-80-2. CNS-8-1400, CNS-14-195H. CNS-21-300, HN-400, HH-200 & HN-100, Beries S.1, 2 & 3 HN-100, Beries S.1, 2 & 3 HAURIN.L V Louisiana Power & Light Co 82/09/07 DAVIB.J Q Office of Nuclear Haterial Safety & Safeguards, Director 1p 13863 187
- DOCKET 71-9086 MODEL, HN-100, SERIES 1, HITTMAN NUCLEAR & DAV C
- B21029049B Requests registration as user of Models GE-1600, CNS-1 CNS-6-80-2; CNS-B-120, CNS-14-195H, CNS-21-300, HN-600, HN-200 & HN-100, Beries B, 1, 2 & 3 MAURIN.L V. Louisiana Power & Light Co B2/09/07 BAVIS, pr. 10ffice of Nuclear Material Bafety & Bafeguards, Director lp. 15863 187

- SOCKET /1-9089 MODEL HH-1008, HITTHAN NUCLEAR & DEVELOP CORP
- 8/10/20043B Requests registration as user of Models GE-1600 CNS-160b. CNS-6-80-2. CNS-8-120. CNS-14-175M. CNS-21-300. MN-600, MN-200 & MI-100, Serves S. 1. 2 /t J. MAWRIN. L. V. Louistana Power / Light Co. 82/09/07 DAVIS. J. G. Misco of Theolean Material Bafely & Safeguards. Director. Jp. 1986 187
- COLKET /1-9091 MODEL JOA / BOB. GULF NUCLEAR CO
- \$210,790430 Requests registration as user of Models QF-1600, CNS-1600, CNS-1600, CNS-6, CNS-6, CNS-6, CNS-6, CNS-6, CNS-6, CNS-1600, CNS-1600, CNS-1600, CNS-1600, CNS-1600, CNS-6, CNS-
- BOCKET 71 9094 MODEL CN3 11 195-H. CHEM-NIK LEAR SYSTEMS. INC
- 8210/30037 Pequests registration as user of Model CHS 14-195-H HILLER.R I Sacramento Municipal Utility District 80/12/24 MACDOMAID.C E. Transportation Branch 1p 15808 352
- DONE TT1-9096 MIDEL INS 21 300. CHEM NUCLEAR SYSTEMS. INC
- 8710240478 Requests registration as user of Models GE-1600, CNS-1600, CNS-1600, CNS-6-80-2, CNS-8-120, CNS-14-17914, CNS-21-300, FNS-600, FNS-200 & FNS-100, Series St. U. 2 v. 3 Endlich V. Louisiana Hower & Light Le. 82/04/07 DAVIS, J. 6 Diffice of Necteal Material Safety? Saroquards Director Lp. 15061-107
- CHEFET 74 90 ME MIDEL UIL 20NO -2 & 2A, UNION CARBIDE CORP
- --GRIO-BOSSY CELLIFICATE OF COMPILANCE YOYU, Revision 3, for Models USC-ROMC-2 & UCC-10MC-2A MACDOMAIN.C F Transportation Branch 82/09/16 3pp 15099 201
- BROKET 71 9111 MODEL CASS 80-2. CHEM NUCLEAR SYSTEMS, INC
- 8210290438 Requests registration as uses of Models OF-1600, CNS-1600, CNS-6 80-2 CNS-08-120, CNS-14-1991, CNS-21-200, IN-600, IN-200 & IN-600, Series St. 1, 7, 7, 1 HAURIN, L. V. Louistana Power & Light Co. 82/09/07 DAVIS, J. G. Office of Nuclear Material Safety & Gafeguards, Director. 1p. 15843-182.

- DOCKET 71-9150 MODEL PAT-2, ENERGY, DEPT OF
- 8210070409 Requests relief from or nod to operational controls on air carriers New evidence provides reasonable technical & economic basis for relief PAT-2 package tafe by all definitions in any onboard location CAUDLE: R E Energy, Dept of 82/08/18 MACDUNALD.C & Division of Fuel Cycle & Material Safety Rpp 15637-223
- --8210070410 "Operational Conditions for Pu Air Transportable Paclaves PAT-1 & PAT-2 " « Ediow International Co 82/04/22 33pp 15637 233
- --8210070413 "Analysis of Crush Environ for Light Weight Fransportable Accident Resistant Containers" MCCLURE, J D Sandia Laboratories SAND80-0763 81/12/31 29µp 15637 272
- DOCKET 71-9151 HODEL HN-100, SERIES 3, HITTMAN NUCLEAR & DEV (GRP
- 8210290438 Requests registration as user of Models GE-1600 CMS-1800-CMS-6-80-2. CRS-8-120.CMS-14-193H. CRS-21-300. HN-600. HR-200 % HN-100. Bernes S. 7.2 & 7 MAURIN, L. V. Louisiana Power & Light Co. 82/09/07 DAVIS. J. G. Office of Nuclear Material Safety & Safeguards Director. Ip 13863-187
- 8210150687 Hotification of registration as user of Model HN-100 Series 3 in response to 820914 request MACDONALD.C E Transportation Branch 82/10/13 MARSHALL.J R Artansas Power & Light Co 1p 15715 318
- DOCKET 71-9167 MODEL TYPE B, AMERSHAM CORP
- 8210080225 Application for certificate of compliance to use Type B keg design containers for storage & shipping of up to 25 Ci Amersham mfg Am-241 & beryllium approved special form sources BAOBY: A Amersham Corp 82/08/25 MACDONALD. C NRC No Detailed Affiliation Civen 2pp 15663 141
- --8210080232 Forwards payment to replace incorrect funds accidentally included in 820225 application for certificate of compliance to use Tupe 8 keg design containers for storage & shipping of up to 25 Ci Amersham mfg Am-241 & beryllium BAOBYL. A Amersham Corp 82/08/26 WEISS.D License fee Management Branch 2pp 15663 142
- --8210080237 "SAR Keg Design Containers Type B Package " • Amersham Corp 82/08/25 75pp 15663 145
- DOCKET 71-9964 MODEL LP-12-1, ENERGY, LEPT OF
- 8210120349 Forwards Revision 2 to Certificate of Compliance 9964 for Model LP-12-1 MACDONALD.C E Transportation Branch 82/09/24 STETSON, N Energy, Dept of 1p 15690 172
- --8210120352 Certificate of Compliance 9964, Revision 2, for Model LP-12-1 MACDONALD, C & Transportation Branch 82/09/24 4pp 15690 173

COMMISSION MEETING RECORDS 100FR

- 6210050435 Unofficial transcript of 820910 public meeting w/ACRS in COUDOMAD Undersicial transcript of 820410 publi Reshington, DC Pp 1-52 4 Commissioners 82/09/10 55pp 15822 164
- 8210050070 Transcript of 820918 affirmation/discussion session in Washington DC Pp i-3 * Commissioners 82/09/i8 7pp 15636 257
- 8210080329 Staff requirements memo informing that Commission was briefed on ORNL rept, "Potential Procursors to Savera Core Quage" on 820721 Qamage" on 820721 CHILK.S J Office of the Secretary of the Commission M820721A 82/07/22 DiRCKS, W J Office of the Executive Director for Operations ip 15663 292
- 8210120581 Transcript of 820918 public meeting in Washington.DC re FEMA briefing on offsite appraisals program Pp 1-63 Visugraphs encl. Commissioners 82/09/18 87pp 15689 232
- B210120599 Staff requirements memo re FEMA B20917 briefing on offsite appraisais program for commercial nuclear power plants FEMA should provide NRC w/info re availability of emergency plans South to be added to the Bernetary of the Commission, H8209178 82/09/24 BICKHIT, L Office of the Executive Director for Operations Dirks, W J Office of the Centeral Country by
- 8210228507 Unofficial transcript of 821007 briefing by Regulatory Reform Test Force re legislative proposals in Washington, DC
- Commissioners 82/10/07 75pp 15786 129
- 8210280402 Addi response to FOIA request for SECY-82-232 & SECY-82-202 Documents iisted in App A available in PDR FELTON.J K Division of Rules and Records 82/09/30 BUCKLEG.R Affiliation Unknown 2pp 15899 10i
- ~-8210190198 Staff requirements memo re 820701 affirmation session concerning SECY 82-202 on amend to LOCFR140 9, "Financial Protection Requirements & Indemnity Agraements "Ubjections to publication of apps as reg guides due by 820719 CHILK.8 J Office of the Secretary of the Commission M820706 B2/0706 DRCKB.W J Office of the Executive Director for Operations 2pp 15837 106 MB20701
- 8210270373 Transcript of 820927 public meeting on 8ECY-82-352 rp GA in Washington, DC Pp 1-85 Marked-up 8ECY-82-352 encl PALLADINO, N : OILINGKY, V : AHEARNE, J : Commissioners 82/09/29 146pp 15865 268
- 8210290400 Unofficial transcript of 820930 public affirmation/ discussion & vote in Washington.DC Pp 1-3 4 Commissioners 82/09/30 App 15866 329

ADVISORY COMMITTEE ON REACTOR BAFEGUARDS ACRS

- 8207180066 Forwards edited version of draft on pressurized thermal shock Wisubstantive changes proposed
 KOUTB-H Brockhaven National Laboratory KOUTB-H ACRS - Advisory
 Committee on Reactor Safeguards 82/08/10 IONE,E ACRS - Advisory
 Committee on Reactor Bafeguards 82/08/10 IONE,E ACRS - Advisoru
- 8207180080 Comments on util group position per 820630 request ATW8 issue remains unresolved because of difference between NRC estimate of ATWS risk & risk preferred by industry DAVIB.PR Affiliation Unknown DAVIB.PR ACR8 Advisory Committee on Reactor Safeguards. 82/08/24. RDEHNERT.P ACR8 Advisory Committee on Reactor Bafeguards 3pp. 13852 043.

- 8208290011 Comments on ACRS Subcommittee on Human Factors 82090/ meeting Planned research program lacks in basic generic research SALVENDY, O ACRS - Advisory Committee on Reactor Safeguards SALVENDY, O Purdue Univ 82/09/09 FISCHER, D ACRS - Advisory Committee on Reactor Safeguards 4pp 13852 034
- 8208290012 Comments on ACRB Bubcommittee on Human Factors Safety integrated program plan Approx ievels of effort to areas & at major units within areas need to be clearly shown BUCK.JR Iowa, Univ of BUCK.JR ACRS ~ Advisory Committee on Reactor Safeguards 82/09/13 WARD, D ACRS ~ Advisory Committee on Reactor Safeguards 82/09/13 WARD, D
- 8208290017 Summarizes 269th ACRS meeting on 820909-11 in Washington, DC THE PROOF SUMMARISE 2016 ACRS meeting on B2030711 in Washing for transport, testing requirements for diesel generators & integrated human factors program plan
 SHEHMON, P ACRE Advisory Committee on Reactor Safeguards
 SL-0278 62/09/21 PALLADINO, N J Commissioners 3pp 15649 236
- 8208290019 Forwards comments on util group response to NRC proposal for reducing ATMS sequences Meeting planned for 821001 MUELLER.C J Argonne National Laboratory MUELLER.C J ACRS ~ Advisory Committee on Reactor Safeguards 82/09/14 DOEHNERT.P ACRS ~ Advisory Committee on Reactor Safeguards 8pp 15852 001
- 8208290026 Outlines two approaches for evaluating seasmic margins AUGAYUUGA DULINES KOO APPROACES FOR EVALUACING SEISMIC MARGI available to accompiish safe shutdown foliowing earthquake of greater severity & lower liklihood than SSE Assessment of margins in terms of risk singularity recommended ZUDANS, Z Franklin Institute/Franklin Research Center ZUDA ACRS - Advisory Committee on Reactor Safeguards 6pp 158: ACRS - Advisory Committee on Reactor Safeguards 6pp 158: ZUDANS, Z 15851 396
- 8210010464 Transcript of ACRS Subcommittee on Reactor Operations 820929 meeting in Washington, DC Pp 1-268 Supporting documentation
 - ACRS Advisory Committee on Reactor Safeguards 82/09/29 370pp 15571 008
- 8210040080 Transcript of ACRS Metal Components Working Group 820930 meeting in Meshington, DC Pp 1-268 Eupporting documentation ACRB - Advisory Committee on Reactor Bafeguards 344pp 15583 195
- 8210050435 Unofficial transcript of 820910 public meeting w/ACRS in Washington, DC Pp 1-52 * Commissioners 82/09/10 55pp 15622 164
- B210120149 Transcript of 270th ACRS general meeting on B21007 in Washington DC Pp 1-267 Visugraphs encl * ACRB Advisory Committee on Reactor Bafeguards B2/10/07 416pp 1955-083
- 8210150157 Transcript of ACRS 270th general meeting on 821008 in Washington, DC Pp 268-399 Bupplemental info encl # ACRS Advisory Committee on Reactor Safeguards 82/10/08 194pp 13697.087
- 8210210324 Ack receipt of 820914 views on BECY-82-001A, "Proposed Commission Policy Statement on Severe Accidents & Related Views on Nuclear Regulation." DIRCKS I J Office of the Executive Director for Operations 82/09/27 BHEHMON, P AGRB - Advisory Committee on Reactor Bafeguards App 15774:315.
- 8210260119 Transcript of ACRS Subcommittee on ATHS 821022 meeting in Heshington DC Pp 1-332 Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards. 82/10/22, 404pp. 15800:001

- 82(0270210 Transcript of ACRS Subcommittee on Extreme External Phenomena 82(022 meeting in Santa Monica CA Pp 352-703

 ACRS ~ Advisory Committee on Reactor Safeguards 82/10/22
 350pp 15826 034
- 8210270217 Transcript of ACRS Subcommittee on Extreme External Phenomena 821021 meeting in Santa Monsca.CA Pp 1-35! * ACRS ~ Advisory Committee on Reactor Safeguards 82/10/21 354pp 15025 040
- 8210270371 Summary of ACRS Subcommittee on Reactor Radiological Effects 820720 meeting in Washington.DC re methods for reducing radiation erposure.exposure histories at PMRS & Status of RUREC-0761. "Radiation Protection Plans for Licenses."

 ACRS Advisory Committee on Reactor Sefeguards 82/09/17 ACRS Advisory Committee on Reactor Sefeguards 17pp 15835 006
- 6210270375 Summary of ACRS Subcommittee on Reactor Radiological Effects 2 Site Evaluation 820623 joint meeting in Washington, OC restatus of revision to 100FR20. "Stds for Protection Against Radiation"

 ACRS Advisory Committee on Reactor Safeguards 82/08/23 ACRS Advisory Committee on Reactor Safeguards 19pp 15835 237
- 8210270378 Summary of ACRS Subcommittee on Safety Research Program 820707 meeting in Hashington, DC Te research program & budget for FYB4-85
- ACRS Advisory Committee on Reactor Safeguards ACRS - Advisory Committee on Reactor Safeguards 19pp 15835 256
- 8210270385 Summary of ACRS Subcommittees on Reactor Radiological Effects & Site Evaluation 820609 joint meeting in Washington DC re proposed FY84-85 research programs & budget
- budget * ACRS Advisory Committee on Reactor Safeguards 82/08/09 ACRS Advisory Committee on Reactor Safeguards 14pp 13833-343
- 8210270404 Summary of ACRS Subcommittee on Waste Mgt 820608 meeting in Washington, DC to review "DDZ Public Draft of Natl Plan in Mainington, DC to review "DUE rublic Draft of Rati Plan for Siting High Level Haste Repositories & Environ Assessment Review " 4 ACRS — Advisory Committee on Reactor Safeguards 82/08/09 ACRS — Advisory Committee on Reactor Safeguards 17pp 15833 251
- 8210270420 Summary of ACRS Bubcommittee on Bafety Research Program 820602 meeting in Washington DC re research program & budget for FY84-85
 - for Figgraph 4 AGES Advisory Committee on Reactor Bafeguards 82/07/23 AGRS Advisory Committee on Reactor Safeguards 20pp 15833-312
- 8210270424 Summary of ACRS Subcommittee on Human Factors 820706 meeting in Mashington,DC re FY84-85 research program & budget & comments on long ronge research plan a ACRS Advisory Committee on Reactor Safeguards 82/07/13 ACRS Advisory Committee on Reactor Safeguards 37pp 15834 263
- 8210280044 Summary of ACRS Ad Hoc Metal Components Subgroup 820511-12 meetings in Mashington DC repressurised thermal shock
- problem # AGRS Advisory Committee on Reactor Safeguards 82/07/27 AGRS Advisory Committee on Reactor Safeguards 19pp 15862 336
- B210280059 Transcript of ACRS Subcommittee on SEP 821026 meeting in Washington, DC Pp 1-292 Supporting documentation encl ACRS Advisory Committee on Reactor Safeguards B2/10/26 453pp 15841 043
- 8210290011 Transcript of AGRS Subcommittee on SEP 821027 hearing in Hashington, DC Pg 293-509 Supporting documentation enci * AGRS Advisory Committee on Reactor Safeguards 82/10/27 335mg 15855 35A

mic Safety Margins Research Program Review ter presentation provided good involved w/correlating marthquake assignments
HAXWELL, J. C ACRS - Advisory
/02/14 DERENT, T D ACRS ards 7pp 15877 206

> | establishment of joint proposed mods Bonetinne

> MARTINEZ.FP Spain ip

- --8206060015 Requests joint program to resolve approval of mods to Mestinghouse Hodel D-3 steam generators & followup evaluation during operating conditions MARTINEZ,F P Spain 82/05/27 PALLADING.N I MARTINEZ: P Spain 82/05/27 PALLADINO.N J Commissioners 2pp 15624 030
- 8206200071 Responds to 820627 inquiry re discussions between NRC & LOS on regularments for site characterization of patential high level waste repositories No negotiations to relax requirements have taken place LADINO,N J Commissioners 82/07/29 MATHESON,S M Utah, Stat 4pp 19624 052 PALLADINO, N J
- --8206270016 Requests verification as to occurrence of informal negotiations w/DOE to relax wasts repository requirements of MATHESON, S. M. Utah, State of 82/09/29 PALLADING, N. J. Commissioners 2pp 15624 056
- 8205200097 Responds to 620502 itr proposing extension of current preliminary design approvals for nuclear power plant designs until reactivation under new guidelines Standardization of designs is Vital component to viable program PALLADIND,N J Commissioners 82/07/29 WALSKE, C Atomic Industrial Forum 2pp 15512 302
- --8204060013 Requests that NRC develop & implement new guidelines Fe preliminary design approval extensions & take action to extend administrative approvals that have expired until activation of new guidelines
 WALSKE,C Atomic Industrial Forum 82/06/02 PALLADINI,N J Commissioners 2pp 15512 303
- --B209270379 Discusses extension of applicability period for previous issued preliminary design approvais Resources already expended should be preserved & standardization program used effectively TMI-related safety issues must be addressed QIBBS.D C Atomic Industrial Forum Bi/05/2B DIRCKS,W J Office of the Executive Director for Operations 2pp 155
- 8206270093 Forwards Science Mgt Corp/DRNL interim rept, "Fresibilit Licensing Nuclear Util Hanagers & Officers " Licensing requirements should not be established for managers & sanior officers W/o encl PALLADINO.N J Commissioners FIN B-0764-1 82x100/4 O'NEILL, TP House of Rep . Speaker of the House 6pp 15076:
- --8210270003 Forwards summary of selected US govt agency licensing programs & Science Mgt Corp/ORNL. "Feasibility of Licensing Nuclear Util Managers & Officers " Licensing requirements whould not be established for managers & senior officers PALLADING N J Commissioners FIN 8-0764-1 82/10/04 Senate President of the Senate
- --8210290006 "Feasibility of Licensing Nuclear Util Managers & Off PRESENCE, J. J. Division of Human Factors Safety SELBYID , BARTINE D E 4-1 _81/12/17_
- 8206270059 Accepts invitation to serve as chairman of 1980 combin federal campaign, w/PO Norry as vice-chairman PALLADINO, N J Commissioners 82/09/16 LEWIB, D Transportation, Dept of ip 15722, 251
- 82:01:50659 Requests apportunity for members of public to comment following full-scale joint exercises involving licenses. state & iocal agencies AHEARNE.J F Commissioners 82/09/14 OIUFF Emergency Management Agency 2pp 15716 348 CIUFFRIDA.LO Feder.
- 8210290423 Public version of weekly info rept for us ending 8205 REHM.T.A Office of the Executive Director for Operations 82/09/30 49pp, 15863 190
- CONTRACT NRC CONTRACTS AND MODIFICATIONS
- 82:0040001 Notification of contract execution "LA Offshore Radiological License Survey," swarded to LA Dept of Natural MCRULTY: A Purchasing Section FIN 8-8703 NRC-05-82-82/07/23 BLAMA.J. YACZKO.C Program Support Branch 15577-246 FIN 8-8703 NRC-05-82-852
- --B210040002 Contract "LA Offshore Radiological Licente Burvey to LA Dapt of Natural Resources.

 SHONEAUX.F.P. Louisiana, State of SMITH.P A Administration of Contracts Branch. IN B-6703 NRC-05-82-252 B2/09/23

- 82)0040003 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Phoenix.AZ Public Library LITTLE, H Purchasing Section NRC-10-82-697 82/09/22 FELTON, J N . SQUDER.J Division of Rules and Records 1p 15577 252
- --8210040004 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)." awarded to Phoenis, AZ Public Library COLLEY, J A Phoenis AZ SMITH.P A Administrative Contracts Branch NRC-10-82-677 82/09/22 7pp 18577 293
- 8210940410 Notification of contract execution. Mod 5 to "Technical Assistance in Support of NRC Reactor Litenaing Actions Program 2 " Contractor Science Applications, Inc FLYNX, M Technical Assistance Contracts Branch NRC-03-82-094 82/09/15 EISENNUT. D 0 . SILVER, H Division of Licensing ip 15597 202
- ~-B210040412 Mod 5, incorporating award fee parned for period Mar-May 1982, to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2"
 4 Science Applications, Inc. HACAN, T.F. Technical Assistance Contracts Branch NRC-03-82-096 82/09/15 2pp 15597 203
- 8210050301 Notlfication of contract execution.Mod 3 to "Unsaturated Flow & Transport Through Fractured Rock re High Level Waste Repositories " Contractor Univ of AZ JACOBB: A Research Contracts Branch FIN B-7291 NRC-04-81-224 82/09/20 BATSON: W. NICHOLSON: J Office of Nuclear Regulatory Research, Director ip 15626 234
- --8210050508 Mod 3.changing reporting requirements, to "Unsaturated Flow & Transport Through Fractured Rock ro High Level Wasts Reportiories"

 CARR.S E Arizona. Univ of QUSTAVE.R P Research Contracts Branch FIN B-7291 NRC-04-81-224 82/09/20 4pp 15828 235
- ERICOSOSIS Notification of contract execution.Mod & to "Hemphis Area Regional Seismic Network " Contractor Memphis State Univ JACOBR. A Research Contracts Branch FIN 11-6275 NRC-04-78-200 82/09/13 FOREMAND.W MURPHY. A Défice of Nuclear Regulatory Retearch. Director ip 15626 354
- --8210050521 Ltr contract.NRC-04-78-200, "Momphis Area Regional Beismic Natuork." Hod d. increasing amount of funds Receipt ack by TO Carperter on 820830 GUSTAVE.R.P. Research Contracts Branch FIN B-6276 IRC-04-78-200 82/08/19 TRENK.N S Memphis State Univ. 1p 15626 255
- 8210050525 Notification of contract execution.Mod 3 to "NOS Calibr Hassurement Assurance Program to Support NRC Fhird Pilot Study Test of Personnel Desimetry Processors " Contractor NDS GUSTAVE.R P Research Contracts Branch. FIN B-7103 NRC-01-80-029 82/09/14 FOREHAND.W, DENNIS,N Office of Nuclear Regulatory Research, Director in 15626 336
- --8210050830 Mod 3.extending period of performance to 630731 at no addl cett, to "NES Califor Measurement Assurance Program to Support NRC Third Pilot Study Test of Personnel Doslmetry Processors"
 - Processors "
 ERREVELD B Commerce, Dept of, National Bureau of Standards
 OUSTAYER P Research Contracts Branch. FIN B-7103
 ARC-01-80-023 82/09/14 fp 15626 337
- 8210050420 Notification of contract execution "Const & Calibr of Br-90 Irradiator for Multiple Dosimeter Irradiations," awarded to Univ of MI MAGRY. H Research Contracts Branch. FIN B-8285 NRC-04-82-024 82709720 FOREHAND. W. DENNIB. N Office of Nuclear Regulatory Research. Director 19 15636 243
- --8210050424 Contract: "Const & Callbr of Br-90 Irradiator for Multiple Dosineter Irradiations," awarded to Univ of MI HATHERS C W Michigan, Univ of MORTON, K V Research Contracts Branch FIN 8-8285 NRC-04-82-024 82/09/20, 9pp 18636:224
- 8210070017 Notification of contract execution. "Reviewing Hydrologic Investigations of Baselt Wast» Isolation Project (BMJP), Project B. " awarded to Golder Associates Inc HILEG.E B Tschnical Assistance Contracts Branch PIN 8-7373-2 NRC-02-82-045. 82/07/20. DAVIS.J., JOHNSON, R Office of Nuclear Material Bafety & Bafeguards, Director. 1p 15646: 304
- --8210070021 Contract: "Reviewing Hydrologic Investigations of Desalt Waste Isolation Project (BHIP), Project B. " awarded to Colder Associates. Inc. WEB1.L J Colder Associates. MATTIA.M. J Technical Assistance Contracts Branch FIN B-7373-2 NRC-02-82-045 82/07/20, 36pp

- 8210070193 Notification of contract execution.Mod 3 to "Fuel Cycle Analysis - Spain " Contractor Nuclear Assurance Corp MCNVLTY.A Administrative Contracts Brench FIN B-7374-2 NRC-02-62-048 8270973 BROWN, R S , THOMAS, B H Program Support Branch 1p 15445 004
- --8210070186 Mod 3.deabligating funds.to "Fuel Cycle Analysis ~ Spasn "
 SMITH.R L Nuclear Assurance Corp RESELLO.J E Division of
 Gantracts FIN 8-7374-2 NRC-02-82-048 82/08/13 ip
- 82:0070456 Notification of contract execution "ADP Planning Assistance" awarded to Dept of Air Force
 MILES.E B Technical Assistance Contracts Branch FIN B-8810
 NRC-33-62-32: 82:09/17 FROST.A Office of Resource Management.
 Director 19 13644 325
- --8210070459 Contract "ADP Planning Assistance," awarded to Dept of Air Force RUPP.W A Air Force, Dept of MATFIA.M J Division of Contracts FIN D-8810 NRC-33-82-321 82/09/17 13pp 13644 326
- --8210080009 Mod 3, adding no-cast extension from 820723 to 0823 to.
 "Resolution of Shipper-Receiver Differences"

 HAVERFIELD: A J Battelle Memorial Institute, Pacific Northwest
 Laboratory QUSTAVER P Research Contracts Branch FIN 8-8103

 (NRC-01-81-012-0 82/09/21 1p 13669 352
- 8210080012 Notification of contract execution. Mod 4 to "Seismicity & Earthquake Hazard Research in Northern AL" Contractor Geological Survey of AL Univ of AL HOLLETT, B Research Contracts Branch FIN G-6674 NRC-04-80-220 82/09/21 BATSON. N. MURPHY, A Office of Nuclear Regulatory Research, Director ip 15669 353
- --8210080022 Hod 4, adding funding for equipment purchases for use under previously approved scope to. "Seismicity & Earthquake Hazard Research in Northern AL."

 MANCINI.E A Alabama Univ of. GUSTAVE.R Research Contracts
 Branch FIN B-6674 NRC-04-80-220 82/09/21 1p 15669 354
- 8210120321 Notl fication of contract execution, Mod 8 to "Development & Implementation of Flow Analysis Bys Dazed on Synthetic Aperture Ultrasonic Imaging Technique" Contractor SWR1 MOLLETT. 8 Research Contracts Branch FIN 0-3605 NRC-09-77-143 82/09/15 FOREHAND, W. NUSCARA, J Gffice of Nuclear Regulatory Research, Director 19 12672 210
- --B210120330 Hod 8, extending period of performance to 630930 & Increasing funding, to "Development & implementation of Flow Analysis Based on Synthetic Aperture Ultransonic Imaging Technique."

 SPRENCELLY F. Bouthwest Research Institute GUSTAVE, R. P. Research Contracts Branch FIN B-5605. NRC-04-77-145 B2/09/1549 15692 219
- 8210120338 Notlification of contract execution. Mod 2 to "Habash Valley Seismic Profile" Contractor Purdue Research Foundation WOLLETT.8 Research Gontracts Branch FIN 8-7223 NRC-04-80-224 82/07/22 BATEON.W., ZURFLEUH.E Office of Nuclear Regulatory Research, Director ip 15691 051
- --8210120342 Mod 2.extending seriod of performance to 830907.to "Wabesh Valley Esismic Profile" | GREENKORN,R A Purdue Research Foundation GUSTAVE.R P. Gontracts Branch FIN 8-7223 NRC-04-80-224 82/09/22 ip
- 82:0120347 Notification of contract execution: "Reviewing Hydrogeologic Investigations of NV Test Sits (NTS)-Project D, " awarded to Geofrans.inc High Colonia Contracts Branch FIN 8-7377-2 NRC-02-82-047 82/07/29, DAVIS J., VERMA, T Office of Nuclear Material Bafety & Safeguards, Director ip 15491 06:
- ~-8210120350 Contract "Reviewing Hydrogsologic Investigations of NV Test Site (NTB)~Project D." awarded to GeoTrans.Inc. HERCER.J W geotrans. Inc MATTIA:N J Division of Contracts FIN 8-7977~2 NRC-02-82-047 82/09/29. 37pp 15691.062

- \$210120354 Notification of contract execution, Mod 2 to "Value-Impact Analysis of Recommendations re Steam Generator Tube Degradations & Rupture Events " Contractor Science FLYRN, M Technical Assistance Contracts Branch FIN 8-8622 NRC-03-82-131 82/09/28 EISSNHUT, D C , BILVER, H Division of Licensing 1p 15690 340 Applications Inc
- --B210120357 Mod 2 redefining tasks extending delivery date of draft technical evaluation rept & increasing contract amount to, "Valua-Impact Analysis of Recommendations re Steam Generator Tube Degradations & Rupture Events "FINDLEY, D & Science Applications, Inc. HAQAN, T F Division of Contracts FIN B-BA22 NRC-03-82-131 82/09/28 2pp Contracts 15690 341
- 8210120361 Notification of contract elecution Mod 3 to "Economic Assistance in Connection w/Antitrust Hearings"

 Contractor JH Kuhlman HOLEAREN.T Technical Assistance Contracts Branch NRC-03-75-097 82/10/05 PENTON DE CONTRACTOR FIN 8-5494 NRC-03-75-097 82/10/05 DENTON.HR Diffice of Nuclear Reactor Regulation, Director ip 15690 247
- --B210120362 Mod 3. deobligating funds, to "Economic Assistance in Connection w/Antitrust Hearings"

 KUHLMAN, J H Kulhman, J M FIN B-5494 NRC-03-75-097 B2/10/05

 1p 15690 248
- 8210120363 Not: #1cation of contract execution. Mod 7 to "Study of Paleotoic Stratignaphy in New Madrid Area of MS Embayment "
 Contractor Univ of KY Research Foundation
 SILVIS,R M Research Contracts Branch FIN 8-3972 NRC-04-76-321
 82/09/20 BATSON.W STEUER.# Office of Nuclear Regulatory
 Research, Director 1p 15690 245
- --82i0120364 Ltr Contract NRC-04-76-321. Mod 7.deobligating funds to "Study of Paleozoic Stratigraphy in New Madrid Aree of MS Embayment" CUSTAVE.R P Research Contracts Branch NRC-04-76-321 82/06/CARTER.R Kentucky, Univ of 1p 15670 246 NRC-04-76-321 82/06/08
- 82(0)20365 Notification of contract elecution "Purchase of BSAM-; Assay Neters for Region 2." awarded to IRT Corp EDOEWORTH.P J Administrative Contracts Branch NRC-29-82-721 82/09/16 STOHR.J P. KONTOUMERY.D H Division of Emergency Preparedness & Operational Support in 15690 222 "Purchase of BSAM-100
- --B210120366 Contract "Purchase of BSAM-100 Assay Meters for Region 2." avanded to IRT Corp * IRT Corp MATTIA: M J Administrative Contracts Branch NRC-29-82-721 82/09/16 82pp 15690 223
- 82(0)2039) Notification of contract elecution "Reviewing Hydrogeologic Investigations of NV Yest Site (NTB)-Project C," awarded to William-Robinette & Associates, Inc Wildeling, E. Technical Assistance Contracts Brench. Fin B-7377-2 NRC-02-B2-046 B2/09/30 DAVIS, J. VERMA, T. Office of Nuclear Katerial Safety & Safeguerde, Director. ip. 15687-242
- ---8210120401 Contract "Reviewing Hydrogeologic Investigations of NV Test Site (NTS)-Project C," awarded to Williams-Robinette Associates, Inc HYLLIAMS, R E Williams-Robinette & Associates, APPLICAMS, R E FIN B-7 WILLIAMS.R E Williams-Robinette & Associates. Inc MATTIA, N J Technical Assistance Contracts Branch FIN 8-7377-2 NRC-02-82-046 82/09/30 36pp 15689 243.
 - i of contract execution. "Maint & Operation of Rooms (LPDRs)." awarded to Appling
 - stive Contracts Branch NRC-10-82-714 SOUDER, J Division of Rules and Records
 - of Local Public Document Rooms ibrary: QA A Administrative Contracts in 15ARO DOS

- 8210120427 Notification of grant execution, Mod 2 to "Aerospace~ ziol2042/ Notification or grant execution mod 2 to "Aerospace" Electric Power Morkshog Conference on Commercial Nuclear Power " Grantse American Inst of Aeronautics & Astronautics HCOERHOTT.D Research Contracts Branch FIN 9-1005 RRC9-04-81-002 82/09/29 RIBL Office of Nuclear Regulatory Research, Director ip 15671 159
- --8210120432 Mod 2.extending no-cost period of performance to 821231.t "Aerospace-Electric Power Morkshop Conference on Commercial Nuclear Power" BRUCE.W R American Institute of Aeronautics & Astronautics HORTON,K V Research Contracts Branch FIN G-1005 NRCO-04-81-002 82/09/29 ip 15671 160
- 82:01:20436 Notification of contract execution "Bioassays Using Resource Ionization Spectroscopy," awarded to Atom Sciences, HAGEY.H Research Contracts Branch FIN 8-8122 NRC-04-82-021 82/09/27 FOREMAND.H NEEL.R Office of Nuclear Regulatory Research Director ip 15671 167
- -- 8210120440 Contract "Bloassays Using Resource Ionization SCHMITTIH W Atom Sciences, Inc MORTON.K V Research Contract. Branch FIN 8-8122 NRC-04-82-021 82/09/27 15pp 15671 168
- 82[0120454 Notification of contract execution, Mod 1 to "Reviewing Hydrologic Investigations of Besalt Waste Isolation Project (BMTP), Project B " Contractor Colder Associates, Inc FLEENOR: C Technical Assistance Contracts Brench FIN 8-7373-2 NRC-02-82-045 82/09/22 DAVIS, J. VERMA: T R Office of Nuclear Material Eafety & Bafeguards, Director ip 15671 207
- --8210120458 Mod 1 increasing funds to "Reviewing Hydrologic Investigations of Baselt Waste Isolation Project (BWIP), Project B " MESTIL J Golder Associates HAGAN, TF Technical Assists Cantrects Brench FIN 8-7373-2 NRC-02-82-045 82/09/22 Technical Assistance
- 82:0120467 Notification of contract execution. Hod 4 to "UB Army Corps of Engineers Geotechnical Assistance " Contractor UB Army Corps of Engineers FLEENOR, C. Technical Assistance Contracts Branch NRC-02-01-036-82/09/24 DAVIS, J. PRESTHOLT, P. Office of Nuclear Katerial Bafe! & Safeguards, Director ip 15672-001
- --821012047; Hod 4 revising reporting requirements extending period performance to 830930 & changing project officer to "UB Army Corps of Engineers Geotechnical Assistance"

 KAVANAUGH.P.F. Army Dept of, Corps of Engineers HAGAN, T.F. Tachnical Assistance Contracts Branch NRC-02-81-026 B2/09/24
 3pp 13672 002
- 8210120483 Notification of grant execution "Horkshop on Strong-Orov Motion Simulation & Engineering Applications," ewarded to Earthquake Engineering Research Inst MCDERMOTT, D. Research Contracts Branch FIN 0-1038 NRC-0-04-82-007 82/09/29, BATBON, W. MURPHY, A. Office of Nucle Regulatory Research, Director Ip 13672 033
- --8210120488 Orant: "Workshop on Strong-Oround Motion Simulation & Engineering Applications," awarded to Earthquake Engineering Research Inst. NOVEMBER 1 185. SCHOLL, R.E. Earthquake Engineering Research Institute. MORTON, K. V. Research Contracts Branch. FIN G-1038 NRC-G-04-82-007 82/09/29 2pp 15672 054.
- 8210120490 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Joseph Hann Library Administrative Contracts Branch NRC-10-82-707.
 LITTLE: M Administrative Contracts Branch NRC-10-82-707.
 82/09/27. FELTON, J H : 8GUDER, J Division of Rules and Records ip 13672 036
- --8210120494 Contract "Maint & Operation of Local Public Documents Rooms (LPDRs)" awerded to Joseph Menn Library HEITKEMPER, E M. Two Rivers. HI BHITH.P.A Administrative Contracts Branch NRC-10-82-707. 82/09/27 9pp 13672 057
- 8210120497 Notification of contract execution. Task Order 25. "Techn Assistance to Support NRC IE Personnel in Investigations of Incidents." awarded to Personnel in Investigations of Incidents." awarded to Personnel Incidents. Research Contracts Branch FIN B-1302. NRC-03-82-24. BQL/09/10 BLAHALJ. LAUDAN.W Director's Office Office of Inspection and Enforcement. ip 15672-072.
- --8210120308 Ltr Contrect NRC-05-B2-249. Task Order 25, "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents," awarded to Parameter. Inc OUBTAVE.R P. Research Contrects Branch. FIN 8-1902 NRC-05-82-249. 82/09/07. LOFY,R A Parameter. Inc 2pp 1947-2072 15672, 073,

- ERIDI20510 Nots fication of contract execution "Mount & Operation of Local Public Document Rooms (LPDRs)," awarded to Exeter/NH Public Library LITTLE.H Administrative Contracts Branch NRC-10-82-712 82/09/30 FELTON.J M, SOUDER, J Division of Rules and Records 1p 15672 081
- --82(0)20517 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Exeter.NR Public Library GLETTUM:P Exeter.NH SHITH:P A. Administrative Contracts Branch NRC-10-82-712 82/09/30 7pp 15672 082
- 8210120534 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Ocean County Library, NJ LITTLE, IMPROVED A CONTRACT OF THE PROPERTY OF T
- --P21012034: Centract "Maint & Operation of Local Public Document Roces (LPDRs)," awarded to Ocean County Library, NJ UNDIXI, J J Ocean County, NJ SMITH,P A Administrative Contracts Branch NRC-10-82-713 82/09/30 7pp 15672 207
- 8210120540 Notification of contract stocution, Mod 7 to "Peer Review of High Level Maste Site Suitability Criteria" Contractor TRM. Inc. MCLEAREN.T Technical Assistance Contracts Branch FIN B-613/-3 NRC-02-77-143 82/09/27 DAVIS.J 0 Office of Nuclear Material Safety & Safeguards, Director 1p 19672 217
- --B210120550 Hod 7, incorporating final indirect rates for FY77 & FY78, to *Peer Review of High Level Waste Bite Buitability Criteria "
 MCDUNELLE J TRH. Inc HAGAN.T F Division of Contracts FIN B-8137-3 NRC-02-77-143 82/09/27 ip 15672 218
- 8210120549 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Ban Clements, CA Public Library LITHER, Administrative Contracts Branch NRG-10-92-708 R2/09/30 FELTON, J M , SOUDER, J Division of Rules and Records
- --8210120556 Contract "Haint & Operation of Local Public Document Rooms (LPDRs)," awarded to San Clements, CA Public Library SHITH, E M San Clements, CA SMITH, P A Administrative Contracts Branch NRC-10-82-708 82/09/30 7pp 15472 227
- 8210120607 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Kowawnee, WI Public Library Little Administrative Contracts Branch NRC-10-B2-694 EELTON, J H , BOUDER, J Division of Rules and Records
- ---8210120613 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Kewawnee, WI Public Library (CRBSHUESCH, B Kawaunee County, WI SMITH, P. A Administrative Contracts Branch NRC-10-82-674 82/09/27 9pp 15684 200
- E21013000B Notification of grant execution. Hod 2 to "Study of Faulting in t Near Surface & Underground Mines of Southwestern IN " Orante IN Univ. HCDERHOTT, D K Research Contracts Branch FIN 0-1019 NG-0-04-81-017 82/09/22 BCHMITT, Office of Nuclear Regulatory Research, Director 1p 15592 333
- --8210130014 Hos 2; incorporating renewal proposal, extending period of performance to B30930 & increasing funding, to "Study of Faulting in & Near Burface & Underground Mines of Southwestern MUNDLLAND, U.D. Indiana Univ HORYON, K.V. Research Contracts Branch FIN 0-1019 NRC-0-04-81-017 B2/09/22 Ip 15492; 334
- 8210(30052 Notification of contract execution: "Expert Opinion During Meetings of NRC Advanced Reactor Subcommittee of ACRB Concerning LHFBRs," awarded to Rockwell Intl.
 TOHNSEND, B L Administrative Contracts Branch FIN 8-1557
 NRC-11-82-433 82/09/23. GABKE, M. C. BOEHNERT, P. A. ACRB Advisory Consistee on Reactor Safeguards. 1p. 15896-277.
- --8210130054 Contract "Expert Opinion During Meetings of NRC Advanced Reactor Subcommittee of ACRS Concerning LMFBRs." awarded to Rockwell Intl.

 MCMMONR A Rockwell International Corp REBELLO, J E A44601strative Contracts Branch FIN 8-1557 NRC-11-82-433 82/09/23. 4pp. 15496:278

- 8210130058 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Southport~ Brunswick NG County Library LITTLE: M Administrative Contracts Branch NRC-10-82-702 82/09/28 FELTON: J H : SOUDER, J Division of Rules and Records to 15-692 274
- --8210130061 Contract "Meint & Operation of Local Public Document Hours (LPDRs)," awarded to Southport-Brunswick NC County Library HARPER, M T Bouthport, NC BHITH, P Administrative Contracts Branch NRC-10-82-702 82/09/28 9pp 15492 275
- B2[013007] Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)." awarded to Somervell County Public Library on Square
 LITTLE, H Administrative Contracts Granch NRC~10~B2-686
 82/09/28 FELTON, J. M. SQUDER, J. Division of Rules and Records
 10 1888 283
- --8210130074 Contract "Haint & Operation of Local Public Document Norms (LPDRs)," awarded to Somervell County Public Library on Square HHITHORTH,F Somervell County,TX SMITH,P A Administrative Contracts Branch NRC-10-92-586 92/09/28 900 15496 254
- 82(01305B7 Notification of contract execution Task Orders 21.22.23 & 24, to "Technical Assistance to Support NRC [E Personnel in Investigations of incidents." Awarded to Personnel reflecting the Contracts Branch FIN 8-1302 RRC-05-82-249 82/09/02 BLAHA.J. LAUDAN.W Director's Office of Inspection and Enforcement ip 13492 338
- --8210130592 Ltr contract executing Task Orders 21,22,23 & 24, to "Technical Assistance to Support NRC IE Personnel in Investigation of Incidents" GUSTAVE, RP Research Contracts Branch FIN B-1302 NRC-09-82-249 82/08/31 LOFTY, RA Parameter, Inc. 2pp 13562 339
- 8210150328 Notification of contract execution, Mod 11 to "Study of Saismicity & Tectonics in New England" Contractor Boston College JACOBS, A Research Contracts Branch FIN A-4086 NRC-04-74-238 B2/09/23 SAISON, H. KURPHY, A Office of Nuclear Regulatory Research, Director 1p 15715-337
- --8210150350 Mod ii.increasing funding.to "Study of Seismicity & Tectonics in New England"

 BMITH, J.R. Boston State College QUSTAVE, R.P. Research Contracts
 Branch FIN A-4056 MRC-04-74-238 82/09/23 5pp 15715 338
- 8210180327 Notification of contract execution: Mod 22 to "Rayisw & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions " Contractor Franklin Inst FLYNN:M Technical Assistance Contracts Branch FIN 11-6590 NRC-03-79-118 82/09/28 EISENHUT: D 9 BAJWA:B Division of Licensing 1p 15746 003
- --B210180332 Mod 22.obligating funds to "Review & Evaluation of Approx 500 Pending Operating Reactore Licensing Actions" BYOVER, J.R. Franklin Institute/Franklin Research Centur HAGAN, T.F. Division of Contracts FIN 8-6590 NRC-03-79-118 B2/09/28 3pg 13744 004
- 82:0180329 Not & Ref inc.
 Inc.
 BAZIN.JP Administrative convigor.
 BAZIN.JP Administrative convigor.
 BAZIN.JP Administrative convigor.
 BZ/09/30 BESAW.W.J. BKQCZLAB.J. BCDTT.B Division of Technical Information & Document Control Ip 15745:339
- --B210180338 Contract "Microfiche Verification & Retrofit," awarded to BSA Bubcontractor Labat-Anderson: Inc. HILL, D. Bmell Business Administration " Labat-Anderson: Inc BMITH:P A Administrative Contracts Branch NRC-10-82-425 B2/09/30 Qpp 15745-340.
- --8210180348 Contract. "Microfiche Verification & Retrofit," awarded to Labat-Anderson. Inc LABAT.V J Labat-Anderson. Inc HILL.D Small Business Administration. NRC-10-82-425 82/09/30 23pp 15745 342
- B2i0180357 Notification of contract execution, Mod 9 to "Seismotectonic Study of New England & Adjacent Areas " Contractor Boston College, JACO85:A Research Contracts Branch FIN 8-5961 NRC-04-76-291 B2/09/23 BATBON:H, HURPHY.A Office of Nuclear Regulatory Research, Director 19 13745.302

- --B210180362 Mod 9, funding FV82 action to "Seismatectonic Study of New England & Adjacent Areas " SMITH.J R Boston Collège GUBTAVF, R P Division of Contracts F1N B-596s NRC-04-76-291 82/09/93 Bpp 15745 303
- 8210180365 Notification of contract ejecution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Calvert County, MD Library LITTLE, M Administrative Contracts Branch NRC-10-82-704 82/09/27 FELTON, J H , SOUDER, J Division of Rules and Records in 15745 311
- --8210(8037) Contract "Maint & Operation of Local Public Document Rooms (LPDRs)." awarded to Calvert County. HD Library HURREY.K C Calvert County, HD REBELLO.J E Division of Contracts NRC-10-82-704 82/09/29 9pp 15745 312
- 8210190384 Notification of contract execution, Mod 23 to, "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions" Contractor Frenklin Inst FLYNM: M. Technical Assistance Contracts Branch FIN 8-6590 NRC-03-79-118 82/09/30 EISENHUT.D., BAUHA:S Division of Licensing 1p 15745 321
- --8210180390 Mod 23. obligating funds, extending performance period to 830331 & assigning new project menager, to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions"

 ZUDANS, Z Franklin Institute/Franklin Research Center MATTIA. H J Division of Contracts FIN 8-6590 NRC-03-79-118 82/09/30 3pp 19745 382
- 8210180395 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Lawson McGhee Public Library
 LITTLE, M. Administrative Contracts Branch NRC-10-82-701
 82/09/28 FELTON, J.M., SDUDER, J. Division of Rules and Records to 15745-270
- --821018040i Contract "Maint & Operation of Local Public Document Rooms itPDRs)." awarded to Lawson McOhee Public Library BARIOLINI.R P Knoiville, TN SMITK.PA Administrative Contracts Branch NRC-10-82-70L 82/09/20 9pp 15745 29i
- 8210180411 Notification of contract execution, "Maint & Operation of Local Public Bocument Rooms (LPDRs)," awarded to Emporia State Univ LITTLE.M. Administrative Contracts Branch NRC-10-82-687 82/09/28 FELTON, J. K. SOUDER, J. Division of Rules and Records 1p 15745-323
- --B210180416 Contract "Maint & Ogeration of Local Public Document Rooms (LPDRs)," awarded to Emporta State Univ VISSER.J E Emporta State Univ SHITH,P A Division of Contracts NRC-10-82-887 82/07/28 8pp 15745 324
- 8210190001 Notification of grant execution "Chapman Conference on Fault Bahavior & Earthquake Generation Process," awarded to American Geophysical Union (HOBERMSTF, D.K. Research Confracts Branch FIN 0-1039 NRC-G-04-82-008 82/09/29 BATSDN.H. HURPHY, A.J. Office of Nuclear Regulatory Research. Director ip 15760 174
- --B210190002 Grant "Chapman Conference on Fault Behavior & Earthquake
 Process," awarded to American Geophysical Union
 American Geophysical Union HURPHY, A J Research
 ach FIN 0-1039 NRC-0-04-82-008 82/09/29 2pp

- 82:01900iB Notification of contract execution. Mod 7 to "Technica)
 Assistance in Bupport of Reactor Licensing Actions Program
 2 "Contractor Science Applications. Inc
 FLYNN, H Technical Assistance Contracts Branch FIR B-8609
 NRC-03-82-094 82/09/30 EISENHUT. D. SILVER, H Division of
 Licensing ip 15760 342
- ~-8210190025 Mod 7, providing incremental funding, to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2"

 Science Applications, Inc. HAQAN, T.F. Technical Assistance Contracts Branch FIN B-8607 NRC-03-82-094 82/09/30 2pp 19760 342
- B210190030 Natification of contract execution.Mod 4 to "Technics]
 Assistance in Support of NRC Reactor Licensing Actions
 Program 2 "Contractor Science Applications: Inc
 FLYNN,M Technical Assistance Contracts Branch Fin B-BAG9
 NRC-03-82-096 82/09/28 EISENAUT.D 0 , BILVER, M Assistant
 Director for Licensing 1p 19761 031
- --8210190037 Mod 6, substituting members of performance evaluation bases a providing incremental funding to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2 "FINDLEY, D & Beience Applications, Inc. HAGAN, T F Tachnical Assistance Contracts Branch FIN B-8609 NRC-03-82-096 82/09/28 2pp 15761 032
- 8210190057 Notification of contract execution "Tornado Hindspeed Documentation," awarded to Univ of Chicago HAGEY,M Research Contracts Branch FIN B-810B NRC-04-82-004 82/09/22 BATBON,W, ORENIER,B, ABDEY,R Office of Nuclear Regulatory Research, Director 1p 15761 049
- --8210190063 Contract "Tornado Windspeed Documentation," awards6 to Univ of Chicago SIDALD S Chicago Univ of MORTON,K V Research Contracts Branch FIN B-8108 NRC-04-82-004 82/09/22 10pp 15761 050
- 82:0190076 Notification of contract execution, Mod 2 to "Degraded Piping Program" Contractor BMI WOLLETT, B Research Contracts Branch FIN 8-7027 NBC-04-81-178 82/09/24 FOREMAND 8, STROSNIGER, J Office of Nuclear Regulators Research, Director ip 18761 098
- --B2101900B7 Mod 2.increasing funding 6 extending period of performants to 830531.to "Degraded Piping Program"

 * Battelle Hemorial Institute, Columbus Laboratories
 OUSTAVE.R.P. Research Contracts Branch NRC-Q4-Bi-178 82/09/24
 3pp 15761 099
- 8210190102 Notification of contract execution, Mod i to "Hydrological Engineering Coastal Review of Operating Factors (I)" Contractor DDD.
 FIELDS, J.A. Technical Assistance Contracts Branch FIN N-DOGA NGC-03-81-132, 82/09/30 VOLLMER, R.H., LEAR, G. Division of Engineering ip 13761 223
- --8210170105 Mod indeabligating balance of FY81 travel funds & oblight FY82 travel funds to "Hydrological Engineering Coastal Review of Operating Factors (I) "

 * Army Dept of FIN B-8006 NRC-03-81-132 82/09/30 2pp 15761 224
- 8210190132 Notification of contract execution. Hod 9 to "Utilication of BHR & PHR Simulator Activities " Contractor TVA JACO89.A Research Contracts Branch NRC-05-76-357 82/09/23 BLAHA, J. POX.E Program Support Branch Ip. 15761 237
- --8210190141 Mod 9, increasing funding, to "Utilization of BWA & PRA Simulator Activities." JOHNSON.R. A Tennessee Valley Authority GUSTAVE.R P Rasear Contracts Branch NRC-05-76-357 82/09/23 ip 15751 238
- B210190147 Notification of contract execution, Mod 4 to "On-Call & Scheduled Monthly Preventive Haint on ECLIPBE 8/230 Computer Sys " Contractor Computer Bys Bupport Corp SMITH, P A. Division of Contracts FIN 8-1671 NRC-10-00-708 82/04/30 DORIE, W H , JOHNBON, C Office of Administration 19 13761 244
- --8210190154 Mod 4, deobligating balance remaining, to "On-Call & Scarl Monthly Preventive Maint on ECLIPSE S/230 Computer Sys ROST.L.E Computer Systems Support Corp SMITH.P.A Division: Contracts FIN 8-1671 NRC-10-80-706 82/09/30 bp 1574121
- 82:0190162 Notification of contract execution. Hod 1 to "Partition: Contractor. Aspects. Inc SMITH.P.A. Division of Contracts. NRC-10-82-401 82/09/30 FETROW. 0 Division of Facilities & Operations ip 15844 138

- ~-8210190167 Hod 1.deobligating balance remaining, to "Partitions" LED.F A Aspects. Inc SMITH.P A Division of Contracts ASC-10-82-401 82/09/30 ip 15758 048
- B21G190172 Notification of contract execution "Near Ground Tornado Mind Fields:" awarded to TX Tach Univ RAGEY.H Research Contracts Branch FIN B-8099 NRC-04-B2-002 B2109721 BATSDN.W r ABBEY.R Office of Nuclear Regulatory Research, Director 1p 13758 049
- --8210190177 Contract "Near Ground Tornado Wind Fields," awarded to TX Tech Univ JONES.J K Texas Tech Univ MORTON.K V Research Contracts Reanch B-8099 NRC-04-82-002 82/09/21 12pp 15758 050
- B210190179 Notification of contract execution "Presentation of General & Refresher Courses in Nondestructive Exam," awarded to Roctuell Intl Corp HACEV.H Research Contracts Branch FIN B-1303 NRC-05-82-246 S2/09/21 FOX.E Program Support Branch ip 15759 114
- --B210190182 Contract "Presentation of General & Refresher Courses in Nondestructive Exam," awarded to Rockwell Intl Corp JOHNSON,R A Rockwell International Corp MORTON,K V Research Contracts Branch FIN B-1303 NRC-05-82-246 82/09/21 3pp 15759 115
- EZIO190210 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Charlevoix, MI Public Library LITTLE, M Administrative Contracts Branch, NRC-10-D2-699 BZ/09/30 FELTON, J M , SOUDER, J Division of Rules and Records to 13759 141
- --8210190215 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Charlevoix MI Public Library WALLICK, HE Charlevoix MI REBELLO, JE Administrative Contracts Branch NRC-10-82-699 82/09/30 9pp i5758 i42
- 6210190219 Notification of contract execution "Radio Frequency Surveillance Receiver & Accessories," ewerded to Micro-Tel Corp. COLEMAN, R Administrative Contracts Branch NRC-10-82-682 BRADY, R, FINGER, R Division of Security ip 15739 151
- --8210170223 Contract "Radio Frequency Surveillance Receiver & Accessories," awarded to Micro-Tel Corp # Hicro-Tel Corp EMITH.P. A Administrative Contracts Branch NRC-10-82-682 82/09/30 21pp 13759:132
- 8210190230 Notification of contract execution, Mod 1 to "Reviewing Hydrogeologic Investigations of MV Test Site (NTS) Project D.* Contractor Geotrans, Inc #1001NB.E Technical Assistance Contracts Branch FJN A-7377-2 PRO-02-82-047 82/09/30 DAVIS.J. VERMA.T. Office of Nuclear Kiterial Safety & Bafeguards, Director. 1p 13758 177
- --82]0190339 Hod 3, correcting accounting & appropriation data, to "Reviewing Hydrogeologic Investigations of NV Test Site (NTS) - Project D" 4 Geotrans, Inc. MATTIA, H. J. Technical Assistance Contracts Branch FIN B-7377-2 NRC-02-82-047, 82/09/30 jp 15758 J78
- 8210210036 Notification of grant execution. Mod 2 to "Development of Kethodology for Systematic Probabilistic Risk Assessment of Nuclear Power Plants." Grantse, IEEE KEDERNOTIO Research Contracts Branch FIN 0-1007 RRC-0-04-81-005 B2/08/30 BATBONIN., JOHNSON, C Office of Nuclear Regulatory Research, Director 1p. 15773, 271
- --9210210038 Med 2.providing add1 funds.to "Development of Methodology for Systematic Probabilistic Risk Assessment of Nuclear Power Plants."

 ** Institute of Electrical & Electronic Engineers HORTON, K V, Research Contracts Branch FIN 0-1007, NRC-0-04-Bi-005 82/00/30, pp 10773 272
- 921021006: Notification of contract execution. Mod 7 to "Bealing Rock Hasses" Contractor. Univ of AZ

 WCOBB: A Research Contracts Brench FIN B-6627 NRC-04-78-271
 82(09/28 BATSB(N,), DOYLEL Office of Nuclear Regulatory
 Research, Director 1p. 15774:123.
- --8210210066 Mod 7, adding govt property, to "Sealing Rock Masses "
 CARR.S E Arizona, Univ of. QUBTAVE.R P Research Contracts
 Branch. Fin 8-6627. NRC-04-78-271 82/09/28. 1p 15774 124

- 8210210147 Notification of contract execution, Mod 1 to "Maint & Operation of Local Public Document Rooms (LPDR) "
 Contractor Richland, MA Public Library
 LiTtle, A Administrative Contracts Branch
 82/09/29 FELTON, J M . SOUDER, J Division of Rules and Records in 15774 299
- --0210210161 Mod [,increasing monetary value of contract,to "Maint & Operation of Local Public Document Rooms (LPDR) " Richland, MA, SMITH,P A Administrative Contracts Branch NRC-10-02-706 82/09/29 ip 15774 300
- 82/02/01/74 Notification of grant execution "Evaluation of Denefits of Response Time In Situ Testing of Neutron Bensons Used in Nuclear Power Research Protection Bys "Awarded to CH State Univ Research Foundation HODERNOTTID Research Contracts Dranch FIN G-1044 NRC-0-04-82-011 82/09/20 HINIZE, A Office of Nuclear Regulatory Research, Director 19 15772 361
- --8210210178 Grant "Evaluation of Benefits of Response Time In 51th Testing of Neutron Sensors Used in Nuclear Power Reactor Protection Sys" SLOAN: K W Onio State Univ MGRTON, K V Research Contracts Branch FIN G-1044 NRC-0-04-82-011 82/09/20 2pp 15772 362
- 8210210438 Notification of contract execution "Facilities Documentation to Update Project," awarded to 58A Subcontractor Bryant & Bryant EDDEMORTH.P Administrative Contracts Branch NRC-10-82-420 82/09/28 CORLEY, J H., FISHER, L. Division of Facilities & Operations ip 15773 273
- --8210210444 Contract "Facilities Documentation & Update Project,"
 awarded to SBA & Bryant & Bryants (subcontractor)
 BRYANT,R E Bryant & Bryant Alb DENNISTON, S F Small Business
 Administration MATIIA, M J Administrative Contracts Branch
 NRC-10-82-420 82/09/28 2ipp 15773 274
- 8210210502 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LFDRs)," awarded to Richland, WA Public Library LITKLE, H Administrative Contracts Branch NRC-10-82-704 82/09/29 FELTON, J H , BOUDER, J Division of Rules and Records ip 18782 273
- --8210210905 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Richland, HA Public Library ROBERTS, D E Richland, HA, SMITH, P A Administrative Contracts Branch NRC-10-82-706 82/09/29. 9pp 15792 274
- B210210564 Notification of contract execution "Transient Prototypical Steam Generator (MB-2) Research Testing Program," awarded to Mestinghouse & EPRI BAIBDEN, L. Research Contracts Branch FIN 11-8252 NRC-04-82-020 82/09/30 BATSON, H. HOPENFELD, J. Office of Nuclear Regulatory Research, Director 2pp 15784 283
- --B210210570 Ltr Contract NRC-04-82-020, "Transient Prototypical Steam Generator (HB-2) Research Testing Program "Accepted by BB Rytkonen on B20929 & J Moore on B20924 HORTON K V Research Contracts Branch FIN B-8252 NRC-04-82-020 82/09/28 FEROUSON K L Westinghouse Electric Corp. RYTKONEN, B D Electric Power Research Institute 11pp 15784, 285

- 3210260237 Notification of grant elecution "Thermal-Hydraulic Transient Behavior of Coolant in Simulated Reactor Loop," awarded to Univ of ND MCDERMOTT, D.K. Research Contracts Branch FIN 0-1043 NRC-0-04-02-013 82/09/27 YOUNG, M. Office of Nuclear Regulatory Research, Director 10 15830 145
- --8210260240 Grant "Thermal-Hydraulic Transient Debavior of Coolant in Simulated Reactor Loop," awarded to Univ of MD CASHHAN.D C Haryland, Univ of MORTON,K V Research Contracts Branch FIN 0-1043 NRC-0-04-82-013 82/09/27 2pp 15830 146
- 8210260278 Notification of contract elecution, Mod 11 to "Technical Assistance to Support NRC IE Personnel in Investigation of Incidents" Contractor Parameter Inc MOLLETT.5 Research Contracts Branch FIN B-1013 NRC-05-80-251 82/09/24 BLAHA. J L . LOFY:R A Program Support Branch Ip 15830 148
- --8210260280 Mod il.increasing colling & changing billing ofc & address for submission of invoices, to "Technical Assistance th Support NRC IE Personnel in Investigation of Incidents " LOFY, R A Parameter. Inc OUSTAVE, R Research Contracts Branch FIN 2-1013 NRC-05-80-251 92/09/24 ip 15830 149
- 8210260282 Notification of contract execution. Mod 4 to "Presentation of CE BUR/6 Design & Operation Courses " Contractor GE JACOBS, A Research Contracts Branch FRN B-1224 NRC-05-80-282 82/09/29 BLAHA, J. PIERCE.R Program Support Branch 19 15830 150
- --8210260284 Mod 4, changing order re-price & funding action, to "Presentation of GE BNR/6 Design & Operation Courses "AVERITIOD D General Electric Co GUSTAVE.R P Division of Contracts FIN B-1224 NRC-05-80-282 82/09/29 2pp
- B210240516 Notification of contrast execution "Maint & Operation of Local Public Document Rooms (LPDRs)." awarded to Chattanooga-Hamilton County TN Bicentennial Library LiTILE.M Administrative Contracts Branch NRC-10-82-703 B2/09/28 FELTON.J M . SOUDER.J Division of Rules and Records 19 15830 158
- --8210260520 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)." awarded to Chattenooga-Hamilton County TN Bicentennial Library ARNOLD-K Chattenooga-TN EMITH-P A Administrative Contracts Branch NRC-10-82-703 82/09/28 9ps 15830 159
- 9210260525 Notification of contract elecution "Maint & Operation of Local Public Document Rooms (LPDRs)." awarded to Lacrosse WI Public Library LITTLE.M Administrative Contracts Branch NRC-10-82-685 82/09/20 FELTON, J M , SOUDER, J Division of Rules and Records ip 15830 179
- --8210260530 Contract "Maint & Operation of Local Public Bocument Rooms (LPDRs)," awarded to Lacrosee HI Public Library WHITE, J H LaCrosee, HI SMITH, P A Admin(strative Contracts Branch NRC-10-82-685 82/09/28 9os 15830 180

- 8210270199 Natification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," swarded to State Library of PA BAZIN.J P Administrative Contracts Branch NRC-10-82-674 E2/09/28 FELTON.J M. SDUDER.J Division of Rules and Records to 15834 001
- --8210270203 Contract "Maint & Operation of Local Public Dotument Rc: (LPDRs)," awarded to State Library of PA SHELKROT.E L Pennsylvania. State of MATTIA.H J Division of Contracts NRC-10-82-696 82/09/28 149p 15836 002
- 8210270207 Notification of contract execution "Availability of Medic.
 Treatment to Minimize Early Fatalities Post-Severe Reactor
 Accidents," awarded to SBA Subcontractor Androlly Research
 Corp
 WIGGINS.E Technical Assistance Contracts Granch FIN B-R616
 NRC-03-82-128 62/09/29 MATTEON.R J. WOHL.M Division of by *t*.
 Integration (post 811005) ip 18836 016
- --8210270221 Contract "Availability of Medical Treatment to Historical Early Fatalities Post-Severe Reactor Accidents," awarded to SBA Bubcontractor Andrulis Research Corp ANDRULIS, H W Andrulis Research Corp DENNISTON, G F Gmajl Business Administration FIN B-8616 NRC-03-82-128 02/09/29 200 15836 017
- 8210270226 Notification of contract execution "Fire Protection Profits Review Case Work Plant 1." awarded to Gega-Babcock & Associates WIGOINS.E Technical Assistance Contracts Dranch FIN B (10.20) NRC-03-82-118 82/09/28 VOLLMER.R H Division of Engineering NOLAN.F Chemical Engineering Branch 1p 15836-046
- --8210270230 Contract "Fire Protection Program Review Case Hurb Plans, i." awarded to Gage-Babcock & Associates COHN, B H Gage-Babcock Associates, Inc. MATTIA, M.J. Divisio & Contracts FIN B-8020 NRC-03-82-118 82/09/28 Ripp 15836 047
- 8210270393 Notification of contract execution, Mod 3 to "Invisor Monitoring Program w/State of NC "Contractor State of NC WOLLETT,8 Research Contracts Branch FIN B-1239 NRC 05 NO 583 82/10/12 COBB.L 1, COHEN.L,V Director's Office, Office of Inspection and Enforcement ip 15833 360
- --8210270375 Mod 3.changing name of NRC billing ofc & address for submission of invoices to "Environ Monitoring Program w/State of NC"

 ** North Caralina, State of, GUSTAVE, R P. Research Contracts Branch FIN 8-1237 NRC-05-80-283 82/10/12 ip 1884 8-51
- 8210270399 Notification of contract execution, Mod 7 to "Hamphis Area Regional Balanic Network " Contractor Memphis State Univ JACOBB. A Research Contracts Branch FIN 8-6276 NRC 04 7th 2277 82/09/13 BATRONN , MURPHY, A Office of Nuclear Regulatory Research, Director ip. 15832 356

- --B210270419 Hod 3, deabligating unexpended balance of contract funds by issuance of no cost settlement after termination, to "Environ Assessment of Raffinate Study Disposal at Kerr-McGes Sequaga Facility, Gore, CK"

 ARCHER, C D Science Applications, Inc HAGAN, T F Technical Assistance Contracts Branch FIN B-7316 NRC-02-81-043 82/09/30 2p 18833 285
- 8210280206 Notification of contract execution "Use of PA Fish & Hildlife Data Base Sys in Environ Analyses for Nuclear Power Plant Licansing," aborded to PA Game Commission HOYLE.A Administrative Contracts Branch FIN B-8812 PRO-25-82-323 82/09/30 BASSETT.H B , JOHNSON, C Division of Data Automation & Hanagement Information ip 15858 355
- --B210280233 Contract "Use of PA Fish & Wildlife Data Date Bys in Environ Analyses for Nuclear Power Plant Licensing." awarded to PA Came Commission SMITH, P A Pennsylvania, Etate of SITLINGER, J i Administrative Contracts Branch FIN 8-8812 NRC-25-82-323 82/09/30 Spp 13858 336
- 8210280297 Notification of contract execution. Mod 2 to "Environ Assessments & EIS for Low Level Waste Disposal Facilities" Contractor Envirosphere Co.
 FLEENOR.C H Technical Assistance Contracts Branch NRC-02-82-026-09 82/10/09 DAVIS, J. PANOBURN.O Office of Nuclear Haterial Safety & Bafeguards. Director 1p 15837-034
- --8210280306 Mod 2, extending period of agreement to 830929 & incorporating administrative changes re billing, to "Environ Agreements & ETS for Low Level Waste Disposal Facilities " & Envirosphere Co HAGAN T F Division of Contracts NRC-02-89-028-09 82/10/05 2pp 15859 037
- 8210280310 Notification of contract execution Mod 2 to "Environ Assessments & EIS for Low Level Waste Disposal Faculities "Contractor Engineering-Science, Inc FLEENDR, C M Technical Assistance Contracts Branch RRC-02-82-026-08 B2/10/05 DAVIS, J. PANOBURN, O Office of Nuclear Material Safety & Safeguards, Director in 15857 039
- --B210280319 Nod 2. extending period of agreement to B30929 to incorporating administrative changes re billing, to "Environ Assessments & EIS for Low Level Waste Disposal Facilities" e Engineering Science HAOAN IT F Division of Contracts NRC-02-B2-025-08 82/10/05 2pp 15859 040
- 8210280327 Notification of contract execution Mod 2 to "Environ Assessments & EIB for Low Level Haste Disposal Pacilities" Contractor Maste higt Group. Inc FLEENOR, C M Technical Assistance Contracts Branch NRC-02-82-026-06 82/10/05 DAVIS.J., PANOBURN, O Office of Nuclear Material Safety & Bafeguards. Director 1p 15859 122
- --8210280331 Mod 2. extending period of agreement to 830929 & incorporating administrative changes re billing to "Environ Assessments & E18 for Low Level Waste Disposal Facilities " & Haste Management Group, Inc. HADAN, TF Division of Contracts NSC-02-82-026-06. 82/10/03 Rpp 15859 123
- 8210280354 Notification of contract execution, Mod 2 to "Environ Assessments & EIB for Low Level Waste Disposal Facilities" Contractor Kamen Tempo FLEENOR, C M Technical Assistance Contracts Branch NGC-02-68-026-05 B2/10/05. DAVIB.J. PANOBURN, O Office Of Muclear Material Safaty & Safaguards, Director 1p 13839:197
- --8210280334 Mod 2, extending pariod of agreement to 830929 & interparating administrative changes re billing, to "Environ Assessment & E18 for Low Level Waste Disposal Facilities" 4 Xawan Tempo HAQAN.T.F Division of Contracts NRC-02-82-026-05 82/10/05. 2pp 15859 178
- 8210280370 Notification of contract execution "Monitoring Use of Equipment Purchased by NRC Under Contract NRC-04-74-187," awarded to GARD inc MCDERMOTT, D Research Contracts Branch NRC-04-82-023, 82/10/07 BATSON W. MWSCARA, J Office of Nuclear Regulatory Research, Director ip 18595-228.
- --8210280374 Contract "Monitoring Use of Equipment Purchased by NRC Under Contract NRC-04-74-187." awarded to OARD. Inc SAIGH.P A Card, Inc MCRTON.K.V Research Contracts Branch. NRC-04-82-023 82/10/07. 7pp. 15857 229
- 8210280384 Notification of contract sxecution, Mod 1 to "Establish Collaborative Program Batween State & Commission to Provide Independent Heasurements of Radioactivity in Effluents & Environ " Contractor CT Dept of Environ Protection SICVIS: R M. Administrative Contracts Brench. NRC-03-73-011. 82/10/15 CDBs.L. I., ROSE.H Director's Office, Office of Inspection and Enforcement. 1p 13839:236

- --8210280397 Mod 1, deobligating funds, to "Establish Collaborative Program Between State & Commission to Provide Independent Measurements of Radioactivity in Effluents & Environ Around Selected Commissioned Licensed Activities "HEUBNER, A T Connecticut, State of GUSTAVE, R P Research Contracts Branch NRC-05-73-011 82/10/15 1p 15859 237
- 8210270104 Notification of contract execution. Mod 1, to "Use of PA Fish & Kildlife Date Base Sys in Environ Analyses for Nuclear Power Plant Licensing " Contractor Commonwealth of PA HOYLE: A Administrative Contracts Branch FIN B-8812 NRC-25-82-323 82/10/18 BASETT-H 8, JOHNSON, C Division of Datu Automation & Management Information 1p 15864 336
- --8210290131 Mod 1, adding statement that data have training will be conducted at game commission. Harrisburg & deleting Reporting Requirement 2, to "Use of PA Fish & Wildlife Data Base Bys in Environ Analyses for Nuclear Power Plant Licensing "REBELLOJE Pennsylvania, State of # Administrative Contrarts Branch FIN 8-8812 NRC-23-82-323 82/10/18 1p 15866 337
- 8210290396 Notification of contract execution "Safety Aspects of Industrial Radiography Course," awarded to Oamma Industries COLEMAN. R Administrative Contracts Branch NRC-05-82-251 BLAHA, J L : HASSELBERG, R Program Support Branch 18666 034
- --8210290398 Contract "Bafety Aspects of Industrial Radiography Course." awarded to Camma Industries * Nuclear System SHIM.P A Administrative Contracts Branch NRC-05-82-251 82/09/28 28pp 15886 055
- 8210290420 Natification of contract execution, Mod 3 to "Hydrologic Engineering Consulting Bycs for Site Bafety Reviews " Constractor ifarta Engineering Co MCLEREN.T Technical Assistance Contracts Branch FIN B-1123 NRC-03-74-308 82/10/08 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 15863 237
- --8210290422 Mod 3.deobligating unliquidated balance of contract funds, to "Hydrologic Engineering Consulting Svcs for Site Safety Reviewe" 4 Haria Engineering Co HAQAN,T F Division of Contracts FIN 8-1120 NRC-03-76-308 82/10/08 1p 15863 240
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 8206060002 Appeals dental of Füla request for segregable portions of draft NUREO-0844. "Resolution of Unresolved Safety issues A-3,A-4 & A-5 Re Bteam Cenerator Tube Integrity UDELLIR A Critical Mass Energy Project 82/06/04 DIRCKS,W J Office of the Executive Director for Operations Rpp 15668 333
- 8207050075 FDIA request for seven categories of documents re Dow Chemical Co & incineration of iou level radwaste MILEON A K Apfiliation Unknown 82/07/01 MALLETY Region 3, Office of Director ip 15748 001
- 8207110026 FOIA request for documents re St Joseph Hosp in 'NH & I-125 seed incident
 DAVIS.L S. Richards. Brandt, Hiller & Nelson 82/07/11
 NUSSBAUMER.D A Assistant Director for State Agreement
 Ip 15874 001

- E207180060 FOIA request for documents to NRC shutdown plan mentioned in weekly info rept for wk ending 810828 to SECY 81-600 to SECY 81-600A
 - SECV BI-600A CONNOR.L Doc-Search Associates 82/08/31 Division of Rules and Records 1p 15758-311
- 8207180061 FOIA request for documents re pre-implementation review of NUREO-0737.1tem II F 2 CONNOR.L Doc-Search Associates 82/09/01 Division of Rules and Records Ip 15669 096
- 8207180064 FOIA request for "Initial Guidance for Performance of Sys Interaction Analysis at Selected LURs" & "Initial Guidance on Diagraph-Katrix Analysis for Sys Interaction Studies at Selected LURs" FABRIZIO, R.F. Roston Edison Co. 92/08/30 Division of Rules and Records ip 15859 117
- 9208290088 FOIA request for SECY 82-419 re use of nonplant-specific
- NEODEMONDS FULL request for SELF METHIN THE USE OF NORMANISPESTAL
 SIMULATORS for Initial-replacement & requalification exams
 for livensed reactor operators & sentor operators
 ARMSTRONG, K A Debevoise & Liberman 82/08/29 FELTON, J M
 Division of Rules and Records tp 15760 177
- 820829089 FOIA request for records to disposal of radwasto & chemical wastes at St Albans Hosp in Gurens, NY FREEDERG, L. Youth News 82/09/07 Division of Rules and Records Ip 15774-313
- B20B29009B FOIA request for all declassified matl on Manhattan Project CHAIKEN.J A Affiliation Unknown B2/09/10 Division of Rules and Records ip 15636 205
- 8208290105 FOIA request for info re each NRC licensee in States of PA. DE & NJ FREDLAND.D R Affiliation Unknown 82/09/15 Office of Administration ip 15646 006
- 8208290108 FOIA request for RFP RS-01E-82-251 "Safety Aspects of Industrial Radiography Course" & related info MILLIANS.D T. Affiliation Unknown 82/10/01 Division of Contracts ip 15877-071
- 8209150056 FOIA request for lists of names & addresses of all NRC Bicensees in ME.VT.MA.OH.CI & MV & appropriate afcs in Agreement States of NH.RI.NY & MD PARKINSON.T W Interstate Nuclear Services 02/07/27 FELTON, J Division of Rules and Records 1p 15843 310
- 8209190057 FOIA request for NRC Annual Rept to Congress for 1981 SCHMLKE.8 Affiliation Unknown 82/09/25 FELTON.J M Division of Rules and Records 1p 19758 309
- 8209290168 Respands to FDIA request for documents prepared by NRC staff & consultants on 10CFR50.App B re GA audits of testing racilities conducted within past to yrs by NRC Related documents listed FELTON, J M Division of Rules and Records 82/08/26 PHILIPB.M H Debevoise & Liberman 2pp 15564 002
- --8209290236 Forwards QA Program Inap Rept 99900905/82-01 on Bi1229-30 No noncompliance noted HEISHMAN R F Reactor Construction Branch 82/05/26 BDUCHEY, O D Washington Public Power Supply System 2pp 15549 660

- --B005270B22 Discusses shortcomings in NUREG-0572, "Review of LERs (1973-1978)" MORER H Office of Management and Program Analysis B0/03/23 HALLER, M Office of Management and Program Analysis 3pp (1927-099
- --8006300104 Forwards BL Cohen 800324 ltr & study re design adequacy of refueling water storage tank Requests views FRALEY,R F ACRB - Advisory Committee on Reactor Sefeguards 80/04/18 DENTON,H R Office of Nuclear Reactor Regulation. Director 1p 15727 104
- --80(0240413 Submits evaluation of NUREG-0667, "Transient Response of Bl Designed Reactors" Recommends related studies be combined & specified Priority 2 items implemented by expanding en existing task in TMI action plan HATTBON.R Division of Safety Technology 80/08/08 DENION, H R Office of Nuclear Reactor Regulation, Director 43pp 15/2/149
- --8010240496 Forwards analysis & recommendations re plants w/v spismial qualified auxiliary feedwater sys Concludes that shutdown of non-seismicality qualified sys would not significantly reduce rist & proposes that more detailed study be initiated MATBON.R Division of Sefety Technology 80/09/08 EISENRUT.D O Division of Licensing 19pp 15727 241
- --Bi03030076 Furwards revision to evaluation of automatic air header de on BHRs transmitted in B01208 memo Revision restructures analysis supporting proposed change to BHR scram discharge sys
 ERNST, H.L. Assistant Director for Technology Review 80/12/12
 DENTON.H R. Office of Nuclear Reactor Regulation, Director 15pp 15727 307
- --- \$103050756 Forwards as part of NUREO--0651 review.cost benefit analyse of radiation detectors on main steam lines to provide added diagnostic capability for PUR operator during steam generator tube rupture
 LOBEL.R . VANDERNOLEN.H Safety Program Evaluation Branch
 BO/12/15 BAER.R Safety Program Evaluation Branch
 10pp
 13727 322
- --BIO30600BB Comments on proposed change to STS re battery sys per LiO1 request for review Operating plants using battery sys not covered by STB should submit for approval equivalent surveillance program Proposed STB & 80123O memo encl ERNST.M L Assistant Director for Technology Review (11/01/OU) SCHROEDER-F Assistant Director for Qeneric Projects ip 15727 332
- --BI03240272 Forwards summary of BI0128 operating reactor givents wert Next meeting scheduled BI0204 LAINA9.0 C Assistant Director for Bafety Assessment BI/0,-/()a EIESMHUT, D 9 Division of Licensing App 13728,000
- --BI03310127 Bummary of 810226 operating reactor events meeting re exwhich occurred since last meeting Next meeting scheduled for Bi031;
 LAINABO C Assistant Director for Bafety Assessment 81/Q I/O 4 EISENHUT.D.O Division of Licensing 6pp, 15728 255
- --B104240059 Discusses reactor coolant pump seal failure, in responde 800612 memo Issue will be considered potential unresolved safety issue Potential failure during station blackout may be taken up under Task Action Pian A-44 MURLEY.T E Division of Safety Technology, 81/03/27 EISENHUT.D 0 Division of Licensing 13pp 18728 336
- --Bi04290103 Discusses IE daily rept for 810406 re alternate office source interlock w/wmergency diesel generators at Unit i Licensee will propose mod to correct non-Class IE interior; preventing automatic operation of safety sus CHIRAMAL, M Director's Office, 81/04/21 Director's Office, 3pp 15729 041 24X Fiche 50-000,82/06/28,8210010008
- ---8105110396 Forwards findings & recommendations for J Elin 910115 ; re requirements of preferred or offsite power sys ASHE, F. Director's Office, 81/04/29 MICHELBON, C Director , Office 4pp 15729 070
- --Bio6100362 Comments on groblem of flow blockage of cooling water by asiatic clams (raf IE Bulletin 81-03). Problem considered potentially serious common mode failure. Quidance for proposed stepwine investigation provided BAER.R.L. Bafety Program Evaluation Branch IED-81-03 Biros MURLEY.T.E Division of Safety Technology 3pp 15787 166.
- --B107070220 Discusses Ofc of Nuclear Regulatory Research comments supporting conclusions of Mar 1981 ofc rept re safety concerns associated widtes breaks in PMR scram sys Shortcomings of analysis listed ORNSTEIN: H L. Director's Office CF-936 81/06/11 HICHEL St. Director's Office CF-936 81/06/11 HICHEL St.

NONDOCKETED HEIVIS

- --Bi07090355 Forwards Nuclear Safety Analysis Ctr/INPO rept. "Significant Event Evaluation & Info Network" & background info re review of steining & preliminary avaluation program/for comment HICHELSON. C Director's Office CF-337 81/06/22 DENTON,H R Office of Nuclear Reactor Regulation, Director 15pp 15727 222
- --B107360386 Provides info as discussed at ACRS B10507 meeting re-control sys failures that could cause or accelerate nuclear power fecility accidents Comments from plant sys unit encl ASME.F Director's Office AE00/Eii4 8i/06/24 MICHELBON, C Director's Office 5pp 15729 25i
- ~~BI0B030041 Discusses prioritization of new requirements for PHR feedwater line cracks Remedial measures development should be responsibility of industry w/approval of design changes responsibility of NRR ERNST.H & Barsty Program Evaluation Branch 81/06/30 KURLEY.T & Division of Bafety Technology 26pp 15729 290
- --310B180604 Discusses review of LERs re setpoint drift occurrences for Barton Model 288 instrument Provides recommendations for NSR ASHE,F Director's Office 81/07/20 MICHELBUN,C Director's Office 2pp 13730 054
 - 3108240273 Forwards marked-up staft Commission paper re integrated operational experience reporting sus for concurrence Draft aswance notice of proposed rulemaking & Congressional itrs and MICHELSON, C. Director's Office 81/07/15 DENTON, H R Office of MICLEAR Reactor Regulation, Director 14pp 15730 007
 - Bi08270056 Forwards concurrence on NUREO-OBOG. "Generic Bafety Evaluation re Integrity of BWR Scram Bys Piping " Any significant changes will be provided for consideration HICHELSON.C Director's Office 8/07/30 EISENHUT.D O Division of Licensing 3pp 15730 083
 - 8109100077 Advises that review of proposed draft supple to IE Bulietin 81-02, "Failure of Oate Type Valves to Ciose Against Differential Pressure," yielded no substantive comments HELTEMES, C. J. Director's Office IEB-81-02 8i/08/06 JORDAN, E. L. Division of Resident & Regional Reactor Inspection 15 18730 106
 - 6109220915 Recommends memo be prepared requesting Off of Nuclear Regulatory Research to initiate preparation of proposed rule thenge on high priority basis for General Design Criteria 4 MCRLEY, T E Division of Bafety Technology 81/08/26 VOLLMER, R H Division of Engineering 2pp 15731 03:
 - -BIO7240007 Comments on NUREG/CR-1459 Vol 2, "Reactor Bafety Btudy Methodology Application Program Ocones 3 PWR Power Plant " DENNING, R. D. Director's Office Bi/09/15 Director's Office 23p 45359*237
 - -8109250504 Comments on proposed IE circular re torque switch jumpers for safeguards svc motors Mora appropriate title could be "Torque Switch Jumpers for Befeguards Box Valva Motor Control Circuits" Marked-up circular enci MICHELBON.C Director's Office #1/08/28 JORDAN.E L Director's Office #1000-142
 - -Bii0010072 Comments on J Austin Bi0306 note re purge & vent valve assembly opereditity during expected accident conditions & potential problems should valve closure be delayed BROWNE J Director's Office 4pp 15730 273
 - --Bilo190928 Discusses 8:0620 memo re approach to sys interactions in LRS No comments were developed which would need to be assimitated into interim guidance Author ofc will offer assistance w/use of sequence coding & search procedure MICHELBON,C Director's Office, 81/09/02 MURLEY.T E Division of Bafety Technology ip 15730 202
 - --8110190933 Forwards background statement & discussion of process & policies setablished for Ofc of Analysis & Evaluation of Operational Data repts. Future repts sent for peer review will be complete & include conclusions & recommendations HICHELSON, C Director's Office 81/09/02. DAVIB. J O Office of Nuclear Material Safety & Bafeguards, Director, 3pp 15730 199
 - --Sti0220004 Forwards summery of activities re PWR primary sys voids; initiated by Ofc for Analysis & Evaluation of Operational Data DIRCKB.W J Dffice of the Executive Director for Operations 86/09/30 PALLADINO:N Commissioners 2pp 15730; 290.

- --Bil1030201 Responds to inquiry into status of BWR scram discharge vol pipe breek safety concerns NUREO-0803 contains guidance for resolving outstanding issues on plant by plant basis RUBIN.S O Director's Office 81/10/02 LEWIS.M I Affiliation Unknown ip 15730 336
- --Biii060130 Forwards draft proposed rule 4 reg guide re new LER sys.for review Comments should indicate whether improved sys wiii meet needs for operational safety data MICHELBON.C Director's Office 81/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 24pp 15730 337
- --Biiii6030B Responds to Bi0B2B memo re draft rept, "Compressed Air & Backup Nitrogen Sus in Nuclear Power Plants " Forwards comments re areas where addl work is suggested prior to final publication HELTEMES,C J Director's Office BI/10/07 ERNST,M L Assistant Director for Technology Review 3pp 15730 361
- --BiliiBOOOI Recommends comprehensive assessment of plant operating conditions to determine specific predetermined time related sequences of occurrence to emergency buses SRP should be revised re design features
 ABHE. F Director's Office BI/10/16 MICHELSON. C Director's Office 4pp 15731 049 24% Fiche 50-000.62/06/28.62100100008
- --8(11240912 Requests Div of Sys Integration review SER section on leak rate & leek rate detection criteria Conclusions should be limited to subj plants but general comments would be appreciated HURLEY,T E Division of Safety Technology 81/10/09 HATTBONR J Division of Systems integration (post 811005) Opp
- --Bli2020725 Comments on draft CRNL Bl0930 rept, "Evaluation of Events Involving Byc Water Sys in Nuclear Power Plants," per Bli020 request Beverai recommendations made w/o sufficient justification to ment serious consideration HICHELSON, C Director's Office Bl/11/10 MINNERS, W Safety Program Evaluation Branch ip 15731 117
- --Bi120305B5 Provides info re better means of coordinating & reducing duplication in acreening LERs & evaluation efforts
 Supporting info encl
 ERNBT.H L Division of Safety Technology 81/11/09
 HELTEMES.C J Director's Office 8pp 15731 107
- --8112100374 Forwards summery of NRR.NM88 & IE actions resulting from Ofc of Analysis of Evaluation & Operational Data activities, in response to recommendations contained in case studies & engineering evaluations

 LANNINO.W Director's Office 81/11/12 MICHELSON.C Director's Office 4pp 19731 118
- --8112210166 Recommends that proposed LER rule including existing & proposed reporting requirements & coordination plan be sent to Commission for consideration STELLO, V. Regional Operations & Generic Requirements 81/11/24 DIRCKS, H. J. Office of the Executive Director for Operations 1p 1272005.
- --8112210193 Requests assistance of Ofc of Nuclear Regulatory Research to complete editorial & administrative activities necessary to issue encl draft reg guide
 HICHELBONIC Director's Office 81/11/17 HINDOUE.R B Office of Nuclear Regulatory Research, Director ip 15731 202,
- --B201060003 Comments on NRC evaluation of MCAP-9558 & MCAP-9787, reaccluding asymmetric blowdown loads in plant design based on leak-before-break acceptance criteria Safety evaluation using sub; basis will require regulation changes ERNBTH L. Assistant Director for Technology Review Bi/JOHN8TON.W V. Assistant Director for Materiais & Qualif Engineering 21pp. 15731-315
- --B20113D322 Provides background info re FIN B-0445. "Analy Reliability Data From Nuclear Power Plants " Review of Bill13 in-plant data program (FIN B-0445) progress revi meeting encl DENNING:R L DITECTOR'S Office FIN B-0445 BI/I2/O2 MICHELBON.C Director's Office Spp 15731:336
- --8201150003 Forwards Chairman Palladino & Aksarna 811110 & Commission brisfing on NRG program for reactor operatio experience evaluation.
 HELTERES, C. D. Director's Office. 81/11/25 BERNERO, R. Nuclear Regulatory Research, Director 1p. 15731 309.

ij

;

41,

- --8201150004 Responds to BillO5 memo re functions of Ofc for Analysis & Evaluation of Operational Data Commission briefing should cover NRC program for reactor operational eigerience evaluation PALLADINO, N J Commissioners 81/11/10 AHEARNE, J Commissioners 1p 15731 310
- --B201150005 Suggests Commission be briefed on current & projected distribution of Ofc of Analysis & Evaluation of Operational Data resources thru FY84 AMEARIELJ Commissioners 81/11/05 PALLADING, N J Commissioners 4pp 15731 311
- --8201190040 Forwards INPO 811110 ltr commenting on draft proposed ruln to modify & codify existing LER reporting requirements Comment 1 should be considered during review of reporting requirements MICHELSON C Director's Office 81/12/11 DEYDUNG, R C Director's Office of Inspection and Enforcement 1p 15732 015
- --820119004! Comments on draft rule 10CFR50 73 re LER sys Rule would significantly reduce number of LERs filed Only significant events would be reported ZEBROSKI.E L Institute of Nuclear Power Operations B-Bi-0.306 BI/11/10 MICHELSON.C Director's Office 60pp 15732 016
- --8201190296 Concurs w/procedures for developing NRC research program, in response to NRC 811112 memo Requests that all research projects collection, storage analysis or evaluation of operational safety data be sent for review & concurrence MICHELEON.C Director's Office 81/11/24 BASECT.H S Office of Management and Program Analysis 1p 15731 246
- --B201270037 Endorses Committee to Review Generic Requirements recommendation that appropriate ofts coordinate outline of reporting requirements interrelated widnate proposed LER rule Identifies documents he reporting requirements DIRCKS;W J Office of the Executive Director for Operations B1/12/08 DAVIS.J G Office of Nuclear Material Safety & Safeguerds, Director 2pp \$5732 003
- 8202020441 "Evaluation of Events Involving Svc Water Sys in Nuclear Power Plants," draft HARIED. J A Clark Ridge National Laboratory FIN 8-0755 82/01/31 47pp 15732 107
- --B202030092 Forwards proposed Commission paper requesting approval of proposed rule which would modify & codify existing LER sys MICHELSON, C Director's Office BI/12/30 DIRCKS,W J Office of the Executive Director for Operations ip 15732-104
- --8203120016 Discusses repetitive failures of emergency feedwater flow value as reported in LERs due to valve operator hydraulic problems LERs encl IMBRO.E V Director's Office AEOD/E211 82/02/24 MICHELSON.C Director's Office 76pp 15732 308 24X Fiche 50-000.82/06/78, 82100160008
- --8203160383 ORNL/NSIG-208
 "Evaluation of Events Involving Unplanned Boron Dilutions in
 Nuclear Power Plants"
 #AGEN.E W Oak Ridge National Laboratory FIN 8-0755 82/03/31
 Office of Nuclear Reactor Regulation. Director 37pp
 15733 017
- --B203170060 Requests that review be conducted on missile protection of safety-related sys at plants to assure adequate protection and the safety-related sys at plants to assure adequate protection of safety-related systems of the safety-related

~50

t Removal Sys in

0755 82/03/31 101pp

ator

r I

- --B2040B0171 Forwards "Recommendations for Improving NRC Incident Response Technical Assessment Capability "Recommendations consistent w/NRC B20104 itr re NUREO-0845 List of recommendations encl MINNERS. M Safety Program Evaluation Dranch 82/03/04 DENTON.H R Office of Nuclear Reactor Regulation. Director DEYDUNG.R C Director's Defice. Office of Inspection and Enforcement 3pp 15733 294
- ---B2040B0260 "Recommendations for Improving NRC Incident Response Technical Assessment Capability " CONGEL,F Office of Nuclear Reactor Regulation, Director B2/02/2B 77pp 15733 297
- --8204270464 Submits engineering evaluation re-potential for air binging or degraded performance of DWR RHR sys pumps during LOCA recirculation phase Air bubble generation will not adversely affect RHR pump performance Oas release calculations end RUBINS Director's Office AEOD/E218 82/03/31 MICHEL 60% C Director's Office Bpp 15745 103
- --B205070377 Advises that proposed circular, "Contamination of Air Serving Safety-Related Equipment," reviewed Followup to [i Notice BI-38 or IE bulletin should be sent requesting info assessment of plant air supply sys ORNBTEIN.H L Director's Office AEGD/E219 82/04/01 MICHELSON.C Director's Office 2pp 15745 263
- --8210010061 Forwards review of BLW ltr rept on effect of fuel rud bowing on DNBR Proposed method acceptable for licensing calculations GRIMES.D K Division of Operating Reactors 79/07/25 VARGA , A Assistant Director for Light Water Reactors 6pp 19/27 D/O
- --8210010065 Notification of ACRS LER Subcommittee G00422 meeting in Mashington, DC Schedule & background info encl
 BATES, A ACRS Advisory Committee on Reactor Safeguards
 B0/04/14 MOELLER, D. MATHIS, W., CATTON, I ACRB Advisory
 Committee on Reactor Safeguards 3pp 15727 078
- --8210010067 Gutlines INPO & Ofc for Analysis & Evaluation of Operation Data 800311 & 20 reviews of nuclear plant operating data Related info encl
 YOUNG, 0 0 ACRS Advisory Committee on Reactor Safeguards
 B0/03/26 ACRS Advisory Committee on Reactor Gafeguards
 (8727 081
- --0210010068 "Status Rept.Ofc for Analysis & Evaluation of Uperational Data"
 MICHELSON, C Director's Office 80/03/20 10pp 15/4/ 00/
- --8210010073 Advises that ACRS 800422 meeting w/LER Bubcommitter & FARC will include discussion of status organization & planned activities of Dfc for Analysis & Evaluation of Operational Data & NRC program for collection of data MICHELBON.C Director's Office 80/03/21 BERNERO.R Probabilistic Analysis Btaff (Pre 801117) CARTER.T F Division of Fuel Cycle & Material Safety EISENHUT.D 0 Division of Operating Reactors 2pp 15727 101
- --8210010076 Confirms telcon re 800422 presentation on INPO w/AIR'S tels
 Bubcommittee Member requested to make presentation on status
 of organization & plans for future activities re use &
 evaluation of operational data from nuclear plants
 BATES.A ACRS Advisory Committee on Reactor Safeguards
 B0/04/14 LAVALLEE,W Electric Power Research Institute to
 15727 103
- --8210010089 Discusses failures of HPCI & RCIC sys subsequent to /fwa event culminating in 790627 loss of both sys 80EHNERT.P ACRS Advisory Committee on Reactor Safaguards 79/09/06 KERR.W ACRS Advisory Committee on Reactor Safaguards 2pp 15727 142 24X Fiche 50-000/82/06/28 8210010008
- --8210010119 Discusses problems w/LER data reporting & recording sys-Form is not designed for subsequent use of data for statistical analyses Draft notes and HDELLER,D H. Harvard Univ. 80/07/01 BATEB,A L. ACRB -- Advance Committee on Reactor Safeguards. App. 15727-146
- --9210010161 Discusses potential problem re sequoyah reactor pressur; nortle-supplementing 800222 memo Underclad cracks found by use of ultrasonic equipment, Addl I tems of recent origin discussed Related info encl
 DENTON:H R Defice of Nuclear Reactor Regulation, Director 80/02/28 AHEARNE.J Commissioners 9pp 15727 178 24T Fichs 50-000, 82/04/28, 8210010008

- --B210010169 Discusses evaluation of applicability of proposed new requirement of Class IE station batteries Div of Licensing should retain responsibility for further exploration of matter in course of licensing reviews
 MATTSON.R J Division of Systems Safety 80/02/28 CISENHUT, D G Division of Licensing 2pp 15727 187
- --B210010172 Forwards comments on NRC LER sys W/o enci BATES.A NRC - No Detailed Affiliation Given B0/07/22 HICHELSON.C Director's Office HALLER.N Office of Management and Program Analysis ip 15727 189
- --8210040368 Discusses NRC procedures for reviewing LERs, in response to request during 245th ACRS meeting on 800904-06 Reporting tequirements require revision to eliminate unneeded matl BATES. A ACRS Advisory Committee on Reactor Safeguards 80/09/23 ACRS Advisory Committee on Reactor Safeguards 3pp 15727 266
- --8210040371 Responds to 800523 request reaction by Dfc for Analysis & Evaluation of Operational Data on two specific LERs Ofc turrently working on more significant safety areas BATES, A NRC No Detailed Affiliation Given 80/07/23 BENDER, M NRC No Detailed Affiliation Given 1p 15727 271
- --8210040379 Bubmits review of IE insps of operating PWRs related to followup actions identified in NUREG-0138 Bensitivity analyses recommended BUTLER, H B Plant Systems Branch 77/12/28 EISENHUT, D G Division of Operating Reactors 12pp 15727 285
- --B2100403Bi Notification of ACRS LER Bubcommittee B01120 meeting in Washington DC to discuss progress toward improving NRC use of operational data BATES. A NRC No Detailed Affiliation Given B0/11/10 MATHIS, W. LAWROSKI, S., RAY, J. NRC No Detailed Affiliation Given ip 15727 304
- --B2100403B3 Notification of ACRS LER Subcommittee 801120 meeting in Mashington DC Schedule oncl Mashington DC Schedule oncl MATES.A ARC - No Detailed Affiliation Given 80/11/10 MICHELSON.C Director's Office 2pp 15727 305
- --B210040396 Submits evaluation of recommendations contained in NURLG-0631, "Evaluation of Steam Ownerator Tubo Rupture Events " Licensees should investigate other lechniques to more rapidly determine damage BAER, R L Safety Program Evaluation Branch B1/02/17 MURLEY, T Division of Safety Technology 26pp 15788-007
- --B21004041i Summary of 81031i operating reactor events meeting Assignment of followup review responsibility discussed Related info encl LAINAS, CC Assistant Director for Bafety Assessment 81/03/13 EISENHUI.D Q Division of Licensing 5pp 15728 263
- --821004041A Bummary of 81031B operating reactor events meeting LAINAS.O C. Assistant Director for Bafety Assessment 81703/24 EISENHUT.D G Division of Licensing 4pp 15728 328
- --8210049421 Summary of 810325 operating reactor events meeting LANAS.0 C Assistant Director for Bafety Assessment D1/03/26 EISENHUT.D O Division of Licensing App 19728 332
- --B210050006 Forwards draft rept, "Potential for Water Hammer During Restart of RHR Pumps for BHR Nuclear Flants " HUANO,Y S Director's Office 81/03/31 MICHRLSON.C Director's Office ip 15727 008
- --8210050007 "Potential for Water Hammer During Restart of RHR Pumps for BKR Nuclear Plants" HUANQU Director's Office 81/03/31 14pp 15729 009
- ~-B210050010 Forwards preliminary rept. "Initial Consideration of Potential for Nater Hammer in Steam Condensing Mode of RHR Bys Operation for BMR Nuclear Plants " HUNNOY B Director's Office. B1/03/31 MICHELSON.C Director's Office 1p 15729 023.
- --8210350011 "Initial Consideration of Potential for Water Hammer in Steam Condensing Mode of RHR Bys Operation for BMR Nuclear Flants" HVANO; J Director's Office 81/03/31, 11pp 15729 024
- --8210050021 Summary of 810408 operating reactor events meeting LABAR.0 C. Assistant Director for Sefety Assessment 81/04/15 EISENBUTD O. Division of Licensing 4pp 15729 035 24 X Fichs 50-000:82/04/28:8210010008

- --8210050031 Speech entitled "Assessment of Operational Safety Duta in NRC" presented at 810427-29 Fourth Symposium on Training of Nuclear Facility Personnel in Gatlinburg.TN MICHELSON.C., HELTEMES.C.J. Director's Office 81/04/27 24pp 15729 046
- --8210050035 Summary of 810422 operating reactor events meeting Related info encl LAINAS.O C Assistant Director for Safety Assessment 81/04/29 EISENHUT.D Q Division of Licensing 10pp 15729 074
- ~-8210050038 "Power Reactor Events, Jan-Feb 1981," Vol 3, Number 2 MASSARO,S A Director's Office 81/05/31 14pp 15729 084
- --B210050064 Summary of 810506 operating reactor events meeting LAINAS.G C Assistant Director for Safety Assessment B1/05/12 E[SENHUT.D Q Division of Licensing 9pp 15729 151
- --B210050075 Summary of 810513 operating reactor events meeting
 LAINAS, O C Assistant Director for Safety Assessment 81/05/18
 EISENHUT D O Assistant Director for Licensing 6pp 15729 160
- --B2100500B2 Forwards iE Bultetin B1-03, "Flow Diockage of Cooling Water to Safety Sys Components by Corbicula Sp (Asiatic Clam) & Mytitus Sp (Mussell)," for issuance on B10410 SNEEZEK,JH Division of Resident & Regional Reactor Inspertion Si/04/08 GRIER,DH Region I, Philadelphia, Office of the Director (81/03/01) D'REILLY,JP Region 2, Atlanta, Office of the Director (81/03/01) KEPPLER,J G Region 3, Chicago, Office of the Director (81/03/01) Pop 15729 169
- --02:0050087 Summary of 8:0520 operating reactor events meeting LAINAB.G C Assistant Director for Safety Assessment 8:1/05/2/ EISENHUT.D G Division of Licensing 7pp 15729 189
- --B210050093 Bummary of B10403 operating reactor events meeting LAINAS, 0 C Assistant Director for Bafety Assessment B1/06/09 EISENHUT.D 0 Division of Licensing 7pp 15729 196 24X Fiche 50-000, 82/06/28.8210010008
- --B210050116 Forwards comments & questions re GE response to Ofc For Analysis & Evaluation of Operational Data safety concerns w/ pipe breaks in BHR scram sys, in response to D Eisenhut 810603 request MICHELBON, C Director's Office 81/06/14 DENTON-H R Office of Nuclear Reactor Regulation, Director 2pp 15729 203
- --B210050124 Summary of B10410 operating reactor events meeting LAINAB, 0 C Assistant Director for Safety Assessment 81/06/1/ EISENHUT.D O Division of Licensing 5pp 13727 217 24X Fiche 50-000, B2/06/28, B210010008
- --8210050139 Summary of 810617 operating reactor events meeting LAINAB-0 C Assistant Director for Safety Assessment 81/06/23 EISENHUT.D 0 Division of Licensing 4pp 15729 246 247 Fiche 50-000.82/06/28.8210010008
- --8210050155 Forwards summary of NUREG/CR-1682. "Electrical ref insulators in Reactor Accident Environ." used as ref in Ofc of Nuclear Regulatory Research comments on safety concerns re pipe breaks in BHR acram sys EL-ZEFTAHY. M Director's Office 81/06/26 Director's Office 5pp. 15727-285
- --8210050164 Summary of 810708 operating reactor events meeting Noxt meeting scheduled on 810715 LAINAB,0 C Assistant Director for Safety Assessment B1/0//13 E18ENUT,D 0 Division of Licensing Bpg 15727 355 247 Ficha 50-000,82/06/28,8210010008
- --8210050181 Discusses plans for managing NRPD8 per 810708 tellon Data & repts from data base will continue to be made available to NRC Mesting scheduled on 810721 HILKINSON.E P Institute of Nuclear Power Operations 81/07/09 DIRCKB, W J Office of the Executive Director for Operations 5pp 1870 And
- --82i0050i90 Summary of Bi0723 operating reactor events meeting Next meeting scheduled for Bi0805 LAINAG.0 C Assistant Director for Safety Assessment Bi/07/29 EISENHUT, D 0 Division of Licensing Spp 15730 075 24X Fiche 50-000,82/06/28,82i0010008
- --8210050200 "Power Reactor Events, Har-Apr 1981: " Vol 3, Number 3 MASBARO, 8 A Director's Défice 81/08/31 18pp 15730 086
- --8210050209 "Operational Safety Data Review," Chapter 0515 d Director's Office. 81/08/12 8pp 15730 107

- --82(00502)2 Summary of 810806 operating reactor events meeting Related info enc! Next meeting scheduled for 8208)2
 LAINAS.OC Assistant Director for Safety Assessment 81/08/10
 EISENHUT, DO Division of Licensing 16pp 15730 115 24X
 Fiche 50-000,82/06/28,8210010008
- --8210050217 Summary of B10819 operating reactor events meeting Status of followup review responsibility assignments ent! LAINAB.O C Assistant Director for Safety Assessment 81/08/24 EISENHUT.D O Division of Licensing 5pp 19730 123 24% Fiche 50-000.82/06/28.821001000B
- --8210050403 Forwards draft rept entitled "Characteristics of LEH Reporting Sys " RYDER, C ACRS - Advisory Committee on Reactor Safeguards 81/08/31 ACRS - Advisory Committee on Reactor Safeguards ip 15730 146
- --8210050407 Draft rept entitled "Characteristics of LER Reporting Sys" RYDER.CP. ABBOTT.E C , MCCRELESS.T O ACRS -- Advisory Committee on Reactor Safeguards 81/08/28 43pp 15730 147
- --B210050424 Advises that SECY B1-494 will be discussed at B10709 subcommittee meeting on evaluation of LERs outTISCHREIBER ACRS Advisory Committee on Reactor Safeguards B1/09/02 MATHIS.W. WARD.D. MCELLER, D. ACRS Advisory Committee on Reactor Safeguards 2pp 15730 203
- --8210050424 Provides presentation schedule for 810909 subcommittee meeting for evaluation of LERs dulTTSCHREIBER ACRS Advisory Committee on Reactor Safeguards 81709702 (HICHELSON.C Director's Office 3pp 15730 227
- ~-8210050434 Comments on LER Subcommittee 810909 meeting Ofc for Analysis & Evaluation of Operational Data could benefit from analytical models used in other fields & other stages of data analysis RYDER, C. ACRS Advisory Committee on Reactor Safeguards 81/09/11 MATHIS-W M. ACRS Advisory Committee on Reactor Safeguards 2pp 15730 238
- --B210050436 Discusses methods for preventing recurrence of LERs Attention should be given to matt suppliers & architect engineers as LER originators MUELLER.D W ACRS - Advisory Committee on Reactor Bafeguards B1/07/06 MATHIB.W ACRS - Advisory Committee on Reactor Safeguards 1p 15730 240
- --82100\$0473 Forwards draft proposed rule re integrated operational experience reporting for comment HICHELBON, C. Director's Office 81/09/IB ROSSIN, D. Affiliation Unknown 9pp 15730-291
- --B210050478 Forwards SECY-B1-505 re systematic assessment of licensee performance, first rept on licensee assessments W/o encl licensee facility ratings for operating power reactor licensees & CP holders

 HAJDR.R. ACRS Advisory Committee on Reactor Safeguards

 B1/09/21 ACRS Advisory Committee on Reactor Safeguards ip

naru of 810915 operating events meeting List of

ector for Safety Assessment 81/09/21 Licensing 9pp 15730 263

> Zudans comments on LER sys tee on Reactor Bafeguards Advisory Committee on Reactor

- --8210050496 Comments on LER reporting sys LER cover sheets contain misleading into re facility in question LERs should not be grouped in packets w/o appropriate subj heading MDELLER,D W ACRB Advisory Committee on Reactor Safeguards 81/09/19 MAJOR,R ACRS Advisory Committee on Reactor Safeguards 1p 15730 278
- --B210050514 Topical rapt evaluations of Revision 2 to MCAP-955B, "Mechanistic Fracture Evaluation of Reactor Coolant Pipe " & MCAP-9787, "Tensil & Toughness Properties of Primary Piping Weld Metal for Use in " * NRC No Detailed Affiliation Given 62/04/28 24pp. 15731 005

- --B210050520 Summary of Gii007 operating reactor events meeting Blatus of previous assignments encl LAINAS.0 C Assistant Director for Safety Assessment Gi/i0/i3 EISENIUT.0 0 Division of Licensing 9pp 15731 033 24X Fiche 50-000, 82/06/28, 8210010008
- --8210050533 Summary of 811021 operating reactor events meeting list of attenders, events discussed & assignments encl LAINAS. 0 C Assistant Director for Safety Assessment 81/10/27 EISENHUT, D 0 Division of Licensing opp 19731 053 24x Fiche 80-000, 82/06/28.8210010008
- --8210050537 Discusses proposed rule dealing w/LER sys Features will include compatibility of sys w/10CFR50 72
 MAJOR.R ACRS Advisory Committee on Reactor Bafeguards 81/11/02 MATHIB.W M ACRS Advisory Committee on Reactor Sefeguards 19 19731 071
- --8210050542 Forwards info re selection of LERs worthy of AD rept at#th*
 MDELLER, D H ACRS Advisory Committee on Reactor Bafeguards
 81/10/24 MAJOR.R ACRS Advisory Committee on Reactor
 Bafeguards 2pp 15731 092
- --8210060001 Summary of 811028 operating reactor events meeting i ist of attendees. Events discussed & review assignments encl
 LAINAB. G C Assistant Director for Bafety Assessment Bi/11/0 J
 ETSENHUT. D Q Division of Licensing 5pp 15731 074.
- ~-82100∆0005 Revised draft rept, "Compressed Air & Backup Nitrogen Bys Nuclear Power Plants" HAGEN,E W Clak Ridge National Laboratory. FIN B~0755 U~7405-EN9~26 B1/11/13 NRC ~ No Detailed Affiliation Gaven BOpp 15731 122
- ~~BR1006000B Forwards background mat! for 81120B reactor operations subcommittee meeting on proposed rule & reg guide ro LER ruleomaking
 MAJOR.R ACRS Advisory Committee on Reactor Safeguards
 81/11/19 MATHIS.W M ACRS Advisory Committee on Reactor Safeguards
 1p 15/31 205
- ~-8210050009 Draft Reg Quide 1 XXX.Revision 3, "LER 8ys " * NRC - No Detailed Affiliation Given 81/11/16 22pp 18731 215
- --8210060026 Discusset Zudans comments he ACRS LER subcommittes the CVU; meeting Change in connectivity function of sequence coding proposed Fundamental change involved MAJOR.R ACRB Advisory Committee on Reactor Safeguards B1/11/20 MATHIS.W M ACRS Advisory Committee on Reactor Safeguards 1 15731.237
- --8210050042 Bummary of 811112 operating reactor events maeting titt ; attendees: events discussed & review assignments enci LAINAB. G C Assistant Director for Safety Assessment 01/11/2; EIBENHUT. D G Division of Licensing 6pp 18731 240
- --8210060068 Discusses Sillo7 itr re LERs & AO repts per SECY Of Sold SECY 81-602 Meeting to discuss proposed LER rule scheduled for Sil208.

 MAJOR.R. AORS Advisory Committee on Reactor Safeguards St/1/24 MOELLER.D.W ACRS Advisory Committee on Reactor Safeguards. Sepp 15731 247
- ~-8210060079 Requests info re-notification of ACRB concerning Propers rule change for immediate notification of significant events per BECY 81-598 MDELLER:D W. ACRS - Advisory Committee on Reactor References B1/11/07. MAJOR:R ACRB - Advisory Committee on Reactor Befeguards 19, 18731 249
- --8210060084 "Background Reading for Discussion of Program & Mathods Screening & Analysis of Operational Info at NRC," presented to IAEA Advisory Group on 811123-27.
 HICHELBON.C Director's Office 81/11/23 25ps 15731 284
- --8210060100 Summary of 811202 operating reactor events mesting 4 and attendees, events discussed & status of previous assignments encl.

 LAINABLO C Assistant Director for Safety Assessment BIF1270.
 EISENHULD 0. Division of Licensing. Spp 15731 345
- --8210060363 Bummary of B11216 operating reactor events meeting the attendees events discussed & status of assignments ento LAINAS-0 C Assistant Director for Bafety Assessment B1/12/20 EISENHUT:D O. Division of Licensing.
- --8210060369 "Power Resector Events, Jul-Aug 1981, " Vol 3, Number 5
 MASSARD, 8 A., RIZZD, J. Director's Office. 62/01/31 14ps

- --B210Cc03B1 Discusses Zudans input re sequence coding & search sys, per B10930 medio Implementation of approach would require major revision to sys HELTEMES: O Director's Office B1/10/22 MAJOR, R ACRS --Asvisory Committee on Reactor Eafeguards ip 15731 239
- --8210050427 Forwards comments re potential consequences of boad drop in LMRs.providing understanding & background of scope of current regulatory review for accidents EL-ZEFTANY. B Director's Office AEOD/E205 82/02/16 Director's Office 13pp 13732 281
- --8210060449 Responds to request for review of LERs on steam generator leaks Distribution of problems from 1976 to 1981 provided RYDER.C.P ACRE - Advisory Committee on Reactor Safeguards 82/03/05 MATHER ACRE - Advisory Committee on Reactor Safeguards 3pp 15745-026
- --8210060452 Comments on "Learning Function in Nuclear Reactor Operation & Implications for Siting Policy " Analysis does not support finding that adding reactors to existing sites enhanced learning MACEUDY, J. A. ACRB Advisory Committee on Reactor Bafeguards 82/03/15 COTTRELL, W.O. Oak Ridge National Laboratory 5pp. 15475-045
- --B21007000B Responds to B20324 request for assessment of reactor coolant year study General rept on all mechanisms of bolting disperration in progress Visual insp of reactor coolant sys bolts recommended HANAUER, B H Division of Bafety Technology B2/04/05 EISENHUT, D O Division of Licensing 5pp 15745 265
- E210040357 "Should Addi Independent Power Source Be Required for CHR Sys " ATEF1.B , LINER.R , HUOHES, A Science Applications, Inc MRC-03-02-096 B2/07/15 10pp 15597 280
- E210040350 Responds to FOIA request for BECY-B2-72B & BECY-B2-72C rutuerSinated program for steam generators Documents available in PDR FELTON, J M Division of Rules and Records 82/09/27 FORTING, K C Lowenstein, Neuman, Reis, Axelrad & Toll ip 15597 291
- --8204200390 SECY-82-0728
 Responds to Chairman 820301 request for short-term actions rs performance of steam generators Comprehensive water chemistry criteria for steam generators should be implemented to Office of the Executive Director for Operations 82/04/03 2pp. 15597 292
- --8205270507 SECY-B2-072C
 Advise: Commission of results of 820428 meeting w/industry re-proposed coordinated program for steam generators.
 Proposal in SECY-82-72A re-formal structural organization such as policy group & steering committee rejected DIRCKS.W J Office of the Executive Director for Operations 82/05/17 3pp 15557 274
- --8205270526 Advises of legal difficulties re coordinated steam generator research program proposed in SECY-82-72A Reconsideration of program organization suggested in light of Federal Advisory Committee Act
 MALSCHING Office of the General Counsel 82/05/05 AHEARNE, J
 Commissioners, 4pp. 15597 297
- 8210340365 Responds to appeal re denial of FOIA request for four affidavits concerning allegations of improper const practices at facility Forwards requested info. Page 4 of E Orave affidavit withheld (ref FOIA Exemption 7).

 DIRCKE, W J. Office of the Executive Director for Operations.
 82/09/24. BTEPTOE, P P. Isham, Lincoln & Beale. 2pp. 15597 303.
- 8210350430 Responds to FOIA request for correspondence between Nuclear Assurance Corp & NRC re 1982 irradiated fuel shipments tetween Ontario & NC. Forwards App A documents. App B decuments withheld (ref FOIA Exemption 3). FRITONLUM Division of Rules and Records 82/08/17. RESNIKOFF, M Council on Economic Priorities 3pp. 15626 172
- --8201050245 Requests approval of alternate routes for planned irradiated fuel shipments from Chalk River Nuclear Labs to DDE Savenneh River facility, Date of arrival deleted, DANEGE,F,L. Nuclear Assurance Corp. 19955. 81/11/13. Division of Safeguards Spp. 15626; 201
- --9210050439 Provides addl info re initial shipment of irradiated fuel per 811110 ltr.Shipment will arrive at destination on 811121. DAMESE:F.L. Nuclear Assurance Corp FLD/81/81/ETS. 81/11/17 Division of Emergency Prepar

- --B210050467 Advises of plans for series of spent fuel shipments from Chalk River to DOE Savennah River Plant DANESE, FL Nuclear Assurance Corp FLD/82/84/ETS 82/07/02 00DY: A Region i. Office of Director 1p 15626 232
- --8210050471 Corrects 820702 prenotification of planned series of irradiated reactor fuel shipments from Chalk River to Sevanneh River Plant Fort of entry is Derby Line, VI DANESE, F L Nuclear Assurance Corp FLD/82/85/ETS 82/07/07 00DY: A Region 1. Office of Director 10 15626 233
- 8210030512 Responds to FOIA request for insp & enforcement records is accidents of F Lauson & H Dillon at facility. Union Electric CP & other NRC safety mails or nanuals Forwards two documents Remaining records available in PDR FELTON, J M Division of Rules and Records 82/09/21 1002, M V 1900. V M 299 15626 244 24% Fiche 50-000, 82/09/21, 8210030512
- ~-B210050918 Region 3 daily rept for 780807 * Region 3. Chicago, Office of the Director 78/08/07 1p 15626 246 244 R4x Fiche, 50-000, 82/09/21, 8210050312
- --B210050522 PND-III-78-062 on 780804, two workers seriously injured whin hit by support girder for polar crane rail OSHA notified BCHWEIBINZ, E.R. Region 3. Chicago, Office of the Director 78/08/04 ip 15626 247 24X Fiche 50-000, 82/07/21, 8210050512
- 8210050562 Responds to FOIA request for SECY-75-588, 5889, SECY-R-74-64, SECY-81-600A & SECY-81-622A Document review in progress FELTON J. M. Division of Rules and Records 82/09/17 CONNOR.L. Doc-Search Associates ip 15626
- 8210060403 FOIA request for itrs from Ohmart Corp & TX Nuclear justifying proprietary claims re FOIA 82-A-12 CQLLINS:P L Research Counsel of Nashington 62/09/03 DIRCKS:W J Office of the Executive Director for Operations ip 19636-235
- 8210060406 Responds to FOIA request for live from Ohmart Corp & 4% Nuclear justifying proprietary claims re FOIA 82-A-12 Forwards documents.
 FELTON.J M Division of Rules and Records 82/09/22 COLLING,P L Research Counsel of Washington ip 15636 236
- --8210060411 Responds to 820630 request for info re FGIA 82-263 All info contained in general license rept considered proprietary Any rept dtd earlier than Apr 1976 may be released w/o significant competitive harm HENDRICKIN O Texas Nuclear Div (subs of Ramsay Eng Co) 82/07/09 FELTON JM Division of Rules and Records 2pp 13636 238
- --8210060415 Responds to 820630 ltr re Ohmart Corp quarterly regts listing devices distributed to general licenses Regts are always treated as confidential Disclosure would harm competitive position CODK.H L. Ohmart Corp. 82/07/13 FELTON.J M. Division of Rules and Records. 2pp. 15636-240.
- 8210060419 Responds to FOIA request for SECY-82-728 & SECY-82-72C recoordinated program for steam generators Document review in progress.
 FELTON, J M Division of Rules and Records, 82/09/17 FORTING, K C Lowerstein, Neuman, Reis, Azelrad & Toll 1p 15636 255
- 8210060429 Forwards CJ Johnson FOIA request for rept to EPA. "Pu & Human Tissues Re Smoking, Age, Residence Near Rocky Flats & Eastern CO " Response requested. FELTON, J M Division of Rules and Records B2/09/27 OREEN. J. B Environmental Protection Agency ip 15634 209
- 8210060434 Responds to FDIA request for all declassified matl un Manhattan Project NRC has no documents subj to request FELTUN, J M Division of Rules and Records 82/09/15 CHAIKEN, J A Affiliation Unknown. ip 13636.206
- BRIOCAD442 Responds to FOIA request for input to Chapter 7 & App J of FEB & suppl to CRER. Documents listed in App A available in PDR App B documents completely withheld advice & opinions (ref FOIA Exemption 5) FELTON, J H Division of Rules and Records, BRIOB/R4 WEISB, E R Harmon & Weiss 4pp. 15636 040.
- 8210070007 Responds to FDIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FDIA Request 81-313, Forwards documents listed in App B FELTON, J. H. Division of Rules and Records 82/08/10. LONG, D. J. Hinthrop, Stimeon, Putnam & Roberts. 9pp 15445-063 24X Fiche-50-000, 82/08/10, 8210070007.

- --7812200285 Summariles steam generator tube leak on 780920 & Insp Leak rate reached 560 gpd at 5 00 AM, caused by two tubes w/cracks located w/in thickness of tube sheet & one tube w/cracks located w/in thickness of tube sheet & one tube w/cracks plug General cause plant conversion to AVT KOONAM, V S Engineering Branch (Pre 791030) 78/12/12 GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 2pp 15645 244 24X Fichs 50~000.82/09/10,8210070007
- --7909280105 Discusses steam generator tube leak & inservice insp Steam generator caused by deep crevice cracking of three tubes within tube sheet Hot leg tube tests indicated 52 tubes w/deep crevice cracking in eccess of 50% plugging limit NOBNAN, V S Engineering Branch (Pre 791030) 79/08/17 FISEINUTL 0 G Division of Operating Reactors 3pp 15645 254 24% Fiche 50-000, 82/08/10.8210070007
- --8201210107 Advises that utils should be informed that impact of tube plugging should be evaluated for all SAR Chapter (5 events & results of evaluation submitted when requesting approval of new steam generator tube plugging limit POVAK.TM Assistant Director for Operating Reactors 81/12/29 Assistant Director for Operating Reactors 200 15645 281
- --E203190034 Forwards State of IL Poliution Control Board 820127 it: & delineates areas of responsibility re response LARMAS, G.C. Assistant Director for Safety Assessment 92/02/09 JOHNSTON: H.V. Assistant Director for Materials & Qualifications Engineering (p. 15645-124
- --8203260003 Recommends that STS limits for coolant activity & sampling requirements be incorporated into remaining operating plant Tech Specs w/other substantive change requests lodine dose problems can be avoided by limiting coolant MOUSTON, R W Assistant Director for Radiation Protection 82/03/04 NOVAK, I Assistant Director for Operating Reactors 2pp 15645 285
- --B210070135 Bevil rept input re Ginna 820125 steam generator tube rupture event MRC 16th monthly status rept to Congress re TMT-1 restart encl # NRC No Detailed Affiliation Given 82/03/11 3pp 19645 128 24X Fiche 50-000 B2/08/10.8210070007
- --8210070196 Distusses intervice inspiprograms for PMR steam generator tubing to monitor conditions of tubing in all PMR operating plants Licensees w/o steam generator tube surveillance program should be required to supplified Specs SCHROEDER: F. Division of Technical Review (MRR-1975 only) 75/04/21 G[MBUSSDA Division of Reactor Licensing (NRR-1975 only) 3pp 15645-207
- --8210070198 Recommended Tach Specs 3 4 5 & 4 4 5 re steam generator tubing surveillance

 * Division of Technical Review (NRR-1975 only) 75/04/21 20pp 19465 210
- --8210070205 Submits summary of findings & comments to facility steam generator tube leak incident & insp results contained in Annual Operating Rept 1976 Recommends that licensee be requested to submit insp program for next scheduled insp SHAOLL C Engineering Branch (Pre 791030) 77/07/25 EISENBUT. B 0 Division of Deprating Reactors Ppp 15645 235 24X Fichs 50-000, 82/08/10, 8210070007
- --8210070235 Agrees w/801028 memo suggestions All assistant directors in Dix of Licensing requested to follow same approach EISENHUT.D Q Division of Licensing E0/11/07 MARTIN.J D Division of Waste Management ip 15445-290
- 8210070029 Partial response to FOIA request for documents re CRBR CIS & all comments evaluations & documents from BNWL re EIS Forwards documents listed in App A FELTON, J M Dayiston of Rules and Records 82/07/16 WEISS, E R Harmon & Keiss 8pp 15648 004
- --B210070123 Forwards updated responses to comments on 1976 DES.

 NUREG-0137 Te safeguards & fuel cycle Info Te raduaste
 shipments.disposal sits & licensed burial site included
 LOMENBERG. H. Office of Nuclear Material Safety &
 Safeguards. Director CRUR 82-49 82/06/15 LEECH.P. Clinch
 River Breeder Reactor Program Office 15pp 15648 073

- --B210070421 Notifies that no physical security concerns exist re expert of low enriched U to Japan under export license application KENN-1896 SHERR.T 9 Material Control & Accountability Development Branch 81/12/17 DEVINC.J B Assistant Director for Export/Import & International Safeguards 1p 15647 007
- --821007042& Recommends that N498 provide representative to join State Dept entourage to Canada on 820112-14 to exchange technical info on application of IAEA safeguards to on-load reactors WIRFSL NRC - No Detailed Affiliation Given 82/01/07 CHAPELL, D NRC - No Detailed Affiliation Given 1p 15647 COU
- --8210070428 Forwards summary of Interagency Steering Group 820106 meeting w/D/c of Intl Programs & NMS8 re action plan activities. US program for technical assistance & resource allocation to IAEA DIRCKS, W J Office of the Executive Director for Operations 82/01/19 PALLADING, N , GILINSKY, V , ERADFORD, J Commissioners App 15647 009
- --8210070431 Requests that summary of Interagency Steering Group D20165 meeting be forwarded to Commission No major decisions reached SHEA.J R Office of International Programs, Director 02/01/19 DIRCKS.W J Office of the Executive Director for Operations 1p 15447 014
- --8210070434 Notifies that no physical protection concerns exist re export of highly enriched U to Japan Update on status of negotiations requested SHERR.T S Haterial Transfer Safeguards Licensing Branch 82/02/09 DEVING.J B Assistant Director for Export/Import & International Safeguards 1p 15647 015
- --8210070436 Notifies that no physical protection concerns exist 18 applications to export low enriched U to Japan under Licenses XBNM-1723,1925,1928 & 1896
 SHERR.T 8 Material Transfer Safeguards Licensing Branch 82/02/23 PETERSON.M R Assistant Director for Export/Import & International Safeguards 1p 15447 016
- --8210070441 Forwards response to Bill29 & 30 ltrs re IACA safeguards & Creceives little specific info concerning intl safeguards Classified info received through briefings PALLADING, N J Commissioners 82/03/02 OTTINGER, R L House of Rep , Energy & Commerce 12pp 15647 017
- --B210070445 Forwards Intl Bafeguards & foreign physical sacurity fewlew for comment & inclusion in draft Commission paper re proposed export of highly enriched U to Hest Gormany & Ewitzerland BURNETT-R F Division of Safeguards B2/03/08 SHEA-J R Diffixe of International Programs: Director 2pp 13647 036
- ---8210070447 Notifies that no physical protection concerns exist reapplications to export low enriched U to Japan, Inforquested restatus of facility attachment to Fukushima I. Unit 4

 SHERR.T S Material Transfer Safeguards Licensing Dranch 82/03/11 PETERSON,MR Assistant Director for Export/Import & International Safeguards lp 15647 038
- ---8210070448 Speech entitled. "Nuclear Common Sense," presented at D20, AIF fuel cycle conference KENNEDY,R T President of US & Executive Offices 82/03/22. I3pp 15647 039
- --8210070451 Forwards trip rept of 820319-26 visit to Vienna.Austria foworking consultants session on IAEA safeguards effectiveness assessments
 BRACH.E W Office of International Programs, Director 02/04/08
 CREEN.L Brookhaven National Laboratory App 18647 052
- --8210070454 Forwards transcript of Bubcommittees on Intl Broursty & Scientific Affairs & Intl Economic Policy & Trade Committee on Foreign Affairs 820318 hearing re IAEA safeguards Edited comments requested by 820402 KAMMERER.C Office of Congressional Affairs 82/03/30 PALLADING.N , OILINSKY.V , AHEARNE, J Commissioners ip 15647 057
- ---8210070458 Transcript of Subcommittees on Intl Becurity & Scientafic Affairs & Intl Economic Policy & Trade & Committee on Foreign Affairs 820318 hearing in Washington DC re IACA safeguards improvements
 4 House of Rep 82/03/18 110pp 15647 038

- --8210070464 Discusses plan established for fulfilling Ofc of Executive Director for Operations request for info re NRC efforts to improve IAEA safeguard's Accuracy of info reported by states to IAEA needs major improvement WIRFS.L NRC NO Detailed Affiliation Olven 82/05/06 BURNETI.8 NRC No Detailed Affiliation Given 4pp 15647 171
- --B210070467 Forwards draft IAEA guidelines for nuclear facility design, incorporating design features to facilitate implementation of intl safeguards Comments requested by B20021
 SHERR.T B Haterial Transfer Safeguards Licensing Branch
 B2/05/07 ERICKSON.R A Power Reactor Safeguards Licensing Branch
 Branth EVANSIL J Fuel Facility Safeguards Licensing Branch
 COMEN.K Defice of International Programs, Director 44pg
 13647 175
- ~~B21007046B Forwards memo for Commission providing summary of significant NRC & Executive Branch efforts to improve IAEA rafeguards H/o encl SHEA, J R Office of International Programs, Director 82/05/21 DIRCKS.W J Office of the Executive Director for Operations 19 13647 223
- ~~ P210070471 Forwards draft Commission paper re application for license to export highly enriched U to France Comments & license conditions specified in Encl 2 should be included in license BURNETT, # F Division of Bafeguards B2/05/25 GHEA, J R Office of International Programs, Director 3pp 15647 224
- --B210070473 Comments on DDE analysis re retransfer of spent fuel assemblies from Japan to United Kingdom & France for reprocessing Advanced notification required if fuel shipment enters US territorial waters SHERR, T.S. Material Transfer Sefeguards Licensing Branch B2/05/03 ZIMMERMAN.J V. Assistant Director for Export/Import & International Safeguards
- --8210070475 Summarizes 820607-08 meeting w/IAEA in Dethesda, MD or lAEA safeguards agreement Problems associated w/US reporting of muclear mati info to IAEA discussed SERRITS Division of Safeguards 82/06/09 DAVIS, J G Diffice of Nuclear Material Safety & Safeguards Director 2pp 15647 229
- --B210070478 Discusses corrective actions re reporting transactions & inventories for US facilities selected by IAEA Bys to provide correction data to IAEA in acceptable format should be developed SHERR.I S Material Transfer Safeguards Licensing Branch B2705718 DDYLE.G J Union Carbide Corp 2pp 15647 231
- --9210070480 Forwards inti safeguards & foreign physical security review sections for inclusion in Commission paper re retransfer of low enriched U feel assembliss from Federal Republic of Giranny to Peru SKERR, T. 9. Material Transfer Safeguards Licensing Granch 82706/16 ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 2pp 15647 233
- ~8210070482 Bubmits summary of activities to support interagency efforts to strengthen IAEA safeguards during first half of CYB2
 BURKETIR F Division of Safeguards B2/07/13 DAVIB, J 0
 Office of Nuclear Material Safety & Safeguards, Director 29pp
 15647 235
- --9210070484 Notifies that no physical protection concerns found reapplication for license to export single reload of low enriched V to Japan SKERR.T 9 Material Transfer Safeguards Licensing Branch 82/06/23 ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards ip 19647 269
- --82100704B5 Forwards list of priorities activities for FYR3 per F Houcks
 820524 memo,
 CDHEN.K D Assistant Director for Export/Import & International
 846894F45 82/07/19 Assistant Director for Export/Import &
 International Safeguards 3pp 15647 264
- --82:0070486 Notifies that no special physical protection or intl safeguerds concerns identified re Amend 1 to application to export low enriched U to Malaysia SHERRIS Haterial Transfer Bafeguards Licensing Branch 82/06/28 ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards 1p. 15647-267.
- --6210070468 Speech entitled "Nuclear Bafeguards Challenges & Realities," presented at 22nd annual meeting of Inst of Nuclear Hatls Mgt KRAYLER:H B International Energy Associates, Ltd 82/09/10 279p 13647 268

- ~-8210070489 Notification of 820906-10 consultant meeting to discuss draft guidelines for design features to facilitate intl safeguards Draft guidelines enc!
 SANDERS.K E Office of Nuclear Haterial Safety & Safeguards, Director 82/06/29 HQUCK,F NRC No Detailed Affiliation Qiven SHERR,T Office of Nuclear Material Safety & Safeguards, Director COHEN,K Office of International Programs, Director 68pp 15647 297
- 8210070417 Responds to FOIA request for info re each NRC licensee in States of PA.DE & NJ Forwards three computer printouts furnishing names & addresses of licensees Info re licensee this executive officers not maintained FELTON-J M Division of Rules and Records 82/09/27 FREDLAND-D R Affiliation Unknown 1p 15446 007
- --B210070423 Computer printputs listing names & addresses of NRC licensees in States of NJ.DE & PA 4 NRC No Detailed Affil(ation Oiven B2/09/24 210pp 19546 008
- 8210080010 Add1 FD1A request re minor additions & deletions to B20403 request for 19 categories of info on nuclear reactor events & safety problems
 UBELLIR A Critical Mass Energy Project 82/06/11 FELTON, J
 Division of Rules and Records ip IS665 022
- B210080015 Add response to FDIA request for 19 categories of into re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B campletely withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 9pp 15645 027 24X Fiche 50-000, 82/07/12, 8210080015
- --8011060346 Discusses licensee responses to NRC request to commit to interim position re Generic Item B-24 venting & purging containments while at full power Plants meet interim position & existing TAGs should be closed out REEVER, E.A. Operating Reactors Branch | BO/08/25 Operating Reactors Branch | JOpp | J5668 | J55
- --8104080309 Std order for DOE work "Program for Cost Estimation for Proposed Safaty Requirements," issued to ID Operations Ofc Statement of work encl GRENIER, D.L. Office of Nuclear Reactor Regulation, Director | IN A-6452-1 20-81-165 81/03/12 App 13665 183
- --BI052B0476 Requests that regions confirm licensee submittal of rept for satisfactory implementation of Item 4 of 1E Bulletin 79-26. Revision 1
 JORDAN, E. L. Division of Resident & Regional Reactor Inspection IEB-79-26. Bi/05/18 GRIER, B. H. Region 1. Philadelphia, Office of the Director (BI/03/01) SEYFRIT, K. V. Region 4. Dallas. Diffice of the Director (BI/03/01) ENGELECN. H. Region 5. San Francisco, Office of the Director (BI/03/01) 1p 15668 130 24X Fiche 50-000, 82/07/12, 82(0080015)
- --BI06220159 Supports efforts in resolving purgs valve leakage & operability issues Incorporation of leak testing position into Tech Specs should assure leakage integrity of containment BAER, R.L. Reactor Engineering Branch Si/06/09 DUTLER, H.R. Containment Systems Branch Spp 15668, 153
- ~-8106220168 Forwards proposed IE bulletin identifying potential Bafety concern re leakage of reactor bidg purge valves O'REILLY'U P. Region 2. Atlanta: Office of the Director (81/03/01) 1EC-77-11 81/03/20 SNIEZEK, J Director's Office 5pp 18668 167
- --B107170126 Comments on proposed IE bulletin re leakage of reactor bidp purge valves Issuence not merited for reasons indicated Generic Issues B-20 & B-24 provide assurance of increased surveillance testing & reduced excessive leakage SNIEZEK.J H Director's Office IEC-77-11 81/07/01 078EILLY.J P Region 2, Atlanta, Office of the Director (81/03/01) 2pp 13668,131
- --8108210025 Forwards draft suppl to IE Bulletin 81-02, "Failure of Onte Type Valves to Close Against Differential Pressure," for review & comment JORDAN, E. L. Director's Office 81/07/23 ORIER, B. H. Region 1, Philadelphia, Office of the Director (81/03/01) O'REILLY, J. P. Region 2, Atlanta, Office of the Director (81/03/01) KEPPLER, J. Q. Region 3, Chicago, Office of the Director (81/03/01) 2pp 15668 181

- 1203040536 Comments on Bi1218 corrections to facility assessment contained in NUREG-0834 re hearings & discussion of sustematic assessment of license performance Revision to NUREC inappropriate Issue closed MOSELEY, N C Systematic Assessment of Licensee Performance Review Group 82/01/04 MESBMAN, R H NRC - No Detailed Affillation Given 1p 15668 256 24X Fiche 50-000.82/07/12.8210080015
- 203040538 Forwards performance element summary for Jul 1979-June 1980 in response to ABLB request for testimony on systematic assessment of license performance in general & facility assessment of license performance in general & facility assessment in particular assessment in particular assessment in particular Enforcement 81/12/18 MOSELEV. N C Systematic Assessment of Licensee Performance Review Group 2pp 15668 254 24X Fiche 50-000,82/07/12.8210080015
- 1204120487 Discusses problems w/water in fuel oil tank Case does not CONSIDERATION DISCUSSES PROFESSION WIGHER IN THE BIT TANK LASE GOES IN HAVE GENERIC IMPlications TREMAIN N Director's Office 82/04/06 MICHELSON.C Director's Office Spp 15665-036 24% Fiche 50-000.82/07/12: 8210080015
- 1205190428 Forwards engineering evaluation rept. "Inadvertent Loss of Reactor Coolant Events at Sequoyah Nuclear Plant, Units 1 & 2 " Rept contains recommendations which should be incorporated in ongoing Task Interface Agreement 81-15 LANNING, N D Director's Office 82/05/11 MICHELSON C Director's Office 1p 15846 095 24X Fiche 50-000, 82/07/12, 8210080015
- 205190441 "Inadvertent Loss of Reactor Coolant Events at Sequoyah Nuclear Plant, Units 1 % 2:" engineering evaluation rept LANNING.N D Director's Office 1EB-80-12 02/05/31 23pp 15866-076 24X Fiche 50-000, 82/07/(2,8210080015
- 205280490 Forwards diesel generator interim reliability program for operating plants 5 proposed Each Specs
 HANAUER'S H Division of Safety Technology 82/03/06
 EISENHUT.D G Division of Licensing MATTSON,R J Division of Systems Integration (post 811005) THOMPSON,H L Division of Human Factors Safety 49p 15666 031
- 205280497 "Diesel Generator Interim Reliability Program for Operating * Division of Safety Technology 82/05/06 22pp 15666 037
- 205280502 Proposed Tech Specs re electrical power sys * Division of Safety Technology 82/05/06 lipp 15444 Ob9
- 206040401 Forwards procedures for screening operational data, particularly LERs received after 820501 Submittal replaces procedures issued by 810429 / 820315 memos MICHELSON, C. Director's Office 82/04/23 Director's Ofi Director's Office
- 206070105 Operating Reactor Event Memo 82-01 re 810810 reactor scram w/water hammer event Study of Unresolved Bafety Issue A-1 shows no other water hammer events in BWR isolation conference EISENHUT, D Q Division of Licensing OREM-82-002 82/05/25 VOLUMER, 8 x Division of Engineering 7pp 15645 150 24% Fiche 50-000, 82/07/12, 8210080015
- 1210080054 Forwards "Cost of Upgrading Capability to Isolate LPWR Mayn Fredwater Bys in Event of Breaks Inside Containment," final rept.in response to statement of work in TE Murley 810616
 1tr re INEL technical assistance to NRR
 SAFFELL B F EG&O, Inc FIN A-6452 SAFF-155-82 82/04/14
 SOLECKI, J E Energy Dept of, Idaho Operations Office ip 15665 167
 - Upgrading Capability to Isolate LPMR Hain Feedwater teaks Inside Containment," final rept,per for DDE Work Order 20-61-165, "Program for Proposed Safety Requirements" A-6452 RGB-2-82 82/03/19 15μp

- --8210080106 Oral presentation of "New Trends in Evaluation & Implementation of 8afety-Related Operating Experience "MICHELSON, C NRC No Detailed Affiliation Olven 1468-CN-39/2 2A 82/07/12, 13pp 15667 278
- ~-8210080187 Forwards draft 1E bulletin on channel independence in Ethi 210080187 Forwards draft 1E bulletin on channel independence in actuation sys for DMB clearance Specific items listed in Part II of app to draft NRC Manual Chapter 02:3 discussed Expedited review & DMB clearance requested URBNAN EL Director's Office 81/05/28 SCOTT, 8 Document Management Branch 7pp iS648 144
- --8210080196 Forwards IE Circulars 80-15 & 81-10.Generic Lit 111 31 & 1 Info Notice 79-13, in response to 810630 request re issuance of IE bulietins concerning steam voids & events at foreign or domestic BWR or comestic SHR STELLO, V Director's Office, Office of Inspection and Infortation OL-81-21 8:707/27 LEMIS.M I Lewis, M 200 15660 LED
- --8210080197 NRC operations ctr usage chart re events at facilities A NRC No Detailed Affiliation Oliven B2/07/12 tp 154/01 24X Fiche 50-000,82/07/12,8210080015
- --8210080202 Forwards questions on licensee performance rating protes for use in preparing for systematic assessment of licensee performance briefing Draft responses dtd 810704 enc1 + NRC - No Detailed Affiliation Given 81/08/28 | NRC Detailed Affiliation Given 81/08/28 | NRC Detailed Affiliation Given 18pp 18668 222
- --8210080206 Forwards SJ Chilk Bl0923 staff requirements mamo re list briefing on systematic assessment of licenses performance rept Excerpts of Bl0922 briefing transcript re Commission guidance encl
 ALLIBON, DP NRC - No Detailed Affiliation Given Bi/(0/0) |
 HOBELEY, N C NRC - No Detailed Affiliation Given 9pp
- --B210080207 Forwards Commission guidance for future conduct of like assessment process per systematic assessment of licenses performance program Commission should be advised of progress CHILK, S J CHILK, 8 J Office of the Secretary of the Commission (infd' i) 8i/10/20 DIRCKS, W J Office of the Executive Director for Operations 4pp 15668 250 Operations
- --8210080213 Forwards revised description of responsibilities & for of Div of Engineering & GA
 JORDAN,E Division of Engineering & Quality Assurance 11,2712,
 BNIEZEKJ NRC No Debailed Affiliation Olven 4pp 170.4%,
- --8210080215 Forwards revised IE organizational charts & funrishing statements for review & comment Reorganizations of 640104 & 25 will be incorporated in NUREO-0325 BLAHAJ L. Program Support Branch 82/04/29 (.118) RHAM ; Enforcement Staff FORTUNAR Director's Office. Office of Financian and Enforcement COBOL I Division of Fuel Facilities, Materials & Safeguards 7pp 13660 261
- --B210080216 Forwards draft IE Manual Chapter 0101 re If prease sat functions Comments requested by 820624 Chapter will be included in Jul quarterly issue of changes to IE manual BRACH, B Director's Office, Office of Inspection and Inforce; 82/06/10 CDBs,L. GRIMES,B., JORDAN,E NRC No Betailes Affiliation O(ven 17pp 15668 272
- --8210080217 Forwards new IE organization chart, functional etatem new organizational units & list of proposed personnel assignments within new organization, per NJ Palladino 811(--:: memb Functional statements for reactor sys specialless u: 1
 DEYQUNO.R C Director's Office, Office of Inspection and
 Enforcement 8i/12/14 Director's Office, Office of Ended
 and Enforcement 32pp 13548 287
- B210080020 Responds to FOIA request for documents re preimplement review of NUREO-0737, Item III F 2 Forwards documents listed in App A FELTON.J M Division of Rules and Records B2/07/16 (Imporial Doc-Search Associates 2pp 15669 097
- ---8108270549 Requests add1 info through C-E guners group for head junction thermocouple reactor vessel level measurement by a info should be submitted by 810901 RUBENBTEIN,L B Assistant Director for Care & Containment C
- --Bi0B19000B Forwards LB Rubenstein 810709 memos requesting from C-E & Westinghouse owners groups re reactor vassel level measurement sys. THI Action Plan Item II F 23 LAINAB.c. Assistant Director for Bafety Assessment RELOT. CRUTCHFIELD.D Operating Reactors Branch 5 2pp 156.6% 2 15669 1

WITH WULLET ALL THE

- --8109110478 Requests that licensee provide plant-specific submittal reinstallation of Wostinghouse reactor vassel level instrument PHILLIPS, L. E. Core Performance Branch 81/08/13 SHEA, J. Operating Reactors Branch 5 2pp 65569 309
- --gj09280464 Requests that project managers transmit encl sample ltr ru Westinghouse reactor væssel level instrumentation sys for monitoring inadequate core cooling. TMI Item 11 F 2 3 to licenseem for plants listed CRUTCHFIELD.O Desretting Reactors Branch 5 81/09/16 VARGA.S A Operating Reactors Branch 1 5pp 15469 110
- --82100800(14 Advises of Commission approval re delay in implementation schedula for NURCO-0737, Item II F.2. "Add I Instrumentation for Detection of Inadequate Core Coping "SECY-Bi-528A withdrawn (ATMAB, O Assistant Director for Safety Assessment 82/02/10 ECSEMBUT, D. O Division of Licensing 2pp 15667 226
- 82100B0038 UCAP-7870 Sizerpt from "Neutron Shielding Pads" + Westinghouse Electric Corp 72/03/31 4pp 15669 242
- --B20B250412 Responds to B20327 memo re broken core barrel assembly thermal shield bolts at Oconee 1 & applicability to other 3tW plants NRR review.described in encl Task interface Agreement B1-17 did G11026, should be completed by B20901 LIEUMINT, D Q Division of Licensing B2/07/17 OLBHINGKI, J A Division of Engineering & Technical Programs 1p 15669 284
- 103000000 Responds to appeal re denial of FOIA request for sagragable portions of draft NUREO-0844, "Resolution of Unresolved Safety Issues A-3.A-4 & A-D Re Steam Generator Tube Integrity." Request denied (ref FOIA Exemption 5) DINCKS.W J Office of the Executive Director for Operations 87/07/19, UDE: L.R.A. Critical Mass Energy Project 2pp 15560 331
- IOI20013 Partial response to FDIA request for documents to St Joseph Hosp in Albuquerque. NH & 1-125 seed incident Forwards documents listed in App Astronomy 1 to State on the State of Rules and Records 82/08/20 DAVIES. L & Richards, Brands, Miller & Neison 3pp 15691 173
- Q012180362 PNA-B0-039 on B01201, State of NM informed NRC of overexposures of patients receiving I-125 seed therapy for treatment of prostate cancer Gausedby computer dose conversion factor error State request hosp rept
- *2210120018 Discusses PNA-BO-039 to overexposures of patients receiving 1-129 seed therapy for prostate cancer at St Joseph Hosp. Albuquerque.NM Computer program error cited as contributing factor LUBERAU.J C NRC No Detailed Affiliation Given 80/12/02 REMM.T NRC No Detailed Affiliation Given 1p 15691 178
- -BRIOIROORI Confirms B01228 telcon w/LW Huppert re misadministration of J-125 seeds used in prostate cancer therapy Definitive rept will be provided by B10202 Related info enci TOPP-A New Mexico, 8tate of 80/12/01 KUEBEL, C St Joseph Hosp Albuquergus, NM 14pp 15491, 180
- -B210120023 Requests assistance in independent technical review of encl rept from St Joseph Hosp re misadministration of 1-125 seed implant Ltr delineating info required & article from Albuquerque Journal and M/o enci. MDLFF.TA New Maxico. State of. 81/02/03 NUSBHAUMER.D A Assistant Director for State Agreements Programs ip 15691 192
- -8210120027 Forwards rept to 8t Joseph Hosp, Albuquerque, NM remisadministration of I-125 seed implant Event attributed to personnel error & lack of communication between computer plan developers & users Comments requested by 810227 NASBUAUMER, D.A. Assistant Director for State Agreements Programs 82/02/23 H1001NB0THAM, L. Radiological Safety Branch.
 CWMINOHAM, R.E. Advenced Fuel & Spent Fuel Licensing Branch 19 15491 193

- --8210120030 Advises that hosp rept re misadministration of I-125 seed implant therapy raises more questions than answers Related info encl.
 H1001NB0THAM, L. Radiological Safety Branch 62/06/20
 NUSSBAUMBER, D.A. Assistant Director for State Agreements Programs lipp 15891 174
- ~-8210120055 Discusses review of hosp rept re misadministration of I-125 seed implant therapy Rept does adequate job of defining magnitude of misadministration Contributing causes unclear Related info encl
 HILLER.Y L Licensing Hanagement Branch 81/03/09
 NUSSBAUMER.D A Assistant Director for State Agreements Programs 82pp 15691 206
- --8210120057 Forwards WR Hender review of selected matts remisadministration of I-125 seeds at St Joseph Hosp Albuquerque M/vo encil
 NUSSBAUMER, D.A. Assistant Director for State Agreements Programs 81/03/25 HIOGENBOTHAM.L. Radiological Sefety Branch MILLER, V.L. Licensing Management Branch ip 1591 289
- --8210120062 Forwards rept re investigation of St Joseph Hosp 1-125 serd Incident Related info encl TOPP:A A New Hexico. State of 81/31/13 NUSSBAUMER.D A Assistant Director for State Agreements Programs 12pp 15591 290
- --B210120066 Statement of St Joseph Hosp president re treatment of 18 prostate cancer patients by 1-126 seed implantation Related info encl KOEBEL, C St Joseph Hosp Albuquerque, NM G0/12/18 68pp 13691 303
- --8210120068 "Radiation Dose Evaluation of 1-125 implants at St Joseph Hosp" ANDERSON, L Affiliation Unknown 81/08/18 30pp 15692 008
- --82(0120075 Forwards State of NM rept re investigation of incident involving overexposure of patients treated w/l-125 seeds AO rept will be included in next quarterly rept W/o encl NUSSBAUMER D A Assistant Director for State Agreements Programs B1/11/24 CUNNINOHAM RE Advanced Fuel & Spent Fuel Licensing Branch 1p 15492 040
- 8210120090 Addl response to FOIA request for 19 categories of documents Forwards "Summery of Events Discussed At Operating Reactors Events Meeting During 1981," "Most Significant Events of 1981," & "Less Significant Events of 1981," & "Less Significant Events of 1981 "FELTON.J Division of Roles and Records 82/07/26 UDELL.R A Critical Mass Energy Project 5pp 15692 041
- 8210120112 Advises that questions re T Hoffett 810817 memo on efforts to expedite licensing of new nuclear power plants should be answered by Chalrman ROBERTS, T M Commissioners 81/08/25 HALLER, N Commissioners Ip 15490
- --8205060558 Expresses concern that 780208 NRC Hanual Chapter NRC-0502, NRC incident response which medates TMI-2 accident, remains effect plan should!

1

11 1

4 1

١, Jij 4

1 (þ Į

Ьi

4.4

Jaji 事

1

1 1/1

4

- 1

- --8210120170 Comments on SECY 82-74 re proposed rulemaking, 10CFR50 55a, "Codes & Stds " First full sentwhee on Page 7 of Encl 1 is misstatement of fact Requests B Direks response ROBERTES T M Commissioners 82/03/04 CHILK, 5 Office of the Secretary of the Commission 1p 15690 154
- --8204010046 Comments on Commissioner Roberts Statement in SECY-82-74 on 20401.0046 Lamments on commissioner Moberts scatement in Setrois Page 7 of Enci I re estimated costs applicant companies incur when applying for ASME approval Statement applies only to ASME charges made to company applying for N stamp MIMOGUE.R B Office of Nuclear Regulatory Research, Director 82/03/18 DIRCKS.N J Office of the Executive Director for Operations ip 15690 155
- --821012017à Forwards Ofc of Nuclear Regulatory Research memo explansning concerns re proposed rolemaking. "Codes & Stds " Section of rule in question not intended to upgrade or doungrade basic quality of product DIRCKS.H J Office of the Executive Director for Operations 82/03/24 ROBERTS.T M Commissioners ip 15490-156
- --B21012018) Requests that P Paris G Irwin & D Cooper experts in fracture mechanics field, be invited to Commission 820504 briefing re Pressurized thermal shock ROBERTS.T M Commissioners E Commissioners Ip 15690 159 82/04/21 PALLADING.N
- --9210120196 Recommends approval of SECY 81-570 proposed amend to IOCFR30. App E mod to emergency preparedness regulations ZECH, G NRC No Detailed Affiliation Given Bi/11/25 ROBERTS. T M Commissioners ip 15690 (6)
- --8210120202 Requests meeting during next visit to Washington.DC to discuss subj of recent ltr to NY Times RDBERTS.T M Commissioners 82/04/16 PARIS.P.C Affiliation Unknown 1p (5690 162
- 7903090181 In accordance w/790118 application, Mati/Syproduct License 21~08362-12 for Dow Corning Corp is amended to read Cs-i37 sealed sources for use in Dimart Model SR-i source holders for density & level measurements

 BASSIN.N Radioisotopes Licensing Branch (Pre 790501) 79/02/15
- --8001080054 Matl/Byproduct License 21-08362-12 for Dow Corning Corp 1s renewed per 790622 application Amend 5 authorizes Cs-137 for source holders for density measurement COUPER.J W Licensing Management Branch 79/11/07 3pp
- ~-8004050154 Mat1/Byproduct Lirense 21-08362-07 for Dow Corning Corp 16 amended per 800227 ltr Amend 9 changes Condition 14 as described in 800227 ltr PETTIJOHN, 5 L. Region 3, Chicago, Office of the Director 80/03/17 10
- ~-8006050188 Matl/Byproduct License 21-08362-12 for Dow Corning Corp is amended per 800227 itr Amend 6 changes Conditions 15 & 18 & allows use of licensed matl by J Sanderson, J Leicht, D Ooff & others
 PETTIJOHNS L. Region 3, Chicago, Office of the Director 80/03/17 ip 15748 094
- --B006170030 Matl/Byproduct License 21-08362-08 for Dow Corning Corp.is amended in its entirety per 790109 application Amend 10 authorizes use of C-14, tritium P-32, 1-125, 1-131 & S-35 for biological tracer studies in plants

 JONES, J. A. Licensing Management Branch 80/05/06 2pp
- ---8008070143 Matl/Byproduct License 21-08362-12 for Dow Corning Corp is amended per 800528 ltr Amend 7 authorizes users of of licensed matl PETTINOHN, 8 L Licensing Management Branch 80/06/26 ip
- --8101270870 Matl/Suproduct License 21-08362-12 for Dow Corning Corp is amended per 801014 ltr Amend authorizes J Senderson, J Leicht-D Goff, A Shovan D Wingert et al to use or supervise use of licensed matl
 PETTIJOHN, S L Region 3, Chicago, Office of the Director 80/11/20 lp 15748 094
- ---8102280175 Mat1/Byproduct License 21-08342-12 for Dow Corning Corp is amended per 801014 itr Amend 8 changes reading of Condition 12 re veers of licensed mat1 (corrected copy), CODPER.J W. Region 3. Chicago: Défice of the Director 81/02/02 ip 15748 077
- --8103i60338 Mat1/Byproduct License 21-08362-05 for Dow Corning Corp is amended per 8010i4 ltr Amend 14 changes Conditions 12 & 16 re users use & possession of licensed mat1 GUINN.P.R Licensing Management Branch 81/02/11 ip

- --BIO3i6O366 Hat1/Byproduct License 2i-OB362-i3 for Dow Corning Coff Is amended per BO1022 ltr Amend 3 changes Condition i2 & i4 re users, possession & use of licensed mat1 GUINN,P R Licensing Management Branch B1/O2/i7 ip 15748 107
- --8i04i70703 Mati/Byproduct License 2i-08362-05 for Dow Corning corp *1 amended per Amend 14 changes reading of Conditions 12 & 16 re use of licensed matl (corrected topy) OUINN.P R Licensing Management Branch 81/03/23 ip
- --8210i80030 Mati/Byproduct License 21-08362-0i für Dow Corning Coff-authorizing possession & use of 10 Ci tritium.100 mCi C-i4 k 100 mCi Cl-36 in any form for lab chemical research BRINKMAN.R E Atomic Energy Commission 62/04/26 lp 15748 004
- -8210180032 Amend 1 to Metl/Byproduct License 21-08362-01.edding 100 nCi 8-35 in any form for lab chemical research.per 630311 application
 BRINKMAN'S E Atomic Energy Commission 63/03/20 16 15748 005
- --9210180034 Amend 2 to Matl/Byproduct License 21-08362-01, extending expiration date to 660430, per 640127 application BRINMANN E Atomic Energy Commission 64/02/24 jp
- ~-BRI0180036 Amend 3 to Matl/Dyproduct License 21-08362-0), https://max amount of C-14 in any form.per 640507 application
 BRINMAN.R E Atomic Energy Commission 64/06/04 ip 1574B 007
- --8210180038 Amend 4 to Hatl/Dyproduct License 21-08362-01.changing iolaboud amend a to metrouproduct Literise allocade ulicense file entirety per 66000 application Amend authorises possession of tritium.C-14 & CI-36 in any form for lab chemical research & activation analysis
 BRINKHAN R E Atomic Energy Commission 66/03/21 299 15748 008
- --B210180040 Amend 5 to Mat1/Byproduct Lizense 21-08362-01, thenging expiration date to 730430, per 680321 application BRINKMAN, R E Atomic Energy Commission 68/04/03 jp 15748 010
- --B210180041 Amend & to Met1/Byproduct License 21-08062-01.changing expiration date to 780430 & amending Condition 12 re users of byproduct mati,per 730201 ltr BRINKMAN, R & Atomic Energy Commission, Directorate of License 73/02/14 1p 15748 011
- --82io180042 Amend 7 to Mati/Byproduct License 21-08362 Ol. changen. Condition 14 repossession & use of byproduct mati described in 1tems 6.7 & 8.per 740529 1tr Atomic Energy Commission, Directorate of Licensing 74/14. 1574B 012
- -- 8210180043 Amend B to Matl/Byproduct License 21-08362 01, than gar Conditions 12 & 14 re possession & use of byproduct watl, per 750304 application # Licensing Menagement Branch 75/06/24 in 75/40 days Licensing Management Branch 75/06/26 ip 15/40 QLA
- --8210180046 Amend 9 to Matl/Byproduct License 21-08362 Oi, changar license in entirety per 780328 application Amend authorises possession of tritium C-14, Cl-36, S-35 & any byproduct matt W/Atomic Numbers 3-83 inclusive in any form COMBB, F C Radio(sotopes Licensing Branch (Pre 790501) 7011 2pp 15748 014
- --B2101B0049 Mat1/Byproduct License 21-08362-05 for Dow Corning C authorizing possession of Br-90 sealed sources as check sources in Victoreen remote area monitoring sys HOHELL, D B Atomic Energy Commission 66/09/02 2pp 1374
- -8210180051 Amend 1 to Matl/Byproduct License 21-08362-03-add in BNL MK-1 strip sources, per 660907 & 22 ltrs CHURCHILL. B W Atomic Energy Commission 66/09/27 lp
- --B210180054 Amend 2 to Mati/Byproduct License 21-08362-05.re=1 Subitams 6.B.7.8 & B. B to authorize possession of 25.006 7.8 CG-60 8N. Ma-1 strip sources.per telegram received 461217 CHRCHILL, B. H Atomic Energy Commission 66/12/29 [p] 15748.019
- --8210180037 Amend 3 to Hetl/Byproduct License 21-08362-05.cbems in entirety. Amend authorizes Co-60 BNL MK-L strip sources for use in hat cell for irradiation of matts & Br. Pc celled sources as check sources in monitoring age CHURCHILL. B W Atomic Energy Commission 67/01/30 3pp

- --2210)80058 Amend 4 to Mati/Byproduct License 21-08362-05, deleting Condition 16.per 670405 ltr CMRCHILLS W Atomic Energy Commission 67/04/27 lp 1738 623
- --P21D180061 Amend 5 to Matl/Byproduct License 21-08362-05, changing Subitems 7 A & B A to read 35,000 Ci sealed sources (BNL MK-1 strip sources or Neutron Products Inc Catalog PP1-12CC5 clad wire) per 710609,0709 & 0820 ltrs PALAGO.U C Atomic Energy Commission 71/08/30 ip 15748 024
- --8210160064 Amend & to Mat1/Byproduct License 21-08362-05, changing license in entirety per 711227 application Amend authorizes Co-60 smaled sources for use in hot cell for irradiation of satts & Sr-90 smaled sources as check sources HEMDRIE, O H Atomic Energy Commission 72/01/25 3pp 15748 025
- --B210180066 Amend 7 to Mat1/Byproduct License 21-08362-05, changing Conditions 12 & 15 re user & possession & use of byproduct metliper 740327 ltr DAVIS, C Atomic Energy Commission, Directorate of Licensing 74/07/23 ip 15748 028
- --8210180072 Amend 8 to Mat1/Suproduct License 21-08362-05, changing Conditions 12 & 15 re user & possession & use of byproduct agt.per 74121 & 750623 ltrs
 SMPE:N W Licensing Management Branch 75/07/22 tp
 15748 029
- --B210180075 Amend 7 to Mati/Byproduct License 21-08362-05.changing Condition 12 re user of lirensed mati-per 750818 ltr CDLLINS.D M Licensing Management Branch 75/i0/09 lp 15748 030
- --821018007G Amend 10 to Mati/Byproduct License 21-08362-05 changing Candition 12 re user of licensed mati.per 761112 application BASSIN.N Radioisotopes Licensing Branch (Pre 790501) 77/01/17 19 15748 031
- --8210180080 Amend il to Mati/Nyproduct License 21-08362-05, changing license in entirety per 761222 application Amend authorizes Co-60 sealed sources for use in hot cell for irradiation of eatls & Sr-90 sealed sources as theth sources ASSIM,N Radioisotopes Licensing Branch (Pre 790501) 77/05/06 3pp 15748 032
- -- \$210180031 Amend i2 to Matl/Dyproduct License 21-08362-05, changing Condition i6 re possession & use of licensed mati.per 771212 application BASSIN.N Radioisotopes Licensing Branch (Pre 790301) 78/02/13 is 15748 035
- --8210180055 Amend 13 to Matl/Byproduct License 21~08362-05, adding Co-60 salid sources for use in Traceriab Model DC-1 doesmeter calibrators for dosimeter calibrators for dosimeter calibrators for Radioisotopes Licensing Branch (Pre 790501) 78/04/20 19 15748 036
- --8210180089 Amend i5 to Matl/Dyproduct License 21-08362-05, changing license in entirety per 811228 application Amend authorites Sr-90 & Co-60 sealed sources as check cources in Victoreen area monitoring sys & as documeter calibrators GUNN, P R Licensing Management Branch 82/04/19 3pp 13748 039
- ~8210180072 Corrected Amend i5 to Matl/Dyproduct License 21-08362-05, changing license in entirety per 811228 application Amend authorizes Br-70 & Co-60 smaled sources are check sources in Victores are amonitoring eys & are dosimeter calibrators QUINN.P R Licensing Management Branch 82/05/04 3pp 13748 042
- --8210180076 Matl/Byproduct License 21-08362-07 for Dow Corning Curpauthorizing tritium as foils in F & M Model 2-2837 detector cell for use w/ges chromatography unit for sample analysis ERINKHAN,R, E Atomic Energy Commission 67/10/12 2pp. 13748 045
- --8210180098 Amend 1 to Metl/Byproduct License 21-08342-07, changing Condition 12 re user of byproduct matl.per 681224 ltr. + Atomic Energy Commission 69/01/10 ip 15748 047
- --B210180102 Ameng 2 to Mat1/Byproduct License 21-08362-07, changing license in entirety per 691113 ltr Amend authorizes tritium as folls in F & H Hodel 2-2837 detector cell for use w/ges chromatography unit for sample analysis.
 BRINKHAN,R E Atomic Energy Commission. 69/11/21. 2pp 13748 048

- --8210180105 Amend 3 to Mail/Byproduct License 21-08362-07, changing Condition 14 re possession & use of byproduct mail.per 700312 ltr BRINKMAN R & Atomic Energy Commission 70/03/23 lp 15748 050
- --8210180108 Amend 4 to Matl/Ryproduct License 21-08362-07.changing expiration date to 771031 & amending Condition 12 re user of byproduct matt, per 720912 application ORINKHAN.R E Atomic Energy Commission 72/10/12 1p 15748 051
- --6210180111 Amend 5 to Hatl/Byproduct License 21-08362-07, changing Condition 14 re possession & use of byproduct matl.per 740529 Itr
- w Atomic Energy Commission, Directorate of Licensing 74/06/20 Ip 13748 052
- --9210180113 Amend 6 to Matl/Byproduct License 21-08362-07, changing Condition 14 rm posmession & use of licensed matl.per 761203 application

 4 Radiomisotopes Licensing Branch (Pre 790501) 77/01/10 ip 15748 053
- --8210180115 Amend 7 to Matl/Byproduct License 21-08362-07, changing Conditions (2 & 14 re user & possession & use of licensed matl.per 761222 application Radioisotopes Licensing Branch (Pre 790501) 77/03/04 Ip 15748 054
- --8210180116 Amend 8 to Matl/Opproduct License 21-08362-07: changing license in entiraty per 770928 application Amend authorszes tritium as US Radium Lab Model 508-1 foils in Hewlett-Packard Model 2-2837 detector cell JONES, J A. Radioisotopes Licensing Branch (Pre 790501) 78/04/16 2pp 13748 055
- --8210180118 Mat1/Byproduct License 21-08342-08 for Dow Corning Corparthorizing C-14, trition & P-32 in any form for use in biological tracer studies on animals & microorganisme BUCKMANAC R Atomic Energy Commission 69/01/09 2pp 15748 098
- --8210180121 Amend 1 to Mat1/Byproduct License 21-08362-08, changing license in entirety per ABILIO ltr Amend authorizes C-14, tritium & P-32 in any form for use in biglogical tracer studies on animals & microorganisms

 BRINKHAN, R C Atomic Energy Commission 69/11/21 ip 15/48 040
- --B210180125 Amend 2 to Mat1/Dyproduct Licenee 21-08362-08, changing Condition 19 re possession & use of byproduct mat1.per 700312 it BRINKMAN.R E Atomic Energy Commission 70/03/20 Ip 15748 Obi
- --8210180127 Amend 3 to Mati/Dyproduct License 21-08362-08, adding I-125 & I-131 in any form for use in biological tracer studies on animels, plants & microargenisms, per 720814 ltr DRINKMAN, R E Atomic Energy Commission 72/09/25 ip 15748 062
- --B2[0]B0]30 Amend 4 to Meti/Byproduct License 21-0B362-0B, changing expiration date to 790]31 & amending Condition 12 re user of byproduct matiliper 731206 application BRINKMAN,R E Atomic Energy Commission, Directorate of Licensing 74/01/04 lp 15748 063
- --8210180132 Amend 5 to Matl/Dysroduct License 21-08362-08, adding 8-35 in any form for use in biological tracer studies on animals. plants & microorganisms.per 740306 ltr # Atomic Energy Commission. Directorate of Licensing 74/03/20 is
- --BR10180136 Amend & to Matl/Byproduct License 21-08362-08, changing Condition 13 re possession & use of byproduct matl.par 740529 ltr # Atomic Energy Commission, Directorete of Licensing 74/06/20 fs 15748 065
- --8210180139 Amend 7 to Matl/Byproduct License 21-08362-08, changing Condition 13 re possession & use of licensed matl.per 761203 application.

 # Radjoisotopes Licensing Branch (Pre 790501). 77/01/10 | Ip
- --B210180140 Amend B to Heti/Euproduct License 21-08362-08; changing Conditions 12 & 13 re user & possision & use of licensed mattrper 761227 application BASBINN Radioisotopes Licensing Brench (Pre 770501) 77/03/02 lp 15748 067.

- --B210180145 Amend 9 to Matt/Ruproduct License 21-08352-08, changing Subitems 8 A & B B +o read 150 mCi & 50 mCi, respectively & amending Condition 13 re possession & use of licensed matt.per 780403 ltr WRIOHT, E @ Radioisotopes Licensing Branch (Pre 790501) 78/08/10 ip 15748 048
- --8210180150 Matl/Byproduct License 21~08362-07 for Dow Corning Corp. authorizing Ni-63 as foils in detector cells (Mawlett-Packard 2-6195) for use in gas chromatography unit for sample analysis
 BRINMAN, R E Atomic Energy Commission 69/03/14 3pp 1973 671
- --8210180152 Amend 1 to Matl/Byproduct License 21-08362-09, adding tritium as titanium tritide foils in detector cells for use in gas chromatograph for chemical analysis, per 700707 application
 ERINMANIR E Atomic Energy Commission 70/07/22 ip 15748 074
- --8210180157 Amend 2 to Matl/Byproduct Literse 21-08362-09, adding Ni-60 as folls in detector cells (Hewlett-Packard 18713A) for use in Hewlett-Packard gas chromatography unit for sample analysis.per 730327 itr
 BRINKMAN.R E Atomic Energy Commission 73/05/02 ip
- --8210180139 Amend 3 to Mat1/Byproduct License 21-08362-09, changing expiration date to 790331 & amending Condition 12 re-user of byproduct mat1.per 740227 application + Atomic Energy Commission. Directorate of Licensing 74/04/01 ip 15748-076
- --8210180164 Amend 4 to Mati/Dyproduct License 21-08352-09, changing Condition 14 re possession 5 use of byproduct mati-per 740527 ftr w Atomic Energy Commission, Directorate of Licensing 74/06/20 15 15748 077
- ~-8210180168 Amend 5 to Matl/Syproduct License 21-QGGA2-07, changing
 license in entiraty per 790288 application Amend authorizes
 N1-63 & tritium as foil source for use in gas chromtography
 units for sample analysis
 CODPER.J W Licensing Hanagement Branck 79/03/16 4pp
 15748 078
- --8210180171 Matl/hyproduct License 21-08362-12 for Dow Corning Corp. authorizing Cs-137 sealed source for use in Ohmart Model ED-4 density gauge * Atomic Energy Commission. Directorate of Licensing 74/07/16 App 15748 082
- --B210180173 Amend 1 to Mat1/Byproduct License 21-08362-12, adding Ca-137 sealed source for use in source holder for magaurement of pipe fluid density, per 750/29 thr
 4 Radioisotopes Licensing Branch (Pre 790001) 74/05/28 2pp 15748 005
- --B210180176 Amend 2 to Matl/Byproduct License 21-08062-12.changing Conditions 12.14 D.15 & 16 re user of licensed math, performance of tests for leakage/contamination & maint, repair & radiation survey,per 761223 ltr
 BELL-J M Radioiaotopes Licensing Branch (Pre 790801) 77/07/29
 2pp 66393 153
- --B210180178 Amend 3 to Matl/Dyproduct License 21-08362-12, changing Subitems B & C of Items 6.7 & B & adding Ce-107 sealed sources for use in source holders for measurement of pips density & level.per 770727 & 1206 Item Radioisotopes Licensing Branch (Pre 770501) 37/12/20 ip. 15748 037
- ---8210180194 Mat1/Dyproduct License 21-08362-13 for Dow Corning Corp. authorizing Co-60 sealed sources for use in two irradiation reaction vessels for irradiation of matls to produce

· (Pr. 790501) 77/03/22 3pp

- --B2[0180213 Amend 4 to Mati/Byproduct License 21-08362-13, changing Items 6.7.8 & 9 to read Co-60 sealed sources for use in three irradiation reaction vassels for irradiation of matls to produce chemical synthesis.per 81031 itr GUINN:P R Licensing Management Brench 81/04/21 ip
- --8210180215 Responds to AEC 411220 ltr re violations noted in Insp of License 21-00265-01 on 610309-10 Corrective actions amend to 11cense requested to permit use of two add1 Co-60 sealed sources & tags fastened to each source holder BEAHER.W H Dow Chemical Co 40369 42/01/02 PRICE.E Atamis Energy Commission 2pp 15748 109
- --8210180219 Corrects 610109 ltr requesting increase in quantity of Cs-137 on License 21-00265-01 Limit of Cs-137 smaled sources requested to be increased to 6,000 mC: Two smaled sources containing 1,500 mC: each of Cs-137 will be ordered BEAMER: WH Dow Chemical Co 3180: 61/01/12 ROCERS.L R Atomic Energy Commission 1p 15748 111
- --8210180222 Requests that limit of Cs-137 sealed sources on License 21-00265-01 be increased to 3:000 mC; Sealed source containing 1,500 mC; Cs-137 will be installed as part of liquid level controller instrument BEAMER. W H Dow Chemical Co 3:007 61/01/09 ROGERS. L R Atomic Energy Commission ip 15748 112
- --8210180229 Inquires about possibility of amending License 2:-00085-i to increase i Ci per yr limit for disposel of tritiated water into effluent sewage stream KEAMER.W H Dow Chemical Co. 58/12/24 BOWYER, J E. Atomic Energy Commission ip 15748 ii3
- --8210180234 Describes relationship of Bechtel Corp to Dow Chemical C (DCC) as agent in purchase of four radioactive Cs-137 sources, par AEC 580616 request Bources will be in physical potsession of DCC before & after installation BEAMER. W H Dow Chemical Co 58/06/24 BONYER, J E Atomic Energy Commission 1p 15748 #14
- --8210180239 Application for renewal of Matl/Byproduct Licenies 21-00245-04,21-00245-02.21-00265-04,21-00245-07,8NM-1253, 8TB-527 & R-108 authorizing any byproduct matl between Atomic Numbers 3 & 83.1 tritium,Po-210 & Am-241 HOYLE,H R Dow Chemical Co 39482 73/06/25 2pp
- --8210180247 Forwards application for renswal of Matl/Bygroduct Lice 21-00265-05 List of plant locations including three plants not authorized under current license & description of hyproduct matl used in lower animals encl W/o application HOYLE,H R Dow Chemical Co 38652 73/06/18 CUNNINGHAM. R £ Abomic Energy Commission 3pp 15748 117
- --8210180251 Forwards application for renewal of Matl/Byproduct L.(c) 21-00265-01 & 21-00265-02 Sample of isotope data card & revisions to radiation protection manual encl BEAMER, W H Dow Chemical Co. 28079 & 60/07/21 HASON, J R. Atomic Energy Commission 5pp 15748 120
- --8210180257 Application for renewal of Matl/Byproduct Licenses 21-00265-01 & 21-00265-02 authorizing use of Elements 3 through 83 in any form & tritium scaled source for RED Sealed source inventory encl Bealed source inventory encl BEAMER.W H Dow Chemical Co. 28079 60/07/21 5pp 157-48 |
- --B2101B0260 Ack receipt of 600113 Amend B to Matl/Byproduct Licens 21-00269-01 adding authorization for use of Pm-147 sources at Bay City plant. Daw Chemical Go will possess beta ray instrument ordered by Bechtel BEAMER. W H Dow Chemical Co 60/01/29 BRINKMAN. R E Atomic Energy Commission ip 15748: 130
- --8210180262 Application for math/byproduct license authorising El i to 84 inclusive in any form for use in chemical & agricultural RED. tracer problems & as sealed sources in Instruments. Std for control of rediation hazards encl BEAMER. H H Dow Chemical Co 56/04/03 20pp 15748-131
- ~-8210180266 Forwards application for renewal of Mati/Byproduct & 21-00265-06 BEAMER, W. H. Dow Chemical Co 66/06/10 Atomic Energy Commission. 1p 15748 151
- --8210180270 Amend if to Mati/Byproduct License 21-00265-03, chang Condition if re-user of byproduct mati & adding Condition in to require compliance w/IOCFR20, Chapter i, "Stds for Protection Against Radiation," per 590105 ltr & Atomic Energy Commission 59/01/29 ip. 15748 155

- -- 2210180275 Hatl/Bygroduct License 21-00245-03 for Dow Chemical Co. authorizing Co-60 as aluminum clad slugs in steinless steel rods per Dow Chemical Drawing ND1-3492 for use in gamma irradiator to initiate chemical reactions a Atomic Energy Commission 57/09/10 1p 15748 15A
- --8210180277 Mat1/Byproduct License 21-00265-02 for Dow Chemical Co. erusiours, natisupproduct alternse el-uoro-uz for Dow Chemic authoriting Co-do as cylindrical sealed source & aluminum clad sings in copper rods per 560706 itr for use in radiction chemistry studies a Atomic Energy Commission 56/09/21 2pp 15748 157
- ~-8210180282 Amend 1 to Matl/Byproduct License 21-00265~02, adding Co-60 sealed sources for use in high level radiation chemistry research, per 570115 application a Atomic Energy Commission 57/02/25 ip 15748 159
- --8210180284 Amend 2 to Matl/Byproduct License 21-00265-02, changing Conditions 11 & 12 re user of byproduct matl & compilance u/10CFR20, Chepter 1. "Stds for Protection Against Radiation" respectively, per 590105 ltr KASON, J R Atomic Energy Commission 59/01/29 (p. 15748-160
- --B230180287 Amend 3 to Mat1/Byproduct License 21~00265-02, changing license in entirety per 610711 epplication Amend authorizes Co-60 as BNL cylindrical source & aluminum clad cobalt siuge for use in irradiator & hot cell for experimental studies MASON, J.R. Atomic Energy Commission 61/07/19 2pp 15748 161
- -- P210180270 Amend 4 to Mat1/Byproduct License 21-00265-02, changing license in entirety per 620531 ltr Amend authorizes Co-50 as cylindrical source in aluminum & as aluminum clad slugs in steinless steel for use in irradiator & hot cell EELL.J M Atomic Energy Commission 62/07/24 2pp 15748 163
- --B210180295 Amend 5 to Metl/Dyproduct License 21-00245-02, changing license in entirety per 620925 itr Amend authorizes Co-60 as tylindrical source in eluminum & as aluminum cied siugs in stainless steel for use in Irradiation & hot cell BELL-J M Atomic Energy Commission 62/11/09 3pp 15748 16 3pp 15740 145
- --8210180278 Amend & to Mati/Suproduct License 21-00265-02, changing Conditions 13 & 14 re possession & use of byproduct mati & written instructions concerning operating procedures for cobalt radiation sources & facilities, per 621219 1tr BELL-J H Atomic Energy Commission 63/01/28 1p 15748 168
- --8210180301 Amand 7 to Mat1/Byproduct License 21-00265-02, adding Condition 19 authorizing disposal of 100 mCi Co-60 by autial, per 621219 ltr
 BELL-J H Atomic Energy Commission 63/02/28 lp 15748 lo 15748 169
- --8210180304 Amend B to Mat1/Byproduct License 21-00265-02, adding 330 Ci Condo as BNL cylindrical source in aluminum for use in leradiator device & revising Subitems 70 & Conditions 13 & 14 rs gossession of byproduct meth.per 630418 & 0317 ltrs BUCHANANC R Atomic Energy Commission 63/06/23 2pp 15748 170
- --8210180307 Amend 9 to Mati/Duproduct License 21-00265-02, deleting Subitems C of Items 6,7,8 & 9 & Condition 18, per 660125 ltr HOMELL,D B. Atomic Energy Commission. 66/02/17 ip 15740 1 19748 172
- --8210180310 Amend 10 to Mat1/Byproduct License 21-00265-02, extending expiretion date to 710930. deleting Subitems 64, 74, 64 & 74 & revising Subitems 78, per 660705 application SOMELL.D B Atomic Energy Commission. 66/09/01 ip 15748, 173
 - 12:0180312 Amend 11 to Mati/Byproduct License 21-00265-02, adding Condition 20 to permit transfer of byproduct mati to new irradiation facility per 661017 1tr CHURCHILLS W. Atomic Energy Commission 66/11/02, 1p 1574B 174
 - 2310190315 Amend 12 to Matl/Byproduct License 21-00265-02, changing license in entirety Amend authorizes Co-60 as aluminum clad slugs in stainless steel & as cylindrical source in aluaique for use in hot cell & irradiation device CHRCHILLB, W. Atomic Energy Commission 67/01/25 3pp 13748 175 15748 175
 - 5210180318 Amand 13 to Mat1/Byproduct License 21-00265-02, revising Eulitens 6 A:7 A & 8.A to read 15,000 Ci Co-60 as aluminum cled slugs in stainless steel & edding Ca-137 as doubly encapsulated stainless steel west sources; per 670126 ltr.
 CKNGCHILL:8 W Atomic Energy Commission 67/02/15 ip. 13748 178

- --8210180319 Amend 14 to Mat1/Buproduct License 21-00265-02, deleting Condition 17.per 670313 ltr BUCHANAN.C R Atomic Energy Commission 67/03/30 15748 179
- --8210180324 Amend 15 to Matl/Byproduct License 21-00245-02, revising Bubitsm 9 A to authorize use of byproduct matl in hot cell or registion reactor for irradiation of various matls, per 690415 1tr BUCHANAN. C R Atomic Energy Commission 69/04/23 15748 180
- --B210180326 Amend 16 to Hatl/Byproduct License 21-00265-02, revising Condition 12 authorizing tR Hoyle to use &/or supervise use of byproduct matl.per 700615 ltr MALARO, J C Atomic Energy Commission 70/07/06 Ip 15748 181
- --8210180328 Amend 17 to Matl/Buntoduct License 21-00265-02 changing Ticense in entirety per 710726 application Amend authorizes
 Co-60 as aluminum tlad slugs in stainless steel & Ca-137 as
 doubly encepsulated stainless steel courtes
 MALARO, J.C. Atomic Energy Commission 71/08/16 3pp 13748
- --8210180333 Amend 18 to Matl/Buproduct License 21-00265-02. revising Condition 16 re possession & use of byproduct mati.per HENDRIE. O H Atomic Energy Commission 71/12/21 ip 15748 185
- --B210180335 Amend 17 to Mati/Byproduct License 21-00265-02, revising Condition 16 re possession & use of licensed mati-per 760315 ltr
 BASSIN.N Redictsotupes Licensing Branch (Pre 790501) 76/05/19 1p 15748 186
- --8210180337 Amend 20 to Mati/Byproduct License 21-00265-02, revising Condition 16 re possession & use of licensed mati/per 760909 ltr BASSIN.N Redicisotopes Licensing Branch (Pre 790501) 76/11/24 15748 187
- -- B210180340 Amend 2 to Mat1/Byproduct License 21-00245-04, changing license in antirety per 651210 application Amend authorizes Co-60 seeled cources for use in industrial rediography by open-air handling techniques MILLER.W O Atomic Energy Commission 65/12/29 2pp 15748 NBG
- --8210180341 Amend 13 to Mat1/Byproduct License 21-00265-04, adding Co-60 sealed source for use in Tech Ops Model 525 exposure device for industrial radiography & adding Conditions 14. C. 15 & 16. per 660729 ltr MILLER, HO Atomic Energy Commission 66/09/27 2pp
- --B210180343 Amend 4 to Matl/Byproduct License 21-00265-04, changing license in entirety per 681227 application Amend authorizes Co-60 seeled sources for use in Tech Ope Model 525 exposure devices for industrial radiography
 MALARO, J C Atomic Energy Commission 69/01/17 4pp 1974B 192
- --8210180344 Amend 5 to Mat1/Dyproduct License 21-00265-04, changing ltam 9, A & Condition 16 re possession & use of byproduct mat1 BASSIN, N Atomic Energy Commission 72/05/19 1p 15748 196
- ---8210180346 Amend & to Meti/Dyproduct License 21-00265-04, changing license in antiraty per 731227 application Amend authorized Co-60 sealed sources for use in Tech Ops Model 525 exposure devices & Model 416 source changers
 RESNER, E P Licensing Management Branch 75/09/10 2 15748 197

- --8210180353 Requests documents indicating disposal of all incensed math possessed under License 21-00265-04, per 770707 telcon in response to licensee 770627 request for termination of license Note of 770707 telcon end.
 JUNES, J A Radiolisatopes Licensing Branch (Pre 770501) 77/09/13 WILLIAMS, P R Dow Chemical Co Rpp 13748 203
- --8210180354 Requests termination of Mati/Byproduct License 21-00265-04 Five Co-60 source used for industrial radiography disposed of via Nuclear Engineering Co at Sheffield.IL N(LLIAMS, P. R. Dow Chemical Co 88359 77/06/27 Redicisotopes Licensing Branch (Fre 790501) ip 15748 205
- --8210180358 Requests termination of Matl/Byproduct License 21-00265-04
 Industrial radiographic source (2 3 Ci Co-60) shipped to
 Shaffield, IL by Nuclear Engineering Co for disposal Bhipping
 record encl
 THOMAS, B R Dow Chemical Co 89463 77/08/25 JONES, J
 Radioisotopes Licensing Branch (Pre 790501) 2pp 15748 206
- --8210180360 Matl/Byproduct License 21-00265-06 for Dou Chemical Coauthorizing any byproduct nat1 between Atomic Numbers 3 & 83 anciusive w/listed erceptions in any form for use in RBD lab tracer studies # Atomic Energy Commission 64/08/14 3pp 15748 208
- --8210180363 Amend i to Mati/Byproduct License 2i-00265-06.increasing max amount of Kr-85 from 10 Ci to 25 Ci & revising Condition 11 re use of instruments devices & gauges containing sealed sources.per 650414 ltr
 BRINKMAN.R E Atomic Energy Commission 65/04/28 ip
- --8210180364 Amend 2 to Mati/Byproduct License 21-00265-06, adding Po-210 as static eliminators & revising Condition 11 re use of instruments devices b gauges containing sealed sources; per 650728 ltr
 4 Atomic Energy Commission 65/09/18 ip 15748 212
- --8210180367 Amend 3 to Mat1/Byproduct ticense 21-00265-06,adding Po-210 in any form for use in R&D, per 65:006 ltr 6 Atomic Energy Commission 69/10/29 ip 15748 213
- --8210180370 Amend 4 to Matl/Byproduct License 21-00265-06, revising Condition II re use of instruments, devices & gauges containing sealed sources.per 660214 ltr
 BUCHANAN.C R Atomic Energy Commission 66/02/24 lp
 15748 214
- --8210160372 Amend 5 to Hati/Byproduct License 21-00265-06 changing license in entirety per 660610 ltr Amend authorizes any byproduct mati between Atomic Numbers 3 & 83 inclusive. tritium & Po-210 in any form for use in R&D BRINKMAN,R E Atomic Energy Commission 66/06/29 App 15748 215
- --8210180373 Amend & to Matl/Byproduct License 21-00265-06, revising Condition 16 re possession & use of byproduct matl.per &46722 itr

 ERINKMAN.R E Atomic Energy Commission 66/08/08 ip 15748 219
- --B210189374 Amend 7 to Mati/Ryproduct License 21-00265-06, adding Am-241 & PU-239 in any form for use in analytical chamistry tracer experiments, per 661216 itr
- * Atomic Energy Commission 67/01/03 ip 15748 220
- --8210180375 Amend 8 to Mati/Ryproduct License 21-00265-06, adding Po-210 sealed source for use in storage & testing of instruments & revising Condition 16 re possession & use of byproduct matl, per 670525 telegram
 BUCHANAN.C R Atomic Energy Commission 67/06/01 ip
 15748 221
- --8210180374 Amend 9 to Mati/Byproduct License 21-00245-04, changing Subitem 8 F to read 10 Ci.per telegram received 670608 * Atomic Energy Commission 67/06/15 ip 15748-222
- --GRIO180377 Amend 10 to Matl/Byproduct License 21-00265-06, changing license in entirety per 680627 application Amend authorizes any byproduct matl between Atomic Numbers 3 & 83 inclusives tritium. Po-210. Am-241 & Pu-239 in any form BRINMAN.R E Atomic Energy Commission, 68/07/16 4pp 15748 223
- --8210180379 Amend 11 to Matl/Byproduct License 21-00265-06, changing Subitem 8 B to read 60 Co.per 681223 it;
 * Atomic Energy Commission 69/01/10 ip 15748, 227

- --8210180380 Amend 12 to Mati/Byproduct License 21-00265-06 changing Subitem 8 A to limit radionuciade to 1 C1 except for Kr-85, C1-137, C0-60, Br-90 & C-14, per 700115 ltr BRINKMAN, R E Atomic Energy Commission 70/01/26 1p 15748 228
- --82101803B1 Amend 13 to Matl/Byproduct License 21-00265-06, changing Condition 12 re user of byproduct mati.per 700615 ltr
 Atomic Energy Commission, 70/06/25 ip 15748 229
- --8210180383 Amend 14 to Matl/Dyproduct License 21-00265-06.changing Condition 10 re use of byproduct matl,per telegram received 710325 BRINKMAN,R E Atomic Energy Commission 71/03/25 ip 19748 230
- --B210180386 Amend 15 to Mati/Byproduct License 21-00265-06.adding Am-24 sealed sources for use in development.standardization & testing of instruments.devices & gauges.per 710809 itr BRINKMAN.R E Atomic Energy Commission 71/08/20 ip 15748 231
- --8210180387 Amend 16 to Hatl/Byproduct License 21-00265-06, changing Subitem 8 0 to read it Ci.per 711t18 itr BRINKMAN.R E Atomic Energy Commission 71/11/30 ip 15748 222
- --B210180371 Amend 17 to Matl/Byproduct License 21-00265-06, changing Substem B Q to read 15 Ciper 720107 itr BRINKHAN R E Atomic Energy Commission 72/01/19 ip
- --B210180397 Amend 19 to Mati/Byproduct License 21-90265-06, changing Subitem B 0 to read 25 Ci.per 720721 ltr
 BRINKMAN.R E Atomic Energy Commission 72/08/03 ip
- --8210180399 Amend 20 to Mati/Byproduct License 21-00265-06, changing Subitem 8 A to limit radionucide to 1 Ci w/exceptions of Kr-85, Ce-137, Co-60, Sr-90 & C-14 & deleting Bubitems & C.7 E. 8 E & 9 E.per 730282 ltr BRINKHAN.R E Atomic Energy Commission. Directorate of Licensing 73/03/08 lp 15748 236
- ~-8210180402 Amend 21 to Mati/Byproduct License 21~00265~04, changing Subitem 8 0 to read 40 Ciper 730301 ltr BRINKHAN.R E. Atomic Energy Commission, Directorate of Licensinj 73/03/27 1p 15748 237
- ~-8210180406 Amend 22 to Matl/Byproduct License 21~00265~06, changing license in entirety per 730625 application Amend authorites any byproduct matl between Atomic Numbers 3 & 63. tritium, Po-210 & Am-241 in any form & Po-210 & Am-241 sealed source BRINKMANNR & Atomic Energy Commission, Directorate of Licensin 73/07/31 App 15748 238
- ~-8210180409 Amend 23 to Hatl/Byproduct License 21~00265-04; changing Subitem 8 B to read 100 Ci,per telegram received 730906 BRINKMAN, R E Atomic Energy Commission, Directorate of Licensin 73/09/26 ip 15748 242
- --8210180410 Amend 24 to Mat1/Byproduct License 21-00265-06, changing Subitem 8 F to read 75 Claper 740401 itr * Atomic Energy Commission, Directorate of Licensing 74/04/1, ip 15748 243
- --8210180413 Amend 25 to Matl/Byproduct License 21-00265-06, changin Conditions 10 & 16 re possession & use of byproduct matl, per 740827 telegram * Atomic Energy Commission, Directorate of Licensing 74/09/6
 - to 15748 244
- --B2101B0417 Amend 26 to Matl/Byproduct License 21-00265-06, adding sealed sources for use in process control instruments & Eberline Model 1000 calibrator.ger 750i03 ltr
 BELL/J M Licensing Management Branch 75/03/20 ip 15-48
- --8210180421 Amend 27 to Matl/Buproduct License 21-00265-06.rsvize Bubitems 8. A, B F, P A, P 8 & P C re amount of redionuclide & use of licensed matl.per 750407 ltr * Licensing Management Branch 75/07/11 1p 15748 246

- --8210(80422 Amend 28 to Mati/Byproduct License 21-00265-06, revising Subjects 7 A.B & C re use of licensed math.per 750714 application 24551N.N Licensing Management Branch 75/09/04 1p 15748 247
- E210180423 Amend 29 to Meti/Byproduct License 2i-00265-01, revising Condition 16 re possession & use of licensed math.per 760315

 Jtr a Radioisotopes Licensing Branch (Pre 790501) 76/05/19 ip 15748 248
- 8210180425 Amend 3D to Matl/Byproduct License 21-00265-06, revising Candition 10 re use of Fe-55 & Am-24i sealed sources, per 760706 application a Radioisotopes Licensing Branch (Fre 79050i) 76/08/26 1p 13748 249
- -8230(80426 Amend 31 to Mati/Byproduct License 21-00265-06, revising Confitions 10 & 16 re possession & use of licensed mati, per 780909,17 & 1019 ltrs 845SIM,N Radioisotopes Licensing Branch (Pre 790901) 76/11/30 by 10748 250
- --8210180427 Forwards up-to-date list of radiation detection instruments, par Item 15 of &&0403 application for renewal of Mati/ Byproduct License 21-00265-06 BEAMERN H Dow Chemical Co &&/07/22 BRINKMAN, R & Atomic Energy Commission, 2pp 15748 333
- --8210180428 Revised "Radiation Protection Manual " a Dow Chemical Co 73/01/3i 159pp 15748 337
- --B210180429 Amend 32 to Mati/Byproduct License 21-00265-06, changing Subitem 8 A to limit radionuclide to 1 Cl w/exceptions of gr-05.Cs-137, Co-60, Br-90, C-14, mixed fission products & Ni-63 & revising Condition 16, per 761102 ltr BASSIN, N Radio(sotopes Licensing Branch (Pre 790501) 77/04/11 jp 15748 251
- --B210180430 Application for amend to Matl/Byproduct License 21-00265-06, (creating dosing of rats & mice to 1,500 uCi C-14 or tritium per animal & 10,000 uCi per animal for monkeys Ferwards revised "Radiation Protection Manual"
 LANGER, P. Dow Chemical Co 2344 77/07/07 URIGHT, E Redictioopes Licensing Branch (Pre 790501) ip 15748 336
- --e210180431 Advises that use of polonium/beryilium neutron source for testing instruments under Matl/Byproduct License 21-00265-06 will cease after reactor OL becomes effective, per licensee 670511 & 16 ltrs.
 BENZER, H H Daw Chemical Co 67/05/25 HADDICAN, W Atomic Energy Commission ip 15748 335
- --8210180432 Amend 33 to Hatl/Byproduct License Ri-00265-06, changing Condition 11 re use of licensed math, per 770404 ltr e Rediolsetopes Licensing Branch (Pre 790801) 77/04/25 ip 15748 252
- --8210180434 Application for renewal of Matl/Byproduct License 21-00265-06, authorizing any hyproduct matle w/Atomic Numbers 1-83,Po-210 & Am-241 in any form for use in R&D LAWDER:R R Dow Chemical Co 95118 78/06/14 AOpp 15748 268

- 8210133067 Add1 response to FOIA request for tape recordings of interviews w/F Oitz on 810225 & O604 Forwards dmitted transcript pages. W/o encl. FRITOM JM Division of Rules and Records 82/10/04 HICKEY, J. P. Stew, Fittman, Potts & Trombridge, ip 15758 353

- 82(0)(50079 Partial response to FOIA request for documents re NRC shutdown plan mentioned in weekly info rept for wx ending 810831 & SECY 81-600 & SECY 81-600A Forwards draft Manual Chapter 1302 FELTON.J M Division of Rules and Records 82/10/01 CONNOR.L Doc-Search Associates Ip 15758 312
- --8210050573 Forwards draft Manual Chapter 1302, "Shutdown Plan Contingency Plan for Periods of Lapsed Appropriations," for review & comment BARRY, L W Office of Resource Management, Director 82/09/03 NRC - No Detailed Affiliation Given 37pp 15758 313
- 82:0190094 Responds to FOIA request for NRC Annual Rept to Congress for 1981 Forwards document W/o encl FELTON.J M Division of Rules and Records 82/10/06 SCHULKE, S Affiliation Unknown ip 15758 310
- 82(0190112 Partial response to FDIA request for five categories of documents re SEP Forwards documents listed in App A App B lists documents evailable in PDR FELTON. J M Division of Rules and Records 82/10/06 GALLO. J Isham, Lincoin & Beale 3pp 15758 18i
- --8210190115 Responds to request for advice on applicability of general design criteria & 10CFR100. App A to older licensed facilities Stds of general design criteria must be used for assessing safety of all facilities
 SCINTO, J. Hearings Division 82/03/10 LAINAS. Q. Assistant
 Ofrector for Safety Assessment 4pp 15758 196
- -- 5210190121 Discusses ingal questions concerning re-review program
 Backfitting recommendations premature, pending re-review for
 particular case
 SCINTO, JF Hearings Division 76/09/03 QDLLER, K R Division
 of Operating Reactors 3pp 15758 200
- --8210190124 Responds to 800116 request for legal opinion re applicability of siting requirements of 100FR100 to operating plants App A elements should be used in seismic adequacy judgments for all reactors SCINTO, Jf Hearings Division 82/10/06 VOLLMER, R Division of Engineering 2pp 15758 203
- --8002080095 Requests consultation re operating reactors legal obligation to fulfill code requirements re seismic & geologic considerations of proposed sites VOLLMERR H Assistant Director for Systems & Projects 60/01/16 CHRISTENDURY, E Hearings Division 2pp 15758 209
- 82:01:90144 Responds to FOIA request for SECY 92-232 re use of nonplant-specific simulators for initial replacement & requalification exams for licensed reactor operators & senior operators FELTON, M. Division of Rules and Records 82:09/30 ARMSTRONG: K. A. Debevoise & Liberman 2pp 15760 178
- --8206180042 SECY-82-232

 Recommende requirements of simulator licensing exam be continued for power reactors w/plant-specific simulator Oral exam per iOCFR55.23 should be administered where facility has no plant-specific simulator DIRCKB, H J Office of the Executive Director for Operations 82/06/07 14pp 16002 236
- --B210190152 Advices that Commission has approved re contin new & specif MOYLE: DIRCKE
- 8210190189 Responds to J Hickey FOIA request for names & plant locations of ail US facilities licensed to possess 100,000 or more Cf Co-60 FELTON, J H Division of Rules and Records , 82/09/08 BUFFALD, V Cobe Laboratories, Inc. ip 15758 356
- --BR10190191 "Co-60 Irredistions w/Possession Limits of 100,000 Ci or Orester"

 4 NRC No Detailed Affiliation Given BR/09/0B 2pp 15758.337.
- 821021007; Responds to FCIA request for records re disposal of radwaste & chemical & medical wastes at St Albans Hosp in Gueens, NY NRC has no documents subj to raquest FELTON, J M, Division of Rules and Records. 82/09/30 FREEDBERG, L. Youth News 1p. 13774-314.

- 8210270083 Add1 response to FDIA request for eight categories of LERs Forwards documents listed in App A App B documents withheld (ref FDIA Exemption 5) FELTON, J M Division of Rules and Records 82/09/20 ARNOLD, J Miaml Herald 4pp 15836-221
- --8204300098 SECY-82-142
 Requests approval of draft Rept to Congress on AD
 (NUREO-0090) for Oct-Dec 1981
 DIRCMS.W J Office of the Executive Director for Operations
 82/04/02 40pp 15836 225
- --8208020047 Responds to B20403 memo re proposed AD Incident involving pressure transients during shutdown does not constitute AD Finding based upon analysis showing integrity of pressure vessel not impaired & fatigue life not affected MINDOUE.R B Office of Nuclear Regulatory Research. Director 82/06/22 MICHELSOR.C Director's Office Jpp 15836 282
- 8210280019 Responds to 750619 memo re QA Program Insp Rept 99700084/ 75-01 Info in rept does not establish reasonable basis for determining violation of criminal statutes Referral to DOJ inappropriate MCTIERNAN-T J Office of Inspector & Auditor 75/10/01 DAVIS, J G Office of Inspection & Enforcement, Office of the Director App 15860 070
- --0210280110 CRNL/NSIC-112 DRFT

 "Pressure Vessel Thermal Shock at US PWRs Events & Precursors, 1763 to Mid-1981," draft interim rept Related info encl

 PRUND.D L Dak Ridge National Laboratory FIN 8-0435 82/05/19

 Office of Nuclear Regulatory Research, Director 218pp 1984 092
- --8210280321 "Extremity Doses & Compliance w/Monitoring Regulations at Nuclear Power Plant"
 HUGGINS.T North Carolina, Univ of 62/06/30 11pp 15961 303
- B2iD2B0376 Responds to FDIA request for "Initial Guidance for Performance of Sys Interaction Analysis at Bilected LHRs" & "Initial Guidance on Diegraph-Matrix Analysis for Sys Interaction "Forwards repts W/o enci FELTON.J M Division of Rules and Records 82/09/14 FADRIZIO.R F Boston Edison Co 1p i5839 118
- 8210280402 Addl response to FDIA request for SECY-82-232 & SECY-82-202 Documents listed in App A available in PDR FELTON.J N. Division of Rules and Records 82/09/30 DUCKLES.R Affiliation Unknown 2pp 15859 101
- --8210280406 Commissioner Absarns Affirmation response sheet re SECY-82-202.amend to 10CFR140, "Financial Protection Requirements & Indomnity Agreements " Comments encl AMEARNE, J. NRC - No Detailed Affiliation Given 82/06/16 3pp 15859 103
- --82:0190198 Staff requirements memo re 820701 affirmation session concerning SECY 82-202 on amend to 10CFR140 9, "Financial Protection Requirements & Indemnity Agreements "Objections to publication of apps as reg guides due by 820719 CHILK, 8 J. Office of the Secretary of the Commission M820701 82/07/06 DIRCKS, W.J. Office of the Executive Director for Operations 2pp 15859 106
- 8210290020 Responds to FDIA request for RFP R8-01E-82-25; "Gafety Aspects of Industrial Radiography Course" & related info Forwards document H/o enc! FELTON. J M Division of Rules and Records 82/10/01 WILLIAMS. D T Affiliation Unknown 1p 15877 072
- 8210290027 "Annex i, Cost Benefit Analysis of Proposed Rule 73 47 of 10CFR73" List of commentors encl
 * NRC No Detailed Affiliation Given 82/09/03 57pp 15844 197
- --8210270032 Discusses impact of proposed sefeguards upgrade rule on nonpower reactors Paper requesting exclusion of nonpower reactors from rule will be initiated MILLER, J R Standardization & Special Projects Branch 82/09/03 SYELLO, V Division of Operating Reactors 4pp 15864 255
- --B210290053 "Licensess-SNM of Hoderate Strategic Bignificance (Category II)"

 * NRC No Detailed Affiliation Given 78/12/05 3pp
 \$5864 267
- --8210290058 "Category 11 Nonpower Reactor Licenses Holdings as of Jan 1979 "
 4 NRC - No Detailed Affiliation Given 82/09/03 2pp 15854 270

- --8210240061 Responds to Commission request for rept on safeguards self-protection criterion impact of safeguards upgrade rule on 23 affected nonpower reactors would be severe Financial expense would force many reactors out of operation DENTON, H. R. Office of Nuclear Reactor Regulation, Director 79706/20 HENDRIE, J. GILINSKY, V. KENNEDY, P. Commissioners 5pp. 15845-065
- --9210290065 Comments on new Commission paper re upgrade rule Nonpower reactors should be exempt from rule Legal backup needed in event of public meeting HILLER, JR Assistant Director for Reactor Bafeguards 79/06/28 BURNETT, R Division of Safeguards 2pp 15865 070
- --B210270067 "Dose Rate Due to Irradiated Fuel "

 + NRC No Detailed Affiliation Given 81/04/14 Spp
 15805 088
- B210270085 Responds to FOIA request for lists of names & addresses of all NRC licensees in HE.VT.MA.OH.CT & WV & appropriate ofcs in Agreement States of NH.RI.NY & MD Forwards requested lists FELTON, J M Division of Rules and Records 82/10/15 PARKINSON, T W Interstate Nuclear Services ip 15863 311
- --8210290090 Lists of active licenses for States of MA,VT,ME,CT,OH & U. & Agreement States as of 820910 4 NRC - No Detailed Affiliation Given 82/10/07 240pp 15963 312

GEN TEC 18 GENERIC TECHNICAL ISSUES

- 8206060002 Appeals denial of FOIA request for segregable portions of draft NUREO-0844, "Resolution of Unresolved Safety Issues A-3.A-4 & A-5 Re Steam Cenerator Tube Integrity UDELL,R A Critical Mass Energy Project 82/06/04 DIRCKS,H J Office of the Executive Director for Operations 2pp 15668 333
- 8207180066 Forwards edited version of draft on pressurized thermal shock w/substantive changes proposed KOUTS.H Brookhaven National Laboratory KOUTS.H ACRS Advisor Committee on Reactor Safeguards 82/08/10 IONE.E ACRS Advisor Committee on Reactor Safeguards 22pp 15852 012
- 8209280424 Discusses status of pressurized thermal shock short term recommendations ACRS Horking Ordup on Metal Components meeting scheduled for 820930 to continue discussion Forwards draft "NRC Staff Evaluation of Pressurized Thermal Shock "DIRCKS.H J Office of the Executive Director for Operations 82/09/20 PALLADINO,N. GILINSKY.V., AHEARNE.J F Commissioners 2pp 15670 033
- --8210120335 "NRC Staff Evaluation of Pressurized Thermal Shock." dra rept Apps enc! 4 Office of the Executive Director for Operations 82/09/13 393pp 13670 035
- 8210010286 Concurs that NUREG-0744. "Resolution of Reactor Vessel Matls Toughness Eafety Issue," need not be reviewed by CROR STELLO, V Regional Operations & Generic Requirements 82/09/30 DENTON, HR Office of Nuclear Reactor Regulation, Director, 1p 15573 881
- 8210080015 Add1 response to FOIA request for 19 categories of info representation events & safety problems. Forwards documents listed in App A Documents in App B completely withheld (reffOIA Exemption 5)
 FELTON, J M Division of Rules and Records 82/07/12 UDELL. H A Critical Mass Energy Project 9pp 15665 027 · 24X
 Fiche 50-000. 82/07/12. 8210080015
- --B011060346 Discusses licensee responses to NRC request to commit interim position re Generic Item B-24 venting & purging containments while at full power Plants meet interim position & existing TACs should be closed out REEVES.E A Operating Reactors Branch 1, 80/08/25, Cherati
- ---Bi06220159 Supports efforts in restiving purge valve leakage & operability issues Incorporation of leak testing position into Tech Specs should assure leakage integrity of containment BAERRAL Reactor Engineering Branch. 81/06/09 BUTLER, W & Containment Systems Branch. 2pp 15668 153

- --Bi07170126 Comments on proposed iE bulletin re leakage of reactor bldg purge vaives Issuance not merited for reasons indicated Centeric Issues B-20 & B-24 provide assurance of increased surveillance testing & reduced excessive leakage SMIZZEKJ H Director's Office IEC-77-11 Bi/07/01 OFFEILY.J P. Region 2, Atlanta, Office of the Director (Bi/03/01) 2pp 15668 151
- --B210CB0037 "Cost of Upgrading Capability to Isolate LPMR Main Feedwater Sys in Event of Breats Inside Containment," final reptiper statement of work for DDE Work Order 20-81-165, "Program for Cost Estimation for Proposed Safety Requirements " EEARDEN.R O EONG, Inc FIN A-6452 RGB-2-82 82/03/17 15pp 13563 149
- --BIO5220157 Supports efforts in resolving purge valve leakage & operability issues incorporation of leak testing position into Tech Specs should assure leakage integrity of containannt BAER.R L Reactor Engineering Branch 81/06/09 BUTLER.W R Containment Systems Branch 2pp 15668 153
- --BIO7170126 Comments on proposed IE builetin re leakage of reactor bldg purge valves issuance not merited for reasons indicated Generic Issues B-20 & B-24 provide assurance of increased surveiliance testing & reduced ercessive leakage SNIEZEKJ M Director's Office IEC-77-11 Bi/O7/O1 O'REFLLY, J.P. Region 2. Atlanta, Office of the Director (BI/O3/O1) 2pp 15668 151
- 6210080021 Summary of 253rd ACRS meeting on 810507 re control sys fallures that could cause or exacerbate nuclear power plant accidents per Task Action Plan A-47
 ASMS-F. Reactor Operations Analysis Branch AEDD/E114 81/06/24
 AICHELSON.C Director's Office 23pp 15669 073
- EXIOOB0059 Responds to appeal re denial of FDIA request for segregable portions of draft NUREO-0844. "Resolution of Unresolved Safety Issues A-3.A-4 & A-5 Re Steam Generator Tube Integrity "Request denied (ref FDIA Exemption 5) DIRCKS.RJ Diffice of the Executive Director for Operations 82/07/19 UDELL.R A Critical Mass Energy Project 2pp 15669 331
- E21008013B Forwards "Potential for Water Hammer During Restart of RHR Pumps for EMR Nuclear Plants" HUANDY 5 Director's Office. AEOD/C105 01/03/31 MICHELEDN.C Director's Office ip 15663 255
 - 9210039165 "Potential for Water Hammer During Restart of RHR Pumps for ELR Ryclear Plants " HUMBJ Director's Office AEOD/E105 81/03/31 14pp 13663 256
 - 10080169 Forwards "Initial Consideration of Potential for Water Paper in Steam Condensing Mode of RHR Gys Operation for BWR Plants " HUNNOV S Director's Office AEOD/E106 81/03/31 MICHELSON. C Director's Office ip 15663 271
 - -P210080172 "Initial Consideration of Potential for Water Hammer in Size Condensing Mode of RHR Sys Operation for BHR Nuclear Plants" MURDJ Director's Office AEOD/E106 B1/03/31 11pp 15663 272
 - 2:00:80294 Forwards "Review of Emergency Response Quidelines Refressmized Thermal Shock "
 RINSEEV.0 D Westinghouse Operating Plants Owners Group
 RINSEEV.0 D Alabama Power Co 00-72 82/06/22 DENTON.H R
 Office of Nuclear Reactor Regulation. Director ip. 15638 208
 - --EMOCEO297 "Review of Emergency Response Quidelines Re Pressurized Thereal Shock "
 Restinghouse Electric Corp 82/06/30 Bapp 19638 209
 - P210150552 MUREO/CR-2791
 NEHMOSLO2Y FOR EVALUATION OF INSULATION DEBRIS EFFECTS
 Continuant Emergency Sump Performance, Unresolved Sefety
 Issula-43
 NEOKRIJ J. KOLBE, R. Sandia Laboratories FIN A-1276 SAND#2-7067
 B2/89/30. Division of Bafety Technology 271pp Available at
 NC 48 00 15725.005
 - 82(6)00002 Requests attendance at CROR Meeting 23 on B21028 in Eilhesfa:ND to discuss cost/banefit info for elternatives for receiving pressurized thermal shock issue SELD.V. Committee to Review Generic Requirements B2/10/14 EISDAV,DQ, Division of Licensing DRDAN.E L Division of Enjacering & Quality Assurance. CUNNINGHAM.R E Diffice of Nuclear Natural Esfety & Bafeguarde, Director. 1p 15718.024

- 8210250156 Notification of CRGR 821110 25th meeting in Bethesda, MD to discuss proposed revision to 100FR20 on stds for protection against radiation, proposed amend to 100FR50 re radiation protection programs & Unresolved Safety Issue A-43 STELLO, V Regional Operations & Generic Requirements 82/10/22 EISENHUT.D G Office of Nuclear Reactor Requirements 02/10/22 EISENHUT.D G Defice of Nuclear Reactor Regulation, Director JURBAN.E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM.R E Office of Nuclear Material Safety & Safeguards, Director ip [5788-288]
- 8210280044 Summary of ACRS Ad Hoc Metal Components Subgroup 820511-12 meetings in Washington.DC repressurized thermal shock problem * ACRS Advisory Committee on Reactor Safeguards 82/07/27 ACRS Advisory Committee on Reactor Safeguards 17ap 15862 336
- 8210290118 Forwards, for info, draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission decision due 821030 M/o enci LAINAS, C C Assistant Director for Operating Reactors 82/09/20 ROCHINO, L Babcock & Hilcox Operating Plants Duners Group RDCKING, L General Public Utilities - GPU Service Corp 2pp 15846-358
- 8210290450 Forwards, for info.draft rept & apps on pressurized thermol shock Completed rept will form basis of Commission paper due 821030 W/a encl LAINABO & Assistant Director for Operating Reactors 82/09/20 HI00INS.P Atomic Industrial Forum 2pp 15863 181
- B210290453 Forwards, for info, draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission paper due B21030 M/o encl
 LAINAS, C C Assistant Director for Operating Reactors B2/09/20 BASKIN, K C-E Operating Plants Owners Group 2pp 15863 185
- 8210270458 Forwards for info draft rept & apps on pressurized thermolyshock Completed rept will form basis of Commission paper due 821030 W/o entl
 LAIMAS.O.C. Assistant Director for Operating Reactors 82/09/28
 KINGSLEY.O. Westinghouse Operating Plants Duners Group KINGSLEY.O.
 Alabama Power Co. 2pp. 19863-183

INSPECTION AND ENFORCEMENT

- 8208190233 IE info Notice 80-35, Suppl 1. "Leaking & Disladged I-125 Implent Beeds" Svc list end COBSL I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & Spp 1974i 250 24
- 8208170238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall/Large-Diameter.Stainless Steel.Recirculation Sys Piping at BNR Plants "Svc list encl BEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 13810 125 24X Fichs 30-000, 82/10/14-8208170238
- 82:0040130 PNO-III-82-102 on 820926, lead container marked radioactive matl found on Cleveland. OH street Hipe survey showed container to be free of radioactive container to the free of radioactive containing Container reportedly mislabeled to discourage theft from auto LASUK. S R . SHENIAHSKI. D J Region 3. Office of Director 82/09 ip 19381 212
- 8210040337 PNO-JII-B2-100 on 820924, stop work order issued for preparatory remedial soils identified problems w/certi per confirmatory action its QARDNER, Region 3, Office of a second problems and a second problems.
- 8210050224 PNO-II-92-105 on 820925,100 mCI Cs-137 mins logging source discovered missing Search of mins premises detected slightly slevated radiation level in one area of coal car POTER, J. 91880N.A Region 2. Office of Director 82/09/30 App 15611.024
- 8210050314 PNO-111-82-104 on 820903:40 42 mCi Ir-172 seeds removed from patient on 820605 determined to be missing Search continuing W/assistance of two NRC inspectors MATSON, E R. BRENIAMBKI, D. J. Region 3, Office of Director 82/09/29 2p 15602 360
- 82:0070265 PNO-THI-82-020 on 82:005; game poacher apprehended on util property & turned over to state police & Game Commission No vital areas threatened Security increased Licensee will issue press release.

 WIEDE, J. Region I. Office of Director. 82/10/06 ip.

- 92(0150496 EN-82-026A on 820722, order to show cause & order suspending license effective immediately issued to Midstate Testing Lab Action based on licensee apparent abandonment of radiographic facility & licensed matl BROCKETT, X AXELRAD, J Director's Office, Office of Inspection and Enforcement 82/10/14 2pp 15714 188
- B210150507 PNO-111-82-109 on B21007, US Army infinity aiming collimator containing 10 Ci gaseous tritium discovered missing Theft suspected State of IL-local police & defense contract administration motified OBERO.C T. HIEDEMAN, D.G. Region 3: Office of Director B2/10/12 ip 15713-208
- 8210190673 PNO-III-82-110 on 821011. Trovier soil density & maisture gauge W/Cs-137 & Am-241 scaled sources reported stolen from const sate in Ashland. Hi Significant inadvertent exposure unlifely since warming Jabels attached OBERG. C. T. WIEDEMAN. D. G. Region 3. Office of Director 82/10/13 1p 15737 253
- 8210250055 FND-V-82-043 on 821016 unusual event declared when grass fire started in 500 kV switchyard On B21017, three 500 kV circuits tripped resulting in loss of all offsite power Second unusual event declared STERNBERO, D M Region 5. Office of Director B2/10/16 ip 15787 100
- 8210260471 PNO-III-82-113 on 820917.Victoreen Model 848-8 calibrator containing 112 mCi of Cs-137 shipped w/o proper warning labels or shipping papers Calibrator discovered in storage on 820924 & read 12 millirem/hour Caused by personnel error SREMIAMSKI.D J . MILLER.J R Region 3. Office of Director 82/10/19 lp 15807 229
- 8210260493 PND-1-82-047 on 821022, kinetic expansion conducted on eight rows of tubes in B once-through steam generator Expansion involves controlled detonation within tube Some media attention expected CONTER Region 1, Office of Director 82/10/22 ip 15806 232
- 8210280072 EN-82-030A on 821026, decision re 820827 order to show cause & order modifying License 41-19870-01 issued Since licensee took adequate corrective actions on violations. License will not be revoked Order to modify license further furthcoming FLACK, F., AXELRAD. J Director's Office, Office of Inspection and Enforcement 62/10/26 to 13837 146
- 8210280073 EN-82-031A order issued rescinding 820903 order to show cause & order temporarily suspending license of Orion Chemical Co Licensee 820924 response describing corrective actions acceptable AXELRAD, J Director's Office, Office of Inspection and Enforcement 82/10/24 ip 13837 164
- USC PURT TO INCUMENT ROOM MISCELLANEOUS

- 0210070476 Forwards findings & recommendations re 810115 memo on requirements offsite power sys design criteria ASHE,F Director's Offsice ACOL/Elio 81/04/29 MICHELSON.C Director's Offsice 4pp 15637 358
- 8210070481 Recommends actions to be taken to lower rate of occurrences of inoperability of instrumentation due to extreme cold weather Suppl to IE Bulletin 79-24 directing changes to Tech Specs should be issued HICHELSON,C Director's Office ACOD/E112 81/06/15 DENTON,H R Office of Nuclear Reactor Regulation, Director STELLO,V Director's Office of Inspection and Enforcement Spp 13644 353
- 8210080057 Summarizes findings of LER review to determine patterns of setpoint drift occurrences for Darton Model 288 instrument for 1975-80 Changes to procedures for BURS w/o analog safety sensor sys recommended ASHE,F Director's Office AEOD/Ei18 81/07/20 MICHELSON,C Director's Office 2pp 15667 324
- B210120073 Compares reactor coolant pump events contained in LERs, NRRDs, RECON & plant records Search indicates little confidence can be placed in single reporting sys.but such mys should be developed BROMN, E. J. Director's Office AEOD/EOO3 BO/O6/19 MICHELGON, C. Director's Office 11pp 15689 172
- 8210120370 Discusses iE Bulletin 80-21, "Integrity of Polymer Coating for Surfaces Inside Containment " Coating developed by Con-Chem.Int could fail when subjected to DDA conditions, releasing debris through sump screen MICHELSON, C Director's Office AEOD/E011 80/08/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15690 1/O
- 8210120372 "Burvey of Valve Operator-Related Events Occurring During 1978.1979 & 1980 "
 BROWN, E. J., ASHE, F. S. Director's Office AEOD/C203 82/05/36
 S8pp
- 8210130545 Forwards abstract & summary cover sheet for gaper re testing of 1/4-inch expansion anchors in repaired concrete Review requested for consideration of paper as candidate for presentation at Aug 1983 SHMRT-7 conference TOGNI.C S Public Service Co of Indiana. Inc 82/10/07 WILLIAMS.M Office of Nuclear Reactor Regulation, Director 15682 287
- 0210150090 Forwards statement of consideration of biomedical wasts disposal published in FR when NRC adopted 10CFR20 304 Adoption of regulation does not pose unreasonable radiological risk to public health & safety M/o enci BURNS 8 0 Regional Operations & Enforcement Division 82/10/07 SCHEVERMANN, K KS Processing Co. Int. 19 15701 197
- 9210260554 Forwards Engineering Planning & Mgt, Inc analysis of NRC sponsored fire tests evaluating 20-ft separation criteria.
 NOTLEY, DP Electrical Engineering Branch 82/09/29 KNIGHTON. O W Research & Standards Coordination Branch 67pp 15830 193
- B210280431 Submits NRC findings re-Phibro-Salamon, inc application for proposed import of 300,000 tons U from Australia, South Africa & other countries Proposal conforms w/std provisions MODRE, R N Office of International Programs, Director 92/09/2& Office of International Programs, Director ip 15860-055

NUREO REPORTS AND RELATED CORRESPONDENCE

- 8206060002 Appeals denial of FOIA request for segregable portions of draft NURGO-0844. "Resolution of Unresolved Bafety Issues A-3.A-4 & A-3 Re Stam Generator Tube Integrity UDELL-R A Critical Mass Energy Project 82/05/04 DIRCKS, H J. Office of the Executive Director for Operations 2pg 15668 333
- B207180061 FOIA request for documents re-pre-implementation review of NUREO-0737. Item II F 2. CONNOR.L Doc-Bearch Associates B2/07/01 Division of Fluies (Records, 1) 15669 096
- 8207290410 NUREG/CR-2229 V02
 BUR LARGE BREAK BIMULATION TESTS-BUR BLOWDOWN/EMERGENCY CORE
 COOLING PROGRAM Volume 2-Appendices I-N
 LEFL 8. General Electric Co FIN 8-3014 GEAP-24962~2. E2/O7/
 Division of Accident Evaluation 552pp. Available at NTIB
 413 00 14126 OOL

- 8:38290017 Summarizes 269th ACRS meeting on 820909-11 in Washington, DC to proposed tafety goals, radioactive math packaging for transport, testing requirements for diesel generators & integrated bugan factors program plon
 SECHSULP ACRS Advisory Committee on Reactor Safeguards
 SL-0278 82/07/21 PALLADING, N J Commissioners 3pp 15647 236
- B209280307 NUREO/BR-0024 NORALNO BAFELY IN OAMMA RADIOGRAPHY A TRAINING MANUAL FOR NOVASTPIAL RADIOGRAPHERS MCOURE, B A , PEABODY, C A Office of Nuclear Regulatory Research, Director 82/09/30 168pp
- E21001000B Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON-J H Division of Rules and Records. E2/06/28 UDELL-R A Critical Mask Energy Project 15pp 18727 005 24% Face 50-000.82/06/28.821001000B
- --8210040379 Submits review of IE ineps of operating PWRs related to eallowup actions identified in NUREO-0138 Sensitivity analyses recommended gruent Branch 77/12/RB EJSEN-JUT, D 0 Givision of Operating Reactors 12pp 15727 285
- -- P210040396 Submits evaluation of recommendations contained in NURLG-0651. "Evaluation of Steam Generator Tube Rupture Events" Licensess should investigate other techniques to more rapidly determine damage RARRE Safety Program Evaluation Branch 81/02/17 MURLEY. T Division of Espety Technology 26pp 15728 007
- --SQ10240413 Submits evaluation of NUREG-0667, "Transient Response of BUH Distance Reactors " Recommends related studies be combined is specified Priority 2 items implemented by expanding an elisting task in TMI action plan MAISGUR. Division of Safety Technology 90/08/08 DENTON, H R Office of Nuclear Reactor Regulation. Director 43pp 15727 199
- -- GIIIG 1920 I Responds to inquiry into status of BUR scram discharge volumes to the state of BUR scram discharge volumes to be stated to the state of the state
- --8109270056 Forwards concurrence on NUREO-OBO3, "Ceneric Safety Evaluation re Integrity of BHR Scram Bys Piping " Any significant changes will be provided for consideration MICHELSON, C Director's Office 81/07/30 EISENBUT, D 9 Division of Licensing 3sp 19730 OB3
- -811030201 Responds to inquiry into status of DWR scram discharge volgig trust safety concerns NUREG-0803 contains guidance for resolving outstanding issues on plant by plant basis RUBINS D Director's Office 81/10/02 LEWIS, M J. Affiliation Uninown ip 19730 336
- -qiqqiqqqo Forwards findings to recommendations for J Elin 810115 memo retraquirements of preferred or offsite power sys ASME, F Director's Office 81/04/29 MICHELBON, C Director's Office 4pp 15729 070
- -8109240007 Comments on NUREO/CR-1699 Vol 2: "Reactor Bafaty Study Reflacingy Application Program Ocones 3 PWR Power Plant " EDWINGR L Director's Office 81/09/15 Director's Office 2p 65589 237
- EXECTION Comments on proposed rule IOCFR50 rs mandatory property instance for decontamination of nuclear reactors & MREC-0891, "Nuclear Property Insurance Status & Outlook "Operes rule WRK.F & Mississippi Power & Light Co 47FR27371 041 82/09/24 Office of the Secretary of the Commission in 15568 019
- ©10010286 Concurs that NUREO-0744, "Rasolution of Reactor Vessel Natt Toughness Sefety Issue," need not be reviewed by CROR SELLO, V Regional Operations & Ceneric Requirements 62/09/30 text06/HR Office of Nuclear Reactor Regulation, Director ip 13373-181

- 8210010307 Package of three comments opposing proposed rule (QCFR50 re mandatory property insurance for decontamination of nuclear reactors
 OIESLER.C H Wisconsin Public Service Corp WITHERS.B D Pacific Qas & Electric Co KELLY.A B American Nuclear Insurers
 47FR27371 82/09/28 CHILK.S J Office of the Secretary of the Commission 19pp 19549 289
- 8210010331 Package of four comments on preposed rule 10CFR50.
 "Mandatory Property Insurance for Decontamination of Nuclear
 Reactors" Supports rule
 MYATT.JM Louisiana Power & Light Co DELLSY.H M Commonwealth
 Edison Co ROBERSON.C O Houston Lighting & Power Co 47FR27371
 82/09/24 Deciting & Services Granch 22pp 15573 059
- 82:004031: Forwards Revision 4 to SCP-01-A. "RABCAL Gamma Thermometers as Local Power Heastring Devices for Use in Cores of PMRs."

 per NUREG-0390

 WARING.J P Scandpower, Inc 82/09/29 BERNARD, H Standardization

 & Special Projects Dranch 1p 15584 198
- 82:0050360 NUREG/CR-2792
 AN ASSESSMENT OF RESIDUAL HEAT REMOVAL AND CONTAINMENT SPRAY FUND PERFORMANCE UNDER AIR AND DEBRIS INSESTING CONDITIONS KAMATH.P S , TANTILLO.T J , SWIFT.W L Creare, Inc | FIN A-1237 B2/09/30 Division of Safety Technology 110pp Available at NRC 45 50 15625-010
- 8210050368 NUREQ/CR-2905
 RAMAN SCATTERING TEMPERATURE MEASUREMENTS FOR WATER VAPOR
 IN NON-EQUILIBRIUM DISPERSED THO-PHASE FLOW
 AMASTASIA.C M. NETL.S. SMITH.W.R. Lehigh Univ. FIN 8-6794
 82/09/30 Division of Accident Evaluation 204pp Available at
 NRC \$7 OQ 15624 061
- B2100503BB NUREQ/CR-2761
 RESULTS OF VORTEX SUPPRESSOR TESTS.SINGLE QUILET SUMP TESTS,
 AND MISCELLANEOUS SENSITIVITY TESTS
 PARMANARIAN.H Alden Research Laboratory * Sandia Laboratories
 FIN A-1237 SAND82-7065 82/09/30 Office of Nuclear Reactor
 Regulation, Director 115pp Available at MRC *6 50 19625 120
- 8210050397 NUREO/CR-2606
 ANALYSES OF 1/13 SCALE CREASE BYPASS TRANSIENT EXPERIMENTS
 KMETYK L N . DUXTON L D . COLE, R K Gandia Laboratories FIN
 A-1115 SANDS-1992 82/09/30 Division of Systems Integration
 (post B11005) 61pp Available at NRC \$9 00 15625 329
- 8210050412 NUREO/CR-2920
 BEHAVIOR OF REIMFORCED CONCRETE SLABS SUBJECTED TO COMDINED FUNCHINO SHEAR AND BIAVIAL TENSION
 JAULE C. WHITE.R N. OEROELY.P. Cornell Univ 92/09/30
 Division of Engineering Technology 103pp Available at NRC 45 50 15624 266
- 0210050418 NUREO/CR-2754
 CRITICAL REVIEW OF STUDIES CN ATMOSPHENIC DISPERSION IN
 COASTAL REGIONS
 SMEARER, D.L.: KALEEL, R.J. TRC Environmental Consultants, Inc. *
 Dattelle Hemorial Institute, Pacific Northwest Laboratory FIN
 B-2304 PNL-4292 02/09/30 Division of Health, Siting &
 Environment 59pp Available at NRC \$4.75 10420 237
- 8210030428 NUREO/CR-2897
 CALCULATIONS OF HYROGEN DETONATIONS IN NUCLEAR CONTAINMENTE
 BY RANDOM CHOI (E RETHOD
 DELICHATBIOS, M., GENADRY, M.D., FARDIS, M.N., Massathusetts Institute
 of Technology FIN 8-7085 82/09/20 Division of Engineering
 Technology 215pp Available at NRC 97 50 15612 117
- 8210030431 NUREC-0858
 COMPARISON BETHER FIELD DATA AND ULTIMATE HEAT SINK COOLING POND AND EPRAY POND MODELS
 CODELL, R B Division of Engineering 82/09/30 67pp Available at NRC #5 00 15626 108
- G210060004 NUREO/CR-1369 ROI
 PROCEDURES EVALUATION CHECKLIST FOR MAINTENANCE, TEST AND
 CALISMATION PROCEDURES USED IN NUCLEAR POWER PLANTS
 SRUNE, R. L. WEINSTEIN, M. HPT. Inc. & Candia Laboratorias FIN
 B-309B SAMDRO-7034 82/09/30 Division of Reactor Programs
 25pp Available at NRC 43 50 15636.308
- 8210060417 NUREO/CR-2260 ERR Errata, Changing Report Number Of MUREO/CR-2260 To NUREO/CR-2260 To.AN ANALYBIB OF PROPOSED INLET FLOW BLOCKAGE EXPERIMENTS USING MAYU-46 4 EG&G. Inc E00-2181 82/06/30 Opfice of Nuclear Regulatory Research, Director 1p 15636 242

- B210070007 Responds to F0iA request for eight categories of records restram generators & steam turbines App A documents provided in R Udell F0iA Request B1-313 Forwards documents listed in App B FELTON. J M Division of Rules and Records 82/08/10 LONG, D J Hinthrop, Stimson, Putnam & Ruberts 9pp 15645 063 24X Fiche S0-000-82/08/10.8210070007
- --B203260003 Recommends that BTS limits for coolant activity & sampling requirements be incorporated into remaining operating plant. Tech Specs w/other substantive change requests lodine dose problems can be avoided by limiting coolant. HOUSTON.R W. Assistant Director for Radiation Protection. 82/03/04. NOVAK.T. Assistant Director for Operating Reactors. 2pp. 15445-285
- 8210070029 Partial response to FDIA request for documents re CRBR EIS & all comments evaluations & documents from BNML re EIS Forwards documents listed in App A FELTON. JM Division of Rules and Records 82/07/16 WEISS.E R Harmon & Weiss 8pp 15648 004
- --8210070123 Forwards updated responses to comments on 1976 DES.
 NUREG-0137 re safequards & fuel cycle (nfo re radwaste shipments, disposal site & licensed burial site included LOMENBERG.H Office of Nuclear Material Bafety & Safeguards, Director CRBR 82-69 82/06/15 LEECH.P Clinch River Breeder Reactor Program Office 15pp 15648 073
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)

 FELTON-J M Division of Rules and Records 82/07/12 UDELL-R A Critical Mass Energy Project 9pp 15665 027 24X

 Fiche 50-000, 82/07/12, 82/0080015
- ~-8210080057 "Cost of Upgrading Capability to Isolate LPWR Main Feedwater Bys in Event of Breaks Inside Containment," final rept.per statement of work for DOE Mork Order 20-81-165, "Program for Cost Estimation for Proposed Safety Reguirements" DEARDEN.R G EG&G. Inc FIN A-6452 RGB-2-82 B2/03/19 15pp 15565 168
- --G21Q0B0215 Forwards revised IE organizational charts & functional statements for review & comment Reorganizations of 6201Q4 & 25 will be incorporated in NUREQ-0325 BLAHA.J L. Program Support Branch 82/04/27 LIEBERMAN.J Enforcement Staff FORTUNA, R. Director's Office. Office of Inspection and Enforcement COBB.L I Division of Fuel Facilities. Materials & Safeguards 7pp 15668 261
- --8203040536 Comments on BliZIB corrections to facility assessment contained in NUREG-0834 re hearings & discussion of systematic assessment of license performance Revision to NUREO inappropriate issue closed MOSELET: N C Systematic Assessment of Licensee Performance Review Group 82/01/04 WESSMAN.R H NRC No Detailed Affiliation Given ip 15668 256 24% Fiche 50-000:82/07/12.8210080015
- 8210080020 Responds to FOIA request for documents re preimplementation of NUREG-0737, Item III F 2 Forwards documents listed

and Records 82/09/16 CONNOR.L

ntation

10

able

- 8210120092 NUREO/CR-2873 VO2
 NUCLEAR FUEL CYCLE RISK ASSESSMENT DESCRIPTIONS OF
 REPRESENTATIVE NON-REACTOR FACILITIES Sections 15-19
 SCHNEIDER,K J. SICKFORD,W E. DALINO,P M Battelle Memorial
 Institute, Pacific Northwest Laboratory FIN 0-2402 PNL-4306,
 B2/09/30 Division of Risk Analysis 361pp Available at NRC
 89 00 15587 328
- 8210120102 NUREO/CR-2873 V01
 NUCLEAR FUEL CYCLE RISK ASSESSMENT DESCRIPTIONS OF
 REPRESENTATIVE NON-REACTOR FACILITIES Sections 1-14
 SCHNEIDER, K J. BICKFORD, W E. DALINO, P M Battelle Memorial
 Institute: Packfic Northwest Laboratory PIN B-2402 PNL-430,
 BZ/097/30 Division of Risk Analysis 376pp Available at MIC
 99 50 13686 313
- 9210120116 NUREG-0748 VOZ NOS OPERATINO REACTORS LICENSING ACTIONS SUMMARY Data As DF August 31,1982 (Grange Book) * Management Information Branch 82/09/30 355pp 15685 J[V
- 8210120119 NUREG-0580 VI1 NO9
 REQULATORY LICENSING STATUS SUMMARY REPORT Data As Of
 September 15, 1982 (Blue Book)
 * Management Information Branch 82/09/30 43pp 15689 004
- 8210120125 NUREO/CR-2820
 RESOLUTION OF SHIPPER-RECEIVER DIFFERENCES
 JOHNSTON, J H . BROWNS.R J , STEWART, K B Battelle Memorial
 Institute, Pacific Northwest Laboratory FIN B-8103 82/09/30
 Division of Facility Operations 117pp Available at NRC 47 20
- 821013038; Comments on proposed rule 10CFR50 re mandatory preperty insurance for decontamination of nuclear reactors (NUREO-0891) Imposition of blanket coverage requirement poses restrictive economic hardship on smaller plants TAYLOR.J W Dairyland Power Cooperative 47FR2737; 042 02/09/17.3 Office of the Secretary of the Commission 2pp 19681 001
- 8210130539 Forwards will comments on proposed rule 100FR30 re mandator property insurance for decontamination of nuclear reactors (NUREG-0891) FLYNN B F Carolina Power & Light Co 47FR27371 044 82/89/29 W000, R B Office of State Programs, Director 1p 15682 22.1
- --B210k30550 Comments on proposed rule 10CFR50 re mandatory property insurance for decontamination of nuclear reactory (MMR0-QB91) Present requirements re property insurance adequate to assure sufficient funds for decontamination BARHAM-C D Carolina Power & Light Co 47FR2791 044 122/49747 CHILK, B J Office of the Secretary of the Commission 12pp
- 8210130554 Comments on proposed rule 10CFR30 re mandatory property insurance for decontamination of nuclear reactors (NUREO-COB9) MITTLIR L Public Service Electric & Gas Co of New Jersey 47FR27371 043 82/09/24 CHILKIS J Docketing & Services Uranch Cop 15584 001
- 8210190547 NUREO-0750 V15 NO5 NUCLEAR REGULATORY COMMISSION ISBUANCES May 1982, • Division of Technical Information & Document Control 1927() D. F. 31 275pp. 15722 Oct
- 6210150548 NUREC/CR-2404
 ANALYZING SAFEQUARDS ALARMS AND RESPONSE DECISIONS
 AL-AYAT, R A , JUDD, B R : MCCORD, R K Laurence Livermore Labtur Detail
 FIN A-0115 UCRL-53034, 82/09/30, Division of Facility
 Operations 115pp Available at NRC, 85 00 15726 133
- 8210|50549 NUREO/CR-2831 A TEST OF THE CONTROLLABLE UNIT APPROACH (CUA) CONCEPT IN A LOW-ENRICHMENT URANIUM FUEL-FABRICATOR FACILITY FOSTER, K & Hound Laboratory/Monsanto FIN A-1075 NLM 245/ 82/10/31 Safeguards Branch 108pp 15724-061
- 8210150550 NUREO/CR-2009
 A TECHNICAL TEST DESCRIPTION OF THE NRC LONG-TERM WHOLE ROD
 AND CRUD PERFORMANCE TEST
 EINZINGER/R E., FISH/R L Hanford Engineering Development
 Laboratory, FIN 8-2435 HEDL/THE 82-32. 82/09/30 Bivision
 Engineering Technology. 77pp Available at NRC \$5.00 IS Full
- 8210150552 NUREG/CR-2791
 METHODOLOGY FOR EVALUATION OF INSULATION DEBRIS EFFECTS
 Containment Emergency Sump Performance, Unresolved Safety
 Issue A-43
 MYSICKI, J. KOLBE, R. Sandia Laboratories FIN A-1296 RAND FSD:
 82/09/30 Division of Safety Technology, 271pp Available
 NRC. 48.00 15725 005

```
E313150553 NAREO/CP-0030

$1790510H ON UNBATURATED FLOW AND TRANSPORT MODELING
$17905
```

₹10130555 INREO/CR-2885

MCCUANISH AND CORRELATION OF DROPLET ENTRAINMENT AND

GEOSITION IN ANNULAR THO-PHASE FLOW

ESTACUA I. ISHI'N Argonne National Laboratory FIN A-2026

ESTACUA I. ISHI'N Argonne National Laboratory FIN A-2026

ESTACUA I 18409/30 Division of Accident Evaluation 74p;

5725 (8)

C120337 NUREO/CR-2839
CALUATION OF AIRCRAFT CRASH HAZARDS FOR NUCLEAR POWER
CALUATO
CALUATOR OF AIRCRAFT CRASH HAZARDS FOR NUCLEAR POWER
CALUATOR
CALUATOR OF AIRCRAFT CRASH HAZARDS FOR NUCLEAR POWER
CALUATION OF AIRCRAFT CRASH POWER
CALUATION OF AIRCRAFT CRASH POW

.3150360 MAREO/CR-0169 V20
LOFT EXPERIMENTAL HEASUREMENTS UNCERTAINTY ANALYSES VOLUME
17 FLUD VELOCITY HEASUREMENT USING PULSED NEUTRON
ATTIVATION
LASSURIOD, TAYLOR, D.J. E086, Inc. FIN A-6043 E00-2037 VRO
LASSURIOD , TAYLOR, D.J. E086 FLORE Evaluation 32pp 15747 296

710150564 MJREO/CR-2874 VOI
HICH-TEMPERATURE GAB-CODLED REACTOR BAFETY STUDICS FOR THE
DIVISION OF ACCIDENT EVALUATION Quarterly Progress Report,
DIVISION OF ACCIDENT EVALUATION QUARTERly Progress Report,
DIVISION OF ACCIDENT STATEMENT OF ACCIDENT
FIN B-0122 ORNL/TM-B443/VI B2/09/30 Division of Accident
Fin B-0122 ORNL/TM-B443/VI B2/09/30 Division of Accident
Fin B-0123 ORNL/TM-B443/VI B2/09/30 Division of Accident

E21013/337 NUREO/CR-2163

DISTERSED FILM FLOW BOILING OF HIGH PRESSURE WATER IN A ROD

PIARE
HERBED 0 . MELINS.C 0 . YODER.O L Oak Ridge National Laboratory
FIM 8-0125 GRML/TM-7864 82/09/30 Division of Accident

Exelution 88pp 15716-246

ED3150889 NAREO/CR-2719

ENAUATION OF INSERVICE INSPECTIONS OF GREASED PRESTRESSING

FORMAL R

ED328 Dat Ridge National Laboratory FIN A-9044

ERV/TH-9278 B2/09/30 Division of Engineering Tethnology

Taj 15716 169

ENGISSES WARED/CR-2730
MIDDORN BURN SURVIVAL PRELIMINARY THERMAL MODEL AND TEST
FESTS
ROLLOGHUN N. RASZEL, A.C. KEMPKA, S.N. Bandia Laboratories FIN
A-1270 SAND62-1150 82/09/30 Division of Accident Evaluation
31, 15716-132

EXCIPOSIT MREG/CR-2000 VOI NB LICENSEE EVENT REPORT (LER) COMPILATION For Month Of Appst 1982 • Cal Ridge National Laboratory FIN B-1583 ORNL/NSIC-200 EXMISSO Director's Office 180pp 15723, 113

EMMM192 MREGICE-2922
GOPATION OF GUICE PREDICTIONS WITH RESULTS OF SELECTED
SECRIT ARRESOL BEHAVIOR EXPERIMENTS
GOPATH, SCHWHACHER, P. M. OIESEKE, J. A. Battelle Memorial
Institute, Columbus Laboratories FIN A-4063, BMI-2079
Giffica of Nuclear Regulatory Research, Director 375p 15726-324

EMMMM Responds to 820805 ltr re unresolved issues from 820615 ltr main substantial formation of responsibility for human factors within NRC & course of operator integrity addressed (CORTALE Office of Nuclear Reactor Regulation, Director 8209/86 BHEENY, E. J. Affiliation Unknown 27ep 15758 207.

-20100089 Informs that response to 820615 ltr incomplete in areas of ioun factor evaluation of ADs & ability of operator to act attained.

SEBY, E.J. Affiliation Unknown 82/08/05 PALLADING, N. U. Confessioners. Bap. 15758 234

8210210014 NUREO/CR-2923
MSPEC USER'S MANUAL
JURDAN, H. SCHUMACHER, P. M. DIESEKE, J. A. Battelle Memorial
Institute, Columbus Laboratories FIN A-4063 BMI-2100 82/09/30
Office of Nuclear Regulatory Research, Director 93pp Available
at NRC 84 75 18784 324

B210210024 NUREG-0940 VOL NO1-2
ENFORCEMENT ACTIONS SIGNIFICANT ACTIONS RESOLVED Quarterly
Progress Report, January-June 1982
** Director's Office Office of Inspection and Enforcement
B2/09/30 250pp Available at NRC \$7.50 15781 187

9210210037 NUREO/CR-2673
EVALUATION OF THERMAL DEVICES FOR DETECTING IN-VESSEL
COOLANT LEVELS IN PURS
HARDY, J E , DAVIS, C E , TURNAGE, K & Dak Ridge National Laboratory
FIN B-0401 QRNL/TH-2806 82/09/30 Division of Accident
Evaluation 73pp 15773 295

8210210039 NUREG/CR-2609
THERMAL-HYDRAULIC TEST FACILITY BUNDLE 3 IN-CORE
INSTRUMENTATION AND OPERATING HISTORY
DITL J Cat Ridge National Laboratory FIN D-0125 CRNL/NURFO 75
82/09/30 Division of Accident Evaluation 104pp 15774 906

8210210046 NUREO/CR-2914
CORRELATION DF LIGHTE BEDB FOR FAULT IDENTIFICATION IN THE
HIBSIBSIPPI EMBAYMENT AREA OF HESTERN KENTUCKY
COBB.J C. WILLIAMB.D A Kentucky. State of FIN 0-5972 82/09/30
Division of Health. Siting & Environment 36pp Available at
NRC 44 50 15786 012

8210210051 NUREO/CR-2909
PALEOZDIC GEOLOGY OF THE NEW MADRID AREA
SCHHALD, FIR Illinois, State of # Illinois, Univ of,
Urbana-Champaign FIN 0-6251 B2/09/30 Division of Health,
Siting & Environment 69pp Available at NRC 45 00 15785 181

8210210034 NUREO/CR-2444 V01
PHR FLECHT SEASET 21-ROD DUNDLE FLOW BLOCKAGE TASK DATA
AND ANALYSIB REPORT, NRC/EPRI/MESTINGHOUSE REPORT NO 11
LOFTUS.H J. HOCHREITER.L E. LEE.N Westinghouse Electric Corp
FIN B-6204 EPRI NP-2014 82/09/30 Division of Accident
Evaluation 560pp 15783 001

8210210327 Forwards proposed proprietary Revision 3 to Topical Rept EDR-1(P)-A. "Edgrers Nuclear Safety-Related Extra-Safety & Monitoring (X-SAM) Granes "Rept withheld (ref 10CFR2 770) CLARK, C W Edgrer, Inc. 82/10/08 THOMAS.C Standardization & Special Projects Branch 2pp 15765-276

8210220047 Proposes to submit by end of CY82, evaluation of ACRS 820818 recommendations recontrol room habitability & NRC plans for implementing design improvements
DIRGK8. U Diffice of the Executive Director for Operations
82/07/17 SHEWNON,P S ACRS - Advisory Committee on Reactor
Bareguerds 3pp 15786 219

--8210220048 Comments on ACRS 820818 ltm re control room habitabylity Response should address bunden of new requirements on litensees, limited NRC budget & overall contribution to total risk goodwisse. F Technical Support Branch 82/08/24 MATTSON.R J Division of Systems Integration (post 811005) 3pp 18784 222

ORC

- 8210220154 NUREG/CR-2444 VOZ
 PHR FLECHT SEASET 21-RQD BUNDLE FLQW BLDCKAGE TASK DATA AND
 ANALYSIS REPORT, NRC /EPRI/WESTINGHQUSE REPORT NO 11
 LOFFUS.H J. HOCHREITER.L E, LEE.H Westinghouse Electric Corp
 EPRI NR-2014 B2/09/30 Division of Accident Evaluation YOSpi
 Available at NRC 115 00 15796 128
- 8210220353 Comments on proposed rule 10CFR50 re mandatory property inturance for decontamination of huclear reactors (NUREO-0891) Insurance problems should remain responsibility of utils & NRC should not impose mandates OLKON.O W South Carolina Electric & Qas Co 47FR27371 046 82/10/11 CHILK.S J Office of the Socretary of the Commission 2pp 15776 271
- 8210250030 Forwards NUREO/CR-2927, "Nuclear Power Plant Electrical Cable Damageability Esperiments" Patential problem recable failures at temps less than min temps required for LOCA atmosphere should be brought to attetion of ASLB NOTLEY.D P Electrical Engineering Branch E2/09/30 KNIGHTON,C W Research & Standards Coordination Branch ip 15808 271
- --82[0250033 Forwards NUREO/CR-292], "Nuclear Power Plant Electrical Cable Danageability Esperiments" LUKENS, L. t. Sandia Laboratories 82/09/20 NOTLEY, D. P. Electrical Engineering Branch 41pp 15808 272
- \$210260206 NUREG/CR-2710
 MASS FLOW MEASUREMENTS UNDER PWR REFLOOD CONDITIONS IN A
 DUNKCOMER AND AT A CORE BARREL VENT VALVE LOCATION
 MARDY, J E Gak Ridge National Laboratory FIN 8-0413
 ORNL/TM-8331 82/09/30 Division of Accident Evaluation 46pp
 15831 001
- 8210260211 NUREO/CR-2877
 INVESTIGATION OF CABLE DETERIORATION IN THE CONTAINMENT
 BUILDING OF THE SAVANNAM RIVER NUCLEAR REACTOR
 GILLEN'N T , CLQUGH'R N , JÜNES'L H Sandia Laboratories FIR
 A-1081 SANDG1-2613 82/09/30 Division of Engineering
 Technology 42pp 15831 048
- 8210260215 "TMI Action Plan Tracking Bys." 820630 issue KINO, M Office of Resource Management. Director 82/06/30 159pp 15831 227
- 8204300098 BECY-82-142
 Requests approval of draft Rept to Congress on AD
 (NUREC-0090) for Oct-Dec 1981
 DIRCKS, U Office of the Executive Director for Operations
 62/04/02 40pp (583e 225
- 8210270106 Forwards request for QKD review & supporting statement re NUREC-0906. "Outdance for Implementation of GRP Rule:" per 10CFRSO 34(g) amend NORRY: P G Office of Administration 82/10/20 5CURRY.N Office or Hanagement & Budget | p 15832 320
- 8210270322 SECY-82-407
 Advises of issues remaining from 820109 meeting reinstrumentation for detection of inadequate core cooling in PWRs Requests action on update recommendations for implementation of NUREO-0737. Item II F 2 DIRCKS: M J Office of the Elecutive Director for Operations 82/10/07 12pp 15851 323
- 8210270331 NUREQ-0267 RO1
 PRINCE AND PRACTICES FOR KEEPIND OCCUPATIONAL RADIATION
 PRINCE AND PRACTICES FOR KEEPIND OCCUPATIONAL RADIATION
 PROBLEM AND PROBLEM OF PROB
- B210270338 NUREO/CR-2789

 A PARAMETRIC STUDY OF CONTAINMENT EMERGENCY SUMP
 PERFORMANCE RESULTS OF VERTICAL DUTLET SUMP TESTS
 KREIN. M S , MESTER. M J , STROM, P.O. Gandis Laboratorias FIN
 A-1296 SANDE2-7062 82/10/31 Division of Engineering
 Technology 113pp Available at MRC \$5.50 15947 271
- 8210270371 Summary of ACRS Subcommittes on Seactor Rediological Effetty 820720 meeting in Hashington.DC re methods for reducing radiation expocure exposure histories at PHRS & Status of NURSO-0761. "Radiation Protection Plans for Licensees" * ACRS - Advisory Committee on Reactor Safeguards. 82/09/17 ACRS - Advisory Committee on Reactor Safeguards 17pp 15935 006

- CORRESPONDENCE WITH OTHER ORGANIZATIONS
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list ent! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 1250 24X Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter. Stainless Steel, Recirculation Sys Piping at BUR Plants " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 [25 24X Fiche 50-000,82/10/14.8208190238
- ~-8210080054 Forwards "Cost of Upgrading Capability to Isolate (PHR Main Feedwater Bys in Event of Breaks Inside Containment," final rept in response to statement of work in TE Muriey 810616 let re INEL technical assistance to NRR SAFFELL B F EGLG, Inc FIN A-6452 SAFF~155-82 82/04/14 SGLECKI.J E Energy, Dept of, Idaho Operations Office 1p 19665 167
- 8210120378 Forwards request for CMB review & supporting statement reporting become requirements of 10CFR73 concerning physical protection of plants b matta NORRY,P of Office of Administration 82/10/08 SCURRY,N Uffice of Management & Budget ip 13692 223
- 8210120388 Forwards request for QMB review & supporting statement ro final amend to 10CFR71 12 concerning general license for shipment in pactages approved for use by another person NORRY.P C Office of Administration 82/10/06 SCURRY.N (Iffice of Management & Budgot ip. 19672 242
- 8210120402 Responds to approval request for info collection restorms Request approved through 850630 under OMB Number S150-0032; per Paperwork Reduction Act.
 SCURRY. N Office of Management & Budget OMB 3150-0032 (12/07/12 SCOTT.S Document Management Branch 2pp 15492 250
- 8210120404 Responds to approval request for info collection by dimpst; itensing of source math.10CFR40 Request approved through 830430 under GMB Number 3130-0020, per Paperbork Reduction Act
 SCURRY, N Office of Management & Budget OMB 3150-0020 IN'/04/.* L
 SCOTT, S Document Management Branch Zpp 13652 232
- 8210120581 Transcript of 820918 public meeting in Washington. BC re-FCMA briefing on offsite appraisals program Pp 1-63 Visugraphs encl + Commissioners 82/09/18 87pp 15685 232
- 8210120599 Staff requirements memo re FEMA 820917 briefing on offsate appraisals program for commercial nuclear power plants FLMA should provide NRC w/info re availability of emergency plans & public broadcasts in foreign language CHILK.8 J Office of the Secretary of the Commission HD2091/A 82709/24. BICKHIT.L Office of the Executive Director for Operations DIRKS.H J Office of the Ceneral Counsel Ip 15672 349
- 8210150236 Forwards 10CFR2 206.10CFR2 202. supplementary mail accompanying issuance of original rule in 1974,1977 amend & FR notice re 10CFR2 206 procedures

 BURNES, B Regional Operations & Enforcement Division 82/07/14,

 GREENER, K Federal Emergency Management Agency Espp. 15706 CFR.
- 8210220072 Informs that proposed rule on radiological protection activities coordination plan will be reviewed within next few months for congruence w/NRC/INPO umbrails memorandum of agreement re plant evaluations
 DIRCKS.H J Office of the Executive Director for Operations
 82/09/20 WILKINSON.E P Institute of Nuclear Power Operations
 200 15786 245.
- ~-BROBO10019 Informs of acceptability of encl draft App 3. "Cuerdama Plan for NRC/INPO Radiological Protection Activities." to NRC/INPO unbrella memorandum of agreement re plant evaluations
 HILMINSON H.P Institute of Nuclear Power Operations. Brackets.
 BIRCKB: H J Office of the Executive Director for Operations.

NUNDUCKETED HEIVIS

- 210260931 Forwards requests for QMB review & supporting statement re groposed revisions to 10CFR30,40 & 70 specifying licensee rapposability for nuclear metis & procedures for termination of specific ilcenses wEPRIPO Office of Administration 82/10/22 SCURRY,N Office of Kanagement & Budget 1p 15814 333
- EZIO250344 Forwards request for QMB review & Congressional infocallection requist re occanonic & worker safety aspects of problem concerning steam generator tube integrity (generic ltr) NCARGEP & Office of Administration 82/10/22 SCURRY.N Office of Minigiment & Budget ip 15814-325
- STIGETOLOG Forwards request for DMB review & supporting statement re NAMES-0905. "Guidance for Implementation of SRP Rule." per ICCFRSO 34(9) amend NCRRY.P O Office of Administration B2/10/20 SCURRY,N Office of Management & Budget 1p 15832 320
- E210270116 Responds to approval request for info collection re 10CFR35 27 concerning records of teletherapy image & 10CFR35 27 concerning records of teletherapy image & 10CFR35 27 concerning records B30630 under GMB Number 3150-0010, per Paperwork Reduction Act 3150-0010, per Paperwork Reduction Act SCURRY, Office of Management & Budget GMB 3150-0010 B2/10/UB SCOTT.S Document Management Branch 2pp. 15832 342
- E210270119 Responds to approval request for info collection re Mark 1 containment program Request approved through 851031 under CM3 Nubber 3150-0091 per Paperwork Reduction Act EXCHAPLY Office of Management & Budget DMB 3150-0091 SOTAS Document Management Branch 2pp 15932 344
- 5010270301 Forwards comments on Aug 1982 draft FEMA planning guidance for preparation of federal radiological emergency response jainsipe 820920 memo NRC needs to continue to work w/ΓΕΜΑ in defining role as cognizant federal agency (ΕΝΙΟΝ-18 R Office of Nuciear Reactor Regulation, Director 62/10/15 DEYGUNO, R C Director's Office, Office of Inspection and Enforcement App 15836 330
- --B2102703D4 Requests comments on planning guidance for preparation of Isiral radiological response plan by 821015 Results of Isiral radiological response plan by 821015 Results of Isiral wide will be provided for consideration & comment EVOUND. C Director's Office Office of Inspection and Enforcement 82/09/20 DENTON. H Office of Nuclear Reactor Regulation. Director MANNES. R C Region 1. Office of Director GYEILLY. J P Region 2. Office of Director 1p 15836 336
 - M0290450 Forwards, for info, draft rept & apps on pressurized thermal that Completed rept will form basis of Commission paper to 821030 H/o smil LAIM9.0 C Assistant Director for Operating Reactors 02/09/28 M031850 Atomic Industrial Forum 2pp 13863 181

R PROPOSED RULE

- 1207149050 Transcript of 820518 public meeting re-certification of ridiographers (Region 5) in Oakland, CA Pp 1-99 Exhibits and Co. 121pp. 13047, 206
- E20010185 Comments on proposed rule 10CFR50 re fitness for duty Rule should be altered to require that any individual solutions in great by licensee application of rule be aftered adequate opportunity to rebut info HACKHONLR F Affiliation Unknown 47FR33980 024. 82/07/24 Detteting & Services Branch 13pp 15568 030
- (2)(0)(0)(0) Consents on proposed ruls 10CFR50 re fitness for duty of sotter pour plant personnel Opposes ruls (CMOOT.D N. Affiliation Unknown 47FR39980 025 82/09/2/ Catating & Services Branch 1p 19568 020
- \$210010218 Comments on proposed rule 10CFR30 rs fitness for duty stautizer power plant personnel Opposes rule 511TH.V E American Nuclear Society 47FR33980 026 82/09/27 bottsling & Services Branch 2pp 15568 028.
- RICO10223 Comments on proposed rule IOCFR50 re mandatory property Invidence for decontamination of nuclear reactors & NREG-0891, "Nuclear Property Insurance Status & Dutlook " Speed rule. TOKKE B Mississippi Power & Light Co. 47FR27371 041, 82/09/24 Office of the Secretary of the Commission 1p 15568 019

- 8210010226 Package of two comments opposing proposed rule 10CFR9D rumandatory property insurance for decontamination of nuclear reactors
 SANDERS.W L Alabama Power Co GUODMAN.L Affiliation Unknown
 47FR27371 82707/27 CHILK.S J Office of the Secretary of the
 Commission 7pp 15568 021
- B210010230 Package of three comments on proposed rule 10CFR50 relicensed operator staffing at nuclear power units COUNSIL.W 0 Connecticity Yanke Atomic Power Co. COUNSIL.W 0 Northeast Nuclear Energy Co. (subs. of Northeast Otilities) COUNSIL.W 0 Northeast Otilities 2 COUNSIL.W 0 Northeast Otilities 3 47FR5B135 82/07/29 Docketing & Bervices Branch. 13pp. 15588-248
- 8210010232 Package of three comments opposing proposed rule 100FR50 rulicensed operator staffing at nuclear power units of 100FR50 rules of 10
- 9210010273 Comments on proposed rule 10CFR50 re licensed operator staffing at nuclear power units Requirement to have two senior reactor operators on shift should be reconsidered to implementation date delayed for 1 yr HDUGHTON, TC MKC. Inc. 47FR38135 008 82/09/27 CHILK.6 J Office of the Secretary of the Commission 14pp 15569 197
- --8207050005 Informs that vendor has been working closely woutchs & NH(
 in developing personnel requirements for operators of
 nuclear power plants INC should issue regulations or
 guidance & not dictate means of meeting requirements
 KNUTH.D F MMC, Inc 82/07/13 PALLADIND,N Commissionors
 7pp 15569 202
- 8210010302 Comments on proposed rule 10CFR50 re mandatory property insurance for decontamination of nuclear reactors Supports ruls
 SPENCER, N.D. Texas Utilities Generating Co. 47FR27371 035
 82/09/22 Office of the Secretary of the Commission 2pp. 15588 308
- 8210010307 Package of three comments apposing proposed rule 1001800) re mandatory property insurance for decontamination of nuclear reactors of the service Corp. Willers, D.D. Pacific Cas & Electric Co. KELLY, A.B. American Nuclear Insurers 47FR27071 82/09/28 Chilk, B.J. Office of the Secretary of the Commission 19pp 15568 209
- 8210010310 Comments on proposed rule 10CFR50 re staffing at nuclear power plants Opposes rule LEMIB.N I Lewis. M 47FR38135 006 82/09/10 Defice of the Becretary of the Commission ip 19568 284
- 8210010322 Comments on proposed rule IOCFR50 relicensed operator staffing at nuclear power units Comment period should be extended 6 months Guring which time NRC should introduce addlevidence to justify proposed rule POPEO.D J Washington Legal Foundation 47FR38135 007 82/09/2/ Bocketing & Services Branch Spp 15574 035
- 8210010374 Package of two comments opposing proposed vule 1007830.
 "Mandatory Property Insurance for Decontamination of Nuclear
 Reactors"
 PARKYN, J D Affiliation Unknown SOUCY, A R Yanker Atomic Electric
 Co 476827871 82/09/24 Docketing & Services Branch 5pp
 15573 090
- 82100103Bi Package of four comments on proposed rule 10CFR50,
 "Mandatory Property Insurance for Decontamination of Nuclear
 Reactors "Supports rule
 WYATT-J H Louisiana Power & Light Co DELLBY-H ft Commonwealth
 Edison Co. ROBERTEON.C O Houston Lighting & Power Co 47FR273/1
 B2207/24 Docksting & Barvices Branch 22pp 15979 037
- 8210120147 Responds to 820830 ltr expressing concern re final version of 100FR61. "Licensing Requirements for Land Disposal of Radwaste." De minimis issue for managing low level radwaste will be addressed within next few yrs HARTIN. J. B. Division of Waste danagement 82/09/21 HARRIS.B J. Health Physics Society 2pp 15692 177
- 8210120173 Forwards minutes of 820729 briefing on 10CF860 W/o enci BELL:M J High Level Waste Technical Development Branch 82/08/31 BOMLINDER: H Lowisiana, State of LIEBOLO: G Affiliation Unknown CAMIL: P C Environmental Protection Agency App 15692: 205

- 8210130270 Package of three comments supporting proposed rule 10CFR50, "Applicability of License Conditions & Tech Specs in Emergency"

 CLAYTON.F L Atabama Power Co HULLER.O E Illinois Power Co PARKYN.J D Afrilation Uninown 47FR35796 82/10/04 CHILK.S J Orrice of the Secretary of the Commission 5pp 15679 008
- 8210130277 Package of two comments opposing proposed rule 10CFRSO rulthess for duty of personnel w/unescorted access to protected areas
 O'TODLE.J D Consolidated Edison Co of New York POPEO, D J
 Washington Legal Foundation 47FR33980 82/10/05 CHILKIS J
 Office of the Secretary of the Commission 11pp 15678 355
- 8210130282 Package of three comments on proposed rule 100FR50 refitness for duty of personnel a/unescorted access to protected areas

 JENS.IN Betroit Edsson Co. GIESLER, C. W. Wisconsin Public Service Corp. KEARNEY, J. J. Edison Electric Institute 47FR33980

 82/10/04 CHILK, S. J. Office of the Secretary of the Commission 14pp. 15678-264
- 8210130331 Comments on proposed rule 10CFR50 re mandatory property insurance for decontamination of nuclear reactors (MUNEG-0871) Imposition of blanket coverage requirement poses restrictive economic hardship on smaller plants TAYLOR. J W Dairyland Power Cooperative 47FR27371 042 82/09/23 Office of the Secretary of the Commission 2pp 15681 001
- 8210130391 Comments on proposed rule 10CFR50 re fitness for duty of personnel u/unescorted access to protected area Existing program adequate Transferring authority to federal level uili not improve effort LUNDWALLIA E Baltimore Gas & Electric Co 47FR33980 027 8/09/30 CF14%, S J Office or the Secretary of the Commission 2pp 15681 004
- 8210130396 Comments on proposed rule 10CFR50 re fitness for duty of personnel D/unescorted access to protected areas Great latitude for implementation would provide better end product than rule that defies compliance Opposes rule ANDOONINI.0 C Arisona Public Service Ca 47FR33980 028 82/09/27 Docketing & Services Granch 4pp 15681 021
- 8210130399 Package of 10 comments opposing proposed role 10CFR50 refiless for duty of personnel w/onescotted access to protected areas.

 KNUTH.D F KMC, Inc. UHRIG.R E Florida Power & Light Co.
 COUNSIL-W G Northeast Utilities 47FR33980 82/10/04 CMILK.b J
 Office of the Secretary of the Commission 33pp 15681 128
- 8210130402 Comments on proposed rule 10CFR50, "Licensed Operator Staffing at Nuclear Power Units " Requirement to have senior reactor operator domiciled to control room would not contribute to overall plant safety DELGCORGE, L D Commonwealth Edison Co. 47FR38135 Q17 82/09/27 Docketing & Services Branch 1p 15692 Oc4
- 8210130433 Comments on proposed rule 10CFR50 "Licensed Operator Staffing at Nuclear Power Units" Need for proposed rule has not been adequately established HELFRICHIRE Yankee Atomic Electric Co. 47FR38135 021 82/09/27 Docketing & Services Branch. 4pp. 15682 055
- 8210130521 Package of two comments on proposed rule 1QCFRSO, "Lacenced Operator Staffing at Nuclear Power Plants"
 MILLS.L. M. Tennessee Valley Authority VANDEWALLE.D.J. Consumers Power Co. 47FR38135 82/10/04 Docketing & Services Granch Opp. 15692 355
 - ents on proposed rule 10CFR80, "Applicability of License Tech Specs in Emergency " Supports rule efense, Dept of, Defense Nuclear Agency 47FR35996 006 ich 50s 15683 001

- 8210130554 Comments on proposed rule 10CFR50 re mandatory property insurance for decontamination of nuclear reactors (NUREG-0891)
 MITTL.R L Public Service Electric & Gas Co. of New Jersey 47FR27371 043 82/09/24 CHILK.S J Docketing & Services Branch App. 15694 001
- 8210130584 Comments on proposed rule 10CFR90. "Licensed Operator Staffing at Nuclear Power Units" Min staffing table should be modified to indicate two-uperator requirement for two-units.one-control room plant FAY.C W Wisconsin Electric Power Co 47FR38135 018 82/09/27 CMILK.S J Office of the Secretary of the Commission 2pp 15679 088
- 8210130594 Comments on proposed rule IOCFR50, "Litensed Operator Staffing at Nuclear Power Units " Due to difficulties in obtaining qualified personnel effective date for rule should be extended to 840101 THORREJUR Operator Public Utilities OPU Service Corp 47FR38135 016 82/09/28 CHILK.S J Office of the Secretary of the Commission ip 15679 116
- 8210130599 Package of two comments opposing proposed rule 10CFR50 "Licensed Operator Staffing at Nuclear Power Units"
 TUCKER.H B Duke Power Co MATTIMOE, J J Sacramento Municipal Utility District 47 FR38135 82/09/30 Docketing & Servicos Branch Bpp 15479 050
- 82/0220226 Comments on proposed rule 10CFR34 providing third party certification of radiographers Measure would be excellent step in direction of safety LOW-R L Associated Technologies, Inc. 47FR19152 090 82/05/11 JONES, J A Office of the Secretary of the Commission ip 1977A 209
- 8210220246 Comments re proposed rule 10CFR34 providing for thiré party radiographic certification Opposes rule THCMP50N.V J Vester J Thompson, Jr , Inc 47FR19152 081 82/05/21 GODWIN.A V Alabama, State of 1p 15776 199
- B210220256 Comments on proposed rule 10CFR34 providing for certification of radiographers Supports rule SACKETIM H Affiliation Unknown 47FR19152 087 82/04/00 JONES J A Office of Nuclear Regulatory Research, Director 3pp
- B210220285 Package of two comments opposing proposed rule 10CFR50 rule titness for duty
 COLLING.R M Dechtel Corp FLYNN.S F Carolina Power & 4.1ght Co
 47FR33980 B2/10/07 Docketing & Services Branch 8pp
- B210220301 Comments on proposed rule locFR50 allowing waiver of Tech Specs during emergency situation if necessary to protect health & safety of public Supports rule HITHERB.B D Portland General Electric Co 47FR35994 Off B2/10/05 Docketing & Services Branch 1p 15776 104
- 8210220306 Comments on proposed rule 10CFR90 re applicability of license conditions & Tech Specs in emergency Applauds rule for providing leeway to protect health & safety of public Deplores need for rule which should be self-evident 0000MAN-L S Affiliation Unknown 47FR35996 010 82/10/07 Docketing & Services Branch 2pp 15776 179
- 82102203i6 Package of five comments on proposed rule [OCFR34 providing for third party radiographic certification
 HAMILTON.J F Oklahoma Bteel Castings Co MODES, N C Universal Technical Testing Laboratories, Inc MCINNIG.E L Jacksonville Shipyards, Inc 47FR19152 B2/10/08 JONES, J A Office of Nuclear Regulatory Research, Director 17pp 15776 128
- B210220321 Package of two comments on proposed rule 10CFR34 providing for certification of radiographers HICKLICH,R M Rockwell International Corp BRADLEY,F J New York, State of 47FR19152 B2/10/08 JONES,J A Office of Nuclear Regulatory Research, Director 7pp 15776 170
- 8210220326 Package of two comments on proposed rule 10CFR50 re licensed operator staffing at nuclear power plants
 HITL.R L Public Service Electric & Qas Co of New Jersey
 PRATT.C M Power Authority of the State of New York 47FR38135
 82/10/07 CHILK.B.J Office of the Secretary of the Commission
 2pp 15776 045
- 8210220333 Comments on proposed rule 10CFR50 re licensed operator staffing Rule lacks true applicability to criteria of TMI lessons learned & ignores complexity, range of different facilities & human factor issue of size of control room PARKYN, J D. Affiliation Unknown 47FR89135 025 82/09/26 Docketing & Gervices Branch 2pp 15776 181

- 2210120334 Package of three comments on proposed rule 10CFR50 re Iltress for duty of parsonnel w/unescorted access to Iratected areas contentions of Power Co DALE, I Mississ Contents to DALE, L F Mississippi 47FR339B0 15776 152
- EZID220339 Comments on proposed rule 10CFR50 re licensed operator staffing Shared control room w/identical layout & controls for each unit of multi-unit stations proposed EAVIDSON, DR. Cleveland Electric Illuminating Co. 47FR3B135 022 22/07/25 Docketing & Services Branch ip 15776 028
- #210220342 Forwards comments on proposed rule 10CFR94 M/o encl PAULICKLE R Pipe Fabrication Institute 47FR19152 086 8 CRES.J A Office of Nuclear Regulatory Research. Director 82/09/09 15776 151
- E310220348 Comments on proposed rule 10CFR90 re fitness for duty of gersonnel u/unescorted access to protected areas Proposed Tile should be coordinated w/ANSI/ANS 3 3 screening rule should requirements
 requirements
 requirements
 republished Stone & Webster Engineering Corp 47FR339BC
 republished Queseting & Services Branch 3pp 15776 268 47FR339BO 045
- E213220333 Comments on proposed rule 10CFR30 re mandatory property insurance for decontamination of nuclear reactors (NAFC-0G91) Insurance problems should remain responsibility of utils & NRC should not impose mandates 110N.0 W South Carolina Electric & Oas Co 47FR27371 046 E27[07]1 CHILK-S J Diffice of the Secretary of the Commission 1877 271
- 1210220359 Comments on proposed rule 10CFR50 re fitness for duty of second Junescorted access to protected areas Most fraction approach would be issuance of general policy states trather than rule AREFORMO.D W. Public Service Co of Colorado 47FR33990 056 P210704 CHIEKS J Office of the Secretary of the Commission
- 62:0220356 Comments on proposed rule LOCFR50 re fitness for duty of personal diunescorted access to protected areas Rule not ceestiary QUATISIN H Penney I vania Power & Light Co 47FR33980 057 22/10/07 HOYLE, J C Office of the Becretary of the Commission 258 15779 199
- E210220372 Package of four comments on proposed rule 100FR50 re fitness for luty of personnel w/unescorted access to protected
- array
 EMANDS.D H Yankee Atomic Electric Co THORPEJ R Oeneral Public
 Littities OPU Bervice Corp QARY.R J Taxas Utilities Generaling
 Co 4FR33980 82/10/12 Dacketing & Services Branch 13pp Occeral Public
- EXIOAXXXXII Comments on proposed rule IOCFR50 re fitness for duty of streamt w/wnstorted access to protected areas Opposes Virginia Electric & Power Co 47FR33980 06: Docketing & Bervices Branch 2pp 13779 182 LEASBURG R H 47FR33980 0A3
- E21020375 Comments on proposed rule IOCFR50 re fitness for duty of streamel w/unescorted access to protected areas Current silvers practiced throughout industry adequate w/o use of strots practices and strong texts to the strong of the strong texts to the strong texts of the strong text o
- 2022379 Comments on proposed rule 10CFR60 re technical criteria is telegic repositories for high level radwaste Overly restrictive & specific performance side not necessary WHILIMGALL MAMERICAN NOTION OF STATES OF THE PROPOSED OF THE CONTROL OF THE PROPOSED OF THE PROPO
- EXISCOSES Package of three comments on proposed rule LOCFR50 refilars for futy of personnel w/unescorted access to icitated areas
 invictors & Liberman DELOEOROE.L O Commonwealth
 fish to MAIER.JE Rochester Oas & Electric Corp. 47FR33780
 82/00/05 CHILK.S. J Office of the Secretary of the Commission 270 13777 391
- 20222095 Package of three comments on proposed rule 10CFR50 re fittiss for duty of personnel w/unescorted access to states areas

 NEMEMBER 7 Florida Power Corp CRANE, P A Pacific Oas & Electric
 C HICHELC J Nuclear Fuel Services, Inc (suba of Oatty Dil
 C) 47833980 82/10/07 CHILK B J Office of the Secretary of
 ReCaedistion 1Gpp 15778 248 statected areas

- 8210220403 Package of two comments on proposed rule 180FR50 re applicability of license conditions & Tech Specs in emerdencu emergency KOESTER:O L Kansas Gas & Electric Co FUENTE.E S Mississippi. State of 47FR35996 82/10/13 Docketing & Gervices Branch 2pp 13779 164
- B210220409 Petition for exemption from schedular requirements of proposed rule 10CFR50 re hydrogen control UTLEY, E.E. Carolina Power & Light Go. 49FR65466 B2/10/11 CHILK, S.J. Office of the Secretary of the Commission 4pp
- 8210270234 Package of four temments supporting proposed rule 10C+R50 re applicability of license conditions & Tech Specs in emergency situations **

 ** LeBosef, Lamb, Leiby & MacRas GIESLER, C W Wisconsin Public Service Corp FJSHER, C R GA Technologies. Inc /General Atomic Co 47FR39795 82/10/21 CHILK, S J Office of the Secretary of the Commission Spp 15883 267
- 8210290237 Comments on proposed rule 100FR30 re applicability of license conditions & Tech Specs in emergency situations Rule vague & unquantified BRADDURY, R & Stone & Webster Engineering Corp. 47FR35996 026 62/10/18 Docteting & Services Branch 2pp. 15853 179 47C83589A 02A
- 8210290239 Package of two comments opposing proposed rule 10CFR50 re Fitness for duty of personnel w/unescorted access to protected areas 8HIELDS-5 W Public Service Co. of Indiana. Inc. MUSOLF, D. Northern States Power Co. 47FR33980 82/10/18 CHILK, S.J. Office of the Serretary of the Commission. 11pp. 19853-239
- 6210270240 Package of six comments supporting proposed rule 1007R50 re applicability of license conditions & Tech Space in emergency situations ZUMMO. J. LCRID.P. Utility Workers Union of America MARSHALL, J.R. Arkansas Power & Light Co. 47FR35795 82/10/18 CHILK, S.J. Office of the Secretary of the Commission 13pp. 15053 182
- 8210290242 Comments on proposed rule 10CFR30 re fitness for duty of personnel U/unescorted access to protected areas Utils elready have related programs SZALAY.R Atomic Industrial Forum 47FRDD 786 Docketing & Services Dranch 2pp 15853 265 47FR33980 070 82/10/22
- 8210290244 Comments on proposed rule 10CFR50 re applicability of licens; conditions & Tech Space in ecorgancy estrations Opposes rule EDOLERAN, W. Affiliation Unknown 4/FR35996 021 82/10/14 Office of the Secretary of the Commission Spp. 15853 254
- 8210290245 Package of two comments supporting proposed rule 1007850 re applicability of license conditions & Tech Specs in amergency situations
 DIXON, Q W. South Carolina Electric & Qas Co. DELOCORDE, L. Q. Commonwealth Edison Co. 47FR35996 82/10/19 CHILM, B J. Diffice the Secretary of the Commission 5pp. 15854 086 Diffees of
- 8210240249 Comments on proposed rule 10CFR30, "Licensed Operator Staffing at Nuclear Rower Units " Rule underestimates difficulty involved in selecting training & licensing NUSCLE, D. Northern States Power Co. 47FR38135 026 82/10/06 Docketing & Services Branch 2pp. 15854 099
- 8210290253 Comments on proposed rule 10CFR50, "Licensed Operator Staffing at Nuclear Power Units " Dpp oses rule STALAY,R Atomic Industrial Forum 47FR38135 027 02/10/22 Docketing & Sarvices Branch 1p 19884 090
- 8210270255 Comments on proposed rule 10CFR50 re reduction in vol of Tech Specs for nuclear power reactors Supports rule HONEY, J American Nuclear Insurers 47FR13369 031 82/10/14 Docketing & Services Branch 6pp 15853 114
- 8210290257 Comments on proposed rule 10CFR3D re applicability of license conditions & Tech Speca in emergency situations BAUBER, N A Lowenstein, Newman, Reis, Azelrad & Toli 47FR35994 014 82/10/15 Docketing & Gervices Branch 2pp 15853 126
- 8210290263 Package of two comments supporting proposed rule 10CFR50 reapplicability of licents conditions & Tech Space in emergency situations EDWARDS. D M Yankse Atomic Electric Co BOOKER. J E Gulf States Utilities Co 47FRQ5996 82/10/20 Doctoting & Services Branch 3pp 15854 091

8210290265 Comments on proposed rule 100FR50 relactions that depart from license conditions or Tech Specs in emergency Supports

MILLS.L M Tennessee Valley Authority 47FR35996 031 8: Orfice of the Secretary of the Commission 19 15854 045

8210290267 Package of two comments opposing proposed rule 10CFR50 refitness for duty of personnel w/unescorted access to protected access to MUBINAK, R A Long Island Lighting Co SANDY, R Affiliation Unknown 47FR3980 62/10/21 Docketing & Services Branch Dp 15834 078

8210290273 Package of two comments opposing proposed rule 10CFR50 re fitness for duty of personnel w/unescorted access to protected areas DIXON.G H South Carolina Electric & Gas Co GUCHA-L T Georgia Power Co 47FR339BO 82/10/19 CHILK.S J Office of the Secretary of the Commission 5pp 15854 054

PRM PETITION FOR RULEMAKING

8210130257 Comments on petition for rulemaking PRM-50-33 re reduction in frequency of emergency planning electises Supports petition & concept of blannial electises Supports HOPMODO.C A Drange County, CA 47FR24252 035 82/0 of the Secretary of the Commission ip 15475 336 82/09/30

8210130280 Comments on petition for rulemaking fRM-50-32 re protection against affects of electromagnetic pulse Petition should be CACNETTA, J.P. Atomic Industrial Forum 47FR27371 021 82/10/04 Docketing & Bervices Branch 20p 15678 350

82:0220294 Comments on petition for rulemaking PRM-50-328 re ejectromagnetic pulse in nuclear power plants Requests that 10CFR50 be amended to require provision for design features for protection against attacks & destructive acts MARSHALL.W H Mapleton Intervenors ISSUANCES OM 82/08/00 Office of the Secretary of the Commission 2pp 15776 066 M 82/09/31 15776 066

8210220386 Comments on petition for rulemaking PRM-50-33 re emergency preparedness Bupports concept of reducing frequency of emergency exercise involving state & local govt GUCKA-L T Georgia Power Co 47FR2925 036 62/10/04 Docketing & Services Branch 1p 15779 170 Docketing

PROJECTS - PREDOCKET LICENSING

8210120360 forwards comments on "Topical SAR for Castor Cask Type ISFSI eivizuoau rorwards comments on "Topical SAR for Castor Cast Type ISI (Dry Storage) " Tests & analysis results do not address site parameters Only generic design info applicable RDUSELL C Advanced Fuel & Spent Fuel Licensing Branch 82/09/29 RDLINS, J D Gesellschaft für Nukleur-Bervice mbH 47pp 15670-249

8210250356 Comments on 820921 proposed order concerning preservation of documents Util should not be allowed to terminate proceeding Parties should provide list of files designated "central files " Certificate of Svc enci of. BLAIR... A 82/10/21

9210270175 Notice of ASLB reconstitution JA Laurenson, chairman LAID, R M Atomic Bafety and Licensing Board Panel ISSUANCE 62/10/25 ip 15922-354 ISSUANCES A

MONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

itrol rod guide tube lants,

214 80/03/14

, tube support pins rating

11 EIBENHUT, D

82(0)20236 Part 21 rept re emergency standby diesel generator set Defect exists in one power piston installed in Cylinder Location 7L in engine 7188 Piston will be replaced by Apr 1983.prior to startup STOLBALF B Cooper Energy Services PT21 82-498-000 82/09/30 Director's Office, Office of Inspection and Enforcement 1p 15652 124

B210130447 Part 21 rept re sheared pinion keys in Limitorque Model 9B-0-25 motor operators Sheared keys apparently resulted from use of inappropriate matis Utils advised to watch for indications of failed pinion keys RAME, E P Westinghouse Electric Corp NS-EPR-2637 B2/09/29 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 15482 028

8210250132 Part 21 rept re preliminary exam of EPRI safety & relief valve test program indicating that Dresser safety valves could chatter reducing capability to relieve pressure Listed plants should determine ring settings
TAYLOR.J H Babcock & Wilcox Co PT21 82-718-000 82/10/15 BEYQUNG.R C Director's Office. Office of Inspection and Enforcement 3pp 15787 013

QUALITY ASSURANCE INSPECTIONS QA999

820929016B Responds to FOIA request for documents prepared by NRC staff & consultants on 10CFR50.App B re GA audite of testing facilities conducted within past 10 yrs by NRC Related Division of Rules and Records 82/08/26 PHILIPS, H N Liberman 2pp 15564 002 FELTON, J H Division Debevoise & Liberman

--8209290236 Forwards GA Program Insp Rept 99900905/82-01 on 811229-30 No moncompliance noted
HEISHMAN.R F Reactor Construction Branch 82/05/26
BOUCHEY.O D Washington Public Power Supply System 2pp 15564 060

--8209290240 GA Program Insp Rept 99900905/82-01 on 811229-30 No noncompliance noted Major areas inspected test set-up of Weidmuller terminal block post-LOCA test program, post-test insp test specimens & test plan AGEE.JR. BENNETT.AB Reactor Construction Branch CRAFT.C M Sandia Laboratories 82/09/18 3pp 15564 062

8210040148 Ack receipt of 820827 ltr informing NRC of steps taken to correct monconformance noted in GA Program Insp Rept 97900063782-01 POTAPDVS,U Division of Vendor & Technical Programs 82/09/27 MOYER,D J Pacific Pumps Div ip 15582 350

--8210040155 Responds to NRC ltr re-nonconformance noted in GA Program Imap Rept 99900063/82-01 Corrective actions visual imap procedure added providing approved written procedure after mfg operations, welding & cleaning MOYER. D J Pacific Pumps Div 82/08/27 POTAPOVS, U Division of Vendor & Technical Programs 2pp 13582, 351

8210040171 Ack receipt of 820908 Itr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900503/82-02

POTAPOVB, U Division of Vendor & Technical Programs 82/09/27 HENDRICKSON, T Burns & Ros Co ip 15582 305

---8210040173 Responds to NRC 820806 itr re nonconformance noted in CA Program Insp Rept 99900503/82-02 Corrective actions special audit will be performed to verify that each corporate operation manual is up-to-date HENDRICKSON, T. Burns & Roe Co of Vendor & Technical Programs 82/09/08, POTAPOVS.U Division 8pp 15582 304

8210040192 Ack receipt of 820823 ltr informing NRC of steps taken to correct nonconformence noted in GA Program Insp Rept 99900404/82-01 99900000732201 PDTAPOUS, Division of Vendor & Technical Programs S2/ SLEMBER,R J Heatinghouse Electric Corp. ip 15583 184, 82/09/27

-- B210040194 Responds to NRC 820811 ltr re nonconformance noted in O

8210040333 Ack receipt of 820904 & 15 ltrs informing NRC of steps to correct nonconformance noted in GA Program Inap Rept 999007(2/82-01
POTAPOVB.U Division of Vendor & Technical Programe, 82/09/27.
CAPRA.L A Systems Control, Inc. 1p. 13586:180

- -- 2210340335 Revises 820904 response to NRC 820806 ltr re nonconformance noted in QA Program Insp Rept 99900712/82-01 Corrective actions QA manual will be revised & new procedure developed to address control of drawings to address control of drawings CAPRAL A Systems Control. Inc 82/09/15 POTAPOVG, U Division of Vendor & Technical Programs 2pp 15586 181
- --2210340340 Responds to NRC 820806 itr re nonconformance noted in OA Program Insp R*pt 99900712/82-01 Corrective actions GA exacts will be revised procedures followed in transmitting travings to instructions developed for control of drawings CAPRAL A Systems Control. Inc 82/09/04 POTAPOVS. U Division of Vendor & Technical Programs 2pp 15386 183
- EXECOSOIBS Ack receipt of 820830 ltr informing NRC of steps taken to correct monconformance noted in GA Program Insp Rept 9900513/82-01 FOTAPOSI.V Bivasion of Vendor & Technical Programs 82/10/01 SALEY.F C Teledine Engineering Services ip 18611 189
- --P216350191 Responds to NRC 820611 Itr re-nonconformance noted in GA Frogram Into Rept 49900513/82-01 Corrective actions dual storage of records design activities re-containment torus hydrodynamic analyses provided in accordance w/GA manual ZALLEY,F C. Teledyne Engineering Services A73-82/01, B2/06/30 P014FUSAU Division of Vendor & Technical Programs 7pp 13611 190
- E2100:0193 Act receipt of 820910 ltr informing NRC of steps taken to carrect nonconformance noted in GA Program Insp Rept 9900033/82-01 POLYEUM. Division of Vendor & Technical Programs 82/10/01 PUFFEL.H D Westinghouse Electric Corp 1p 15609 175
- --0210050190 Responds to NRC G20810 ltr re nonconformance noted in flA frogram Inso Rept 97900032/62-01 Corrective actions, error cerrection tag revised for easier reading & documented for failure of reactor colant pump diffuser adaptor capecreus RCPELHD Lestinghouse Electric Corp 82/09/10 POTAPOVS, U Division of Vandor & Technical Programs 3pp 15609 174
- 8240030284 Act receipt of 820188 & 811006 ltrs informing NRC of steps taten to correct nonconformance noted in GA Program Insp East 99700334/81-02. Two nonconformances, ltems C & D. closed with require no further action 907480VS.V Division of Vendor & Technical Programs 82/10/01 MATERIS.C Transamerica Delayal, Inc. ip 15611 163
- --gaig0030287 Act reteipt of 820128 & 811006 ltms informing NRC of steps tilen to correct monconformance noted in GA Program Insp Rist 93900304/81-02 Gusstions re validity of honconformance. Item C & Dies environ qualification of motors unacceptable poissous U Division of Vondor & Technical Programs 82/05/06 KATMEVS.C Transamerica Dajaval, Inc. 200 15611 164
- --8210050290 Responds to NRC B20114 ltr re-nonconformance noted in GA Fragram Insp Rept 99900334/61-02 Requests reconsideration of achievements Items C & D Hotor name plate & motor test rist indicate motors are environmentally qualified.

 EVER.R E Transamerica Dalaval, Inc B2/01/28 POTARDVB, U Winder Inspection Branch 2pp 19611 166
- -- 8210030272 Ack receipt of 811006 ltr re nunconformance noted in GA fregram (msp Rept 99900334/81-02 Addl info required in order to consider request for re-eyeluation putpeyOSU Vendor Inspection Branch 82/01/14 MATHEMS. C Transperice Delaysi, Inc. 2pp 13611 168.
- --210030275 Responds to NRC 810718 ltr re-nonconformance noted in OA freque insp Rept 9990034/81-02 Corrective actions drawing a showing installation of oil plug revised. Requests riconideration of items B.C & D 2016; R & Transamerica Delaval. Inc 81/10/04 POTAPOVE. U Vander Inspection Branch App 13611:170
- 8210120222 Forwards OA Program Insp Rept 99900522/82-02 on 820712-15 is noncompliance noted MIAFBUS-U Division of Vendor & Technical Programs 82/09/15 STATION C D Bechtel Corp Spp 15452 130
- -- P2[DI2023] GA Program Insp Rept 99900522/82-02 on 820712-15 No rentempliance noted, Major areas inspected: procedures & rappesentative records re hydrodynamic load analysis, interviews u/personnel & observations by inspectors.

 COSTELLO, J. R., MALE, C. J. Division of Vendor & Technical Programs 62/09/08 11pp 15632 133.
- 82(0)20280 Ack receipt of 820525 ltr informing NRC of steps taken to surett senconformance noted in GA Program Insp Rapt \$75(0)02/81-02.
 FOLKPURAU Division of Vendor & Tachnical Programs \$2/10/06 RHIMAU NA Western Piping & Engineering Co. / Inc Ip 18413-02

- --8210120285 Forward: ASME ltr indicating status of inquiry re nonconformance noted in GA Program Insp Rept 97900302/81-02 HAYTACK.R K Western Piping & Engineering Co , Inc 82/08/23 POTAPOVB.U Division of Vendor & Technical Programs 2pp 1559 053
- --8210120293 Responds to NRC 820904 ltr re nancanformance noted in UA Program Insp Rept 99900302/81-02 Categorically denses allegations of nonconformance re design of component supports
 FRIEDMAN, K.A. Western Piping & Engineering Co., Inc. 82/05/25 POTAPOVS, U. Division of Vendor & Technical Programs 3pp 19583 055
- 8210120301 Act receipt of 820623 & 0901 itrs informing NRC of steps taken to correct nonconformance noted in QA Program (nsp Rept 97900400/79-04 POTAPOVS.U Division of Vendor & Technical Programs 82/60/05 GUILBERT.D & Babcock & Hilcox Co ip 15653 041
- --B210120304 Responds to NRC 820811 ltr re nanconformance notes in UA Program Insp Rept 99900400/79-04 Corrective actions input ref for old calculations winew effectivities verifies OULDERTY DE Babcock & Micco Co 82/09/01 POTAPOUS, U Division of Vendor & Technical Programs 2pg | \$5653 042
- --8210120309 Ack receipt of 820523 lir informing NRC of steps taken to correct nonconformance noted in OA Program Insp Rept 97904600/79-04 Riquests verification of input lef for revised calculations POTAPOVS.U Division of Vendor & Technical Programs B2/08/11 GUILBERT.D E Babcock & Hilcox Co lp 15659 044
- --8210120313 Forwards rept re nanconformance noted in QA Program Insp 99900400/79-04 Corrective actions treatment of new & revised calculations defined for source ref pilot program QUILBERT D E Babcack & Milcot Co B2/06/23 POTAPOVS, U Division of Vendor & Technical Programs Spg 15653 045
- G21G12G3il Forwards GA Program Insp Rept 999007B0/B2-01 on B20712-16 & notice of violation & monconformance
 PGTAFOVS, U Division of Vandor & Technical Programs
 B2/09/15
 BTEVENBON, J G Magnetrol International Inc 2pp 15652
- --8210120912 Notice of violation from insp on 820712-16
 # Division of Vendor & Technical Programs 82/09/15 is \$5652.061
- --82(0120317 Notice of nonconformance from insp on E20712-16 # Sivision of Vendor & Technical Programs 82/09/15 ip 13652:062.
- 6210150513 Ack receipt of 820713 & 0914 lift re nonconformances noted in GA Program Insp Rept 9900289782-01 POTAFOV8.9 Division of Vendor & Technical Programs 62/10/08 DUSROWA & Barg-Marner Corp. 1p. 15714 212
- ~-8210150517 Responds to NRC 820831 ltm re nonconformances noted in 0A Program Insp Rept 99900289/82-01 Corrective actions systematic check of drawings made No syldence of similar error found MILINAZZO.P.L. Barg-Herner Corp. 0~82~084/PLM 82/07/16 PUTAPOVB.U. Division of Vendor & Technical Programs 3pp 15714 213
- --8210150521 Ack receipt of 820713 ltr re honconformances in Program Thep Rept 79700289/82-01 Response unacceptable. Required design incomplete Revised response expected within 25 days of ltr receipt POTAPOVS.U Division of Vendor & Technical Programs DUSROW.A L Sorg-Warner Corp in 15714 216
- --8210150526 Responds to NRC itr re-nonconformances noted Insp Rept 99900289/82-01 Corrective actions disagraps ; revealed nonconformance Systematic check of remaining drawings found no similar error MJLINAZIG,P L. Barg-Marner Corp Q-82-063/PLM 82/0 POTAPOVS.U. Division of Vendor & Technical Programa 15/14-217.

- 6210150522 Ack receipt or 811123, 820111 & 0723 ltrs in response to GA Program insp Rept 99900759/81-01 Efforts to account for 10 missing or unaccounted for defective springs & 8 remaining governors w/defective springs continuing POTAPOVS, U Division of Vendor & Technical Programs 82/10/08 SUNDSTEDTIJ & Moodward Governor Co Ip 15713 149
- --B210150536 Forwards 1tr sent to customers to exemption from 10CFR21 6 posting regulations, per NRC 820506 1tr & in response to GA Program insp Rept 97900759/81-01 List of customers enci ZWIEG.A Hoodward Governor Co. 82/07/23 POTAPOVS, U. Division of Vendor & Technical Programs. 6pp. 15713 150
- --8210150540 Ack receipt of Bili23 & 820111 ltrs in response to GA Program insp Rept 97900759/81-01 lnfo re corrective action measures required within 25 days PDTAPDOS.U Division of Vendor & Technical Programs 92/05/06 SUNDSTEDT.J E Woodward Governor Co 1p 18713 156
- ---8210190544 Supplemental response to violations noted in GA Program
 Insp Rept 99900799/01-01 Corrective actions second complete
 investigation results search conducted to verify original
 results Ltrs to customers encl
 VEITCH.J L Woodward Operior Co 82/01/11 POTAPOVS, U Vendor
 inspectson Branch 51pp 15713 157
- 8210170369 Ack receipt of 820930 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900769/82-02 POTAPOVS.U Division of Vendor & Technical Programs 82/10/14 HESS.L & Pacific Air Products Co ip 19741 [33]
- --B210190372 Responds to NRC B20823 ltr re monconformances noted in GA Program Insp Rept 99900769/82-02 Corrective actions calibr date labels on micrometers talipers & Porta-Lab replaced & GC insp implemented to inspect/replace labels Audits encl RESS.L R. CONLON.E T. Pacific Air Products Co. 82/09/20 POTAPDVS.U. Division of Vendor & Technical Programs. 20pp 15741-134.
- 8210190725 Forwards QA Program Insp Rept 99900902/82-06 on 820525-26, 0603-05 & 29-0701 No noncompliance noted POTAPOVS,U Division of Vendor & Technical Programs 82/10/01 SHITH E W Hyle Laboratories 3pp 15737 114
- --8210190761 GA Program Insp Rept 97900902/82-06 on 820525-26,0603-05 & 29-0701 No noncompliance noted Major areas inspected first 24-h of LOCA/HELB environ qualification tests for Fosboro N-E 10 & Rosemount 1193 Series D pressure transmitters PHILLIPS-H 3. JGHNSGN.A R Division of Vendor & Technical Programs 82/09/20 11pp 15737 117
- 8210190756 Forwards QA Program Insp Rept 99900907/82-02 on 620621-22 No noncompliance moted POTAPOUS, U Division of Vendor & Technical Programs 82/09/27 EDELSTEIN, A National Testing Systems Opp 15737 105
- --8210190766 QA Program Insp Rept 97900707/82-02 on 820621-22 No noncompliance noted Major areas inspected followup insp of alisyations made against employee & initial testing of Dorg Warner modulating electrohydraulic valve operator AGEE. J R. PHILLIPS.H S. Region 4. Office of Director 82/09/23 App. 15737 108
- 8210220407 Responds to 820803 itr re Woodward Obvernor Co failure to adopt appropriate procedures, per 10CFR21 21(a) & failure to post procedures, per 10CFR21 & Dedication of governors falls on procuring party, per 10CFR21 POTABOVS. U Division of Vendor & Technical Programs 82/10/05 HORIARTY, J Colt Industries, Inc. 1p 15778 297
- ~-B210220417 Discusses Woodward Governor Co failure to comply w/10CFR21 6 posting requirement No further action will be talen unless advised by NRC MCRIARTY.J M Coit Industries Inc 82/08/03 PDTAPDV9,U Division of Vendor & Technical Programs 3pp 15778 278
- 8210250121 Ack receipt of 820923 ltr informing NRC of steps taken to correct nonconformance noted GA Program Insp Rept 99700005/82-01
 POTAPOVS.V Division of Vendor & Technical Programs 62/10/20
 JACOBI.W N Westinghouse Electric Corp 19 15787 038
- --8210250128 Responds to NRC 820902 itr re nonconformance noted in GA Program Insp Rept 77900003/82-01 Corrective actions GC instruction revised to include instruction to area supervisors & procedure placed in assigned book RUSSO, H L Westinghouse Electric Corp 82/09/23 PDTAPOVB, U Division of Vendor & Technical Programs 3pp 15787 039

- 92:0250:35 Ack receipt of 820924 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900294/82~01
 POTAPOVS, U Division of Vendor & Technical Programs 82/10/20
 HOWURD, D.L. Westinghouse Electric Corp. 10 15787 007
- --8210250141 Responds to MRC 820817 ltr re nonconformance noted in QA Program Insp Rept 99900294/82-01 Corrective actions ltr sent to district sales ofce requesting copy of customer purchase order for any nuclear safety-related orders
 MCKEEVER.R F Westinghouse Electric Corp 82/09/24 POTAPBYS, U Division of Vendor & Technical Programs 3pp 13787 008
- 8210260126 Forwards GA Program Insp Rept 99900400/82-03 on B20817-10 & notice of nonconformance POTAPOVG.U Division of Vendor & Technical Programs 82/10/05 GUILBERT, D G Babcock & Milcox Co 2pp 15799 057
- --8210260127 Notice of nonconformance from insp on 820817-18

 « Division of Vendor & Technical Programs 82/10/05 2pp
 15797 059
- --8210260131 GA Program Insp Rept 99900400/82-03 on 620817-16
 Noncompliance noted error identified in hybrid computer
 program POWER TRAIN not processed per Procedure NPG-0903-13
 HALE: C J Division of Vendor & Technical Programs 82/09/27
 700 15799 061
- 8210260494 Forwards GA Program lnsp Rept 99900003/82-02 on 820824-27 & notice of nonconformance POTAPOVS,U Division of Vendor & Technical Programs 82/10/12 LONG J A Deneral Electric Co 20p 15805 116
- ~-8210260496 Notice of nonconformance from insp on 820824-27
 Division of Vendor & Technical Programs 82/10/12 2pp
- ~-8210260558 QA Program insp Rept 9990003/82-02 on 820824-27
 Noncompliance noted all purchase order requirements not
 verified, purchased bulk chemicals not always examined upon
 delivery & hardness tester not calibr every 3 months
 MCNEILL-W M , BARNES: 1 Division of Vendor & Technical Programs
 82/10/05 Bpp 15805 120
- RECOD REGULATORY CUIDES
- B210060009 Draft Reg Guide i XXX, Revision 3, "LER 8ys"

 NRC No Detailed Affiliation Olven 81/11/16 22pp 15731 215
- 8210050017 Forwards proposed response to Ballot N13 on proposed ANBI Std N721.per draft Reg Guide OP 713-4, "Internal Dosimetry Stds for Iritium." for concurrence COOL.M Occupational Health Standards Brench 79/03/16 URODSKY.A NRC - No Detailed Affiliation Olven 4pp 15612 332
- ---8210050020 Forwards "Quidelines for Bloassay Requirements for Tritium" to assist in development of licensing program, per draft Reg Quide OP 713-4

 ALEXANDER.R.E. Occupational Health Standards Branch, (after 740072.4 see SB091) 77/10/27 SINGER.B Radioisotopes Licensing Branch (Pre 790001) ip 1562-335
- --8210050026 Concurs w/NMSS position on proposed ANBI Btd, N721, "Internal Dosimetry Btds for Tritium." per draft Reg Guide GP 713-4 Considerable empirical data available to develop reg guide similar to branch position used by NMSS BRODSKY, A NRC NO Detailed Affiliation Civen 79/01/21 COOL, W Occupational Health Standards Branch 2pp 15612 344
- --8210050030 Forwards Environ Evaluation Branch comments on proposed ANG Std N721, "Internal Dostmetry Stds for Tritium" per draft Reg Guide OP 713-4 Std suitable for implementation as reg guide DENTGN-HR Office of Nuclear Reactor Regulation, Director 79/01/29 HINDOUE,R Office of Standards Development, Director App 13612-346
- --8210050034 Comments on proposed ANSI Std N721. "Internal Dosimetry Std for Tritium." per draft Reg Quide GP 713-4 Document Unacceptable as reg guide in present form because prof background required for comprehension CUNNINOHAM; R E Division of Fuel Cycle & Material Bafety 77/01/23 OCLERK Division of Biting, Heelth & Bafeguards Standards 3pp 15412 350

- --821CO50039 Recommends affirmative ballot re proposed ANBI Std N721.
 -Internal Dosimetry Stds for Tritium." per draft Reg Guide
 CP 783-4
 APSEMALIF. J Division of Safeguards. Fuel Cycle & Environmental
 Regearth 79/01/18 OCLLER.K R Division of Siting, Health &
 Safeguards Standards ip 15612 353
- --E21G050042 Requests technical review of encl proposed ANSI Std N721, *Internal Dosimetry Stds for Tritium" per draft Reg Guide GP 713-4 Recommendations for action on Ltr Ballot N13 requested by 7f017 M/o encl GQLERK R Division of Siting, Health & Safeguards Standards 78/12/27 DAVIS, J G Office of Inspection & Enforcement. Office of the Director DENTON.H R Office of Nuclear Reactor Regulation, Director DIRCKS,W J Office of Nuclear Material Safety & Safeguards, Director 2pp 15612 354
- Eliazod112 Reg Guide 2 B. Revision 2, "Preparation of Environ Repts for U Mills " • Office of Nuclear Regulatory Research, Director 82/10/31 49pp 13763 318
- Elicabolic Forwards prograetary & nonproprietary responses to Revision its Res Guide 1 92. "Combining Model Responses & Spatial tersons in Seismic Response Analysis" to assist in fuel assistly analysis Response withheld (ref 100FR2 790). TALEEF Pestinghouse Electric Corp NS-EPR-2659 82/09/17 SERLINGER, G. NEYER, R. O. Core Performance Branch 2pp 15803 045
- --5210240351 Submits application for withholding proprietary response to Revision t to Reg Guide 1 72, "Combining Model Responses & Eyattal Components in Scismic Response Analysis " Affidavit & nosproprietary response encl WIESEMANNR A Westinghouse Electric Corp AW-82-55 82/09/17 REPLIMEER, C H Corp Performance Branch 7pp 15803 047
- \$2.000247 Comments on draft Reg Guide QP 722-4, "Qualification for Paration Safety Officer in Large-Scale Non-Fuel-Cycle Referencies Program " Small hosp will be at disadvantage 14 fulfi is adopted ALENJJ St Luxes Hosp Milwaukee, WI 82/09/28 BELLJ M NRC No Dataited Affiliation Oliven 2pp 15854 088

12200251 Comments on draft Reg Guide OP 722-4, "Qualification for Fifiation Bafety Officer in Large-Scale Non-Fuel-Cycle Program " Guide should be more specific re program requiring expertise CACM-S R Forbrs Health Sys, East Suburban Health Center Mitterville, PA 82/10/15 Docketing & Services Branch 1p 1555 125

RESEARCH AND TECHNICAL ASSISTANCE REPORTS

- Ed0060425 "Quarterly Mgt Rept ORNL Programs for NRC Ofc of Nuclear Agailtong Research," third quarter ICHSAL, BAYLOR, V.B., HOMAN, F.J. Oak Ridge National Laboratory 27/9/01 Office of Nuclear Regulatory Research, Director 72pg 1555-308
- KIMMO169 "SSC Development, Validation & Application, " & "Owneric Inlace of Plant Modeling," monthly highlights for Aug 1982 92FT.J 0 Brookhaven National Laboratory FIN A-3015 B2/09/08 UMIS.8 T Bever Accident Assessment Branch Bpp 15637-348
- E 069322 "Actual Emission/Flaw Relationships for Inservice Multipling of Nuclear Pressure Vessels," monthly progress righton Aug 1982 3,773,P H. HUTTON,P H. Battelle Memorial Institute, Pacific Knitest Laberatory FIN 8-2088 82/09/22 MUSCARA, J. Materials "spirering Branch 8pp 15668 323.
 - H20118 "Reactor Expert Sys for Diagnosis & Treatment of Nuclear Hilor Accidents," presented to Natl Conference on Hillital Intelligence, 820818-20 H20NJR R E040, Inc. E00-M-09782 82/08/20 Office of Nuclear Hydrary Research
 - 018124 "Multimethods Approach to Bafety Parameter Display Vibation" AVS.K B., SLACKMAN, H. B., QERTMAN, D. I. EQ4G, Inc. EQG-M-11782 AVS.K B., ARC. No Detailed Affiliation Given 7pp 15692 255

- 8210120367 "Source Terms of Radionuclides in Ghallow Land Burial Sites " PIETRZAK,R F , DAYAL,R Brookhaven National Laboratory BNL-NUREQ-31834 82/10/05 NRC - No Detailed Affiliation Given 9pp 15690 213
- 8210120368 "Approximate Tolerance Intervals Based on Max Likelihood Estimates" "ATHOOD.C L EO&G. Inc EGG-M-11682 82/10/05 NRC - No Detailed Affiliation Given 22pp 15690 191
- 8210120390 "Stress Corrosian Cracking of PMR Steam Generator Tubing," monthly highlights for Aug 1982 VAN ROUYEN.D Broothaven National Laboratory FIN A-3208 B2/09/17 TABOADA.A Office of Nuclear Regulatory Research, Director 5pp 15691 103
- 82:0120397 "Safety Parameter Display Sys Progress Statement "
 MEYER O R E000, Inc HARMON D L Combustion Engineering, Inc
 LONGA B Electric Power Research Institute E60-M-04382
 B2/10/05 NRC No Detailed Affiliation Given 13pp 15691 124
- 8210120400 "LWR Bebris from Severe In-Pile Transient Tests " HODBINS.R R . COOK.8 A . MASON.R E EG&G. Inc 82/10/05 NRC -No Detailed Affiliation Given 5pp 1569; 137
- 8210120428 "Investigation of Accident Induced Flow & Matl Transport in Nuclear Facilities," progress rept for Aug 1982 MARTIN,R A., OREGORY,W S. Los Alamos Scientific Laboratory FIN A-7029 &-6-507 (R673) 62/09/28 BERNSTEIM,S. Transportation & Materials Risk Branch 6pp | 15671 161
- S210120430 "Polynomial Regression for Tektronix 4052 Computer" BHATIA/P E0&0. Inc FIN A-6043 E00-LGFI-5937 82/09/30 LANDRY.R P Experimental Programs Branch 92p 15571 067
- 8210120453 "Rept of Foreign Travel of AP Malinauskas to England. Austria & Germany." foreign trip rept MALINAUSKAS.A Oak Ridge National Laboratory FIN B-0127 GRNL/FTR-1355 82/09/07 MINOGUE.R B Office of Nuclear Regulatory Research, Director 2pp 15671 167
- 8210120455 "Stress Corrosion Cracking, Calvanic Corrosion & Selective Leaching Test Requirements for TiCode-12 High Level Waste Containers," draft rept BIBNIND B Brookhaven National Laboratory FIN A-3167 BNL-NUREO-31755 82/09/3; Office of Nuclear Material Safety & Safeguards Director 43pp 15671 210
- 8210120459 "Crevice Corrosion Data Requirements for TiCode-12 High Level Maste Containers," draft rept LEE,B B Brookhaven National Laboratory FIN A-3164 BNL-RURED-31775 82/08/31 Office of Nuclear Material Safety & Safeguards, Director 26pp 15671 253
- 82(0)20460 "Hechanical Failure Mode Data Requirements for TiCode-12 liigh Level Waste Container Sys." draft rept SDD.P. BREWSTER,C., SCHWEITZER.D.O. Brookhaven Mational Laboratory FJN A-3164 BNL-NURED-31774 82/08/31 Office of Nuclear Material Safety & Safeguards.Director 17pp 15671 279
- 8210120463 "Statistical Margin to DNB Safety Analys LOFT" ATKINGON, S A EQ&O, Inc 82/10/05 Office of Research, Dire '-- '00- '44/-- --
- 8210120400 On..... Requirements for TiCode-12 High Level
 Haste Containers." draft rept.
 JAIN.K Broothaven National Laboratory FIN A-3167
 BNL-NUREO-31754 82/09/31
 Bafeguards: Director 34pp 15671.310
- 02/01/20530 "HTOR Bafety Program," monthly highlights for Aug 1982 BABTAE.C Brookhaven National Laboratory FIN A-3016 02/09/14 FOULDB.O Diffice of Nuclear Regulatory Research, Director 488 15672.360.
- B210120649 "Thermal-Hydraulic LMFBR & LWS Bafety Experiments,"
 monthly highlights for Aug 1982
 OINSBERG,T , ORECNE,Q A Broothaven National Laboratory FIN
 A-3024 82/08/31 CURTIS,R T. Severe Accident Assessment Branch
 Aon. 15684 237
- 8210120453 "Rept of Foreign Travel of TS Kress to Heeting of CSNI Oroug of Experts on Nuclear Aerosols in ParisiFrance re Aerosol Release & Transport Program." Foreign trip rept. KREBS: T 8 Oak Ridge National Laboratory FIN 8-0121 ORNL/FTR-137: 82/09/15 BILBERO: M Division of Accident Evaluation 899 15672 279

- 82i0120654 "TRAC-BD1 Turbine Model for Code Development & improvements" informal technical rept GILES:M M E08G. Inc. FIN A-6052 EGG-CDD-6029 82/09/30 ODAR:F Office of Nuclear Regulatory Research. Director 47pp 15472 287
- 8210120557 "Advanced Display Concepts in Nuclear Control Rooms "
 CLARKIM T . BANKS,W W . BLACKMAN,H S E080. inc 82/10/05
 Office of Nuclear Regulatory Research. Director 11pp 19672 335
- 8210150409 Speech entitled. "Sealing Criteria & Assessment of Semiscale Mod-3 Scaling for Small Break Loss-of-Coolant Transients." presented at NRC/ANS 820914-15 meeting on Basic Thermal Hydraulic Mechanisms in LWR Analysis in Bethesda, MD LARSUN.T K. ANDERSON, J L. SHIMECK, D J E086, Inc E69-M-21082 82/09/15 47pp 15716 001
- 8210150412 Speech entitled, "Power Burst Facility Severe Fuel Damage Test Program," presented at 820728-1001 Intl Topical Meeting on Irradiation Technology MCCARDELL,R K , MACDONALD,R & EG&G, Inc. EGG-M-06682 82/10/01 17pp 15716 049
- B210150415 Speech entitled, "Monitoring PtB Reactor Vessel Liquid Level w/BPND During LOCAs:" presented at ANB 820922-24 meeting on Advances in Reactor Physics & Core Thermal Hydraulict ADARS. J P 60%0, inc EGG-M-14082 82/09/24 15pg 15716 0&B
- 8210150421 "Natural Circulation in Experimental Facility Scaled from PUR" LOOMES G C EG&G, Inc SDDA, K Japan Atomic Energy Research Inst 82/10/12 NRC - No Detailed Affiliation Given 6pp 15716 UB4
- 9210150616 "Best Estimate Prediction for LOFT Experiment Series L6-8C." interim rept CONDIE.K Q EG&G. Inc FIN A-6048 EGG-LOFT-5982 82/08/31 MCPHERSON.C D Integral Systems Section 48pp 15717 017
- 8210150625 "LOFT Experiment Operating Spec.LOFT Anticipated Transient Series 1.6 Nuclear Experiment L6-8," interim rept Document Revision Requests 1.4950 & L.4954 enc!

 SILVERHAN. 8 EQ&O. Inc FIN A-6048 EGG-LOFT-5733 82/07/21 MCPHERSON, C D Office of Nuclear Regulatory Research. Director 63pp 15717 114
- 8210150631 "Exam of Health Effects Associated W/Unit Radionuclide Releases to Surface Environ " IELTON: J Arijona State Univ « Sandja Laboratories FIN A-1165 SAND92-1855 B1/12/31 Division of Waste Management 85pp
- 9210180497 "ORNL Programs for Ofc of Nuclear Regulatory Research," Jul 1992 monthly highlights LOTTS.A L. BAYLOR, V B., HOMAN, F J. Dak Ridge National Laboratory 82/09/25 Office of Nuclear Regulatory Research, Director 96pp 1574A 019
- 8210200102 "Fiber Optic Void Fraction Measurement Sys for Steam Generator in LOFT" SNYDERS C EGG. inc FIN A-8043 EGG-tOFT-5999 82/09/30 LANDRY. R R Division of Accident Evaluation 20pp 15767 283
- 8210270421 "Accident Aerosol Characterization," quarterly rept for Jul-Sept 1982 ONCZARSKI, P C Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2287 82/10/13 BERNSTEIN,S Transportation & Materials Risk Branch 18pp 15833 332
 - "Preliminary Two-Phase Instrumentation Evaluation," status
 - 3 R E089, Inc FIN A~6376 E00-1D-6040 82/09/30 N Instrumentation & Control Branch 23pp 15859 013

or Aug 1982," interim rept 76-LOFT-4039 82/09/30 72pp 15832 299 8210270397 "Network Flow & Transport/Distributed Velocity Methods, Self-Teaching Curriculum" FINLEY,N C Sentia Laboratories LONGSINE,D E Divewood Corp CAMPDELL,J E INTERA Environmental Consultants.Inc FIN A-1158 SANDB1-0826 81/08/31 Division of Waste Management 245pp 15866-083

REVIEW GRP NRC RESEARCH REVIEW GROUPS

- 8210010286 Concurs that NUREO-0744. "Resolution of Reactor Vessel Matis Toughness Safety Issue." need not be reviewed by CRGR STELLD.V Regional Operations & Generic Requirements 82/09/30 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 15573 181
- 8210040314 Summary of CROR Meeting 19 on 820915 re cost/benefit study of design requirements for Inadequate core cooling instrumentation & open technical issues from CROR Meeting if on 820324 STELLO. V Regional Operations & Generic Requirements 82/09/22 DIRCKS.W J Office of the Executive Director for Operations 6pp 15504 124
- E210080109 Notification of 8R1008 CRGR Meeting 22 in Bethesda, MD to consider proposed bulletin re-stress corrosion cracking as Category I requirement under provision of iII-D of CRGR charter Attendance should be limited to senior staff STELLO, V Regional Operations & Generic Requirements B2/10/07 EISENHUT, D G Division of Licensing JORDAN, E Director's Office of Fice of Inspection and Enforcement CUNNINGHAN, R Office of Nuclear Material Safety & Safeguards, Director ip 15640 021
- 8210120049 Forwards response to 820819 memo re standby shutdown racilities Postviated 88E tould cause failure of condenser circulating sys Util seismic criteria permits auxiliary syc water sys backup
 DENTON: HR Office of Nuclear Reactor Regulation, Director
 92/09/23 STELLO, V Regional Operations & Generic Requirements
 4pp 15689 207
- --8210120053 Requests briefing re standby shutdown facility design requirement changes, focusing on integration of NRC backfit efforts Briefing requested at 820708 CRQR meeting STELLO.V Regional Operations & Generic Requirements 82/08/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15889 218
- 8210120216 Forwards summary rept of CROR activities for 820828-1001 SCHWINK, W. Regional Operations & Generic Requirements 82/10/08 Regional Operations & Generic Requirements 6pp 15652 144
- 8210120326 Forwards 820713 ltr documenting 820623 meeting between Licensing Review Group 1 & NRR BOYDAR 9 KMC, inc 82/10/06 THOMAB.C 0 Standardization & Special Projects Branch 1p, 15652 333
- --B210120331 Forwards summary of 820623 meeting w/Licensing Review Group I Tech Spec Group & NRR in Bethesda. ND STB issues, proposed mods & justification enci BOYD, R S KMC, inc. B2/07/13 TEDESCO, R L Assistant Director for Licensing 52pp 15652 334
- 8210150138 Summary of CRGR Meeting 20 on 820921 re proposed resolution of reactor coolant pump trip issue & BWR pipe cracking issue STELLO. V Committee to Review Generic Requirements 82/10/05 BIRCKS.W J Office of the Elecutive Director for Operations Spp 15498 310
- 8210180002 Requests attendance at CRGR Meeting 23 on 821028 in Sethesda, MD to discuss cost/benefit info for alternatives for resolving pressurized thermal shock issue STELLO, V Committee to Review Generic Requirements 82/10/14 EISENHUT, D Division of Licensing JORDAN, E L Division of Engineering & Quality Assurance CUNNINGHAM, R E Office of Nuclear Material Bafety & Safeguards, Director ip 15718 024
- 8210190006 Notifies of CROR Heeting 20 on 820921 to discuss proposed resolution of reactor coglant pump trip issue & proposed bulletin to address BHR pipe cracking STELLO.V. Regional Operations & Generic Requirements 62/09/20 EISENHUT, D. G. Office of Nuclear Reactor Regulation, Director, JORDAN, E. L. Director's Office, Office of Inspection and Enforcement HAUSSHARDT, D. B. Office of Nuclear Material Safety & Bafeguards, Director 50pp 15760-240

- ELICOCOP2 Designates R Purple as NRR co-chair of Safety/Safeguards fitted Committee Comprehensive re-evaluation of sifety/safeguards program should consider human factors elegants CAITCH, H & Office of Nuclear Reactor Regulation, Director 22.707/30 DAVIS, J & Office of Nuclear Material Safety & Safeguards, Director 4pp 15761 115
- -Ril190075 Responds to encl Commission 820816 memo & forwards draft
 Setsg/Safequards Review Committee charter, describing
 stoposed committee responsibilities
 stoposed committee responsibilities
 Street, R.F. Division of Safeguards 82/07/14 STELLO, V
 Pagsonal Operations & Generic Requirements DENTON, R.R. Defice of
 N-clear Rescute Regulation, Director MINDGUC, R. Defice of
 N-clear Rescute Regulation, Director 2pp 15761 119
- 11:10:18 Responds to B20805 ltr re unresolved issues from 820415 ltr re inadequate requirements developed per TMI Item 1 D I savignment of responsibility for human factors within NRC & savignment of responsibility addressed savignment of the savi
- --EXYJIBOOBS Informs that response to 820615 ltr incomplete in areas of 3-can factor evaluation of AOs & ability of operator to act as trained SEEHY,E J Affiliation Unknown 82/08/05 PALLADIND,N J Camissioners 8pp 15758 234
- SittPOSDI Ferrards long-range CROR agenda for Oct 1982-Sept 1983 Mods for signal items not reflecting current status should be first affect to H Schwink by Editol Listed info for new items for consideration re 820616 CROR charter requested ITELLO.V Committee to Review Generic Requirements 82/10/18 IDECTA . MINDOVER B NRC No Detailed Affiliation Given CAUTOMHR Office of Nuclear Reactor Regulation, Director 12pp 13749 013
- 81.2350331 Notifies of CROR meeting on 821103 in Bethesda, MD Requests the firstions limit attendance to senior staff needed to stiffess stands items
 STELO.Y Regional Operations & Generic Requirements 82/10/20 STELO.Y Regional Operations & Generic Requirements 82/10/20 STELO.Y D Division of Licensing 29p 15787 114
- E.M70199 Summary of CRGR 22nd meeting on S21008 re proposed IE Littin. Stress Corrosion Cracking in Thick-Mall Large Claster Stainless Steel Recirculation Sys Piping at BWR Flists & reactor coolant pump criteria for PWRs Fittur Regional Operations & Generic Requirements IED-79-05C EM10/20 DIRCKS: U.J. Office of the Executive Director for Curations dpp 15822 357.
- ETROMB Comments on summary of CROR Meeting 21 on 821006 re proposed printing criteria for vessel ref temp NDT Figure provides implicitual crack extension frequencies for mean surface while than computed mean plus 2 sigma SMMDJF RRG No Detailed Affiliation Given 82/10/26 IELEC Regional Operations & Generic Requirements ip 1937-043
 - EDENOSI Summary of CROR Meeting 21 on 821006 in Bethesda.MD List of attenders and section at Generic Requirements 82/10/20 MRESAW J Office of the Executive Director for Operations App 19839 044

ET POSITION PAPERS BEFORE THE COMMISSION

Z52049) EECY-82-184
kiiflik Cesaission of current status of makeup nozzle
kiiflik Cesaission of current status of makeup nozzle
ritide problems in B&W plants Problem under evaluation
Pidenters have established task group to oversee followup
stills Group will meet w/NRC in early May 1982
IMASS V Office of the Executive Director for Operations
RXCS/01 6pp 15597.082.

\$253312 SECY-82-247
Griders postponing work on comprehensive fire protection
firs for nuclear power plants, Recommends Commission redirect
full to prepare comprehensive fire protection rule for new
rollin power plants by June 1984.
BURGAN J Office of the Elecutive Director for Operations
BURGAN 1 6pg 13636 033.

- 8210040360 Responds to FDIA request for SECV-82-728 & SECY-82-72C re coordinated program for steam generators Documents available in PDR FELTONIJ M Division of Rules and Records 82/09/27 FORTINO.K C Lowenstein.Newman.Ress.Arelrad & Toll 1p 15597 291
- --B204200390 SECY-82-0728
 Responds to Chairman 620301 request for short-term actions reperformance of steam generators Comprehensive water chemistry criteria for steam generators should be implemented
 DIRCKS:W J Dffice of the Executive Director for Operations
 82/04/03 2pp 15597 292
- --8205270507 SECY-82-072C
 Advises Commission of results of 820428 meeting w/sndustry
 re-proposed coordinated program for steam generators
 Proposal in SECY-82-72A re-formal structural organization
 such as policy group & steering committee rejected
 DIRCHS.W J Office of the Executive Director for Operations
 82/05/17 3pp 15597 294
- 8210190144 Responds to FOIA request for SECY 82-232 re use of nonplant-specific simulators for initial replacement & requeilification exams for licensed reactor operators & senior operators
 FELTON.J H Division of Rules and Records 82/09/30 ARMSTRONG,K A Debavoise & Liberman 2pp 15760 178
- --8206180042 SECY-82-232
 Recommends requirements of simulator licensing exam be continued for power reactors w/plant-specific simulator Oral exam per 100FR55 23 should be administered where facility has no plant-specific simulator DIRCKS.W J Office of the Executive Director for Operations 82/06/07 14pp 16002 236
- 9210220534 SECY-82-399
 Informs Commission of status of "Nuclear Standardization Act of 1982" & proposed plan for 1983 legislative proposals TOURTELLOTTE, J. Regulatory Reform Task Force. 92/09/30 28pp 15786-049
- 8210270083 Add1 response to FOIA request for eight categories of LERs Forwards documents listed in App A App B documents withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 82/09/20 ARNOLD, J Miami Herald 4pp 15836 221
- B210270322 SECY-82-407
 Advises of issues remaining from 820108 meeting reinstrumentation for detection of inadequate core cooling in PMRs Requests action on update recommendations for implementation of NURE9-0737, item [I F 2 DIRCKB, H J. Office of the Ejecutive Director for Operations 82/10/07 12pp 15951 323
- B210270373 Transcript of B20727 public meeting on SECY-82-352 re QA in Washington.DC.Pp 1-85 Marked-up SECY-82-352 encl PALLADING.N., OILINSKY.V., AMEARNE.J. Commissioners B2/07/29 146pp 15865 268

STATE PROD STATE PROGRAMS

- 82:00:00|6 Comments on state actions outlined in 82:06:17 & 09 ltrs re NRC recommendations on State of KY radiation control program Program adequate to protect public health & safety NRC should be kept informed of staff augmentation O'REILLY, J.P. Region 2: Office of Director 82/08/13 BTUMBD.W G Kentucky, State of Rpp. 13365-160
- 821001004B Forwards rept of NRC 1982 review of State of TN radiation control program for agreement matts Program adequate to prutuct public health & safety Physicists should receive specific radiation safety control training.

 HODDRUFF.R.L. Region 2. Office of Disector. 82/09/13
 FOWINKLE.E M Tennesses, State of 106pp 15565 010
- B21001010D Responds to B20609 itr re NRC review of State of KY radiation control program NRC comments re review of selected license files encl Licensing comments minor.Rept not yet completed.

 SWOODRUFF,R L. Region 2, Office of Director. 82/08/13 HUGHES, D Kentucky, State of 12pp 15565,243

- 8210010154 Forwards rept % evaluation of State of MS radiation control program for 800426-810911 Program adequate to protect public health & safety MDDRUFF,R L. Region 2, Office of Director 82/09/08 COBB,A B Mississippi. State of 72pp 15568 140
- 82:0010358 Forwards "Rept & Evaluation of GA Radiation Control Program for Period Jul 15, 1980 to Nov 25, 1981, " twelfth regulatory review program MODDREFF.R L. Region 2, Office of Director 82/09/10 LEDBETTER.J G. Georgia, State of 1p 15574 160
- --8210010363 "Rept & Evaluation of GA Radiation Control Program for Period Jul 15:1980 to Nov 25:1981." twelfth regulatory review program * NRC - No Detailed Affiliation Given 82/09/10 129pp 15574 161
- 62:0120015 Partial response to FOIA request for documents re St Joseph Hosp in Albuquerque, NM & I-125 seed incident Forwards documents listed in App A FELTON, JM Division of Rules and Records 82/08/20 DAVIES, L S Richards, Orandt, Miller & Nelson 3pp 15691 173
- --8012180362 PNA-80-037 on 801201. State of NH informed NRC of oversiposures of patients receiving 1-125 seed therapy for treatment of prostate cancer Causedby computer dose conversion factor error State request hosp rept LUBENAU, J O Office of State Programs. Director 80/12/02 ip 15691 176
- --8210120023 Requests assistance in independent technical review of encirent from St Joseph Hosp re misadministration of [-125 seed implant Ltr delineating info required & article from Albuquerque Journal enct M/o encl HOLFF.T A New Mexico. State of 81/02/03 NUSSHAUMER.D A Assistant Director for State Agreements Programs ip 15691 192
- --B210120027 Forwards rept to St Joseph Hosp, Albuquerque, NM remissadministration of I-125 seed implant Event attributed to personnel error & lack of communication between computer plan developers & users Comments requested by 810227 NUSSBAUMER, D.A. Assistant Director for State Agreements Programs 82/02/23 HIOGINBOTHAM, L. Radiological Bafety Branch CUNNINGHAM, R.E. Advanced Fuel & Spent Fuel Licensing Branch | Jp 15691 193
- --8210120037 Forwards WR Hendee review of selected matls re misadministration of I-125 seeds at St Joseph Hosp, Albuquerque W/o enci NUSSBAUMER, D A Assistant Director for State Agreements Programs 61/03/25 H100ENBOTHAM, L Radiological Safety Branch HILLER, V L. Licensing Management Oranch ip 13591 289
- --8210120075 Forwards State of NM rept of investigation of incident involving overexposure of patients treated w/1-125 seeds AD rept will be included in next quarterly rept N/o encl NUSSBAUMER. D A Assistant Director for State Agreements Programs B1/11/24 CUNNINGHAM. R E Advanced Fuel & Spent Fuel Licensing Branch ip 15492 040
- 82(0130152 Discusses insp of Western Industrial X-Ray at Hunters Point Naval Shippard on 820922 Two violations of DDT regulations, 49CFR 172-re placarding of transportation vehicle observed State of CA consideration of enforcement action requested 800K: H E Division of Radiological Safety & Safeguards Program 82/10/08 HONEY, D California, State of 2pp 15573 080
- 82:0190530 Forwards results of insp of Model Ce-30 gauge mfg by Industrial Gauging & Control GAMPBELL,M A Region i. Office of Director 82/10/12 CORCORAH,R G Maryland, State of 1p 15751 250
- --B210190533 Responds to 820806 request for insp of general licenses cility to obtain info re C-Frame type gauge mfg by dustrial Gauging & Control ENIAMERI, D J Region 3. Office of Director 82/09/20
- 8210270393 Notification of contract execution, Mod 3 to "Environ Monitoring Program w/State of NC " Contractor State of NC HOLLETTS Research Contracts Branch Fin 8-1239 NRC-03-80-102 SP/10/19 CORD : CONTRACTS Branch Fin 8-1239 NRC-03-80-102

- --8210270395 Mod 3, changing name of NRC billing ofc & address for submission of invoices to "Environ Monitoring Program u/State of NC " # North Carolina, State of GUSTAVE.R P Research Contracts Branch FIN B-1239 NRC-05-80-283 82/10/12 ip 15833 361
- 8210280386 Notification of contract execution, Mod 1 to "Establish Collaborative Program Between State & Commission to Provide Independent Heasurements of Radioactivity in Effluents & Environ "Contractor CT Dept of Environ Protection SILVIS.R M Administrative Contracts Branch NRC-05-73-011 82/10/15 COBB.L I. ROSE.H Director's Office, Office of Inspection and Enforcement 10 15859 236
- --82(0280397 Mod 1.deobligating funds, to "Establish Collaborative Program Between State & Commission to Provide Independent Heasurements of Radioactivity in Effluents & Environ Around Selected Commissioned Licensed Activities "HEURNER, A T Connecticut, State of GUSTAVE, R P Research Contracts Branch NRC-05-73-011 82/10/15 1p 15859 237
- 8210290085 Responds to FDIA request for lists of names & addresses of all NRC licensess in ME,VT.MA,OH,CT & MV & appropriate ofcs in Agreement States of NH.RI.NY & MD Forwards requested lists FELTON.J H Dsylsion of Rules and Records 82/10/15 PARKINSON.T W Interstate Nuclear Services 1p 15863 311
- --B210270070 Lists of active licenses for States of MA.VT.ME.CT.OH & HV & Agreement States as of 820910 & NRC No Detailed Affiliation Given 82/10/07 240pp 15863 312
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- 8207070000 Forwards response to NRC 820723 questions on BAW-10149P, "Statistical Core Design Applied to Babcock 205 Core," including proprietary response to Question 20 & microfiche records of computer runs associated w
- 82(0010008 Responds to FOIA request for 17 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- --8210050514 Topical rept evaluations of Revision 2 to WCAP-9558,
 "Rechamistic Fracture Evaluation of Reactor Coolant
 Fipe "& WCAP-9787, "Tensil & Toughness Properties of
 Primary Piping Weld Metal for Use in "

 NRC No Detailed Affiliation Given 82/06/28 26pp
 15731-005
- 8210010217 Forwards "Mark I Dwners Group Response to Humphrey Containment Concerns," per 820715 request SHERNODD, G Q General Electric Co MFN 138-82 82/09/24 EISENHUT, D O Division of Licensing 2pp 15567 351
- ~-8210010224 NSE0-88-0982

 "Mari I Owners Group Response to Humphrey Containment
 Concerns "
 BILLIO,P F , RODERS,A E General Electric Cp T23-00452
 82/09/30 28pp 15547 353
- 8210010351 Forwards proprietary NEDE-22232, "Shutdown of Reactor Power w/Boron Injection " Rept withheld GRAVES.C C Reactor Systems Branch 82/09/16 DIAMOND.D Brookhaven National Laboratory. 1p 15573.124
- 8210040229 Forwards XN-NF-507(P), "Exxon Nuclear Co Betpoint Methodology for C-E Reactors Statistical Setpoint Methodology. Suppl 1 " Rept withheld (ref 10CFR2 790) UMSLEY. OF Exion Nuclear Co. Inc. (subs. of Exxon Corp.) CFO 077 82 82709/29 THOMAS, C O Standardization & Special Projects Branch 4pp 15595 338
- 8210040275 Forwards complaint & amended complaint re law suit filed by ML Williams per BF Williams death allegedly caused by radiation exposure during employment from 1988 to Oct 1980 HARHARD. J E American Nuclear Insurers, 82/09/13 SALTZMAN. J Assistant Director for State & Licensee Relations 14pp 15587 155
- 8210040311 Forwards Revision 4 to SCP-D1-A, "RADCAL Gamma Thermometers as Local Power Measuring Devices for Use in Cores of PWRs," per NUREO-0390 MARINO, J. P. Bcandpower, Inc. 82/09/29, BERNARD, H. Standardization : & Special Projects Branch ip 15584:198.

- --22:CO40319 SCP-01-A R04
 Revision 4 to "RADCAL Gamma Thermometers as Local Fuel
 Revision 5 to "RADCAL Gamma Thermometers as Local Fuel
 Revision 4 to "RADCAL Gamma Thermometers as Local Fuel
 Revision 5 to 15 to
- FILCHORN Forwards nonproprietary & proprietary versions of Suppl 3 to Figural Rapt CEN-185, "Heated Junction Thermocouple Phase 118 Test Rept "Proprietary version withheld 118 Test 100FF2 7901

 REKINLY P C-E Operating Plants Guners Group DASKIN, K P Starker California Edison Co 82/09/30 BERNARD, H Starker California Edison Co 82/09/30 BERNARD, H Starker California Edison Co 82/09/30 BERNARD, H Starker California Edison & Special Projects Branch 7pp 15641 304
- EI:040394 Forwards request for add1 info re NNi-Bi-6(P), "Waste Silidification & Patkaging Sys "
 TICMAS.C O Standarditation & Special Projects Branch 82/09/08
 ESSEMBALH R Neuport News Industrial Corp (subs of Newport News
- ELDISOID4 Forwards revised organization chart for Div of Nuclear Power as described in TVA-TR75-1A. "GA Program Description for Issign.Const & Operation of TVA Nuclear Plants"

 **ILLS.L. H. Fennesses Valley Authority 82/09/29 HAABS.W P. Sp. Stranger Const. P. 15605 159
- i. UA0152 Forwards Steam Generator owners group comments on draft steam generator generic requirements discussed during 820729 resting SMMDDLAD Steam Cenerator Owners Group SCHMIDTLAD Florida STATE Light to 82/09/30 EISENHUT.D 0 Division of Licensing 12p 15603 244
- 2.0250255 Forwards proprietary & nonproprietary versions of AECC-2-NP 1P Refease to VRC \$\frac{1}{2}\] PRESENTE Val Reduction Sys.Amend 1," in response to NRC \$\frac{1}{2}\] 110 & 820428 requests for addition Proprietary version sixilid fref 10CFR2 790) (ARIMA Aerojet Energy Conversion Co (subs of General Tire & Lilly Co + StoO 2891 RG RR \$2/10/01 THOMAS, C Standardization & Special Projects Branch Ip 15615 109
- --:210050257 Affidavit of SP Ferreira requesting withholding of AECC-2-P, flatviete Vol Reduction Bys," from public disclosure (ref IOCFR2.790), FEREIRA B P Aerojet Energy Conversion Co (subs of General Yire FRobber Co) 82/09/29 App 15615 111
- -E2ICO50259 AECC-2-NP AOI
 h.proprietary version "Radwaste Vol Reduction Sys.Amend 1"
 s Aerojet Energy Conversion Co (subs of General Tire & Rubber
 to 8 E2/10/01 72pp 15415 115
- \$1000345 Forwards BAM-10153P, "Extended-Burnup Evaluation, "Rept will truid to suggest util customer OL applications for fuel litt average burnups up to 45,000 mMd/mtU Rept withheld lift 10CFR2 790).

 TAMOR.J H Babcock & Wilcox Co 82/09/30. BERGOREN. J. B Stanfardication & Special Projects Branch Spp 15615 100
- EINOTODIA Advises that proprietary WCAP-9863(P), "Rod Bank Worth Tastwinents Utilizing Bank Exchange," contains info of incern to NRC. Resolution of concern needed to proceed white NRC viewpoint withheld TOMASC 0 Standardization & Special Projects Branch 82/09/06 6ASEFP Mestinghouse Electric Corp. ip 15628 081
- :DOOLIO Forwards request for add1 info re XN-NF-82-25(P), "Generic Mitterical Design, Erxon 17x17 Fuel Assembly " Requests date for planned submitted of info Proprietary questions withing the property of the Proprietary Research B2/09/13, USEN, 6, For Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) ip. 1951 073
- 20060038 McAP-7870 Intiri from "Neutron Shielding Pads " : Histinghause Electric Corp. 72/05/31 4pp 15669 242

- 8210080138 Forwards "Potential for Mater Hammer During Restart of KHR Pumps for BHR Nuclear Plants " HUANO.Y S Director's Office AEOD/E105 81/03/31 MICHELSON.C Director's Office ip 15663 255
- --B2100B0165 "Potential for Water Hammer During Restart of RHR Pumps for BHR Nuclear Plants " HUANO.J Director's Office AEOD/E105 81/03/31 14pp 15663 256
- 8210080169 Forwards "Initial Consideration of Potential for Mater Hammer in Steam Condensing Mode of RHR Sys Operation for BMR Plants " HUANO, Y S Director's Office AEOD/E106 81/03/31 MICHELSON.C Director's Office 1p 15663 271
- --8210080172 "Initial Consideration of Potential for Hater Hammer in Steam Condensing Mode of RHR Sys Operation for BWR Nuclear Plants " HUANG, J Director's Office AEDD/E106 81/03/31 11pp 13643 272
- 82:0080229 Forwards proprietory response to E020 questions/comments resismic aspects of equipment qualification program & "Beismic Analysis of Safety Injectson Motors for Byron Nuclear Stations 1 & 2 & Graidwood Nuclear Stations 1 & 2 " RAHE, E P Westinghouse Electric Corp NB-EPR-2667 82:10/05 ROSZICCZY, Z Equipment Qualification Branch 1p 15438 007
- 8210080262 Forwards slide presentation w/summary of 820917 meeting in Dathesda. MD re Intergranular Stress Corrosion Cracking Progress Rept 8 Encl withheld (ref 10CFR2 790)
 ORIDLEY.R L Qeneral Electric Co MFN-141-82 82/09/30
 JBMSTORN M V Assistant Director for Materials & Qualifications
 Engineering 6pp 15638 00:
- 8210080267 Recommends OE t/or affected BMR licensees be requested to submit & commit to schedule for replacement of all hold down beams W/Improved design Potential for water hommer type loads on jet gump integrity should be evaluated MICHELSON,C Director's Office AEOD/E002 80/05/23 DENTON,H R DFFIce of Nuclear Reactor Regulation, Director 4pp 15667 270
- B210080274 Forwards "Roview of Emergency Response Guidelines Re-Pressurized Thermal Shock "
 KINOBLEY,O D Hestinghouse Operating Plants Owners Group
 KINOBLEY,O D Alabama Power Co 00-72 82/06/22 DENYON,H R
 Office of Nuclear Reactor Regulation, Director ip 15639 208
- --B210080297 "Review of Emergency Response Guidelines Re Pressurised Thermal Bhock " * Westinghouse Electric Corp. 82/06/30 86pp 15638 209
- 8210150173 Forwards nonproprietary "Combined Seismic-LOGA Mechanical Evaluation for Exxon Nuclear 15x15 Relaad Fuel for Hestinghouse PMRs" OHBLEY, 0 F Exxon Nuclear Co., inc. (subs. of Exxon Corp.) GFO 082 82 82/10/08 THOMAS.CO Standardization & Special Projects Branch ip 15706 361
- --B210180182 XN-NF-76-47(NP)(A)

 Nonproprietary "Combined Seismic-LOCA Mechanical Evaluation for Exxon Nuclear 15x15 Reload Fuel for Westinghouse PWRs "

 # Exxon Nuclear Co : Inc (subs of Exxon Corp) B2/10/04
 176pp 15707 001
- 8210150416 Forwards proprietary responses to NRC 820708 request for add1 info, Questions (-5 re NEOE-23785-1(P), "GESTR-LOCA & SAFER Models for Evaluation of LOCA" Responses withheld (ref 10CFR2 790)

 GUIRK-J F Ceneral Electric Co MFN-144-82 82/10/07 THOMAS, C O Standarfization & Special Projects Branch 19 19715 263
- 8210150445 Summarise 820802 meeting w/NRC re planned dynamic testing of BHR 4/5 HPCI turbine Mods to original HPCI seismic qualification test extremely conservative Viewgraphs and QUIRK, JF General Electric Co. MFN-146-82 82/10/07 JCHNBTON. W. V. Assistant Director for Materials & Qualifications Engineering 8pp. 15703 156
- 9210150461 Forwards slide presentation used at 820929 meeting w/NRC to discuss OE environ qualification program as defined in NEDE-24026-P Info withheld OUIRK, J F. Ganeral Electric Co MFN-145-82 82/10/07 JOHNSTON, H V Division of Engineering 2pp 15715-279
- B210130511 Forwards XN-NF-80-19(P), "Exton Nuclear Methodology for BHRs Application of ENC Methodology to BHR Reloads," Vol 4 Rept withheld (ref 100FR2 790) CHANDLER, J C. Exton Nuclear Co., Inc. (subs of Exxon Corp.) JCC, 098.82 B2/10/13 THOMAS, C C Btandardization & Special Projects Branch Ip. 15715.162

- 6210150656 Notification of 821005 branch meeting in BethesdarMD to discuss STS for rod position indication TAM.P S Operating Reactors Branch 1 82/09/28 VARQA.S A Operating Reactors Branch 1 tp 15715 310
- B210150681 Discusses review of Licensing Topical Rept XN-NF-77-57
 "Exton Nuclear Power Distribution Control for PMR Phase 11"
 Rept acceptable for referencing in Westinghouse-designed reactor reload license applications
 THOMAG. C Standardization & Special Projects Branch B2/09/24
 OHSLEY, O. P. Exton Nuclear Co., Inc. (subs. of Exton Corp.) 2pp
- 8210180023 Forwards request for additinfo needed to review Topical Rept CENPD-266(P). "ROCS & DIT Computer Code for Nuclear Design " THOMAS.C O Standardisation & Special Projects Granch 82/09/15 SCHERER,A E Combustion Engineering, Inc. 4pp 15721-265
- B210180050 Forwards NEDE-24632, "Mark I Containment Program Cumulative Distribution Functions for Typical Dynamic Responses of Mark I Torus & Attached Piping Sys." per NRC 820909 request Rept withheld PFEFFERLEN.H C General Electric Co MFN-147-82 82/10/07 VASSALLO,D B Operating Reactors Branch 2 9pp 15720 016
- B210190607 Submits add1 info per B21014 discussion \(\omega/\)C Lainas re review of Dresser safety valve performance observed in EPRI safety \(\phi\) relief valve test program Valves consistently achieved rated steam flow
 RAHELE P Westinghouse Electric Corp NS-EPR-2669 B2/10/15
 EISENNUT,D O Division of Licensing 3pp 15739 334
- 8210190755 Forwards comments on NRC proposed steam generator requirements, distributed at 820727 meeting w/NRC & industry representatives in Detheada. MD MILLS, L. M. Tennessee Valley Authority 82/10/13 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp 15737 100
- B210190810 Forwards proprietary slide presentation entitled, "GE BWR Fuel Performance" from NRC/GE 820708 meeting in San Jose, CA Slides not properly labeled proprietary Slides withheld (ref 10CFR2 790) CHARNLEY J General Electric Co JSC-017-B2 82/10/12 BERLINER, C H Core Performance Branch 1p 15736-317
- e210200113 Notification of 921015 meeting w/BHR numers group & EPRI in BethesdarMD to discuss status of research on pipe cracking in ENRs & questions raised at 820927 meeting w/BMR licensees CLARK, D Operating Reactors Branch 2 82/10/13 VASSALLO, D B Operating Reactors Branch 2 3pp 15767 320
- 8210210329 Forwards proposed proprietary Revision 3 to Topical Rept ERR-1(P)-A. "Ederers Nuclear Safety-Related Extra-Safety & Monitoring (X-SAM) Cranes "Rept withheld (ref 10CFR2 770) CLARK,C W Ederer, Inc. 82/10/08 THOMAS,C Standardization & Special Projects Branch 2pp 15765 296
- 8210220152 Notifies of organization re restructuring within Water Reactor Div effective 820727 & forwards clarification of GA program plan GA plan in MCAP-8370 is accurate description of GA program controls GAUTET Westinghouse Electric Corp. NS-EPR-2666 82/10/14 Quality Assurance Branch 13pp 15778 093

- 8210260072 Notification of 820930 meeting w/8&W in Bethesda, MD to discuss status of work re generic accident source term considerations
 HOUSTON.R W Assistant Director for Radiation Protection 82/09/21
 DENTON.H R, CASE, E, MINOGUE, R NRC No Detailed Affiliation Oiven ip 15808 359
- 8210260305 Requests review of Instrumentation & Control Sys Branch proposed requirement for addit reactor trip breaker circuit tests in near-term Westinghouse plants TVA recommended procedures represent potential threat to safety RAHE,E P Westinghouse Electric Corp NS-EPR-2660 82/[0/18 SPEIS.TF Division of Systems Integration (post 811005) 2pp 15805 231
- --8206300370 Ack receipt of 820427 ltr providing position on testing of shunt trip circuits of reactor trip breakers in Westinghouse plants Instrumentation & Control Sys Branch does not concur w/vendor position Evaluation enc!

 ROSA: F Instrumentation & Control Systems Branch 82/06/18

 RAME: EP Westinghouse Electric Corp 6pp 15805 233
- 8210260340 Forwards proprietary & nonproprietary responses to Revision i to Reg Guide 1 92, "Combining Model Responses & Spatial Components in Sefamic Response Analysis" to assist in fuel assembly analysis Response withheld (ref 10CFR2 790) RAHG, E P Westinghouse Electric Corp NS-EPR-2568 82/09/\$7 DERLINGER, C , MEYER, R Q Core Performance Branch 2pp 15803 045
- --92i0260351 Submits application for withholding proprietary response to Revision 1 to Reg Ouide 1 92, "Combining Modal Responses & Spatial Components in Seismic Response Analysis " Affidavit & nonproprietary response enci WIESEMANN.R A Hestinghouse Electric Corp AW-82-55 82/09/17 BERLINGER.C H Core Performance Branch 9pp 15803 047
- 9210270092 Forwards proprietary "Cxxon Nuclear Power Distribution Control for PWRs - Phase II." Suppl 2 & Addendem 1 to Suppl 2 Encl withheld (ref 100FR2 790) OWSLEY, 0 F Exxon Nuclear Co., Inc. (subs of Exxon Corp.) OFO 087 92 92/10/21 THOMAS. CO. Standardization & Special Projects Branch 1p 15829 317
- 8210270164 Forwards nonproprietary & proprietary "Generic Mechanical Design for Exxon Nuclear Jet Pump BHR Reload Fuel: "per NRC 820822 request Proprietary rept withheld (ref 100FR2 790) CHANDLER: J C Exxon Nuclear Co . Inc (subs of Exxon Corp.) JCC 094 82 82/09/29 THOMAS, C O Standardization & Special Projects Branch ip 15824 236
- --8210270(49 XN-NF-81-21(NP)(A)
 Nonproprietary "Generic Mechanical Design for Exxon Nuclear
 Jet Pump BHR Reload Fuel "
 # Exxon Nuclear Co. Inc (subs of Exxon Corp.) 82/09/22
 113pp 15824 238
- 9210270214 Forwards proprietary revision to "RODEX2 Fuel Rod Thermæ]—
 Mechanical Response Evaluation Model " Revision modifies
 RODEX2 code based on benchmarking of model to enlarge date
 base Rept withheld fref 10CFR2.7701

 CMSLEV.0 F Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)
 QFO 088 82 62/10/22 THOMAS.C O Standardization & Special
 Projects Branch 1p 15822 347
- 8210280433 Forwards review of Westinghouse safety parameter display sys, in response to 820506 request Verification & validation program generally acceptable Outstanding concerns must be resolved before review completion CRUTCHFIELD, D Operating Reactors Dranch 5 LS05-82-10-005 82/10/05 RAHE, E P Westinghouse Electric Corp 7pp 15860 056.
- 8210290118 Forwards for info draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission decision due 821030 W/o enci LAINAS G C Assistant Director for Operating Reactors 82/09/28 ROCHINO.L Babcock & Wilcox Operating Plants Owners Group ROCHINO.L Operating Plants Owners Group 15866 358
- 8210290141 Forwards GA Topical Rept, Amend 7
 FISHER, C R GA Technologies, Inc / General Atomic Co LRB 67. CRF; 82/10/19 HAASS, W P. Guality Assurance Branch ip 13854 310.
- --8210290144 GA-A13010A A07 Amend 7 to GA program * GA Technologies, Inc /General Atomic Co. GA-LTR-11 62/10/31 71pp 15854 311.

ī.

8210270288 Confirms 821020 telcon re new fatigue curve (Figure 2-11b) added to NRDE-24011-P-A-4 Curve illustrates atreas/cycle relationships used in fatigue evaluations & serves as basis for failure analysis of approved PBxBR fuel design [PAxRM_EY, J S Ogneral Electric Co MFN-154-B2 B SERGGREN, J S NRC - No Detailed Affiliation Given 82/10/25

10270453 Forwards for info draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission paper due PAGENTH NO ONCE
LAUMAS G C Assistant Director for Operating Reactors 82/09/28
PAGENIN K C-E Operating Plants Owners Group 2pp 15863 185

1029045B Forwards, for info, draft rept & apps on pressurized thermol short Completed rept will form basis of Commission paper for 524030 H/a enci

STE HOT NUCLEAR WASTE MANAGEMENT

iO120131 Summary of 820903 meeting w/DDE.BNL & DuPont re environ issetscent & draft finding of no significant impact re use if borosilicate glass in defense waste processing facility istandence list ent!

*ELLH J High Level Waste Licensing Management Branch 82/09/if High Level Waste Licensing Management 3pp 15692 154

|0120133 Requests copies of papers presented at Bozeman Montain Resing of Rocky Mountain Section of Geological Boc of Larrica, dealing w/geologic aspects of Basalt Waste Isolation 'roject SIGHT,R J High Level Waste Technical Development Branch SIZOB/31 SOUIRES,D Energy, Dept of in 18692 169

,0120147 Responds to 820830 ltr expressing concern re finel version Oligical Heapones to GAUSSO it expressing toncern re final versions for Land Disposal of ladvaste. "Licensing Requirements for Land Disposal of ladvaste "De minimis issue for managing low level radwaste will be addressed within next few yrs warsh. JB Division of Waste Management 82/09/21 HARRIS, B J Halth Physics Society 2pp 19692 177

[0120173 Forwards minutes of B20729 briefing on iOCFR40 W/o encl [ELL, H J High Level Waste Technical Development Branch 62/08/31 [ORLINGER, L Louisiana, State of LIEBOLD, H G Affiliation Internal CAMIL, P C Environmental Protection Agency 4pp 5692 205

.0120179 Notification of 820709 meeting w/Basa)t Waste Isolation regect coordinators in Silver Spring MD for site issue malysis treatment & systematic review & comparison of site 111175

REGNIA J High Level Waste Technical Development Branch 92/09/31 BELL,M J. BOYLE,R, COOK,R High Level Waste Licensing fanagement Branch 2pp 15692 209

10120322 Forwards draft DDE/NWTS-33(3). "NWTS Program Criteria for

| IO120324 Forwards draft DOE/NWTS-33(3), "NWTS Program Criteria for the Grologic Disposal of Nuclear Wastes Repository Serforance & Development Criteria "Comments on QA stds requested by 821006 W/o and IONER R High Level Waste Licensing Management Branch 100. IONER R HIGH LANGE R 62/09/21

101203R5 Forwards "Corrosion of Cast Iron & Low Carbon Steel Nuclear Isla Containers in Basalt Repository " Draft rept will be saved as NUREO RIGHTR J High Level Waste Technical Development Branch .fived 4% nongo RighTiR J High Level Waste Technical Devel 12/09/20 SQUIRES:D Energy, Dept of 1p

1210120327 "Corrosion of Cast Iron & Low Carbon Steel Nuclear Waste Containers in Basalt Repository," draft rept RALL, E.E. NRC - No Detailed Affiliation Given 82/08/26 44pp 15590 354

--8210120353 "Draft Technical Position on Radionuclide Spec & Solubility Determinations "
BROOKS, D. CORRADO, J. NRC - No Detailed Affiliation Given 82/08/30 28pp 13690 302

6210120355 Trip rept of 820507 internal dosimetry symposium in Harrisburg.PA
FEHRINGER.D J High Level Waste Licensing Management Granch
82/09/10 KNAPP.H R High Level Waste Licensing Management Granch

8210120356 Trip rept of 820830-0703 visit to Denver, CQ & Los Alamos, NM to attend fourth annual DOE iow level waste mgt program participants info meeting HAMKINS, EF, STARMER, R J Low Level Waste Licensing Branch 82/09/21 6CARANO, R A Low Level Waste Licensing Branch 4pp 15690 347

8210120358 Proposes lead responsibilities for Basalt Haste Isolation Project
WRIGHT:R J High Level Haste Technical Development Branch
B2709/22 High Level Waste Technical Development Branch

8210120359 Requests list of documents referenced in ECR for Basult Maste Isolation Project MRIGHT.R J thigh Level Waste Technical Development Branch 82/09/21 BDYLE.R . COOK.R . OREEVES.J Bivision of Waste Management 3pp 13690 293

89:10:20375 Requests review & comments on enci DDE/NWT6-33(3), "NWT6 Program Criteria for Hined Geologic Disposal of Nuclear Wastes Repository Performance & Development Criteria " W/o encl

BELL, M J High Level Waste Licensing Management Branch B:
ARGENAULT, F Division of Health, Siting & Environment 1p 82/09/21

S2:01:20377 Forwards preliminary geological hydrological & geotechnical evaluation of Coke Oven Site, Montrose County, CO Heeting planned for parity Sept to discuse comments JACODIL, W. Colorado. State of B2/08/20 SHITH, R.D. Low Level Waste Litensing Branch ip 15697 330

--821012038& Preiminary geological, hydrological & geotechnical evaluation of Coke Site. Mentrase County. Ca ROSAGCO, PV , HEATH, R A Fox Consulting Engineers & Geologists 82/07/31 147pp 15689 331

821012044B Forwards draft DOE/NWTS-33(3), "NWTS Program Criteria for AIDIZUMEN FORWARDS GRAFT DUB/KNIS-CICID. "NATH PROGRAM Criteria Mined Geologic Disposal of Nuclear Hastes Repository Performance & Development Criteria " Radiciogical safety & Bosimetry comments requested by S21006 M/o encl BOYLE.R R Migh Level Waste Licensing Management Branch 62/KNAPP.M R High Level Waste Licensing Management Branch 1p. 18624-187 62/09/21

8210120554 Comments on Jul 1982 monthly rept for Edgemont cleanup action program No changes to costs or final delivery of contracted products authorized FLORY, G A Uranium Recovery Licensing Branch FIN D-2217 82/09/14 HOGMAN, N A Battelie Hamoriai Institute, Pacific Northwest Laboratory 2pp 15684 216

82:0120574 Forwards comments on draft remedial action concept paper for U mili tailings site.

SCARAND,R A Low Level Haste Licensing Branch
CAMPBELL,R H Energy, Dept of 3pp 15695 2 82/09/20. 15695 229

8210120648 Trip rept of \$20830-31 visit to Edgement.SD to evaluate progress on remedial action program
FLORY, C.A. Uranium Recovery Licensing Branch FIN 3-2217
62/09/15 BRITH, R.D. Uranium Recovery Licensing Branch Rpg
13684:235

8210220037 Forwards NRC comments on final draft remedial action concept paper for Durango. CO inactive U mil) tailings site Comments can be easily resolved. paper for porangolog analysis of many can be easily resolved.

SCARANGER A Uranium Recovery Licensing Branch
CAMPBELLER H Energy, Dept of Jpp 15786 278 82/09/09

8210250025 UMTRA-DOE/ALD-34 DRF Draft "Rumedial Action Concept Paper for U Mill Tailings Site at Shiprock: NM "

* Navajo Nation CAMPBELL: R. H Energy, Dept of 20482
82/08/31 27pp 15778 316

8210260086 Forwards "Certificate of Hater Analysis Hay 1982" CAIN. J Cotter Corp 20591 82/05/09 HAZLE, A J Cotor of. 2pp. 15814 153. Colorado, State --8210260091 "Certificate of Water Analysis Hay 1982 " Five oversize tistings encl Aperture cards available in PDR MCDEMELL. J. CURREY. H. HERRERA. D. Cotter Corp. 05-82 82/07/12 5pp. 1584 155

CEORTI IC EXPORT AND IMPORT LICENSES

- 8210040392 Ltr of assurance re export of 330 32 kg U-235.contained in 11,590 kg U.to Japan SHIRAKANA.T Japan 82/09/02 GRIFFIN.J A Energy, Dept of 1p 15597 211
- 8210040385 Ltr of assurance re export of 268 kg U-235, contained in 10,936 kg V.to Japan SHIRAKANA.T Japan 82/09/02 GRIFFIN.J A Energy Dept of 1p 15597 212
- 8210040387 Ltr of assurance re export of 340 28 kg U-235, contained in 10.470 kg U. to Japan SHJRAKAMA.T Japan 82/07/02 GRIFFIN.J A Energy, Dept of ip 15597 213
- 8210040403 Executive Branch position re Mitsubishi Intl Corp application to export 575 kg U-235 contained in 29.698 kg U, to Japan Ltr of assurance encl License should be granted DEVINELJ B State. Dept of Bureau of Oceans & Internati Environ Scientific Affairs 82/09/10 SNEA.J R Office of International Programs. Director 2pp 15597 230
- ~-8210030467 Advises of plans for series of spent fuel shipments from Chall River to DOE Savannah River Plant DANESE,F L. Nuclear Assurance Corp FLD/82/B4/ET6 82/07/02 GDDY, A. Region 1. Office of Director 1p 15626 232
- --8210050471 Corrects 820702 prenotification of planned series of irradiated reactor fuel shipments from Chalk River to Savannah River Plant Port of entry is Derby Line, VI DANESE, F. L. Nuclear Assurance Corp. FLD/82/86/ETS 82/07/07 GDDY, A. Region 1, Office of Director 1p 15624 233
- 8210060007 Amend 5 to GE export license, changing licensee & consignee addresses & adding 3 addi consignees PETERSON, M R Assistant Director for Export/Import & International Safeguards ODM-073-82 82/08/31 jp 15636-267
- 8210060471 Ltr of assurance re-application to export 319 20 kg U-235. contained in 11.200 kg U to Japan SHIRAKAMA.T Japan 82/09/02 @RIFFIN.J A Energy. Dept of lp 15636 219
- 8210070411 Add) response to FOIA request for documents re IAEA nuclear math safeguards program Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/09/10 OREENBERO.E V Tuttle & Taylor 3pp 18647

Urity concerns exist

D- -1

- -8210070421 Notifies that no physical security concerns erist re eigert of low enriched U to Japan under export license application KENM-1896 SHERR.TS Material Control & Accountability Development Brunch 81/12/17 DEVINE.JS Assistant Director for Export/Import & International Safeguards ip 15647-007
- --8210070436 Notifies that no physical protection concerns exist re applications to export low enriched U to Japan under Licenses X6NM-1923, 1925, 1928 & 1896 SHERR.TS Haterial Transfer Safeguards Licensing Branch 82/02/25 PETERSON.MR Assistant Director for Export/Import & International Safeguards Ip 15647 016
- --B210070434 Notifies that no physical protection concerns exist re export of highly enriched U to Japan Update on status of negotiations requested negotiations requested SHERR.T B Haterial Transfer Safeguards Licensing Branch 82/02/09 DEVINE,J B Assistant Director for Export/Import & International Safeguards 1p 15647 015
- --8210070436 Notifies that no physical protection concerns exist re applications to export low enriched U to Japan under Licenses XSNM-1923, 1925, 1928 & 1896 SHERR.TS Material Transfer Safeguards Licensing Granch 82/02/25 PETERSON.M R Assistant Director for Export/Import & International Safeguards 1p 15647 016
- --8210070471 Forwards draft Commission paper re application for license to export highly enriched U to Franco Comments & license conditions specified in Encl 2 should be included in BURNETTR F Division of Safeguards 82/05/25 GHEA.J.R Office of International Programs, Director 3pp 15647-224
- --8210070436 Notifies that no physical protection concerns exist re applications to export low enriched U to Japan under Licenses XSNK-1923,1925,1928 & 1896 GHERR: T S Material Transfer Safeguards Licensing Branch 82/02/25 PETERSON: M R Assistant Director for Espart/Import & International Safeguards ip 15647 016
- --B210070447 Notifies that no physical protection concerns exist re applications to export low enriched U to Japan Info requested re status of facility attachment to Fukushima I. Unit 4 SHEAR,TS Material Transfer Safeguards Licensing Branch S2/03/11 PETERSON,MR Assistant Director for Export/laport & International Safeguards ip 15447-038
- ---9210070484 Notifies that no physical protection concerns found re application for license to export single reload of low application to literature to the second of t
- 8210070493 License for Transmuclear, Inc. to import 17,000 kg U, enriched to 1 04 U-235, as U herafluoride, from France ZIMMERNALJ V Assistant Director for Export/Import & International Safeguards 82/09/24 ip 15637 336
- 8210070439 License for Exxon Nuclear Co.Inc to import 93,020 kg U, enriched to 4 3X U-235 contained in fuel rods or assemblies. From Taiwan
 ZIMMERMAN.J V Assistant Director for Export/Import & International
 Safeguards 82/09/26 ip 15637 344
- 8210070443 License for Phibro-Salamon, Inc to import 500,000 kg U, including normal U & U enriched to 5 0% U-235, in any form except U contained in irradiation fuels, from any country ZIMMERMAN, U V Assistant Director for Export/Import & International Safeguards 82/09/26 ip 15637 347
- 8210070452 Application for license to import 21,702 kg U.containing 418 49 kg U-235 & 21,346 kg U.containing 544 232 kg U-235, from West Germany HANNETT,B A Transnuclear, Inc TNF 418. 82/09/28 HOORE,N Office of International Programs, Director 2pp 15637 356
- 8210080003 Forwards application for license to export 500,000 Ci tritium gas to United Kingdom SHAMIA Ediaw International Co. 82/09/10 HEMBY.E Assistant Director for Export/Import & International Safeguards ip 15668 353.
- --8210080005 Application for license to export 500,000 Ci tritium gas to United Kingdom 5HAH, A 6 15668 354 Edlow International Co BRD-1(82) 82/09/10

NONDOCKETED ITEMS

- E210090033 Forwards application for license to export 400 ig castierite, enriched to 0 4% to United Kingdom vax RIPER.0 0 AMAX. Inc 82/09/09 HEMBY.E NRC No Detailed Afeiliation Given ip 15669 001
 - -8210080035 Application for license to export 400 kg cassiterite, enriched to 0 4% to United Kingdom DISTLER. IF AMAX. Inc SN-EXP 82/09/10 1p 15669 002
- 210080037 Forwards application for license to export 86 861 mC; Cf-252 as cermst wire to France HANKEITLE A Transnuclear, Inc 82/09/08 MODRE,N Office of International Programs, Director 1p 15667 003
- -8210080040 Application for license to export 85 861 mCi Cf-252 as census wire to France
 HARRETT, B A Transnuclear, Inc (TNP 414) 82/09/08 ip
 13689 004
- --B210080042 Advises that CEA will fabricate Cf-252 & send entire source to institut Oustave Roussy de Villejuif, in response to questions on 820908 application for license to export 88.861 mCi Cf-252 as cermet wire to France HAMETT, BA Transnoclear, Inc. 82/07/15 HEMBY, E. Director's Office Office of Inspection and Enforcement 2pp. 19649 005
- 3210080065 Corrected license for Edlaw Intl Co to import 30,000 tg U.enriched to 3 5% U-235.from France IJHSERMAN.J V Assistant Director for Export/Import & International Safeguards 82/09/15 1p 15663 330
- 821008007(Application for license to import 5,000,000 kg U.containing 250,000 kg U-235 SMANA Ediow International Co 82/09/17 Assistant Director for Expert/Import & International Baseguards 1p 15669 363
- 8210080108 Application for license to import 21,000 kg U.containing 210 bg U-235,from the Netherlands
 HAURETT,D A Transnuclear, Inc. 82/09/20 MODRRE,N Office of International Programs. Director 2pp 15649-360
- 8210083113 Application to amend export license, submitting addl info reinteractiate consignees WIEDDA B D General Electric Co BDW-083-82 82/09/07 WRIGHT, B L NRC - No Detailed Affiliation Olven 1p 15669 362
- 8210080(i) Executive Branch position re Carpanter Technology Corpapplication to export Zircalog tubing to Norway License should be granted DEVINE.J B State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs 82/09/17 SHEA.J R Office of International Prograss. Director 2pp 13663 283
- 8210080126 Executive Branch position re KMS Fusion, Inc application to export 300 Ci trition in hollow glass pellets to United Xington License should be granted DEVINE, J.B. Stats, Dept of, Bureau of Oceans & Internat! Environ & Scientific Affairs, 82/09/10, SHEA, J.R. Office of International Programs, Director 1p 15463 315
- 8210080130 Application for license to import 27,280 kg U.containing 872 % by U-235, from West Germany HWMETTA A Transnuclear, Inc 82/09/13 MODRE, N Office of International Programs. Director 3pp 15663,243
- 82:0080133 Application for license to import 27:000 kg U.containing 32 kg U-235, from the Netherlands MANETT.B A Transnuclear, Inc 82/07/20. MOORE.N Office of International Programs. Director 2pp. 13663 246
- 8210380135 Application to amend export license submitting addl info reinterediate consignees
 NLISON, B. D. General Electric Co. BDW-083-82 82/09/07
 NRIONT, B.L. NRC No Detailed Affiliation Given. Ip 15663:248
- 8210090138 License for Mitsui & Co (USA), Inc to export 33,000 lb licealoy-4 tube shells to Japan IIMERHAN, J V Assistant Director for Export/Import & International Staguards 136261, 82/07/20, lp. 13663,249.
- E2100B0143 Licanse for Westinghouse to export 15 kg depleted U oxide in fire of sintered pellets to Canada IMMERNAD V. Assistant Director for Export/Import & International Safeguards ILB-194 82/09/22 1p 15663.250

- 82100B0149 License for Hestinghouse to export 1.808 microgram Cf-252, contained in eight cermat scaled sources & 480 mg Np-237, contained in 24 radiation surveillance capsules to South Korea
 ZIMKERMAN, J V Assistant Director for Export/Import & International Safeguards 11.6-167 82/09/22 2pp 15663 251
- 8210080153 License for Wastinghouse to export three ionization Chambers & three gamma chambers to West Germany ZIMMERNAN.J V Assistant Director for Export/Import & International Safeguards ZE 10478 82/09/22 ip 15663 253
- 8210080137 License for Exxon Nuclear Co.Inc to export fuel rod hardware & cage assemblies to France ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 82/09/22 ip 15663 254
- 8210080162 Amend I to Transnuclear, Inc export license, increasing quantity of U-235 from 91 434 kg.contained in 98 kg U, to 94 513 kg.contained in 101 3 kg U
 ZIMMERAN.J V Assistant Director for Export/Import & International Bafeguards 81-269/01 82/09/21 1p 13663 270
- 82100B0319 Forwards application for license to export four Zircaloy-4 alloy fuel channels to Republic of China WOZNIAK.D R Carpenter Technology Corp 2-909-028 B2/09/09 HEMBY.E Assistant Director for Export/Import & International Bafeguards ip 15643 358
- --8210080320 Application for license to export four Zircalog-4 allog fuel channels to Republic of China * Carpenter Technology Corp 82/09/09 2pp 15663 359
- 8210080321 Forwards application to export 15 kg depleted (9 oxide to Canada HERRCHM H Westinghouse Electric Corp. ILS-174 B2/07/15 ZIMMERMAN, J V Assistant Director for Export/Import & International Sefequency 10 15663 361
- --B2100B0323 Application for license to export 15 kg depleted U axide, in form of sintered pellets, to Canada
 HERBOLM H Westinghouse Electric Corp B2/09/15 lp 15663 362
- B210080324 Application for license to export 12 guide thimble tubes to Japan * C. Itoh & Co (America), Inc. M-004 B2/09/16 in 15663 288
- 8210080327 Forwards application for license to export 9,500 kg individual rare earth compounds or mixtures & concentrates to various countries BARNUMLE C Molycorp. Inc 82/09/16 HEMBY.E Assistant Director for Export/Import & International Safeguards 2pp 13663 289
- --8210080331 Application for license to export 9.500 kg individual rare earth computed so mixtures & concentrates to various countries Elements consist primarily of cerium, lanthonum, neodynium & prassodynium, WARHOL. W N Holycorp, Inc 82/09/16 1p 15663 291
- 8210080334 License for Luigi Serra Inc to export 18,400 springs to Italy
 ZIMMERHAN, J V Assistant Director for Export/Import & International Bafeguards 828-536 82/09/22 ip 13663 329
- 8210080339 Application for license to export 4,050 ft zirconium Grade II seemless tubing to Canada TUPPER.K F. Cabot Gorp 1-6730101-28043 82/09/15 ip 15863;328
- 8210080343 License for Edlow Intl Co to export 0 01 microq 0 17 microgram Pu-239 to Philippines ZIMMERMAN.J V Assistant Director for Export/Import & Bafeguards PMC-1 82/09/20 2pp 15683 321
- 8210080345 Advises of issuance of license to Wastinghouse ke depleted U to Canada w/o 15-day waiting period since matl to be shipped on 820924

 ZIMMERMAN, J V Assistant Director for Export/Import & Safeyuards 82/09/22 Assistant Director for Export International Safeguards. 1p 15663 320
- 8210080349 Requests Executive Branch position re Intl Co application for license to expert 500,000 Ci bulk tritium gas to United Kingdom ZIMMERMAN, J. V Assistant Director for Export/Import & Bafeguards 82/0722 STOIBER, C R. State, Dept of Da & Internati Environ & Scientific Affairs 1p 15663

- 8210120117 License for KMS Fusion, Inc to export 300 Ci tritium: contained in microshell hollow glass pellets, to United Kingdom ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards KMSF-882-RO 82/09/22 Ip 15689 157
- 8210120503 Application for Elecase to Import 26 kg low enriched U digite pellets from Japan CROSBLE.K L TRT Corp 82/10/01 MODRE,N NRC - No Detailed Affiliation Given ip 85672 075
- 8210120511 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
 IRMERNAN, J V Assistant Director for Export/Import t International Safeguards 82/09/30 GRIFFIN.J A Energy, Dept of ip
- 8210120519 License for Transnuclear. Inc. to import 31,000 kg U.enriched to i 10% U-235 as U hazafluoride. from France ZIMMERMAN. J V Assistant Director for Esport/Import & International Safeguards 82/09/24 ip 15672-095
- S210130049 License for Transnuctear. Inc to export 1 464 kg U-235, contained in 3 223 kg U & 1 264 kg U-235, contained in 6 329 kg U to Japan ZimmermANNS R Assistant Director for Export/import & International Safeguards (NUM 405)82-097 82/09/28 2pp 15694 361
- 9210130055 License for Pechiney Ugine Kuhlmann Development, Inc to export 6 547 kg U-225 tontained in 7 OIB kg U. to Greece ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 7/2/82 92/09/24 2pp 15674 275
- 8210130059 License for Mitsu; & Co (USA). Inc to export 237 lb Zircaloy-2 barrier tube shells to Japan ZIMMERMAN.J V Assistant Director for Export/Emport & International Safeguards 136249 82/09/26 2pp 15694 358
- 8210130062 License for Isotope Products Labs to export 0 0125 mg Cm-244 to Gatar ZIMHERMAN.J V Assistant Director for Export/Import & International Safeguards W/O 9888 82/09/24 ip 15694 357
- 8210130066 License for Carpenter Technology Corp to export 24 piecer of Zircaloy tubing to Norway ZimmERMAN.J V Assistant Director for Export/import & International Safeguards CARTECH-SPD 150 82/09/24 1p 15696 267
- 9210130070 Amend 6 to GE export license, extending expiration date to BB0101.changing intermediate consignees & increasing quantity of matt for export to 8,055 kg U-235.contained in i26.539 kg U, to Italy ZIMMERMANLJ V Assistant Director for Export/Import & International Safeguards BDH-074-82 82/09/24 lp 15696 263
- 6210130072 Application for license to export equivalent of 5 kg deuterium to Malaysia * Sigma Chemical Co D-97 82/09/23 lp 15696.252
 - oplication for license to export 2 mg Cf-252, contained in orce, Model GEN-CF123, doubly encapsulated, to

- 82:0220517 Application for license to export 7 54 kg thorsumcontained in 10 kg Thorium fluoride in granular form, to Lichtenstein (Suitzerland) COLTON.E Cerac, Inc. 82/09/24 lp 15786-084
- 8210260083 License for Instrumentation Research Technology Corp to import 26 kg U.enriched to 4% U-235, as U dxide pellets from Japan ZIMMERHAN, J V Office of International Programs, Director 82/10/01 ip 15814 324
- 8210260523 Notifies that Westinghouse 821007 application to export cable assemblies to Belgium has been approved w/o 15-day waiting period Equipment ready for immediate shipment ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 82/10/14 Assistant Director for Export/Import & International Safeguards 1p 15830 178
- 8210260541 Not; fies that Westinghouse 821107 application to export one compensated conjustion chamber to Belgium has been approved w/o normal i5-day waiting period Equipment ready for immediate shipment
 ZIMMERHAN, J V Assistant Director for Export/Import & International Safeguards 82/10/14 Assistant Director for Export/Import & International Safeguards 82/10/14 Assistant Director for Export/Import & International Safeguards 1p 15830 355
- 8210260570 Application to amend export license extending expiration date to B51231

 MJLSON,B D General Electric Co IDN-089-82 82/10/05 IEMNY,F O Office of International Programs, Director ip 15814 357
- 8210260573 License for Sigma Chemical Co to export 5 0 kg deuterium oside to Malaysia ZIMMEMAN.J V Assistant Director for Export/Import & International Safeguards D-97 82/10/13 ip 13814 359
- 9210260574 Amend 1 to GE export license, extonding expiration date to 851231
 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BDH-089~82 82/10/14 1p 15814 360
- 9210260578 Amend 3 to GE Co. Inc export license.extending expiration date to 991231 & changing end use statement ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards KKL-9DW 81008 82/10/13 ip 15830 141
- 8210240580 Amend 1 to CE export license, extending expiration date to B41231
 ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards BDM-79201 82/10/13 1p 15830 142
- 8210270001 Amend 1 to Sandvik Bpecial Metals Corp export license, increasing quantity of matl from 12,800 to 20,000 lb & increasing value of export ZIMHERMAN.J V Assistant Director for Export/Import & International Safeguards 82/10/13 lp 15836 078
- 8210270003 Amend 1 to GA Co export license extending expiration date to 851101
 ZIMMERHAN, J V Assistant Director for Export/Import & International Safeguards IEL-4015 82/10/13 1p 15836-079
- 8210270005 Amend 6 to Transnuclear, Inc export license, extending expiration date to 880301
 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards RBU-33180-120/0 82/10/13 1p 15836 080
- 8210270007 Application for Amend 1 to export license, increasing value of equipment to be shipped to Japan TBUKUDA: T Mitsui & Co (U S A). Inc (Subs of Mitsui & Co .Ltd) 82/10/12 WRIGHT.D L Office of International Programs. Director 1p 15836.081
- 8210270011 Application for license to export 24,860 lb Zircaloy tres to Germany AERNI, B L Teledyne Wah Chang Albany 2326(JFM) 82/10/08 1p 15836 082
- 8210270014 Application for license to export compensated ionization chamber, Model WL23084, to Japan POCHAL W F Westinghouse Electric Corp ZE 60252 82/10/06 1
- B210270017 Application for license to export compensated ionization chamber, Hodel ML23774, to Belgium POCHAL, W F Gestinghouse Electric Corp ZE20561 82/10/07 ip 15836 084

- 8210270021 Application for license to export 12 6 kg U as metal to Canada SMAN, A Edlow International Co AECL-1(82) 82/10/13 ip 15836 085
- e21027007& Application for license to export 4.850 lb Zircaloy trex to Mest Germany AERNI.B L Teledyne Wah Chang Albany 2420 (JFM) 82/10/14 lp 15838-299
- 8210270094 Application to amend export litense, changing quantity to be apported to 50 g U-225, contained in 500 g U & 300 g Th-222 MARCHAL.J European Communities. Commission of 62/09/27 GRIFFIN.J A Energy, Dept of tp 15836 218
- 8210270099 License for Seperative Work Unit Corp to import 2.000,000 it natural V in any form & 300,000 kg V.enriched to 5% V-235 in any form from any country [PMERRANI.] V Office of International Programs, Director 62/10/04 ip 15836 219
- 8210270103 Advises that proposed import of 26 kg U. enriched to 4% U-235 constitutes no undue risk to public health, safety or entired. By Hester of International Programs, Director 22/10/6
- envison MCGRE.R M. Office of Intornational Programs, Director 82/10/04 Office of International Programs, Director 1p 15836-220
- 92/02/010B Advises that license to import 26 kg U dioxide pellets, enriched to 4%, from Japan issued w/o 15-day weiting period since matl urgently needed for testing IIMMERHAN.J V Assistant Director for Export/Import & International Safeguards 82/10/04 Assistant Director for Export/Import & International Safeguards ip 15832 340
- 8210270114 Advises that proposed import of 27.280 kg Userriched to 3.27 U-235.constitutes no undus risk to public health, safety or anylron MOQRE.R N Office of International Programs. Director 82/10/05 Office of International Programs. Director 15832 341
- 8210270122 Advises that license to import 27, 280 kg low enriched U in farm of U hexafluoride from West Germany issued prior to espiration of 30-day period stated in FR 2HMERHAN.J V Assistant Director for Export/Import & International Bafeguards 82/10/05 Assistant Director for Export/Import & International Bafeguards ip 15832 347
- 82(0270127 Advises that license to export 23B lb Zircaloy-2 barrier tubs shells to Japan issued w/o 15-day waiting period since tubing ready for immediate shipment & urgently required by customer
 IIPMEMANN.J V Assistant Director for Export/Import & International 24feguards 82/09/26 Assistant Director for Export/Import & international Safeguards Ip 15832 346
- 5210270147 Application for license to import 13,500 kg U.enriched to 0 83% U-235.from France
 HAMMETT.B A Transnuclear, Inc 62/09/30 MODRE.N Office of international Programs. Director 2pp 15834-342
- 8210270149 Forwards application for export license for minor nuclear ipart Ltr of assurance required IMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/10/05 GRIFFIN, J A Energy, Dept of 1p 15834-344
- --8210270152 Application to amend import license, increasing amount of U from 10 to 15 kg
 (MSEH.R # National Nuclear Corp. 82/09/29 WRIGHT, B L
 Assistant Director for Export/Import & International Safeguards
 19 15834,345.
- 8210270155 Forwards application for export license for minor nuclear export Ltr of assurance required W/o enci INMERHAN, J V Assistant Director for Export/Import & International Safeguards 82/10/06 QRIFFIN, J A Energy, Dept. of 19 13835 077
- 8210270158 Ltr of assurance re export of SNM to Switzerland FISCH. C Switzerland 82/09/28 GRIFFIN. J A Energy. Dept of 3pp 15834.346
- 8210270163 Application to amend export license. Increasing quantity to he laported from 12:1806 to 20:000 ib.
 MENIER.L. Bandvik Spacial Metals Corp. B2/10/04 HEMBY.E NRC No Ostabled Affiliation Given ip 15834 349
- 82:0270168 Requests exemption from 30-day FR notice requirement for import bicense Hatl must be exported immediately HMSETT.B A Transnuclear, Inc. TNF-415 82/09/23, MODRE, N Office of International Programs, Director. 1p 18834-350

- 8210270194 Application for license to export 5 kg deuterium bilde liquid over 2-yr priod to Halaysia 4 Sigma Chemical Co D-98 82/09/30 1p 15835 348
- 8210270201 Amend 3 to GA Co export license extending expiration date to 851001 & intreasing quantity of mat1 authorized for export to 50 g U-235, contained in 500 g U & 500 g fh-232, to West Oarmany
 ZIMMERMAN, J V Assistant Director for Export/import & International Safeguards [EL-954 82/10/06 ip 15936 033
- 92:0270233 License for Transnuclear. Inc. to export 86 861 mCi Cf-25d.as cerment wire-to France ZIMMERHAN, J V Assistant Director for Export/Import & International Safeguards (TMP-414) 92/10/05 ip 15836 072
- B21027023B Litense for Carpenter Technology Corp to export four Zircalog-4 aliqy fuel channels to Taxwan ZIMMERMAN,J V Assistant Director for Export/Import & International Bafeguards CARIECH 2-909-0 82/10/05 lp 15836 075
- B210270243 Informs that Amend 5 to License XSNM-1686 may be issued Nu matt changed circumstances since issuance of License XSNM-1840 HODRE, R N Assistant Director for Export/Import & International Safeguards B2/10/06 Assistant Director for Export/Import & International Safeguards 1p 15836 076
- 8210270281 Application for license to export 10 kg thurlum oxide powder to Italy COLTON.E Ceraci Inc 82/10/06 HEMBY, E NRC No Detailed Affiliation Olven tp 15836 304
- 8210270282 Amend t to Mitsul Air Intl.inc export license, increasing value of equipment for export to Japan Zimmerman, J V Assistant Director for Export/Import & International Safeguards 82/10/14 1p 15836 305
- 8210270283 Application to amend export license, extending expiration data to 841231 WILGON, D D General Electric Co BDU-088-82 82/10/05 1p 15835-306
- 8210270284 License for Wastinghouse to export one compensated ionization chamber.Model ML23774.to Belgium ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards ZE-20561 82/10/14 ip 15836-307
- 8210270285 License for Westinghouse to export one triax cable assembly, Model WL-24058 & one coax cable assembly, Model WL-24060 to Belgium ZimmenMAN.J V Assistant Director for Export/Import & International Safeguerds ZE-20547 82/10/14 ip 15836 308
- 8210270286 License for Natl Nuclear Corp to export 2 0 milligrams CF-252,contained in one newtron source, to United Kingdom ZIMMERNAN.J V Assistant Director for Export/Import & International Refeguards BNFL-0-578 82/10/14 tp 13836 300
- 8210270287 License for CERAC. Inc. to export 7 54 kg thoroum.contended in 10 kg thoroum fluoride to Switzerland ZIMHERMAN. J V. Assistant Director for Export/Import & International Safeguards TLX-6725 82/10/13 2pp 19836 301
- B210270290 Litense for Molycorp. Ir to Australia, Austria. Beigium, C Greece, Ireland, Italy, Japan, Lus Norway, Sweden, United Kingdom ZIKHERNAN, J V Assistant Q: Safeguards 82/10/08 ip
- B210270313 Requests Executive ... application for license to export small amounts of thorium contained in rare earth products W/o encl
 ZIMMERHAN, J V Assistant Director for Export/Import & International Safeguards 82/10/13 STDIBER. C R State, Dept of, Eureau of Oceans & Internatl, Environ & Scientific Affairs 2pp 15836 339
- B210270391 Application for license to export 4.850 lb Zirceloy trex to West Germany
 AERNI, B L Teledyne Hah Chang Albany. 2419 (TFM) B2/10/14 lp 15833 362
- B210270431 License for AMAX, Inc to export 180 kg natural U, contained in 35 metric tons tin concentrate & 180 kg natural thorium, to United Kingdom ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards SN-EXP 82/10/05 tp 15833 250

- 8210270446 License for Cabot Corp to export 4.050 ft :irconium Grade 1; seamless tubing of various outside diameters & lengths to Canada ZIMMERMAN, J V V Assistant Director for Export/Import & International 1-6930 82/10/05 1p 15833 280
- 8210270448 Forwards application for license to export 11,279 kg U.
 enriched to 3 95% U-235, to Japan
 HATTORI.H Mitsul & Co. (U.S. A.), Inc. (Subs. of Mitsul & Co., Ltd.)
 82/09/27 Assistant Director for Export/Import & International
 Sareguards ip 15832 361
- --8210270452 Application for license to export 11,279 kg U, enriched to 3 956 U-235 ko Japan HOHDBUT Mitsut & Co. Ltd) MSK-ZFI-R2-(8) 82/09/27 lp (5832 362
- 8210280030 Application for license to export 0 0000125 mg Cm-244 lsotope Products Laboratories 4/0 9975 82/09/20 JAMRISKA, D 15863 003
- ADIODRO032 Application for license to export 355 Zircaloy-4 guide Thimble tubes to Japan

 BANGERTER.D H Bandvik Special Metals Corp \$5M-2927 82/09/27

 1p 15862 362
- 6210280035 License for GA Co to export (1 kg U-235, contained in 55 4 kg Yide Book State St
- 8210280038 License for Transnuclear, Inc to import 27,280 kg U.enriched to 3 2/ U-235, from Hest Germany ZIMMERMAN, J V Assistant Director for Export/Import & International Bareguards 82/10/05 lp 15862 361
- 8210280040 License for C Itah & Ca. Ltd to export 12 guide thimble tubes Assistant Director for Export/Import & International ZIMMERMANL J V M-004 Satequards
- 6210280043 Application for license to export 2,490 Zircaloy-4 guide thimble tubes 405 Zircaloy-4 instrument tubes & 720 double thimble tubes to Japan End use statement encl BANGERTER, D H Sandvik Special Metals Corp SSM-2893-2906 88M-2893-2900
- 8210280052 Application for license to export 2,002 mC; Cf-252 as cornet wire to France HANNETT,D A Transnuclear, Inc (TNP 421) 82/10/04 2pp 15962 355
- 8210280056 Forwards applications for licenses to export 15 038 kg U, enriched to 93 3% U-235 to Denmark & 2,002 mCi CF-252,as cermet wire Application for U-235 only enci HAINETT.B A Transnuclear, Inc. 62/10/04 MDORE,N Office of International Programs. Director ip 15862 (20
 - Application for license to export 15 038 kg U.enriched to 5.to Denmark End use statement enc!
 1 Transnuclear, Inc. NUK-420 82/10/04 3pp

- 9210280062 Application to amend export license extending expiration date 3 yrs ears 3 yrs
 MDMRY.WR GA Technologies. Inc /General Atomic Co IEL-40:5
 62/09/30 ZIMMERMAN.J Assistant Director for Export/Import &
 International Safaguards 1p 15962 233
- 8210280064 Application to amend export license increasing quantity to 15 g U-235.contained in 330 g U MARCHAL.J European Communities, Commission of GRIFFIN.J A Energy, Dept of 1p 15862 234
- 8210280088 Application to emend export license, increasing quantity to 10 g U-235, contained in 220 g total U HARCHAL, J European Communities, Commission of GRIFFIN, J A Energy, Dapt of 1p 15842 235
- 8210280403 Application for license to export 5 kg deuterium axide to India nois Sigma Chemical Co D-100 82/10/12 6pp 15859 319
- 8210280409 Amend 1 to Westinghouse export license, increasing quantity of metl authorized for export to 10 g U-235, contained 220 g U, to Belgium V Assistant Director for Export/Import & International ILB-150 82/10/05 ip 15859 331 Safrauards
- 8210280414 Amend 5 to Transnuclear, Inc export license, increasing 210220414 Ameno o to franshuctear.inc export itsense.increasing quantity of matt authorited for export to 6.738 665 kg
 U-235.contained in fol.131 620 kg U.to Switzerland
 ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards ROU 331 80-120/ 82/10/12 p 15859 357
- 8210280418 Amend i to Westinghouse export license, increasing quantity of mati authorized for export to 10 g U-235, contained in 220 g U, to France V Assistant Director for Export/Import & International ILS-150 82/10/06 ip 19859 360 ZIHMERHAN, J V
- 8210280422 Amend I to Westinghouse export license increasing quantity of matl authorized for export to 15 g U-235 contained in 330 g U to United Kingdom Zimmerran, V Assistant Director for Export/Import & International

Safequards

- ZIMMERHANJ V Assistant Director for Export/Import & International Safeguards 16-150 82/10/06 ip 15860 013
- 8210280435 Ltr of assurance re application to export 1 464 kg U-235, contained in 3 223 kg U & 1 264 kg U-235, contained in CONTRAINED AND APPAN
 6 327 kg Unto Japan
 SMIRAKAMA,T Japan 82/09/16 GRIFFIN,J A Energy, Dept of Ip 15860 063
- 8210290367 Requests assistance in expediting issuence of export PICEWOOD REQUESTS assistance in expending issuance of expendic license Addi valves must be shipped to reactor site ARROT. OE Borg-Harner Corp CGA/82/484 82/10/13 HEMBY. C. Assistant Director for Export/Import & International Safeguards 15865 247
- --8210270372 Application for license to export carbon & stainless steel valves, various globes, gates & supporting drawings & data to ARNOT, G E Borg-Warner Corp A-55127 82/10/13 ip 15865 248

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS, These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AVE. (5)	ACCESSION	SUBJECT
	~~			~~~~~~~		AUTHOR	NUMBER	CATEGORY
larodt, m H	8210050192	50-287 G	ALLAN, J M	821022041 l	50-271 g	ATK INSON, S. A.	0310100110	
A.F. GDT. N H	8210210359	50-289 Q	WITEN'S S	8210290247	RECOD	ATWEED, C L	8210120463 8210120368	RES
ад∽рот. Н Н	8210260400	50-287 0	ALLEN, R E	8210270060*	50~537 G	AULUCK, R	8210270072	RES
AARON, J A	*\$410E101S9	50-296 B	ALLISON D P	8510080506*	FQIA	AULUCK, R	8210270072	50-377 A
ABEOTT, E C	B210050409*	FOIA	AMAKO, V	8210260409	50-322 H	AUST III. Q	8210150411+	50-397 A 50-295 P
ASELSON, H	0210180311	50-3\$2 A	AMES, X	8210270041*	50-285 P			30 273 1
ASELSON, H	8210290167	50-352 A	ANASTABIA, C M	8210090368	NUREG	A M, MITEUA	8210130308*	70-135
ASSTAUCE D L	8210010381	PR	ANDERSON, J. L.	8210150409	RES	AUTER IND. L	021010007t*	50-286 R
ACHERHALL H C	8210150597	40-8743	ANDERSON, L. L.	8210120068*	FQIA	AUTIO, II A	6510130518	90-29 G
#IMERHAN W C	8210210254	40-6659	ANDERSON.M T	8510130544#	59-306 Q	A H OITUA A H OITUA	8210130230 8210130519	50-27 6
PLAME, J B	8210040042#	50~445 Q	ANDERSON, P	8210040125	EA 514 -	AGILGIII A	0210130314	50-29 9
4 L.EXA14	8210150415	RES	AMPERSON, P	8210250120	50-266 Q 50-266 D	A H, DITUA	8510390109	50-29 9
ACCOCK, B R	8210130528	PR	ANDERSON, R L	8210210037	NUREQ	AUTID: IL A	8210260109	50-27 8
ACENEAN E Q	8210070016	50~404 A	ANDERSON, T M	8005070094	PT21	A H (DITUA	8210240165	50-27 8
AZENEAM E O	8210130046	50-369 H	ANDERSON, T M	E005070079*	PT21	AUTIO, H A	8210260428	50-29 S
PAZIGOTIA V				GDG3G7GG77#	rial	A H DITUA	8510580082	50-29 \$
aleieah.e o Aleneah.e o	8210180254 8210180267	50-349 F 50-329 A	ANDOGNINI.O C	9210130394	PR	AVERITT.D D	0210260284*	CONTRACT
AGENSAMAE O	8210180418	50-329 A 50-404 A	ANDRULIB, M H	8210260563	70-2949	AXELRAD. J	0210010170	50-325 Q
ACENSAME G	8210190110	50-404 K	ANO, W P	8210270221*	CONTRACT	AXELRAD, J	8210070336	50-461 Q
	0210220511		APPEL, R R	0210150170*	50-324 Q	AXELRAD. J	8210150267	50-271 9
ACENSAMIE O	0310220311	50-329 A	WALETY K	8510380035	40-8781	AXELHAD. J	0210170285	50-249 Q
ACENSAM.E O	8210280407	50-369 P	APPELIR R	8210280412	40-B72B	AXELRAD. J	551616655	
ACLER: R V	8510090518	20~584 O	APPLEGATE. T W	0209270271*	50-358 H	AXELRAD, J	G\$10150360	50-315 Q
ASLER H U	6210210378	50-287 O	ARAGON, J J	0210150571	NUREO	AYELRAD, J	0210150496	I &E
PEPHIL B L	8210270011	XPORTLIC	ARCHER, C D	8210270413*	50-387 x	AXELRAD, J	8210280073	ire
acpye, b l	8210270076	XPORTLIC	ARCHER.C D	B210270419*	CONTRACT	AXELRAD, J	8210280143	14E 50-312 P
AEANI. D L	B210270391	XPORTLIC	ARCHER, C D	B210270428#	70-1113	AXELRAD, J	55.0005004	-
A,APWAL,R	82062300204	50-245 P	ARCHITZELIR E	0210150235*	50-317 G	AXELRAD, J A	8510500551	50-272 0
A.EE. J R	8209290240#	FOIA	ARCHITZEL.R E	8210190714*	50-317 0	AXCLRAD, J A	0210040047	50-321 0
ace. J r	8210190766*	QA999	ARMSTRONO, K A	B20829008B	FOIA	AXELRAD, J A	821004004B	70-143
ACKEN H H	8210270187	71-30	ARNOT, O E	6210270367	XPORTLIC	AXELRAD, J A	8210170577 8210150473	50-344 Q 70-143
AMEARNENI	8201150005#	FOIA	ARNDT, G E	8210290372*	XPORTLIC	4 to 60 to 1 to 1		
AHEARNE, J	8210280406*	FOIA	ARNOLD, E M	0210150553	NUREQ	VXELEVD' 1 V	8510140535	20-507 0
AHEARNE, J	8210290393	1 OCFR	ARNOLD, K	6510570250*	CONTRACT	AXECEON: H	8310080321	-
A-EAPRIE J F	8210150659	COMMISSION	ARNOLD, M L	8210270370	40-8153	AXELEON H L	8210040185#	
A-ISENS. P	8210040190	50-309 0	ARNOLD, R C	8210060342	50-287 P	AXELSON, H L	0210040334* 0210080204*	
A-GENS, P	B210280227	50-309 G	ARNOLD, R C	8210130279	50-320 P			
A101FOFF, B	0210150206*	50-322 1	ARNOLD, R C	8210270204	50-289 P	VYECSON H F	821015Q495*	
TOTACFF. B	8210150204	50-322 1	ARBENAULT, F J	8210050039×	REQQD	AKELBON, W L		
AL-ACATOR A	8210150548	NUREG	ASHBAUGH, C E	8210290043*	50-142 F	AYER, J E		
ALBERT. J H	8210080281#	50-416 8	ABHDAUGH, C E	B210290051*	50-142 F	AYER, J E		
		-				DACHAND, D		
ALEERT, J H	6210220282*	50-416 8	ASHE, F	B105110396*	FOIA	BACHMANN, R O		
ALBERT, J K	0210290135*	50-416 S	ASHE, F	B107160386*	FOIA	BACHHANN.R G		
ALBERT, J H	8210290351*	50-416 8	ASHE, F	8108180604*	FOIA	BACHITANN, R G		
ALBERT, W.O.	8210060163*	50-508 Q	ASHE, F	8111180001*	50-33B 8	BACKLEY, B T		
ALERICHT. F H	8210010137*	50-324 Q	ASHE, F	8111270314×	50-295 s	BACKUS, R A		
ALCEN, II H	8210150282	50-277 P	AEHE, F	8510050053*	50-278 8	BACKUS, R A		
HTGERN W	8210220194*	50-277 R	ASKE, F	8210070429	50-275 8	BACKUS, R A		
ALCERSON, C E	82(0010111#	50-400 Q	ASHE, F	8210070432	HISC	BACKUS, R A		
ALCERSON, C.E.	8210220406#	50-438 Q	ABHE, F	8210070474	50-278 8	BACON, J L		
ALDERSON, C E	8210220432*	50-438 Q	ashe, f	8210070476	HISC	BAER. R L		
ALDERSON, C. E.	8210220446*	50-438 Q	ASHE. F	8210080021	GEN TEC 18	DAER, R L		
ALEXANDER, R. E.	8210050020*	RECOD	ASHE, F	8210080059	MISC	BAER, R L		
ALLAN, J H	8210170580	50-244 G	ASHE, F 8	8210120372	MISC	BAER, R L		
ALLAN J H	8210210139	50-309 Q	ATEFI.B	8210040355*	50-537 A	DAER, R L		
WITES A H	8210220182	50-219 Q	ATEF1.B	8210040357*	FOIA	BAGBY, L. A		

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUIHÜR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGO»,
BAGBY, L A GAILEY, F C BAIR G G BAIR, G G GAISDEN, L	0210080232* 0210050191* 0210250093* 0210250175* 0210210554	71-9167 94999 50-344 S 50-344 B CONTRACT	BASSIN, N BASSIN, N BASSIN, N BASSIN, N BASSIN, N	8210180344* 8210180347* 8210180349* 8210180351* 8210180352*	FOIA FOIA FOIA FOIA FOIA	BEAMER, W H	8210180257+ 8210180260+ 8210180262+ 8210180266+ 8210180424+	FOIA FOIA FOIA FOIA 70-278
CA19DEN.L Bamer.c E Damer.c E Damer.c E Damer.c E	8210210576 8210320516 8210250006 8210250034 8210260017	CONTRACT 40-8481 40-8481 40-8481 40-8481	BASSIN.N BASSIN.N BASSIN.N BASSO.L F DASSO.L F	8210180422* 8210180425* 8210180429* 8210250095* 8210250160*	F01A F01A F01A 50-318 S 50-317 S	BEAMER, W H BEAMER, W H BEARDEN, R G BEARDEN, R G BECHHOEFER, C	821018042/* 821018043!* 8210080057* 8210080064* 8210060229	F01A F01A F01A 50-317 P 50-329 C
EAZER.C E BAKER.C E CAKER.C E BALL.S J BALLARD.R L	8210260022 8210270209 8210270435 8210150564 8111240071*	40-8681 40-8681 40-8681 NUREG 50-266 P	BASTIAN.B E DATES.A BATES.A DATES.A BATES.A	8210070358* 8210010045* 8210010076* 8210010172* 8210040368*	50-438 A Foia Foia Foia Foia	BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C	8210130304 8210130421 8210180172 8210210270 8210220322	50-329 ¢ 50-329 ¢ 50-496 ¢ 50-329 ¢
BALLARD R L BANGART.R BANGERTER.D H BANGERTER.D H BANGS N R	8202120129* 7912280014* 8210280032 8210280043 8210120124	50-266 P 50-324 P XPORTLIC XPORTLIC RES	BATES,A BATES,A BATES,A BATES,J BAUER,E O	9210040371 # 9210040381 # 8210040383 # 8210150067 # 8210200063 *	FOIA FOIA FOIA 70-1113 50-277 P	BECK, G P BECKER, R A BECKHAM, J T BECKHAM, J T BECKHAM, J T	8210130476 8210040454 8210010022* 8210040231 8210040275	50~151 S 50-537 A 50-321 Q 50-344 P 50-346 P
Baing, W W Barber G Barham, C D Barnes, C Barnes, I	8210120657 8210150285 8210130550 * 8208290097 8210120319 *	RES 50-269 G PR 50-148 H GA999	BAUER.E G BAUER.T L BAUM.S L BAUM.S L BAUNACK.W	8210220007* 8210250174 8210250245 8210250245 8210270415	50~278 P 50~192 P 50~247 G 50~247 G 50~410 G	BECKHAM, J T BECKMAN, J T BEILMAN, T P BELANGER, J L BELANT, J L	8210120047 8210150327 8210040205* 8210050110* 8210040162*	50-366 P 50-321 P 50-315 S 50-305 G 50-305 S
BARNETT, JE BARNETT, JE BARNUM, E C BARON, JE BARON, JE	8210260558	GA999 70-1621 xportlic 50-322 T 50-322 T	BAUNACK, W H BAUSER, M A BAYTER, F BAXTER, T A GAXTER, T A	8210270173* 8210270259 8210070160 8210120262 8210120262	50-244 Q PR 50-443 A 50-483 Q 50-483 G	BELISLE, Q A BELISLE, O A BELL, J M BELL, J M BELL, J M	8210180052* 8210150256* 8210180176* 8210180290* 8210180295*	50-324 G 50-327 G FOIA FOIA FOIA
DARON, J S RARDII, J S DARP, K CARR, K BARR X P	8210150290 + 8210150290 * 8210150136 * 8210220341 * 8210010122 *	50-322 T 50-322 T 70-824 50-160 G 50-83 0	BAKTER, T A BAKTER, T A BAKTER, T A BAKTER, T A BAKTER, T A	8210200009 8210200009 8210200013* 8210200013* 6210210365	50-400 0 50-400 G 50-400 G 50-400 G 50-483 G	BELL.J M BELL.J M BELL.J M DELL.M J BELL.M J	8210180278* 8210160301* 8210180417* 8210120131 8210120173	FOIA FOIA FOIA WAGTE HOT PR
GARR, K P GARR, K P GARR K P GARR K P GARR, X P	82100:0127# 82100:0137* 8210150086* 8210150358* 8210220356*	70-1201 50-324 Q 50-348 Q 50-335 Q 50-280 Q	BACTER, TA BACTER, TA BACTER, TA BACTER, TA BACTER, TA	8210210365 8210250248 8210250248 8210250253* 8210250253*	50-483 G 50-483 G 50-483 G 50-483 G 50-483 G	BELL,M J BELL,N DELLAMY.R DELLAMY.R DELLMAN,T P	8210120375 8210050389 8210050537 8210070265 8210170757#	WASTE HOT 50-522 0 50-520 P 50-289 S 50-J15 S
DAPR,K P BARR,K P BARR,K P GARRETT,D J GAPRETT,L	82102204014 8210220442* 8210220485* 8205230020* 8006240851	50-259 G 70-1113 50-327 G 50-245 P 50-247 P	BAKTER,T A BAKTER,T A BAYLOR,V B BAYLOR,V B BAYLOR,V B	8210280360 8210280360 8210060425 8210180407 8210060198	50-202 P 30-289 G 50-289 G	BEMIB, PR BENDER, M BENDER, PC BENNECHE, PE BENNETT, AB	8210010436* 8210040374* 8210120132* 8210080237 8209270240*	50-369 0 50-320 5 50-400 0 50-62 P FOIA
GARRETT, L H BARRETT, L H BARRETT, L H BARRETT, L H BARRETT, L H	8009100100 8009100104 8210070063 8210070150 8210190012	50-247 P 50-247 P 50-320 R 50-320 R 50-320 R	DAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY	8210060263 8210150216 8210170681 8210170671 8210210421	50-302 P 50-302 P 50-302 P 50-302 P 50-302 P	BENSINOER,P B BENTON,J W BERGHOLZ,W E BERGHOLZ,W E	8210130379 8210210159# 8210210159# 8210030184 8210060185	68 50-382 0 50-382 0 50-537 0 50-537 0
BAPRETT,L H BARRETT,L H BARROWS,J BARRY,L W BARTH,C A	8210190052 8210190127 8210260202 82102605734 8210200062	50-320 P 50-320 R 50-309 H F01A 50-400 0	BAYNARD, P Y	8210220207 8210220375 8210240010* 8210240310* 8210240377*	50-302 P PR 50-302 F 50-302 Q 50-302 Q	BERGHOLZ, W E BERGHOLZ, W E BERGHOLZ, W E BERGHOLZ, W E DERLIN, K	8210060200 8210130343 8210130435 8210200057 8210150474	50 537 ¢ 50-537 0 50-537 0 70-143 50-528 0
BARTHIC A BARTINE, D E BARTLETT, J BARTOLINI, R P	8210270087 8210270006# 8210150135 8210180401# 77	50-255 G C DMMIS81DN 50-220 B C DNIRACT 50-206 P	BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY	8210260422 8210260436 8210260454 8210260477 8210270186	50-302 P 50-302 P 50-302 P 50-302 P 50-302 S	BERLIN, K BERLIN, K BERLIN, K BERLIN, K BERLIN, K	8210150499 8210150499 8210150512* 8210150512* 8210290297	50-528 0 50-528 0 50-528 0 50-528 0 50-528 0
	23 23 17 32 32	TOPREP TOPREP 50-361 P 50-206 P 50-363 A	P AYNARD P AYNED P C.JANYAB P C.JANYAB P C.JANYAB	8210270312 8210040213* 8210040317 8210050079 8210050083	50-302 8 50-286 F 90-333 Q 50-286 F 50-333 F	BERNABEI, L BERNABEI, L BERNABEI, L BERNABEI, L BERNAGET, S L	8210150449 8210150449 8210150457* 8210150457* 8210040159*	30-358
	14 15 14 14	50~361 P 50~206 P 50~206 P 50~361 P 50~361 P	P C ,3MYAB P C ,3MYAB P C ,3MYAB P C ,3MYAB	8210040181 8210120233 8210150031 8210170411 8210170713	50-286 P 50-247 P 50-286 P 50-333 Q 50-286 H	DERNHOFT, B L BETTENHAUSEN, L BETTENHAUSEN, L BETTENHAUSEN, L BETTENHAUSEN, L	8210190356* 8210070263* 8210070330* 8210210097* 8210210162*	50-303 S 50-273 Q 50-277 Q 50-354 Q 50-272 Q
)5 9 8 2 3	50-206 F 50-206 P 50-206 P 50-206 P 50-375 H	P (,3MYAB B (,3MYAB D (,3MYAB D ()3MYAB D ()3MYAB	8210190728 8210190738 8210200028 8210200039* 8210200074	50-284 P 50-284 F 50-333 P 50-333 P 50-333 P	BETTENHAUBEN, L BETTENHAUBEN, L BHATIA, P BIBB, H E BICKFORD, W E	8210270132* 8210270356* 8210120430 8210220303* 8210120072	50-322 Q 50-322 Q REB 50-335 Q NUREO
	15* 11* 8* 10* 11*	50-289 Q FOIA FOIA FOIA FOIA	BAYNE, J P BAYNE, J P BAYNE, J P BAZIN, J P BAZIN, J P	8210210459 8210210470* 8210280070 8210180329 8210270199	50-286 P 50-286 P 50-286 P CONTRACT CONTRACT	BICKFORD, W E BICKWIT, L BICKWIT, L BIDINOER, O H BIDINOER, O H	8210120102 8210120254 8210120314 8210040397# 8210220028*	NUREO 50-209 0 50-289 0 70-371 70-1257
	0+ '7* 0* 5* 7*	FOIA FOIA FOIA FOIA	BEAMER, W H BEAMER, W H BEAMER, W H BEAMER, W H	8210180215* 8210180217* 8210180222* 8210180234* 8210180251*	FOIA FOIA FOIA FOIA	BIDINOER, O H BIELAWSKI, A P BIELAWSKI, A P, BILLIO, P F BILLS, J M	6210270436* 6210030391 6210050391 6210010224* 6210060390*	70-1151 50-454 Q 50-454 Q TOPREP 50-317 S

										•
	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	<i>(</i>	AU THOR	ACCESSIUN NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
	E:).,;ELI, B L BIN,;ELI, B L BIECHOFF, C A BIECHOFF, C A EISCHOFF, C A	8210170473* 8210260411* 8210130417 8210130417 8210170171	50-295 50~528 50~528	5 5 6 6	BLOCH, P B BLOCH, P B BLOCH, P B BLOCH, P B BLODGETT, T H	8210210349 8210210476 8210220242 8210220336 8210040072	50-155 0 50-440 G 50-266 0 50-155 G 50-369 R	BOUCHEY, G D BOUCHEY, G D BOUCHEY, G D BOUCHEY, G D	8210030154 8210050348 8210060273 8210060317 8210060445	50-397 E 50-397 A 50-397 A 50-397 E 50-397 F
	518CHCFF.C A 518HOP.L L 618HOP.L L 618HOP.L L 618HOP.L L	8210270171 8210070132 8210070132 8210070136 6210070136	50-528 50-329 50-329 50-329 50-329	6 6 6 0	BLODGETT,T H BLODGETT,T H BLODGETT,T H BLODGETT,T H BLOUGH,A R	8210040334 8210150431 8210260114 8210260466 8210150302*	50-387 A 50-387 R 50-389 A 50-389 R 50-277 G	BOUCHEY, Q D BOUCHEY, Q D BOUCHEY, Q D BOUCHEY, Q D	E210070141 E210080075 E210120174 E210120177 8210130188	50-397 A 50-397 K 50-508 K 50-508 A 50-397 A
	616469.LL 316469.LL 316469.LL 816489.LL 816469.LL 816469.RH	8210200054 8210200054 8210200061 8210200061 8210260459	50-329 50-329 50-329 50-329 50-245	0 0 0 P	BLUBAUGHIR E BLUMDERGIN BLUMBERGIN BOARDMANIJ R BODINEIJ C	8210150596 8210210213* 8210210236* 8210170419* 8210150648*	40-3453 50-244 G 50-334 G 50-498 G 50-244 F	BOUCHEY, O D BOUCHEY, O D BOUCHEY, O D BOUCHEY, O D	8210130194 8210130575 8210190574 8210190644 8210190708	50-397 F 50-397 F 50-397 E 50-397 Q 50-397 F
	515+CP.R W 315+CP.T W 815+CP.T W 815+CP.T W 815+CP.T W	8210260459 8210060109 8210060133 8210060264 8210060294	50-245 50-362 50-275 50-206 50-206	P Q Q Q	BODINE, J C UDEHNERT, P BOEHNERT, P BOEHNERT, P BOLLINGER, L J	8210250343* 8210010083* 8210010089* 8210010095* 8210270179	50-244 6 50-321 5 50-366 5 50-366 5 40-8577	BOUCHEY, C D BOUCHEY, C D BOUCHEY, C D BOUCHEY, C D	8210190764 8210210045 8210210049 8210210146 8210210276	50-397 A 50-397 K 50-397 E 50-397 E 50-397 E
	21540P. T W B1540P. T W B1540P. T W B1540P. T W	8210080210 8210080212 8210190250 8210190478 8210250222	50~204 50~204 50~361 50~361 50~361	0 9 9	BOLT, S E BOMBERGER, C BOOK, H E BOOK, H E BOOK, H E	8210050504 82101800264 8210060126 8210060131* 8210080302	RES 50-346 P 50-228 Q 50-228 Q 70-754	BOUCHEY, O D BOUCHEY, O D BOWEN, L A BOWER (NO, D BOWERS, H (8210210327 8210270012 8210180146* 8210270064* 8210270064*	50-397 A 50-508 A 50-454 G COMMISSION 50-537 O
	SISHOP. T W SISHOP. T W SISHOP. T W BISSETT. P SISHETT, P	8210280287 8210280324 8210280330* 8210210213* 8210210236*	50-275 50-275 50-275 50-244 50-334	0 0 0 0	800K, H E 800K, H E 800K, H E 800K, H E	8210080311* 8210130152 8210190450 8210190473 8210190612*	70→754 State Prog 50-361 G 70-754 50-312 G	BOWMAKER,N J BOYD,R S BOYER,R E BOYER,R E BOYER,R E	82(0150423 8210120324 8210120331* 8210050270* 8210050275*	50-317 F REVIEW GRP REVIEW GRP GA999 GA999
	elach.r L Elack.r L Elach.r L Elach.r L Elach.r L	8210150309* 8210150324* 8210150337* 8210150351* 8210150365*	50-322 50-322 50-322 50-322 50-322	0 0 0	800K.H E 800K.H E 800K.H E	82[0190632 8210190636* 82[0250173 82[0250178* 82[028024]	50-27 0 50-27 0 50-362 0 50-362 0 50-397 0	BOYLE, R R BOYLE, R R BOYLE, R R BRACK, B BRACK, E W	6210120322 6210120324 6210120448 8210060216* 6210070451*	WASTE MGT WASTE MGT WASTE MGT FOIA FOIA
	ELACA:R L ELACY:R L ELACY:R L ELACY:R L ELACY:R L	8210150393* 8210150402* 8210150410* 9210150422* 821015052/*	50-322 50-322 50-322 50-322 50-322	0 0 0 0	BOOK, H E BOOK, H O BOOKER, J E BOOKER, J E BOOKER, J E	8210280248* 8210190605 8210050201 8210050219 8210050317	50-397 0 50-312 0 50-458 8 50-458 8 50-458 8	DRADBURY, R D BRADBURY, R D DRADFORD, L GRADFORD, L GRADFORD, L	8210220348 8210290237 8210050176 8210050237 8210280236	PR PR 50-289 Q 50-289 G 50-289 H
	ELACH.R L ELACH.R L ELACK.R L ELACK.R L	B210180079 B210190370 B210190373 B2101903B1 B210190390	50-322 50-312 50-522 50-312 50-466	0000	BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E	8210050350 8210130182 8210130514 8210170347 8210170518	50-458 8 50-458 8 50-458 8 50-458 8 50-458 8	GRADFORD.W M BRADLEY.E J DRADLEY.E J DRADLEY.E J BRADLEY.E J	8210220232* 8207070201 8207170147 8210060276 8210150126	50-348 Q 50-278 P 50-352 F 50-277 J 50-352 A
	Black.8 L Blackhau H S Blackhau H S Blackhau H S Blackhau R F	8210280251 0210260285 8210120124 8210120657 8210010185	50-322 50-382 RES RES PR	G A	BOOKER.JE BOOKER.JE BOOKER.JE BOOKER.JE	8210190629 8210200037 8210220376 8210250118 8210260286	50-458 S 50-458 S PR 50-458 S 50-458 S	BRADLEY, E J BRADLEY, E J BRADLEY, E J BRADLEY, E J BRADLEY, E J	8210150377 8210200046 8210200067* 8210220006 8210220007*	50-352 C 50-277 P 50-277 P 50-278 P 50-278 P
	elaya, j l Elaya, b s Elaya, b s Playa, b s Elaya, e l	9210080215* 9210250356 9210250356 9210250356 9210070194	FOIA PROJ PROJ PROJ 50-289	o	BOOKER, J C BOOKER, J E BOOS, A BOOTHROYD, J C	8210260272 8210270263 8210260504 8210260504 8210260504	90-458 S PR 50-329 T 50-329 T 50-201 P	BRADLEY, E J BRADLEY, F J BRANCH, M W BRANDENBURG, B BRANDENBURG, B	821026015A 8210230321 8210150502* 8210250081 8210250099	50-352 A PR 50-407 G 50-247 G 50-247 G
	elave, e l Slave, e l Slave, e l Slave, e l Blave, e l	8210070174 8210080074 8210080094 8210130275 8210130275	50-269 50-289 50-269 50-269 50-289	0000	BORCHERT, R BORDENICK, D BORDENICK, D M BORDENICK, D M BORDENICK, B M	8210220064* 8210250059* 8210040011 8210040063 8210050243	50-332 Q 50-322 Q 50-322 Q 50-323 Q	BRANDENBURD.B BRANDENBURO.B BRAUND.C D BREHENY.P J BRENIZER.J S	8210250324 8210290271 8210190787* 8210190760* 8210060086	50-247 G 50-247 G 50-440 G 50-254 F
	Slaxe, E L Slaxe, E L Ilare, J Blaxe, J Blaxe, J	8210200033 8210200033 8210150170* 8210150404* 8210220218*	50-289 50-289 50-324 50-259 50-424	0 0 0 0	BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDINE, T C	8210150117 8210200036 8210280209 8210280234 8210130471*	50-322	BREWNER, L DREWNER, L DREWNER, L DREWNTER, C DREY, H L	8210010354 8210210383 8210220332 8210120440	
	BLAKE, J J BLAKE, J J BLAKE, J J SLAKE, J J SLAKE, J J	8210010071* 8210010110* 8210010305* 8210010314*	50-400 50-413 50-267 50-389 50-338	0 0 0	BORDINE,T C BORDINE,T C BORGMANN,E A BORGMANN,E A BORGMANN,E A	8210150505 8210250371 8210050137 8210050332 8210040271	50-155 P 50-155 F 50-358 8 50-358 K 50-359 8			
	PLAYE, J J PLAYE, J J BLAYE, J J BLAYEYARD, B	8210010447* 8210150063* 8210150114* 8210150123* 8210040322	50-416 50-324 50-324 50-369 50-413	G G G D	BOROMANN, E A BOROMANN, E A BOROMANN, E A BOROMANN, E A BOROMANN, E A	8210040309 8210040358 8210130372 8210150387 8210150443	50-358 8 50-358 8 50-358 8 50-358 K 50-358 S			
	PLASSAK, L J PLAVER, H H BLAVER, H H BLAVER, H H BLOCH, P B	8210040183* 8210150204* 8210150250* 8210180257* 8210050751	50-220 50-322 50-322 50-322 50-266	P T T C	BOROMANN, E A BOROMANN, E A BOROMANN, E A BOROMANN, E A BOROMANN, E A	8210260279 8210260488 8210270281* 8210270285* 8210270270*	50-358 S 50-358 E 50-358 Q 50-358 Q 50-358 Q			
Service of the Party of the State of	Bloch, PB Bloch, PB Bloch, PB Bloch, PB Bloch, PB	8210070137 8210120337 8210130329 8210130339 8210200027	50-440 50-440 50-440 50-440 50-266	0 0 0	BORBT.F J BORYBIAK.M BOUCHEY.G D BOUCHEY.G D BOUCHEY.G D	8210280382 8210190359* 8210010020 8210040255 8210050126	71-9044 50-346 B 50-508 H 50-397 A 50-397 E			
-										

FENDUNAL AUTHUR INDEX

RDH1 UA	ALLES ION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEB910A NUMBER	5 3 E - CATE, -
of Inaman, r e drinkman, r e drilaman, r e drinkman, r e drikman, r e	8210180152+ 8210180157+ 8210180363+ 8210180372+ 821018037J+	FOIA FOIA FOIA FOIA	BUCK, J R BUCK, J R BUCKLES, J BURDOIN, J F BURDER, C	8208290012 8208290012 8210040313 8210040141* 8210010206*	ACRS 50-315 J 50-275 0 50-325 Q	CAREY, J J CAREY, J J CARLSON, J D CARR, A V CARR, A V	8210270267 8210270268* 8210280303* 8210250125 8210250262	50 334 50 3.4 (50-215 50 413 (50-413
GRIMMAN, R E GRIMMAN, R E SPINAMAN, R E SPINAMAN, R E BRIMMAN, R E	8210180377+ 8210180386+ 8210180383+ 8210180386+ 8210180387+	FOIA FOIA	BURGER, C BURGER, C BURGER, C BURGER, C W BURGER, C W	B210220173* B210220503* B210220504* B210010205* B210010397*	50-324 Q 50-324 Q 50-261 Q 50-324 Q 50-400 Q	CARR, A V CARR, S E CARR, B E CARRICO, J B CARRICO, J B	8210240415 8210050500# 8210210064# 8210220064 8210220092#	20 411 COW +4.1 COV, F1.7 40 811
BRIDAMAN R E BRIDAMAN R E BRIDAMAN R E BRIDAMAN R E BRIDAMAN R E	8210180371* 8210180374* 8210180377* 8210180399* 8210180402*	FOIA FOIA FOIA FOIA	BURGER, C W BURGER, C W BURGER, C W BURGER, F J BURGESS, B L	8210170300 8210170657 8210220163* 6210130173* 8210170750*	50-324 S 50-324 S 50-490 Q 50-271 R 50-329 Q	CARTER.R E CARTER.R B CARTER.R S CARTER.B CARTER.B	821013014 8210130160 8210130163: 82102Y0321: 8210060422:	50 62 1 50 184 1 50 184 1 50 457 50 457
OFINMAN, RE OFINMAN RE DROCKETT, T BRODE, R H BRODEKY, A	6210160406* 6210160409* 8210150496 6210060354* 8210050026*	FOIA FOIA 1%E 50~261 F REGGD	BURKE.D J BURKE.E M BURKETT.P T BURNETT.P T BURNETT.P T	8210010245* 8210260504 8210010151* 8210010176* 8210010472*	50-280 0 50-327 T 50-416 0 50-261 0 50-395 0	CARTWRIGHT, W CARTWRIGHT, W CARTWRIGHT, W CARTWRIGHT, W R CARTWRIGHT, W R	8207230301 8207230301+ 8210010140 8210010145+ 8210010163	59-33 (59-33 (53-33 (50-34 (
Broden. A Brons. J C Brons. J C Brooks. D Brooks. E	8210270331 8213040371 8213180388 8213120353* 8213010238*	NUREC 50-286 F 50-286 R MASTE MOT 50-348 O	BURNETT,P T BURNETT,R F BURNETT,R F BURNETT,R F BURNETT,R F	8210150143* 8210070047* 8210070445* 8210070471* 8210070482*	50-269 Q 50-537 D FOIA FOIA FOIA	CARTURIGHT.W R CARTURIGHT.W R CARTURIGHT.W R CARTURIGHT.W R CARTURIGHT.W R	8210010140+ 8210010219+ 8210010231 8210010234+	10 31- 1 50 Jul 50 Jul 50 Jul 50 Jul 50 Jul
GROOMS.E H GROOMS.H GROUM.C H GROUM.E J BROUM.E J	6210010432+ 8210210200+ 8210150384+ 8110010072+ 8111040084+	50-259 Q 50-271 P 50-243 Q F81A 50-313 S	BURNETT,R F BURNETT,R F BURNETTE,R D BURNS,R A BURNS,S	8210180107* 8210170095* 8210080258* 8210170435* 8210150236	70-143 REVIEW GRP 50-267 P 50-393 Q DRG	CARTWRIGHT, W R	8210080182 8210080185* 8210190264 8210190270* 8210190329	50 43 1 50-03 5 50-03 1 50-03 1
SROWN, E J BRECKK E J BROWN, E J BROWN, E J	6209150106+ 6210076104 6210070111 8210120093 6210120372	50 261 P 50-313 S 50-348 S MISC MISC	BURNS.S G BURSEY.B BURSTEIN.S BURWELL,S B BUSCH.S L	8210150090 8210150458 8210050055 8210210025 8210070099#	M1SC 50-395 0 50-246 P 50-445 A 50-29 P	CARTWRIGHT, U R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, N R	821019033/• 8210220227 82102202J4* 8210220415 8210220421•	50 7 3 1 50 0 3 1 50 0 3 1 10 0 3 1 50 0 31 1
BROWN, G B BROWN, G B BROWN, G B	821070383 8210220123 8210220161 8210220464 8210280180	40-4622 40-1162 40-2259 40-4622 40-7980	BUSCH, S. L. RUSH, N. BUSS, R. D. BUTLER, M. B. BUKTOK, L. D.	B#10120300# 8210120425# 8210130390# 8210040379# 8210050397	50-213 P CONTRACT 50-254 R FOIA NOREG	CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	8210220441 82102204501 8210260281 82102602874 8210260290	50 34 50-14 1 50-04 1 50 31 1 50-3
BROWN H H BROWN H H BROWN H II BROWN H II	8210950180 8210050180 8210050189 8210050189 8210250097	50-275 0 50-275 0 50-322 0 50-322 0 50-275 P	Byrd, r Byrd, r Byrd, r Byrd, r Byrd, r	8210080127* 8210080289* 8210080298* 8210220274* 8210220431*	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	CARTURIGHT, W R CARTURIGHT, W R CARTURIGHT, W R CARTURIGHT, W R CARTURIGHT, W R	821026029% 8210260346 8210260360* 8210290337 8210290347*	50 3 d 5 50 3 f 6 50 32 f 1 50 37 f
Brown. P Brown. P Brown. R Brown. R Brown. R C	8210290097 8210060214# 8210010231 8210070281 8210220171#	50-275 P 50-443 Q 70-2873 40-8745 40-2259	BYRD, R DYRD, R BYRD, R W CAGNETTA, J P CAGNETTA, J P	8210220462* 8210270345* 8210270055* 8210130280 8210130331	50-416 S 50-416 S 50-416 S FRM 50-213 P	CARUSO, R CARUSO, R CARUSO, R CARUSO, R CARUSO, R	8210070085 8210070169 8210120207 8210120245 8210120272	50 29 F 50 28 F 50-29 F 50-29 F 50-27 F
BROWN R C BROWNLEE, V L BROWNLEE, V L BROWNLEE, V L	8210130250# 8210070118# 821001031# 8210010327# 8210010469#	50-537 A 50-537 A 50-321 G 50-321 G 50-325 G	CAGNETTA, J P CAGNETTA, J P CAHILL, W J CAIN, C L CAIN, C L	8210130331 8210130331 8210040215 8210070374# 8210220070#	50-213 P 50-213 P 50-458 K 40-6622 40-8111	CARUSO, R CARVER, A M CAGE, E O CASEY, B J CASHMAN, D C	821021012J 8210010115+ 8210260339+ 8210170720+ 8210260240+	50 29 9 50 24 8 50 24 8 50 24 9 CUNTRACT
BROWNLEE, V L BROWNLEE, V L BROWNLEE, V L BROWNEE, V L BROWNB, R J	8210150103* 8210190271 8210220159* 8210220232* 8210120125	50-424 0 50-302 8 50-424 0 50-348 0 NUREO	CAIN, C L CAIN, J CALDNELL, R A CALL, V B CAMPBELL, D	8210220128* 8210240084 8210260301* 8210270288* 9210170040*	40~1162 Harte Mgt 50~278	CASSEL, D W CASSEL, D W CASSEL, D W CASSEL, D W CATCHPOLE, G J	8210210346 8210210345 8210210347* 8210210347* 8210260377	50 454 6 8 50 454 6 8 50 454 6 8 50 454 6 8
BRUCE, W R BRUNE, R L BRUNNER, E BRUNNER, E BRUNNER, J E	8210120432* 9210060004 8210010007 8210220255 8210050246	CONTRACT NUREQ 50-220 9 50-339 8 50-329 0	CAMPBELL, G CAMPBELL, J E CAMPBELL, M A CAMPBELL, R H CANTER, H	8210290066# 8210170330 8210170530 8210250025	50-259 8 RES State Prog WASTE MOT 50-312 8	CAUDLE, R E CAVANAUGH, H CAVANAUGH, H CHAIKEN, J A	8210070409 8210040109 8210250159 8210260180* 8208290098	71-9150 50 313 / 50 358 / 50 313 1 FOIA
DRUNNER. J E DRUNNER. J E BRYAN, R H BRYAN, V J	8210040193 8210180212 8210220381 8210050304 8210240084	50-327 G 50-327 G 50-327 G RES 40-8452	CANTER, H L CANTRELL, F S CANTRELL, F S CANTWELL, P E CAPHTON, D L	8210060336# 8210150032# 8210150334# 8210180175# 8210210056#	50-312 Q 50-416 Q 50-518 Q 50-304 B 50-289 Q	CHAN.T L CHANDLER, J C CHANDLER, J C CHANDLER, J C CHANDLER, L J	8210050393 8210120230 6210130511 6210270164 8210040009	50-315 4 50 316 1 10PPEP 10FFEP 50-361 1
DRYANT J C THAYAB C LTHAYAB C LTHAYAB C LTHAYAB	8210280446 8210010166* 8210010436* 8210010474* 8210170447	40~8452 50~269 0 50~369 0 50~269 0 50~287 S	CAPHTON, D L CAPHTON, D L CAPHTON, D L CAPRA, L A CAPRA, L A	B2 0210213* 8210210236* 8210270072* 8210040335* 8210040340*	50-244 Q 50-334 Q 50-289 Q QA979 QA979	CHANDLER, L J CHANDLER, L J CHAPLIN, B D CHARNLEY, J B CHARNLEY, J B	8210180075 8210220240 8210150289# 8210170810 8210250074#	50-361 4 50-361 1 50-320 1 70PAEP 50-260 1
BRYANT, J C BRYANT, R E BUCHANAN, C R BUCHANAN, C R BUCHANAN, C R	8210220471# 8210210444# 8210180118# 8210180304# 8210180319#	SO-413 0 CGNTRACT FOIA FOIA FOIA	CARALIE, Q P. CAREY, J J CAREY, J J CAREY, J J CAREY, J J	8210050213* 8210010013 8210050165 8210060076 8210130561	70-2942 50-334 F 50-334 P 50-334 R 50-334 P	Charnley, J 8 Charterina, J Chase, J, Chase, J, W Chaudhary, 8 K	6210290288 8210070181+ 82102205031 8210150032+ 8210290210+	10PREP 50-219 1 50-324 6 50-618 6 50-352 1
BUCHANAN, CR BUCHANAN, CR BUCHANAN, CR BUCHHEIT, RD BUCHHOLZ, RH	8210180324* 8210180370* 8210180375* 8210190420* 8207120147	FOIA FOIA FOIA 50~333 G 50~447 A	CAREY, J J CAREY, J J CAREY, J J CAREY, J J CAREY, J J	8210150018* 8210150312 8210170747 8210220184 8210240458	50-334 Q 50-334 P 50-334 P 50-334 Q 50-334 F	CHECK, P 8 CHECK, P 8 CHECK, P 8 CHECK, P 8 CHECK, P 8	8002140204+ 8003310179+ 8004100193+ 8010210783 8011200025	50-265 P 50-266 P 10-265 T 50-267 P

AUTHOR	NUMBER C	TOBUEUR YRQDBTA:		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	• ••	AUTHOR	ACCESSION NUMBER	EUBJEC T CATEGORY
HECKLP S HECKLP S HECKLP S HECKLP S HECKLP S	8203040474* F0 8210050477 50 8210060458* 50 8210080053 50	31A 0-537 A 0-537 D 0-537 D UREO		CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W CHURCHILL, B H	8210080084 8210080090 8210080090 8210180051* 8210180054*	50-382 50-382 50-382 FOIA FOIA	G G O	CLAYTON, F L CLAYTON, F L CLEMENTS, H D CLEMONS, P CLEMONS, P E	8210280282 8210290289 8210240042* 8210220255 8210070314*	50-364 P 50-364 B 50-445 Q 50-333 S 70-364
MEN'S J MEN'S J HEMAULT, N H HEMAULT, N H HEMAULT, N H	B107270196* 50 B210190567* 50 B210220150* 50	0-266 0 0-266 0 0-416 5 0-416 6 0-416 5		CHURCHILL, B W	8210180057* 6210180058* 8210180312* 8210180315* 8210180318*	FOIA FOIA FOIA FOIA		CLEVELAND, J C GLIFFORD, J H GLINE, H E GLOUGH, R H GLOUGH, R H	8210150564 8210220513 8210150401* 8107270178* 8107270182*	NUMEG 50-445 A 50-261 0 50-266 G 50-266 G
HENAULT, H H HENAULT, H H HENO, N H HIANOI, N J HIANOI, N J	B210290081* 5 B210270208* 5 B210180141 5	D-416 S 0-416 S 0-338 P 0-400 S 0-400 S		CHURCHILL, B W	8210260406 8210280253 8210280253 8210280387 8210280387	50-266 50-266 50-266 50-382 50-382	6 6 6 6 6	CLOUGH, R W CLOUGH, R W CLOUGH, R W CLOUGH, R W CLOUGH, R W	8107270185* 8107270186* 8107270191* 8107270194* 8107270198*	50-266 0 50-266 0 50-266 0 50-266 0 50-266 0
HILK.S J HILK.S J HILK.S J HILK.S J	8210040102 5 8210040108 5 8210040189 5	D-143 0-275 G 0-247 G 0-133 G 0-287 G		CILIMBERO,R L CILIMBERO,R L CILIMBERO,R L CILLIS,M CILLIS,M	8210040415 8210050538 8210250340 8210040131# 8210250178*	50-315 50-315 50-315 50-248 50-342	የ የ ዕ ዕ	CLOUGH.R W CLOUGH.R W COBO.J C COBO.J C CCOBO.L I	8107270199* 8210260211 8210040231 8210210046 8208190237	50-266 0 NUREO 50 264 J NUREG 50-3 0
HILK'S A HILK'S A HILK'S A HILK'S A	8210070183 8210070192 8210080207*	00-275 0 00-201 0 00-537 G 01A 100FR		ClPOLLA.A J CLAPP.N E CLARK.A T CLARK.C W CLARK.D	8210150600 8210150564 8210070313* 8210210329 8210200113	40-3392 NUREO 50-537 TOPREP TOPREP	D	COCHRAN, T B COCHRAN, T B COCHRAN, T B CODELL, R CODELL, R B	6210210240* 6210220277* 6210220283* 8007260312 6210059431	50-53/ G 50-537 G 50-537 G 50-247 P NUREG
HIER'S A HIER'S A HIER'S A HIER'S A	8210120599 8210130075 8210130087#	50-275 0 100FR 50-289 T 50-289 T 50-395 T		CLARK.K M CLARK.L CLARK.M T CLARK.N E CLARK.P R	8210170621 8210170334 8210120657 8210080276 8210210280	50~424 50-20 RES 50-395 50-219	ន F P	COHEN, I COHEN, K D COHM, B M COLARULLI, P F COLARULLI, P F	9210290107* 9210070485* 9210270230* 9210250272 9210250272	50-220 G FOIA CONTRACT 50-247 H 50-247 H
HILKS J HILKS J HILKS J	8210130327 8210130336 8210180193	50-395 T 50-275 G 50-397 G 50-133 G 50-437 G	 	CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A	8110270050* 8207210514 8210010018 8210040044* 8210040443	50-266 50-309 50-317 50-335 30-309	6 6 6	COLDURN, T O COLBURN, T G COLBURN, T G COLE, R K COLE, S	6110300460* 6210270274 6210270426 6210050377 6210260232	50-266 P 50-266 P 50-266 P NUREG 50-322 T
HILKS J HILKS J HILKS J HILKS J	8210180180 8210180180	70-143 50-269 (50-413 (FOIA 50-269 ()	CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A	8210040414 8210040420# 8210040427# 8210050484 8210050504#	50-266 50-266 50-266 50-317 50-309	Р Р Р	COLE, S COLEMAN, J II COLEMAN, J M COLEMAN, J M COLEMAN, J M	8210260239* 8210260367 8210260367 8210260373 8210260373	50-322 T 50-338 G 50-338 G 50-338 G
41FK 8 3 41FK 8 3 41FK 8 3 41FK 8 3	8210210422 8210210427 8210210428 8210210493 8210210508	50-329 50-269 50-269) 0 1 0 1	CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A	8210050507# 8210070012 8210070059* 8210070060* 8210070117*	50-309 50-344 50-309 50-309 50-317	6 6 6 6	COLEMAN, R COLEY, J L COLEY, J L COLEY, J L	8210170217 8210270376 8210101110# 8210170114# 8210220218#	CONTRACT CONTRACT 50-413 0 50-324 0 50-424 0
11LK, 8 J 11LK, 8 J 11LK, 8 J 11LK, 8 J 11LK, 8 J	8210220249 8210220415 8210220473 8210230010 8210230010	50-275 50-382 50-387	P T G P G	CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A	8210070130* 8210120134 8210130599 8210190008 8210210387	50-317 50-317 50-213 50-313 50-336	# 0 P F	COLLEY, J A COLLINS, D M COLLINS, J T COLLINS, J T COLLINS, J T	8210040004# 8210189075# 7811200399# 7905290357# 7908130654#	CONTRACT FOIA 50-325 5 50-324 P 50-261 P
11 CK/8 J 12 CK/8 J 13 CK/8 J 11 CK/8 J	8210260468 8210270161 0210270170 8210280265 8210270446	50-289 50-329 50-320 50-289 50-275	0 0 0 0	CLARKIP A CLARKIR A CLARKIR A CLARKIR A CLARKIR A	8210220020 8210250050* 8210250267 8210260551 8210270297*	50-336 50-335 50-307 50-335 50-246	р Р Р	COLLINS, J T COLLINS, J T COLLINS, J T COLLINS, J T	9210220030 9210280024* 9210280027* 9210280042*	8tate frog 50-324 f 50-324 f 50-261 f
HRAISAL B HRAMAL B HRAMAL H HRAMAL B	8103050987* 8104290103* 810908417* 8112010310* 8201050061*	50-327 50-366 50-302 50-336 50-324	9 8 8 8	CLARK.R A CLARK.R A CLARK.R A CLARK.R A CLARK.R A	8210270303* 8210280210 8210270038 8210270042 8210270413	50-266 50-344 50-285 50-338 50-344	р Р Q	COLLINS, H COLLINS, H COLLINS, F L COLLINS, E H		
11 rahal n Berayal n Berayal n Beryal n Berayal n Berayal n	8201190538* 8203170060* 8204210289* 8210030027* 8210070115	50-346 FDIA 50-416 80-348 50-346	8 8	CLARKIR A CLARKIR A CLARKIR A CLARKIR A CLARKIR A	B210270416* B210270421* B210270428* B210270431* B210270441*	50-338 50-317 50-264	Ե Ե			
IRANAL: M IRANAL: M IRANAL: M IRANAL: M IRANAL: M	B210070122 B210070442 B210070440 B210070470 B21008001B	50-327 50-324 50-346 50-348 50-336	8 8 8 8	CLARK, R. A CLARK, R. G CLAV, E. L. CLAYTON, F. L.	92102904444 9210290041* 9210010460* 9210010398* 9210010129					
Franal, M Franal, M Franal, M Franal, M Franal, M	8210080067 8210120155 8210120171 8210120369 8210220519	50-339 50-293 50-321 50-272 50-333	8 8 8	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	6210010195 6210050066 6210050087 621013027 621013052					
DNG.L R RIGSOTINDS.N RIGSINAN.J N RIGSTOFFER.O	8210080055* 8011040548* 8210150279 8210150279 8210050311*	50-537 30-254 50-322 50-322 50-331	D 9 0 0	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F. L CLAYTON, F. L	821015007 821015033! 8210190606 821019072; 821019076.					
RESTOPHER, W. RESTOPHER, W. JRCHILL, B W. JRCHILL, B W. JRCHILL, B W.	8210130174* 8210290057* 8210070124 8210070124 8210070184	50-382 50-382 50-382 50-382	0 0 8 8	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F. L CLAYTON, F. L	821025009(82102604(! 821026043; 821026045' 821028013(

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUP FOT CATEGORI
CONVERTE L CHIERTE L OKTERT B OKTERT B OUTER T B	6210040043 8210250048 6210050197 6210050197 8210050326	50-335 P 50-325 P 50-352 C 50-352 C	CORMIER.W H CORRADO, J COSTELLO, J R COTTER.B P COTTER.B P	8210250076 8210120353* 8210120233* 8210200056	50-142 G Waste Mot Qa999 50-482 G 50-397 G	CRANE, P A CRANE, P A CREED, J R CREED, J R CRESWELL, J S	8210260359 8210270276 8210050110* 8210050311* 8210120380	50-137 50-275 50-325 50-338 50-327
OTIER, T.B. CERVER, T.B. COVIER, T.B. COVIER, T.B. COMPER, T.B.	8210050382 8210050392 8210070402 9210970402 8210200066	50-352 G 50-358 G 50-358 G 50-358 G 50-352 G	COTTER.B P COUNSIL,W O COUNSIL,W C COUNSIL.W G COUNSIL.W C	8210200087 8209300324 8210010207 8210010207 8210010207	50-70 G 50-213 P 50-213 P 50-213 P 50-213 P	CREWS.J L CREWS.J L CREWS.J L CRISCIONE.J L CROCKER,H W	8210010042 8210010285 8210190731 8210010383* 8210150059*	50 205 } MISC 50 344 4 50-335 \$ 50 322 }
COMMER. T B COMMOR. L COMMOR. L COMMOR. L LONGOY, B W	0210200066 8207180058 8207180060 8207180061 8210270180	50-352 G FOIA FOIA FOIA 40-8502	COUMSIL, W C COUNSIL, W C COUNSIL, W C COUNSIL, W C	8210010230 8210010230 8210010312 8210010312	PR PR 50-213 P 50-213 P	CROCKER, H W CROFF, A G CROMER, D L CROSBLE, % L CROSSMAN, W A	8218218142• 821887825 1• 8218186186 821812058 3 8218058399*	50-337 50-537 50-4(3) 70-4*3 4
COUTE R COUTE R COUTESER, T S COOK, B A CHOK H L	8210150091# 8210260483 8210130399 8210120400 8210060415#	50-289 Q 50-289 S PR RES FOTA	COUMSIL.W G COUMSIL.W G COUMSIL.W G COUMSIL.W G	8210010312 8210040120 8210040120 8210050090 8210050090	50~213 P 50~245 F 50~245 F 50~336 P 50~336 P	CROSSMAN, U A CROSSMAN, U A CROUSE, R P CROUSE, R P CROUSE, R P	8210190417+ 8210190452+ 8210050255 8210050256+ 8210050304	50 546 1 50 346 1 50 345 4 50 345 4
1 00% 1 M 1 00% 1 M 1 00% 1 M 2 00% 1 M 2 00% 1 M	0210120243* 8207070419 8207070422* 8210010278 8210010437	50-333 R 50-329 K 50-329 K 50-329 E 50-329 A	COUNSIL.# G COUNSIL.# G COUNSIL.# G COUNSIL.# G	8210050118 8210050118 8210050177 8210050177 8210050179	50-245 P 50-245 P 50-245 P 50-245 P 50-336 P	CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P	8210090313+ 8210090313+ 8210050337 8210040314 8210080280+	50 345 F 50 345 F 50 345 F 50 345 F
0004 U B 0004 U B 0007 U B 1 004 U B 1 004 U B	8210050143 8210080115 8210120274 8210130005+ 8210130264	50-329 S 50-329 R 50-329 A 50-329 F 50-329 F	COUMSIL. W G COUNSIL. W G COUNSIL. W G COUMSIL. W G	8210050179 8210050376 8210060048 8210060048 8210060094	50-336 P 50-213 Q 50-245 P 50-245 P 50-245 P	CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P	8210180174 8210190303 8210190623 8210210458 8210220013	50-346 P 50-341 6 50-346 P 50-346 P
COOK J G COOK J G COOK J G COOK J W	821013026A* 8210190520 8210210294 8210260121 8210260121	50-329 K 50-329 E 50-329 A 50-329 S 50-329 O	COUNSIL, W G COUNSIL, W G COUNSIL, W G COUNSIL, W G	8210060094 8210060233 8210060233 8210060237 8210060237	50-245 P 50-245 Q 50-245 Q 50-336 P 50-336 P	CROUSE.R P CROW.W T CROW.W T CROW.W T	8210260260 8210040397* 8210210514 8210210593 8210220028*	50 345 7 70 371 70-(11) 70-35 70-3-37
100% 7 W 100% 7 M 100% 7 M 100% 9 M	8210280076 8210290163* 8210290228 8210290229* 8210290380*	50-329 S 50-329 Q 50-329 A 50-329 Q	COUNSIL. H G COUNSIL. H G COUNSIL. H G COUNSIL. H G COUNSIL, H G	8210070354* 8210070356* 8210080105 8210130331 8210130331	50-245 0 50-245 0 50-423 A 50-213 P 50-213 P	CROWLET.B R	821027043&+ 8210280421+ 8210270211 8210270172+ 8210010124+	70 1151 70 4557 70 473 70 2744 50-217 1
COOKEN U COOKEN M U COOKEN M U COOKEN M U COOKEN M U	8210190750* 8210050017 8210060017 8210060047 8210060074	50-327 Q REGGD 50-278 S 50-277 S 50-277 S	COUNSIL, II G COUNSIL, H O COUNSIL, H O COUNSIL, H G COUNSIL, H G	8210130331 8210130399 8210190555 8210190555 8210190663	50-213 P PR 50-423 S 50-423 S 50-213 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8109200494* 82100100a0 82100400a2 82100400a7 8210040099	50 213 P 50 213 P 50 407 P 50 105 P
L M.73 (00) L M.73 (00) L M.73 (00) L M.73 (00) L M.73 (00)	B2100400B3* B210040177 B210040353 B210070177 B210130224	50-277 S 50-277 S 50-277 S 50-277 G 50-278 S	COUNSIL, W G COUNSIL, W G COUNSIL, W G COUNSIL, W G	8210210340 8210210340 8210250290 8210250290 8210250329	50-423 S 50-423 S 50-423 S 50-423 S 50-423 S	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	821004013-1 82100402-1 8210040265- 8210090059 8210050065	50 27 F 50 217 F 50 217 F 50 244 F
COOKEY, M U COOKEY, M U COOKEY, M U COOKEY, M U COOKEY, M U	8210150154 8210150179* 8210150400 8210230190 8210240112	50-277 S 50-277 8 50-277 S 50-277 R 50-277 R	COUNSIL. W G COUNSIL. W G COUNSIL. W G COUNSIL. W G	8210250329 8210260194 8210260194 8210260414 8210260414	50-423 S 50-245 P 50-245 P 50-245 P 50-245 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8210050072 8210070010 8210070404 8210120296 8210130088	00 ± 55 F 30 213 F 50 213 F 50 203 F
CODNEY M J COGPER, J W COGPER, J W COGPER, J W COGPER, W E	8210240329 8001080054* 8102280195* 8210180148* 8210080191	50-277 P FOIA FOIA FOIA 50-275 P	COUNSIL. H O COUNSIL. H O COUNSIL. H G COUNSIL. H G COUNSIL. H O	8210260459 8210260459 8210260519 8210260519 8210270200	50-245 P 50-245 P 50-245 P 50-245 P 50-213 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8210130893 8210130205 8210130375 8210180059 8210180065	50 245 F 50 243 F 50-407 F 50-237 F 50-206 F
COOPER W E COOPER, W E COOPER, W E COOPER, W E COOPER, W E	8210080193* 8210080272 8210190583 8210190584 8210250147	50-275 P 50-275 P 50-275 P 50-275 P 50-275 P	COUNSIL, H G COURSIL, C CONGILL, C COG, H T	8210270200 8210270200 8210060374 8210070275* 8210190244*	50-213 P 50-213 P 50-219 S 50-219 Q 50-261 S	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8210180070 8210180073* 8210180074 8210180077* 8210180082	50-205 P 50-206 P 50-244 I 50-244 P
COOPER.W E COOPER.W E COOPER.W E COOPER.W E COOPER.W E	6210290197 6210250240 6210250291 6210260211 6210260277	50~275 R 50~275 P 50~275 P 50~275 R 50~275 P	COLH T COLH T COLH T CRAFT.C M CRAIQ, J	8210220247* 8210270078* 8210270339* 8207270240* 8210150247	50-261 8 50-261 8 50-261 8 F01A 50-271 0	GRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D	8210180087* 8210180094* 8210180110 8210180112 8210180149	39-244 F 50-244 F 50-255 F 50-244 F
CODPER, W E COPELAND, V G COPELAND, V G COPELAND, V G	0210290319 0210130446 0210130448 0210130457* 0210130457*	50-275 R 50-155 G 50-155 G 50-155 O 50-155 O	CRAIO.J Cranc.J Crane.P a Crane.P a Crane.P a	8210150388 8210280143 8210010198 8210010406 8210010413*	50-315 Q 50-312 P 50-133 F 50-275 P 50-275 P	CRUTCHFIELD. D GRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	8210180153* 8210180161* 8210180183 8210180187	50-214 # 50-214 # 50-214 P 50-409 # 50-29 P
COPPER.W E CORDARO.M CORDARO.M CORDARO.M C CORDARO.M C	8210250318 8210150204* 8210150250* 8210150223* 8210150257*	90-275 P 50-322 T 50-322 T 90-322 T 50-322 T	CRANE, P A	8210050122 8210050144 8210120278 8210130272 8210150151	50-275 P 50-275 P 50-275 P 50-275 G 50-275 R	Crutchfield, D Crutchfield, D Crutchfield, D Crutchfield, D Crutchfield, D	8210170680 8210200015 8210200016 8210200025 8210200031	50-237 P 50-409 P 50-409 P 50-409 P
CORDARD, H C CORE, H R CORLEY, W O CORLEY, W G CORMIER, W H	8210150290* 8210090303* 8210260527 8210260527 8210150456	50-322 T 50-285 S 50-327 T 50-329 T 50-142 0	CRANE, P A	8210150389 8210210044* 8210220371 8210220395 8210250192	50-275 P 50-275 F 50-275 P PR 50-133 R	CRUTCHFIELD, B CRUTCHFIELD, D CRUTCHFIELD, B CRUTCHFIELD, D, CRUTCHFIELD, D	8210200038 8210200041 8210200040 8210200070 8210210224	50-109 P 30-155 P 50-219 P 50-219 P 50-211 P

AUTHOR	ACCESSION NUMBER	CATEG	DRY	AUTHOR	ACCESSION NUMBER	SUBJE		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
OTHERENORD FORMERENORD FORMERENORD FORMERENORD	8210210246 8210210336 8210210545 8210210552* 8210210555*	50-29	P G P P P	CUTCHIE, J M D'ANGELG, A J DAHLMAN, L C DALE, L F DALE, L F	8210290100 8210190478* 8210130544* 8210010023 8210040053	50-289 50-397 50-306 50-416 50-416	0 0 0 F P	DANESE, F L	8210050471* 8210270427* 8210270427* 8210270437* 8210270438*	FOIA 70-1510 70-1510 70-1510
UTCHFIELD. D UTCHFIELD. D UTCHFIELD. D UTCHFIELD. D UTCHFIELD. D	821 0220233 821 0220272 621 0220368 821 0220449	50-244 50-155 50-409 50-409	P O P P	DALE.L F DALE.L F DALE.L F DALE.L F DALE.L F	8210040264 8210040353 8210060295 8210070044* 8210150013	50-416 50-416 50-416 50-416 50-416	P P F O	DARIELSON.D H DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R	82100403084 8210040146 8210050132 8210130173 8210130177	50-440 0 50-440 K 50-440 S 50-440 E 50-440 A
JICHFIELD. D JICHFIELD. D JICHFIELD. D JICHFIELD. D JICHFIELD. D	8210250071 8210250124 8210250203 8210250213 8210250310	50-155 50-245 50-237 50-155 50-155	P P P P	DALE, L F DALE, L F DALE, L F DALE, L F	8210190494 8210190521 8210190566 8210200005 8210200030	50-416 50-416 50-416 50-416 50-416	# # E E	DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R	8210130354 8210150233 8210170326 8210170333 8210170633	90-440 8 50-440 E 50-440 A 50-440 E 50-440 E
JTC+FIELD: D JTC+FIELD: D JTC+FIELD: D JTC+FIELD: D JTC+FIELD: D	6210250327* 6210250337* 6210250363 9210260162	50-155 50-155 50-155 50-213 50-217	ь ь ь	DALE, L. F DALE, L. F DALE, L. F DALE, L. F DALE, L. F	8210200064 8210200073 8210210217 8210220334 8210220425	50-416 50-416 50-416 PR 50-4(6	E P E	DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R	8210210079 8210220339 8210220372 8210240009 8210240011*	50-440 A PR PR 70-2968 70-2968
,1, PFIELD, D ,1() PFIELD, D ,1() PFIELD, D ,1() PFIELD, D ,1() PFIELD, D	8210260185* 8210260191* 8210260299 8210260296 8210270004	50-219 50-219 50-206 50-237 50-219	P P P P	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8210260264 8210260412 8210270277 8210280132 8210280135	50-416 50-416 50-416 50-416 50-416	P P Q P	DAVIDSON, D R DAVIDSON, D R DAVIDSON, D R DAVIS, C E DAVIS, F C	8210260337* 8210260419 8210260575* 8210210037 8210180066*	50-440 Q 50-440 A 50-440 F NUREG FDIA
TCHFIELD.D TCHFIELD.D TCHFIELD.D TCHFIELD.D TCHFIELD.D	8210270202 8210270265 8210270270 8210280287 8210280433	50-219 50-155 50-155 50-409 TOPREP	P P P	DALE, L F DALING, P M DALING, P M DALTON, C DALTROFF, B	8210270102 8210120092 8210120102 8210220357# 8207070208*	50-416 NUREG NUREG 50-387 50-278	P H P	DAVIS, J O DAVIS, J O DAVIS, J O DAVIS, J S DAVIS, L S	8210070070* 8210070071* 8210120135 8210120187 8207110026	50-537 A 50-537 A 27-47 40-2061 FULA
Allician G E 1014 (ECD' D 1014 (ECD' D 1014 (ECD' D 1014 (ECD' D	8210290169 8210290175# 8210290183# 8210290316 8210150348	50-204 50-204 50-204 50-204 71-5926	P P V	DALTROFF.S L DALTROFF.S L DALTROFF.S L DALTROFF.S L DALTROFF.S L	8210130294* 8210150069 8210210297 8210210330 8210280196	50-277 50-277 50-277 50-277 50-277	0 P P	DAVIS.H J DAVIS.P R DAVIS.P R DAVIS.P R DAVIS.P R	8210010245x 8207180080 8207180080 8207180085 8207180085	20-325 0 20-325 0 20-325 0 20-580 0
ILMGHAM, O E ILMGHAM, R E ILMGHAM, R E ILMGHAM, R E	8210250110 8210270037 8210050034* 8210070093* 8210070179*	50-70 71-5939 REGGD 50-537 50-537	P A A	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8106220165# 8210010088# 8210010106 8210010113 8210010117	50-241 50-335 50-413 50-321 50-249	р 0 0 0	DAVIS,R DAVIS,S H DAVIS,S H DAVIS,S H DAVIS,S H	8210220314 8210170276* 8210270280* 8210280200* 8210280301*	PR 50-317 8 50-317 5 50-310 6 50-317 8
INCHARL R E INCHARL R E IAN D IAN D IAN D	8210070182# 6210280434 8208270094 8210200026 8210200026	50-537 40-2041 50-322 50-443 50-443	A G G	DANGE, H C DANGE, H C DANGE, H C DANGE, H C DANGE, H C	8210010142 8210010155 8210010158 8210010162 8210010204	50-335 50-335 50-269 50-424 50-348	0 0 0 0	DAVIS, W DAYAL.R DE AGAZIO.A W DE AGAZIO.A W DEAN.V	8210210034 8210120367 8210120025 8210290378 8210290378	50-259 F RES 50-344 P 50-346 P 50-352 1
AN D AN D AN D AN D AN D	8210200035* 6210200035* 8210200042* 8210200042* 8210200047*	50-443 50-443 50-443 50-443 50-443	0000	DANCE.H C DANCE.H C DANCE.H C DANCE.H C DANCE.H C	8210010213 8210010221 8210010235 8210010245* 8210010300	50-389 50-336 50-321 50-280 50-338	0 0 0 0	DEARIEN.J A DEBBAGE.A G DEBBAGE.A G DEBBAGE.A G DEGROOT.D M	6210290017 6210010143# 6210150315# 6210220145* 6210010190	RES 90-413 0 50-390 0 50-400 0
ay. 0 Ey. B Is. N W Is. N W 18. N W	8210200049* 8210260091* 8210010268 8210010417 8210040052	50-443 Wabte M 50-388 50-387 50-387	G S F E	DANCE.H C DANCE.H C DANCE.H C DANCE.H C DANCE.H C	8210010301 8210010309 8210010316 8210010380 8210010424	50-389 50-321 50-250 50-404 50-369	0 0 0 0	DELGEORGE, L O	62100402464 6210050056# 8210050073 8210050123 8210040268#	50-456 Q 50-373 Q 50-456 A 50-454 A 50-373 Q
12' H H 18' H H 12' H H 12' H H	8210050325 8210050370 8210060179 8210080083 8210130122	50-387 50-397 50-387 50-387 50-387	Р Р Р	DANCE, H C DANCE, M C DANCE, H C DANCE, H C DANCE, H C	8210010451 8210010466 8210010467 8210080227 8210150014	50-369 50-395 50-395 50-321 50-369	Q Q Q Q	DELOEGROE.L G DELOEGROE.L G DELOEGROE.L G DELOEGROE.L G	8210130370 8210130402 8210220383 8210260308+ 8210280125+	50-454 F FR FR 50-454 Q
8' 14 14 8' 14 14 18' 16 14 18' 16 14 18' 16 14	0210130341 8210190297 8210210020 8210210137 8210220102	50-397 50-397 50-387 50-387 50-387	C 8 8 4 8	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	6210150053 6210150072 6210150078* 6210150076 6210150116	50-370 50-348 50-348 50-424 50-369	0 0 0 0	DELGEORGE, L. O DELICHATSIOG, M DELICHATSIOG, M DELLA RATTA, A DELLA RATTA, A	8210270245 8210050428 8210130574 8210060370* 8210210238*	PR NUREG NUREG 70-1100 50-271 Q
6. n u 5. n u 5. n u 5. n u	8210220179 8210220366 8210250256 8210250264* 6210250367	50-387 PR 50-387 50-387 50-387	J P P	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210 5013 8210 50187 8210 50253 8210 50262 8210 50345	50-269 50-338 50-269 50-389 50-335	Q Q Q Q	DELLSY, H M DELONG, S R DEN ISON, E DEN ISON, E DEN ISON, E	8210010381 8210290251 8210080078 8210080080* 8210250221	PR REGGD 50-275 P 50-275 P
5. N Y 5. N H 6. N H 7. N H 8. N H	8210250373* 8210260270* 8210260366 8210260379* 8210290318	50-387 50-387 50-387 50-387 50-387	P G P P	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210190683 8210220158 8210220204 8210220211# 8210220229	50-269 50-424 50-424 50-424 50-348	5 G G	Denison, e Denison, e Deniing, r Denning, r Denniston, s F	8210270184 8210270185* 8109240007* 8201130322* 8210210444*	50-275 R 50-275 P 50-275 P FOIA FOIA CONTRACT
IN	8210050069 8210060303 8210060321* 8210150175 8210150275	50-440 50-440 50-440 50-440 50-440	00000	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210220280 8210220291# 8210220328 8210220331 8210220454	50-335 50-335 50-370 50-280 50-338	9 9 9	DENNISTON, B F DENNISTON, B F DENTE, T J DENTON, H R DENTON, H R	8210270221x 8210270223x 8210250181 8107010140x 8210010149	CONTRACT CONTRACT TOPREP 50-241 P 50-278 F
H 6 H H 7 H H 7 H H 7 H H 7 H	8210190475 8210250365 8210260383 8210260395 8210280346	50-440 50-440 50-440 50-440 50-440	00000	DANCE, H C DANESE, F L. DANESE, F L DANESE, F L. DANESE, F. L	8210220467 8201060245* 8210050439* 8210050446* 8210050467*	50-413 F0IA F0IA 70-1510 F0IA	o	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8210010161# 8210050030# 8210060473 8210080350 8210120049	50-327 8 REGOD 50-320 P 50-275 P REVIEW GNP

# ITHIR	ACCESSIO 4 NJMEER	SUBJE	DRY	AUTHOR	ACCESSION NUMBER	SUBJE	ORY	AUTHOR	ACCE 49 ICH NUMBER	b fa Fa :
CE ITC I H R	821012-083	50-244	Р	DIETZ. C R	8210010298	50-324				- '
"E ITE I H R	6210190092	REVIEW		DIETZ, C R	8210010399			N O WOX 10	8210100156	\$1 g
DENTC + H R	8210190118	REVIEW		DIETZ. C R	8210010473	50-324	5	N D YOX 1 C	8510140325	: .
LENTE I H R	82102700764		5	DIETZ. C R	8210040320	50-324	ទ	01 (00, 0 4	0210190505	3. 1
EENTC I H R	8210270331	ORG		DIETZ, C R	8510080181	50-325	s	DI (ON, D W	821019051J 8210190557	\$7.4
Lentou H A	8210290061¢	FOIA		DIETZ, C R	9210080220	50-325	5			
CF 'TC I H P	8210290449	50-275	G	DIETZ, C R	8210080221	50-324	s	א סיאסאזם	8510570 140	\$ 55
Egyfe" H R	8210270451*		G	DIETZ. C R	8210130477	50-325	8	M O'NDX10	0510550143	FP ,
CENTON H A CEUSTER R W	82102704544		G	DIETZ, C R	8210130489	50-325	5	DIXON'O M	0210420478	5,1,5
TENZIEK M M	62102605924	50-201	G	DIETZ. C R	8210150016*	50-324	G	# 0,407.1d	0510590140	80 d 80 m
CEVINCENTIS, J	8210010465	50-443	A	DIETZ, C R	8210150023*	50-324	G.			•4
CEVIT CENTIS J	8214016465	50~443	A	DIETZ, C R	8210150038*	50-324	Q	DIXON'O M	8210260159	4. 1
CEVIALENTIS J CEVIACENTIS J	8210040112	50-443	Ą	DIETZ, C R	8210150041	50-324	s	DIXON O H	8210260172	4 - 1
CEVITCENTIS J	8210040112 8210040193	50-443 50-443	A	DIETZ, C R DIETZ, C R	8210150045#	50-324	Q	DIKON, O W	0210390245	PŘ
1-11112111121	8210040173	30-443	*	DIEILL K	8210150106#	50-324	G	W D WDX10	021029027) 02102902#4	1335,
CEMP CENTIS J	B210040193	50-443	A	DIETZ. C R	8210150291	50-324	6		1744 VA 70411 7	142),
CEVINCENTIS J CEVINCENTIS J	8210050199 8213053199	50-443	A	DIETZ, C R	B210150295*	50-324	a	טנעסאי מ א	0210290115	35 3
CEVINCENTIS, J	6210030144	50-443 50-443	A	DIETZIC R	8210170666	50-325	5	DODDS, R	0510140344*	\$2.00
DEVINCENTIS J	8210070105	50-443	A	DIETZ, C R DIETZ, C R	8210190748 8210190754	50-324	8	DODDS,R T DODDS,R T	0210060157*	
				51E1E74 II	0210170754	50-324	8	DODOS, R T	## \$1000016 P	1011
DEVINCENTIE J	8210130436	50-443	A	DIETZ, C R	B2102204924	50~324	Q		MATERIA INC.	
DEVINGENTIS J DEVINGENTIS J	8210130436 8210150510	50-443	A	DIETZ, C R	8210260256	50-325	8	DODDS,RT	B2101905564	40.00
CETTALENTIS J	8210150510	50-443 50-443	A	DIETZ, C R	8210260269	50-324	5	DODDB, R T	401 40910128	\$2.71
CEVINCENTIE J	8210180001	50-443	A	DIETZ.C R Dietz.c R	8210260294	50-325	6	DODDS.R T DODDS.R T	0210140533	50,00
	*********	30 113	^	DIEIZIC K	8210260344	50-325	ន	DOERFLEIN, L T	021019074 1• 8210210115•	\$3 54 g
EEVINGENTIS J	B210180001	50-443	A	DIETZ, C R	8210290079	50~324	6		05105101134	£2.3
DE' INCENTIS, J DEVINCENTIS, J	9210190126	50-443	5	DIETZ.C R	8210290243	50-324	6	DOMER, J A	8210190105	50.0%
CEVINCENTIS. J	8210170126 8210170136	50-443	5	DIETZ, C R	8210270325	50-325	ŝ	DOOLITILE, E. L.	0210120031	50 41
CEVINCENTIS J	8210170136	50~443 50-443	S S	DIETZ, C R	8210290336	50-324	S	DOOLITTLE, E L	0210210021	2.5 24
		30-443	5	DIETZ, C R	8210290346	50-325	6	DOROSEY, J A	0210010176	37.74
DEVINCENTIS, J	8210190363	50-443	8	DIFFERENT, P M	8210060203*	50-416	8	DEMOCITO A	8510070134	3 .
DEVINCENTIS J DEVINCENTIS J	8210190363 8210260149	50-443	s	DIFFERENT, P M	8210080192*	50-416	8	DORSEY, J A	8210070199	4 4- 4
CEVINCENTIS, J	8210240149	50-443 50-443	S	DIFFERENT P M	8210190424*	50~416	ទី	DOUGAN, J R	821019056V	1. 7, 1
CEVINCENTIS J	8210240330	50-443	5 5	D1005, R	BS10130010	50-440	Ä	DOUGHERTY, J D	8210260140	
		04-443		DIGCS.R M	8210040049	50-346	Ի	DOVOHERTY, J D DRAKE, J H	0210240155	1 1
DEVINCENTIS J CEVINCENTIS, J	8210260330	50-443	S	DIGGS.R M	8210050589	50-250	p.	DUNNELO II	D2102400V)	\$ 1-14
DEVINCENTIS. J	8210280119 8210280119	50~443	Ą	DIGGS, R M	8219070033	50-266	ů.	DRAPER, D M	02100400/5=	5, 11
CEVINE J B	8210040403	50-443 XPORTLIC	A	DIGOS, R M	8210130050	50-331	ĕ	DUBRY, N E	82102001714	1
CEVINE, J B	8210080119	XFORTLIC		DIGGS.R M	8210270278	50-280	P	DUDA.L.E	B\$10150065	
CEVINE, J B				DIGNAN, T O	8210130314	50-309	Q	DUOA, L. E	0510170105	fr + Li
DEVINE, T	6510080129	XFORTLIC		DIGNAN, T O	8210130314	50-309	_	DUCEY, B	0210240441*	50 m
CEVINE. T	8210040375+ 8210150457*	50-373	Q	DIIANNI, D C	8210120589	50-202	Ç	DUNLAP, J N	0210040044+	
CEVINE, T	8210150457*	50-358 50-358	¢	DIMABOID, N J	8210150188*	50~322	ŕ	DUNLAP, J H	02100070444	9 i in
CEVINE. 7	8210210391	50-358	G G	DIMASCID, N J	8210150240*	50-322	÷	DUNLOP, P	8210140445	\$3.23
* F		30 330	v	DIMASCIO, N J	G210150270*	50-322	ŕ	DUINE L A	0210210041	
Cevine, T Devine, T	8210210371	50~358	Q .	DIRCKS, W J	8110220004#			DUROIN, H W	6210130207+	25.00
DEVINE, T	8210210400# 8210210400#	50-358	G	DIRCKB, W J	8201150180*	FOIA		DURR, J P		•
DEWANDEL, E P	82102100534	50-358 50~280	0	DIRCKS, W J	8201270037*	50-206 FOIA	8	DURR, J P	8210060215+ 8210070403+	13 63
DENEY, L S	8210120271	50-522	F G	DIRCKS, W J	82031103744	FOIA		DURR, J P	0510510005	10 411 50 112
DEWEY. L S			•	DIRCKS, W J.	8204200390*	FOIA		DURR, J P	0210210264	43.2
DEMEA'T B	8210120288	50-522	G	DIRCKS, H J	02040000			a Linnua	8510550500+	23.00
DEWEN L B	8210150247 8210220429		0	DIRCKS, W J	8204300098* 8205040550*	FOIA		DUTTON O		
DEYOUNG, R C	8208190238		0	DIRCKS, H J	8205270507*	FOIA FOIA		DUTTON, D DUTTON, D	02100/0140	22 4,6 1
C	42104170530	20-3	Q	DIRCKS, W J	8205280495	SECY		BUTTON, D. E.	0210150362	32 4.1
				DISCRE' H A	8206180042*	FOIA		DYNES, R R	0210270246 021015022 ft	30 (.) 32 %
								DYNEB, R R	B2101502231	9 m 1944 4 m 175

FUCCIONE MOTURE INDEV

AUTHOR	ACCESSION NUMBER	SUBJECT	,	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	_	AUTHOR	ACCESSION NUMBER	SUBJECT	Y
EDLOW, J EDWARDS, D EDWARDS, D EDWARDS, D ETCHEWHOLZ, H	8210210543* 8210240077 8210220372 8210270243 8210150017*	70-2955 40-3453 PR PR 50-293	o.	EVANS, L J EVANS, L J EVERETT, R J EVERETT, R J EVERETT, R J	8210070058* 8210070044* 8210070394* 8210220128* 8210220171*		D D	FELYON. J M FELTON. J M FELTON. J M FELTON. J M FELTON. J M	8210180028 8210190013 8210190019 8210190033	50-321 50-322	P A C Q
EICHLEA, T V E1921: (GER, R E EISENHUT, D G EISENHUT, D G EISENHUT, D G	8210150557 8210150550 8007010658 8007070448 8103170719*	NUREQ NUREQ 50-247 50-245	P P S	FABRIZIO,R F FABRIZIO,R F FALCONER, D FALCONER, D FARDIS, M N	8207180064 8210180039 8210010166* 8210010474* 8210050428	50-269	a a a	FELTON, J M	8210190036 8210190042 8210190066 8210190047 8210190079	50-315 50-321 50-348 FOIA FOIA	r r
E1SEXHULD 0 E1SEXHUT.D 0 E1SEXHUT.D 0 E1SEXHUT.D 0	8111300367* 8204290048* 8206070106* 8208250412* 8210010212	50-206 50-270 50-245 FOIA 50-361	8 A S	FARDIS, M N FASANO, A FASANO, A FAW, R E FAY, C U	8210150574 8210150071* 8210150232* 82101502365 8107270156	50-289 50-188	a ด ส ฉ	FELTON, J M	8210190074 8210190077 8210190112 8210190144 8210190198	FO1A 50-047 A104 FO1A 50-047	r r
EIGENHUT, D G EIGENHUT, D G EIGENHUT, D G EIGENHUT, D G	8210010215# 8210050495# 8210060433# 8210070217# 8210070235#	50-361 50-289 50-272 50-266 FOIA	P F P	FAY, C W FAY, C W FAY, C W FAY, C W	8210040119 8210050005 8210050054 8210050222 8210050256	50-266 50-266 50-266	F P F P Q	FELTON, J M	6210190163 6210190176 6210190189 6210190179 6210190133	50-219 50-250 F01A 50-440 50-275	r r r
EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q TISENHUT, D Q	8210120505 8210120590* 8210130024 8210130029* 8210150519	50-305 50-278 50-416 50-416 50-287	Բ Ե Ե	FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	8210050272 8210040325 8210040333* 8210130584 8210130150	50-301 50-301 98	F S S	FELTON, J M	8210210050 8210210071 8210210073 8210210544 8210260008	50-240 FOIA 50-267 50-317 50-302	F F I
TISERBUT.D G TISERBUT.D G TISERBUT.D G TISERBUT.D G TISERBUT.D G	8210250168 8210260521* 8210260532 8210280021* 8210280423	50-275 50-272 50-382 50-324 50-305	P F A P F	FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	8210150158× 8210150430 8210150471 8210180047 8210190284	50-244 50-244 50-244	Я Р Г О Р	FELTON, J M	8210260122 8210260572 8210270083 8210270132 8210270256	50-314 50-440 50-251 50-266 50-266	F S r r
ISENHULD O ISENHULD O ISENHULF T L-ZEFTAHY, M L-ZEFTAHY, M	8210280425* 8210290203 8210040122* 8207120140* 8210030155*	50-305 50-286 50-387 50-324 FOIA	r 0 8 P	FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	8210190519 8210250258 8210250242* 8210250344 8210250352*	50~246 50-266 50-266 50-266 50-266	555	FELTON, J M	8210270423 8210270426 8210280013 8210280016 8210280033	70-1510 50-271 50-261 50-369 50-322	F P T
L-ZEFTAWY, M LASSER, T C LORED, D T LORED, D T LIN, J O	8210060427* 8210210174* 8210250277* 8210280078* 8210170478*	F01A 50-245 50-346 50-346 50-397	9 8 9	FAY, C W FAY, C W FAY, C W FAY, C W FEHRINGER, D J	8210260476 8210270259* 8210280295 8210290294 8210120355	50-266 50-266 50-266 50-266 HASTE MG	Р F Р Т	FELTON, J M	02 0760045 02 0280058 62 0280108 62 0280117 62 0280134	50 409 50-255 50-313 50-295 50-271	F F F
LLIS.J LLIS.J LLIS.T S LLIS.T S	8210150224 8210250104 8210260355 8210200003	50-445 50-445 50-445 50-322 50-322	0000	FE1TKNECHT, C FELTON, J FELTON, J M FELTON, J M FELTON, J M	8210060088 8210120070 8207150434 8207210425 8207270125	50-334 F01A 50-247 50-251 50-10	R F S F	FELTON.J M FELTON.J M FELTON.J M FELTON.J M FELTON.J M	0210280140 6210280361 6210280370 6210280389 6210280394	50-3 50-254 50-315 50-148 FOIA	r F H
LROD, S A LSASSER, T LSASSER, T LSASSER, T LSASSER, T C	8210220303* 8210190017* 8210210261* 8210220521 8210270174*	50-335 50-273 50-423 50-273 50-213	0 0 0 0	FELTON: J M	8209290148 8210010008 8210040020 8210040343 8210040340	FDIA 50-311 50-445 50-537 FDIA	e G A	FELTON. J M	8210280399 8210280402 8210280419 8210280442 8210290020	50-315 FOIA 50-275 50-275 FOIA	r F
MMERT.R M NOEL.R E NOELKEN.R H NOELKEN.R H NOELKEN.R H	8207070324* 8207090224* 8210010267 8210250372* 8210270048*	70-2748 50-278 50-362 50-275 50-142	Р Q Р	FELTON. J M	8210050013 8210050430 8210050512 8210050557 8210050562	50-309 70-1510 50-483 50-335 FOIA	F B F	FELTON, J M FELTON, J M FELTON, J M FENSTERMACHER FERNANDEZ, W	8210290023 8210290047 8210290085 8009250234 8210190077*	50-142 50-10 FOIA 50-247 50-233	F F F 8
MGLE.L. R MOLERT. B R MTHISLE.E B MILISMA.R B	8210290414 8210280272 8210150200 8210150200 8210010284*	50-338 RES 50-170 50-170 50-329	₽ H H E	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210050582 8210060419 8210060423 8210060423	50-322 FOIA FOIA 50-358 50-537	C H	FERREIRA, B P FERRELL, C FERRELL, C FERTNER, K FICOLER, F B	8210060257# 8210060451# 8210060455# 8208190170# 8210010077	TOPREP 50-537 50-537 50-213 50-219	A A P P
RIKSON, K T RIKSON, K T RIKSON, K T RIKSON, K T RIKST, M L	8210260232 8210260239* 8210260239* 8210260239*	50-322 50-322 50-322 50-322	T T T	FELTON, J M	8210060429* 8210060434 8210060437 8210060442 8210070003	FOIA FOIA 50-149 50-537 50-346	H D F	FIEDLER, P D FIEDLER, P D FIEDLER, P D FIEDLER, P D FIEDLER, P D	8210070178 8210070238 8210130167 8210130357 8210130078	90-219 50-219 90-219 50-219 50-219	\$ 5 5
RNST.M L RNST.M L RNST.M L RNST.M L URYSL H	810306008B* 8108030041* 8112030565* 8201060003* 8210030007	FOIA FOIA FOIA FOIA 50-241	P	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210070007 8210070029 8210070040 8210070411 8210070417	50-244 50-537 50-416 FOEA FOEA	P D F	FIEDLER, P D FIEDLER, P D FIEDLER, P D FIEDLER, P D FIEDLER, P D	8210190398× 8210190704 8210220187* 8210250072 8210250136	50-219 50-219 50-219 50-219 50-219	а Р а Р
384.2 H 384.2 H 384.2 H 384.2 H 384.2 H	8210050362 8210060013 8210190709 8210260244 8210260323	50-324 50-241 50-241 50-324 50-324	Р Р Р	FELTON, J M	8210080015 8210080020 8210080029 8210080034 8210080129	50-281 FD1A 50-295 50-249 50-315	5 F P F	FIEDLER, P D FIEDLER, P D FIEDLER, P D FIELDS, C FIELDS, C	8210250189 8210250285 8210290254 8210220443* 8210290286*	50-219 50-219 50-219 50-395 50-395	P B S
JRY.L N JRY.L N JRY.L N JAIG, C A JAIG, C D	8210260405 8210260475 8210260508 8210010178* 8210010118*	50-324 50-241 50-241 50-313 50-321	P P G G	FELTON, J M	8210120015 8210120103 8210120392 8210120545 8210120643		የ የ የ የ	FIELDS.C FIELDS.J A FIELDS.W W FINAMORE.B FINAMORE.B A	8210290338* 8210190102 8210190720* 8210220286* 8210060195	CONTRAC 50-261	CT P Q
/ANS. C. D /ANS. C. D /ANS. C. D /ANS. L. J /ANS. L. J	8210150219* 8210150239* 8210150263* 8210070037* 8210070056*	70-27 50-249 50-537	G D D	FELTON, J M	8210130004 8210130105 8210130594 8210130421 8210180014	50-338 50-315 50-244	F F F F	FINAMORE.B A FINAMORE.B A FINAMORE.B A FINAMORE.B A FINAMORE.B A	8210210232 82102102327 8210130246 8210130246	50-537 50-537 50-537 50-537	000

RÜHTUA	ACCESSION NUMBER	SUBJEC T CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FINAMORE.B A FINAMORE.B A FINAMORE.B A FINAMORE.B A FINAMORE.B A	8210210232 8210210357 8210210357 8210210453 8210210453	50-537 0 50-537 0 50-537 0 50-537 0 50-537 0	Frahm, r Frahm, r Frahm, r Frahm, r Frahm, r	8210130358* 8210150065* 8210150093* 8210150118* 8210150140*	50-311 S 50-311 S 50-311 S 50-311 S 50-272 S	GARCIA.P J GARCIA.P J GARCIA.P J GARCIA.R GARDNER.R	8210210021 8210210525* 8210220475 8210040255 8210040337	40-3453 40-3453 40-1162 10PREP 50-329 S
finamone.B a Finamore.B a Finamore.B a Finamore.B a Finamore.B a	8210220268 82102202863 82102202953 8210260397 8210260397	50-537 G 50-537 G 50-537 G 50-537 G 50-537 G	FRAHM, R FRAHM, R FRAHM, R FRAHM, R FRAHM, R	8210150320* 8210150339* 8210210144* 8210250057* 8210250389*	50-311	GARDNER,R N GARDNER,R N GARNER,L GARNER,L W GARNER,L W	9210050154* 8210190750* 8210010206* 8210010205* 8210010415*	50-329 Q 50-329 Q 50-325 Q 50-324 Q 50-324 Q
FIMMORE, B A FINCKE, J R FINCKE, J R FINDLEY, D E FINDLEY, D E	8210260404+ 8210260404+ 8210280339 8210120357+ 8210190037*	50-537 G 50-537 G RES CONTRACT CONTRACT	Frahm, R Frahm, R Frahm, R Frahm, R Frahm, R	8210280128* 8210280154* 8210270218* 8210270314* 8210270361*	50-311 S 50-311 S 50-272 S 50-272 S 50-272 S	GARNER, L W GARNER, L W GARRITY, J H GARRITY, J H GARRITY, J H	8210220173* 8210220503* 8210010230 8210040074 8210040077	50-324 Q 50-324 Q PR 50-309 P 50-309 P
FINALL A E FINLAYSON, F C FINLEY, N C FIGRAVANTE, H FIGRE, R A	8210210097* 8210260246* 8210290399 8210120139* 8210260352*	50-354 0 50-322 T RES 50-317 F 40-8610	FRALEY, R F FRANCIS. E FRANCIS. E FRANCIS. P FRANTZ, S P	8006300104* 8210130607 8210270054 8210010116 8210200058	FO1A 40-299 40-2259 70-633 50-522 G	GARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H	8210040217 8210060302 8210150398 8210220203 8210220212	50-307 P 50-307 Q 50-307 Q 50-307 P 50-309 P
i Iore.r a Fidrei Li.g Fisch.c Fischer.l Fish.r L	8210260352* 8210060345* 8210270158 8210150500* 8210150550	40-8610 50-520 0 XPORTL10 50-263 P NUREG	FRANTZ, S.P. FREDLAND, D.R. FREDRICKSON, P. FREEDBERG, L.	8210200058 8208290105 8210010350* 8210150256* 8208290089	50-522 G FGIA 50-324 G 50-327 G FGIA	GARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H	8210250078 8210260144 8210260327 8210260420 8210270008	50-307 P 50-307 G 50-307 B 50-307 P 50-309 G
FISHER.C R FISHER.C R FISHER.L F1TZPATRICK.B FLACK.E	8210290141 8210290234 82101505094 8210040145* 8210070336	TCPREP PR 50-263 P 50-247 S 50-461 0	FRENCH, L D FRENCH, L D FRIEDMAN, K A FRIEDMAN, P FRIEND, H B	8210(30531* 8210260169* 8210120293* 8210150272* 9210190470	50-29 8 50-29 8 QA979 50-322 T 50-275 P	GARRITY, J H GARRITY, J H GARV, R J GARY, R J GARY, R J	8210280087 8210280141 8210290343 8210040318 8210130576	50-307 F 50-307 P 50-207 5 50-445 S 50-445 F
FLACK, E FI EEROR, C FLEEROR, C FI EEROR C FLEEROR, C	8210280072 8210120454 8210120467 8210190180 8210270416	ILE CONTRACT CONTRACT 50-320 F CONTRACT	FRIEND, H B FRYE, J H FRYE, J H FUENTE, E 5	6210270351 6210270351 6210220343 6210250223 6210250223	50~275 P 50~275 P 50~70 G 50~142 G PR	GARY,R J GARY,R J GARY,R J GARY,R J GARY,R J	8210180004 8210220372 8210250338 8210250346 8210260375	50-445 # PR 50-445 \$ 50-445 \$
FLEENCR.C M FLEEHOR.C M FLEEHOR.C M FLEEHOR.C M FLEEHOR.C M	8210120411 8210770411 8210270425 8210280299 8210280310	27-39 50-387 X 70-1113 CONTRACT CONTRACT	FUHRMAN, G R FULFORD, P J FULLER, C FULLER, C FULLER, R	8210190730 8210210306* 8210050337* 8210190543* 8210120092	50-317 S 50-329 A 50-267 S 50-267 S NUREQ	GEE.O N GEFFEN.C A GEFFEN.C A GENADRY.M D GERDEMAN.F W	8210150553 8210120092 8210120102 8210050428 8210260019	Nureg Nureg Nureg Nureg 40-8698
FLEENDR, C H FLEENDR, C M FLEISHER, Z S FLEISHER, Z S FLEISHER, Z S	8210280327 8210280354 8210180203 8210200017 8210210390	CONTRACT CONTRACT 50-247 G 50-247 G 50-247 G	FULCHOODER R FURGALED T FURGATORE H GADER K GADER K	8210120104 8210180571 8210070355# 8210130314 8210130314	NUREG NUREG 50~438 A 50~307 G 50~309 G	GERETY, H F GERGELY, P GERNER, L F GERSTNER, W C GERSTNER, W C	8210150147 8210050412 8210280364* 8210190354 8210280050	50-289 J NUREG 50-254 F 50-461 E 50-461 G
LEISHER, Z G LEMING, T E LESSNER, S A FLIPPO, T A FLORY, C A	8210210397* 8210120536 82092902254 8210190349* 8210120554	50-247 G 40-0771 50-10 F 50-205 G WASTE MGT	GAD, R K GAD, R K GAD, R K GAD, R K GALLE, D P	8210270153 8210270153 8210270166 8210270166 8210270088*	50-443	GERTMAN, D I GERWIN, E F GIANELLI, J GIANELLI, J GIANELLI, J	8210120124 8210150474 8112018310* 8210070416 82100800[8	RE9 50-526 & 50-336 \$ 50-324 \$ 50-336 \$
FLGRY, C A FLYNN, B FLYNN, K FLYNN, M	8210120604 8210120648 8210140410 8210120354 8210180327	4D-8452 Waste mot Contract Contract Contract	GALLO, J GALLO, J GALLO, J GALLO, J	6207160052 6207160052 6210010408 6210010408 6210010446	FDIA FOIA 50-155	GIBDONB.T S GIBBB.D C GIBSON.A GIBSON.A F GIBSON.A F	8210150207* 8209270379* 8210050224 8210010121 8210010162	50-438 G CONHESSION 1&E 70-1201 70-143
FLYNN, K FLYNU, M FLYNN, M FLYNN, M J FL+NN, S F	8210180384 8210190018 8210190030 8210190005 8210130539	CONTRACT CONTRACT CONTRACT CONTRACT PR	GALLO, J GALLO, J GALLO, J GALLO, J GALLO, J	8210010446 8210050232 8210050232 8210050356 8210050356	50-155	G1860N, A F G1860N, A F G1860N, A F G1860N, A F G1860N, A F	8210010313 8210010353 8210010364 8210010388 8210080179	70-143 70-27 70-143 70-824 70-143
FLYIN, S F FLYIN, S F FOGARTY, D J FOLEY, T FOLEY, T	B210150305 B210220285 B210080211* B210070216* B210210307*	50-400 G PR 50-206 Q 50-286 Q 50-247 Q	GALLO, J GALLO, J GALLO, J GALLO, J	8210060204 8210060204 8210120457* 8210120457* 8210150300	50-155	01880N. A F 01890N. A F 01890N. A F 01890N. A F 01890N. A F	8210150064 8210150130 8210150197 8210150215 8210150229	70-1113 70-824 70-143 70-1201 70-27
FOLSOM.R O FOLSOM.R D FONNER.R L FORD.E W FORD.E W	8210220074* 8210220077* 8210180103 8210130319* 8210130530*	40-8111 40-8111 70-143 50-302 5 50-302 9	GALLO, J GALLO, J GALLO, J GALLO, J	8210150300 8210150470 8210150470 8210180142 8210180142	50~155 G 50-155 G 50-155 G 50-454 G 50-454 O	GIBSON, A F GIBSON, A F GIBSON, A F GIBSON, A F GIBSON, A F	8210150361 8210150403 8210210174 8210210216 8210210341	70-143 70-143 50-13 Q 70-1201 70-27
FORTUNA.R A FOSTER.D O FOSTER.D O FOSTER.H FOSTER.J E	8210280047* 8210220078 8210220208* 8210010189 8210130557*	50-324 P 50-424 B 50-424 Q 70-1151 50-461 Q	GALLO, J GALLO, J GALLO, J GALLO, J	8210180206 8210180206 8210180242 8210180242 8210200029	50-155 0 50-155 0 50-155 0 50-155 G 50-155 G	GIBSON, A F GIESEKE, J A GIESEKE, J A GIESEKER, J GIESLER, C W	8210220308 8210180592 8210210014 8210260118* 8210010179	70-1113 NUREO NUREO 50-373 \$ 50-305 P
FOSTER, K. W FRAHM, R FRAHM, R FRAHM, R FRAHM, R	8210150547 8210070231* 8210070252* 8210070258* 8210070314*	NUREO 50-31: \$ 50-31: \$ 50-31: \$ 50-272 8	GALLO, J GALLO, R GALLO, R GALLO, R M GALLO, R M	8210200029 8210070361* 8210070393* 8210150274* 8210290157*	50-155 Q 50-307 Q 50-271 Q 50-271 Q 50-27 Q	GIESLER.C W GIESLER.C W GIESLER.C W GIESLER.C W GIESLER.C W	8210010232 8210010307 8210040156 8210050263 8210060312	PR 50-305 S 50-305 Y 50-305 F
FRAHM, R FRAHM, R FRAHM, R FRAHM, R FRAHM, R	8210070377* 8210070398* 8210130170* 8210130227* 8210130345*	50-311 S 50-272 S 50-311 S 50-311 S 50-311 S	GALUNIC, B GAMMILL, W P GAMMILL, W P GARCIA, E M GARCIA, P J	8210050206* 8104290774* 8201120280* 8210190636* 8210120628	50-443 A 50-324 P 50-324 P 50-27 Q 40-6659	GIEBLER, C W GIEBLER, C W GIEBLER, C W GIEBLER, C W	8210130581 8210130300 8210130300 8210040338	50-305 Q 50-305 F 50-305 F 50-305 F

Control Cont	SOHTUA	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCESSION	SUBJECT CATEGORY		ACCESSION	SUBJECT
LL 1961 1	SEELER, C W SIESLER, C W SIESLER, C W SIESLER, C W SILERT, O D	8210170353 8210170487 8210260260 8210270234 8210270144*	50~305 50~305 PR 50~349	р 5 Г	H 3 (YARD H 3 (YARD R L (ADDR) B L (ADDR) U H (ADDR)	8210210125+ 8210210264+ 8210220445 8210270137+ 8207300170	90-354 Q 90-220 Q 50-287 Q 50-407 Q	GOTOEWOND'N G GOTOEWOND'N G	NUMBER B210180089* 8210180072* 8210180213* 8210250116*	FDIA FOIA FOIA FOIA 50-373 0
C.	CLEERT, L D CLEENH H CLINSKY, V CLINSKY, V	8210170776# 8210120454 8210220351 8210220363	50-449 REH 50-367 50-275	11	GUEEN'H A GUEEN'H A GUEEN'H A	8210060219 8210060265 8210060409	50-227 9 50-276 S 50-259 S	GULKAN, P GULKAN, P GUPPY, J G	8107270185# 8107270194# 8210070449	50-246 Q 50-246 Q RES
Included	TLLEN D H TLLEN D H TLLEN D H	0210270373 0210040363 0210210534*	10CFR 40~0501 40-0601	٥	CHECH'H 7 CHECH'H 7 CHECH'H 7	6210130165 6210130172 6210110317	50-257 S 50-259 S 50-32/ S	GUSTAVE.R GUSTAVE.R P GUSTAVE.R P	8210240559 8210050508# 821005052 ! #	CONTRACT CONTRACT CONTRACT
Common C	ALLILAND, J T INSBERO, T FIRAND, E H IFARD, E H P.ETTUM, P	6210120649 6210010076# 6210170406#	RES 50-335 50-259	O.	ORECHIH J ORECHIH J	8210130565 8210130572 8210190378	90-259 S 50-328 S 50-327 S	GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	8210080007* 8210120330* 8210120342*	CONTRACT CONTRACT CONTRACT
	leason, JP Heason, JP Heason, JP Heason, JP Hover, M9	0210150092 0210150141 0210200069	50-24/ 50-24/ 50-24/	0	U NATORO U NATORO U NATORO	9210220050 0210230001 0210230100	90-328 8 50-327 6 50-328 6	GUSTAVE.R P GUSTAVE.R P GUSTAVE.R P	821012050G* 8210130572* 8210150350=	CONTRACT CONTRACT CONTRACT
Colorado	LCVER, M S FIDARD, R J FIDARD, R J FIDARD, R J FIDARD, R J	8210040001 8210040003* 8210150167	50-155 50-155 50-155	0	CHINH J CHINH J CHIENH J	8210260381 8210260417 8210290054	50-259 S 50-260 S 50-259 S	GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	8210170004* 8210170087* 8210170141*	CONTRACT CONTRACT CONTRACT
23.7. A T	CODARD.R J COY.A T COY.A T COY.A T COY.A T	8210040049* 8210040370* 8210130449*	50- 27 70-1100 XPURILIC	Ö.	C H-M3380 C H-M3380 C H-M3480	8210290231 8210290277 8210290317	50-274 8 50 J27 8 50-257 B	GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	8210260284# 8210270033# 8210270395#	CONTRACT CONTRACT CONTRACT
SCLEBERJ JI SCLOBOOD 2 0 0498 A GRILIMAN DISCOSOFICATION OF CONTROL STATE	031. A T C37. A T C37. A T C37. A T C37. A T	8210220172* 8210220179* 8210220264*	70 371 70 371 70 607		GREENBLATT; 1) GREENBLATT; 1) GREENBEATT; D	8210210308 8210210419 8210210419	50-400 G 50-400 G 50-400 G	GUTTERREZ.J H GUTTERREZ.J M	6210260397* 6210050241 6210060069	CONTRACT 50~498 Q 50-309 G
NO.DER.B. G. G210190007	COY, A T OLCEERO, J H OLCEERO, J H OLCEERO, J H OLCEERO, S C	8210270237 8210200075 8310200092	50 498 50 -498 50-498	^	GREENMANTE O OREENMANTE O	0210060127* 0210060127*	50-030 8 50-017 0 50-270 0	HAASSIN P HACKETTID B HAELZIA	8207210413* 8010070320* 8210150535*	50-520 A 50-305 P 50-287 P
RLERA R 8210090042; RLGOD OFFICER R 9210130401; 90-409 0 100001; F 2210180332; CRIMTACT 90LER R 92101907172; 50-249 0 OFFICER R 9210130401; F 221019023; CRIMTACT 90LER R 92101907187; 50-246 P OFFICER R 92101007187; 50-246 P OFFICER R 92101007187; 50-246 P OFFICER R 92101007187; 50-246 P OFFICER R 921010007187; 50-246 P OFFICER R 9210100007; CRIMTACT 90LER R 9210100007; CRIMTACT 90LER R 9210100007; CRIMTACT 90LER R 92101000007; CRIMTACT 90LER R 921010000000000000000000000000000000000	Cadero, 8 C Cadero, 8 C Cadero, 8 C Cadero, 8 C Cadero, 9 C	8210150087 8210280347 8210270105	50 -454 50 -454 50 -454	0 0	GRELNMAN, F. O. GRELNMAN, F. O. GREGER, L. R.	0210210451* 0210270344* 0210070112*	50-272	HAGANIT F HAGANIT F HAGANIT F	8210120419* 8210120423* 8210120458*	27-39 50-389 M CUNTRACT
DODE R	OLLERIKA OLLERIKA OLLERIKA OLLERIKA	8210050042* 8210070172* 8210070185*	RLOOD 50~249 50~266	p	GREGGERIL R GREGGER J GREGGER J	9210130400* 9210230014 9210240109	50 -407 Q 70 -020 70 -020	HAGAN, T F HAGAN, T F HAGAN, T F	8210180332* 8210190025* 8210190037*	CONTRACT CONTRACT CONTRACT
CODIE J	Chialeta Odder R Odder R Odder R W Odder R W	8210210204× 8210240515* 8210210223*	50~13 50-335 70-1201	a	GREGORY, H B GRENIER, B L GREVE, F	0210120428 8104080307* 8207140494*	RES FOIA 90-373 G			
DODN'H E F 821020048 NUREO ROESGULO J P 8210260504 50-324 P ROESGULO J P 8210260504 50-324 P ROESGULO J P 8210260504 50-324 P ROESGULO J P ROESGULO	CCEMOPE A C CODIE J 8 CCEMANA CCEMANA CCEMANA 8	6210260501 6210010226 6210010232	50-374 PR PR		GROBE, J GROBE, J GROBE, J A	8210060384* 8210260467 8210060393*	50-373 Q 50-254 B 50-315 Q			
### ### ### ### ######################	Oddmanil 8 Oodwinie F Oolo. J P Rada. K D Raesser. K L	8210220048* 8210260504 8210050168*	NUREQ 50-329 50-334	p	GROESHULECH, B GROSSHAN, H	8210050378# 8210120613* 8210150217	50-382 Q T 3ANTAD 2 C 395 Q			
**AESSER.K L	Paceser. X L Paceser. X L Paceser. X L Paceser. X L Paceser. X L	8210180408 8210180167 8210190483	50-295 50-304 50-295	R 8	GROTENHUTE, H QUADAGNO, V QUCHA, L. T	8210120621 8210270376* 8210030330	50-250 P 40-8624 50-321 F			
AVESIA C B210010351 TOPRE 0110.R B2100000B1 50~413 AVESIA N B210150122 50~213 B 0UINN.P R B10316033B# FDIA AVESIA N B210270245 50~213 B 0UINN.P R B103160366# FDIA	raesserik L Raesserik L Raesserik L Rantij H Rantij H	8210260233 8210260399 8210080312	50-275 50-275 50-424	8 8	QUCHA, L T QUCHA, L T QUILBERT. D E	8210220386 8210290273 8210120304*	PRM PR QA999			
	DAIT. X 8 DAVES.C C ZAVES.R H PAVES.R H RAVES.R H	8210010351 8210150122 8210270245	TOPREP 50-213 50-213	8	OUILD, R OUINN, P R OUINN, P R	8103160368 8103160368 8103160368	50-413 FOIA FOIA			

ENSUMAL AUTHUN IMPEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR	ACCESSION NUMBER	gug s 1 CATEr f
HALL, D P	8210280213	50~461 A	HEIDER, L H	8210130353	50-29	Ρ	***************************************		
HALL, E E	8210120329*	HASTE MOT	HE LDER, L H	8210190484	50-29	P	HIDALOD, P A	8107270174*	50-215
HALLER, N M	8005270820*	FOIA	HEIDER, L H	8210220157*	50-29	a	HIETALA, J	8210260297*	50 JIJ
HAMAWI.J N	8210150290*	50-322 T	HEIDER, L. H	8210280094	50-29	P	HIETALA, J	8510590351*	50-37
HAMILTON. J F	8510550317	PR	HEINZ, E L	8210270182*	40-8577		HIGGINBOTHAM, L HILF, C L	8210120030: 8210250074:	F014 30-2-1
HAMILTON, P P	8210050214	50-244 P	HEISHMAN, R F	8209290236*	FOIA		HILL, D		
HAMMER, S	8210190293*	50-243 S	HEESHMAN, R F	8209290240*	FOIA		HILL, D	8210180336	CCMTFA
HANAUER, 8 H	9205280470*	FOIA	HEISHMAN, R F	8210050522*	50-483	s	HILLIK L	8210180346*	CONTRAC
HANAUER, B H	82100700084	FOIA	HEITKEMPER, E M	8210120496*	CONTRACT		HILLIK L	8210040376* 8210130137*	30 331
A L.XDDDAAH	8210130310	50-302 S	HEITHER, K L	8210040423	50-309	P	HILL.K L	6210130390+	50 III 50 III
HANCOCK, J A	8210130520	50-302 8	HEITNER, K L	8210070054	50-309	P	HILL.K L		
HANCOCK, J A	8210220052	50-302 S	HEITNER, K L	8210290160	50-309	P	HILL, K L	82101305904 82102302614	\$0.3%
HANNETT, B A	8210070452	XPORTLIC	HETTNER, K L	8210290165	50-309	P	HILLIK L	8210250300	533.
HANNETT, B A	8210080037	XPORTLIC	HELFRICH, R E	8210130433	PR		HILLIK L	8210230387	3C-31
HANNETT, B A	8210080040*	XPORTL1C	HELGESON, K A	8210200104	70-820		HILL O F	0210230387	50 30L 50 517
HANNETT, B A	\$210080042*	XPDRTLIC	HELGESON, K. A	8210250012	70-820		HILL. II H		
HANNETT, B A	8210080108	XPORTLIC	HELGESDN:K A	8510590038	70-820		HILLMAN, C R	82101904194	50 613
HANNETT B A	8210080130	XPORTLIC	HELGESON, K A	8210270206	70-820		A CANIN	8210150609 • 8210040184	70 17/
HANNETT, G A	8510080133	XPORTLIC	HELGESON, K. A.	8210270218	70-820	_	HIND, J A	8210080201	50 4,7 50-35
HANNETT, B A	8210270147	XPORTLIC	HELLER, J K	8210170449*	50-255	Q	A LIGNIH	651014072	50 311
HANNETT, B A	B21027016B	XPORTL CC	HELLER, R	8210010047*	50-311	8	HIND, J A	0340400740	
HANNETT, B A	8210280052	XPORTLIC	HELLER, R	8510010153	50-311	8	A L.DAIH	9210190753 921025028A	50-24
HANNETT, B A	8210280054	21JTRO9X	HELLER. R	8210010128*	116-05	S	HIND, J A	8210260374	50-30 50 %-1
HANNETT, B A HARBDUR, J	6210280057*	XPORTLIC	HELLER, R	8210010150*	50-311	5	HINRICHS, O	6210250149	20-541
ט מטטטאאר	8210010254	50~329 G	HELLER, R	8210010192*	50-272	ន	HODBINS, R R	8210120400	AES
HARBOUR. J	8210210393	50-416 C	HELLER, R	8210010239*	116-06	8	HOCH, J B	001010000	
HARDING, M R	8210010115*	50-327 s	HELLER, R	8210010355*	116-02	5	HOCHREITER, L E	8210150159* 8210210054	50-2-5
HARDING, M R	8510040551*	50-327 B	HELLER. R	8210010370*		8	HOCHREITER, L E	8210220154	ALFCS
HARDING, M R	8210130452*	50-327 6	HELLER, R	8210010412*		8	HODGDON, A P	8210040087	ለምቂያ 50-3\ያ
HARDING, H R	8210130579*	50-328 8	HELLER. R	8210010423*	116-05	8	HODODON, A P	8210030088	50 34
HARDING, M R	8210170386*	50-327 B	HELLER, R	8210010461*		8	HODGDON, A. P.	051000001	
HARDING, M R	8510550075*	50-328 5	HELLER, R	8210070248*		8	HODGDON, A P	8210260040 8210260207	10 332
HARDING, M R	8210220085*	50-327 8	HELLER, R	#98E0700158		8	HODGE, S A	8210210034	50 312
HARDING, IS R	#9610590128	50-328 8	HELLER, R	8210070375*		₿	HOFFMAN, D P	9210150146	50-257
HARDING, H R	8210270094*	50-328 S	HELLER, R	8210150066*	50-272	8	HOFFMAN, J C	8510130580	50-211 50-297
HARDINO, H R	8210290279*	50-327 8	HELLER, R	8210150075#		В	HOLLAND, P	DDI ALBARA	
HARDY, J E	8210210037	NUREO	HELLER, R	B210150121*		8	HOLLAND, P	8210130201*	10 247 '
HARDY, J E	8210260206	NUREO	HELLER, R	8210150155*		8	HOLLAND, P	8210250276+ 8210250276+	30-217 1
HARIED, J A	8202020441* 8203250320*	FOIA	HELTENEBIC J	8109100077*	FOIA		HOLMES-RAY, P	8210010327	50 321 1
	8503520350*	FOIA	HELTENES, C J	8111140308*	FOIA		HOLT, J	8310300013	50 247 1
HARMON, D. L.	B210120397	RES	HELTEMES, C J	8112210538*	50-304	8	URIANI P. A		
HARPER, M T	*1900E101ZB	CONTRACT	HELTEKES, C J	8201150003#	FOIA	-	HOMAN, F J	8210060425	RES
HARRINGTON, R M	8210150564	NUREO	HELTEHEBIC J	#1E0050011#	FOIA		HOMAN, F J HONEY, J	8210180407	RES
HARRINGTON. W D	6204160222*	50-293 0	HELTEMES, C J	#18E0900128	FOIA		HOPKINS, J B	8210290259 8210210272	PR
HARRINGTON. W D	8210070080	50-293 P	HELTEMEB, C J	8210070422	50-275	8	HUBRING''I B	8410510515	50 607

NOCHAE VOLLOU HADEV

		5110.1537			**************************************	OUD IEAE					
AU FHOR	ACCESSION NUMBER	SUBJECT	<u>-</u>	AUTHOR	ACCESSION NUMBER	SUBJECT		AUTHOR	ACCESSION NUMBER	SUBJECT	•
MANG. Y MANG. J MANG. Y MANG. Y MANG. Y MANG. Y	8210080165* 8210080172* 8210090006* 8210050010* 8210080158	GEN TEC IS GEN TEC IS FOIA FOIA GEN TEC IS	3	IMBRO, E V IMBRO, E V IPPOLITO, T IPPOLITO, T A IPPOLITO, T A	8210130065 8210190009 8210070139* 8206070250* 8209210383*		0	7044204'8 D 7044204'8 D 7044204'8 D 7044204'8 D	8210060213 8210120078 8210130146 8210180186 8210190604	50-255 5 50-255 6 50-255 5 50-255 5	3
WAME, Y S WOMEEK, W G WENTON, R L WOSOIT, C R	8210080169 8210190419* 8201200662* 8210270052* 8210270056*	50-241 50-537		A T.OFILTORI A T.OFILTORI A E.YERI J. B.YERI J. B.YERI J. B.YERI	8210070121* 8210080002* 8209300175* 8210130438* 8210130569*	50-244 50-237 50-259 50-259 50-259	5 5	JOHNSON, 8 D JOHNSON, 8 D JOHNSON, 8 D JOHNSON, 8 D JOHNSON, 8 D	8210190620 8210190639 8210220186 8210260183* 8210280107	50-255 S	•
Pudson. S D Puffmara G H Puffmara G H Puggins T Pudafs. A	8210070350# 8210010159# 8210220461# 8210280321# 8210040357#	50-335	3 3 3	IRBY.B J IRWIN.D P ISABELLE.L D ISHII.M ISLEY.T	8210290232* 8210200036 8210290267 8210150556 8210170261*	50-296 50-322 50-247 NUREQ 50-346	8 0 5 8	JOHNSON.C E JOHNSON.C E JOHNSON.C R JOHNSON.C R	8210250276 8208290084 8210190452* 8210280448 8210290155		3 A D
POCHES, P G NOPILL.H D NOPILL.H D NOPILL.H D NOPILL.H D	8210220056* 8210050113 8210050196 8210060228 8210070372	50-289 50-289 50-289		JABBOUR.K N JABBOUR.K N JABBOUR.K N JACK.R A JACKIN.I	8210190071 8210220026 8210260065 8210260582* 8210190694*	50-413 50-413 50-413 50-201 50-373	A A V G G	JOHNSON, D F JOHNSON, G E JOHNSON, G E JOHNSON, G E JOHNSON, G E	8210010225* 8210040121* 8210040015 8210040017 8210040023	50-304 50-440 50-440	0 0 0
UNILL.H D LEATLL.H D UNILL.H D UNILL.H D UNILL.H D	8210080043 8210080308 8210130206 8210130210* 8210130248	50-289 (50-289 (50-289 (3 3 3 3 3	JACKIN, I N JACKIN, I N JACKSON, L H JACKSON, L H	8210060335* 8210170601* 8210170626* 8210010350* 8210150132*	50-10 50-373 50-295 50-324 50-324	6 0 0 0 0	JOHNSON, G E JOHNSON, G E JOHNSON, G E JOHNSON, G E JOHNSON, G E	8210060191 8210170377 8210200071 8210210197 8210210197=	50-440 50-413 50-413	0 0 0
OPILE.H D CPICE.H D CPICE.H D OAIEL.H D OPILE.H D	8210130515 8210130548 8210150202 8210250097* 8210260499	50-287 50-287 50-219	3 3 3 7	JACKSON.L H JACOBI.W JACOBS.A JACOBS.A JACOBS.A	8210220307* 8210120379 8210050501 8210050516 8210150328	50-321 HASTE MG1 CONTRACT CONTRACT	τ	JOHNBON, Q E JOHNBON, Q E JOHNBON, J JOHNBON, J H JOHNBON, J H	8210250370 8210270002 8210270010 6210150017* 8210240232	50~413 50~413 50~293	0 0 0 0 T
OLMAN, L G ULMAN, L G ULMAN, L G ULIMER, M M UNVICUIT, D M	6203050073* 6203220512* 6210290405 6210190362* 6210050397*	50~537 50~245 50~331		JACOBS, A JACOBS, A JACOBS, A JACOBS, A JACOBS, A	8210180357 8210180414 8210190003 8210190132 8210210041	CONTRACT 50-201 CONTRACT CONTRACT CONTRACT	P	JOHNSON, J L JOHNSON, R A JOHNSON, R A JOHNSON, R A JOHNSON, W 0	8210130315* 8210130054* 8210170141* 8210170162* 8210260474	CONTRACT CONTRACT CONTRACT	A 8
CHICOTT, B M WHICOTT, B M KHICOTT, B M CHICOTT, B M CHICOTT, B M	8210170347* 8210170452* 8210170515* 8210170537* 8210170508*	50-382 50-313 50-285	3 3 3 3	JACOBS.A JACOBS.A JACOBS.H R JACOBS.J L JACOBS.R H	8210260282 8210270399 8210260230* 8210010434* 8210120043	CONTRACT CONTRACT 50-72 40-1202 50-289	R P	O NOTENHOU W NOTENHOU V W NOTENHOU V W NOTENHOU V W NOTENHOU	8210060345* 8210120125 8202170310* 8203110403* 8205280532*	NUREQ 50-244 50-244	G P P O
ULNICUTT, D M UNSTAD, A A UNSTAD, A A UNSTAD, A A UNSTAD, A A	6210190776* 6210130533* 6210150390* 8210190745* 8210250163*	50-282 50-282 50-306	3 3 3 3 3	JACOBS.R H JAFFE, D JAFFE, D H JAFFE, D H JAFFE, D H	8210270162 8210120139* 8210070104 8210070125* 8210200108	50-289 50-317 50-317 50-317 50-317	Р F P P	JOHNSTON, U V JONES, B W JONES, B W JONES, C R	8205280533* 8210010064 8210040097 8210060183 8210260217	50-537 50-275 50-537	P Q Q Q
UNSTABLA A UNF.M D UNT.M D UNTER D UNTER,R S	8210250376* 8210010462* 8210220189* 8210170627 8210010362	50-390 50-438 50-358	3 3 5 5	JANUSKA.A O JANUSKA.D JANUSKA.D JAFFE.D H	8210290412 8210120466 8210280030 8210040208# 8210150543#	50-317 RES XPORTLIC 50-331 50-10	Р О	JONES, D L JONES, J A JONES, J A JONES, J A JONES, J A	8210270009* 8210010317* 8006170030* 8210010028 8210180116*	70-143 FOIA	G H
UNTER.R S UNTER.R S UNTER.R S UNTER.R S UNTER.R S	8210050138 8210050159 8210050211 8210050349 8210060256*	50-315 50-316 50-315	2 2 3 3	Jape. F Jape. F Jape. F Jape. F Jape. F	8210010151* 8210010176* 8210010208* 8210010240* 8210010432*	50-416 50-261 50-348 50-321 50-257	0 0 0 0	JONES, J A JONES, J K JONES, L H JONES, R A	0210180353* 8210170177* 9210150004* 6210260211 6210040030*	NUREO	8
UNTER.R S UNTER.R S UNTER.R S UNTER.R S URREY.K C	8210190676 8210220393 8210220478 8210250228 8210180371*	50~315 50-315	3 5 5	JAPE. F JAPE. F JAPE. F JAPE. F JAPE. F	8210010459* 8210010472* 8210150062* 8210150143* 8210150269*	50-369 50-395 50-370 50-269 50-389	0 0 0 0	JONES, R A JONES, S Z JONES, S Z JONES, W C	8210180008* 8210120527 8210120628 8210210527 8209170051	40-8102 40-6659 40-6659	K F
JAT.D JAT.O JAT.O JAT.O JAT.O	8210070039# 8210070043# 8210070047# 8210070050# 8210070053#	50-537 1 50-537 1 50-537 1	A D D D	JAPE, F JAPE, F JAU, W C JENKINS, O R JENKINS, G R	8210220147* 8210220337* 8210050412 8210010159* 8210150021*	50-324 50-370 NUREG 50-335 50-369	Q Q Q	TONES'N C TONES'N C TONES'N C TONES'N C	8210040184 8210050247 8210050301 8210060196 8210070333*	50-265 50-265	8 9 9 0
JSEBY.D E JSEBY.D E JSEBY.D E JTTON.J W JTTON.P H	6210170276* 6210270273* 6210260267* 8210070133 6210060322	50-317 50-317	8 9 7	JENKINS, OR JENKINS, OR JENKINS, OR JENNINGS, RT JENS, WH	8210150025* 8210150401* 8210220461* 8210130358* 8210130282	50-349 50-241 50-338 50-317 PR	Q Q C S	JONES, U C JONES, U C JONES, U C JORDAN, E JORDAN, E L	8210130570 8210190736 8210200077 8210080213* 8101050528	50-265	8 R P
PATONIS, A MATONIS, A MESO, V MAD, E MESO, E	8210190447 8210190453 8207180037 8104100203* 8107300148*	50-269 50-483 50-313	3 3 5 6 6	DENSEN, J NERNAHDL JURANSEN, J JURANSEN, J JURASEN, W JURASEN, W JURASEN, W JURASEN, W JURASEN, W JURASEN, W JURASEN, W JURASEN, J	8210270075* 8210260345* 8210290241* 8210010426* 8210060227*	50-289 40-8610 70-33 40-1202 70-7	Q	JORDAN, E L. JORDAN, E L. JORDAN, E L JORDAN, E L JORDAN, E L	8105040420* 8105280476* 8108210025* 8210080187* 8210150592	50-352 50-263 F01A F01A NUREG	Q Q
1980. E 1980. E 1980. E 1980. E 1980. E V	8112010310* 8210070416 8210080018 8210080028 8203120016*	50-324 50-336 50-368	5 5 5 6 6 8	JOHNSON, A H JOHNSON, A H JOHNSON, A H JOHNSON, A R JOHNSON, B	8210010459* 8210150062* 8210220337* 8210190761* 8210040346*	50-369 50-370 50-370 64979 50-537	G G A	JORDAN, H JORDAN, M JORDAN, M JORDAN, M J JORDAN, W 8	8210210014 8210050182 8210050353 8210150538* 8210200026	NUREQ 50-263 50-407 50-10 50-443	8 8 0
19RO.E V 19RO.E V 19RO.E V 19RO.E V 19RO.E V	8203290028 * 8203290031 * 8210060430 * 8210070425 8210080017	50-293 50-336 50-335		JOHNBON, B JOHNBON, B JOHNBON, B JOHNBON, B JOHNBON, B D	8210040349* 8210040351* 8210210274 8210050265 8210050302	50-537 50-537 50-454 50-255 50-255	A Q P P	Jordan, W 8 Jordan, W, 8 Jordan, W 8 Jordan, W 8 Jordan, W 8	8210200024 8210200035* 8210200035* 8210200042* 8210200042*	50-443 50-443 50-443 50-443	00000
1											

AUTHOR	ACCESSION NUMBER	SUBJE		AUTHOR	ACCESSION NUMBER	SUBJ CATE		AUTHOR	ACCESSION	
JORDAN,W S JORDAN,W 5 JORGENSEN,B L JORGENSEN,B L JUDD,B R	8210200049 8210200049 8210190449 8210190707 8210150548	* 50-443 * 50-255 * 50-255 NUREG	G G	KEISER, H W KEISER, H W KEISER, H W KEISER, H W KEISER, H W	8210040084 8210040118 8210130352 8210130363 8210130377	50-38 50-38 50-38 50-38 50-38	7 S 7 S 7 S 7 S	KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D	8210180243 8210180243 8210180255 8210180378 8210190056 8210210026	50-387 ± 50-441 ± 50-387 •
JULIAN, C JULIAN, C JULIAN, C JULIAN, C JULIAN, C	92100102066 92100102255 92100103466 92102203296 9210190376	50-338 50-250 50-250 50-251	Ġ	KEISER, H W KEISER, H W KEISER, H W KEISER, H W KEISER, H W	8210210285 8210210433 8210210440 8210250347 8210250357	50~38; 50~38; 50~38; 50~38;	7 5 7 8 7 S	KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D	8210210028 8210210317 8210210500 8210270006 8210270324	50-389 (50-382 (50-5-9 (
JULIAN.C A JUNGE.M A JUNGE.M A JUNGE.M A JUNGE.M A JUSTUS.P S KACICH.R M	8210220303+ 8210040069+ 8210040219+ 8210130578+ 8210120351	50-318 50-318 50-317 WASTE		KEISER, H W KEISER, H H KEISER, H H KEISER, H H KEITH, H N	8210250369 8210250381 8210260509 8210260215 8210040332*	50-387 50-387 50-387 50-387	7 S 7 S 7 S	KERRIGAN, J D KERRIGAN, J D KESSLER, J KETZLACH, N KEY, W J	8210270339 8210280416 8210200019 8210290392 8210130557	50-3 ₉ 50-5 50-24 70-26
KACICH.R M KADAMBI.N P KADAMBI.N P KADAMBI.N P KAEFER.W B	8210130326 8210130326 8210150647 8210210258 8210210312	50-10 50-10 50-400 50-400 50-400	P A A A	MEITH, H N KELLER, H T KELLEY, D L KELLEY, J L KELLEY, J L	8210240292* 8210270208* 8210070369* 8210050247 8210060184		3 P 5 Q	KIEL, R L KINDER, E T KING, M KINGSLEY, O D KINGSLEY, O D	92102605610 9210250307 9210260215 9210090294 9210090294	CONTRI 50-64; NUSEO TOFFER TOFFER
KAHLE.J B KAHLE.J B KAISER.G D KAISER.W T	821021022# 8210010127# 8210150136# 8210210306# 8210170427#	50-275 70-1201 70~824 50-329 50-282	S A P	KELLY, J A F KELLY, J A F KELLY, J J KELLY, J H	8210010307 8210010178* 8210240301* 8210040145 8210220497	PR 50-313 50-298 50-247 70-27	l ĝ	D L MAMBUNIA D L MAMBUNIA D L MAMBUNIA D L MAMBUNIA D L MAMBUNIA	8210010418 8210060225 8210060227* 8210260341 8210260345*	40 LE 70-7 70-7 40-8±.
KALEEL,R J KALIVIANAKIS,N KALIVIANAKIS,N KALIVIANAKIS,N KALIVIANAKIS,N	8210050418 6210040395 8210120551* 8210130192 8210130251	NUREQ 50-254 50-254 50-254 50-254	9 F S	KELLY, J W KELMERS, A D KEMPER, J S KEMPER, J S KEMPER, J S	8210270232 8210150564 8210040224 8210040362 8210220374*	70-27 NUREG 50-352 50-352 50-352	A	KINNEMAN, J D KINNEMAN, J M KINNEY, W W KINTNER, L KIPER, K L	8210290241* 8210010426* 8210290304* 8210120026 8210080313	70-33 40-12 50-164 50-341 50-454
KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N	8210130324 8210130386 9210130413 8210130466 8210130501	50-254 50-254 50-254 50-254 50-254	5 5 5	KEMPKA,S N KENNEDY,D M KENNEDY,R T KENNEDY,R T KENNEDY,R T	821015057; 8210130138 8210010099* 8210010105* 8210070448*	NUREG 50-255 50-366 50-366 FOIA	R S 8	KIRK. G B KIRSCH. D F KIRSCH. D F KIRSCH, D F KIRSCH, D F	8210270074+ 6210060124+ 6210060269+ 8210190250 6210190501+	50-328 50-342 50-334 50-351
KALIVIANAKIS, N KALIVIANAKIS, N KALMAN, K L KAMATH, P S KAMMER, D S	8210190658 8210250148 8210040344 8210050360 8210010135*	50-254 50-254 40-8697 NUREG 50-327	s s g	KENYY, T J KENYON, B D KENYON, B D KENYON, B D KENYON, B D	8210070216# 8210060391 8210080142 8210080146# 8210210417	50-286 50-387 50-387 50-387 50-387	Ф Р Р	KIRSCH, D F KIRSHEN, A H KIBTER, H KISTER, H KISTER, H	8210280303+ 8210040244 8210010007 8210040044+ 8210070214+	50-361 50-275 50-765 50-260 50-247
KAMMER.DS KAMMER.DS KAMMER.DS KAMMER.DS KAMMER.DS	8210010197* 8210010420* 8210250236 8210250244 8210260148	50-438 50-518 50-259 50-250 50-327	0 F F P	KENYON, B D KENYON, B D KENYON, T J KEPPLER, J O KEPPLER, J O	8210260350 8210290230 8210190084 8011060565* 8209160503	50-387 50-387 50-390 50-254 50-295	P A S	KISTER.H KISTER.H D KISTER.H B KISTER.H B KLEINSORGE,W P	8210210307* 8210070350* 8210210115* 8210270173*	50-284 50-217 50-223 50-333 50-244
KAMMER.D S KAMMERER.G KANE.R S KANE.U F KANE.W F	B210260228 B210070454# B210050341 B210080309 8210290136*	50-327 F01A 50-179 50-395 50-387	P P P	KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	8209270242 8210050105 8210050107* 8210050186 8210050194*	50-358 50-295 50-295 50-266 50-266	H Q Q	KLINE, J R KLINE, J R KLINE, J R KLINE, J R KMETYK, L N	8210010091# 8210050251 8210070137 8210130333 8210210476	50-400 50-245 50-440 50-440 50-440
KANEN, A C KANGA, B K KANGA, B K KANGA, B K KANGA, B K	8210260232 8210040200 8210070220 8210070226 8210070365	50-322 50-320 50-320 50-320 50-320	T P R P	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8210040253 8210080194 8210130184 8210130400 8210130403*	50-315 50-315 50-341 50-409 50-409	0 P 0 0	KNIGHT, J P KNOLL, F J KNOP, R KNOP, R C KNOP, R C	8210050397 8210270202 8210170637 8210130221	NUMES 50-264 50-264 50-461 50-546
KANGA, B K KANGA, B K KANGA, B K KANGA, B K	9210130583 9210150043 8210150085 8210190570 9210200012	50-320 50-320 50-320 50-320 50-320	P P P P	KEPPLER, J O KEPPLER, J O KEPPLER, J G KEPPLER, J G KEPPLER, J G	8210130451 8210130459* 8210130547 8210150487 8210190532	50~461 50~461 50~461 50~254 50~305	9 9	KNOP.R C KNOX.J KNUTH, D F KNUTH, D F KNUTH, L J	8210280174* 8210120128 8210120128 8207050005* 8210130399	50-441 50-441 50-443 PR PR
KANGA, B K KAPLAN, C KATAOKA, I KAUCHER, J E KAUCHER, J E	8210260236* 8210180138 8210150556 8208190178* 8208190290*	50-320 50-247 NURE0 50-213 50-302	0 0 P P	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8210190635 8210190699 8210190763 8210190771* 8210250312	50-358 50-255 50-440 50-440 50-395	0 0 0 0 F	KOCH, L J KOCH, L J KOEBEL, C KOESTER, O L KOESTER, O L	8210050183 8210130325 8210130470 8210120066* 8210040364	50-461 50-461 50-461 FOIA 50-482
KAVANAUOH, P F KAY, D KAY, J KAY, J A	8210120471* 8210190744* 8210190346* 8210130401 8210150363	CONTRACT 50-373 50-373 50-29 50-29	8 6 0 P	KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J G	9210250320 9210260179 9210240198 9210240204 9210260371	50-243 50-255 50-243 50-441 50-409	P P F A	KOESTER, O L KOESTER, O L KOLBE, R KOLTAY, P KOLTAY, P	8210120199 8210130399 8210220403 8210130552 821004046*	PR PR NUREG 50-217
KAYANABIN C KEAMER, W H KEARNEY, B KEARNEY, J KECKEISEN, T	8210250097* 8210180229* 8210270054 8210130282 8210260353*	50-219 FOIA 40-2259 PR 50-260	P S	KEPPLER, J Q KEPPLER, J G KEPPLER, J, G KEPPLER, P	8210280170 8210280174* 8210280174* 8210280174* 8210290330 8210250035	50-461 50-461 50-461 50-358 40-8820	G G A	KONKLIN, J E KONG, Y H KONG, K H	8210210307± 8210210160+ 8210280201± 8210130222+ 8210130529+	50-247 50-335 50-277 50-545 50-493
KEDDIS, N N KEIMIG KEIMIG, R KEIMIG, R	8210270124 8210130405 8210290366 8210220447 8210260483		A 8 8 6	KERCH, H W KERR, V B KERRIGAN, J KERRIGAN, J KERRIGAN, J	8210290093* 8210050466 8210010229* 8210050393	50-322 50-320 50-361 50-443 50-361	G P A P	KONKLIN, J E KOON, A R KORNEGAY, F C KOT, C A KOUTS, H	9210150564 8210150597 8207180066	50-341 4 50-395 F NUREQ NUREQ ACRS
KEIMIO,R R KEIMIO,R R KEISER,H W KEISER,H W KEISER,H W	8210070240* 8210290304* 8210010177 8210010228 8210010393	50-367 50-367	0 8 8	Kerr Igan, J Kerr Igan, J Kerr Igan, J Kerr Igan, J. D	8210130573* 8210210035 8210010037 8210120025 8210180237	50-361 50-400 50-400 50-528 50-389	PAFAE	KOUTS, H KOVACK, T S KRATZER, M B KRAVSE, D KREGER, H E KREGER, W, E	8210280354* 8210070498* 8210040203* 8108270422*	ACRS 50-25% / FOIA 50-313 \$ 50-261 ! 50-266 !
				nenn aumme u - D	₩2101 80237	50-389	E			

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUFHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PEGER, W E	8112020885*	50-324 P	LAINAS, C C	8210210553*	50-346 P	LEASBURG, R H	8210120258	50-280 P
. ⇒EGER W E	8112300287*	50-324 P	LAINAS, O C	8210290118	TOPREP	LEASBURG R H	8210120265	50~280 P
PREGER, W E	8201150176* 8201200658*	50-537 D 50-241 P	LAINAS, G C	8210290450	ORG	LEASBURG,R H	8210120297	50-280 P
•≈ EGER, W E	82102/0338	NUREG	LAINAS, G C LAINAS, G C	8210290453 8210290458	TOPREP TOPREP	LEASOURG, R H	8210130112*	50-338 F
→F走IN, If 5	6210270000	HONES	ERITAS, G C	0210270450	JUNKER	LEASBURG, R H	8210130427	50-280 G
FFESIT S	8210120653	RES	LAIRD, R C	8210040163*	50-220 P	LEASBURG, R H	8210190321	50-339 P
3 9.EU3 4	8210130284	50-341 F	LAMP. M S	8510070313*	50-316 8	LEASBURG R H	8210200043	50-280 P
## IEGER. R H	8210080093	50-206 P 50-206 P	LANCASTER, B T	8210040033#	50~445 Q	LEASBURG R H	8210220011	50-338 P
AR FEUFR, R W	8210240214 8210260272	50-206 P 50-206 P	LANDGRAF,L C LANDGRAF,L C	8210010287 8210010287	50-341 K 50-341 K	LEASBURG, R H	8210220170	50-200 P
PREGER. R W	551050000	30-E00 /	EMMOGRAFIE C	9510010584	30-341 K	LEASBURG, R H	8210220178	50-280 P
PAINAR W	8210070075	50~440 0	LANDIS, K D	8210190376	50-251 5	LEASBURG, R H	8210220200	50-33B Q
P F POST S	8510130191	50-289 F	LANDSMAN,R B	8210050154*	50-329 Q	LEASBURG R H	8210220373	PR
U S PMIG	6210130320	50-289 F	LANDSMAN, R D	8210190750+	50-329 0	LEASBURG, R H	821025020B	50-338 F
FRIMM R N	6210130430 6210220147*	50-387 F 50-324 0	LANGER, R R	8210180430*	FOIA	LEASBURO, R H	8510590133	50-338 P
PAUS H E	R5105501474	30-324 0	LANGER, R R	0210160434*	FOIA	LEASBURG, R H	8210270160	50-338 P
PUBLINAK R A	8210290249	PR	LANIK, O	8011060561	50~254 8	LEASSURG.R H	8210270204	50-338 P
FUC ZYNERI, L A	8210010402*	50-387 5	LANIK, O	8210040082*	50-296 S	LEASBURG, R H	8210270256	50-338 P
PUCZYMEPI, L A	8210040088#	50-387 5	LANIK, Q	8210070438	50-219 8	LEASBURG. R H	8210280130	50-280 P
N U PANJENA	8210120342*	CONTRACT	LANIK.O F	8110230085*	50-219 8	LEASBURG. R H	9510580599	50-280 P
ALLERY MASSIL J. P.	8210120423*	M 98E-06	LANNING, H	8112100374*	FOIA	LEASER, J D	8207090224*	50-278 P
PURITA P H	8210080352	RES	LANNING, H	8202120236*	50-272 6	LECLAIR, D E	8210170004*	CONTRACT
FUESINER N L	8210210321*	50-309 G	LANNING, W D	8012270118	50-302 8	LEDDICK, R S	#210070161*	50~508 Q
+ HEUPEUX, R W	02101305/8*	50-317 S	LANYING H D	8107140079*	90-260 S	LEE. B S	8210120459	RES
L V TABNI	B2(0)8034H*	CONTRACT	TANHING! M D	*PB00501118	50-313 B	LEE.L S	8207290410	NUREG
ACE: N J	8210240129*	50~334 F	TANNING! H D	8205030617#	50-247 B	LEE. N	8210210054	NUREG
LACEY IN S	B210040045	50-334 S	LANIMING, H D	8205030619*	50-247 S	LEE, N	8210220154	NUREO
LACEYIN S	B2101901B5	50-334 E	LANHING, H D	8205190428*	50-327 S	LEE, D R	8210250083	50-267 F
LHCEY.U S	8210150179	50-334 8	LANKING, H D	8205190441*	50~327 S	LEE, O R	8210270104	50-267 P
L-CEWH S	8210150201*	50-334 S	LANHING, II D	8209150106#	50-261 P	LEE. O R	B210270113*	50~267 P
tacerall S	8210190274	50-334 B	CANHING W D	8210070104	50-313 6	LEE, T D	8210150204*	70-143
LACELLUS	8210190282*	50-334 S	LAMMING: N D	8210070490	50-260 S	LEECH. P	8210010082*	50-537 Q
CACES IN S	8510510009	50 - 334 S	CANNING, H D	8510150150	50-334 P	LEIGH, D N	8210010440*	40-1202
LACES H S	8210210065	50-334 B	LANNING W D	8210120182	50-295 6	LE [KEN. L	8210200057	70-143
LACETINE	8210260163 8210260203	50-334 8 50-334 S	LANPHER, L C	8210050383	50-322 0	LETKEN. L	8210250040	70~143
LACEY. (1 S	9510500807	30-334 5	LANPHER. L C	8210050383	50-322 0	LEMPGES, T E	8210010165*	50-220 G
LHCE1.H 5	8210240478	50-334 S	LANPHER L C	8510500037	50-322 ¢	LEMPGES, T E	8210010287*	50-220 4
LACEY H 5	8210260487*	50-334 S 50-334 S	LAMPHER, L C	8210200076	50~322 G	LEMPOES, T E	8210040182	50-220 P
LHCEY H S	8210280271 8210280280	50-334 S 50-334 S	LANPHER, L C	8210200074	50-322 G 50-322 G	LEMPGES, T E	8210050148	50-220 F
LHCEY.N 5	8210280307	50-334 B	LANPHER: L C LANPHER: L C	8210200083*	50-322 G 50-322 G	LEMPGES, T E	8510090508*	50-220 Q
LACEN.II S	8510550307	30 351 5	CARAGRIC C	051050000-	JU-322 U	LEMPGES. T E	8210040284	50-220 S
LADUMIR	8210290241*	70-33	LANPHER, L C	8210200089*	90-322 G	LEMPGES, T E	8210130347	50-220 R
H M.TRAGEAL	BZ102503B3	50-219 F	LARPHER, L C	8210200089*	50~322 G	Lempges. T e	8210260184*	50-220 0
LAGIENSKI, J 5	8210040144*	50-317 B 50-317 S	LANSFORD, R A	8210040042*	50-445 0	LEMPGES, T E	8210280144	50-220 P
LAGIENSKI J S	8210130465* 8210270269*	50-317 B	LARSON, C E LARSON, C E	0210150255* 0210190439*	50-292 G 50-292 G	LENTINE, F G	8210050207	50~295 F
Lag 1 en en 1 J	85105705074	50-317 6	TWEDTH' F E	8510170437×	30-505 a	LENTINE, F Q	8210050270	50-295 P
LAGIENSKI, J S	8210270273*	50-317 S	LARSON, T K	8210150409	RES	LENTINE, F 0	8210080111	50-275 P
(AGIENSKI, J S	8210280141#	50-318 8	LASHER, C. E	8207120253*	50-447 A	LENTINE, F 0	8210220399	50-275 P
LAI NAS. G	8105190008* 8011120579	FOIA 50-247 P	LASOTA, J	8210150474 8210150560	50-528 0 NUREG	LEG, F A	8210190167*	CONTRACT
141745. G C	B103120107*	20-321 B	LASSAHN, O D LASSAHN, G D	8210280339	RES	LESSY, R P	8210050075	27-39
(Alfias, C C	PIOPIEGIO/*	99-9E+ D	CHOSHING D	2510200337	Hea.	LESSY, R P	8210190370	50-312 G
LATHABLE C	B103240292#	FOIA	LASUA.S R	9210040130	I &E	LEVINE, J H	8210050346	50-366 8
LA (J) L+B+D+C	0103310127*	FOIA	LATHAM, S. D.	82101903094	50-322 0	LEWIS D F	8210130505#	50-329 T
LAINIAS G C	B106150555* B203170034*	50-302 S F01A	LATHAM, S B LATHAM, S B	9210150337# 9210150351#	50-322 G 50-32 2 G	LEWIS, D. F.	8210130505#	50-329 T
laimas, g c Laimas, g c	B210040411*	FOIA	LATHAM, B B	8210150365*	50-322 0	LEWIS, H D LEWIS, H I	8210260442	50-397 A
CHTISHING A	UK - UNIVIO - + 1		Entinity & M	~~ • ~ 1 5 6 6 6 5 7	30 4 0	CEMIQIII I		

LEUSONAL AO LUOK INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AU THOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	513 E
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8210150027* 8210150034* 8210150036 8210150040* 8210150048*	50-416 50-324 50-324 50-324 50-324	0 0 0 0	LINNEMANN, R E LINVILLE, J C LIPINSKI, D R LIPINSKI, R LIPPOLD, W J	8210190178 8210210115 8210210196 8210190601 8210190601	50-333 Q 50-245 Q	LOWENBERO, H LOWENBERO, H LOWENBERO, H LOWENBERO, H LOWENBERO, H	8210010079* 8210070086* 8210070089* 8210070099* 8210070098*	50-537 . 50-5-7 50-5-7
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8210150100 8210150113* 8210150171 8210150189* 8210150225	50-324 50-324 50-438 50-438 50-327	0 0 0 0	LITERSKI,L A LITTLE,B H LITTLE,M LITTLE,M LITTLE,M	8209290225* 8210250080* 8210040003 8210120414 8210120490	50-10 F 50-341 G CONTRACT CONTRACT CONTRACT	LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H	8210070101 ± 82100701193 ± 8210070123 ± 8210070124 ± 8210070128 ±	50-51", 50-517 50-51"
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	9210150237* 9210150260* 9210150278* 9210150384 9210150394	50-390 50-416	0 0 0 0	LITTLE, M LITTLE, M LITTLE, H LITTLE, M	8210120510 8210120534 8210120549 8210120607 8210130058	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	Lowenberg, H Lowenberg, H Lowenberg, H Lowenberg, H Lowenberg, H	8210070131+ 8210070134+ 8210070139+ 8210070142+ 8210070146+	
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8210220127 8210220137* 8210220237 8210220277 8210220272*	50-400 50-438 50-321 50-321	9 9 9 9	LITTLE, M LITTLE, M LITTLE, M LITTLE, H LITTLE, B	8210130071 8210180345 8210180375 8210180411 8210190210	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	LOWENBERO, H LOWENBERO, H LOWENBERO, H LOWENBERO, H LOWENBERO, H	8210070148* 6210070151* 8210070154* 821007015/*	50-501 50-501 50-501 50-501 50-501
FEMIS'S C FEMIS'S C FEMIS'S C FEMIS'S C	52 0220296 52 0220310* 62 0220469 62 0220495 52 0220500*	50-250 50-327 50-261	Q Q Q Q	Little, M Liftle, M Little, M Little, M Little, W Little, W	6210210147 8210210502 8210260516 8210260525 8210260305	CONTRACT CONTRACT CONTRACT CONTRACT 50-440 Q	LOWENDERG, H LOWENDERG, H LOWENDERG, H LOWENDERG, H LOWENDERG, H	8210070166* 8210070170* 8210070170* 8210070186* 8210070190*	50-131 50-131 50-131 50-131 50-53
LEHIS,R C LEHIS,R C LEHIS,R C LEHIS,R C LEHIS,R C	8210240309 8210240370 8210240374 8210240310* 8210270229	50-302 50-335 50-335	0 0 0 0 0	L	6210040329 8210040379 8210130368 8210190589 8210190617	50-10 0 50-373 0 50-341 0 50-373 0 50-275 0	LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H	8210070195# 8210070200# 8210070202# 8210070204# 8210070207#	50-531 50-531 50-531 50-537
LENIS, 5 H LENIS, 5 H LEWIS, 5 H LIAW, C Y LICITRA, E A	8210040017 8210040021 8210040022 8205250020* 8210130053	50-320 50-367 50-155	0 0 0 P A	LITTLE, H S LITTLE, N S LITTLE, H S LIU, L LIVERMORE, H	8210190619 8210190669 8210190682 8210130509 8210190633	50-440 A 50-266 G 50-373 G 50-331 P 50-461 S	Lowenberg, H Lowenberg, H Lowenberg, H Lowenberg, H Lowenberg, H	9210070222+ 9210070223+ 9210070225+ 9210070251+ 9210070259+	50 53* 50-53; 50-53; 50-53; 50-53;
LICITRA,E A LIDEN,E A LIDEN,E A LIDEN,E A LIEDERMAN,E	8210210320 8210160009 8210190507 8210220275 6210150188*	50-272 50-272 50-272	A P P P T	LIVERMORE, H H LIVERMORE, H H LO, R LO, T LO, T	B210130557* 8210250232* B210050537 B205250010* 8207300222*	50-461 Q 50-461 Q 50-320 P 50-155 P 50-206 P	LOWENBERO, H LOWENBERO, H LOWENBERO, H LOWENBERO, H LOWENBERO, H	8210070260+ 8210070262+ 8210070264+ 8210070264+ 8210070269+	50 501 50-507 50-507 50-507 50-507
LIEBERMAN, E LIEBERMAN, E LIEBERMAN, E LIEBERMAN, J	821015018B* 8210150204* 8210150240* 8210150240* 8208260424	50-322 50-322 50-322	T T T Q	LOBEL.R LOCHSTET.N A LOCKE.R F LOCKE.R F LOCKE.R F	8103050756* 8210130487 8210060220 8210250192 8210250196*	FOIA 50-413 D 50-275 G 50-133 R 50-133 R	LOWENDERO, H LOWENBERO, H LOWENBERO, H LOWENBERG, H LOWENBERG, H	8210070273* 6210070274* 8210070280* 8210070285*	50-517 50-517 50-537 50-537 50-537
LIHDU, H LIHDU, H LIHDU, H LIHDU, H	8210130253* 8210130473* 821013051[* 8210250153* 8210150557	50-254 S	8 8 8	LOFTUS, M J LOFTUS, M J LOFY, R A LOGSDON, M J LOMBARDO, J J	8210210054 8210220154 8210260280* 8210040338 8210250284	NUREO NUREO CONTRACT 40-8502 50-217 P	LOHENDERO, H LOWENDERO, H LOWENDERG, H LOYSEN, P LUBENAU, J O	8210070291+ 8210070293+ 8210070298+ 8210120299+ 8012180342+	50-537 53-537 50-537 50-257 FOIA
LINDER, E A LINDER, F LINDER, F LINDER, F LINDER, F	8210270136 8210010389 8210040152 8210050067 8210050339	50-272 F 50-409 F 50-409 F 50-409 F		LONG.A B LONG.D J LONG.F J LONG.F L LONG.J #	8210120397 8207050085 8210010174# 8210220180 8210180137*	RES 50-247 P 50-324 Q 50-438 Q 50-344 S	LUBENAU, J O LUDWIG. P G LUEBKE, E A LUEIT, W LUKENS, L L	8210120018+ 8210130465+ 8210250223 8210060252+ 8210250033+	F014 50-317 50-142 50 373 NURES
LINDER, F LINDER, F LINDER, F LINDER, F	8210130365 8210150203 8210150446 8210150448 8210150454#	50-409 F 50-409 F 50-409 F 50-409 G	; ;	LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8210250097* 8209300353 8210040147 8210040251 8210040304	50-219 P 50-537 B 50-537 A 50-537 A 50-537 A	LUNDELL.B E LUNDVALL.A E LUNDVALL.A E LUNDVALL.A E LUNDVALL.A E	8210240059* 8210070159 8210130103* 8210130338 8210130391	40 8 % 1 50-317 : 50-317 : 50-317 P
Linder, F Linder, F Linder, F Linder, F	6210220009 6210220174 6210230349 6210240319 6210280046*	50-409 U 50-409 G 50-409 F 50-409 F	<u>.</u>	LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8210060217 8210060249 8210130246 8210130249 8210130311	50-537 A 50-537 A 50-537 B 50-537 A 50-537 A	LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUTKEHAUS, T C	9210180005 8210180124 8210190803* 8210220376 8210190677	50-317 1 50-317 1 50-317 1 50-318 7 50-322 1
LINDER, F LINDER, F LINDER, F LINDER, F LINDEY, I D	8210250051* 8210250055* 8210250151 8210250307 8210150462	50-409 F 50-409 F 50-409 P 50-409 P 50-416 G		LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8210150186 8210210022 8210210273 8210260168 8210260302	50-537 A 50-537 A 50-537 A 50-537 A 50-537 A	LYNCH, M D LYNCH, M D LYNCH, M D LYDNS, J E LYDNS, J E	8210010380 8210220463 8210220468 82022403974 8203020267*	50-447 # 50-447 # 50-447 # 50-244 P 50-246 #
Linehan, J J Linehan, J J Linehan, J J Linehan, J J Linehan, J J	8210040338 8210040344 8210040348 8210040365 8210120479	40-8502 40-8697 40-8793 40-8769 40-8786		LONGENECKER, J LONGSINE, D E LOGKABAUGH, A L LOGKABAUGH, A L LOGMIS, O O	8210260401 8210290399 8210210159* 8210210159* 8210150421	50-537 A RES 50-382 G 50-382 G RES	LYONS, J E LYONS, J E LYONS, J E LYONS, J E	8203040502* 8203100393* 8203110334* 8203110339* 8210070038*	50-244 / 50-244 / 50-244 / 50-244 / 50-244 /
LINEHAN, J J LINEHAN, J J LINEHAN, J J LINEHBERGER, O LINER, R		40-8745 40-8681 40-8714 50-537 G 50-537 A		LORENZ,R A LORIO,P LOTITO,E LOTITO,E M LOTTS,A L	8210210034 8210270240 8210210457* 8210210328 8210040425	50-259 F PR 50-317 R 50-317 R RES	LYONS, J E LYONS, J E LYONS, J E LYONS, J E LYONS, J E	8210070058* 8210070074* 8210070074* 8210070080* 8210070083*	50-244 / 50-244 / 50-244 / 50-244 / 50-244 /
LIMER.R LIMER.R T LINNEMANN,R E LIMNEMANN,R E LIMNEMANN,R E	8210040350* 8210040037* 8210040037*	FOIA 50-537 A 50-445 O 50-445 O 50-322 T		LOTTS,A L LOVE,R S LOVENDALE,P C LOVENDALE,P C LOY,R L	8210180407 8210130557* 8210050205* 8210050380* 8210020226	RES 50-461 G 50-266 O 50-186 G PR	LYONS, J E LYONS, J E, LYONS, P J MACDONALD, C E MACDONALD, C E	8210070087* 8210070090* 8210220491 8210120146	50-244 P 50-244 P 40-299 71-6347 71-6347

MUTHER	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY
MARIEC, VALDE C E MARIECHAIDE C E MARIECHAIDE C E MARIECHAIDE C F MARIECHAIDE C E	8210120158 8210120166* 8210120169 8210120174* 8210120180	71-9001 71-9001 71-9034 71-9034 71-6703	MAJOR, R MAJOR, R MAJOR, R MAJOR, R MALARO, J C	82100800051# 8210080051# 8210080051#	FOIA FOIA FOIA 50-289 D FOIA	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	9210040365 9210070277 9210070296 9210070307 9210070317	70~1100 50-273 Q 50-278 Q 70-364 50-277 Q
MACDDYALD.C E MACDDYALD.C E MACDDYALD.C E MACDDYALD.C E MACDDYALD.C E	8210120192* 6210120334 8210120336* 8210120339 6210120340*	71-6703 71-9010 71-9010 71-9037 71-9037	MALARD. J C MALARD. J C MALARD. J C MALARD J C MALINAUSHAS. A	8210180326* 8210180328* 8210180343* 8210220080* 8210120453	F01A F01A F01A 40-8111 RES	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210070341 8210070392 8210070392 8210130079 8210130178	50-219 Q 50-245 Q 50-443 Q 50-317 Q 50-309 Q
milloral D C E mar donald, C F mar donald, C F maredinald, C E maredinald, C E maredinald, C E	8210120344 8210120352* 8210120381 8210120384* 8210190653	71-9964 71-9964 71-5908 71-5908 71-6346	MALLETT.B S MALLETT.B S MALMROS.M H MALSCH.M G MANCINI.E A	82(0180435# 82(0180436# 82(0190743# 8205270526# 82(0080022#	FOIA FOIA 50-344 Q FOIA CONTRACT	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	6210130441 8210170375 8210210052 8210210069 8210210091	XPORTLIC 50~219 Q 50~289 Q 50~352 Q 50~354 Q
MACODYALD C E MACOD IALD C E MACODYALD C E MACODYALD C E MACODYALD C E	8210150607 8210150691 8210280311 8210280311 82102803164	71-9151 71-9044 70-143 71-905/ 71-9057	MANEATIS, G A MANGAN, C V MANGAN, C V HANGAN, C V MANGAN, C V	8210010413* 8210010033 8210040117 8210040276 8210050111	50-275 P 50-220 P 50-220 P 50-220 F 50-220 P	MARTIN T I MARTIN T T MARTIN T T MARTIN T T MARTIN T T	8210210109 8210210146 8210210201 8210210221 8210210221	50-354
MACDONALD C E MACDONALD C E MACDONALD C E FACEONALD C E MACDONALD C E	6210280324 6210280324 6210280324 6210280334* 6210260334	71-6346 71-6346 71-6745 71-6745 71-6677	MANGAN, C V MANGAN, C V MANGAN, C V MANGAN, C V MANNO, S F	8210050260 8210050354 8210130107 8210210322 8210040071	50-220 P 50-220 P 50-220 P 50-410 H 50-410 S	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210210255 8210210313 8210210435 8210210437 8210220168	50-220 0 50-309 0 50-272 0 70-2116 70-371
HACDONALD C E HACDONALD C E HALDONALD C E HALDONALD C E HALDONALD C E	8210280137# 8210280338 8210280342# 8210280341 8210780345#	71-6677 71-6678 71-6678 71-6115 71-6115	MANNO.B F MANNO.B F MANNO.S F MANNO.S F MANNO.S F MANNO.C C	8210040170 8210040190 8210150129 8210250378 8210010184	50-410	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210220177 8210220240 8210220347 8210240177 8210240734	70-371 70-487 50-352
MACDORALDIC E MACEDIALDIC E MACDORALDIR E MALEVONI JA MALEVONI JA	6210280357 6210280759* 6210150412 6210060452* 8210060317	71-9098 71-9098 Res Foia 50-170 G	MANSER, W C MANSER W C MANSER, W C MANSER, W C MARCHAL, J	8210150061 8210150371± 8210150408± 8210150477± 8210270074	70 -143 70 -143 70 -143 70 -143 xportlic	MARTIN, T T MARTIU, T T MARTIU, T T MARTIN, T T MARTIN, T T	8210270048 8210270084 8210270103 8210270125 8210270201	50-209
emipling maipling tackling maipling maipling	8210150317 8210150395 8210150375 8210770439 8210720439	50-1/0 G 50-1/0 G 50-1/0 G 50-1/0 G 50-1/0 G	MARCHAL, J HARCHAL, J MARCHI, M L MARDIS, D O MARGULIES, M D	8210280064 8210280088 8210260263* 8210010049* 8210150383	XFORTLIC XPORTLIC 50-309 8 50-302 0 50-454 6	MARTIN T T MARTIN T T MARTIN T T MARTIN T T MARTINEZ, F P	6210270236 6210270275 6210270341 6210270350 6206060015#	00-37 50-272 50-322 6 50-322 6 6 6 6 6 6 7 7 8 8 8 8 8 8 8 8 8 8 8 8
MACALINA MACHENA MACHENA US MACHENA US MACHENA US	8210280220 8210280220 82102804444 82102204488 821022043774	50-170 G 50-170 G 50-170 G 50-170 G 50-170 G	MARGULIES,M B MARGULIES,M B MARKT,D MARKT,D MARKT,D	9210180164 9210180170 8210280138* 9210280138* 8210270430*	50-454	R C.NOBAM R V.NOBAM B NAOBAM A S.DRABBAM A B.ORABBAM	0210180284# 8210180287# 8210120400 0210050038# 8210000200#	FOIA FOIA RES FOIA FOIA
madison.a Madisola L Madeen G L Madeen G L Madeen G L	8210250114# 8210150396# 8210050226 8210050387 8210070364	50-3/3	MARKT, D. 1 MARSHALL, J. R. MARSHALL, J. R. MARSHALL, J. R. MARSHALL, J. R.	B210270430* B210070395 B210120247* B210120252* B210130212	50-271 F 50-313 F 50-313 Q 50-313 Q 50-313 S	MASBARO, B A MASBARO, B A MATERG, D R MATERS, D R MATHESON, S M	8210050500# 8210060367# 8210130158 8210280222 8206270016#	FDIA FDIA 50-341 A 50-341 A COMMISSION
Mageen g l Madeen, g l Padeen, g l Madeen, g l Pacten, c l	8210190772 8210190413 8210190547 8210190547	50-382 Q 50-498 Q 50-382 Q 50-267 S 50-445 Q	Marshall, J R Marshall, J R Marshall, J R Marshall, J R Marshall, J R	8210130382 8210130409 8210130513 8210130002 8210130073	50-313	U D.RIHTAM U D.RIHTAM U D.RIHTAM U D.RIHTAM U D.RIHTAM	8210040100 8210060023 8210070245 8210070340 8210130472	50-273 B 50-293 S 50-293 S 50-293 S 50-293 S
Madsell G L Madsell G L Madsell G L Madsell G L Madsell G L	8210190816 8210720122 8210220130 8210220404 8210260278	50-445 0 50-498 0 50-298 0 50-267 0 50-298 0	Marshall. J r Marshall. J r Marshall. J r Marshall. J r Marshall. J r	8210190494 8210190517 8210190545 8210220114 8210250206	50-313 P 50-313 S 50-348 S 50-313 P 50-313 P	MATHIS.C J MATHIS.C J MATHIS.C J MATHIN.E	8210170235 8210250122 8210280127 8210280144 8210130315*	90-273 S 71-6346 50-273 S 50-273 S 50-537 A
Padjen, G L Pajer, T R Majpus, D Magnus, D Maler, J E	8210280142 821045042/# 8210280041* 8210280041* 8210010357	50-267 Q 50-155 P 50-322 F 50-322 F 50-244 P	Marshall, J R Marshall, J R Marshall, J R Marshall, J R Marshall, J R	8210240240 82102601120 82102601120 82102601120	50-349 8 50-348 6 50-313 P 50-313 F PR	MATLOCK,R O MATLOCK,R G MATLOCK,R G MATLOCK,R G MATLOCK,R G	8210070302# 8210070370 8210080195 8210080275 8210080304	50-397
Maier. J e Maier. J e Maier. J e Maier. J e Maier. J e	B2100103554 B210010444 B210040281 B210040284# B210130175	50-244 P 50-244 P 50-244 P 50-244 P 50-244 S	MARSHALL, W II MARSHALL, W H MARSHALL, W H MARSOLAIS, L D MARSTON, R R	8210070398 8210070398 8210220274 8210180190 8210150021	50-329 0 50-329 0 50-329 0 50-271 F 50-369 0	MATLOCK,R © MATSON,E R MATTHEWS.C W MATTEA,J C MATTEA,H J	8210130217 8210050314 8210060424# 8210210261# 821007002[#	BG-397 B I &E CONTRACY BG-423 G CONTRACY
Maier. J e Maier. J e Maier. J e Maier. J e Maier. J e	8210130439 8210150643* 8210190591* 8210190618* 8210190637*	50-244	MARSTON.R R MARTIN.D E MARTIN.J MARTIN.J B MARTIN.J B	8210220461 8210120536 8210260113 8210010460 8210070103	40-8771 > 50~397 A > 50~341 A	MATTIA: H J MATTIA: H J MATTIA: H J MATTIA: H J MATTIA: H J	8210070459* 8210120350* 8210120364* 8210120401* 8210180370*	CONTRACT CONTRACT CONTRACT
Maier. J e Maier. J e Maier. J e Maiep. J e Maier. J e	8210170647* 8210220352* 8210220360* 8210220383 8210220383	50,~244 G	MARTIN, J B MARTIN, R A MARTIN, T J MARTIN, T T MARTIN, T T	9210120147 9210120428 9210060326 9210010157 9210010332	* 50-254 Q 50-220 Q 50-213 Q	HATTIA:M J MATTIA:H J MATTIA:H J MATTIA:H J MATTIA:H J	8210170010* 8210170185* 8210170337* 8210210444* 8210270203*	50-320 F CONTRACT CONTRACT
maier. J e maiep. J e major. R major. R major. R	B210250334 B210270217* B210050478* B210050473* B210050539*	FOIA FOIA	MARTIN, T T MARIIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210040258 8210060034 8210060079 8210060138 8210060211	50-29	MAITTAM J MAITTAM J J L.3OMITTAM J L.3OMITTAM J L.3OMITTAM	8210270223* 8210270230* 8210010057 8210050220 8210070287*	50-312 F 50-312 P

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESS LON NUMBER	SI Crice.
L . SONITTAM L C . SONITTAM L L . SONITTAM L L . SONITTAM L L . SONITTAM	8210070294* 8210070331* 8210130175 8210130599 8210190331	50-312 Q 50-312 Q 50-312 P PR 50-312 P	MCGLESKEY, K E MCGLESKEY, K E MCGLESKEY, K E MCGLESKEY, K E MCGLESKEY, K E	8210150351* 8210150365* 8210150393* 8210150402* 8210150410*	50-322 0 50-322 0 50-322 0 50-322 0 50-322 0	MCGUIRE.D R MCGUIRE.D R MCGUIRE.D R MCGUIRE.D R MCGUIRE.M F	8210210342* 8210260265* 8210260515* 8210270237* 8210210054	70-21 50-327 50-2 5 50-3.2 Nures
L LJONITTAN L LJONITTAN L LJONITTAN L LJONITTAN L LJONITTAN L LJONITTAN	8210190594 8210250065 8210250074 8210250386 8210260231	50-312 P 50-312 F 50-312 P 50-312 S 50-312 P	MCCLESKEY, K E MCCLESKEY, K E MCCLUNO, C E MCCLUNO, C E	8210150422* 8210150527* 8210250059* 8210150490 8210150490	50-322	MCGUIRE, M F MCGUIRE, B A MCGURREN, H J MCGURREN, H J MCGURREN, H J	8210230154 8207280307 8210200055 8210200057 8210280353	20 511 20-511 20-517 Mrz63 Hrbe?
L CONTITAM MATTEON, R MATTEON, R MATTEON, R MATTEON, R MATTEON, R J	8210280228 8010240413* 8010240496* 8007150303 8208310034*	50-312 P F01A F0[A 50-247 P 50-155 P	MCCLUNG, C E MCCLURE, J D MCCORD, R K MCCORKLE, G MCCRELESS, T G	8210150490 8210070413* 8210150548 8210070084* 8210050409*	50-361 G 71-9150 NUREO 50-537 D FOIA	MCINNIS, D MCINNIS, E L MCINIOSH, H D MCKEEVER, R F MCKENNA, E H	820/180044 8210220316 8210280020* 8210250141* 8010210036	50-291 PR 50-297 DAPP, 50-3
MATTONIR J MATTONIR J MATUSCHECKIR J MAURAIF MAURAIFIR J	8210010169* 8210070032* 8210270046 8210170694* 8210180419*	FGIA 50-289	MCCULLOCH, W H MCDERHOTT, D MCDERHOTT, D MCDERHOTT, D MCDERHOTT, D	8210150571 8210120427 8210120483 8210210036 8210210174	NUREO CONTRACT CONTRACT CONTRACT CONTRACT	MCKEMNA, M MCLEAREN, T MCLEAREN, T MCLEAREN, T MCLENDON, O D	8210050204+ 8210120361 8210120416 8210120540 8210150347	50-443 COMIRACI 50 367 COMIRACI 50-042
MAURIN: L V MAURIN: L V MAURIN: L V MAURIN: L V MAURIN: L V	8209150432 8209150438* 8209220135 8210010370 8210040078	70-2946 70-2946 50-382 A 50-382 F 50-382 S	MCDERMOTT, D MCDERMOTT, D K MCDERMOTT, D K MCDERMOTT, D K MCDIARMID, R C	8210280370 8210130008 8210190001 8210260237 8210250356	CONTRACT CONTRACT CONTRACT CONTRACT PROJ	MGLEREN, T MCMURRAY, C M MCMURRAY, C M MCMURRAY, C M MCMURRAY, C M	8210290420 8210010375 8210010375 8210150309= 8210150324•	CENTAL 50-322 50-322 50-322
MAURIN.L V MAURIN.L V MAURIN.L V MAURIN.L V MAURIN.L V	8210040110 8210040168 8210040191 8210130174 8210130243	50-362 A 50-382 F 50-382 A 50-382 S 50-382 S	KCDIARMID, R C MCDONALD, G K MCDONALD, J A MCDDINELL, E J MCDOWELL, J	8210250354 8210240493* 8210150303* 8210120550* 8210260091*	PROJ 50-358 E 50-390 O CONTRACT WASTE MGT	MCMURRAY.C M MCMURRAY.C M MCMURRAY.C M MCMURRAY.C M MCMURRAY.C M	8210150337* 8210150351* 8210150345* 8210150373* 8210150402*	50-322 50-322 50-322 50-322 50-322
MAURIN.L V MAURIN.L V MAURIN.L V MAURIN.L V MAURIN.L V	8210130245 8210130551 8210130564 8210170345 8210170542	50-382 & 50-382 & 50-382 & 50-382 & 50-382 &	MCDUFFIE.M A MCDUFFIE.M A MCDUFFIE.M A MCDUFFIE.M A MCDUFFIE.M A	8210050106 8210050125 8210170512 8210200032 8210200084	50-400 A 50-400 A 50-400 A 50-400 C 50-400 C	MGHURRAY, C M MGMURRAY, C M MGMURRAY, C M MGMURRAY, C M MGMURRAY, C M	8210150410* 6210150422* 8210150527* 6210250656 8210250656	50-322 50-322 50-322 50-322
MAURIN, L V MAURIN, L V MAURIN, L V MAURIN, L V MAURIN, L V	8210250217 8210250242 8210250254 8210250341 8210250355	50-382 S 50-382 S 50-382 S 50-382 B 50-382 A	MCDUFFIE, M A MCFARLAND, C R MCFAUGHY, J P MCGARRY, J M MCGARRY, J M	8210240442 8210150315* 8210080282 8210050202 8210050202	50-400 A 50-370 Q 50-416 S 50-413 Q 50-413 Q	MCMURRAY.C M MGMURRAY.C M MCMURRAY.C M MCMEILL.C A MCNEILL.G A	6210250057+ 6210270283 6210270283 6210040324 6210060285	50-372 50-322 50-323 50-333 50-333
MAURIN, L V MAURIN, L V MAURIN, L V MAXWELL, D F MA(WELL, J C	8210260362 8210270190 8210290438 8210220163* 8210290035	50-382 F 50-382 K 71-6574 50-400 Q ACRS	n Cyrragom M Cyrragom MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P	6210050208* 6210050208* 6210010234 6210010243 6210060201	50-413	MCNEILL, C A MCNEILL, C A MCNEILL, C A MCNEILL, C A MCNEILL, C A	8210120240 8210150263* 8210170067 8210200018 8210260170	50-333 50-333 50-333 50-333 50-333
MAKWELL.JC MAY.E L MAYER.L O MAYER.L O MAYES.R L	8210270035 8210130225* 8210150174 8210150381 8107270146*	ACRS 50-27 & 50-263 & 50-282 & 50-266 0	McGauchy, J P McGauchy, J P McGauchy, J P McGauchy, J P McGauchy, J P	8210060224 8210080120 8210080186 8210080223 8210080277	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	MCNEILL, C A MCNEILL, C A MCNEILL, H M MCNIVEN, H D	8210260306 8210260338* 8210260378 8210260558* 8107270166*	50-333 50-333 50-333 0A979 50-265
Mayes, R L Mayes, R L Mayes, R L Mayes, R L Mayes, R L	8107270169* 8107270174* 8107270178* 8107270182* 8107270185*	50-266 0 50-266 0 50-266 0 50-266 0	McGauchy, J P McGauchy, J P McGauchy, J P McGauchy, J P McGauchy, J P	8210080284 8210080295 8210150011* 8210150019* 8210150024*	50-416	MCNIVEN, H D MCNULTY, A MCNULTY, A MCTIERNAN, T J MEDFORD, M D	8107270174* 8210040001 8210070153 8210280019* 8210260450	50-244 Contra Contra Contra Fola 50-204
Mayes, R L Mayes, R L Mayes, R L Mayes, R L. Mayes, R L	81072701884 81072701914 81072701944 81072701944 81072701982	50-244 0 50-246 0 50-264 0 50-266 0 50-266 0	HCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P	8210180104 8210190417 8210190561 8210220065 8210220131	50-416 R 50-416 S 50-416 S 50-416 S 50-416 S	MEDLOCK, R L MEHAFFEY, R F MELKONIAN, E MENCZER, H D MENDENHALL, E E	8210150644 8210040187* 8210270309 8210040005 8210060405*	40-815 50-285 50-208 50-263 50-254
MAYEB,R L MAZETIB,G R MGALPINE,E J MGALPINE,E J MGALPINE,E J	8107270199* 6205050480* 6210010317* 6210010361* 6210010371*	50-266 G 50-261 P 70-143 70-27 70-143	MCGAUGHY.J P MCGAUGHY.J P MCGAUGHY.J P MCGAUGHY.J P MCGAUGHY.J P	8210220198 8210220196 8210220399 8210220269	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	MENDEZ, R MENDONCA, M MENDONCA, M MENTER, L MERCER, J W	8210060384* 8210170501* 8210280303* 8210280303* 8210230350*	50-313 50-331 50-275 XPDRIL CONTRA
MCALPINE, E J MCALPINE, E J MCALPINE, E J MCBREARTY, R A MCBREARTY, R A	8210190898# 8210190067# 8210190204# 8210210264# 8210290280#	70-824 70-1113 70-143 50-220 Q 50-293 Q	McGauchy, J P McGauchy, J P McGauchy, J P McGauchy, J P McGauchy, J P	8210220278 8210220284 8210220428 8210220438 8210260445	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	Merkle, J o Merrineather, n Merrineather, n Merrineather, n Merrineather, n	8210050504 8210010214# 8210010384# 8210010433# 8210220189#	RES 50-389 50-404 50-516 50-438
MCBRIDE,L M MCBRIDE,L H MCBRIDE,M F MCGABE MCGABE,E C	8210130349* 8210190667* 8210280250 8210060376 8210130405	50-267 R 50-267 R 50-289 Q 50-219 E 50-387 B	MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P	8210260513 8210270050 8210270073 8210270124 8210270193	50-416 S 50-416 S 50-416 S 50-416 S 50-417 B	METZGER, J R MEYER, G W MEYER, J F MEYER, J F MEYER, K A	8210150136# 8210210056# 8008130744 8009080464 8210120399#	70-821 50-281 50-247 50-3 50-331
McCabe, e c McCabe, e c McCabe, e c McCabe, e c McCabe, e c	8210150235* 8210170714* 8210270210* 8210270366 8210150302*	50-317 G 50-317 G 50-352 G 50-277 S 50-277 G	McGauchy. J P McGauchy. J P McGauchy, J P McGrath. J R McGuire. D R.	8210290311 8210290340 8210290348 8210120308* 8210080228*	50-416 8 50-416 8 50-416 8 50-259 0 50-321 Q	Meyer.or Michel.c J Michel.c J Michel.c J Michel.c J	8210120397 8210220395 8210260568 8210260571 8210270235	res Pr 70-14: 70-14: 70-14:
MCCARDELL, R K MCCLESKEY, K E MCCLESKEY, K E MCCLESKEY, K E MCCLESKEY, K. E.	8210150412 8210150296* 8210150309* 8210150324* 8210150337*	#E8 50-322 0 50-322 0 50-322 0	MCGUIRE.D R MCGUIRE.D R MCGUIRE.D R MCGUIRE.D R MCGUIRE.D R	8210150380* 8210150380* 8210150007* 8210210206* 8210210223*	50-395 Q 70-143 50-348 Q 50-13 Q 70-1201	Michelbon, C Michelbon, C Michelbon, C Michelbon, C Michelbon, C	8009240202 8107010161* 8107090355* 8108240273* 6108270054*	50-33(50-34) FOIA FOIA FOIA

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCESSION NUMBER	EUBJECT CATEGOR	Y	AUTHOR	ACCESSION NUMBER	SUBJECT	
The same of the sa	8109250504#	AIDS		MIDURA, H J	8210290216	50-272	s	YILLS, L M	8210070255	50-259	ь
MICHELSON C MICHELSON C	8109280036#	50-312	S	L H ARUGIN	8210270310	50-272	8	MILLS, L M	8210070348	50-438	Α
HICHELSON C	8110190928	FOIA		H ANDURA	8210290353	50-272	S	MILLS.L M	8210080160	50-390	8
HICKELEON. C	8110190933*	FOIA		WIELE'H F	8210150178*	50-322	т	HILLS.L H	8210080160	50-390	8
MI HELEON. C	#0E10401118	FOIA		MILES E D	8210070017	CONTRACT		MILLS, L M	8510080518	50-259	P
	81111910424	50-206	Q.	MILES, E B	8210070456	CONTRACT		MILLS.L. H	8210080219	50-257	G
richei edur c Richereon c	0112020725*	LOIY		MILETI, D S	8210150223*	50-322	T	MILLELL M	8510080555	50-438	s
HICHELSON, C	8112210193*	FOIA		MILETI.D S	82(0150223#	50-322	Ŧ	MILLS.L H	8210080247	50-390	5
MICHIELSON C	9201190040*	FOIA		MILINAZZOLP L	A210150517#	BA999		MILLS, L II	8210080255	50-390	6
MICHELSON, C	8201190296*	FOIA		MILINAZZO, P L	8210190524*	GV&&&		HILLS, L H	8210080278	50-478	s
#14~ELGON C	8201200653*	50-255	S	MILLER, D E	0210050112#	50-295	O	MILLE, L M	0510080580	50-390	ន
HICHEL SOIL C	8202030072*	FOIA		MILLER D S	0210050236	50-309	Q	MILLS, L. M	0210080291	50-390	8
HICHELEON C	8202180457	HISC		MILLER, D S	821003023 6	50-309	G .	MILLS, L M	8210080292	50-438	9
MICHEL SOIL C	8203100549*	50-313	S	HJLLER,D S	0210200085	50~309	G	MILLS, L M	8210080307	50-436	g
HICHELSON C	8203300220#	LUIV		MILLER. D S	0210200065	50-309	O .	MILLS, L M	010080310	50-390	S
HICHELSON C	6203310089#	50-311	₽	MILLER D S	8210290303	50-309	G	HILLS. L. M	8210120284	50~327	p
HI THELEON C	8205130114#	50-290	P	MILLER, D S	8510540303	90-309	0	HILLS L H	8210130142	50-257	P
MICHELEON C	6206040401#	FOIA		MILLER J R	8101500355*	50-142	Г	HILLS.L. M	8210130150	50-327	P
MECHEL SON C	0,204110104*	50~41A	8	HILLER J R	0210050052	50-373	Q	HILLS L H	8210130247	50-390	3
HICHELEON C	8210010048*	A103		HILLER JR	0210050102	50~305	G .	MILLE, L. H	0210130379	50~390	s
-ICHELSON C	0210010073#	FOIA		MILLER, J R	6210050308	50-371	Q	MILLS, L M	8210130364	90-290	В
HINHELEGNI C	0210050031*	FØ1A		MILLEN, J R	6210050359	50-186	Q	MILLS.L. M	8210130407	50-439	Ē
MICHEL SOM C	821005Q1T9*	Alga		MILLER, J. R	#84E050015B	50~186	0	MILLS.L M	8210130521	PR	
MICHEL SOU, C	8210050475*	LOIV		MILLER, J R	8210260471	14E		MILLS.L H	8210130560	50~390	5
HICHELEDIA C	*PE0090013B	L01V		MILLER, J R	0210290032*	FOIA		MILLS, L M	0210150101*	50-438	0
MICHELSON C	*36 POA00150	50 -334	S	MILLER: J R	6210290065*	FOIA		MILLS.L M	8210150218	50-257	a
HICHELSON C	8210070412	50 -312	8	MILLER, J. R	8210290129	50~409	Q	MILLS.L. H	8210150230*	50-370	Ö
MICHELSON, C	8210070415	50 -259	5	MILLER, L	85100905984	50-206	Q.	MILLS, L M	8210150231+	50-327	O
MICHELSON C	0210070401	WISC	_	HILLER, L K	8210200014*	116~06	R	MILLS, L M	0210150241*	50-390	0
HICHELSON C	82100800854	50 244	5	MILLER, L K	6210200090*	50~272	R	MILLB, L H	8210150291*	50-370	O
MI CHELSON, C	8210080104	50~250	s	MILLER, M E	9210040099	50-445	o .	MILLS.L M	0210180117	50~327	Р
MICHELSON C	0210000106*	FUIA		MILLER M E	8210030259	50-456	Q.	HILLBIL H	0210170307	50-370	g
MI CHELSON C	02100802 & 9	LOPREP		MILLER, M E	8210270178	50~537	0	HILLS.L M	0210190357	50~370	6
MICHELSON C	8/101/20114	50~267	S	MILLER, M I	8210050227*	50-329	Q	MILLS. L H	8210190467	50-438	۸
MICHEL SON: C	8510150154	50-296	B	MILLER, M I	8210090229+	50~329	q	MILLBIL M	0210170526	50~438	8
MICHELEONIC	8210120370	MISC		MILLER, M I	0210130373	50-454	Q .	WILLEY F. W	8210190755	TOPREP	
MICHELSON C	0210130077	50 334	9	MILLER, M. I	8210130373	50~454	G	MILLE, L H	8210220071	50-438	9
MICHELEON C	8510510004	50-266	P	HILLER, M. J.	0210250211	50-456	Q	MILLS.L. M	8210220098	50-390	6
HICHITCHER M	0510550351	PR		HILLERAN J	0210250211	50-456	Q	MILLS.L H	8210220151	50-257	G
HIDWA, H J	0210010045	50 -31 1	S	MILLER, N E	0210120092	NUREO		MILLBIL H	8210220223	50-390	a
нарача Ј	8210019123	50+311	ទ	MILLER, N E	0510150105	NUREO		MILLS, L M	8210220225	50-390	F
HIEURA, H. J.	0210010144	50 -31 i	ß	MILLER,R I	6210250037	71 9094		MILLB.L M	8210220271*	50-430	0
HIDUMA, H J	8210010191	50~272	S	HILLER' A L	0210120055*	EOIV		MILLS.L M	8210220350	50~439	5
HIEURA, H. J.	0510010537	50 - 31 1	S	HILLER'N O	8210040429	50-275	þ	MILLS.L M	8210220422*	50~438	a
HIDUHA, H J	0210010344	50 -311	S	MILLER, W O	8210040430	50-510	Α	HILLS, L. II	6210220466*	50 - 370	a
MIDUAA, N. J.	621001039 (50 -272	6	MILLER, W O	8310070003	50-204	P	MILLB, L. M	8210220474*	50-327	q
MICORA. H J	8210010407	50-3(1	5	MILLER, W O	8%10120033	50-255	b	MILLS, L M	8210230067	50-260	P
HIDURA, H. J.	0210010419	50-311	9	MILLER, W O	0210150428	71-9010		WILLEY F M	8210230046	20-257	P
MIDURA H J	0210010455	50-311	5 5	MILLER, W.O.	0210150432	40-8102		HILLS.L M	8210260100	50-390	5
MIDURA.H J	B210070221	50 -311	8	MILLER, W O	6210150433	70-1143		MILLS. L M	0210240105	50-438	s
MIDURA, H. J.	0210070243	50-311	S	MILLER, W O	8210180316	70-36		MILLBIL H	0210260107	50-438	8
MIDS#A.H.J	6210020246	50-311	S S	MILLER, W O	0210160340+	FOLA		MILLS, L. H	0210260174	50 -370	F
MIDURA II J	0210070249	50-311	8	MILLER, W O	8210180341*	F01A 50-349	p	HILLS L H	8210260186	50~370	er er
HIDDING IF A	0210070254 0210070305	50-311 50-272	9	MILLER, W O	8210180789 8210070384	50-369	8	MILLBILL H	0210260169	50 370	F
rappga. It J	DE1/01/A302	AN WALK	-	HILLIONITH H	##104/04##	DO-DEK		HILLEN L. M	8210260251	50-	

AUFHUR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSIO NUMBER	N SUBJE CATEG		447450	ACCESSIO	
MINGR.G C MIRAGLIA.F MIRAGLIA.F J MIRAGLIA.F J	8210260242 9210080001 8210040422 9210120029 8210180308	50-322 T 50-237 P 50-498 A 50-443 D 50-528 A	MOYER, D J MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J	821004015 821001037 821001037 821007025 821007025	6 50-336 6 50-336 0 50-245		AUTHOR MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D	NUMBER 621014028 821014042 621014042 621014047 821014045 621045017	9 90-260 7 90-283 9 50-763 6 90-766
MISBREKER, J M MITCHELL D G MITCHELL D G MITCHELL D G MITCHELL D O	9210130281 9210210034 8210010180# 9210130241* 9210130371#	50-387 8 50-387 8	MROCZKA,E J MROCZKA,E J MROCZKA,E J MROCZKA,E J MROCZKA,E J	821007030 821007036 8210070366 8210070366 8210130228	4 50-245 50-245 50-245	5 5 5 5	MUSOLF. D MUSOLF. D MUSOLF. D MUSOLF. D MUSOLF. D	821024034 821024039 821024029 821027024 821029023	4 50 .82 1 50 .82 7 50 263 7 50 262
MITCHELL, D O MITCHELL, D O MITCHELL, D G MITCHELL, D G MITCHELL, D G	8210130387* 8210210293* 8210210436* 8210210446* 8210250377*	50-387 S 50-387 S 50-387 S 50-387 S	MRDGZKA,E J MRDGZKA,E J MRDGZKA,E J MRDGZKA,E J MRDGZKA,E J	8210130226 8210190472 8210210155 8210210155 8210210425	50-336 50-336 50-336	80 888	MUSOLF. D MYERG. D CI MYERG. D CI MYERG. D CI MYERG. D CI	821029024 821001020 821001041 82102017 821022050	F P48 50 724 50 724 50 724
MITCHELL, D G MITTL, R L MITTL, R L MIZUNO, G S MIZUNO, G S	8210250385* 8210260219* 8210130554 8210220324 8210040183	50-387 S 50-387 S PR PR 50-537 G	MROCZKA, E J HROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J	8210210425 8210220060 8210220060 8210220103 8210220103	50-336 50-336	***	MYERB, R V MYERB, R V NACERIA NADIPURAM, P NAIDU, K R	8210070189 8210210317 8210180374 6210130117	50 522 50 572 NUREO 4 50 247
MODES.H C MOELLER.D W MOELLER.D W MOELLER D W	8210130272 8210220316 8210010117> 8210040367* 8210050436*	50-445 G PR FDIA 50-366 S FOIA	Mroczka, e j Mroczka, e j Mroczka, e j Mroczka, e j Mroczka, e j	8210220112 8210220195 8210220195 8210260432 8210260432	50-245 50-245 50-245 50-336 50-336	88888	NAIDU, K R NAIDU, K R NANCE, G R NAPIER, B A	8210130374 8210130957 8210190787 8210070358 8210270041	* 50 481 * 50 480 * 50 431
MOELLER, D W MOELLER, D W MOELLER, D W MOK. G MONDEN. T	8210050476* 8210050542* 8210060079* 8210280178* 8210270452*	FOIA FOIA FOIA 50-277 P XPORTLIC	MUCHA,E MUELLER,C J MUELLER,C J MUELLER,J J MULHOLLAND,J D	82020101670 8208270017 8208270017 82102001060 8210130014	ACRS ACRS 70-820	P	NAPUDA, O NARAYANI, I V NARDI, A J NARDOCI, P B NARDOCI, P B	8210290072 8210190720 8210130420 8210130180 82102207274	50 A61 7 50 A61 7 50 A2 8 50 B59 8
MONIGOMERY, D H	8210010118* 8210150219* 8210150239* 8210150263* 8210270158	50-321 Q 70-1201 70-27 50-269 Q 50-522 A	MULLINS,C D MUNTITHS,L M MURDOCK,E B MURDOCK,E S MURLEY,T E	8210150567 8210220379 8210180415 8210180420* 8103090389*	NUREG PR 40-6622 40-6622 50-247	s	NATHAN, B. J. NATHAN, G. J. NAVE, C. NE (LD, J. NE (LL, J. M.	921 0060,134 i 921 0210 305 i 921 01 3015 7 e 921 01 901 42 i 971 01 902 25 e	50 44 A 50 44 S 50 259 S 50 640 S
MOORE, D E MOORE, D E MOORE, J MOORE, J E MOORE, R D	8210260228* 821026025* 8210260230 8210280230 8210280230	50-321 Q 50-327 Q 50-247 Q 50-247 G 50-10 F	MURLEY, T E MURLEY, T E MURLEY, T E MURPHY, A J MURPHY, C E	8104240059* 8109220915* 8111240912* 821019002* 8210190342*	FOIA FOIA FOIA CONTRACT 50-015		NEILL, J K NCISLER, J H NCLSON, C C NELSON, O H NELSON, Q H	82101802264 82101305094 8210050497 8210060491 62100604964	50 461 s 50 461 s 50 409 s
MDORE.R E HOORE.R H MOORE.R H MOORE.R H MOORE.R N	8210270035> 8005270822+ 8210270103 8210270114 8210270243	50-537 Q FOIA XPORTLIC XPORTLIC XPORTLIC	MURPHY, D D MURPHY, D E MURPHY, D E MURPHY, D E MURPHY, D W	8210220406* 8210060412* 8210260222* 8210270371* 8209140027*	50-438 50-259 50-259 50-259 50-244	0 6 5 5	NELSON, I NELSON, I NELSON, I NELSON, I C NELSON, I C	6710070315+ 6210070127+ 6210070465+ 6210070310+	70 25 50 517 6 50 517 6 50 517 6 50 517 5
MODRE, R N MODRE, S N MODRE, V A MORGAN, C MORGAN, C	8210130117 8010240329 8210040235	MISC 50-413 D 50-247 P 50-247 G 50-247 G	HURPHY, D W HURPHY, M E MURPHY, W P MURPHY, W P MURPHY, W P	8209210523* 8210190349* 8210040113 8210130189 8210130447	50-309 50-285 50-271 50-271	P Q Q R	NETRON' I C NETRON' I C NETRON' I C	6810070323x 0210070332x 0210070315x 0210070347x 0210210016x	50 511 : 50 511 : 50 511 : 50 50 :
MORGAN, C MORGAN, C MORGAN, C MORGAN, C MORGAN, C	8210250081 8210250216 8210250216	50-247 0 50-247 G 50-247 G 50-247 O 50-247 G	MURPHY, W P MURPHY, W P MURRAY, B MURRAY, B MURRAY, B	8210220418* 8210270432* 8210070394* 8210120073*	50-271 50-271 40-6622 50-382	P G F G	NELSON.R H NELSON.R L NELSON.R L NELSON.R W NELSON.W R	0210/40200+ 0210/40208+ 0210/40202+ 0210/40224 0210/20118	50 N/F S 50 N/F S 50 P/S Q 616410 RES
MORGAN, C MORGAN, W MORGAN, W MORIARTY, J M MORISI. A V	8210190412* 8210250348* 8210220417*	50-247 G 50-249 B 50-249 S 0A999 50-293 Q	HURRAY, P L HURRAY, P L HURRAY, P L HURRAY, P L HURRAY, T D	821022028 [* 8210260457 8210260457 8210260465* 8210260465*	50-309 50-309 50-309	0 0 0 0	NERGES, V NERGES, V NERGES, V NERGES, V NERGES, V	62101204055 6210120562# 6210120266 6210120266	1 167 OC 1 167 OC 1 167 OC 1 167 OC
MORISI.A V MORISI.A V MORISI.A V MORKEN.D J MORRILL,P J	8210250085 8210250372*	50-293 P 50-293 Q 50-293 P 50-213 P 50-275 Q	MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D	8210050323 8210050355 8210070006* 8210130124 8210130356	50-346 (50-346 (50-346 (50-346 (50-346 (F	NERBEG, V NERBEB, V NETI. 8 NEUMANN, M R NEUMANN, M R	8210180348 8210020348 8310510241 8310510521	50-107 A 50-707 A 50-707 3
MORRIS, D O MORTON, D K MORTON, K V MORTON, K V MORTON, K V	8210120300* 5 8210120432* C	UREO 60-213 P ONTRACT ONTRACT ONTRACT	MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D	8210130404 8210180131 8210190254 8210190358 8210250226	50-346 g 50-346 g 50-346 g	5 3 3	NEWMAN, J R NEWMAN, J R NEWMAN, J R NEWMAN, J R NEWMAN, J R	8210250043 8210070120 8210070120 8210070147 8210070147	40 0697 50 466 6 50 466 6 50 466 6
MORTON, K V MORTON, K V MORTON, K V MORTON, K V MORTON, K V	8210120488* CI 8210130014* CI 8210170063* CI 8210170177* CI	ONTRACT ONTRACT ONTRACT ONTRACT ONTRACT	MURRAY, T D MURRAY, T D MURRAY, T D MUSOLF, D MUSOLF, D	8210250270 8210260283 8210280078 8210010036 8210010041#	50-346 p 50-346 p 50-346 g 50-263 p	3 :	NEWMAN, JR NICHOLAB, H NICHOLAB, JB NICHOLAB, JB.	8210210363 8210210363 8210290396# 8210120073# 8210120238	50 499 6 50 499 6 50-322 0 50-382 0 50-313 4
HORTON, K V HORTON, K V HORTON, K V MORTON, K V HORTON, K V	8210210038* C0 8210210178* C0 8210210570* C0 8210210581* C0	ONTRACT ONTRACT ONTRACT ONTRACT ONTRACT	MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D	8210010060 8210040123 8210050319 8210040258	50-263 p 50-263 p 50-282 p 50-282 p 50-263 8		NICHOLSON, H A NIMITZ, R L NIY, H C NIY, H C NIX, H C	82100100943* 8210010094 8210010094	50-10 a 50-278 0 50-366 5
MORTON, K V MORTON, K V MORTON, K V MOSELEY, N C MOWRY, W R	8210260240* CO 8210260561* CO 8210280374* CO 8203040536* 50	INTRACT INTRACT INTRACT INTRACT	MUSQLF, D MUSQLF, D MUSQLF, D MUSQLF, D	8210060377 8210060380# 8210130260 8210130261 8210130510	50-263 P 50-263 P 50-263 P		NIX, H C NIX, H C NIX, H C	8210060317 8210080234	50-366 S 50-366 S 50-366 S 50-366 S
	8210280062 XP	DRTLIC	MUSOLF, D MUSOLF, D	8210130563 8210150364	50-282 g 50-306 Q 50-263 p		NIX, H C, NIX, H C, NIX, H, C NIX, H, C	8510130529 8510130550 8510130183	70-324

		SUBJECT CATEGURY		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		AU FHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AUTHOR JEHC IEHC IEHC IEHC IEHC	8210130541 5 8210190504 5 8210190595 5 8210220219 5	0-366 S 0-366 S 0-366 S 0-321 S 0-321 S		O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8210010016 8210010019 8210010025* 8210010035 8210010051	50-321 50-259		OTT.L J OVERBECK.O J OMCZARSKI.P C CWSLEV.G F GWSLEY.O F	8210210039 8210050068* 8210270421 8210040229 8210130123	NUREG 50-409 P RES TOPREP 50-316 P
10 M C 10 M C 10 M C 10 H C	8210290096 5 8210290204 9 8210290262 5	0-366 S 0-321 S 0-366 S 0-321 S 0-321 S		O REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8210010052 8210010102 8210010112 8210010227 8210010238*	70-143 50-400 50-324 50-348 50-280	@ @ P 0	OWSLEY, 0 F OWSLEY, 0 F OWSLEY, 0 F OWSLEY, 0 F	8210150033 8210150173 8210190502 8210270092 8210270214	50-316 P TOPREP 50-219 P TOPREP TOPREP
14 H G 16 H G 16 H G 16 H G 16 H G	8210290349 8210290357 8210290373	50-321 S 50-321 S 50-366 S 50-321 S 50-366 S		0.100FE' 7 0.100FE' 7 0.4EIYFA' 7 0.4EIFFA' 7 0.4EIFFA' 7 6.4E	8210010326 8210150020* 821022038/ 8210130559* 8210010401	50-259 50-369 50-438 50-247 50-3	Q Q Q Q	PACE, D L PACE, P PACE, P L PACE, P L PACE, P L	8210220242* 8210130542* 8210010174* 8210040212* 8210060257*	50-416 S 50-335 S 50-335 S 50-251 S 50-250 S
CH W A CAT V S CHAN V S CHAN V S CHAN V S	7812200285* 7909280105* 8001300616*	10-8355 50-266 P 50-266 P 50-266 P 50-227 F		0.100FE' A B 0.100FE' A B 0.100	8210010409* 8210010425* 8210010443* 8210040141 8210040232	50-3 50-3 50-3 50-247 50-247	Р Р 5 Т	PACE, P L PACE, P L PACE, P L PACE, P L PADMANABHAN, M	8210130462* 8210150039* 8210260117* 8210260369* 8210050388	50-335 8 50-335 S 50-250 S 50-335 S NUREO
CHAN.V S PREMIAUG.L R PERMAUG.L B PELMOS C E PELMOS C E	8210260309 8210260402 8210040230	50-286 0 70-1257 70-1257 50-456 0 50-481 0)	0.100FY D 0.100FY D 0.100FY D 0.100FY D 0.100FY D	8210060394 8210070361 8210120253 8210130277 8210130411	50-247 50-247 50-247 PR 50-247	8 8 8	PAGE,R G PAGE,R G PAGE,R G PAGE,R G PAGE,R G	8205240010* 8210040392 8210120646 8210220025 8210270434	40-8355 70-971 70-25 70-1257 70-1151
PELIVA E PELIVA E PELIVA E PELIVA E PELIVA E	8210080284 8210190360 8210190361*	50-346 (50-331 (50-331 (3 3 2 3	0.100FE' A D 0.100FE' A D 0.100FE' A D 0.100FE' A D	8210130455 8210190693 8210200078 8210250145 8210260332	50-247 50-247 50-247 50-247 50-247	P G S P	PAGE.R Q PAGE.R Q PAGE.R Q PAGLIARD.J PAGLIARD.J A	8210280415 8210280417* 6210290383 8210080251 8210040185*	70-2957 70-2957 70-2944 50-155 9 50-409 0
PE: 198: C E -E: 198: C F -E: 198: C E -E: 198: C F	8210260176 8210260307 8210260315	50 255 50-454 50-155	0 0 0 0 0	O'TOOLE, J D DAKLEY, C B DAKUM, K E OBERO, C T OBERO, C T	8210280154* 8210070363* 8210270373 8210150507 8210170673	50-3 50-430 40-8824 1&E 1&E	F A	PAGE (ARO, J A PAJONSKI, J E PAJONSKI, J E PAELADINO, N PAELADINO, N J	8210080204* 8209290189* 8209290225* 8210290393 8201150004*	50-305 0 50-10 F 50-10 F 10CFR FOIA
をE105.C を をE105.C を あらいなり 限利のM11 リ RIS-M M	8210260372 8210290278 8210220447 8210210477* 82101J0244*	50-358 50-334 50-272	0 8 9 R	OESTMANNIM J OHLDACHIR OLSENIA F OLSENIA F OLSENIR N	8210080171* 8210250172 8210040214 8210220231 8210270152*	50-358 50-133 50-13 70-824 XPORTLEO	Q R P	PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J	8206200086 8206200091 8206200097 8206270053 8206270059	COMMISSION COMMISSION COMMISSION COMMISSION
A1.P O Ar.P O Br.P G B1.P G	8210120378 8210120388 8210260531 8210260544 8210260544	080 080 080 080 080		H J.MAHEJO A L.IXENTHEJO OL.IXENTHEJO A L.IXENTHEJO OLSHINELIJA	8011070227 8010240644 8010270312 8208250417* 8210150376*	50-247 50-247 50-247 50-269 70-143	ት ት	PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J PALMER, R A	8207050040* 8210070441* 8210120151* 8210270003* 8210040209*	50-287 P FOIA 50-244 P COMMISSION 50-316 S
TH:14 9 1601, J F ARD, J A LE24 D P LE25 D P	0210190612* 8210190608* 0210190281* 8210250030 8210260554	50-312 50-482 50-322 NUREO MISC	Q Q T	OLSHINSKI. J A OLSHINSKI. J A OMATE. Y OMATE. Y OMATE. Y	8210220420 8210220430* 8107270188* 8107270191* 8107270194*	70~1113 70~1113 50-266 50-266 50-266	a a	PALMER.R A PALMER.R A PALMER.R A PALMER.R A PALMER.R A	8210040327* 8210040330* 8210040307* 8210160129* 8210190389*	50-314 B 50-314 B 50-315 B 50-316 S 50-315 B
Ab. T Ar. T 19 Ar. T 19 Ar. T 19 Ap. E 15	8001030220 8006230784 8201210107* 8204790237* 8205130256	50-247 50-247 FOIA 50-289 50-269	P G P	OPEVA. J F OPEKA. J F OPEKA. J F OPEKA. J F	8210250270 8210250270 8210250327 8210250327 8210260414	50-423 50-423 50-423 50-423 50-245	ចល្ល	Palmer, R A Palmer, R A Pang, J F Pangburn, G C Pangburn, G C	8210190404* 8210190578* 8210080311* 8210120144 8210120445	50-315 B 50-315 G 70-754 27-47 27-47
120. T 24 GR. T 24 GR. T 29 GR. T 29 30. T 25	6204140329# 8210010015 8210040424 8210040426 8210050492	50-289 50-373 50-369 50-327 50-362	P F P A	OPEKA, J F OPEKA, J F OPEKA, J F OPEKA, J F	8210260414 8210260519 8210260519 8210270200 8210270200	50-245 50-245 50-245 50-213 50-213	P የ የ የ	PAPAY, L T PAPAY, L T PAPAY, L T. PAPERIELLO, C PAPERIELLO, C J	821 0080214* 821 0190495* 821 0250227* 821 0080251 821 0040202	50-204 Q 50-361 Q 50-361 Q 50-135 8 50-331 Q
N° L b2 N° L 51 N° L 51 N° L 61 N° L 13	8210070042 8210070045* 8210070051* 8210070055* 8210070061*	50-373 50-373 50-373 50-373 50-373	н н н	OPREA.Q W OPREA.Q W OPREA.Q W OPREA.Q W OPREA.Q W	8210050327 8210220125# 8210250112 8210250249 8210250259	50-498 50-498 50-498 50-498 50-498	5 9 8 8 A	PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J	8210040204* 8210040345 8210050142 8210080166 8210080174	50-331
は、T 計 は、T 計 は、T 計 が、T 1 れ、T 2 れ、T 21	8210070046* 8210070107 8210080340 8210130595 8210180331	50-373 50-329 50-389 50-556 50-390	H 8 A A	Oprea. O W Oprea. G W Oprea. O W Orders. W Orders. W	8210250263 8210250358 8210260452 8210010146* 8210010474*	50-49B 50-49B 50-49B 50-269 50-269	A 8 0	Paperielld, C J Paperielld, C J Paperielld, C J Paris, O H Paris, O H	8210150539 8210250247* 8210260220 8210050254 8210150092	50~10 Q 50~346 Q 50~155 Q 50~247 Q 50~247 Q
8. F 11 8. F 15 8. F 15 9. A 16 117. E L	8210210212 8210210244 8210210498 8210210448* 8210150607	50-400 50-387 50-361 70-2116 40-2259	D P P	ORNSTEIN, H ORNSTEIN, H ORNSTEIN, H L ORNSTEIN, H L ORNSTEIN, H L	8107180478* 8210080026 8004020420 801023043\$ 8107070220*	50-289 50-289 50-302 30-302 FOIA	្ត ទ ខ	Paris.o H Paris.o H Paris.o H Paris.o H Parker.l B	6210210349 6210220338 6210250223 6210270176 6210120319*	50-155 0 50-155 0 50-142 0 50-320 0 QA777
BAUHER. D A BAUHER. D A BAUHER, D A LEN. J LEN. J LEN. J N	8210120027* 8210120057* 82101200754 8210060336* 8210220135	FOIA FOIA FOIA 50-312 NUREO	a	ORNSTEIN: H L ORNSTEIN: H L ORNSTEIN: H L	8108130268* 8205070377* 8210050141* 8210060460* 8210080024	50-206 FOIA 50-320 50-320 50-320	8 566	PARKER. W O PARKER. W O PARKINSON, T W PARKYN, J D PARKYN, J D	8210150012* 8210150079 8209150056 8210010374 8210130270	50-369 0 50-269 6 FOIA PR PR
100.0 P 111.0 H 111.0 H 111.0 H 111.0 H	B10P550198# B510500051# B510020351# B510020354#	50-237 50-346 50-400 50-400 FOIA	P 8 0 0	ORNSTEIN.H L ORNSTEIN.H L ORNSTEIN.H L ORNSTEIN.H L OSTER.J	8210080061 8210080124 8210120079 8210120404 8210060283	50-320 50-206 50-321 50-320 50-295	P P	PARSON, R M PARSON, R M PARSONG, R M PARSONG, R M PARSONG, R M PARSONG, R M	821020333 8210130567 8210010360* 8210080180 8210080283	PR 50-400 8 50-400 9 50-400 8 50-400 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AU [HŪR	ACCF6810m NUMBER	SHB KLI CATE _A SI
PARSONS, R M PARSONS, R M PARSONS, R M PARSONS, R M PARSONS, R M	8210220075 8210220132* 8210220412 8210220484 8210220484	50-400 S 50-400 U 50-400 S 50-400 S 50-400 S	PETTENGILL, H J PETTENGILL, H J PETTIJOHN, S L PETTIJOHN, S L PETTIJOHN, S L	8210210527 8210210530 8006050154* 8006050188* 8008070143*	40-6659 40-6659 FOIA FOIA FOIA	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8210150546# 8210170364 8210170364 8210170725 8210170756 8210407	0A9 W 0A9 P 0A9 P 0A9 P 0A9 P
PARSONS,R M PARSONS,R M PASTVA.M J PASTVA.M J PASTVA.M J	6210270258 6210270240 6210010303* 6210010475* 8210040327*	50-400 S 50-400 S 50-324 S 50-324 S 50-324 S	PETTIJOHI, S L PETTY, J C PETTY, J C PETTY, J C PETTY, J C	8101270870* 8210290087* 8210290199* 8210290313* 8210290365*	FOIA 50-270 8 50-269 8 50-287 8 50-269 8	Potapovs, u Potapovs, u Potapovs, u Potapovs, u Potter, J	8210/70121 8210250135 8210260126 8210260494 8210750224	04444 04444 04444 146
PASTVA.M J PASTVA.M J PASTVA.M J PASTVA.M J PASTVA.M J	8210080183* 8210080230* 8210130483* 8210130497* 8210150046*	50-325 S 50-324 S 50-325 S 50-325 S 50-325 S	PEVEY, L E PFAFF, S J PFEFFERLEN, H C PHILLIP.G A PHILLIP.G A	82108401474 8210220910 8210180050 8210040185* 8210130557*	70-398 40-6659 Yoprep 50-409 Q 50-461 O	POITER, J P POULK, R M POULK, R M POWERS, T B POWERS, T D	821001007± 8209140311* 8210190674* 821012009? 821012010±	M144 50 125 50 325 5 NUMBS NUMBS
PASTVA.H J PASTVA.H J PASTVA.H J PASTVA.H J PASTVA.H J	8210150308* 8210170759* 8210170762* 8210260266* 8210260318*	50~324 \$ 50~324 \$ 50~324 \$ 50~325 \$ 50~324 \$	PHILLIPS, H S PHILLIPS, L E PHILLIPS, L E	8210190209* 8210190761* 8210190766* 8109110478* 8210150495*	50~440 F GA999 GA999 F01A 50~254 G	PRATT.C M PREUSS.M PREVATTE.R PRICHARD.R P PROFFITT.U L	8210270324 8210190700* 8210270017* 8210270074 8210040270*	FH 50 J\$4 8 50 J*4 F 71 F*37 50 F J F
PASTVA, H J PASTVA, H J PASTVA, H J PASTVA, H J HASTVA, H J	8210240368* 8210270079* 8210270243 8210270331* 8210270342*	50-325 S 50-324 S 50-324 S 50-325 S 50-324 S	PHUNG.D L PIANKI.F J PIEHL.R H PIEHL.R H PIERRET.J A	8210280110* 8210130504* 8210180123* 8210190588* 8210280184*	F01A 70-1100 50-316 S 50-315 S 40-7580	PROFFITT,W L PROFFITT,W L PULLAN1,S V PUZEY,A M PYLE,R B	82100402474 82100403154 82103703304 82101400214 8210390064	50 443 4 50 343 4 50 ,21 1 50 184 6 50 ,52 6
PASTVA, M J PATON, N D PATROUN N PATTERSON, J P PAUL, R A	8210270352* 82100800&6 8210080271* 821040354* 8210130408*	50~325 & 50~327 & 50~327 & 6 50~220 & 50~282 & 0 50~407 & 0	PIETRIAMA F PICOTT, D R PICOTT, D R PICOTT, D R PICOTT, D R	9210120367 9210130309 9210130309 9210150454 9210150454	RES 50-361 0 50-361 0 50-361 0 50-361 0	PYLE.R B GUICK, D R GUICK, D R GUIGG, C GUINN, M D	6210260429 6210150301+ 6210210229 6210210229	50 .5 · · · 50 .75 · · 50 .75 · · 50 .75 · ·
PAULICK, L. R PAULSON, W PAULSON, W PAULSON, W PAULSON, W A	821020342 8210040153 8210050300 8210200023 8210150298	PR 50-206 P 50-206 P 50-206 P 50-206 P	PIGOTT, D R PIGOTT, D R PILANT, J M PILANT, J M PILANT, J M	8210150482 8210150482 8210010058 8210130318 8210220136*	50-361 G 50-361 G 50-298 F 50-298 F 50-298 G	GUINN, H D GUIRK, J F GUIRK, J F GUIRK, J F GUITTSCHREIBER	8210289074* 8210190416 8210150445 8210150461 8210050424*	50 (13 3 1666)P 16966P 16966P 601A
PAULSON, H A PAVIS, G S PAVIS, O S PAWLICKI, S S PAKSON, E	0210190671 8210290095* 8210250160* 8009040493* 8210270208*	50~206 P 50~316 8 50~317 8 50~266 P 50~339 P	PILANT, J K PILANT, J K PILANT, J M PIRTLE, O L PITCHER, P M	8210220254 8210260328 8210290323 8210290137# 8210190457#	50-298 P 50-298 Q 50-298 P 50-409 Q 50-395 P	GUITTSCHREIDER RAGONE, S RAHE, E P RAHE, E P RAHE, E P	6210050424* 6210040325* 6210060229 6210130447 6210130535*	EDJA 50-178-8 1061£F 21≥4 50-354->
PAYTON, H C PAYNE, M T PAYNE, M T PEABODY, C A PECK.L S	8210050251 8210210419 8210210419 8209280307 8210190457*	50-266 G 50-400 G 50-400 G NUREO 50-375 P	PLIME, G PLIME, G PLIME, G PLISCOLL R	8210080030# 8210280120# 8210280424# 8210280445# 8210270132#	50-295 F 50-295 F 50-295 F 50-295 F 50-322 Q	RAHE, E P RAHE, E P RAHE, E P RAHE, E P RAMOLE, E	8210196507 821022015,1 8210260305 8210260340 82100604474	turfie Turfee Turfe Turfe Turfe Sorui
PEERY, W W PEERY, W W PEERY, N W PELIZZA, M B R	8210010122* 8210150084* 8210220341* 8210180356 8210130222*	50-83	PLOSXI.T J PLUMLEE, Q L PLUMLEE, K E POCALUJXA.L P POCALUJKA.L P	8210250297* 8210050239* 8210060127* 8210150290* 8210150290*	50~344 0 50~267 0 50~317 0 50~322 T 50~322 T	RAMPY, L W RANDAZZA, J B RANDAZZA, J B RANDAZZA, J B RANDAZZA, J B	9210290202 1710400129 2750E10128 F850E10128 8210130340	50 7r4 5 50 939 6 50 658 6 50 668 6 50 768 6
	0109090011* 0201300308* 0210190022 010190029*	50-289 P 50-312 S 50-271 B 50-271 S	POCHAL, N F POCHAL, N F POHLE, J A POLLARD, R D POLLOCK, M S	8210270014 8210270017 8210220515 8210120274 8210040274#	XPORTL1C XPORTL1C 40-8714 90-289 Q 50-322 Q	RANKIN, W B RANY, J RAITA, A D RAIZEL, A C RAUSCH, T J	02102900414 0210280067* 0210202644* 0210150571 0210010009	50 264 F 50 455 F 70 407 NUREG 50 247 F
			3 L	8210040361# 8210260141# 8210150281# 8210150281# 8207180077	50-322 0 50-322 0 50-322 T 50-322 T 50-3 0	RAUSCH, T J RAUSCH, T J RAUSCH, T J RAUSCH, T J RAUSCH, T J	8210080178 8210180174 8210190464 8210190565 8210190780	50 k37 5 50-10 # 50 247 F 50 247 # 90 254 #
PERLIS, R Q PERNY, C	8210270159 8210270239#	50-483 Q 50-483 Q	POPECL K PORTER, F W	8207180077 8210010322 8210130277 8210280388 8210120419#	50-3 D PR PR 71-6601 27-39	RAUSCH, T J RAUSCH, T J RAUSCH, T J RAUSCH, T J RAUSCH, T J	8210250069 8210250114 8210250155 8210250309 8210260485	50 m37 P 50 054 P 50 054 F 50 054 F 50-037 P
PERNY,C D PERSH.R L PESCHEL,J M PETERS.R F PETERSON,D A	9210150380* 9210180274 9210170675* 8210210556* 8210130145*	70-143 50-387 P 50-266 Q 50-346 P 50-255 R	PORTER.M R PORTER.M R POSNER.P POTAPOVS.U POTAPOVS.U	8210040270* 8210220057* 8210200019 82102001148 8210040171	50-296 8 30-259 8 50-247 9 GA999 OA999	RAWSON, R J RAWSON, R J RAWSON, R J RAWSON, R J RAY, H B	8210060182 8210120291 8210150190 8210270090 8210050008	50-434 & 50-257 & 50-454 & 50-287 : 50-361 \$
PETERSON,M R PETRICK,N A PETRICK,N A PETRICK,N A PETRONE,C D	8210040007 8210080240 8210220252 8210240274 8210070283*	XPORTLIC 50-482 K 50-482 A 50-482 A 50-293 Q	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8210040192 8210040333 8210050188 8210050195 8210080284	QA979 QA979 QA979 QA979 QA979	RAY,H B RAY,H B RAY,H D RAY,H D RAY,H B	8210050012+ 8210050014 8210050014+ 8210050024+ 8210050027+	50-361 \$ 50-361 \$ 50-361 £ 50-361 \$ 50-361 \$
PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J	8210120494 8210120514 8210120529 8210120619 8210120624*	40-8728 40-2239 40-8102 40-8781 40-8781	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8210050287* 8210050272* 8210120222 8210120280 8210120301	QA999 QA999 QA999 OA999 QA999	RAY, H B RAY, H B RAY, H B RAY, H D RAY, H B	8210050032* 8210050037* 8210050041* 8210050044* 8210050048*	50-361 \$ 50-361 \$ 50-361 \$ 50-361 \$ 50-361 \$
PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J PETTENGILL.H J	8210120634 8210120644 8210210021 8210210515 8210210525*	40-8452 40-6522 40-3453 40-8084 40-3453	POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U	8210120309* 8210120311 8210150513 8210150521* 8210150532	QA797 GA797 QA797 QA799 GA799	RAY, H B RAY, H B RAY, H B RAY, H B RAY, H B	8210050050* 8210050076 8210050070* 8210050101* 8210050151	50-361 S 50-361 S 50-361 S 50-361 S

ROHIUA	ACCESSIDN NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	TOSUBUS CATEGORY
FA: H B FA: H B FA: H B FA: H B FA: H B	8210050234# 8210050261 8210050266# 8210050381 8210050390#	50-36t 5 50-36t 9 50-36t 9 50-36t 9 50-36t 9	RIBEIRO, J RICCARDELLA, P RICE, D A RICHARDS, B L RICHARDS, S A	8210040183* 6210050427* 8210130235* 8210010317* 8210240132*	50-220 P 50-155 P 50-29 S 70-143 50-322 Q	ROOT, L D ROOT, L D ROOT, L E ROOT, R W ROOT, R W	8210260138 8210260461 8210190156* 8210070297 8210070311	50-331 P 50-331 F CONTRACT 50-440 S 50-440 S
FAL. H B FAL. H B FAL. H B FAL. H B FAL. H B	8210130269 8210130274* 8210130276 8210130285* 8210130469	50-351 S 50-351 S 50-351 S 50-351 S 50-351 S	RICHARDSON, J D RICHTER, L RICHARD, D C RIDGELY, J RIDGWAY, D A	82101601094 8210170357# 8210260425 8210150535# 8210010435	50-416 R 50-346 S 50-170 C 50-287 P 50-382 G	ROOT, R W ROOT, R W ROOT, R W ROOT, R W ROOT, R W	8210070338 8210070387* 8210130425* 8210130432* 8210280190*	50-460 6 50-460 0 50-460 0 50-460 0
FA, U B FA, H B FA, H B FA, H B	8210130478* 8210130485* 8210130493* 8210130497 8210130508*	50-361 S 50-361 S 50-361 S 50-361 S	PIGGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A	8210070197 8210070197 8210120267 8210120267 8210210266	50-382 0 50-382 G 50-264 0 50-266 G 50-320 0	RODY, R W ROSA, P ROSANO, R ROSASCO, P V ROSE, B	8210280297* 8204300370* 8210280221 8210120384* 8210070127	50-460 0 TOPREP 50-272 0 WASTE NGT 50-454 0
FA; H D FA; H D FA; H D FA; H D	8210170369 8210170317* 8210170323* 8210170326* 8210170470	50~361 S 50~361 S 50~361 S 50~361 S 50~206 S	RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A	8210210266 8210210372 8210210372 8210260423 8210260423	50-320 0 50-382 0 50-382 0 50-382 0	AOSE, B ROSE, B ROSE, B ROSE, B	8210070127 8210070129* 8210070129* 8210180151 8210210278	50-454
601. H B 601 H B 601 H B 601 H B 601 H B	8210190506* 8210250137 8210250140* 8210250207 8210250214	50~206 S 50~361 S 50~361 S 50~361 S 50~361 S	RIEDLINGER.B A RIGAMONII,G RIGGLE.E I RILEY.J L RIVELLO.J	6210060311# 6210050204# 6210070241# 6210260150 6210150204#	70-754 50-443 A 50-219 S 50-413 D 50-322 T	ROSE, B ROSE, B ROSE, B ROSE, B ROSE, B	8210210278 8210210384 8210210384 8210250071 8210260380	50-454 0 50-454 0 50-454 0 50-454 0 50-454 0
8A1, H B 8A1, H B 8A2 + P B 8A2 + H B 8A2 + H B	8210250214* 9210250269 9210250273* 8210250280 8210280066	50-361	RIVELLO, J RIVELLO, J RIZZO, O RIZZO, J RIZZO, J	8210150223# 8210150250# 8210270269# 8210050500# 8210060369#	50-322 T 50-322 T 50-317 S FOIA FOIA	ROSE. B ROSE. B ROSE. B ROSE. B ROSE. B	8210240384 8210240384* 8210240293 8210240293	50-454
PAY H B RAVY B RAY H B RAUCHYAR J W ONCHYAR	8210280048* 6210280080 8210280084* 8210070373* 8210150274*	50-206 8 50-361 8 50-361 5 50-271 0 50-271 0	RIZZO, P G RIZZO, P G RIZZO, P G RIZZO, P G RODERDS, J	8210280200+ 8210280284+ 8210280301+ 8210280313+ 8210190452+	50-318 S 50-318 S 50-317 B 50-317 B 50-382 0	ROSE, B ROSE, G ROTHSCHILD, M U ROTHSCHILD, M U	8210270305 8210270352 82100702404 8210130292 8210280259	50-454
PAILOR J H READ D F READ D F HEAD D F READALR	6210280141* 6210010328 6210010337 6210150340 6208010022	90-318 S 90-400 G 90-400 G 90-400 G M180	ROBERTS.D E ROBERTS.T K ROBERTS.T K ROBERTS.T K ROBERTS.T K	9210210505* 8205060558* 8210120112* 8210120123* 8210120140*	CONTRACT FUIA FUIA 50-537 G 50-537 A	ROUSE, L. C ROUSE, L. C ROUSE, L. C ROUSE, L. C ROUSE, L. C	8210070301* 8210070310* 8210120360 8210280452 8210280453*	50-537 A 50-537 A PRGJ 70-364 70-364
REAVIS.JA REDELLO JE REBELLO JE REBELLO JE	8210190552# 8210190791# 8210070156# 8210130054# 8210180371#	50-249 R 50-369 R CONTRACT GUNTRACT CONTRACT	RODERTS. T M RODERTS. T M RODERTS. T M RODERTS, T M RODERTS, T M	8210(20143# 8210120161* 8210120170# 821012018[# 8210120202*	50-537 A FOIA FOIA FOIA FOIA	ROME.C A ROME.C A ROZAK.S ROZAK.B RUBENSTEIN.L	8210070345* 6210210491* 8210040208* 8210080171* 8011240024*	50-219 Q 50-272 Q 50-331 Q 50-358 Q 50-247 S
AFBELLO, J E AEBELLO, J E AEBEL CASKI, T AEBEL CASKI, T AEBEL GWSKI, T	8210190215# 8210190131# 8210060046# 8210210307# 8210290174#	50-247 Q	ROBERTS, T M ROBERTS, T M ROBERTSON, C Q ROBERTSON, C Q ROBINSON, D	8210150469 8210250332* 8210010381 8210220334 8210170694*	50-155	RUBENSTEIN L S RUBENSTEIN L S RUBENSTEIN L S RUBIN S RUBIN S D	8008210627 6007030334 8108270549* 8204270464* 8111030201*	50~247 P 50~247 P FOIA FOIA FOIA
REGOAND R T REED. C REED. J G REED. J G PEEDI. R F	8210280149* 8210060367* 8210060197 8210070152 8210250247	50-267	RODINSON, D.L. RODINSON, S RODRIOUEZ, R.J. ROEDER, J. R. ROCERS, A. E.	8210190626# 8208290090 8210190278 8210270079# 8207120253#	50-295 0 50-148 H 50-312 R 71-6439 50-447 A	RUFF, A B RUFF, A B RUFF, A B RUNKLE, J RUNKLE, J D	8210010187* 8210150174* 8210220323* 8210210419 8210210348	50-424 Q 50-338 Q 50-370 Q 50-400 Q 50-400 Q
FERDI.R F FERDY.R F REEVES.E A REEVES.E A FERVES.E A	8210280157 8210280272 801(060346) 8210040038 8210280410	50-275 R 50-275 P FOIA 50-364 P 50-348 G	ROGERS, A E ROGERS, H R ROGERS, H R ROGERS, H R ROGERS, H R	8210010224* 8210060221* 8210130452* 8210130579* 8210220062*	50-327 5 50-327 5 50-328 5	RUNKLE.J D RUPP.U A RUPPEL.H D RUSSELL.B RUSSELL.J E	9210219349 9210070459* 9210050198* 9210040064 9210220476*	50-31B 8 40-6622
regay, W H rewr. T A reim. T A reimaw. F W revito W A	82022404461 82100800321 8210290423 82100603351 82102101621	COMMISSION 6	ROGERS.H R ROGERS.H R ROGERS.P ROGERS.P ROGERS.P	8210220085* 8210270277* 8210130214* 8210130388* 8210130322*	90-327 6 50-313 8 50-313 8	RVSSELL.J E RVSSELL.J L RVSSELL.J L RVSSELL.L B RVSSELL.L B	8210250028 8210270177 8210220317* 8210040142 8210040211	50-317 8 50-318 8
reijoerger, D Reiji, W F Peiii W F Pepha. D A Pepha. D A	8210260113 8210150148 8210150272 8210190385 8210280240	50-322 f	ROCERS, P ROCERS, P ROCERS, P ROCERS, R ROCERS, R F	8210190526 8210190558 8210250298 8210260123 8210010031	+ 50~368	RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B	8210040216 8210060395 8210060394# 8210139461 8210139543	50-317 8 50-317 6
resner. e p resner. h e resniksfr. h penes. l penes. l	8210180346 8210280100 8207110023 8210080088 8210080189	* 50-250 P	ROCERS.R F ROGOE.J F ROHDE,J E ROHRER.D M ROHAN.T W	8210010327 8210190271 8210260234 8210190516 8210130330	50-302	RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B	8210130548 8210190290 8210250088 8210250154 8210270297	50-317 8 50-317 8 50-318 6 50-317 6 50-318 8
REVES. L REVES. L REVES. L A REVISS. L A REVINDEDS. J R	8210190599 8210280171 8210190449 8210280232 8210050218	* 50-282 0 * 50-255 0 * 50-305 0	ROMINE. W D ROMINE. W D ROOD, H ROOD, H ROONEY. V	8210190386 8210260194 8210180258 8210210184 8210210200	* 50-328 B A 266-06 V 136-06	RUSBELL.L B RUGBELL.L B RUSBELL.L.D RUSSELL.L B RUSSELL.L B	8210270244 8210270252 8210270256 8210270272 8210270274	50-317 8 50-317 8 50-317 8 50-317 8 50-317 8
REYNOLDS: UR REYNOLDS: US REYNOLDS: US REYNOLDS: US REYNOLDS: US RHEE: S	8210050218 8210130299 8210130299 8210220383 8210050233	90-445 0 90-445 0 PR	RDONEY. V L ROOT, L D ROOT, L D ROOT, L D ROOT, L D	6210210101 8210050307 8210130544 6210150160 8210190664	* 50-331 Q 50-331 Q 50-331 P	RUSSELL, L. B RUSSELL, L. B RUSSELL, L. B RUSSELL, L. B RUSSELL, L. B	8210270274 8210270279 8210280134 8210280191 8210280194	50-317 B 50-317 B 50-318 S 50-318 B 50-318 B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCLSSION NUMBER	SUPLECT CATEGOLI
RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L D	8210280203 8210280249 8210280263 8210280279 8210280276	50-317 S 50-317 S 50-317 S 50-318 S 50-317 S	SCHULTZ.S D SCHUMACHER.M SCHUMACHER.M C SCHUMACHER.M C SCHUMACHER.P M	8210130379 8210080171* 8210040208* 8210150543* 8210150572	PR 50-358 Q 50-331 Q 50-10 Q NUREG	Shapiro, r Shapiro, r Shapiro, r Shapiro, r Shapiro, r	8210150402= 8210150410+ 8210150422+ 8210150527+ 8210250059+	50-322 , 50-322 ; 50-322 ; 50-322 ; 50-322 ;
RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSO, H L RUTENKROGER, E	8210260305 8210260316 8210280336 8210250128* 8210150605	50-317 S 50-317 S 50-318 S QA999 70-1739	SCHUMACHER, P M SCHWALB, H R SCHWEIBINZ, E SCHWEIBINZ, E R SCHWEITZER, D G	8210210014 8210210051 8210190627 8210050522* 8210120440	NUREG NUREG 50-358 S 50-483 S RES	Sharison, S S Shaub, E Shaub, T Shail, A Shah, A	820827007 <i>9</i> 8210270072* 8210210236* 8210080003*	50-322 (50-267 , 50-334 , 17DRTLIC 17DRTLIC
RUZICKA, W 6 RYDER, C RYDER, C RYDER, C P RYDER, C P	8210270057 8210050403* 8210050434* 8210050407* 8210060449*	70-687 FOIA FOIA FOIA FOIA	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8208040341 8210050479 8210050488 8210070218* 8210080068	50-373 P 50-352 A 50-322 A 50-266 P 50-397 A	SHAW, A SHAW, A SHAW, A T SHEA, J	8210080071 8210210537 8210270021 8210200036 8210040237	1PBRFLIC 70-2955 XPDRFLIC 50-372 1 50-245 F
SABADOS, J W SABADOS, J W SACKETT, M H SAFFELL, B F SAGENDORF, J F	8210010361* 8210150967* 8210220256 8210080054* 8210220149	70-27 70-1113 PR F01A Nureg	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWINK, W	8210130043* 8210190134 8210210510 8210220032 8210120216	50-414 P 50-352 A 50-322 A 50-414 P REVIEW GRP	SHEA. J SHEA. J SHEA. J SHEA. J J SHEA. J J	6210040293 9210150362 8210250219 8210010320 8210220479	50-245 P 50-245 P 50-245 P 50-245 P 50-245 2
SAIGH, PA SALUMDN, SN SALVENDY, O SALVENDY, O SANCIC, D	8210280374* 8210120316* 8208270011 8208270011 8210170435*	CONTRACT 50-259 G ACRS ACRS 50-333 G	SCINTO, J SCINTO, J SCINTO, J F SCINTO, J F SCINTO, J F	8210050536* 8210190115* 8210190121* 8210190124* 8210280348	50-289 P FOIA FOIA FOIA REVIEW ORP	SHEA.J J SHEA.J R SHEA.J R SHEARCR.D L SHEDLOSKY.J T	8210220486 8210070431* 8210070468* 8210050418 8210210196*	50-245 P FOIA FOIA NUFEO 50-245 G
SANDERS, X E SANDERS, W F SANDERS, W L SANDQUIST, G M SANDS, B P	8210070489* 8210220159* 8210010226 8210240234* 8109280175*	FOIA 50-424 0 PR 50-72 R 50-29 S	SCOTT.D E SCOTT.D J SCOTT.D J SCOTT.D J	8210150032* 8210040126 8210040188 8210050227 8210130197	50-416 Q 50-249 S 50-237 S 50-237 S 50-249 S	SHEEHY.E J SHEERAN.R E SHELKROT.E L SHELLEY.W J SHELLEY.W J	6207180086* 8210220440 6210270203* 8210220487 8210260543	Review G= 70-1100 Contract 40-8027 40-8027
Sande, 8 P Sandusky, W F Sandy, W Sanford, J C Sanford, J C	8110050018* 8210220149 8210290249 8210040024* 8210040024*	50-369 S NUREG PR 50-445 Q 50-445 Q	SCOTT.D J SCOTT.D J SCOTT.D J SCOTT.D J	8210150044 8210150097 8210180097 8210190403 8210190458	50-237 S 50-249 S 50-10 R 50-249 S 50-249 S	SHEFFEA'M A SHEFFEA'M A SHEFFEA'M A SHEFFEA'M A	8210240565 8210240574 8210270077 8210270088* 8210270242	40-8027 40-8027 40-2041 40-2061 40-8027
SANTELLA, A SARSTEN. O E BASTRE, C SATTERFIELD, R SAUNDERS, O A	8210150112* 8210260205 8210120630 8011210284 8210280046	50-219 S 50-324 S RES 50-247 P 40-8745	SCOTT. D J SCOTT. D J SCOTT. D J SCOTT. D J	8210250248 8210250283 8210250304 8210250328 8210260023	50-237 8 50-237 5 50-249 8 50-249 5 71-9079	SHELLEY.W J SHERON.B IJ SHERR.T S SHERR.T S SHERR.T B	8210270247+ 8210270075* 8204200405* 8204200408* 8204220144*	40-8027 50-289 70-1510 70-1510 70-1510
SAUNDERS,W F SAW1CK1,S D SCACE,S E SCARAND,R A SCARAND,R A	8210150103* 8207180055 8210010214* 8210120574 8210220036	50-424 Q 50-440 F 50-213 P WASTE MGT 40-8714	SCOTT, D J SCURRY, N SCURRY, N SCURRY, N SCURRY, N	8210270251 8210120402 8210120404 8210270116 8210270119	50-249 S ORG ORG ORG ORG	SHERR, T S SHERR, T S SHERR, T S SHERR, T S SHERR, T S	8210050451* 8210050456* 8210070418* 8210070421* 8210070434*	70-1510 70-1510 FOIA FOIA FOIA
SCARAND, R A SCHANEN, J F SCHAPKER, J F SCHEINER, C A SCHERER, A E	8210220037 8210130566* 8210150334* 8210200019 8210150306	WASTE MGT 50-306 Q 50-518 Q 50-247 Q 50-470 E	SECOR, D T SEIDLE. W C SEIDLE. W C SEIDLE. W C SEIDLE, W C	8210170457* 8210010175 8210070326 8210120241 8210120246	50-395 P 50-313 Q 50-295 Q 50-313 G 50-313 Q	SHERR.T S SHERR.T S SHERR.T S SHERR.T S SHCRR.T S	8210070436* 8210070447* 8210070467* 8210070473* 8210070475*	FOIA FOIA FOIA FOIA
Scherer, a e Scherer, a e Scherer, a e Scherr, s J Scherrer, J	8210200022 8210280202 8210290240 8210290901 8206300188*	50-368 P 50-470 B PR 70-143 50-155 Q	SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8210190347 8210190497 8210190531 8210190596 8210220110	50-285	SHERR, T S SHERR, T S SHERR, T S SHERR, T S SHERRER, J	8210070478* 8210070480* 8210070484* 8210070486* 8208100269*	FOIA FOIA FOIA SO-29 P
SCHERRER, J SCHIFFMACHER, W SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D	8207190431* 8210150168 8210050152 8210050152 8210150035	50-29 0 50-322 T TDPREP TOPREP 50-335 8	SEIDLE.W C SEIDLE.W C SEIDLE.W C	8210220270 8210220377 8210240178 8210240224 8210280225	50-313 0 50-313 0 50-313 0 50-72 R 50-482 0	SHERWOOD, O G SHERWOOD, O O SHERWOOD, O O SHEWMON, P SHEWMON, P	8210010217 8210050328 8210270046 8207180073* 8208290017	TOPREP 50-447 A 50-447 A NUREO ACRS
	8210060354* 8210120440* 8210150257* 8210150265* 8210150290*	50-261 F CONTRACT 80-322 T 50-322 T 50-322 T	BELAN, J C BELAN, J C BELBY, D SEMMEL, H SEMMEL, H	8209130461* 8209200475* 8210290006* 8210150341 8210150341	50-293 P 50-29 P COMMISSION 50-155 G 50-155 G	SHEWION, P SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W	8208290018 8210010230 8210250130 8210290239 8210290240	50-244 : PR 50-546 3 PR PR
	8210280451 8210190599* 8210120092 8210120102 8210050299	40-8697 50-295 Q NUREO NUREO 50-480 A	SEMMEL.H SEMMEL.H SENIUM.P SERINI.B L SESTAK.F	8210210381 8210210381 8210250231* 8210280421* 8210250308	50-155 Q 50-155 Q 50-346 S 70-2957 50-275 R	SHIFFER. J D SHIM. K SHIM. K BHIMECK. D J SHIRAKAWA, T	8210290219 8210040247* 8210190715* 8210150409 8210040382	50-275 \$ 50-304 \$ 50-275 \$ RES XFORTLIC
	8210130555* 8210130176* 8210120488* 8210150102* 8210180100*	50-463 G 50-254 B CONTRACT 50-249 S 50-10 R	SHAFER.P N SHAFER.W SHAFER.W D SHAFER.W D SHAFER.W D	8210130416* 8210040337 8210050154* 8210170362* 8210170750*	50-409	SHIRAKAWA, T SHIRAKAWA, T SHIRAKAWA, T SHIRAKAWA, T SHIRLEY, S	8210040385 8210040387 8210040471 8210280435 8210080077	XPORTLIC XPORTLIC XPORTLIC XPORTLIC 50-142 F
	8210270254* 8210040221 8210050077 8210130233 9210130241	50-249 B 50-373 P 50-373 P 50-373 P 50-373 P	SHAMLA, W A SHAD, L C SHAPIRO, R SHAPIRO, R SHAPIRO, R	8210080117 8210070205* 8210150234 8210150234 8210150307*	50-263 S 50-266 P 50-322 0 50-322 0 50-322 0	SHIVELY, C SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J	8210270101 8210150464 8210200006 8210260433 8210260447	50-348 P 50-445 £ 50-289 ¢ 50-289 ¢ 50-209 ¢
	8210190606 8210070196* 8210130199* 8209150057 8210220369*	50-373 & FOIA 50-244 \$ FOIA 50-275 H	SHAPIRO.R SHAPIRO.R SHAPIRO.R SHAPIRO.R SHAPIRO.R	8210150324* 8210150337* 8210150351* 8210150365* 8210150393*	50-322	SHOEMAKER, C J SHON, F J SHON, F J SHON, F J SHON, F J	8210280269 8210050254 8210070137 8210130333 8210150092	50-289 0 50-247 0 50-440 0 50-440 0 50-247 0

MO THOR	ACCESSION	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SHOWER USES FOR SHOWER USES FOR SHOWER USES FOR SHOWER USES FOR SHOWER TO SHOW IT TO SHO	8210210349 8210210476 8210220338 8210270176 8210220128#	90-155	SMITH. FI & SMITH. P A SMITH. P A SMITH. P A	8210040277 8210130041# 8210040002# 8210040004# 82101420425#	50-316 S CONTRACT CONTRACT CONTRACT CONTRACT	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8210130514 8210130523# 8210190432 8210190433 8210190368	50-493 0 50-493 0 50-282 0 50-287 0 50-275 0
SHORD, E M SHORD, E M SHEEL, D B SHORD E HIS MUGAREL P	8210050162 8210190746# 9210050530# 8210070240# 8210220504	50-367 0 50-285 R CONTRACT 70-33 50-329 T	SMITH, P A SMITH, P A SMITH, P A SMITH, P A SMITH, P A	8210120496# 8210120517# 8210120541# 8210120613* 8210130074#	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8210190613 8210190638 8210190707* 8210250072 8210250075*	50~295 0 50-409 0 50-255 0 50-341 0 50-341 0
emine. It H eminimosky to steden. U D eteden U D etemen. D L	8210160072# 8210010225# 8210050168* 8210260125# 8210120320	F01A 50-03B 0 50-334 P 50-004 P 27-09	SM[1H, P A SM1TH, P A SM1TH, P A SM1TH, P A	9210190338* 9210180401* 9210190416* 9210190149 9210190156*	CONTRACT CONTRACT CONTRACT CONTRACT	SPESSARD.R L SPESSARD.R L SPESSARD.R L SPESSARD.R L SPESSARD.R L	8210250104 8210260161 8210260387 8210280122 8210280174+	50-409 0 50-305 0 50-454 0 50-373 0 50-461 0
STEGEL.B STANID G STUDENG JE STUDENG JE STUDENG JE	8210180320 8210173043* 8210050374 8210050374 8210150161	50-298 F CONTRACT 50-440 G 50-440 G 50-440 G	Smith.p A Smith.p A Smith.p A Smith.p A	8210170162 8210170167* 8210170223* 8210210161* 8210210506*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SPICKLER.I SPILHAUS.A F SPITZBERG.D B SPRENCEL.J F SRENIAWBKI.D J	8210040453* 8210190002* 8210220004 8210120330* 8207070319	50~537 A CONTRACT 70-416 CONTRACT 70-2748
FILBERG. JE FILBERG. JE FILDERG. JE FILDERG. JE FILDERG. JE	8210150161 8210150228 8210150228 8210210284 8210210284	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G	SM(TH, P A SM(TH, P A SM(TH, P A SM(TH, P A SM(TH, R D	8210260520* 8210260530* 8210280235* 8210270378* 8210120578	CONTRACT CONTRACT CONTRACT CONTRACT 40-8102	JUSHAINARE L G IJASHAINARE L G IJASHAINARE L G IJASHAINARE J G IJASHAINARE	8210040130 8210050204 8210050314 8210190533* 8210260471	1&E 70-2942 1&E State Prog 1&E
SILCERG. J E EILSERG. J E CILCERG. J E CILCERG. J E CLOERG. J E	6210210357 621021035	50-440	SMITH, R D SMITH, R D SMITH, R L SMITH, R M SMITH, S K	8210210521 8210210532 8210070154* 8210280095* 8210150377*	40-3453 40-8681 CONTRACT 50-324 P 50-263 P	STADNICK, S STAHL. D M STAHL. D M STAHLE, C STAMIRIS, B	8210130232* 8210130482 8210130482 8210210542 8210210542	50-336 S 50-329 0 50-329 G 50-327 P 50-329 0
RIERG.JE NEEPO.JE JLLEPHON.S JLLIS.R M JLVIS.R M	8210250322 8210260216 8210150625 8210120363 8210220403	50-440 G 50-440 O RES CONTRACT CONTRACT	SMITH. W Q SMITH. W Q SMITH. W Q SMITH. W Q	6210040073 6210040199 6210040201 6210040212 6210040321	50-315 8 50-315 8 50-314 8 50-315 P 50-314 8	STAMERIS, D STAMPLEY, N STAMPLEY, N STAMSBERRY, N STAMSBERRY, N	8210050240 8210210370 8210050193 8210260515* 8210180007*	50-329 0 50-329 0 50-416 S 50-335 0 50-348 0
11015.8 8 1 195.8 1 1951.8 A 1 196.05 0 E	8210280386 8210190040* 8210120264 8210220198 8210150025#	CONTRACT 50-345 F 90-528 R 50-520 R 50-347 0	SMITH.U G SMITH.U G SMITH.U G SMITH.U G	8210020300 8210180120 8210190266 8210190340 8210190380	50-315 8 50-316 5 50-315 8 50-315 8 50-315 8	STARK,R M STARK,R M STARK,R M STARK,R M STARK,R M	8208270699 8210120445 8210130069 8210220023 8210280436	50-537 A 50-537 A 50-537 A 50-537 A 50-537 A
IT JULEAUN F P INCLAIR M INCLAIR M INCLAIR M INCERMAN R W	8210049302% 8210670140 8210070140 8210170480 8210150307#	CONTPACT 50-329 0 50-329 0 50-255 0 50-155 0	SNIEZEK, J H SNITH, W O SNITH, W R SNITH, W R	8210190572 8210190727 8210190749 8210050368 8105040512#	50-315 S 50-316 S 50-315 S NUREO 50-285 P	STARKEY.R D STARKEY.R B STARKEY.R B STARKEY.R B STARKEY.R B	8210130242 8210190240 8210220265 8210220499* 8210290074	50-261 R 50-261 S 50-261 S 50-261 G 50-261 G
10* 140. 8 111 140.8; J 1 > 16:168. P 16 > 11:168. P 11 • 11:158. J 1	8210120455 8210260235* 8210170132* 8210120307* 8210010467*	RES CONTRACT 50-324 Q 50-321 Q 50-375 O	SNICZEW, J H SNIEZEK, J H SNGW, B A SNYDER, B J SNYDER, B J	8107170126* 8210050082* 8210170703 8210260535 8210270328	F01A F01A 50-244 8 50-320 P 50-320 P	STARKEY.R B STARMER.R J STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8210270333 8210120354 8203050387 8210010274* 8210060024	50-261 S WASTE MGT 50-317 O 50-220 O 50-247 O
FCLDS, J.L. FULLHOLLT, D.J. ENCER, R.J. ENCER, R.J. ENCER, E.M. WITH, E.M.	8210080259* 8210290034* 8210040196* 8210210178* 8210120956*	50-395 Q 50-142 F GA999 CONTRACT CONTRACT	SNIDER, S.C. SODA, K. SOLLEMBERGER, D. SOLLEMBERGER, D. SOO, P.	8210200102 8210150421 8210120494 8210120514 8210120460	RES REG 40-8728 40-2259 RES	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8210060150 8210060240 8210060318 8210070214 8210070239	50-293
13TH E M 11TH C C 11TH C C 11TH C C 11TH C C	0210120556* 0210040049* 0210110449* 0210220172* 0210040206	CONTRACT 50-24 Q XPORTUIC 70-371 50-286 F	SURRELL, E C SUPRELL, E C SOUCY, A R SPARKS, O L SPARKS, O L	8210190016* 8210190046* 8210010374 8210010248* 8210090203*	50-321 F 50-321 F PR 50-416 S 50-416 S	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	9210070268 9210070337 9210070357 9210070352 9210070376	50~219 0 50~220 0 50~309 0 50~333 0 50~271 0
117H, 0 H 117H, 0 H 127H, 0 H 117H, 0 H 117H, 0 H	8210040202 8210040304 8210080063 8210150055 8210040379	50-220 0 50-27 0 50-217 P 50-322 0 50-29 P	SPARKS, G L SPARKS, G L SPARKS, G L SPECTER, A SPECTER, B M	8210060224* 8210220162* 8210220191* 8208010014* 8210130648*	50-416 S 50-416 S 50-416 S 50-289 H 50-244 F	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	9210130271 9210130303 9210130476 9210130556 9210150001	50-277 0 70-135 70-1100 50-247 0 50-293 0
ITH E H ITH. E H ITH E H ITH. J A ITH. J C	8210010427 9210150476 8210150480 8210130132* 8210150601	50-207 0 50-514 0 50-440 0 50-321 R 40-6622	SPELMAY, H J SPELS, T P SPELMAY, H J SPELMAY, H J	8210220096* 8010280078 8011110084 8210150463 8210250315	40-8111 50-247 P 50-247 P 40-2041 40-2061	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8210150015 8210150076 8210150083* 8210150214 8210150221	50-334 0 50-287 0 50-287 0 50-317 0 50-287 0
117H, J C 117H, J C 117H, J E 117H, J E 117H, J E	8210180420* 8210240013 8210010218 8210010232 8210010232	40~6622 40~6622 PR PR PR	SPELMAN, H J GPENCER, D SPENCER, M D SPESSARD, R SPESSARD, R	8210250319 8210040134* 8210010302 8210080088 8210080187	90-275 S 50-216 B	STAROSTECKI: R STAROSTECKI: R STAROSTECKI: R STAROSTECKI: R STAROSTECKI: R	8210150244 8210150271 8210150299 8210190702* 8210190797	50-271 9 50-233 9 50-277 9 50-317 9 50-317 9
17H, J K 17H, J K 17H, J K 17H, J L 17H, J L	0210150500 0210150504 8210150507 8210280034 8210280037	• 50~263 P • 50~263 P • 50~322 F	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	6210040070 8210050304 6210050336 8210060264 8210060357	50-461 A 50-331 Q 50-155 Q 50-373 Q 50-237 Q	STAROSTECKI: R STAROSTECKI: R STAROSTECKI: R STAROSTECKI: R STAROSTECKI: R	8210210100 8210210182 8210210241 8210210300 8210210464	50-333 0 50-245 0 50-423 0 50-247 0 50-272 0
THE J R THE J R THE G THE G THE M J	82101503501 8210180362 8210270227 8210060400 8210150495	# CONTRACT # 40-8632 # 50-247 8	SPESSAPD.R L SPESSARD.R L SPESSARD.R L SPESSARD.R L SPESSARD.R L	8210080190 8210130186 8210130211 8210130240 8210130484	50-237 Q 50-263 Q 50-409 Q 50-461 Q 50-463 Q	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8210220153 821022034 8210220134 821026025 8210260257#	50-29 Q 50-244 Q 50-322 Q 50-320 Q 50-387 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AU FHOR	ACCESSION NUMBER	evelet Cated 11
STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8210260483 8210290147 8210290171 8210290189 8210290208	50~289 S 50~29 Q 50~244 Q 50~213 Q 50~352 Q	STOLZIJ F STOLZIJ F STOLZIJ F STOLZIJ F STOLZIJ F	8210270342 8210270372 8210270382# 8210270387* 8210270143*	50-287 P 50-346 P 50-346 P 50-346 P 50-313 P	TARIS, D N TAUSER, H TAUSER, H TAUSER, H TAUSER, H TAUSER, H	8210270222 8210010456 6210080046 8210150322 8210160160	40-8612 50-341 a 50-341 a 50-341 a 50-341 a
STAROSIECKI.R STAROSTECKI.R STASEK.8 STASZESKY.F M STEED.L L	8210290212 8210290300 8210250114* 8204160212 8210060096*	50-244	STOLZ, J F STOLZ, J F STOLZ, J F STONE, J C STONER, M A	8210270148* 8210270382* 8210270387* 8210040373* 8210210301*	50-313 P 50-346 P 50-346 P 50-315 Q 50-329 A	TAUGER. H TAUGER. H TAYLOR. D TAYLOR. D TAYLOR. J	8210190896 8210220414 8210260446 • 8210150560 8210120270	50-24) 6 50-34: 4 50 24° 5 NUFEC 50-413 •
STEELE.R L STEELE.R L STEELE.W J STEFAND.J STEFAND.J	8210250084 8210250164 8210150089* 8210190011 8210270073	50-344 5 50-344 5 50-311 5 50-440 F 50-440 A	STGVER, J R STREETER, J STREETER, J STREETER, J STREETER, J	8210180332* 8210040178 8210080088 8210080189 8210260447	CONTRACT 50-237 S 50-295 S 50-316 S 50-254 S	TAYLOR, J H TAYLOR, J H TAYLOR, J H TAYLOR, J W TAYLOR, P A	8209090009 8210060346 8210250132 8210130381 8210150569•	TOPAEP TOPAEP P T 21 P R 50-38+
STELLO. V STELLO. V STELLO. V STELLO. V	8210170631 8112210166* 8210010109* 8210010286 8210040314	REVIEW GRP FOIA 50-366 6 REVIEW GRP REVIEW GRP	STREETER, J F STREETER, J F STREETER, J F STREETER, J F STREETER, J F	8210050253 8210050274 8210150249 8210150385 8210150497	50-346 0 50-315 0 50-282 0 50-263 0 50-409 0	TAYLOR, R G TEDESCO, R L TERC, IT M TEST, R Z THADANI.A	8210190820 + 8210260482 + 8210190059 + 8210270249 + 8203190016 +	50 444 1 50 409 4 50-362 6 50 213 5 50-537 1
STELLO, V STELLO, V STELLO, V STELLO, V	8210080109 8210080176* 8210120053* 8210150138 8210180002	REVIEW ORP FOIA REVIEW ORP REVIEW ORP REVIEW ORP	STREETER, J F STREETER, J F STREETER, J F STREETER, J F STREETER, J F	8210150523 8210150530* 8210170421 8210170427* 8210170643	50-10 Q 50-10 Q 50-255 Q 50-255 Q 50-331 Q	THATCHER, T L THATCHER, T L THATCHER, T L THATCHER, T L THIES, A C	8210080073 8210080073 8210080073 8210220434 8210260331	50-522 (50-522 (50-522 (50-522 (50-54) (
STELLO, V STELLO, V STELLO, V STELLO, V	8210170004 8210250131 8210250154 8210270178 8210280031*	REVIEW GRP REVIEW GRP REVIEW GRP REVIEW GRP 50-334 P	STREETER, J F STREETER, J F STREETER, J F STREETER, J F STREETER, J F	8210250105 8210250109* 8210280164 8210280168* 8210280223	50-373 0 50-373 0 50-282 0 50-282 0 50-305 0	THOMA, J O THOMA, J O THOMA, J O THOMA, J O THOMAS, B R	8210040406 8210080049 8210130047 8210130063 82101803584	50-206 / 50-247 / 50-261 f 50-265 / FOIA
STELLO V STEPHENSON, C J STEPTOE, P STEPTOE, P STEPTOE, P P	8210280351* 8210130524* 8210050223 8210050223 8210050215	REVIEW GRP 50-289 S 50-329 G 50-329 G 50-329 G	STREETER. J F STREETER. J F STRENGE. D L STRON. P O STUCKY, S W	8210280226* 8210280229* 8210270041* 8210270338 8210180147	50-305 0 50-305 0 50-537 0 NUREG 50-397 0	THOMAS, C O	8210040394 8210050460 8210050540 8210050543± 8210070074	T 0568P 50-461
STEPTOE, P P STEPTOE, P P STEPTOE, P P STEPTOE, P P STEPTOE, P P	8210050215 8210080082 8210080082 8210080079 8210080079	90-329 0 50-255 0 90-255 0 50-255 0 50-255 0	STUCKY, S W SUBRAMONIAN, N SUGARMAN, R J SUGARMAN, R J SUGARMAN, R J	8210250325 8210120640# 8210010244 8210010244 8210180204	50-289	THOMAS, C O THOMAS, C O THOMAS, C O THOMAS, C O THOMAS, C O	8210070110 8210120475 8210120480* 8210120492* 8210120413	TOPFF9 50-62 / 50-62 F 50-62 I 50-142 I
STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M	8210010053 8210060155 8210060330 8210060341 8210070158	50~344	SUGARMANIR J SUGARMANIR J SUGARMANIR J SUGARMANIR J SUGARMANIR J	8210180204 8210180208* 8210180208* 8210180217 8210180217	50-352 G 50-352 G 50-352 G 50-352 G	THOMAS, C O THOMAS, J	8210150481 8210180027 8210220185 8210240504 821007027\$*	T GPAEP T GPAEP T GPAEP 50-157 P 50-219 1
STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M	8210070278 8210070290 8210070297 8210070319 8210070378	50-312 Q 50-312 Q 50-397 Q 50-312 Q 50-460 Q	SUQARMAN,R J SUQARMAN,R J SUQARMAN,R J SUQARMAN,R J SUQARMAN,R J	8210180223 8210180223 8210180224 8210180224 8210180226*	50-352 0 50-352 0 50-352 0 50-352 0 50-352 0	THOMAS, L M THOMAS, L M THOMAS, R D THOMAS, R D THOMAS, R D	8210070109 8210250170 8210080311+ 8210130130 8210260304	50-445 F 50-10 F 70-754 27-48 27-10
STEBNBEDD V M	001388864			8210180226* 8210180253 8210180253 8210190364 8210210477*	50-352 0 50-352 0 50-352 0 50-327 K 50-272 0	THOMPSON, D THOMPSON, T R THOMPSON, T R THOMPSON, V J THOMSEN, F J	8207180041 8210070099* 8210270288* 8210220246 8210010382	FDIA 50-27 50-105 PR 50-522 (
				8210060248* 8210270334* 8210270364* 8210270381* 8210010064	50-346 B 50-321 S 50-346 S 50-346 S 50-537 Q	FHOMSEN, F T THOMSEN, F T THOMSEN, F T THOMSEN, F T THOMSEN, F T	8210050171 8210050171 8210130190 8210130367 8210130367	50-522 (50-522 (50-522 (50-522 (
				8210060183 8210200047 8210200080 8210250383 8207140471*	50-537 Q 50-537 Q 50-537 Q 50-537 Q 50-373 Q	THOMSEN, F T	8210130498 8210130498 8210200045 8210200045 8210260420	50-522 F 50-522 F 50-522 F 50-522 F 50-522 F
				8210120105 8210130376 8210190443 8210190445 8210220335	50-237 P 50-10 F 50-295 P 50-237 P 50-237 P	THORNTON, P THORNTON, P THORNTON, P THORNTON, P THORNTON, P	8210050232 8210050232 8210050356 8210050356 8210150470	50-155 50-155 50-155 50-155 50-155
				8210260151 8210010284* 8210270015 9210070381* 3210050360	50-373 P 50-329 E 50-537 O 50-309 Q NUREO	THORNTON, P THORPE, A A THORPE, J R THORPE, J R THORSEN, E O	8210150470 8210260407# 8210130574 8210220372 8210220375	50-155 6 50-259 5 PR PR 50-247 6
				3210130294 3210180154 3210290242 3210290253 3210280204*	50-358 A 50-358 A PR PR 50-277 P	THULL, T 8 THULL, T 5 THULL, T 5 THULL, T 5 THULL, T 5 TIETZ, O	8210210430* 8210220108* 8210220116* 8210220201* 8210130423*	50-245 \$ 50-245 \$ 50-245 \$ 50-245 \$ 50-245 \$
)210260223*)210190444*)210080045)210150656)210050360	50-304 8 50-375 P 50-334 F TOPREP NUREG	Tillmail A Timbon. B S Tipps. S B Tipps. S B Tipps. S B	8210150380* 8210210041 8210010098* 8210050084* 8210060289*	70-243 50-201 / 50-366 \$ 50-366 \$ 50-366 \$

	ACCESSION NUMBER	SUBJECT CATEGORY	ROHT VA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TIPES D TIPES D TIPES D TIPES D TIPES D TIPES B	8210760324* 8210780240* 8210130185* 8210130224* 8210130256*	90-366 S 90-366 S 90-366 S 90-366 S 50-366 S 50-321 S	TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B	8210010134+ 8210010282 8210010382 8210010387 8210010463*	50-413 0 50-349 0 50-249 F 50-370 0 50-269 0	UHRIG, R E UHRIG, R E UHRIG, R E UHRIG, R E UHRIG, R E	8210050416 8210050567* 8210060236 8210060276 8210060281	50-397 A 50-335 F 50-387 8 50-389 A 50-250 P
TIPES S B	8210130414# 8210130549# 8210191511# 821019060# 8210220282#	50-364 S 50-366 S 50-366 S 50-366 S 50-321 S	TUCKER, IC B TUCKER, IC B TUCKER, IC B TUCKER, IC B TUCKER, IC B	8210040107 8210040232 8210040254 8210040273* 8210050130	50-269 P 50-269 P 50-369 K 50-369 K 50-413 A	UHRIG:R E UHRIG:R E UHRIG:R E UHRIG:R E UHRIG:R E	8210060288 8210060371 8210080264 8210130090 8210130287	50-367 R 50-365 Q 50-367 6 50-369 E
1162 6 8 1162 6 8 1163 6 8 1164 6 8 8	0210;40274# 0210240109# 0210240109# 0210540204# 0210;40274#	50-321 S 50-366 5 50-321 S 50-366 S 50-321 S	TUCKER, H B	8210050264 8210050384 9210060311 8210070072 8210070092	50-413 A 50-413 A 50-413 A 50-369 F 50-413 A	UHRIO, REUHRIG, REUHRIG, REUHRIG, REUHRIG, REUHRIG, REUHRIG, REUHRIG, REUHRIG, RE	8210130289 8210130301 8210130348 8210130399 8210130534	50-389 A 50-389 F PR 50-389 B
(「FPT ら b (FPP 5 B (FPP 5 B (FPP 5 B	8010290339# 8010290359# 8010290375# 6210270327 8210270332#	50-321 5 50-321 5 50-321 5 50-382 f1 50-382 M	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8210080208 8210130159 8210130177 8210130262 8210130270	50~413 5 50~269 P 50~369 5 50~369 K 50~269 Q	UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E	8210150407 8210150439 8210150186* 8210150310 8210150348	50-250 P 50-250 F 50-335 P 50-389 A
OBJANEA OBJANEA OBJANEA OBJANEA OBJANEA OBJANEA	8210150180# 8210010371# 8210130545 8210190774# 8210010257	50-263 5 70-143 MIRC 50-445 0 50-237 0	TUCKER, IF B TUCKER, IF B TUCKER, IF B TUCKER, IF B TUCKER, IF B	8210130399 8210130467 9210130502 8210130599 8210150068	PR 50-369 P 50-287 P PR 50-413 0	UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE	8210190351 8210190371 8210190440 8210190559 8210220090	50-335 F 50-250 F 50-250 P 50-251 P
CHAPTES I A CHAPTES B A LIVER B B A CHAPTES B A CHAPTES B A	8 (1604009) 8: 10050275 8:10060191 8:1077031) 8:10 (80=56	50-31,	TUCKER, H B	8210150094 8210150369 8210150518 8210150617 8210180055	50-413 K 50-269 0 50-369 F 70-2944 50-269 F	uhrio, r e uhrio, r e uhrio, r e uhrio, r e uhrio, r e	8210220167 8210220214 8210220286# 8210220304# 8210220304#	90-389 9 50-389 0 90-335 0 50-250 0 50-395 0
CHERLE A CTURE E A CHERLE A CHERLE A CHERLE A	8210170573 8210190469 8210190505 8210190546 8210170117	50-155 P 50-155 P 50-255 P 50-255 P 90-155 P	TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B	8210180040* 8210180128 8210170103* 8210170544 8210170611	50-267 P 50-370 A 50-369 F 50-269 R 50-413 F	UHRIC, R E UHRIO, R E UHRIO, R E UHRIO, R E UHRIO, R E	8210250313 8210250317 8210260391# 8210270253 8210280067	50-387 A 50-337 R 50-335 0 50-350 P 50-387 E
THING, THE THE THE A PARTIE A A PARTIE A A PARTIE A A PARTIE A PARTIE A PARTIE A A PARTIE A A PARTIE A	85101503034 85101500954 85101504514 85101505184 85101010191	50-237 5 50-10 0 FUIA 701A 50-247 0	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8210190740 8210190742 8210210131 8210210407 8210220134	50-370 F 50-349 R 50-249 P 50-249 P 50-413 Q	WHRIO, R E UMRIO, R E UMRIO, R E WLLRICH, J ULRICH, W T	8210280254 8210280271 8210270240 8210130215* 8210130272*	50-389 A 50-250 F PR 50-373 R 50-277 P
TH A D TI 4811 37te, 1 TILETID R HILLETID R	#510080139 #510080138 #510750334 #510750334	50-397	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	0210250102 0210220158 0210220316 0210220203	50-369 Q 50-369 Q 50-369 S 50-269 Q 50-413 D	UNTERMEYER UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M	8210130076 8210010143* 8210010350* 8210150052* 8210150132*	XPORTLIC 50-413 0 50-324 0 50-324 0 50-324 0
COLLEGE DE RESTRESSE DE R	8510250488 8510506585 8510506585 8510506585	50-537 0 50-537 0 50-537 0 50-537 0 50-537 0	TUCKER, H D TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8210250304 8210260201 8210270139* 8210280017* 8210280065	50-369 P 30-413 A 50-369 F 50-369 F 50-413 E	UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M	8210150256* 8210150315* 8210220145* 8210220307* 8210220307*	50-327
CONTRACTOR OF THE CONTRACTOR O	U.10. 70295# U210720295# U210720295# U210720297 U20130057 U20130057	90-53/ 0 50-537 0 10018ACT	Tucker, H B Tucker, H B Tucker, H B Tucker, H B Tucker, H B	6210270045 6210270083 6210270117 6210270170 8210270250	50-370 \$ 50-270 \$ 50-413 \$ 50-269 \$ 50-413 \$	VALKOVIC.M M UTECHT.R D UTECHT.R D URYC.B URYC.B	8210220406* 8210220406* 8210220469 8210210054	50-400 G 50-438 G PR PR NUNCG
r et. T ft	6210010±02 6210010±71 6210740060 6/10040249 6/10190294	50 454 E 50-454 A 50 454 K 50 457 9 50-456 5	Tucker, H B Tucker, H B Tucker, H B Tupper, K F Turk, B E	0210290308 8210290354 8210290358 8210080339 8210040059	50-287 S 50-413 S 50-269 S XFDRTLIC 50-382 Q	VALKOVICA H VAN BRUNTAE E VAN BRUNTAE E VAN BRUNTAE E VAN BRUNTAE E	8210220154 8210060413 8210070371 8210040272 8210040305*	NUREO 50-529 G 50-529 B 50-529 H
APH 1 P APH 1 P APH 1 P APH 2 C AN A C	8210170552 8210220354 8210270104 8210170354 8210170427	50-496 8 50-10 F 50-454 E 50-344 P * 50-282 P	Turk. H E Turk. H E Turk. G E Turk. G E Furk. S E	8210040061 8210060183 8210080070 8210130124 8210130183	50~382 0 50~382 0 50~382 0 50~445 0 50~445 0	VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E	8210040245 6210070210 6210070213 8210070217 6210070227	50-528 A 50-528 G 50-528 B 50-528 B
2HAN, H K 2HAN, H K 2H JUN K 1HAN, H	8203310094 8204120487 8205180693 8219270402 8219270400	* 50-311 P * 50-281 8 * 50-281 8 * CONTRACT	TURK. S E TURK. S E TURK. S E TURNAGE. K O TURNER. L C	8210130364 8210230288 8210230288 821023037 8210130304	50-445 G 50-382 G 50-282 G NUREO 50-413 D	YAN DRUKT. E E VAN BRUNT. E E VAN BRUNT. E E VAN BRUNT. E E VAN BRUNT. E E	8210070320 8210070321 8210070359 8210070354 8210070374	50-520 8 50-520 8 50-520 8 50-520 8 50-520 8
IFINAC.H B IFENAC.H B IMBLE.D C IMP PP L F	0210270408 8210150235 8210060376 8210070275 8210210477	50-275 0 50-317 0 50-217 8 50-217 0	TURNOUEST, L UDELL, R A UDELL, R A UDELL, R A UDERITZ, R A	8210170471 8204040032 8210010004 8210080010 6210120328	FOIA FOIA FOIA	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8210080155 8210130187 8210130443 8210130446 8210130491	50-526 G 50-526 G 50-520 G 50-530 G 50-530 B
PP 1 E MERIDOE.O F MERIDOE.O F MERIDOE.O F MERIDOE.O F MERIDOE.O F	9210210173 9210210173 9210210175 9210210175 921021037	3 50-320 0 3 50-320 0 7* 50-320 0 3* 50-320 0	UDERITZ.R A UDY.A C UDY.A C UHRIG.R E UHRIG.R E	82101500BD 6210250372 6210280432 6209170062 6210010017	* 50-213 P * 50-247 P 50-250 F	VAN BRURT, E.E. VAN BRURT, E.E. VAN BRURT, E.E. VAN BRURT, E.E. VAN BRURT, E.E.	8210130495 8210130544 8210150163 8210130176 8210170318	50-528 E
HER. H B HER. H B HER. H B HER. H B	931931937- 921927000- 920917005- 921001009- 921001009-	A 50-289 0 7 XPORTLIC 3 50-413 F 0 50-369 0	UHRIO, R E UHRIO, R E UHRIO, R E UHRIO, R E UHRIO, R E	8210010084 8210010153 8210010272 8210010271 8210050041	14 50-335 G 50-250 P 14 50-250 Q	VAN BRUNT.E E VAN BRUNT.E E. VAN BRUNT.E E. VAN BRUNT.E E VAN BRUNT.E.E	9210190463 8210190717 8210220394 8210250100 8210250305	50-528 A 50-528 G 50-528 B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	Y.	AU THÛR	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCESSION NUMBER	SUBJECT CARE
VAN BRUNT, E E	8210250326	50-528	5	VEITCH, J L	8210150544*	0A999		WALKER, R	8210260457	50 2*4
VAN BRUNT, E E	8210260275	50-528	š	VERRELL?.D	8210180004	50-340	0	WALKER, R D	821015038A=	50-267
VAN BRUNT, E E	8210270211	50-528	Ā	VERRELL!, D	B2102A0245	50-327	0	WALKER, R D	8210150502+	50 107
VAN BRUNT, E E	8210280057	50-528	Ä	VERRELLI, D M	8210010086	50-400	Q	WALKER, R. D.	0210150538×	50-10
VAN BRUNT, E E	8210280139	50-528	Ä	VERRELLS, D M	8210010130	50~83	O	WALKER, R D	0210250116*	50 373
VAN BRUNT.E E	6210280199	50-528	A	VERRELLI, D M	8210010132	50-324	Q.	WALLACE, T	£810280183	50 223
VAN BRUIT. E E	8210280274	50~528	E	VERRELLI.D H	8210010148	50-416	0	WALLICK, M É	Ø210190215+	CBMB//
VAN ERP. J B	8210150557	NUREG		VERREL LI. D M	8210010171	50~324	o .	WALSKE, C	8204040013+	COMMITTEE
VAN RIPER. D G	8210080033	XPORTL (C		VERRELLI, D M	8210010173	50-241	Q	WAMBACH, T V	6510150353	50 255
VAN ROOYEN. D	8210120370	RES		VERRELLI, D M	8210010171	50-438	a	WARD, E C	8210020184	50-283
VAN SYCC. C	8207190051	50-219	H	VERRELLI.D (1	8210010200*	50-438	0	WARD, E. C.	9210250200	50-262
VANDEL T E	8210140908	50-482	Q	VERRELLI, D II	B210010333	50-390	g .	NARD, K D	8510000308*	50-463
VANDENDERG, D	0210130145*	50-255	R	VERRELLI.D M	8210010336	50-324	Ø	WARD, W J	8010130163	50-247
VANDERMOLEN, H	8103050756*	FOIA		VERRELLI, D M	0210010340*	50-324	g .	WARD W J	8101140002	50-224
VANDEWALLE: D J	8210040342	50-155	P	VERRELLI.D M	8510010411	50-518	Q	WAREMBOURG	6210040114	50 267
VANDEWALLE, D J	82100503424	50-155	Q	VERRELLI, D M	8210010421	50-438	Q.	WARE MOGURG. D	9209150440*	5-0~247
VANDEWALLE, D J	8210050425	50-155	P	VERRELLI, D M	82100104264	50-518	Q	WAREMBOURG, D	8210050331	50-267
VANDEWALLE, D J	0210060152	50-155	P	VERRELLI, D M	8210010430	50-259	G .	WAREMBOURG, D	8210130344	50-267
VANDEWALLE, D J	9210060222	50-155	F	VERRELLI, D M	8210010442	50-414	0	WAREMBOURG, D	8210190537	50-267
VANGEWALLE, D J	8210060239	50-155	p	VERRELLI.D M	8210010452	50-390	q	WAREMBOURG D	8210190655	50~247
VANDEWALLE.D J	8210070013	50-155	ρ	VERRELLI, D M	8210150024	50~390	Q	WAREMBOURG. D II	8210080256	50-247
VANDEWALLE.D J	8210080279	50-155	a	VERRELLI.D M	8210150108	50-324	0	WAREMBOURG, D W	8210190306	50-767
VANDEWALLE.D J	0210130334	50-255	P	VERRELLI, D H	8210150149	50-438	a	WAREMBOURG, D W	8510510081+	50-767
VANDENALLE.D J	8210130521	PR		VERRELLI, D M	8210150162	50-324	Q	WAREMBOURG, D W	8210220359	PR
VANDEWALLE, D J	8210220334	PR		YERRELLI, D M	0210150209	50~390	Q	WARFIOL, W 11	8210080331*	APORTLI.
VANDENALLE, D. J.	82102603164	50-155	o	VERRELLI, D M	8210150288	50-324	0	WARING, J P	9216040311	TOPPEP
VANDEWALLE, D J	8210290240	PR	-	VERRELL I.D M	8210150304	50~390	Q	WARNICK, R	8210040337	50 327
VANDOORN, D K	6210220471*	50-413	a	VERRELLI, D M	8210150318	50~518	Q	WARNICK, R	8210190627	50~358
VARELA, A A	8210060215*	50-412	G.	VERRELL 1, D M	8210150323	50~390	Q	WARNICK, R F	8210040185*	50-409
VARELA, A A	8210070400#	50-443	a	VERRELLI, D M	8210150349	50-390	a	WARNICK, R F	8210050139	50-32,
VARELA, A. A.	8210210082*	50~352	Q	VERRELLI, D M	8210150379	50-259	0	WARNICK, R F	8210050146*	50-317
VARGA, S A	8209170041	50-305	F	VERRELLI.D M	8210220139	50-324	Q	WARNICK, R F	8510080168	50-307
VARGA.S A	8210040039#	50-364	P	VERRELLI, D M	8510550190	50-400	q	WARLICK, R F	8210130557+	50-461
VARGA,S A	B210040041*	50-364	P	VERRELLI, D M	8210220169	50-324	o .	WARNICK, R F	8210150441	50-329
VARGA.S A	8210040417 *	50-315	b	VERRELLI, D M	8510550315	50-160	a	WARNICK, R F	8210190739	50-3.7
VARCA, S A	8210040419+	50~315	Ρ	VERRELLI, D M	8210220315	50-390	Q	WARNICK, R F	82101907874	50-440
VAROA, S A	8210040428	50-315	P	VERRELLI, D M	8210220325*	50-160	Q	WARNICK, R F	8210240190	50-329
VARCA, S A	8210030452	50-286	P	VERRELLI, D M	0510550340	90-259	a	WARNICK, R F	8210270154	50-327
VARGA, S A	8210050485	50-272	P	VERRELLI, D M	8210220459	50-390	Q	WARNICK, R F	8210290377	50-327
VARGA, S A	8210050487	50-334	P	VERRELL I.D M	8210220472	50-390	O .	WARNOCK. R	8510580085	50-261
VARGA, S. A.	8210050534	50-286	ρ	VERRELLI, D M	8210220480*	50-327	Q	WATERS, J R	8210190599+	50-275
VARGA.S A	8210050541*	50-315	P	VERRELLI, D M	8210220489	50~324	Q	WATSON M E	8210200098*	50-331
VARGA, 6 A	8210060431	50-272	F	VERRELLI.D M	8210220474*	50-324	Q	WEBB.W A	8210190185*	50-320
VARGA, S A	8210120557	50-315	P	VETERE, L A	8210250287	50-247	G.	WEBER, C F	8210210034	50-259
VARQA, S A	8210120560*	50-315	ρ	VILLA, R	8210050398	50~447	A	WEDER, D A	8210280432*	50-247
VARCA.S A	8210120565*	50-315	Б	VILLA.R	B210050408*	50-447	A	WEBER, W V	821005042/#	50-155
VARGA. G A	6210130400	50~305	P	VILLA.R	8210270051#	50-447	A	WEE, D T	6210040169#	50-237
VARGA.S A	6510130705	50-247	P	VILLFORTH, J C	8210180149	50-413	D	WEGST, W F	8210200081	50-142
VARGA, S A	8210130603	50-272	P	VINCE, 5	8210190040*	50-315	F	WEIGLAND, G G	82102/0338	NUREG
VARGA, S A	6210130604	50 -286	F	VISSER, J E	8210180416*	CONTRACT		WEIL.C H	82101907874	50-410 .

яФ н тиа,	ACCESSION NUMBER	SUBJECT CATEGORY	AU THOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
E150 E R %E150 E P %E150 E P %E150 E P %E150 E R	821020410 821020465 821020465 8210260397 8210260397	50-247 G 50-287 G 50-289 O 50-537 G 50-537 G	Wiesemani() R A Wiesemann, R A Wiggins, E Wiggins E Wiggins, E	8210190508 8210260351* 8210120347 8210120391 8210190230	50-395 P TOPREP CONTRACT CONTRACT CONTRACT	Wilson, J L Wilson, J L Wilson, J L Wilson, J L Wilson, J L	6210040378* 8210130204 8210130208* 8210130213* 8210130214*	50-280 6 50-280 8 50-280 8 50-280 8 50-280 8
155 E R 155 E R 155 E R 155 E R 155 E R	8210240397 8210260404* 8210260404* 8210260404* 8210260242	50-537 G 50-537 G 50-537 G 50-537 G 50-247 G	Miggins, e Migginion, d Migginion, d Migginion, d	8210270207 8210270226 821026061 8210270344 8210280405	CONTRACT CONTRACT 50-315 P 50-295 P 50-295 F	WILSON, J L WILSON, J L WILSON, J L WILSON, J L	8210130500 8210130507* 8210150054 8210150075 8210150139	50-280 8 50-280 8 50-280 8 50-280 8 50-280 8
WEISSER WELLS DA MELLS DA MELLS DA MELLS DA	8210280242 8210190332 8210040084 8210040127 8210190657	50-247 0 50-341 S 50-341 S 50-341 S 50-341 S	WILTER, D WILTER, D WILCOVE, M N WILCOVE, M N WILCOVE, M N	8210210381 8210210381 8210010062 8210040018 8210040057	50-155	NILSON, J L WILSON, J L WILSON, J L WILSON, J L WILSON, J L	8210150359 8210150394 8210220095 8210220097* 8210220100*	50-281 5 50-280 5 50-280 5 50-280 5 90-280 8
MENDERLICH R L MENDERLICH R L MENDERLICH R L MENDERLICH R L	82102802474 8210102888* 8210102888 82102802474	50-341 S 50-341 Q 50-318 S 50-317 S 50-317 S	HILCOVE.N H HILCOVE.N H WILCOVE.N H WILCOVE.N H WILCOVE.N H	8210150486 8210200051 8210260364 8210260388 8210130328#	50-320 0 50-329 0 50-329 6 50-329 6 50-254 8	WILSON, J L WILSON, J L WILSON, J L WILSON, J L WILSON, J L	8210220372 8210220378* 8210220408* 8210220413* 8210220424	50-260 8 50-260 8 50-280 8 50-280 8 50-261 8
MEINCEPHICH PL MEINCEPHICH RL MEINCEPHICH F MEINCEPHICH A MEINCEPHICH A	8210280284* 8210280313* 8210010240 8210040131* 8210190512*	50-310 S 50-317 S 50-206 S 50-220 Q 50-312 0	WILKINSON, E P WILKINSON, W P WILLETT, D J WILLIAMS, C C WILLIAMS, C C	8210050181* 8208010019* 8210190569* 8210190787* 8210060384*	FOTA ORG 50-397 G 50-440 G 50-373 G	MITEON 7 F MITEON 7 F MITEON 7 F MITEON 7 F	8210220435* 8210270212 8210270215* 8210270220* 8210270224*	50-281 5 50-280 8 50-280 5 50-280 9 50-280 8
HEI, LAMERILE A HEI TUNKEKILE A HEI BLAKSKILE A HEIJELAKEKILE A HEIJEL A H	R210,006448 8210250178# 8210280244# 8210280248# 8210210054	50-27 0 50-362 0 50-397 0 50-397 0 NURFO	WILLIAMS, C C WILLIAMS, C C WILLIAMS, C C WILLIAMS, D A WILLIAMS, D T	8210050393* 8210130374* 8210130557* 8210210045 8208290108	50-315 G 50-341 G 50-461 G NUREG FOIA	WELSON, J L WILSON, J L WILSON, J L WILSON, J L WILSON, K R	8210290264 8210290270* 8210290276* 8210290282* 8210190687*	50-280 S 50-280 S 50-280 S 50-280 S 50-302 S
enjelah Penjahan Penjahan Penjahan Penjahan	6210720154 6210130176# 6203040536# 6210050771 6210050221	NUREG 50-346 S 50-329 G 50-329 G 50-329 G	n f'ewyl Tin n f'ewyl Tin n f'ewyl Tin n fewyl Tin n fel i wyl	8210010164 8210060209 8210080252 8210130456 8210130552	90-335 8 50-251 8 50-250 9 50-335 9 80-335 9	MILEON, R D MILT, D D MILT, D D MILT, D D MILT, D D	8210200053 8210010250 8210010250 8210010323 8210010323	50-400 G 50-440 G 50-440 G 50-440 G 50-440 G
CST A E EST. A E EST L J EST. L J ESTLRGM. A D	8210050250 8210050230 8210050821* 8210120458* 8210040355	50-329 G 50-329 G CONTRACT CONTRACT 40-8748	WILLIAMS, J W WALLIAMS, J W WILLIAMS, R E WILLIAMS, R E WILLIAMS, R E	8210240114 8210240357 8210180354* 8210120401* 8210120604*	50-250 S 50-335 S FDIA CBNTRACT 40-8745	WILT.D D WILT.D D WILT.D D WILT.D D WILT.D D	8210050173 8210050173 8210050228 8210050228 8210050228	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G
ESTEROZY, W B ESTER, M I STERMAN, I F ESTERMAN, I F	8210176479 8210,770338 8210050239* 8210070369* 8210170547	40-8786 NURFO 50-267 0 50-445 0 50-267 6	WILLMORE, R L	8210010345 8210010345 8210010457 8210010457 8210050255	50-440 0 50-440 0 50-440 0 50-440 0 50-440 0	WILT, D D WILT, D D WILT, D D WILT, D D WILT, D D	8210050242 8210050252 8210050252 8210250331 8210250331	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G
ESTERMANT F ESTERMANT F ESTERMANT F ESTERMANN N ETTERMANN N ETTERMANN N ETTERMANN N	0210190776# 8210190820# 8210280149# 821069099 8210690279	50-445 0 50-445 0 50-267 0 27-39 50-358 0	WILLMORE, R L WILLMORE, R L WILLMORE, R L WILLMORE, R L WILLMORE, R L	8210050255 8210070405 8210070405 8210150467 8210150467	50-440	WINKS, R W WINTERHOFF, D WINTERHOFF, D WINTERHOFF, D WIRFS, L	8210010284* 8210130236* 8210250163* 6210260313* 8210070426*	50-329 E 50-373 B 50-373 B 50-373 B FOIA
TTTERMINE II J IALEIL R GELERIL GELERIL	8210270279 82100401278 82102503148 82092105508 8210180214	50-249 B	WILLMORE, R L WILLMORE, R L WILLMORE, R L WILLMORE, R L WILLMORE, R L	8210220309 8210220305 8210180155 8210180155	50-440 0 50-440 0 50-440 0 50-440 0 50-440 0	WIRFS, L WITHERS, B D WITHERS, B D WITHERS, B D WITHERS, B D	8210070464* 8210010307 8210040163 8210080253* 8210130379	FDIA PR 50-344 P 50-344 O PR
EEWERLL ATE.A J ATE.A J ATE.J R ATE.J W	0210120617 0210220067* 0210290332* 0210290344* 0210260530*	90-416 8 50-322 0	WILLMORE, R L WILLMORE, R L WILLMORE, R L WILLMORE, R L WILLMORE, R L	8210220309 8210220396 8210220396 8210220405* 8210220405*	50-440 Q 50-440 Q 50-440 Q 50-440 Q 50-440 Q	WITHERS, B D WITHERSPOON, J WIZNER, D G WIZNER, D G WIZNER, D G	8210220301 8210130315# 8210170277# 8210170287# 8210170415#	PR 50-537 A 50-315 8 50-315 8 50-315 8
TIMEN'O O TIE'EB'H T TIE'B H TIE'B T	8206170006# 8210050418 8210010459# 8210220147# 8210040105#	NUREO 90~349 0 50~324 0	WILLHORE, R L WILLHORE, R L WILLHORE, R L WILLHORE, R L WILLHORE, R L	8210280231 8210280231 8210280246 8210280246 8210290287	50-440	WIZNER,D G WOJCHOUSKI,A V WOJNAS,E J WOLF,J F WOLF,J F	8210190735# 8210060260# 8210210142# 8210270176 8210280245	50-316 8 50-263 8 50-309 0 50-320 0 50-275 0
itney.o c itney.o c itney.o o itney.o o	8210060030) 8210070247) 8210070346) 8210130479 8210170237	* 50-273 B * 50-273 B * 50-273 B	WILLMORE, R E WILLSEY, W B WILLSEY, W B WILSON, A K WILSON, B A	8210270287 8210050320 8210150356 8207050075 8210260065	50-440	WOLF, TR WOLF, TR WOLF, TR WOLF, TR WOLF, TR	8203120103* 8206220591* 8207120140* 8207150162* 8209150164	50-331 S 50-324 P 50-324 P 50-325 P 50-324 S
TNEY. C C TMEY. C C TIEN. J E TWORTH F RIOM R D	62102801314 8210280150 62102201714 8210130074 8210080276	* 50-293 B * 40-2259 * CONTRACT	WILSON, B D WILSON, B D WILSON, B D WILSON, B D WILSON, J L	8210080113 821008013! 821026057(821027028; 8210050071	XFORTL1C	MOFEET	821013Q366 *	50~34 <i>6</i> Я
Hare, k r Huffr, r p Be, J Deman, d g Deman, d g	8007310117 8210210034 8210070245 8210080273 8210080279	70-2789	MILSON, J L MILSON, J L MILSON, J L MILSON, J L	8210050074 8210050076 8210050081 8210050086 8210050091				
DEMAN, D O DEMAN, D O DEMAN, D O DEMAN, D O DEM A N, D O DEM A N, D DEM A N, A N, A	8210150507 8210190673 8210250190 8210260402 8210180587	70-2450 70-1257	WILSON, J L WILSON, J L WILSON, J L WILSON, J L	8210050092 8210050103 8210050109 8210060361 8210060372				

ROTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	CATEGOR		AUTHOR	ACCESS LON NUMBER	EUB ECT CATEG #
WOLLETT, S WOLLETT, S WOLLETT, S	8210130587 8210190076 8210260278	CONTRACT	YATES,K R YODER,Q L YORK,F S	8210120102 8210150567 8210010223	NUREG NUREG PR		ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	\$400E10150	STO-TER STO-TER
MOLLETT, S MOLLETT, S	8210270027 8210270373	CONTRACT CONTRACT	YORK, J W YORK, J W	8210010203 8210010305	50-438	Q Q	ZIMMERMAN, J V	6210130070 621026000 6210260523) F () 9 Tr. J.
HOLLEVER.E J HOLTNER.E HOLTNER.E F HONG.T	8210240143 82102901074 82102102384 8210190246		YORK, J W YOUNG, F YOUNG, G G	8210010314: 8210150091: 8210010067:	50-287 FOIA	0 0	ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8210260541 8210260577 8210260574	RPLUMET
WOOD, E C	8210250019 8210210015	40-299	YDUNG, M A	8210280040 8210040014	50-440 50-244	G G	ZIMMERHAN, J. V. ZIMMERMAN, J. V	051059590 0510590440	
₩000.E C ₩000.E C	8210260193 8210260193 8210260199 8210270165	50-309 8 50-309 8 50-309 8 50-309 8	YOUNG, T YOUNG, T YOUNG, T	0210060336* 0210060345* 8210250138	50-528 50-312	9 9 8	V U JAAMAHMII V U JAAMAHMII V U JAAMIHMIII	021027400J 00007400J 00007400J	ነር ያየጫን የአ መንያነት የህዝር የርህ የመቀየለ
HOODHEAD, C P	8210120261 8210120261	50-34I G	YOUNG, T YOUNG, T	0210250361* 0210250375*	50-528	G G	Z IMMERMAN, J. V Z IMMERMAN, J. V	851057006A	14 (43/)\ (43/)\
WOODQUFF.R L WOODRUFF.R L WOODRUFF.R L	8210010048 8210010100 8210010154	50-142 G State Prog State Prog State Prog	YOUNGSLOOD, B J	8210280372* 8210040348 8210040285*	40-8793 50-338	Q P	V U HAMRIMATI V V V VAMREMMIZ V V VAMRIMATI	0210270122 8210270127 8210270147	KANDATOR KANDATOR KANDATOR
WOODRUFF.R L	8210010358 8101090296*	State Prog	ADDINGBEOOD'B 1	8210040307* 8210040320*	50-338 50-338	P P	ZIMMERMAN, J. V. ZIMMERMAN, J. V.	8210/70156 8210/70101	ar cett fo
WOOLEVER, E J WOOLEVER, E J WOOLEVER, E J	9210070155 8210070233 8210240135	50-247	AONIGBEOOD'B ? AONIGBEOOD'B ?	8210040370 8210040373 8210040377	50~483 50~482 50~341	A F A	Z IMMERHAN, J. V Z IMMERMAN, J. V Z IMMERMAN, J. V	8210270233 8210270238 8210270230	AFCORPLES
WOOLSEY, R T	82101206135 8210120619	40-8781 40-8781	YOUNGBLOOD, B J	8210120341 8210120344	50-424 50-358	٨	ZIRMERMAN, J V ZIMMERMAN, J V	0510530502 0510530509 0510530505	NETHATA NETHATA NETHATA
HOOLSEY,R T WOZNIAK,D R WRAY,J R	8210210515 8210080319 8210070345*	40-8084 XPORTLIC 50-219 G	YOUNGBLOOD, B J	8210120348 8210210288 8210280420	50-544 50-387 50-454	۸ ه	ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8210270206 8210270207 8210370290	A PLACE I.
WRAY, J R	8210080179 8210150350*	70-143 50-335 Q	YOUNGBLOOD, B J	8210280429 8210290008	50-454 50-546	٨	Z THMERMAN, J. V. Z THMERMAN, J. V.	0210270314 0210270414 0210270414	# F 17 1 # L &1 # JP L 19 P L &1 # # 19 4 P L
WRAY.R WRIGHT.E G WRIGHT.E G	8210250210 8210180145* 8210180433*	50-275 P FOIA FOIA	YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J YUHAS, G	8210290115 8210290128* 8210290363	50-387 50-387 50-454	Р Р <i>F</i>	ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	021027044& 8210289035 8210280038	RECORDER C
WRIGHT, G WRIGHT, N A	8210250114* 8210040018	50-373 Ω 50-329 Q	YUHAS, G P YUNDT, C P	8210010260 8210280248*	50-206 50-397	G Q	ZIMHERHAN, J V ZIMHERHAN, J V	6210/40040 6210/400409	negrater Kerater Kerater
WRIGHT, N A WRIGHT, N A WRIGHT, R J	821020033 8210260033 8210080062	50-329 G 50-440 G WASTE MOT	YUNDT, C P YUNDT, C P ZARBIS, W A	8210170026* 8210250084 8210250164	50-344	F 6 8	7 IMMERMAN, J. V. 2 IMMERMAN, J. V. 2 IMMERMAN, J. V.	0210780414 0210780410 0210780477	nt (ATL) nt (ATL) rijedjeje
WRIGHT, R J	821012017B 8210120325	WASTE MOT	ZEBROSZI, E L ZECH, G	8210250074* 8201190041*	FOIA	P	ZIMMERMAN, R. P. Zimmerman, B. R	#210290171s #210060316	90 544 1
WRIGHT, R J WRIGHT, R W	8210120358 8210120359 8210010143*	WASTE MGT WASTE MGT 50-413 Q	ZECH, Q ZIBULSYY, H ZIBULSKY, H	8210120188* 8210120194* 8210220179*	Γ0ΙΑ 70~37Ι	P	7 IMMERMAN, 6 K 7 IMMERMAN, 8 R 7 IMMERMAN, 9 R	0210060349 0210120649+ 0210130049	50 261 F 50 261 F RPB91610
WRICHT,R W WUDZKI,J J WULLER,G E	8210220145* B210120541*	50-400 Q CONTRACT	ZIELENBACH, W R	8210120092 8210120092	70~687 NUREG		7 IMMERMAN, B R 2 IMMERMAN, B R	881013035J	30 TH /
WULLER, O E WULLER, O E WULLER, G E	8209290072 8210040104 8210050278	50-461 A 50-461 A 50-461 E	ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	9210120102 9210070433 9210070439 9210070443	NUREG XPORTLIC XPORTLIC		ZIMMERMAN, 8 R ZIMMERMAN, 8 R ZIMMERMAN, 6 R	82101300 In 8210130170 8210130264	50 2/4 F 50 2/4 F
WULLER, G E WULLER, O E	8210050281 8210050289	50-461 E 50-461 E	ZIMMERMAN, J V ZIMMERMAN, J V	8210090045	XPORTLIC XPORTLIC		ZIMMERHAN, S. R. ZIMMERMAN, S. R.	0210290202	50 £61 + 50 4.0 (
WULLER, O E WULLER, G E WULLER, O E	8210130181 8210130270 8210130379	50-461 G PR PR	ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8210080143 8210080149 8210080153	XPORTLIC XPORTLIC XPORTLIC		ZIMMERMAN, G R ZIMMERMAN, S R ZIRWAB, K R	8210280275 8210290356 8210150049#	50-314 F 50 247 F 50 247 S
HULLER, G E WULLER, G E	8210130490 8210150357	50-461 A	ZIMMERMAN, J V ZIMMERMAN, J V	8210080157 8210080162	XPORTLIC XPORTLIC		ZUDANS, Z ZUDANS, Z	0200290026 0200290026	ACRS ACRS
WULLER, G E WYATT, J H WYSOCKI, J	8210260003 8210280089 8210010381 8210150552	70-2946 50-461 A PR	ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8210080334 8210080343 8210080345	XPORTLIC XPORTLIC XPORTLIC XPORTLIC		ZUDANB, Z ZUDANB, Z	9210180390+ 92102/0398 9210270398	CCMIRACI 50 341 (50-341)
YANDELL, L A YANICHKO, S E	8210190539* 8210190429*	NUREG 50-285 Q 50-282 P	ZIMMERMAN, J V	8210080348	XPORTLIC XPORTLIC		ZUFELT, E ZUKOR, D	8503040594 8503040594 8510500054	50 333 · 50-351 ·
YARNICK, T P YARNICK, T P YATES, K R	8210260557 8210270195 8210120092	40-8102 40-8102 NUREG	ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8210120511 8210120517 8210130055 8210130059	XPORTLIC XPORTLIC XPORTLIC XPORTLIC		ZMCIZIO O B ZMUNDON M ZMUNDON M ZMUNDON M	8210290240 8210290245 8210080311* 8210060141*	PR 50-272 F 70-754 50-275 2
					41144		ZWETZIO, O B	0210060279# 02101505364	50 205 1 QA959

82101505364 QA959

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents,"

AUTHUR AFF 1L IATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILJATION	ACCESSION NUMBER	SUBJECT CATEGORY
AMAX, Inc ATResearch Associates, Inc Arnodts, The	8210080035# 8210080035# 8210250035 8210150557 8210050192	XPORTLIC XPORTLIC 40-8820 NUREG 50-269		Alden Research Laboratory Allied Chemical Corp American Electric Power Service Corp	82100 80022 * 82100 30388 82100 30287 * 82101 30287 * 82101 50600 82100 70286 *	CONTRACT NUREO 50-389 E 40-3392 50-315 I
	8210210359 8210260400	50-289 50-289	о 0	American Deophysical Union American Institute of Aeronautics &	8210190002* 8210120432*	CONTRACT
Aarojet Emerqų Conversion Co. (subs. of General Tile & Hubber Co.)	8210060255 8210060257* 8210060259*	TOPREP TOPREP		Astronautics American Nuclear Insurers	8210010307 8210040275 8210290255	PR TOPREP PR
Air Force, Dept of Air Force, Dept of, Radiossotope Committee	8210070459* 8210270179 8210270182*	CONTRACT 40-8577 40-8577		American Nuclear Society	8210010218 8210010232 8210220379	2년 2년 2년
Alabama Power Co	8210010129 8210010129	50-248 50-248	6 8	Amerisham Corp	8510080535* 8510080535*	71-9167 71-9167
	8210010139* 8210010147* 8210010175 8210010175 8210010224	50-348 50-348 50-348 50-348 FA	9 F F	Anaheim, CA Andrulis Research Carp Antioch College of Law	8210980239* 8210250356 8210270221* 8210270223* 8210150341	71-91&7 FROJ CONTRACT CONTRACT 50-135 G
	8210050066 8210050069 8210080294 8210130270 8210130527	50-364 50-364 TOPREP PR 50-364	ь ь	Appling County, OA Argonne National Laboratory	6210210361 6210120425* 6206270017 621 621	SO-155 G CONTRACT
	8210150074* 8210150338 8210150344* 8210190073* 8210190073* 821019009 8210190614* 8210190722	50-348 50-348 50-348 50-348 50-348 50-348 50-348	. O.P.F.F. S.B.R.	Arizona Public Service Co		
	8210190723* 8210190767	50-348 50-344	R R			
	8210190773* 8210250090 8210260418 8210260437 8210260453	50-364 50-364 50-364 50-364 50-348	F F F F		8210070213 8210070219 8210070229 8210070229 8210070229	50-528 R 50-530 B 50-528 B 50-528 B 50-528 S
	8210240453 8210260463# 8210260470# 8210260480# 8210260490#	50-348 50-348 50-348 50-348 50-348	8 8 8 8		0210070320 6210070320 8210070320 8210070321 8210070339	50-528 S 50-528 S 50-528 S 50-528 S 50-528 S
	8210280158 8210280158 8210280145# 8210280145# 8210280282	50-348 50-348 50-348 50-348 50-364	Р Р Р		8210070339 8210070339 8210070354 8210070374 8210070371	50-528 8 50-528 8 50-528 8 50-528 8
labara. Univ of.	8210290289 8210290292* 8210070355* 8210070358*	50-364 50-364 50-438 50-438	8 A A	•	8210080155 8210130187 8210130394 8210130443	50-528 0 50-528 8 PR 50-528 0

AUTHOR AFF 14 1 AY 10 N	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFF] L (A T (ON	ACCESSION NUMBER	SUBJECT CATEGORY
	82:01 30444 82:01 30491 82:01 30495 82:01 30544 82:01 30544	50-530 S 50-530 S 50-527 S 50-527 S 50-527 S	DWR Owners Group Babcock & Hilcox Co	8210270253 8210050053 8210250181 8210250184* 8207070007	PR TOPREP TOPREP TOPREP TOPREP
	8210150163 8210150176* 8210170315 8210170463 8210170717	50-528 A 50-528 A 50-528 E 50-528 A 50-528 A		8210010284* 8210040344 8210120304* 8210120315* 8210130308*	50-329 E Toprep Gaggg Gaggg 70-135
	8210190717 8210220394 6210250100 8210250305 6210250326	50-528 A 50-528 G 50-528 S 50-528 S 50-528 S	Backus, R A	8210220231 8210220497 8210250132 8210270232 8210060194	70-824 70-27 PT&! 70-27 50-443 G
	8210240275 8210240543 8210270211 8210280057 8210280057	50-528 S 70-2947 50-528 A 50-528 A 50-528 A	Baltımore Oas & Electric Co	8210040194 8210040204* 8210040204* 8210040044 8210040049*	50-443 C 50-443 C 50-443 C 50-318 '1 50-318 S
	8210280057 8210260139 8210280137 8210280139 8210280199	50-528 A 50-528 A 50-528 A 50-528 A 50-528 A		8210040142 8210040144* 8210040211 8210040216 8210040219*	50-317 9 50-317 5 50-318 5 50-318 5
Arizona State Univ Arizona, Univ Of	8210280199 8210280199 8210280274 8210150491 8210050508*	50-528 A 50-528 A 50-528 E RES CONTRACT		8210040226* 8210040385 8210040390* 8210040394* 8210070159	50-310 R 50-317 B 50-317 S 50-317 S
Arkansas Power & Light Co	8210210066# 8210040109 8210040111# 8210050346 8210070395	CONTRACT 50-313 P 50-313 P 50-368 S 50-313 F		8210130103* 8210130338 8210130338 8210130342* 8210130342*	50-317 Q 50-317 P 50-317 P 50-317 P 50-317 P
	8210070395 8210120247# 8210120252# 8210130212 8210130214#	50-313 F 50-313 0 50-313 0 50-313 8 50-313 8		8210130391 8210130461 8210130465* 8210130543 8210130558*	PR 50-317 6 50-317 5 50-317 5 50-317 5
	8210130382 8210130388* 8210130409 8210130513 8210130522*	50-313 S 50-313 B 50-348 P 50-313 S 50-313 S		8210130548 8210130578* 8210150423 8210180005 8210180039	50-317 5 50-317 6 50-317 F 50-317 F 50-318 0
	8210150002 8210150073 8210150073 8210150494 8210190517	50-313 P 50-313 F 50-313 F 90-313 P 50-313 S		8210180124 8210190290 8210190296* 8210190730 8210190803*	50-317 P 50-317 S 50-317 S 50-317 G
	8210190526* 8210190545 8210190559* 8210220114 8210250159	50-313 8 50-368 8 50-368 9 50-313 P 50-368 P		8210190803# 8210210328 8210210328 8210210457# 8210210457#	50-317 Q 50-317 P 50-317 R 50-317 R
	821 0250161 * 821 0250204 821 0250292 821 0250298 * 821 0240120	50-368 P 50-313 P 50-368 S 50-368 S 50-368 S		8210210546* 8210210546* 8210210551* 8210210551* 8210220378	50-317 F 50-317 F 50-317 F 50-317 F 50-318 P
	8210240123* 8210240193 8210240192 8210270101 8210280112*	50-348 8 50-313 Q 50-313 P 50-348 P 50-313 F		8210220385* 8210250088 8210250075* 8210250154 8210250160*	50-318 P 50-318 S 50-318 S 50-317 S 50-317 S
Armed Forces Radiobiological Research Institute	6210260112* 6210260114* 6210270240 6210260425	50-313 F 50-313 F FR 50-170 0		82;0240299 8210270237 82:0270241* 62:0270244 82:0270248*	50-318 S 50-318 S 50-317 S 50-317 S
Army, Dept of, Headquarters Hateriel Davelopment & Readiness Command Army, Dept of Army, Dept of, Cores of Engineers	8210270227* 8210190105* 8210120471*	40-8632 CONTRACT CONTRACT		8210270252 8210270257* 8210270266 8210270269* 8210270272	50-317 9 50-317 S 50-317 S 50-317 S 50-317 S
Aspects, Inc Associated Technologies, Inc Atlas Minerals	8210190147* 8210220226 8210150596 8210260079 8210260080*	CONTRACT PR 40-3453 40-3453 40-3453		8210270273* 8210270274 8210270275* 8210270276 8210270278*	50-317 S 50-317 S 50-317 S 50-317 S 50-317 S
Atom Sciences, Inc. Atomic Industrial Forum	82101 20440* 82060 60013* 8207270377* 82101 30280 8210270242	CONTRACT COMMISSION COMMISSION PRM PR	,	8210270279 6210270280* 8210280134 8210280141* 8210280171	50-317 S 50-317 S 50-318 S 50-318 S 50-318 S

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGO		AUTHOR	ACCESSION	SUBJEC.	Ť
	8210280194 8210280195* 8210280200* 8210280203 8210280205*	50-318 50-318 50-318 50-317 50-317		AFFILIATION	NUMBER 8210050166 8210060023 8210060030* 8210060085	CATEGOI 50-293 50-293 50-293 50-293	
	8210280249 8210280255* 8210280263 8210280267* 8210280279	50-317 50-317 50-317 50-317 50-318	3 3 3 5 3 5 3 5 4 5 5 5 6 5 7 5 8		8210060164* 8210060160* 8210070245 8210070247* 8210070340	50-293 50-293 50-293 50-293 50-293	0 9 8 8
	8210280294 8210280294 8210280301 * 8210280303 8210280313*	50-318 50-317 50-317 50-317 50-317	ច ច ច ច ច		8210070346* 8210130399 8210130472 8210130479* 8210130444	50-273 PR 50-273 50-273 50-273	8 8 8
Cattelly Memorial Institute, Columbus Laboratories	6210200310 6210200332* 6210260334 6210260341* 6210150592	50-317 50-317 50-318 50-318 NUREO	8 8 9		8210190235 8210190237* 8210190721 8210250085 8210250122	50-293 50-293 50-293 50-293 71-6346	8 9 9
ittelle Kemorial Institute, Pacific	8210190087* 8210190420* 8210190428* 8210210014 8209140027*	CONTRACT 50-333 50-333 NUREG 50-244	Г () ()	Boston State College	8210280127 8210280131 * 8210280146 8210280150 * 8210150350 *	50-293 50-293 50-293 50-293 50-273	9 8 8 8
marthuest Laboratory	8209210523* 6210050418 8210070254* 8210070315*	50~309 NUREQ 50-537 50~537	P A D	Broothaven National Laboratory	8207180044 8210070449 8210120367 8210120390 8210120435	ACRS RES RES RES RES	
	8210070318* 8210070323* 8210070327* 8210070332* 8210070335*	50-537 50-537 50-537 50-537 50-537	D D D D		8210120459 8210120460 8210120466 8210120630 8210120642*	res res res res 50-341	A
	8210070347# 8210070465# 8210080009# 8210080332 0210120092	50-537 50-537 CONTRACT REB NUREG	D D	Dryant & Bryant AIA Burns & Roe Co Bursey, B	8210120649 8210220135 8210210444* 8210040173* 8210150458	RES NUREG CONTRACT GATT 50-375	G
	B210120102 B210120125 B210150553 B210220149 B210270041#	NUREO NUREO NUREO NUREO 50-537	o	C-E Operating Plants Duners Oroup C Itoh & Go (America), Inc Cabot Corp California, State of	8210040323 8210080324 6210080339 8210050160 8210290097	TOPREP XFORTLIC XPORTLIC 50-275 50-275	
ar Crent Uranium Co chtel Corp	8210270421 8210270041* 9210150644 8210050248 8210060241*	NES 50-285 40-8452 50-329 50-155	P R P	Calitornia, Univ of, Barkelay	8107270146* 8107270149* 8107270174* 8107270178* 8107270178*	50-264 50-266 50-266 50-266 50-266	а а а а
	8210130503* 8210150373* 8210190470 8210190470 8210220283	50-329 50-424 50-275 50-275 PR	A P P		8107270182* 8107270182* 8107270185* 8107270185* 8107270188*	50-266 50-266 50-266 50-266 50-264	0 0 0 0
uvrordyne Psychological Corp uinger, DuPont & Associates, Inc	0210260904 1207020151 1207020158 770010158 770010158	50-329 50-275 50-275 PR PR	r P		8107270191* 8107270194* 8107270196* 8107270198* 8107270199*	50-266 50-266 50-266 50-266 50-266	Q Q Q Q
erzége, l'ajrbants, & Dzamond Choff, C A	8210240347 8210240347 8210240373 8210240373 8210130417	50-338 50-338 50-338 50-338 50-528	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	California, Univ of, Los Angeles	8210150456 8210200081 8210250076 8210250043* 8210250051*	50-142 50-142 50-142 50-142 50-142	о в е г
hep. L t.	8210270171 8210070132 8210070132 8210070136 8210070136	50-528 50-327 50-329 50-329 50-329	0 6 8	Caivert Gounty, MD Cammer & Shapiro Carolina Environmental Study Group Carolina Power & Light Co	8210180371* 6210150234 6210260150 6207140148 6207140153*	CONTRACT 50-322 50-413 50-324 50-324	o p r F
ing Computer Services, Inc. (subs. of ling Co.) J-Marner Corp	8210070140 8210260561* 8210150517* 8210150526*	50-329 CONTRACT GA999 GA999	Q.		8209160299 8209160311* 8210010028 8210010183* 8210010188*	50-325 50-325 50-24! 50-324 50-324	8 H G
en Colleg∉ on Edison Co	8210270372* 8210270372* 8210180362* 8204160212 8204160222*	XPORTLIC XPORTLIC CONTRACT 50-293 50-293	o 0		8210010298 8210010303* 8210010340* 8210010399* 8210010473	50-324 50-324 50-400 50-324 50-324	8 8 0 0 8
	82041 60225* 82071 80064 82100 40100 82100 40105*	50-293 FOIA 50-293 50-293	8		8210010475* 8210050009 8210050106 8210050106 8210050125	50-324 50-261 50-400 50-400 50-400	B A A A
i							

AUTHOR AFÉ ILIATION	ACCESSION NUMBER	CATEGO		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8210030125 8210050362 8210050362 8210050371* 8210050371*	50-400 50-324 50-324 50-324 50-324	A P P P		8210220409 8210220412 8210220412 8210220484 8210220492*	PR 50-400 50-400 50-400 50-324	0 5
	8210060013 8210060016* 8210060316 8210060316 8210060320	50-261 50-261 50-324 50-324 50-324	ዞ F F S		8210220499* 8210250202 8210260244 8210260244 8210260256	50-261 50-261 50-324 50-324 50-325	9 5 5 6
	8210060323# 8210060323# 8210060327# 8210060349 8210080180	50-324 50-324 50-324 50-261 50-400	F F 9 F 9		8210260266* 8210260269 8210260294 8210260318* 8210260323	50-325 50-324 50-325 50-324 50-324	4 4 7
	8210080321 8210080320 8210080320 8210080330	50-400 50-325 50-325 50-325 50-324	ញ ទ ទ ទ		8210260323 8210260325* 8210260325* 8210260344 8210260368*	50-324 50-324 50-325 50-325	5 6 6 7 8
	8210080230* 8210080283 8210120645* 8210120647* 8210130242	50-324 50-400 50-261 50-261 50-261	ន ទ ក ស		8210260398 8210260398 8210260405 8210260405 8210260410*	50-400 50-400 50-324 50-324 50-324	9946
	8210130244* 8210130295 8210130295 8210130323 8210130323	50-261 50-324 50-324 50-261 50-261	ክ ኖ ፅ ዘ ዘ		8210260410* 8210260462 8210260475 8210260482* 8210260508	50-324 50-400 50-261 50-261 50-261	ቀ የ የ የ
	8210130323 8210130323 8210130477 8210130483* 8210130489	50-261 50-261 50-325 50-325 50-325	11 H S S		8210260511* 8210280054 8210280275 8210280275 8210280278*	50-261 50-400 50-324 50-324 50-324	P C C C C
	8210130497* 8210130539 8210130550* 8210130567 8210130016*	50-325 PR PR 50-400 50-324	8 9 0		8210280278* 8210290074 8210290078* 8210290079 8210290099*	50-324 50-261 50-261 50-324 50-324	86501
	82101 50023# 82101 50030 82101 50038# 82101 50041 82101 50045#	50-324 50-324 50-324 50-324 50-324	0 p 0 S Q		8210290243 8210290246* 8210290258 8210290258 8210290256	50-324 50-324 50-400 50-400 50-400	20000
	82101 50046* 82101 50106* 82101 50198 82101 50264 82101 50291	50-324 50-324 50-261 50-261 50-324	9 0 P P P		8210270325 8210270331* 8210270333 8210270336 8210270337*	50-325 50-325 50-261 50-324 50-261	9 9 9 9
		50-324 50-400 50-324 50-155 50-400	a ¢ 9 p B	Carpenter Technology Corp	8210270342# 8210270346 8210270352# 8210270358 8210080317	50-324 50-325 50-325 50-261 XPGRTL16	5 5 6
			8 8 8 8 A A	Center for Law in the Public Interest Gerac, Inc Chapel Hill Anti-Nuclear Group Effort	8210080320* 8210050218 8210220517 8210270281 8210010328	XPORTLIC 50-275 XPORTLIC XPORTLIC 50-400	, O
				Gharleyoix.MI Ghattanooga-TN	8210010337 8210150340 8210210419 8210190215* 8210260520*	50-400 50-400 50-400 CONTRACT CONTRACT	
	e#1040009	50~400	Ğ	Chem-Nuclear Systems. Inc Cherry, M. M./Cherry, Flynn & Kanter	8210280388 8210070127 8210070127 8210070127	71-6601 50-454 50-454 50-454	G G
	#210200013* #210200013* #210200021* #210200032 #210200032	50-400 50-400 50-400 50-400 50-400 50-400	0 0 0 0 C		8210180151 8210210278 8210210278 8210210278 8210210384 8210210384	50-454 50-454 50-454 50-454 50-454 50-454	00000
	8210200084 8210200084 8210200086* 8210200086* 8210220075	50-400 50-400 50-400 50-400 50-400	C C C C C C C C C C C C C C C C C C C		8210250071 8210240380 8210240380 8210240384* 8210240384*	50-454 50-454 50-454 50-454 50-454	00000
	8210220075 8210220132* 8210220255 8210220247* 8210220265	50-400 50-400 50-261 50-261 PR	8 9 9	Chicago, Univ of Christa-Maria	8210270273 8210270305 8210170063* 8210150341 8210210381	50-454 50-454 CONTRACT 50-155 50-155	000

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJEC		ROHTUA ROITALLIA	ACCESSION NUMBER	SUBJI	
trezensts Gas & Electric Go	8210050137 8210050332 82100503324# 8210040271 8210040309	50-358 50-358 50-358 50-358 50-358	K 8 9		8210240419 8210240419 8210280231 8210280246 8210290287	CATE 50-440 50-440 50-440 50-440	0 A 0 A 0 G
	8210040358 8210070402 8210130294 8210130297* 8210130372	50-358 50-358 50-358 50-358 50-356	8 0 0 0 0	Coalition for Bafe Power Cobe Laboratories, Inc Colorado State Univ Colorado, State of Colt Industries, Inc	8210050389 6207180039 8210150223 8210120379 8210200417*	50-522 FOIA 50-322 HABTE	2 G
	8210150387 8210150443 8210180154 8210260279 8210260488	50-358 50-358 50-358 50-358 50-358	K 84 84 84 84 84 84 84 84 84 84 84 84 84	Columbia Univ Combustion Engineering, Inc	8210270307 62100403277 6210120377 8210120374 8210150304	50-20B	o
tizens Association for Sound Energy	8210270281 * 8210270285 * 8210270270 * 8210270277 821027024	50-358 50-358 50-358 50-358 50-445	G G G G		8210150313* 8210150319* 8210180133* 8210170004* 8210200022	50-470 50-470 50-470 50-317 CONTRAI	E E P
tizens for Nuclear Reactor Sefety, Inc	8210250104 8210280355 8210150200 8210150317 8210150395	50-445 50-445 50-170 50-170 50-170	G 11 G 0	Coemerce.Dept of. National Bureau of Standards	B210220440 8210280202 B210290240 8210050530#	70-1100 50-470 PR CONTRAC	o B
	8210150395 8210220439 8210220448*	90-170 50-170	Q G		8210040147*	70-398	
reland Electric [[]]uminating Co	8210280220 8210010345 8210010345 8210010457	50-170 50-170 50-440 50-440	0	Cammonwealth Edison Ca	6210130160 6210130163* 6209290225* 6209290225*	50-184 50-184 50-10 50-10 50-237	R R F F
	8210010457 8210040145 8210040145 8210040150#	50-440 50-440 50-440 50-440 50-440	6 K K		8210010009 8210010009 8210010009	50-237 50-237 50-454 50-454	£ C
	8210040150* 8210050132 8210050255 8210050253	50-440 50-440 50-440 50-440	K B G		8210010202 6210010202 6210010271 8210010271	50-454 50-454 50-454 50-454 50-454	E E A A
	8210050374 8210050374 8210070405 8210130173 8210130173	50-440 50-440 50-440 50-440 50-440	9 9 5 5		9210010271 8210010271 8210010271 8210010281 8210040040	50-454 50-454 50-454 PR	A A
	8210130179 8210130179 8210130364 8210130364 8210150161	50-440 50-440 50-440 50-440 50-440	A B B		6210040060 6210040116 6210040121* 6210040126	50-454 50-454 50-304 50-304 50-249	8 8 K
	8210150228 8210150228 8210150233 8210150447 8210180155	30-440 50-440 50-440 50-440	0000		8210040129* 8210040131 8210040134* 8210040188	50-249 50-373 50-373 50-237	5 5 8
	8210180155	50-440	o o		8210040189* 8210040218 8210040218	50-237 50-295 50-295	P P
	8210190324 8210190324 8210190333 8210190333	50-440 50-440 50-440	A E E		8210040221 8210040223* 8210040223* 8210040244* 8210040247	50-373 50-373 50-373 50-456	ե ե
	8210170683 8210170683 8210210079 8210210284 8210210284	50-440 50-440 50-440 50-440 50-440	E A Q		8210050056*		
	8210210353 8210210353 8210220305 8210220305 8210220309	50-440 50-440 50-440 50-440 50-440	0000				
	6210220309 6210220339 6210220372 6210220396 6210220396	50-440 PR PR 50-440 50-440	0				
	8210220405* 8210220405* 8210250299 8210250299 8210250322	50-440 50-440 50-440 50-440 50-440	9 9 9		6210060252* 6210060262 8210060267*	50-373 50-304 50-304	8 8
	8210250322 8210260009	50-440 70-2948	G		8210040248*	50-373 50-295	g J
	8210260011* 8210260337* 8210260337*	70-2968 50-440 50-440	q q		8210060367* 8210060367* 8210060395 8210060405*	50-237 50-237 50-254 50-254	0 9 8 8

- '-

CUMPURATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFF ILIATIO	n	ACCESSION NUMBER	SUBJECT CATEGOR	
	8210080030# 8210080031# 8210080031# 8210080111 8210080111	50-295 50-295 50-295 50-295 50-295	Г Г Г Р			8210170344 8210170346* 8210170403 8210170412* 8210170443	50-373 50-373 50-249 50-249 50-295	9 9 9
	9210080178 9210080178 9210080178 9210080178 9210080178	50-237 50-237 50-237 50-237 50-237	Q Q Q Q			8210190445 8210190445 8210190445 8210190445 8210190445	50-237 50-237 50-237 50-237 50-237	ր թ թ
	B210080178 B210080178 B210120105 B210120105 B210120105	50-237 50-237 50-237 50-237 50-237	ե ե գ			8210190458 8210190462 8210190464 8210190468* 8210190471*	50-249 50-373 50-237 50-373 50-249	ន ទ ទ ទ
	8210120105 8210120551* 8210130192 8210130196* 8210130197	50-237 50-254 50-254 50-254 50-249	P F S S			8210190481* 8210190483 8210190487 8210190493* 8210190494*	50-373 50-295 50-373 50-295 50-373	5 6 5 5
	9210130200 9210130201* 9210130233 9210130233 9210130233	50-373 50-249 50-373 50-373 50-373	R S R P P			8210190498 8210190503* 8210190509 8210190514* 8210190522	50-373 50-373 50-373 50-373 50-373	9 9 9
	8210130234 8210130236* 8210130241 8210130241 8210130251	50-373 50-373 50-373 50-373 50-254	5 6 P 8			8210190525* 8210190536 8210190545 8210190573* 8210190606	50-373 50-373 50-237 50-373 50-373	9 9 8 8
	8210130253* 8210130324 8210130328* 8210130370 8210130370	50-254 50-254 50-254 50-454 50-454	8 9 F			8210170624* 6210170624* 6210170656 6210170662 6210170667	50-275 50-275 50-254 50-456 50-275	9 9 9
	8210130373 8210130373 8210130374 8210130374 8210130376	50-454 50-454 50-10 50-10 50-10	0 G F F			8210190700* 8210190715* 8210190737 8210190744* 8210190780	50-254 50-275 50-373 50-373 50-254	98
	8210130374 8210130374 8210130374 8210130374 8210130374	50-10 50-10 50-10 50-10 50-10	F F F			8210200002 8210200007* 8210200078 8210220335 8210220358	50-373 50-373 50-247 50-237 50-10	0 0 0 F
	8210130374 8210130374 8210130374 8210130374 8210130374	50-10 50-10 50-10 50-10 50-10	F F C			8210220358 8210220358 8210220358 8210220358 8210220358	50-10 50-10 50-10 50-10 50-10	Г Г Г Б
	8210130374 8210130384 8210130384 8210130370* 8210130390*	50-10 50-254 50-254 50-254 50-254	F R R R			6210220358 6210220363 6210220399 6210250049 6210250049	50-10 PR 50-245 50-237 50-237	Р Р
	8210130402 8210130413 8210130423# 8210130464 8210130473#	PR 50-254 50-254 50-254 50-254	8 8			8210250049 8210250108 8210250108 8210250108 8210250114	50-237 50-454 50-454 50-454 50-254	6 E C
	8210130501 8210130511* 8210130044 8210150049* 8210150097	50-254 50-254 50-237 50-237 50-249	8 8 8			8210250124# 8210250148 8210250152 8210250153# 8210250155	50-254 50-254 50-373 50-254 50-254	P S S P
	8210150102* 8210150405 8210150405 8210150411* 8210150411*	50-249 50-295 50-295 50-295 50-295	8 8 8			8210250155 8210250163* 8210250169* 8210250169* 8210250211	50-254 50-373 50-254 50-254 50-456	P 9 P 0
	8210180097 8210180097 8210180097 8210180100* 8210180100*	50-10 50-10 50-10 50-10 50-10	R R R R			8210250211 8210250268 8210250276* 8210250283 8210250294*	50-456 50-237 50-237 50-237 50-237	888
	8210180100# 8210180142 8210180142 8210180146# 8210180167	50-10 50-454 50-454 50-454 50-304	R			8210250304 8210250309 8210250316* 8210250324 8210250324	50-249 50-254 50-249 50-247 50-247	8 5 8 9 9
	8210180175* 8210180196 8210190050 8210190058* 8210190299	50-304 50-10 50-373 50-373 50-456	9 9 8			8210250328 8210250348* 8210260023 8210260115 8210260118*	50-249 50-249 71-9079 50-373 50-373	9

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJEC CATEQO	RY
	8210240221# 8210240210 8210240210	50~373 50~373 50~373 50~304 50~373	6 8 8	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	8210270200 8210270245 8210270247* 8210280071 8210280074*	50-213 50-213 50-213 50-213	9 8 8
	8210260223* 8210260227 8210260233 8210260238* 8210260254*	50-204 50-273 50-275 50-273 50-275	a a a a	Connecticut, State of Conner & Hetterhahn	8210280397# 8210050197 8210050197 8210050326 8210050382	CONTRACT 50-352 50-352 50-352 50-352	7 0 0 0
	0210260295 8210260297* 8210260308* 8210260311 8210260313*	50-373 50-373 50-454 50-373 50-373	6 8 9 9	Compver & Associates, Inc. Insurance	8210050382 8210070402 8210200066 8210270297 8210060020	50-352 50-352 50-352 50-358 70-1621	0 0 0
	8210260317 8210260321* 8210260399 8210260411* 8210260485	50-373 50-373 50-295 50-295 50-237	3 3 5 5 6 F	Conservation Council of North Carolina Consolidated Edison Co. of New York	821021034B 8210010401 8210010401 8210010409* 8210010409*	50-400 50-3 50-3 50-3 50-3	ե 6
	8210260526 8210260526 8210260526 8210260526 8210260526	50-10 50-10 50-10 50-10 50-10	Р Р Р		8210010414* 8210010414* 8210010425* 8210010438* 8210010443*	50-3 50-3 50-3 50-3	ն 6 6
	8210260526 8210260526 8210260526 8210260526 8210260526	50-10 50-10 50-10 50-10 50-10	6 6 9 8		8210010449* 8210040141 8210040145* 8210040232 8210060232	50-3 50-247 50-247 50-247 50-247	P 9 T T
	8210260526 8210260526 8210260526 8210260526 8210260542#	50-10 50-10 50-10 50-10 50-10	t P P		8210060396 8210060400* 8210070361 8210070366* 8210120253	50-247 50-247 50-247 50-247 50-247	8 8 8
	8210260542* 8210260542* 8210260542* 8210260542* 8210260542*	50-10 50-10 50-10 50-10 50-10	р р р Р		8210130277 8210130411 8210130419* 8210130455 8210130559*	PR 50-247 50-247 50-247 50-247	6 6 8
	8210260542* 8210260575* 8210260575* 8210260579* 8210260579*	50-10 50-440 50-440 50-440 50-440	ր - -		92101 70693 92102 50091 92102 50091 92102 50077 92102 50145	50-247 50-247 50-247 50-247 50-247	6 0 8
	8210270251 8210270254* 8210280120* 8210280120* 8210280125*	50-249 50-249 50-295 50-295 50-273	ច ភ ខ ខ		8210250149* 8210260392 8210280154* 8210280154* 8210280159*	50-247 50-247 50-3 50-3 50-3	د د د
	8210280126# 8210280126# 8210280364# 8210280364# 8210280375#	50-275 50-275 50-254 50-254 50-254	г г г г	Consolidation Coal Co Consumers Power Co	8210290271 8210040214 8207070419 8207070419 8207070422#	50-247 50-10 50-329 50-329 50-329	о к к
	8210280375# 8210280424# 8210280424# 8210280427# 8210280427#	50-254 50-295 50-295 50-295 50-295	F F F F		8207070422# 8207070428# 8207180052 8210010278	50-329 50-329 FOI A 50-329	K K E
	8210280445* 8210280445* 8210280447* 8210280447* 8210280447*	50-295 50-295 50-295 50-295 50-10	f F F				
tech Engineering Services, Inc., ter Systems Support Corp	8210270077* 8210270088* 8210270245 8210040178* 8210170010*	50-10 50-10 Pr 50-206 Contract	f f p				
eticut Vantes Atomic Power Co	8210170156* 8207300326 8210010207 8210010207 8210010207	CONTRACT 50-213 50-213 50-213 50-213	ն Ն ե				
	8210010312 8210010312 8210010312 8210010312	50-213 PR 50-213 50-213 50-213	Р Р Р				
	8210050376 8210130331 6210150122 8210150128* 8210190663	50-213 50-213 50-213 50-213	0 P 8 8				

AUTHOR Affiliation	ACCESSION NUMBER	SUBJECT		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT	
	8210040193 8210040204 8210040213 8210040214* 8210040222	50-329 50-155 50-255 50-255 50-155	0 0 8 9 F		8210280076 8210280107 8210280276 8210290163* 8210290163*	50-327 50-255 50-255 50-329 50-329	5 F Q
	8210040239 8210070013 8210070013 8210070013 8210070014*	50-155 50-155 50-155 50-155 50-155	ն Ն Ն Ե		8210270228 8210270228 8210270227# 8210270227# 8210270240	50-329 50-329 50-329 50-329 PR	A A A
	8210070014* 8210070018* 8210070018* 8210080082	50-155 50-155 50-155 50-255	թ 6 6	Controls for Environmental Pollution, Inc	8210290380* 8210290380* 8210200104*	50~329 50~329 70~820	a
	8210080099	50-255	Q		8210260041* 8210260049*	70-820 70-820	
	82100 80115 82100 80115 82100 80279 82101 20078 82101 30005*	50-329 50-329 50-155 50-255 50-329	R R G P F	Canvai, Inc Cooper Energy Services Cornell Univ Cotter Corp	8210290247 8210120234 8210030412 8210240084 8210240091*	50-247 PT21 NUREO WASTE MO WASTE MO	
	8210130007* 8210130138 8210130145* 8210130146 8210130156*	50-329 50-255 50-255 50-255 50-255	F R S S	Council on Economic Priorities Creare, Inc Critical Mass Energy Project	8207110023 8210050360 8206060002 8210010006 8210080010	70-1510 NUREQ FOIA FOIA FOIA	
	8210130264 8210130264 8210130265 8210130265 8210130266*	50-329 50-329 50-329 50-329 50-329	K K T K	D'Appolonia Consulting Engineers, Inc Dairyland Power Cooperative	8210270439* 8210010389 8210010394* 8210040152 8210050067	40-8681 50-409 50-409 50-409 50-409	P P F
	8210130267* 8210130267* 8210130334 8210130448 8210130457*	50-329 50-329 50-255 50-155 50-155	K F G		8210050070* 8210050339 8210130365 8210130381 8210130416*		0 1 1
	8210130471* 8210130482 8210130494 8210130494 8210130505*	50-155 50-329 50-329 50-329 50-329	0 T T T		8210150203 8210190446 8210190448 8210190454* 8210190654*	50-409 50-409 50-409 50-409 50-409	р Б В
	8210130505# 8210130521 8210150146 8210150152# 8210150300	50-329 PR 50-255 50-255 50-155	T 9 9 6		8210220009 8210220174 8210250349 8210260319 8210280048*	50-409 50-409 50-409 50-409 50-409	1 6 L
	82101 50307# 82101 50470 82101 50533 82101 80186 82101 80191#	50-155 50-155 50-155 50-255 50-255	0 0 F 5 5		8210280051* 8210280053* 8210280055* 8210290151 8210290307	50-409 50-409 50-409 50-409 50-409	ե Ե Ե
	821018 <i>0</i> 206 821018 <i>0</i> 212 821018 <i>0</i> 242	50-155 50-329 50-155	ଜ ଜ ଜ	Data Design Laboratories DeXalb Area Alliance for Responsible	8210060348# 8210210346	50-269 50-454	p
	82101 90364 82101 90364	50-329 50-329	K K	Energy	8210210346 8210210347* 8210210347*	50-454 50-454 50-454	0 0
	8210190459 8210190439 8210190520 8210190535 8210190546	50-155 50-156 50-329 50-255 50-255	P P E P P E	Debeyoise & Liberman	8208290088 8210040024* 8210050202 8210050202 8210050208*	FGIA 50-445 50-413 50-413 50-413	0000
	8210190415* 8210190420 8210190428* 8210190439	50~255 50~255 50~255 50~255		Debevoise & Plimpton Defense,Dept of, Defense Nuclear Agency	8210050208# 8210130299 8210220383 8210040179 8210130528	50~413 50~445 PR 50~348 PR	0 0
	8210190649# 8210200029 8210210294 8210210294 8210220117	50-255 50-155 50-329 50-329 50-155	G A A P	Del-Aware Unlimited, Inc.	8210010244 8210010244 8210180204 8210180204	50-352 50-352 50-352 50-352	00000
	8210220186 8210220334 8210220381 8210220381 8210230371	50~255 PR 50~329 50~329 50~155	P Q Q T		8210180208* 8210180208* 8210180217 8210180217 8210180223	50-352 50-352 50-352 50-352 50-352	00000
	8210240121 8210240121 8210240183* 8210240175* 8210240175*	50-329 50-329 50-255 50-329 50-329	8 9 9		8210180223 8210180224 8210180224 8210180226* 8210180226*	50-352 50-352 50-352 50-352 50-352	0 0
	8210260316* 8210260504 8210260527 8210280061* 8210280063*	50-135 50-329 50-329 50-255 50-255	Q T T F	Delaware, Univ of Detroit Edison Co	8210180253 8210180253 8210150223* 8210010289	50-352 50-352 50-322 50-341	Q T K

AUTHOR AFF (LIATION	ACCESSION NUMBER	SUBJECT CAFEGORY		AUTHOR AFFILIATION	 ACCESSION NUMBER	SUBJECT	
	8210010295* 8210010297* 8210010456 8210040084 8210040127	50-341 50-341 50-341 50-341 50-341	8 8 8		8210070092 8210080208 8210120276 8210130159 8210130177	50-413 50-413 50-329 50-269 50-369	A B P B
	8210080046 8210130158 8210130282 8210130284 8210150322	50-341 50-341 PR 50-341 50-341	A A F Q		8210130180* 8210130242 8210130243* 8210130243*	50-347 745-05 745-05 745-05	8 K K K K
	8210180188 8210170332 8210170657 8210170676 8210220414	50-341 50-341 50-341 50-341 50-341	A S S G A		8210130290 8210130399 8210130467 8210130302 8210130399	50-269 PR 50-369 50-287 PR	Qi P P
.ood Corp Emarch Associates	8210250191 8210260382* 8210280222 8210290399 8210290399	50-341 50-341 50-341 RES FOIA	8 G A		8210150012* 8210150068 8210150079 8210150084* 8210150094	50-349 50-413 50-269 50-269 50-413	8 8 0
y, JA ersy, JB	8207180060 8207180061 8210070199 8210260348 8210260348	FOIA FOIA 50-352 50-338 50-338	G O O		8210150074 8210150101# 8210150101# 82101503A9 8210150318	50-413 50-413 50-413 50-269 50-369	Х К Б Б
hemical Co	8210260355 8210260355 8210040231 8210180177* 8210180215*	50-338 50-338 50-264 50-10 FOIA	G C D		8210150518 8210150522* 8210150522* 8210150617 8210160055	50-369 50-369 50-369 70-2944 50-269	F F P
	8210180219* 8210180222* 8210180227* 8210180234* 8210180239*	FOIA FOIA FOIA FOIA			6210180055 6210180055 6210180060* 6210180060* 6210180060*	50-249 50-249 50-249 50-249 50-269	ե ե ե
	8210180247* 8210180251* 8210180257* 8210180240* 8210180242*	FOIA FOIA FOIA FOIA			8210180128 8210190103+ 6210190103+ 8210190108* 8210190544	50-370 50-369 50-369 50-369 50-269	F F R
	8210180264* 8210180354* 8210180358* 8210180424* 8210180427*	FOIA FOIA FOIA 70-278 FOIA			8210170544 8210170544 8210170552* 8210170552* 8210170552*	50-269 50-269 50-269 50-269 50-269	R R R
	8210180428* 8210180430* 8210180431* 8210180434* 8210290202	FOIA FOIA FOIA FOIA 50-264	8		6210170411 6210170411 6210170475 6210170475 6210170740	50-419 50-419 50-270 50-270 50-370	8 8 F
⊔ef €o	6209170053 8210010090 8210010090 8210010093 8210010134*	50-413 50-369 50-369 50-370 50-413	r ወ ወ ብ		8210190742 8210190751# 8210210131 8210210407 8210210407	50-369 50-269 50-269 50-269 50-269	R P P
	8210010232 8210010282 8210010352 8210010367 8210010463	PR 50-349 50-269 50-370 50-269	a F G a		8210210407 8210210411* 8210210411* 8210210411* 8210220134	50-269 50-269 50-269 50-269 50-413	។ ក្ ស្
	8210040107 8210040232 8210040232 8210040233 8210040245	50-269 50-269 50-269 50-269	የ የ የ የ		821 0220134 821 0220202 821 0220202 821 0220206 821 0220206	50-413 50-369 50-369 50-369 50-369	0 0 0 0
	8210040245 8210040245 8210040254 8210040254 8210040253	* 50-269 50-369 50-369	Р Г К К		8210220318 8210220327* 8210220426 8210220426 8210220426	50-369 50-369 50-269 50-269 50-269	8 8
	8210040273 8210040279 8210040277 8210040286 8210040286	* 50-349 * 50-349 * 50-369	К К К К		8210250282 8210250282 8210250125 8210250125	50-413 50-413 50-413 50-413 50-413	6 6 6
	82100 50130 82100 50202 82100 50202 82100 50208 82100 50208	50-413 50-413 50-413 \$0-413	۵		8210250304 8210260201 8210260331 8210260336* 8210260415	50-349 50-413 50-369 50-369 50-413	6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
	9210050264 9210050364 9210060311 9210070078 9210070078	50-413 50-413 50-369	A A F		8210270139* 8210270139* 8210270144* 8210280017* 8210280017*	50-369 50-369 50-369 50-369 50-369	11 11 11 11

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8210280020* 6210280020* 8210280045 8210280045 8210280045	50-369 50-369 50-413 50-413 50-370	F E E E		8210250372* 8210270266* 8210280292 8210280323 8210280337	50-213 50-155 RES RES RES	
	8210270083 8210270087* 8210270117 8210270190 8210270197*	50-270 50-270 50-413 50-269 50-269	9 8 9 9	ENSA, Inc Earthquake Engineering Research Institute Ebasco Bervices, Inc (subs of Enserch		RES CONTRACT CONTRACT	P
	8210290250 8210290308 8210290313* 8210290354 8210290354	50-413 50-287 50-287 50-413 50-413	8 8 8 8 8	Corp }	8210040334 6210150431 8210190720# 8210240114 8210240464	50-387 50-261 50-387	A R P A R
Duquesns Light Co	8210290355 8210290365* 8210010013 8210040065 8210050165	50-249 50-249 50-334 50-334 50-334	8 9 F 0 P	Eddlemen, H	8210210308 8210210308 8210210376 8210210374	50-400 50-400 50-400	2 00000
	8210050168* 8210060076 8210060081* 8210060088 8210060096*	50-334 50-334 50-334 50-334 50-334	P R R R	Edelstein & Payn* Ederer, Inc	8210210419 8210250048 8210250048 8210210419 8210210329	50-400 50-400 50-400 TOPREP	0 6 6
	8210070155 8210070233 8210130561 8210150018* 8210150185	50-412 50-412 50-334 50-334 50-334	\$ 8 P Q S	Edgar, G L Edison Electric Institute Edlow international Co	8210050184 8210040185 8210040200 8210130282 8210070410*	50-537 50-537 PR 71-9150	G G
	8210150199 8210150201* 8210150208* 8210150312 8210150316*	50-334 50-334 50-334 50-334 50-334	8 8 9 P		8210080003 8210080005* 8210080071 6210210539 8210210543*	XPORTLIC XPORTLIC XPORTLIC 70-2955 70-2955	
	8210190274 8210190282* 8210190747 8210210006 8210210010*	50-334 50-334 50-334 50-334 50-334	8 8 8	Electric Power Research Institute Emporta State Univ Energy Fuels Nuclear, Inc	6210120397 8210180416* 8210280516 8210250006 8210250008*	XPGRTLIC RES CONTRACT 40~8691 40~8691	
	8210210065 8210210072* 8210220184 8210260125* 8210260129*	50-334 50-334 50-334 50-334 50-334	9 9 6 F		8210250034 8210240017 8210240018* 8210240022 8210270209	40-8681 40-8681 40-8681 40-8681 40-8681	
	8210260135 8210260143 8210260163 8210260167* 8210260203	50-412 50-412 50-334 50-334 50-334	8 8 9 9	Energy, Dept of	8210270435 8210040251 8210030184 8210040185 8210040200	40-8481 50-537 50-537 50-537 50-537	A G C G
	821 0240226* 821 0240458 821 0240478 821 0240487* 821 0270247	50-334 50-334 50-334 50-334 50-334	8 8 6		8210070409 8210130246 8210130249 8210130311	71-9150 50-537 50-537 50-537 50-537	BAAQ
	821 0270268+ 821 0270271+ 821 0280271 821 0280280 821 0280307	50-334 50-334 50-334 50-334 50-334	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8		8210130343 8210130435 8210170466* 8210200057 8210210022	50-537 50-322 70-143 50-537	Q A
EQ&O, Inc	8010070320* 8205250020* 8210060417 8210070079* 8210080054*	50-305 50-155 Nureg 50-29 Fola	р Р		8210210273 8210250025 8210250040 8210250041* 8210260148	WASTE HO' 70-143 70-143 50-537	٨
	8210080057* 8210080064* 8210120118 8210120124 8210120300*	FOIA 50-317 RES RES 50-213	P P	Energy, Dept of, Clinch River Breeder	8210260401 8210270074 8210270079* 8209300353	50-537 50-537 71-6639 71-6639 50-537	A
	8210120369 8210120397	REB REB REB		Reactor Plant	8210040167	50-537	A
	8210120400 8210120430 8210120463	RES RES			8210040304 8210060217 8210060249	50-537 50-537 50-537	AAAA
	8210120654 8210120657 8210150409	REB REB RES		Engineering Decision Analysis Company, Inc	8210150186 8210070091*	50-537 50-29	P
	8210150412 8210150415	RES RES		Engineering Science Entwisie, E B, Enviro Audite	8210280319* 8210150200 8210040301*	CONTRACT 50-170 50-338	H P
	8210150421 8210150560 8210150611	RES NUREO RES		Enviro Audita Environmental Protection Agency	821040301* 8210130117 8210260235	50-413 50-440	D
,	8210150625 8210200102	REB REB		Envirosphere Co European Communities, Commission of	8210280306* 8210270094	CONTRACT XPORTLIC	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGGR		AUTHOR AFF IL I ATION	ACCESSION NUMBER	SUBJECT CATEGOR	
Ereter.IM Erson Nuclear Co . Inc (subs of Exxon Corp)	8210280064 8210280088 8210120517* 8201200662*	XPORTLIC XPORTLIC CONTRACT 50-261 TOPREP			82101 70348 82101 70351 82101 70351 82101 70371 82101 70371 82101 70374*	50-387 50-250 50-250 50-335 50-335	
	8210120230 8210130123 8210150033 8210150173 8210150182*	50-316 50-316 50-316 TOPREP TOPREP	P P P		8210190440 8210190440 8210190440 8210190440 8210190559	50-250 50-250 50-250 50-250 50-250	٠ د د د
	8210150511 8210190502 8210260557 8210260560# 8210270092	TOPREP 50-219 40-8102 40-8102 TOPREP	la .		8210190559 8210220090 8210220167 8210220214 8210220286*	50-250 50-251 50-389 50-389 50-335	6 6 6 6 5
	8210270164 8210270169* 8210270195 8210270197* 8210270214	TOPREP TOPREP 40-8102 40-8102 TOPREP			8210220304= 8210220451 8210250313 8210250317 8210260116	50-250 50-335 50-389 50-389 50-250	Q A R S
Farsteal Metals (subs of Fanstee),Inc) Federal Emergency Management Agency	8210280184* 8210070075 8210070109 8210070109 8210070112*	40~7580 50~440 50~445 50~445 50~445	G F F		8210240117* 8210240357 8210240349* 8210240391* 8210270253	50-250 50-335 50-335 50-335 50-250	9 9 8 8
	8210070112* 8210130161 8210130320 8210130430 8210170760*	50-445 50-289 50-289 50-387 50-254	3 4 7 7		6210280067 6210280254 6210280291 6210280291 6210280293*	50-387 50-387 50-250 50-250 50-250	E A F F
Finamore, B A Fiore & Jaskot	8210210159* 6210250170 6210130268 6210210232 6210260352*	50-382 50-10 50-537 50-537 40-8410	о г о	Florida Power Corp	8210280293* 6210290240 6210010049* 6210060198 6210060263	50-250 FR 50-302 50-302 50-302	F Q P P
Fleomang, Anderson, McClung & Finch Florida Power & Light Co	8210150490 8209170062 8210010017 8210010084* 8210010153*	50-361 50-250 50-389 50-335 50-335	G F A Q		8210130310 8210130319# 8210130520 8210130530# 8210150216	50-302 50-302 50-302 50-302 50-302	8888
	8210010164 8210010174* 8210010292 8210010292 8210010321*	50-335 50-335 50-250 50-250 50-250	្ ត ន		82101 90677 82101 90681 82101 90687# 82101 90691 82102 10421	50-302 50-302 50-302 50-302	8 6 8 6
	8210050061 8210050152 8210050416 8210050417* 8210050567*	50-335 TOPREP 50-389 50-389 50-335	P A A F		8210220052 8210220036* 8210220207 8210220395 8210260010*	50-302 50-302 50-302 PR 50-302	9 9 P
	8210060209 8210060212# 8210060236 8210060276 8210060281	50-251 50-251 50-387 50-387 50-250	8 9 8 A P		6210240012+ 8210240310+ 8210240377+ 8210240422 6210240434	50-302 50-302 50-302 50-302 50-302	F Q Q P P
	8210040288 8210040288 8210040371 8210080252 8210080257*	50-335 50-335 50-389 50-250 50-250	P P R S S	Food & Drug Administration	8210260454 6210260497 8210290186 6210290312 8210190118	50-302 50-302 50-302 50-302	P 9 8
	8210080264 8210130090 8210130257 8210130289 8210130301	50-335 50-389 50-389 50-389 50-389	9 £ A	Forbes Health Sys , East Suburban Health Center Monroeville, PA Fox Consulting Engineers & Geologists Franklin Institute/Franklin Research Center	85101503894 8510540421	HEOGD HASTE HO	T _n
	8210130348 8210130399 8210130454 8210130462* 8210130334	50-389 PR 50-335 50-335 50-389	F S B				
	8210130552 8210130562* 8210150035 8210150039* 8210150407	50-335 50-335 50-335 50-335 50-250	8 5 6 9 P				
	8210150407 8210150413* 8210150413* 8210150439 8210150439	50-250 50-250 50-250 50-250 50-250	թ թ				
	8210190186* 8210190186* 8210190194* 8210190310	50-250 50-250 50-250 50-335	F F P	Friends & Family of OA Technologies: Ir			

CONFURMIC SOUNCE INDEX

ROHTUA AFF ILIATION	ACCEBBION NUMBER	SUBJECT	AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
GUARD	8210280062 8210270141 8210270144* 8210270234 8210150470	XPORTLIC TOPREP TOPREP PR 50-361			50-289 50-219 50-320 50-320 50-3219	
Gage-Babcock Associates, Inc Galiagher, PK Galio, J Gard. Inc General Accounting Office	9210270230* 8210150490 8210060204 8210280374* 9210270020*	CONTRACT 50~361 50~155 CONTRACT 50~537		8210200012 8210210280 8210220187* 8210220372 8210250092	50-320 50-219 50-219 PR 50-219	р Р О
Opneral Electric Co.	8207090224 * 8207120147 8207120253 * 8207290410 8210010217	50-270 50-447 50-447 NUREQ TOPREP		8210250097* 8210250134 8210250189 8210250285 8210250383	50-219 50-219 50-219 50-219 50-219	و د د
	8210010224* 8210050328 8210050398 8210050408* 8210080113	TOPREP 50-447 50-447 50-447 XPORTLIC		8210260234* 8210260479 8210260505* 8210280124 8210280127	50-320 50-289 50-289 50-320 50-320	0 R R S
	8210080135 8210080262 8210150348 8210150416 8210150445	XPORTLIC TOPREP 71-5924 TOPREP TOPREP	Georgie Institute of Technology Georgie Power Co	8210270204 8210270234 8210270254 8210270317# 8210010022*	50-289 PR 50-219 50-160 50-321	Р О О
	8210150461 8210180050 8210190785* 8210190785* 8210190810	TOPREP TOPREP 50-254 I 50-254 I TOPREP		8210010094 8210010098* 8210050080 8210050084* 8210050330	50-366 50-366 50-366 50-366 50-321	8 8 S 5 8 P
	8210220174* 8210220205 8210220320* 8210220427* 8210250074*	50-447 70-1113 70-1113 70-1113 50-260		8210050330 8210060231 8210060246 8210060248* 8210060275	50-321 50-366 50-366 50-366 50-366	6 6 6
	8210250077* 8210250078* 8210250110 8210250113* 8210250177*	50-260 50-260 50-70 50-70 50-254		8210060278# 8210060287 8210060287# 8210060317	50-366 50-366 50-366 50-366 50-366	ក ទ ទ
	8210250184* 8210260284* 8210260570 8210270046 8210270051*	TOPREP CONTRACT XPORTLIC 50-447 / 50-447 /		8210070148 8210080234 8210080240± 8210120047 8210120050*	50-424 50-366 50-366 50-366 50-366	6 8 8
	8210270057 8210270283 8210280198* 8210280201* 8210290288	71-5939 XPORTLIC 50-277 & 50-277 TOPREP		8210130129 8210130127 8210130132# 8210130132# 8210130183	50-321 50-321 50-321 50-321 50-366	R R R B
		, ,		8210130185# 8210130220 8210130223# 8210130256 8210130258#	50-3&6 50-3&6 50-3&6 50-3&1 50-3&1	8 8 8
				8210130406 8210130414* 8210130541 8210130549* 8210150329	50-366 50-366 50-366 50-366 50-321	888
				82101 80333 • 82101 50362 82101 50362 82101 70016 * 82101 70016 *	50-321 50-424 50-424 50-321 50-321	P A F F
				8210190017* 8210190017* 8210190046* 8210190046* 8210190051*	50-321 50-321 50-321 50-321 50-321	F F F F
				8210190504 8210190511# 8210190595 8210190602# 8210220078	50-366 50-366 50-366 50-366 50-424	88888
				6210220208* 6210220219 6210220222* 6210220267* 6210220267*	50-424 50-321 50-321 50-321 50-321	999
				8210220290 82102202984 8210220384 8210220386 8210220388*	50~346 50~366 50~321 PRM 50~321	P 5 8

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFF IL TATION	ACCESSION NUMBER	SUBJECT CATEODRY	
	8210270246 8210270246 8210270075 8210270080* 8210270076	50-424 50-424 50-366 50-366 50-321	A A S S S		8210220258 8210220276* 8210220288* 8210220295* 8210220410	50-537 50-537 50-537 50-537 50-247	0000
	8210270106* 8210270206 8210270207* 8210270272*	50~321 50~366 50~366 50~321 50~321	3 8 8 8 5 5 5	Harold J Spelman & Associates	8210220455 8210240397 8210240404* 8210280242 8210150463	50-289 50-537 50-537 50-247 40-2041	0000
	8210270273 8210270326 8210270327 8210270327* 8210270334*	PR 50-321 50-321 50-321 50-321	S S G	Harper-Grace Hosps Detroit.Mi Harvard Univ Harsa Engineering Co House of Rep	8210250315 8210050213* 8210010119* 8210270422* 8210070458*	40-2061 70-2942 FOIA CONTRACT FOIA	
	8210290349 8210290357 8210290359 × 8210290364 × 8210290373	50-321 50-366 50-321 50-366 50-321	3 3 3 3	Housing & Urban Development, Dept of Houston Lighting & Power Co	8210270066 8210010301 8210050329 8210070120 8210070147	40-8781 FR 50-478 50-466 50-466	B 0 0
trans, Inc	8210290374 8210290375 ± 8210290381 ± 8210120350 ± 8210190339 ±	50-344 50-321 50-364 CONTRACT CONTRACT			8210200052 8210200052 8210200075 8210200052	80-498 50-498 80-498 80-498 50-498	A A 0 0
ty Q:1 Co (Petrotomics) ps & Hill: Inc (subs of Drayo Corp) der Associates	8210220510 8210270124 8210270129* 8210070021* 8210120458*	40-6659 50-584 50-584 CONTRACT			8210220239 8210220239 8210220123× 8210220123×	50-498 50-498 50-498 50-498 50-498	0 0 0 0 0
lds Pumps. Inc	8210150326* 8210150330* 8210150335* 8210150449 8210150457*	50-341 50-341 50-341 50-358 50-358	Q Q Q Q Q		8210220241* 8210220334 8210250112 8210250247 8210250259	50-498 PR 50-498 50-498 50-498	A 8 8 A
at Lates Energy Alliance เคอไatt, D	8210210391 8210210400* 8210190480 8210210308 8210210308	50-358 50-358 50-255 50-400 50-400	G G G	Hovis, R L	8210250263 8210250358 8210260452 8210260452 8210050169	50-478 50-478 50-478 50-478 50-522	A A B B
d. R ' States Utilities Co	6210210419 8210210419 6210060081 6210040215 6210040215	50-400 50-400 50-413 50-458 50-458	e g k k	Hunton & Williams INTERA Environmental Consultants, Inc	8210120307 8210150277 8210150296* 8210200003 8210290377	50-322 50-322 50-322 50-322 RFB	0 0 0
	8210040220* 8210040220* 8210050201 8210050219 8210050317	50-459 50-459 50-459 50-459 50-459	K K S S	IRT Corp Idaho, State of Igos, V M Illinois Power Co	6210120346* 8210120503 6210270023* 6207160037 6207270072	CONTRACT XPORTLIC 50-597 50-489 50-461	Q B A
	8210050350 8210130182 8210130516 8210170367 8210170318	50-458 50-458 50-458 50-458 50-458	8 9 9 8		6210040104 6210050163 8210050165* 6210050276 6210050261	50-461 50-461 50-461 50-461 50-461	AKKEE AKKEE
	8210190429 8210200037 8210220374 8210250118 8210260286	50-458 50-458 PR 50-458 50-458	8 6 8 8		8210050289 8210130181 8210130184* 8210130270 8210130325	50-461 50-461 50-461 PR 50-461	E G G
Inc ind Engineering Development inatory	8210240292 8210290243 8210040004 8210150550	50-458 PR NUREO NUREO	9		6210130399 6210130470 6210130490 6210150357 6210170350	PR 50-461 50-461 50-461 50-461	F A A B
n & Heirs	8207110033 8207110034 8208270074 8210040175 8210040210 8210120274	50-537 50-537 50-322 50-537 50-289 50-289	A D O O O		8210170354 8210170416 821026003 8210260030 8210260089	50-461 50-461 70-2946 50-461 50-461	8 8 9 0 A
	8210120327 8210130383 8210200026 8210200026 8210200035*	50-537 70-143 50-443 50-443 50-443	0 0 0	Itlinois, State of	8210280160 8210280213 8210210031 8210260501 8210120417*	50-461 50-461 NUREO 50-374 27-39	3 A
	8210200035* 8210200042* 8210200042* 8210200047*	50-443 50-443 50-443 50-443 50-443	G G G		8210130265 8210130265 8210130476 8210130494 8210130494	50-329 50-329 50-151 50-329 50-329	T T 8 T
	8210200054 8210200061 8210210357 8210210453	50-329 50-329 50-337 50-537	e e e	Indiana & Michigan Electric Co.	8210210051 8210010362 8210040073 8210040075# 8210040199	NUREO 50-315 50-315 50-315	F 9 8

AUTHOR AFF IL IATION	ACCESSION NUMBER		JECT EGORY	AFFILIATION	ACCESSIO NUMBER		JECT FODAY
	8210040201 8210040203* 8210040205* 8210040209* 8210040212	50-31 50-31 50-31	15 B 15 B 14 B 15 P	Interior Dept of Interior Dept of, Fish & Wildlife Berwice International Energy Associates, Ltd	821028008 821004032 821003021 821007048 820715005	12 50~41 4 50~24 13∗ ΓΩΙΑ	ıo n
	8210040321 8210040327* 8210040330* 8210050138 8210050138	50-31 50-31 50-31 50-31	6 B 5 P		821004036 821004037 821005030 8210120374 821013013	6* 90-33 7* 50-33 9* 9013	#1 6 Q F
	82;0050159 82;0050159 82;0050140# 82;0050160# 82;005021;1	50~31 50~31 50~31 50~31 50~31	5 P 5 P 5 P		210130137 210130492 210130391 210130304 210130317	1 50-33 1 50-31 3 50-31	1 5 1 9 1 #
	9210050276# 9210050349 9210050349 9210060256# 9210060277	50~315 50~315 50~315 50~315	5 P 5 P	6 8	2101 20546 2101 20565 2101 20570 2101 30140 2101 90664	50-J1 # 50-(131 # 50-3.11	4 1 3 1
	9210040300 9210040307* 9210040313* 9210070279 9210070279	50-315 50-315 50-316 50-315	8 8	0 8	210250269 10250251 10250251 210200076 210200090	90 331 50-911 50-111	11 11 12 12 12 12 12 12 12 12 12 12 12 1
	8210070286* 8210070286* 8210080132* 8210080132* 8210080136*	50-315 50-315 50-315 50-315	I F	83 83 85	210250300* 210250364 210250367* 210260136 20240461	50 333 50-341	i, ii ii fi F
	8210080136* 8210150604* 8210150604* 8210150616* 8210150616*	50~315 50~315 50~315 50~315 50~315	4 4 4 4	District of October 1997 Since Proceedings of October 1997 Since October 1997 Since Proceedings of October 1	10240489 10240495• 08290012 07180052 10010408	50-371	٥ ١٩
	8210180120 8210180123* 8210180129* 8210190040* 8210190246	50-316 50-316 50-315 50-315	3 6 6 7	82 82 82 82	10010446 100502;5 10050221 10050221	50~155 50~329 50~329 50~329 50~329	0 0
	8210190287* 8210190340 8210190342* 8210190380	50-315 50-315 50-315 50-315 50-315	8 8 8	82 82 82 82	0050R23 0050R29* 0050R30 0050R30 0050R32	50-329 50-329 50-329 50-329	00000
	8210190404* 8210190415* 8210190572 8210190578*	50-315 50-315 50-315 50-315 50-315	8 8 8	02) 621 021 621	0050304 1980800 2800000 9900800	50-135 50-434 50-235 50-235	9 9 9
	8210190676 8210190676 8210190685* 8210190685*	50-315 50-315 50-315 50-315 50-315	e R R R	921 1221 1321 1321	01 90449 01 90457# 01 90462 01 90900 01 50970	50-454 50-155 50-155 50-155 50-155	0 0000
	B210190735* 8210190749 8210190757*	50-316 50-315 50-315 50-315	8 8 8 8	821 821 821 821)1801A2)180206)180242)200029	50-155 50-454 50-155 50-155 50-155	0 0000
	5 5 5	00-315 00-315 00-315 00-315 00-315	ት 6 6	Isotope Products Laboratories 19216 Jacksonville Shieyards, Inc 19216 Japan 19216 19210	250211 280030 220314 040382 040385	XPORTLIC PA XPORTLIC XPORTLIC	Q.
	5 5 5 3	0-315	F F F F	H210 Japan Atomic Energy Research Inst H210 Joint Applicants-Glinch River Breeder H210 Reactor	040387 040471 280435 180421 200082	XPORTLIC XPORTLIC XPORTLIC REA 50-537	o
	50 50 50	0-170 0-170	0 0 0	8210 8210	130417 30417 30486# 30486#	50-528 0 50-528 0	e e e
	56 50	0-170	e e	Joint Intervenors - Haterford 연결(oc B2100 KLD Associates, Ing. B2100	5037#¥ 8037#¥	50-528 (6 2 3
	OR FC 50	RQ DIA D-219	Р А	MMC, Inc 82102	50188# 50240# 80041# 50005# 10893	50-322 T 50-322 T 50-322 F PR PR REVIEW CAP	,

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
าลก Tempo กรลจ Gas & Electric Co	8210120331* 8210130399 8210280354* 8210040364 8210120199	REVIEW G PR CONTRACT 50-482 50-482	RP		8210150204* 8210150223* 8210150240* 8210150250* 8210150257*	50-322 50-322 50-322 50-322	T T T T
nsas State Univ nnecoll Copper Corp	8210130399 8210220403 8210190365 8210220074* 8210220077*	PR PR 50-188 40-8111 40-8111	R		8210150265* 8210150272* 8210150279 8210150281* 8210150290*	50-322 50-322 50-322 50-322 50-322	T 0 T T
ntucky. State of rr-Haces Chemical Corp (subs of ter-Haces Corp)	8210220086* 8210210046 8210260574	40-8111 NUREG 40-8027			8210150309# 8210150324# 8210150337# 8210150351#	50-322 50-322 50-322 50-322	9 9 9
r-HrGee Corp	8210260543 8210260548*	40~8027 40-8027			8210150345* 8210150393*	50-322 50-322	e e
	8210260565 8210270077 8210270088* 8210270242 8210270247*	40-8027 40-2061 40-2061 40-8027 40-8027			8210150402= 8210150410+ 8210150422+ 8210150527+	50-322 50-322 50-322 50-322	000
r-HcGee Nuclear Corp awner County, WI ipatrick Lorkhart, Hill, Christopher Fhillips		40-8027 CONTRACT 50-322	Q		8210200003 8210200035 8210250059* 8210260141* 8210280036*	50-322 50-322 50-322 50-322 50-322	96065
	8210050180 8210050189	50-275 50-322	<u> </u>		8210280039* 8210280041*	50-322 50-322	F
	821 00 50383 821 0200076 821 0200083* 821 0200089* 821 0230058	50-322 50-322 50-322 50-322	0000	Los Alamos Scientific Laboratory	8210280285 8210290249 8210120428	50-322 PR RES	8
	8210290097 8210290097 8210290283	50-322 50-275 50-322	P P G	Louise County, VA Louisians Power & Light Co	821 02 6 03 6 7 821 02 6 03 6 7 821 02 6 03 7 3 821 02 6 03 7 3 820 9 1 5 0 4 3 2	50-338 50-338 50-338 50-338 70-2946	0000
shen. AH cville: IN	8210060244 8210180401*	50-285 CONTRACT			82091 50436* 82091 50436*	70-2946 70-2946	
ru Allsance inam. J M osse, Wi	8210210419 8210120362* 8210120423* 8210260530* 8210180338*	50-400 CONTRACT 50-389 CONTRACT CONTRACT	н		8209220135 8209220137* 8210010370	30-382 50-382 50-382	A F
ence General Hosp Lawrence,MA ence Livermore Laboratory	8210180338* 8210210448* 8205250010* 8206170006*	CONTRACT 70-2116 50-155 50-312			8210010381 8210010435 8210040078 8210040110 8210040148	PR 50-382 50-382 50-382 50-382	0 8 4 F
	8207300222* 8209130461* 8209200475* 8210150548 8210290113*	50-204 50-293 50-29 NUREG 50-324	p p p		8210040191 8210070124 8210070197 8210080086 8210080090	50-382 50-382 50-382 50-382	< 0 0 0 0
euf, Lamb, Leiby & MacRao	8210010287	50-341	K		8210130174 8210130243	50-382 50-382	8
ue of Homen Vaters of Rockford, JL	8210180160 8210280250 8210290234 8210070127 8210070127	50-289 50-289 PR 50-454 50-454	0 0 0		8210130245 8210130551 8210130564 8210150347	50-382 50-382 50-382 50-382	9 9 8 8
	8210070129 * 8210070129 * 8210210274 8210210274	50-454 50-454 50-454 50-454	000000000000000000000000000000000000000		8210190345 8210190542 8210210372 8210250217	50-382 50-382 50-382 50-382	0808
	8210210278 8210210278 8210210384 8210210384	50-454 50-454 50-454 50-454	ত ভ ভ		8210250242 8210250254 8210250341 8210250355 8210240362	50-382 50-382 50-382 30-382 50-382	9 9 A F
	6210240380 6210240380 6210240384* 6210240384*	50-454 50-454 50-454	00 00		8210260423 8210270190 8210270193# 8210280387	50-362 50-362 50-362 50-362	Q K K Q
	8210260392* 8210260392* 8210290293	50-454 50-454 50-454	9	Lovisiane, State of	8210290438 8210040002*	71-6574 CONTRACT	
on Steel Foundry h Univ , M	8210270305 8210270370 8210050348 8210010310	50-454 40-8153 NUREO PR	o	Lowell, Univ of Lowerstein Newman, Reis, Axelrad & Yoll	8210150462 8210280183 8210280186# 8210070120	50-416 50-223 50-223 50-466	R R O
ick Ecology Action Estand Lighting Co	8210290304 8210070199 8210040274* 8210040361* 8210070384	50-289 50-352 50-322 50-322 50-322	9 9 9		8210070147 8210200058 8210210363 8210210363 8210210368*	50-466 50-522 50-478 50-478 50-478	00000
	B210120307	50-322	o .		8210210368* 8210290259	50-498 PR	Q
	9210150148 9210150178* 9210150188*	50-322 50-322 50-322	T T T	MPR Associates. Inc. Maine Nuclear Referendum Committee	8210240202 8210010085* 8210010081*	50-219 50-219 50-309	Р Н

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT		AUTI AFF IL I	ACCESSION NUMBER	SUBJECT	
Maine Yankee Atomic Power Co	8210010230 8210040074 8210040077 8210040217 8210050015*	PR 50-309 50-309 50-309 50-309	P P		8210050193 8210050203* 8210060201 8210060203* 8210060224	50-416 50-416 50-416 50-416 50-416	\$ 5 5 5
	8210050018* 8210060171 8210060173* 8210060302 8210130252	50-309 50-309 50-309 50-309 50-309	F P Q P		8210060226# 8210060295 8210060295 8210070044# 8210070044#	50-416 50-416 50-416 50-416 50-416	9 P F
	8210130254* 8210130283 8210130284* 8210130314 8210130340	50-309 50-309 50-309 50-309 50-309	P P G P		8210070048# 8210070048# 8210080120 8210080127# 8210080186	50-416 50-416 50-416 50-416 50-416	F 5 5 5
	8210130369* 8210150398 8210210015 8210210018* 8210220203	50-309 50-309 50-309 50-309 50-309	ր 9 9		8210080192# 8210080223 8210080277 8210080201# 8210080282	50-416 50-416 50-416 50-416 50-416	9888
	8210280212 8210280098 8210240144 8210240193 8210240199	50-309 50-309 50-309 50-309 50-309	ម ល ម ម		8210080284 8210080287* 8210080289* 8210080295 8210080298*	50-416 50-416 50-416 50-416 50-416	9 9 9
	8210240200# 8210240209# 8210240327 8210240420 8210270008	50-309 50-309 50-309 50-309 50-309	8 8 P a		8210150011* 8210150013 8210150019* 8210150024* 8210180104	50-416 50-416 50-416 50-416 50-416	0 0 0 R
	8210270009# 8210270165 8210270177# 8210280087 8210280161	50-309 50-309 50-309 50-309 50-309	0 8 6 f F		8210180109* 8210190417 8210190424* 8210190496 8210190521	50-416 50-416 50-416 50-416 50-416	8 8 9 9
Haine, State of Hanhattan College Hapieton intervenors	8210290343 8210060190 8210280227 8210080341 8210070398	50-309 50-309 50-309 50-179 50-329	8 0 0 P 0		8210190561 8210190566 8210190566 8210190567* 8210200005	50-416 50-416 50-416 50-416 50-416	8 E E
Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div Marshall, M M Maryland, Univ. of Massachusetts Institute of Technology	8210220294 8210040313 8210070398 8210240240* 8210050428	50-329 50-315 50-329 CONTRACT NUREQ	9		8210200005 8210200030 8210200030 8210200064 8210200073	50-416 50-416 50-416 50-416 50-416	E E E
Maywood, NJ McDonald Engineering Analysis Co , Inc	8210150574 8210190334 8210260352* 8210150343* 8210150346*	NUREQ 50-20 40-8610 50-341 50-341	F G G		8210200073 8210210217 8210210217 8210220065 8210220067*	50-416 50-416 50-416 50-416 50-416	P P 8
Memphis State Univ Metropolitan Edison Co	6210150352* 8210260493* 8210270402* 6210060210 8210070194	50-341 50-358 CONTRACT 50-289 50-289	Q E Q		8210220131 8210220150* 8210220158 8210220162* 8210220181	50-416 50-416 50-416 50-416 50-416	99988
	6210080094 8210130275 6210150280 6210150289* 8210200033	50-289 50-289 50-320 50-320 50-289	Q Q B B		8210220191* 8210220194 8210220199* 8210220259 8210220262*	50-416 50-416 50-416 50-416 50-416	9 9 9
	8210210173 8210210179* 8210210266 8210210374 8210280360	50-320 50-320 50-320 50-287 50-289	0 0 0 0		8210220269 8210220274* 8210220278 8210220282* 8210220284	50-416 50-416 50-416 50-416 50-416	99999
Miami Valley Power Project Michigan, Univ. of	6210150449 6210150457# 8210210391 6210210400# 6210060424#	50-358 50-358 50-358 50-358 CONTRACT	0 0		8210220285* 8210220334 8210220425 8210220428 8210220431*	50-414 PR 50-414 50-416 50-416	8 E 8
Micro-Tel Corp Miller, D S. Mississippi Power & Light Co.	8210190223# 8210030236 8210200065 8210290303 8210010023	CONTRACT 50-309 50-309 50-309 50-416	Q Q F		8210220458 8210220462* 8210260264 8210260412 8210260445	50-416 50-416 50-416 50-416 50-416	\$ P P
	8210010223 8210010234 8210010243 8210010248* 8210040053	PR 50-416 50-416 50-416 50-416	F 9 9		8210240513 8210270277 8210280132 8210280132 8210280135	50-416 50-416 50-416 50-416 50-416	8 0 0 0
	8210040053 8210040264 8210040353 8210040353	50-416 50-416 50-416 50-416	P P P		8210280135 8210290050 8210290055* 8210290073 8210290081*	50-416 50-416 50-416 50-416 50-416	P 8 8 8

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	łΥ
	8210290102 8210290102 8210290124 8210290125* 8210290193	50-416 50-416 50-416 50-416 50-417	8888 66888	New Hampshire, State of New Mexico, State of	8210200049* 8210200049* 6210250307 6210120021* 8210120023*	50-443 50-443 50-443 FOIA FOIA	G G A
	8210290311 8210290332* 8210290340 8210290345* 8210290348	50-416 50-416 50-416 50-416 50-416	9 8 8 8 9	New York, State Univ of, Buffalo New York, State of	8210120042* 8210010277 8208290099 8210180419* 8210210041	FOIA 50-57 50-322 50-201 50-201	F & P P
isstsilppi. State of issouri. State of itsut & Co (U S A).inc (Subs of	8210290351* 8210220403 8210270033* 8210130078	50-416 PR CONTRACT XPORTLIC	8	New York, State of, Energy Research & Development Administration New York, NY	8210220321 8210260582*	PR 50-201 50-247	a
Hitsuf & Co (Ltd)	8210130080¥	XPORTLIC		News & Observer News-Herald Willoughby, OH	8207180044 8207180055	50-241 50-440	P
olycorp. Inc	8210270007 8210270448 8210270452* 8210080327 8210080331*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		Niagara Hohaut Power Corp	8210010033 8210010145* 8210010207* 8210040071 8210040117	50-220 50-220 50-220 50-410 50-220	P 0 0 0 0 P
nroe K-Ray Co , Inc Irgan Associates	8210010005 8210010024* 8210040235 6210250081 6210250081	71-481 71-481 50-247 50-247 50-247	000		B210040170 B2100401B2 B2100401B3* B210040170 B210040276	50-410 50-220 50-220 50-410 50-220	9 P P P
	8210250216 8210250216 8210250265 8210250265 8210250272	50-247 50-247 50-247 50-247 50-247	6 6 6 H		8210040303* 8210050111 8210050148 8210050260 8210050354	50-220 50-220 50-220 50-220	t t t
rgan. Lewis & Bockius yns Laboratory/Monsanto rray. Plumb & Murray	8210250272 8210270271 8210240581 8210150547 8210240457	50-247 50-247 50-201 NUREQ 50-309	9 9		8210060208* 8210060284 8210060271* 8210130107 8210130347	50-220 50-220 50-220 50-220	8 8 8
industries. Inc 3 Corp	B210240445# B210010434# B210010440# B210040354# B210210304#	50-309 40-1202 40-1202 50-261 50-329	r A		8210130350* 8210150127 8210150135 8210150142* 8210210322	50-220 50-410 50-220 50-220 50-410	R 8 8 8
IECH (Nuclear Technology, Inc)	8210010440# 8210050427# 8210150377# 8210150500# 8210150504#	50-341 50-155 50-263 50-263 50-263	А Р Р	North Carolina, State of	821025037B 8210260184* 8210260121 8210280144 8210220518	50-410 50-220 50-220 50-220 70-1113	6 8
ional Nuclear Corp ional Wildlife Federation	8210150509# 8210130076 8210270152# 8210080073 8210220434	50-263 XPORTLIC XPORTLIC 50-522 50-522		North Carolina, Univ of North Shore Committee Against Nuclear & Thermal Pollution	8210270395* 8210280321* 8210150234	CONTRACT FOIA 50~322 50~322	9
ural Resources Defense Council	8210040195 8210120302 8210120327 8210130248 8210130383	50-537 50-537 50-537 50-537 70-143	0 0 0		8210150324* 8210150337* 8210150351* 8210150345* 8210150393*	20-325 20-335 20-335 20-335	0 0000
	8210200001 8210200004# 8210210232 8210210240# 8210210357	70-143 70-143 50-537 50-537 50-537	G G	Northeast Nuclear Energy Co (subs. of	8210150410* 8210150410* 8210150422* 8210150527* 8210250059* 8210016207	50-322 50-322 50-322 50-322 50-323	40000
	8210210453 8210220248 8210220274* 8210220277* 8210220283* 8210220283*	50-537 50-537 50-537 50-537 50-537	0 0 0 0 0	Northeast Utilities)	8210010207 8210010207 8210010214* 8210010230	50-213 50-213 50-213 PR	b b
)jo Nation 4314 Public Power District	8210220295* 8210260397 8210260404* 8210250025	50-537 50-537 50-537 WASTE MG	000		9210010312 9210010312 9210010376 9210010385* 9210040120	50-213 50-336 50-336 50-345	4 4884
#398 LANTIC + AMBL DISSILVEA	8210130318 8210220136* 8210220254 8210260217	50-298 50-298 50-298 50-298 50-298	, e e a		8210050118 8210050117 8210050177 8210050187#	50-336 50-245 50-245 50-336 50-336	6 6 6 6
England Coalition on Nuclear Juston	8210200026 8210200026 8210200026 8210200035*	50-276 50-296 50-443 50-443	0 0		8210060044 8210060094 8210060237	50-245 50-245 50-245 50-336	P P G P S
	8210200035* 8210200042* 8210200042*	50-443 50-443 50-443	000		8210070238# 8210070250 8210070304 8210070356#	50-336 50-245 50-245 50-245	8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	TOBLEUB RODBIAD	
	8210070340 8210080105 8210130228 8210130232* 8210130326	50-245 S 50-423 A 50-336 S 50-336 S 50-10 P		8210060380* 8210060386* 8210080117 8210080184 8210080184	50~263 50~263 50~263 50~282 50~282	P G F F
	8210130331 8210130331 8210130331 8210190472 8210190476*	50-213 P 50-213 P 50-213 P 50-334 Q 50-334 Q		8210130240 8210130241 8210130510 8210130533* 8210130563	50-263 50-263 50-282 50-282 50-306	1
	8210190555 8210210155 8210210160* 8210210340 8210210425	50-423		8210130544 8210150174 8210150180 8210150255 8210150255	50-304 50-263 50-263 50-282 50-282	0 5 8 0
Northeast Utilities	8210220060 8210220103 8210220108* 8210220108*	50-336 8 50-336 9 50-245 8 50-245 9 50-245 9		8210150364 8210150381 8210150390> 8210190289 8210190293*	50-263 50-282 50-282 50-263	p 5 5 6 6
	8210220116# 8210220195 8210220201# 8210250290 8210250329	50-245 B 50-245 S 50-245 S 50-423 S 50-423 S		8210190422 8210190439* 8210190439* 8210190479 8210190726	50-282 50-282 50-282 50-263 50-306	8 9 9
	8210260174 8210260414 8210260432 8210260441+ 8210260459	50-245 P 50-245 P 50-336 B 50-336 B 50-245 P		8210190745* 8210250179 8210250183* 8210250200 8210250364	50+306 50-282 50-282 50-282 50-282	9 9 9 9
	8210240317 8210270200 8210270200 8210010207 8210010207	50-245 P 50-213 P 50-213 P 50-213 P 50-213 P		8210250376* 8210260154 8210260154 8210260209 8210270262	50-282 50-282 50-282 50-243 50-262	5 P P P
	8210010207 8210010230 8210010312 8210010312 8210010376	50-213 P PR 50-213 P 50-213 P 50-336 S	Nuclear Assurance Corp	8210270242 8210270237 8210270249 8201040245* 8210050437*	50~282 PR FR FOIA FOIA	ŀ
	82100 40120 82100 50070 82100 50118 82100 50177 82100 50179	50-245 F 50-334 P 50-245 P 50-245 P 50-336 P		8210050446* 8210050467* 8210050471* 8210070156* 8210270427*	70-1510 FOTA FOTA CONTRACT 70-1510	ļ
	82100 40048 82100 60074 82100 40233 82100 60237 82100 70250	50-245 P 50-245 P 50-245 Q 50-336 P 50-245 8		8210270429* 8210270437* 8210270438* 8210280448 8210290155	70-1510 70-1510 70-1510 71-9010 71-6698	
	6210070304 6210070354* 6210070340	50-245 G 50-245 G 50-245 S	Nuclear Energy Service, Inc Nuclear Fuel Services, Inc (subs of Getty Gil Co)	8210040228# 8210010184	50+352 70-143	G
	8210130228 8210130331	50-336 9 50-213 P	311 July 201	8210150061 8210150371* 8210150408*	70-143 70-143 70-143	
	B210130331 B210130397 B210190555 B210210155 B210210340	50-213 P PR 50-423 S 50-336 S 50-423 S		8210150477 > 8210220395 8210240548 821024057 8210240581	70-143 PR 70-143 70-143 50-201	o
	B210210425 B210210430* B210220040 B210220103 B210220195	50-245 B 50-245 B 50-336 B 50-245 S 50-245 S	Nuclear Lew Ganter Nuclear System Oak Ridoe National Laboratory	9210260592* 9210270235 9207180041 9210290398* 9202020441*	50-201 70-143 FOIA CONTRACT FOIA	G
	8210250290 8210250329 8210260194 8210260414 8210260432	50-423 8 50-423 8 50-245 P 50-245 P 50-334 8		82031 60383* 82032 50320* 821 00 50504 821 00 60005* 821 00 60425	FOIA FOIA REG FOIA REB	
Northern California Power Agency, California:State of, Northern Indiana Public Service Co	8210260457 8210260519 8210270200 8210250356 8210250462	50-245 P 50-245 P 50-213 P PROJ 50-367 Q		8210070253# 8210120453 8210120653 8210150564	50-537 RES RES NUREO NUREO	A
Northern Indiana Public Service Co Northern States Power Co	8210010034 8210010041* 8210010046* 8210010040 8210040123	50-263 P 50-263 P 50-263 P 50-263 P 50-282 P	,	8210150567 9210150569 9210150577 8210180407 8210210034 8210210037	NUREO NUREO REB 50-259 NUREO	r
	8210050319 8210040258 8210040260* 8210040377	50-282 P 50-263 8 50-263 8 50-263 P		8210210039 8210260206 8210270035* 8210270052*	NUREQ NUREQ 50-537 50-537	e e

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR Affiliation	ACCESSION NUMBER	EUBJECT CATEGO!	
Czean County, NJ	8210270056* 8210270068* 8210280110* 8210290006* 8210120541*	50-537 50-597 FOIA COMMISSI CONTRACT		Parameter, inc Parents Concerned About Indian Point	8210240260* 8210200019 8210200019 8210220369 8210220369	CONTRACT 50-247 50-247 50-247 50-247	7 0 0
Gfrace of Management & Budget	8210120402 8210120404 8210270116 8210270119	org Org Org Org		Pathfinder Mines Corp	8210150601 8210150607 8210150613* 8210180415	40-6622 40-2259 40-2259 40-6622	
Cyle Petroleum. Inc	8210260577 8210270063 8210280046 8210280049* 8210010335 8210010335	40-8745 40-8745 40-8745 40-8745 50-440 50-440	G G		8210180420* 8210220476* 8210250028 8210260013 8210260014* 8210270054	40-6622 40-6622 40-6622 40-6622 40-6622 40-2259	
	8210010366 8210010366 8210010377 8210010377 8210010386	50-440 50-440 50-440 50-440 50-440	0 0 0 0	Pennsylvania Power & Light Co	8210270177 8210010177 8210010180* 8210010228 8210010228	40-6622 50-387 50-387 50-387 50-388	8 8
	82100 10386 82100 10416 82100 10416 82100 60207 82101 50192	50-440 50-440 50-440 50-440 50-400	0 0 0		82100 0393 82100 0402* 82100 0417 82100 40052 82100 4008&	50-387 50-387 50-387 50-387 50-387	8 F 8
	8210180211 8210210351 8210210351 8210210358* 8210210358*	50-440 50-440 50-440 50-440 50-440	0 0 0 0		82100 40088* 62100 40 116 62100 40 122* 62100 50325 62100 50370	50-387 50-387 50-387 50-387 50-387	9 9 6 7
ghio State Univ Ohmant Corp	6210210366* 6210210366* 6210220461 6210210176* 6210060415*	50-440 50-440 50-440 CONTRACT FOLA	G G		82100 60 199 82100 6039 1 82100 80083 82100 80 142 82100 80 146*	50-387 50-387 50-387 50-387 50-387	ր թ թ
Dal.Chemical & Atomic Workers Int) Oilahona Steel Castings Co Uraha Public Power District	8210130281 8210220316 8209170051 8210040186 8210040187*	70-143 PR 50-285 50-285 50-285	۲ 9		8210080151* 8210130122 8210130341 8210130332 8210130341*	50-387 50-387 50-387 50-387 50-387	8 C b b
	82100 50247 62100 5030 1 62100 50303* 82100 60176 62100 70333*	50-285 50-285 50-285 50-285 50-285	6 6 6 6		8210130343 8210130371* 8210130377 8210130389* 8210170164*	50-367 50-367 50-367 50-367 50-367	ម ១ ១ ទ
drange County, CA	8210130570 8210190736 8210190746* 8210200077 8210130259	50-285 50-285 50-285 50-285 PRM	B R R P		8210190166# 8210190173# 8210190173# 8210190297 8210210020	50-387 50-387 50-387 50-387 50-387	F F F 9
uregon Environmental Council Orrack, Herrington & Sutcliffe	8210080073 8210130309 8210150454 8210150454 8210150482	50-522 50-361 50-361 50-361 50-361	9 9 9		8210210020 8210210137 8210210137 8210210285 8210210293#	50-387 50-387 50-387 50-387 50-387	8 8 8
Pacific Air Products Co Pacific Oas & Electric Co	8210150482 8210190372* 8210010198 8210010307 8210010404	50-361 0A999 50-133 PR 50-275	е г Р		8210210417 8210210433 8210210436# 8210210440 8210210446#	50-387 50-387 50-387 50-387 50-387	p 8 8 8
	8210010413* 8210050122 8210050144 8210050144 8210060220	\$0-275 \$0-275 \$0-275 \$0-275 \$0-275	17 17 18 18 18 18 18 18 18 18 18 18 18 18 18		6210220102 6210220175 6210220366 6210250256 6210250264*	50-387 50-387 PR 50-387 50-387	6 6 7
	8210120278 8210120283* 8210130272 8210150151 8210150159*	50-275 50-275 50-275 50-275 50-275	P P R R		8210250276# 6210250347 6210250357 6210250367 6210250369	50-387 50-387 50-387 50-387 50-387	P 8 P 8
	B210150389 B210210044# B210210048# B210220371 B210220395	50-275 50-275 50-275 50-275 PR	ե ե ե		8210250373# 8210250377# 8210250380# 8210250381 8210250385#	50-367 50-367 50-367 50-367 50-367	p 9 9 8
	8210250192 8210250196* 8210260359 8210270236 8210270240*	50-133 50-133 50-133 50-275 50-275	R P R R		8210240270* 8210240350 8210240354* 8210240364 8210240379*	50-387 50-387 50-387 50-387 50-387	0 P P P
Pacific Pumps Div Palmetto Alliance	8210270351 8210290219 8210290222* 8210040155* 8210080081	50-275 50-275 50-275 0A999 50-413	6 8 8		8210240330 8210280217* 8210280215 8210240385*	50-387 50-387 50-387 50-387 50-387	P 8 8 6

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEQURY		AUTHOR AFF IL IATION	ACCESSION NUMBER	SUBJECT CATEGORI	
Pennsylvanía State Univ Pennsylvania, State of	8210290318 8210130487 8210040218 8210210378 8210270203*	50-387 F 50-413 D 50-289 G 50-289 G CONTRACT	F D G	Pollution & Environmental Problems, Inc Portland Cament Association Portland General Electric Co	8210210235 8210240527 8210040163 8210080253# 8210130399	50-275 / 50-329 ; 50-344 / 50-344 (PR	
Perkans, Coie, Stone, Olsen & Williams	8210280235* 8210290131* 8210010382 8210050171 8210130190	CONTRACT CONTRACT 50-522 C 50-522 C 50-522 C			8210190024* 8210190026* 8210220301 8210250084 8210250093*	50-344 50-344 FR 50-344 50-344	
	8210130367 8210130367 8210130498 8210130498 8210200045	50-522 G 50-522 G	G G G G	Power Authority of the State of New York	8210250164 8210250175± 8210040213• 8210040317 8210040324	50-344 \ 50-344 \ 50-286 \ 50-333 \ 50-333 \	
Philadelphia Electric Go	8210260430 8207090201 8207090208# 8207090215# 8209170149	50-278 f 50-278 f 50-278 f	B የ የ የ የ		8210040332* 8210050079 8210050083 8210050085* 8210050085*	50-333 50-284 50-333 50-333 50-333	
	8210040224 8210040362 8210040362 8210050197 8210050197	50-352 A 50-352 A 50-352 G	G A G G		8210060091 8210060145 8210060148* 8210060181 8210060235	50-286 50-247 50-247 50-286 P 50-247 6	
	8210050320 8210050321 * 8210050321 * 8210050321 *	50-277 F 50-277 F 50-277 F	P P P G		82100A0235 82100A0285 82100A0292* 8210120240 8210120243*	50-247 C 50-333 S 50-333 S 50-333 R 50-333 R	
	8210050382 8210060017 8210060047 8210060074 8210060083#	50-278 S 50-277 S 50-277 S	0 5 5 5		8210120253 8210150031 8210150283* 8210160088 8210180091*	50-247 P 50-286 P 50-333 0 50-286 R 50-286 R	1
	8210060177 8210060296 8210060296 8210060353 8210070177	50-277 5 50-277 5 50-277 5	9 J G Q		8210190069 8210190077# 8210190411 8210190435# 8210190713	50-333 9 50-333 9 50-333 0 50-333 0	
	8210070188* 8210130226 8210130294* 8210150069 8210150126	50-278 S 50-277 G 50-277 G	а э о о Л		8210190728 8210190734* 8210190738 8210200018 8210200024*	50-286 P 50-286 P 50-286 F 90-333 R 50-333 R	
	8210150126 8210150133* 8210150133* 8210150154 8210150179*	50-352 A 50-352 A 50-277 8	A A B B		8210200028 8210200039* 8210200074 8210210459 8210210470*	50-333 P 50-333 P 50-333 P 50-286 P 50-286 P	•
	8210150282 8210150292* 8210150354 8210150356 8210150368*	50-277 F 50-277 F 50-277 F	F R R ,		8210210473* 8210220324 8210250081 8210250081 82102502816	50-205 P PR 50-247 0 50-247 0 50-247 0	:
	6210150368* 8210150397 8210150397 8210150400 8210200046	50-352 0 50-352 0 50-277 8	fi c c s p		8210250214 8210250245 8210250265 8210250272 8210250272	50-247 0 50-247 0 50-247 0 50-247 15 50-247 16	
	8210200044 8210200063* 8210200066 8210200066	50-277 P 50-352 G	P P P G P		8210260170 8210260175* 8210260304 8210260338* 8210260378	50-333 S 50-333 S 50-333 S 50-333 S	i
	8210200068* 6210210297 8210210297 8210210330 8210210330	50-277 F 50-277 F 50-277 F	ե Ե Ե	President of US & Executive Offices	8210260386* 8210280070 8210290271 8208010022 8210070448*	50-333 \$ 50-286 P 50-247 O MISC FOIA	1
	8210220006 8210220007* 8210220190 8210220190 8210220194*	50-278 P 50-277 R 50-277 R	e የ የ የ	Project Management Corp	8210050184 8210060185 8210060200 8210130343 8210130435	50-537 0 50-537 0 50-537 0 50-537 0 50-537 0	
	8210220174* 8210220374* 8210260112 8210260158 8210260327	50-352 0 50-277 8	R O S A F	Public Interset Research Group, New York	8210260361 8210130335 8210130337* 8210130337*	50-537 © 50-247 © 50-247 0 50-247 0 50-247 0	† !
Phosnix, AZ Pipe Fabrication Institute Plateau Resources, Ltd,	8210280194 8210280204* 8210040004* 8210220342 8210260019	50-277 P 50-277 P CONTRACT PR 40-8698		Public Service Co, of Colorado	8210200019 8209150440# 8210040114 8210050331 8210050337#	50-247 0 50-257 F 50-257 P 50-257 S 50-267 S	

AUTHOR AFF (LIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8210040273 8210040282* 8210040284* 8210080254 8210130344	50-267 50-267 50-267 50-267 50-267	P P P R		8210070314* 8210070351 8210070359* 8210070368 8210070371	50-272 50-311 50-311 50-272 50-311	
	8210130347* 8210190306 8210190537 8210190543* 8210190655	50-267 50-267 50-267 50-267 50-267	a r s s n		8210070375* 8210070377* 8210070380 8210070388* 8210080241	50-272 50-311 50-272 50-272 50-311	8 8 8
	8210190467* 8210190701 8210190704* 821021008(* 8210210089*	50-267 50-267 50-267 50-267 50-267	ր բ ր		8210080294 8210120328 8210130164 8210130170* 8210130219	50-311 50-272 50-311 50-311 50-311	86899
	6210220359 6210250083 6210270104 6210270113* 6210270118*	PR 50-267 50-267 50-267 50-267	F P P		8210130227* 8210130340 8210130345* 8210130351 8210130358*	50-311 50-311 50-311 50-311 50-311	8888
Public Service Co of Indiana, Inc	8210280382 8210010230 8210130545 8210250130 8210290239	71-9044 PR MISC 50-546 PR	ß		8210130554 8210150057 8210150058 8210150065* 8210150066*	PR 50-311 50-272 50-311 50-272	8 8 8
Public Service Co of New Hampshire	8210290240 8210010445 8210010470* 8210010470*	PR 50-443 50-443 50-443 50-443	A A A		8210150071 8210150075* 8210150080 8210150088 8210150089*	50-272 50-272 50-311 50-311 50-311	8 8 8
	BR10040112 8210040112 8210040193 8210040193 8210050199	50-443 50-443 50-443 50-443	A A A A		8210150093* 8210150099 8210150109 8210150111 8210150118*	50-311 50-311 50-311 50-272 50-311	8 8 8 8
	8210050199 8210070105 8210130436 8210150510 8210180001	50-443 50-443 50-443 50-443 50-443	^ ^ ^ ^		8210150121# 8210150127 8210150140# 8210150148 8210150155#	50-272 50-272 50-272 50-272 50-272	8 8 8
	82101 90126 82101 90126 82101 90136 82101 90363	50-443 50-443 50-443 50-443 50-443	5 5 5 8		8210150311 8210150320* 8210150337* 8210180009 8210190307	50-311 50-311 50-311 50-272 50-272	8 8 8
	8210260149 6210260330 8210270153 6210270153 8210270166	50-443 56-443 50-443 50-443 50-443	9 9 6		8210190507 8210190515* 8210190515* 8210190444 8210190451	50-272 50-272 50-272 50-311 50-311	8 6 6
Public Service Electric & Gas Co of New Jersey	8210270164 8210280117 8210280119 8210010045	50~443 50~443 50~443 50~311	0 A A 8		8210200010 8210200014* 8210200085 8210200070* 8210210134	50-311 50-311 50-272 50-272 50-272	8 R R R
	82100 10123 82100 10128* 82100 10144 82100 10150* 82100 10161	50-311 50-311 50-311 50-311 50-272	9 9 8 9		8210210144# 6210220275 6210220326 8210250053	50-272 50-272 PR 50-311	8 8
	82100 10172* 82100 1023/ 82100 10237* 82100 10344 82100 10355*	50-272 50-311 50-311 50-311 50-311	9 9 9 9				
	82100 10383 82100 10390* 82100 10407 82100 10412* 82100 10419	50-272 50-272 50-311 50-311 50-311	5 5 6 8 8				
	82100 10423* 82100 10455 82100 10461* 8210060326* 8210070221	50-311 50-311 50-311 50-354 50-311	8 9 9 9				
	8210070231* 8210070243 8210070246 8210070248* 8210070249	50-311 50-311 50-311 50-311 50-311	9 9 9 9	Puget Sound Pows			
	8210070252* 8210070254 8210070258* 8210070305	50-311 50-311 50-311 50-272	8 8 8				

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8210130367 8210130478 8210130478 8210200045 8210200058	50-522 50-522 50-522 50-522 50-522	6 0 0 0		6210190331 8210190594 8210190598* 6210190603* 8210250037	50-312 P 50-312 P 50-312 P 50-312 P 71-9094
Purdus Research Foundation	8210210337 8210210337 8210210339# 8210210339# 8210120342#	50-522 50-522 50-522 50-522 CONTRACT	8 B B D		8210250065 8210250094 8210250386 8210250390# 8210260231	50-312 F 50-312 F 50-312 S 50-312 S 50-312 P
Purdue Univ Pyle, R Ø	8208270011 8210250063 8210250063 8210250063 8210260427	ACRS 50-259 50-259 50-259 50-259	0 0	Safe Power for Maine San Clemente, CA Sandia Laboratories	6210280228 8210260457 8210260465; 8210120556; 8209290240;	50-3/2 P 50-309 G 50-309 C CONTRACT FOJA
R F Reedy, Inc	8210260429 8210260429 8210250247 8210280157 8210280272	50-259 50-259 50-275 50-275 50-275	Q Q R R R		8210050368 6210050397 8210050004 8210070413* 8210150552	NUREG NUREG NUREG 71-9150 NUREG
Rediation Management Corp Reed, J O Research Counsel of Washington Richards, Brandt, Miller & Nelson	8210040037* 8210150178* 8210060197 8210060403 8207110026	50-445 50-322 50-483 FOIA FOIA	C T G		8210150571 8210150431 8210250033* 8210240211	NUREG RES NUREG NUREG
Richland, WA, Ridihaigh, Eggers & Associates Riverside, CA Robert L Cloud Associates, Inc	6210210161* 6210210505* 9210270085* 6210250356 6210080078	CONTRACT CONTRACT 71-6639 PROJ 50-275	Р	Sandvik Special Hatal4 Corp Santa Monica,CA	8210270338 82102703399 8210270143 8210280032 8210280043 8210080077	NUREG RES XPORTLIC XPORTLIC XPORTLIC 50-142 0
Rochester Oas & Electric Corp	8210080080* 8210250221 8210270184 8210270185* 8210010357	50-275 50-275 50-275 50-275 50-244	Р Р Р	Scandpower, Inc Science Applications, Inc	8210040311 8210040319* 8206210571* 8210040346* 8210040349*	TOPREP TOPREP 50-266 P 50-537 A 50-537 A
	8210010365* 8210010367* 8210010444 8210040281 8210040284*	50-244 50-244 50-244 50-244 50-244	ե Ե Լ		8210040350* 8210040351* 8210040355* 8210040357* 8210040412*	50-537 A 50-537 A 50-537 A FOLA CONTRACT
	6210040288* 6210070030* 6210130195 6210130199* 8210130439	50-244 50-244 50-244 50-244 50-244	P P S B Q		8210060447* 8210120357* 8210120422* 8210170025* 8210170037*	50-537 D CONTRACT CONTRACT CONTRACT CONTRACT
	8210150643* 8210150648* 8210190591* 8210190618* 8210190637*	50-244 50-244 50-244 50-244 50-244	F Q Q	Science Management Corp	8210270413# 8210270419# 8210270428# 8210270320# 8210270006#	50-397 X CONTRACT 70-1113 50-206 V COMMISSION
	8210190647* 8210190703 8210220352* 8210220360* 8210220383	50-244 50-244 50-244 50-244 PR	Q 9 0 0	Beioto Memorsal Hosp Portsmouth.OH Bracoast Anti-Pollution League	8207070324* 8210060194 8210060194 8210060206* 8210060206*	70-2748 50-443 G 50-443 G 50-443 G 50-443 G
Rockland Citizens for Safe Energy	8210250275 9210250334 8210250343* 8210250217* 8210200019	50-244 50-244 50-244 50-244 50-247	9 8 0	Senate Sensible Maine Power	8210060214* 8210060214* 8208010016* 8210050236 8210200065	50-443 Q 50-443 Q 50-289 II 50-309 Q 50-309 Q
Rockland County, NY Rockwell International Corp	8210220375 8210130054* 8210130315* 6210170182* 8210220321	50-247 CONTRACT 50-537 CONTRACT PR	A	Shaw, Pittman, Potta & Troubridge	8210290303 8210010345 8210010457 8210050255 8210050255	50~309 G 50~440 G 50~440 G 50~440 G 50~440 G
Rocky Mountain Energy Co Roif Jensen & Associates, Inc Rondout Associates	8210180398 8210180405* 8210250043 8210170185*	40-8380 40-8380 40-8697 50-320	F O		8210050374 8210050374 8210070124 8210070194	50~440 0 50~440 0 50~382 0 50~289 9
Ropes & Gray	8207180077 8210130314 8210270153 8210270153 8210270166 8210270166	50-307 50-307 50-443 50-443 50-443	00000		8210070197 8210070405 8210080086 8210080090 8210080094 8210120282	50-382 Q 50-382 Q 50-382 Q 50-382 Q 50-289 G 50-483 Q
SEP Owners Group Sacramento Municipal Utility District	8210130326 8210010057 8210050220 8210070287* 8210070294*	50-10 50-312 50-312 50-312 50-312	P P Q		8210120267 8210130275 8210150161 8210150228 8210150467	50-266 G 50-267 G 50-440 G 50-440 G
	8210070331# 8210130175 8210130599 8210190278 8210190285#	50-312 50-312 PR 50-312 50-312	а Р R R		8210180155 8210200009 8210200007 8210200013# 8210200013*	50-440 Q 50-400 Q 50-400 Q 50-400 Q

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	٧_
	8210200021* 8210200021* 8210200033 8210210173 8210210179*	50-400	0 0 0 0 0		8210010348 8210050175 8210050210 8210050324 8210040242	50-395 50-395 50-395	8 E P F F
	8210210266 8210210284 8210210284 8210210353 8210210353	50-320 50-440 50-440 50-440 50-440	G G G G		821,0080230 × 621,0080276 821,0120249 821,0180156 821,0180162 ×	50-375 50-375 50-375	ե ե գ
	8210210365 9210210372 9210210374 8210220305 8210220305	50-483 50-382 50-287 50-440 50-440	G G G G		8210170352 8210170457# 8210170505 8210170513 8210170553	50-395 50-395 50-395	ն 6 6
	8210220307 8210220307 8210220394 8210220396 8210220405*	50-440 50-440 50-440 50-440 50-440	0 G G G		8210220340 8210220346* 8210220353 8210220438 8210220443*	50-375 PR 50-375	8 8 8
	8210220405* 8210250248 8210250253* 8210250299 8210250299	50-440 50-483 50-483 50-440 50-440	6 6 6 6		6210250330 6210250339* 6210250140 6210250159 6210250166*	50~395 50-395 50-395	Р Р Р
	8210250322 6210250322 6210240404 6210240423 6210260214	50-440 50-440 50-266 50-382 50-440	0 G G O		821 02 60 172 821 02 70245 821 02 70273 821 02 70284 821 02 70284 #	PR PR	۲ 8
	8210280216 8210280231 8210280231 8210280246 8210280253	50-440 50-440 50-440 50-440 50-266	0 0 0 0	South Carolina, State of South Carolina, Univ of	8210290335 8210290338 * 8210130506 8210180106 8210190444 *	50-375 50-375 50-413 50-413 50-375	8 9 9 9
Shoreham Opponents Coalition	8210280360 8210280387 8210290287 8210150309* 8210150324*	50-287 50-382 50-440 50-322 50-322	6 6 6 6 6	Southern California Edison Co	8210940177 8210040323 8210050008 8210050012* 8210050016	50–206 Toprep 50–361 50–361 50–361	Р В В
	8210150337* 8210150351* 8210150365* 8210150393* 8210150402*	50-322 50-322 50-322 50-322 50-322	0 0 0 0		8210050019# 8210050024# 8210050029# 8210050032# 8210050037#	50-361 50-361 50-361 50-361 50-361	8 9 9
	B210150410* B210150422* B210150527* B210200036 B210250059*	50-322 50-322 50-322 50-322 50-322	0 0 0 0		821,0050041* 821,0050044* 821,0050048* 821,0050050* 821,0050096	50-361 50-361 50-361 50-361 50-361	8 8 6 6
Samera Club	8210060195 8210120327 8210210232 8210210357 8210210453	50-537 50-537 50-537 50-537 50-537	0 0 0 0		8210050098* 8210050101* 8210050151 8210050234* 8210050234	50-361 50-361 50-361 60-361	8 8 8
	8210220248 8210220288* 8210220295* 8210240397 8210240404*	50-537 50-537 50-537 50-537 50-537	0 0 0 0				
igma Chemical Co liver King Mining, Inc	8210130072 8210270194 8210280403 8210250054 8210250054	XPORTLIC XPORTLIC XPORTLIC 40-8502 40-8502					
inclate M	8210270048 8210070132 8210070132 8210070136 8210070136	40-8602 50-327 50-327 50-327 50-327	0 0 0				
anissippi Alliance for the Environment	8210070140 8210200054 8210200061 8210210346	50-327 50-327 50-327 50-454	0 0 0				
SAFE!	8210210346	50-454	G				
all Business Administration	8210210347* 8210210347* 8210180338* 8210180348* 8210210444*	50-454 50-454 CONTRACT CONTRACT	Ť				
merwell County, TX uth Carolina Electric & Oas Co	8210270221* 8210270223* 8210130074* 8210010167	CONTRACT CONTRACT CONTRACT 50-395	r T				

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT
	8210150482 8210150482 8210190309 8210190317* 8210190323*	50-361		8210150324+ 8210150337+ 8210150351+ 8210150365+ 8210150393+	50-322 G 50-322 G 50-322 G 50-322 G 50-322 G
	8210190328* 8210190455* 8210190490 8210190506* 8210190534	50-361 S 50-361 Q 50-206 S 50-206 S 30-361 P		8210130402 ± 8210130410 ± 8210130422 ± 8210130527 ≠ 8210200036	50-322
	8210190560 8210190560 8210190625 8210190625 8210190625	50-361 P 50-361 P 50-206 F 50-206 F 50-206 F		8210200076 8210200083* 8210200089* 8210250058 8210250059*	50-322 G 50-322 G 50-322 G 50-322 G
	8210250137 8210250140* 8210250207 8210250214 8210250218*	50-361 S 50-361 S 50-361 S 50-361 S 50-361 S		8210240232 8210240237 * 8210240242* 8210240244* 8210240409	50-322 T 50-322 T 50-322 T 50-322 H
	821 02 50227* 821 02 50267 821 02 50273* 821 02 50260 821 02 50302	50-361	Sugarman, A J	8210290283 8210010244 8210010244 8210180204 8210180204	50-322 G 50-352 G 50-352 G 50-352 G
	8210260214 8210260249 8210260272 8210260416 8210260424*	50-206 P 50-206 P 50-206 P 50-361 P 50-361 P		8210160208# 8210180208# 8210180217 8210180217 8210180223	50-352 0 50-352 0 50-352 0 50-352 0 50-352 0
	8210260435* 8210260448 8210260450 8210260472 8210260477*	50-361 P 50-206 P 50-206 P 50-206 P 50-206 P		8210180223 8210180224 8210180224 8210180224* 8210180226*	50-352 0 50-352 0 50-352 0 50-352 0 50-352 0
	8210290063 8210280080 8210280080 82102800869 8210280046	50-206 S 50-206 S 50-361 S 50-361 S 50-361 A	Sunflower Alliance	8210180253 8210180253 8210010250 8210010250 8210010323	50-352
Southern California, Univ of Southport.NC Southwest Research Institute Spain	#210290059* #210270408 #210130061* #210120330* #206060015*	50-361 A 50-295 D CONTRACT CONTRACT COMMISSION		8210010323 8210050173 8210050173 8210050228 8210050228	50-440 0 50-440 0 50-440 0 50-440 0 50-440 0
Spiegel & McDiarmid St Joseph Hosp Albuquerque, NM St Lukes Hosp Milwaukee,WI Stamiris, B	8210250354 6210120066* 6210290247 8210050238 6210050238	PROJ FOIA REGGD 50-329 G 50-329 G		8210050242 8210050242 8210050252 8210050252 8210250331	50-440 G 50-440 G 50-440 G 50-440 G
Standardized Nuclear Unit Power Plant System	8210050240 8210050240 8210210370 8210080260	50-329 G 50-329 G 50-329 G 50-482 K 50-482 K	Switzerland Systems Control, Inc TRC Environmental Consultants, Inc	8210270158 8210040335* 8210040340* 8210050418 8210150290*	XPORTLIC QAPPP QAPPP NUREO T 222
	8210080240 8210080246* 8210080264* 8210080264* 8210220252	50-482 K 50-482 K 50-482 K 50-482 K 50-482 K	TRW, Inc Target Research, Inc Teledyne Energy Systems	8210120550 * 8210270373 8210270376 * 8210080123 8210080272	CONTRACT 40-8824 40-8824 50-275 P
State,Dept.of, Bureau of Oceans & Internati Environ & Scientific Affairs	8210220253* 8210240274 8210040403	50-482 A 50-482 A XPORTLIC	Teledyne Engineering Services	8210050191 * 6210060191 8210080193* 6210190563 8210190584	0A999 50-275 ₽ 50-275 ₽ 50-275 ₽ 50-275 ₽
Steam Cenerator Duners Group Stearns-Roger Engineering Corp Stevenson & Associates	8210080119 8210080124 8210080152 8210220316 8210190468*	XPORTLIC XPORTLIC TOPREP PR 50-213 P		8210190584 8210250167 8210250171* 8210250197	50-275 P 50-275 P 50-275 P 50-275 R
Stone & Webster Engineering Corp	8210150206# 8210150265# 8210150270* 8210170472 8210170500* 82(0220346	50-322 T 50-322 T 50-322 T 50-325 P 50-395 P PR		8210250201* 8210250210 8210250210 8210250240 8210250291 8210250318	50-275 P 50-275 P 50-275 P 50-275 P 50-275 P 50-275 P
Stone & Webster, Inc. Stoner Associates, Inc Structural Dynamics Research Corp	8210250308 8210270237 8210150281* 8210210301* 8210180143*	50-275 R PR 50-322 T 50-329 A 50-358 A		8210250318 8210280211 8210280212* 8210280277 8210290319	50-275 P 50-275 R 50-275 R 50-275 P 50-275 R
Suffolk County, NY	8210050189 8210050383 8210150309*	50-322 0 50-322 0 50-322 0	Teledyne Wah Chang Albany Tennessee Velley Authority	8210270322* 8210270011 8210270076 8210270391 8208170297	50-275 R XPORTLIC XPORTLIC XPORTLIC XPORTLIC 50-259 K

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AF	AUTHOR FILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	820917004B 8209170101 8209300170 8209300175* 8210010011		- - - -			9210080219 9210080219 9210080219 9210080222 9210080222	50-259 50-259 50-259 50-438 50-438	G G S S
	8210010104* 8210010104* 8210010104* 8210010109 8210010115*	50-259 50-259 50-259 50-327 50-327	0 0 9 9			8210080247 8210080247 8210080247 8210080247 8210080247	50-390 50-390 50-390 50-390 50-390	8 8 8 8 8 8 8
	8210010135* 8210010197* 8210010304* 8210010304* 8210010304*	50-327 50-438 50-259 50-259 50-259	0 0 0 0 0			8210080247 8210080255 8210080255 8210080278 8210080278	50-390 50-390 50-390 50-438 50-438	8 9 8 8 8 8
	8210010341* 8210010420* 8210010427* 8210050053 8210050062	50-390 50-518 50-438 TOPREP 50-390	a a o			8210080280 8210080280 8210080291 8210080291 8210080292	50-390 50-290 50-390 50-390 50-438	8 8 8 8 9
	8210050042 8210050094 8210050094 8210050099 8210050104	50-390 50-438 50-438 50-390 TOPREP	6 6 5 8			8210080292 8210080307 8210080310 8210080310 8210120284	50-438 50-438 50-290 50-290 50-327	8 8 8 9
	8210050114 8210050114 8210050115 8210050115 8210050119	50-370 50-370 50-438 50-438 50-438	S 8 8 8 8			8210120289* 8210120269* 8210130142 8210130150 8210130150	50-327 50-327 50-259 50-327 50-327	ե ե ե
	8210050119 8210050158 8210050158 8210050216 8210050216	50-438 50-390 50-390 50-327 50-327	9 8 8 P			8210130157 9210130162* 8210130165 8210130169* 8210130172	50-276 50-276 50-259 50-259 50-259	8 8 8
	8210050249 8210050249 8210050268 8210050271* 8210050285	50-438 50-438 50-259 50-259 50-566	8 9 P P 3			92101301764 8210130247 8210130247 8210130317 8210130379	50~259 50~390 50~390 50~327 50~390	8 8 9 8
	8210050293 8210050293 8210050293 8210050293 8210050293	50-390 50-390 50-390 50-390 50-390	9 B B B			8210130384 8210130407 8210130429 8210130438# 8210130442	50~370 50~438 50~259 50~259 50~327	8 8 8 8 8
	82100 50316 82100 50316 82100 50344 82100 50344 82100 50407	50-370 50-370 50-370 50-370 50-438	8 0 0 8			8210130452# 8210130521 8210130540 8210130560 8210130865	50-327 PR 50-370 50-370 50-257	8 9 9
	8210050407 8210060205 8210060205 8210060219 8210060221*	50-438 50-390 50-390 50-327 50-327	8 8 8 8			8210130549* 8210130572 8210130579* 8210150105 8210150181*	50-259 50-328 50-328 50-259 50-438	9 8 8
	8210060265 8210060270* 8210060274 8210060279 8210060279	50-294 50-294 50-438 50-390 50-390	8 9 8 8			8210150218 8210150218 8210150230+ 8210150230+ 8210150231+	50-390	0 0 0
	8210060280 8210060280 8210060301 8210060304* 8210060347	50-390 50-390 50-259 50-259 50-327	S 9 P F			82101502414 82101502514 8210160117 8210180117		
	8210060352* 8210060352* 8210060409 8210060412* 8210060414	50-327 50-327 50-259 50-259 50-259						
	8210040422* 8210070133 8210070255 8210070255 8210070348	50-259 50-259 50-259 50-259 50-438	B T P P A					
	8210070348 8210080160 8210080160 8210080160 8210080160	50-43B 50-390 50-390 50-390 50-390	4 5 5 5 5					
	8210080160 8210080168 8210080218 8210080218 8210080218	50-390 50-390 50-259 50-259 50-259	6 8 P P					

AUTHOR AFF ILIATION	ACCESSION NUMBER	CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Γ ₹∀
	8210220225 8210220271* 8210220271* 8210220350 8210220422*	50-390 50-438 50-438 50-438 50-438	6 0 8 0		6210290236 8210290236 8210290236 8210290236 8210290236	50-390 50-390 50-390 50-390 50-390	5 6 6 5
	8210220466* 8210220474* 8210220474* 8210250067 8210250070*	50-390 50-327 50-327 50-260 50-260	О О Р Р		8210270236 8210270248 8210270265 8210270266 8210270266	50~390 50~438 PR 50~390 50~390	5 5 5
	8210250096 8210250096 8210250096 8210250101* 8210250101*	50-259 50-259 50-259 50-259 50-259	ተ ዓ ዓ		8210290274 8210290274 8210290274 8210290277 8210290279*	50-328 50-328 50-328 50-327 50-327	56655
	8210250101* 8210250236 8210250236 8210250236 8210250244	50-259 50-259 50-259 50-259 50-250	9 F F F		6210270317 6210270321* 6210270324 6210270324 6210270328	50-259 50-259 50-438 50-438 50-390	ខានាខាន
	8210250244 8210250244 8210260100 8210260100 8210260105	50-250 50-250 50-390 50-390 50-438	F 8 8		8210270328 8210270328 8210270328 8210270368 8210270371*	50-370 50-370 50-370 50-257 50-259	នាធានាធានា
	8210260105 8210260107 8210260148 8210260174 8210260174	50-438 50-438 50-327 50-390 50-390	8 9 F	Teton Exploration Drilling Co , Inc Texas A & M Univ Texas Nuclear Div (subs of Ramsay Eng Co)	8210280412 8210250195 8210250198# 8210040411#	40-8728 50-341 50-341 FDIA	F F
	8210240184 8210240186 8210240188	50-390 50-390	8 8	Taxas Tach Univ Taxas Utilities Deparating Co	8210190177# 821001030 <i>2</i>	CONTRACT PR	
	8210260189 8210260189	50-328 50-390 50-390 50-390	F		8210040024* 8210040024* 8210040026* 8210040026*	50-445 50-445 50-445 50-445	0 0
	8210240189 8210240196 8210240212 8210240222#	50-390 50-390 50-328 50-259	F 9 9		8210040030* 8210040030* 8210040033* 8210040033* 8210040037*	50-445 50-445 50-445 50-445 50-445	0 0 0 0
	8210260228 8210260251 8210260320 8210260320	50-327 50-438 50-390 50-390	P 8 8		8210040037* 8210040318 8210130299 8210130299 8210130576	50-445 50-445 50-445 50-445 50-445	9 9 9 6
	821 02 40320 821 02 40320 821 02 40320 821 02 40320	50-390 50-390 50-390 50-390 50-438	88989		8210130578 8210180006 8210180006 8210180008#	50-445 50-445 50-445 50-445 50-445	F K K K
	8210240322 8210240349 8210240353* 8210240361 6210240390	50-43B 50-260 50-260 50-259 50-390 50-390	ជា ជា ជា ជា		8210220372 8210250338 8210250338 8210250344 8210260375	PR 50-445 50-445 50-445 50-445	
	6210260407* 8210260408 6210260408 8210260417	50-259 50-390 50-390 50-260	5 5 6	Texas, State of Texas, Univ of Thatcher, T L Three Mile Island Alert	8210040042* 8210050174 8210080073 8210050176 8210050237	50-445 50-192 50-522 50-289 50-289	0 0 0 0 0
	8210260446* 8210260451 8210260451 8210280208 8210290049	50-260 50-390 50-390 50-390 50-391	8 8 A 8	Toledo Edison Co	8210280234 8210050235 8210050258* 8210050304 8210050310	50-287 50-346 50-346 50-346 50-346	H C C P P
	8210270052 8210270054 8210270057* 8210270057 8210270057	50-390 50-259 50-259 50-438 50-438	8 8 8 8		8210050313* 8210050318* 8210050323 8210050327* 8210050333	50-346 50-346 50-346 50-346 50-346	P P S S P
	8210290062 8210290066* 8210290091 8210290094* 8210290178	50-259 50-259 50-328 50-328 50-370	88888		9210050355 9210050361* 9210060314 9210070005* 9210070006*	50-345 50-345 50-346 50-346 50-346	
	8210270187 8210270187 8210270187 8210270187 8210270187	50-518 50-518 50-518 50-518 50-518	8 8 8 8		#210080288* #210130124 #210130325 #210130356	50-346 50-346 50-346 50-346 50-346	. 0988
	8210290231 8210290232* 8210290236 8210290236	50-294 50-294 50-390 50-390 50-390	9988		8210130404 8210130410* 8210130410* 8210180131	50-345 50-345 50-345 50-345	5 5 9 9

AUTHOR AFF (L1ATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8210180137* 8210170254 8210170261* 8210170303 8210170358	50-346 50-346 50-346 50-341 50-346	8 0 0 8 0 0 8 0 0 0 0 0 0 0 0 0 0 0 0 0		8210260108 8210270179 8210270204 8210270213 8210270218	70-820 70-820 70-820 70-820 70-820
	8210190359* 8210190423 8210210458 8210210554* 8210210559*	50-346 50-346 50-346 50-346 50-346	8 F P P	Universal Technical Testing Laboratories, Inc Vranium Resources, Inc Utah, State of Utah, Univ of	821022031A 821018035A 8210250013 8208270016* 8210240230*	PR 40~8784 40~8786 COMMISSION 50~72 R
	8210220013 8210250224 8210250231* 8210250270 8210250279*	50-346 50-346 50-346 50-346 50-346	e 8 8 8	Utility Horkers Union of America Vermont Yankse Nuclear Power Corp	8210240234 * 8210290240 8210290240 8210130189 8210130193 *	50-72 R PR 50-271 Q 50-271 R 50-271 R
, Parks, Selager, Simonoff & irlan	8210240248 8210240283 8210280075 8210280076* 8207180051	90-344 50-344 50-344 50-344 50-219	H 8 6 6		6210150447 8210180190 8210190022 6210190029* 8210210204	50-271 P 50-271 F 50-271 B 50-271 B 50-271 B
ų Pines Fachnology	8210120264 8210150353* 8210220198 8210220198 8210220198	50-528 50-382 50-528 50-528 50-528	R A R R		8210210214* 6210220416* 8210270430* 6210270432* 8210280138*	50-271 B 50-271 G 50-271 F 50-271 F 50-271 F
mentos Deloval, Inc	8210220244# 8210220244# 8210220244# 8210050290# 8210050295*	50-528 50-528 50-528 GA999 GA999	R R R	Vester J. Thompson, Jr., Inc Virginia Electric & Power Co	8210280143* 8210220244 8206140306* 8207230301 8207230303*	50-271 F FR 50-280 Q 50-339 B 50-339 S
uclear. Inc	8210070452 8210080037 8210080040* 8210080042* 8210080108	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			8208090114 8208090114 8210010103 8210010107* 8210010123	50-338 P 50-338 P 50-337 P 50-337 P 50-260 F
	8210080130 8210080133 8210270147 8210270168 8210280052	XPORTLIC XPORTLIC XPORTLIC XPORTLIC			8210010125 8210010125 8210010140 8210010145* 8210010163	50-280 F 50-280 F 50-338 9 50-338 8
ite Motor Transit Co (subs of la Pacific Corp) larsiUS	8210280056 8210280059* 8210150405	XPORTLIC XPORTLIC 70-1739 CONTRACT			6210010162* 6210010207 6210010233 6210010236*	50-338 9 50-338 8 50-338 8 50-337 8 50-337 8
p ogų. Inc (Formerly Nuclear eringi arbide Corp	8210120286* 8210130302 8210130306*	50-275 27-39 50-54 50-54	b b		6210010246* 6210010246* 8210010247* 6210040277 8210040277	50-338 P 50-338 P 50-338 P 50-338 P
	8210190244 8210190254* 8210220491 8210250019 8210250021*	40-299 40-299 40-299 40-299 40-299			B210040290* 8210040297* 8210040315* 8210040325* 8210050071	50-338 P 50-338 P 50-338 P 50-338 P 50-280 S
jectrác Co	6210270047 6210270070* 6210030299 6210120242 6210130555* 6210210345	70-687 70-687 50-483 50-483 50-483	A G Q		8210050074* 8210050076 8210050078* 8210050081 8210050081	50-280 S 50-280 F 50-280 S 50-280 S
Concerned Scientists	8210250248 9210250253* 9210120274 9210130335 9210130335 9210130337*	50-483 50-483 50-289 50-247 50-247 50-247	6 6 6 6 6		8210020103 8210020103 8210020092# 8210020086#	
	8210130337* 8210220274* 8210220410 8210220465 8210280242	50-247 50-537 50-247 50-269 50-247	0 0			
irlings. Inc (subs of UAL)	8210220316	PR				
constructors, Inc	8210050206*	50-443	A			
if Raythean Co.)	8210260205 8210270060# 8210200104	50-324 50-537 70-820	8 C			
	8210250012 8210250014 8210250016 8210250032 8210260038	70-820 70-820 70-371 40-8781 70-820				

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	CATECORY	٧
	8210120297 8210120297 8210120305* 8210120305* 8210120305*	50-280 50-280 50-280 50-280	ր թ թ		8210270258 8210280130 8210280266 8210290264 8210290270#	50-338 50-280 50-280 50-280 50-280	P P G G
	8210120305* 8210120305* 8210130112* 8210130114* 8210130114*	50-280 50-280 50-336 50-338 50-338	ր Բ F	Virginia. Univ of	8210290276# 8210290282# 8210290337 8210290347# 8210060086	50-280 50-280 50-338 50-62	8 9 9 P
	8210130204 8210130204 8210130208* 8210130213* 8210130216*	50-280 50-280 50-280 50-280 50-280	55 55 55 55 55 55 55 55 55 55 55 55 55	Washington Legel Foundation Washington Public Power Supply System	8210080237 6210010322 8210130277 8210010020 6210040255	50-62 PR PR 50-508 50-377	P H A
	8210130427 8210130431* 8210130500 8210130507* 8210150054	50-280 50-280 50-280 50-280 50-280	Q Q S S S		8210050124 8210050156 8210050348 8210060223 8210060319	50-397 50-397 50-397 50-397 50-397	E 4 4 C
	8210150095 8210150139 8210150359 8210150394 8210170264	50-280 50-280 50-281 50-280 50-338	5 5 5 5 5		8210040445 8210070141 8210070144* 8210070161* 8210070297	50-397 50-397 50-397 50-509 50-460	F A Q S
	8210190270* 8210190321 8210190329 8210190329 8210190327* 8210200043	50-338 50-339 50-338 50-338 50-280	ន ទ ន ព		8210070297 8210070302# 8210070311 8210070311 8210070338	50-460 50-397 50-460 50-460 50-460	8 8
	8210200043 8210200048* 8210200048* 8210210053* 8210210053*	50-280 50-280 50-280 50-280 50-280	Р Р Г Г		8210070370 8210070387* 8210070387* 8210080075 8210080100*	50-397 50-460 50-460 50-397 50-397	8 9 8 K K
	8210210055* 8210210055* 8210210058* 8210210058* 8210220011	50-280 50-280 50-280 50-280 50-338	F F F P		8210080195 8210080275 8210080304 8210120194 8210120197	50-397 50-397 50-397 50-508 50-508	0 9 6 8 8
	8210220011 8210220095 8210220097* 8210220097*	50-339 50-280 50-280 50-280 50-280	P 8 9 9		8210120200* 8210130188 6210130194 8210130217 8210130425*	50-508 50-397 50-397 50-397 50-460	K A F 9
	6210220170 8210220178 6210220178 6210220178 8210220178	50-280 50-280 50-280 50-280 50-280	р Р Р Р		8210130432* 8210130432* 8210130575 8210190576 8210190582*	50-460 50-460 50-397 50-397 50-397	E 0 0
	8210220200 8210220227 8210220234* 8210220373 8210220373	50-338 50-338 50-338 PR 50-280	g 9		8210190584* 8210190644 8210190708 8210190764 8210210045	50-397 50-397 50-397 50-397 50-397	K 0 E
	8210220392 8210220398* 8210220408* 8210220413* 8210220413	50-280 50-280 50-280 50-280 50-337	9 9 9		8210210049 8210210148 8210210276 8210210327 8210260113*	50-397 50-397 50-397 50-397 50-397	E 6
	8210220421* 6210220424 6210220435* 6210220441 6210220450*	50-339 50-281 50-281 50-339 50-339	6 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	Washington, State of Waste Management Group, Inc	8210270012 8210280170* 8210280297* 6210240442 8210280331*	50-508 50-460 50-460 50-397 CONTRACT	A G G A
	8210250208 8210250208 8210250212* 8210240133 8210240139	50-338 50-338 50-338 50-338 50-338	F F P P	West Branch Conservation Association West Chicago, IL	8210180203 8210200019 8210210390 8210210397* 8210250315	50-247 50-247 50-247 50-247 40-2061	0 0
	8210240134* 8210240134* 8210240281 8210240287* 8210240270	50-338 50-338 50-339 50-339 50-338	P 8 8	Westchester Gounty, NY Westchester Peoples Action Coalition, Inc Western Geophysical Western Piping & Engineering Co. Inc	8210250287 8210200019 8209300332* 8209300336* 8210120285*	50-247 50-247 50-213 50-213 9A999	0 0 P P
	8210260293* 8210260346 8210260360* 8210270160 8210270204	50-338 50-339 50-338 50-338	8 8 8 8	Westinghouse Electric Corp	8210120293* 8005070094 8005070099* 8210010189 8210040196*	Qaqqq PT21 PT21 70-1151 Qaqqq	
	8210270212 8210270212 8210270215* 8210270220* 8210270224*	50-260 50-260 50-260 50-260 50-260	8 8 8 8		821005019B* 821008003B* 8210080229 8210080227* 8210080321	GA999 FOIA TOPREP TOPREP XPORTLIG	c

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT	Y	AUTHOR AFF ILIATION	ACCESSION NUMBER	CATEGO	
-	8210080323* 8210120250* 8210130250* 8210130420 8210130426*	XPORTLIC 50-395 50-537 50-22 50-22		8	210280255 210280275 210280275 210280278*	50-266 50-266 50-266 50-266 50-266	6 6 6
	8210130447 8210130535* 8210170429* 8210170508* 8210170607	PT21 50-344 50-282 50-395 TOPREP	p p	Hisconein Public Servic∈ Corp S S	210290294 210010179 210010186* 210010232 210010307	50-266 50-305 50-305 PR PR	b b
	8210210054 8210220152 8210220154 8210250128* 8210250141*	NUREG TOPREP NUREG GA999 GA999		8 6	210040156 210040159* 210040162* 210050263 210060312	50-305 50-305 50-305 50-305 50-305	9 9 9 P
	8210260305 8210260340 8210260351* 8210270014 8210270017	TOPREP TOPREP TOPREP XPORTLIC XPORTLIC		8 8	2100 60328 2100 70108 2101 30282 2101 30300 2101 30581	50-305 50-305 PR 50-305 50-305	0 P F
ntinghouse Operating Plents Owners Jour	8210270208* 8210270260* 8210080274	50-338 50-338 TOPREP	P ρ	8 3 8	210190353 210190355* 210190356* 210190489	50-305 50-305 50-305 50-305	8 8 P
(Miams-Robinette & Associates, Inc	8210120401* 8210120404*	CONTRACT 40-8745			310290593* 510590590	50-305 50-305	8 8
tisan. R	8210200053 8210010250 8210010250 8210010323 8210010323	50-400 50-440 50-440 50-440 50-440	0000	B: Wisconsin's Environmental Decade B: Woodward Governor Co B:	210290234 210040125 210250120 210150536*	PR 50-266 50-266 GA999	G G
	8210050173 8210050173 8210050228 8210050228 8210050228	50-440 50-440 50-440 50-440 50-440	00000	Hyoming Mineral Corp Si Bi Wyoming, State of Si	210150544* 210270180 210270183* 210130607 210150597	0A999 40-8502 40-8502 40-299 40-0743	
	8210050242 8210050252 8210050252 8210250331	50-440 50-440 50-440 50-440	0 0	6: 82 8:	210210254 210260084 210260096 210260099* 210280446	40-6452 40-6452 40-8761 40-8761 40-8452	
inthrop, Stimson, Putnam & Roberts	82070 50085 8107270154 8207290257 8207290279 8210040119	50-247 50-266 50-266 50-266 50-266	POKKE	Yakima Indian Nation Si Yale Univ. Si Si	110280451 110050169 110260232 110260239*	40-9697 50-522 50-322 50-322 PR	e r T
	8210050005 8210050005 8210050054 8210050054 8210050055	50-266 50-266 50-266 50-266	t bitte	83 85 86	10010465 10010465 10040112 10040112	50-443 50-443 50-443 50-443 50-443	A A A A
	821005055 821005022 821005022 8210050231* 8210050231*	50-266 50-266 50-266 50-266 50-266	ե 1 1 1	63 81 82	10040193 10050199 10050199 10060310* 10070105	50-443 50-443 50-443 50-29 50-443	A A G A

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	łΥ	AFF ILIATION	ACCESSION NUMBER	SUDJECT CATECON
	8210260165 6210260169* 6210260330 6210260428	50-29 50-29 50-443 50-29	SSSS	82.	0280119	50-29 50-443 50-271
	8210270430# 8210280085 8210280094	50-271 50-29 50-29	F 8 P	52	0290263	50-27 PR FOIA

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEODRY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGOR	
1 JA 300 1000-PLN-7200 01 R00 106-92/H7KF 11410 R01 8630 1	8210070355*	50-438 A 50-219 P 50-389 E 50-358 A 50-338 P		CRBR-ARD-0119 DEY-16-0201 R01 DNS-DI-034 EDAC 175-130 02 DRF EERC 75-19	6210130250* 6210010460* 8210180199* 8210070091* 6107270198*	50-537 50-341 50-10 50-29 50-266	A A P DDE/ET 34205-33 P
1159 C-21 HC152 1 I2-12 2-032 210050504	8210040241* 8210170668* 8210170444* 8210280178* 8210050504	50-155 P 50-213 P 50-375 P	0020A	EERC 75-21 EERC 76-16 EERC 76-8 ECO-1183-4168 ECO-EA-5307 ROI	8107270199* 8107270191* 8107270188* 8010070320* 8210280432*	50-266 50-266 50-266 50-305 50-247	0 0 0 0 P P TAC 12992
210060425 210070449 210080322 220120118 210120124	9210050425 9210070449 9210090322 9210120118 9210120124	RES RES RES RES	E00-M-09782 E00-M-11782	EGG-EA-6016 EGG-EA-6017 EGG-EA-6033 EGG-EA-6051 END-81-106	8210120300* 8210070079* 8210250372* 8210270288* 8210270020*	50-213 50-27 50-213 90-155 50-537	Р Р Р
210120367 210120368 210120390 210120397 210120400	8210120367 8210120368 8210120390 8210120397 8210120400	REB REB REB REB	BNL-NUREO-31834 EGG-H-11482 EGG-M-04382	GA-AI3010A AO7 GA-AI6764 GIBSAR-17-A AO6 MBS/PDG-77-1 ME-146	8210290144* 8210080258* 8210270129* 8210040279* 8210180352*	TDPREP 30~247 50~584 50~369 50~341	QA-LTR-11 P UC-77 A X
10120428 10120430 10120453 10120455 10120459	8210120428 8210120430 8210120453 8210120455 8210120459	RES RES RES RES	Q-6-507 (R673) E0Q-LDFT-5937 GRNL/FTR-1365 BNL-MUREG-31735 BNL-MUREG-31775	ME-229 ME-230 ME-684 MPR-733 MPR-734	8210150343* 8210150346* 8210260473* 8210010081* 8210010085*	50-341 50-341 50-358 50-219 50-219	а е е Р
10120460 10120463 10120466 10120630 10120649	8210120460 8210120463 8210120466 8210120630 8210120649	RES RES RES RES RES	BNL-NUREG-31774 BNL-NUREG-31754	NEDO-21471-01 801 NEDO-22192 NEDO-24088-1 NO4 ERR NEDO-24088-1 NO5 ERR NEDO-24146A ERR OØ	8207120253* 8210190765* 8210250077* 8210250078* 8210250177*	50-254 50-260 50-260	A 79NED99R P 82NED080 P 77NED360 F 77NED360 P 79NED273
10120653 10120654 10120657 10180409 10150412	9210120653 9210120654 9210120657 9210150409 9210150412	RES RES RES RES RES	DRNL/FTR-1371 E0G-CDD-6029 E0G-M-21082 E0G-M-06682	NEDD-24934 ERR RO2 NSE-50-0582 NSE0-72-0782 NSE0-88-0982 NSP-77-001 ROO	8210250164* 8210280201* 8210280204* 8210010224* 8210150500*	TOPREP 50-277 50-277 TOPREP 50-263	P DRF-F13-00023 P DRF-F13-00023 T23-00452 P 30 1777 0100
0150415 0150421 0150421 0150625 0150631	8210150415 8210150421 8210150611 8210150625 8210150631	RES RES RES RES RES	E09-M-14082 E09-LDFT-5782 E09-LDFT-5733 SAND82-1853	NEP-77-003 R00 NSP-77-007 R00 NSP-77-008 NUREO-0030 V06 N02 NUREO-0267 R01	8210150509* 8210150504* 8210150377* 8210220142 8210270331	50-263 50-263 50-263 Nureo Nureo	P 30 1777 0102 P 30 1777 0106 P 30 1777 0026
0180407 0200102 0270421 0280292 0280323	8210180407 8210200102 8210270421 8210280272 8210280323	RES RES RES RES RES	E00-L0FT5999 E00-1D-6040 E00-L0FT-6039	NUREO-0580 V11 NO9 NUREO-0748 V02 NO8 NUREO-0750 V15 NO5 NUREO-0793 NUREO-0822 DRFY	8210120119 8210120116 8210150547 8210210030 8210270345	NUREO NUREO NUREO 50-229 50-219	E
0280039 0290017 0290399 -FRFE-282 -22-NP A01	6210280339 6210290017 6210290379 6210270208* 8210060259*	REB RES RES 50-338 F TOPREP	EGG-ID-6037 EGG-WRR-6019 BANDB1-0826	NUREO-0846 NUREO-0847 801 NUREO-0857 803 NUREO-0858 NUREO-0928	8210050422 8210050405 8210060006 8210050431 8210050377	40-1341 50-390 50-528 Nureo 50-62	E E
-1743 -04261 -04261 -185-NP -2161B) -01-110 R00	8210010284# 8210120642# 8210040329# 8210180133# 8210050427#	50-341 / TOPREP 50-317 /	1	NUREO-0940 VOI NOI-2 NUREO/BR-0024 NUREO/CR-0030 NUREO/CR-0149 V20 NUREO/CR-1349 ROI	8210210024 8207280307 8210150353 8210150360 8210040004	NUREO NUREO NUREO NUREO NUREO	PNL-8A-10325 E00-2037 V20 SANDBO-7054

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT	
NUREO/CR-2000 V01 NB NUREO/CR-2182 V02 NUREO/CR-2183 NUREO/CR-2227 V02 NUREO/CR-2240 ERR	8210150577 8210210034 8210150567 8207290410 8210060417	NUREG	ORNL/NSIC-200 F ORNL/NUREG/TM-4 ORNL/TH-7864 OEAP-24962-2 EGG-2181	SAI-184-028-22 SAI-184-029-17 SAND80-0783 SCP-01-A RO4 SECY-82-0728	8206210571* 8210290320* 8210070413* 8210040319* 8204200390*	50-266 6 50-206 6 71-9150 TOPREP FOIA	•
NUREG/CR-2404 NUREG/CR-2444 V01 NUREG/CR-2444 V02 NUREG/CR-2606 NUREG/CR-2609	8210150548 8210210054 8210220154 8210050397 8210210039	NUREG NUREG NUREG NUREG NUREG	UCRL-53034 EPRI NP-2014 EPRI NP-2014 SANDB1-1932 ORML/NURE0-75	8ECY-82-072C SECY-82-142 SECY-82-166 SECY-82-232 SECY-82-255	9205270507* 9204300078* 9205280475 9206180042* 9206240187*	FOIA FOIA SECY FOIA 50-251	3
NUREG/CR-2673 NUREG/CR-2710 NUREG/CR-2719 NUREG/CR-2730 NUREG/CR-2754	8210210037 8210260206 8210150569 8210150571 8210050418	NUREO NUREO NUREO NUREO NUREO	ORNL/IH-8306 DRNL/IH-8331 ORNL/IH-8278 SANDS2-1150 PNL-4272	SECY-82-267 SECY-82-384 SECY-82-399 SECY-82-407 SECY-92-414	8204290412 8210210503 8210220534 8210270322 8210290214	SECY 50-289 F SECY SECY 50-275 F	
NUREG/CR-2759 NUREG/CR-2761 NUREG/CR-2771 NUREG/CR-2792 NUREG/CR-2820	8210270338 8210050388 8210150552 8210050340 8210120125	NUREG NUREG NUREG NUREG NUREG	SAND82-7062 SAND82-7065 SAND82-7067	GR0-307 F1002745 R03 TER-63237-282 TER-63237-294 TER-65237-317	8205250020* 82[0120283* 8208[90290* 8208[90]78* 8209[60459*	50-155 50-275 50-302 50-213 50-155 50-	p
NUREG/CR-2831 NUREG/CR-2846 NUREG/CR-2859 NUREG/CR-2862 NUREG/CR-2873 VOI	8210150549 8210220135 8210150557 8210210041 8210120102	NUREO NUREO NUREO 50-20 I NUREO	MLM-2957 BNL/NUREO-51567 ANL-CT-81-32 P PNL-4306	TER-C9257-318 TER-C9257-403 TER-C9257-414 TER-C8237-426 TER-C8257-530	8208170083* 8204230020* 8208180082* 8208100269* 8210180026*	50-204 F 50-245 F 50-155 F 50-29 F 50-346 F	p 5
NUREO/CR-2873 VO2 NUREO/CR-2874 VO1 NUREO/CR-2877 NUREO/CR-2885 NUREO/CR-2889	8210120092 8210150564 8210260211 8210150556 8210150550	NUREO NUREO NUREO NUREO NUREO	PNL-4306 ORNL/TK-8443/VI SAND81-2613 ANL-82-44 HEDL/THE 82-32	TER-C3257-542 TER-C3257-544 TER-C3506-151 TER-C5506-309 TER-C5506-58	8204300188* 8207170431* 8204030064* 8210120640* 8202010167*	50-29 (50-206 f	9 4
NUREG/CR-2897 NUREG/CR-2898 NUREG/CR-2905 NUREG/CR-2909 NUREG/CR-2914	8210050428 8210150574 8210050368 8210210051 8210210046	NUREO NUREO NUREO NUREO NUREO		UCB/EERC-77/07 UCB/EERC-78/17 UCB/EERC-78/27 VO1 UCB/EERC-78/28 VO2 UCB/EERC-79/12 VO3	8107270196# 8107270194# 8107270166# 8107270169# 8107270174#	50-266 (50-266 (50-266 (50-266 (50-266 (3 9 9
NUREO/CR-2919 NUREO/CR-2920 NUREO/CR-2922 NUREO/CR-2923 NUS-4146 RO1	8210220149 8210050412 8210150592 8210210014 8210210306*	NUREG NUREG NUREG NUREG 50-329	PNL-4380 BMI-2079 BMI-2100 A	UCB/EERC-79/23 VO1 UCB/EERC-79/24 VO2 UCB/EERC-79/25 VO3 UCID-18689 RO1 UCID-19113	8107270178* 8107270182* 8107270185* 8209130461* 8206170006*	50-266	
NUB-4154 ORNL-5470 ORNL-7M-4687 ORNL/NBIC-112 DRFT ORNL/NBIC-208	8210060354* 8210270052* 8210270035* 8210280110* 8203160383*	50-537	F 0 0	UCID-19141 DRFT UCID-19147 UE&C-ANL-810930 UMTRA-DDE/ALG-34 DRF URS/JAB 8216	8207300222# 8207200475* 8210270060# 8210250025 8210120286*		P D COO-64 -1 20682
CRNL/NSIC-209 P 105-4-839-008 ROO PNL-3524 R543-02 VO5 RAI-C5504-196	8203250320* 8210080080* 8210270041* 8210040178* 8210050068*	50-206	b 0 nc-11 b	VEP-FRD-33 ERR HCAP-10102 HCAP-10162 HCAP-7870 XN-NF-76-47(NF)(A)	8210120305* 8210190429* 9210130535* 8210080038* 9210150182*	50-280 50-282 50-364 FOIA TOPREP	p
				XN-NF-81-21(NP)(A) Y1003501A40 Y1003J01A20 R01	8210270169* 8210250074* 8207090224*		P DRF L12-00304-1

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCESSION NUMBER

PRINCIPAL

DATE

SUB. IECT

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGO	
7811200399	8210280013	82/09/17	50-325	8
78122002B5	8210070007	82/09/10	50-266	P
7903090181	8210180028	62/08/20	FOIA	7
7905290357	8210280013	02/09/17	50-324	P
7908130454	8210280013	82/09/17	50-261	ė
, , 5010,000 (0210200010	42.07717	00 4.01	٠
7909280105	8210070007	82/08/10	50-244	P
7912280014	8210280013	82/09/17	50-324	P
8001080054	8210180028	82/08/20	FOIA	
9002080095	8210190112	82/10/06	FOIA	
8002140204	B21001000B	82/06/28	50-266	Р
8003310179	8210010008	85/06/58	50-244	P
8004100193	8210010008	85/09/58	50-265	P
8004300616	8210070007	83/08/10	50-266	P
BC05070099	8005070094	80/03/14	1574	
8005270820	8210010008	82/06/58	FO1A	
6005270822	8210010008	85/09/58	FOIA	
6006050154	8210180028	85/08/50	FOIA	
8004050188	8210180028	82/08/20	FOIA	
8006170030	8210180028	82/08/20	FOIA	
B006300104	8510010008	82/06/58	FOIA	
8008050265	8210010008	65/09/59	50-327	P
8008070143	8210180028	82/08/20	FOIA	•
8009040493	8210070007	82/08/10	50-266	ρ
8007040473	8210070007	82/08/10	50-266	P
BO 10070320	8210210395	82/09/30	50-305	P
010070020	DE10#10313	047 077 30	30 000	•
8010210037	8210010008	82/04/28	50-327	8
8010240413	821001000B	82/06/28	FOIA	
8010240496	8210010008	82/06/28	FOIA	
8011060346	8210080015	82/07/12	FOIA	
8011060568	8011060561	80/10/20	50-254	8
8011040548	8011040241	BO/10/20	50-254	8
8011120679	8210010008	85/09/58	50-247	s
8011240024	8210010008	85/07/58	50-247	5
8015180365	8510150012	82/08/20	FOIA	_
8101090294	8210010008	82/06/28	50-247	8
2141140002	8210280013	62/09/17	50~324	р
B101140002	8210280013	82/09/03	50-142	F
8101200322	8210180028	82/08/20	FOIA	•
8101270870	8210180028	82/08/20	FOIA	
8102280195	8210010008	82/06/28	FOIA	
8103030076	9510010009	02/00/20	1414	
6103050756	8210010008	82/04/28	FOIA	
81Q3Q50987	8210010008	82/06/28	50-327	р
8103060088	8210010008	82/06/28	FOIA	
8103070387	8210010008	82/06/28	50~247	8
8103120107	8210010008	82/06/28	50-321	6
8103160338	8210180028	82/08/20	FOIA	
0103160366	8210180028	82/08/20	FOIA	
6103190719	8210010008	85/06/58	50-245	ន
8103240292	8210010008	82/06/28	FOIA	
8103310127	8210010008	82/06/28	FQIA	

	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	Y
			02/07/40		
	8104080909	8210080015	82/07/12	FOIA	
	8104170703	8210180028	82/08/20	FOIA	
	8104240059	8210010008	82/06/28	FOIA	_
	8104290103	8210010008	85/09/58	50-366	8
	8104290774	8210280013	82/09/17	50-324	P
	8105040420	8210080015	82/07/12	50-352	0
	8105040512	8210080015	82/07/12	50-285	P
	8105110396	8210010008	82/06/28	AIQR	
	8105280476	8210080015	82/07/12	50-263	G
	0106100203	8510010008	82/06/28	E1E-05	P
	8106100362	8210010008	82/06/28	FOIA	
	B104150555	8210010008	82/06/28	50-302	8
	8106220159	8210080015	82/07/12	FOIA	
	8106220165	8510080012	82/07/12	50-261	P
	8100220168	8210080015	82/07/12	FOIA	
_	Ø107010140	8210280013	82/09/17	50-261	Р
•	0107010141	8210010008	85/06/58	50-368	ġ
	8107070220	8210010008	82/06/28	FOIA	
	8107090355	8210010008	83/06/28	FOIA	
	8107160079	8210010008	82/06/28	50-240	6
		· -			**
	8107160396	8210010008	82/06/28	FOIA	
	8107170126	8210080015	82/07/12	FOIA	
	8107270161	8107270156	81/07/1 7	50~246	G
	8107270166	8107270156	G1/07/17	50-264	a
	B107270169	8107270156	B1/07/17	50~244	Q
	8107270174	8107270154	81/07/17	50-266	a
	B10727017B	8107270156	81/07/17	50-266	Q
	8107270182	8107270156	81/07/17	50-246	Œ
	8107270185	8107270156	81/07/17	50-266	ã
	8107270188	8107270154	81/07/17	50-266	ā
	8107270191	8107270155	81/07/17	50-266	Q
	8107270194	8107270156	81/07/17	50-266	G
	8107270176	B107270156	81/07/17	50-266	G
	8107270198	8107270156	81/07/17	50-266	æ
	8107270199	8107270156	81/07/17	50-266	Œ
	8107300148	8210010008	82/06/28	50-324	8
	B10B030041	B21001000B	82/06/28	AIDA	

ACCESSION	NUMBER				ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8109180478 8109220915 8109240007 8109250504 8109280036	8210010008 8210010008 8210010008 8210010008	82/06/28 82/06/28 82/06/28 82/06/28 82/06/28	50-287 FOIA FOIA FOIA 50-312		8203120103 8203160383 8203170060 8203170016 8203170034	8210010008 8210010008 8210010008 8210040442 8210070007	62/04/28 62/06/28 62/06/28 62/06/28 62/08/24 62/08/10	50-331 S FOIA FOIA 50-537 A	
8109280175 8109280684 8110010072 8110050018 8110190928	8210010008 8210080020 8210010008 8210010008 8210010008	82/06/28 82/06/28 82/06/28 82/06/28	50-29 FOIA FDIA 50-369 FOIA	s	8203220512 8203220514 8203250320 8203250303 8203250003	8210060442 8210280013 8210010008 8210070007 8210080015	82/08/24 82/09/17 82/06/28 82/08/10 62/07/12	50-537 D 50-261 P FOIA FOIA 50-293 P	
8110170733 8110220004 8110230085 8110270050 8110300460	821001000B 821001000B 821001000B 8210070007 8210070007	82/06/28 82/06/28 82/06/29 82/08/10	FOIA FOIA 50-219 50-266 50-266	8 P P	8203270031 8203300270 8203310089 8203310094 8204010046	8510150103 8510010008 8510010008 8510010008	82/07/12 82/06/28 82/06/28 82/06/28 82/06/12	50-293 P FOIA 50-311 P 50-31E P FOIA	
8111030201 8111040084 8111040130 8111090062 8111160309	821001000B 821001000B 821001000B 8210070007 821001000B	82/06/28 82/06/28 82/06/10 82/06/28	F01A 50-313 FDIA 50-246 F01A	S P	8204080171 8204080260 8204120487 8204160222 8204160225	8210010008 8210010008 8210080015 8204160212 8204160212	82/04/28 82/04/28 82/03/19 82/03/19	FOIA FOIA 50-281 5 50-293 0 50-293 0	
Bill180001 8111191042 Bill240071 8111240912 Bill270314	8210010008 8210010008 8210070007 8210010008 8210010008	82/06/28 82/06/28 82/06/28 82/06/28	50-338 50-206 50-266 FOIA 50-295	5 0 P 5	8204200370 8204200405 8204200408 8204200438 8204200442	8210040360 8210050430 8210270423 8210080015 8210080015	82/09/27 82/08/17 82/09/23 82/07/12 82/07/12	FOIA 70-1510 70-1510 50-289 P 50-289 P	
8111300367 8112010310 8112020725 8112020852 8112020885	8210010008 8210010008 8210010008 8210010008	82/06/28 82/06/28 82/06/28 82/09/17 82/09/17	50-206 50-336 FUIA 50-261 50-324	9 8 P P	8204210289 8204220144 8204270464 8204270048 8204290237	8210010008 8210270423 8210010008 8210010008 8210080015	82/04/28 82/09/23 82/04/28 82/06/28 82/07/12	50-414 S 70-1510 F01A 50-270 A 50-289 P	
8112030585 8112100374 8112210166 8112210193 8112210538	8210010008 8210010008 8210010008 8210010008	82/06/28 82/06/28 82/06/28 82/06/28 82/06/28	FOIA FOIA FOIA FOIA 50-304	5	8204290408 8204300078 8205030617 8205030619 8205050480	8210060442 8210270083 8210080015 8210080015 8210280013	82/08/24 82/09/20 82/07/12 82/07/12 82/09/17	50-537 D FOIA 50-247 S 50-247 S 50-261 P	
81 12300287 8201050061 8201060003 8201060245 8201120280	8210280013 8210010008 8210010008 8210050430 8210280013	82/09/17 82/06/28 82/06/28 82/08/17 92/09/17	50-324 50-324 FOIA FOIA 50-324	P S	82050A0550 82050A0558 8205070377 8205130114 8205170128	8210120103 8210120103 8210080015 8210080015	82/07/12 82/07/12 82/06/28 82/07/12 82/09/17	F01A F01A F01A 50-293 P 50-324 P	
B201130322 B201150003 B201150004 B201150005 B201150087	8210010008 8210010008 8210010008 8210010008 6210060442	82/06/28 82/06/28 82/06/28 82/06/28 82/08/24	FOIA FOIA FOIA FOIA 80-537	מ	8205180693 8205190428 8205190441 8205240006 8205240010	8210080015 8210080015 8210080015 8205240003 8205240003	82/07/12 82/07/12 82/07/12 82/05/05 82/05/05	50-281 S 50-327 S 50-327 S 40-8355 40-8355	
8201150176 8201150180 8201170040 8201170041 8201170276	6210060442 6210010008 6210010008 6210010008 6210010008	82/08/24 82/06/28 82/06/28 82/06/28 82/06/28	50-537 50-206 FOIA FOIA FOIA	D S	6205250010 8205250020 8205270507 8205270524 8205280490	8210270270 8210270270 8210040360 8210040360 8210080015	82/10/19 82/10/19 82/09/27 82/09/27 82/07/12	50-155 P 50-155 P FOIA FOIA FOIA	
9201190538 9201200653 9201200658 9201200662 9201210107	8210010008 8210010008 8210280013 8210280013 8210070007	82/06/28 82/06/28 82/09/17 82/09/17 82/08/10	50-346 50-255 50-261 50-261 FOIA	53 P P	8205280497 8205280502 8205280532 8205280533 8206030064	8210080015 8210080015 8210080015 8210080015 8210040062	82/07/12 82/07/12 82/07/12 82/07/12 82/09/27	FDJA FDJA 50-289 D 50-206 P	
					8204040401 8204040013 8204040015 8204070104 8204070250	8210080015 8206200097 8206200086 8210080015 8210070007	82/07/12 82/07/29 82/07/19 82/07/12 82/08/10	FOIA COMMISSION COMMISSION 50-245 6 50-244 P	
					8206080467 8206110186 8206140329 8206160306 8206170006	8210060442 8210080015 8210080015 8208260424 8210180175	82/08/24 82/07/12 82/07/12 82/07/29 82/09/20	50-537 D 50-416 S 50-289 P 50-280 Q 50-312 F	
					8206180042 8206210571 8206220591 8206230020 8206240119	8210190144 8210040414 8210280013 8210150382 8210270083	82/09/30 82/08/31 82/09/17 82/09/30 82/09/20	FOIA 50-266 P 50-324 P 50-245 P 50-251 S	
					8206270016 8206290695 8206290666 8206300188 8206300370	8206200071 8210070007 8210080015 8210220233 8210260305	82/07/29 82/08/10 82/07/12 82/10/12 82/10/18	COMMISSION 50-244 P 50-287 P 50-155 Q TOPREP	
					8207050005 8207050040 8207070324 8207070422 8207070428	8210010293 8210050506 8207070319 8207070419 8207070419	82/09/27 82/09/16 82/06/30 82/06/28 82/06/28	PR 50-269 P 70-2746 50-329 K 50-329 K	

ACCESSION	NUMBER				ACCE9910	N NVMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 189UED	SUB JECT CATEGOR		ENCLOSURE	PRINCIPAL BOCUMENT	DATE ISSUED	SUBJECT	
#207090208 #207090215 #207090224 #207120140 #207120253	8207090201 8207090201 8207090201 8210280013 8207120147	82/07/06 82/07/06 82/07/06 82/07/06 82/09/17 80/06/18	50-278 50-278 50-278 50-276 50-324 50-447	PPPFA	821001095 821001095 821001098 821001099 821001099	8210010008 8210010075 8210010094 8210010008 8210010097	82/06/28 82/09/15 82/09/21 92/06/28 82/09/22	50-346 50-335 50-346 50-366 50-259	s 0 5 8
8207140138 8207140491 8207140494 8207140497 8207140500	8210060442 6210040366 6210040366 6210040366 6210040366	82/08/24 82/08/24 82/08/24 82/08/24 82/08/24	50-537 50-373 50-373 50-373 50-373	0000	8210010105 6210010107 8210010100 8210010110 8210010111	8210010102 8210010103 82100101008 82100101008	82/06/28 82/09/27 82/06/28 82/09/13 82/09/13	50-366 50-339 50-366 50-413 50-400	8 9 0
6207180073 £207180088 6207190431 6207230303 6207300222	8210220047 8210190118 8210120272 8207230301 8210050300	82/09/17 82/09/16 82/10/04 82/07/13 82/09/21	NUREC REVIEW C 50-29 50-339 50-206	RP 0 5 8	9210010115 8210010118 8210010119 8210010122 8210010124	8210010108 8210010113 8210010008 8210010120 8210010117	82/09/24 82/09/07 82/06/28 82/08/31 82/09/02	50-327 50-321 FOIA 50-83 50-269	5 0 0
6208010016 6208010019 6206020047 6208100269 6208110271	8210070440 8210220072 8210270083 8210120245 8210270270	82/09/14 82/09/20 82/09/20 82/09/30 82/10/19	50-289 GRG FO1A 50-29 50-155	P P	8210010126 8210010127 8210010128 8210010134 6210010135	8210010121 8210010121 8210010131	82/07/20 82/07/16 82/07/16 82/07/22	50-324 70-1201 50-311 50-413 50-327	9 9 9
6208170063 6208180082 6208170178 6208170270 6208250412	8210050300 8210200041 8210130205 8210180035 8210080036	82/09/21 92/10/12 92/10/05 82/09/27 82/09/13	50-206 50-155 50-213 50-302 FOIA	P P P	6210010137 6210010139 6210010139 6210010141 6210010143	6210010132 6210010131 6210010131 6210010131	82/09/01 82/09/22 82/09/27 82/09/22 82/09/22	50-324 50-413 50-348 50-413 50-413	0 8 0
6206250417 6208310034 6209130461 6209140027 6209140153	8210080036 8210280013 8210220015 8210220105 8209140148	82/08/13 82/09/17 82/10/08 82/10/18 82/09/08	50~269 50~155 50~293 50~244 50~324	P P P F	B210010145 8210010147 8210010150 6210010151 8210010153	8210010140 8210010127 8210010144 8210010148 8210010142	82/09/22 82/09/27 82/09/16 82/09/07 82/09/17	50-338 50-340 50-311 50-416 50-335	5 5 0 0
8209150106 8209150162 8209150436 8209150438 8209150440	8210280013 8210280013 8209150432 8209150432 8209150434	92/09/17 92/09/17 92/07/23 92/07/23 92/09/25	50~261 50~325 70~2946 70~2946 50~267	P P F	8210010159 8210010161 8210010165 8210010166 8210010168	8210010195 8210010008 8210010157 8210010158 8210010163	82/09/08 82/06/28 82/09/24 82/09/02 82/09/22	50-335 50-327 50-220 50-269 50-338	0 5 0 8
8209160311 8209160459 8209200475 8209210383 8209210413	8207160277 8210250071 8210040132 8210080001 8210180308	82/08/31 82/09/30 82/09/27 82/09/14 82/09/17	50-325 50-155 50-29 50-237 50-528	S P P A	9210010169 8210010172 8210010174 8210010176 8210010178	8210010008 8210010008 8210010164 8210010173 8210010175	82/06/28 82/06/28 82/09/24 82/09/08 82/09/16	FOIA FOIA 50-335 50-241 50-313	S Q Q
8209210523 8209210529 8209210550 8209220137 8209270271	8207210514 8207210425 8210180214 8207220135 8207270242	82/09/01 82/09/20 82/09/17 82/09/13 82/09/24	50-309 50-251 50-508 50-382 50-358	P S A A H	8210010180 8210010183 8210010187 8210010187 8210010188	8210010177 8210010171 8210010179 8210010182 8210010171	82/07/22 82/07/16 82/07/27 82/07/07 82/07/16	50-387 50-324 50-306 50-424 50-324	8 9 0
0207270379 62072701 87 6207270225 6207270236 6207270240	8206200097 8209290125 8209290125 8209290168 8209290168	82/07/27 82/09/16 82/09/16 82/08/26 82/08/26	COMMISSI 50-10 50-10 FOIA FOIA	011 F F	8210010192 8210010193 8210010194 8210010197 8210010199	8210010181 8210010170 8210010171 8210010191 8210010171	82/07/16 82/07/15 82/07/16 82/07/22 82/07/16	50-272 50-325 50-324 50-438 50-324	8 0 0
8209300175 8309300332 8209300334 8209300355 8210010022	8209300170 8209300324 8209300324 8209300353 8210010019	82/09/24 82/09/22 82/09/22 82/09/30 82/09/16	50-259 50-213 50-213 50-537 50-321	5 P B O	8210010200 8210010203 8210010208 8210010206	8210010191 8210010191 8210010171 8210010170 6210010204	82/09/22 82/09/22 82/09/16 82/09/15 82/08/30	50-438 50-438 50-324 50-325 50-348	G G G
9210010024 9210010029 6210010029 9210010031 9210010041	8210010005 8210010017 8210010017 8210010017 8210010034	82/07/07 82/09/14 82/09/16 82/09/16 82/09/24	71-481 50-321 50-321 50-321 50-263	а а а Р	9210010210 9210010214 9210010215 9210010215 9210010217	8210010207 8210010207 8210010212 8210010213 8210010207	82/09/22 82/09/22 82/09/17 82/08/31 82/09/22	50-213 50-213 50-361 50-389 50-338	P P Q
8210010046 8210010047 8210010049 8210010061 8210010065	8210010034 8210010045 8210010004 8210010008	82/09/24 82/09/16 82/09/22 82/06/28 82/06/28	50-263 50-311 50-302 FOIA FOIA	P S G	8210010222 8210010224 8210010229 8210010229 8210010236	8210010212 8210010217 8210010221 8210010212 8210010233	82/09/17 82/09/24 82/08/31 82/09/17 82/09/22		
8210010047 8210010048 8210010073 8210010076 8210010078	8210010008 8210010008 8210010008 8210010008 8210010075	82/06/28 82/06/28 82/06/28 82/06/28 82/09/15	FO1A FO1A FO1A FO1A 50-335	g	8210010238 8210010239 8210010240 8210010245 8210010245	8208260424 8210010237 8210010235 8208260424 8208070114			
8210010079 8210010081 8210010082 8210010083 8210010084	8210010064 8210010077 8210010064 8210010008 8210010075	82/09/29 82/09/24 82/09/29 82/06/28 82/09/15	50-537 50-219 50-537 50-321 50-335	6 P 0 8 0	8210010247 8210010248 8210010280 8210010284 8210010287	820807011; 821001024; 821001027; 821001027; 8210010275			
8210010085 8210010089 8210010089 6210010091 8210010092	8210010077 8210010075 8210010008 8210010086 8210010075	82/09/24 82/09/15 82/06/28 82/09/13 82/09/15	50-219 50-335 50-366 50-400 50-335	Posoo	8210010274 8210010273 8210010277 8210010203 8210010203	8210010275 8210010287 8210010281 8210010291 8210010291			

TO PRINCIPAL DOCUMENTS

ACCESSIO	N NUMBER				ACCE8910	N PERUN N			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 189UED	SUBJECT CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8210010305 8210010314 8210010317 8210010321 8210010327	8210010301 8210010300 8210010313 8210010316 8210010309	82/09/10 82/09/03 82/09/13 82/09/13	50-389 50-338 70-143 50-250 50-321	0 0 0	8210040075 8210040083 8210040083 8210040105 8210040111	8210040073 8210040081 8210040086 8210040100 8210040107	82/09/22 82/10/01 82/09/24 82/09/22 82/09/29	50-315 50-155 50-387 50-293 50-313	S & S & P
8210010329 8210010338 8210010340 8210010341 8210010346	8210010316 8210010314 8210010336 8210010333 6210010316	82/09/13 82/09/13 82/09/16 82/09/17 82/09/13	50-250 50-250 50-324 50-390 50-250	0 0 0 0	8210040121 6210040122 8210040129 8210040134 8210040137	8210040116 8210040118 8210040126 8210040131 8210040132	82/09/24 82/09/24 82/09/16 82/09/15 82/09/27	50-304 50-387 50-249 50-373 50-29	5555
8210010350 8210010355 8210010360 8210010361 8210010363	8210010336 8210010344 8210010347 8210010353 8210010358	82/09/16 82/09/16 82/09/22 82/09/10 82/09/10	50-324 50-311 50-400 70-27 State Fr	_	8210040144 8210040145 8210040150 6210040155 8210040159	8210040142 8210040141 8210040144 8210040148 8210040156	82/09/24 82/09/28 82/09/30 82/09/27 82/09/24	50-317 50-247 50-440 0A999 50-305	S K S
8210010365 8210010368 8210010369 8210010371 8210010373	8210010357 8210010349 8210010357 8210010364 8210010349	82/09/28 82/09/28 82/09/28 82/09/29	50-244 50-400 50-244 70-143 50-400	P Q P	8210040162 8210040173 8210040178 8210040183 8210040183	8210040156 8210040171 8210040177 8210040182 8210040184	82/09/24 82/09/27 82/09/30 82/09/27 82/09/09	50-305 0A979 50-206 50-220 50-409	5 P 0
8210010384 8210010385 8210010390 8210010394 8210010397	8210010380 8210010376 8210010383 8210010389 8210010349	82/09/13 82/09/22 82/09/16 82/09/23 82/09/22	50-404 50-334 50-272 50-409 50-400	6 8 8 6	8210040187 8210040189 8210040194 8210040203 8210040204	8210040185 8210040188 8210040172 8210040179 8210040202	82/09/20 82/09/15 82/09/27 82/09/24 82/09/10	50-285 50-237 0A999 50-315 50-331	s s g
8210010378 8210010379 8210010402 8210010405 8210010409	8210010388 8210010391 8210010393 8210010391 6210010401	82/09/22 82/09/22 82/09/22 82/09/22 82/08/31	70~824 50~324 50~387 50~324 50~3	0 5 0 P	8210040205 8210040208 8210040213 8210040213 8210040213	8210040199 8210040202 8210040201 8210040206 8210040211	82/09/24 82/09/10 82/09/23 82/09/27 82/09/24	50~315 50~331 50~314 50~284 50~318	5 0 5 F 5
8210010410 8210010412 8210010413 8210010414 8210010415	8210010391 8210010407 8210010406 8210010401 8210010391	82/09/22 82/09/16 82/09/17 82/08/31 82/09/22	50-324 50-311 50-275 50-3 50-324	0 9 9	8210040220 8210040223 8210040228 8210040228 8210040245	8210040215 8210040221 8210040216 8210040224 8210040232	82/09/27 82/09/24 82/09/23 82/09/24 82/09/27	50-45B 50-373 50-31B 50-352 50-269	К Р С Р
8210010420 8210010423 8210010425 8210010426 8210010428	8210010411 8210010417 8210010401 8210010411 8210010418	82/09/22 82/09/14 62/08/31 82/09/22 82/09/23	50-518 50-311 50-3 50-518 40-1202	0 5 P 0	6210040246 8210040265 8210040273 8210040274 8210040279	8210040230 8210040261 8210040254 8210040258 8210040254	62/09/27 92/09/28 82/10/01 82/09/27 82/10/01	50-454 50-219 50-349 50-322 50-369	0 F K O K
8210010429 8210010431 8210010432 8210010433 8210010434	8210010421 8210010411 8210010430 8210010411 8210010418	82/09/17 82/09/22 82/09/03 82/09/22 82/09/23	50-438 50-518 50-259 50-518 40-1202	Q Q Q	8210040284 8210040285 8210040286 8210040288 8210040290	8210040281 8210040277 8210040254 8210040281 8210040277	82/09/28 82/09/27 62/10/01 62/09/28 82/09/27	50-244 50-338 50-369 50-244 50-338	Р К Р
8210010436 8210010438 8210010440 8210010443	8210010424 8210010401 8210010418 8210010401 8210010442	62/09/08 62/08/31 62/09/23 62/08/31 62/09/03	50-369 50-3 40-1202 50-3 50-416	Q P Q	9210040297 9210040301 9210040303 9210040305 9210040307	8210040277 8210040277 8210040296 8210040292 8210040277	82/09/27 82/09/27 82/10/01 82/09/28 82/09/27	50-338 50-339 50-220 50-528 50-338	P F H P
	8210010401 8210010451 8210010486	62/08/31 82/09/08 62/09/22 32/09/16	50~3 50~369 50~341 50~311 50~390	P Q A B Q	8210040315 8210040319 8210040320 8210040325 8210040327	8210040277 8210040311 8210040277 8210040277 8210040321	82/09/27 82/09/29 82/09/27 82/09/27 82/09/22	50-338 TOPREP 50-338 50-338 50-314	P P S
			50-269 50-269 50-395 50-443	0 0 A 0	8210040327 8210040330 8210040335 8210040335 8210040340	8210040323 8210040321 8210040324 8210040333 8210040333	82/09/30 82/09/22 82/09/21 82/09/27 82/09/27	Toprep 50-316 50-333 GA999 GA999	6
				9	8210040346 8210040347 8210040350 8210040351 8210040354	8210040343 8210040343 821040043 821040043 821040045	82/08/20 82/08/20 82/08/20 82/08/20	50~537 50~537 50~537 50~537 50~282	A A A
					8210040355 8210040357 8210040367 8210040367 8210040368	8210040343 8210040343 8210040258 8210010008 8210010008	82/08/20 82/09/20 82/09/27 82/06/28 82/06/28	50-537 FOIA 50-322 50-366 FOIA	A Q S
					8210040371 8210040374 8210040375 9210040376 8210040379	8210010008 8210010008 8210040364 8210040367 8210010008	82/06/28 82/06/28 82/08/24 82/09/24 82/06/28	F01A 50-320 50-373 50-331 F01A	80
					8210040381 8210040383 8210040376 8210040377 8210040411	8210010008 8210010008 8210010008 8210040392 8210010008	82/06/28 82/06/28 82/06/28 82/09/07 82/06/28	FOIA FOIA FOIA 70-371 FOIA	

ACCESS10	N NUMBER				ACCE88101	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJEC CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	CATE ISSUED	SUBJEC	
8210040412 8210040416	8210040410 8210010008	82/09/15 82/06/28	CONTRAC		8210050208	8210050202	82/10/04	50-413	0
8210040417 8210040418 8210040419	9210040415 8210040415 8210040415	82/09/15 82/09/15 82/09/15	50-315 50-315 50-315	P P	8210030207 8210050212 8210050213 8210050217	8210010008 8210010008 8210050204 8210010008	82/06/28 82/06/28 82/10/01 82/04/28	FOIA FOIA 70-2942 FOIA	?
8210040420 8210040421	8210040414 8210010008	82/08/28 92/08/31	50-266 FDIA	P	8210050229 8210050231	8210050223 8210050222	82/09/28 82/09/30	50-329 50-266	0 P
8210040425 8210040427 8210050006	8210040414 8210040414 8210010008	82/06/28 82/08/31 82/08/31	50-266 50-266 FOIA	Þ	8210050233 8210050234 8210050239	6210050227 6210050151 6210050224	82/09/16 82/09/22 82/09/22	50-237 50-361 50-267	8 0
8210050007 8210050010 8210050011	8210010008 8210010008	85/04/28	FOIA FOIA		8210050258 8210050266	8210050253 8210050261	82/09/24 82/09/23	50-344 50-341	Q S
8210050012 8210050015	821005000B 8210050013	82/06/28 82/09/24 82/09/16	FOIA 50-361 50-307	8 F	8210050271 8210050276 8210050287	8210050268 8210050274 8210050284	82/09/21 82/09/24 82/10/01	50-259 50-315 9A999	Q Q
6510020018 6510020018 6510020050	8210050013 8210050016	82/09/16 82/09/24	50-309 50-361	F	8210050290 8210050292	8210050284 8210050284	82/10/01 82/10/01	QA999 QA999	
6210050021 6210050021	8210050017 8210010008 8210010008	79/03/16 82/06/28 82/06/28	REGGD FOIA 50~278	ន	8210050295 8210050303 8210050307	8210050284 8210050301 8210050306	82/10/01 82/10/01 82/09/24	0A999 50-285 50-331	S
8210050024 8210050026 8210050027	8210050016 8210050017	82/09/24 79/03/16	50-341 Regod	5	8210050311 8210050313	9210050308 9210050310	82/09/29 82/09/30	50-331 50-346	G P
8210050029 8210050030	8210010008 8210050016 8210050017	82/06/28 82/09/24 79/03/16	50-348 50-361 Reged	s	82:0050318 82:0050321 82:0050327	8210050310 8210050320 8210050323	82/09/28 82/09/28 82/09/22	50-346 50-277 50-346	8 6 6
8210050031 8210050032 8210050034	8210010008 8210050016	82/06/28 82/09/24	FOIA 50~361	s	8210050334 8210050337	8210050332 8210050331	82/09/20 82/09/20	50-358 50-267	K
9210050037 8210050037	8210050017 8210010008 8210050016	79/03/14 82/06/28 82/09/24	REGGD A DT 50-361	s	8210050342 8210050361 8210050365	821005033 <u>&</u> 8210050355 821005035 <i>9</i>	82/09/24 82/09/24 82/09/15	50~1 55 50~346 50~1 66	0 5 0
8210050038 8210050039	821001000B 8210050017	92/06/28 79/03/16	FOIA REGOD		8210050371 8210050372	8210050342 8210050366	82/09/29 82/09/29	50-324 50-382	P
8210050041 8210050042 8210050044	8210050016 8210050017 8210050016	82/09/24 79/03/16 82/09/24	10-361 00039 146-08	8 5	8210050378 8210050380 8210050390	8210050356 8210050359 8210050381	82/09/29 82/09/15 82/09/23	50-382 50-186 50-361	0 8
8210050048 8210050050	8210050016 8210050016	82/09/24 82/09/24	50-361 50-361	2 3		8210050387 8210010008	85/09/58	50-458 FOIA	O
8210050056 8210050064 8210050068	8210050052 8210010008 8210050045	85/04/58 85/04/58 82/04/30	50-373 FOIA 50-409	P P	8210050409	8210050398 8210010008 8210050416	85/04/30 85/04/38 85/04/53	50-447 F01A 50-389	A
8210050070 8210050074	8210050067 8210050071	82/09/29 82/09/27	50-409 50-280	B		821001000B	85\09\58 85\09\58	FOIA FOIA	
8210050075 8210050077 8210050078	8210010008 8210050073 8210050071	85/04/51 85/04/30 85/06/58	50~304 50~456 50~280	5 A 5	8210050434	8210050425 8210010008 8210010008	85/06/28 85/06/28	50-155 FOIA FOIA	P
8210050082 8210050084 8210050085	8210010008 8210050080	82/04/28 82/04/23	F01A A6E~02	s	£210050446	8210050430 8210050430	82/08/17 82/08/17	F01A 70~1510	
8210050085 8210050087	8210050083 8210050081 8210010008	82/06/28 82/06/28	50-333 50-260 FOIA	F S	6210050456	8210050430 8210050430 8210050430	82/08/17 82/08/17 82/08/17	70-1510 70-1510 FDIA	
8210050091 8210050092 8210050093	8210050081 8210050081 8210010008	82/09/27 82/09/27 82/06/28	50-280 50-280 FOIA	5 5	8210050473	B210050430 B210010008	82/08/17 82/06/28	FOIA FOIA	
8210050191 8210050101	8210050096 8210050096	82/09/24 82/09/24	50~361 50~361	s	8210050481	8210010008 8210010008 8210050485	82/04/28 82/04/28 82/09/20	F01A F01A 80-272	P
8210050107 8210050109 8210050110	8210050105 8210050103 8210050102	82/07/09 82/09/24 82/09/30	50~295 50~280 50~305	0 S Q	8210050495	821001000B 8210030491	82/06/28 82/09/14		
8210050116 8210050116	8510010008 8510020102	82/07/09 82/06/28	50-295 FOIA	Ġ.	8210050500	8210010008 8210010008 8210050497	83/09/28 83/06/38		
8210050124 8210050135	8210010008 8210010008 8210050139	85/04/28 85/04/28	50-311 FOIA 50-329	S	821005050B	8210050497 8210050501			
8210050146 8210050154 8210050155	8210050139 8210010008	85\09\58 85\04\55 85\04\55	50-329 FOIA	a a	8210050514	8210050497 8210010008 8210030512			
8210050160 8210050161	8210050159 8210010008	82/09/29 82/06/28	50~315 50~320	բ 8	8210050521	8210010008 8210050516			
8210050144 8210050148 8210050181	831001000B 831001000B 831001000B	82/06/28 82/09/29 82/06/28	F01A 50^334 F01A	P	8210050528	8210050512 8210050504 8210050525			
8210050185 8210050187	8210050183 8210050179	82/09/30 82/09/24	50-461 50-336	K P	€21QQ50536	821001000B 8210030504			
8210050190 8210050191 8210050194	8210020189 8210020188 8210010008	62/06/28 62/10/01 62/09/15	F01A GA999 50-266	a	E210050541	8210010008 8210050538 8210010008			
8210050198 8210050200	8210050195 8210010008	82/10/01 82/06/28	GA999 FOIA		B≥10050544	B210050540 B21005053B			
8210050203 8210050205 8210050204	8210050184 8210050184 8210050199	82/09/28 82/09/15 82/09/30	50~416 50~246 50~443	g A	8210050546 8210050548 8210050567	8210050538 8210050540 8210050559			

ACCESSION					ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 168UED	SUBJECT		PRINCIPAL Enclosure document	DATE ISBUED	SUBJECT	75
8210050573 8210060001 8210060005 8210060008 8210060009	8210190079 8210010008 8210010008 8210010008 8210010008	82/10/01 82/06/28 82/06/28 82/06/28	FOIA FOIA FOIA FOIA		8210060345	82/10/01 82/10/01 82/10/04	50-528 50-289 50-327 50-261 70-25	а Р Г
8210040014 8210040026 8210040030 8210040041 8210040042	8210040013 8210010008 8210040023 8210040024 8210010008	82/10/01 82/06/28 82/09/24 82/09/17 82/06/28	50-261 F01A 50-293 50-247 F01A	ዖ 8 0	8210060363 8210010008 8210060367 8210060357 8210060370 821006036 8210060370 8210060361 8210060372 8210060361	82/10/01 82/06/28	F01A 50-237 F01A 70-1100 50-280	Q S
8210060046 8210060047 8210060068 8210060077 8210060081	6210060024 6210060034 6210010009 6210010008 6210060076	82/09/17 82/09/27 82/06/28 82/06/28 82/09/23	50-247 50-29 FOIA FOIA 50-334	g g	8210060380	82/04/28 82/09/21 82/09/30	50-263 FDIA 50-373 50-263 50-317	g P S
6210040082 8210040083 8210040084 6210040085 8210040075	8210010003 6210040074 6210010008 6210040060 6210040069	82/06/28 82/09/24 82/06/28 82/09/30 82/09/28	50-296 50-277 FOIA 50-293 50-334	8 8 8	8210060373 8210060387 8210060374 821006036 8210060379 8210060316 8210060400 8210060376 8210060403 6210060376	82/09/27 82/09/30 82/09/24	50-315 50-317 50-280 50-247 50-254	9 9 9 9
8210060100 8210060104 8210060119 8210060124 8210060127	8210010008 8210040079 8210040117 8210040109 8210040079	82/06/28 82/09/17 82/09/30 82/09/16 82/09/17	FOIA 50-317 50-341 50-342 50-317	е Р О	8210060411 8210060406 8210060412 8210060409 8210060413 8210060414 8210060422 8210060414 8210060424 8210060426	82/09/30 82/09/22 82/09/30	FD1A 50-257 FO1A 50-257 CONTRACT	8
8210060131 8210060141 8210060147 8210060148 8210060157	8210060126 8210060133 8210060138 8210060145 8210060155	82/09/15 82/09/17 82/09/30 82/09/15 82/09/24	50-228 50-275 70-398 50-247 50-508	0 0 F 0	#210060427 #210010008 #210060429 #210060428 #210060430 #210010008 #210060432 #210010008 #210060433 #210060431	82/09/29 82/06/28 82/06/28	F01A F01A 50-336 50-334 50-272	s s F
8210040163 8210040164 8210040173 8210040180 8210040203	8210060155 8210060150 8210060171 8210060150 8210060201	82/09/24 82/09/30 82/09/29 82/09/30 82/09/29	50-508 50-293 50-309 50-293 50-416	0 0 P 0 B	8210040447 8210040449 8210040449 821001008 8210040451 8210010044 8210040452 8210010008 8210040453 8210040442	82/06/28 82/08/24 82/06/28	50-537 F01A 50-537 F01A 50-537	D A A
8210060206 8210060208 8210060212 8210060214 8210060215	8210060174 8210060202 8210060207 8210060174 8210060211	62/09/30 82/09/29 82/10/01 82/09/30 82/09/17	50-443 50-220 50-251 50-443 50-412	0 8 0 0	. 8210060455 8210060442 8210060458 8210060442 8210060460 8210010008 8210070005 8210070003 8210070004 8210070003	82/08/24 82/06/28 82/09/17	50-537 50-537 50-320 50-346 50-346	A B F F
8210060216 8210060221 8210060226 8210060227 8210060230	8210060213 8210060219 8210060224 8210060225 8210060228	82/09/29 82/09/30 82/09/30 82/09/30	50-255 50-327 50-416 70-7 50-289	8 8 8	8210070008 8210010008 8210070014 8210070013 8210070018 8210070015 8210070021 8210070003 8210070030 8210070007	82/09/29 82/09/29 82/07/20	FOIA 50-155 50-155 CONTRACT 50-244	P P
8210050238 8210050241 8210050243 8210050247 8210050248	8210060237 8210060239 8210060240 8210060245 8210060246	82/09/24 82/09/30 82/09/29 82/10/01 82/09/23	50-336 50-155 50-317 50-528 50-366	8 8 8	8210070032 8210070025 8210070035 8210070025 8210070037 8210070025 8210070039 8210070025 8210070039 8210070025	82/09/14 82/07/16 82/08/10	50-289 50-289 50-537 50-244 50-537	G D G A
6210060252 6210060254 6210060254 6210060257 6210060259	8210060251 8210060253 8210060253 8210060255 8210060255	82/09/20 82/10/04 82/10/04 82/10/01 82/10/01	50-373 50-315 50-315 TOPREP TOPREP	0	8210070049 8210070029 8210070044 8210070044 8210070045 8210070045 8210070047 8210070046 8210070048 8210070046	82/09/17 82/09/10 82/07/16	50-537 50-416 50-373 50-537 50-416	D F H D F
					8210070050 8210070023 8210070051 8210070044 8210070053 8210070025 8210070055 8210070025 8210070056 8210070025	92/09/10 9 82/07/16 9 82/09/10	50~537 50~373 50~537 50~373 50~537	D H D H D
					8210070058 8210070025 8210070059 8210070054 8210070060 8210070054 8210070061 8210070024 8210070064 8210070026	82/09/15 82/09/15 82/09/10	50-597 50-309 50-309 50-373 50-597	D P H D
					8210070046 8210070047 6210070047 9210070027 6210070048 8210070007 6210070070 8210070027 6210070071 8210070027	82/07/16 82/08/10 82/07/16	50-373 50-337 50-244 50-537 50-537	H P A A
					8210070073 8210070000 8210070074 8210070000 8210070080 8210070000 8210070083 8210070002 8210070084 821007002	82/08/10 62/08/10 82/08/10	50-244 50-244 50-244 50-244 50-537	P P P
					8210070086 8210070025 8210070087 8210070000 8210070089 8210070000 8210070070 8210070000 8210070091 8210070085	82/08/10 92/07/16 82/08/10	50-537 50-244 50-537 50-244 50-29	PAPP

ACCESSION	I NUMBER				ACCESS 16	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	
8210070093 8210070094 8210070095 8210070098 8210070099	8210070029 8210070085 8210070029 8210070029 8210070085	82/07/16 82/10/04 82/07/16 82/07/16 82/10/04	50-537 50-29 50-537 50-537 50-29	4 4 4 4	8210070249 8210070270 8210070273 8210070273 8210070275	8210070029 8210070248 8210070029 8210070029 8210070029	82/07/16 82/09/22 82/09/22 82/07/16 82/09/22 82/07/16	50-537 50-219 50-537 50-219 50-537	F G A G
8210070101 8210070103 8210070112 8210070117 8210070118	8210070029 8210070029 8210070109 8210070106 8210070029	82/07/16 82/07/16 82/09/29 82/09/20 82/07/16	50-537 50-537 50-445 50-317 50-537	D A F A	8210070280 8210070282 8210070283 8210070285 8210070286	8210070027 8210070027 8210070277 8210070027 8210070277	82/07/16 82/07/16 82/09/22 82/07/16 82/10/04	50-537 50-537 50-293 50-537 50-315	C A Q A
8210070119 6210070121 6210070123 6210070125 6210070124	8210070029 8210070007 8210070029 8210070106 8210070029	82/07/16 62/08/10 82/07/16 62/09/20 82/07/16	50-537 50-244 50-537 50-317 50-537	D P D P D	8210070287 8210070291 8210070293 8210070293 8210070298	8210070278 8210070029 8210070029 8210070290 8210070029	82/10/04 82/07/16 82/07/16 82/10/04 82/07/16	50-312 50-537 50-537 50-312 50-537	G G A G A
8210070128 8210070129 8210070130 8210070131 8210070134	8210070029 8210070127 8210070108 8210070029 8210070029	82/07/16 82/10/05 82/09/20 82/07/16 82/07/16	50-537 50-454 50-317 50-537 50-537	00000	8210070301 8210070302 8210070304 8210070308 8210070310	8210070029 8210070299 8210070029 8210070296 8210070029	82/07/16 82/10/04 82/07/16 82/09/24 82/07/16	50-537 50-397 50-537 50-278 50-537	A G A G
9210070135 9210070139 9210070137 9210070142 9210070144	8210070007 8210070029 8210070007 8210070029 8210070141	82/08/10 62/07/16 82/08/10 82/07/16 82/07/16	50-244 50-537 50-29 50-337 50-397	P C G C A	8210070312 8210070313 8210070314 8210070315 8210070315	8210070307 8210070029 8210070305 8210070029 8210070307	82/09/24 82/07/16 82/09/22 82/07/16 82/09/24	70-344 50-537 50-272 50-537 70-344	D S D
8210070146 8210070148 8210070151 8210070154 8210070156	8210070029 8210070029 8210070029 8210070029 8210070153	82/07/16 82/07/16 82/07/16 82/07/16 82/08/13	50-537 50-537 50-537 50-537 CDNTRACT	C F A F	8210070318 8210070323 8210070323 8210070323 8210070330	8210070027 8210070317 8210070029 8210070029 8210070317	82/07/16 82/07/22 82/07/16 82/07/16 82/07/22	50-537 50-277 50-537 50-537 50-277	D D D
8210070157 8210070161 8210070163 8210070165 8210070166	8210070029 8210070158 8210070029 8210070007 8210070029	82/07/16 82/10/04 82/07/16 82/08/10 82/07/16	50-537 50-508 50-537 50-244 50-537	A A P D	8210070331 8210070332 8210070333 8210070335 8210070336	8210070319 8210070029 8210070326 8210070029 8210070337	82/10/04 82/07/16 82/10/05 82/07/16 82/07/22	50-312 50-537 50-285 50-537 50-220	Q D Q D
8210070170 8210070172 8210070174 8210070179 8210070181	8210070029 8210070007 8210070029 8210070029 8210070178	82/07/16 82/08/10 82/07/16 82/07/16 82/09/24	50-537 50-269 50-537 50-537 50-219	C G C A S	8210070345 9210070346 8210070347 8210070350 821007035	8210070341 8210070340 8210070029 8210070337 8210070348	82/09/24 82/09/29 82/07/16 82/09/22 82/10/04	50-219 50-293 50-537 50-220 50-438	9 9 9 4
8210070182 8210070185 8210070184 8210070187 8210070188	8210070029 8210070007 8210070029 8210070007 8210070177	82/07/16 82/08/10 82/07/16 82/08/10 82/09/29	50-537 50-266 50-537 50-266 50-277	A P D P G	8210070356 8210070358 8210070359 6210070363 8210070366	B210070352 B210070348 B210070351 B210070348 B210070361	82/10/05 82/10/04 82/07/22 82/10/04 82/09/27	50~245 50~438 50~311 50~438 50~247	G A B A B
8210070190 8210070191 8210070193 8210070195 8210070196	8210070029 8210070007 8210070189 8210070029 8210070007	82/07/16 82/08/10 82/09/16 82/07/16 82/08/10	50-537 50-266 50-522 50-537 FOIA	D P C C	8210070367 8210070349 8210070375 8210070377 8210070391	8210070362 8210070364 8210070368 8210070371 8210070357	82/10/04 82/07/22 82/07/22 82/07/22 82/07/20	50-333 50-445 50-272 50-311 50-309	G G S G
6210070198 6210070200 8210070202 8210070205 8210070204	8210070007 8210070029 8210070007 8210070007 8210070029	82/08/10 82/07/16 82/07/16 82/08/10 82/07/16	F01A 50-537 50-537 50-246 50-537	C D P C	8210070385 8210070397 8210070388 8210070393 8210070393	8210070363 6210070378 6210070380 6210070376 6210070383	82/08/13 82/10/04 82/07/22 82/07/24 82/08/13	40-6622 50-460 50-272 50-271 40-6622	Q Q
8210070207 8210070208 8210070216 8210070217 6210070218	8210070029 8210070007 8210070214 8210070007 8210070007	82/07/16 82/08/10 82/09/23 82/08/10 82/08/10	50-537 50-266 50-286 50-266 50-266	D P Q P	8210070400 9210070410 9210070413 9210070418 9210070421	8210070392 8210070409 8210070409 8210070411 8210070411	82/09/22 82/08/18 82/08/18 82/09/10 82/09/10	50-443 71-9150 71-9150 FOIA FOIA	a
8210070222 8210070223 8210070228 8210070228 8210070231	8210070029 8210070029 8210070029 8210070007 8210070221	82/07/16 82/07/16 82/07/16 82/08/10 82/09/22	50-537 50-537 50-537 50-244 50-311	A A Q G	8210070423 8210070426 8210070428 8210070431 821007043	8210070417 8210070411 8210070411 8210070411 8210070411	82/09/27 82/09/10 82/09/10 82/09/10	FOIA FOIA FOIA FOIA	
8210070235 8210070240 8210070241 8210070247 8210070248	B210070007 B210070239 B21007023B B210070245 B210070246	82/08/10 82/09/22 82/09/27 82/09/29 82/09/22	FOIA 70-33 50-219 50-293 50-311	s 5	6210070436 8210070441 9210070445 8210070445 8210070448	8210070411 8210070411 8210070411 8210070411 8210070411	82/09/10 82/09/10 82/09/10 82/09/10 82/09/10	FDIA FOIA FDIA FOIA	
8210070251 8210070252 8210070253 8210070254 8210070258	8210070029 8210070029 8210070029 8210070029 8210070254	82/07/16 82/09/22 82/07/16 82/07/16 82/09/22	50-537 50-311 50-537 50-537 50-311	A A A	9210070451 8210070454 8210070458 8210070459 8210070464	8210070411 8210070411 8210070411 8210070456 8210070411	82/09/10 82/09/10 82/09/10 82/09/17 82/09/10	FOIA FOIA FOIA CONTRACT FOIA	
8210070259 8210070260 8210070262 8210070264 8210070266	8210070029 8210070029 8210070029 8210070029 8210070029	82/07/16 82/07/16 82/07/16 82/07/16 82/07/16	50-537 50-537 50-537 50-537 50-537	ACCFA	8210070465 8210070467 8210070468 8210070491 8210070471	8210070029 8210070411 8210070411 8210070411 8210070411	82/07/16 82/09/10 82/09/10 82/09/10 82/09/10	50-537 FOIA FOIA FOIA FOIA	D

TO PRINCIPAL DOCUMENTS

ACCESSIO	R3EHUN N				ACCES	B10N	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEODS		ENCLOSURI	E	PRINCIPAL DOCUMENT	DATE 195UED	SUBJECT CATEGORY	4
8210070475 8210070478 8210070480 8210070482 8210070484	8210070411 8210070411 8210070411 8210070411	82/09/10 82/09/10 82/09/10 82/09/10 82/09/10	FOIA FOIA FOIA FOIA		82100802 82100802 82100802 82100802	214 215 216 217	8210080212 8210080015 8210080015 8210080015 8210080227	82/10/04 82/07/12 82/07/12 82/07/12 82/10/04	FOIA FOIA	a 0
8210070485 8210070486 8210070488 8210070489 8210080002	8210070411 8210070411 8210070411 8210070411 8210080001	82/09/10 82/09/10 82/09/10 82/09/10 82/09/14	PUIA FOIA FOIA FOIA 50~237	þ	82100802 82100802 82100802 82100802	232 239 240	8210080221 8210080225 8210080225 8210080234 8210080248	82/09/29 82/08/25 82/08/25 82/09/28 82/10/06	50-324 71-9167 71-9167 50-366 50-395	5 9 0
8210080005 8210080022 8210080030 8210080030	8210080003 8210080012 8210080029 8210080029	82/09/10 82/09/21 82/09/21 82/09/22 82/09/22	XPORTLIC CONTRACT CONTRACT 50-295 50-295	r	82100802 82100802 82100802 82100802 82100802	254 257 258	8210080249 8210080248 8210080252 8210080254 8210080248	82/10/05 82/10/06 82/10/01 82/07/27 82/10/06	50-344 50-395 50-250 50-267 50-395	0 0 5 7 0
8210080032 8210080034 8210080035 8210080038 6210080040	8210080020 8210080020 8210080033 8210080037	82/09/16 82/09/16 82/09/09 82/08/13 82/09/08	FOIA FOIA XPORTLIC FOIA XPORTLIC		82100802 82100802 82100802 82100802	281 287 288	8210080240 8210080277 8210080282 8210080283 8210080284	82/09/30 82/10/04 82/10/04 82/10/04 82/10/05	50~482 50~416 50~416 50~346 50~416	
6210080042 8210080044 8210080047 8210080051 8210080054	8210080037 8210080036 8210080036 8210080015 8210080015	82/09/08 82/08/13 82/08/13 82/07/12 82/07/12	XPORTL IO 50-269 50-287 50-289 FOIA	P P O	82100802 82100803 82100803 82100803	298 299 311	8210080294 8210080295 8210080293 8210080302 8210080319	82/06/22 82/10/05 82/10/05 82/10/05 82/09/09	10PREP 50-416 70-2789 70-754 XPORTLIC	s
8210080055 8210080057 8210080064 8210080079 8210080080	8210080053 8210080015 8210080015 8210080063 8210080078	82/09/23 62/07/12 82/07/12 82/09/29 82/10/05	50-537 FOIA 50-317 50-219 50-275	D P P	82100803 82100803 82101200 82101200 82101200	331 318 321	8210080321 8210080327 8210120015 8210120015 8210120015	82/09/15 82/09/16 82/08/20 82/08/20 82/08/20	XPORTLIC XPORTLIC FOIA FOIA FOIA	
8210080085 8210080091 8210080190 8210080101	8210080015 8210080015 8210080015 8210080095 8210080015	82/07/12 82/07/12 82/07/12 82/07/28 82/07/12	50-244 50-289 50-289 50-397 FOJA	B P K	82101200 82101200 82101200 82101200	030 050 053	8210120015 8210120015 8210120047 8210120049 8210120015	82/08/20 82/08/20 82/10/04 82/09/23 82/08/20	FOIA 50-366 REVIEW C	P RP
8210080102 8210080106 8210080112 8210080114 8210080118	8210080078 8210080015 8210080015 8210080015 8210080015	82/09/30 82/07/12 82/07/12 82/07/12 82/07/12	50-29 FOIA 50-313 50-334 50-259	P 0 0	82101200 82101200 82101200 82101200	046 046 042	8210120015 8210120015 8210120015 8210120015 8210120058	82/08/20 82/08/20 82/08/20 82/08/20 82/09/24	FOIA FOIA FOIA FOIA 50-382	a
8210080122 8210080125 8210080127 8210080128	8210080015 8210080015 8210080120 8210080015 8210080129	82/07/12 82/07/12 82/10/04 82/07/12 82/09/22	50-324 50-302 50-416 50-346 50-315	9 9 8 9 8	82101201 82101201 82101201 62101201	133 133 112	8210120015 8210120103 8210120103 8210120103 8210120134	82/08/20 82/07/12 82/07/12 82/07/12 82/09/27	F01A F01A 50-537 50-400 50-317	Ç Ç F
8310000 5	1	82/07/12 82/09/22 82/07/12 82/07/12	50-333 50-315 50-247 50-220 50-219	0 F 0 0	82101201 92101201 92101201 92101201	143 150 151	8210120103 8210120103 8210120104 8210120103 8210120103	82/07/12 82/07/12 82/10/01 82/07/12 82/07/12	50-537 50-537 71-6347 50-244 FOIA	A A P
			10-255 10-293 10-387 10-312	G G P Q	82101501 82101501 82101501 82101501	166 170 174	8210120155 8210120158 8210120103 8210120169 8210120103	80/12/18 82/09/30 82/07/12 82/10/01 82/07/12	50-293 71-9001 FOIA 71-9034 FOIA	5
					82101201 82101201 82101201 82101201	188 192 196	8210120103 8210120103 8210120180 8210120103 8210120174	82/07/12 82/07/12 82/10/01 82/07/12 82/10/06	FOIA 50-3 71-6703 FOIA 50-508	P
					82101203 82101203 82101203 82101203 82101203	225 233 243	8210120103 8210120215 8210120222 8210120240 8210120241	82/07/12 82/10/01 82/09/15 82/10/04 82/10/06	FOIA 50-338 GA999 50-333 50-313	P R Q
					82101203 82101203 82101203 82101203	252 281 283	8210120248 8210120246 8210120276 8210120278 8210120280	82/10/04 82/10/01 82/10/05 82/10/01 82/10/06	50-395 50-313 50-329 50-275 0A999	P G A P
					82101203 82101203 82101203 82101203	289 293 299	8210120278 8210120284 8210120280 8210120291 8210120296	82/10/01 82/09/27 82/10/06 82/10/08 82/10/04	50-275 50-327 6A999 50-259 50-213	P 0 P
					85101503 85101503 85101503 85101503	305 308 309	8210120301 8210120297 8210120291 8210120301 8210120311	82/10/05 82/10/04 82/10/08 82/10/05 82/09/15	GA779 50-280 50-239 GA779 GA777	P

ACCESSIO				ACCESSION NUMBER	
ENCLOSURE	PRINCIPAL	DATE	SUBJECT	PRINCIPAL DATE	SUBJECT
	DDCUMENT	ISSUED	CATEGORY	ENGLOSURE DOCUMENT ISSUED	CATEGORY
8210120315 8210120316 8210120317 8210120319 8210120329	8210120301 8210120311 8210120311 8210120325	82/10/05 82/10/08 82/09/15 82/09/15 82/09/20	GA799 50-259 GA799 GA799 HASTE MGT	8210130193 8210130189 82/10/08 8210130194 8210130192 82/10/01 8210130197 8210130195 82/10/01 8210130201 8210130197 82/09/28 8210130208 8210130204 82/10/04	50-271 R 50-254 B 50-244 B 50-249 S 50-280 S
8210120330	8210120321	82/09/15	CONTRACT	8210130210 8210130206 82/09/30	50-289 P
8210120331	8210120326	82/10/06	REVIEW GRA	8210130213 8210130204 82/10/04	50-280 S
8210120335	8209280426	82/09/20	GEN TEC IS	8210130214 8210130212 82/09/30	50-313 S
8210120336	8210120334	82/09/24	71-9010	8210130215 8210130200 82/10/07	50-373 R
8210120340	8210120339	82/10/01	71-9037	8210130216 8210130204 82/10/04	50-280 S
8210120342	8210120338	82/09/22	CONTRACT	8210130222 8210130221 82/09/21	50-546 G
8210120350	8210120347	82/09/29	CONTRACT	8210130223 8210130220 82/09/20	50-364 B
8210120352	8210120349	82/09/24	71-9964	8210130225 8210130219 82/10/01	50-29 8
8210120353	8210120351	82/08/30	WASTE MOT	8210130227 8210130219 82/09/29	50-311 B
8210120357	8210120354	82/09/28	CONTRACT	8210130232 8210130228 82/10/01	50-336 B
8210120362	8210120361	82/10/05	CONTRACT	8210130235 8210130230 82/09/30	50-29 S
8210120364	8210120363	82/09/20	CONTRACT	8210130234 8210130234 82/09/30	50-373 S
8210120366	8210120365	82/09/16	CONTRACT	8210130244 8210130242 82/10/08	50-261 R
8210120384	8210120381	82/09/13	71-5908	8210130256 8210130249 82/10/07	50-537 A
8210120386	8210120379	82/08/20	WASTE MOT	8210130253 8210130251 82/09/30	50-254 B
8210120377	8210120392	82/09/24	50-331 F	8210130254 8210130252 82/10/07	50-309 P
8210120401	8210120391	82/09/30	CONTRACT	8210130258 8210130256 82/05/28	50-221 S
8210120417	8210120411	82/09/28	27-39	8210130263 8210130264 82/10/07	50-349 K
8210120422	8210120417	82/09/27	CONTRACT	8210130264 8210130264 82/10/07	50-329 K
8210120423	8210120416	82/10/03	50-389 M	8210130267 8210130264 82/10/07	50-329 K
8210120425	B210120414	82/09/30	CONTRACT	8210130274 8210130269 82/09/27	50-341 8
8210120432	8210120427	82/09/29	CONTRACT	8210130285 8210130278 82/09/30	50-341 8
8210120440	8210120436	82/09/27	CONTRACT	8210130286 8210130289 82/10/07	50-309 P
8210120458	8210120454	82/09/22	CONTRACT	8210130287 8210130257 82/10/06	50-389 E
8210120471	8210120467	82/09/24	CONTRACT	8210130296 8210130271 82/10/06	50-277 Q
8210120480	8210120475	82/09/30	50-62 P	8210130297 8210130294 82/10/07	50-358 A
8210120487	8210120475	82/09/30	50-62 P	8210130306 8210130302 82/09/29	50-54 P
8210120488	8210120483	82/09/29	CONTRACT	8210130309 8210130303 82/10/06	70-135
8210120492	8210120475	82/09/30	50-62 P	8210130315 8210130311 82/10/07	50-537 A
8210120494	8210120490	82/09/27	CONTRACT	8210130319 8210130310 82/10/01	50-302 8
8210120508	8210120497	82/09/10	CONTRACT	8210130328 8210190324 82/09/28	50-254 8
8210120517	8210120510	82/09/30	CONTRACT	8210130337 8210130335 82/10/07	50-247 0
8210120541	8210120534	82/09/30	CONTRACT	8210130342 8210130338 82/09/29	50-317 P
8210120550	8210120540	82/09/27	CONTRACT	8210130345 8210130340 82/09/29	50-311 8
8210120551	8210120546	82/09/24	50-254 F	8210130349 8210130344 92/10/04	50-267 R
6210120556	8210120549	82/09/30	CONTRACT	8210130350 8210130347 82/10/06	50-220 R
8210120560	8210120557	82/09/17	50-315 P	8210130358 8210130351 82/09/29	50-311 B
8210120565	8210120557	82/09/17	50-315 P	8210130361 8210130352 82/10/01	50-387 B
8210120590	8210120584	82/09/15	50-298 P	8210130362 8210130353 82/09/30	50-29 P
8210120604	8210120591	82/09/10	40-8745	8210130366 8210130356 82/09/28	50-346 S
8210120613 8210120624 8210120636 8210120640 8210120642	8210120607 8210120619 8210120627 8210120627 8210120627	82/09/27 82/09/20 82/09/23 82/09/23 82/09/23	CONTRACT 40~8781 50-341 A 50-341 A		50-309 P 50-387 S 50-341 Q 50-313 S 50-387 S
6210120645 8210120647 8210130005 8210130007 8210130014	8210120643 8210120643 8210130004 8210130004 8210130008	82/09/24 82/09/24 82/09/23 82/09/23 82/09/22	50-261 F 50-261 F 50-329 F 50-329 F CONTRACT	8210130498 8210130593 82710701 8210130403 8210130400 82709724 8210130408 8210130400 82709724	50~254 R 50~331 B 50~409 Q 50~409 G 50~346 B
8210130029	8210130024	82/09/20	50-416 P	8210130417 8210130411 82/09/28	50-366 8
8210130038	8210130024	82/09/20	50-416 P		50-409 0
8210130043	8210130024	82/09/20	50-416 P		50-247 8
8210130054	8210130052	82/09/23	CONTRACT		50-254 8
8210130061	8210130058	82/09/28	CONTRACT		50-460 0
8210130074 8210130080 8210130087 8210130103 8210130106	8210130071 8210130078 8210130075 8210130097 8210130101	82/09/28 82/09/17 82/09/28 82/10/06 82/09/28	CONTRACT XPORTLIC 50-289 T 50-317 Q 50-395 T	8210130431 8210130427 82/09/21 8210130432 8210130415 82/10/06 8210130438 8210130427 82/10/07	50-22 R 50-280 G 50-460 G 50-257 8 XPORTLIC
8210130112	8210130105	82/09/28	50-338 F	8230130452 8210130442 82/10/05	50-327 & 50-135 0 50-461 G 50-335 & 50-317 &
8210130114	8210130105	82/09/28	50-338 F	8210130457 8210130448 82/10/06	
8210130128	8210130124	82/09/30	50-346 S	8210130457 8210130451 82/10/06	
8210130132	8210130129	82/10/07	50-321 R	8210130454 8210130454 82/10/06	
8210130137	8210130133	82/10/01	50-331 8	8210130465 8210130461 82/09/30	
8210130145	821013013B	82/10/08	50-255 R	8210130471 8210130448 82/10/06	50-155 Q
8210130156	8210130146	62/09/30	50-255 9	8210130473 8210130466 82/09/30	50-254 B
8210130162	8210130157	62/10/07	50-296 8	8210130479 8210130467 82/10/01	50-361 B
8210130163	8210130160	82/09/30	50-184 R	8210130479 8210130472 82/09/30	50-293 B
8210130167	8210130165	62/10/07	50-259 8	8210130483 8210130477 82/10/04	50-325 B
8210130170 8210130176 8210130180 8210130184 8210130185	8210130164 8210130172 8210130177 8210130181 8210130183	82/09/29 82/10/07 82/10/01 82/10/06 82/09/28	50-311 8 50-259 8 50-369 8 50-461 0 50-366 8	8210130486 8210130417 82/10/05 8210130493 8210130469 82/10/01 8210130497 8210130489 82/10/04	50-341 8 50-529 0 50-341 8 50-325 8 70-1100

TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER		ACCESSION NUMBER		
PRINCIPAL DECUMENT IS	DATE SUBJECT SSUED CATEGORY	PRINCIP ENCLOSURE DOCUME	T ISBUED CATE	ECT CORY
8210130505 E210130474 E2/ E210130507 8210130500 E2/ 8210130508 E210130499 E2/ E210130511 8210130501 E2/	/10/08 50-329 /10/04 50-280 /09/30 50-361 /09/29 50-254 /09/30 50-331	8210150123 8210150 8 8210150128 8210150 8 8210150129 8210150 8 8210150132 8210150 9 8210150134 8210150	116 82/09/24 50-36 122 82/10/05 50-21 100 82/09/24 50-32 126 82/10/12 50-35	3 8 24 0 32 A
B2[0]30529	/09/24 50-313 /09/16 50-483 /09/29 50-289 /09/16 50-483 /10/01 50-302	B	135 81/07/07 50-22 131 82/09/23 50-26 146 81/03/27 50-25	9 6 9 9 5 5
8210130533 8210130510 82/ 8210130535 8210130527 82/ 8210130549 8210130541 82/	/10/01 50-29 /10/06 50-282 /10/08 50-364 /09/28 50-366 /09/29 PR	8 8210150158 8210150 8 8210150157 8210150 9 821015014 8210150 8 8210150170 8210150 8 8210150176 8210150	51	5 R 8 G
8210130557 8210130547 82/ 8210130558 8210130543 82/ 8210130559 8210130556 82/	/10/05 50-483 /08/04 50-461 /09/30 50-317 /10/06 50-247 /10/04 50-335	0 8210150178 8210150 0 8210150179 8210150 6 82(0150180 8210150 0 82(0150181 8210150 5 82(0150182 8210150	154 82/10/01 50-27 174 81/08/24 50-24 171 82/09/23 50-43	7 6 3 5
8210130569 8210130565 82/ 8210130573 8210130571 82/ 8210130577 8210130571 82/	/10/05 50-306 /10/05 50-259 /10/07 50-341 /10/07 50-341 /09/30 50-317	9 8210150188 8210150 8 8210150187 8210150 9 8210150194 8210150 9 8210150195 8210150 8 8210150201 8210150	71	18 Q 18 Q
8210130582 8210130571 82/ 8210130584 8210130583 82/ 8210130590 8210130585 92/	/10/05 50-328 /10/07 50-361 /10/06 50-320 /10/01 50-331 /09/02 CONTRACT	8 9210150204 9210150 P 8210150206 9210150 P 8210150207 9210150 8 8210150208 9210150 8210150217 9210190	168 82/10/12 50-32 171 82/09/23 50-43 199 82/09/27 50-33	12 T 18 0 14 S
8210150011 8210150005 82 8210150012 8210150004 82 8210150014 8210150008 82	/09/28 50-293 //09/24 30-416 //08/13 50-369 //09/30 30-324 //09/28 50-293	9 8210150223 8210150 9 8210150224 8210150 9 8210150230 8210150 9 8210150231 8210150 9 8210150232 8210150	214 82/09/27 50-31 209 82/10/04 50-39 225 82/10/05 50-33	17 Q 10 Q 27 Q
8210150017 8210150005 82, 8210150020 8210150005 82, 8210150021 8210150014 82,	/10/08 50-334 //07/24 50-416 //08/13 50-369 //09/24 50-369 //09/30 50-324	0 8210150235 8210150 0 8210150237 8210150 0 8210150237 8210150 0 8210150240 8210150 0 8210150241 8210150	225 82/10/05 50-32 229 82/09/17 70-27 168 82/10/12 50-32	27 G 7 22 T
8210150025 8210150006 82 8210150027 8210150005 82 8210150028 8210150005 82	7/09/24 50-416 1/08/13 50-369 1/09/24 50-416 1/09/24 50-416 1/09/24 50-416	Q 8210150245 8210150 6	68 82/10/12 50-33 209 82/10/04 50-39 249 82/10/08 50-28	22 T 70 G 32 G
8210150038 8210150036 82 8210150039 8210150035 81 8210150040 8210150008 82	7/09/30	Q 8210150257 8210150 Q 8210150258 8210150 8 8210150260 8210150 Q 8210150263 8210150 Q 8210150265 8210150	246 82/09/27 50-27 209 82/10/04 50-35 253 82/09/17 50-26	71 G 70 G
8210150048 8210150036 82 8210150049 8210150044 81 8210150052 8210150036 82	/03/25 50-324 2/10/05 50-324 1/10/08 50-237 2/10/05 50-324 2/09/30 50-322	8 8210150268 8210150 9 8210150267 8210150 8 8210150272 8210150 9 8210150274 8210150 9 8210150278 8210150	262 82/09/27 50-38 168 82/10/12 50-32 246 82/09/27 50-23	39 Q 22 T 71 Q
8210150063 8210150008 82 8210150065 8210150057 82 8210150066 8210150058 82	2/09/22 50-370 2/09/30 50-324 2/09/29 50-311 2/09/29 50-272 2/09/27 70-1113	B 6510120540 8510120 8 8510120582 8510120 9 8510120583 8510120 0 8510120581 8510120	271 82/10/07 50-30 209 82/10/04 50-30 280 81/06/08 50-30	13 G 70 G 20 S
8210150075 8210150071 82 8210150078 8210150072 82 8210150082 8210150072 82	2/10/04 50-348 2/09/29 50-272 2/10/04 50-348 2/10/04 50-348 2/10/05 50-289	Q 8210130272 8210130275 G 8210130276 6210130 G 8210130303 8210130303 G 8210130303 8210130303	288 82/10/05 50-32 27 <i>9</i> 82/10/12 50-32 29 <i>9</i> 82/09/27 50-27	24 Q 22 Q 77 Q
8210150084 8210150072 82 8210150089 8210150080 81 8210150091 8210150074 82	1/02/04 50-269 2/10/04 50-348 1/02/09 50-311 2/10/05 50-289 2/09/30 50-311	8 8210150307 8210150 9 8210150308 8210150 9 8210150307 8210150 9 8210150313 8210150 8 8210150315 8210150	291 81/02/27 50-32 279 82/10/12 50-32 306 82/10/08 50-4	24 B 22 Q 70 E
8210150102 8210150097 81 8210150103 8210150096 82 8210150106 8210150100 82	2/10/12 50-413 1/10/13 50-247 2/09/15 50-424 2/09/24 50-324 2/10/01 50-219	X 8210150316 8210150 8 8210150319 8210150 0 8210150320 8210150 2 8210150324 8210150 8 8210150326 8210150	306 82/10/08 50-43 077 82/07/30 50-3 277 82/10/12 50-33	70 E 11 B 22 G
8210150114 8210150108 82 8210150118 8210150109 82 8210150120 8210150100 82	2/09/24 50-324 2/09/24 50-324 2/09/29 50-311 2/09/24 50-324 2/09/29 50-272	Q 8210150330 8210150331 8210150331 8210150331 8210150333 8210150334 8210150334 8210150334 8210150334 8210150334 8210150334 8210150335 821015035	323 82/09/14 50-3: 329 82/10/06 50-3: 318 82/09/20 50-5:	70 a 21 p 18 a

ACCESSION	I NUMBER				ACCESSI	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEODS		ENGLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	
8210150337 8210150339 8210150343 8210150344 8210150344	8210 [50279 6210 [5031] 6210 [50322 8210 [50338 6210 [50322	82/10/12 82/09/30 82/10/11 82/10/11 82/10/11	50-322 50-311 50-341 50-344 50-341	0 5 0 4	8210180075 8210180075 8210180076 8210180076 8210180079	8210180070 8210180028 8210180070 8210180028 8210180070	62/10/06 62/08/20 62/10/06 62/08/20 62/10/06	50-206 FDIA 50-206 FDIA 50-206	P P
8210150350 8210150351 8210150352 8210150353 8210150355	8210150328 8210150279 8210150322 8210150347 8210150349	82/09/23 82/10/12 82/10/11 82/10/04 82/10/07	CONTRACT 50-322 50-341 50-382 50-390	G G A	8210180080 8210180081 8210180083 8210180085 8210180087	8210180028 8210180028 8210180074 8210180028 8210180082	82/08/20 82/08/20 82/10/07 82/08/20 82/10/07	FOIA FOIA 50~244 FOIA 50~244	P P
8210150358 8210150365 8210150368 8210150371 8210150373	8210150345 8210150279 8210150356 8210150361 8210150362	82/09/22 82/10/12 82/10/08 82/10/07 82/10/15	50-335 50-322 50-277 70-143 50-424	Q Q R	82101600B7 8210160070 8210160071 6210180072 8210160074	8210180082 8210180088 8210180088 8210180082	82/08/20 82/10/07 82/09/12 82/08/20 82/10/07	FOIA 50-244 50-286 FOIA 50-244	P R
8210150376 8210150377 8210150380 8210150386 8210150390	8210150361 8210150364 8210150361 8210150385 8210150381	82/10/07 82/10/11 82/10/07 82/09/28 81/08/24	70-143 50-263 70-143 50-263 50-262	P (1) (5)	8210160076 8210160078 8230160100 8240180102 82(0160105	8210180028 8210180028 8210180097 8210180028 8210180028	62/08/20 62/08/20 62/10/01 82/08/20 62/08/20	FOIA FOIA 50-10 FOIA FOIA	R
6210150393 6210150401 6210150402 6210150406 6210150408	8210150279 8210150396 8210150279 8210150279 8210150399	82/10/12 82/09/17 82/09/20 82/09/20 82/10/06	50-322 50-261 50-322 50-259 70-143	е е е	8210180107 8210180108 8210180107 8210180111 6210180113	8210180103 8210180028 8210180104 8210180028 8210180028	82/10/14 82/08/20 62/10/14 62/08/20 82/08/20	70-143 FOIA 50-416 FOIA FOIA	R
8210150410 8210150411 8210150413 8210150422 8210150437	8210150279 8210150405 8210150407 8210150279 8210150434	82/10/05 82/10/12 82/10/12 82/10/12	50-322 50-275 50-250 50-322 50-315	Q R P G P	8210180115 8210180114 8210180118 8210180121 8210180123	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20 82/10/05	FOIA FOIA FOIA FOIA 50-316	8
8210150457 8210150477 8210150495 8210150500 8210150502	8210150449 8210150473 8210150487 8210150364 8210150497	82/10/11 82/09/22 82/09/30 82/10/11 82/09/28	50-358 70-143 50-254 50-243 50-409	0 0 P 0	8210180125 8210180127 8210180129 8210180130 8210180132	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/10/05 82/08/20 82/08/20	FOIA FOIA 50-316 FOIA FOIA	8
8210150504 8210150509 8210150512 8210150517 8210150521	8210150364 8210150364 8210150499 8210150513 8210150513	82/10/11 82/10/13 82/10/08 82/10/08	50-263 50-263 50-528 6A999 0A999	P P G	8210180133 8210180136 8210180137 8210180137 8210180140	8210180124 8210180028 8210180131 8210180028 8210180028	82/09/22 82/08/20 82/10/04 82/08/20 82/08/20	50-317 FOIA 50-346 FOIA FOIA	р В
8210150522 8210150526 8210150527 8210150528 8210150530	8210150518 8210150513 8210150279 8210150519 8210150523	82/10/07 82/10/08 82/10/12 82/10/04 82/09/28	50-369 GA999 50-322 50-287 50-10	F G P G	8210180145 8210180146 8210180150 8260180153 8210180153	6210 (80028 6210 180142 6210 180028 6210 180028 6210 180149	82/08/20 82/10/14 82/08/20 82/08/20 82/10/08	F01A 50-454 F01A F01A 50-244	o P
8210150535 8210150536 8210150538 8210150540 8210150540	8210150519 8210150532 8210150523 8210150532 8210150539	82/10/06 82/10/08 82/09/28 82/10/08 82/10/01	50-287 GA979 50-10 GA999 50-10	P G G	8210180157 8210180159 8210180159 8210180141 8210180142	8210180028 8210180149 8210180028 8210180149 8210180156	82/08/20 82/10/08 82/10/08 82/10/08	FO1A 50-244 FO1A 50-244 50-295	P P
6210150544 6210150604 6210150607 6210150615 6210150616	8210150532 8210150594 8210150605 8210150607 8210150594	82/10/08 82/09/30 82/09/01 82/08/31 82/09/30	GAPP9 50-315 70-1739 40-2259 50-315	F	8210180143 8210180144 8210180148 8210180171 8210180173	8210180154 8210180028 8210180028 8210180028 8210180028	82/10/13 82/08/20 82/08/20 82/08/20 82/08/20	50-359 FOIA FOIA FOIA FOIA	A
6210150649 6210150648 6210180007 6210180008 6210180026	8210150621 8210150621 8210180004 8210180006 8210180025	82/09/30 82/09/30 82/10/12 82/10/12 82/09/23	50-244 50-244 50-349 50-445 50-346	F G K P	8210180175 8210180176 8210180179 8210180191 8210180194	8210 180147 8210 180028 8210 180028 8210 180186 8210 180028	82/10/07 82/08/20 62/08/20 82/10/05 82/08/20	50-304 FOIA FOIA 50-255 FOIA	5
8210180030 8210180032 8210180034 8210180036 8210180038	6210180028 6210180028 6210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA		8210180197 8210180199 8210180200 8210180201 8210180208	8210180028 8210180194 8210180028 8210180195 8210180204	82/08/20 82/10/12 82/09/20 82/09/20	FOIA 50-10 FOIA 50-312 50-352	P P G
8210180040 8210180042 8210180043 8210180046	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA		8210180213 6210180215 8210180217 8210180225 8210180225	6210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20 82/09/27	FOIA FOIA FOIA FOIA 50-352	٥
8210180049 8210180051 8210180054 8210180057 8210180058	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA FOIA		8210180229 8210180234 6210180239 8210180247 8210180248	8210180058	62/09/20 62/08/20 62/08/20 62/08/20 62/09/23	F01A F01A 50-244 F01A 50-528	P A
8210180060 8210180061 8210180064 8210180066 8210180072	8210180055 8210180028 8210180028 8210180028 8210180028	82/10/08 82/08/20 82/08/20 82/08/20 82/08/20	50-269 FOIA FOIA FOIA FOIA	P	8210180251 8210180257 8210180266 8210180266	8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA FOIA	

ACCESSID:	NUMBER			ACCE8810			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT Category
8210180270 8210180275 8210180277 8210180282 8210180284	8210180028 8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA FOIA	8210180427 8210180428 8210180429 8210180430 8210180431	8210 180028 8210 180028 8210 180028 8210 180028 8210 180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA
8210180287 8210180295 8210180298 8210180298	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA	8210180432 8210180433 8210180434 6210180435 8210180436	8210180028 8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA
8210180304 8210180307 8210180310 8210180312 8210180315	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA FOIA	8210170002 8210170004 8210170010 8210170016 8210170017	8210190001 8210190003 8210190005 8210190013 8210190013	82/09/29 82/09/20 82/09/23 82/09/29 82/09/29	CONTRACT CONTRACT CONTRACT 50-321 F 50-321 F
8210180318 8210180319 8210180324 8210180326 8210180328	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA FOIA	8210190024 8210190025 8210190026 8210190029 8210190037	8210170020 8210170018 8210170020 8210170022 8210170030	82/10/01 82/09/30 82/10/01 82/10/05 82/09/28	50-344 F CONTRACT 50-344 F 50-271 S CONTRACT
8210180332 8210180333 8210180335 8210180337 8210180338	8210180327 8210180028 8210180028 8210180028 8210180329	82/09/30 82/08/20 82/08/20 82/08/20	CONTRACT FOIA FOIA CONTRACT	8210170040 8210170046 8210170051 8210170058 8210170063	8210170036 8210170042 8210170042 8210170050 8210170057	82/10/01 82/10/01 82/10/01 82/10/05 82/09/22	50~315 F 50~321 F 50~321 F 50~373 B CONTRACT
8210180340 8210180341 8210180343 8210180344 8210180346	8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA FOIA	8210170073 8210170077 8210170087 8210170095 8210170103	8210190066 8210190069 8210190076 8210190092 8210190097	82/10/01 82/10/07 82/09/24 82/09/30 82/09/29	50-348 F 50-330 S CONTRACT REVIEW GRP 50-369 F
8210180347 8210180348 8210180347 8210180351 8210180352	8210180028 8210180329 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA CONTRACT FOIA FOIA FOIA	8210190105 8210190108 8210190115 8210190121 8210190124	8210190102 8210190097 8210190112 8210190112 8210190112	82/09/30 82/09/29 82/10/06 82/10/06	CONTRACT 50-369 F FDIA FOIA FOIA
8210180353 8210180354 8210180358 8210180359 8210180360	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	F01A F01A F01A 40-8786 F01A	8210170141 8210170152 8210170154 8210170156 8210170161	8210170132 8210170144 8210170145 8210170147 8210170145	82/09/23 82/09/29 82/09/30 82/09/29	CONTRACT FO1A 50-269 P CONTRACT 50-269 P
8210180362 8210180363 8210180366 8210180367 8210180370	8210180357 8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	CONTRACT FOIA FOIA FOIA FOIA	8210170166 8210170167 8210170167 8210170173 8210170177	8210170158 8210170162 8210170145 8210170158 8210170172	82/09/28 82/09/30 82/09/29 82/09/28 82/09/21	50~387 F CONTRACT 50~269 P 50~307 F CONTRACT
8210180371 8210180372 8210180373 8210180374 8210180374	8210180345 8210180028 8210180028 8210180028	82/09/29 82/08/20 82/08/20 82/08/20	CONTRACT FOIA FOIA FOIA	8210190182 8210190185 8210190186 8210190191 8210190194	8210190179 8210190180 8210190178 8210190189 8210190178	82/09/29 82/09/30 82/09/30 82/09/30	CONTRACT 50-320 F 50-250 F FOIA 50-250 F
				8210170178 8210170204 8210170207 8210170215 8210170223	8210280402 8210170177 8210170177 8210170210 8210170217	82/09/30 82/09/15 82/09/15 82/09/30 82/09/30	FOIA 50-440 F 50-440 F CONTRACT CONTRACT
				8210190231 8210190237 8210190244 8210190256 8210190261	8210190228 8210190235 8210190240 8210190246 8210190254	82/10/14 82/10/01 82/10/11 82/09/03 82/10/07	50-312 Q 50-293 B 50-261 B 40-299 50-346 B
				8210190270 8210190277 8210190282 8210190285 8210190287	8210190264 8210190266 8210190274 8210190278 8210190266	82/10/12 82/10/12 82/10/04 82/10/13 82/10/12	50-338 8 50-315 8 50-334 8 50-312 R 50-315 S
				8210190293 8210190296 8210190317 8210190323 8210190328	8210190269 6210190290 8210190309 6210190309 6210190309	82/10/08 82/10/08 82/10/08 82/10/08	50-243 B 50-317 B 50-361 B 50-361 B
				8210190337 8210190339 8210190342 8210190346 8210190349	8210190329 8210190230 8210190340 8210190344 8210190347	82/10/12 82/09/30 82/10/12 82/10/04 82/09/22	50-338 8 CONTRACT 50-315 8 50-373 8 50-285 0
				8210190355 8210190356 8210190359 8210190361 8210190362	8210190353 8210190353 8210190358 8210190360 8210190360	82/10/11 82/10/11 82/10/11 82/10/05 82/10/05	50-305 Ø 50-305 Ø 50-346 Ø 50-331 Ø 50-331 Ø

ACCESSION	NUMBER					ION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO		ENCLOSURE	PRINCIPAL	DATE ISSUED	CATEGO	
8210190348 8210190372 8210190374 8210190386 8210190389	8210170366 8210170369 8210170371 8210170378 8210170380	82/09/28 82/10/14 82/10/12 82/10/14 82/10/13	50-397 QA999 50-335 50-327 50-315	e F B B	821019065 821019065 821019066 821019066 821019069	8 8210190669 8 8210190665 8 8210190676 8 8210190677	82/10/04 82/10/01 82/10/01 82/10/08 82/10/15	50-266 50-397 50-315 50-302 50-29	G R B P
8210190398 8210190404 8210190412 8210190415 8210190419	8210190375 8210190380 8210190403 8210190380 8210190413	82/10/12 82/10/13 82/10/06 82/10/13 82/09/28	50-219 50-315 50-249 50-315 50-498	8 8 9	821017045 821017070 821017070 821017070 821017070	0 8210190658 2 8203050387 6 8210190701	82/10/04 82/10/04 82/02/16 82/10/06 82/10/04	50-373 50-254 50-317 50-247 50-255	9 0
8210190420 8210190424 8210190427 8210190428 8210190429	8210190411 8210190417 8210190421 8210190411 8210190422	82/10/15 82/10/13 82/09/29 82/10/15 82/10/12	50-333 50-416 50-255 50-333 50-282	0 8 0 9	821014071 821014071 821014072 821014072 821014073	5 8210190689 0 8210190709 3 8210190722	82/02/16 82/10/05 82/10/14 82/10/12 82/10/06	50-317 50-295 50-261 50-348 50-344	0 8 P R 0
8210170435 8210170437 8210170437 8210170444 8210170447	8210190411 8210190431 8210190432 8210190352 8210190421	82/10/15 82/09/30 82/10/07 82/10/12 82/09/29	50-333 50-382 50-282 50-375 50-255	0 0 p 0	821019073 821019074 821019074 821019074 821019074	8210190727 8210190731 8210190737	92/10/12 92/10/08 92/10/04 92/10/07 92/10/08	50-284 50-316 50-344 50-373 50-306	8 6 8
8210190452 8210190454 8210190455 8210190457 8210190466	8210190431 8210190448 8210190450 8210190352 8210190019	02/07/30 82/10/11 02/10/13 02/10/12 02/10/06	50-382 50-409 50-361 50-395 50-322	G S Q P A	821019075 821019075 821019075 821019075	0 8210190739 1 8210190742 7 8210190749	82/10/12 92/10/06 82/10/15 92/10/07 82/10/15	50-285 50-329 50-349 50-315 50-324	RGRB
8210190471 8210190476 8210190481	8210190462 8210190458 8210190472 8210190462 8210190483	82/09/29 82/10/05 82/10/06 82/09/29 82/10/08	50-373 50-249 50-336 50-373 50-295	9 5 6 8 9	821019076(821019076) 821019076(821019076(821019077)	8210190725 8210190754 8210190756	82/10/12 82/10/01 82/10/08 82/09/27 82/09/27	50-254 QA799 50-324 QA999 50-440	F 8 0
8210190500 8210190501 8210190503	8210190487 6210190492 8210190478 6210190498 6210190490	82/09/29 82/10/15 82/10/05 82/09/29 82/10/04	50-373 50-375 50-361 50-373 50-204	5 9 6 8	8210190773 8210190784 8210190783 8210190783 8210190803	8210190772 8210190780 8210190763	82/10/12 82/10/01 82/10/12 82/07/27 82/10/12	50-364 50-445 50-254 50-440 50-317	Rapag
8210190511 8210190514 8210190515	8210190505 8210190504 8210190509 8210190507 8210190497	82/10/12 82/10/05 82/09/29 82/10/05 82/09/28	50-395 50-366 50-373 50-272 50-313	P 8 8 9	8210190620 821020000 821020000 8210200015 8210200015	8210200001 8210200002	82/07/27 82/10/15 82/07/29 82/10/15 82/10/10	50-445 70-143 50-373 50-400 50-311	Q B Q R
8210190525 8210190526 8210190533 8210190537 8210190543	8210190522 8210190517 8210190530 8210190531 8210190537	82/09/29 82/10/07 82/10/12 82/09/22 82/10/08	50-373 50-313 State Pr 50-285 50-247	S 0 0 8	9210200031 8210200034 8210200035 8210200035 8210200042	8510500058 8510500059 8510500018	82/10/15 82/02/03 82/10/13 82/10/15 82/10/13	50-440 50-333 50-443 50-333 50-443	0 2 0 2 0
6210190552 8210190554 8210190558 8210190567 8210190569	6210190544 6210190549 6210190545 6210190561 6210190562	82/10/15 82/10/01 82/10/06 82/10/13 82/09/28	50-269 50-344 50-368 50-416 50-397	R Q S G	8210200045 8210200045 8210200065 8210200066 8210200083	9210200024 9 8210200044 9 8210200046	82/10/06 82/10/13 82/10/15 82/10/15 82/10/12	50-280 50-443 50-277 50-277 50-322	P 0 P 0
8210190573 8210190577 8210190578 8210190579 8210190582	8210190536 8210190570 8210190572 8210190568 8210190576	82/10/08 82/10/13 82/10/08 82/07/30 82/10/04	50-373 50-320 50-315 50-295 50-397	S P S O E	9210200084 8210200094 821020094 8210200104	9 8210200074 9 8210200085 8 8210200093	82/10/15 82/10/12 82/10/10 82/10/13	50-400 50-322 50-272 50-331 70-820	G Q R R
8210190586 8210190586 8210190591 8210190598 8210190599	8210190576 8210190572 8210190580 8210190594 8210190548	82/10/04 82/10/08 82/10/07 82/09/28 82/09/30	50-397 50-315 50-244 50-312 50-295	E G P Q	8210210016 8210210016 821021003 8210210046 8210210046	8210210015 8210210036 8210210033	82/10/07 82/10/12 82/08/30		
8210190601 8210190602 8210190603 8210190608 8210190612	B2101905B9 B210190595 B210190594 B210190596 B210190605	82/09/29 82/10/05 82/09/28 82/09/22 82/09/30	50-373 50-366 50-312 50-482 50-312	0 8 9 0	821021005: 821021005 821021005 821021006:	5 5 3			
8210170614 8210170615 8210170618 8210170624 8210170626	8210190609 8210190604 8210190580 8210190613 8210190617	82/10/08 82/10/11 82/10/07 82/10/07 82/10/05	50-348 50-255 50-244 50-295 50-295	8 9 9	821021007 821021008 821021008 821021008 821021009	2			
8210170528 8210170636 8210170637 8210170647 8210170647	8210190620 8210190632 8210190580 8210190580 8210190639	82/10/11 82/10/01 82/10/07 82/10/07 82/10/11	50-255 50-27 50-244 50-244 50-255	8 0 0 8	821021011 82102101 82102101 821021011 821021011				
8210190654 8210190664 8210190667 8210190668 8210190674	8210 190638 8210 190643 8210 190655 8210 190663 8210 190666		50-409 50-331 50-267 50-213 50-325	0 R P B	85105(011 85105(011 85105(011 85105(011)				

TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION	NUMBER			
PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188VED	SUBJECT CATEGORY	Y
8210210161	82/09/29 82/10/05 82/09/20 82/10/20 82/10/07	CONTRACT 50-272 CONTRACT 50-320 50-245	a	8210220092 8210220097 8210220100 8210220108 8210220116	8210220064 8210220095 8210220095 8210220103 8210220112	82/10/01 82/10/14 82/10/14 82/10/13 82/10/15	40-8111 50-280 50-280 50-245 50-245	5556
8210210197 8210210187 8210210200 8210210185 8210210206 8210210174 8210210213 8210210201 8210210214 8210210204	82/10/19 82/09/15 82/10/15 82/10/06 82/10/12	50-413 50-271 50-13 50-244 50-271	G P Q Q B	8210220125 8210220128 8210220132 8210220134 8210220137	8210220122 8210220123 8210220127 8210220130 8210220127	82/10/14 82/09/28 82/10/12 82/10/14 82/10/12	50-498 40-1142 50-400 50-298 50-400	@ @ @
8210210223 8210210216 8210210236 8210210231 8210210238 8210210221 8210210240 8210210232 8210210248 8210210241	82/10/15 82/10/06 82/10/04 82/10/19 82/10/06	70~1201 50~334 50~271 50~537 50~423	0 0 0 0	9210220141 8210220145 8210220147 8210220150 8210220157	8210220127 8210220127 8210220139 8210220131 8210220153	82/10/12 92/10/12 82/10/04 82/10/18 92/10/15	50-400 50-400 50-324 50-416 50-29	0 0 0 8
8210210261 8210210241 8210210264 8210210255 8210210293 8210210285 8210210397 8210210285 8210210301 8210210294	82/10/06 82/10/06 82/10/11 82/09/29 82/10/19	50-423 50-220 50-387 50-287 50-329	Q Q E P A	8210220159 8210220162 8210220163 8210220165 8210220171	8210220155 8210220158 8210220160 8210220161 8210220161	82/09/29 82/10/08 82/10/04 82/09/27 82/09/27	50-424 50-416 50-400 40-2259 40-2259	0 0
8210210306 8210210274 8210210307 8210210303 8210210316 8210210313 8210210321 8210210313 8210210337 8210210337	82/10/19 82/10/07 82/10/07 82/10/07 82/10/08	50-329 50-247 50-309 50-309 50-522	8 G G	8210220172 8210220173 8210220174 8210220179 8210220183	6210220166 8210220169 8210050398 8210220177 6210220180	82/10/08 82/10/04 82/09/23 82/10/14 82/06/28	70-371 50-324 50-447 70-371 50-438	Ø A
8210210342 8210210341 8210210347 8210210346 8210210358 8210210351 8210210368 8210210351 8210210368 8210210363	82/10/15 82/10/18 82/10/15 82/10/15 82/10/18	70-27 50-454 50-440 50-440 50-498	0 0 0 0	8210220187 8210220188 8210220189 8210220191 8210220191	8210220182 8210220185 8210220180 8210220181 8210220190	82/10/12 82/10/13 82/06/28 82/10/08 82/10/15	50-219 TOPREP 50-438 50-416 50-277	Q S R
6210210397 6210210390 6210210400 8210210391 8210210403 8210210395 6210210410 8210210395 8210210411 8210210407	82/10/18 82/10/18 82/09/30 82/09/30 82/10/14	50-247 50-358 50-305 50-305 50-269	G G P P P	8210220199 8210220201 8210220208 8210220211 8210220213	8210220176 8210220175 8210220204 8210220204 8210220204	82/10/07 82/10/15 82/10/15 82/10/15 82/10/15	50-416 50-245 50-424 50-424 50-424	8 0 0
8210210430 8210210425 8210210434 8210210428 8210210436 8210210438 8210210444 8210210438 8210210444 8210210440	82/10/12 82/10/15 82/10/11 82/09/28 82/10/08	50-245 50-289 50-387 CONTRACT 50-387	8 T s	8210220218 8210220222 8210220232 8210220234 8210220241	8210220204 8210220219 8210220229 8210220227 8210220239	82/10/15 82/10/07 82/10/04 82/10/07 82/10/20	50-424 50-321 50-348 50-338 50-498	0 9 9 A
8210210448 8210210437 8210210451 8210210435 8210210457 8210210328 8210210469 8210210464 8210210470 8210210459	82/10/14 82/10/06 82/10/15 82/10/06 82/10/18	70-2116 50-272 50-317 50-272 50-286	Q R Q P	8210220244 8210220299 8210220262 8210220264 8210220267	8210220198 8210220259 8210220259 8210220260 8210220265	82/10/18 82/10/18 82/10/06 82/10/13 82/10/06	50-528 50-482 50-416 70-687 50-261	R A B
8210210473 8210210457 8210210477 8210210444 8210210505 8210210502 8210210512 8210210508 8210210525 8210210521	82/10/18 82/10/06 82/09/29 82/10/05 82/09/30	50-286 50-272 CONTRACT 50-373 40-3453	P a T	8210220271 8210220274 8210220276 8210220279 8210220281	8210220237 8210220269 8210220268 8210220268 8210220270	82/10/15 82/10/18 82/10/20 82/10/20 82/10/05	50-438 50-414 50-537 50-537 50-313	0 0 0 0
8210210534 8210210532 8210210543 8210210549 8210210545 8210210544 8210210550 8210210548 8210210551 8210210544	82/09/30 82/06/21 82/09/23 82/09/20 82/09/23	40-8481 70-2955 50-317 50-346 50-317	P F	8210220282 8210220283 8210220284 8210220287 8210220288	8210220278 8210220268 8210220280 8210220277 8210220268	82/10/18 82/10/20 82/10/15 82/10/14 82/10/20	50-416 50-537 50-335 50-321 50-537	8 0
8210210552 8210210545 8210210553 8210210548 8210210555 8210210545 8210210555 8210210548 8210210559 8210210548	82/09/30 82/09/20 82/09/30 82/09/20 82/09/20	50-29 50-346 50-29 50-346 50-346	P P P P	8210220289 8210220291 8210220292 8210220293 8210220293	8210220284 8210220280 8210220277 8210220248 8210220280	82/10/18 82/10/15 82/10/14 82/10/20 82/10/15	50-416 50-335 50-321 50-537 50-335	8 6 6
8210210570 8210210544 8210210581 8210210574 8210210594 8210210584 8210220007 8210220006 8210220017 8210220015	92/09/30 92/09/30 92/09/30 92/10/19 92/10/08	CONTRACT CONTRACT CONTRACT 50-278 50-293	r	8210220278 8210220279 8210220303 8210220304 8210220307	8210220270 8210220277 8210220280 8210220296 8210220277	82/10/15 82/10/14 82/10/15 82/10/08 82/10/14	50-366 50-321 50-335 50-250 50-321	P 0 0 0
8210220027 8210220020 8210220028 8210220023 8210220048 8210220047 8210220056 8210220052 8210220057 8210220053	82/09/30 82/09/29 82/09/17 82/10/15 82/10/08	50-334 70-1257 NUREO 50-302 50-259	P 8 8	8210220310 8210220317 8210220317 8210220320 8210220323	8210220294 8210220294 8210220312 8210220308 8210220315	82/10/08 82/10/08 82/10/14 82/10/15 82/09/30	50-250 50-250 50-140 70-1113 50-370	Q G G
B210220062 B21022005B B210220064 B210220060 B210220067 B210220065 B210220070 B210220066 B210220074 B210220066	82/10/08 82/10/14 82/10/11 82/10/01 82/10/01	50~328 50~336 50~416 40~8111 40~8111	8 6 9	8210220325 8210220327 8210220329 8210220330 8210220337	8210220312 8210220318 8210220276 8210220312 8210220328	82/10/14 82/10/15 82/10/08 82/10/14 82/09/29	50-140 50-369 50-250 50-160 50-370	8 0 0
8210220077 8210220066 8210220080 8210220086 8210220086 8210220081 8210220086 8210220066 8210220089 8210220066	82/10/01 82/10/01 92/10/08 82/10/01 62/10/01	40-8111 40-8111 50-327 40-8111 40-8111	S	8210220341 8210220344 8210220352 8210220354 8210220357	8210220312 8210220340 8210220344 8210220331 8210220331	82/10/14 82/10/15 82/10/13 82/10/04 82/10/20	50-160 50-395 50-244 50-280 50-387	0 0 8

ACCESS10	NUMBER				ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEOD		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGO	RY
8210220369 8210220369 8210220374 8210220385 8210220388	8210220344 8210220363 8210220367 8210220378 8210220384	82/10/13 82/10/20 82/10/13 82/10/15 82/09/28	50-244 50-275 50-352 50-318 50-321	9 4 0 4 8	6210250184 6210250194 8210250198 8210250201 8210250212	8210250181 8210250172 8210250175 8210250177 8210250208	82/10/04 82/10/01 82/07/23 82/10/08 82/08/30	TOPREP 50-133 50-341 50-275 50-338	R F R F
8210220398 8210220401 8210220405 8210220406 8210220408	8210220392 8210220396 8210220387 8210220387	82/10/08 82/10/19 82/10/12 82/10/08	50-280 50-259 50-440 50-439 50-280	9 9	8210250218 8210280227 8210250231 8210250232 8210250253	8210250214 8210250222 8210250226 8210250224 8210250248	82/10/15 82/10/18 82/10/14 82/10/04 82/10/20	50-361 50-341 50-345 50-461 50-483	5 6 6 0
8210220413 8210220417 8210220418 8210220421 8210220422	8210220392 8210220407 8210220411 6210220415 8210220387	82/10/08 82/10/05 82/10/12 82/10/07 82/10/12	50-280 0A999 50-271 50-339 50-438	0 9	6210250261 6210250264 6210250264 8210250273 6210250273	8210250251 8210250258 8210250254 8210250249 8210250256	82/10/11 82/10/13 82/10/19 82/10/15 82/10/19	50-331 50-266 50-387 50-361 50-387	8 P 8 P
8210220430 8210220430 8210220431 8210220432 8210220435	8210220420 8210220420 8210220428 8210220387 8210220424	92/10/12 92/10/12 92/10/18 92/10/12 82/10/07	70~1113 70~1113 50~414 50~438 50~281	9 0 5	8210250278 8210250279 8210250296 8210250297 8210250297	8210250268 8210250270 8210250283 8210250286 8210250272	82/10/12 82/10/12 82/10/14 82/10/07 82/10/13	50-237 50-346 50-237 50-346 50-368	8 8 0 8
8210220437 8210220442 8210220443 8210220446 8210220448	8210220420 8210220420 8210220438 8210220387 8210220439	82/10/12 82/10/12 82/10/15 82/10/12 82/10/19	70-1163 70-1113 50-395 50-439 50-170	s q o	8210250300 8210250314 8210250327 8210250332 6210250333	8210250287 8210250304 8210250323 8210250323 8210250323	82/10/11 82/09/22 82/10/18 82/10/21 82/10/18	50-331 50-249 50-135 50-289 50-155	8 8 9 9
8210220450 8210220461 8210220462 8210220466 8210220471	8210220441 8210220454 8210220458 8210220459 8210220457	82/10/07 82/10/04 82/10/08 82/10/18 82/07/29	50-339 50-338 50-414 50-390 50-413	8 8 9 9	8210250337 8210250339 8210250342 8210250343 8210250348	8210250323 8210250330 8210250336 6210250334 8210250328	82/10/18 82/10/19 82/10/07 82/10/15 82/09/22	50-155 50-375 50-331 50-244 50-249	P Q B S
8210220474 8210220476 8210220480 8210220482 8210220485	8210220469 8210220464 8210220469 8210220469 8210220469	82/10/18 82/09/27 82/10/18 82/10/18 82/10/18	50-327 40-6622 50-327 50-327 50-327	Q Q Q	8210250350 8210280352 8210280361 8210250372 8210250373	8210250334 8210250344 8210250351 8210250363 8210250367	82/10/07 82/10/15 82/10/08 82/10/20 82/10/17	50-331 50-266 50-528 50-213 50-387	0 8 9 P
8210220492 8210220494 8210220496 8210220499 8210220500	6210220489 6210220489 6210220489 6210220495 6210220495	82/10/18 82/10/18 82/10/18 82/10/18	50~324 50-324 50-324 50-261 50-261	0 0	8210250375 8210250376 8210250377 6210250380 8210250385	8210250351 8210250364 8210250367 8210250367 8210250381	82/10/09 82/10/15 82/10/14 82/10/19 82/10/14	50-528 50-292 50-397 50-397 50-397	0 8 8 P 8
8210220501 8210220503 8210220504 8210250008 8210250021	8210220495 8210220489 8210220495 8210250006 8210250019	82/10/18 82/10/18 82/10/18 82/08/27 82/07/30	50-261 50-324 50-261 40-8681 40-299	0 0	8210250387 8210250387 8210250370 8210250372 8210250372	8210250384 8210250382 8210250384 8210250168 8210250340	92/10/12 92/10/06 92/10/15 92/10/06 92/10/04	50-331 50-311 50-312 50-275 50-315	8 8 8 8 8
8210250033 8210250050 8210250051 8210250056 8210250057	8210250030 8210250048 8210250048 8210250054 8210250053	82/09/30 82/09/21 82/09/21 82/08/27 82/10/06	NUREQ 50-335 50-335 40-8402 50-311	Р Р	8210250394 8210250395 8210240010 8210240011 8210240012	8210250340 8210250340 8210260008 8210260009 8210260008	82/10/04 82/10/04 82/10/05 82/08/30 82/10/05	50-315 50-315 50-302 70-2968 50-302	P F F
8210250059 8210250061 8210250070 8210250074 8210250075	821025005B 8210250060 8210250067 8210250067 8210250072	82/10/19 82/10/21 82/10/15 82/10/15 82/10/07	50-322 70-143 50-260 50-260 50-341	P P G	6210240014 8210240018 8210240041 8210240049 8210240080	8210260013 8210260017 8210260038 8210260038 8210260079	82/09/30 82/09/31 82/09/02 82/09/02	40-6622 40-8685 70-820 70-820 40-3453	
8210250077 8210250078 8210250080 8210250093 8210250095	8210250067 8210250067 8210250072 8210250084 8210250088	82/10/15 82/10/15 82/10/07 82/10/11 82/10/15	50-260 50-260 50-341 50-344 50-318	P 0 6 8	1900620128 710260128 110260129 110260129 110261128	8210260086 8210260096 8210170764 8210260116 8210260115	82/06/09 82/08/26 82/10/07 82/10/18 82/10/17	WASTE AV 40-8781 50-397 50-250 50-373	710 A 8 8
8210250097 8210250101 8210250109 8210250113 8210250116	8210250092 8210250094 8210250105 8210250110 8210250105	82/10/12 82/10/15 82/10/07 82/10/12 82/10/07	50-219 50-259 50-373 50-70 50-373	P P 0 P 0	8210260123 8210260125 8210260127 8210260127	8210260126 8210260122 8210260122 8210260122	52/10/15 52/10/08 52/10/05 52/10/05 52/10/05	50-368 50-334 06799 50-334 08799	g F
6210250126 6210250128 6210250140 6210250141 6210250149	8210250114 6210250121 8210250137 8210250135 8210250135	82/10/18 82/10/20 82/10/20 82/10/20	50-254 QA999 50-361 QA999 50-247	P 6 8	8210240134 8210240146 8210240146 8210240147 8210240147	8210260133 8210260134 8210260159 8210260163	82/10/13 82/10/13 82/10/25 82/10/21	50-338 50-322 50-395 50-334 50-29	P 0 P 8
8210250153 8210250161 8210250163 8210250163	9210250148 8210250154 8210250159 8210250152 8210250155	82/10/07 82/10/13 82/10/15 82/10/15 82/10/18	50-254 50-317 50-368 50-373 50-254	8 P B P	8210240175 8210240180 8210240183 8210240183 8210240184	8210260170 8210260178 8210260174 8210260177 8210260182	82/10/19 82/10/19 82/10/18 82/10/21 82/10/15	50-333 50-313 50-255 50-220 50-219	8 9 9
8210250171 8210250175 8210250177 8210250178 8210250183	8210250167 8210250164 8210250155 8210250173 8210250173	62/10/08	50-275 50-344 50-254 50-362 50-282	P 9 9 9	8210240187 8210240191 8210240195 8210240196 8210240194	8210260182 8210260182 8210260170 8210260188 8210260173	82/10/13 82/10/15 82/10/20 82/10/20 82/10/16	50-219 50-219 50-329 50-328 50-309	9 0 8

ACCESS 10					ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGOR	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJECT CATEGORY	,
8210260208 8210260221 8210260222 8210260223 8210260225	8210240179 8210260210 8210260212 8210260217 8210260203	82/10/18 92/10/18 82/10/20 82/10/19 82/10/14	50-309 50-373 50-259 50-304 50-334	8 8 8 8	8210260330 8210260538 8210260548 8210260547 8210260547	8210260525 8210260535 8210260526 8210260535 8210260543	82/09/28 82/09/24 82/10/06 82/09/24 82/09/01	CONTRACT 50-320 50-10 50-320 40-8027	Р Р
8210260230 8210260234 8210260236 8210260238 8210260239	8210260224 8210260224 8210260225 8210260227 8210260232	82/10/12 82/10/18 82/10/18 82/10/18	50-72 50-72 50-320 50-373 50-322	R R O B T	8210260552 8210260558 8210260550 8210260561 8210260561	8210260535 8210260494 8210260557 8210260559 8210260568	82/09/24 82/10/12 82/09/03 82/09/28 82/08/30	50-320 0A979 40-B102 CONTRACT 70-143	Þ
8210260240 8210260242 8210260246 8210260247 8210260254	8210250237 8210250232 8210250232 8210250231 8210250233	82/09/27 82/10/12 82/10/12 82/10/01 82/10/20	CONTRACT 50-322 50-322 50-387 50-295	T Q S	9210260575 8210260579 8210260579 8210270009 8210270020	8210260572 8210260572 8210260581 8210270009 8210270015	82/10/0B 82/10/08 82/09/16 82/10/12 82/10/22	50-440 50-440 50-201 50-307 50-537	F F O G O
8210260257 8210260263 8210260265 8210260266 8210260270	8210260241 8210260260 8210260245 8210260255 8210260241	82/10/01 82/10/18 82/10/22 82/10/18 82/10/01	50-387 50-305 50-327 50-325 50-387	9 8 9 9	9210270023 9210270033 8210270035 8210270041 9210270051	8210270015 6210270027 6210270015 8210270015 6210270046	82/10/22 82/10/12 82/10/22 82/10/23 82/10/18	50-537 CONTRACT 50-537 50-537 50-447	G G C A
8210260280 8210260284 8210260287 8210260273 8210260277	8210260278 8210260282 8210260281 8210260270 8210260275	82/09/24 82/09/29 82/10/19 82/10/19 82/10/19	CONTRACT CONTRACT 50-337 50-338 50-373		8210270052 8210270050 8210270060 8210270064 8210270068	8210270015 8210270015 8210270015 8210270015 8210270015	82/10/22 82/10/22 82/10/22 82/10/22	50-537 50-537 50-537 50-537 50-537	0000
8210240301 8210240310 8210240313 8210240314	8210260298 8210260307 8210260309 8210260311 8210260315	82/10/22 82/10/22 82/10/22 82/10/18 82/10/22	50-298 50-454 50-302 50-373 50-155	9 9 9	8210270049 8210270070 8210270079 8210270081 8210270085	6210270015 6210270067 6210270074 6210270077 6210270074	82/10/22 82/09/03 82/09/07 82/09/14 82/09/07	50-537 70-687 71-6639 40-2061 71-6639	o
8210260318 8210260321 8210260325 8210260326 8210260337	8210260269 8210260317 8210260323 8210260331 8210260333	82/10/14 82/10/19 82/10/21 82/10/21 82/10/21	50-324 50-373 50-324 50-369 50-440	8 P 0	8210270088 8210270095 821027001 8210270113 8210270118	8210270077 8210270090 8210270083 8210270104 8210270104	62/09/14 62/10/25 62/09/20 62/10/15 62/10/15	40-2061 50-289 50-251 50-247 50-247	0 8 P
6210240338 6210240345 6210240351 6210240352 6210240353	8210260334 8210260341 8210260340 8210260341 8210260349	02/10/21 02/10/22 02/09/17 02/10/22 02/10/19	50-333 40-8610 TOPREP 40-8610 50-260	8	8210270127 8210270139 8210270142 8210270144 8210270152	8210270124 8210270132 8210270136 8210270132 8210270149	82/10/25 82/10/08 82/10/07 82/10/08 82/10/05	50-584 50-369 50-272 50-369 XPORTLIC	A F F F
8210260354 8210260360 8210260369 8210260369 8210260377	8210260350 8210260346 8210260344 8210260357 8210260370	82/10/20 82/10/19 82/10/19 82/10/15 82/09/17	50-387 50-339 50-325 50-335 50-302	6 8 8	6210270169 8210270177 6210270162 8210270163 6210270163	8210270164 8210270165 8210270177 8210270180 8210270184	82/09/29 81/05/26 82/09/14 82/08/25 82/10/22	40-8577 40-8502	9
8210260379 8210260382 8210260384 8210260385 8210260386	8210260366 8210260372 8210260360 8210260366 8210260378	82/10/22 82/10/18 82/10/22 82/10/22 82/10/17	50-387 50-341 50-454 50-387 50-333	8 6 6 6	8210270193 8210270197 8210270203 8210270205 8210270215	8210270190 8210270195 8210270199 8210270204 8210270212	82/10/20 82/09/02 82/09/28 82/10/26 81/12/07	40-8102 Contract 50-338	Ж Р 8
8210260391 8210260392 8210260404 8210260407 8210260410	8210260376 8210260380 8210260397 8210260381 8210260405	82/10/22 82/10/22 82/10/21 82/10/19 82/10/22	50-335 50-454 50-537 50-259 50-324	0 0 8 P	8210270220 8210270221 8210270223 8210270224 8210270227	8210270212 8210270207 8210270207 8210270212 8210270222	81/12/07 82/09/29 82/09/29 81/12/07 82/08/27	CONTRACT CONTRACT	8
8210260411 8210260424 8210260435 8210260441 8210260446	8210260399 8210260416 8210260416 8210260432 8210260417	82/10/19 82/10/21 82/10/21 82/10/17 82/10/19	50-295 50-3&1 50-3&1 50-336 50-260	8848	6210270230 8210270239 6210270240 8210270241 6210270247	8210270226 8210270229 8210270236 8210270237 8210270242	82/07/28 82/07/26 82/10/22 81/03/13 82/09/24	50-275	G R B
8210260453 8210260465 8210260470 8210260477 8210260479	8210260453 8210260457 8210260453 8210260472 8210260476	82/10/18 82/10/20 82/10/21 82/10/18	50-348 50-309 50-348 50-204 50-244	8 0 8 P P	8210270248 8210270249 8210270254 8210270257 8210270257	8210270244 8210270245 8210270251 8210270252 8210270256	81/06/05 81/05/18 81/12/15 81/05/22 82/10/08	50-249	5 8 8 F
				8 A P B S	6210270240 8210270241 8210270248 8210270269 8210270271	8210270258 8210270256 8210270267 8210270266 8210270267	82/10/12 82/10/08 82/10/22 81/05/20 82/10/22		P F P B P
	p&10460476	82/10/22	\$0 - 335	E P R G	6210270273 8210270275 8210270278 8210270280 8210270280	8210270272 8210270274 8210270276 8210270279 8210270270	81/06/01 81/05/20 81/05/22 81/05/01 82/10/19	50-317 50-317 50-317 50-317 50-155	8 8 8 6 P
8210260511 8210260515 8210260520 8210260521 8210260524	8210260508 8210260376 8210260516 8210260518 8210260518	82/10/22 82/10/22 82/09/28 82/09/16 82/09/16	50-261 50-335 CONTRACT 50-272 50-272	P G F F	8210270297 8210270302 8210270303 8210270304 8210270317	6210270294 6210270294 6210270294 6210270301 6210270314	82/10/13 82/10/13 82/10/13 82/10/13 82/09/29	50-266 50-266 50-266 ORG 50-312	P P

ACCESSION						ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJE	
8210270320 8210270325 8210270332 8210270355 8210270360	8210270314 8210270319 8210270327 8210270352 8210270352	82/09/29 82/10/13 82/10/14 82/10/18 82/10/18	50-312 50-346 50-382 50-272 50-272	PPMPP	8210280200 6210280201 8210280204 8210280205 6210280212	8210280174 8210280174 8210280176	81/04/03 82/10/25 82/10/25 81/04/16 82/10/22	50-318 50-277 50-277 50-317 50-275	8 P 8 R
8210270366 8210270376 8210270382 8210270386 8210270387	8210270352 8210270373 8210270372 8210270372 8210270372	82/10/18 82/09/15 82/10/13 82/10/13	50-272 40-8824 50-346 50-346 50-346	P P P	8210280219 8210280226 8210280229 8210280232 8210280232	8210280215 8210280223 8210280223 8210280223	82/10/19 82/10/13 82/10/13 82/10/13 82/09/30	50-387 50-05 50-05 50-05 50-05	8 0 0
8210270395 8210270402 8210270407 8210270413 8210270419	8210270393 8210270399 8210270403 8210270411 8210270416	82/10/12 82/10/13 82/10/20 82/09/30 82/09/30	CONTRACT CONTRACT CONTRACT 50-387 CONTRACT	x	8210280244 8210280245 8210280245 8210280267 8210280278	8210280241 8210280241 8210280249 8210280263 8210280275	82/10/12 82/10/12 81/04/23 81/04/16 82/10/22	50-397 50-397 50-317 50-317 50-324	0 6 8 F
8210270427 8210270428 8210270429 8210270430 8210270432	8210270423 8210270425 8210270423 8210270426 8210270426	82/09/23 82/09/23 82/09/23 82/10/08 82/10/08		F F	8210280284 8210280297 8210280297 8210280298 8210280301	6210280277 8210280271 8210280286 6210280273 8210280276	81/04/03 82/10/22 82/10/22 82/10/21 81/04/14	50-318 50-250 50-460 50-266 50-317	\$ F O P S
8210270436 8210270437 8210270438 8210270439 8210270452	8210270434 8210270423 8210270423 8210270435 8210270448	82/10/12 82/09/23 82/09/23 82/09/03 82/09/27	70-1151 70-1510 70-1510 40-8481 XPORTLIC		00000108 000000108 010000108 010000108 010000108	8210280287 8210280299 8210280305 8210280311 8210280310	62/10/14 62/10/05 81/04/10 62/10/01 82/10/05	50-275 CONTRAC 50-317 71-9057 CONTRAC	6
8210280017 8210280019 8210280020 8210280021 8210280024	8210280016 8210280013 8210280016 8210280013 8210280013	82/10/12 82/07/17 82/10/12 82/09/17 82/09/17	F01A 50-349 50-324	F P P	8210280371 8210280330 8210280330 8210280333	8210280013 8210280322 8210280324 8210280327 8210280318	82/09/17 82/10/01 82/10/14 82/10/05 81/05/12	FOIA 71-6346 50-279 CONTRACT 50-317	G S
8210280027 8210280031 8210280036 8210280037 8210280041	8210280013 8210280013 8210280033 8210280033 8210280033	82/09/17 82/09/17 82/10/08 82/10/08 82/10/08	50~336 1 50-322 1 50-322 1	P F F	8210280333 8210280337 8210280341 8210280342 8210280345	8210280329 8210280334 8210280336 8210280338 8210280343	82/10/01 82/09/17 81/04/17 82/09/17 82/09/21	71-6745 71-6677 50-318 71-6678 71-6115	ទ
8210280042 8210280047 8210280048 8210280049 8210280051	8210280013 8210280013 8210280045 8210280046 8210280045	82/09/17 82/09/17 82/10/08 82/09/10 82/10/08	50-324 50-409 40-8745	P P F	8210280351 8210280355 8210280359 8210280364 8210280372	8210280348 8210280354 8210280357 8210280361 8210280368	82/10/26 82/10/05 82/07/16 82/10/12 82/10/13	REVIEW O CONTRACT 71-9098 50-254 50-528	
821,0280053 6210280055 6210280059 6210280061 6210280063	8210280045 8210280045 8210280056 8210280058 8210280058	82/10/08 82/10/08 82/10/04 82/10/08 82/10/08	50-409 XPORTLIC 50-255	F F F	8210280374 8210280375 8210280380 8210280393 8210280397	8210280370 8210280361 8210280378 8210280378 8210280386	82/10/07 82/10/12 82/10/12 82/10/12 62/10/15	CONTRACT 50-254 50-315 50-315 CONTRACT	F
8210280068 8210280074 8210280078 8210280082 8210280084	8210280066 8210280071 8210280075 8210280013 8210280080	82/10/19 82/10/20 82/10/19 82/09/17 82/10/19	50~213 50~346 50~261	8 8 8 8	8210280406 8210280408 8210290413 8210280417 6210280421	8210280402 8210280397 8210280399 8210280415 8210280415	82/09/30 82/10/12 82/10/12 82/10/14 82/10/14	FOIA 50-315 50-315 70-2957 70-2957	F
8210280095 8210280103 8210280110 8210280110	8210280013 8210280013 8210280074 8210280013 8210280108	82/09/17 82/09/17 82/10/15 82/09/17 82/10/12	50-250 50-29 F01A	P P P	8210280424 8210280425 8210280427 8210280430 8210280430	8210280419 8210280423 8210280419 8210280428 8210280428	82/10/12 82/10/15 82/10/12 92/10/18 82/10/18	50-295 50-305 50-295 50-247 50-247	F F P P
8210280114 8210280120 8210280125 8210280124 8210280128	8210280108 8210280117 8210280122 8210280117 8210280123	82/10/12 82/10/12 82/10/22 82/10/12 82/10/15	50-295 50-373	F Q F S	8210280445 8210280447 8210280453 8210270003 8210270006	8210280442 8210280442 8210280452 8206270053 8206270053	82/10/12 82/10/12 82/09/21 82/10/04 82/10/04	50-295 50-295 70-364 COMM 1581 COMM 1581	
8210280131 8210280138 8210280141 8210280143 9210280145	8210280129 8210280136 8210280134 8210280136 8210280142	82/10/20 82/10/12 82/10/20 82/10/12 82/10/04	50-273 50-271 50-318 50-271 50-267	8 F 9 F 0	8210270027 8210270032 8210270031 8210270041 8210270043	8210270023 8210270023 8210270023 8210270038 8210270023	82/09/03 82/09/03 82/09/03 82/10/12 82/09/03	FOIA FOIA 50-142 50-285 50-142	F
B210280149 B210280150 B210280154 B210280154 B210280159	8210280142 8210280144 8210280148 8210280152 8210280148	82/10/06 62/10/20 62/10/12 62/10/15 82/10/12	50-247 50-293 50-3 50-311 50-3	9 5 5 5	B21029004B B210290051 B210290055 B210290055 B210290057	8210270023 8210270023 8210270023 8210270050 8210270054	82/09/03 82/09/03 82/09/03 82/10/23 82/10/13	50-142 50-142 FOIA 50-416 50-259	G F B
8210280165 8210280168 8210280171 8210280174 8210280174	8210280158 8210280164 8210280164 8210280170 8210280170	82/10/25 82/10/13 82/10/13 82/10/13 82/10/13	50-348 50-282 50-282 50-461 50-461	P 0 0	8210279058 8210279065 8210279065 8210279066	8210290023 8210290047 8210290023 8210290023 8210290062	82/09/03 82/10/08 82/09/03 82/09/03 82/10/13	FDIA 50-10 FDIA FOIA 50-259	F
8210280184 8210280186 8210280190 8210280195 8210280198	8210280180 8210280183 8210280185 8210280191 8210280194	82/10/22 81/04/08	40-7580 50-223 50-460 50-318 50-277	R 0 S P	8210270067 821027007 8210270071 8210270072 8210270077	8210270023 8210270063 8210270042 8210270068 8210270047	82/09/03 79/08/16 82/10/04 82/10/15 82/10/08	FOIA 50-361 50-338 50-289 50-10	A P Q F

ACCESSION NUMBE			ACCESSIO	N NUMBER			
PRINC ENCLOSURE DOCU	IPAL DATE	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	Y
8210290078 82102 8210290080 82102 8210290081 82102 8210290087 82102 8210290088 82102	70075 82/10/19 70073 82/10/25 70083 82/10/15	50-261 50-366 50-416 50-270 50-10	8210270286 8210270270 8210270272 8210270301 8210270304	8210290284 8210290278 8210290289 8210290300 8210290300	82/10/21 62/10/26 82/10/17 82/10/08 82/10/08	50-395 50-358 50-364 50-184 50-184	8080
82102700B9 82102 8210270070 82102 8210270073 82102 8210270074 82102 8210270077 82102	70085 B2/10/15 70084 B2/10/15 70071 B2/10/14	50-322 FOIA 50-322 50-328 50-324	8210270313 8210270314 8210270320 8210270321 8210270322	821029030B 8210290310 8210290316 8210290317 8210290319	82/10/18 82/10/06 82/10/26 82/10/13 82/09/24	50-267 50-272 50-206 50-259 50-275	\$ 8 V 5 R
8210270106 82102 8210270107 82102 8210270113 82102 8210270128 82102 8210270130 82102	70103 82/10/08 70110 82/10/01 70115 82/10/04	50-321 50-220 50-324 50-387 50-387	8210270327 8210270332 8210270332 8210270334 8210270338	8210290326 8210290325 8210290311 8210290327 8210290335	82/10/14 82/10/15 82/10/25 82/10/12 82/10/21	50-321 50-325 50-41 <i>6</i> 50-321 50-395	99999
8210270131 821025 8210270132 821025 8210270133 821025 8210270136 821025 8210270137 821025	70125 82/10/15 70124 82/10/23 70115 82/10/04	CONTRACT 50-322 50-416 50-387 50-409	8210270339 8210270342 8210270345 8210270345 8210270347	8210290333 8210290336 8210290341 8210290340 8210290337	82/10/22 82/10/15 82/10/12 82/10/23 82/10/13	50-261 50-324 50-322 50-416 50-338	9999
8210270143 821029 8210270144 821029 8210270146 821029 8210270148 821029 8210270157 821029	70141 82/10/17 70140 82/09/21 70140 82/09/21	50-313 TOPREP 50-313 50-313	8210270351 8210270352 8210270354 8210270354 8210270361	8210270348 8210270346 8210270350 8210270347 8210270353	82/10/25 82/10/04 82/10/04 82/10/21 82/10/04	50-416 50-325 50-322 50-321 50-272	50056
8210290163 821029 8210290173 821029 8210290175 821029 8210290180 821029 8210290183 821029	70171 82/10/14 70169 82/10/22 70169 82/10/22	50~329 50~244 50~206 50~206 50~206	8210270364 8210270365 821027037 6210270372 8210270375	8210290357 8210290355 8210290368 8210290367 8210290373	62/10/07 82/10/14 82/10/15 82/10/13 62/10/12	50-366 50-269 50-259 XPORTL IC 50-321	ន ន ន
8210270174 821025 8210270177 821025 8210270207 821025 8210270207 821025 8210270210 821025	70190 82/10/15 70201 82/10/08 70206 82/10/14	50-213 (50-269 (50-387 (50-366 (50-352 (8210270380 8210270381 8210270383 8210270383 8210270383	B210290377 B210290374 B210290378 B210290378 B210290378	62/10/26 62/10/12 62/10/20 62/10/20 62/10/20	50~327 50~366 50~346 50~346 50~346	Ф \$ P P
8210270217 821025 8210270218 821025 8210270222 821025 8210270227 821025 8210270232 821025	0216 82/10/06 0217 82/10/18 0228 82/07/23	50-244 0 50-272 8 50-275 8 50-329 4 50-296 8	8210270392 8210270398 8210270416 8210270417 8210270418	8210270383 6210270376 8210270414 8210270413 8210270414	82/10/12 82/07/28 82/10/04 82/10/07 82/10/04	50-344	е 0 е
8210290241 821029 8210290246 821029 8210290270 821029 8210290272 821029 8210290276 821029	0243 82/10/21 0264 82/10/22 0262 82/10/14	70-33 50-324 8 50-280 8 50-321 8 50-280 8	6210270421 8210270422 8210270428 6210270431 8210270434	8210270414 8210270420 8210270412 8210270426 8210270426	82/10/04 82/10/08 82/09/23 82/10/04 82/10/04	CONTRACT 50-317 50-266	ե ե ե
8210290279 821029 8210290280 821029 8210290281 821029 8210290282 821029 8210290285 821029	0275 82/10/13 0278 82/10/24 0244 82/10/22	50-327 8 50-293 6 50-358 6 50-280 8 50-358 6	8210290439 821029044 8210290444 8210290451 8210290454	8210270412 8210270426 8210270412 8210270447 8210270447	82/09/23 82/10/04 82/09/23 82/09/22 82/09/22	50-266 50-317 50-275	P P P 0

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are

- 1. Application for construction permit
- 2. General Information submitted with construction permit application.
- 3 Amendments and changes to items 1 and 2
- 4. NRC questions, requests for additional information, and applicant responses
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6 Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9 Construction Permit, amendments, and correspondence relating to the construction permit.
- 10 Scheduling of license application submission or review.
- 11 Environmental review information
- 12. Application for operating license
- 13. General Information submitted with operating license application
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility, not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.

- 1. Satety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- l Change of address notifications
- 2 Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8 Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- ² Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit

- 1. Limited Work Authorizations (LWA) and amendments.
- 2 Correspondence pertaining to work performed under LWAs.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2 Correspondence where the primary topic of discussion is antitrust matters
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews
- 2 Correspondence from ACRS
- 3 Announcement of ACRS meetings
- 4 Transmittal and acknowledgement letters
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7 Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

-- pp- , or region 1 allu 4

- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1 Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN s).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

- 1 Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets

5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNOS, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER s) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences)
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports
- 4 Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO s) and Preliminary Notification of Safeguards Events (PN s)
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1 Operator licenses or administrative information bearing on licensing of operators.
- 2 NRC examination results.
- 3 Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan,
 Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4 Documents relating to disposal of radioactive material and decontamination of the site,
- 5. Other correspondence relating to above items,
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

X ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record, record of votes of Commissioners on items under consideration at meetings

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

 Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE. For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or 1FB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development, and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are

- 1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility, e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR),
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- o. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission teview of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects (1) commercial nuclear power plants for which NRC has full licensing responsibilities, and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

l. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - 2. Amendments and changes to the PSAR,
 - 3. Transmittal letters.
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.

- Inspection reports of the applicant's quality assurance program.
- Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include.

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling e 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR by utilities for specific facilities. Documents in this category include:

ection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspecover the design, fabrication, construction and testing of structural systems and

ns.

3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are.

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examin
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by cont
- 8. Letter, monthly, quarterly, interim or annual status or projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with to and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting pleted research programs.

NOTE: For final reports of research conducted by contracto

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of N groups provide a broad base of technical expertise to aid mana

projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG — State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

of haison and cooperative activities regarding such functions as licensing and siting. It includes.

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State haison officers, regarding
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations, i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4 Agreement State Licensing Statistics Reports

NOTE For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

in the waste isolation Pilot Plan (WIPP) for burial of defense wastes.

4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 US NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET	1 REPORT NUMBER (Assigned by DDC) NUREG-0540 Vol. 4, No. 10
4 TITLE AND SUBTITLE (Add Volume No. 11 appropriate) Title List of Documents Made Publicly Available October 1-31, 1982	2 (Leave biank)
	3 RECIPIENT'S ACCESSION NO
7 AUTHORIS:	5 DATE REPORT COMPLETED MONTH YEAR
PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Division of Technical Information and Document Contr Office of Administration U.S. Nuclear Regulatory Commission Washington, DC 20555	OATE REPORT ISSUED MONTH YEAR January 1983 6 (Leave blank)
2 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)	· · · ·
Same as 9, above.	11 FIN NO
	COVERED (Inclusive dates)
Monthly	
5. SUPPLEMENTARY NOTES	14 (Leave olank)
This document is a monthly publication containing des received and generated by the U.S. NRC. This informa material associated with civilian nuclear power plant active materials, and (2) nondocketed material receiv pertinent to its role as a regulatory agency. The fo Personal Author Index, Corporate Source Index, Report Reference to Principal Documents Index.	ation includes (1) docketed is and other uses of radio- ived and generated by NRC illowing indexes are included:
KEY WORDS AND DOCUMENT ANALYSIS 17a DESCRI	IPTORS
D IDENTIFIERS OPEN ENDED TERMS	
AVAILABILITY STATEMENT	CURITY CLASS (This report) 21 NO OF PAGES Inclassified CURITY CLASS (This name) 22 PRICE

Umlimited